# Available from

NRC/GPO Sales Program Superintendent of Documents Government Printing Office Washington, D.C. 20402

A year's subscription consists of 12 issues of this publication

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program U.S. Nuclear Regulatory Commission Washington, D.C. 20555

# Title List of Documents Made Publicly Available

March 1-31, 1981

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





# CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Alphabetic Arrangement of Docket 50 Items by Facility Name xix
Docketed Items
Low Level Radwaste Disposal Sites - Docket 27
Domestic Licensing of Source Material - Docket 40
Domestic Licensing of Production and Utilization Facilities Docket 50 14
Domestic Licensing of Special Nuclear Material - Docket 70 404
Packaging of Radioactive Material for Transport and Transportation of
Radioactive Material Under Certain Conditions - Docket 71 417
Nondocketed Items
10 CFR - Commission Meeting Records
ACRS – Advisory Committee on Reactor Safeguards 429
COMMISSION – NRC Commissioners
CONTRACT – NRC Contracts and Modifications
FOIA - Freedom of Information Act Requests and Releases
GEN TECH IS - Generic Technical Issues
I&E - Inspection and Enforcement 447
MISC – Public Document Room Miscellaneous
NUREG NUREG Reports and Related Correspondence 451
ORG Correspondence with Other Organizations
PR – Proposed Rule
PRM – Petition for Rulemaking
PROJ – Projects - Predocket Licensing
PT21 – Noncompliance Reports and Related Correspondence
QAyyy = Quanty Assurance inspections
REGGID - Regulatory Guides
RES - Research and Position Pasistance Reports
REVIEW GRP NRC Research Review Groups
STATE PROG — State Programs
TOPREP – Vendor Reports and Related Correspondence
WASTE MGT – Nuclear Waste Management
XPORTLIC – Export and Import Licenses
1 Cisoffat Fibrillot Micox
Corporate Source Index
Report Number Index
Cross Reference of Enclosures to Principal Documents 563
Appendix A – Definitions of Docket 50 Categories
Appendix B Definitions of Nondocketed Categories

#### PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the Title List includes the information formerly issued through the Department of Energy publication Power Reactor Docket Information, last published in January 1979. Microfiche of the docketed information listed in the Title List is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- 1:. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- O. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

V. Decommissioning stage documents and correspondence


Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P Operating license stage documents & correspondence

7904170015 Forwards into on TMEJM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- t. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
- 9. This three-digit portion of this entry is the number of the frame on which this document starts.
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room. 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

.:

1&E — Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT9 — Public Records

PT21 - Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES - Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY - Position Papers Before the Commission

STATE PROG - State Programs

TOPREP — Vendor Reports and Related Correspondence

WASTE MGT - Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:


1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

(4) The Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration Environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.



- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
- 11. This three-digit portion of this entry is the number of the frame on which this document starts.

the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

## NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-7924	Schott Optical Glass, Inc.
27-043	Peekskill, NY, Nuclear Diagnostic Laboratories	1	40-8027	Kerr-McGee Corp.
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	2	40-8040	Cerac, Inc.
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8064	Exxon Minerals Co. USA, Exxon Corp.
40-0086	W.R. Grace & Co.	2	40-8084	Lisbon Mine, Rio Algom Corp.
40-0229	Union Carbide Corp.	2	40-8102	Exxon Minerals Co. USA, Exxon Corp.
40-0299	Union Carbide Corp.	2	40-8129	Dept. of the Army
40-0341	General Services Administration, Federal Property Resources Services	3	40-8151	Dept. of the Navy, Naval Sea Systems Command
40-0659	General Electric Co., Aircraft Engine Group	3	40-8155	Amax Specialty Metals Corp.
40-0672	Nuclear Metals, Inc.	3	40-8200	Cleveland-Cliffs Iron Co.
40-1162	Western Nuclear, Inc.	3	40-8348	In Situ Uranium Leaching Project
40-1341	Edgemont Uranium Mine, TVA and	4	40-8380	Rocky Mountain Energy Co.
	Mines Development, Inc.		40-8384	Minerals Exploration Co.
40-1947	Stepan Chemical Co.	4	40-8452	Bear Creek Uranium Co.
40-2061	West Chicago Facility, Kerr-McGeo Corp.	6	40-8502	Itigatay Mine, Wyoming Mining Corp.
40-2259	Pathfinder Mines Corp.	6	40-8511	Cotter Corp.
40-2274	Chase Brace & Co., Cleveland Refactory Metals Division	6	40-8584	Union 76 Minerals Exploration Co.
40-3392	Allied Chemical Corp.	7	40-8585	Wyoming Mineral Corp.
40-3453	Atlas Minerals	7	40-8602	United Nuclear Corp.
40-4348	Dept. of Commerce, National Bureau of	7	40-8610	Stepan Chemical Co.
	Standards		40-8663	Nuclear Dynamies, Inc.
40-4492	Federal American Partners (Mining)	7	40-8674	Plateau Resources, Ltd.
40-5021	Standard Oil Co.	8	40-8681	Energy Fuels Nuclear, Inc.
40-5293	Northeastern Univ.	8	40-8693	Ogle Petroleum, Inc.
40-6622	Pathfinder Mines Corp.	8	40-8697	Rocky Mountain Energy Co.
40-6659	Getty Oil Co., Petrotomics Co. Division	8	40-8698	Plateau Resources, Ltd.
40-7869	Pluteau Resources, Ltd.	8	40-8700	Dept. of the Army

Jocket	Name	Page	Docket	Name	Pa
40-8702	Dept. of the Army, Armament Materials	13	50.89	General Atomic Co.	2
	Readiness Command		50-94	Rockwell International Research Reactor	2
40-8714	Cleveland-Cliffs Iron Co.	13	50-99	Babcock & Wilcox Co. Test Reactor	2
40-8722	Brush-Wellman, Inc.	13	50-106	Oregon State Univ.	2
40-8726	New Mexico Health-Environment Dept.	13	50-111	North Carolina State Univ. Research	2
40-8728	Teton Exploration Drilling Co., Inc-	13		Reactor	
40-8743	Conoco, Sand Rock Mill Project	13	50-112	Univ. of Oklahoma Research Reactor	2
40-8745	Olge Petroleum, Inc.	13	50-113	Univ. of Arizona Research Reactor	2
40-8760	Edlow International Corp.	13	50-116	Iowa State Univ. Research Reactor	2
40-8781	Teton Exploration Drilling Co., Inc.	13	50-123	Univ. of Missouri Research Reactor	2
40-8786	Uranium Resources, Inc.	14	50-124	Virginia Polytechnic Institute Training Reactor	2
40-8788	Union Carbide Corp.	14	50-128	Texas A&M Univ. Research Reactor	2
50-2	Univ. of Michigan Research Reactor	14	50-129	West Virginia Univ. Research Reactor	2
50-3	Indian Point Station, Unit 1	14	50-131	Omaha Veterans Administration Hospital	2
50-5	Pennsylvania State Univ. Research Reactor	15		Research Reactor	
50-10	Dresden Nuclear Power Station, Unit 1	15	50-133	Humboldt Bay Power Plant, Unit 3	2
50-13	Babcock & Wilcox Co, Critical Facility	18	50-139	Univ. of Washington Research Reactor	2
50-18	Vallecitos Boiling Water Reactor	18	50-141	Stanford Univ. Research Reactor	2
50-20	Massachusetts Institute of Technology	18	50-142	UCLA Training Reactor	2
	Research Reactor		50-148	Univ. of Kansas Research Reactor	2
50-27	Washington State Univ. Research Reactor	18	50-150	Ohio State Univ. Research Reactor	2
\$0-29	Yankee-Rowe Nuclear Power Station	18	50-151	Univ. of Illinois Research Reactor	2
50-30	Plum Brook Research Reactor Facility	20	50-155	Big Rock Point Nuclear Plant	2
50-34	Yankee Atomic Power Reactor	21	50-156	Univ. of Wisconsin Research Reactor	3
50-54	Union Carbide Research Reactor	21	50-160	Georgia Institute of Technology Research Reactor	3
50-57	State Univ. of New York Research Reactor	21	50-163	General Atomic Company	3
50-59	Texas A&M Univ. Research Reactor	21	50-170	National Naval Medical Center	-
50-62	Univ. of Virginia Research Reactor	21	50-171	Peach Bottom Atomic Power Station,	3
50-70	General Electric Test Reactor	21	30-171	Unit 1	3
50-72	Univ. of Utah Research Reactor	22	50-182	Purdue Univ. Research Reactor	3
50-73	General Electric Nuclear Test Reactor	22	50-183	Vallecitos Experimental Superheat Reactor	3
50-77	Catholic Univ. of America Research Reactor	22	50-184	National Bureau of Standards Reactor	3
50-83	Univ. of Florida Training Reactor	22	50-185	Plum Brook Reactor-Mock-Up	:

50-186

Westinghouse Critical Experiment

50-87

Univ. of Missouri Research Reactor

3

Docket	Name	Page	Docket	Name	Page
\$0-187	Space Radiation Research Reactor	32	50-267	Fort St. Vrain Nuclear Generating Station	90
50-188	Kansas State Univ. Research Reactor	32	50-269	Oconee Nuclear Station, Unit 1	93
50-192	Univ. of Texus Research Reactor	32	50-270	Oconee Nuclear Station, Unit 2	
50-193	Rhode Island & Providence Plantations AEC	33			96
50-201	West Valley Reprocessing Plant	33	50-271	Vermont Yankee Nuclear Power Station	98
50-206	San Onofre Nuclear Station, Unit 1	33	50-272	Salem Nuclear Generating Station, Unit 1	101
50-213	Haddam Neck Plant	37	50-273	Beznau Nuclear Station, Unit 1, Switzerland	104
\$0-219	Oyster Creek Nuclear Power Plant	39	50-274	U.S. Geological Survey Research Reactor	105
\$0-220	Nine Mile Point Nuclear Station, Unit 1	42	50-275	Diable Canyon Nuclear Power Plant	105
50-223	Univ. of Lowell Research Reactor	45	60.344	Unit 1	1.00
50-224	Univ. of California Research Reactor	45	50-276	Georgia Tech Research Reactor	109
50-225	RPI Critical Experiment	45	50-277	Peach Bottom Atomic Power Station, Unit 2	109
50-228	Aerotest Radiography & Research Reactor	45	50-278	Peach Bottom Atomic Power Station, Unit 3	111
50-237	Dresden Nuclear Power Station, Unit 2	45	50-280	Surry Power Station, Unit 1	113
50-243	Oregon State Univ. Research Reactor	49		•	
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	49	50-281	Surry Power Station, Unit 2	116
50-245	Millstone Nuclear Power Station, Unit 1	52	50-282	Prairie Island Nuclear Station, Unit 1	811
50-247	Indian Point Station, Unit 2	55	50-284	Idaho State Univ. Research Reactor	120
50-249	Dresden Nuclear Power Station, Unit 3	58	50-285	Fort Calhoun Station, Unit 1	120
50-250	Turkey Point Plant, Unit 3	61	50-286	Indian Point Station, Unit 3	122
50-251	Turkey Point Plant, Unit 4	64	50-287	Oconce Nuclear Station, Unit 3	125
50-252	Univ. of New Mexico Research Reactor	68	50-288	Reed College Research Reactor	128
50-254	Quad-Cities Station, Unit 1	68	50-289	Three Mile Island Nuclear Station, Unit 1	128
50-255	Palisades Nuclear Plant	70	50-293	Pilgrim Nuclear Power Station, Unit 1	139
50-259	Browns Ferry Nuclear Power Station,	73	50-294	Michigan State Univ. Research Reactor	141
60.260	Unit 1	77	50-295	Zion Nuclear Power Station, Unit 1	141
50-260	Browns Ferry Nuclear Power Station, Unit 2	,,	50-296	Browns Ferry Nuclear Power Station,	144
50-261	H. B. Robinson Plant, Unit 2	80	60 307	Unit 3  North Carolina State Univ. PULSTAR	148
50-262	Brigham Young Univ. Research Reactor	83	50-297	Reactor	140
50-263	Monticello Nuclear Generating Plant	83	50-298	Cooper Nuclear Station	148
50-264	Dow Chemical Co.	86	50-301	Point Beach Nuclear Plant, Unit 2	150
50-265	Quad-Cities Station, Unit 2	86	50-302	Crystal River Nuclear Plant, Unit 3	152
50-266	Point Beach Nuclear Plant, Unit 1	88	50-304	Zion Nuclear Power Station, Unit 2	155

Docket	Name	Page	Docket	Name	Page
50-305	Kewaunee Nuclear Power Plant	158	50-344	Trojan Nuclear Plant	239
50-306	Prairie Island Nuclear Station, Unit 2	160	50-346	Davis-Besse Nuclear Power Station, Unit 1	242
\$0-309	Maine Yankee Atomic Power Plant	162	50-348	Joseph M. Farley Nuclear Plant, Unit 1	245
50-311	Salem Nuclear Generating Station, Unit 2	164	50-352	Limerick Generating Station, Unit 1	247
50-312	Rancho Seco Nuclear Generating Station	166	50-353	Limerick Generating Station, Unit 2	25()
50-313	Arkansas Nuclear One, Unit 1	170	50-354	Hope Creek Nuclear Station, Unit 1	253
50-315	Donald C. Cook Nuclear Power Plant,	173	50-355	Hope Creek Nuclear Station, Unit 2	254
	Unit 1		50-356	Univ. of Illinois LOPRA Research	255
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	175		Reactor	20.4
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	177	50-358	William H. Zimmer Nuclear Station, Unit 1	256
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	180	50-360	Battelle Memorial Institute Critical Facility	258
50-320	Three Mile Island Nuclear Station, Unit 2	183	50-361	San Onofre Nuclear Station, Unit 2	258
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	189	50-362	San Onofre Nuclear Station, Unit 3	263
50-322	Shoreham Nuclear Power Station	192	\$0-363	Forked River Nuclear Station, Unit 1	268
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	193	50-364	Joseph M. Farley Nuclear Plant, Unit 2	268
50-324	Brunswick Steam Electric Plant, Unit 2	198	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	271
50-325	Brunswick Steam Electric Plant, Unit 1	201	50-367	Bailly Generating Station	274
50-326	Univ. of California at Irvine Research	205	50-368	Arkansas Nuclear One, Unit 2	276
	Reactor		50-369	William B. McGuire Nuclear Station, Unit 1	278
50-327	Sequoyah Nuclear Plant, Unit 1	205	50-370	William B. McGuire Nuclear Station,	283
50-328	Sequoyah Nuclear Plant, Unit 2	209	30-370	Unit 2	200
50-329	Midland Plant, Unit 1	212	50-373	LaSalle County Station, Unit 1	285
50-330	Midland Plant, Unit 2	215	50-374	LaSalle County Station, Unit 2	288
50-331	Duane Atnold Energy Center	218	50-375	Nuclear Examination Reactor	290
50-333	James A. Fitzpatrick Nuclear Power Plant	220	50-376	North Coast Nuclear Plant, Puerto Rico	290
50-334	Beaver Valley Power Station, Unit 1	223	50-382	Waterford Generating Station, Unit 3	290
50-335	St. Lucie Plant, Unit 1	227	50-387	Susquehanna Steam Electric Station, Unit 1	293
50-336	Millstone Nuclear Power Station, Unit 2	229	50-388	Susquehanna Steam Electric Station,	297
50-338	North Anna Power Station, Unit 1	231		Unit 2	
50-339	North Anna Power Station, Unit 2	234	50-389	St. Lucie Plant, Unit 2	301
50-341	Enrico Fermi Atomic Power Plant,	238	50-390	Watts Bar Nuclear Plant, Unit 1	303
	Unit 2		50-391	Watts Bar Nuclear Plant, Unit 2	305

Docket	Name	Page	Docket	Name	Pag
50-394	California State Polytechnic College Research Reactor	307	50-445	Comanche Peak Steam Electric Station, Unit 1	34
50-395	Virgil C. Summer Nuclear Station, Unit 1	307	50-446	Comanche Peak Steam Electric Station, Unit 2	34
50-396	Univ. of Virginia Cavalier Reactor	311	50-448	Douglas Point Nuclear Station, Unit 1	348
50-397	WPPSS Nuclear Project, Unit 2	311	50-449	Douglas Point Nuclear Station, Unit 2	348
50-400	Shearon Harris Nuclear Power Plant, Unit 1	313	50-450	Summit Nuclear Power Station, Unit 1	34
50-401	Shearon Hatris Nuclear Power Plant,	314	50-451	Summit Nuclear Power Station, Unit 2	34:
	Unit 2		50-452	Greenwood Energy Center, Unit 2	341
50-402	Shearon Harris Nuclear Power Plant, Unit 3	315	50-453	Greenwood Energy Center, Unit 3	34
50-403	Shearon Harris Nuclear Power Plant,	316	50-454	Byron Station, Unit 1	34
	Unit 4		50-455	Byron Station, Unit 2	350
50-404	North Anna Power Station, Unit 3	317	50-456	Braldwood Station, Unit 1	351
50-405	North Anna Power Station, Unit 4	318	50-457	Braidwood Station, Unit 2	35
50-406	Tuskegee Institute Research Reactor	318	50-458	River Bend Station, Unit 1	35
50-407	Univ. of Utah Research Reactor	318	50-459	River Bend Station, Unit 2	35
50-409	La Crosse Boiling Water Reactor	318	50-460	WPPSS Nuclear Project, Unit 1	35
50-410	Nine Mile Point Nuclear Station, Unit 2	321	50-461	Clinton Power Station, Unit 1	35
50-412	Beaver Valley Power Station, Unit 2	322	50-462	Clinton Power Station, Unit 2	35
50-413	Catawba Nuclear Station, Unit 1	323	50-463	Fulton Generating Station, Unit 1	36
50-414	Catawba Nuclear Station, Unit 2	324	50-464	Fulton Generating Station, Unit 2	36
50-416	Grand Gulf Nuclear Station, Unit 1	326	STN-50-466	Allens Creek Nuclear Station, Unit 1	36
50-417	Grand Gulf Nuclear Station, Unit 2	328	STN-50-467	Allens Creek Nuclear Station, Unit 2	36
50-423	Millstone Nuclear Power Station, Unit 3	330	STN-50-470	CESSAR System 80	36
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	331	50-471	Pilgrim Nuclear Power Station, Unit 2	36
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	332	50-472	Pilgrim Nuclear Power Station, Unit 3	36
50-433	Univ. of California at Santa Barbara Research Reactor	333	STN-50-482	Wolf Creek Generating Station	36
STN-50-437	Floating Nuclear Plant	333	STN-50-483	Callaway Plant, Unit 1	36
50-438	Bellefonte Nuclear Plant, Unit 1	333	STN-50-484	Tyrone Energy Park, Unit 1	36
50-439	Bellefonte Nuclear Plant, Unit 2	336	STN-50-485	Sterling Power Nuclear Project, Unit 1	36
50-440	Perry Nuclear Power Plant, Unit 1	338	STN-50-486	Callaway Plant, Unit 2	36
50-441	Perry Nuclear Power Plant, Unit 2	339	STN-50-488	Perkins Nuclear Station, Unit 1	37
50-443	Seabrook Nuclear Station, Unit 1	341	STN-50-489	Perkins Nuclear Station, Unit 2	37

50-444

Seabrook Nuclear Station, Unit 2

STN-50-490 Perkins Nuclear Station, Unit 3

37

Docket	Name	Page	Docket	Name	P
STN-50-491	Cherokee Nuclear Station, Unit 1	372	STN-50-547	Marble Hill Nuclear Station, Unit 2	3
STN-50-492	Cherokee Nuclear Station, Unit 2	37 <b>3</b>	STN-50-553	Phipps Bend Nuclear Station, Unit 1	4
STN-50-493	Cherokee Nuclear Station, Unit 3	374	STN-50-554	Phipps Bend Nuclear Station, Unit 2	4
50-496	Montague Nuclear Power Station, Unit 1	374	STN-50-556	Black Fox Station, Unit 1	4
50-497	Montague Nuclear Power Station, Unit 2	374	STN-50-557	Black Fox Station, Unit 2	4
STN-50-498	South Texas Project, Unit 1	375	50-564	Nuclear Fuels Recovery & Recycle	4
STN-50-499	South Texas Project, Unit 2	377	0201 60 666	Center	,
\$0-500	Davis-Besse Nuclear Power Station, Unit 2	380	STN-50-566 STN-50-567	Yellow Creek Nuclear Plant, Unit 1  Yellow Creek Nuclear Plant, Unit 2	4
50-501	Davis-Besse Nuclear Power Station,	380	50-578	Santillan Nuclear Power Station, Spain	4
	Unit 3		50-579	TRIGA Mark II, Pool-Type Reactor	4
STN-50-502	Haven Nuclear Plant, Unit 1	380	50-583	Sundesert, Unit 2	4
STN-50-503	Haven Nuclear Plant, Unit 2	380	STN-50-592	Palo Verde Nuclear Station, Unit 4	4
STN-50-508	WPPSS Nuclear Project, Unit 3	381	STN-50-593	Palo Verde Nuclear Station, Unit 5	4
STN-50-509	WPPSS Nuclear Project, Unit 5	382	50-596	New Haven, Unit 1	4
50-510	Blue Hills Station, Unit 1	383	50-597	New Haven, Unit 2	4
50-511	Blue Hills Station, Unit 2	383		•	4
50-513	WPPSS Nuclear Project, Unit 4	383	70-0008	Battelle Columbus Laboratories	•
50-514	Pebble Springs Nuclear Plant, Unit 1	384	70-0025	Rockwell International Corp.	4
50-515	Pebble Springs Nuclear Plant, Unit 2	385	70-0027	Babcock & Wilcox Co.	4
STN-50-516	Jamesport Nuclear Station, Unit 1	385	70.0033	Texas Instruments, Inc.	4
STN-50-517	Jamesport Nuclear Station, Unit 2	385	70-0036	Combustion Engineering, Inc.	4
STN-50-518	Hartsville Nuclear Plant, Unit 1	385	70-0053	Yale Univ.	4
STN-50-519	Hartsville Nuclear Plant, Unit 2	386	70-0124	Teledyne Isotopes	4
STN-50-520	Hartsville Nuclear Plant, Unit 3	387	70-0135	Babcock &Wilcox Co.	4
STN-50-521	Hartsville Nuclear Plant, Unit 4	389	70-0143	Nuclear Fuel Services, Inc.	4
STN-50-522	Skagit Nuclear Power Project, Unit 1	390	70-0152	Purdue Univ.	4
STN-50-523	Skagit Nuclear Power Project, Unit 2	390	70-0157	Univ. of Texas	4
STN-50-528	Palo Verde Nuclear Station, Unit 1	390	70-0162	Lucius Pitkin, Inc.	4
STN-50-529	Palo Verde Nuclear Station, Unit 2	392	70-0262	Oklahoma State University	4
STN-50-530	Palo Verde Nuclear Station, Unit 3	394	70-0267	Nuclear Science & Technology Facility at Suny	4
50-537	Clinch River Breeder Reactor	397	70-0303	Carnegie Mellon Univ.	4
50-538	Memphis State Univ. Research Reactor	397	70-0309	Western Michigan Univ.	۵
STN-50-546	Marble Hill Nuclear Station, Unit 1	397	70-0315	Dept. of the Navy	7 1
				Fr me truty	4

Docket	Name	Page	Docket	Name	Pag
70-0364	Parks Township Site, Babcock & Wilcox Co.	408	70-1374	Idaho State Univ.	415
70-0371	United Nuclear Corp.	408	70-1388	Mt. Carmel Mercy Hospital & Medical Center, Detroit, MI	415
70-0394	Northeastern Univ.	408	70-1402	Abington Memorial Hospital, Abington, PA	415
70-0398	Dept. of Commerce	408	70-1407	St. Luke's Hospital, Davenport, IA	415
70-0475	Carnegic Mellon Univ.	408	70-1416	Incarnate Word Hospital, St. Louis, MO	415
70-0687	Union Carbide Corp.	408	70-1426	Transnuclear, Inc.	415
70-0698	Waltz Mill Site, Westinghouse Electric Corp.	409	70-1441	Easton Hospital, Easton, PA	415
70-0734	General Atomic Co.	409	70-1500	Washington Hospital Center, Washington, DC	415
70-0754	Vallecitos Nuclear Center, General Electric Co.	409	70-1621	Conover & Associates, Inc.	415
70-0820	United Nuclear Corp.	410	70-1703	Eastman Kodak Co.	415
70-0824	Babcock & Wilcox Co	410	70-1739	Tri-State Motor Transit Co.	416
70-0854	Isotopie Analysis, Inc.	411	70-1997	Dept. of Army	416
70-0925	Cimarron Facility, Kerr-McGee Corp.	411	70-2240	St. Francis Hospital, Blue Island, IL	416
70-0971	Oregon State Univ.	411	70-2313	Nuclear Fuel Services	416
70-0984	Pacific Northwest Lab	411	70-2317	Teledyne Cast Products	416
70-0992	David Witherspoon, Inc.	411	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	416
70-1100	Combustion Engineering, Inc.	411	70-2707	Ingham Medical Center, Lansing, MI	416
70-1113	General Electric Co.	412	70-2745	General Electric Co.	416
70-1143	Westinghouse Electric Corp.	412	70-2838	Cincinnati Gas & Electric Co.	416
70-1144	Ohmart Corp.	412	70-2882	Southern California Edison Co.	416
70-1151	Westinghouse Electric Corp.	412	70-2909	Westinghouse Electric Corp. Power Systems	416
70-1193	Cimarron Facility, Kerr-McGee Corp.	413	70-2915	Princeton Gamma-Tech	417
70-1201	UF-6 Conversion Facility, Babcock &	413	70-2928	Tennessee Valley Authority	417
70.140	Wilcox Co.	410	70-2930	Five Four Three Co., Inc.	417
70-1207	Dept. of the Navy	413	70-2936	Mississippi Power & Light Co.	417
70-1220	General Electric Co.	413	70-2937	Pennsylvania Power & Light Co.	417
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	413	70-2941	Tennessee Valley Authority	417
70-1271	Sandwich Community Unit Schools	414	71-0002	Chem-Nuclear Systems, Inc.	417
70-1277	Dept. of Agriculture, Agriculture Research Service	414	71-0033	Industrial Testing Laboratory Services Corp.	418
70-1308	Morris Operations, General Electric Co.	414	71-0138	Battelle Columbus Laboratories	418
70-1308	Morris Operations, Sources & Standards,	415	71-0164	Massachusetts Institute of Technology	418
W-1303	General		71-0179	Nuclear Containers, Inc.	418

Docket	Name	Page	Docket	Name	Pag
71-0219	Terex Division, GM Corp.	418	71-5641	Model: UNC-2500, United Nuclear Corp.	42
71-0271	Ridihalgh, Eggers & Associates	418	71-5645	Model: AL-L 8, Dept. of Energy	4 21
71-0318	Marathon Oil Co.	418	71-5740	Model: ORNL TRU CF Shipping Container, Dept. of Energy	42
71-0345	Carolina Power & Light Co.	418	71-5753	Model: ORNL LOOP Transport Cask,	42
71-0403	Schlumberger Well Services	418	71.3733	Dept. of Energy	
71-0405	Fneigy, Inc.	418	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	42
71-0406	J.G. Sylvester & Associates, Inc.	418	71-5805	Model: Vandenburgh, Chem-Nuclear	42
71-0407	Refinery Products Corp.	418	71-3700	System, Inc.	
71-0408	Missouri Steel Castings Co.	419	71-5885	Model: AL-L 11, Dept. of Energy	42
71-0409	Bristol Steel & Iron Works, Inc., Bristol Division	419	71-5926	Model: GE-100, General Electric Co.	42
71-0412	Air Products & Chemicals	419	71-5939	Model: GE-1500, General Electric Co.	42
71-0412	Construction Engineering Consultants, Inc.	-	71-5942	Model: GE-700, General Electric Co.	42
71-0413	Clark Equipment Co.	419 419	71-6078	Model: 927A1 & 927C1, Combustion Engineering Co.	42
71-0415	Duquesne Light Co.	419	71-6104	Model: ANL-390-SPM, Dept. of Energy	42
71-0416	Thiokol Corp.	419	71-6144	Model: B-2, U.S. Ecology	42
71-0417	Caribe Shell & Tube, Inc.	419	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	42
71-0418	Alloy Crafts Co.	419	71-6275	Model: 1.L-28-4, Chem-Nuclear Systems, Inc.	42
71-0419	Northwestern Research & Testing, Inc.	419	71-6346	Model: FSV-1, General Atomic Co.	42
71-0420	Radiation Technology, Inc.	420	71-6347	Model: FSV-3, General Atomic Co.	42
71-0421	Dept. of the Navy, Forces Afloat	420	71-6375	Model: CNS 4-45, Chem-Nuclear	42
71-0422	Oktahoma Steel Castings Co.	420	••••	Systems, Inc.	
71-0423	H & H X-Ray Services, Inc.	420	71-6400	Model: 6400, Westinghouse Electric Corp.	42
71-0425	Quad City Testing Laboratory	420	71-6421	Model: CBE-14, Dept. of Energy	42
71-4960	Model: LLD-1, Dept. of Energy	420	71-6458	Model: BU-5, General Electric Co.	42
71-4986	Model: RA-1, RA-2, RA-3, RA-J, General Electric Co.	420	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	42
71-5026	Modet: CNS 14-190, Chem-Nuclear Systems, Inc.	420	71-6581	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	42
71-5450	Model: RCC-1, -2, -3, -4, Westinghouse Electric Co.	420	71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	42
71-5552	Model: Gas Cylinder Fire Impact Shield,	420	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	42
M. ##60	Dept. of Energy		71-6717	Model: 6717-B, Gamma Industries, Inc.	42
71-5560	Model: VCD, Union Carbide Corp.	420	71-9001	Model: IF-300, General Electric Co.	42
71-5595	L&M ORNL Uranium Shielded Cask, Dept. of Energy	420	71-9006	Model: 500-SU, Automation Industries, Inc.	42

Docket	Name	Page	Docket	Name	Page
71-9007	Model: 520, Automation Industries, Inc.	423	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	424
71-9010	Model: NLI-1/2, Nuclear Assurance Corp.	423	71-9096	Model: CNS 21-300, Chem-Nuclear	424
71-9013	Model: 521, Isomedia, Inc.	423	71-3030	Systems, Inc.	727
71-9033	Model: 660 & 660E, Technical Operations, Inc.	423	71-9105	Model: RAD-WASTE CR. 1, Chem-Nuclear Systems, Inc.	424
71-9034	Model: TRIGA-1, General Atomic Co.	423	71-9107	Model: 771, Technical Operations, Inc.	424
71-9035	Model: 680 & 680E, Technical Operations, Inc.	423	71-9108	Model: AL-33-90, Chem-Nuclear Systems, Inc.	424
71-9036	Model: C-1, Source Production & Equipment Co.	423	71-9111	Model: CN6-80A, Chem-Nuclear Systems, Inc.	424
71-9044	Model: GE-1600, General Electric Co.	423	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	425
71-9056	Model: SPEC 2-T, Source Production & Equipment Co.	423	71-9127	Model: 100, 100A, 200, 200A, Gamma Industries, Inc.	425
71-9070	Model: N-55, Dept. of Energy	423	71-9128	Model: C-8, Gamma Industries, Inc.	425
71-9079	Model: HN-100 Series 2, Hittman	423	71-9132	Model: T-3, Nuclear Packaging, Inc.	425
	Nuclear & Development Corp.		71-9139	Model: 589, General Electric Co.	425
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	423	71-9143	Model: 920, Technical Operations, Inc.	425
71-9081	Model: CNS-1600, Chem-Nuclear Systems, Inc.	424	71-9145	Model: NUPAC 50-1, 5L, 2.5L, 3.0L & 4.0L, Nuclear Packaging, Inc.	425
	•		71-9147	Model: 850, Technical Operations, Inc.	425
71-9086	Model: IIN-100 Series 1. Hittman Nuclear & Development Corp.	424	71-9851	Model: Lithium Hydroxide Fire/Impact Shield, Oak Ridge National Laboratory	425
71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	424	71-9852	Model: DT-14, Dept. of Energy	425

# ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name

Docket

pag

Page

Docket

Name

Aerolest Radiography & Research Reactor	50-228	45	Browns Ferry Nuclear Power Station, Unit 3	50-296	144
Allens Creek Nuclear Station, Unit 1	50-466	361	Brunswick Steam, Electric Plant, Unit 1	50-325	20
Allens Creek Nuclear Station, Unit 2	50-467	363	Brunswick Steam Electric Plant, Unit 2	50-324	198
Arkansas Nuclear One, Unit 1	50-313	170	Byron Station, Unit 1	50-454	348
Arkansas Nuclear One, Unit 2	50-368	276	Byron Station, Unit 2	50-455	350
Duane Arnold Energy Center	50-331	218	California State Polytechnic College	50-394	307
Babcock & Wilcox Co. Critical Facility	50-13	18	Research Reactor	30-374	50,
Babcock & Wilcox Co. Test Reactor	50-99	23	Callaway Plant, Unit 1	STN-50-483	366
Bailly Generating Station	50-367	274	Callaway Plant, Unit 2	STN-50-486	369
Battelle Memorial Institute Critical Lacility	50-360	258	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	177
Beaver Valley Power Station, Unit 1	50-334	223	Calvert Cliffs Nuclear Power Plant,	50-318	180
Beaver Valley Power Station, Unit 2	50-412	322	Unit 2		
Bellefonte Nuclear Plant, Unit 1	50-438	333	Catawba Nuclear Station, Unit 1	50 <del>-1</del> 13	323
Bellefonte Nuclear Plant, Unit 2	50-439	336	Catawba Nuclear Station, Unit 2	50-414	324
Beznau Nuclear Station, Unit 1, Switzerland	50-273	104	Catholic Univ. of America Research Reactor	50-77	22
Big Rock Point Nuclear Power Plant	50-155	26	CESSAR System 80	STN-50-470	363
Black Fox Station, Unit 1	STN-50-556	401	Cherokee Nuclear Station, Unit 1	STN-50-491	372
Black Fox Station, Unit 2	STN-50-557	402	Cherokee Nuclear Station, Unit 2	STN-50-492	373
Blue Hills Station, Unit 1	50-510	383	Cherokee Nuclear Station, Unit 3	STN-50-493	374
Blue Hills Station, Unit 2	50-511	383	Clinch River Breeder Reactor	50-537	391
Braidwood Station, Unit 1	50-456	352	Clinton Power Station, Unit 1	50-461	358
Braidwood Station, Unit 2	50-457	353	Clinton Power Station, Unit 2	50-462	359
Brigham Young Univ. Research Reactor	50-262	83	Comanche Peak Steam Electric Station,	\$0-445	34
Browns Ferry Nuclear Power Station, Unit 1	50-259	73	Unit 1  Comanche Peak Steam Electric Station,	50-446	340
Browns Ferry Nuclear Power Station, Unit 2	50-260	77	Unit 2  Donald C. Cook Nuclear Power Plant, Unit 1	50-315	173

Name	Docket	Page	Name	Docket	Page
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	175	Georgia Tech Research Reactor	50-276	109
Cooper Nuclear Station	50-298	148	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	49
Crystal River Nuclear Plant, Unit 3	50-302	152	Grand Gulf Nuclear Station, Unit 1	50-416	326
Davis-Besse Nuclear Power Station, Unit 1	50-346	242	Grand Gulf Nuclear Station, Unit 2	50-417	328
Davis-Besse Nuclear Power Station,	50-500	380	Greenwood Energy Center, Unit 2	50-452	348
Unit 2			Greenwood Energy Center, Unit 3	50-453	348
Davis-Besse Nuclear Power Station, Unit 3	50-501	380	Haddam Neck Plant	50-213	37
Diablo Canyon Nuclear Power Plant, Unit I	50-275	105	Shearon Harris Nuclear Power Plant, Unit 1	50-400	313
Diablo Canyon Nuclear Power Plant. Unit 2	50-323	193	Shearon Harris Nuclear Power Plant, Unit 2	50-401	314
Douglas Point Nuclear Station, Unit 1	50-448	348	Shearon Harris Nuclear Power Plant, Unit 3	50-402	315
Douglas Point Nuclear Station, Unit 2	50-449	348	Shearon Harris Nuclear Power Plant,	50-403	316
Dow Chemical Co.	50-264	86	Unit 4	0001 40 410	9.5
Dresden Nuclear Power Station, Unit 1	50-10	15	Hartsville Nuclear Plant, Unit 1	STN-50-518	385
Dresden Nuclear Power Station, Unit 2	50-237	45	Hartsville Nuclear Plant, Unit 2	STN-50-519	386
Dresden Nuclear Power Station, Unit 3	50-249	58	Hartsville Nuclear Plant, Unit 3	STN-50-520	387
oseph M. Farley Nuclear Plant, Unit 1	50-348	245	Hartsville Nuclear Plant, Unit 4	STN-50-521	389
oseph M. Farley Nuclear Plant, Unit 2	50-364	268	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	189
Enrico Fermi Atomic Power Plant, Unit 2	50-341	238	Edwin I. Hatch Nuclear Plant, Unit 2  Haven Nuclear Plant, Unit 1	50-366 STN-50-502	27° 380
James A. Fitzpatrick Nuclear Power Plant	50-333	220	Haven Nuclear Plant, Unit 2	STN-50-503	380
Floating Nuclear Plant	STN-50-437	333	Hope Creek Nuclear Station, Unit 1	50-354	25
Forked River Nuclear Station, Unit 1	50-363	268	Hope Creek Nuclear Station, Unit 2	50-355	25
Fort Calhoun Station, Unit 1	50-285	120	Humboldt Bay Power Plant, Unit 3	50-133	2-
	50-267	90	Idaho State Univ. Research Reactor	50-284	12
	50-463	360	Indian Point Station, Unit 1	50-3	1
	50-464	361	Indian Point Station, Unit 2	50-247	5
			Indian Point Station, Unit 3	50-286	12
	50-89	23	Iowa State Univ. Research Reactor	50-116	2
	50-163	30	Jamesport Nuclear Station, Unit 1	STN-50-516	38
	50-73	22	Jamesport Nuclear Station, Unit 2	STN-50-517	38
	50-70	21	Kansas State Univ. Research Reactor	50-188	3
	50-160	30			

50-160

30

Kewaunee Nuclear Power Plant

50-305

15

Name	Docket	Page	Name	Docket	Pag
La Crosse Boiling Water Reactor	50-409	318	North Anna Power Station, Unit 3	50-404	311
LaSalle County Station, Unit I	50-373	285	North Anna Power Station, Unit 4	50-405	318
LaSalle County Station, Unit 2	50-374	288	North Carolina State Univ. PULSTAR	50-297	148
Limerick Generating Station, Unit 1	50-352	247	Reactor	60.111	2.1
Limerick Generating Station, Unit 2	50-353	250	North Carolina State Univ. Research Reactor		23
Maine Yankee Atomic Power Plant	\$0-309	162	North Coast Nuclear Plant, Puerto Rico	50-376	290
Marble Hill Nuclear Station, Unit 1	STN-50-546	397	Nuclear Examination Reactor	50-375	290
Marble Hill Nuclear Station, Unit 2	STN-50-547	398	Nuclear Fuels Recovery & Recycle Center	50-564	402
Massachusetts Institute of Technology	50-20	18	Oconee Nuclear Station, Unit 1	50-269	93
Research Reactor			Oconee Nuclear Station, Unit 2	50-270	96
William B. McGuire Nuclear Station, Unit 1	50-369	278	Oconee Nuclear Station, Unit 3	50-287	1 25
William B. McGuire Nuclear Station,	50-370	283	Ohio State Univ. Research Reactor	50-150	26
Unit 2			Omaha Veterans Administration Hospital Research Reactor	50-131	24
Memphis State Univ. Research Reactor	50-538	397	Oregon State Univ.	50-106	23
Michigan State Univ. Research Reactor	50-294	141	Oregon State Univ. Research Reactor	50-243	49
Midland Plant, Unit 1	50-329	212	V	50-219	39
Midland Plant, Unit 2	50-330	215	Oyster Creek Nuclear Power Plant		
Millstone Nuclear Power Station,	50-245	52	Palisades Nuclear Plant	50-255	70
Unit I			Palo Verde Nuclear Station, Unit 1	STN-50-528	390
Milistone Nuclear Power Station, Unit 2	\$0.336	229	Palo Verde Nuclear Station, Unit 2	STN-50-529	392
Millstone Nuclear Power Station,	50-423	330	Palo Verde Nuclear Station, Unit 3	STN-50-530	394
Unit 3			Palo Verde Nuclear Station, Unit 4	STN-50-592	404
Montague Nuclear Power Station, Unit 1	50-496	374	Palo Verde Nuclear Station, Unit 5	STN-50-593	404
Montague Nuclear Power Station, Unit 2	50-497	374	Peach Bottom Atomic Power Station, Unit 1	50-171	30
Monticello Nuclear Generating Plant	50-263	83	Peach Bottom Atomic Power Station,	50-277	10
National Bureau of Standards Reactor	50-184	31	Unit 2		
National Naval Medical Center	50-170	30	Peach Bottom Atomic Power Station, Unit 3	50-278	1 <b>1</b>
New Haven, Unit 1	50-596	404	Pubble Springs Nuclear Plant, Unit 1	50-514	384
New Haven, Unit 2	50-597	404	Pebble Springs Nuclear Plant, Unit 2	50-515	38:
Nine Mile Point Nuclear Station. Unit 1	50-220	42	Pennsylvania State Univ. Research Reactor	50.5	1:
Nine Mile Point Nuclear Station, Unit 2	50-410	321	Perkins Nuclear Station, Unit 1	STN-50-488	37
North Anna Power Station, Unit 1	50-338	231	Perkins Nuclear Station, Unit 2	STN-50-489	37
North Anna Power Station, Unit 2	50-339	234	Perkins Nuclear Station, Unit 3	STN-50-490	37

Nome	Daylar	n.	M-		b
Name	Docket	Page	Name	Docket	Page 205
Perry Nuclear Power Plant, Unit 1	\$0-440	338	Sequoyalı Nuclear Plant, Unit 1	50-327	
Perry Nuclear Power Plant, Unit 2	50-441	339	Sequoyah Nuclear Plant, Unit 2	50-328	209
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	400	Shoreham Nuclear Power Station	50-322	192
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	401	Skagit Nuclear Power Project, Unit I	STN-50-522	390
Pilgrim Nuclear Power Station, Unit 1	50-293	139	Skagit Nuclear Power Project, Unit 2	STN-50-523	390
Pilgrim Nuclear Power Station, Unit 2	50-471	363	South Texas Project, Unit 1	STN-50-498	375
Pilgrim Nuclear Power Station, Unit 3	50-472	364	South Texas Project, Unit 2	STN-50-499	377
Plum Brook Reactor - Mock-Up	50-185	31	Space Radiation Research Reactor	50-187	32
Plum Brook Research Reactor Facility	50-30	20	Stanford Univ. Research Reactor	50-141	25
Point Beach Nuclear Plant, Unit 1	50-266	88	State Univ. of New York Research Reactor	50-57	21
Point Beach Nuclear Plant, Unit 2	\$0-301	150	Sterling Power Project, Nuclear,	STN-50-485	368
Prairie Island Nuclear Station, Unit 1	50-282	118	Unit 1		
Prairie Island Nuclear Station, Unit 2	50-306	160	St. Lucie Plant, Unit 1	50-335	227
Purdue Univ. Research Reactor	50-182	31	St. Lucie Plant, Unit 2	50-389	301
Quad-Cities Station, Unit 1	50-254	68	Virgit C. Summer Nuclear Station, Unit 1	50-395	307
Quad-Cities Station, Unit 2	50-265	86	Summit Nuclear Power Station, Unit 1	50-450	348
Rancho Seco Nuclear Generating Station	50-312	166	Summit Nuclear Power Station, Unit 2	50-451	348
Reed College Research Reactor	50-288	128	Sundesert, Unit 2	50-583	403
Rhode Island & Providence	50-193	33	Surry Power Station, Unit 1	50-280	113
Plantations AEC			Surry Power Station, Unit 2	50-281	116
River Bend Station, Unit 1	50-458	354	Susquehanna Steam Electric Station, Unit 1	50-387	293
River Bend Station, Unit 2	50-459	356		- 0 000	20-
H.B. Robinson Plant, Unit 2	50-261	80	Susquehanna Steam Electric Station, Unit 2	50-388	297
Rockwell International Research Reactor	50-94	23	Texas A&M Univ. Research Reactor	50-59	21
RPI Critical Experiment	50-225	45	Texas A&M Univ. Research Reactor	50-128	24
Salem Nuclear Generating Station, Unit 1	50-272	101	Three Mile Island Nuclear Station, Unit 1	50-289	128
Salem Nuclear Generating Station, Unit 2	50-311	164	Three Mile Island Nuclear Station, Unit 2	50-320	183
San Onofre Nuclear Station, Unit 1	50-206	33	TRIGA Mark II, Pool-Type Reactor	50-579	403
San Onofre Nuclear Station, Unit 2	50-361	258	Trojan Nuclear Plant	50-344	239
San Onofre Nuclear Station, Unit 3	50-362	263	Turkey Point Plant, Unit 3	50-250	61
Santillan Nuclear Power Station, Spain	50-578	403	Turkey Point Plant, Unit 4	50-251	64
Seabrook Nuclear Station, Unit 1	50-443	<b>3</b> 41	Tuskegee Institute Research Reactor	50-406	318
Scabrook Nuclear Station, Unit 2	50-444	342	Tyrone Energy Park, Unit I	STN-50-484	368

Name	Docket	Page	Name	Docket	Page
UCLA Training Reactor	50-142	25	Vallecitos Experimental Superheat Reactor	50-183	31
Union Carbide Research Reactor	50-54	21	Vermont Yankee Nuclear Power Station	50-271	98
Univ. of Arizona Research Reactor	50-113	23	Virginia Polytechnic Institute Training	50-124	24
Univ. of California at Irvine Research Reactor	50-326	205	Reactor		
Univ. of California at Santa Barbara	50-433	333	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	331
Research Reactor	30-433	223	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	332
Univ. of California Research Reactor	50-224	45	Washington State Univ. Research Reactor	50-27	18
Univ. of Florida Training Reactor	50-83	22	Waterford Generating Station, Unit 3	50-382	290
Univ. of Illinois LOPRA Research Reactor	50-356	255	Watts Bar Nuclear Plant, Unit 1	50-390	303
Univ. of Illinois Research Reactor	50-151	26	Watts Bar Nuclear Plant, Unit 2	50-391	305
Univ. of Kansas Research Reactor	50-148	26	Westinghouse Critical Experiment	50-87	23
Univ. of Lowell Research Reactor	50-223	45	West Valley Reprocessing Plant	50-201	33
Univ. of Michigan Research Reactor	50-2	14	West Virginia Univ. Research Reactor	50-129	24
Univ. of Missouri Research Reactor	50-123	24	Wolf Creek Generating Station	STN-50-482	364
Univ. of Missouri Research Reactor	50-186	31	WPPSS Nuclear Project, Unit 1	50-460	357
Univ. of New Mexico Research Reactor	50-252	68	WPPSS Nuclear Project, Unit 2	50-397	311
Univ. of Oklahoma Research Reactor	50-112	23	WPPSS Nuclear Project, Unit 3	STN-50-508	381
Univ. of Texas Research Reactor	50-192	32	WPPSS Nuclear Project, Unit 4	50-513	38 <b>3</b>
Univ. of Utah Research Reactor	50-72	22	WPPSS Nuclear Project, Unit 5	STN-50-509	382
Univ. of Utah Research Reactor	50-407	318	Yankee Atomic Power Reactor	50-34	21
Univ. of Virginia Cavalier Reactor	50-396	311	Yankee-Rowe Nuclear Power Station	50-29	18
Univ. of Virginia Research Reactor	50-62	21	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	402
Univ. of Washington Research Reactor	50-139	25	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	403
Univ. of Wisconsin Research Reactor	50-156	30	William H. Zimmer Nuclear Station, Unit 1	50-358	256
U.S. Geological Survey Research Reactor	50-274	105	Zion Nuclear Power Station, Unit 1	50-295	141
Vallecitos Boiling Water Reactor	50-18	18	Zion Nuclear Power Station, Unit 2	50-304	155



## **DOCKETED ITEMS**

#### LOW LEVEL RADWASTE DISPOSAL SITES

- DOCKET 27-039 SHEFFIELD. IL. NUCLEAR ENGINEERING CO
- 8103030395 Forwards UB Ecology proposals for recompacting & recovering tranches above base of sisting caps
  COMMER.T B Miller & Chevalier B1/02/10 2pg 07790 024
- 8103050849 Discusses B10216 tolcon w/EU Reis re arrangements to examine NRC documents & to schedule meeting to discuss closure conditions in accordance w/prehearing conference CDMER.T.B Conner. Hoore & Corber. 81/02/23 200. 07828 168
- 8103200714 Motion to clarify & reconsider in part ABLB 810225 prehearing conference order & order ruling on discovery requests, objections & motions Alternately request questions be referred to Commission W/Certificate of Svc. CHABNOFF, B A , FAHNER, T. C. Illinois, State of 81/03/09 8pp. 02970 007
- Bi03200707 Motion for clarification of prehearing conference order & ruling on discovery requests; objections & motions Order should not be construed to require UB Ecology to produce proprietary or privileged documents, U/Certificate of Svc CCNNER.T.B., RADER.R.M. UB Ecology, inc. (Formerly Nuclear Engineering) CONNER.T B Conner, Hoore & Corber. 81/03/10 [2pp
- BiO3260912 Advises that only Procedure 0-004 & Section 4.0 of geology & geotechnical engineering rept on trenches 14 & 14A be considered proprietary per 761287-30 & 770907 Itrs. Requests justification for other mati being proprietary.

  IMAMINS F Low Level Waste Licensing Branch. Bi/03/II 2pp. 08037-204.
- --Bi03260522 Forwards revised application for withholding info from public disclosure & accompanying affidavit per 761221 meeting & 761228 for Revision modifies 761124 application. MURR.P. H. US Ecology, Inc. (Formarly Nuclear Engineering) 76/12/29 12pp 08037:206
- --B103260530 Forwards JN Neel 761228 ltr confirming understandings reached at 761221 meeting w/NRC re application to amend usage of low level radwaste disposal trenches 14 & 14A. EABCN.C.F. US Ecology, Inc. (Formerly Nuclear Engineering), 76/12/30, 1p. 08037:218.
- --8103260537 Confirms understandings reached at 761221 meeting reproprietary info contained in application to amond usage of law level redwaste disposal trenches 14 b 14A.

  81NOERS. Bivision of Fuel Cycle & Material Safety 76/12/28
  2pp. 08037:219.
- Bi03270502 Forwards revised Page 8 to U8 Ecology 810310 motion for clarification Line inedvertently emitted from original submission.

  RADER, R. M. Conner, Moore & Corber, 81/03/13, 1p. 08034:132.
- --BI03270507 Revised Page 5 to motion for clarification • UB Ecology, Inc. (Formerly Nuclear Engineering). BI/03/13. Ip. 08034: 133
- BiO3i70340 Forwards list of technical documents in NRC files in Willste Bidg in Bilver Spring, MD per 610309 telcon file files will be searched on 810324 & 25.Louisville.KY ofc file search to be conducted on 810414 & 15.H/o encl.
  MCGURREN.H.J. Hearing Branch i. 81/03/16. 2pp. 07924:033.
- 8103170513 Response to US Ecology 901010 & 24 requests for admissions, interrogatories & requests for production of documents. Requests for admissions denied.

  MCGURREN, H. J. Hearing Branch 1. 81/03/16. 19pp. 07930; 249.

- --8103170519 Discusses 801112 telcon Survey & map made from two penchmants which are file mants on inside of well casings FRANKLING R. Randolph Associates, inc. 80/11/14 | p
- --Bi03170524 Forwards 801128 trip rept on B01014-15 site visit re observation & comments on surface conditions in specified areas of site SIEFKEN. 0 L., BHAFFNER. J. A. Low Level Waste Litensing Branch 80/11/28 ip
- ~~8103170532 IE Insp Rept 27-0039/80-02 on 801022 No noncompliance Major areas inspected drainage & erosion at site. J Shaffner efficavit & Certificate of Svc encl LANDSMAY.R . GRANT.W . PAPERIECLO.C. J Region 3. Chicago. Off of the Director 80/11/12 App.
- B103230671 State of IL second response to interrogatories from Chi Section.AMS.per ASLB B10226 order. Involves identification of documents relied upon for preparation of position on license termination Affidavit encl Related correspondence AMSPACH.K 0. FAHKER.T C litinois, State of. 81/03/16 14pp 07973-338
- 8103230724 Second response to US Ecology request for admissions, interrogatories & production of documents.per ASL8 810226 order. Documents available upon request Affidavit & Certificate of Svc enci ANSPACH.K 9 . FAHNER.T C | Illinois, State of. 81/03/16 24pp
  - 07974.126
- B103260739 Answers to NRC first set of interrogatories & request & production of documents Certificate of Svc encl Related correspondence
  BAER.T B UB Ecology. Inc (Formerly Nuclear Engineering). Q1/C 10pp. 08035.394
- 8103260743 Answers to State of IL first set of interrogatories re Nuclear Engineering Co & Teledyne Inc relationship decision to abanden facility, decommissioning costs & maint of facility Certificate of Svc encl. Related correspondence. BAER-T.S. US Ecology. Inc (Formerly Nuclear Engineering). 81/6 210p. 08036-002
- 8103270599 Response in opposition to State of IL 810309 motion to clarify 810225 prehearing conference order. Order clearly dismissed interrogatories 55.96 & 82 as irrelevant & calling for speculation. Certificate of 80c encl.

  CONNER.T.B. RADER.R.M. UB Ecology: Inc. (Formerly Nuclear Engineering). CONNER.T.B. Conner. Moore & Corber. 81/03/25 08034-061
- 8103020587 County of Bureau answers to Nuclear Engineering Cointerrogatories Notice of withdrawal of appearance in proceeding notice of appearance in proceeding & Certificate of Svc encl Related correspondence. OURNING.B. H. [11]thois. Bate of. BI/02/12 9pp. 07782.065.
- DOCKET 27-043 PEEKSKILL, NY. NUCLEAR DIAGNOSTIC LABORATORIES
- 8103180864 Comments on NUREQ-0693 re draft programmatic EIB for decontamination & disposal of raduasts from THI-2 accident. Buggests raduastes be entombed in THI-2 containment. Prof papers encl.

  BR088-1.0. Roswell Park Manorial Institute. 80/09/05. 29pp. 07944:272
- --Bi03180880 Comments on "Draft EIS. Nest Vailey Liquid High Level Naste Immobilization Project (WVLHLNIP) " BROSS, I. D. Roswell Perk Memorial Institute, 80/02/02, 20pp 07944:335.

DOCAET 27-047 BARNWELL, SC. CHEM-NUCLEAR BYSTEMS, INC.

- B1052905:4 Forwards IE Waste Packaging Insp Rept 1500039/81-01 on B101:5-16 to noncompliance noted. STOHR.JP Region 2. Atlanta. Fuel Facility & Materials Safety Branch 81/02/13 1p 07996 239
- ---Bi09250624 IE Waste Packaging Insp Rept 1500039/81-01 on Bi0115-16.No noncompliance noted Major areas inspected licensee-shipper vehicle for compliance/JOD & hqC regulations, including shipping paper & DOT placerding requirements MACARTHUR, T.C., POTTERLY P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 81/02/09, 5pp 07996-240.
- 8:00270809 Act receipt of 810213 ltr informing NRC of steps taken to correct violations noted in 16 Maste Packaging Insp Rept 50-333/80-24 (15000034/80-21) Item of moncompliance cited in 310115 ltr ulli te withdraun SMITH-0 H Region I. Philadelphia, Fuel Facility & Materials Safety Branck 81/02/20 lp 08034 119.
- --0103270915 Responds to NRC BiJ115 ltr re violations noted in IE Waste Packaging Insp Rept 50-333/80-24 (15000034/80-21) Corrective actions obtaining photographic records of each waste shipment showing vehicle tractor & trailer numbers PASIERNAM.R J Power Authority of the State of New York 81/02/13. 350 08034 120
- --6103270921 Forwards IE Waste Packaging Insp Rept 50-333/80-24 (1500039/80-21) on 801106 & notice of violation SMITH.O.H Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 81/01/15 2pp. 08034 123.
- --B103270B26 Notice of violation from insp on B01106.

   Region 1. Philadelphia. Office of the Director B0/12/02. 1p.
- --9103270832 IE Waste Packaging Insp Rept 30-333/80-24 (18000034/80-21) on 801106 Noncompliance noted one shipment of radioactive nat1 arrived at burial site w/o prescribed placard on front of tractor or front of trailer.

  MACARTHUR. Y.C. Region 1. Philadelphia. Office of the Director. FOTTER. J.P. Region 1. Philadelphia. Fuel Facility & Materials 8afety 3ranch 80/12/02 4pp 08034 126
- B103260141 IE Waite Parkaging Imp Rept 19-00039/81-02 on 910209-13 No noncompliance noted 01080NAF Region 2. Atlanta. Office of the Birector. B1/03/06 19 08041 283.
- --BI03260157 IE Waste Packaging Insp Rept 15-00039/BI-02 on 810209-13 No noncompliance noted Major areas inspected compliance w/DOT & NRC regulations including shipping paper & DOT placerding requirements radiation level & rerovable contamination MACARTHUR, T C, PEERV. W M Region 2. Atlanta, Fuel Facility & Materials Safoty Branch. 81/03/04 6pp C8041 284
- DOCKET 27-048 RICHLAND, WA. NUCLEAR ENGINEERING CD . INC.
- B103290136 For Jards IE Waste Packaging Insp Rept 15000046/80-98 Advises that breach of package integrity essociated wradioactive matis shipment originating at facility was found No response required BDDA.H E. Region 5. San Francisco, Fuel Facility & Materials Bafety Branch B1/02/24 2pp
- --B103250144 1E Waste Pactaging Insp Rept 15000046/80-98 on B01215 Noncompliance noted drum found to have loose lock ring Region 5. State of MA & DDT are to take enforcement actions. ZURAKDESKI, P. R. Region 5. San Francisco. Office of the Director THOMAS, R. D., BOOK, H. E. Region 5. San Francisco, Fuel Facility & Material's Safety Breach. Bi/Ol/20. Spp

## DOMESTIC LICENSING OF SOURCE MATERIAL

DECKET 40-0086 W.R. GRACE & CO.

8103100150 Responds to 810120 telephone inquiry requesting cooperation whinfo request from D Waks of Wayne. NJ re facility NRC will conduct radiation survey of grounds during us of 810126. Requests most recent radiation survey KINNEMAN. J. D. Region 1. Philadelphia. Evel Facility & Materials Bafety Branch. 81/01/26 12. 07865-357.

DOCKET 40-0229 UNION CARBIDE CORP.

- BiO2260479 Partial response to FOIA request for all documents re fi categories of info concerning U mills in UT.NM.AZ.CO & MY Forwards Documents 1-17 listed in app Document 18 may be citained from NTIS FELTCY.J M Division of Rules and Records 81/02/05 2pp
- --BI02260338 Requests specific review & rept re-tailings discharge operations due to occurrences of release of tailings matl from impoundment sys Rept should include description of physical condition of embankment sys Related info encl. ROUSELL C Fuel Process & Fab. Branch (Pre 790727) 27/05/04/760
- B103310609 Forwards table entitled "Locations & Specs for Monitor Hells." per License Condition SB Also forwards one oversize drawing prawing available in Central Files only WONG. T. Union Carbide Corp. Metals Div. 81/03/25 Jpp. 08062
- COCKET 40-0299 UNION CARBIDE CORP.
- B103110325 Discusses site visits to Union Carbide & Split Rock mil nines Incremental impacts resulting from abandoned heaps seem (neignificant. BEBKID.N J Argonne National Laboratory 79/07/27. 2pp 07904145
- 8103110315 Discusses maths submitted by Union Carbide Corp re tail disposal project at Oas Hills operation. Alternative VII considered sound tailings mpt alternative. Groundwater mound formation up to pit bottom is fairly certain.

  NELSCH. J. D. Colprado State Univ. 79/10/05 2pp 07684:147
- B103160333 Comments on licensee specs for placement of compacted c inner at Pit A-9 Permeability tests should be initiated on representative samples using raffinate or tailings water NELSDN, J.D. Colorado State Univ. 79/10/10. ip. 07916:083
- Bi03160327 Discusses 791113 site visit to facility re-clay liner of bottom of Pit A-9 & underdrain systicenses should present grain size distribution curves of matla used in constitution show how closely filter criteria was net NELBON. J. D. Colorado State Univ. 79/12/04 7pp. 07916:032
- BiO310334 Forwards filter criteria for matls used in drain for A-C pit Filter criteria have been not marginally RELEGIA D Colorado State Univ. 79/12/26 6pp. 07875.339
- 8103020785 Notifies of environ monitoring program mod.in response licensee Bioli4 5 15 requests Requirements deleted re air particulate monitoring as onsite houses & sampling of monitor Hells 3.8 & 35. KOTBCH.J.L. Uranium Recovery Licensing Branch. Bi/02/11 2pp. 07782 137
- B1031601B7 Discusses review of IE B00522-23 insp of facility No licensing action is necessary on basis of review. KGTBCH.J.L. Uranium Recovery Licensing Branch B1/03/03 [p. 07918-318
- 8103200111 Advises that now literate application fee will be require rather than amend fee originally requested. H/o encl. ME185.D. License Fee Hanagement Branch 81/03/04 pp. 07972-
- 8103120792 Forwards safety evaluation supporting License SUA-648 renewal for Union Carbide Corp Gas Hills Mill MOTSCH-J L. Granium Recovery Licensing Branch. 81/03/05. ip. 07903-280.
- --BIO3120797 Safety evaluation supporting License BUA-648 renewal a Union Carbida Corp Gas Hills Hill. HOOLBEY, R. T., PETTENOILL, H.J. Uranium Recovery Licensing Brant BI/03/04. 50pp 07903:281.
- 8103181104 Forwards safety evaluation to renewal of License SUA-646 M/g enc! PETTENGILL,H J. Uranium Recovery Licensing Branch. 81/03/10. 9 07954-153
- 8103181112 Informs that NRC is issuing Amend 2 to License 8UA-648 / corrects editorial error in elisting Condition 18 re-radiological safety insp. SCARAND, R A Uranium Recovery Licensing Branch. 81/03/10. 2pp. 07994-151.

DOCKET 40-0341 DENERAL BERVICES ADMIN . FED. PROP RESOURCES SERVICES

- 8103040480 Forwards regulations past & present licenses & site plan re licensed activities of Maywood Chemical Horks & Stepan Chemical Co. Regulations not encl. KINNEMAN.J.D. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 81/01/29 ip
- --Bi03040539 License authorizing underground storage of source matl by Stepan Chemical Co Bite plan encl. BASSIN.N Radio(sotopes Licensing Branch (Pre 790301) 78/04/04
- DOCKET 40-0659 GENERAL ELECTRIC CO. . AIRCRAFT ENGINE GROUP
- 0103160350 Discusses IE safety insp of Licenses 34-00497-10 & 818-53 on 810119 & 20 & forwards notice of violation. FIBHER.W L. Region 3. Chicago. Fuel Facility & Materials Safety Branch 81/02/12 1p 07922 057
- --Bi03160368 Notice of violation from insp on Bi0119 & 20 Noncompliance noted: failure to post machining & waste storage areas possessing emounts of licensed math above those specified & radiation survey meters not calibr every 70 days FISHER.M.L. Region 4. Dalles. Fuel Facility & Materials Bafoty Branch. Bi/02/10 ip 07928:058
- 810326001B Ack receipt of 810302 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 34-00499-10 & 8TB-93 GRENIANSKI.B. J. Region 3. Chicago. Office of the Director 81/03/16. 1p. 08041:127.
- ---Bi03260021 Responds to NRC 819212 ltr re violations noted in IE insp of Licenses 34-00499-10 & BTB-53 corrective actions: signs posted in waste storage area & matching area & radiation neters calibr Quarterly audit form and.

  ENGEL J. D. General Electric Co. 81/03/02 3pp. 08041.128.

#### DOCKET 40-0672 NUCLEAR METALS. INC.

- 8103050239 Discusses IE insp on 801120 & forwards notice of violation & imposition of civil penalty STELLO.V. Director's Office Office of Inspection and Enforcement. 81702726. 2pp. 07825:239
- ---Bi03050248 Notice of violation & imposition of civil penalty in amount of \$5,000 for item of noncompliance re delivery of radioactive mat) to carrier in package that was not strong & tight resulting in leakage as noted in IE imap on 801120 BTELLO.V. Director's Office, Office of Inspection and Enforcement, 81702726 2pp. 07025,241.

#### DOCKET 40-1162 WEBTERN NUCLEAR. INC.

- B103060119 Forwards pleiometer summary sheet per 800623 request. B00DEN.0. Western Nuclear: Inc. (subs. of Phelps Dodge Corp.). 80/06/23. 2pp. 07839:037.
- BiO2260479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NN.AZ.CO & HY. Forwards Documents 1-17 listed in app. Document IB may be obtained from NTIS.

  FELTON, U.M. Division of Rules and Records. Bi/02/05. 2pp. 07760, 229.
- --B102260329 Accepts Option I presented in 770420 engineering rept as interim remedial action for tailings retention sys.

  Authorizes continued operation of mill under License SUA-36 until 770930 under listed condition.

  ROUSE, L. C. Puel Process. & Fab. Branch (Pre 790727). 77/04/22.
  2pp.
- --Bi02260533 Forwards itr sent to licensee re 770412 discovery of break in mill teilings earthen retention dam at Western Nuclear, Inc U mill at Jeffrey City, WY. Mill is presently shut down for cleanup & repair. KERR. O. M. Assistant Director for State Agreements Programs. 77704/25. 1p.

- 810309004B Forwards "Subsurface Resistivity Study in Vicinity of Western Nuclear Mill." final rept.partially Pulfilling Condition 23 of License 50A-56.
  BDODEN.G "Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 81702709. 10 07849 296
- --BIO3090099 "Subsurface Resistivity Study in Vicinity of Western Mills" final rept prepared for D'Appolonia Consulting Engineers.Inc.
  KELLER.O.V. BODE.R M. STOYER.C H. Colorado School of Mines BI/01/31 1050: 07849 297.
- 8103060794 Discusses review of nuclear tailings dam inspirept for 801110-16 Results of EPC of Nuclear Reactor Regulation review will be contained in safety evaluation Pollowing resolution of concerns to lifts at tailings dam GARCIA-P J. Uranium Recovery Licensing Branch. 81/02/12. ip. 07834-119
- B103060797 Discusses review of nuclear tailings dem inspirept for 801117-23 Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns relifts at tailings dam GARCIA-P J. Uranium Recovery Licensing Branch. 81/02/12. 1p.07836-120
- 8103060800 Discusses review of nuclear tailings dan inspirept for 801124-30 Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns relifts at tailings dam GARCIA-P. U. Uranium Recovery Licensing Branch 81/02/12 1p 07836 121.
- 8103060804 Discusses review of nuclear tailings dam inspirest for 801215-21 Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns re lifts at tailings dam OARCIA.P. J. Uranium Recovery Licensing Branch 81/02/12. 1p 07036-122
- Bi03060807 Discusses review of nuclear teilings dam inspirent for 801222-28 Results of Ofc of Nuclear Reactor Regulation review will be contained in sefety evaluation following resolution of concerns relifts at teilings dam GARCIA-P J Uranium Recovery Licensing Branch 81/02/12 lp 07836-123.
- 8103060810 Discusses review of nuclear teilings dam insp rept for 801229-810104 Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns re lifts at teilings dam QARCIA.P. J. Urenium Recovery Licensing Branch. 81/02/12 ip. 07836-124
- 8103060812 Discusses review of nuclear tailings dam inep rept for 610105-11. Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns re lifts at tailings dam OARCIA.P. J. Uranium Recovery Licensing Branch. 81/02/12. 1p. 07836-125
- 8103050813 Discusses review of nuclear tailings dam inspirept for 810f12-18. Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns relifts at tailings dam QARCIA-PU. Uranium Recovery Licensing Branch. 81/02/12 ip. 07836-126.
- 8103060815 Discusses review of nuclear tailings dam inspirent for 801103-09 Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns relifts at tailings dam OARCIA.P.J. Uranium Recovery Licensing Branch. 81/02/12. 1p. 07836-127
- 8103060819 Discusses review of nuclear tailings dam inep rept for 801201-07. Results of Ofc of Nuclear Reactor Regulation review will be contained in safety evaluation following resolution of concerns re lifts at tailings dam GARCIA-P. J. Uranium Recovery Licensing Branch. 81/02/12 1p. 07836-128.
- 8103050459 Forwards two oversize drawings re tailings flow instrumentation. Aperture cards in PDR. BGODEN.O. Mestern Nuclear, Inc. (subs. of Phalps Dodge Corp.) 81/02/13. 2pp. 07830:001.

- 8103110834 Forwards historical & archeological review of Western 103110834 Forwards historical & archeological review of Wei hurlear Inc split rock to mill tailing pond expansion proposal Forther work indicated before cultural clearance recommended by My State Historic Preservation Officer. THEOPERING WESTING State Miscoric Preservation Utricer.
  JUNIER N. O. Westing, State of 81/02/18 4op. 07873 328.
- 6103160241 Forustés mill tailings dam inspirept for 810202-08 8305EM.0 Western Muclear. Inc. (subs. of Phelps Dodge Corp.) 81702/24 4pp 07918 384
- 8103250559 Forwards Split Rock oill tailings dan inspirept.810216-22 8090EN.3 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 81/02/25. 359 08022 137
- BIO3250565 Forwards Split Rock mill tailings der inspirept.BIO309-19. BC9DEN-9 Western Nuclear. Inc. (subs. of Phelps Dodge Corp.) BI/02/29 App. 08022.133
- B103259743 Requests changes in due dates for subrittals required by License Conditions 26 & 45 to B10401 Agrees that annual review date would be applicable to License Conditions 16.31
- 8 40 & 40. BODDEN.G. Western Nuclear. Inc. (subs. of Phelps Dodge Corp.) BIJO2/25 ip 08000 Di9
- 8103120716 Surmary of BiDi30 meeting t/Meetern Nuclear Inc & Energy Fuels Nuclear in Silver Spring-MD re reclamation of Day-toma heap leach site. GARCIA.P J. Uranium Recovery Licensing Branch. 81/02/26 3pp
- 8103260006 Supple 810225 1tr Requests extension of 4 months for completion of License Condition 33 requirements re-site

07918-338

- cleasus
- 8103261213 Advises that control air sampling station will be located 5 sumedictal nevisors that tuneral are sampling station unit be i miles west of millette at Oraham Ranch where electricity is available & will meet anvison monitoring program EOCDEN.G Mestern Nuclear, Inc. (subs. of Phelps Dodge Corp.). 81/02/27 to 08040-251.
- B103160231 Cornents on Region & 800714-15 insp rept of operations at mills Inspectors adequately inspected mill operations addressed in existing license No licensing action is
- necessary GARCIA.P.J., PETTENGILL.H.J. Uranium Recovery Licensing Branch. 81/03/04 2pp 07918-352
- 8103160218 Forwards WY State Historic Preservation of comments re company rept. "Burnary Historical & Archeological Situation Repts Tailings Disposal Bites Jeffrey City Mill " PETTENSILL. H.J. Uranium Recovery Licensing Branch. 81/03/09 lp
- B103270153 Forwards State of MY water quality insp rept for Green Mountain IX facility BOOKEN, O Western Nuclear, Inc. (subs. of Phalps Dodge Corp.) 81/03/10 Bop
- 8103270123 Forwards Split Rock Mill tailings dam insp rept for
- 80-20E018 803DEM, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 81/03/11 App.
- 8103270036 Summary of Bi0123 mpeting w/Western Nuclear-Inc in Silver Spring-MD re license conditions. OARCIA-P.J. Uranium Recovery Licensing Branch. 81/03/13 13pp.
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC.
- BiO312062: Requests extension until BiO331 ms technical assistance contract for Edge-out tailings agt evaluation. MARTIN. J D. Division of Waste Management. FIN B-6994-0. BI/OI/O6 07901:238
- 8103110809 Forwards summary discussion of big game wildlife utilization of Edgemont Jacomnissioning project preferred & alternate disposal sites HILLS, L. M. Ternessee Valley Authority, 81/02/23 3pp.
- 3103170180 Responds to FDIA request for all written legal opinions & subsequent documents re NRC role in control of offsite tailings locations & whether NRC has authority to order cleanup of locations forwards documents listed in app. FELTON J.N. Division of Rules and Records. 81/02/23. 2pp.

- --8103170197 Requests legal opinion re U mill tailings in locations au from licensed U recovery facility sites named U . Office of Nuclear Material Safety & Safequards, Director 80/02/28. 20p
- 8103180280 Forwards "Semiannual Effluent Release Rept 11, Jul-Dec 1980. MILLS-L H Tennessee Valley Authority. B1/02/27 1p. 07944:065
- --BIODIBO287 "Berlannual Effluent Release Rept 11. Jul-Dec 1980 "
  a Tannessee Valley Authority. 81/02/28. 9pp. 07944:066
- DOCKET 40-1947 STEPAN CHEMICAL CO.
- 8103040480 Forwards regulations past & present licenses & site plan r licensed activities of Maywood Chemical Horks & Stepan Chemical Co. Regulations not entl. unwhice: to regulations not end.
  KinnCHAN.J D. Region 1, Philadelphia. Fuel Facility & Materials
  Sefety Branch. B1/01/29. 1p.
- --8103040493 License authorizing possession of & title to raw source & transfer of matl to licensed person within limits of license by Maywood Chemical Worts.

  J3HNSQN: 4. Atomic Energy Commission 54/04/01 1p.
- --8103040499 License authorizing possession of & title to naw source & transfer of meti to licensed person within limits of license by Maywood Chemical Works
  JOHNSON, L. Atomic Energy Commission. 56/11/19. 2pp
- --0103040528 License authorizing possession & use of source mat) for decontamination, storage & resale only by Stepan Chemical Co. NUSBRAUMER, D. A. Atomic Energy Commission. 64/06/26. Ip
- --8103040532 License authorizing possession & use of source matl for decontamination, storage & resalt only by Stepan Chemical Co HARMON.D.F Atomic Energy Commission 67/05/18 Ip
- Bi0326004B Addl response to FQIA request for siz categories of info r reduced edol response to rule request for six categor radioactive matls found in Haywood & Rockelle Park.NJ Forwards Cocuments listed in App A Documents 1.2 & 6
- rurmerus cocuments issed in App A Documents 1.2 % 6 pertially withheld home addresses (ref FGIA Elemption 6). FELTOV. M. Division of Rules and Records. B1/03/03 CB040 105 --Bi03260354 Advises that Bispan Chemical Co must renew License BTC-I to authorize storage of thorium.
  ROY.O W NRC - No Detailed Affiliation Given. 76/12/13. 1p.
- SWANSON, E. A. Stepan Chemical Co. 71/06/23 1p.
- --B103260450 Responds to 710422 ltr re disposition of thorium waste teilings & status of License STC-130 Requests that amend fee or application for approval to dispose of radwaste by burial be provided to AEC.
- LAYFIELD. R. L. Atomic Energy Commission 71/06/11. 200. --Bi03260479 Discusses Stepen Chemical Co disposition of thorium was tailings & status of License STC-130 Recommends that licenses divest radioactive matl or pay license fee.
- Provision re possible escavation control should be made. LAYFIELD, R. L. Atomic Energy Commission 71/05/26 2pg
- --8103260488 Ack receipt of 710407 ltr re H-3 held under License 29-13725-01 Forwards fee covering cost of specific metl license required & provides into to eld in processing application for license termination.
  SHANBON, E. A. Stepan Chemical Co. 71/04/22. 2pp.
- --8103260499 Responds to 710208 ltr.returning license fee Invoices L-2645-71 & L-2646-71 & informing NRC that vendor no longer possesses radioactive nats. Requests info re disposition of catts held under Licenses 29-13725-01 & 8TC-130.

  LAYFIELD.R. L Atomic Energy Commission 71/04/07. 1p.
- --8103260506 Returns NRC Invoices L-2645-71 & L-2646-71 re fees concerning possession & use of excessive quantities of source meth & other specific meths bicenses Company no longer uses or possesses source meth Myo Invoice L-2646-71. SWANSON.E.A. Stepen Chemical Go. 71/02/08. 2pp.
- --B103260532 Confirms 690930 telcon re release of recent file on dis of thorium wastes to PDR Vendor has no objection Oversized topographic map of Heckensack, NJ encl
  - SWANSON, E. A. Stepan Chemical Co. 68/10/01. 2pp.

- ~~BI03260539 Approves of 680815 request for unrestricted release of Bidg 77 (former weste storage area) & south dise storage area No hazard to health & safety posed. RL Gilbert 680905 it encl HARMON.D F About Energy Commission 68/09/04 See
- ~~B103260548 Requests that AEC release two former storage areas for use on unrestricted basis isotopes. Inc surveys encl W/o diagrams of storage areas
  BMANGEN,E.A. Stapen Chemical Co. 68/08/15 Ann.
- ~-8103260553 Submits Amend 1 to Source Hatl License STC-130, per 680228 1tr Amend 1 authorizes relocation of radioactive tallings. HARDDN.D.F. Atomic Emergy Commission 48/03/19 10
- ~-8103260562 Confirms 680227 telcon re-waste tailings stored on property from former thorium process. Proposes to relocate waste tailings to excavation on another area of property & provide min 3-ft cover.

  SHANBON E. A. Stepan Chemical Co 68/02/28. 2pp
- --Bi03260572 Confirms 68010B telcon re release of contaminated properties & termination of License BTC-130 Requests rept in order to approve transfer of contaminated equipment bidgs or progerties to individuals not in passession of licenses. MARMON.D.F. Atomic Energy Commission. 68/01/19 2pp.
- --8103260577 Forwards Stepan Chemical Co 671129 ltr.in response to 671205 request.
  CLEVELAND.R.S Atomic Energy Commission. 67/12/06. [p
- --Bi03260590 Discusses AEC 671121 ltr citing noncompliance items in activities under License BTC-130 Thorium processing bldgs were decontaminated & dismentied in 1966. License BTC-130 should be continued to cover safer storage of radwasts. FRANCIS. D. H. Stepan Chemical Co. 67/11/29. 2pp.
- --8103260600 Discusses Stephan Chemical Co request for termination of License STC-130, Sefety evaluation of reducete burial will be performed. Requests meeting to discuss vendor response to AEC notice & further enforcement action. NUBSBAUMER.D.A. Atomic Energy Commission 67/12/01. 1p
- --8103260606 Discusses IE insps of License BTC-130 on 671018 & 1102 & forwards notice of violation.

  KIRKHAN,R W. Atomic Energy Commission. 67/11/21 lb.
- --8103760614 Notice of violation from insps on 671018 & 1102
  Noncompliance noted: radwaste was buried on licensee property in excess of prescribed limits. Therium contaminated timbers from dismantled thorium process bidgs were incinerated.
  8HOPENN.N M. Atomic Energy Commission. 67/11/21. 1p.
- --8103260620 Discusses items of noncompliance found during IE inspe of License STC-130 on 671018 & 1102 Burial of waste slurry mati was most appropriate action for licenses to take Ralated info encl Info partially withheld (ref FOIA Exemption 6). BHOPENN.N.M. Atomic Energy Commission. 67711/21. 48pp.
- --8103260623 Forwards renewed Bource Matl License STC-130. HARMON. D. F. Atomic Energy Commission. 67/05/18. Ip.
- --BIO3260627 Renewal of Source Matl License BTC-130 for Stepan Chemical Co. authorizing possession of unlimited amounts of thorium for decontamination, storage & resale.

  HARMON.D.F. Atomic Energy Commission. 67/05/19. 1p.
- --B103260631 Forwards application for renewal of License BTC-130, FRANCIS, D. H. Btepan Chemical Co. 67/05/08. 2pp.
- --Bi03250638 Application for renewal of Source Matl License STC-130, authorizing possession & storage of 2:160:000 lb mud. containing 1.5% thorium. FRANCIB.D.H. Stepan Chemical Co. 67/05/08. 2pp.
- --B103260642 Notifies that Bource Natl License BTC-130 expires on 670630. Describes procedures by which licenses can renew terminate or amend license. NUBSBAUMER, D. A. Atomic Energy Commission. 67/04/25. ip.
- --B103260646 Forwards renewed Source Matl License BTC-130. NUBBBAUMER, D. A. Atomic Energy Commission. 64/06/26. ip.
- --8103260652 Renewal of Bource Metl License BTC-130 for Stepen Chemical Co. authorizing possession of unlimited amounts of thorium for decontamination, storage & resale.
  NUSBBAUMER, D. A. Atomic Energy Commission. 64/06/26. 1p.

- ~~810326065B Submits responses to Items 1-6 contained in AEC 631114 1 re License BTC-130 Includes info re decontamination procedure & ajsporae activity tests FRANCIS.D H. Stepan Chemical Co. 64/03/12 3pp
- --Bi03260666 Requests info contained in Items 1-6 of AEC 631114 ltr is order to continue review of 640127 application for renewal of License STC-130. Requires topographical map of area, showing bldg & residue storage areas.

  NJSBBAUMER. D. A. Atomic Energy Conmission 64/02/14 lp
- --8103260672 Responds to 640125 ltr. Main slurry pile areas should be maintained as restricted areas until radiation levels are reduced Litense amend request will be reviewed w/440127 application for renewal of License STC-130 PRICE, E.R. Atomic Energy Commission 64/02/07 lp.
- --8103260678 Forwards Application for renewal of License 8TC-130. FRANCIS.D.H. Stepan Chemical Co. 64/01/27 1g
- --8103260683 Application for renewal of License STC-130, authorizing possession & storage of 2.160,000 lb mud.containing 1.5% thorium FRANCIS.D H. Stepen Chemical Co. 64/01/27 20n
- --8103260692 Notifies that License BTC-130 expires on 640229 Lists mea by which licensee can renew, terminate or amend license NUSBBAUMER.D A Atomic Energy Complesion 64/01/17 jp
- ---B103260698 Requests add1 clarifying info re corrective actions taken deficiencies noted in AEC 631114 itr.including date when full compilance will be actioned.
  PRICE, E.R. Adomic Energy Commission. 64/01/06 200
- --BIO3260703 Responds to AEC 431114 lit re noncompliances noted during ineps on 630830 & 0904 Corrective action bottles containing thorium have radiation warning labels which specify chemical contents.

  FRANCIS. D. H. Stepen Chemical Co. 63/12/03 2pp
- --8103260709 Discusses AEC inaps of Licensa STC-130 on 630830 & 0904. Noncompliance noted excessive radiation levels were found in unrestricted areas Radiation areas were not posted w/caution signs.

  PRICE: E. R. Atomic Energy Commission 63/11/14 4pp
- ~-Bi03260713 Forwards compliance insp rept for License 8TC-130 conduct on 630830 & 0904 Requests appropriate enforcement actions. CLEVELAND.R. 8 Atomic Energy Commission 63/09/24. 3pp
- ~-Bio3260715 Compliance insp rept on 630830 & 0904 Noncompliances note radiation levels in unrestricted areas exceeded permissible levels. Rooms & bottles containing thorium were not properly posted RESNER, E.P., CLEVELAND, R.B. Atomic Energy Commission. 63/09/23.
- ~~BIO3260719 Ack receipt of 611002 itr informing AEC of steps taken to correct deficiences noted in AEC 610901 itr.Licensed activities will be reviewed during next insp.
  PRICE\_ER Acomst Energy Commission. 6110720 tp.
- --Bi03260721 Ack receipt of 610901 itr re deficiencies noted in AEC in Grace Chemical Co is responsible for radioactive products.

  Open stockpile has been fenced to guarantee personnel safety.

  FRANCIS.D.H. Stepan Chemical Co. 61/10/02 ip.
- --Bi03260722 Ack receipt of 610808 ltr re steps taken to correct deficiencies noted in AEC 610726 ltr. Proposed corrective measures are adequate for Items 1,4.5 & 6. Requests corrective info for Item 2.

  PRICELE R. Atomic Energy Commission. 61/09/01. 2pp.
- --8103260723 Responds to AEC 610726 ltr re violations noted in AEC ins Corrective actions: caution signs will be placed in restricted areas. Cartons & drums will be labeled, Open stockpile of thorium phosphete will be fenced and posted. FRANCIS. D.H. Stepan Chemical Co. 61708708. 2pp.
- --BIOGRÉO724 Discusses AEC insp of License BTC-130 on 610315. Nancompliences noted:caution signs were not posted in restricted areas. Lunchroom area had not been surveyed for external & airborne radiation. PRICE, E. R. Atomic Energy Commission. 61/07/26. 3pp.
- --Bi03240725 Forwards compliance insp rept re reinspection of License BTC-130. Lists noncompliances & corrective actions taken.
  KIRKMAN.R.W. Atomic Energy Commission. 61/07/10. App.

- --BIOJ260726 Compliance this rept on 610319 Noncompliances noted radiation in unrestricted areas exceeded permissible levels. Therrith phosphate is stored in open pile & is not secured against unauthorited removel EPSTEIN.E., KIRKMAN.R.W. Atomic Energy Commission 61/07/10
- --81032:0728 Forwards application for renewal of License STC-130 to authorize transfer & delivery of thorium source catl to licensed receipients SPIESS.H.R. Stepan Chemical Co. 61/02/28 lp
- --B103260729 Application for renewal of License STC-130 authorizing transfer delivery export or receipt of thorizing source mail FRAMCIS.D H Stepan Chemical Co. 61/02/20 3pp
- --8103260730 Forwards application for license to transfer deliver export or receive thorium source math yan XANDTLO R Steeps Chemical Co. 59/12/20 1p
- --810326073: Application for license to transfer deliver export or receive thorium source mati VAN ZAIGOTO R Btopan Chemical Co 59/12/23 4pp
- --B103260732 Requests Form AEC-2 to renew Litense R-103. Litense expires on 600131 SPIESB. H.R. Stepan Chemical Co. 39/12/13 1p
- --8103260733 Guggests that source matl license for Maywood Chemical Works be renewed if Traceriab Inc recommendations are followed. RD2ERS.L R atomic Energy Commission 39/01/20 lp
- ~-8103260734 Forwards rept. "Radiological Survey at Maywood Chemical Co " Licensee will comply w/rept recommendations when operation resumes VAN ZANOT, D.R. Stepan Chemical Co. 58/12/24 | p.
- --0103260736 "Radiological Survey at Naywood Chemical Co '
- --8103260738 Responds to S81017 ltm & 581218 telcon me renewal of License R-103 Requests addl informs description of instruments available to perform health & safety surveys & types of surveys that will be performed DELANEY.J.C. Atomit Emergy Commission 38/12/19. 1p.
- --9103260740 Discusses Maywood Chemical Works application for renewal of License R-103.Request should be treated as new application due to lack of info contained in docket file ROGERS.L.R Atomic Energy Commission. 50/12/07. Ip.
- ---BIO3260742 Informs AEC that 581017 roneual for License R-103 cas never received Requests info.
  VAN ZANDT. B. 8tepen Chemical Co. 58/12/08 lb.
- --Bi03260745 Orants Source Mati License STC-130.authorizing receipt & possession of source mati PELA/EV.J.C. Atomic Energy Commission, 38/12/01 1p
- --BI03260748 Application for meti/byproduct license to transfer, deliver. export & receive throium source mati. VAN ZANDT, D.R. Stepen Chemical Co. 58/12/01 4pp
- --S100260751 Forwards application for license to process & expert source matl. W/q encl.
  VAN ZANDT,D R Stepen Chemical Co. 58/10/17, 1p.
- --BI03240753 Requests application to renew License R-103 License expires on 581201 Rediction sefety check sheet ent.

  VAN ZANDT.D R Stepan Chemical Co. 58/10/08 3pp
- ~-8103260757 Requests reinspection of facility due to potential hazard discovered in AEC 1957 insp Surveys to determine magnitude of potential hazards should be included in reinspection. RUGERS.L. H Atomic Energy Commission. 98/06/04 ip.
- --B103260759 Orants Meti/Byproduct License R-103, authorizing receipt & possession of source meth in any quantity for processing & resale
  DELANEY, J. C. Atomic Energy Cormission. 37/11/20. 1p

- --Big3C6O7±2 Application for mati/byproduct license to transfer delivererport or receive sourcematl in any quantity for processing & receie. VAN ZANDT, D. R. Biesen Chemical Co. 37/11/14 4pp
- --BIOD260765 Forwards application for matl/byproduct license to process & export source matl W/o enci VAN ZANDT.D R Stepan Chemical Co 57/11/14 1p
- --Bi03260772 Discusses renewal of License R-103 authorizing possession & use of source matls in any quantity for processing & resale insp on 370324 revealed that licensee activities do not comply w/AEC regulations.
  NELSON.C A Atomic Energy Commission. 37/07/11 2pp.
- DOCKET 40-2061 WEST CHICAGO FACILITY, KEHR-MCGEE CORP
- B1030400308 Forwards draft findings, request for info & order to show cause re radioactive & nonradioactive releases from facility into surface & ground waters & air at unacceptable levels.

  Certificate of Bvc encl
  MCGUIRE. J Environmental Protection Agency. 01/02/05 6pp. 07509, 001
- 8103250119 Forwards info to be sent to EPA on B10313 re environ monitoring Questions EPA jurisdiction in matter. SHELLEY.H. J. Kerr-McGee Corp. 81/03/11 9pp. 07997.271
- BIO3250866 Requests that Kerr-McGee decommissioning plan exclude strip mining in city REANELBAR E West Chicago, IL 81/03/12 [p.
- DOCKET 40-2259 PATHFINDER MINES CORP.
- 8102240479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NM.AZ.CO & MY. Forwards Documents 1-17 listed in app Document 10 may be obtained from NTIS FELTON.J.M. Division of Rules and Records. 01/02/05. 200
- --Bio222033B Requests specific review & rept re tailings discharge operations due to occurrences of release of tailings matl from impoundment sys. Rept should include description of physical condition of embankment sys. Related info encil ROUSE-L. C. Fuel Process. & Fab. Branch (Pre 770727). 77/03/04/709
- 8103040793 Forwards "Bemiannual Effluent Monitoring Rept." for Jul-Dec 1980 Corrected Lead-210 data for second & third quarters included. MUDENT-E L. Pathfinder Mines Corp. 81/02/27 5pp. 07813:063
- --8103040788 "Bemtannual Effluent Monitoring Rept," for Jul-Dec 1980 \*\* Pathfinder Mines Corp 81/02/27 7pp. 07812:068.
- B103170467 Forwards application to amend License BUA-672.modifying Part 5 of 770930 request for license renewal & 780619 emergency action plan to accommodate personnel changes.Fee encl.

  NUCENT.E L. Pathfinder Mines Corp. 81/03/11. 2pp. 07934:344.
- --BiO3/70470 Application to amend License SVA-627, modifying Part 5 of 770930 request for license rensual re operations organization & 7806/7 emergency action plan for yellowcake transportation accidents.
  NUGCNIE L Pathfinder Mines Corp. 81/03/11. 15pp. 07934-346
- B103310650 Forwards approved bond rider reclamation bond summary to support ref obligation & verification notice certifying that band is in effect, submitted per License Condition 42. Amend 5 to License GUA-672. PGYSER.R. N Pathfinder Mines Corp. 81/03/23. 7pp.
- Bi03310608 Forwards supplemental info in support of Bi0204 application for amend of License BUA-672. Blear test re moisture placement criteria for Zone 1 fill being conducted. NUCENT.E. L. Pathfinder Mines Corp. 81/03/24, 10pp.
- BOCKET 40-2274 CHASE BRACE & CD . CLEVELAND REFACTORY METALS DIV.
- 8103110422 Forwards IE Insp Rept 40-2274/80-09 on 801216 & 23 & 810119. No noncompliance noted. FISHER.W. L. Region 3. Chicago, Fuel Facility & Meterials Safety Branch. 81/02/06 2pp. 07868:229.

- --BIO3110432 IE inep Ropt 40-2274/BO-09 on 801216 & 23 & BIO119 Clossout insp to determine status of expired license & to conduct independent surveys of physical facilities used DESTMANN.M J. PAPERIELLO.C J. Region 3. Chicago. Office of the Director. 81/02/05 7pp 07868 231.
- DOCKET 40-3392 ALLIED CHEMICAL CORP
- 8103190824 Forwards 1E Insp Rept 40-3392/80-02 on 800514-15 & 0806-07 & notice of violation Expresses concern re mgt control sys & lack of ALARA program implementation.

  \*\*EPPLER: J O Region 3: Chicago: Office of the Director 81/02/05 2pp 07965.306.
- --8103190830 Notice of violation from insp on 800514-15 & 0806-07 KEPPLER.J.G. Region 3. Chicago, Office of the Director 81/02/05. 2pp 07965-305
- --8103190839 IE Insp Rept 40-3372/80-02 on 800514-15 & 0806-07 Noncompliance noted personnel exposure insufficient engineering controls & exposure exceeding 40-h control crasure. PAULIR A. DENNIBIN Region 3. Chicago. Office of the Director FIBHER.H.L. Region 3. Chicago. Fuel Facility & Materials Bafety Branch 81/01/20. 11pp. 07965-310
- Bi03120513 Confirms informal discussions w/NRC re recycling plans for wastewater treatment process generated calcium flouride. Discusses wastewater treatment process & disposal methods. CIPPOLA.A J. Allied Chemical Corp. Bi/OZ/11 2pp 07906.122

#### DOCKET 40-0490 ATLAS MINERALS

- B102260479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NM.AZ.CD & MY. Forwards Documents 1-17 listed in app. Document 18 may be obtained from NTIS.

  FELTON-J M Division of Rules and Records 81/02/05. Zpp.
- --BI02260538 Requests specific review & rept re tailings discharge operations due to occurrences of release of tailings mat! from impoundment sys Rept should include description of physical condition of embankment sys Related info encl. ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727). 77/05/04
- 8103031135 Bubmits contract costs incurred & manhours used to review 791203 application for Amend 2 to License BUA-917 Bummary rept Encl OACTA-P.J., LINEHAN-J J. Uranium Recovery Licensing Branch. 81/02/06. 2pp. 07808-242
- 8103040903 Notifies of partial refund fee re 791203 application for Amend 2 to License BUA-917.
  MILLER.W.D. License Fee Henagement Branch. 81/02/19. 1p.
- B103090566 Summary of G01211 meeting w/Atlas Minerals & UT Dept of Health in Silver Spring. MD refuture storage of tailings, saepage at Moab Site, surety, authorization of increased yellowcake production rate & new rules on U milling. GARCIA.P. J. Urenium Recovery Litensing Branch. 81/02/20. 8pp. 07845: 226.
- 9103110308 Responds to NRC 801125 ltr re background monitoring station. Installation completed Unit started up. BKANBY-0.T. Atlas Minorals. 81/02/20. 1p. 07884-149
- B103110343 Confirms that agreement was reached w/NRC that no additional written responses to B01024 & B10112 itrs would be sent until addi hydrology work was completed.

  BHANBY, G. T. Atlas Minerals. B1/02/20. Ip. 07884:144.
- 8103120602 Requests approval of Amend 4 to License SUA-917, adding Condition 46 to require installation of new scrubber for yellowcake hearth dryer exhaust & operational checks. GARCIA.P.J., PETTENDILL.H.J. Uranium Recovery Licensing Branch. 81/02/20. 2p. 07901:236
- 0103120644 Amend 4 to License BUA-917, adding Condition 46 to authorize installation of new scrubber unit for yellowcake hearth dryer eshaust periodic operational checks are required.

  BCARAND, R. A. Uranium Recovery Licensing Branch. 81/02/20. 2pp. 07904:347.
- 8103200123 Submits annual environ monitoring rept for 1981. SWANBY.O.J. Atlas Minorals. 81/02/24. 2pp. 07971; 167.

- B103260675 Forwards rept of personnel whole body esposures for CYBC EDMARDS D L Atlas Minerals 81/02/26 ip 08040 292
- --8103260681 Rept of personnel whole body exposures for CY 80 \* Atlas Minerals 81/02/26 2pp 08040 293
- 8103181146 Forwards effluent monitoring tept data for Jul-Dec 1980 FOMARDS D. 1. Atlas Minerals 81/02/27 400nn 07986 001
- B103160443 Notifies that Arend 4 to License BUA-917 should be exemption from fees Arend was initiated by NRC OARCIA.P J. PETTENGILL.H J. Uranium Recovery Licensing Branch B1/03/04 1p. 07916 201.
- 8103260943 Forwards correction of calculation error in fourth quart 1980 rept re riverwater samples, submitted 810327 EDNARDS D. L. Atlas Minerals 81/03/09 ip 08040-286
- --8103260948 Corrected page of fourth quarter 1980 cept re riversuat semples.submitted 810227 • Atlas Minerals 81/03/09. 1p 08040 287
- 8103181100 Responds to 810115 Itr re-unresolved Issues Amond to Lic Conditions 25(d).36 & 43 was issued 810206 Prior to issuance of 18-ft lift to existing tailings inpoundment analyses redam stability, surety & reclaration must be submitted SCARAND.R A Uranium Recovery Licensing Branch 81/03/10 3pp
- 6103240373 Advises that facility is in compliance u/environ b efflumentioring 8 reporting requirements of License SUA-917 GARCIAP J , PEYTENSILL, H J . Uranium Recovery Licensing Branch B1/03/11 2pp. 07981-352
- DOCKET 40-4348 COMMERCE, DEPT. OF, NATIONAL BUREAU OF STANDARDS
- 8103040646 Requests amend to Licenses 08-00566-05.6NM-362 & 8MM-405 allow regular lab waste disposal of solid waste to contain less than one percent of 10CFR20 App C quantities or of concentration less than 10CFR20 App 0.Table 2.Column 2. PEVEY.L E Commerce.Dept of. National Bureau of Blandards 81/02/26 1p 07810-056
- DUCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)
- 8102230689 Forwards Danes & Hoore rept. "Detailed Seepage Investiga of Mill Waste Disposal Alternatives. West Cas Hills. WY for Federal-American Partners." Vols 1 & 2. Water quality data encl.

  BLUBAUGH. R. E. Federal American Partners 81/02/04. 9pp 07733: 001.
- --Bi02230694 "Detailed Seepage Investigation of Mill Waste Disposal Alternatives Wast Gas Hills-MY for Federal-American Partners." Vols 1 & 2. MURDOCK-L 7 . HIGHLAND.W R. Dames & Moore. 81/01/31 350pp 07733-010.
- B102260479 Partial response to FOIA request for all documents re fir categories of info concerning U mills in UT.NM.AZ.CO & MY Forwards Documents [-17 listed in app Document 18 may be obtained from NTIS. FELTON.J.M Division of Rules and Records 81/02/05. 2pp
- --Bi0226033B Requests specific review & rept re tailings discharge operations due to occurrences of release of tailings matifrom impoundment sys. Rept should include description of physical condition of embankment sys. Related info enci. ROUSE, L. C. Fuel Process. & Fab. Branch (Pre 790727) 77/05/04 7pp.
- B103030B38 Forwards "Beniannual Rept on Radioactive Effluent per 10CFR40 65" for Jul-Dec 1980.
  BLUBAUOH,R.E., LANE,J.R. Federal American Partners. 81/02/19
- ---8103030866 "Semiannual Rept on Radioactive Effluent per IOCFR40, 6 Jul-Dec 1980. \* Faderal American Partners 81/02/19. 46pp.
- 8103260936 Informs that certain locations will no longer be sampled to cessation of crushing activity. Other locations will be sampled when new SAO mill is placed into operation.

  LANE. J. R. Federal American Partners. 81702725. 2pp. 08040-204

- 8103261916 Forwards "Sentannual Effluent Monitoring Rept.Jul-Dec 1980 "
  Data unavailable for pravious rapt is now included Corrected 
  Pt-210 data also included for pravious rapts. 
  NUCENTE L Pathforder Mines Corp. 81/02/27. 7pp
- --9(0)261022 Serianusal Effluent Monitoring Rept. Jul-Dec 1980 "
   Pathfinder Mines Corp 81/02/27. Spp

DOCKET 40-5021 STANDARD OIL CO

B103190119 IE Inep Findings & Licensee Act atc B10203 of Licenses 543-785 & 12-13897-01. Insp findings no noncompliance noted.
• Region 3. Chicago. Office of the Director B1/02/03 ip

DOCKET 40-5293 NORTHEASTERN UNIV

- B103050719 Act receipt of B10108 ltr informing NRC of steps taken to correct violations noted in 16 lnsp Repts 70-0394/80-01. 40-02937/80-01 & 30-13307/80-01. kln:@RAN.J.D Region 1. Philedelphia Fuel Facility & Materials Safety Branch 81/01/28 1p 07821 347
- --Bi03050726 Responds to ARC 801211 ltr re-violations noted in IE Insp. Repts 70-0394/B0-01.40-3393/80-01.2 30-13307/80-01 moted in IE Insp. Corrective actions will conduct surveys of contamination flor general radiation at end of each experiment or wit LATORRE.P. Northeastern Univ. B1/01/08 2pp 07820 348
- --Bi03050734 Discusses IE Insp Repts 70-0394/80-01.40-5293/80-01 & 30-13307/80-01 on B01113 & forwards notice of violation KINTEMAN.J.D. Region I. Philadelphia Fuel Facility & Materials Safety Branch 80/12/11 2pp 07821-350
- --Bi0g030742 Notice of violation from insp on 801113 Noncompliance noted radiation monitoring surveys not performed by all individuals in labs routinally using radioactive ratis & some labs should evidence of smoking & crimbing Region 4, Dallas, Office of the Director 80/12/11. Ip 0/981:352

DOCKET 40-6522 PATHFINDER MINES CORP

- 8102260479 Partial response to FOTA request for all documents re five categories of info concerning U mills in UT.NM.AZ.CO & WY Forwards Documents 1-17 listed in app. Document 18 may be obtained from hTIS FELTON.J.M. Division of Rules and Records. 81/02/05 2cp.
- --B102260538 Requests specific review & rept re tailings discharge operations due to occurrences of release of tailings mail from impoundment sys Rept should include description of physical condition of embantment sys.Related info enci ROUSE-L.C. Fuel Process, & Fab. Branch (Pre 790727). 77/05/04.
- 8103060093 Ack receipt of NRC 910121 ltr advising that source matl license expires on 810430 Forwards License BVA-442indicating expiration date of 820930. RUSSELL-J.E. Pathfinder Mines Corp. 81/02/12. ip. 07838 361.
  - e SUA-442 for Lucky HcUranium Corpresented in 761130 application & rs.
    rs. 77/09/30. ip.

' Licens# 8UA-44⊉ was n expiration ∸n proper

81/03/13. 1p.

DOCKET 40-6659 DETTY DIL CO. PETROTOMICS CO. DIV.

B103160207 Notifies of Amend 8 to License SUA-551, adding Condition 29 to authorize receipt for surface wastes from U solution extraction processes for disposal in tailing impoundment. SCARANO, R. A. Uranium Recovery Licensing Branch. B1/01/29. 1p. 07918-329

- 8103060785 Discusses review of licenses proposed corrective action violetions noted in IE insp on 800915-16 & 0603 Proposals are acceptable Licensing action is required for tailings transfer & revision of implant air sampling. KOTSCH. J & Uranium Recovery Licensing Branch. 81/02/12 ip 07976 118
- B103160382 Recommends approval of Amend 10 to License SUA-551. Tevi Sections 4 1.1 & 4 1.1 is of rediction safety program to establish new airborne dust sampling locations. KOTSCH.J L. Uranium Recovery Licensing Branch B1/02/24. 2pp. 65114 292
- 8103160195 Notifies of Amend ID to License BUA-551 revising Conditions use of radioactive math in response to 810220 request SCARA\*D.R A Uranium Recovery Licensing Branch. 81/02/24. 1p. 07919:3146
- 8103180695 Notifies that no radionuclide liquid effluents were related unrestricted areas during Jul-Dec 1980 Amounts of particulate in form of stack gases released to unrestricted areas listed PFAFF.8 J. Getty Oil Co., Petrotomics Co. Div. 81/03/10. ip. 07945 051

DOCKET 40-7869 PLATEAU RESQUECES, LTD

- BIO3050186 Bubmits effluent monitoring rept for Jul-Dec 1980.
  ALLEND J. Plateau Resources, Ltd. 81/02/25, 2pp 07827-039.
- DOCKET 40-7924 BCHOTT OFTICAL OLASS, INC.
- 8103100157 Responds to 810[21 ltr forwarding radiation survey mept area behind bidg. Amount of thorium in waste glass constitutes licensable quantity. Area may not be released for unrestricted use w/o NRC approval. KINNEMAN, J. D. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 81/02/06 Ip. 07865.349
- --Bi03100164 Forwards "Rept on Rediation Burvey of Cullet Dump Are Schott Optical Olass Plant-Durgea.PA." per agreement of understanding reached re IE Insp Repts 40-7924/80-01 & 30-09864/80-01 Amount of gless poses no threat KALO:561.4 W Schott Optical Olass, Inc 81/01/21. 2pp. 07865-330.
- --BIO3100172 "Rept on Radiation Gurvey of Cullet Dump Area at Boho Optical Glass Plant, Duryes, PA " Bite plan encl. GALLAGHARR.R.O., NIPAR.J.E. Applied Health Physics, Inc. Bi/O 3pp. 07865.392
- DOCKET 40-8027 KERR-MCGEE CORP
- B103050856 Forwards 1979 environ surveillance rept on monitor well SHELLEY, N. J. Kerr-McGee Corp., 81/02/11. 10. 07989.001.
- --8103050859 Environ surveillance rept on monitor wells for 1979 \* Werr-McGee Corp. 81/02/11. 12pp. 07585:001.
- 8103090234 Forwards orders re mod of Licenses 8UB-1010 & 9NM-1174requiring preparation & submission of radiological contingency plans. CUNNINGHAM.R E. Division of Fuel Cycle & Material Bafety. 81/0 1p. 07849:049.
- --Bi00090239 Order requiring mod of License SUB-1010, Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 120 days.

  CUNNINGHAM.R.E. Division of Fuel Cycle & Material Bafety.

  D1/02/11. App. 07849:080.
- --Bi03090251 Order requiring nod of License 8NM-1174. Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days. CUNNINONAN.R.E. Division of Fuel Cycle & Material Sefety. 01/02/11. dpp. 07849:086.
- B103130031 Amend 12 to License SUB-1010, authorizing use of hay groon test site as described in B10119 application.
  PAGE.R.9. Uranium Fuel Licensing Branch. 81/02/24. ip. 07908

dispose of hay grown on land fertilized w/bartum-treated neutralized raffinate Recommends approval. NIKON,W A. CROW,W T. Uranium Fuel Licensing Branch 81/02/24 2nn 07908 2A9

B103300231 Bubmits monitoring rept re wells M5-10 showing high nitrate in 1980 No explanation offered for contamination source or erratic variation of water investigation will continue when well again contains water
SHELLEY.N.J. Kerr-McOde Corp. B1/02/27 in 08093-020

DOCKET 40-8040 CERAC. INC

8103180015 Act receipt of 810113.20 & 0218 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-804/83-01 FISHER.W L Region 3. Chicago. Office of the Director 81/02/27 pp 07943 334

--8103180020 Responds to 801223 ltr & notice of violation.ltem 1.App A & forwards health physics 810207 audit rept COLTON.E Cerac. Inc 81/02/18 18pp 07943.337

--B103180024 Responds to NRC B01223 ltr re violations noted in IE Inep Rept 40-B040/80-01 Corrective actions contaminated concrete removed & radiation levels dropped. ROBLEE,P.D. Gerac. Inc. B1/01/20. 1p. 07943-336

--8103180030 Responds to NRC 801223 ltr re violations noted in 1E Insp Rept 40-8040/80-01 Corrective actions contaminated concrete removed & radiation levels dropped ROBLEE,P D Cerac. Inc 81/01/13 2pp 07943 339

DOCKET 40-8064 EXXON MINERALS CO. UBA, EXXON CORP.

B103030342 Notifies that chloride & sulfate readings exceeded upper control limits in Well E-0-B during B01209-18 sampling period. Sulfate should be deleted as excursion parameter B1681N0GR.R.H. Expor Minerals Co., USA B0/12/23 4pp. 07791 183.

--Bi03030352 Requests deletion of sulfate as excursion parameter Sulfate assay is poor indicator due to low sulfate levels of loach sys Supporting analyses encl TRUSBELL.H H Excon Minerals Co., USA 80/10/16 14pp 07791:187.

8103020099 Forwards fourth quarter sample analysis results. Leach solution production & injection decreased during quarter, due to cessation of injection in fourth pattern Bolution mine well pattern encl.
81881NGER.R.H. Exxon Hinerals Co., UBA, 81/01/23 2pp. 07789,004.

--B103020103 Fourth quarter well sample analysis results.
\* Ezzon Minerals Co., USA. B1/01/23. 7pp 07788 006.

G103180792 Forwards updated tables of water quality analyses for solution mining wells E-0-7.E-0-8 & E-0-7.final progress rept.
BISSINGER.R.H Esxon Minerals Co., UBA 81/02/24 ip 65126:241

--8103180800 Updated tables for "Analysis of Bamples From Wells E-0-7, E-0-8 & E-0-9."

# Exxon Minerals Co., USA 81/02/24. 1p. 65126.342.

DOCKET 40-8084 LISSON MINE. RIO ALOOM CORP

B103160479 Submits data omitted in 900804 ltr to NRC re average weekly apposure calculations BURNETI.J T. B16 Algon, Ltd. 80/08/13 1p. 07916:307.

Bi03260695 Notifies of payment of civil penalty & additesponse to Item 11. Two men were not sent for whole body counts because Battelle readings were lower than readings taken at mine. Analysis sheets withheld due to sensitive info.

LAWTON: N B. Rio Algom, Ltd. B1/01/27. 3pp. 08040: 288.

8102260479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NM.AZ.CO & MY. Forwards Documents 1-17 listed in app. Document 18 may be obtained from NTIS.
FELTON.J. H. Division of Rules and Records. 81/02/05. 2pp.

operations due to occurrences of release of tailings call from impoundment sys Rept should include description of physical condition of ambaniment sys Related info enci RDUSE.L C Fuel Process. 5. Fab Branch (Pre 790727) 77/05/0

B103050731 Ack receipt of B10123.26 & 27 ltrs & payment of civil penalties imposed by NRC B10113 order THOMPSON.D Director's Dffice B1/02/12 ip 07825 071

B103090816 Discusses compliance review conducted to provide basis future licensing actions to correct noncompliances Civil penalties were imposed for violations noted in IE insp. rept. on 800429-27 Review is terminated KOTSCH.J.L. Uranium Recovery Licensing Branch. 81/02/12 1p.

8103160172 Discusses review of Rio Algom nept on ambient air sampl data Error in submitted data was corrected in 810130 telcon KOTBCH.J L Urantum Recovery Licensing Branch 81/03/03 1p 07919 351

H103250740 Informs that Dames & Moore seepage study, "Rept on Groundwater Investigations.Lisbon Hine Near La Sal, UT. for Rio Algom Corp." has been sent via parcei port LAHTON.M D. Rio Algon. Ltd. B1/03/12 1p. 68000:320

BIO3260967 Concurs w/IE actions to review of licensee average week exposure calculations rept Licensee failed to meet requirements re surveys limits for airborne radioactivity & posting of airborne radioactivity areas KOTSCH. J.C. Wranium Recovery Licensing Branch BI/03/12 2pp 000400 200

DOCKET 40-8102 EXXON MINERALS CD USA, EXXON CORP

8103160343 "Review of Long-Term Stability of Proposed Reclamation | Highland U Mill Tailings Impoundment " HELSON.J D . AST.S R Colorado State Univ 80/05/31 68pp 07916-085

G102260479 Partial response to FOIA request for all documents refeategories of info concerning U mills in UT.NM.AZ.CD & WY Forwards Documents 1-17 listed in app Document 18 may be obtained from NTIB FELTON.J M. Division of Rules and Records 81/02/05 2pp.

--BI02260538 Requests specific review & rept re tailings discharge operations due to decurrences of release of tailings ratifrom impoundment sys Rept should include description of physical condition of embankment sys Related info encl. ROUSELL C Fuel Process. & Fab Brench (Pre 790727) 77/05/07/09/08

8103090641 Forwards "Rept of Airborne Emissions of Principle Radionuclides for Jui-Dec 1980 " PHICLIPS, J. P. Exton Minerals Co., USA 01/02/20 [pp 07848]

--B103090646 "Rept of Airborne Emissions of Principle Radionuclide Jul-Dec 1980." « Exxon Nuclear Co : Inc. (subs of Exxon Corp.) 81/02/20. 07848 255

DOCKET 40-8129 ARMY, DEPT. OF

8103100700 IE Insp Findings & Licensee Ack dtd 801201 of License 8TB-1124 Insp findings: no noncompliance noted 8ROWN.R A Region 2. Atlanta, Office of the Director 80/12/01 1p. 07862:192

DOCKET 40-8151 NAVY, DEPT. OF, NAVAL BEA BYSTEMS COMMAND

8103100711 IE Insp Findings & Licensee Ack dtd 801203 of License SMB-1145 Insp findings no noncompliance noted. BROWN, R. A. Region 2. Atlanta. Offico of the Director. 80/12/03 pp. 07862:196.

DOCKET 40-8155 AMAX SPECIALTY HETALS CORP.

8103110082 IE Insp Findings & Licenses Ack dtd 810218 of License 818-1161 Insp findings:no noncompliance noted. BLAWINSHI.-W.J. Region 3: Chicago, Office of the Director. 81/0 1p. 07885: 226.

## DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO

Bio3160412 Responds to BOIIIB request re transfer & ultimate disposal of 12 55-gallon steel droms of waste math. Storage & use of literace and a another location is violation of Conditions 8 2 9 of Literace SUA-1199 SCARANO. A A Uranium Recovery Literaing Branch. Bi/02/12 3pp 07916. 190

## DOCKET 40-8348 IN SITU URANIUM LEACHING PROJECT

BIOJ260983 Informs of inability so approve BIOJ18 final project rept & logs due to 12 listed problems If production cone confinement can be shown & explanation given for Ra-226 level in Well OM-2.final reclaration can proceed.

ENGELMAN.9 Wyorang, State of BI/O3/O4 293 08040 280

## DOCKET 40-0380 ROCKY MOUNTAIN ENERGY CO

B102260105 Supports amend of License SUA-1228.codifying sampling/ monitoring program for restoration circuit feed MEUMARM R. Rocky Mountain Energy Co. 80/10/14. 1p. 07587-001

B103051016 Forwards B01007 & 1107 sampling results of Pattern 3 monitor cells No significant changes have developed NEUMANI, M R. Rocky Mountain Energy Co. 80/11/19 Spp

8103260701 Forwards "Nine Mile Late Pattern IV Monitor Wells. Feb 1981 ' NEUMANN.M R Rocky Mountain Energy Co 81/02/25 ip

~-0103260705 "Nine Mile Lake Pattern IV Monitor Hells.Feb 1981" \* Rocky Mountain Energy Co 01/02/25 Bpp

8103100628 Forwards personnel manitoring rept for 1979 SPIELES.P. Rocky Mountain Energy Co. 81/03/02 Ip. 07863 029

--8103100631 Personnel monitoring rept for 1979 \* Rocky Hountain Energy Co 81/03/02 ip. 07863-030

## COCKET 40-8384 MINERALS EXPLORATION CO

8103181138 Advises that Minerals Exploration Co 801007 ameno request is unnecessary Request rejected Application requested 30-day due date extension Rept submitted before extension was granted Fee should be refunded FISHER.8 Uranium Recovery Licensing Branch. 81/03/06 1p 07994 140.

#### DOCKET 40-B432 BEAR CREEK URANIUM CO

B103120776 Responds to B01009 ltr re decision not to replace culvert on runoff diversion sys for tailings injoundment Upstream areas of culvert should be removed or plugged to prevent runoff from entering PETTEN3ILL.H J. Uranium Recovery Licensing Branch 81/02/23. 1p 07901-333

B103040473 Forwards "Semiannual Rept.Environ Monitoring, Jul-Dec 1980 " BL0580M.J N. Bear Creek Uranium Co 81/02/27 ip 07810 070.

--8103040470 'Semiannual Rept Environ Monitoring, Jul-Dec 1980." a Bear Creek Uranium Co - 81/02/27 - 13pp

B103160204 Submits contract costs & ranhours used in reviewing company 600331 application for Amend B to License SUA-1310. OARCIAP J. LINEHAN. J. Uranium Recovery Licensing Branch. 61/03/03 Ip 07918-327.

8103190120 Responds to discussions at 810203 meeting & 810210 follower litr re-deletion of 8-3 pit from consideration as bailings discosal site. Requests subnittal of alternate site study by 811013. 5CARAND.R A Uranium Recovery Licensing Branch 81/03/06. 2pp. 07965:113

8103261083 Discusses review of Bear Creek tailings mgt alternatives B-3 pit need not receive further consideration as disposal alternative Pit is located near confluence of several large

COCKET 40-8502 IRIGARAY MINE, HYOMING MINING CORP

Bi02270638 Forwards data from conitoring activities of preside causing leaks identified in R8-41.R8-42 & R8-43 pruo wells have been shut down to chloride levels decreased eversite haps enc) Aperture Cards in P0R HICHERS.D L. Wyoning Mineral Corp. 80/12/18 64PP.

8102190832 Forwards exploration hole location maps & revises, 14 for incorporation into Irigaray 1979-80 annual rept. MICHERG.D L. Wyoning Mineral Corp. 8)/01/09 1p.

--B102190837 Revised Pages 13 & 14 to "Annual Operating FRED. B00818 ' Wyoring Mineral Corp. 81/01/09 2pp 07708:040.

B102200397 Forwards well data monitoring rept. Two over \$ i # Por enc! Drawings available in PDR WICHERS.D L. Ryoming Mineral Corp 81/01/23 28pp 07

BIO3031126 Subhits review of company 800921 rept & BOO926 Sinesults of clean up operations hydrogeologic investigation & 2011 plugging operations at in situ leach mine. Operation may be safely resumed under conditions in 800821 rept. VAVIOELLT D. MARTIN, D.E. Uranium Recovery Licensing 1974.

810324003B Forwards "Irigeray Mine Bite Becond Quarterly Re. Oct-Dec 1981: W/o encl MICHERBLD L Wyoming Mineral Corp 81/02/04 lp. 0799

BIDD110304 Forwards coal fone monitoring sthams approved by of State of MY Data From Unit 2 indicate continuing problin area MICHERS D. L. Wyoming Mineral Corp. 81/02/09. 2pp. 078

8103030030 Bummary of 801009 meeting wivendor in Bethesda. M E results of NRC review of ratis submitted for continued expanded solution mining & conditions to be satisfied for authorisation of operations. MARTIN.D.E. Uranium Recovery Licensing Branch. 81/02/12 07791-212.

8103160267 Forwards LE Rykken & TE Herrera prof qualific at 1 support of 801031 application for amend to License 8UA--13 SCHENOSEL & Rygoning Hineral Corp. 81/02/16 4pp. 07

8103160365 Subrits 801211 observations at site while in spectests for HY Cept of Environ Quality Yellowcake slurry was being discharged into natural drainage RAMULDALP Affiliation Unknoun 81/02/27. 2pp.

8103180931 Forwards rept summarizing status of Evaporation Stater detected in inspitube was assumed to be from outsid source Chloride values in water indicated normal ground was levels.

MICHERS D. L. Myoming Mineral Corp. 81/03/03. Spp. OFF

B103240325 Reviews B01218 & B10123 status repts of shallow uster table contion romes for License BUA-1341. Specific casing integrity casing tests must be performed on all websfore continuing mining in Units 1-5.

VANDELL T. D. Uranium Recovery Licensing Branch. B1/03/1

#### DOCKET 40-8511 COTTER CORP.

8103120348 Forwards "Aquifer Characteristics Part 3," per completion schedule discussed in 801219-810105 & 22 ltrs MCCLUBKEY, J. P. Cotter Corp. 81/02/09. 1p. 07904-022

--0103120351 "Aquifer Characteristics.Part 3."
• Cotter Corp. COT 1028100. 81/02/09 28pp. 07906:

8103110802 Forwards Wolf Park Mine water quality data table revising 810130 itr Revision supplies originally omitted water constituent units of measurement MCCLUSKEY, A J Cotter Corp. 81/02/23 2pp. 07873: 326.

- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 8103240610 Forwards interim rept re separation in synthetic pool liner discovered on 801229 Caused by west chemical weld & mechanical stress Repairs will be completed by 810109 ENVBER.H L Minerals Exploration Co (subs of Union Oil Co. of California) 8101/06 3pp 0799 182
- Bi03060B24 Requests fee exemption for Amend 5 to License SUA-1350 issued on Bi0102.

  OILLEN.D. LINEHAN.J Uranium Recovery Licensing Branch Bi/01/28 to 078.36.129
- B103051012 Forwards Jan 1981 revised GC program for U analysis in urine.

  BNAPER H.L. Union Minerals B1/02/03 2no 07831 319
- B103130197 Forwards trip repts of B10110 & 11 visits to Sweetwater & Teton Mills to inspect pend liners Repairs are adequate. JOHNSON T L. Uranium Recovery Licensing Branch. B1/02/24, 10pp. 07908-108
- 8103120682 Amend & to License SUA-1350 revising Condition 29 to require that licensee adhere to 810203 GA program for U in urine specimens & perform spiked analysis of unknown worker specimens.

  SCARANJR A Uranium Recovery Licensing Branch 81/02/25 ip 07901:332
- 8103130187 Recommends approval of Amend & to License SUA-1350, revising Condition 29 re GA program for U in urine specimens in response to applicant 810203 ltr.
  HEYER.R.B., PETIENGILL.H.J. Uranium Recovery Licensing Branch 81/02/25. 2pp 07708 104
- BIO3100427 Informs that Bweetwater U Project Hill commissioning began on BIO214 SNyBER. If L Union Minerals. BI/03/03 ip 07893:192
- 8103230339 Notifies that Sweetwater U Project Mill commissioning began 810214
  BNYDER.H.L. Union 76 Minerals Exploration Co. 81/03/03 1p. 07980-268
- 810319013B Discusses review of Dec 1978 Preoperational Monitoring Rept & 800604 suppl data. Requests add1 info re Pb-210 activity concentrations & well monitoring data for second & third quarters 1980. PETTENDILL H. J. Occupational Health Standards Branch. 81/03/05. 2pp. 07465-104.
- 6103240487 Submits annual rept on survey within 5-mile area at U mill site.per License Condition 33. Livestock grazing & recreational activity levels remain unchanged. Transient campers declined. Oil & gas exploration is active.

  SNYDER.H.L. Hinerals Exploration Co. (subs. of Union Oil Co. of California) 81/03/16 1p 07987:359.
- 8103240490 Requests change to Amend & of License SUA-1330 issued on Bi0225 NRC approval of QA program for U in unine samples is not cost effective, due to increased workload required to analyze unthoun samples.

  SNYDER-H.L Minerals Exploration Co. (subs. of Union Dil Co. of California) BI/O3/16 ip. 07989.362.
- DOCKET 40-8595 WYOMING MINERAL CORP.
- 8103120036 Requests amend to License SUA-1315 revising License Condition 29 re degraded resin disposal Administrative change fee encl Submiss info re currently held resin for disposal. SCHENDEL, K.R. Wyoming Mineral Corp. 81/02/03. 2pp. 07900:168.
- --8103120042 Forwards fee to be processed as part of 810203 application per NRC 810117 request Unused portion should be refunded. 8CHENDEL, K. R. Wyoming Mineral Corp. 81/02/24. 1p 07900:170.
- 8103020779 Recommends revision of License Condition 10 re qualifications of plant supervisor, corporate radiation protection officer & compliance review board, per licensee 801029 application to amend License SUA-1315. HEYER, R. S. Uranium Recovery Licensing Branch. 81/02/11. 2pp. 07882.139.
- B103040635 Forwards semiannual effluent monitoring rept for Jul-Dec 1980. PLATZKE, R. N., BERG, R. E. Wyoming Mineral Corp. B1/02/26. 1p. 07815-126

- --8103040638 Semiannual effluent monitoring rept for Jul-Dec 1980.
   Wyoming Mineral Corp. 81/02/26. 1p 07815 127
- 8103260953 Recommends approval of Amend 3 to License SUA-1315 revision Condition 29 re shipping of degraded resins above specified radiologic concentration & raising concentration limits for Ra-226 % Th-230 SDLLENBERGER. D. PETTENDILL. H. J. Uranium Recovery Licensing Orance 81/03/12 200 08040 220
- B103270744 Informs that Condition 29 to License SUA-1315 has been anended requiring transfer of degraded resins above specified radiologic concentrations to either NRC-bicensed U recovery facility or to licensed dispose
- DOCKET 40-8602 UNITED NUCLEAR CORP
- 8103090645 Forwards "Morton Ranch Annual Land Use Survey.Jan-Dec 1980 per License Condition 33 Two oversize drawings encl Aperture cards in PDR WOLFF.C E United Nuclear Corp., UNC Recovery Systems Div 81/02/26. | jp 07844 286
- --B103090652 'Morton Ranch Annual Land Use Survey.Jan-Dec 1980 "

   United Nuclear Corp . UNC Recovery Systems Div. B1/02/26 2
- DOCKET 40-8610 STEPAN CHEMICAL CO
- BiO310064B Responds to B01211 ltr re-proximity to area indicated in Bergen County Record B01704 article "Radiation Under Study in Two Tours." Proximity to area under study does not increase radiation exposure to employees KINNEMAN, J. D. Region I. Philadelphia. Fuel Facility & Materials Safety Branch. 81/01/22 ip 07863 011.
- --Bi03100651 Requests info re facility location & level of radiation, response to anci Bergen County Record B01204 article.
  "Radiation Under Study in Two Forms '
  COLLINS.J.J. Fimeplex.inc B0/12/11. 2pp. 07863-012
- 8103110197 Ack receipt of 801211 ltr re newspaper article. "Radiation Under Study in Too Towns." NRC will have area surveyed aerially KINNEMAN. J.D. Region 1. Philadelphia. Fuel Facility & Materials Sefetu Branch 51/01/22 to 07803-246.
- --BIO3110206 Forwards newspaper article. "Radiation Under Study in Ju Towns: "Requests add1 info. PALMIOTTO.N. STC Systems-Inc. 89/12/11. 3pp. 07884.247
- Bi03040480 Forwards regulations.past & present licenses & site plan r licensed activities of Maywood Chemical Works & Stepan Chemical Co Regulations not enci. XINNEMAN.J.D. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. Bi/01/29 1p.
- --BIO3040493 License authorizing possession of & title to raw source & transfer of matl to licensed person within limits of license by Maywood Chemical Works. JOHNSON, L. Atomic Energy Commission. 94/04/01. 1p
- ~~8103040499 License authorizing possession of & title to raw source & transfer of hat1 to licensed person within limits of license by Maywood Chemical Horks
  JOHNSON.L. Atomic Energy Commission. 36/11/19. 2pp.
- --Bi03040507 License authorizing possession of & title to raw source & transfer of matl to licensed person within limits of license by Maywood Chemical Morks. DELANEY, J. C. Atonic Energy Commission 58/12/01. 1p.
- --Biogo40515 License authorizing possession of & title to raw source & trensfer of matl to licensed person within limits of license by Maywood Chemical Morts.

  DELANEY.J.C. Atomic Energy Commission. 60/01/04. 1p.
- --8103040521 License authoriting possession & use of source matl for resale only by Maywood Chemical Works.

  DELANEY, J. C. Atomic Energy Commission. 61/03/07. 1p.
- --8103040928 License authorizing possession & use of source matl for decontemination, storage & resals only by Btepan Chemical Co. NUSSBAUMER.D A. Atomic Energy Commission 64/06/26. 1p.

- --BIO3040539 Litense authorizing underground storage of source tail by Stepan Chemical Co. Site plan enti BASSIM Radioisotopes Litensing Branch (Fre 770501) 78/C4/04
- 8103260048 Addi response to FOIA request for all categories of info re radioactive ratis found in Maymood & Rochelle Park.NJ Forwards documents listed in App A Documents 1.2 & 6 partially uithheld have addresses (ref FOIA Exemption 5) FELTOW. JH Division of Rules and Records B1/03/03
- --Bi03260103 Responds to B012(1 ltm re newspaper article entitled "Radiation Under Study in Two Towns" Company employees are not endangered by proximity to specified area KIMEMANUAD. Region 1. Philadelphia. Diffice of the Director B1/01/22 lp.
- --8103260113 Responds to 801112 ltr re newspaper article entitled "Radiation Under Study in Two Towns " There is no immediate haiard to public health & safety Survey results will be made public upon completion BI/OP/22 to Birector
- ---8103250161 Forwards maps & drawings to assist in preparation of proposed serial survey of Stopan Chemical Co Large quantities of thorium were processed on site 1916-56. (Newspaper articles & list of meeting attendees enct KIN'EMAN. J D. Region 1. Philadelphia, Office of the Director 80/12/18 Bos
- --8103263174 Notification of 801203 meeting between NRC. Stepan Chemical Co & state & local representatives in Maywood NJ re presence of radioactive mat) in unrestricted area mear facility & to destribe Puture NRC survey plans Handwritten notes enci COSIELLO.F Region I. Philadelphia. Diffice of the Director. 80/12/02 2pp
- --8103260171 Requests plan for disposal of radwaste currently on premises Plan should include time ostimate to rerove accumulated waste & description of radiation survey, air sampling & bibassay requirements GUINNIP R Asi B0/09/16 Ess Assistant Director for Material Bafety & Licensins
- --BIO326019B Requests status of application for amend to License BTC-1333 I Levenstein BO3829 ltr retesting of soil in Maywood, UJ encl SWANSON, E. A. Stepan Chemical Co. 80/09/09 230
- --8103260255 Forwards signed check for amend to Mati/Byproduct License STC-1333. Apalegites for sending unsigned check.
  SHANSON, E.A. Biepan Chemical Co. 80/04/11 10
- ---B103260241 Returns theck submitted on B00221 re request for amend to Mati/Byproduct License STC-1333 Check was not signed.

  JACKSON G License Fee Management Branch. BD/04/08 10
- --8103240247 Forwards check for amend of Matl/Byproduct License STC-1333 SWANSOW E. A. Stepan Chemical Co. 80/03/23 lp.
- --BIOJE60254 Ack receipt of 800221 itr requesting amend of Matl/Byproduct License STC-1333. Requests amend fee JACKBON, G. License Fee Management Branch. 80/03/18 1p
- --B103240263 Requests amend of Matl/Ouproduct License BTC-1333 to delete survey & sampling requirements SWANSON, E. A. Stepan Chemical Co. 80/02/21. 7pp.
- --Bi03260281 Forwards License BTC-1333, authorizing possession of thorium tailings buried on property Recommends license termination BABBIN.N. Radioisatopes Licensing Brench (Fre 790501). 78/04/04.
- --8103260319 Forwards application for renewal of License STC-130 Includes application fee. Swahmed Co. 77/03/02: 1p
- --BI03260325 Application for renewal of Source Matl License BTC-i30, authorizing burial of 9.500 CI thorium waste tailings at two SWANSON, E. A. Stepan Chemical Co 77/03/02. 2pp.

- DOCKET 40-8663 NUCLEAR DYNAMICS, INC.
- 8103180802 Forwards WY Dept of Environ Quality 791003 ltr of approva to perform resotration stabilization tests
  CARNADAY, F. X. Nuclear Dunamics. 79/11/06 [n. 07953 357
- 8103240642 Forwards ennual insp rept for Oshoto ISL test MORROW, D. Nyoning, State of 80/09/22 3pp
- DOCKET 40-8674 PLATEAU RESOURCES, LTD
- B103050186 Bubmits effluent monitoring rept Por Jul-Dec 1780 ALLEN D J Plateau Respurces, Ltd. 81/02/25, 2pp 07827 039
- 8:03:80027 Submits effluent monitoring rept for Jul-Dec 1980, covering Quantities of gaseous & liquid effluents released to unrestricted areas ALLEN.D J Platoau Resources, Ltd B1/02/25 200, 07944-040
- DOCHET 40-96B1 ENERGY FUELS NUCLEAR, INC.
- B103050879 Ack receipt of NRC 810114 ltr re mad to White Mesa 10.00008/9 Ack receipt or NNC BIOLIA itr re mod to White Mes. memorand wim of agreement Mods accurately reflect state position. Approval of Plano Consultants is reserved, pending receipt of final rept 541TH. If Utah. State of B1/02/02 ip 07829:346.
- DOCKET 40-8693 DOLE PETROLEUM, INC.
- 8103130457 Bubbits environ monitoring querterly rept for Nov 1980 J 1981 for pilot in-situ U solution mining operation SAUNDERG. 0 A . CATCHPOLE. 0. J. Ogle Petroleum, Inc. 81/03/03.
- 8103310504 Submits special rept on monitor well analytical results resampling of Wells 303-6-N & M 4.per Condition 17 to License 6UA-1336
- BAUNDERB. O A , CATCHPOLE. O J Ogle Petroleum, Inc. 81/03/29. 30a
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO.
- BIO3100628 Forwards personnel nonitoring rept for 1979. GPIELEB.P Rocky Mountain Energy Co. 81/03/02. 1p. 07863:029
- --B103100631 Personnel monitoring rept for 1979, Rocky Mountain Energy Co. 01/03/02, 1p, 07863:030.
- DGCKET 40-8498 PLATEAU REBOURCES, LTD.
- 810309074B Informs that "Mill Bite Reclamation Contract" w/State of U is unacceptable Contractual mechanism does not provide adequate assumance that sufficient funds will be available to perform reclamation & decommissioning SCARAGO, R. A. Uranium Recovery Licensing Branch. 81/02/06. 2pp. 02844 188
- B103090186 Bubmits effluent monitoring rept for Jul-Dec 1980. ALLEN-D. J Plateau Resources. Ltd 81/02/25 2pp. 07827.039.
- 8103180027 Bubmits effluent monitoring rept for Jul-Dec 1980, covering quantities of gaseous & liquid effluents released to unrestricted ereas. ALLEN.D. J. Plateau Resources, Ltd. 81/02/29, 2pp. 07944:040.
- 9103160221 Requests that IE perform preoperational insp for mill prior to startup of milling operations. Insp should include both mill & tailings impoundment.

  BCARANOR A. Uranium Recovery Litensing Branch. 81/02/26. 1p 07918 344
- B103040464 Submits effluent monitoring rept for 1780 Gaseaus effluente totalled 9.3 Ci Rn-282 No liquid effluents released. JACKSON, K.E. Plateau Resources, Ltd. 81/02/27. 1p. 07812:339.

#### 118 Submits efficent monitoring rept.Jul-Dec 1980 DN.K.E. Plateau Resources. Ltd. 81/02/27 1p 07971 249

40-8700 ARMY, DEPT DF

341 IE Insp Findings & Licensee Ack dtd 810302-03 of License 340. Insp findings a cicensee Act at 810302-03 of License 340. Insp findings. no noncompliance noted. ERLY.L.W Region 3, Chicago, Office of the Director. 81/03/03 07996-344

40-8702 ARMY, DEPT. OF, ARMAMENT MAT READINESS COMMAND

224 Forwards IE Inso Rept 40-8702/80-04 on 801120 No. ppliance noted

1AN.J.D. Region 1. Philadelphia, Fuel Facility & Materials

2 Branch 81/01/07 2pp 07839:292.

60259 IE Inap Rept 40-8702/80-04 on 801120 No noncompliance noted or areas inspected decontamination plans & schedules & specifent measurements of grab samples of soil & metl in 

308 Forwards IE Inso Rept 40-8702/80-05 on 801218 No. poliance noted.

ANN.J D. Region 1. Philadelphia. Fuel Facility & Materials.

Branch 01/01/22. 2pp. 07944.235.

30324 IE Insp Rept 40-8702/80-05 on 801218 No noncompliance noted or areas inspected decontamination plans & schedules & spendent measurements of Bldgs 46.521 & 308 (B. J B. ROME.C. Region i. Philadelphia. Office of the sctor KINNEMAN.J.D. Region 1. Philadelphia. Fuel Facility & sctor KINNEMAN.J.D. Region 1. Philadelphia. Fuel Facility & scrials Bafety Branch (BI/01/21) 2pp 07944.237

0-8714 CLEVELAND CLIFFE IRON CO.

301 Notifies of personnel & telephone number changes Contact is JE Louderback. Executive in charge is JB Hollister. BACK, J. E. Claveland-Cliffs Iron Co. BI/01/06, ip 248

ISS Discusses results of samples from well field Monitor Well selved for sulfate arsenic & selenium. Sulfate tration is not related to excursion of mine rone wals. No possible corrective actions known.

BACK.T.E. Cleveland-Cliffs Iron Co. 81/02/09, 3pp.

18 Confirms 810203 request for authorization to operate ch ammonta stripping tube at in situ mine & to remove a from restoration groundwater. Pages to be orated in license application encl. BACK.T.E. Cleveland-Cliffs from Co. 81/02/10. 12pp. 092.

38 Forwards excerpts from Cleveland Cliff in situ R&D license ents & responses re monitoring of leach field. T.M.A. Wyaming: State of. 81/03/04, 13pp. 07946:103

39 Returns check sent w/810210 request for amend to e SUA-1352. Amend not required. D. License Fee Management Branch. 81/03/05. ip. 07916:200.

18 Advises that 810210 proposal to operate ammonia stripping a within ecope of existing license. No amend is aru. O.R.A. Uranium Recovery Licensing Branch. 81/03/11. 1p.

150.

64 Discusses review of Cleveland Cliffs Iron Co 810210 Itr ting license amend to operate research ammonia ing tube at Collins Draw Bince stripping operation is scope of license, no amend necessary. U.A. Uramium Recovery Licensing Branch. 81/03/11. 2pp 122.

## DOCKET 40-8722 BRUSH-WELLMAN, THE

8103060244 Requests addl info re 791115 plan for decompissioning U recovery circuit More detailed description of decontamination & reclamation procedures is negeted. Revised Plan must be submitted by 810403

SCARAND.R A Uranium Recovery Licensing Branch 81/02/11 200

# DOCKET 40-8726 NEW MEXICO HEALTH - ENVIRONMENT DEPT

8103240331 Trip rept re 791029-1101 site visits re proposed U in site extraction operations Scoping meeting held B01101 for Bison Basin project List of attendees enc! XAUFHAMAR S Uranium Recovery Licensing Branch B0/03/20 Spp. 07982 235

## DOCKET 40-8728 TETON EXPLORATION DRILLING CD . INC.

8103130197 Forwards trip repts of 810110 & 11 visits to Sweetwater & Teton Mills to inspect pond liners Repairs are adequate
JOHNBON T L Uranium Recovery Licensing Branch 81/02/24, 10nn

8103i60184 Discusses review of facility waste disposal plan to bury wastes in solar evaporation pends Facility should be required to revise plah to include ultimate disposal at existing licensed tailings disposal site existing Licensed tailings disposal site EAATHER, J C Uranium Recovery Licensing Branch 81/03/03 1p. 07918:317

### DOCKET 40-8743 CONDON, SAND ROCK MILL PROJECT

B103120596 Requests issuance of RFPAs for technical assistance task orders to extend term of & change NRC project officer on CO State Univ beilings mpt long-term stability review & change NRC officer v/Ott Water Engineers.

MRC officer v/Ott Water Engineers.

MRTIN.J.B. Division of Waste Management. FIN 8-7308-1. 81/02/23 10 07901 331

## DOCKET 40-8745 CLOS PETROLEUM. INC.

Bi03240331 Trip rept re 791029-1101 site visits re proposed U in site extraction operations Scoping meeting held B01101 for Bison

Basin project List of attendees ancl.

KAUFMAN.R S. Uranium Recovery Licensing Branch B0/03/20 Spp 07982 235

8103170113 Responds to licenses 801229 ltr re authorization to drill up to 100 wells at Bison Basin facility NRC is available to explore alternate measures SCARANO.R A. Urantum Recovery Licensing Branch 81/03/03 ip 02939-028

### DOCKET 40-8760 EDLOW INTERNATIONAL CORP

8103130248 Ack receipt of 810212 ltr informing NRC of steps taken to correct violations noted in IE insp of License 6NC-1377 FIBHER.M.L. Region 3. Chicago. Fuel Facility & Materials Safety Stanch. 81/02/25. ip. 07911.101.

--Bi03130255 Responds to NRC Bi0128 ltr re violations noted in IE insp of License BMC-1377. Corrective actions: detectors placed at locations noted on data sheet w/instructions to warshouse personnel for locating detectors.

EDLOW, J Edlow International Co. B1/02/12 4pp. 07911:102.

# DOCKET 40-8781 TETON EXPLORATION DRILLING CO. . INC.

8103060124 Forwards application to State of MY Dept of Environ Quality for permit to mine.Forwarding 1tr to ORNL only encl.

APPELIAR R. Teton Exploration Drilling Co., Inc. 81/02/06. 2pp. 07839.039.

8103060395 Forwards ref documentation for preparation of EIS for in situ U leaching facility.per 810203 telcon.H/o encle. LINEHAN.J J. Uranium Recovery Licensing Branch. 81/02/12 1p. 07835: 360.

- B103190795 Forwards commercial application to assist review effort W/o encl encl APPEL R R United Nuclear Corp. B1/02/24 ip 07965-229
- DOCKET 40-8785 URANIUM RESOURCES, INC.
- B10305032B Summary of B10115 reeting U/U Resources. Inc re status of proposed A&D in situ leach site near Glennock MY Bcheratics of Lell field area, Geologic X section % evaporation ponds encl VANOBLL. T D Uranium Recovery Licensing Branch B1/02/12 App
- COCKET 40-8788 UNION CARBIDE CORP

07826 051

B103200111 Advises that new license application fee will be required. Father than amend fee originally requested W/o encl. WFIGS.D. License Fee Management Branch 81/03/04 ip 07972.168

# DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- COCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 9103060437 Forwards organizational thants depicting NRC Region 3 reorganization, effective 810216.

  XEPPLER J 0 Region 3. Chicago. Office of the Director 81/02/20 2nn 07836 015
- Q inspection reports: IE Bulletins & correspondence
- G103181111 Forwards IE loap Rept 50-002/81-01 on 610126-20 & notice of violation HEISHMAN, R. F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 61/02/10 2pp 07933-128
- --Bio3lBiil3 Natice of violation from inep on Bio126-28 HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch, 81/02/10 ip. 07953 130
- --B103181123 IE Insp Rept 50-002/B1-01 on B10126-28 Noncompliance noted primary coolant sys surveillance not completed in entirety during 1983 Christmas shutdown RIDGMAY.K R. PESCHELJ H. BDYD.D C. Region 3. Chicago, Office of the Director. B1/02/09 Spp. 07953.131
- DOCKET 50-3 INDIAN POINT STATION. UNIT 1
- F Security, medical, emergency & fire protection plans
- B101070352 Releases public version of NRC comments on util revised emergency plan.
  FELTON J. M. Division of Rules and Records 80/12/01. 1p
  07403-149
- --8101220618 Forwards public version of util revised energoncy plan CAHILL.H.J. Consolidated Edison Co. of New York 80/02/14. 7pp. 04021.048
- --8101070334 Public version of Revision 2 to emergency plan for factifities a Consolidated Edison Co of New York. 80/02/29 80pp. 07403-151
- B103;B0264 Ltr to all power reactor licenses u/plants licensed prior to 790;01. Forwards NRC position & request for add1 info re eafe shutdown capability for compliance u/B01;119 fire protection rule.

  EISENHUT.D Q. Division of Licensing. B1/02/20. 13pp 07944:105.
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. U/o encl.

  ELSENHUT-D.O Division of Licensing 81/03/05. 692. Q8Q79-077
- 8103260392 Responds to 810128 & 29 lirs, expressing concern that NRC may adopt emergency response plans for facility environs w/o signatures of four counties on plans NRC rule requires 810401 implementation, except for alert & notification sys STELLO.V Director's Office. Office of Inspection and Enforcement.

- O Adjudicatory correspondence
- BIO3030707 Forwards application for amend to Observation conradiologic environ protection plan necessary to permit implementation settlatent agreement re condenser cooling sys Class I & III amend fees encl
  BAYRE. J P Power Authority of the State of New York 81/02/27
- --8103030717 Settlement agreement between EPA, State of NY, Con Ed, PASN Central Hudson Gas & Electric Corp. Orange & Rockland Utils, Inc. Nigara Motauk Power Corp. NRDC & Scenic Hudson, Inc recondenser cooling sus environmental Protection Agency. 80/12/19 69pp
- --Bi03030733 Joint notion seeking order deleting from OLs existing requirement for termination of operation of units w/once-through cooling Draft stipulations & affidavits of svc re-motion & Bi0227 application to amend OL encl PRAIT.C.N Power Authority of the State of New York 81/02/27 37on
- P. Operating license stage documents & correspondence
- 8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR natice of final rule SEP plants need not comply w/rule until program is complete Non-BEP plants nust comply within specified time frame EISENHUT.D @ Division of Licensing 80/12/15. 13pp.
- B103190732 Litrs to all licensees of operating plants, applicants for OLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREQ-0612 Forwards NRC position reinterin actions & request for add
- 8103190732 Ltrs to all licensess of operating plants, applicants for OLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREG-0612. Forwards NRC position reinterim actions & request for addl info. FIRMHULD 0. Division of Licensing. 80/12/22. 30pp.
- BIO31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs rs program for environ qualification of mafety-related electrical equipment Items addressed involve cold shutdown: replacement parts & NUREG-0737.
  EISENHUTID 0. Division of Licensing. BI/01/19 dep. 07964:090.
- 8103120014 Ltr to all licensees of operating plants, CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & THI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads.
  ETSENHUT, D. G. Division of Licensing. 81/02/03. 6pp.
- B100300160 Ltr to all operating PWR licenses requesting info on euriliary feedwater sys seismic design Forwards request for addl info. list of actions requested of licensess w/o seismically qualified sys & results of RCC walkdowns.
  EIBENHUT, D. O Division of Licensing. 81/02/10. 13pp. 08053:145.
- 8)03160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A.1.2 re upgrade of emorgency support facilities. Requests confirmation within 45 days that implementation dates will be met EISENNUT.D.O. Division of Licensing. 81/02/18. 12pp. 07915:247
- B103250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may subsit analysis to justify use of existing low flow controller.
  EISENHUT.D.O. Division of Licensing. 81/02/20. 8pp. 07997:161.
- 8103230030 Ltr to all licensess of operating nuclear power plants & applicants for OLs (except Bt Lucis, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures, EISENHUT, D. C. Division of Licensing. 81/02/25. 5pp. 07980:269.
- 8103230B13 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR30.71(a), "Periodic Updating of FSARs," effective 800722 Info re PSAR legal status format & content encl EISERHUT.D.O. Division of Licensing. 81/02/26.

- 8103030707 Forwards application for amend to DLs adding nonradiological environ protection plan necessary to permit implementation settlement agreement re condenser conling sys Class 1 & III amend fees encl.

  8AYIGLUP Power Authority of the State of New York 0'TOOLE. J D Consolidated Edison Co of New York 81/02/27. 2pp. 07799 232
- --BIO3030712 Application to amend Licenses DPR-9.DPR-26 & DPR-64, adding nonradiological environ protection plan necessary to permit implementation of settlement agreement re condenser cooling sys.

  BAYNE, J. P. Power Authority of the State of New York D-TOOLE, J.D. Consolidated Edison Co. of New York. BI/02/27 4pp. 07799-234
- --8103030717 Settlement agreement between EPA State of NY.Con Ed.PASNY.
  Central Hudson Gas & Electric Corp. Grange & Rockland Utils.
  Inc.Nigara Mohauk Power Corp.NRDC & Scenic Hudson. Inc re
  condenser cooling sys
  Environmental Protection Agency. 
  Consolidated Edison Co. of New York. 80/12/19. 69pp. 07799.238.
- --8103030720 Proposed ETS Environ protection plan (nonrediplogical)

   Consolidated Edison Co of New York 81/02/27 14pp
- --BIO3030723 Proposed ETS (radiological) for facilities deleting nonradiological requirements

  a Consolidated Edison Co. of New York B1/02/27 68pp 0779 322
- --BI03030726 Proposed ETS Environ protection plan (nonradiological).

   Power Authority of the State of New York. 81/02/27. 14pp.
  07800:028
- --Bi03030729 Proposed ETB (radiological) for facility, deleting nonradiological requirements. Bafety evaluation: environ inpact evaluation & cost-benefit analysis and:
   Power Authority of the State of New York. 01/02/27. 70pp. 02800 042
- --Bi03030733 Joint motion seeking order deleting from QLs existing requirement for termination of operation of units w/once-through cooling. Draft stipulations & affidavits of svc re-motion & Bi0227 application to amend QL encl. PRAYT.C. H. Power Authority of the Btate of New York. BRADENBURG.B.L. Consolidated Edison Co. of New York. 81/02/27. 37pp. 07800:108
- 8103310804 Ltr to all licensees of operating plants applicants for OLs tholders of CPs forwarding SECY-81-119 re info necessary to astablish environ qualification of safety-related electrical equipment EIBENMUT. D. O. Division of Licensing. 81/03/10. 6pp 08077:270.
- --BIO3160B39 Informs that objections have been raised by certain aquipment vandors re NRC handling of info concerning Class IE electrical equipment. Bummary data alone is not acceptable to qualify equipment.

  DIRCKB.H.J. Office of the Executive Director for Operations.

  SECY-B1-119. B1/02/24 2pp. 65119.146.
- 8103130391 Forwards application to amend OLs:revising Tech Boacs refacility mpt, technical support & organization Class I & II amend fees & affidavit of svc encl.
  O'TQOLE: J. D. Consolidated Edison Co. of New York. 81/03/11. 3pp. 07908:199.
- --8103130408 Application to amend Licenses DPR-3 & DPR-26 changing Tech Bpecs 3.1 & 6.0 of Units 1 & 2.respectively.re facility mgt. technical support & organization. D'TOOLE.J D. Consolidated Edison Co. of Naw York. 81/03/11. 2pp. 07908.202
- --8103130412 Proposed Tech Spacs 3.1 & 6.0 of Units 1 & 2, respectively, revising facility mgt, technical support & organization.

  4 Consolidated Edison Co. of New York 81/03/11. 16pp. 07908:204.
- G. Inspection reports: IE Bulletins & correspondence
- B103040205 Forwards IE Info Natice 81-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/10CFR50.72." No written response required. GRIER.B.H. Region 1. Philadelphia, Dffice of the Director. 81/02/12 ip. 07813:135.
- 8103200145 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required. ORIER\_B.H. Region 1. Philadelphia, Office of the Director. 81/02/27. 1p. 07971:351.

- 8103200149 Forwards IE Circular 81-03, 'Inoperable Seismic Monitori Instrumentation' No written response required. GRIER, B H. Region I. Philadelphia, Office of the Director 81/03/02 ip 07971 353
- B103200091 Forwards revised IE Bulletin B1-01. "Surveillance of Machanical Snubbers." w/corrected Pages 3 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements CRIER. B. H. Region 1. Philadelphia. Office of the Director. B1/03/04 ip 07968 219
- 8103200206 Forwards IE Info Notice 81-06. "Failure of ITE Model K-6 Circuit Breaker" No response required GRIER.B H Region 1. Philadelphia. Office of the Director 81/03/11 1p 07968 316
- R Periodic operating reports & related correspondence
- B103100517 Forwards "Effluent & Waste Disposal Semiannual Rept. Jul-1980." O'100LE. J D Consolidated Edison Co of New York 81/03/01. 1p 07867-165
- ~~8103100518 "Effluent & Weste Disposal Seniannual Rept. Jul-Dec 198 \* Consolidated Edison Co of New York 81/03/01, 43pp 07867: 166
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

  8 Reportable occurrences, LERs & related correspondence
- Bi03060609 RD. on Bi0217-discovered that activation of electrical connections for two panel lights prevented console switch from disconnecting power from control rods Caused by faulty installation Lights were reconnected to separate power LEVINE.S H Pennsylvania State Univ. 81/02/27 45pp 07840.29:
- DOCKET 90-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plane
- B103040336 Forwards summary of staff requirements to resolve open it & FR notice refire protection features. Applicable provisions of App R-effective B10217, discussed W/a encl. B18ENHUT.D.O. Division of Licensing. 80/11/24 7pp 07820 126.
- 8101080051 Releases public version of util draft emergency plan NAMEG-0654 (nfo enc) FELTON.J.M. Division of Rules and Records 80/12/02 (Bpp 07416-038
- --Bibi230943 Forwards public version of draft energency plan for generating stations
  PEDPLES.D. Commonwealth Edison Co. 80/04/24 3pp. 04837;14
- --Bi01080068 Public version of draft emergency plan for generating stations.

  \* Commonwealth Edison Co 80/07/31 150pp. 07416:056.
- B1010B0003 Releases public version of util revised draft emergency plan. FELTON, J. H. Division of Rules and Records. 80/12/03 ip
- --Bi01220258 Forwards public version of util revised draft energence w/station ennerges.
  PEOPLES.D.L. Commonwealth Edison Co B0/06/04. 2pp. 05370:00
- --B101080014 Public version of draft emergency plan annex.

  \* Commonwealth Edison Co. 80/07/31. 48pp. 07417.002

07417:001.

- --Bi010B0019 Public version of Revision 1 to draft Amergency plan.
  \* Commonwealth Edison Co. 80/07/31 139pp 07417:031.
- --Bi010B0029 Public version of draft emergency plan annex \* Commonwealth Edison Co B0/07/31. 90pp 07417 191.
- --B1010B0033 Public version of draft emergency plan annex. \* Commonwealth Edison Co. B0/07/31 52pp 07417:242.
- --8101080039 Public version of draft emergency plan annex.
  \*\* Communuealth Edison Co. 80/07/3!. 37pp 07417:294

- Bib3041004 Forwards fire protection review of incomplete items identified in fire protection safety evaluation Several requirements have been satisfactorily resolved by litensee action subsequent to MRC EG0709 & 1124 ltms CRUTCHFIELD, D. Operating Reactors Branch 5 81/02/10 5pp 07812-187
- 8103185264 Ltr to all power reactor licensees u/plants licensed prior to 790(0) Forwards NRC position & request for addl info resafe shutdon capability for compliance u/80(1)19 fire protection rule
  FISCHWILLD O Division of Licensian BA/02/22 13cc
- BIODDIO33B Lir to all licensees of operating plants 5 holders of CPs forwarding NUREO-0596. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for reeting NRC requirements M/o enci
- 8103130740 Ack receipt of 810217 request for completion date extension for fire protection mod Class II fee required DIGOS.R M License Fee Management Branch 81/03/06 1p 07912-058
- 8103170250 Grants request for extension of time for co-pletion of fire protection mads to 810319 & 811217 Facility must remain shut down through entire period Reactor or primary containment structure must not contain fuel during period DENTOTH R Office of Nuclear Reactor Regulation. Director 81/03/06 3pc. 07925 253
- --8103170256 Notice of extension of fire protection mod completion dates.

  DENTON-H R Office of Notlear Reactor Regulation. Director

  81/03/06 1p 07/25 256.
- 8103240340 Requests that completion date for required fire protection features be revised to prior to facility startup from refueling-mod 6 chemical cleaning outage. Lists bases for elegation request ABELL 15 Correnuealth Edison Co. 81/03/17 200 07987 348
- 8103260123 Concurs w/801217 request to install two-way headset jacks on specified emergency notification says 5 health physics telephones provided that use will be discontinued if communications quality unacceptably degraded #FPPLER.10 Region 3. Chicago. Office of the Director 81/03/17. ip 08042 129
- --Bi03260137 Subrits location for installation of one-way headset jacks on emergency notification sys & health physics network per B01119 request Requests concurrence by 010201
  RAUSCH-T J. Commonwealth Edison Co. 80/12/17 2pp 08042 130
- Bio3250685 Releases public version of implementing procedures for emergency plan. FELTON-UM Division of Rules and Records 81/03/19 ip 07806 001.
- --BI03250702 Public version of emergency plan implementing procedures for corporate command cir.environ director & plant-specific procedures.

   Commanwealth Edison Co 91/02/27. 1400pp. 07806-001
- H. General correspondence
- B103020113 Add1 response to FDIA request for three categories of documents re facility decontamination Forwards documents listed in App A FELTCM.J M Division of Rules and Records B1/02/23 2gp. 07703.090
- ---8103020120 Forwards response to K Drey litring use of chelates in facility decontamination FEB discusses solidification of wastes & identifies independent tests to confirm that wastes will be solid BROWNING.R E. Division of Waste Management. 80/12/29, 3pp
- --8103020124 Forwards LA Drey request for info re facility decontamination Requests response BROWNING.R.E. Division of Maste Management. 80/11/06 jp

### ] Financial information

- 8103310613 Forwards guarantee of payment of deferred premiums for 1981 per NRC request nRTER.J Commonwealth Edison Co 81/03/27 1p
- --BIO3310620 Forwards Annual Rept for CY30 & statement of internal cash file projected for 1981 & actual for 1980 per provisions of 10CPR140,Chapter 1.Bection 140 21 & ARC 770615 ltr NEXC9.H H Componwealth Edison Co. 81/03/27 6pp
- J. Insurance & indemnity information
- 8103090581 Forwards Endorsement 5 to NELIA Binders EB-1.EB-2.EB-3, EB-29.EB-30.EB-42.EB-43. MAELU Binders XB-1.XB-2.XB-3.XB-43
- P Caerating license stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NURG-0612. Forwards NRC position reinterim actions & request for addlinfo EISENUT.D O Division of Licensing B0/12/22 30pp
- B103190387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment items addressed involve cold shutdown replacement parts & NUREO-0737 EISERMUT.D Q. Division of Licensing B10/1/19 App.
- B103240290 Ltr to all BHR licensess forwarding Suppl 1 to generic safety evaluation on DWR scram discharge sys Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation.
  EISEKHUT.D 0 Division of Licensing 81/01/23 2pp. 07986.312
- --8103240336 Suppl | to generic tafety evaluation on BWR scram discharge sut Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation # Division of Licensing. 81/01/12 8pp 07986-314
- 6102260268 Qeneric Ltr 81-08 to all holders of CPs & DLs for BHRs. forwarding safety evaluation & supplemental safety evaluation re NEOD-24159 & NEOE-24159-P. 'Qualification of Dne-Olmensional Core Transfent Hodel for BHRs 'EISEMIUT.D & Division of Licensing 81/01/29. 3pp.
- 8103120014 Ltr to all licenses of operating plants CP holders & OL applicants except Indian Point 2 & 3.7ion 1 & 2 & THI-1. forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads.
  EISENNUT.D O. Division of Licensing. 01/02/03 App.
- 8103180894 Forwards Amends 33.56 & 49 to Licenses DPR-2.0PR-19 & DPR-23, respectively & notice of issuance & availability CRUTCHFIELD.D. Operating Reactors Branch 5. 81/02/11. 3pp. 07953-217
- --810318086; Amends 33.36 & 49 to Licenses DPR-2.DPR-19 & DPR-25, respectively, adding requirement to naintain guard training & qualification plan to be implemented within 60 days Becurity personnel to be qualified within 2 yrs. CRUICHFIELD.D. Operating Reactors Branch 3 IPPOLITO.T A Operating Reactors Branch 6pp 07793: 220.
- ~-8103180871 Notice of issuance 5 availability of Amends 33.56 & 49 to Licenses DPR-2.DPR-19 & DPR-25.respectively CRUICHFIELD, D. Operating Reactors Branch 5 81/02/11. 2pp. 0793-7254
- 8103160569 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A.1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.0 0 Division of Licensing. 81/02/18. 12pp.
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216. KEPPLERJ 9. Region 3. Chicago, Office of the Director. 81/02/20. 2pp 07865:219
- Bi03250024 Ltr to all power reactor licensess & license applicants re NUREO-Obj9 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licenses may submit analysis to justify use of existing low flow controller EISENMUT.D.O. Division of Licensing 81/02/20. 8pp. 07997.141

- 8(03230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 5t Lycle, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & propetly implement emergency procedures EISENHUT, D O. Division of Licensing 81/02/25. Spp
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends & fitting mati per guidelines of encl Revision 1 to NUREG-0313 Model Tech Bpecs only encl EIBENHUT, D O Division of Licensing 81/02/26 3pp 07934 315
- --8103170266 Model Tech Specs Pages 3/4 0-2/3/4 0-3/3/4 4-7 & 3/4 4-8 re surveillance requirements for ABME Code Class 1/2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements • General Electric Co 81/02/26. 4pp 07934/318
- 8103230813 Generic Ltr 81-06 to all CP holders & DL applicants re 10CFR90 71(e). "Periodic Updating of FSARs." effective 860722 Info re FSAR legal status, format & content enci EISENHUT.D Q Division of Licensing 81/02/26 10pp
- BiO33IG804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding BECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  FIBENHULT, D Q Division of Licensina 81/03/10 App.
- 8103180517 Informs NRC that util will continue to require full radiation training for MRC personnel entering radiation areas at facilities, pending further MRC communications TRAMM.T R Communusalth Edison Co. 81/03/11, 1p. 07944:201.
- B103200351 Forwards revised abstract & Pages 2-2,4-2,4-5,7-2 & 18-2 of CE-1-A, Revision 16 re GA program Revisions reflect ASME winter addends code changes changes made per ASME survey & clarifications & corrections TRAMM, T.R. Commonwealth Edison Co 81/03/16, 1p. 07971 038
- --BI03200369 Revised abstract % Pages 2-2, 4-2, 4-5, 7-2 & 10-2 of Revision 16 to GA program

  \* Commonwealth Edison Co. CE-1-A R16 BI/03/16. 6pp. 07971-039
- Q. Inspection reports. IE Bulletins & correspondence
- 8103130227 Forwards IE Insp Repts 50-010/80-23,30-237/80-25 & 50-249/80-30 on 801115-1231 & notice of violation. HEIBHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 81/02/03 2pp. 07912-193.
- --9103130233 Notice of violation from insp on 801115-1231 HCIBHMAN F. Raylon 3. Chicago, Reactor Operations Nuclear Bupport Branch. BI/02/03. 1p. 07912-195.
- --8103130245 IE Insp Repts 50-010/80-23.50-237/80-25 & 50-249/80-30 on 801110-1231. Noncompliance noted pressure regulator setpoint below reactor pressure during startup resulting in reactor scram.
  TORQUE, T. M., REIMANN, F. W., JORDAN, M. J., Region 3, Chicago, Office of the Director. 81/02/02 10pp. 07912:196
- 8103020115 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals Hhile on Duty." No written response required. KEPPLER. J. G. Region J. Chicago, Office of the Director. 81/02/09. 2pp. 07788.020.
- 8103040251 Forwards IE Info Notice 81-03, "Checklist for Licensess Making Notifications of Significant Events In Accordance W/IOCFR50, 72." No written response required. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 81/02/12. 2pp. 07813.283
- 8103030302 Forwards Buppl 8 to 18 Bulletin 80-17, "Failure of Control Rods to Insert During Scram et BHR." No written response required.

  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 81/02/13.
  299. 07790:337.
- 8103060455 Ack receipt of 801218 & 810203 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/80-21:50-237/80-23 & 50-249/80-27. PIBNER-W.L. Region 3. Chicago: Fuel Facility & Materials Bafety Branch. 81/02/23. 1p. 07837:231.

- --8103060465 Supplemental response to NRC 801125 Itr re violation in IE Imap Rapts 50-010/80-21, 50-237/80-23 & 50-249/80-27 Corrective actions log established to be filled out by vendor representative when collecting environ samples ABELJ 8 Commonwealth Edison Co. 81/02/03 1p 07837 232
- --8103060481 Responds to NRC 801125 ltr re violations noted in 18 Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 Corrective actions. preparing ltr to vendor reinforcing need for strict compliance w/radiological environ monitoring program ABELJ S Commonwealth Edison Co 80/12/18 2pp 07837 23
- 8103160494 Forwards 1E Circular 81-03. 'Inoperatic Science Monitor Instrumentation' No response required KEPPLER. J G Region 3. Chicago, Office of the Director. 81/0: 20g 07915-308
- 8103170371 Responds to IE Bulletin 81-01. "Surveillance of Mechan Shubbers " No Nuclear Safeguards Corp shubbers have been installed or will be installed on safety-related sys JANECEK.R F. Commonwealth Edison Co. 81/03/02. 2pp. 07925-2
- B103160894 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Snubbers.' w/corrected Pages 5 & 6 Change in identification on facilities w/CPs to which bulletin is applicable does not affect util requirements

  KEPPLER-J G Region 3. Chicago. Office of the Director DI/OT.

  19. 07919 065
- 8103200394 Forwards IE Info Notice B1-06: "Failure of ITE Model K Circuit Breaker" No response required KEPPLER.J.O. Region 3. Chicago. Office of the Director. 81/03 2pp 07972:153.
- B103200695 Forwards IE Info Notice Bi-O5. "Degraded DC Bys at Palisades." No action required KEPPLER.J G. Region J. Chicago. Office of the Director. 81/03 2pp 07966 133
- 8103200269 Forwards IE Info Notice 81-07, "Potential Problem W/Mater~Soluble Purge Dem Matls Used During Inert Cas Welding." No response required KEPPLER. J O. Region 3. Chicago, Office of the Director. 81/03 2pp. 07966.226.
- 81032&1193 Responds to 1E Bulletin 80-25. "Operating Problems H/T Rock Bafety Reijef Valves at BKRs." Engineering review of LaBalle safety relief valve pneumatic supply systatil in progress Mods will be completed prior to fuel loading RAUBCH.T. J. Commonwealth Edison Co. 81/03/19. 7pp 08040:25
- R Periodic operating reports & related correspondence
- B103020369 Forwards semiannual rept re radioactive effluent disch & solid radioactive waste for Jul-Dec 1980 SCOTT.D J Commonwealth Edison Co 81/02/06. Ip 07784-234
- --Bj03020374 Semjannual rapt re-radioactive effluent discharges & radioactive usate for Jul-Dec 1980 
   Commonwealth Edison Co 81/02/06. 19pp 07784: 235
- B103030792 Forwards accupational radiation exposures rept for 198 BITEL.J B. Commonwealth Edison Co. 81/02/25 ip. 07793-055.
- --8103030807 Occupational radiation exposures rept for 1980.
  # Commonwealth Edison Co. 81/02/29. 3pp. 07795.086
- 8103130353 Forwards monthly operating repts for Feb 1981 800TT.D.J. Commonwealth Edison Co. 81/03/03. 1p 07911 121
- --8103130358 Monthly operating repts for Feb 1981.
  MAXWELL, D. C. Commonwealth Edison Co 81/03/03. 17pp. 0791
- 8103240348 Forwards "Annual Operating Rept for 1980 " 800TT-D.J. Commonwealth Edison Co. 81/03/11. 1p. 07987.183
- --8103240353 "Annual Operating Rept for 1980."
  \* Commonwealth Edison Co. 81/03/11. 23pp. 07987 186.
- 8. Reportable occurrences. LERs & related correspondence
- B100240387 PND-1[I-6]-032: info pickets set up at facility gate by operating engineers Local 190 AFL-CIO against McCarten & McCullen, Inc. Pickets established because contractor does not have operating engineers on eite.
  TONOUE, I. REIMANN, F. KNOP, R. Region 3, Chicago, Opfice of the Director. 81/03/16. 1p. 07987:254

#### V Operator Examinations

- 8103030769 Forwards supplemental info re-shift technical advisor training, ger NUREG-0737. Item 1 A 1 i (3) Info includes response to training requirements for shift control rock engineers & projected schedule for training completion.

  ADEL JS Correquealth Edison C 81/02/24 4p: 07796-089
- 9103050140 Forwards list of shift control room engineers recting training & education requirements by dates indicated Many engineers completed training by 810101 Target date for completion of training is mid-1981 ASELUS Common\_ealth Edison Co 81/02/24 4pp 07821 324
- 8103203574 Forwards supplemental info re long-term shift technical advisor program. Including candidate qualification, selection criteria, training plans & bases for phase-out of shift technical advisor program mandated by N.REG-0737 ABEL J & Commonwealth Edison Co. 81/03/17 1900 07972 084
- GECKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

  G Inspection reports, IE Bulletins & correspondence
- 8303020138 For ands [E Circular 81-02. Performance of NRC-Licensed Individuals Unite on Duty " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 81/02/09. ip. 07788-044
- DOCKET 50-18 VALLECITES BOILING WATER REACIDE

  R Periodic operating reports & related correspondence
- B103170143 Forwards "Vallecitos BUR Annual Rept 16 (Deactivated) 1980, " CUNVINGMAN.O E General Electric Co. 81/02/25, 19 07934:240
- ~-8103170146 "Valletitos BWR Annual Rept 16 (Deactivated): 1980 " GILLILAND.D L. General Electric Co 81/02/75 4pp 07934 241
- DOCKET 50-20 MASSACHUSETTS INST OF TECH REB REACTER

  8 Utility Preliminary Gafety Analysis Report. amends
- B103120142 Responds to NRC B01031 request for add1 info re QA program for redirective met1 shipping packages. Forwards revised Chapter 11 to MIT Research Reactor BAR: "GA" CLARK L. Massachusetts Imstitute of Technology, B1/02/26. 2pp 07900 IB9
- --B103120147 Revised Chapter 11 to MIT Research Reactor BAR, "QA."

   Massachusetts Institute of Technology G1/02/10. 7pp.
  07900 191
- DOCKET 50-27 MASHINGTON STATE UNIV RESEARCH REACTOR
  P. Operating Discesse stage documents & correspondence
- 8103060473 Forwards updated & corrected drawings for inclusion in SAR & changes to proposed Toch Specs re reactor ventilation sys.

  HILBON, W.E. Washington State Univ. B1/03/02 Japp 07840 242
- B103230661 Requests deferment of add1 fee payment pending MRC decision on final amount required NRC has completed final neview of change to definition of word "operable" in Tech Baccs SMITH, R.L. Vermont Yankee Nuclear Pawer Corp. B1/03/18 [p. 07978:356
- O. Inspection reports, IE Bulletins & correspondence
- Bi03020010 Forwards IE Circular Bi=02. "Performance of NRC-Licensed Individuals While on Duty." No written response required ENGELKEN.R.M. Region 5. San Francisco. Office of the Director. Bi/02/09. 1p 07/87, 174.
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION
  F. Security, medical, emergency & fire protection plans
- B103040326 Forwards summary of staff requirements to resolve open items & FR notice we fire protection features. Applicable provisions of App R. offective B10217. discussed W/o enci EISEN.HUT, D. O. Division of Licensing 80/11/24 App. 07820-121

- B102030617 Notifies of change relissuance of NOAA receivers for home in lieu of recommendations stated in Analytical Sys Engineering Corp study.per meeting w/FEMA & States of MS.VT & FM KAY.J A. Yantee Atomic Electric Co. 81/02/10 1p 07794 178
- 8103090299 Approves extension of installation of fire dampers betwee control & suitchgear rooms & turbine bldg to 810415 & installation of new fire tank & diesel fire pump to 810218 FR notice enci DCNTON-H R Office of Nuclear Reactor Regulation. Director 81/02/13 3cs 07832 142
- --B103050309 Notice of extension of installation dates for fire damp new fire tank & diesel fire pump CASE.E O Office of Nuclear Reactor Regulation. Director 81/02/13 ip 07832 145
- 8103180264 Ltr to all power reactor licensees u/plants licensed prior to 750101 Forwards NRC position & request for add1 info research shutdown capability for compliance u/801119 fire protection rule EISENNUT.D Q. Division of Licensing. 81/02/20. 13pp
  - B103100674 Requests that encl emergency planning into be made public available N/o encl.
    SDUDER: J L Division of Rules and Records 81/02/27. ip 07865-311
  - 810311019t Releases public version of draft energency plan for facility. FELTON-J M Division of Rules and Records 81/03/05. 1p 07804 Dos
  - --8103110201 Forwards public version of draft emergency plan. Plan includes State of MA radiological response plan. Readeboro. Stanford. Whitingham & Wilmington, VT energency plans & local plans for II towns in MA. MAY. J. A. Yankee Atomic Electric Co. 81/01/02 2pp. 07806-001.
  - --B103110209 Public version of draft emergency plan Plan Includes St. of MA radiological response plan. Readsbord, Stanford, Whitingham & Wilmington, VT emergency plans & local plans for
    - 11 towns in MA.
      ▶ Yantee Atomic Electric Co. 81/01/02 800pp. 07806.001.
  - 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. N/o encl EISENHUT.D O Division of Licensing. 81/03/03 6pp
  - 8103230486 Approves extension of completion date for installation of fire-reled replacement seal to next refueling outage FR notice encl.

    DENTON.H R. Office of Nuclear Reactor Regulation, Director.

    81/03/11. 3pp 07975:346
  - --B103230490 Notice of extension of completion date for installation fire-rated replacement seal to next refueling outage DENTON.H R Office of Nuclear Reactor Regulation, Director B1703711. ip 07973:349.
  - 8103230342 Forwards refund on Class III fee submitted w/810211 application for extension of completion date of three mods for plant fire protection sys.

    MELER.W.O. License Fee Management Branch. 81/03/16. Ip. 07974-342
- 8103230469 Responds to NRC 801124 itr re-fire protection criteria Mods will be installed during 1982 refueling outage, dependent upon timely NRC approval, BEP integrated assessment is scheduled for 1982.
  MEIDER-L.H. Yankee Atomic Electric Co. 81/03/19. 11pp. 07975:33
- 8103270605 Forwards emergency planning info for placement in LPBR W/o B103110201. BOUDER, J. L. Division of Rules and Records. 81/03/19. 1p. C8044:243.
- I. Financial information
- B103270392 Forwards financial statements for 1980. Summary of financial protection encl.
  CANNER, I.E. Yantee Atomic Electric Co. 81/03/24. 6pp. 08043:044
- 810327066) Forwards Annual Financial Rept 1980. CANNER, J. E. Yanise Atomic Electric Co. B1/03/24. ip. 08047:102.

- BIO3090587 Forwards Endorsement 5 to MAELU binder XB-4 & Endorsement 6 to NELIA Policy EB-4
  SQUEY.A R Yanise Atomic Electric Co 81/03/02 4pp 07849 236
- 8103310452 Forwards Endorsement 8 to MELIA Binder E8-4 & Endorsement 95 to NELIA Policy NF-76.
  SINIBIJ M Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 81/03/27 4pp 08078 329
- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for Oks & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position reliateria actions & request for addlinfo first-MHUT.D O Division of Licensino. 80/12/22 3000
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of sefety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737.
  EISENHUT,D O Division of Licensing 81/01/19 App
- 8103050150 Forwards Amend 43 to License DPR-3 & notice of issuence & availability.
  CRUTCHFIELD.D Operating Reactors Branch 5 81/01/23 3pp 07027 349
- --Bi03050196 Amend 63 to License DPR-3 adding condition to include Commission approved safeguards contingency plan CRUTCHFIELD D. Operating Reactors Branch 5. B1/01/23. 2pp 07827-352.
- --Bi03050162 Notice of issuance & availability of Amend 63 to License DPR-3. CRUTCHFIELD, D. Operating Reactors Granch 5 81/01/23 2pp 07827-354
- 8:03060275 Advises that review of potential problems w/surveillance procedures & multiple feilures is resolved.
  CRUICHFIELD.D. Operating Reactors Branch 5. Bi/O1/28 2pp.
  07836-361.
- 8103120014 Ltr to all licensees of operating plants, CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & THI-1, forwarding inadvertently amitted pages from NRC 801222 request for addl info re control of heavy loads.

  EISENHUT, D. O. Division of Licensing 81/02/03. 6pp.
- B103030B0D Submits assessment of BEP Topic 11-2. A. "Bevere Weather Phenomena." NRC consultant should make site specific review of terrain effects & re-evaluate potential of tornadoes & max wind speeds at site.

  KAY, J. A. Yankes Atomic Electric Co B1/02/10. 3pp. 07796:160.
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design. Forwards request for addl info. list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns. EISENHUT.D.O. Division of Licensing. 81/02/10. 13pp
- B103060365 Forwards "Environ Qualification of Bafety-Related Electrical Equipment," partial review Written response required. LAINAB.G.C. Assistant Director for Bafety Assessment, B1/02/11. 3pp. 07836:296.
- --Bi03060374 "Environ Qualification of Bafety-Related Electrical Equipment," partial review. • Dffice of Nuclear Reactor Regulation, Director. Bi/02/11. 18pp. 07836: 299.
- BiO3160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A. 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met.

  EISENHUT, D. G. Division of Licensing. Bi/02/1B i2pp.
- 8103230024 Ltr to all power reactor licensees & license applicants re NUREG-0619 criteria.Footnote 2 in Table 2 contains error due to leakage testing deletions.Licensee may submit analysis to justify use of existing low flow controller.
  EISENHUT.D.O. Division of Licensing. 81/02/20. 8pp. 07997.161.

- 8103100197 Bunnary of 801217 meeting w/util & EES re seismic capabi of facility Final site specific spectrum will be decided upon by June.1981 W/list of attendees CARUSD. R. Operating Reactors Branch 5 81/02/25 6pp 07867
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 5t Lucio.Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EIBENNUT. D 0 Division of Licensina 81/02/25 Soc.
- 8103100336 Reconfirms util intention to complete EEP in espeditious ranner & consistent w/clarification discussed in 810219 meeting Lists specific obligations
  KAY. J. A. Vantee Atomic Electric Co. 81/02/27 2pp. 07869-065
- B103120269 Forwards request for add1 info on SEP Topic VI-7 B reengineered safety features switchover from injection to recirculation modes Response should be submitted within 30 days CRUTCHFIELD,D. Operating Reactors Branch 5 81/02/27. 3pp 07906 339
- 810312D312 Forwards request for add1 info re 8EP Topic VIII-2.diesel generators Technical basis for using assumed notor afficiency of 93% & load lists/description for each load on tCC-1 & tCC-2 requested within 30 days
  CRUTCHFIELD.D Operating Reactors Branch 5 81/02/27 3pp 07901-253
- Bi03090323 Forwards "Best Estimate Post-Test Prediction for LOFT Nuclear Experiment L3-6" Prediction carried out by RELAP4/ Mod 3 based licensed code Util will submit another post-test prediction of LOFT L3-6 as calculated RELAP5/Mod1 KAY. J Yankee Atomic Electric Co. 81/03/03. ip 07890 229
- --8103090330 "Best Estinate Post-Test Prediction for LOFT Nuclear Experiment L3-6" 6CHOR.L., L00HIS. J. HUBAIN.A. Yankee Atomic Electric Co 81/03/03 70pp. 07850 230.
- B103120443 Forwards fee for model change review of YAEC-1231 reincorporation of lower plenum phase separation model in large break LOCA methodology.

  XAY, J. A. Yantes Atomic Electric Co. B1/03/06 ip. 07901 248
- --8103120471 Ack receipt of itr w/check to be processed directly by License Fee Mgt Branch. D109B.R.M. License Fee Management Branch. 81/03/10. ip. 07901.249
- Bi0316035B Responds to NRC B01229 ltr requesting info for review of Topic IV-2 re reactivity control sys design & protoction against single failures. Draft safety evaluation of topic uill be written upon completion of NRC review.

  KAY, J.A. Yankee Atomic Electric Co. 81/03/06 1g. 07917.148
- BIO3130351 Forwards YOGAP-1-A operational QA program Revision 9, reduties & responsibilities of personnel involved in establishing & executing operational QA program JOHNSON W P. Yankee Atomic Electric Co. 81/03/09. 1p. 07907 16
- --B103130359 Operational QA program Revision 9, re-duties & responsibilities of personnel involved in establishing & executing operational QA program. MARTIN,R.L., PIKE-D.B. j. MDDDY-D.E. Yankee Atomic Electric Co. B1/03/09. 43pp. 07907:105.
- B103180592 Bubmits schedule change re commitments for providing info concerning TMI Action Plan Items II.E.1.2 & II.F.2.1.AFMB flow indication & noble gas effluent monitor.respectively. Info will be provided by B10331. KAY, J. A. Yankee Atomic Electric Co B1/03/10. 1p 07953:324
- B103310804 Ltr to all licensees of operating plants, applicants for (
  & holders of CPs forwarding SECY-81-119 re info necessary to 
  satablish environ qualification of safety-related electrical 
  squipment. 
  EISENHUT, D. O. Division of Licensing. 81/03/10 App.

- 8103203729 Advises that SEP Topics VI-7 C (ECCS single failure criterian & requirements for locking out power to valves) & VI-7. C 2 (failure nate analysis) are complete except for integrated assessments Amend 21 of DPR-3 is duplicative CRUTCHFIELD.D Operating Reactors Branch 5 81/03/13 3pp.07947 324
- 8103200196 Forwards comments on ARC draft safety evaluation re SEP Topics II-3 A re-hydrologic description & II-3 B (partial) re-flooding potential & protection requirements YAEC-1207.
  "Design Basis Flood Analysis." also forwards
  AAY. JA Yantee Atomic Electric Co. 81/09/16 7pg. 07970:097
- --8103200204 Design Basis Flood Analysis "

  \* Yanker Atomic Electric Co YAEC-1207 B0/10/31 110pp
  07970 094
- 8103200327 Notifies that SEP Topic III-4 B. "Turbine Missiles." rade generic Low pressure turbine disc cracking problem to be handled as part of solution to multi-plant generic cracking problem applicable to all plants w/destinghouse turbines CRUTCHEIELD.D. Operating Reactors Branch 5 81/03/16 4pp.
- BIO32405BO informs that Class IV fee required for BO0916 application reproposed changes to Tech Specs per THI lessons learned Category A Licens Previous remittance is insufficient DIGOS, R M License Fee Management Branch 81/03/17 ip 07982 328
- B103310P26 Forwards "Best Estimate Post-Test Prediction for LOFT Nuclear Experiment L3-6 (BELAP5/Mod) Predictions) " MAY.J A Yanke Atomic Electric Co B1/03/20. ip 08060 143
- --BI03310231 "Best Estimate Post-Test Prediction for LOFT Auclear Experiment L3-6 (RELAPS/Mode Predictions) ' HUBAIN-A LCOMIS.J BCH0R.L. Yankee Atomic Electric Co BI703/20 88pp 08060:144
- G. Inspection reports. IE Bulletins & correspondence

1

- B103050294 Forwards IE Insp Rept 50-029/80-15 on 800916-1031 No noncompliance noted. BRUNNER.E. J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch. 81/01/16. 2pp. 07826-001
- --8103050298 JE Insp Rept 50-029/80-16 on 900916-1031 No noncompliance noted Major areas inspected (ags. records & tours of facility follows of operational events & witness of survaillance test
  FOLEY.T. RAYMOND W J Region 1, Philadelphia, Office of the Director. MARTIN.T T Region 1, Philadelphia, Reactor Operations Nuclear Eupport Branch. 80/12/30 22pp 07826.003
- B103190062 Forwards IE Insp Rept 50-029/80-18 on 801101-1201 No noncompliance noted ERUNNER.E J. Region 1. Philadelphia, Reactor Operations Muclear Support Sranch 81/01/21 2pp. 07964-127
- --Bi03190067 IE Combined Insp Rept 50-029/80-18 on B01(01-1201. No noncompliance noted Hajor areas inspected status of previous inspections including tours of facility b logs & record revies.

  FOLEY.T. Region 1. Philadelphia, Office of the Director areas of previous tours of facility by the previous of the Director areas of the

n 601201-31.No

Cerations Nuclear

noncompliance Fional

> ir. Juclear

- Making Notifications of Significant Events in Accordance W/100FR90, 72 " No written response required GRIER, B. H. Region I. Philadelphia, Diffice of the Director. 81/02/12 ip. 07813 250
- 8103200198 Forwards IE Info Notice B1-04: "Cracking in Main Steam Lines." No response required GRIER.8 H. Region 1: Philadelphia. Office of the Director 81/02/27. ip. 07972.038

- BIO3200159 Forwards IE Circular B1-03. "Inoperable Seismic Monitoring Instrumentation." No written response required GRIER, B. H. Region I. Philadelphia, Office of the Director G1/03/02 | pp. 07971 334
- BIO2200022 Forwards revised IE Gulletin BI-01. "Surveillance of Machanical Snubbers." w/corrected Pagec 5 & 6 Changs in Identification of facilities w/CP to which bulletin is applicable does not affect util requirements CRIER.B H Region 1. Philadelphia. Office of the Director BI/02/04 bp 07968 218
- BIO3200277 Forwards IE Info Notice 81-06. "Failure of IIE Model K-600 Circuit Breaker" No response required GRIER.O H. Region 1. Philadelphia. Office of the Director. BI/03/11 |p 07969.010
- R Periodic operating reports & related correspondence
- 8103090511 Ferwards "Annual Operating Rept for 1980 " MCDDY, D.E. Yankee Atomic Electric Co. 81/02/27 Ip. 07845.302.
- --8103090512 "Annual Operating Rept for 1980 "

   Vankee Atomic Electric Co 81/02/27, lipp 07845:303.
- B103100153 Forwards 'Effluent & Haste Disposal Bemiannual Rept.
  Jul-Det 1980 "
  MDDDV, DE Vankee Atomic Electric Co 81/02/27 in
- --8103100159 'Effluent & Waste Disposal Semiannuel Rept.Jul-Dec 1980

  \* Yankee Atomic Electric Co 81/02/27 | Lpp.
- 8103310631 Submits clarification & corrections to 1980 annual operations rept
  H000Y.D.E. Yankow Atomic Electric Co. 81/03/24 Ip. 08063-010
- 5 Reportable occurrences, LERs & related correspondence
- B103170599 Forwards LER B1-002/03L-0 AUTID H A Yankee Atomic Electric Co 81/03/13. ip.
- --8103170964 LER 81-002/03L-O on 810211, two cable tray house fire detectors gave false alarms in control room Caused by condensation in detector completing alarm circuit Detection sys replaced MAY. 6.4. Vanise Atomic Electric Co. 81/03/13 fp. 07933-350,
- DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

  C. Utility Environmental Report (ER). Amends & Correspondence
- 8103020638 Forwards Amend 1 to "Dismantling Plan, Plum Brook Reactor Dismantling," "Environ Rept. Plum Brook Reactor Dismantling," "
  "Dismantling Plan, Plum Brook Mock-Up Reactor Dismantling," &
  "Environ Rept. Plum Brook Mock-Up."
  BENEDICT. D. E. National Aeronautics & Space Admin. 81/02/23. 2pp. 07782: 106.
- --8103020646 Amend 1 to "Environ Rept.Plum Brook Reactor Dismantling • National Aeromautics & Space Admin 81/02/18 4pp. 07782:11
- --Bi03020654 Amend 1 to "Environ Rept.Plum Brook Mock-Up Reactor Dismantling." • National Aeronautics & Space Admin. 81/02/18. 4pp. 07782.11
- P. Operating license stage documents & correspondence
- B103030396 Responds to B00317 application & B01107 ltr re dismentling reactors & decontaminating labs. Proposed rediation limits must be revised to meet enci levels.

  REID.R.W. Operating Reactors Branch 4. B1/02/11. 3pp. 07790:026
- 8103020638 Forwards Amend 1 to "Dismantling Plan, Plum Brook Reactor Dismantling," "Environ Rept. Plum Brook Reactor Dismantling," "Environ Rept. Plum Brook Most-Up Reactor Dismantling," & 'Environ Rept. Plum Brook Moci-Up."

  BENEDICT. D. E. National Aeronautics & Space Admin. 81/02/23 2pp. 07782:106
- --8103020640 Amend 1 to "Dismantling Plan.Plum Brook Reactor Dismantling."

  National Aeronautics & Space Admin. 81/02/18. 4pg. 07782:10
- --Bi03020646 Amend 1 to "Environ Rept.Plum Brook Reactor Dismantling"

  \* National Aeronautics & Space Admin. 81/02/18. 4pp. 07782:112

- --BIO3020651 Amend I to "Dismantling Plan. Plum Brook Mock-Up Reactor Discenting "

  \* National Aeronautics & Space Admin 81/02/18
- --8103020694 Amend 1 to "Environ Rept. Plum Brook Mock-Up Reactor Bismantling National Agronautics & Space Admin 81/02/18 4pp 07782 [17
- R Periodic operating reports & related correspondence
- 8103030663 Forwards "Rept of Reactor Standby for NABA Plum Brook Reactor, 1980. 801TEL.E.C , RICHLEY,E A 81/02/20 200 07798 231 National Aeronautics & Space Admin
- --B103030666 "Rept of Reactor Standby Condition for NABA Plum Brook Reactor, 1980. National Agronautics & Space Admin 81/02/17 1200 07798 233
- BOCKET SO-24 VANAFE ATOMIC POWER REACTOR P Operating license stage documents & correspondence
- 8102120542 Natification of rescheduled 810129 meeting w/vendor to discuss plans for reviewing \$ improving small break LOCA licensing codes
  OUTTMANN, J Rea Reactor Sustans Branch 80/12/12 4nn 07665 316
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR P Operating license stage documents & correspondence
- 8103120659 Requests amend to License R-B1 & SNM-639, changing name of licensee from Union Carbide Corp to Union Carbide Subsidiary B. Inc. Amend fee encl MCGDVERN, J. J. Union Carbide Corp. 81/01/08 1p 07906 135.
- B103050236 Forwards Amond 15 to License R-B1 MILLER, J. R. Standardization & Special Projects Branch. 81/02/19 2pp. 07825:235.
- --8103050241 Amend 15 to License R-81, changing name to Union Carbide-Carbide Bubsidiary 8 (nc. (Company B)
  MILLER, J.R. Standardization & Special Projects Branch. 81/02/19.
  2pp. 07025:237.
- DOCKET 50-97 STATE UNIV. OF NEW YORK RESEARCH REACTOR P. Operating license stage documents & correspondence
- B103261132 Forwards draft revised SNM accountability manual for nuclear science & technology facility incorporating changes & including revised internal accounting forms.

  HENRY, L. Q. New York, State Univ. of, Duffalo. 80/08/14 ip.
- --B103261139 Accountability menual for nuclear science & technology ORLDBK/,P.M., PIERRO,M.A. New York, State Univ of, Buffalo. 80/08/14. 31pp. 08036:329.
- DOCKET 50-99 TEXAS A&M UNIV. RESEARCH REACTOR P. Operating license stage documents & correspondence
- Bi03310542 Discusses calibr of regulating control rod for Core VI & sefety amplifier response to noise transients. Calibr performed on 810119 due to extended period of maint. On 810130, two sefety control rode scrammed. FELIZ.D.E. Texas A & M Univ. 81/02/05. 2pp. 08062:398.
- 8103030127 Forwards revised NRC Region 4 organization chart-effective 810227 SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 81/02/17.
- G. Inspection reports, IE Bulleting & correspondence
- 8103200292 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 81/02/09. lp. 07966.234.

- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR O Inspection reports, IE Bulletins & correspondence
- 810302016B Forwards [E Circular Q1-02. 'Performance of NRC-Licenses Individuals While on Duty "No written response required D'REILLY. J P. Region 2. Atlanta. Office of the Director 81/02/19 07785 273
- DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR G Adjudicatory correspondence
- 8103020581 Requests date time & place of public hearings & procedur HUBBARD.H Citizens for Total Energy 81/02/08 to 07782 0AT
- 8103030854 Notice of withdrawal from proceeding Certificate of Boc BALONIN-W A Friends of the Earth BALONIU. W.A. Raldwin, W.A. B1/02/20 3pp 07793 140
- 8103050789 Notice of appearance in show cause proceeding Certificat Svc anci CADY O W. Friends of the Earth CADY O W. Affiliation Unknown BI/02/24 3pp 07028 117
- 8103050662 Interveners' joint response to NRC interrogatories Concessismic & geologic design bases & identification of uitnesses. Prof qualifications & Certificate of Svc encl CADY.O W. Friends of the Earth HALTERMAY.H L. Affiliation Unknown 81/02/25 23pp
- B103130427 First request for production of documents directed to Congressman Deliums requesting O Gray repts & J Caid uniting Related correspondence EDGAR.O L. General Electric Co. 81/03/05 | pp. 07911:230
- ~-8103130430 Interrogatories directed to Congressman Dellums requos info re background of Q Grey. J Caid & J Rutherford & earthquake data Certificate of 8vc encl EDGAR.G L. General Electric Co 81/03/03 App 07911 231
- 8103130433 Request for production of documents directed to Friends the Earth O Grey repts % J Cald writing must be hade available for copying Related correspondence EDOAR.O L General Electric Co. 81/03/05 ip. 07911:237
- -- 8103130439 Becond set of interrogatories directed to intervenors friends of the Earth requesting into to background of Q Grey. J Caid & J Rutherford & garthquake data Certificate
- of Byc encl EDOAR, O L General Electric Co. 81/03/05 6pp 07911 238 8103120250 Advises that notice of public hearings on facility will
- forwarded when issued in response to 810208 ltr Explains procedure for making limited appearance statement. BACHNANN.R Q. Office of the Executive Logal Director 81/03/10
- 8103230639 Advises of request to make limited appearance statement. startup hearing on 810527 Requests placement on mailing list for related notices & info TBCHAECHE, A N People for Energy Progress. 81/03/11 1p 07979 329
- 8103170479 Forwards JF Devine prof qualifications to be included w/810325 updated NRC responses to Friends of the Earth interrogatories Certificate of Svc encl BACHMANN.R.O. Office of the Executive Legal Director. Bi/03/13
- 5pp. 07933.291.
- 8103170471 Requests for admissions & interrogatories directed to licensee re geologic data. Verona fault, soil displacement & BWANBON, D. T. Hearing Branch 1. 81/03/16. 7pp. 07933 252
- ~-B103170473 Request for admissions, interrogatories & documents dir to intervenors Friends of the Earth & Delluns re geologic data. Verona fault, soil displacement & earthquetes Certificate of 8vc encl. BHANBON, D. T. Hearing Branch 1. BACHMANN, R. O. Office of the Executive Legal Director. 81/03/16. 32pp. 07933:259
- 8103270479 Interrogatories directed to licensee. Concerns effects of seismic event on structures, sys & components. Related correspondence CADY, C. W. Friends of the Earth. 81/03/16 3pp. 08032.291

- 8103270491 Request for production of documents directed to licensee Includes specs for const of facility, structural-general notes & typical details & protabilistics studies. Related correspondence
  HALTERHAN, II Affiliation Unanown HALTERHAN, H L Affiliation Uninown B1/03/16. Ip 08033.166
- 8103270497 Supplemental Jocument request directed to licensee re-matls presented at ACRS meeting held in Nov 1979.
  HALTERHAM: H Affiliation Unknown. HALTERHAM: H L Affiliation Unknown. B1/03/16 1p 08034 131
- 8103270548 Interrogatories directed to ARC requesting info re selsmic design criteria Related correspondence
  CADY.0 H Friends of the Earth 81/03/16 9pp. 08034 015
- 8103270573 Request for production of 69 documents on behalf of intervenors Congressian Dellows Burton & Burton HALTERMAN. H L. Affiliation Unincum HALTERMAN. H L. Affiliation Unincum B1/03/16 6pp 08034.034
- BI03270501 Interrogetories directed to NRC re sestimany Ralated correspondence HALTERMANIH L Affiliation Unknown, PALTERMANIH L HaltermaniH L BI/03/16 to 08043 239
- 8103270172 Lists corrections to ARC 810316 request for admissions & interrogatories to licensee SMANS3N.D 1 Hearing Branch : 81/03/29. 2pp C8045-316
- R103270587 Response in objection to intervenor Bi0316 Interrogatories 5 % 6 Subj matter of proceeding controlled 771024 show cause order. Accident consequences do not fall within scope of order Protoctive order should be granted \$50AR,0 L. Ogereal Electric Co. 81/03/25 3pp 08034 050
- 8103270695 Objections to intervenor Delium 810316 request for production of Jocuments No statement made as to relevancy of any documents requested Some not available per 10CFR2 790 or are obtainable from another source 86CHMANJ-R. G. Rulemaking & Enforcement Bivision, 81/03/25 2pp 08030 278
- --B103270697 Ubjections to intervenor Dellom 910316 supplemental document request Items 2 & 3 concern site reviews of other reactors & Item 4 lacis particularity BACHMANIAR 0 Rulemeting & Enforcement Division 81/03/25 Lp
- --9100270699 Objections to intervenor Friends of the Earth 610316 Interrogatories (1, 22, 23, 28, 44, 50, 51, 53, 54, 57, 59 & 60 Info sought is irrelevant to issues Certificate of Svc encl. BACHMANN.R G Rulemating & Enforcement Division 81/03/25. App 08043 281
- P Operating license stage documents & correspondence
- B103060839 Advises that review of 751021 application for renewal of License TR-1 has been completed Environ review will be initiated Environ info rept should be distributed in accordance w/encl
  MILLER.J R. Standardilation & Special Projects Branch 81/02/19
  550 07836 131
- B103130446 Forwards RW Darmitiel affidevitiper NRC 810219 request DARMITZEL.R W. Oeneral Electric Co. 81/03/06 10 07911 344
- --8103130449 Affidavit re environ info rept distribution during wk of B10222 DARMITZEL.R.W. General Electric Co 81/03/06 ip. 07911.345
- 8103130342 Forwards summaries of fuel flooding sys acceptance test procedure 5 trigital seismic suitches acceptance test & proposed Tech Specs for seismic mods DARMITZEL.R.W Opnoral Electric Co. 81/03/11 5pp. 07908-233
- --9103130443 Proposed Tech Specs. 16, 4 0, 4 5, 6 0, 6 10, 6, 11, 6 12, 7 1, 7 6 through 7 15, 8 2, 9, 5 & 10, 6 re seismic mods a Oeneral Electric Co 91/03/10, 30pp 07908 238
- 8103160396 Informs that marthquake of 4.1 Richter magnitude occurred at 2.45 AM on 810303 Existing selsmic trip nechanism worked as designed Bus works reliably DARMITZEC.R G. Openeral Electric Co. 81/03/11 1p. 07917.143

- 3 Inspection reports: IE Bulletins & correspondence
- 0103020031 Forwards 1E Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty" No written response required. ENGELMEN.R H Region 5. San Francisco. Office of the Director 81/02/09 1; 07787 224
- DOCAET 50-72 UNIV OF UTAH RESEARCH REACTOR

  F Securit, medical, emergency & fire protection plans
- 8101070341 Releases public version of univenergency plan for resear reactors FELTOW, J. II. Division of Rules and Records 80/12/02 ip 07414, 300
- --8101220624 Forwards public version of univ reactor emergency plan. TURLEY.R E. Utah Univ of 80/01/31 ip 04025 115.
- --8/01/07/0345 Public version of univ reactor emergency plan SAMDQUIBT.0 (1. JENSEN.C H. Utah, Univ of. UTEC ME 80-015 80/21/01 18pp. 07414 301
- $P \Omega_P \, erating \, \, 1$  :cense stage documents & correspondence
- 8103030158 Forwards revised NRC Region 4 organization chart. effectiv 810227. SEYFRIT.K V Region 4. Dellas. Office of the Director 81/02/17.
- @ Inspection reports. If Bulletins & correspondence
- Bi03200214 forwards IE Circular Bi-02. "Performance of NRC-Licensed Individuals White on Duty." No written response required EEYFRIT. N V Region 4. Dallas. Office of the Director 81/02/09 ip. 97972 049
- DOCKET 30-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR
  P Operating license stage documents & correspondence
- 8103090539 Forwards list of license renewal documents required for N review BAR & Tech Specs will be submitted by 910430 CUNRINHAM. S.E. General Electric Co. 81/03/02 2pp 07848.164
- ④ Inspection reports. 1€ Bulletins & correspondence
- 8103020031 Forwards [E Circular 81-02, "Performance of NRC-Licensed Individuals Hhile on Duty," No written response required. FNGELKEN.R H. Region 5, San Francisco Office of the Director 81/02/09 1p 07787, 224
- DDCXET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- 8103130388 Forwards organization chart per NRC telcon re licenses 791115 ltr. Change to Tech Specs 16.6 i.2 re provost requested. JORDAN,E.B. Catholic Univ. 81/03/06 ip. 07907:079.
- ODCKET 50-03 UNIV. OF FLORIDA TRAINING REACTOR

  G. inspection reports. IE Sulletins & correspondence
- 8103020164 Forwards 1E Circular Bi-02, "Performance of NRC-Licensed Individuals While on Outy." No written response required O'REILLY, J.P., Region 2, Atlanta, Office of the Director. B1/02/01p. 07785:268
- S. Reportable occurrences, LERs & related correspondence
- 8103130461 Initial deficiency meptine operator requalification progresecution No record exists of operator wait—through due Feb. 1980. Benior reactor operator has been appointed acting assistant reactor manager Items expected complete by 810430, DIAZ-N J. Florida, Univ. of. Oainesville 81/03/09. 2pp. 07911-338

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

P Operating license stage documents & correspondence

8103090183 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 MEPPLER.J.O Region 3. Chicago, Office of the Director 81/02/20 2pp. 07890 329

BiO3240375 Forwards "Safety Consideration for 24 Element Oraphite-Reflected Core " Proposed core configuration does not present or constitute unreviewed safety questions or involve charge in Tech Specs Core loading diagrams enci NARDI. A J Westinghouse Electric Corp Bi/03/19 3og 07986 277

--8103240380 "Bafety Consideration for 24 Element Graphite-Reflected Core" • Westinghouse Electric Corp 80/12/03 12pp 07986 280

DOCKET 50-89 GENERAL ATOMIC CO

F Security, medical, emergency & fire protection plans

8103120636 Discusses GA Co 800516 physical security plan & payment of fee Ng more fees usil be collected until review & approvals are conjected DI003.R.M License Fee Management Branch 81/03/06 1p 07906-128

## J Insurance & indomnity information

8102030266 Forwards Endorsements 114 & 115 to ANT Policy NF-34 CORREACC Marsh & McLennan, Inc., 11 & M Nuclear Consultants, Inc. Div 81/01/16 4pp 07606 320

8103060511 Forwards Endorsement 52 to MAELU Policy MF-59 CORREAM A. Marsh & McLennan.Inc., M & M Nuclear Consultants.inc Div 81/01/30 2pp 0/839 356

0. Inspection reports: IE Bulletins & correspondence

9103040246 Forwards 1E Insp Repts 50-089/80-03 & 50-163/80-03 on 801215-18 No noncompliance noted 800K.H E. Region 5. Ban Francisco. Fuel Facility & Materials Safety Branch 81/01/16 2pp 07813:268

--8103040261 IE Insp Repts 50-163/80-03 & 50-089/80-03 on 801215-18 No noncompliance noted Major areas inspected radiation protection, environ monitoring, emergency aspects of TRION Mark 1 & Mark F reactors & records & logs CURTIS. J. R. WENBLAMSKI.F. Region 5. Ban Francisco. Office of the Director BODK.H E Region 5. Ban Francisco. Fuel Facility & Materials Safety Branch 81/01/16. Spp 07813.270

8103020102 Forwards [E Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required ENGELKEN.R. H. Region 5, Ban Francisco, Office of the Director 91/02/09. 1p 07787 359

R Periodic operating reports & related correspondence

Bi03030818 Bubmits annual operating rept for 1980 HDMRY, W.R. General Atomic Co. (subs. of Gulf Gil Co.). Bi/02/27. 7pp. 07795.048

OGCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

1 Inspection reports, 1E Bulletins & correspondence

BIO3020027 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. ENGELKEN.R.H. Region 5. Ben Francisco. Défice of the Director. BI/02/09. 1p. 07787 214

DOCKEY 50-99 BABCOCK & WILCOX TEBT REACTOR

G Inspection reports. IE Bullstins & correspondence

8103020138 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Duty," No written response required, 0'REILLY, J.C. Region 2, Atlanta, Office of the Director. 81/02/09. 1p. 07788:044.

DOCAET 50-106 OREGUN STATE UNIV

O Inspection reports: IE Bulletins & correspondence

8103020016 Forwards IR Circular 81-02. 'Performance of NRC-License Individuals While on Duty "No written response required ENGELKEN.R H Region 3. San Francisco. Office of the Director 81/02/09 is 07787 194

N Periodic operating reports & related correspondence

8103230500 Forwards "Rept of Personnel Whole Body Exposures for CY WAND C H Oregon State Univ 81/03/13 ip 07975 287

--8103230507 "Rept of Personnel Whole Body Exposures for CY80 " 4 Oregon State Univ 81/03/13 ip 07975 208

DOCKET 90-111 NORTH CARGLINA STATE UNIV RESEARCH REACTOR
H. General correspondence

B)03179622 Advises of two organizational changes in Nuclear Engine
Dept PJ Turinsky replaces TS Elleran as dept head RG
Cockrell replaces JR Bohannon as Director of Nuclear Reactor
Program Requests appropriate changes to mailing lists.
COCKRELL.R O North Carolina State Univ 81/03/12 1p 07925

Q Inspection reports, IE Bulletins & correspondence

8103020196 Forwards IE Circular 81-02, "Performance of NRC-License Individuals While on Duty" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/02 ip 07788 089

8103030864 Requests dismantling of R-3 reactor & termination of Li R-3 TURINSKY,P J., THOMAS.J.L. North Carolina State Univ. 81/02/19 200 07795 179

B1032000B5 Ack receipt of 800605 & 810219 ltrs re authorization to dismantle training & research reactor & terminate license Criteria for release of reactor facility to unrestricted access should be revised per encl.

REIDER W. Operating Reactors Branch 4 81/03/06 3pp 07970

DOCKET 30-112 UNIV OF OKLAHOMA RESEARCH REACTOR
P Operating license stage documents & correspondence

B10303010B Forwards revised NRC Region 4 organization chart effect B10227 SEYFRIT.X V Region 4. Dallas. Office of the Director. 81/02/1

Q. Inspection reports: IE Bulletins & correspondence

B103200237 Forwards IE Circular B1-02. "Performance of NRC-License Individuals While on Duty." No written response required BEYFRIT.K V Region 4. Dellas. Office of the Director 81/02/0 1p 07972 071.

DOCKET 50-113 UNIV. OF ARIZONA RESEARCH REACTOR

G. Inspection reports: IE Bulletins & correspondence

8103180183 Forwards IE Insp Rept 50-113/81-01 on 810119-22.No noncompliance noted. BOCK.H E Repion 5. San Francisco. Fuel Facility & Materials Ba Branch 81/02/03. 2pp. 07945-241

--8103180192 IE Insp Rept 50-113/81-01 on 810119-22. No noncompliant noted Major areas inspected; radiation protection, environ controls & emergency response planning programs CURTIB.JR, WENBLAWSKI.FA. Region 5, San Francisco. Défice of the Director. BOUX.H E. Region 5, San Francisco. Fuel Facili Materials Safety Branch. 81/02/04 5pp. 07945.243

BIO3020015 Forwards IE Circular B1-02. 'Performance of NRC-Licanse Individuals While on Duty." No written response required ENGELKEN.R.H Region 5. San Francisco, Office of the Director BI/02/09 ip. 07787-189.

- EDUKET 50-116 IDMA STATE UNIV RESEARCH REACTER
  P. Operating license stage decurents & correspondence
- B103060494 Forwards organizational charts depicting NRC Region 3 reorganization effective B10216 KEPPLER.J G Region 3. Chicago. Office of the Director B1/02/20 250 07436 069
- G. Inspection reports. IE Bulletins & currespondence
- B1030200\$0 For and a IF Circular B1-02. Performance of HRC-Licensed Individuals While on Duty " No written response required MEPPLER. J. G. Region 3. Chicago, Office of the Director B1/02/09 255 07787.245

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTUR

P. Deprating license stage documents & correspondence

8103060498 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 XEPPLER.J C Region 3. Chicago, Office of the Director 81/02/20 200 07836 079.

## V Operator Examinations

8163170203 Forwards operator requalification program, per NRC 810305 1tr ELL10TT.A E Montana, Univ. of 81/03/11 is 07937 217.

--8103170208 Operator requalification program 4 Montana. Univ of 81/03/11 19:p 07939 218

DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR

G. Inspection reports. IE Bulleting & correspondence

- B103020145 Forwards IE Circular B1-02. Performance of NRC-Licensed Individuals Unite on Duty 'No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B1/02/09. ip 07788 049
- R Pariodic operating reports & related correspondence
- BIO3030715 Forwards "Annual Operations Rept.Nuclear Research Reactor. VA Polytechnic Inst & State Unsv. 1980 "
  CURTNER: A P Virginia Tech BIO2025 Ip 07798.031
- --B103030719 "Annual Operations Regt. Nuclear Research Reactor, VA Polytechnic Inst & State Univ. 1980 " CURTICE, A P. PARKINSCH.T.F. Virginia Tech. 91/02/25 60pp 07798 032

DOCKET 90-128 TEXAS ASM UNIV RESEARCH REACTOR

P Depreting license stage documents & correspondence

- 8103310942 Discusses callbr of regulating control rod for Core VI & safety amplifier response to noise transients Callbr performed on 810119 due to extended period of maint On 810130.two safety control rods scramed. FELT2.D E. Texas A & M Univ 81/02/05. 2pp. 08062 358
- B103030127 Forwards revised NRC Region 4 organization chart.effective B10227 SEYFRIT.R V Region 4. Dallas. Office of the Director B1/02/17. 200.
- O Inspection reports. IE Bulletins & correspondence
- B100200292 Forwards JE Circular D1-02. "Performance of NRC-Licensed Individuals While on Duty." No written response required EEYFRIT.K V Region 4. Dallas. Office of the Birector 91/02/09. pp. 07966. 234.

DOCKET 55-129 WEST VIRGINIA UNIV RESEARCH REACTOR

- a Inspection reports. IE Bulletins & correspondence
- Bi03020147 Forwards IE Circular Bi-02, "Performance of NRC-Licens individuals Wile on Duty " No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 81/0 op 07768 034

COCKET 30-131 CMAHA VET ADMIN HISP RESEARCH REACTOR
P. Operating license stage documents & correspondence

- BIO3030169 Forwards revised MRC Region 4 organization chart, effect BI0227 SEVERIT, K V Region 4. Dallas, Office of the Director BI/02/
- 9 Inspection reports. IE Bulletins & correspondence
- 810320624 Forwards IE Circular 81-02. "Performance of NRC-Liters Individuals While on Duty " No written response required. SEYRIT.K V Region 4. Dallas. Office of the Director 81/02/0 to 07972 059

COCKET 50-133 HUMBGLDT BAY POWER PLANT. UNIT 3

F. Security, medical, emergency & fire protection plans

- BiO3180264 Ltr to all power reactor licensees w/plants licensed pto 790101. Forwards NRC position & request for add1 info resafe shutdown capability for compliance w/BOI119 fire protection rule EISEINJI.D O Division of Licensing BI/02/20 13pp.
- 8103310338 Ltr to all licenses of operating plants & holders of (
  forwarding NUMEO-0696. "Functional Criteria Por Emergency 
  Assonse Faculities." Criteria describe acceptable method 
  for meeting tAPC requirements U/o encl 
  EISEN-UI, D Q Division of Licensing 81/03/05 App.

#### H General correspondence

- 8103040230 Responds to FOIA request for H Denton 771010 memo & supporting documents. Forwards documents listed in App A Rept entitled 'Hutbold Bay Power Plant Site Geology Investigation' is available in PDR FELION, J. II Division of Rules and Records 81/02/24 Spp. 07820 OAR
- --G103040250 Forwards Geosciences Branch position re geologic cond at Facility There is no reasonable assurance that surface displacement will not occur in plant site during expected plant life DENTON.HR Division of Site Safety & Environmental Analysis. 77/08/10. 15pp
- --8103040256 Summary of 770706-07 mosting u/util, Univ of DE, UBGB, D Petroleum. Inc & Anderson Warren & Associates re geology of Hurboldt Bay region Discusses surface displacement at site. List of mosting attendess encl. hELSGN, C Operating Reactors Branch 4 (Pre 800428). 77/08/04 4pp
- --Bi00040269 Submits concerns re geologic/seismic questions re fac Forwards preliminary rept re geologic considerations relative to seismic safety AMMOTO, P. Y. OAY, T. E. California, State of 77/07/29. Opp.
- --Bi03040301 Surmary of 770504 meeting w/USQB state representative Corps of Engineers, Times-Std. Stanford Univ & util in Menio Park, CA re CA Div of Minos & Geology comments on util draft final rept of geologic investigations at plant site.

  CARBONE. A T Geosciences Branch. 77/06/07. 3pp.
- J Insurance & indemnity information
- B103020516 Forwards Endorsement 90 to NELIA Policy NF-113.

  CRANE P A Pacific Gas & Electric Co. 81/02/24 2pp. 07784:0

## P Operating license stage documents & correspondence

- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interim actions & request for add1 info FISECHUID O Division of Licensine 80/12/22 30nn
- BiD31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREO-0737. EISENHUT.D & Division of Licensing 81/01/19 6pp
- 8103240290 Ltr to all BHR licensees forwarding Suppl i to generic safety evaluation on BHR scram discharge sys Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation EISE(HVID & Olyvision of Licensing 81/01/23 2pp
- B103120014 Ltr to all licensees of operating plants.CP holders & (IL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently unitted pages from NRC 801222 request for add) info re control of heavy loads EIBENHUI.D Q Division of Licensing 81/02/03 App
- 8103160667 Ltr to 41) operating plants & CP holders forwarding clarification of THI Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be not.

  EISENHUT, D. O. Division of Litemaing. 81/02/18 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnate 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EIGENHUT-D O Division of Licensing. 81/02/20 8pp.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs lexcept Bt Lucie.Units 1 & 2) Requests util review to determine capability to nitigate station blackout event & promptly implement emergency procedures EISENHUT.D.Q. Division of Licensing. 81/02/23. 3pp
- 8103170225 Ltr to all DWR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends & fitting mail per guidelines of encl Revision ( to MUREO-0313, Model Tech Specs only encl. EIBENHUT.D O. Division of Licensing. 81/02/26 | 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 % 3/4 4-8 re surveillance requirements for ABME Code Class 1,2 % 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements. • General Electric Co. 81/02/26. 4pp.
- B103310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  ETECHHUT. D. O. Division of Licensing. B1/03/10 App.
- 8103240443 Responds to NRC 801120 request for license amend application to revise Tech Specs to include surveillance of snubbers used in tadety-related applications Changes will be submitted upon decision to resume operation.

  CRANE.P.A. Pacific Gas & Electric Co... 81/03/20... 1p. 07987:355
- û Inspection reports: IE Bulletins & correspondence
- 9103100004 Forwards IE Insp Rept 50-133/80-04 on 801201-05 & notice of violation.

  BOOK.H.E. Region 5. Ban Francisco. Fuel Facility & Materiale Bafety Branch. 81/01/15 2pp. 07862:084.
- --8103100008 Notice of violation from insp on 801201-05.

  \* Region 5. San Francisco, Office of the Director. 81/01/15 lp. 07842:086.
- --B103100010 IE Insp Rept 30-133/80-04 on B01201-05. Noncompliance noted. failure to properly complete radioactive matl shipping papers.

  ORCIA:E.M., YUHAB:Q.P., WENSLAHSKI,F.A. Region 3: San Francisco, Diffice of the Director. B1/01/13. 13pp. 07862-087.
- 8103020076 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While an Duty." No written response required. ENGELKEN.R.H. Region 5, Sen Francisco, Office of the Director. 81/02/09. 1p. 07787.342.

- B103160636 Forwards 1E Info Notice B1.03 'Checklist for Litensees Making Notification of Significant Events in Accordance W/10CFR50 72 'No response required ENGELMEN.R H Region 3. San Francisco. Office of the Director B1/02/12 Ip 07917 094
- BioJ200897 Forwards Euppl 9 to IE Bulletin 80~17. "Failure of Cont Rods to Insert During Scram at BMR." to Inform of actions no longer required No written response required FMGELMEN.R H Region 5, San Francisco, Office of the Director 81/02/13. 1; 07967 224
- B103179023 Forwards 1E Circular B1-03. "Inoperable Beismic Monitor Instrumentation" No response required ENGELKEIAR H. Region S. San Francisco. Office of the Director B1/03/02 ip 07939 149
- 0103160052 Forwards revised IE Builetin 01-01. "Surveillance of Mochanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements FN3ELKEN.R H Region 5. San Francisco. Office of the Director 01/03/04 in 0.7914 209
- 0103200252 Forwards IE Info Notice 81-05, "Failure of ITE Model K-Cincuit Breaker" No response required ENGELMEN.R ii Region S. Gan Francisco. Office of the Director 81/03/11 1p 07968 340
- 8103200047 Forwards IE Info Notice 81-05. "Degraded DC Bys at Palisades" No response required ENOGLKEN.R H Region 5. San Francisco. Office of the Director 81/03/13 1p 07970 019
- R Periodic operating reports & related correspondence
- 8:03050226 Forwards "Rept on Radioactive Effluent Rejeases & Waste Disposal for Humboldt Bay Power Plant.Unit 3.
  Jul-Dec 1980 "
  CRANE, P. A. Pacific Oas & Electric Co. 81/03/03 in 07827 09
- --Bi03050233 "Rept on Radioactive Effluent Releases & Waste Dispos Humboldt Bay Power Plant Unit 3.Jul-Dec 1980 " 4 Pacific des & Electric Co. 81/03/03 53pp. 07827 054
- DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTER

  9 Inspection reports. IE Bulletins & correspondence
- B103020005 Forwards 1E Circular 81-02, "Performance of NRC-License Individuals While on Duty " No written response required ENGELKEN.R.H. Region 5, San Francisco, Office of the Director B1/02/09 tp 07785 360
- B. Reportable occurrences. LERs & related correspondence
- B102270094 PNA-B1-001 on B10129, cease & desist order issued by Sta MA, based upon B10126-29 insp findings. Insp disclosed that administrative controls re-radioactive mati-procurement & use were inadequate or not enforced NUBBBAUMER, D. A. Assistant Director for Material Safety & Licens SCHNEIDER, M. M. Office of State Programs. Director. B1/02/04 AS0029-044.
- DOCKET 50-141 STANFORD UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8103240102 Advises that License R+60 may be terminated when indeperence to firm that residue radioactivity levels meet NRC criteria for facility release to unrestricted access. Wo enci criteria & Reg Guide 1.86 STQLZ.J.F. Operating Reactors Branch 4 81/03/17 2pp. 07989
- DOCKET 90-142 UCLA TRAINING REACTOR

  F Security, medical, emergency & fire protection plans
- 8103060326 Forwards Amend 2 to physical security plan for protecti of SMM of moderate strategic significance Amend withheld (ref 10CFR2.790). CATTON, I., UECST, U. California, Univ. of, Los Angeles. 81/02/2 1p. 07837-062

#### 3 Adjudicatory correspondence

- BIOGOSOSOS Response in opposition to intervenor Committee to Bridge the Gap BIOGCé motion to compel further answers to interrogetories. Operating logs will be available for viewing BIOGO Certificate of Svc erol Related correspondence HERMICK.C. California. Univ. of. Los Angeles. 81/02/23. 14pp 07827 CBI
- B)03030509 Answer supporting intervenor Committee to Bridge the Cap motion to compol applicant answers to interrogatories Concurs u/intervenor assertion that applicant has not fully answered discovery requests for info.M/Oz/tificate of Svc MDECHEADLOP Hearing Branch 3. 81/02/27 6pp 07795 319
- Bj03j30453 Order directing applicant to respond to Connittee to Bridge the Gao B01020 interrogatories 4.5.6 % 9 re reactor usage & financing BCMERG.E S Ato-ic Safety and Licensing Opend Panel B1/03/10 352 07911 271
- 0100240542 Driven subsequent to second prehearing conference reviewing contentions detailed in MRC 801201 submittal Contentions V 3 & 11. XV.XVIII & XIII admitted Remaining contentions cented deferred or admitted as modified 80-485.8 S Atomic Safety and Livensing Board Panel 81/03/20 16pp 97986 034

#### · General correspondence

- 9109230670 Requests parts of operating logs & annual specialized activity repts Related correspondence.
  HIPSCH.D Consistor to Bridge the Gap 81/03/13 2pp 07977-090
- 9103240428 Advises that J Hornor will become campus radiation safety officer effective 810311 but will continue as member of radiation use committee for reactor facility OSTARALDER. N.C. California. Univ. of. Los Angeles 81/03/18 [p. 07790-169
- ) Inspection respects. IE Bulletins & correspondence
- 9103020007 Forwards IE Eircular B1-02. "Performance of NRC-Licensed Individuals While on Budy "No written response required ENOELXEN R H Region 5. Sen Francisco, Office of the Director B1/02/09 ip 07/87 lo9
- OCKET 50-148 UNIV OF HANBAB RESEARCH REACTOR

  Deerating license stage documents & correspondence
- 9103030119 Forwards revised NRC Region 4 organization chart-effective B10227 SEYERIT.K V Region 4. Dallas. Office of the Director B1/02/17
- арр
- ) inspection reports. IE Bulletins & correspondence
- 310320982 Forwards (E Circular Bi-O2. "Performance of MRC-Licensed Individuals While on Duty " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director Bi/O2/09 ip 07967 177
- DOCKET 30-150 ONIO STATE UNIV RESEARCH REACTOR

  Derrating license stage documents & correspondence
- BIO30604B2 Forwards organisational charts depicting NRC Region 3 reorganisation affective BIO216. KEPPLER.J G. Region 3. Chicago. Office of the Director BI/02/20 2pp 07836:050
- COCKET 50-151 UNIV OF ILLINGIS REBEARCH REACTOR

  7. Operating license stage documents & correspondence
- 9103060501 Forwards organizational charts depicting NRC Region 3 reorganization.effective 910216 KEPPLER.J. J. Region 3. Chicago. Dffice of the Director 81/02/20. 2pp 07836:081

- 8103310465 Advises that fission chamber which became inoperable Oct 1780 was replaced on 810318 Normal operations started 810319 8ECA-0 P 1111nois. Univ of Urbana-Champaign 81/03/26 ip 03059 207.
- O Inspection reports. IE Buildins & correspondence
- B103030401 Forwards IE Insp Rept 50-191/80-04 on 801204 & notice of violation. HEIBHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch B1/01/02 2pp. 07795 001
- --Bi030304i0 Notice of violation from insp on 001204 HEISHMAIR F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/12/31 ip 07795:003
- --8103030425 IE Insp Rept 50-151/80-04 on 801204 Noncumpliance noted fuel temp instruments & associated safety sys scram capability removed from eve during period when power to fuel temp reasuring channels was inadvertently turned off RIDSWAY. K R . BDONE. J. M . BOYO. B C Region 3. Chicago. Office of the Director BO/12/23 4pp. 07795 004
- 8103020354 Forwards IE Circular B1-02, 'Performance of NRC-Licensed Individuals While on Duty " No written response required XEPPLER. J G Region 3, Chicago, Office of the Director. 81/02/09. 2pp. 07787-256
- R Periodic operating reports & related correspondence
- 8103040750 Forwards "Annual Rept.IL Advanced TRIGA.1980." BECK.G.P., MILAVICKAS.L., MILEY.O.H. 1111nois, Univ. of. Urbana-Champaign 81/02/28 Ip. 07812-271.
- --B103040755 "Annual Rept. IL Advanced TRIGA. 1980 "

  \* Illinois. Univ of Urbana-Champaign 81/02/28 2pp
- DOCKET SO-155 BIO ROCK POINT NUCLEAR PLANT

  F Becurity, medical, emergency & fire protection plans
- B1010900B3 Releases public version of "Calculations Re Establishment of Primary Emergency Planning Zone (EPZ) Redius of 5 Miles for 8ig Rock Point Plant."
  FELTON. JM. Division of Rules and Records 80/12/02 ip D7441: 184
- --Bi0122023k Forwards public vorsion of, "Calculations of Establishment of Frimary Emergency Planning Zone (EPZ) of Five Miles "FROSTS R Consumers Power Co. 80/04/24. 1p. 04696:347
- --Biologooba Public Version of "Calculations Re Establishment of Primary Emergency Planning Zone (EPZ) Radius of 5 Miles for Big Roof Point Plant."

   Consurars Power Co. 80/04/24, 10pp 07441.185
- B103056220 Releases public version of emergency plan. FELTON, J M Division of Rules and Records. 81/02/18 ip. 07806-005
- --8103050256 Forwards public version of emergency plan in response to IMC 801113 request includes State of MI draft emergency preparadness plan. Emmet County. MI draft incident procedures & Charlevoix County. MI draft emergency operations plan. HOFFMAN. D. P. Consumers Power Co. 81/01/30. 3pp 07806-001
- --8103050266 Public version of emergency plan Includes State of MI draft omergency preparedness plan. Emergency Danty, MI draft incident procedures & Charlevols County, MI draft emergency operations plan. not yet approved by PEMA.

   Michigan, State of Charlevols, MI. Affiliation Unknown. B0/04/30. 500pp. 07806 001.
- 8103180264 i.tr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addl info resafe shutdown capability for compliance u/801119 fire protection rule EISECHUT.D.O. Division of Licensing. 81/02/20. 13pp.
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl. EISENMUT.D.Q. Division of Licensing. 81/03/05. 6pp.

BIOGRADO Formards aggregate planning into for placement in LPDR W/o 81.13656504 Division of Bules and Becords - 81/03/11 to SQUDER, J L CBO 40: 26B 8103190140 Releases public version of implementing procedures for emernencu plan FELTON.J M Division of Rules and Records 81/03/12 to

-- 9100190147 Forwards public version of plant manual, Vol 9A re site emergency plan implementing procedures, in response to NRC BATILY PROPER HOFFMAN, B P Consumers Power Co 81/02/23 1p. 07806.001

07806.001

--Bio3(90193 Public version of plant ranual.Vol 9A re site emergency plan implementing procedures includes activation of emergency plan, activation of support ctrs, emergency personnel & post-accident monitoring procedures
HARTMANIC J Consumers Power Co 80/12/03 20000 07806 001

A163940120 Bubmits plans & schedules to achieve compilance w/applicable sections of App R Design description provided for NRC approval of fire protection most necessary to safisfy Section III 0 3. Design changes to be submitted by 810517 JOHNSON 8 D. Consumers Power Co. 81/03/19. Spp. 0799( 07990 290

8103261183 Requests that encl emergency planning info be placed in LPDR W/0 8103190147 SQUDER, J. L. Division of Rules and Records B1/03/24 in. 08040 233

O. Adjudicatory correspondence

8103020592 Order denying J Leithauser request for 810109 transcript of based on Comptroller General decision that program procluded by Appropriations Act BISHOP C J. At Atomic Bafety and Licensing Board Panel 81/02/25

8103040609 Forwards 810225 notice of finality of Commission action w/ regard to generic FEB on handling & storage of spent light water power reactor fuel (NUREG-0575) MODREJ E. Hearing Brench 2 81/03/03 1p 07817-077

8103)(0500 Informs that time for Commission to act to review Director's Decision DD-80-34 has expired Decision became final agency action on 810303 CHILN, S J Office of the Secretary of the Commission 1p. 07872.201.

8103110621 Comments on licensee 810117 motion to strike partians of CEG lift & NRC response to motion. Opposes licensee motion. CEG had no opportunity to respond to questions re NEPA at oral argument % CEO ltr was to clarify issue. SHEA.J.F. Council on Environmental Quality. 81/03/05. [p. 07887.088.

8103110619 Withdraws 810302 motion for appropriate delay of 15 days since being informed of contents of CEQ missing envelops.

O'NEILL, J. Affiliation Unknown 81/03/09. 1p. 07882:362.

8103120374 Withdraws 810302 motion for appropriate delay of 15 days due to info re contents of missing envelops obtained from Council on Environ Quality Q-METLL-J. Affiliation Unknown. BI/03/09. Ip. 07904: 358.

B103180567 Withdraws 810203 motion to delay proceeding 15 days. D'NEILL-J. Aff[liation Unknown. 81/03/09. 1p.

8103250249 Request that Commission take official notice of J Leithauser status as intervenor on need for power issue. Leithauser notion to intervene was granted on 800319 Certificate of Byc encl LEITHAUSER, J. A. Affiliation Unknown. 81/03/10. Spp.

9103270639 Forwards NRC responses to D'Neill interogatories, served on BO1105.per Smith B10325 telcon W/o encl MODRE, J. E. Hearing Branch 2. 81/03/25. ip. 00043:245.

H General correspondence 8103260349 Responds to 810223 & 0131 ltrs re public ed & info for emergency planning Agraes w/previous NRC 810309 & FEMA 810220 responses Constructive comments will be seriously Considered in NRC roview of public info pamphlet.

BTELLO.V. Director's Office, Office of Inspection and Enforcement.

B1/03/20. 1p. --8103260357 Comments on NUREO-0654 Document is force & case of munderque -nnlinenc D'SULLIVAN. J.F. Affiliation Unknown 81/02/23 ic

--8103260365 Forwards 'Detailed Critique of Parphlet Guide to Charleynia 10J2COVACO FORMATOS (PERSILEO CTILIQUE OF PATRICE COISE TO \$ Emmot County.MI Erergency Operations Plans "Illustratio contradict \$ violate principles of protection from nuclear fallout Cover page of pamphlot encl D'SULL(PVAN.JF Affiliation Unknown 81/01/31 9pp Illustrations

8103160528 Forwards Annual Financial Rept 1980 PERRY, P. A. Consumers Power Co. B1/03/11 10 07917 192 --8103160538 Annual Financial Rept 1983 \* Consumers Power Co 81/02/13 28pp 07985 001

I Financial information

07812 356

P Doerating license stage documents & correspondence

7905310447 Responds to IE Builetin 78-128. 'Atypical Held Matl in Reactor Pressure Vossels " C-E engaged in performing records search per IE Bulletins 78-12.78-124 & 78-128 Oeneric rept to be submitted directly to NAC before 790608 DIXEL D A Consumers Power Co 79/05/29

8)03040163 Forwards Arend 34 to License DPR-6, safety evaluation to instice of issuance & availability CRUTCHFIELD. D Operating Reactors Branch 5 80/09/16 2pp

07012 348 --8103040178 Amend 34 to License DPR-6, changing low reactor water level

trip setpoint.
CRUTCHFIELD.D. Operating Reactors Branch 3 80/09/16 Age 07812 350 .-B103040186 Bafety evaluation supporting Amend 34 to License DPR-6

Office of Nuclear Reactor Regulation, Director 80/09/14

--8103040195 Notice of issuance & evailability of Amend 34 to Liconse DPR-A CRUTCHFIELD, D. Goprating Reactors Branch 5. 80/09/16 200 07812 398

8103199732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests raview per guidelines in NUREG-0512 Forwards NRC position re interim actions & request for addi info EISENHUT, D. C. Division of Licensing 80/12/22 30pp

07785: 013 B103030935 Forwards Amend 36 to License DPR-6. safety evaluation & notice of issuance & availability. CRUTCHFIELD. D. Operating Reactors Branch 9 81/01/12 3pp

B103020088 Requests submittal of Tech Spec change re sys integrity

measurements program as discussed in NRC 800702 ltr

CRUTCHPIELD, D. Operating Reactors Branch 5 91/01/07

07795: 245. --8103030947 Amend 36 to License DPR-6 removing restrictions on allowable

locations for auxiliary neutron sources & modifying physical description of auxiliary neutron sources, allowing placement of sources in fuel assembly ctr CRUTCHFIELD D. Operating Reactors Branch 9 81/01/12 4pp 07795 248

--8103030993 Safety evaluation supporting Amend 35 to License DPR-6 - Office of Nuclear Reactor Regulation, Director 81/01/12 07795 252 ---B103030998 Notice of issuance & evailability of Ahend 36 to License

CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/12. 2pp 07795.254. 8103090232 Forwards Amend 39 to License DPR-6. safety evaluation & notice of issuance & availability.

CRUTCHFIELD.D. Operating Reactors Branch 5. 81/01/19. 3pp 07819: 036. --B103090236 Amend 39 to License DPR-6, incorporating surveillance

requirements for new automatic isolation valve in fire protection water spray sys protecting yard transformers CRUTCHFIELD, D. Operating Reactors Branch 5. 81/01/19 69p 07849 039

- --8103090238 Safety avaiuation supporting Arend 37 to License BPR-6 • Office of Nuclear Reactor Regulation. Director 81/01/19 2pt 07849-045
- ---BiG3090243 Notice of issuance & availability of Amend 39 to License OFR-6
  CRUTCHFIELD. D. Operating Reactors Branch 5 81/CI/I9 2pp
- 9103190387 Ltr to all licensees of operating plants & applicants for O.s & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve toll shutdoun.replacement parts & NUREG-0737 £15EN-NUT-D 0 pyrision of Licensing 81/071/19 App
- Bi03240290 Ltr to all BWR licenses forwarding Supplif to generic safety evaluation on BWR scram discharge sys Summarlies re-evaluation of interim reasures recommended per 80/201 safety evaluation of Licensing 81/01/23 2pp
- 9103090318 Forwards request for add1 info re adequacy of station electric distribution voltages
  CRUTCHFIELD.D Operating Reactors Branch 3 81/01/27 Spp.
  07832-138
- B:03120035 Requests revision to proposed inservice testing program to include Category E safety-related locked valves Revision should be eade within 45 days
  CRUICHFIELD.9 Operating Reactors Branch 5 81/01/27 4pp 0790A 338
- 8103090326 Advises that proposed 810401 completion date for mods re anchorage & support of safety-related electrical equipment is acceptable CRUICHFIELD.D Operating Reactors Branch 5 81/01/28 3pp 07602-172
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants except fidian Point 2 & 3.Zion 1 & 2 & TMI-1, forwarding inadvertently unitted pages from MRC 801222 request for addlinfore control of heavy loads EISEMAJT.D O Division of Licensing 81/02/03 App
- 8103030590 Burnary of 810119 neeting "/util in Detheads HD to provide NRC U/overview of probabilistic risk assessment program at facility List of attendees 2 visugraphs enc! PAULSON-U. A Operating Reactors Branch 5 81/02/06 7pp. 07793 175.
- B103090681 Forwards "Environ Qualification of Bafety-Related Electrical Equipment," partial review Written response required LANAS.O.C. Assistant Director for Bafety Assessment 81/02/13 4pp 07844 253
- --8103090585 "Environ Qualification of Safety-Related Electrical Equipment." partial review. -- Office of Nuclear Reactor Regulation, Director. 81/02/13 18pp 07844 257
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1.2 re upprade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met.

  EISENHUT.D O Division of Licensing 81/02/18. 12pp
- Bi00090240 Forwards organizational charts depicting NRC Region 3 reorganization.effective Bi0216.

  KEFPLER. J O Region 3. Chicago. Office of the Director Bi/02/20 2pp 07852.044
- B103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENRUT. D. O Division of Licensing. 81/02/20 Bpp
- 8103060567 Forwards topical rept evaluation of XN-NF-78-25. Revision 1.

  "Big Rock Point LOCA Analysis Using Erzon Nuclear Co Non-Jet
  Pump SMR Evaluation Model Large-Break Erzongle Problem."
  CRUICHFIELD.D. Operating Reactors Branch 5 81/02/23 3pp
  07840. 260
- --Bi03060572 Topical rept evaluation of XN-NF-7B-25. Revision 1. "Big Rock Point LOCA Analysis Using Erron Nuclear Co Non-Jet Pump BMR Evaluation Nodel Large-Break Example Problem." Rept acceptable Operating Reactors Branch 9 81/02/23 10pp 07840.263

- Bi03130266 Fauerds Arends 41 3 65 to Licenses DPR-6 & DPR-20, respectively & notice of issuance & availability CRUTCHFIELD. O Operating Reactors Branch 5 81/02/25, 4pp. 07912 181
- --8103130275 Amends 41 & 65 to Licenses DPR-6 & DPR-20, respectively, including requirement to maintain guard training & qualification plan & for full implementation within 60 days CRUICHFIELD.D Operating Reactors Branch 5 81/02/25 4pp 07912-189
- --Bi931302BO Notice of issuance & availability of Amends 41 & 65 to Licenses EPR-6 & DPR-20, respectively CRUTCHFIELD. D. Operating Reactors Branch S. 81/02/25 2pp 07912:189
- Bio3230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 8t Lucie Units 1 & 2). Requests util review to determine capability to mitigate station blectout event & promptly implement emergency procedures EISSINIJT.D G Division of Licensing 81/02/25 Spp
- 8103020409 Forwards probablistic risk assessment sections re recirculation pump trip efficacy.per Amend 3B to License DP9-6 WIFHRDJ-0 C Consumers Power Co. 81/02/26 100pp 07784 122.
- 8103170225 Ltr to all DHR licensees (ercept Humboldt Bay & LaCrosse) requesting review of ASME Code Class | 1 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision i to NUREO-0313 Model Teth Specs only encl EISE(RMUT.D 9 Division of Licensing B1/02/26. 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 surveillance requirements for ABME Code Class 1,2 & 3 tomponants & RCS operational leakage limiting conditions for operation & surveillance requirements # General Electric Co 81/02/26 4pp
- 9103230813 Generic Ltr 81-06 to all CP holders & QL applicants re ICCFR\$0 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status.format & content encl EISENUT.D 0 Olivision of Licensing 81/02/26 iOpp
- 9103160fil Forwards safety evaluation & technical evaluation of BEP Topic VIII-3 A station battery capacity test requirements CRUICHFEELD. D. Operating Reactors Branch 5 81/02/27 3pp.
- --8103160116 Sefety evaluation to SEP Topic VIII-3 A station battery capacity test requirements Approves proposed change to diesel generator start battery testing.

   Operating Reactors Branch 5 81/02/27 2pp.
- --8103160124 Final draft GEP technical evaluation of Topic VIII-3.A. "Battery Capacity Tests."
  RDBERTS.E W Affiliation Unknown. 79/12/20 3pp.
- B103170222 Forwards request for add1 info re mechanical operability of containment purps & vent valves. Response requested within 45 days of receipt of itr CRUTCHFIELD.D. Operating Reactors Branch 5. B1/02/27, 5pp 07929 257
- 8103090269 Cornents on NRC 810213 Itr re environ qualification of sefety-related electrical equipment Plant operation may continue safely
  - WITHROW, 0 & Consumers Power Co. 81/03/02 9pp. 07832: 194.
- 8103090392 Forwards notorized statement under oath & effirmation for 810122 & 0226 submittals which provided NRC requested info re Amend 38 to License DPR-6 HOFFHAN D.P. Consumers Power Co. 81/03/04. 2pp. 07850-213
- 8103090412 Forwards application to amend OL.Incorporating Tech Specs addressing actions taken in response to Category A Lessons Learned items
  HOFFMAN D. P. Consumers Power Co. 81/03/05, 2pp 07846, 171.
- --8103090418 Application to amend OL/ incorporating Tech Specs addressli actions taken in response to Category A Lessons Laerned items BEWITT.R.B. Consumers Power Co. 81/03/05. 2pp. 07846:173
- BID3110707 Forwards request for add1 info on SEP Topic VI-7. B, engineered safety feature switchover from injection to recirculation modes Response should be submitted within 30 days.

  CRUTCHFIELD. D. Operating Reactors Branch 5. BI/03/05. App. 07885-031.

- 17 Forwards application to amend License DPR-b, changing Tech 117 Forwards application to amenu Literse umra-o.cnangin; ections 6 4.2 % 6.4 3 re use of TLDs as alternate to or environ monitoring process.Class II amend fee encl N<sub>F</sub>D P Consumers Power Co. B1/O3/O6 Ip. 07865-060
- 0921 Application to amend to License DPR-6, changing Tech Bpecions 6 42 % 6 4 3 re use of TLDs as alternate to Pilm environ monitoring process.
  TT.R.B. Consumers Power Co. 81/03/06 2pp 07865 061
- 23 Requests NRC attendance at B10317 meeting w/util in Jackson-discuss utilization of probabalistic risk assessment ermination of overall plant safety. Agenda encl -R B Consumers Power Co. B1/03/06 4pp. 07907.073
- 17 Submits final response to NRC 801217 ltr re SEP Topic ing strikes.ice loading.design wind speeds and when ting provided

  F.R.A. Consumers Power Co. 81/03/09 4no. 07878 214
- 35 Forwards evaluation of SEP Topic V-5 re reactor coolant re boundary leakage detection Requests info re ences between as-built facility & licensing basis 30 days.

  FIELD, D. Operating Reactors Branch 5. 81/03/10 10pp.
- 015
- O4 Ltr to all licensees of operating plants, applicants for CLs ers of CPs forwarding SECY-81-119 re info necessary to ish environ qualification of safety-related electrical ent UT.D.O. Division of Licensing 81/03/10 App.
- 67 Notification of BiO317 & 18 meeting w/util in Bethesde.MD to a licensee probablistic risk assessment for facility encl.
  W.W. A. Operating Reactors Branch 9 81/03/11 2pp
- ii Confirms telton re 810320 meeting w/Dfc of Nuclear Reactor tion to discuss items to upgrading licenses GA topical
- N.D. P. Consumers Power Co. 81/03/16, 2nd 07964:150
- 56 Forwards responses to NRC 810127 request for addl info re cy of station electric distribution voltages.Provides y of actual running bus loads & total connected bus based on ampero & watt feeder readings.

  N.D. P. Consumers Power Co. 81/03/23 8pp. 08039:162.
- 49 Forwards request for Tech Specs change to reduce high encluse acram setting per NURED-0737, Item II. 8 4.2. inment isolation Dependability. "
  N.D.P. Consumers Power Co. 81/03/23 App. 08037.169.
- 80 Forwards revised pages to inservice test program for pumps & to include Category E valves in response to NRC request N. D. P. Consumers Power Co. 81/03/23. 4pp. 08037:358.
- 76 Notifies that util commits to completing Item 32 main panel CO2 anchorage at hert cold shutdown All other items in ment 1 to 910122 Itr will be completed by 810401.
  N.D. P. Consumers Power Co. 81/03/26 ip. 08058.127.
- ction reports. IE Bulletins & correspondence
- 98 Forwards IE Insp Rept 50-155/80-19 on 810108-09. No pliance noted. pliance noted. AN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support 81/01/27. 2pp. 07824:297.
- 0403 IE Insp Rept 50-155/80-19 on 801208-09.Ng moncompliance one in the new our largorit on BOLEUS-DY.No BORCO d.Major areas inspected:maint & IE bulletin.circular R Pollowy.
- HT.O.C., PARKER,M.E., BDVD,D.C. Region 3, Chicago Office of Director. 81/01/27, 8pp. 07824:299.
- 67 Ack receipt of 810113 ltr informing NRC of steps taken to t violations noted in IE Insp Rept 50-155/80-14. AN R.F. Region 3, Chicago, Reactor Operations Nuclear Support

- 8103020125 Forwards IE Circular 81-02. 'Performance of NRC-Licensed Individuals While on Outy "No written response required AEPPLER. J. G. Region 3. Chicago, Office of the Director 81/02/09 200 07788 02A
- B103040295 Forwards JE Jr.fo Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance M/10CFR50 72." No written response required MEPPLER. J O. Region 3. Chicago, Office of the Director 81/02/12 2pp 97815 257
- 8103030279 Forwards Suppl 5 to 1E Bulletin 80-17. "Failure of Control Reds to Insert During Scram at BUR ' No written response MEPPLER. J G Region 3. Chicago, Office of the Director 81/02/13 200. 07790 325
- 8103160508 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required KEPPLER, J. O. Region 3. Chicago, Office of the Director 81/03/02 2pp 97916 COA
- 8103160890 Forwards revised [E Bulletin Bi-Oi. "Surveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  KEPPLER, J G Region 3. Chicago, Office of the Director 81/03/04 07915 047
- 8103190351 Submits supplemental response to IE Bulletin 80-0a. "Engineered Bafety Feature (ESF) Reset Controls " Valve designation for 800625 Response 1. Item 5 should be CV-4190 instead of CV-4090 Approx 130 menhaurs expended on review MITHROW-9. C. Consumers Power Co. 81/03/11 2pp 07955.002
- 8103200868 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater" No written response required KEPPLER. J Region 3. Chicago. Diffice of the Director. 81/03/11 2pp 0/785.195.
- 8103200677 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades." No action required.
  REPPLER.J G Region 3. Chicago. Office of the Director 81/03/13 2pp 07966 173
- B103231069 Responds to IE Bulletin B1-01, "Gurveillance of Mechanical Bnubbers," No snubbers mfg by Intl Nuclear Bafeguards Corp in use Visual Insp & functional testing for snubbers is scheduled for 1982 refueling outage WITHROW.O.C Consumers Power Co. B1/03/13 2pp 07976.329
- B1032310B1 Responds to IE Bulletin 80-25. "Operating Problems w/Taryet Roct Bafety-Relief Valves at BWRs " No mods to target rock relief valves or actuation sys required.
  MITHROW O. C. Consumers Power Co. 81/03/13 4pp 07976-323
- 8103200260 Forwards 1E Info Notice 81-07, "Potential Problem M/Water-Boluble Purge Dam Matls Used During Inert Gas Welding " No response required KEPPLER. J. Q. Region 3, Chicago, Office of the Director 81/03/16 2pp. 07970.349
- R Periodic operating reports & related correspondence
- B103030781 Forwards annual occupational exposure rept for 1980 WITHROW G.C. Consumers Power Co. 81/02/26. 1p. 07795 075
- --8103030787 Annual occupational exposure rept for 1980. \* Consumers Power Co. 81/02/26. 9pp 07793: 076
- 8103040669 Forwards "Big Rock Point Nuclear Power Plant Radioactive Effluent Release. Jul-Dec 1980." WITHROW, Q. C. Consumers Power Co. 81/02/27, 1p 07810:173.
- ~-Bi03040673 "Big Rock Point Nuclear Power Plant Radioactive Efficient Release-Jul-Dec 1980 " # Consumers Power Co Bi/02/27. Bpp. 07810-174.
- 8103110471 Forwards monthly operating rept for Feb 1981. HARTMAN.C J. Consumers Power Co. B1/03/06. 1p. 07869:348.

- S Reportable occurrences. LERs & related correspondence
- B10304003B Ph0-111-60-233 electrical connector problems resulted in plant shutdown over two days Caused by lack of adequate rati &/or test date to determine acceptability of connectors Program identified to rework connectors MRIGHT.0. GDVb.D.C. HEISHMAN.R.F. Region 3. Chicago. Office of the Director B3/12/19 ip. 0/816-331
- 8103030797 Forwards LER 81-003/03L-0 MITHREN, 9 C. Consumers Power Co. B1/02/26 1p. 07797 356
- --8105030804 LER 81-003/00L-0 on 810128. backup mitrogen bottle supply for containment vacuum rollef valve control sys depressurized Caused by fractured bottle isolation valve body probably due to overtightening bonnet mounting nut Valve replaced a Consumers Power Co. 81/02/28 1p. 07797:337
- 8103060550 Forwards updated LER 80-034/01X-1. HOFFMAN, D.P. Consumers Power Co. 81/03/02 lp. 07837:164
- --6103060555 Updated LER 80-034/01X-1 on E0tiol.M51V M07090 failed to close on renote manual initiation Gaused by buildur of graphite packing matt on valve ster Valve repected + Consumers Power Co. 81/03/02 200 07837 165

#### V Operator Examinations

- 8103020367 Forwards updated response to NUREG-0737 items re-shift technical advisor.post-accident sampling capability.noble gas effluent monitor sampling analysis of plant effluents & upgrade emergency support facilities.
  FROST, S.R. Conscers Power Co. 81/02/29. Bpp. 07783-096
- B103310470 Discusses NRC concerns relack of mechanism to inform plant personnel about industry problems such as St Lucie incident. IE Circular 80-15 Mechanism explained in 801217 response to NAREG-0737 % at B10214 ceeting No further changes needed FROSIS R Consupers Power Co 81/03/25. Ip
- ODCKET 50-196 UNIV OF WISCONSIN RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- 8103060431 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216 PEPPLER, J. G. Region 3, Chicago, Office of the Director 81/02/20 2pp 07836,008
- DOCKET 80-360 GEORGIA INST OF TECH. RESEARCH REACTOR

  G. Inspection reports: IE Dulletins & correspondence
- 8103020149 Forwards 1E Circular 81-02. "Performance of NRC-Licensed Individuals Waile on Duty " No written response required. G'REILLY-J.P. Region 2. Atlanta, Office of the Director. 81/02/09. ip 07780-059
- DOCKET 50-163 GENERAL ATOMIC COMPANY

  F. Security, redical, emergency & fire protection plans
- 8103120636 Discusses GA Co 800516 physical security plan 5 payment of fee. No more face will be collected until review 5 approvals are completed DIGGER M License Fee Management Branch. 81/03/06 ip. 07906.128
- J. Insurance & indemnity information
- 8103060911 Forwards Endorserent 52 to MASLU Policy MF-59 CORREALM.A. Marsh & McLennen.Inc., N & H Nuclear Consultants.Inc. Div B1/01/30 200 07839:356
- Q. Inspection reports: IE Bulletins & correspondence
- 8103040246 Forwards IE Insp Repts 90-089/80-03 & 50-163/80-03 on 801215-18 No noncompliance noted. BDOK-H.E. Region 5- Ban Francisco, Fuel Facility & Materials Safety Branch. 81/01/16 2pg. 07813:268

- --Bi03040261 IE Insp Repts 50-163/B0-03 & 50-069/B0-03 on B01215-18 ho nance-plience moted. Major areas inspected radiation protection, environ monitoring, emergency aspects of TRIGA Mark 1 & Mark F reactors & records & logs CURTIB.J R , WEMSLAKSKI.F Region 5. Can Francisco. Office of the Director BCEK.H E. Region 5. San Francisco. Fuel Facility & Paterials Safety Branch 81/01/16 Spp 07813:270
- 8103020102 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals White on Duty ' No written response required. ENSELKEN.R H Region 5. Ban Francisco. Défice of the Director 81702709 ip 07787 359
- R Periodic operating reports & related correspondence
- B103030B25 Submits annual operating rept for 1980. MCMRY. M. R. General Atomic Co. (subs. of Gulf Oil Co.). 81/02/27 Acc. 0.7797-346.
- OCCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

  G Adjudicatory correspondence
- BIO3230717 Advises that notice of appearance re TRIGA research reactor inadvertently not filed.Notice & Certificate of Svc encl. BRITTIGAN. B L. Defense.Dept. of: Defense Nuclear Agency. 81/03/12 ip 07977 335
- --BI03230718 Rotice of appearance at Armed Forces Radiobiological Research Inst License renewal hearing Contificate of Bvc enci BRITTIGAN.R.L Defense Dept of Defense Nuclear Agency. 81/03/12 2pp 07977 356
- U Congressional/Executive Correspondence
- 810324013B Responds to 810109 1tr re-relicensing of facility. AGL8 hearings will be hold in Betheeda. MD area RRC will conduct analysis of environ & safety-related aspects of reactor operations. AHEARINE, JF Commissioners 81/02/20 2pp 07990.123.
- ODCKET 30-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT I
- 8103170984 Forwards Annual Financial Rept 1980.

  RHABLEY, E. J. Philadelphia Electric Co. 81/03/13 700
- --B103170596 Annual Financial Rept 1980

   Public Service Electric & Gas Co. of New Jersey. 81/02/16
  5200.
- --8103170606 Annual Financial Rept 1980.
   Philadelphia Electric Co. 81/03/13. 46pp.
- ~~8103170616 Annual Financial Rept 1980. \* Atlantic Electric of New Jersey. Bi/03/13. 40pp.
- --8103170626 Annual Financial Rept 1980 \* Delmarva Power & Light Co. 81/03/06 40pp.
- P. Operating license stage documents & correspondence
- 8102270565 Notification of contract execution.Mod 2 to "Environ Monitoring Program W/Commonweelth of PA." Contractor: Commonweelth of PA BAISDEN.L. Research Contracts Brench. FIN B-5111. 81/01/07. Jp 07772.351.
- --8102270590 Mod 2,adding TLD monitoring around facilities & increasing amount of contract to "Environ Monitoring Program W/Commonwealth of PA."
  GERUSKY.T.M Pennsylvania, Stats of MDRTGN.K.V. Research Contracts Branch. Fin 8-5111. 81701/07. 4pp. 07772:352.

DOCKET 50-182 PURDUE UNIV REBEARCH REACTOR

F Security, medical energency 3 fire protection plans

B103230125 Forwards Amend 5 to License R-B7 which identifies approved physical security plan Requests submittal of transportation physical security plan-120 days prior to any anticipated stipments or receipts of SNM MILLERJR Standardization % Special Projects Branch B1/03/10 3pp 07981 253

--3103230129 Amend 5 to License R-87, updating latest requirements of physical security plan MILLER. J R Standardization & Special Projects Branch 81/03/10 2nc 07981 255.

#### P Operating license stage documents & correspondence

8103060423 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 KEPPLER, J. G. Ragion 3. Chicago, Office of the Director 81/02/20 2pp. 07836:002

8103230125 Forwards Amend 5 to License R-87 which identifies approved physical security plan Requests submitted of transportation physical security plan. 120 days prior to any anticipated shipments or receipts of SNM.
MILLER-J.R. Standardization & Special Projects Branch 81/03/10.
30m. 07981-233

--8193230129 Amend 5 to License R-B7.updating latest requirements of physical security plan
MILLER.J.R Standardization & Special Projects Branch 81/03/10
2pp. 07981 256

## Q. Inspection reports. IE Bulletins & correspondence

Bi03090480 Forwards IE Inso Repts 50-102/81-01 & 70-0152/Bi-01 on Bi0112-14. No noncompliance noted. FIBHER.M.L. Region 3. Chicago, Fuel Facility & Materials Safety Brench. Bi/02/05 2pp 07847:340.

--8103090485 1E Insp Repts 50-182/8]-01 & 70-0132/81-01 on B10112-14 No noncompliance noted Major areas inspected organization, safety committees criticality safety radiation protection & radwaste mgt.

PECK.C.C. Region 3. Chicago, Office of the Director. FIGHER-W L.

Region 3. Chicago, Evel Facility & Moterials Safety Branch.

81/02/05. 7pp 07847:342.

OCCRET 50-183 VALLECITOS EXPERIMENTAL BUPERHEAT REACTOR

R Periodic operating reports & related correspondence

810317063B Farwards "ESADA Vallecitos Experimental Superheat Reactor Annual Rept 13.1980 " CUNNINDHAM-0 2 General Electric Co. 81/02/25. 1p. 07739.238.

~-8103170644 "EGADA Vallacitos Experimental Buperheat Reactor Annual Rapt 13, 1980. "

General Electric Co. 81/02/25. 3pp. 07939:239.

OOCKET 90-184 NATIONAL BUREAU OF STANDARDS REACTOR
C. Utility Environmental Report (ER), amends & correspondence

8103130533 Certifies eve of environ rept for NBB reactor on 810304. RABY.T.M. Commerce.Dept.of. National Bureau of Standards. 81/03/04. 3pp. 07908:312.

# P. Operating license stage documents & correspondence

Bi03060009 Advises of initiation of NRC environ review re 801202 QL renewal application. EIA must be distributed according to enci list. Affidavit assuring distribution completion must be submitted within 10 days after filing.
MILLER.J.R. Stendardization & Special Projects Branch. BI/02/19. 4pp. 07837:049.

## R. Periodic operating reports & related correspondence

8103240225 Forwards "Operations Rept 30 for Jul-Dec 1980." CARIER.R. 8. Commerce.Dept.of. National Bureau of Standards. 81/03/20. 1p. 07989:394

--8103240237 "Operations Rept 30 for Jul-Dec 1980 '
CARTER.R B Correcte Dept of, National Bureau of Standards
B1/07/20 eeu 07989 355

DOCKET 50-185 PLUM BROOK REACTOR - MCCK-UP

C Utility Environmental Report (ER), amends & correspondence

B10302063B Forwards Amend 1 to "Dismantling Plan.Plum Brook Reactor Dismantling." "Environ Rept.Plum Brook Reactor Dismantling." "Dismantling Plan.Plum Brook Mock-Up Reactor Dismantling." & "Environ Rept.Plum Brook Mock-Up"

BENEDICT.D E National Aeronautics & Space Admin B1/02/23 2

--Bi03020554 Amend 1 to "Environ Rept.Plum Brook Mock-Up Reactor Dismantling." • National Accupantics & Space Advin 91/02/18 4no

 $\boldsymbol{P}$  . Operating license stage documents & correspondence

8103030396 Responds to 800317 application & 801107 itr re dismanti reactors & decontaminating labs. Proposed radiation limits must be revised to seet encl levels PEID. R.W. Operating Reactors Dranch 4 81/02/11. 3pp. 07790

810302083B Forwards Amend 1 to "Dismantling Plan. Plum Brook Reacto Dismantling." "Environ Rept. Plum Brook Reactor Dismantling." "Dismantling Plan. Plum Brook Mcc:-Up Reactor Dismantling." to "Environ Rept. Plum Brook Mcc:-Up Reactor Dismantling. "to "Environ Rept. Plum Brook Mcc:-Up"

DENEDICT. D E National Aeronautics & Space Admin 81/02/23 207782 106

--8103020651 Amend | to "Dismantling Plan, Plum Brook Mock-Up React Dismantling "

\* National Agronautics & Space Admin 81/02/18 4ng

--Bi03020654 Amend 1 to 'Environ Rept.Plum Brook Mock-Up Reactor Dismantling " National Aeronautics & Space Admin Bi/02/18 4op 07782

R Periodic operating reports & related correspondence

8103030692 Forwards "Rept of Reactor Standby Condition for NAGA.Pl Brook Mockup Reactor, 1980." BDITELE C., RICHLEY.E. A National Aeronautics & Space Admin B1/02/20 2pp. 07798 262

=-8103030694 "Rept of Reactor Standby Condition for NASA-Plum Broo Moctup Reactor, (980. "

\* National Aeronautics & Space Admin 81/02/17. 2pp 07798

DOCKET 50-186 UNIV. OF MISSOURT RESEARCH REACTOR
P. Operating license stage documents & correspondence

B103050477 Forwards organizational charts depicting NRC Region 3 reorganization effective B10216. REPPLER. J.O. Region 3. Chicago. Office of the Director 91/02/2pp. 07836:044

B103100418 Requests change to 801218 proposed Tech Spec Sections 1, 20(d) & 1, 20, b(2) to clerify statement of control rodwork.

MCKIBBEN.J C. Missouri, Univ. of, Columbia. 81/03/03 2pp. 07855 210.

--8103100423 Proposed revision to Tech Spec Sections 1, 20(d) & 1 2 clarifying statement of control rod work.

\* Missouri, Univ. of. Columbia. 81/03/03 lp 07865,212

BiO3160519 Forwards Amend 13 to License R-103. MILLER,J.R. Standardization & Special Projects Dranch. Bi/03/0 3pp. 07916.311.

--Bi03i60526 Amend 13 to License R-103, changing organizational str outlined in Figure 6.0 of Tech Spec 6.1 to reflect current organization. MILLER-J. R. Standardization & Special Projects Branch Bi/03 4pp. 07916-314

- O Inspection reports. IE Bulletins & correspondence
- 8103261997 For and 1E Insp Rept 50-186/81-01 on 810120-23 No noncompliance noted FISHER.WL Region 3. Chicago, Fuel Facility & Materials Safety Branch 81/02/23 2pp 08035 235
- --BiO326i107 IE (nsp Rept 50-186/8i-0] on 810120-23 No noncompliance note: Major areas inspected radiation protection program & raduaste mgt program including qualifications.eudits. training, instruments & equipment LOVENDALE,P C. Region 3. Chicago, Office of the Director FISHER. Wt. Region 3. Chicago, Fuel Facility & Materials Bafety Branch B1/02/17 9pp 08035 237
- S. Reportable occurrences. LERs & related correspondence
- 8103180552 RD. on 810213, while performing reactor startup, nuclear instrumentation channel 3 failed to respond positively to changes in reactor subcritical multiplication Caused by faulty cable installation Cables were properly connected MCMISEERIJC, BROODER, R. M. Missouri, Univ. of. Columbia 81/03/13 2pp 07953 231
- RIO3240510 RO. on 810223: isolation valve V946B failed to move to fully opened position following normal shutdown Caused by difficulty in rovement of valve actuator Valve rebuilt. Iubricated 5 reinstalled MCKIBPEN-J C Missouri. Univ of. Columbia 81/03/17 2pp 07982 355
- 8103240471 RO. on B10223 w/reactor shut down for maintisolation valve for containment tid; leat rate determination sys found in open position Cause not stated Valve line up conducted Pipe cap installed on open ended line inside containment. PKRIBEEN.J C. Missouri, Univ. of, Columbia 81/03/20 2pp 07990-165
- 8103300297 RO on 810223. O/reactor shutdown for scheduled raint. isolation valve for containment blidg lear rate determination sis found in open position Cause not stated Valve Lineup on containment lear rate sys conducted Pipe cap installed MCK188EN. J C Missouri, Univ of, Columbia 81/03/20. 2pp 08055-278

#### V Operator Examinations

- 8103170203 Forwards operator requalification program, per ARC 810305 ltr. ELLIGITA E. Montana, Univ of 81/03/11 1p 07939 217.
  - --81031702CB Operator requalification program \* Montana. Univ of 81/03/11 [9pp 07939 218
  - DOCKET 50-107 SPACE RADIATION RESEARCH REACTER

    O Inspection reports. IE Builetins & correspondence
  - 8102020039 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. EAGELKEN.R H Region 5, San Francisco. Défice of the Director. 81/02/09 1p. 07787 229.
  - B103230179 Forwards IE Insp Rept 50-187/B1-01 on B10225 No noncompliance noted Rept withheld (ref IOCFR2 790). NGNDERHAU3-L R Region 5, San Francisco, Bafeguards Branch, B1/03/11 2pp 07977:235
  - R. Periodic operating reports & related correspondence
  - B103300261 "Natural Environ Radicactivity Survey for Period of Sept 1979 Through Aug 1980 "AVANTA D. COZENS.C. WOODS.J. Northpop Research & Technical Center. B1/03/27. Spp. 08055.283
  - ODCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

    P. Operating license stage documents & correspondence
  - B103030100 Forwards revised NRC Region 4 organization chart effective B10227. SEYFRIT-K. V Region 4. Dallas. Office of the Director. 81/02/17 Zpp.

- 8103310552 Responds to questions re power fluctuations at TRIOA Mark II Fluctuations are generic to TRIOA reactors cooled by natural convection FAM.R E Kansas State Univ 81/03/26 2pp 08062 360
- Q. Inspection reports. [E Bullatins & correspondence
- 8:03200230 Forwards IE Circular 81-02. "Performance of NGC-Licensed Individuals Hhale on Duty " No written response required SEYFRII.K V Region 4. Dallas. Office of the Director 01/02/09 ip 07972 067
- DOCKET 30-192 UNIV GF TEXAS RESEARCH REACTOR

  8. Utility Preliminary Safety Analysis Report. amends
- B103030673 RBAR for Univ of TX TRIGA MARK 1. + Teras, Univ of B1/01/31 204pp 07800 145.
- B103030675 Chapter I to Univ of IX TRIOA PARK I RBAR, "Introduction Eurasty + Teyas, Univ of 81/01/31 5pp 07800 154.
- B1030306B1 Chapter 2 to Univ of TX TRIOA MARK I RSAR "Bite Description"
- 8103030584 Chapter 3 to Univ of TX TRICA MARK I RSAR, "Reactor."
   Teles. Univ of 81/01/31 85op. 07800:181
- 8103030691 Chapter 4 to Univ of TX TRIOA MARK I RBAR, "RCS" • Texas: Univ of 81/01/31 8pg 07800 266.
- B100030693 Chapter 5 to Univ of TX TRICA MARK I RBAR. "Reactor Room
   Texas, Univ of 81/01/31 24op 07800,274
- 8103030697 Chapter & to Univ of TX TRICA MARK 1 RGAR, "Instrumentat
- B103030700 Chapter 7 to Univ of TX TRIOA MARK 1 RBAR, "Radwastes & Radiation Protection."

   Teras, Univ of B1/01/31 Spc. 07800:313.
- \* Teras: Univ of 81/01/31 3pp. 07800:313.
- Analysis "

  # Texas- Univ uf. 81/01/31 27pp 07800.316

\* Texas: Univ of 81/01/31 15pp. 07800.298

- 8103333706 Chapter 9 to Univ of TX TRIOA MARK 1 R6AR, "Organization \* Teres. Univ of 81/01/31 4pp. 07800:343
- 1 Financial information
- B103240506 Forwards "Environ Impact Rept." & Annual Financial Rept. 1979.
  BAUER J. L. Teras, Univ. of. 81/03/11 1p 07981:260.
- --B1032405i1 Annual Financial Rept 1979.
   Texas, Univ. of. B1/03/11. 43pp. 07981:270.
- P Operating license stage documents & correspondence
- B103030143 Forwards revised NRC Region 4 organization chart.effecti B10227. SEYFRIT.K V. Region 4. Dallas. Office of the Director. 81/02/17
- 8103020368 Application for amend to License R-92 changing Tech Specinstallation of ejitered eshaust stack unit Unit will be maintained u/damper control shut during operation or until
- --B103020372 Revised Tech Spec 4.2.4 re pool water sys. e Texas Univ. of B1/02/24. 2pp. 07785:245.

revised Tech Spers are in effect.

BAUER, T. L. Texas, Univ. of 81/02/24, 1p. 07785; 244.

- Q Inspection reports. IE Bulletins & correspondence
- 8103200299 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required.

- R Periodic operating reports & related correspondence
- 9103240505 Forwards "Environ Impact Rept." & Annual Financial Rept 1979. BAUER.T L. Teras, Univ. of 81/03/11. lb 07981 260
- --B103240508 'Environ Impact Rept."

   Texas, Univ of. 81/03/11 9op 07981.261
- --8103240511 Annual Financial Rept 1979
   Texas, Univ. of 81/03/11, 43pp 07981,270
- DOCKET 30-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
- Bi03270667 Provides alternate route from Narragansett.RI to Aiken.SC. updating B00610 proposal Use of private grounds is not enticipated DiMCOLULA F. Rhode Island. State of 80/10/27 3pg. 08046-260
- DOCKET 50-201 HEST VALLEY REPROCESSING PLANT
- B103270752 Act receipt of B01007 ltr Encounter between resident & individual claiming to be guard found to be apparent hoax. Issue is considered closed.per resident request HAUGHNEY.C J. Advanced Fuel & Spent Fuel Licensing Branch B0/10/30. 1p. 08044 312
- 8103230930 Responds to 810218 ltr re-nuclear wastes Forwards description of waste burial grounds & BMI-X698 re-alternatives for decommissioning & future use of wastern NY NFB center. Wo encl. RQUBErL. C. Advanced Fuel & Spent Fuel Licensing Branch 81/03/13 2nn 07979:348
- P. Operating license stage documents & correspondence
- 8103260497 Notification of 801030 meeting w/vendor & NY State Energy R&D Authority in Bilver Spring.MD to discuss facility indemification is liability issues associated w/icplementation of work by Rockwell Hanford Operations HAUGHNEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch 80/10/27. 1p. 08041:028.
- 0103260905 Notification of 801210 meeting w/vendor in Bilver Spring.MD to discuss efforts to process available technical info needed to provide basis for future decontamination & decommissioning of facility.

  HAUGHNEY.C J. Advanced Fuel & Spent Fuel Licensing Branch.

  80/10/27. 2pp. 08041-029
- 81032501B3 Bummery of B01023 meeting w/DDE.Nuclear Fuel Bvcs & NV Btate Energy R&D Authority in Silver Spring.MD refacility indemnification & Ilability Issues associated w/ implementation of work by Rockwell Hanford Operations.
  HAUDHKEY.C.J. Advanced Fuel & Spent Fuel Licensing Branch.
  B0/10/29. 3pp. 07996-057.
- 8103260518 Burmary of 801022 meeting w/vendor & NY Btate Energy R&D Authority in Bilver Boring HD to discuss efforts to process technical data useful for decontamination & decommissioning of Pacility, Attendance list & data index encl.

  MAUDHNEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch.
  80/10/29, 15pp. 08041:057.
- B103270844 Forwards fifty-eight quarterly rept for Jul-Bept 1980 & corrected replacement pages for two prior repts. DUCKNORTH.J.P. Nuclear Euel Bervices. Inc. (subs. of Getty Dil Co.). 80/10/29. ip. 08043:315.
- --8103270849 Replacement page for 800718 rept, consisting of ltr forwarding fifty-seventh quarterly rept for Apr-June 1780. BUCKHORTH.J P. Nuclear Fuel Bervices, Inc. (subs. of Getty Dil Co.). 80/10/29, 1p. 08043-316.
- ---S103270853 Replacement page for 800428 rept.consisting of ltr forwarding fifty-seventh quarterly rept for Jan-Mer 1980. Rept for Jul-Bept 1980 encl. DUCKWORTH.J.P. Nuclear Fuel Borvices, Inc. (subs. of Getty Oil Co.). 80/10/29, 12pp. 08043;317.

- R Periodic operating reports & related correspondence
- B103300004 Forwards flow measurments & results for Oct 1980 DUCKMORTH.JP Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) B0/11/06 Aon
- B103120482 Forwards 'Environ Rept 29.Jul-Dec 1980 ' DUCKHORTH.J.P Nuclear Fuel Services. Inc (subs of Getty Oil Co ) 81/02/25 1a 07905 095
- --Bi03120485 'Environ Rept 29. Jul-Dec 1980 "
  WILCOX.D P Nuclear Fuel Services. Inc. (subs. of Oetty Oil Co.)
  81/02/29 26pp 07905-096
- 8103110460 Monthly rept for Feb 1781 re mat] discards & inventory discrepancy under License SYM-1648 BURN.P Nuclear Fuel Services. Inc (subs of Getty Dil Co ) 81/03/05 1p. 07882 158
- DUCKET 50-206 SAN ONOFRE NUCLEAR STATION. UNIT 1

  E NRC Sefety Evaluation Report (SER), supply & correspondence
- B103230891 Discusses OL hearing scheduling process SER technical input schedules for CY81 & CY82 enci DENION.H R Office of Nuclear Reactor Regulation, Director. B1/03/13 70e 07977 062
- F Security, medical, emergency & fire protection plans
- 8103200373 Forwards FR notice he extension of time for completion of fire protection mods from 800719 to 811117 Description of mods encl DENTON-H R. Office of Nuclear Reactor Regulation, Director 81/02/13 4pp. 07971 275
- --8103200387 Notice of extension of completion dates of fire protection mods from 800719 to 811117

  CASE.E 0 Office of Nuclear Reactor Regulation. Director 81/02/13 ip. 07971 279.
- 9103050336 Releases public version of emergency plan for facility FELTON.J.M. Division of Rules and Records 81/02/18 ip 07806-001
- --BI03050362 Forwards public version of emergency plan for facility. BABKIN,K.P. Bouthern California Edison Co. 81/01/29 ip 07806-001.
- --BI03030367 Public version of emergency plan for facility - Bouthern California Edition Co. \* San Diego Cas & Electric Co 81/01/31. 300pp 07806-001
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addlinfore safe shutdown capability for compliance w/801119 fire protection rule EISEMMUN. 0. 0 Division of Licensing. 81/02/20. iSpp.
- Bio33i033B Ltr to all licensees of operating plants & holders of CPs forwarding NURSG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. H/o encl EISENHUT, D. G. Division of Licensing. Bi/03/05 6pp.
- 8103110336 Forwards "Physical Security Plan. San Gnofre Nuclear Generating Station. Units 1.2 & 3. Mer. 1981." Plan withheld fref 10CFR2.790. BASKIN.K.P. Southern California Edison Co. 81/03/10. 3pp. 07872.317.
- 8103261066 Forwards emergency planning info for placement in LPDR W/o 8103050362. 800DER.J.L. Division of Rules and Records. 81/03/11. ip. 08040.269.
- 8103230336 Forwards refund on Class III fee submitted 810210 w/application for extension of completion detes for eight mods for fire protection sys.

  MILLER.W. O. License Fee Management Branch 81/03/16 ip. 07974:341.

9103240355 Provides info required by new fire protection regulations 10CFR90. 48 Installation of smoke detectors emergency lighting reactor coolant pump lube oil collection sys & provision of safe shukdown capability discussed BASKIN.X P Southern California Edison Co 81/03/17 App 07990 250

## H General correspondence

- 8103040200 Responds to FOIA request for H Denton 771010 reno 2 supporting documents Forwards documents listed in App A Rept entitled "Humboldt Ba, Power Plant Site Geology Investigation" is available in PDR. FELTON. J.M. Division of Rules and Records 81/02/24 2pp 02000 048
- BIO3120852 Responds to FOIA request for documents re Abalone Alliance. 770806 demonstration at San Onofre huclear plant & 780806 demonstration at Diablo Canyon nuclear plant Forwards EC Case 770203 it to Southern CA Edison Co. FELTON. J II Division of Rules and Records 81/03/10 ip 07904 342
- --Bi03i20860 Approves of interim response force measures implemented at Pacility, rending resolution of local law enforcement jurisdiction & related questions Revised response plan should be issued for NRC approval upon issue resolution CAEC.E G. Office of Nuclear Reactor Regulation. Director 77/09/23 [p.
- P Operating license stage documents & correspondence
- 8103270592 Requests approval of revised route for shipping fuel from San Clemente. CA to Morris. It. Route will utilize US interstate & CA freeway sys

  LADESICH J Southern California Edison Cp 80/10/28 2pp

  08044 319.
- 8103190732 Etrs to all licensees of operating plants applicants for DLs 2 holders of CPs re-control of heavy loads. Requests review per guidelines in NUREG-0612 Forwards NRC position relinterin actions & request for add info.

  EISENHUT. B.O. Division of Licensing 80/12/22 30pp
- 8101150319 Discusses followop study re degradation of internal appurtenences in LWR piping during rormal plant operation & patential effects when degraded appurtenances are subj to accident loads. Recomends show traview of recurrent problems BROWNE. J Director's Office 80/12/24 4pp.
- B103020712 Surmary of 801030 meeting w/util in Bethesda: HD re loss of saltwater cooling event at facility & effects of desictant in compressed air sys W/list of attondees
  MONICKE-8 J Operating Reactors Branch 5 81/01/06. 7pm.
- BIGG190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737.

  EISENHUT. D G Division of Licensing 81/01/19 app.
- BiO3120014 Ltr to all licensees of operating plants, CP holders & OL applicants, except Indian Point R & 3, Zion 1 & 2 & IMI-1, forwarding inadvertently onitted pages from NRC 801222 request for add info re control of heavy loads RISENHUT, D Q Division of Licensing, 81/02/03. 6pp.
- BiD3030129 Forwards Amend 52 to Provisional Litense DPR-13, safety evaluation & notice of issuance & availability.
  CRUTCHFIELD. D Departing Reactors Branch 5 81/02/06. 3pp. 07805-336.
- --Bi03030145 Amend 52 to Provisional License DPR-13.changing Tech Space to permit use of newly constructed electrical switchyard CRUTCHFIELD.D. Operating Reactors Branch 3, 81/02/06, 3pp 07805-338
- --Bi03030161 Sefety evaluation supporting Amend 52 to Provisional License DPR-13.
   Operating Reactors Branch 5. 81/02/06 4pp. 07605-343.
- --Bi03030170 Notice of issuance & availability of Amend 92 to Provisional License DPR-13. CRUTCHFIELD.D Operating Reactors Branch 5. Bi/02/06. 2pp. 07805:347

- Bi03300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design forwards request for addl info. List of actions requested of licensees w/o seismically qualified sys & results of MRC unlatowns.
  EISEINVILO O Division of Licensing BI/02/10 13pp.
- 8103100183 Requests clarification of NRC 801015 ltr requiring use of accountability controls for steam generator channel heads then expandable soals & cover plates in RCS piping nozzles are not in place.

  144Y:ES.J.O. Southern California Edison Co. 81/02/13 2pp.
  07893 189
- B103060344 Forwards "Environ Qualification of Bafety-Related Electri Equipment," partial review Written response required LAIMAB. 0 C Assistant Director for Safety Assessment. 81/02/17 3aa 07876 322
- --Bl03360355 'Environ Qualification of Befety-Related Electrical Equipment,' partial review • Office of Nuclear Reactor Regulation, Director. 81/02/17. 1806. 07836-325
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A 1 2 re upgrade of erangency support facilities Requests confirmation within 45 days that implementation dates will be met EIBENHUT. D 0 Division of Licensing 81/02/18 12pp.
- 8103030992 Notification of contract execution Mod 1 to "Followon Simulation of Earthquake Ground Motions for Ban Onofre Nuclear Generating Station LITILE.M Administrative Contracts Branch FIN 8-6898-0 81/02/ 10 07828 241
- --8103051001 Mod 1.changing period of performance & obligating addition "Follown Simulation of Earthquake Ground Motions for San Unoffer Nuclear Generating Station"

  ANT. K. Hassachusetts Institute of Technology. PERLMAN, J. Administrative Contracts Branch. FIN B-6898-0 81/02/20 1p. 07878 242
- B103250024 Ltr to all power reactor licensees & license applicants of MUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller.

  EISENHUT-D 0 Division of Licensing. 81/02/20. 8pp.
- 8103120188 Notification of 810225 meeting w/util in Bethesda,MD to discuss status of facility steam generator repairs including technical details & results of generator sleeving.
  NCHCMI.6 J Operating Reactors Branch 5 81/02/23. 2pp. 07900:284.
- 8103100345 Ichediate action ltr confirming modified controls to maintain cleanliness of RCS Juring steam generator repair. Uritten procedures will be revised to include accountability controls for reactor primery tooling sys.
  ENOBLAGN.R.H. Region 5. San Francisco, Office of the Director. B1/02/25. 2pp. 07865:190.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUT. D O Division of Licensing 81/02/23. 3pp.
- B103190033 Notification of contract execution, Mod 5 to "Bimulation of Earthqueke Oround Motions for Ban Onofre Nuclear Generating Station, Final Rept." Contractor: RB Herrann.

  LETTLE-M Administrative Contracts Branch. FIN B-6531. B1/02/26 ip. 07964.163.
- --B10319C042 Mod 5, deobligating balance & closing out contract, to "Simulation of Earthaquake Ground Motions for Ban Onofre Nuclear Generating Station, Final Rept "HERRIANN, R. B. Ferrmann, R. E. PERLMAN, J. Administrative Contract Branch. FIN 8-6531 81/02/26 1p. 07964: 164.
- 8103060636 Confirms understanding reached at 810225 meeting reproduction installation of leek limiting sleeves in steam generators. Submittal of rept re leak limiting sleeves will be delayed until 810336.

  BASKIN.K P. Southern California Edison Co. 81/03/02. 1p. 07835-355.
- BiO3230501 Forwards evaluations for BEP Topics VIII-2. "Diesel Generators" & VIII-4. "Electrical Penetrations of Reactor Containment." Requests info re differences between as-built facility & licensing basis within 30 days. CRUTCHFIELD.D. Operating Reactors Branch 5. 81/03/02. 23pp. 07977: 130

- BiO3120304 Forwards request for addl info re SEP Topic VI-7 8.
  engineered safet; feature suitchover Description of davice
  quilification & installation as Class IE equipment requested
  within 30 Jays
  CRUICHFIELD.D. Operating Reactors Branch 5 81/03/04 3pp
  07901-296
- BiO3130486 Forwards application for withholding proprietary info from public disclosure re encl proprietary & nonproprietary versions of NS-MF8E-81-054 Revision 2. "Technical Evaluation Ropt for Hybrid Jaint "Rept not enc!
  ANDERSON, T. M. Westinghouse Electric Corp. 81/03/04 2pp. 07907-013
- --BIO3130490 Requests withholding of proprietery info from NB-MFRE-Bi-O5.
  "Technical Evaluation Rept for Hybrid Joint." (ref
  10CFRR 790) Affidevit enci
  MIESEMANN.R A Westinghouse Electric Corp BI/O3/04 7pp
- 8100090398 Forwards proprietary & nonproprietary versions of Mestinghouse rept. NS-MFSC-BI-054. "Technical Evaluation Rept for Hybrid Bleeve "Affidavit also encl Proprietary version withheld (ref ICCFR2 790). BASKIN.K.P. Southern California Edison Co. 81/03/05 9pp 07892 069
- --Bi03090403 Nonproprietary version of "Technical Evaluation Rept for Hybrid Bleeve "

  \* Westinghouse Electric Corp. NS-MF8E-Bi-054 Bi/03/31. 26pp 07832.074
- Bi03110550 Responds to 810217 "Partial Review Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulations " 801031 submittal provides adequate justification for continued operation. Requests info ro NRC basis for establishing deficiencies BASKIN.K.P. Southern California Edison Co 81/03/05 2pp 07877:352.
- BiO311072B Forwards evaluation of BEP Topic V-5 re reactor coolant pressure boundary leakage detection. Requests info redifferences between as-built facility & licensing basis within 30 days.

  CRUTCHFIELD.D. Operating Reactors Branch 5 81/03/10 5pp.
- 8103310804 Ltr to all licensess of operating plants, applicants for OLs & holders of CPs forwarding BECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT, D O Division of Licensing. 81/03/10 App.
- 8103200719 Advises that SEP Topics VI-7.C (ECCB single failure criterion & requirements for locking out power to valves) & VI-7 C.2 (failure mode analysis) are complete except three mode to be implemented Amend 25 to DPR-13 is duplicative. CRUICHFIELD.D. Operating Reactore Branch 5. 81/03/13. 2pp. 07947-249
- 8103190916 Notifies that final decision on Unit i seismic input ground motion delayed due to respure limitation Util should continue seismic reanalysis using R/3g Housner ground response spectrum Response requested within 20 days. CRUTCHFIELD.B. Operating Reactors Branch 9. 81/03/15. 2pp 07948:1546
- 8103200525 Forwards request for add1 info re BEP Topics VII-1.A.VII-2 & VII-3.Requests response within 30 days.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 81/03/16. 6pp 07971-303
- 8103230519 Advises that SEP Topic III-4.0 re turbine missiles has been made generic, due to multi-plent cracking problem at plants u/Westinghouse low pressure turbines. CRUICHFIELD. D. Operating Reactors Branch 5. 81/03/16. 4pp. 07979:342.
- 8103240399 Forwards listing containing brief description of design changes completed during 1980 per 10CFR50.596 & rapt on challenges to relief & safety valves per NUREO-0578. HAYNEG J. O. Southern California Edison Co. 81/03/17. 22pp. 07987:209.
- 810324033B Forwards comments on NRC safety evaluation of SEP Topic II-2. A. "Severe Weather Phenomena." Tornado windspeed for facility should be max of 172 miles per h.not 260 miles per h.as stated in safety evaluation.

  MODDY.W.C. Bouthern California Edison Co. 81/03/18. 3pp. 07981:358.

- 8103270690 Advises that post-accident sampling sys.described in licensee 800707 ltr.will not include capability to perform chloride analysis, por NUREO-0737 & NUREO-0578 Chloride analyses using dilute samples are inaccurate 8ASXIII.K P Southern California Edison Co 81/03/18 2pp 08046 317.
- B103240310 Forwards Revision 1 to BE-SP-88(80) (nonproprietary vert & SE-5P-40(80) (proprietary vertion). "Steam Generator Repair Rept ' Proprietary vertion) withheld (ref 100FR2 790) Affilavit 5 application for withholding encl ANDERSON. T M. Westinghouse Electric Corp. B1/03/20 | 11pp. 07989 743
- --8103240314 Nonproprietary version of Revision 1 to "Steam General Repair Rept." AXIN.R.C. ROSENTHAL-W.P., DEROBA.P.P. Westinghouse Electric C 8E-5P-98(80) R1 B1/03/31 380pp 0798R 001
- B103250180 Notification of B10325 meeting w/util & Westinghouse in Bethesda.MD to present review of info previously used to define sleeving boundry re-repair of individual tubes within boundary NONICKI.S J. Operating Reactors Branch 5. B1/03/23. 2pp 07996-056
- B103310489 Advises that info re SEP Topic XV-16. 'Radiological Consequences of Failbre of Small Lines Carrying Primary Coolant Outside Conteinment.' uill be submitted by B10410. H30DV: N C Bouthern California Edison Co 81/03/25 ip 08099 213
- 8103310495 Provides status of investigation of anchorage of safetyrelated electrical equipment in response to NRC 800101 & 0720 requests Mode associated w/items identified in Encl 1 scheduled for completion by 810501. BASKINIK P Southern California Edison Co. 81/03/25 8pp 000097 209
- Q Inspection reports: IE Bulletins & correspondence
- B103240101 Responds to NRC B01024 ltr re violations noted in IE In: Rept 30-206/B0-28 Corrective actions station procedure B01-11I-1 14 to be revised to increase chloride limit during shutdown when reactor sys must be append for outages PAPAN.L T Bouthern Celifornia Edison Co. B0/11/13 3pp 07909-236.
- --Bi03240106 Supple 801113 response to NRC 801024 itr re violation: in IE Insp Rept 50-206/80-28 Corrective actions chloride limit administrative procedures will be revised to reflect Westinghouse chemistry 818 PAPAY.L.T. Bauthern California Edison Co. BI/02/18 3pp 07989-239
- --B103240114 Act receipt of B01113 & B10218 ltrs informing NRC of taten to correct violations noted in IE Insp Rept 50-206/80-28.

  CREWB.J. L. Region 5. Ban Francisco. Reactor Operations Nuclear Bupport Branch B1/03/12 ip 07789:242
- B103100454 Forwards IE Insp Rept 90-206/80-33 on B01215-18 No noncompliance noted 800K.H.E. Region 5, San Francisco, Fuel Facility & Materials Sa-Branch. B1/01/19. 2pp. 07862:261
- --9103100464 IE Insp Rept 50-206/80-33 on 801215-18.No noncompliant noted Major areas inspected radiation protection program associated wisteam generator repair activity & IE Bulletin 80-10 response.
  Cit.IB.M., VUMAB, C.P., WENBLANSKI.F.A. Region 5, San Francisco Office of the Director. 81/01/19 8pp. 07862-263.
- 8103020051 Forwards 1E Circular 81-02. "Performance of NRG-License: Individuals While on Duty " No written response required. ENGELMEN.R.H. Region 9. Sen Francisco, Office of the Director. 81/02/09 1p. 07787-251.
- B103250037 Forwards IE Insp Rept 80-206/81-03 on B10112-16.No noncompliance noted.

  CREWS.J.L. Region 5. San Francisco, Reactor Operations Nuclear Bupport Branch. B1/02/11 2pp. 07998:274.
- --Bi03250040 IE Insp Rept 50-206/81-03 on Bi0112-16 No noncomplian noted Major areas inspected: implementation of TMI task action items & independent insp effort.

  CHAFFEE.A. Region 5. San Francisco. Office of the Director FAULKENGERRY, B. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 81/02/11. 5pp. 07798:R76.

- BIO3160322 Forwards JE Info Notice BI-93 "Checklist for Licensee Making Notifications of Bignificant Events in Accordance W/IOCFR90 72 " No response required ENGELKEM H Region 5, Ban Francisco. Office of the Director BI/02/12 1; 07922 692
- B103050124 Act receipt of B10121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/80-32 CREHB. J L. Region 5. Ban Francisco. Reactor Operations Nuclear Support Branch. B1/02/13 ip 07827-303
- --B103050129 Forwards IE Insp Rept 50-206/80-32 on B01103-26 & notice of violation Notice of violation withheld (ref 10CFR2 790) CREWS.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch B1/01/09 2pp 07827 304
- --8103050135 [E insp Rept 50-206/80-32 on 801103-26 Moncompliance noted failure to implement physical security plan requirement. MILLER. Region 5. San Francisco, Office of the Director. FAULKENGERRY. B. Region 5. San Francisco, Reactor Operations Notlear Support Branch. 80/12/30. 599 07837:306
- 8103;80586 Forwards [E. Inep. Rept. 50-206/81-02 on 810;19-23 No noncompliance noted.

  81003;18 E. Region 5: San Francisco: Fuel Facility & Materials Bafety Stanch 81/02/\$3 2pp. 07933 03t
- --8103180591 IE Insp Rept 50-206/81-02 on 810119-23 No noncompliance noted Major areas inspected response to 1E Circujars 80-03, 80-14 & 80-18, review of LER 80-37 & following of previous insp findings YUMAS-9 P. NENBLANSKI.F.A. Region 3, San Francisco. Effice of the Director. 830K, H.E. Region 5, San Francisco. Fuel Facility & Materials Safety Brench 81/02/13 100p 07933-033
- 8103231107 Responds to IE Bulletin 60-10. "Contamination of Nonradioactive Sys & Resulting Potential for Uncontiored. Uncontrolled Release of Radioactivity to Environ." Gily waste & yard drain sumps are addl release paths to environ. HAYNES. J. 7. Southern California Edison Co. 81/02/17. 2pp 07977-032.
- 8103250136 Forwards IF Maste Packaging Insp Rept 19000046/80-98.
  Advises that breach of package integrity associated whratioactive matle shipment originating at facility was found No response required.
  BDDK-H E Region 5: Ban Francisco, Fuel Facility & Materials Safety Branch 81/02/24 2pp
- --8103290144 IE Waste Packaging Insp Rept 15000046/80-98 on 801215
  Noncompliance noted drum found to have loose lock ring
  Region 5. State of MA & DOT are to take enforcement actions,
  ZURAKCHSKI,P. R. Region 5. San Francisco. Office of the Director,
  TMOMAS.R D. 8004.4 E. Region 5. San Francisco Fuel Facility &
  Materials Safety Branch 81/01/20, 5pp
- 8103240719 Forwards 18 Insp Rept 50-206/80-04 on 801229-810130 No noncompliance hoted. CREMS.J.L. Region 9. San Francisco, Reactor Operations Nuclear Support Branch. B1/02/26. 2pp 07983.261
- ----B103240728 IE Insp Rept 50-R06/B1-04 on 801229-810130.No noncompliance noted Hajor areas inspected: follows on systematic appraisal of licensee performence & allegation by contractor exployee. MILLER, L. Region 5. San Francisco, Office of the Director. ILLERIGA, B. Region 5. San Francisco, Office of the Director. ILLERIGA, B. Region 5. San Francisco, Reactor Operations Nuclear Support Branch, 81/02/25. Bpp. 07983:263.
- B103160659 Forwards IE Info Notice B1-04. "Crecking in Nein Steam Lines: "No response required. ENGELKEN, R.H. Region 5. San Francisco. Office of the Director. B1/02/27. 1p 07914:237.
- 8103260088 Responds to IE Bulletin B1-01. 'Burveillance of Mechanical Snubbers.' No snubbers meg by Intl Nuclear Safeguards Corpused in safety-related sys.All mechanical snubbers will be inspected prior to return to power from outage.

  HAYNES-J.O. Southern California Edison Co. 81/02/27 lp. 06042:132.
- 8103170002 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required. ENGELKEN.R. H. Region 3, San Francisco, Office of the Director. 81/03/02, 1p. 07939: 100.
- 8103180317 Ack receipt of 810212 ltr informing NRC of steps taken to correct violations noted in EC Imap Rept 30-206/60-34. CREMS.J.L. Region 5. San Francisco, Reactor Operations Nuclear Bupport Branch. 81/03/02. ip. 07944:239.

- --B103180331 Responds to NRC 810127 ltr re violations noted in IE:
  Rept 30-206/B0-34 Corrective actions approved denied for
  procedure to perforate steam generator tubes Enc1 2
  withheld (ref 10CFR2 790)
  PAPAYL T Southern California Edison Co 81/02/12 3pp
  07944 239
- --8103180344 Forwards 16 Insp Rept 50~206/80-34 on 801201-24 & not violation CREWS.J L. Region 5. San Francisco. Reactor Operations Nuclear Bupport Branch 81/01/27 2pp 07944 243
- --BIO3180331 Notice of violation from ins; on 801201-24
  FAULKENDERRY.B. Rejion 5. Ban Francisco. Office of the Directo
  81/01/22. lpp 0794:245
- ---Bi03180361 IE insp Rept 50-206/80-34 on B01201-24. Noncompliance of failure to implement physical security plan requirement & insufficent review of safety-related procedure MILLER. L., PAYE. R. Region S. San Francisco. Office of the Director. FAULXENBERRY, B. Region 5, Ban Francisco. Reactor Operations Nuclear Support Branch. 81/01/22 9pp. 07944.246
- Bi03260078 Responds to IE Bulletin 80-24. "Prevention of Damage Dus Mater Leakage Inside Containment." Addl time needed to compile, collate, evaluate & review into Response will be delayed until 810320.

  144YNES.J.O. Gouthern California Edison Co. 81/03/03. ip. 08042 121.
- 8103160882 Forwards revised [E Bulletin Bi-Ol, "Surveillance of Mechanical Boubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ENDELKEN, R H Region 5, San Francisco, Office of the Director 81/03/04 ip. 07915-021
- Bio3110659 Responds to IE Bulletin BO-04. "Analysis of PHR Main Ste Line Break U/Continued Feedwater Addition." Auxiliary Feedwater sys automatic initiation will occur on low steam generator level U/setpoint at 5% of marrow range instrument BASKIN.K P Southern California Edison Co Bi/03/06. 78pp. 07ER3 24B.
- B103230086 Ack receipt of B10203 ltr responding to B10112 notice of violation
  NORDERHAUD, L. R. Region 5, Ban Francisco, Bafaguarde Branch.
  B1/03/10 ip. 07978-304.
- 8103200243 Forwards IE Info Notice B1-06. "Failure of ITE Model K-4 Circuit Breaker." No response required. ENUELKEN.R H. Region 3. Ben Francisco. Office of the Director. B1/03/11 1p. 07968:331.
- 8103230088 Forwards IE Insp Rept 50-204/81-07 on 810223-25. No noncompliance noted Rept withheld (ref 100F82,790). MGROERHAUG-L R Region 5. San Francisco. Safeguerds Branch. 81/00/12 2pp. 07980-308.
- B103200072 Forwards IE Info Notice B1-05. "Degraded DC Bys at Pallsedes" No response required.
  ENGELKEN,R H Region 5, Sen Francisco. Office of the Director.
  B1/03/13. ID. 07970.264
- 8103260461 Forwards IE Insp Repts 90~206/81~03 & 90~301/81~03 on 810210~13 & notice of violation. Notice of viplation withheld (ref 10CFR2 770)
  NORELIUS.C.E. Region 3, Chicago, Office of the Birector. 81/03/19 08040 332.
- ~-8103260474 [E Insp Repts 90-206/81-03 & 90-301/81-03 on B10210-10 Details withheld (ref 100FR2, 790), GREEO, J. R. Region 3, Chicago: Bafeguards Branch, MADEDA, T. J. Region 3, Chicago: Office of the Director, B1/03/10, Lp. 08040, 034.
- 8 Reportable occurrences, LERs & related correspondence
- 9103100528 Provides status rept on corrective actions taken to ensu continued operability of sefety-related air-using equipment. Blowdom of header performed to remove dessicant Preventive raint grogram is under development. [WYNES.]. O. Southern California Edison Ca. 81/02/23. App. 07865:242.
- BiO3100406 PNB-V-Bi-003 on BiO303, switchboard operator received bow threat from unidentified caller. Bearch of facility revealed no bomb onsite. Info assessment team has been notified. BCHMAN.C., MORTENSEN.W. Region 5. Ben Francisco. Office of the Director. Bi/03/04. Ip. 07865: 206.

8103100452 PNS-V-81-004 on 810305. Los Angeles Federal Info Ctr relayed both threat received by telephone Search was conducted w/ negative results SCHWAN. C. SCHUSTER M Region 5. San Francisco. Office of the Director 81/03/04 in 0.7985 067

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

B103050335 Advises that 790820 guard training & qualification plan requires minor revisions & addl info Revised plan should be submitted within 30 days CRUTCHFIELD. O Operating Reactors Branch 9 81/01/27 4pp 07832 127

B100060348 Forwards Suppl 2 to 7B1003 safety evaluation supporting firs protection sys.
CRUTCHFIELD.D Operating Reactors Branch 5 B1/02/06 2pp 07836 318

--B103060398 Suppl 2 to safety evaluation supporting fire protection sys • Operating Reactors Branch S B1/02/06 2pp. 07836 320

8103180264 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance u/B01119 fire protection rule EISENHUT.D Q Division of Licensing 81/02/20 13pp

8103100094 Requests that encl emergency planning into be made publicly available. W/o encl.

SOUDER, J. L. pivision of Rules and Records 81/02/27. 1p 07853 174

8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/o encl. EISENHUT.D 9 Division of Licensing. 81/03/05 6pp

8103250391 Requests exemptions to App R.fire protection requirements. Disputes NRC conclusion that no addit costs will be incurred through compliance. Bubmist dedicated shutdown sys description & analysis of implementation costs.

CDUNGIL.H. O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/03/19 29pp. 08022.102

8103300340 Requests exemption from certain requirements of 10CFR50 App R & 10CFR50.48 re fire protection program. Justification discusses BER open items. emergency lighting & evaluation of alternate & dedicated shutdown eys.

COUNSIL-W 0. Connecticut Yankee Atomic Power Co. COUNSIL-W 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).

B1/03/19. 29pp. 08055-155

# J Insurance & indemnity information

8103130426 Forwards Endorsement 7 to NELIA Binder EB-11. CONNELL T. J. Northeast Utilities. 81/03/04. 2pp. 07908 222

8103120431 Forwards Endorsement 67 to NELIA Policy NF-151, IFFLAND.R.R. Northeast Utilities. 81703706. 2pp. 07901:222.

BiO3310498 Forwards Endorsement 8 to NELIA Binder ED-11 & Endorsement 68 to NELIA Policy NF-151. SINIBILJ M. Harsh & McLennan.inc . M & M Nuclear Consultants.inc. DIV. Bi/03/26 4pp. 08078:339.

# P. Operating license stage documents & correspondence

8103060300 Responds to 801121 ltr re analysis of & mod to supports for safety-related electrical equipment. SEP Topic III-11.
Proposed 810131 date for mod completion is acceptable.
CRUTCHFIELD.D. Operating Reactors Branch 5. 80/12/30. 2pp.
07836-336

8103040217 Forwards request for additinfo & clarification re BEP Topic VIII-1.degraded grid & adequacy at station electric distribution say voltages.
CRUTCHFIELD.D. Operating Reactors Branch 5. 81/01/13. 4pp. 07812:284.

8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown, replacement parts & NUREG-0737.
EISENHUT.D.Q. Division of Licensing. 81/01/19. opp.

8103090063 Responds to 791019 ltm re inadvertent safety imject during surveillance testing Response adequately addresses concerns MRC considers matter resolved CRUTCHFIELD.O. Operating Reactors Branch 5 81/01/29 3pp 07852

B103120014 Ltr to all licensees of operating plants.CP holders applicants.except Indian Point 2 & 3.Zion 1 & 2 & THI-1, forwarding inadvertently omitted pages from NRC 801222 request for addlinfore control of heavy loads. EISEKHUT.D & Division of Licensing B1/02/03 App

8103300160 Ltr to all operating PWR licensees requesting info autiliary feedwater sys seignic design forwards request for add info. list of actions requested of licensees who seismically qualified sys & results of NRC walkdowns EIBENHUT.D Q Division of Licensing. 81/02/10 13pp

BIO3160465 Forwards preliminary results of review of environ qualification of safety-related electrical equipment Util must respond of unitten statement that facility can be safely operated LAIMAS.O.C. Assistant Director for Bafety Assessment BI/O 22pp 07916-278

8103160669 Ltr to all operating plants & CP holders forwarding clarification of TM1 Action Plan Item III A 1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.D 0 Division of Licensing 81/02/18. 12pp

8103290024 Lir to all power reactor licensees & license applic MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENMUT.D O Division of Licensing 81/02/20 8pp

B103100565 Forwards proprietary & nonproprietary versions of "Pressure Turbine Disc Info " Util will continue w/plans to inspect two low pressure turbines during 1981 refueling outage Proprietary version withheld (ref 100582 790) COUNSILN 0 Connecticut Yankee Atamic Power Co B1/02/25 07867-299.

--Bi03100569 Requests that util response to NRC B00225 request re low pressure turbine disk Integrity be withheld (ref 10CFR2.790).
WILLIAMSON, R Westinghouse Electric Carp 80/03/14 7pp 07B67:301

--8103100574 Nonproprietary version of "Low Pressure Turbine D \* Westinghouse Electric Corp. B0/09/22 24pp

8103230030 Ltr to all licensees of operating nuclear power platapplicants for DLs (except Bt Lucie, Units 1 & 2) Requests util review to determine capebility to mitigate station blackout event & promptly implement emergency procedures. EISENHUT, D G Division of Licensing. 81/02/25 Spp.

B103100776 Notification of 810310 meeting w/util in Bethesda MI discuss future LOCA modeling of facility using Relap V code. CARUSO.R Operating Reactors Branch 5 81/02/26. 2pp. 070

8103230813 Generic Ltr 81-06 to all CP holders & OL applicants 10CFR50. 71(a). "Periodic Updating of FBARs." effective 800722 Info re FBAR legal status, format & content encl EISENHUT.0 0 Division of Licensing. 81/02/26

8103240977 Forwards Amend 37 to License DPR-61, safety evaluate notice of issuance & availability. CRUYCHFIELD, D. Operating Reactors Branch 5. \$1/02/26. 3pp 07986.050

--Bi03240582 Amend 37 to License DPR-61 replacing current inse & valve testing Tech Specs w/theorvice insp & testing program which meets requirements per 10CFR50. 95a(g) Aiso revises test requirements for certain ECCS valves CRUTCHFIELD. D. Operating Reactors Branch 5. 01/02/26 i 07986.053.

--Bi03240585 Bafety evaluation supporting Amend 37 to License \* Office of Nuclear Reactor Regulation. Director. 81/02/ 81pp. 0798-066.

--Bi03240605 "Primary Coolant Bys Pressure Isolation Valves."
evaluation rept.
NDELL.P N . STILUELL.T.C. Franklin Institute/Franklin Res
Canter. IRC-03-79-118 80/10/24. Spp 07986-118.

- DPR-46 CRUTCHFIELD, D. Operating Reactors Branch S. 81/02/26 3pp 07986 126
- 8103030886 Responds to 801118 request for containment sump info 199030866 Hesponds to Bullis request for consuments of the forwards drawing showing containment such design features & dismonsions & incation to reactor primary sys Sub-its list of thermal intulation used in containment.

  COUNSIL.W.O Connecticut Yankes Atomic Power Co 81/02/27 5pp 07795 154.
- 8103060902 Forwards SEP redirection lists emending util 810204 connitment re SEP tepics categorized as candidates for congletion Topics have been subdivided to recognize two congletion dates, 810430 & 810630. completion dates, 810430 & 810530. CCUMBILLN G Northeast Nuclear Energy Co (subs. of Northeast Utilities) CDUNSIL.N O. Connecticut Yankee Atomic Power Co 81/02/27 L8pp 07837 201
- BIO3090284 Informs that Tech Specs for safety-grade automatic auxiliary faecuater sys will be submitted by BIO415 Original deadline had been extended from BIO215 to BIO227 CDU/SIGNLW 0 Connecticut Yankee Atomic Power Co. 81/02/27. 2pp 07846 221
- B103090414 Forwards info re containment sump & insulation utilized within containment Harked-up drawings & aparture cards enci.

  CDURBILLE G. Connecticut Yankee Atomic Power Co. 81/02/27. Spp. 81/02/27. 5pp 07844 201
- Biogo70528 Provides overall finding in response to NGC requirement for environ qualification of safety-related electrical equipment Concerns expressed in NGC Bio213 ltr do not alter outil determination that facilities can be operated safely CQU'BlivN O Connecticut Yankee Atomic Power Co COUNSIL.N 9. Northeast Nuclear Energy Co (subs of Northeast Utilities) Bi/O2/27 7pp 07844.274
- 8103120073 Forwards request for addl info prepared as part of evaluation of engineered sefety feature suitchover from injection to recirculation modes at facility. Response within 30 days requested CRUICHFIELD, D. Operating Reactors Branch 5 91/02/27 3pp 07900 110
- 8103160227 Responds to util 810204 ltm re-containment pressure during LOCA at facility Util wost submit reanalysis to confirm that existing Tech Spec value will not result in exceeding design pressure or propose change to Tech Specs CRUICHFIELD. D. Operating Reactors Branch S. 81/02/27 3pp 07918 349
- BIO3260557 Discusses costs for implementation of THI action plan requirements NRC estimates of required injustry resources have been consistently low Companison of NRC estimate w/ actual costs encl COUNBIL:N G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL:N G. Connecticut Yankee Atomic Power Co. B1/03/02 App. C8040:172
- 8103120339 Forwards ECCS outage rept for facilities for 1980-in response to NURES-0737-item II K 3.17 No sus or Tech Spec
- BiO3190603 Bubmits add1 info re SEP Topic VIII-1. 'Degraded Grid Voltage." in response to NRC 810113 request info will enable NRC to complete review of BEP topic. Util has addified proposal to more directly comply w//RC position COU/891L.19 Q. Connecticut Yankee Atonic Power Co. CCU/891L.W O. Northeast Utilities 81/03/09 App 07996:051.
- 8103120300 Forwards SEP Topic V-5 evaluation to RCPB lookage detection Requests response within 30 days if as-built facility differs from licensing basis assumed in topic assessment Evaluation will be basic input to safety assessment. CRUTCHFIELD.D. Operating Reactors Branch 9. 81/03/10 Spp 07906: 327
- 0100180812 Forwards Amend 38 to License DPR-61 & notice of issuance & availability. CRUTCHFIELD.D. Operating Reactors Branch 5. 81/03/10 3pp 07753: 176
- --8103180821 Amend 38 to License DPR-61 revising Tech Specs by deleting Section 4.2 requirements for shad nonitoring program. CRUTCHFIELD 0 Operating Reactors Branch 5 BL/03/10 5pp 07953: 179.

CRUTCHF1ELD.D Operating Reactors Branch 5 81/03/10

07957 1R4

- 8103310804 Ltr to all licensees of operating plants applicant to holders of CPs forwarding SECY-81-119 re info mecessary to establish environ qualification of safety-related electrics
- BIO32005CB Advises that SEP Topics VI-7 C (ECCS single failur criterion % requirements for locking out power to valves) & VI-7.C 2 (failure mode analysis) are complete.except for integrated assessment Amend 15 to DPR-61 is duplicative CRUTCHFIELD.D Operating Reactors Branch 5 BI/03/13 26
- BIORDROAD Advises that SEP Topic III-4 8 re turbine missiles togguour Agrises that SEP lopic list4 8 me turbine missiles made generic, due to multi-plant cracking problem at plants w/Westinghouse low pressure turbines CRUTCHFIELD, D Decrating Reactors Branch 9 81/03/16. 4
- g inspection reports. IE Oulletins & correspondence
- 8103050261 Forwards 1E Imap Rept 50-213/80-21 on 801006-1107 03050251 Forearty is they neve to 2.50 to 1.00 montempliance noted BRUNNER, E. J. Region I. Philadelphia, Reactor Operations No Support Branch 81/01/09, 2pp 07829 295
- --8103050271 IE insp Rept 50-213/80-21 on 801006-1107 No noncompted Major areas inspected plant operations licensee act on previous insp findings & review of periodic & special repts
  SMITH.T II Region 1. Philadelphia, Office of the Directo
  KEIMIO.R.R. Region 1. Philadelphia, Reactor Operations f
  Support Branch. 81/01/08 12pp 07823 257
- 8103190662 Act receipt of 810130 ltr informing NRC of steps of correct violations noted in 1E Insp Rept 50-213/80-11.
  88UNNER.E. J. Region i. Philadelphia, Reactor Operations No Support Branch 81/02/09. ip. 07964 098
- --8103190664 Responds to NRC 801231 ltr re violations noted Rept 50-213/80-11 Corrective actions vol control lank sampling values & charging pump sampling values tip wire locked Procedure revised. COUNSIL, W.G. Connecticut Yankee Atomic Power Co. 81/01. 07984 059
- --8103190666 Forwards 1E lnsp Rept 50-213/80-11 on 800803-22 notice of violation BRUNNER,E J Region 1, Philadelphia, Reactor Operations Support Franch. BO/12/31 2pp. 07964:061
- --8103190670 Natice of violation from insp on 800803-22 & 09
  Region 1, Philadelphia, Office of the Director. 80/13 07964 063
- --8103190672 1E Insp Rept 50-213/80-11 on 800803-22 & 0910-20 Noncompliance noted Tech Specs noble gas release limit exceeded. excesses. SMITH T K Region 1, Philadelphia, Office of the Direct KEIMIG.R R. Region 1, Philadelphia, Reactor Operations I Support Branch 80/12/15 7pp. 07964.064
- 8103040207 Forwards IE Info Notice 81-03. "Checklist for Lic Making Notifications of Bignificant Events In Accordance W/10CFR30. 72 "No written response required.
  GRIER.B H. Region I. Philadelphia, Office of the Director.
  B1/02/12. 1p 07B13:149
- 8103200576 Ack receipt of 810123 ltr informing NRC of steps carrect violations noted in IE Insp Rept 50-213/80-24. BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations N Support Branch. 81/02/12 1p 07967-047.
- --BI03200578 Responds to NRC 801223 ltr re violations noted Rept 50-213/B0-24 Corrective actions correct algebraic or point correction made to reactivity worth of Control Rod COUNSIL 4 0. FEE.W F. Connecticut Yankee Atomic Power 6 81/01/23. Rpp 07967-048.
- --8103200579 Forwards IC Insp Rept 50-213/80-24 on 801119-21 violation BRUNNER, E. J. Region 1. Philedelphia, Reactor Operations Support Branch BO/12/23 2pp 07967:090.

- --8103200581 Notice of violation from insp on 801119-21 BRUNNER.E J Region i. Philadelphia. Reactor Operations Nuclear Support Branch 90/12/21 1p 07947 052
- --8103200582 IE Insp Rept 50-213/80-24 on 801119-21 Noncompliance noted incorrect algebraic end point correction made to reactivity worth of rod B-31 & errors rade in data analysis of moderator temp coefficient BETTENMAUSEN.L. PETRONE.C D Region 1. Philadelphia. Office of the Director CAPHION.D L Region 1. Philadelphia. Reactor Operations Nuclear Support Granch 80/12/19 7pp 07967 093
- 8103200198 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines." No response required. ORIER.B H. Region 1. Philadelphia. Office of the Director 81/02/27. If 07971-337
- BIO3200131 Forwards IE Circular 81-03, 'Inoperable Seismic Monitoring Instrumentation' No written response required, GRIER, B.H. Region 1. Philadelphia. Office of the Director BI/03/02 if 07971 34
- Bi0320007B Forwards revised IE Bulletin Bi-Oi. "Burveillance of Mechanical Enubbers." U/corrected Pages 5 & 6 Change in identification of facilities U/CP to which bulletin is applicable does not affect util requirements CRIER.B H Region 1. Philadelphia. Office of the Director Bi/O3/04 ip 0796B.209
- B103180400 Forwards Page 2 of Amend 37 to License DPR-61, replacing insp & testing u/inservice insp & valve testing program CRUICHFIELD.D Operating Reactors Branch 5. B1/03/06 2pc 95231 039
- --BIO3[BO405 Forwards Amend 37 to License DPR-61, safety evaluation & notice of issuance & availability. Amend 37 only encl CRUTCHFIELD, D. Operating Reactors Branch S. B1/02/26 2pp 02983 098
- ~-BI03180413 Amend 37 to License DPR-61, replacing inservice insp & testing Tech Bpecs w/inservice insp & valve testing Fech Speck & revising ECCS valve testing requirements CRUTCHFIELD.D Operating Reactors Branch 9 81/02/26 2pp 07953 097
- 8103200130 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Broater." No response required. CRIER.B.H. Region 1. Philadelphia. Office of the Director 81/03/11. 1p. 07971:336.
- R. Periodic operating reports & related correspondence
- 8103030547 Forwards "Annual Operating Rept. 1980." 9RAVES.R.H. Connecticut Yankee Atomic Power Co. B1/02/17 1p.
- --8103030554 "Annual Operating Rept. 1980."

  \* Connecticut Yankoe Atomic Power Co. 81/02/18 31pp 07793.144
- B103030822 Forwards "Bemiannual Radioactive Effluent & Waste Disposal Rept. Jul-Dec 1980."

  GRAVEB.R H Connecticut Vantee Atomic Power Co 81/02/26 1p.

  07780:279.
- --8103030827 "Semiannual Radioactive Effluent & Maste Disposal Rept, Jul-Dec 1980." • Connecticut Yankee Atomic Power Co. 81/02/26 93pp 07788:280
- B103170344 Forwards monthly operating rept for Feb 1981. ORAVES.R.H. Connecticut Yantee Atomic Power Co. 81/03/12. 1p. 07924-039
- --8103170349 Monthly operating rept for Feb 1981.
  \* Connecticut Vantee Atomic Power Co. 81/03/12. Opp. 07924.040.
- S. Reportable occurrences. LERs & related correspondence
- B103090342 Forwards LER B1-001/03L=0. ORAVES.R.H. Connecticut Yankse Atomic Power Co. 81/03/02. 1p 07844:339.

- --Bi03090944 LER Bi-001/03L-0 on Bi0205.one of four fans in top sect of bypess dampers did not close during monthly containment air recirculation fan damper tests Caused by inoperable air motor used to position damper Motor dismantied b cleaned FLEMIN9.8 T Connecticut Yankee Atomic Power Co 81/03/02 1p 07844-360
- BIO3170600 Forwards LER 80-012/03x-1 GRAVES.R H Connecticut Yanise Atonic Power Co Bi/03/12 1p 07930 131
- --810317060; LER 80-012/Cox-1 on 800717 during precritical checks, re coalant pump 2 seal water supply bugass valve stem bushing broke, allowing valve to go full open Caused by high closing torque Vender has designed alternate throattling trim LEVINE. J M Connecticut Yankee Atomic Power Co 81/03/12 2pp 07930-132
- DOCKEY 50-219 DYSTER CREEK NUCLEAR POWER PLANT
  F Becurity, medical, emergency & fire protection plans
- B103030970 Forwards summary of staff requirements to resolve open it. & FR notice re-fire protection features Applicable App R provisions, effective B10217, discussed EIBENHUT.D.O Division of Licensing 80/i1/24 4pp 07795, 2a0
- 8103100138 Notifies that NRC contractors.WR Thomas & DF Cameron.uill conduct vital area analysis at facility on 800113 CRUTCHFIELD.D Operating Reactors Branch 5 81/01/08 2pp 07865 341
- 8103020250 Approves 801201 request for delay in conducting emergency preparedness exercise until Mar 1981 Delay based on scheduled submittal of upgraded emergency plan on 810102 u/inplementation by 810401. CRUICHFIELD 0 Operating Reactors Branch 5. 81/01/13 2pp 07784-276.
- 8103180264 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addl info resafe shutdown capability for compliance u/801119 fire protection rule EISEMHUT.O O Division of Licensing. 81/02/20 13pp
- 8103260989 Ack receipt of 801107 ltr re proposed change to security plan Plan will be withheld tref 10CFR2 790) CRUTCHFIELD.D Operating Reactors Branch 5. 81/02/24 2pp 08040 228.
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements U/o encl ETSENHUT.D O. Division of Licensing 81/03/05 App.
- B103170101 Releases public version of implementing procedures for emergency plan FELTON, M. Division of Rules and Records. B1/03/12 ip 07806:001
- --8103170105 Forwards public version of implementing procedures for emergency plan. FINFROCK.I.R. Jersey Central Power & Light Co. 81/03/02 ip
- B103230417 Requests extension for emergency plan exercise, due to five training & equipment procurement delays. Excorcise can be performed 3 wis following completion of Apr 1981 outago. FINFROCK, 1 R. Jersey Central Power & Light Co. 81/03/16 2pp 07997: 357
- BiO3260288 Bubnits response to 10CFR50 48 requirements Engineering we have been initiated to provide emergency lighting Requests extension until 820117 for submittal of plans for alternate shutdown sys. App R Item III. 0 is not applicable. FINFROCK, I. R. Jersey Central Power & Light Co B1/03/20. 2pp 08037:349.
- B103270012 Requests that encl emergency planning info be placed in LPDR.W/o 8103170105 BOUDER.J.L. Division of Rules and Records. 81/03/24. 1p. 08047-071.

```
8103310207 Forwards temporary change to physical security plan Encl
  103310207 Forwards temporary change to physical security bio. a
bithheld (ref 100FR2 790)
FINTROCK, I R. Jersey Control Power & Light Co. 81/03/26 fp
   08062, 101
```

- 9. Adjudicatory correspondence
- 8103040599 Forwards order for license mod.requiring automatic dump sys design to be independent of air pressure instrumentation for manual scram CRUTCHFIELD.D Cogratury Reactors Branch 5 81/01/09 200 07810 341
- --B103040569 Order for med to License CPR-16-designing automatic dump sys-to be independent of air pressure instrumentation for manual scrae FISENHUT, D 3 Division of Licensing 81/01/09 600 07810 344
- J insurance & indennity information

н,

- 8103090596 Forwards Endorsement 56 to MAELU Policy MF-44 CONTROL OF THE PROPERTY OF THE
- 81031AD395 For Jards Endorsegents 5 to MAELU Sinder X8-13 & NELIA Binder FB-13 GERETY, H F General Public Utilities - GPU Service Corp 91/03/11 4pp 07917 347
- F Operating license stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NGC position re interim actions & request for add1 infa EISENHUT, D. O Division of Licensing 80/12/22 30pp
- 8103040558 Forwards order for license modinaquiring automatic dump sys design to be independent of air pressure instrumentation for manual screen CRUTCHFIELD, D. Operating Reactors Branch 5. 81/01/09 2pp 07810 341
- --B103040559 Order for mod to License CPR-15.designing automatic dump sys to be independent of air pressure instrumentation for markal scram EISENHUT.D G Division of Licensing 81/01/09 app 07810 344 8103190387 Lir to all licensees of operating plants & applicants for
- Dus & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cald shutdown, replacement parts & EUREG-0737 EIBENHUF, D.O. Division of Licensing, 81/01/19 Opp 8:03240290 Ltr to all BWR licensees forwarding Suppl i to generic safety evaluation on BUR stram discharge sys Summarites re-evaluation of interim measures recommended per 801201
  - safety evaluation EISENHUT, D. O. Division of Licensing 81/01/23 2pp BiQ2280182 Requests review & approval of changed shipment route directed by NJ Bureau of Radiation Protection CARROLL J T Public Service Electric & Gas Co of New Jersey Bi/O1/29 Ip 07777 198
  - 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except indian Point 2 & 3.7son 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads EISENHUT.D 0 Division of Licensing. 81/02/03 6pp
  - 8103060387 Forwards "Environ Qualification of Safety-Related Electrical

Equipment," partial review Written response required. LAINAS.Q.C. Assistant Director for Bafety Assessment 81/02/10

--B103060393 "Environ Qualification of Bafety-Related Electrical Equipment." partial review.

# Dffice of Nuclear Reactor Regulation. Director. 81/02/10
18pp. 07836:271

3pp. 07836 268

8103040774 Forwards Amend 52 to License DPR-16. safety evaluation & hotice of issuance & availability CRUTCHFIELD.D. Operating Reactors Branch 5. 81/02/11 200 07815 078.

Tach Spec 4 5 bases section CRUICHF(ELD.D Operating Reactors Branch 5 81/02/11. 400 07815 080

--RIO3040778 Amend 32 to License DPR-16, revising testing procedu

logovoro ameng 52 to license ben-lo-revising testing proceding distance of carbon samples removed from standby gas treatment sys & correcting

- --Bi03040784 Safety evaluation supporting Amend 52 to License DP 81/02/11 07815 086
- -- 9103040790 Notice of issuance & availability of Amend 52 to Li CRUTCHF1ELD.D. Operating Reactors Branch 9 81/02/11 200 07815 066

BIO3050249 Forwards Amend 53 to License CPR-16 & notice of issue

CRUTCHFIELD.D. Operating Reactors Branch 5 B1/02/11 3pp 07825.243 --8103050258 Amend 53 to License DPR-16, including requirement to implement quard training & qualification plan within 60 days & to qualify all security personnel within 2 yrs (RNICHFIELD, D. Operating Restors Branch 5 91/02/1) 200

avent labition

D7825 246

- --B103050265 Notice of issuance & availability of Amend 53 to Li CRUYCHFIELD.D. Operating Reactors Branch 5 81/02/11. 2pp 07825, 248 8(03)60669 Ltr to all operating plants & CP holders forwarding clarification of TM1 Action Plan Item III A 1.2 re upprade
- of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EIBENHUT, D. O. Division of Licensing. 81/02/18 12pp Bi03250024 Ltr to all power reactor licensees & license applican INREO-0619 criteria Footnote 2 in Table 2 contains error due to teakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D. Q. Division of Licensing. Bi/02/20. Bpp
- 8103230030 Ltr to all licensees of operating nuclear power plant applicants for OLs (except Bi Lucie Units 1 & 2). Requests util review to determine capability to mitigate station blactout event & promptly implement emergency procedures. EISEMHUT.D.O Division of Licensing 81/02/29 Spp.
- B103170225 Ltr to all BMR licensess (except Humboldt Bay & LaCro requesting review of ASME Code Class I & 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision 1 to NUREO-0313 Model Tech Specs only encl. EISENHUT.D.O Division of Licensing B1/02/26 Upp. --Bi03170266 Model Tech Bock Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/ surveillance requirements for ABNE Code Class 1:2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements. \* General Electric Co 81/02/26 4p

Bio3090273 Commits to safe operation of facility re environ qualification of safety-related electrical equipment.per

FINFRDCK, I.R. Jersey Central Power & Light Co. 81/02/27 | Ip 07890 328 8103190337 ECOLDOICAL STUDIES OF WOOD-BORING BIVALVES IN THE VIC OF THE DYSTER CREEK NUCLEAR GENERATING STATION HOAGLAND, N. E., CROCKET, L. Lehigh Univ. FIN 8-3744, NUREO/CR HOAGLAND, M. E., CROCKET, L. Lehigh Unity. FIN 8-3744, NUREO/CR 81/02/28 58pp. 08025:037.

810210 request.

- B103110703 Forwards Tech Spec Change Request 92 FINFROCK-I.R. Jersey Central Power & Light Co. B1/03/04. 1p 07885: 035.
- --Bi031i0708 Tech Bpec Change Request 92 re control rod drive ec discharge vol capability Certificate of Bvc encl FINFROCK, I. R. Jersey Central Power & Light Co. 81/03/04.
- 07885 036 8103130864 Forwards License Change Request 96 & info supporting proposed changes.
  FINFROCK, I. R. Jersey Central Power & Light Co. 81/03/09. 1p
- --81031309AB License Change Request 96 to License DPR-16.permitt of QE fuel during future fuel loads Certificate of Bvc & supporting info enti-

- Big03010804 Ltr to all licensees of operating plants.applicants for QLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment FISENBULD O Division of Licensing 81/03/10 660
- B103;60397 Forwards application to amend License DPR-16, submitted as Tech Spec Change Request 95, re-proposed mods to core spray sus-pargers & piping Encl design side is preliminary Tech Spec change planned for Fall 1781 Certificate of Svc enci FINFROCK, I R Jersey Central Power & Light Co 81/03/13 2pp 07918-058
- --B103160561 Application to amend License DPR-16, submitted as Tech Base Change Request 95, providing preliminary design info re proposed mod to core spray sys FINFRDCK. I R. Jersey Central Power & Light Co 81/03/13 2pp 07918 060
- --8103160565 "Core Spray Preliminary Mod Rept." re Tech Sprc Sections 3-9 for removal replacement structural evaluation performance analysis & testing # Jersey Central Power & Linkt Co. 81/03/13 27no 07918 067
- 8103160776 Requests extension of 810407 deadline re installation of autoratic sys to initiate control rod insertion on low pressure in control air header Required mods can be done curing outage scheduled on or before 810501 FINRROCK. I R Jersey Central Power & Light Co 81/03/13 ip again 100
- 8103200517 Advises that SEP Topics VI-7 C (ECCH single failure criterion & requirements for locking out power to valves) & VI-7. C R (failure mode analysis) are complete, except for integrated assessment. Amend 15 to DPR-16 is duplicative CAUTCHFIELD. D Operating Reactors Branch S 01/03/13. 2pp 07921 017
- 8103230368 Forwards refund on Class III fee for 810129 application requesting postponement of installation of alternate water supply tank.
  MILLER:N 0 License Fee Management Branch. 01/03/16 | Ip 07980-356
- BiO3230534 Forwards evaluation of BEP Topics V-5 re RCPB leakage detection b V-12 A re-water purity of BUR primary coolant testage detection sys does not have required sensitivity No Tech Beec mods are necessary for water purity CRUTCHFIELD. D Operating Reactors Branch 5 81/03/16 25pp
- 8103270095 Bummary of B10304 meeting w/Mark I owners group & OE in Bethesda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREO-0861 Blide presentation & list of attendees encl ORIMES.C.I. Literaing Branch 3 81/03/16 Spp 08049, 203.
- B103240576 Informs that Class IV fee required for 600923 application re proposed changes to Tech Specs per IMI lessons learned Category A items D1005.R M License Fee Management Branch 81/03/18 ip 07982 309
- 810324051\$ Forwards revised Page 4.7-la of Tech Spec Change Request 8B, stipulating specific gravity for station batteries. KNUBEL.J. Jersey Central Power & Light Co. 81/03/19 2pp 07982.353.
- ~-9103240518 Revised Page 4.7-1a of Tech Spec Change Request 88, stipulating that specific gravity for station batteries shall be greater than or equal to 1.190 # Jersey Contral Power 3 Light Co. 81/03/19. 2pp. 07982.354.
- BiO3261005 Notification of BiO329 meeting w/util in Bethesda.M0 to discuss review of postulated pipe breaks inside & outside containment PAULBOH.M. A. Operating Reactors Brench S. Bi/O3/23. 2pp 08035:152.
- G Inspection reports. IE Bullatins & correspondence
- 8103020158 Forwards IE Info Notice 81-01, "Possible Failures of OE Type HFA Relays:" No response required. ORIER.B.H. Region 1, Philadelphia, Office of the Director. B1/01/16, ip. 07785.247.

--BIO319030B IE Insp Rept 50-219/BO-35 on B01201-31 No noncompliance noted Major areas inspected licensee action on previous insp findings log b recent review fallows of ansite events to IE builetins t circulars
THDMAS.J A . BRIGGS.L E Region L Philadelphia. Office of the Director XEIMIG.R R Region I. Philadelphia. Reactor Operation Nuclear Support Branch 81/01/28 Bpc 07954 276

Support Stanta 81/01/29 266 98981 355

- 8103200313 Responds to IE Bulletin 80-17. Suppl 4. "Fajlure of Control Rods to Insert During Stram at BuR " Personnel performing field calibr of continuous monitoring sys are facility technicians

  FINEROCK. I R Jersey Central Power & Light Co. 81/02/02 62p 07971 068
- B103230909 Forwards IE Mgt Meeting Rept 90-219/81-02 on B10114 No noncompliance noted GRIER.8 H. Region I. Philadelphia. Office of the Director B1/02/11. 1p 07974 009
- --8103230913 IE Mgt Meeting Rept 50-219/B1-02 on BIO114 No concompliar noted Areas discussed physical security program reviolations identified during Physical Security Insp 50-219/80-36 on B01215-19 Details withheld (ref 100FH2 740) BM1TM-0. C. BAILEY-R J. Region 1. Philadelphia. Office of the Director DEVIN-J W. Region 1. Philadelphia. Safeguards Branch B1/02/06 1p 07974-010
- 8103040200 Forwards IE Info Notice 81-03. 'Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CFR50 72 " No written response required GRIER.B K Region I. Philadelphia. Office of the Director 81/02/12 is 07813.123
- 8103030296 Forwards Suppl 9 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Stram at BUR": No written response required
  ORIER.B H Region 1. Philadelphia, Office of the Director 81/02/13. 10 07770 394
- B103200185 Forwards IC Info Notice 81-04. "Cracking in Main Steam Lines" No response required GRIER, B H Region 1. Philadelphia, Office of the birector 81/02/27 1p 07972-028
- B103200187 Forwards 1E Circular 81-03. 'Inoperable Seismic Monitoring Instrumentation' No written response required GRIER.8 H. Region 1. Philadelphia. Office of the Director 81/03/02. 12 07966 189
- BIO3200099 Forwards revised IE Bulletin BI-OI. "Burveillance of Mochanical Shubbers." w/corrected Pages 5 & 6 Change in identification of Pacilities w/CP to which bulletin is applicable dose not affect util requirements. GRIER.B H Region I. Philadelphia. Office of the Director BI/O3/04 1p 07949-05
- 8103200298 Forwards IE Info Notice 81-06. "Failure of ITE Model M-600 Circuit Breaker" No response required ORIER.8 H. Region 1. Philadelphia, Office of the Director 81/03/11 | 1p. 07969-004
- R Pariodic operating reports & related correspondence
- 810304020B Forwards "Eculogical Studies at Dyster Creek Nuclear Generating Station," progress rept for Sept 1979 - Oct 1980 Erecutive summary encl FINFRUCK.I.R Carolina Power & Light Co 81/02/27 4pp. 07814:001.
- --8103040215 "Ecological Studies at Oyster Creek Nuclear Generating Station." progress rept for Sept 1979 - Oct 1980 • Ecological Analysts, Inc. JCP9113 B1/02/28, 440pp 07814-005
- 8103060295 Forwards "Effluent Release Rept." for Jul-Dec 1980 FINFROCK I. R. Jersey Central Power & Light Co 81/03/02 ip 07898 267
- --8103060298 "Effluent Release Rept." for Jul-Dec 1980.

  \* Jersey Central Power & Light Co 81/03/02 76pp. 07838 268

- 9100240174 Forwards "Mondborer Study Associated U/Cyster Creek Cenerating Station to JCPSL 801111-810220": Also forwards corrected Page 8 Table 5 of June-Aug 1980 rept FIGERECK, C. R. Jersey Central Power 5 Light Co. 81/03/18 Ip 85138 222
- --Bi03240178 Corrected Page 8. Table 5. of June-Aug 1780 Moodborer study rept

   Sattelle Menorial Institute, Columbus Laboratories 15008
  60/09/15 in 65138 223
- --8103240186 Woodborer Study Associated W/Gyster Creek Generating Station to JCPUL.8001111-810220 MACIGLEK-SLAVE. DELMCRE.C I . HILLMAN R E Battelle Memorial Institute. Columbus Laboratorias (5039 B1/02/27 21pp 65138 224
- 0:03240062 Forwards monthly operating rept for Fet 1981 FINEROCK: 1 R Jersey Central Power & Light Co 81/03/19 1; 07987 231
- --81032403a7 Monthly operating rept for Feb 1981 SKLAR-J 9 Jersey Central Power & Light Cc 81/03/12 9pp 07587 232
- S. Reportable occurrences. LEAs & related correspondence

- 6103100456 ForLerds LER 80-062/03L-1 FINEPOCK.1 R Jersey Central Power & Light Co 81/03/06 4pp 07862,271
- --Bi03100465 LER 80-062/03.-1 on B01218, control rod driveline purp NCOBA failed inservice during normal plant operation Caused by failure of purp shaft outboard of balancing disc Purp internals & jump motor replaced CROS
- 8103170633 Forwards LER 91-008/03L-0 FINFROCK, I R Jersey Central Power & Light Go 81/03/12 3pg
- --BI03170&40 LER 81-0CB/03L-0 on BI0210 cater seepage observed along west uall of NRN blog Direct survey should detectable ground contamination only within & inches of wall Caused by high levels in bant vaults Herculite secured & sealed to wall FITZGERALD. M. J. Jersey Central Power & Light Co. 81/03/12 ip 07925 160
- 8103240587 Forwards LER 81-009/03L-O Dataited event analysis submitted FINFROCK, I 8 Jersey Central Power & Light Co 81/03/16 3pp
- ~-BIO3R40592 LER 8I-009/03L-0 on BIO2I3; snubber 23/3 found w/very low oil level % cil discovered on floor at base connection during MRC walk-around insp Caused by failure of inner shaft seal due to deterioration Snubber replaced u/operable spare FITZ6ERALD.M J. Jersey Central Power & Light Co. 8I/03/16 ip 07982 340

OUCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Eecurity, medical, energency & fire protection plans

- 8103060406 Approves BCC807 request for completion date extension remots for protection systs shutdown panel until 810730.for sprinkler systematical control extension duct penetration until 81971ng 1981 refueling FR notice encl DENTON.H.R. Office of Nuclear Reactor Regulation, Director 81702713. Spp. 07835.300
- --8103050-115 Notice of extension of completion dates for facility fire protection mode CASE.E O. Office of Nuclear Reactor Regulation. Director 81/02/13 1p 07835-305

- B103180264 Ltr to all power reactor licensees w/plants licensed proto 790101 Forwards ARC position & request for addl info ne safe shutdown capability for compliance w/B01119 fire protection rule EISEMANT, D.O. Division of Licensing 81/02/20 13pp
- 810331033B Ler to all licensees of operating plants & holders of CP forwarding NJREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for neeting NRC requirements N/o entl EISECHUT.D 0 Division of Licensing 81/03/05 6PP
- 8103310155 Responds to 790817 itr submitting guard training & qualification plan Review indicates need for revisions & add! info Comments encl. Response requested within 30 days of receipt of itr [PPCLITG.T A Operating Reactors Branch 2 81/03/24 4pp. 000A2 311
- O Adjudicatory correspondence
- 8103200538 Stipulation withdrawing appeal from active court consideration to permit ongoing settlement negotiations to continue u/a necessary time strictures Withdrawal is w/o prejudice Related correspondence. AULICK. D. Affiliation Unknown MCBRICE. M. Niagara Mohawk Power Corp. SCHWMAN. H. J. Office of the General Counsel. 81/02/25 07971-315
- 8103030566 Petition by TJ Perkins to intervene in proceeding All requirements for late filing satisfied Notices of appearance in proceeding 8 Certificate of Svc entl CHARNOFF. 0 Affiliation Unknown CHARNOFF. 0. Bhas. Pittman. Po & Teasbridge 81/02/26. 8gp 07793 228
- 8103230484 Confirms that appointment of hearing board re allegation against licensee would be premature Licensee will attempt to resolve matters by 810327 Suggests that expedited hearing ho held if issues are not resolved Related correspondence FITZOERALD. J A Office of the General Counsel 81/03/13 1p 07979 332.
- BIO3300496 Clarifies reasons for NRC 801126 enforcement actions Results of investigation determined that Perkins possess necessary character & reliability to be reinstated in nuclear industry Order withdrawing show cause & mode encl STELLOV. Director's Office. Office of Inspection and Enforcemen 81/03/29 2pp 08057.185
- ---9103300498 Order withdrawing ordered and & order to show cause & terminating of 801126 proceedings STELLO. V Director's Office, Office of Inspection and Enforces 81/03/20 4pp 08057 187
- i Financial information
- 8103160462 Forwards Annual Financial Rept 1980. LEMPGES: T.E. Niegara Mohawk Power Corp. 81/03/12 1p. 07916 2
- --8103160467 Annual Financial Rept 1980 MAEHL J. G. BONLON W. J. Miagara Mohauk Power Corp. 81/02/02 38ep 07989 001
- P. Operating license stage documents & correspondence
- 8103199732 Ltrs to all licensees of operating plants, applicants for ULs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREQ-0612 Forwards NRC position re interim actions & request for addl info.

  EISENHUT. D O. Division of Licensing 80/12/22. 30pp
- B103190387 Ltr to all licensess of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown.replacement parts & NUREO-0737.
  EIBENHUT.D O Division of Licensing. B1/01/19. 600
- 8103240270 Ltr to all BUR licensees forwarding Suppl I to generic sefety evaluation on BUR scram discharge sys. Summerizes re-evaluation of interim measures recommended per 801201 safety evaluation.
  EISENHUT. D. G. Division of Licensing. 81/01/23. 2pp
- 8103120014 Ltr to all licensess of operating plants.CP holders & OL applicants, except Indian Point 2 & 3, Ziom 1 & 2 & TMI-1, forwarding inadvertently unitted pages from NRC 801222 request for additioner e control of heavy loads.

  EISENHUT, D. G Division of Licensing. 81/02/03 App.

- MUREQ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of elisting low flow controller EISENHUT.D Q Division of Licensing 81/02/20 App
- BiO3230030 Ltr to all licensees of aperating nuclear power plants & applicants for CLs (except St Lucie Units 1 \$ 2) Requests util review to determine capability to mitigate station blactout event & promptly implement emergency procedures £185NHUT.D O Division of Licensing Bi/O2/25 5cp
- B103170225 Ltr to all BKR licensees (orcept Humboldt Bay & LaCrosse) requesting review of ASME Code Class & 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision 1 to NUREO-0313 Model Tech Specs only encl EISENHUT, D Ø Division of Licensing 81/02/26 3pp
- --8103170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ABHE Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements. a General Electric Co. 81/02/26 App
- 8103030683 Forwards application to arend License DPR-63 changing Tech Spec Section 3 2 7 re core spray high point vent limiting condition for operation Class II amend fee encl THOMAS.E B LeBoeuf. Lamb. Leiby & MacRae 81/03/02 2pp 037989-983
- --BIO3030686 Application to amend License DPR-63, changing Tech Spec Section 3.2.7 re-core spray high point vent limiting condition for operation DISE.D P Niagara Mohauk Power Corp. B1/02/27 2pp. 07798.255
- --B103030588 Proposed Tech Spec Section 3.2 7, changing core spray high point vent limiting condition for operation. Supporting info & fee classification encl • Niagara Mohauk Power Corp 81/02/27 Spp 07798 257
- B103180011 Forwards Amend 40 to License DPR-63 & notice of issuance & evallability.

  IPPDLITO.T A Operating Reactors Branch 2 81/03/05. 3pp 07943 327
- --8103180012 Amend 40 to License DPR-63 requiring safeguards contingency plan be fully implemented within 30 days of approval by Commission IPPOLITG.T.A. Operating Reactors Brench 2 81/03/04. 3pp. 07943:330
- --Bi03180013 Notice of issuance & availability of Amend 40 to License pR-63.
  IPPOLITO.T A Operating Reactors Branch 2: 81/03/05. 2pp 07943:332
- 8103|60375 Informs that all mods necessary to meet NRC acceptance criteria on Mark I program will be completed by 830131.per NRC 810113 order.

  DISC.D.P. Niagara Mohawk Power Corp. 81/03/10. ipp. 07917.145.
- 8103310804 Ltr to all licensess of operating plants applicants for QLs & holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT, D. O. Division of Licensing 81/03/10. 600
- 9103160507 Advises that mnd re-control room annunciation for condition of diesel generator isolation switch & normal supply breaker control switch will be completed during Spring 1983 refueling outage.

  DISG.D.P. Niegara Mohauk Power Corp. 91/03/11 [p. 07921:120.
- 8103270095 Summary of 810304 meeting w/Mark I owners group & GE in Bethesda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MAREC-0661. Blide presentation & list of attendees encl. ORIMEB.C I. Licensing Branch 3. 81/03/16. Spp. 08045.203.
- 8103260413 Forwards Amend 41 to License DPR-63 safety evaluation & notice of issuance & availability.

  IPPDLITO.T.A. Operating Reactors Branch 2 81/03/19. 3pp. 08039-289

0100710117

08033 320

07944: 140

--8103260442 Notice of issuance & availability of Arand 41 to Li-DPR-63 IPPOLITO.T A Operating Reactors Branch 2 81/03/19 2pp 08039 329

\* Office of Nuclear Reactor Regulation, Director 81/03/19

- 8103260799 Submits licensee plans for schedule 2 design descript per Section III 0 3 of 10CFR50. App R Will install safet shutdwon panel to provide alternate control for energency condenser injet.return 3 makeup level control valves.

  DISC. DP Nicagra Mohau-Power Corp. 8103219, 2pp. 08037
- 8103270745 Forwards Tech Spec revisions for snubber surveillance 801120 request DISE.D P. Niegara Mohaus Power Corp. 81/03/20 3up. 08043
- --8103270750 Proposed Tech Specs 3/4 6 4 re shock suppressors (s & Tables 3 6 4a-b re safety-related hydraulic snubbers. Bases for 3/4 6 4 & supporting info encl \* Niagara Mohauk Power Corp 81/03/20 14pp 08043.169.
- 8103270710 Responds to NAC BIO202 request for addl info re degragrid voltge Clarifications on issue are required prior to
  - submittal of response
    DISE.D P Niagara Mohauf Power Corp. 81/03/23 1p 08045.10
- Q Inspection reports, IE Bulletins & correspondence
- 8103170248 FOIA request for documents re investigation of former superintendent TJ Perkins ALBERTA Affiliation Unknown 80/12/19 2pp. 07934.323
- 8103050784 Forwards IE Insp Rept 50-220/80-15 on 801020-24 No noncompliance nated BRUNNER.E J Region i. Philadelphia. Reactor Operations Nucle. Support Branch 81/01/06 2pp 07828-120
- --BIO3050769 IE Insp Rept 50-220/80-15 on 801020-24 No noncomply noted Major areas inspected GA program changes audits, design changes/mods & licensee action on previous Insp findings
  NAPUDA-0. Region 1. Philadelphia- Office of the Director.
  OREENMAN, E. Region 1. Philadelphia- Reactor Operations Nucl. Support Branch. 80/12/29 4pp 07823 122
- 8103050212 Responds to IE Bulletin BO-17. Buppl 4. "Failure of Cor Rods to Insert During Brown at BWR " Provisions made for operation, periodic testing, calibr & repair procedures as described in Item 6 LEMPOES T & Niagare Mohawk Power Corp 81/01/30 2pp 078:
- 8103180463 Forwards supplemental response to IE Builatin 79-01B.
  Environ Gualification of Class IE Equipment" & response to
  Buppl 3 to builetin Info provided re components previously
  identified as lacking documentation.
- 8103180696 Ack receipt of 810120 ltr informing NRC of steps take correct violations noted in IE. Insp. Rept 50-220/80-13.
  BRUNNER,E. J. Region 1, Philadelphia, Reactor Operations Nucle Support Branch. B1/02/04. 1p. 07949
- --B103180659 Responds to NRC 801219 ltr re violations nated in I Rept 50-220/80-13 Corrective actions fire door closed, autoclosure mechanism replaced & daily fire door insp implemented in mid-Dec 1980 LEMPORB. T.E. Niagara Mohauk Power Corp. 81/01/20. 2pp. 37949-249.
- --8103180660 Forwards IE Insp Rept 50-220/80-13 on 800916-1019 & of violation.
  BRUNNER,E.J. Region 1. Philadelphia. Reactor Operations Nuc Support Branch 80/12/15 2pp 07949-251.
- --B103180663 Notice of violation from insp on B00916-1019

  \* Region 1, Philadelphia, Office of the Director. B0/12/12
  0799-283.

- 6103230854 Responds further to 16 Bulletin 79-018. 'Environ Qualification of Class 16 Equipment' Updates 810202 committeent to perform qualification testing of IMI-related valve monitoring sys from Jul 1981 to Nov 1981 LEMPGES. F.E. Niegara Mohaus Power Corp. 81702/10 ip 07975 032
- E103040190 Forwards IE Info Notice 81-03, "Checklist for Licensees Making Notifications of Significant Events In Accordance II/10CER50 72 " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director B1/02/12 | p 07813 | 11
- Bio3030406 Forwards Suppl 5 to IE Bulletin B3-17. "Failure of Control Rods to Insert During Scram at BWR" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director B1/02/13 [c. 07755 011
- B103270351 Ack receipt of B10128 ltr informing NRC of steps taken to correct violations moted in IE linsp Rept 50-220780-16 CARLSCRIP I Region L. Philacelphia, Reactor Construction & Engineering Support Branch B1702720.
- -8103270361 Responds to MRC 810107 ltm re violations noted in IE Insp Rept 50-220/60-16. Corrective actions cabling separated & area roped off to prevent physical interference LEMPGES T E Niagara Mohaus Power Corp 81/01/28 ip 1833-1934
- --BiD3270366 Forwards IE Insp Rept 50-220/80-46 on 801119-20 No noncompliance noted CARLSON, R T Region 1. Philadelphia, Ruactor Construction & Engineering Support Branch 81/01/07 2pp. 08043-229.
- --6100270390 1E Insp Rept 90-220/80-16 un 801119-20 No noncompitance holed Major areas inspected main stear isolation sys & emergency cooling sys to verify component installation & identification per IE Bulletin 79-018 response PAGLING.R J. Region 1. Philadelphia. Office of the Director EGNETER.S D. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/12/40. Spp. 06043 231
- 8103200166 Forwards 1E Info Notice 81-04. "Cracking in Hain Steam Lines" No response required GRIER.8 H Region 1. Philadelphia. Office of the Director 81/02/27 ip 07972 010
- 8103170243 Responds to FDIA request for documents re investigation of former sits superintenient. TJ Perkins IE Insp Rept 50-220/79-17 is completely withheld (ref FDIA Exemption 6) FECTOR, J.M. Division of Rules and Records. B1/03/02, jp.
- B103200223 Forwards IE Circular B1-03. Inogenable Boismic Manitoring Instrumentation "No written response required GRIER.B H Region 1. Philadelphia. Office of the Director B1/03/02. 19 07966.206
- 8103200095 Forwards revised IE Bulletin B1-01, "Surveillance of Mechanical Brubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements ORIER, B H. Region 1, Philadelphia, OPPice of the Director B1/03/04, ip 07968, 192
- B\$03200165 Forwards IE Info Notice Bi-O6. "Feilure of ITE Model K-600 Circult Breater." No response required GRIER.8 H. Region 1. Philadelphia. Office of the Director Bi/03/11. ip 07968:301
- 8103270316 Discusses relative merits of lead cave & lead brick when used w/portable high-range monitor. Lead brick would not have prevented distortions in roadings. Previous submittals to NRC were not completely accurate LEMPOEG. T. E. Niagara Mohauk Power Corp. 81/03/20 ip 08044:177
- 8103300496 Clariffes reasons for NRC 801126 enforcement actions Results of investigation determined that Perkins possess necessary character & reliability to be reinstated in nuclear industry. Order withdrawing show cause & nods encl SECLOV. Director's Office, Office of Inspection and Enforcement. 81703720 2c; 08097 185

- BID3060297 Forwards "Radioactive Effluent Release Semiannual Rept. vul-Cec 1980 " Includes reteorological data in accordance u/Reo Outde ( 23
- UJReg Ouide ( 23 SILLIMAN M A Niagara mohaut Power Corp 81/02/27 Ip 07840 168

  --8103060309 'Radinactive Effluent Release Seniannual Rept. Jul-Dec 1980

  A Niagara Mohaut Power Corp 81/02/27 5200 07840 169
- S Resortable occurrences. LERs & related correspondence
- 8103240520 RO 81-04 on B10209 main steam line radiation monitor lil reactor protection sys attuation relay blocked during repair of monitor electronics, rendering monitor inoperable Caused by multiple spurious half screm actuations RCMAN.TW Hisgara Mohauk Power Corp 81/02/10 Ip 07986 165
- 8103030753 Forcards LER 81-004/01T-0 LEMPGES T E - Magara Monauk Power Corp 81/02/20 2pp 07791:310
- --Bi03039757 LER 81-004/011-0 on 810209.main stean radiation monitor 11 signal fluctuates.causing multiple half scrams.Caused by losse detector-to-cable connector Connector tightened HARRIBON.P Niagara Mohaui Power Corp 81/02/23 2pp 07791 312
- 8103120532 Forwards LER 81-007/03L-0 LEMP0ES.T E Niagara Mohawk Power Corp 81/03/04 1p 07901 290
- ---8103120534 LER 81-007/05L-0 on 810292 during weekly surveillance, diese fire pump oil leak was identified Caused by leak in coupling to tubing weld joint Joint removed, retraised & returned to svc • Niagara Monauk Power Corp 81/03/04 lp 07901-291.
- B103120536 Forwards LER 81-005/04L-0 LEMP0EB.T E Niagara Mohawk Power Corp 81/03/04. 1p 07901 292.
- --8103120539 LFR 81-005/04L-0 on 810202.plant discharge temp vs plant injet temp Teck Spec was exceeded for 52-h during circulating water revelse flow operation Cause not stated. Checklist to be revised to prevent future occurrence MARRISGY.P Niagara Mohauk Power Corp 81/03/04 2pp 07901 293
- B103170628 Forwards LER 81-006/03L-0 LEMPGES T E Niagana Mohawi Power Comp 81/03/06 1p. 07925.167
- -8103170631 LER 81-006/031-0 on B10207.during fire sys preventive main test.electric fire pump failed to start Causad by broken grop spring in 4160V motor breaker Spring replaced & pump returned to evc. HARRISSN-P Niegara Mohawk Power Corp 81/03/09 1p 07929 163.
- B103250415 PNO-EN-B0-052A on B10320, proposed penalty reduced to \$215.000. util site nuclear superintendent reinstated & B01126 order to show cause rescinded.
  THUMPSDN-D. Enforcement & Investigation Staff B1/03/23 ip. 07948.083

### V. Operator Exeminations

- 8103110669 Advises of compliance w/min senior operator staffing requirements by Jul 1782 Assistance station shift supervisors will be upgraded Training will begin in mid-1981 for licensing by July 1782 LEMP0EB.TE Niagera Hohawk Power Corp 81/03/03. 2pp. 07885-051
- B103310939 Forwards training program outline scheduled for Bpring 1981 refueling outage Program satisfies requirements of NUREG-0737. Item 11 8.4 re training for mittigating core damage. Program will be completed by 811001.
  DISE-D P Niagara Mohawk Power Corp 81/03/25 7pp. 08059:190



CUCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

5 Reportable occurrences. LERS & related correspondence

0103060235 RO on 810130, emergency generator failed to maintain proper operating voltage & generator cycled radically Caused by Improperly positiohed voltage regulator manual-auto switch Harning label added to panel LALLACE, T. J. Lawell. Univ of 81/02/09 2m 07839 306

GCCKET 90-224 UNIV OF CALIFORNIA RESEARCH REACTOR

Q Inspection reports. 16 Bulletins & correspondence

B103020012 Forwards IE Circular B1-02. "Performance of NRC-Licensed Individuals While on Duty." No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director B1/02/09 Ip 07787-184

DUCKET 50-225 RP1 CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

G103230808 Advises that 791119 1tr re inadvertent wafety injection during surveillance testing adequately addresses NRC concerns Matter is resolved CRUICHFIELD.D. Operating Reactors Dranch 5 81/02/24 2pp 07976:345

R. Periodic operating reports & related correspondence

8103190572 Bubmits annual rept of tests & experiments for 800301-810301. Facility was utilized for graduate course on reactor esperiments, summer course on reactor design & project work to satisfy degree requirements

NELSON.P.R. Reneseleer Polytechnic Inst 81/03/01 2pp
07999 119

DCCKET 30-228 AEROTEST RADIOGRAPhy & RESEARCH REACTOR
F. Security, medical, energency & fire protection plans

Bi03300071 Forwards revised physical security plan for info only Plan withheld (ref 100f8.790) MEWACHECK.R.L. Aerotest Operations 81/03/23 in 08053 053

Q Inspection reports. IE Bulletins & correspondence

8103020028 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required ENGELKEN R H Region 5. San Francisco, Office of the Director 81/02/09. 1p. 07787:219.

DOCKET 50-237 DREBDEN NUCLEAR POWER STATION, UNIT 2
F. Security, medical, emergency & fire protection plans

8101080051 Releases public version of util draft emergency plan. MUREO-0654 info encl. FELTON-J.H. Division of Rules and Records 80/12/02 18pp. 07416-038.

--B101230543 Forwards public version of draft emergency plan for generating stations. PEDPLES.D.L. Commonwealth Edison Co. 80/04/24 3pp. 04837:169

~-Bi010B006B Public version of draft emergency plan for generating stations.

\* Commonwealth Edison Co. 80/07/31. 190pp. 07416.096.

BioloBoods Releases public version of util revised draft emergency plan. FELTOW J.M. Division of Rules and Records. 80/12/03 lp. 07417:001

--8101220259 Forwards public version of util revised draft emergency plan W/station annexes.
PEOPLES.D.L. Commonwealth Edison Co. 80/06/04, 2pp. 05370:005

--BI010B0019 Public version of Revision 1 to draft emergency plan.
• Commonwealth Edison Co 80/07/31. 139pp. 07417:051.

--8101080033 Public version of draft emergency plan annex \* Commonwealth Edison Co 80/07/31 52pp 07417 242

8103100646 Forwards evaluation of previously unresolved items & in of current status of items identified as requiring action during fire protection review IPPOLITO T A Operating Reactors Branch 2 81/02/17 Spp 07863 014

BiO3180264 Ltr to all power reactor licensees u/plants licensed pr to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance u/801119 fire protection rule EISENHUT.D O Division of Licensin; Bi/02/20 13pp

B103310338 Ltr to all licensees of operating plants & holders of C forwarding NUREO-0896. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/o encl EISENNOT.D G. Division of Licensing. 81/03/05. opp

8103260123 Concure w/601217 request to install two-way headset jac specified emergency notification sys 5 health physics telephones provided that use will be discontinued if communications quality unacceptably degraded KEPPLER. J. G. Region 3. Chicago. Office of the Director 81/03/10 30042 127

--B103260137 Submits lucation for installation of one-way headed on emergency notification sys & health physics network per B01119 request Requests concurrence by B10201 RAUSCH.T J Commonwealth Edison Co. 80/12/17 2pp. 08042 [

BiO3250689 Releases public version of implementing procedures for emergency plan FELTON-J M Division of Rules and Records 81/03/19 ip 07806 001

--B103250672 Forwards public version of emergency plan implementin procedures for corporate command ctrenviron director & plant-specific procedures

DELOEOROEL D Commonwealth Edison Co B1/02/27 2pp 07606 001

O Adjudicatory correspondence

9103120022 Forwards order for license rod requiring licensee to de autometic dump sys to be independent of air pressure instrumentation for manual scram. Action would assure safe operation of BURs w/inadequate hydraulic coupling CRUICHFIELD D Operating Reactors Branch 5. 81/01/09 2pp 07906.352

--BIO3120029 Order for license mod requiring licenses to design as dump sys to be independent of air pressure instrumentation for manual scram
EIBENNUT.D O Division of Licensing B1/01/09. 6pp 07906

B101300233 Forwards NRC B10113 orders for mod of licenses & grantiextension of exemption. Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 80 IPPOLITO. T.A. Operating Reactors Branch 2 B1/01/13 3pp

--Bi01300244 Order modifying license & granting extension of exemp Licensee must reassess suppression pool hydrodynemic loads & complete mods to meet General Design Criterion 90 by B30131 E15ENHUT-D.G Division of Licensing. B1/01/13 7pp 07582

B103090704 Informs of error in Ragan supplemental testimony refuel channel blowing to be corrected formally at hearings. Applicant does not object to NRC proposed findings of fact & no formal reply will be filed.

STEPTOE

8103100339 Forwards 810225 notice of finelity of Commission action wiregerd to generic FES on handling & storage of spent light water power reactor fuel (NUREG-0575)
GDDDARDLR.J. Hearing Branch 2. 81703706 3pp. 07864-222

- 8103180379 For arts PM O'Connon 810313 affidavit & 810312 menoluf Stell 810210 menolu Khisal 810226 menolt/WREG-0612 generic Etro of 801222 & 810203 NUREG-0606 Vol 3 Number 1. SECV-80-325, SU Chill 801224 meno & MU Kurray meno GODDAMDLR U Hearing Branch 2 81703713 2pp 07745 347
- \*\*-B1031B037B lightifies 21 unresolved safety issues relevant to spent fuel pool tool for facility gradition given. B1/03/12 app applies and
- --B1030902)& Responds to ASLE B10127 membrandum & order re safety relevance of generic unresolved Bafety Issue A-17 on Mys interaction Lytespect to spent fuel pool mod Mod will not increase vulnerability of plant SIOUZJF Systems Interaction Branch B1/02/10 pp
- ~-BiggiBO920 UPRESOLVED SAFETY (SSUES SUMMARY Data as of February 13. 1981 (Aqua Coot) • Internal Information Systems Branch NUREO-0606 v03 NOI B1/02/28 Sipp Available at NTIS 0/945,358
- --B103180932 Requests Commission approval of unresolved safety issues for reporting to Congress in accordance w/1979 ASC annual rept commitment Results of systematic review of candidate issues encl DENTON. H. B. Office of Nuclear Reactor Regulation. Director SECY-80-325 60/08/09 97pp 07945 359
- --8103180943 Informs that Commission has approved only listed new unresolved safety issues per SECY-80-325 Oilinsty would have included steam line break w/s-all LOCA NRC to prepare revised rept to discuss each unresolved safety issue GHLK-5 U Office of the Secretary of the Commission 80/12/24 2ap 97946 094
- --8103160958 Discusses screening/selection criteria for unresolved safety issues issue screened out if initial screening criteria in SECY-80-329 are met Lists questions issues should address for consideration

  HARRAHAM, E. J. Uffice of Policy Evaluations 80/11/20 13pp
  07946-096
- --8103180967 Provides list of generic technical issues as requested MURRAY.N J lilinois, State of 81/03/13, 3pp 07946; 697
- B103260792 Forwards RE Hubbard B10317 affidavit outlining unresolved safety issues relevant to spent fuel mod proceeding. Certificate of Svc encl MVRRAV-M J #111nois- State of 81/03/17 2pp 08036 153
- --8103260800 Affidavit identifying 34 generic unresolved safety issues & generic TRI issues & describing why issues ray impact public health A safety Prof qualifications enc!
  HUBBARD. 9 E MMB Technical Associates 81/03/17 35pp 08036 155
- 9100270700 Notice of further hearings on proposed amend to facility OL re spent fuel pool mod HOLF, J.F. Atomic Safety and Licensing Board Panel 81/03/17 2pp. 08042 342.
- I Financial information
- 8103310613 Forwards guarantoe of payment of deferred promitors for 1981 per NRC request
  OSTER, J. Componwealth Edison Co. 81/03/27 (p.
- ~-8103310620 Forwards Annual Rept for CY80 & statement of internal cash flow projected for 1981 & actual for 1983 per provisions of 10CFR140.Chapter 1. Section 140 21 & 1920 770615 for NEXON.H H Commonwealth Edison Co. 81703/27 Spp
- J Insurance & Indemnity information
- P. Operating license stage documents & correspondence
- B103050359 Forwards requests for add1 info re SEP Topic VI-7 A.3 concerning ECCS test capabilities.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 80/12/15 3pp 67/72-114

- 8103197732 Line to all licensees of operating plants applicants for Obe & noicers of CPs re control of heavy loads Requests review per guidelines in NURG-0612 Forwards NRC position re interior actions & request for addl info resemble. Do O Division of Licensing 89/12/22 30op
- 8103053168 Forwards Amend 53 to License DAR-19, safety evaluation & notice of issuance & availability CRUTCHFIELD.D Operating Reactors Branch 5 80/12/30 2pp. 07895-174
- --B103050173 Arend 53 to License BPR-19 extending date for compliance U/803221 confirmatory order to 810104 CRUTCHFIELD. D (Sperating Reactors Branch 5 80/12/30 2pp 07825-176
- --BIO3050176 Safety evaluation supporting Amend 53 to License DPN-19

   Office of Nuclear Reactor Regulation, Director 80/12/30. 3pp
  07839-178
- --B103050185 Notice of issuance & availability of Amend 53 to Liconse EPR-19 CRUICHFIELD, D Uperating Reactors Branch 5 80/12/30 2pp 07825 181
- 8103060285 Advises that 761028 request to amend Tech Specs to authorize operation J/one automatic depressurization valve out of suc for up to 30 days is no longer under active review & is considered withdrawn CRUTCHFIELD. Operating Reactors Branch 5 81/01/08 Rpp 07836 359
- 8103120022 Forwards order for license mod requiring licensee to design automatic dump sys to be independent of air pressure instrumentation for manual scram Action would assure safe operation of BLRs w/inadequate hydraulic coupling CRUTCHFIELD.0 Operating Reactors Branch 5. 81/01/09 2pp. 07906-332
- --Bi03120029 Order for license and requiring licenses to design submat dum; sys to be independent of air pressure instrumentation for manual scrae.

  EIESTAUL, D. G. Division of Licensing Bi/Ol/09 App. 07906-034
- Bi01300233 Forwards NRC 810113 orders for mod of licenses & granting extension of elemption. Licenses must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 30 1990LTD. T.A. Operating Reactors Branch 2 81/01/13, 3pp.
- ~-8101330244 Green modifying license % granting extension of exemption Licenses must reassess suppression pool hydrodynamic loads % complete mods to meet General Design Criterion 5D by 830131. EISEMMUT.D Q Division of Licensing 81/01/13 7pp. 07882 148
- --8101300259 Order modifying litense & granting extension of examption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterian 50 by 821231. EIBENHUT.D 0. Division of Licensing. 81/01/13. 7pp 07502 162
- --Biol 300267 Order modifying license & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to neet Conerel Design Criterion 50 by B21231. EISEGUID.D O Division of Licensing. 81/01/13 7pp. 07582 160
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown-replacement parts & NUREG-0737.
  EISENHUTID O Division of Licensing. 81/01/19. dpp.
- 8103240290 Ltr to all BMR licensees forwarding Suppl 1 to generic safety evaluation on BMR scena discharge sys. Summarties re-evaluation of interin measures recommended per S01201 safety evaluation Electivity. D Q Division of Licensing. 81/01/23. 2pp.
- 8103120014 Lit to all likensees of operating plants.CP holders & QL applicants.escept indian Point 2 & 3.2 ton 1 & 2 & TMI-1, forwarding inadvertently united pages from NRC 801222 request for add info re control of heavy loads. EIBENNUT.D Q. Division of Licensing. 81/02/03. App.
- 8103180854 Forwards Amends 33.56 & 49 to Licenses DPR-2,DPR-19 & DPR-25.respectively & notice of issuance & availability CRUICHFIELD. D Decrating Reactors Branch 5. 81/02/11. 3pp. 07953-217

### DOCKETED ITEMS

- --R103180B51 Amends 33.55 & 49 to Licenses DPR-2. DPR-19 & DPR-25, respectively, adding requirement to maintain guard training & qualification plan to be implemented within 60 days Security personnel to be qualified within 2 yrs CRUICHFIELD. D. Operating Reactors Branch 5 IPPCLITO.T A Operating Reactors Branch 2 81/02/11 App 07953 220
- --BIO31B0B71 Notice of issuance & availability of Amends 33,56 & 49 to Licenses DPR-2.DPR-19 & DPR-25, respectively CRUICHFIELD.D Operating Reactors Branch 5 B1/02/11 2pp 07943-22A
- 8103060436 Forwards "Environ Qualification of Safety-Related Electrical Equipment," partial review Unitten response required, LAINAS.Q.C Assistant Director for Safety Assessment 81/02/13 3pp. 07835 280
- --gg/3060447 "Environ Qualification of Safety-Related Electrical Equipment," partial review w Office of Nuclear Reactor Regulation, Director 81/02/13 18pp 07835 253
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be ret EISENHUT.D.O. Division of Licensing 81/02/18 12pp
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 XEPPLER. J O Rugion 3. Chicago, Office of the Director 81/02/20 200. 07865 219
- 8(03250024 Ltr to all power reactor licensees & license applicants re AUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D.O Division of Licensing. 81/02/20 Bpp
- BIO3020487 Forwards revised pages to BIO128 proposed amond of License DPR-19.Changing Tech Spoce to allow implementation of future reloads per IOCFRSO 59
  AANCEEKAR F Corronwealth Edison Co. BI/02/23 lp.
- --Bi03020489 Tech Spece 1.1.2 1.3.5 & 4.5 re safety limit, limiting safety ifnit, limiting safety sys setting, limiting condition for operation & surveillance requirement Table 3.2.3 for red black instrumentation & proposed App A encl a Commence of the C
- 8103060524 Requests remittance of Class 3 safety issue fee required by 801224 request for extension of 800221 confirmatory order retriculation pump trip installation.
  DIOGS, RM License Fee Management Branch. 81/02/24. 1p 07836:143
- BiO310063B Advises that some pages of BiO12B proposed amend to App A Tech Specs to License DPR-19 are illegible Reproducible actiginal copy of proposed Tech Spec changes should be submitted.

  O'CONNOR.P. W Operating Reactors Branch 5. B1/02/25 ip 07863:027
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for OLs (except St Lucis,Units I & 2). Requests util review to determine capability to mitigate station blathout event & promptly implement emergency procedures. EISENHUT.D.Q. Division of Licensing. 81/02/25. Spp
- B103100743 Discusses response to ABLB B10127 membrandum & order respent fuel pool and applicability to generic unresolved safety issues Control of heavy loads near spent fuel & seismic design criteria should be addressed.

  KNIEL-K Generic Issues Branch. 81/02/26. 2pp 07865:316
- 9103110192 Submits info re safety relevance, if any of various generic unresolved safety issues under continuing study to proposed spent fuel pool mods per BiOI27 ABLO memorandum & order. KNIEL-K. Cameric Issues Branch. BI/O2/26 2pp. 07884.297.
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping-sefe ands & fitting math per guidelines of encl Revision I to NUREQ-0313 Model Tech Specs only encl. EISENHUT, D G. Division of Licensing. 81/02/26. 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ASME Code Class 1.2 & 3

- 8103230813 Generic Ltr 81-05 to all CP holders & OL applicants re ICCFRSO 71(e). 'Periodic Updating of FSARs.' effective BOO722 Info re FSAR legal status format & content oncl El365HUT. D O Division of Licensing 81/02/26 logs
- 8103030860 Forwards status summary for NUREG-0737 Items to which ut committed to respond by 810301 Long-term program under intensive Internal review Program will be submitted by 810316
  810316
  8BELUS Commonwealth Edison Co
- 8103050198 Forwards add1 info re containment purge & vent valve operability. In response to NRC 801202 ltr JANECEK.R F Cormonwealth Edison Co. 81/02/27 20pp
- B103090658 Responds to NRC B10213 ltr providing list of potential equipment deficiencies identified in NRC review of safety-related electrical equipment Util will respond to deficiencies when NRC identifies basis for each ABCL, JS Commonwealth Edison Co. B1/03/02 2pp. 07848-259
- 8103130407 Advises that add1 clarification on ltows 1.5.9a-b & 10 / EEP Topics 111-b & 11 re-seismic design consideration & component integrity per 910130 request will be provided by H10313 JANECEK, R. F. Commonwealth Edison Co. 81/03/03 lp. 07907-068
- BiO3120548 Forwards Class II application fee re request for extension of confirmatory order in response to NRC BiO224 request JAPIEZEK, R. F. Commonwealth Edison Co. Bi/O3/06 pp. 07901 234
- --BIO3120590 Ack receipt of application fee for facility re util BIO request
  DIOGER License Fee Management Branch B1/03/10 Ip
  37901 235.
- 8103310804 Ltr to all licensees of operating plants applicants for C & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISERHULB 3 Division of Licensing 81/03/10 6sp
- 8103130505 Forwards evaluations of EEP Topic VI-7 C 1.App K.re electrical.instrumentation & control re-reviews & Topic VII-3 re safe shutdown sys Requests differences between as-built facility & licensing basis within 30 days CRUTCHFIELD, D Operating Reactors Branch 5 81/03/11 44pp. 07911.293.
- 8)03180817 Informs NRC that util will continue to require full radiation training for NRC personnel entering radiation areas at facilities, pending further IRRC communications. TRANM, T R Commonwealth Edison Co. 81/03/11.
- B1031B0531 Forwards procedures for BEP Topics V-10.B.V-11.B.VII-3 & IX-3 re safe shutdown & control room evacuation Also forwards one oversize drawing Aperture card is available in PDR JANACEK, R.F. Commonwealth Edison Co. 81/03/12 2pp 07965-341.
- --B103180542 Revision 9 to "Unit 2/3 Normal Unit Shutdown." \* Commanwealth Edison Co. B0/07/31. [ipp. 07965-343
- --BIO3180851 Revision 7 to "Unit 2/3 Shutdown From Power Operation 6 Standby."

  # Commonwealth Edison Co 80/07/31. 10pp. 07965.354.
- --8103180363 "Control Roon Evacuation/Bafe Shutdown," (Primary Responsibility-Operations Director ) > Commonwealth Edison Co. 80/07/31 11pp. 07966-001
- B103180745 Responds to 810130 ltr re review of E00-EA-5065. "Summary of Dresden Unit 2 Piping Calculation." Comments will be submitted by 810424. JANECEK.R.F. Commonwealth Edison Co. 81/03/13 3pp 07954-101
- 8103200351 Forwards revised abstract & Pages 2-2,4-2,4-5,7-2 & 18-2 CE-1-A, Revision 16 re GA program Revisions reflect ABME winter addenda code changes changes made per ASME survey & clarifications & corrections
- TRAMM.T R. Commonweelth Edison Co 81/03/16 lp. 07971:038
  --B103200369 Revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of Rev
- 16 to GA program

  \* Commonwealth Edison Co CE-1-A R16 B1/03/16 6pp
  07971:039

- BIO3230799 Forwards responses to NAC question re adequaty of station electrical distribution sys voltages Revised table showing auxiliary power bus voltages when unit heserve auxiliary transformer is carrying shutdown load enci.
  INARCEAR F Commenceals Edison Co. 81/03/18 350 07975 325
- 8103200383 Notifies that NPC 800217 itr re SEP Topics VI-7 A 3.VI-10 A 5.VII-2 reviewed 5 found acceptable Areas covered included ECCS actuation sys 5 testing of reactor trip sys 5 engineered safety features assets. RF Companyealth Edison Co. 81/03/18 19 08057 243
- @100240198 Requests clarification of constraints placed on BMR fuel exposures of BOI112 SER Requirement in conflict urgeneric fRC approval of operation received by GE in Nov 1980 ltr Util assimas previous commitment no longer applicable JANECEAR F Commonwealth Edison Co. 81/03/19 2pp 07990 342
- 9 Inspectson reports, IE Bulletine & correspondence
- 0103240711 Responds to Suppl 3 of 1E Bulletin 79-01B. 'Environ Obalification of Class If Equipment' Suppliers have been contacted to provide qualification of acoustic monitors on relief & safety valves
  ABELJ 5 Coronapalth Edison Co 81/02/02 3pp 07989:212
- 8:03:30:227 Forwards IE Inst Repts 50-0:0/80-23.50-237/80-25 & 53-249/80-30 on 80:115-1231 & notice of violation WithWith F Region 3. Chicago. Reactor Operations Nuclear Support Stanch 81/02/03 2pp 079:2-193
- --8103130233 Natice of violation from insp on 801115-1231 HEISHMAN R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 81/02/03 ip 07912 199
- --8103130245 IE Inst Repts 50-010/80-23.50-207/80-25 % 50-249/80-30 on E01115-1231 Moncompliance noted pressure regulator setpoint below reactor pressure furing startum resulting in reactor scran TONGUE.T M. REIMANN.F W. JCRDAN.H J. Region J. Chicago. Office of the Director 81/02/02 10pp 07912 196
- B103020115 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Outy," No written response required MEPPLER, J.) Region 3. Chicago. Office of the Director 81/02/09 250 07768 020
- 8103200044 Forwards sinfo re ultratonic test scram discharge vol continuous constoring sye in response to 18 Bulletin 80-17. Suppl 4 M/c arci. RAUSCHT J. Commonwealth Edison Co. 81/02/11 2pp 07968.190
- 8103200284 Forwards technical info.updating 810202 response to IE Bulletin 80-17-Supp 4, "Failure of Control Rods to Insert During Scram at BMR " M/o encl RAUSCH.T J Commonwealth Edison Co 81/02/11. 2pp. 07971 155
- B103040251 Forwards IE Info Notice B1-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/1007850 72" No written response required KEPPLER. J & Region 3. Chicago. Office of the Director B1/02/12 2no 07813 283
- 8103030302 Forwards Suppl 5 to 1E Bulletin 80-17. "Failure of Control Rods to Insert During Scram at 848." No written response required.

  KEPPLER J. O. Region 3. Chicago: Office of the Director 81/02/13 2nn 07793 357
- B103260044 Forwards IE Insp Rept 30-237/B1-01 on B10106-07.14-15 & 22 No noncompliance noted F10RELL1.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch B1/02/13 2pp 08041 211
- --8103260051 IE linsp Rept 3D-237/B1-01 on Bi0106-07.14-15 & 22 No noncompliance noted Major areas inspected; inservice inspectagement review, procedure review observation of activities & review of exam documentation KEY, M. J. Region 3. Chicago, Office of the Director DANIELSON, D. M. Region 3. Chicago, Reactor Construction & Engineering Support Branch 81/02/12 7pp 08041:213

- --BIO3060049 Order imposing civil panelty in amount of 340,000 for for noncompliance noted in IE insp on BOSBOB re apprature observed by resident inspector to be esteep. Evaluation of licensee response encl BTELLO, V Director's Office. Office of Inspection and Enforcement BIO22/23 10pp 07639 242
- 8103060455 Ack receipt of 801218 & 810203 ltrs informing NRC of steps taken to correct violations noted in 1E Inep Ropts 50-010/80-21:50-237/80-23 & 50-249/80-27 FISHER.W L Region 3. Chicajo. Fuel Facility & Materials Safety Branch 81/02/23 lp 07837 231.
- --BIO3060465 Supplemental response to NRC 801125 ltr re violations noted in IE Imap Repts 50-010/80-21,50-237/80-23 & 50-249/80-27 Corrective actions log established to be filled out by vendor representative when collecting environ samples. ABELJ 5 Commonwealth Edison Co. 81/02/03: 1p. 07837 232.
- --Biggo604B1 Responds to NRC 801125 ltr re-violations noted in IE Insp Repts 50-010780-21.50-237780-23 % 50-249780-27 Corrective actions preparing ltr to vendor reinforcing need for strict compliance w/radiological environ monitoring program ABEL-J B Commonwealth Edison Co. 80/12/18 2pp 07837 233
- B103160373 Forwards monthly status rept re evaluations purformed in response to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Rolated Piping Bys." Tables listing excessive pipe stresses end.
  JANECEK.R F. Commonwealth Edison Co. 81/02/23 1p 07916-186.
- B103160494 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation" No response required. \*\*XEPPLER.J G Region 3. Chicago, Office of the Director 81/03/02 2pg 97915 308
- B10317037! Responds to IR Bulletin B1-01. "Burveillance of Mechanical Snubbers ' No Nuclear Bafeguards Corp snubbers have been installed or uill be installed on safety-related sys JANECEK.R F Commonwealth Edison Co. 81/03/02 20p 07925 250.
- 8103160094 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements KEPPLER. J © Region 3. Chicago. Office of the Director 81/03/04 1p 07915 065
- 8103200394 Forwards 1E info Notice 81-06, "Failure of ITE Model K-600 Circuit Breaker," No response required, MEPPLER, J.9. Region 3, Chicago, Office of the Director 81/03/81, 2pp. 07972 193
- 8103200695 Forwards 1E Info Notice 81-05, "Degraded DC Bys at Paliades" No action required MEPPLER.J O Region 3. Chicago. Office of the Director 81/03/13 200 07964.133
- 8103200269 Forwards IE Info Notice Bi-07, "Potential Problem W/Water-Boluble Purge Dem Matts Used During Inert Cas Weiding." No response required KEPPLER.J @. Region 3, Chicago, Office of the Director. Bi/03/16. 20p. 07966
- BiO3261193 Responds to IE Bulletin 80-25, "Operating Problems W/Target Rot! Safety Relief Valves at BWRs " Engineering review of LaSaile safety relief valve pneumatic supply sys still in progress Mode will be completed prior to fuel loading. RAUSCH.T. J. Commonwealth Edison Co. 81/03/19. 7pp. 08040.252.
- BiO3270484 Confirms info in 800610 response to IE Bulletin 80~06, "Engineered Bafety Feature (ESF) Reset Controls," Valves 2301-64.65.27 % 30 close on HPCI sys initiation HPCI auxiliary oil pump will not deplete power source.

  JANECEK.R F. Commonwealth Edison Co. 81/03/20. 4pp 08046-221
- R. Periodic operating reports & related correspondence
- B103020369 Forwards semiannual rept re-radioactive offluent discharges & solid radioactive waste for Jul-Dec 1980 SCOTT.D.J. Commonwealth Edison Co. 81/02/06. 1p. 07784.234
- --8103020374 Semiannual rept to redirective effluent discharges & solid radioactive waste for Jul-Dec 1980 . 60-mnonwealth Edison Co. 81/02/06. 1500. 07784-235



- 8103030792 Forwards occupational radiation exposures rept for 1980 BITEL.J S Commonwealth Edison Co 81/02/25 ip 07795 055
- --8103030807 Occupational radiation exposures rept for 1980

   Corroquealth Edison Co 81/02/29 3pp 07795 096
- 8:03130353 Forwards monthly operating repts for Feb 1981 SCOTT.D.J. Commanwealth Edison Co. 81/03/03 ip 07911 121
- --8103130358 Monthly operating cepts for Feb 1981.
  MAXWELL, D. C. Commonwealth Edison Co. 81/03/03 17pp 07911 122
- 8103240348 Forwards "Annual Operating Rept for 1980" 500TT.D J Commonwealth Edison Co 81/03/11 12 07987 189
- --8103240353 "Annual Operating Rept for 1980."
  e Commonwealth Edison Co. 81/03/11 23pp 07987.186
- S. Reportable occurrences, LERs & related correspondence
- 8:03030942 PND-111-80-229 on 801211.unit manually tripped following hi-hi alarm from scram discharge vol continuous monitoring sys Caused by water leading into 8DV during maint on control rod drive hydraulic control unit 18-11 Drawing encl REIMANN.F. 80yD.D.C. HEIBHMAN.R.F. Region 3. Chicago. Office of the Director. 80/12/11 3pp 07795 242
- 8103110694 Forwards LER 80-044/03X-1 SCOTT.D J Commonwealth Edison Co. 81/02/06 1p. 07887 099.
- ~-Bi03110701 LER 80-044/03X-1 on B01124 target rock safety relief valve 2A inoperable pressure alarm annunclated indicating inoperability of target rock in safety mode Caused by shorted & grounded bellows leak pressure switch greRDFF.R Commonwealth Edison Co 81/02/25 3pp 07887 100
- B103170580 Forwards LER 79-017/01X-3 BC0TT-D J Commonwealth Edison Co. B1/02/06 2pp. 07935:329.
- --8103170587 LER 79-017/01X-3 on 790327.containment isolation valves A0-2-1600;-23.24.60.61.62 & 63 leakage exceeded Tech Specilimits. Caused by leaking valve shaft seals 1601-23 & 24 Valve 1601-24 replaced & shaft seals on 1601-23 & 60 fixed. FIRMAS.K. Commonwealth Edison Co. 81/02/19 3pp. 07935-330
- 8103030779 Forwards LER 81-009/03L-0 8COTT,D J. Commonwealth Edison Co. 81/02/26 Ip. 07797:352
- --Bi03030783 LER 81-009/03L-0 on Bi0129, reactor protection sys 28 M-0 set output breaker failed to trip. Caused by stuck trip mechanism on breaker probably due to dirt buildup or inadequate lubrication. Breaker replaced. BADER-8. Commonwealth Edison Co. 81/02/26. lp. 07797-393
- 8103170543 Forwards LER 81-010/01T-0 ECDITID.J. Commonwealth Edison Co. 81/03/09. 1p. 07929:180.
- --8103170548 LER 81-010/01T-0: on 810218 during refueling outage, snubbers at drywell locations 4.8.32.33 & 29 failed bench test. Caused by rough handling at location 4 & by environ conditions in drywell at other locations Snubbers replaced.

  6PEROFF. R. Commonwealth Edison Co. 81/03/10. 5pp. 07925.181.
- 8103180618 Forwards LER 81-013/017-0. SCOTT.D.J. Commonwealth Edison Co. 81/03/13. Ip. 07947:282.
- --BIO3180823 LER 81-013/017-0: on BIO302 engineering evaluation revealed that HPC1 piping dose not meet FBAR seismic requirements. Caused by as-built configurations not reflecting as-designed configuration. Beismic restraints will be installed. ZIRMAB.K. Componwealth Edison Co. 81/03/13. 2pp. 07947:283
- 8103240387 PND-111-81-032: info pickets set up at facility gate by operating engineers Local 150 AFL-CIO against McCarten & McCollen. Inc Pickets established because contractor does not have operating engineers on site.
  TONQUEIT. REIMANN.F. KNDP.R. Region 3, Chicago, Office of the Director. 81/03/16 pp. 07987: 254.
- T Hearing transcripts on non-antitrust matters
- B103230014 Forwards HK Shaw supplemental testimony on spent fuel essembly channel bowing. Discusses 810313 conference call re-ASLB Question 2 & related testimony.

  GDDDARD.R.J. Hearing Branch 2 81/03/23. 1p. 07998-028.

- --BI03250922 Supplemental testimony on spent fuel assembly channel bouing Concern re interference developed between walls of fuel assemblies & storage locations within proposed spent fuel racis is not safety problem W/prof qualifications.

  5MAM.H N. Operating Reactors Assessment Branch 81/03/23 Sp. 07988 329
- V Operator Examinations
- BIO3030769 Forwards supplemental info re shift technical advisor training per NUREG-0737. Item I A 1 1 (3) Info includes response to training requirements for shift control room engineers & projected schedule for training completion.

  ABEL. J B Commonwealth Edison Co B1/02/24 App 07796 085
- 8103090140 Forwards list of shift control room engineers meeting training & education requirements by dates indicated Many engineers completed training by 810101 Target date for completion of training is mif-1931 ABEL. J S Commonwealth Edison Co 81/02/24 4pp 07821 324
- 8103200574 Forwards supplemental info re long-term shift technical advisor program.including tandidate qualification.selection criteria, training plans & bases for phase-out of shift technical advisor program randated by NARGE-0737

  ABEL.J.8 Commonwealth Edison Co. 81/03/17 19pp 07972 084
- DOCKET 50-243 GREGON STATE UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8103040708 Application for amend to License R-106 requesting change organizational structure described in Tech Spec Section 6 1 WAND, C 11 SMITH C V Oregon State Univ 81/02/26 2pp 07810 041
- ---8103040710 Tech Spec Section 6.1 for administrative controls re organization • Oregon State Univ 81/02/26 Ip 07810 043
- Q. Inspection reports: IE Bulletins & correspondence
- 8103020016 Forwards 1E Circular 81-02, 'Performance of NRC-Licensed Individuals While on Duty " No written response required. ENUBLKEN,R H Region 5, San Francisco. Office of the Director 81/02/09 ip 07787:194
- R Periodic operating reports & related correspondence
- 8103230500 Forwards "Rept of Personnel Whole Body Exposures for CYE WARD, C. H. Oregon State Univ. 01/03/13 1p. 07975 287
- --8103230507 "Rept of Personnel Whole Body Exposures for CY80."

  # Gregon State Univ 81/03/13 ip 07975 288
- DOCKET 50-244 ROBERT EMMEY OF NA NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 8103090706 Forwards Suppl 1 to 790214 fire protection safety evaluation Proposed mode are acceptable. Dedicated shutdown says must be installed within 3 months of NRC approval. CRUTCHFIELD. D Operating Reactors Brench 5.
- --8103090712 Suppl 1 to safety evaluation supporting fire protection mods.

  \* Office of Nuclear Reactor Regulation, Director. 80/12/17.
- 8103040110 Forwards facility emergency planning info W/o 8101290589 BOUDER, J. L. Division of Rules and Records. 81/02/12. Ip. 07819-325.
- 8103060138 Requests Class III fee for review of B10126 application extension to complete fire protection features Installation D1008.R.M. License Fee Management Branch. 81/02/18. Ip 07839:049.
- 8103180264 Ltr to all power reactor licensees w/plants licensed proto 790101. Forwards NRC position & request for addlinfo resease shutdown capability for compliance w/801119 fire protection rule.
  ETSENHUT, D. O. Division of Licensing. 81/02/20. 13pp.

- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NJREG-C696. Functional Criteria for Energency Hesponse Facilities 'Criteria describe acceptable method for meeting NRC requirements N/o encl ELSE/NYJF.D 0 Division of Licensino 81/03/05 620
- 8103200575 Describes plens to provide additfireproofing of structural steel near tyrkine lube oil reservoir & mear screen house & turbine blig, per fire protection safety evaluation Item 3 2 8

  MAIER J. E. Rochester Gas & Electric Corp. 81/03/16 ip. 079AG CEN
- 8103270709 Forwards fee for review & approved of extension of time for completion of installation of operain fire protection features in response to 810218 ltr MAIER J E Rochester Gas & Electric Corp 88/03/16 2pp 08047 100
- 8103200997 Forwards "Bafc-ShutJoun Capability Assessment & Profosed Mods ICCFP50.App R Ginna Unit 1." per revised MSC critteria Review of fine protection items should include integrated approach MIER.JE Rochester Gas & Electric Corp. 81/03/19. 2pp 07928 114
- --8103200598 'Gafe-Shutdown Capability Assessment & Proposed Mode-IOCFRBO. App R -- Olinna Unit 1 " • Rochester Oas & Electric Corp 81/03/31 66ss 07968 [16
- H General correspondence

2**10** 1

- 8103030816 Hotifies of change of mailing address for indemnity fee invoices, arends & other math re indemnsty Agreement 8-38 invoice for 810320-52 fee received & will be paid MUSBIELR R Roccester Gas & Electric Corp. 81/02/26. Ip 07795 176
- J. Insurance & indemnity information
- 8103200423 Forwards Endorsement 5 to NELIA Binder EB-14 & MAELU Binder XB-14 KUSSIE.R F Rockester Cas & Electric Corp. 81/03/16 3pp 07971 2A9
- P Operating license stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NJREG-0612 Forwards NRC position reliatorism actions & request for addlinfo. EISEN:NUT.D D. Division of Licensing 80/12/22. 30pp
- B103040B62 Approves B01106 request for withholding of technical info re planned sleeving of steam generator tubes, ser 100FR2, 790 (RUTCHFIELD, D. Operating Reactors Branch 5 80/12/30 3pp. 07985 001
- B103190387 Lit to all licensees of operating plants & applicants for OLS & holders of CPS re-program for environ qualification of sefety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737.

  EISEMHUI, D. G. Division of Licensing. 81/01/19 669
- BIO3020110 Forwards safety evaluation for auxiliary feedwater sys Requests discussion re open items in evaluation CRUICHFIELD.D. Operating Reactors Branch 5 B1/01/29, 2pp 07784-34R
- --Bi03020116 Safety evaluation for auxiliary feedwater sys • Operating Reactors Branch 5. 81/01/29. 15pp. 07784:350
- 810312C014 Ltr to all licensees of operating plants, CP holders & CL applicants, except Indian Point 2 & 3. Zion L & 2 & TMI-1, forwarding inadvertently anitted pages from NRC 801222 request for add info re control of heavy loads EISECHHUI.D Q. Division of Licensing. 81/02/03 App.
- Bio3030983 Informs of review of 791107 itr re inadvertent safety injection during surveillance testing. Response acceptable Requests notification when administrative & callbr procedures re supervisor notification have been rodified CRUTCHFIELD. D. Operating Reactors Branch 5. B1/02/05 2pp 07795-037.

- 07784 273
- B103330160 Ltr to all operating PHR licensees requesting info on autiliary feedwater sys selsmic design Forwards request for aidl info sist of actions requested of licensees u/o seigmically qualified sys & results of NRC walkdowns. Effecting To. O. Division of Licenseng. B1/02/10 13pp
- 6103260400 Forwards "Environ Gualification of Safety-Related Electric Equipment," partial review Written response required LANAS. G C Assistant Director for Bafety Assessment 61/02/11 304 07932 224
- --BIO306040B 'Environ Qualification of Safety-Related Electrical Equipment, partial review • Office of Nuclear Reactor Regulation, Director 81/02/11 1869 07838 247
- 8103140669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A 1.2 re upgrade of erorgency support facilities. Requests confirmation within 45 days that implementation dates will be met EIGENHUT. D © Division of Licensing. 81/02/18 12pp
- 8103G41024 Notifies of fee refund re util 800409 application for organizational changes & of addl fee required for util 801103 application for Fech Space changes. Considering both factors, balance of payment must be remitted.

  HQLLOMAY.C. J. License Fee Management Branch 81/02/20 2PP 07820 077
- 8103230024 Ltr to all cower reactor licensees & license applicants rum. MREG-0619 criteria Footnote 2 in Table 2 contains error due to tackage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISEIMUT.D G Division of Licensing. 81/02/20 Spp
- 8103230817 Forwards request for add1 info re welding & nondestructive examples expenses requested within 60 days to complete review of Buppi 4. Revision 7 to OL application technical suppl CAUTCHFIELD.D. Operating Reactors Branch 5. 81/02/24. 3pp. 02924 782
- 8103293030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except Bi Lucie, Units 1 & 2) Requests util review to deterning capability to mitigate station blackout event 1 promptly implement amergency procedures. CISENHUT, D. 0. Division of Licensing. 81/02/23. 3pp
- 8103030784 Forwards listing of piping sys inside containment per NRC B10221 request.Listing contains each analysis line for AGHE Class 2 & 3 tys which are parts of selseic upgrade program Revision i of upgrade criteria document submitted B01104 MAIER.J E. Rochester Gas & Electric Corp. B1/02/27. 6pp 07/98.339.
- 8103090931 Corrects completion date noted in util 801222 rept re anchorage & support of safety-related electrical equipment. Final mode were completed on B10215 MAIER. J. E. Rochester Gee & Electric Corp. 81/02/27. 1p. 07848 160
- BiO3120279 Forwards request for additinfo on SEP Topic VI-07 B re engineered safety features switchover from importion to rectriviation modes. Response should be submitted within 30 days CRUTCHFIELD.D. Operating Reactors Branch 5. Bi/02/27. 3pp. 07906-3933
- 8103120305 Forwards final evaluation of SEP Topic V-II.A re (solation of high & low pressure sys & SEP Topic VI-7 C.1 re independence of redundant onsite power sys. CRUTCHFIELD D. Operating Reactors Branch S. 81/02/27. 18pp 0.7905-310
- Bi03090423 Forwards Revision 2 to GA program manual.App C re inservice pump 5 valve testing for 1981-90. Revision clarifies licensee 810130 submittal in reponse to NRC review comments. MAIER.J E. Rochester Gas & Electric Corp. B1/03/02. ip. 07848:150
- --B103090427 Revision 2 to QA program manual App C re inservice pump & valve testing for B10101-901231.
  ANDERSON.C.R Rochester Gas & Electric Corp. B1/02/01. App. 07848:151

- 8103160375 Informs that info requested in ARC 810113 itr re SEP Topic 111-1. "Classification." will be provided by 810630 Info has not been reviewed sufficiently MAIERJUE Rochester Oas & Electric Corp 81/03/02 ip 07865:198
- 8103100580 Forwards response to NRC 810112 questions re BEP Topic VI-4 re containment isolation (purge valve reset) Facility design does not allow containment isolation valves to open automatically after reset MAIER. J.E. Rochester Gas & Electric Corp. 81/03/02. 2pp. 67863-101
- 8103160255 Forwards Amend 36 to License DPR-18, safety evaluation & rotice of issuance & availability (RUTCHFIELD, D. Operating Reactors Branch 5 81/03/02 3pp. 67948 295
- --8103180262 Amend 36 to License DPR-10 authorizing Tech Epecs re min water level to be maintained above irradiated fuel assemblies during refueling operations CRUTCHFIELD, D. Operating Reactors Branch 5 81/03/02 14pp 07943-296
- --8103183269 Bafety evaluation supporting Amend 36 to License DPR-18

   Office of Nuclear Reactor Regulation, Director 81/03/02 2pp
- --8103180276 Notice of issuance & availability of Amend 36 to License DPR-18 CRUTCHF1ELD.D Operating Reactors Branch 5. 81/03/02 2pp 07943-314
- 8103100520 Responds to 810209 Itr re agreement between BEP owners group & BEP Branch. BEP III-4 A "Tectonic Province." SEP III-4.C "Historical Beisolicity Within 200 Miles of Plant" & SEP III.7.C will not be reviewed by 810630 MILER. J.E. Rochester Oas & Electric Corp. 81/03/02 ip. 07833 104.
- 6103100447 Forwards eight oversize drawings re containment sumps, per MC 801105 request Also forwards insulation info Aperture cerds in PDR.
  MAIER.J.E. Rochester Oas & Electric Corp. 81/03/04. Spp. 07853.001
- 8103110656 Forwards evaluation of 8EP Topic V-5. "Reactor Coolant Pressure Boundary Leakage Detection" Requests notification if facility differs from assumed licensing basis Evaluation is basis for safety assessment if no changes identified CRUTCHFIELD.D. Operating Reactors Branch 5 81/03/10. Spp 07882:897
- 6103310804 Ltr to all licensess of operating plants applicants for OLs b holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENRUT. 0.9. Division of Licensing. 81/09/10. 6pp.
- 9503570418 Describes plans for Cycle 11 fuel loading Cycle 11 operation does not constitute unreviewed safety question or require change in plant Tech Boccs.
  MAIER.J.E. Rochester Ges & Electric Corp. 81/03/11. 2pp. 07923:201
- 9:03:D1145 Forwards Amend 37 to License OPR-18 & notice of issuance & availability.
  CRUTCHFIELD.D. Operating Reactors Brench 5 81/03/11. 3pp. 07953.119.
- ~-BIO31BI150 Amend 37 to License DPR~IB.adding requirement to maintain safeguards contingency plan. Fully implemented within 30 days of Commission approval & reflecting security plan revised through 800910.

  CRUTCHFIELD.D. Operating Reactors Branch 5. BI/O3/II. 20p. 07953-1320
- ~-8103181153 Notice of issuance & availability of Amend 37 to Licence OPR-18. CRUTCHFIELD D. Operating Reactors Branch 5. 81/03/11. 2pp. 07983: 124.
- 8103170421 Forwards four architectural drawings for use in BEP review of Topic III-3.A re effects of high water level on structures, Aperture cards are available in PDR.
  MAIER. J. E. Rochester Gas & Electric Corp. 81/03/12. ip.
  07954: 285

- 8103250242 Advises that Westinghouse training to mitigate core d in response to Item II 3 4 of NUREG-0737.will not begin prior to Apr 1981 due to Westinghouse manpower shortage Training will be complete: by Oct 1981 MAIER. J E Rochester Gas & Electric Corp 81/03/13 1p 07907 274
- 8103200384 Responds to D0 Eisenhut 810220 Itr re compliance u/100 Plant dosign complies w/requirements of Section III J. energency lighting & Section III D. ail collection sys for reactor coolant pump MAIER. J E. Rachester Gas & Electric Corp. 81/03/16 ip 07972 103
- B103230697 Advises that SEP Topic III-4 8 re turbine missiles had made generic due to neu info issued by Westinghouse Previously issued assessment for facility is no longer valid CRUICHFIELD. D. Operating Reactors Branch 5 B1/03/16 4pp 07978: 307
- 8103260376 Surnary of B10219 neeting w/util & Oilbert Associates discuss capability of foct anchor sys for containment bidg at facility Wenci calculation tobles & charts SNAIDER.R P Operating Reactors Branch 5. 81/03/17 Spp
- --B103260387 Requests that Ofc of Nuclear Reactor Regulation eval containment tendon survailtance test results to determine need for add1 licensee action UGRDAN.E L. Office of Inspection & Enforcement, Office of th Director 79/11/30 4Bpp 08042 058
- B103230666 Requests summary of history of motor-operated valve performance at facility for NRC review of BEP Topic III-10 A re thermal-overload protection for motors of motor-operated valves
  CRUICHFIELD.D. Operating Reactors Branch 5 B1/03/18. 2pp. 72778 211
- B103260519 Bubmits currently scheduled completion dates for evaluate of certain items in SEP Topics III-6. "Beisnic Design Considerations" & III-11. "Component Integrity "
  MAIER. J E. Rechaster Oas & Electric Corp. 81/03/23. 1p
  08040-316
- G103300203 Responds to SEP Topic V-3, "RCPO Leak Detection " Over inclusion of Item 11 in Table I. Topic assessment should include refs which specifically denote bases for compliance w/current criteria MAjER.J. Rochester Oss & Electric Corp. 91/03/23 Ip. 08099
- 8103260571 Forwards 'Final SEP Technical Evaluation Topic VI-7 F. 'Accumulator (solation Valves Power & Control Bys Design'." submitted as page revisions to May 1980 draft CRUTCHFIELD.D Operating Reactors Branch 5 81/03/24 29p 08041.118
- --9103260580 "Final SEP Technical Evaluation Topic VI-7 F. 'Accur | Isolation Values Power & Control Bys Design'". • Operating Reactors Branch 5 81/03/31 2pp 08041 122
- 8103260611 Forwards SER for SEP Topic IV-2. "Reactivity Control 5 Including Functional Design & Protection Against Single Failures." Response requested within 30 days. CRUTCHFIELD.D. Operating Reactors Branch 5 81/03/24.
- --Bi03260621 Bafety evaluation for BEP Topic IV-2, "Reactivity Co Bys Including Functional Besign & Protection Against Single Failures." Concludes that General Design Criteria 28 satisfied re electrical failures within subj control sys. « Operating Reactors Branch 5, 81/03/24, 3pp. 08041:112.
- 8103310636 Forwards draft evaluation of SEP Topic III-3. A. Corment requested within 30 days of receipt of 1tr CRUTCHFIELD.D. Operating Reactors Branch 5. 81/03/24. days. 07586:001.
- Q. Inspection reports: IE Bulletins & correspondence
- 8103060197 Forwards supplemental info to response to IE Bulletin "Masonry Mall Design." Masonry well mode have been installed per drawings submitted on 801104 & drawings encl u/minor changes due to field interference.
  MAIER. J. E. Rochester Oas & Electric Corp. 81/01/30. 45pp. 07837.121.

- d103040182 Forwards IE Info Notice 81-03. "Checilist for Licensess Making Notifications of Significant Events in Accordance W/10CFR50 72 No unitten response required GRIER.B H. Region 1. Philadelphia. Office of the Director 81/02/12 pp. 07813-025
- B103200202 Forwards IE Info Notice 81-04. Cracking in Main Steam Lines 'Ny response required. GRIER B If Region I. Philadelphia. Office of the Director. B102/27 ip 07972 043
- 8)03200159 Forwards IE Circular 81-03. Inoperable Seismic Monitoring Instrumentation. No unitten response sequired CRIER.9. It Region is Philadelphia. Office of the Director. 81/03/02 ip 07968 262
- B103200353 Forwards revised 1E Bulletin 81-01. "Surveillance of Mechanical Shubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements GRIER.B H. Region 1. Philadelphia. Diffice of the Director. B1703704 1p. 07968 200
- 8103200133 Forwards IE Info Notice 81-05. "Failure of IIE Model X-600 Circuit Breaker" No response required SRIER.B H Region 1. Philaielphia. Office of the Director 81/03/11 1p. 07968 268
- S. Reportable occurrences, LERs & related correspondence
- 8103030813 Forwards LER 81-004/03%-0.
  MAIER J E Rochester Cas & Electric Corp 81/02/25. 1p
  02797 399
- --BIO3030B19 LER BI-004/03L-O on Bi0211 containment fan cooler unit C contensate dumps à sump A pumping rate increased during normal steady state operation Probably caused by galvanic reaction of carbon steel plug in copper motor cooler.

  EPECTOR. S. M. Rochester Oas & Electric Corp. BI/02/23 Lp. 202727 360
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION. UNIT 1
  F. Becurity, medical, emergency & fire protection plans
- B103020089 Forwards summary of staff requirements to resolve open items & FR notice re fire protection features Applicable provisions of B10217 App R discussed W/o encl ETBENHUT. B Q Division of Licensing B0/11/24, 6pp 07787 324
- B103040192 Requests response to encl comments re Aug 1979 guard training & qualification plan.
  CRUTCHFIELD.D. Operating Reactors Branch 5. 81/01/27 3pp.
- 8103180264 Ltr to all power reactor licensees u/plents licensed prior to 790101. Forwards NRC position & request for additing respects shutdown capability for compliance u/801119 fire protection rule.

  EISENHUT.D.Q Division of Licensing 81/02/20. 13pp.
- 8103100092 Requests that enci emergency planning info be rade publicly available N/o enci.
  SOUDER, J. L. Division of Rules and Records. 81/02/27. 1p. 07853:173
- B10331033B Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. U/o encl EISCUMPILO Q. Division of Licensing 81/03/05. Opp
- 8103230391 Requests exemptions to App R.fire protection requirements
  Disputes NRC conclusion that no addit costs will be incurred
  through compliance. Submits dedicated shutdown say
  description & analysis of implementation costs.
  CCUMSIL-M G. Northeast Nuclear Energy Co (subs of Northeast
  Utilities) 81/03/19 27pp 08022 182
- B103300360 Requests exemption from certain requirements of iOCFR30 App R & IOCFR30 48 re fire protection program Justification discusses SER open items, emergency lighting & evaluation of alternate & dedicated shutdown sys CDUNBIL:N G Connecticut Yankee Atomic Power Co. COUNBIL:N G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). BI/03/19. 28pp 08355-155.

### G Adjudicatory correspondence

- 8103040169 Forwards order for mod of license to assure safe operation of BHRs w/inadequate screm discharge vol instrument vol hydraulic coupling CRUTCHFIELD.D. Operating Reactors Branch 5 81/01/09 2pp 07912 328
- --GL)3049177 Order for mod of license re BMR scram discharge sys Recu prompt implementation of actions to assure safe operation w/invadequate scram discharge vol - instrument vol.hydraulic coupling ft15CANUT.D C Division of Licensing 81/01/09 6pp 07812 331
- 8103090033 Forwards order for mod of License CPR-21 & grant of exemption of exemption CRUTCHFIELD D Operating Reactors Branch 5 81/01/13 3pp. 07849 283
- --8103090039 Order for mod of license DPR-21 & grant of extension of exemption from General Design Criterion 90 License is anymodel to include assessment of suppression pool hydrodynamic loads
  ETBELHUT. D. G. Division of Licensing. 81/01/13 7pp. 07849 269
- 8103100398 Withdraus request for hearing transmitted in 810217 itr License condition has been clarified Hearing not required. CCUNBIL-W O Northeast Nuclear Energy Co. (subs of Northeast Utilities). 81/02/27 1p 07867:232
- J Insurance & indemnity information
- 8103100411 Forwards Endorsement 5 to NELIA Binders EB-15 & EB-16 CONNELL, T J Northeast Utilities 81/03/04 2pp 07865 207
- 8100310493 Forwards Endorsements 6 to NELIA Binders EB-15 & EB-16 & Endorsement 67 to NELIA Policy NF-173
  SINIBILJ.H Marsh & McLennen.Inc., M & M Nuclear Consultants.Inc Div 81/03/26 6pp. 08078:355
- 8103310424 Forwards Endorsement 60 to MAELU Policy MF-52. SNRISILJ M Marsh & McLennen Inc., M & M Nuclear Consultants Inc DIV 81/03/27. 3pp. 08078 293
- P Operating license stage documents & correspondence
- B103190732 Line to all licensess of operating plants applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NU980-0612 Forwards NRC position re interim actions & request for addl info.

  EISENHUT. D @ plvision of Licensing. B0/12/22. 30pp.
- BiO3040169 Forwards order for not of license to assure safe operation of BMRs of inadequate scram discharge vol instrument vol hydraulic coupling.
  CRUTCHFIELD.D Operating Reactors Branch 5. 81/01/09. 2pp. 07412. 328
- --8103040177 Order for mod of license re BWR scram discharge sys.Req prompt implementation of actions to assure safe operation u/inadequate scram discharge vol - instrument vol.hydraulic coupling. EIECHMUT.D Q. Division of Licensing 81/01/09. App. 07812 33
- B103090033 Forwards order for mod of License DPR-21 & grant of extension of exerction.
  CRUTCHFIELD, D. Operating Reactors Branch 5. B1/01/13. 3pp 07849.2B3.
- --8103090039 Order for mod of license QPR-21 & grant of extension of exemption from General Design Criterion 50. License is anended to include essessment of suppression pool hydrodynamic loads.
  EIEENTUF.D @ Division of Licensing. 81/01/13. 7pp 07849:28
- 8103190387 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment items addressed invoive cold shutdown.replacement parts & NUREG-0737.
  EISENHUT.D O. Division of Licensing. Bi/01/19. Spp.
- 8103240290 Ltr to all BWR licensees forwarding Suppl 1 to generic safety evaluation on BWR scram discharge sys. Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation EISENHULD. O. Division of Licensing. 81/01/23, 2pp.

- 8103040221 Forwards request for add1 info for App J review re containment leakage rate tosting CRUTCHFIELD.D Operating Reactors Branch 5 81/02/02 4pp 07812:279
- 9103120014 Ltr to all licensees of operating plants.CP holders & O., applicants.except Indian Point 2 & 3./ion 1 & 2 & TMI-1, forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D O Division of Licensing 81/02/03 6pp
- BIO3190648 Forwards test criteria in response to 801015 ltr requesting Region i acceptance criteria for forthcoming containment integrated leak rate test Esisting Tech Specs require 24-h test duration Shorter duration requires NRC approval QRIER, B H Region 1. Philadelphia. Office of the Director 81/02/12 3pp 07954 354
- 8103030193 Forwards Amends 72 & 64 to Provisional License DPR-21 & DPR-65.respectively & notice of issuance & availability CRUTCHFIELD.D Operating Reactors Branch 5 81/02/13. 3pp 03908 122
- --Bi03030205 Amends 72 & 64 to Provisional License DPR-21 & License DPR-65 respectively, revising Apps A & B Tech Specs to reflect organizational changes.

  CRUTCHF[ELD, D Operating Reactors Branch 5 81/02/13 27pp 07808 125
- --Bi03030214 Notice of issuance & availability of Amends 72 & 64 to Provisional License DPR-21 & License DPR-65 respectively CRUTCHFIELD.D Operating Reactors Branch 5 B1/02/13 2pp 02808 193
- B103090014 forwards preliminary partial review of environ qualification of safety-related electrical equipment. Requests review of deficiency 8 overall finding re continued safe operation of facility
  LAINAS.O.C. Assistant Director for Safety Assessment. B1/02/13
  27pp. 07849.245.
- 8103110723 Forwards Amend 71 to Provisional License DPR-21 re 810105 application for mods to fire protection program Amend deletes requirements for mods within scope of 10CFR50-App R. W/o entl CRUTCHFIELD.D. Operating Reactors Branch 5. 81/02/13 2pp. 078/85-027
- 9103160869 Ltr to all operating plants & CP holders forwarding clarification of TM1 Action Plan Item III.A 1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation datas will be met.
  EISENHUT.D.O Division of Licensing 01/02/10. 12pp.
- BIOG290024 Ltr to all power reactor licensess & license applicants re NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller.

  EIGENHUT-D.O Division of Licensing 81/02/20. 8pp.
- BiO3090201 Natification of BiO311 meeting w/util in Bathesda, MD for presentation by util & QE prior to facility startup.

  BHEALJ.J. Operating Reactors Brench 5. 81/02/23. 2pp. 07848:352.
- 8103120179 Notification of 810303 meeting w/wtil in Bethesda,MD for presentation by util & GE prior to startup. SHEA.J. Uperating Reactors Breach 5 81/02/23. 2pp. 07900-282.
- Bio3030746 Forwards inspirepts from OE reldye-penetrent exam of control and driveline reactor vessel notate & its verifying that no evidence of penetration into reactor vessel base metal exists.

  SICKLES.K.H. Northeest Utilities. 81/02/25. 10pp. 07789-021.
- 8103090438 Forwards response to NRC questions on Reload 7 license amend submittal.

  COUNSIL.H. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/02/25. 12pp. 07846:139.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except Bt Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUT.D.O. Division of Licensing 81/02/25. Spp.
- 8103090337 Application to amend License DPR-21 revising Tech Specs to be consistent w/local leak rate acceptance criteria per 819 for QE BHRs. COUNBILLH Q. FEE, H. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/02/26. 3pp. 07850:223.

- --BIJ3090340 Tech Specs 3/4 7-B for local leak rate tests

  Northeast Nuclear Energy Co (subs of Northeast Utilities)
  BIJ02/2H 3nn 37850 224
- 8103170225 Ltr to all 3kR licensees texcept Humboldt Bay & LaCross requesting review of ASME Code Class i & 2 pressure boundary piping, safe ends & fitting natl per guidelines of enci Revision I to NUREO-0313 Model Tech Specs only enci EISERMUT. 0 O Division of Licensing 81/02/26 3pp
- --Bi03170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 surveillance requirements for ABME Code Class 1/2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements \* General Electric Co 81/02/26 4pp
- B103060502 Forwards SEP redirection lists, amending util B10204 commitment re SEP topics categorized as condidates for completion Topics have been subdivided to recognize two completion dates, B10430 8 B10630 COUNSIL-W G Northeast Nuclear Energy Co isuts of Northeast Utilities) COUNSIL-W G Connecticut Yankee Atomic Power Co B1/02/27 ISpp 07837 301
- 8103090628 Provides overall finding in response to CRC requirement eliviron qualification of safety-related electrical equipment Concerns expressed in NRC 810213 ltr do not altor util determination that facilities can be operated safely CQUNSIL.H 9 Connecticut Vankee Atoric Power Co CQUNSIL.H 0 Northeast Huclear Energy Co (subs of Northeast Utilities) 81/02/27 7pp 07044 294.
- 8103100398 Withdraws request for hearing transmitted in 810217 ltr License condition has been clarified Hearing not required COUNSIL W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities). 81/02/27 ip 07867-232
- BiO3110705 Forwards info & IIO electrical drawing aperture cards re SEP Topics VII-1 A & VII-2. In response to MRC Bi0124 questions QE relay stds & aperture cards encl Aperture cards in PDR CDUNBIL-W O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) Bi/03/02 Bpp 07875.331
- 8103110705 Forwards info & 110 electrical drawing aperture cards re EEP Topics VII-1 A & VII-2 in response to NRC 810124 questions GE relay stds & aperture cards encl Aperture cards in PDR CUUNBIL.W O. Northeast Nuclear Energy Co (subs of Northeast Utilities). 81/03/02 82p
- B103250537 Discusses costs for implementation of TM1 action plan requirements NRC estimates of required industry resources have been consistently low. Comparison of NRC estimate w/ actual costs encl.

  COVERTILE 0 flortheast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Pawer Co. B1/03/02 6pp 08040 172
- U103120335 Forwards ECCS outage rept for facilities for 1980 in response to NUREO-0737. Item II K 3 17. No sys or Tech Spec mods are required.

  CQUISIL. W G Connecticut Yankee Atomic Power Co CQUINGIL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/03/04. IBpp 07901:200
- 8103120757 Notification of 810306 meeting w/util & GE for presentably participants prior to facility etartup. Second change in date & time.
  SHEALJR. Operating Reactors Branch 5 81/03/05. 2pp. 07905.
- B103130428 Ack receipt of completed evaluations of BEP Topics V-10 V-11. A.V 11.8 & IX-3 re safe shutdown sys Due to current refueling outsige manpower requirements.comments of end evaluations will be delayed from B10224 to B10401. COUNBIL I/O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/03/05 lp 07911:346.
- 8103110625 Forwards drawings & calculations re-battery racks & char 41607480 volt transformer diesel generator romote control board, motor control ctr & emergency svc water pump, in response to SEP Topic 111-6 Aperture cards in PDR COUNSIL-H. O. Northeast Nuclear Energy Co. (subs of Northeast Utilities). Bi/03/06 71pp
- 8103310804 Ltr to all licensees of operating plants applicants for k holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment. ETBENHUT, D. G. Division of Licensing. 81/03/10. 6pp.

- 8103260218 Forwards Amend 73 to License DPR-21.safety evaluation 5 notice of issuance 5 availability CRUICHFIELD D Operating Reactors Stanch 5 81703/11. 250 08041-312
- --Bi00260229 Amend 73 to License DPR-21 approving App A Jean Specs to allow return to full power operation following seventh refueling outage CRUICHFIELD.D (perating Reactors Branch 5 81/03/11 29pp
- --8103260238 Safety evaluation supporting Amend 73 to License DPR-21 s Office of hyclear Reactor Regulation. Director 81/03/11
- GL03260251 Notice of issuance & availability of Ameni 73 to License DPR-21
  CMUTCHFIELD.D. Operating Reactors Branch 5 B1/03/11 2pp ORBAL 338
- 6103240850 Summary of 810306 meeting w/util in Sethesda.HD to brief NRC representatives on pipe tracking at facility tist of attendees & visual aids encl
  SHEA.J J Gorating Reactors Granch 5 81/03/16 80pp
- 8103250325 Forwards support details relemergency svc water purp shutdown heat eschanger & oil storage day tank into provided for NRC revies of SEP Topic III-6 four oversite drawings encl Aperture cards are avabilable in PDR COUNSILE G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81703716 105p
- G103270095 Summary of A10304 meeting u/Mart I numers group & GE in Bethosde:MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREG-0061 Slide presentation & list of attendees encl GRIMES.C I Licensing Branch 3 G1/03/16 Spp
- B103230676 Forwards evaluation of SEP Topic V-5 to RCPB leakage detection Two add1 leakage detection methods & increase in sensitivity are necessary.

  CRUTCHF1ELD.D. Operating Reactors Branch 5 81/03/18 Spp. 09978 313
- B103310352 Submits add1 info requested re elemption from airlock testing requirements of App J to 107850 & Identification of mode necessary to met requirements for reverse direction testing.

  COUNSIL-U G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 81/03/20 2pp 08075 173
- Bi03310704 Notification of B10401 meeting w/util in Bethasca. MD to resolve differences between util & IRC re-draft SER on SEP Topic VIII-4 re-electrical penetrations SHEA.J.J. Operating Reactors branch 5 Bi/03/24 3pp 08061-069.
- G. Inspection reports: IE Bulletine & correspondence
- 8103020148 Forwards IE Info Notice 81-01. 'Possible Failures of GE Type WFA Relays ' No response required.
  GRIER.B H Region 1. Philadelphia. Office of the Director 81701/16 ip 07783 253
- 8103100212 Confirms 810120 telcon re findings of special 810116 insp.
  Radiation work permit procedure will be revised to prohibit
  work not fully described on permit General employee training
  program will be revised by 810215
  6RIER.8 H Region i. Philadelphia. Office of the Director
  81/01/21 2pp 07863.234
- 8:03:00:240 Responds to IE Bulletin 80-17. Suppl 4. "Failure of Control Rods to Insert During Scram at 84R." GE has submitted test info to JRC. Calibr test will be performed by instrument technician trained in electronics COUNSIL 19. Northeest Nuclear Energy Co (subs. of Northeest Utilities) 8:1/01/26 Spp. 07863-210
- B103180304 Forwards IE Insp Repts 50-248/80-24 & 50-336/80-23 on B01109-1231 No noncompliance nated. BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. B1/01/29 2pp. 07944.225
- --8103180315 IE Inep Repts 50-245/80-24 & 50-336/80-23 on 801109-1231 No noncompilance noted Major areas inspected control rooms & accessible portions of Unit 1 reactor turbine raduaste & gas turbine generator.

  SHEDLOSKY J T Region 1. Philadelphia, Office of the Director.

  KEIMIG.R R. Region 1. Philadelphia, Reactor Operations Nuclear Support Granch 81/01/27 Spp. 07944.227.

- BiC3040196 Forwards IE Info Notice Bi-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CFR30 72 "No written response required GRIER.B H Region I. Philadelphia. Office of the Director 81/02/12 lp 07813 117
- B103030379 Forwards Buppl 5 to IE Bulletin B0-17. "Failure of Control Rods to Insert During Scram at BUR" No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director B1/02/13 1p 07808 225
- B103030746 Forwards inspirepts from GE re dye-penetrant eiam of control rod driveline reactor vessel notale & ith verifying that no evidence of penetration into reactor vessel base metal exists
  SICKLES,K M. Northeast Utilities B1/02/25, 10pp 07789,021
- 8100200181 Forwards 1E Info Notice 81-04. "Cracking in Main Steam Lines" No response required ORIER.8 H Region I. Philadelphia, Office of the Director. 81/02/27 ip 07972 026
- B103200239 Forwards 1E Circular 81-03, "Inoperable Boismic Monitoring Instrumentation" No written response required. GRIER.B.H. Region 1. Philadelphia, Office of the Director 81/03/02 ip 07972:073.
- B103200039 Forwards revised IE Bulletin B1-01, "Surveillance of Mechanical Shubbers," wicorrected Pages 3 & 6 Change in identification on fracilities wife to bulletin is applicable does not affect util requirements. GRIER.B H Region 1. Philadelphia. Office of the Director. 81/03/04 p 07968-188
- 8103200184 Forwards IE Info Notice 81-06. 'Failure of ITE Model K-600 Circuit Breaker' No response required CRIER.B H. Region 1. Philadelphia. Office of the Director 81/03/|| 18. 07968 310
- 8103270754 Provides results of util evaluation of BWR scram discharge sys & mods necessary to compily w/BWR owner's group evaluation critersa re IE Bulletin 80-17 Mod implementation scheduled for next refueling outage.
  CGU:SIL.W 9 Northeast Nuclear Energy Co. (subs. of Northeast Utilities) B1/03/20 8p. 08043-183
- R Periodic operating reports & related correspondence
- 8103030904 Forwards "Bemi-Annual Radioactive Effluents Release Rept. Jul-Dec 1980" per format of Reg Quide 1.21 & requirements of Reg Quide 10.1. COUNSIL-W G Northeast Nuclear Energy Co (subs. of Northeast Utilities). 81/02/27. 1p 07794 206.
- ~-Bi03030909 "Semi-Annual Radioactive Effluents Release Rept.JulnDac 1980 -\* Northeast Nuclear Energy Co. (subs. of Northeast Utilities) Bi/02/27 112pp. 07794 207
- 8103050673 Forwards "Millstone Nuclear Power Station Units 1 & 2.Annual Rept. 1980" NROCTARAE J Northeast Utilities 81/02/27. 16. 07829.301
- --8103050676 "Milistone Nuclear Power Station Units 1 & 2,Annual Rept. 1980 "

  • Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/02/27. 38pp. 07829-302.
- B103170663 Forwards monthly operating tept for Feb 1981.

  MRDCZKA/E J. Northeast Nuclear Energy Co (subs. of Northeast Utilities). B1/03/11. ip 07939:010.
- --B103170566 Monthly operating rept for Feb 1981.

  HARRAN.O. Northeast Nuclear Energy Co. (subs. of Northeast
  Utilities) B1/03/05. 4pp 07939:011.
- B103310476 Forwards corrected Reg Ouide 1 16 repts for "Annual Operating Rept.1980." originally submitted on 810227. RROCKAR.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/03/26. 1p. 08081.208.
- ~-8103310482 Corrected Reg Quide 1.16 repts for "Annual Operating Rept. 1980." originally submitted on 810227.

  Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/03/06 2pp. 08081:209.

- containment penetration I inboard isolation check valve Cause not known investigation in progress MRDCZKA.E J Northeest Utilities. 81/02/10 ip
- 8103040630 Forwards LER 81-001/017-0 MRGCZXA.E J Northeast Nuclear Energy Co (subs. of Nurtheast (tell(tes) 81/02/23 in. 07817-072
- --Bi03040433 LER Bi-001/017-0 on Bi0209, flaw found in pipe weld in piping between primary containment penetration & LPCI inboard scolation check valve Caused by intergrantular & transgrannular stress corrosion cracking

  Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
  Bi/02/23 20c 07817-073
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8101070352 Releases public version of RRC comments on util revised emergency plan FELTON.J.M. Division of Rules and Records. 80/12/01 lp. 07403 149
- --Bi01220618 Forwards public version of util revised emergency plan
  CAMPILLIN J. Consolidated Edison So. of New York B0/02/14 7p;
  DADP: 1-048
- --Bi01070394 Public version of Revision 2 to emergency plan for facilities.

  # Consolidated Edison Co of New York. 80/02/29. 80pp 07403 151
- B103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Farwards NRC position & request for add1 info resafe shutdown capability for compliance w/B01119 fire protection rule EIBERHUT. 0.0. Division of Licensing B1/02/20. 13pp
- BIO3310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements. Mrd encl.

  EIBENHUT.D. O Division of Licensing. Bi/03/05 6pp
- B103260392 Responds to B1012B & 29 ltrs.expressing concern that NRC may adopt energency response plans for facility environs w/o signatures of four counties on plans NRC rule requires B10401 implementation.except for elert & notification sys BTELLOV Director's Office. Office of Inspection and Enforcement. B1/03/20 2pp. 08040-346.
- O Adjudicatory correspondence
- B103090140 Corrects typographical error in 810209 ltr re second ASLAB conclusion
  VARQALB A Operating Reactors Branch 1. 81/02/13 lp. 07848-296.
- B103030707 Forwards application for amend to DLs, adding nonradiological environ protection plan necessary to permit implementation settlement agreement re condenser cooling sys. Class I & III amend fees and BAYNE, J P. Power Authority of the State of New York B1/02/27.
- ~~8103030717 Settlement agreement between EPA, State of NY, Con Ed. PASNY. Central Hudson Qas & Electric Corp. Grange & Rockland Utils. Inc. Nigara Mohauk Power Corp. NRDC & Scenic Hudson. Inc recondenser cooling sys.

   Environmental Protection Agency. 80/12/19. 69pp.
- --Bi03030733 Joint motion seeking order deleting from OLs existing requirement for termination of operation of units w/once-through cooling. Draft stipulations & affidavits of svc re-motion & 810227 application to amend DL enci. PRATT-C.M. Power Authority of the State of New York. Bi/02/27 3700.
- 8103040483 Request for order deleting OL requirement for termination of operation of units w/once-through cooling. If motion granted, settlement agreement could be initiated allowing facility to be equipped w/circulating water pumps & screens.

  BRANDENBERG, 8 Consolidated Edison Co. of New York. PRATT.C M Power Authority of the State of New York. 81/02/27. 12pp. 07810-071

- No Detailed Affiliation Given + New York, State of 74/12/01 20pp.
- 8103100793 Ack receipt of 810105 & 0211 ltrs refuting allegations refailure of mot control sys & forwards order imposing civil penalties in amount of \$210.000 No basis for litigation exists.

  STELLO.V Director's Office Office of Inspection and Enforcement 81/03/02 3pp 07862 205
- --B103100760 Order imposing civil penalties in amount of \$210.000 re B01017 containment flooding Evaluations & conclusions enct STELLO.V Director's Office. Office of Inspection and Enforcemen B1/03/02 Jlpp 07862-208
- B103180672 Advises that reply to NRC & util responses util be sent 10 days following receipt of licenses submission GOLDBERO, IL Public Interest Research Group. New York B1/03/04 pp. 37954 181
- 8103160374 Discusses ML Coldberg B10304 ltr to Chairman Miller advise that NY PIRO % other petitioners uguld be filing replies to answers to petitions to intervene No procedural rule allows filing of such replies MOORE. J E Hearing Granch 2 81/03/13 p 07922 059
- 8103230065 Response supporting licensee 810227 motion for order deleting certain provisions from facility licenses, directing 780113 stipulation be superseded & directing termination of pending actions re condenser cooling sys MCORE. J E Hearing Irench 2 81703719 9ps. 07978:244
- --B103230074 Affidavit re technical aspects of settlement agreement A environ concerns have received addl thorough exam Agreement represents resolution of environ dispute Prof qualifications & Certificate of Sv. encl B1LLUPS.C W Environmental Engineering Branth. B1/03/19 Spp 07978 292
- H General correspondence
- 810302006B FOIA request for documents re methodology, assumptions, data 5 procedures used by task force on interim operation of facility.

  HOLL, R.R. New York Univ 81/01/27. 2pp. 07783 042
- 8103020064 Responds to FDIA request for documents re-methodology, assumptions, data & procedures used by task force on interim operation of facility Lists three documents which have been published Unpublished documents will be forwarded FELTON, J. M. Division of Rules and Records 81/02/24 ip. 07703-041.
- 8103130441 Responds to 810115 request for info needed to respond to constituent concern re decision not to shut down facility. Task force concluded design did not warrant shutdown during ASLB hearing ASLB recommendations due 820108.

  8ICKHIT.L Office of the General Counsel 81/02/28 2pp 07911:244.
- --BiO3120444 Forwards constituent B Jones BiO110 ltr re failure to sh down facility for response WILLIAMS.H A Senate 61/01/15 2pp. 07911:246.
- P Operating license stage documents & correspondence
- B007010587 Forwards tabular summary of comments & comments received a director's decision & Commission review of shutdown of facilities BICKHIT.L Office of the General Counsel. SECY-80-168 80/03/28 11pp. 07972.287.
- BIO3190732 Ltrs to all licensuse of operating plants, applicants for DLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREO-Obiz. Forwards NRC position reinterim actions & request for addl info. EIBENHUT. D. O. Division of Licensing. 80/12/22. 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737. EIBENHUT.D. G. Division of Licensing. 81/01/19. App.

- B100040682 'Adequacy of Station Electrical Distribution Sys Voltages, Indian Point Nuclear Station, Unit 2.' technical evaluation rept
  WEBER, D. A. EGEG [dato, Inc. FIN A-6429 8103040682 81/01/31 13co 07818, 25
- 8103120014 Ltr to all licensees of operating plants.CP holders & O., applicants.ercept Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding imadvertently chitted pages from NRC 801222 request for add info re control of heavy loads EISEURUI.D C Division of Licensing 81/02/03 App
- 8103031113 Forwards Amend 66 to License DPR-26 safety evaluation & notice of issuance & availability VARDA.5 A Operating Reactors Branch 1 81/02/09 2pp 07789 312
- --8103031118 Amend 66 to License DPR-26 changing Tech Specs to accompodate operation w/low parasitic fuel. VARGA-8 A. Coerating Reactors Branch 1 B1/02/09 12pp 07789 314
- ....C103031122 Eafety evaluation supporting Amend 66 to License DPR-26 + Office of Nuclear Reactor Regulation, Director 81/02/09 2pp 07794 374
- --Bi03031132 Kotice of Issuance & dvailability of Amend 66 to License PPR-26 VAROA.5 A Operating Reactors Branch 1 81/02/09 2pp 07789 328
- BLC305013B Forwards Amend 67 to License DPR-26 safety evaluation & notice of issuance & availability VAROA S. A. Operating Reactors Branch 1 81/02/10 3pp. 07827 314
- surveillance specimen renoval program in Toch Specs
  VAROA-S A Operating Reactors Branch 1. 81/02/10 2pp
  07827 317
- --G103050161 Gafety evaluation supporting Amend 67 to License DPR-26

   Office of Nuclear Reactor Regulation, Director 81/02/10 2pp.

  07627 324

  --D103050169 Notice of issuance & availability of Amend 67 to License
- Bio3300160 Ltr to all operating PHR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for addl info. List of actions requested of licensees w/o seismically qualified sys 5 results of NRC walkdowns. EISENWINT.D.O. Division of Licensing 81/02/10. 1300

07827 324

VARGA. S. A. Operating Reactors Dranch 1. 81/02/10 2pp

- B103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A L 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be -pt. EISENRUT. D O. Division of Licensing 81/02/18 12pp
- 45 days that implementation dates will be net.
  EISENMUT.D.O. Division of Licensing 81/02/18 12pp

  8103030873 Forwards add1 info re ECCS/LOCA reanalysis for limiting break case evaluation in response to NRC request Limiting break size for 12% tube plugging case was unchanged from
- oriesting break size on plugging case was unchanged from existing break size of TOCLE. D Consolidated Edison Co. of New York. 81/02/20 app. 07796-213
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria. Pootnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISENHUT, D. O. Division of Licensing. 81/02/20 8pp.
- 8103050723 Notification of 810227 meeting w/util in Bethesda.MD to discuss fan cooler replacement for facility OLSHAN.L. Operating Reactors Branch I 81/02/24. 1p. 07828-034
- 8103230030 Ltr to all licensess of operating nuclear power plants & applicants for OLs (except 8t Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & prompt laying learnt emergency procedures, EIBENHUT, D. Q. Division of Licensing. 81/02/25 3pp
- 8103030722 Forwards response to NUREO-0737, "Clarification of TMI Action Plan Requirements " Auxiliary botler Psod pump turbing missile analysis summary & training program for mitigating reactor core damage encl D'TOOLE J. D. Consolidated Edison Co. of New York. 81/02/26 81pp 07795-338.

- 8103230813 Generic Ltr 81-06 to a[] CP holders & OL applicants re 10CFR80 71(e). "Persodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl E16EKHUT.D @ Division of Licensing 81/02/26 10pp
- 8103020393 Responds to ARC BIO211 ltr transmitting preliminary result of review of environ qualifications of safety-related electrical equipment. Potential equipment deficiencies have
- electrical equipment rotation of New York 81/02/27 to 07784 233
- 8103030707 Forwards application for amend to OLs, adding normadiolog environ protection plan necessary to permit implementation settlement agreement re condenser cooling eys Class I & III
- settlement agreement to condenser cooling sys Class I & III arend fees encl.

  BAYNE, J P. Power Authority of the State of New York O'TODE, J Consolidated Edison Co. of New York B1/02/27 2pp. 07799: 232
- --Bi03030712 Application to amend Licenses DPR-5. DPR-26 & DPR-64.ad normaliological environ protection plan necessary to permit implementation of settlement agreement re condenser cooling sys
  BAYNE.JP Power Authority of the State of New York (0'TOULE, Consolidated Edison Co. of New York (81/02/27 4no. 0779/) 2
- --B103030717 Settlement agreement between EPA. State of NY. Con Ed. PA Central Hudson Gas & Electric Corp. Drange & Rockland Utils. Inc. Nigara Mohawk Power Corp. NRDC & Scenic Hudson. Inc. ve
- --B103030723 Proposed ETS (radiological) for facilities, deleting normalitological requirements

  \* Consolidated Edison Co. of New York 81/02/27. 68pp 07797.322
- --BI03030733 Joint motion seeking order deleting from BLs existing requirement for termination of operation of units u/ence-through cooling Draft stipulations & affidavits of secret routin & BI0227 application to seem of CL enci. PRAIT.C M Power Authority of the State of New York. BRADENBURG.B L. Consolidated Edison Co. of New York. BI/O2/2/37pp 07800.108
- 8103190256 Summary of 810227 meeting u/util re fan cooler replacers other activities underway during current outage List of attendees & containment sump info encl. QLGHAN-L W. Operating Reactors Branch 1 81/03/09, 10pp 07955 261
- 8103310804 ttr to all licensees of operating plants, applicants for & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical
- equipment
  EIBEN-UT. D G Division of Licensing DI/03/10 App
  BI03130391 Forwards application to arend DLs, revising Tech Specs re
- 8103130391 Forwards application to arend DLs.revising Tech Specs refacility rightechnical support & organization. Class 1 & 11 amend fees & affidavit of svc encl D\*TODLE.J.D Consolidated Edison Co. of New York. 91/03/11 3p 07908-199
- --Bi03i30408 Application to amend Licenses DPR-3 & DPR-26 changing Specs 3 i & 6 O of Units i & 2.respectively.re facility mgt. technical support & organization
- 0'100LE.J.D. Consolidated Edison Co. of New York. 81/03/11. 07908:202
- --8103130412 Proposed Tech Speca 3 1 & 6.0 of Units 1 & 2.respective revising facility mgt.technical support & organization.

  \* Consolidated Edison Co. of New York. 81/03/11. 16pp. 07708:204
- BiO3170472 Forwards response to NRC 800923 request for additinfo re program O'TOOLE, J.D. Consolidated Edison Co. of New York. 81/03/11 40 07925:193
- B103170274 Forwards corrected affidavits of svc to replace affidavi in B01010 ltr & in two ltrs dtd B01219. D'TGOLE J. D. Consolidated Edison Co. of New York. B1/03/12 Bp 07933-229.

- BiO3200589 Forwards info re containment fan coder units gasket matt radiation resistance capability in response to NRC request Gasket matt retained functional capability under test conditions U\*100LE.J D Consolidated Edison Co of New York B1/03/17 9pp 079AB 105
- BIG3250246 Forwards addl info needed by NRC to continue review of fracture toughness design of steam generator & reactur coolant purp supports. In response to NRC B00721 ltr 0:100LE.J.D. Consolidated Edison Co. of New York. B1/03/19 66pp
- B103270764 Advises that probabilistic safety analysis rept will be available June 1981
  BAYNE, J.P. Power Authority of the State of New York 0'100LE, J.D. Consolidated Edison Co. of New York 81/03/23 2pp 08043:193
- 8100000304 Forwards additinfo re electrical override/bypass aspects of engineered safety features actuation sys.per NRC 810224 request.
  O'TEOLE J D. Consolidated Edison Co. of New York. 81/03/23 7pp. non55-124
- 8100310341 Forwards application for amend to License DPR-26 O'700LE.J D Consolidated Edison Co of New York 81/03/26 Ip
- --Bi03310346 Application for amend to License DPR-26 to revise Teth Specs re limiting conditions of operation & surveillance requirements for leak detection & renoval says for reactor coolant says & total leakage into containment free vol D'TOCKE-J D Consolidated Edison Co of New York B1/03/26 2pp 08075-176
- --Bi03310353 Proposed revisions for Tech Specs 1 B-13, 3, 1 F. 4, 16 & Tables 4, 1-1, 2 & 3 for questant power tilt ratio, surveillance intervals, pressure toundary & identified leaks, reactor coolant sys & containment free volume leakage at al. e. Consolidated Edison Co. of New York B1/03/26 21pp. 08075 178.
- G. Inspection reports: IE Bulletins & correspondence
- B103090067 Responds to IE Bulletin B0~21. "Valve Yokes Bupplied by Malcolm Foundry Co.Inc." Bulletin does not apply to plant. O'TODLE.J D. Consolidated Edison Co. of New York B1/01/20 1p.07852.156
- B103230394 Forwards IE Insp Rept 50-247/80-15 on B00824-1004 No noncompliance noted BRUNNER.E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 81/01/26 2pg. 07975 033.
- --GIO3230407 IE Insp Rept 50-247/80-15 on 800824-1004. No noncompliance noted. Major areas inspected plant operations including review of shift logs & records. Licensee action on previous insp findings & observation of physical security MENNY. T., REBELOUSKI, T., Region 1. Philadelphia, Office of the Director KIBITEA, H. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. Bi/O1/27. 18pp. 07978:035.
- 8103050449 Ack receipt of Bi0106 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/80-18.

  MARTIN.W O. Region 1. Philadelphia. Safeguards Dranch B1/01/29.

  1p. 07824:352
- --BIO3050456 Responds to NRC B01125 ltr re-violations noted in 1E Insp. Rept 50-247/80-18. Corrective actions withheld (ruf 100782-790).

  O'100LE.J.D. Consolidated Edison Co. of New York. B1/01/06 ip. 07824:353.
- --Bi03050463 Forwards IE Insp Rept 50-247/80-18 on B01006-10 & notice of violation Notice of violation withheld (ref 100FR2 790). MARTIN.W.O. Region I. Philadelphia, Safeguards Branch. B0/11/25. 2pp. 07824:354
- --Bi03030478 IE Insp Rept 50-247/80-18 on 801006-10. Noncompliance noted. failure to train watchperson prior to assignment & to maintain isolation zone free of obstructions. Details withheld (ref 10CFR2.790).

  BAILEY/R. J. Region i, Philadelphia, Office of the Director. DEVLIN.J.W. Region i, Philadelphia, Safeguards Branch. 80/11/13. pp. 07824:356.
- B103240092 Forwards Addendum ( to Attachment A of 790928 response to IE Bulletin 79-14. "Beismic Analysis for As-Built Bafety-Related Piping Bys." Includes results of eddl pipe support insp on thermally insulated lines.

  O'TODUE.J.D. Consolidated Edison Co. of New York. B1/02/06. 2pp. 07989: 222.

- --B103240099 "Rept of Pipe Support Insps Performed on Thernally Inst Lines in Response to 1E Bulletin 79-14." Attachment A. Addendum I \* Consolidated Edison Co. of New York B1/02/28 12pp 07989 224
- B103040205 Forwards IF. Info Notice B1-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/10CFR30 72 ^ No written response required ORIER.B.H. Region 1. Philadelphia. Office of the Director B1/02/12 ip 07813 i33
- 8103200145 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines" No response required GRIER.0 H Region 1. Philadelphia. Office of the Director 81/02/27 ip 07971 351
- BiO3100753 Ack receipt of BiO105 & O211 litrs refuting allegations re failure of mot control sys & forwards order imposing civil penalties in amount of 4210.000 No basis for litigation exists. BTELLO.V Director's Office. Office of Inspection and Enforcement BI/O3/02 3pp 07862 205
- --BI03100760 Order imposing civil penalties in amount of \$210,000 re B01017 containment flooding Evaluations & conclusions ench BTELLO.V. Director's Office. Office of Inspection and Enforceme B1/03/02 31pp 07862 208
- BIO3200091 Forwards revised IE Bulletin BI-01. "Gurveillance of Mochanical Shubbers." w/corrected Pages 9 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements ORIER. B H Region I. Philadelphia, Office of the Director BI/03/04 ip 07968 217
- 9103200206 Forwards IE Info Notice 81-06. "Failure of ITE Model K-60 Circuit Breaker." No response required GRIER.B.H Region I. Philadelphia. Office of the Director 81/03/11 1p 07968:316
- 8103170613 Forwards "Steam Cenerator Insp Program & Results, 1980/1981 Refueling Maint Outage." per Amend 58 to License DRR-26 & 801202 & B10116 ltrs Class 3 fee enc! D'TOCLE.J D. Consolidated Edison Co. of New York 81/03/13 2pp 07929: 349
- ~-Bi03170620 "Steam Generator Insp Program & Results.1980/1981 Refue & Maint Outage ' # Consolidated Edison Co of New York. 81/03/31 98pp 07929.351
- R Periodic operating reports & related correspondence

07867: 165

- B102250439 Forwards "Hudson River Ecological Study in Area of Indian Point." 1979 annual rept. Affidavit of svc encl.

  O'TODLE. J D Consolidated Edison Co of New York, 81/02/20 4pp 07745-001
- --8102270774 "Hudson River Ecological Bludy in Area of Indian Point. 1979 annual rept. \* Texas Instruments, Inc. 81/02/20 190pp. 07767;001
- B103100517 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-D 1980." O'TOOLE.J D. Consolidated Edison Co. of New York. 81/03/01. 1p
- ~~8103100518 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1980 \* Consolidated Edison Co. of New York 81/03/01 43pp. 07867.166
- 8103230578 Forwards monthly operating rept for Feb 1981.

  O'TGOLE-J D. Consolidated Edison Co. of New York. 81/03/13 1p.

  07974.169.
- --8103230585 Monthly operating rept for Feb 1981. EICH.E. Consolidated Edison Co. of New York 81/03/06 4pp 07974.170

# 5 Reportable occurrences, LERs & related correspondence

- 8103036503 Pt.5-1-81-305 on 8:0225.Con Ei custoner svc representative received bond threat by telephone Corporate ofc & facilities notified 3cm3 searches initiated w/negative results No Further action anticipated MARQUINLU W Region 1. Philadelphia, Office MARQUINLU , JOYLER J H , DEV. INLU W Region 1. Philadelphia, Office of the Director 01/02/26 to 07708 034 further action anticipated
- 8103030842 Pt.J-1-81-605 on 810225 customer sys representative received 103036842 Pt.J-1-B1-C05 on M10225.custorer ave representative rece borb threat 5, telephone Util corporate afc notified & borb search initiated Results negative MCMCOWAL IS. JOYNER J.H. DEVLIN, J.M. Region S. Philadelphia. Office of the Director B1/02/26 22p 07793 173
- 8103110511 RO 81-305/01 loose objects retrieved from bottom area of 10311USIL RO 81-905/01 loose objects retrieved from botton area of reactor vessel during engoing refueling outage licentified as reactor coolant pump latyrinth seal ring & mounting bolts. Pump to be replaced investigation continuing MCMILM A Consolidated Edison Co. of Na., Yerk. 81/03/03. 3pp. 07862 157
- 8:03240975 Forwards LER 81-006/01T-0 O'TOCLE J D Commonwealth Edison Co 81/03/16 ip 07986 029.
- -- 810324058; LER 81-636/017-0 on 810332 loose objects retrieved from 1034-0581 LER 81-038-011-9 on B19334 locks stjetts retrieved to lover portion of reactor vessel Coused by typics stress failure of reactor collant pung 24 labryinth seal ring & mounting boils due to entry of foreign not 1 into small gap e Componiselth Edison Co. 81/03/16 dpp 07986 030
- B103190393 RD B1-037/-i notified by vendor of possible degrading of fiber; lass prefitters used in front of cooling coils under accident conditions investigating feasibility & availability alternate qualified prefilters
  partial A Composidated Edison Co of New York 61/03/18 2cp MADITION A 07945 187
- 8103260574 Foreards updated LER 81-002/998-1 0-TOCLE. J D Consolidated Edison Co of Neu York 81/03/20 19 AGA25 70B
- -- 8103260387 Vocated LER 81-002/99x-1: on 810106, grid strap damage found n fyel assemblies in form of torm or missing corners Coused by corner-to-corner (interaction between adjacent assemblies during fuel handling operations
  PUPCHIT, 8 Consolidated Edison Co of New York 81/03/20. 5pp 08035 339
- V Operator Examinations
- 8103030722 Forwards response to NUREO-0737, "Clarification of TMI Action Plan Requirements" Auxiliary boiler feed purp turbine missile analysis surrary & training program for mitigating reactor core damage encl. D'TCOLE. J D. Consolidated Edison Co. of New York. 81/02/26 81pp. 07705 33R
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION. UNIT 3 F. Security, medical, emergency & fire protection plans
- BIO1080051 Releases public vorsion of util draft emergency plan. MUREG-0694 into encl FELTON J M Division of Rules and Records. BO/12/02 18pp
- --8101230943 Forwards public version of draft omergency plan for generating stations PEOPLES.D L Commo Commonwealth Edison Co 80/04/24. 3pp. 04837 169.
- -- 8101080060 Public version of Craft emergency plan for generating stations.
  - Commonwealth Edison Co 80/07/31. 150pp
- 8101080093 Releases public version of util draft emergency plan, FELTON-J M. Division of Rules and Records 80/12/03 ip
- --BI01220258 Forwards public version of util revised draft emergency plan w/station anneses PEGPLES, D.L. Commonwealth Edison Co. 80/05/04 2pp 05370:003.
- --- 8101080019 Public version of Revision 1 to draft amargancy plan + Commonwealth Edison Co 80/07/31. 139pp
- --BiolDB0D33 Public version of draft emergency plan annex.

  \* Commonwealth Edison Co. B0/07/31 52cp. 07417-242.

- 8103:00646 Forwards evaluation of previously unresolved items & listing of current status of items identified as requiring action during fire protection review [PPDLITD, I A Greenting Reactors Branch 2 81/02/12 Son 07863 014
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 740t03 Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 fire protection rule ELSEANUT.DO Division of Licensing. 81/02/20 13pp
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Responso Facilities." Criteria Jescribe acceptable method ponso Facilities "Uniteria Jescribe Acceptable me meeting NRC requirements W/o encl ENNYTID O Division of Litensing. B1/03/05 App CIGENHUT, D.O.
- RIG3260123 Concurs w/801217 request to install two-way headest jacks on indignosize functors with the second of the communications quality unacceptably degraded.

  REPPLER. J O Region 3. Chicago, Office of the Director. GL/03/17 12 08042 129
- --8103260137 Submits location for installation of one-way headest jacks iouscolo, againts interior for installation of one-weg on emergency notification sys bealth physics notwork per Boli 19 request Requests concurrence by Bio201. RAUSCH.T.J Commonwealth Edison Co. 80/12/17. 2pp 08042:130
- BIO3250685 Releases cubilic version of implementing procedures for deld conserve FELTON, J. M. Division of Rules and Records 81/03/19. Ip 07806 001
- --8103250692 Forwards public version of emergency plan implementing procedures for corporate com-and ctr.environ director & plant-specific procedures
  DELGEORGE, L. O. Commonwealth Edison Co. 81/02/27 2pp. 07006 001
- --8103250702 Public version of emergency pien implementing procedures \*corporate command ctr. environ director & plant-specific erocedures. Correquealth Edison Co 81/02/27. 1400pp 07806.001

### Q Adjudicatory correspondence

- Bi01300233 Forwards NRC 810113 orders for mod of licenses & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Besign Criterion 50 IPPOLITO, T. A. Operating Reactors Branch 2. 81/01/13 3pp
- 8:03050704 Informs of error in Ragan supplemental testimony of fuel channel blowing to be corrected formally at hearings. Applicant does not object to NRC proposed findings of fact and formal reply will be filed.

  STEPTOE.P.P. Isham Lincoln & Boale. 81/02/24. 3pp. 07029 R90
- BID3100339 Forcerds 810225 notice of finality of Commission action w/regard to generic FEB on handling & storage of spent light cater power reactor feb (NUREG-0975) CODDARD R J Hearing Branch 2 81/03/06 3pp 07844:222
- B103180379 Forwards PW O'Connor B10313 affidavit & B10312 riemo. JF | Stol: 810210 memo.K Kritel 810320 memo.NJRE0-0612.generic | ttra of 80:222 & 8:0203, NURE3-0604.Vol 3, Number 1, | SECY-80-329, 8J Chilk 801224 memo & HJ Hurray memo. GCGDARD, R. J. Hearing Branch 2 81/03/13. 2pp. 07945.347.
- --8103180398 Identifies 21 unresolved safety issues relevant to spent fuel pool med for facility.
  O'COMMOR, P. NRC - No Detailed Affiliation Given - 81/03/12 - App 02945.349
- --6103090216 Responds to ABLB 810127 mamorandum & order re safety IDJUVELO RESPONDS TO MELS BIDIA? mamoranoum & order to sar relevance of genoric currosolved Safety (ssuc A-17 on sys interaction w/respect to spent fuel pool mod, Mod will not increase vulnerability of plant. BTOLZ-J F Systems Intoraction Branch. 81/02/10. ip.
- 8103260792 Forwards RE Hubbard 810317 affidavit putlining unresolved safity issues relevant to spent fuel mod proceeding. Certificate of Svc encl. Illinois, State of. 81/03/17. 2pp. 08036:193. HURRAY, N. J.

- --8103260800 Affidavit identifying 34 generic unresulved safety issues & generic TMI issues & describing why issues may impact public health & safety Prof qualifications encl KUBBARD, R E MHB Technical Associates 81/03/17 35no PPI AFORD
- minagro70700 Notice of further hearings on proposed amend to facility DL re spent fuel pool nod table. If there hearings on proposed amend to facility DL re spent fuel pool nod table. J.F. Atomic Safety and Licensing Roard Panel. 81/03/17 2pp. 08042.342
- 1. Financial information
- B103310613 Forwards quarantee of payment of deferred premiums for 1981 per NRC request. CRIER. .. Commonwealth Edison Co. BL/03/27 to
- -- 8103310520 Forwards Annual Rept for CY80 & statement of internal cash for the first that the first that for 1980 per provisions of 1980 per provisions of 1981 to NEXOV.H H Commonwealth Edison Co 81/03/27 Ann
- J. Insurance & indumnity information
- BI03090581 Forwards Endorsoment 5 to NELIA Binders EB-1.EB-2.EB-3. EB-29, EB-30, EB-42, EB-43 & MAELU Binders XB-1, XB-2, XB-3, 18-29, XB-30, XB-42, XB-43 OSTER-J Commonwealth Edison Co 81/03/02 1500 07850 142
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for Ots & holders of CPs re control of heavy loads. Requests Ols & holders or CPs re-control or heavy loads. Requests reviou per guidelines in NUREO-0612. Forwards NRC position re-Interim actions & request for add1 info.
  EISENHUT D 0. Division of Licensing 80/12/22 30pp
- 8103040285 Advises that 761028 request to amond Tech Specs to authorize operation w/one automatic depressurisation valve out of ave for up to 30 days is no longer under active review & is considered withdrawn. CRUTCHFIELD D. Operating Reactors Branch 5 81/01/08. 2pp. 07836: 359.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT. D. O. Division of Licensing 81/01/19 bpp
- BIO3240270 Ltr to all BWR licenses forwarding Buppl 1 to generic safety evaluation on BMR scram discharge sys Summarizes rs-evaluation of interim measures recommended per 801201 safetu evaluation EISENHUT, D. G. Division of Licensing 81/01/23 2pp
- B103120014 Ltr to all licensees of operating plants.CP holders & Oi. applicants.except indian Point 2 & 3.2ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC B01222 request for addl info ne control of heavy loads.

  EISENHUT.D.O. Division of Licensing B1/02/03 Gpp.
- 8103180854 Forwards Amends 33.56 & 49 to Licenses DPR-2.DPR-17 & DPR-25,respectively & notice of issuance & availability. CRUTCHFIELD.D Operating Reactors Branch 5 81/02/11 3pp 07953.217.
- ==81031B0R61 Amends 33.56 & 47 to Licenses DPR=2, DPR=19 & DPR=25. respectively, adding requirement to maintain guard training & qualification plan to be implemented within 60 days Security personnel to be qualified within 2 yrs CRUTCHFIELD.D. Operating Reactors Branch 5. IPPOLITO.T A Dyporating Reactors Branch 2. 01/02/11 6pp. 07953 820.
- ~~BIO31BOB71 Notice of issuance & availability of Amends 33.56 & 49 to Licenses DPR-2.ppR-19 & DPR-25.respectively CRUTCHFIELD.D. Operating Reactors Branch S. 81/02/11. 2pp. 07993 226
- BiO3i60669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met EISENHUT, D. Q. Division of Licensing. 81/02/18. 12pp.
- 8103100214 Forwards organizational charts depicting NRC Region 3 teorganization.effective B10216.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 81/02/20 KEPPLER, J. O. R 2pp 07865: 219

- 8103250024 Ltr to all power reactor licenses & license applicants re RUREO-0519 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing law flaw controller
  EISENAUT.D G Division of Licensing 81/02/20 8pp
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except 5t Lucie. Units 1 & 2) Requests util review to determine capability to mixigate station blackout event & promptly implement energency procedures EISENMUT.D G Division of Licensing B1/02/23 3pp
- 8103100743 Discusses response to AELS 810127 memorandum & order re spent fuel pool mod applicability to generic unresolved safety issues Control of heavy loads near spent fuel t seismic design criteria should be addressed KNIEL K Generic Issues Branch B1/02/26 2pp 07865 316
- B103110152 Bubrits info re safety relevance, if any of various generic unresolved safety issues under continuing study to proposed spent fuel pool mods per B10127 ASLB memorandum & order KNIEL.K. Generic Issues Branch B1/02/26 2pp 07884 297
- B103170225 Ltr to all BWR licensees fescept Humboldt Ray & LaCrosse)
  requesting review of ABME Code Class 1 & 2 pressure boundary
  piping, safe ends & filting matl per guidelines of encl
  Revision 1 to NUREG-0313 Mocel Tech Spocs only encl EISENMUT.D 0 Division of Licensing 81/02/26
- --8103170266 Madel Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 surveillance requirements for ABPE Code Class 1.2 & 3 components & RCS operational leakage limiting conditions for aperation & surveillance requirements

  # General Electric Co. 81/02/24 4/
- 8103230813 Generic Ltr 81-06 to all CP holders & O. applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status.format & content encl EISENHUT, D. Q. Division of Licensing 81/02/24 10pp
- 8103030960 Forwards status summary for NUREC-0737 items to which util committed to respond by 810301 Long-term program under Intensive internal review Program will be submitted by ALCOIS ABEL, J. 9 Commonwealth Edjaon Co. 81/02/27 3pp. 65067 351.
- 0103030158 Forwards add1 info re containment furge & vent valve operability. In response to NRC 031202 ltr JANECER.R F. Commonwealth Edison Co. Bi/02/27 20pp
- 8103110367 Advises that 810220 ltr providing notification of intent t operate facility w/fuel supplied by Exxon Nuclear Co should be considered proposed amond to License DPR-29 Fee for Class III amend provided ABEL. J.S. Commonwealth Edison Co. 81/03/09 1p. 07872 313
- 8103310804 Ltr to all licensees of operating plants applicants for Ci. 3 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment. EISENHUT, D.O. Division of Licensing 81/03/10 App
- 8103180517 Informs NRC that util will continue to require full radiation training for NRC personnel entering radiation areas at facilities, pending further NRC communications, TRAMM, T.R. Commonwealth Edison Co. 81/03/11 1p. 07944 201.
- 8103180531 Forwards procedures for SEP Topics V-10 8, V-11 8, V11-3 & IX-3 re safe shutdown & control room evacuation Also forwards one oversite drawing Aperture card is evailable in ROS JANACEK, R. F. Commonwealth Edison Co. 81/03/12. 2pp 07965 341.
- --8103180542 Revision 9 to 'Unit 2/3 Normal Unit Shutdown " Commonwealth Edison Co. 80/07/31 11pp 07965.343
- --BIO3180591 Revision 7 to "Unit 2/3 Shotdown From Power Operation to Standbu. "
  - \* Commonwealth Edison Co. 80/07/31 10pp 07965-354
- --BIO3180563 "Control Room Evacuation/Bafe Shutdown." (Primary Responsibility-Operations Director Commonwealth Edison Co 80/07/31 11pp 07966.001.
- 8103200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 % 18-2 c CE-1-A.Revision 16 re QA program Revisions reflect ASME winter addenda codo Changes, changes made per ASME survey & clarifications & corrections TRAMM.TR Commonwealth Edison Co. 81/03/16 1p 07971 038.

- R103270095 Stmary of B10304 meeting w/Mark I coners group & GE in Bethesda. MD re supplementary tests conducted in full-scale test facility & resolution of outstancing Mark I issues per MJREG-0661 Slide presentation & jist of attendess encl GRIMES. C. I. Licensing Branch D. 81/03/16 Spp.
- 8103230799 For ands responses to NRC question re adequacy of station electrical distribution sys voltages Revised table showing auxiliary poler bus voltages when unit reserve auxiliary transformer is carrying shutdown load encl JANCCEN.R F. Commonwealth Edison Co. 81/03/18 3pp. 07975 329
- Bio324017B Requests clarification of constraints placed on BWR fuel exposures per BO1112 SER Requirement in conflict u/generic NRC approval of operation received by GE in Nov 1980 Itr Util assumes previous commitment no longer applicable JANCERLR F Commonwealth Edison Ca BI/03/19 2pp 07990 342.
- Q Inspection reports. IE Bulletine & correspondence
- 8062190210 Forwards third timonthly status rept on IE Bulletin 79-018 re environ qualification of Class IE equipment HAYES.D.W. Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/12/09 2pp
- 8100240711 Responds to Suppl 3 of IE Bulletin 79-018. Environ Qualification of Class IE Equipment. Suppliers have been contacted to provide qualification of acoustic monitors on relief 8 safety valves ABELL 9. Commonwealth Edison Co. Bi/02/02 3pp. 07989-212
- 8103130227 Forwards IE insp Repts 50-010/80-23.50-237/80-25 & 50-249/80-30 on 801115-1231 & notice of violation HEISHMAN R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 81/02/03 2pp 07912:193.
- --8103130233 Notice of vinlation from insp on 931115-1231 HGISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 81/02/03 ip 07912 195
- --B103130245 1E Insp Repts 50-010/80-23.50-237/80-25 & 50-249/80-30 on 801115-1231 Mancompliance noted pressure regulator setpoint below reactor pressure during startup resulting in reactor scram TONQUE, T.M., REIMANN, F.W., JORDAN, H.J., Region 3, Chicago, Office of the Director B1/02/02 10ps 07912:196
- B103020115 Forwards IE Circular B1-02, 'Performance of NAC-Licensed Individuals While on Duty." No written response required MEPPLER, J.O. Region 3, Chicago, Office of the Director B1/02/09, 2pp 0778B 020.
- Sicc200284 Forwards technical info.updating 810202 response to IE Gulletin 80-17. Supp 4. "Failure of Control Rods to Insert During Scram at BHR." W/o encl RAUSCH.T J Commonwealth Edison Co. 81/02/11 2pp 07971 165
- B103040251 Forwards IE Info Notice 81-03, "Checilist for Licensees Maing Notifications of Bignificant Events In Accordance M/10CFR50 72 " No written response required MEPPLER. J G Region 3, Chicago, Office of the Director 81/02/12. 2pp 07813 283
- Ø103030302 Forwards Suppl 5 to 16 Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required. KEPPLER, J 9 Region 3. Chicago, Office of the Director BI/02/13. 2pp 07790 337
- 8103060039 Discusses IE insp on 800808 & forwards order imposing civil penalty SYELLO.V Director's Office. Office of Inspection and Enforcement. 81/02/23. 1p 07839-241.
- --8103060049 Order imposing civil penalty in amount of \$40,000 for item of noncompliance noted in IE imap on 800808 re operators observed by resident inspector to be asleep Evaluation of licensee response ent!

  STELLO, V. Director's Office. Office of Inspection and Enforcement 81/02/23 10pp. 07839-242.

- 8103360395 Act receipt of 801218 & 810203 ltrs informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 FISHER-H L Rejion 3. Chicago. Fuel Facility & Materials Safety Reach 81/02/23 to 07807 231
- --B1030a0465 Supplemental response to NRC B01125 ltr re violations notes in IE Insp Repts 50-010/B0-21.50-237/B0-23 & 50-249/B0-27 Corrective actions log established to be filled out by vendor representative when collecting environ samples ABELJ S Commonwealth Edison Co B102/03 in 07837 232
- --8103060481 Responds to NRC 801129 ltr re violations noted in [E Insp. Repts 50-010789-21.50-237/80-23 & 30-249/80-27 Corrective actions: preparing ltr to vendor reinforcing need for strict compliance wirediological environ conitoring program ABEL-4 B. Commonwealth Edison Co. 80/12/18. 2pp 07837 233
- 8103160373 Forwards monthly status rept re-evaluations performed in response to IE Bulletin 79-14. 'Seisnic Analysis for As-Built Safety-Related Piping Sys." Tables listing excessive pipe stresses encl.

  JANECEK-R F. Commonwealth Edison Co. 81/02/25 ip. 07916-185
- 8103160494 Forwards IE Circular 81-03. "Inoperable Seiemic Monitoring Instructation " No response required. KEPPLER. J. O. Region 3. Chicago. Office of the Director 91/03/02 2pp 07915 308
- 8103170371 Responds to 1E Bulletin 81-01, "Surveillance of Mechanical Shubbers" No Nuclear Eafeguards Corp shubbers have been installed or will be installed on safety-related sys JANCEEAR F. Commonwealth Edison Co. 81703702. 2pp 07925:250
- B103160874 Forwards revised IE Bulletin B1-01, "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements WEPPLER:) G. Region 3. Chicago, Dffice of the Director. B1/03/04 ip. 07919.065
- 8103200394 Forwards [E Info Notice 81-06, "Failure of ITE Model k-600 Circuit Breaker " No response required PEPPLER. O Region 3. Chicago. Office of the Director 81/03/11 2pp 07972 193
- 9103200695 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades" No action required KEPPLER.J.O. Region 3, Chicago, Office of the Director. 81/03/13 2pp 07966-133
- 8103200269 Forwards IE Info Notice 81-07. "Potential Problem MrMatter Salubis Purse Dam Matts Used During Inert Gas Welding." No response required.
  KERPHERL J 0 Region 3. Chicago. Office of the Director 81/03/16 2pp. 07966 226.
- 8103261193 Responds to 1E Bulletin BO-25. "Operating Problems W/Terget Rock Bafety Relief Valves at BURs." Engineering review of LaBaile safety relief valve pneumatic supply sys still in progress Rods will be completed prior to fuel loading. RAUBCH.T J. Commonwealth Edison Co. 81/03/19. 7pp. 08040:252.
- 8103270484 Confirms info in 800610 response to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls." Valves 2301-64.65.29 t 30 close on HPCI supplication. HPCI auxiliary oil pump will not deplete power source JANECEK-R. F. Commonwealth Edison Co. 81/03/20. 4pp 08046 221.
- R. Periodic operating reports & related correspondence
- 8103020369 Forwards semiannual rept re radioactive effluent discharges 5 solid radioactive waste for Jul-Dec 1980 SCOTIN J Componwealth Edison Co. 81/02/06 1p. 07784.234
- --8103020374 Semiannual rept re radioactive effluent discharges & solid radioactive waste for Jul-Dec 1980
   Corronwealth Edison Co. 81/02/96. 15co. 07784:235
- 8103030792 Forwards occupational radiation exposures rapt for 1980 817EL.J S Commonwealth Edison Co. 81/02/25 ip. 07795:085.
- --8103030807 Occupational radiation exposures rept for 1980. # Commonwealth Edison Co. 81/02/25 3pp. 07798:056.
- 8103130353 Forwards monthly operating repts for Feb 1981. SCOTE D J Communication Edison Co. 81/03/03. 1p. 07911-121.

- --8103130358 Monthly operating repts for Feb 1981 MAXMELL,D C Commonwealth Edison Co 81/03/03 17pp 079|| 122
- 8103240348 Forwards "Annual Operating Rept for 1980" ECDIT.D J. Commonwealth Edition Co. 81/03/11. |p. 07987-185
- --BI03240353 "Annual Operating Rept for 1980 "

  \* Commencealth Edison Co BI/03/11 23pp 07987 186
- S. Reportable occurrences. LERs & related correspondence
- Bi03030418 PKO-111-B0-234 on B01219 unit shut down for scheduled outage. Tech Specs violated when primary containment personnel doors stayed open & when reactor pressure was 90 psig w/HPCI & isolation condenser sys out of svc TOMOUE.T. REIMANN.F. HEISIMAN.R.F. Region 3. Chicago, Office of the Director B0/12/22, 2pp 07799 013

- --Bi03090552 LER Bi-004/63X-i on Bi0102, discovered that surveillance procedure. DIB 500-B. EHC low oil pressure scram. not performed Caused by personnel error Surveillance performed & personnel reinstructed MCGEC. W.E. Commonwealth Edison Co. 81/02/19 ip 07845, 259
- 8:03:7053: Forwards LER 8:-006/03L-0 8CDTT.D J Commonwealth Edison Co 8:/03/07 to 07925:86
- --BIO3170537 LER 81-006/03.-0 on BIO212, during normal operation, BBLC sodium pentaborate solution temp dropped to 77 F. in violation of Tech Bpec Figure 3 4 2. Caused by incorrect setting of 86 F for temp controller Betpoint was raised MAGROW.R. Commonwealth Edison Co B1/03/09 2pp 07925 187
- B103240307 PND-III-B1-032 info pickets set up at facility gate by operating engineers Local 150 AFL-CIO against McCarten & McGullen, Inc. Pickets established because contractor does not have operating engineers on site.

  TDNOUE.T., CREED.J Region 3. Chicago, Office of the Director B1/03/16 1p
- --8103240450 LER B1-007/03L-0 on 910218, during surveillance, refueling floor area radiation monitor Ch A tripped at 105 mr/h, esceeding 100 mr/h limit per Tech Spec Caused by instrument drift Betpoint adjusted & operability verified.

  RHEE: 8 J. Commonwealth Edison Co 81/03/13 ip. 07984:313
- T Hearing transcripts on non-antitrust matters
- Bi03290014 Forwards HK Shew supplemental testimony on spent fuel assembly channel bowing. Discusses Bi0313 conference call re ASLB Question 2 % related testimony.

  ODDDARD. R. J. Hearing Branch 2. 81/03/23. Ip 07998:028.
- --BI03250022 Bupplemental testimony on spent fuel assembly channel bowing Concern re interference developed between walls of fuel assemblies & storage locations within proposed spent fuel racks is not safety problem. If/prof qualifications.
  BHAM: H. K. Operating Reactors Assessment Branch. B1/03/23 5pp. 07998:029.
- V Operator Examinations
- 8103030769 Forwards supplemental info re shift technical advisor training-per NUREQ-0737. Item I. A. 1. I (3) Info includes response to training requirements for shift control room engineers & projected schedule for training completion.

  ABEL-J.S. Commonwealth Edison Co. 81/02/24. 4pp. 07796-085.
- Bi03050140 Forwards list of shift control room engineers meeting training & education requirements by dates indicated Many engineers completed training by Bi0101. Target date for completion of training is mid-1981.

  ABEL-J.S. Commonweelth Edison Co. B1/02/24. 4pp. 07821:324.

- 8103203574 Forwards supplemental info re long-term shift technic advisor program. Including candidate qualification, selection criteria, training plans & bases for phase-out of shift technical advisor program mandates by NUREG-0737 ABEL. J S Commonwealth Edison Co 81/03/17 1900 07972 08
- DOCKET 50-290 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- B103090400 Forwards addl info re diesel generator outages.per It II K 3 17 of NUREG-0737 Info supple B10101 submittal. UNRIGER E Florida Power & Light Co 81/03/03 Spp
- 8103030330 Forwards first round comments & requests for add1 info util B10102 radiation emergency plan Add1 info needed re names of individuals responsible for each organization response & ambulance transportation support VAROA-S A Operating Reactors Branch 1 01/02/07 19pp 07791 164
- B103120765 Approves util B10213 request for extension of complete dates for four fire protection sys nods per 790321 SER FR notice encl
  DENTON.H R Office of Nuclear Reactor Regulation. Director B1/02/13 3pp 07903 056
- --Bi03120774 Notice of extension until 810802 for completion of a fire protection sys CASE.E.Q Office of Nuclear Reactor Regulation, Director 81/02/13. p. 07903-059
- B103050320 Releases public version of Revision 6 to emergency pla facility. FELTON, J M Division of Rules and Records 81/02/17 ip 07806 001
- --8103050324 Forwards public version of Revision & to emergency p facility UHRIO.R E. Florida Power & Light Co. 81/02/02. 3pp 07806
- --Bi0305032? Public version of Revision 6 to emergency plan for f \* Florida Power & Light Co. Bi/01/30 22gg 07806 00t
- 8103180264 Ltr to all power reactor licensees u/plants licensed p to 790101 Forwards NRC position 8 request for addl info re safe shutdown capability for compliance u/801119 fire protection rule EISENHUT.D Q Division of Licensing. 81/02/20. 13pp
- B1033:033B Ltr to all licensees of operating plants & holders of forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRG requirements Who enci EISENRUT, D.G. Division of Licensing 81/03/05 6pp
- 8103260972 Forwards emergency planning info for placement in LPDR 8103090324
  BOUDER, J. L. Division of Rules and Records 81/03/11 ip. 08040 282
- 8103250343 Requests exemption from certain requirements of 10CFR5 & App R re-extension of submittal & Implementation dates refire protection program
  UHRIG-R.E. Florida Power & Light Co. 81/03/19. 17pp 08040.
- B103270612 Forwards emergency planning info for placement in LPDR B103050324.
  SDUDER, J. L. Division of Rules and Records. \$1/03/19 ip. 08043:041.
- G Adjudicatory correspondence
- 8103030892 Forwards comments on NUREG-0743.DES for steam generato repairs at facilities by intervenor MP Oncavage.J Lorion. T Brown.M Joldberg.J Allen.MZ Morgan & G Minor Extension to 810302 for submission granted ONCAVA
- Biogo90023 informs of error in section refs to updated steem gene repair safety evaluation in Paragraphs 3.5 % 6 on Pages 4 % 5 of NRC Bio220 summary disposition motion. Correct cite should be Section 3.2.3. GOLDBERO.S.C. Hearing Branch 2. Bi/O3/O5. ip. 07849.123

conferences Evidentiary hearing to commence 810602 Limited appearance statements will be permitted at hearing MILLER.M.E. Atomic Safety and Licensing Board Panel 81/03/10 2pp 07911 200

- Bio3230701 Answer supporting ARC 790223 netton for sunmary disposition of Contention 14 No genuine issue exists u/nespect to 15 mgtl facts listed in motion Centificate of Svc enc] REIS.H F Florida Power & Light Co REIS.H F Cowenstein.Newman.Reis.Azelrad & foll 81/03/16 5pp 07974 326
- 8103240394 Second notion for surrary disposition of Contentions 2 & 6 No documents or evidence exist establishing senume dispute as to matl facts Dismissal of contentions is varranted as a matter of law GCL DESR2.8 C Hearing Branch 2. 81/03/23 10pp 07987 276
- --B103240405 Affidavit re Contention 2. Licensee workforce is sufficent to satisfactorily & safely perform necessary repair activities. Licensee proposed programs & procedures for steam generator repairs meet requirements W/prof qualifications. MINNS. J. Radiological Assessment Branch. 81/03/10 7pp NOAD DBA
- --8103240414 Affilavit re Contention 2 In applying ALARA concept.NRC uses qualitative, programmatic approach rather than imposing quentifative operating limit Prof qualifications encl NEMEMIAS. J. V. Radiological Assessment Branch 81/03/19 1339 0797 293
- --BI03240519 Affidavit re Contentions 6(a), (b), (c) & (e) Storage structure will be located at olevation of 17.5 feet mean low water Design basis flood would not cause significant innersion of steam generators. Prof qualifications and COBELLA B. Hydrologic & Geotechnical Engineering Branch BI703/11 & &pp. 07987:306
- --Bi03240526 Affidavit re Contention 6(d) Protebility of through-wall corrosion crack is so small as to be insignificant Sept welds required to be coaled dyvarnies to assure no injress of organ through seal weld Prof qualifications encl TUROV.IN.3 Chemical Engineering Branch B1/03/09 4pp 07987-312
- --BIO3240531 Affidavit re Contention Atel Risk of leatage of radioactive matl from storage facility is effectively eliminated of applicant provision of concrete floor Steam generator assemblies may be stored in bidg H/Centificate of Svc. GROTEN-UIS.M. Operating Reactors Branch 1. BI/O3/12 4pp 0.7987 316
- H General correspondence
- 8103030693 Comments on DES released generator repairs Document fails to approach basic characteristics necessary for ASLD to ejercise statutory powers ALARA criterion does not address environ impact.

  JAPFER, J. Affiliation Unknown 81/02/20 4pp.
- B103180649 Requests cornents & views on encl util ltr re licensing schedule CHILES.L Senate. 81/03/10 ip 07953 170
- --8103180653 Urges licensing schedule be revised to reflect Oct 1982 completion date not Dec 1983 MCDDMALD.M Florida Power & Light Co 81/03/03. Spp 07953 171
- B103230667 Forwards newspaper article re danger of cancer to facility uprhers during upcoming steam generator replacement FAIRFIELD. P. Affiliation Unknown 81/03/10. 2pp 07976:354.
- J. Insurance & indemnity information
- B103060327 Forwards Endorsement 45 to MAELU Policy MF-55 FIELDER, J. Marsh & McLennan, Inc., K & M Nuclear Consultants, Inc. Div. B1/01/27, 2pp. 07840 223
- B103050330 Forwards Endorsement 4 to MAELU Binders XB-25 & XB-26 FIELDER, J. Marsh & McLennan, Inc., M & M. Nuclear Consultants, Inc. Div. 81/01/27 599 07836, 345
- B103110447 Forwards Endorsement 5 to MAELU SFP Binders X8-25 & XB-26 FIELDER, J. Harsh & McLennan, Inc., M & M Nutlear Consultants, Inc. piv 81/03/06 3pp 07873 338.

- 8103190732 Line to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NURCO-0612 Forwards NRC position to interim actions & request for addl info cremmust. n o Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for U. & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREO-0737 FIST.WHIT. D Q Division of Licensing 81/01/19 bpp
- B103120014 Ltr to all licensees of operating plants.CP holders & UL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1. for warding inadvertently omitted pages from NRC 801222 request for add1 info re control of beavy loads.

  EISENHUT, D O Division of Licensing B1/02/03 App.
- B103300160 Ltr to all operating PHR licensees requesting info on auriliary feedwater sys seismic design Forwards request for additofo. List of actions requested of licensees w/o seismically qualified sys & results of NRC walldowns EISENHULD 0 Division of Licensing B1/02/10 13pp
- B103040784 Forwards preliminary review of environ qualifications of safety-related electrical equipment Potential equipment deficienties found involving lack of proper documentation t/or inadequate environ testing of equipment.

  MOVAK.T II Assistant Director for Operating Reactors B1/02/il 3pr 07812 192
- --BIOJO40994 "Equipment Evaluation Rept." partial review List of equipment requiring addl info &/or corrective action enci • Equipment Qualification Dranch BI/OZ/II 33pp 07812 175
- B103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 to upgrade of prergency support facilities Requests confirmation within 45 days that implementation dates will be mot EISERHUT.0 0 Division of Licensing B1/02/1B 12pp.
- Bio3250024 Ltr to all power reactor licensees & license applicants or MXREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing Jeletions Licensee may submit analysis to justify use of existing low flow controller.

  EISE(HAUT, D O Division of Licensing, BI/O2/20 Opp
- B103060265 Forwards Amends 63 % 95 to Licenses DPR-31 % DPR-41, respectively % notice of issuance & availability VAROA.6. A Operating Reactors Branch 1 81/02/23 3pp 07839 23/
- --8103050267 Amends 63 & 55 to Licenses DPR-31 & DPR-41 respectively, moving precipitation sample station to uncontaminated area, insuring capability of obtaining reliable monthly precipitation samples from unsite location VAROA+8 A Operating Reactors Branch 1. 81/02/23. 6pp. 07839:240
- --8103060269 Notice of issuance & availability of Amende 63 & 93 to Licenses DPR-31 & BPR-41 respectively. WAROALS A. Operating Reactors Branch 1 81/02/23 2pp. 07839:266
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for GLs (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISEGHUT.D 0 Division of Licensing. 81/02/25. Spp.
- 8103230813 Generic Ltr 81-06 to all CP holders & JL applicants re-ICCFR80 71(e), "Periodic Updating of FBARs," effective 800722. Info re-FBAR legal status, format & content encl. EIBENHUT.D C. Division of Licensing. 81/02/26. 10pp
- 8103060622 Responds to NRC 810211 partial review of environ qualification of mafety-related electrical equipment.

  Meetings should be held between NRC & util to identify each concern.

  UNREGRE Florida Power & Light Co 81/02/27. 5pp. 07840-340
- B103100334 Submits safety & power operated relief valve actuations for Apr-Dec 1989, per NUREO-0737 & NRC 800807 ltr re five edd1 TMI-2 related requirements for operating reactors. UHRIGR E. Florida Power & Light Co. 81/02/27, 1p. 07865.064
- Bi03100314 Advises that info requested in NRC B01031 ltr re containments upps & insulation will be submitted by B10401.
  UNRIG.R.E. Florida Power & Light Co. 81/03/02 lp. 07865:059

- BIO3090400 Forwards and into re diesel generator outages, per Item 11 K.3 17 of NUREG-0737 Info supple BIO101 submittal UMRIO, R E Florida Power & Light Co B1/03/03 Spp 07846 179
- G103110510 Application for arond to App A of Licenses DPR-31 & DPR-41 changing Tech Specs to conform w/Reg Guide 1.14 & Section XI of ASME Ociler & Pressure Vessel Code MARIO.R & Florida Power & Light Co 81/03/09. 2pp. 07878 210
- --8103110513 Tech Spec Table 4 2-1 Item 7 1 for reactor coolant pump flywbre1 Safety evaluation encl. • Florida Power & Light Co 81/03/05 2pp 07878.212
- B103110663 Application to amend App A of Licenses DPR-31 & DPR-41, enabling 28% tube plugging level UMRICH R F Floride Power & Light Co B1/03/05 3pp. 07882 266.
- --BI03110672 Proposed App A Tech Spec Pages 2 3-2,2 3-3,3 1-7 & 3 2-3 & Figures 2-1-16 & 3 2-3 re 28% tube plugging level Florida Power & Light Co. 81/03/05 67pp. 07882,269
- 8103230261 Forwards errata to NUREQ-0756 VARQA.6 A Operating Reactors Branch 1 81/03/09 2pp 07974 355
- --8103230291 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR REPAIR AT TURKEY POINT PLANT, UNITS 3 AND 4.

  4 Office of Nuclear Reactor Regulation. Director NUREO-0756 ERR 81/03/09. 2pp 07974 357.
- 8103180649 Requests comments & views on encl util ltr re licensing schedule
  CHILES.L. Senate 81/03/10 in
- --8103180653 Urges licensing schedule be revised to reflect Oct 1982 completion date, not Dec 1983. MCDDNALD,M Florida Power & Light Co 81/03/03 5pp 07933 171.
- BiO3190700 Forwards review comments from State of Ft. Dept of Environ Regulation on DEB re steam generator repair at facilities.

  During preparation of FES for project-encl comments should be considered & responded to accordingly

  KGLS-W. O. Filorida, State of Bi/03/10 3no 07965 174
- B103230617 Application to amend App A of Licenses DPR-31 & DPR-41, revising Tech Specs re facility fire protection mods described in NRC 790321 safety evaluation Pages from OL, reflecting proposed changes, encl. UHR10:R E. Florida Power & Light Co. 81/03/10. 5pp. 07975:320
- --Bi03230631 Proposed Tech Spec Pages 3 14-1.3.14-2.3 14-3.3 14-4.4.19-1.
  4.15-2.4.15-3.6-5.6-6 & B3 14-1 re fire protection mods
  Florida Power & Light Co. 81/03/10. 10pp. 07975-333
- 8103270879 Application to amend Licenses DPR-31 & DPR-41 revising Tech Spec & O re-administrative controls UHRIO,R.E Floride Power & Light Co 81/03/10. 4pp. 08043:203.
- --Bi03270883 Proposed Tech Spec 6 Q for administrative controls.

   Florida Power & Light Co. Bi/03/10. 9pp. 08043-207.
- 8103310376 Application for amend of Licenses DPR-31 & 41 changing license contained in 800702 ltr.re TMI-related changes.

   Florida Power & Light Co. 81/03/10. 3pp. 08075.169.
- --8103310380 Proposed Tech Specs 6.13 re environ qualifications sys integrity, indine monitoring & backup methods for determining subcooling mergin # Florida Power & Light Co 81/03/10, ip 08075:172
- 8103310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish soviron qualification of safety-related electrical equipment.
  EISENHUT, D. Q. Division of Licensing. 81/03/10 opp.
- 8103170427 Comments on NUREO-0743.DES.re steam generator repair at facilities Open storage should be held onsite as precaution for over-degradation of steam generator DOHERTY-J.F. Affiliation Unknown. 81/03/12. Ip.

- 8103310329 Forwards safety evaluation by Dfc of Nuclear Reactor Regulation, documenting analysis that radiological effluent releases during plant operations will conform u/dose design objectives
  GLDBERDS C Hearing Granch 2 81/03/30 in 08079 ID7
- --B103310335 Safety evaluation documenting analysis that radiological effluent releases during plant operations will conform widose design objectives
- w/dose design objectives

  Office of Nuclear Reactor Regulation, Director B1/03/27

  10ps. 08-379 109
- Q Inspection reports. IE Bulletins & correspondence
- 8i03120829 Forwards 1E Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required O'REILLY.J P. Region 2. Atlanta. Office of the Director 80/12/10 Ip. 07906-015
- 8103030293 Forwards 1E lnsp Repts 50-290/80-33 & 50-251/80-32 on 801001-31 No noncompliance noted LEVIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/12 2pp 07790-344
- --Bi03030306 IE insp Repts 50-290/80-33 % 50-251/80-32 on 801001-31 Noncompliance noted Major areas inspected licensee implementation of TMI task action plan Category A stem requirements & surveillance test observations IGNATORIS.A J. MARSH.H C. Region 2. Atlanta. Gefice of the Director. MARIN.R D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/01/07 8pp. 07790-346
- B103090792 Forwards IE Mgt Meeting Repts 50-250/80-31, 50-291/80-29, 50-335/80-33 & 50-389/80-14 on B01029 No noncompliance noted.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/03 2pp. 07848 262
- --8103090766 1E Mgt Meeting Repts 90-250/80-31.30-251/80-29.50-335/80 & 50-389/80-14 on 801029 to discuss results of evaluation of util regulatory performance LENIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. Bi/02/02 219p. 07848.264.
- B103020251 Forwards IE Circular 81-02, 'Performance of N9C-Licensed Individuals While on Outy " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/09 ip 07785-321.
- B103040742 Responds to 1E Bulletin B0-11 Adequacy of 60 masurry walls has been confirmed by re-evaluation Remaining 37 walls scheduled for re-evaluation completion by Mar 1981. URIGER E Florida Power & Light Co. B1/02/11. 1p 07810.124.
- 8103040164 Forwards IE into Notice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/10CFR30 72 " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/12 ip. 07813 001.
- BiO3230409 Forwards response to Suppl 3 of IE Bulletin 79-018. "Envir Qualification of Class IE Equipment" & updates B00703 response to bulletin New component evaluation sheets & revised master list pages encl. URRIO, R.E. Florida Power & Light Co. 81/02/12. 28pp. 07979 247
- 8103130090 Forwards request for add1 info re IE Bulletin B0-06 response. Response should be submitted within 45 days. VARQA.5.A Doeraking Reactors Branch 1 81/02/23. 3pp. 07912 00
- 8103160718 Forwards IE info Notice 81-04, "Cracking in Main Steam Lings." No response required. O'REILLV.J P. Region 2, Atlanta, Office of the Director 81/02/27 ip. 07914.100.
- 8103160663 Forwards IE Circular 81-03, "Inoperable Saismic Monitoring Instrumentation." No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/03/02 1p. 07914-262.

- BiD317C028 Forwards revised 1E Bulletin Bi-Oi. "Burveillance of Mechanical Snubbers." w/corrected Pages 9 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY. J P. Region 2: Atlanta: Office of the Director 81/03/06
  12 07939 153
- 8103190282 Ack receipt of 810224 ltr informing MRC of steps taken to correct violations noted in IE insp Repts 50-250/E0-36 & 50-251/80-34 Region 2. Atlanta, Office of the Director 81/03/10 LEWIS, P. C
- Sp. 07965 371
- --B103193294 Resconds to NRC 810130 ltr re violations noted in IE losp 10319299 Responds to NHC BIUI30 It re-violations noted in it insp. Repts 50-250/80-36 & 50-251/80-34 Corrective actions gipe support returned to original configuration & insulation reinstalled No proprietary sinfo LHR10.R E Florida Power & Light Co Bi/02/24, Spp. 07965-322
- --8103190300 Forwards IE Insc Repts 50-250/80-36 & 50-251/80-34 on BOILOL-30 & notice of violation
  LEMIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support
  Branch. 81/01/30 2pp 07965-327
- 48103193306 Notice of violation from insp on 801101-30

   Region 2, Atlanta, Office of the Director 81/01/30 lp
- --8103190312 IE Insp Repts 50-250/80-35 \$ 50-251/80-34 on 801101-30 Noncompliance noted failure to fully restore whom a portions of safety-related sys to normal conditions following maint IGNATORIES.A.J. MARSH.W.C. Region 2. Atlanta. Office of the Director JULIAN.C.A. Region 2. Atlanta. Office of the Nicelear Support Branch. B1/01/29 &pp. 07965:330
- BLOD20027: Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breaker" No response required D REILLY J.P. Region 2. Atlanta. Dffice of the Director 81/03/11 lp. 07849-007
- Bit/3240244 Ack receipt of 810303 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-250/80-33 % 50-251/80-33 Finding E. re control of tegs locks & combinations, reading open pending security plan revision LEWIS.R.C. Region 2. Atlanta: Office of the Director 81/03/88 Ir. 07780 260
- --8103240249 Responds to NRC 810206 ltm re violations noted in IE Insp. Repts 50-250/80-33 & 90-251/80-33 Corrective actions withheld fref (DCFR2 790) UHRIO.R E Florida Power & Light Co 81/03/03. Ip 07980 261
- --8103240257 Forwards 1E Insp Repts 50-250/80-35 & 50-251/80-33 on 801201-05 & notice of violation Natice of violation withheld (ref 10CFR2, 790) KENNA, W. B. Region 2: Atlanta, Safeguards Branch 81/02/06 2pp. 07980:262
- --8103240261 IE Insp Repts 50-250/80-39 & 50-251/80-33 on 801201-05 10324026) It has repts 50-250/80-35 & 50-25/89-33 on 80/201-05 Noncompliance noted failure to maintain surveillance of escorted vehicle & to search all areas of vehicle. Details withheld (ref 10GFR2 790) TILLMAN. A. PERNY-C D. Region 2. Atlanta, Oppice of the Director ECGUIRE. D.R. Region 2. Atlanta, Befeguards Branch B1/02/05 07980 264
- 8103200019 Forwards IE Info Notice 81-05. "Degraded DC Bys at Palisades.' No response required.

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director - 61/03/13

  1g. 07969-083
- R. Periodic operating reports & related correspondence
- 8103110711 Forwards 'Radioactive Effluent Release Date.Jul-Dec 1980." & "Environ Radiological Monitoring Program Surrary, Dade County, FL, Jul-Dec 1980 UHRIO.R E Florida Power & Light Co 81/03/02. 1p 07885-097
- --8103110714 "Radioactive Efficient Release Data, Jul-Dec 1980 " Florida Power & Light Co 81/02/21. 15pp. 07865 098.
- --8103110719 "Environ Rediological Monitoring Program Survey, Dade County, FL. Jul-Dec 1980, " Florida Power & Light Co. 81/03/02, 13pp. 07885-113.
- BLO3130350 Forwards monthly operating repts for Feb 1981 SCHMIDT A D. Florida Power & Light Co. B1/03/07 ip 07911 107

- --8103130334 Monthly operating repts for Feb 1981 CHILSON V T Florida Power & Light Co 81/03/07 900. 02011 IAG
- S Reportable occurrences. LERs & related correspondence
- 8103060325 RD 250-81-3 on 810105, while investigating potential observed in GC Type MFA relay coil spools, new coil assembly was confirmed to have cracked spool end plate Insp program is being developed HAYS, J.K. Florida Power & Light Co. 81/01/06 1p. 07586
- 8103160731 Forwards LER 81-004/03L-0 SCHMIDIAD Finida Power & Light Co. 81/02/19 to 079
- -- 8103150735 LER 81-004/03L-0 on 810120.auxiliary feedwater pu provided the discovery of the pressure control valve CV-3705 and to meet acceptance criteria per Tech Spec Caused by damage valve plug in steam turbine pressure control valve CV-3705 and tause not determined Stem & plug replaced PACE: P L Florida Power & Light Co B1/02/19. 1p 0791
- I Hearing transcripts on non-antitrust ratters
- 8103270498 Transcript of 810324 hearing in Homestead.FL re pro amends to Pacifity operating rights permitting steam generator repairs Pp 1-208

  Atomic Safety and Licensing Board Panel BI/03/24. 213p 08032.078
- U Congressional/Esecutive Correspondence
- 8103270110 Responds to request for rept on possible addl impro to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
  MENDRIE.J.M. Cormissioners 81/03/12 Spp.
- --8103270947 Bubmits recommendations re-scheduling.personnel r hearing mgt for OL proceedings Panel rust obtain exemption from hiring freeze for two recently appointed chairmen. COTTER.B.P. Atomic Safety and Licensing Board Panel. 617
- V Operator Examinations

07806 031

- 8103160259 Grants util 810112 request for 1-month extension fo 1980-81 licensed operator requalification progra COLL INB. P. F. Operator Licensing Branch 81/03/06 1p.
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4 F. Security, medical, emergency & Pire protection plans
- 8103030330 Forwards first round comments & requests for add1 i util 810102 radiation emergency plan Addl info needed re names of individuals responsible for each organization response & ambulance transportation support
- 07791 164. B103120765 Approves util B10213 request for extension of compl dates for four fire protection sys nods per 790321 BER. FR DENTON H R Office of Nuclear Reactor Regulation, Director B1/02/13. 3pp 07903 056

VARQA.S.A. Operating Reactors Branch 1. 81/02/07. 19pp.

- -- B103120774 Natice of extension until 810802 for completion o fire protection sys. CASE E.O. Office of Nuclear Reactor Regulation, Director B1/02/13. 1p. Q7903:059.
- B103050320 Releases public version of Revision 6 to emergency FELTON J.H. Division of Rules and Records. 81/02/17. ip.
- --8103050324 Forwards public version of Revision 6 to emergenc Pacility. UHRIG-R.E. Florida Power & Light Co. 81/02/02. 3pp. 07
- --8103050329 Public version of Revision 6 to emergency plan fo \* Florida Power & Light Co 81/01/30. 22pp. 07806:001

- S103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101. Forwards NRC position & request for addl info resafe shutdown capability for compliance w/801119 fire protection rule riscituation of Licensino 81/02/20 17cm
- B103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements N/o encl EISENHULD 9 Division of Licensing B1/03/05 App.
- 8103260972 Forwards emergency planning info for placement in LPDR W/o 8103090324 SOUDER-J L Division of Rules and Records 81/03/11 1p
- Bio3260543 Requests exemption from certain requirements of 10CFR50 48 & App R Telestension of submittal & implementation dates refire protection program intRIO.RE Florida Power & Light Co. Bi/03/19 17an OBD40 178
- 8103270612 Forwards emergency planning into for placement in LPOR M/o 8103050324.

  SCUDER, J.C. Division of Rules and Records 81/03/19 ip openal out
- O Adjudicatory correspondence
- 8103030892 Forwards comments on NUREO-0743.DEG for steam generator repairs at facilities by intervenor HP Oncavage.J Lorion, T Brown.W Goldberg.J Allen.W2 Morgan & O Minor Extension to B10302 for submission granted DNCAVAGE.M P Affiliation Uninown 81/02/26 136pp 07798-095
- B103090023 Informs of error in section refs to updated steam generator repair sefety evaluation in Paragraphs 3.5 & 6 on Pages 4 & 5 of NRC B10220 summary disposition motion Correct cite should be Section 3.2.3 GCLOBER0.8 C. Hearing Branch 2. 81/03/05 1p 07849.123
- 8103130402 Notice of 810324-23,0427-28 & 0921-22 prehearing conferences Evidentiary hearing to commence 810602 Limited appearance statements will be permitted at hearing MILLER.H E. Atomic Befety and Licensing Board Panel. 81/03/10 2pp. 07911:200
- B103230701 Answer supporting NRC 790220 motion for summery disposition of Contention 14. No genuine issue exists w/respect to 19 mat) facts listed in motion. Certificate of Svc encl.
  REIB.H F Florida Power & Light Co. REIB.H F.
  Lowenstein.Newman.Reis.Axelrad & Toll. B1/03/16. Spp. 07974:326
- 8103240394 Second motion for summary disposition of Contentions 2 & 6 No documents or evidence exist establishing genuina dispute as to matt facts Dismissal of contentions is warranted as a matter of law GOLDSERO.B.C. Hearing Branch 2. BI/03/23 10pp 07907:276
- --Bi03240405 Affidavit re Contention 2 Licensee workforce is sufficent to satisfactorily & safely perform necessary repair activities Licensee proposed programs & procedures for steam generator repairs meet requirements. W/prof qualifications.
  MINNS.U.L. Rediological Assessment Branch. 81/03/10. 7pp 07987-284
- --Bi03240414 Affidevit re Contention 2. In applying ALARA concept,NRC uses qualitative,programmatic approach rather than imposing quantitative operating limit. Prof qualifications encl. NEHEMIAB. J. V. Rediological Assessment Branch. Bi/03/19, 13pp. 07987-299
- --8103240519 Affidavit re Contentions 6(a), (b), (c) & (e). Storage structure will be located at elevation of 17.5 feet mean low water. Besign basis flood would not cause significant immersion of steem generators. Prof qualifications encl. COBELL-R.B. Hydrologic & Geotechnical Engineering Branch. 81/03/11. 6pp. 07987:306
- --Bi03240526 Affidavit re Contention old). Probability of through-wall corrosion crack is so small as to be insignificant Seal walds required to be coated w/warnish to assure no ingress of daygen through seal wald. Prof qualifications encl. TURDW.IN.8. Chemical Engineering Brench. 81/03/09 4pp. 07987-312

- --8103240531 Afficavit re Contention 6(e) Risk of leakage of rad mat1 from storage facility is effectively pliminated a/applicant provision of concrete floor Steam generator assemblies may be stored in bldg W/Certificate of Svc GROTEN-015. M. Operating Reactors Branch 1. 81/03/12 4pp 07987 31A
- H General correspondence
- 8103030680 Cornents on DES re steam generator repairs Document f. approach basic characteristics necessary for ASL8 to ejective statutory powers ALARA critorion does not address environ impact JAFFER. J. AFFIliation Unknown 81/02/20 4pp
- 8103180649 Requests comments & views on enci util ltr re licensis schedule. CMILES-L Senate 81/03/10 in 07953 170
- 0103230667 Forwards newspaper article re danger of cancer to facworkers during upcoming steen generator replacement FAIRFIELD.R P. Affiliation Unknown 81/03/10 2pp 07976 3
- J insurance & indemnity information
- 8103040327 Forwards Endorsement 45 to MAELU Policy MF-55 FIELDER: J. Warsh & McLennan: Inc., M & M Nuclear Consultants, In DIV 81/01/27 2pp 07840 223
- 8103060330 Forwards Endorsement 4 to MAELU Binders x8-25 & X8-26 FIELDER. J. Marsh & McLennan, Inc. , N & M Nuclear Consultants, It DIV. 81/01/27 5pp 07836 345
- 8103110447 Forwards Endorsement 5 to MAELU SFP Binders X8-25 \$ XI FIELDER.J Harsh & McLennah Inc., M & M Nuclear Consultants, fr Div 81/03/06 3pp 07873 338
- P . Depending license stage documents & correspondence
- 8103190732 Ltrs to all licenses of operating plants applicants of DLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-Ob12 Forwards NRC position reinterim actions & request for addl info
- 8i0i190319 Discusses followup study re degradation of internal appurtenances in LMR piping during normal plant operation & potential effects chem degraded appurtenances are subj to accident loads Recommends broad review of recurrent problems BROWN-E. J Director's Office 80/12/24 4pp.
- 8)03:90387 Ltr to a)) licensees of operating plants & applicants OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Itoms addressed involve cold shutdown-replacement parts & NUREO-0737 EIBENHUT.D.O. Division of Licensing. 8:/01/19 App.
- BiO3120014 Ltr to all licenses of operating plants CP holders & applicants, except Indian Point 2 & 3.7 ton 1 & 2 & TMI-1, forwarding inadvertently omitted pages from MRC B01222 request for addl info re control of heavy loads EISENHUT. D G. Division of Licensing. BI/02/03 opp.
- 8103300160 Ltr to all operating PWR liconsees requesting info on auxiliary feedwater sys seismic design Forwards request for addl info. List of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISENHUT. D G. Division of Licensing 81/02/10 13pp
- B103040984 Forwards preliminary review of environ qualifications safety-related electrical equipment Potential equipment deficiencies found involving lack of proper documentation 6/or inadequate environ testing of equipment. NDVAK, T. M. Assistant Director for Operating Reactors. B1/02/13pp. 07812:192.
- ~-B103040974 "Equipment Evaluation Rept," partial review.List of equipment requiring additinfo &/or corrective action encl.

  \* Equipment Qualification Branch. B1/02/11. 33pp. 07812 1
- 8103160667 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A.1.2 re upgrade of amergancy support facilities. Requests confirmation within 45 days that implementation dates will be met.
  EISENHUT.D.G. Division of Licensing. 81/02/18 | 12pp

- 8103250024 Ltr to all power reactor licensees & license applicants re KUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISERBUT.D Q Divysion of Licensing 81/02/20 Epp
- B103060265 Forwards Amends 63 & 55 to Licenses DPR-31 & DPR-41.

  respectively binotice of issuance biavailability

  VAROALS A Operating Reactors Branch 1 81/02/23 3pp 07839 257.
- --8103050267 Arends 63 & 55 to Licenses DPR-31 & DPR-41 respectively, moving precipitation sample station to uncontaminated area, insuring capability of obtaining reliable monthly precipitation samples from onsite location VAROA.S A Epenating Reactors Branch 1 81/02/23 6pp 0/2839 240
- --8103060269 Notice of issuance & availability of Amends 63 & 55 to Licenses DPR-31 & DPR-41, respectively VAROA.5 A Operating Reacture Branch | 81/02/23 2c; D7819 204
- B103230030 Lt\* to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to ditigate station blackbout event & promptly implement emergency procedures EISENHUT, D. O Division of Licensing 81/02/25 Spp
- 8103230813 General Ltr 81-06 to all CP holders & CL applicants re lCCFR30 71(e). Periodic Updating of FSARs: " effective 800722 Info re FSAR legal status format & content encl EISERHUT. D O Division of Licensing 81/02/26 10pp
- E103060622 Responds to NRC BI0211 partial review of environ qualification of safety-related electrical equipment Heetings should be held between NRC & util to identify each concern WRIG. R. E. Florids Power & Light Co. 81/02/27. Spp. 07840 340
- B103100334 Subrits safety & power operated rollef valve actuations for Apr-Doc 1980, per NUREO-0737 & NURC 800507 ltr re-five add1 THI-2 related requirements for operating reactors UMRIQ-R E Florida Power & Light Co 81/02/27, 1p 07865.064
- 8103109314 Advises that info requested in ARC 801031 ltr re-containment sumps & insulation will be submitted by 810401 UHRICA E. Florida fower & Light Co. 81/03/02 1p. 07865-059.
- B103100399 Informs that Westinghouse rept for NUREO-0737 Items If. 4.3 1 & 11 K 3 2 will constitute util response, subj to final review Rept expected during Mar 1981.

  UHRIG.R E Florida Pawer & Light Co B1/03/02 1p 07863-095
- 8103090400 Forwards add1 info re diesel generator outages.per Item II.K.3 17 of NUREO-0737 Info supple 810101 submittel UHR10.8 E Florida Power & Light Co 81/03/03 8pp. 07846 175
- BIO3110910 Application for amend to App A of Licenses DPR-3; & DPR-41 changing Tech Specs to conform w/Reg Guide I 14 & Section XI of ASME Builer & Pressure Vessel Code.
  UH910.R.E. Florida Power & Light Co. 81/03/05 2pp 07878 210
- --8103110313 Tech Spec Yable 4 2-1 Iten 7 1 for reactor codlant pump flywheel Safety evaluation enc! 4 Florida Power & Light Co. 81/03/05 2pp 07878 212
- 9103110663 Application to amend App A of Licenses DPR-31 & DPR-41, enabling 28% tube plugging level.

  UMRIGRE Pluside Power & Light Co 61/03/05 3pp. 07882 266.
- --8103110472 Proposed App A Tech Spec Pages 2.3-2.2 3-3.3 1-7 & 3.2-3 & Figures 2-1-16 & 3.2-3 re 28% tube plugging level.
   Fiorida Power & Light Co. 81/03/05. 67pp. 07882-269
- 8103230281 Forwards errets to NUREG-0756 VARGA, B. A. Operating Reactors Branch 1, 91/03/09 2pp. 07974 355,
- --B103230291 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATER REPAIR AT TURKEY POINT PLANT.UNITS 3 AND 4

  \* Office of Nuclear Reactor Agguilation, Director NUREO-0756 ERR: B1/03/09 299 07974-357.
- 8103180649 Requests comments & views on encl util 1tr re licensing schedule
  CHILES-L Senate, 81/03/10 1p

- --DIO3183653 Urges licensing schedule be revised to reflect Dct 1982 completion date not Dec 1983 MCD3/ALD.M Florida Power & Light Co 81/03/03 5pp 07953 1
  - pical 90700 Forwards review comments from State of FL Dept of Environ Regulation on CES re-steam generator repair at facilities During preparation of FES for project encl comments should be considered & responded to accordingly KOLB.W D Florida, State of 81/03/10 3pp 07965-174.
- B103230617 Application to amend App A of Licenses DPR-31 & DPR-41, revising Tech Space re facility fire protection mode described in NRC 790321 safety evaluation Pages from OL, reflecting proposed changes, encl.

  LHRIG.R E Florida Power & Light Co B1/03/10. Spp. 07975 328
- 9103270879 Application to amend Licenses DPR-31 & DPR-41 revising Telegraph 6 0 re administrative controls DRROR E Figure Power & Licht Co. B1/03/10 400 DRD43 2011
- --8103270883 Proposed Tech Spec 6.0 for administrative controls • Florida Power & Light Co. 81703710. 9pp. 08043 207
- B103310376 Application for arend of Licenses DPR-31 & 41 changing license contained in B00702 ltr.re THI-related changes # Florida Power & Light Co | B1/03/10 | 3pp | 08075.169
- --Bi033103B0 Proposed Tech Specs & 13 re environ qualifications, mysintegrity, iddine monitoring & backup methods for determining subcooling mangin

  Florids Power & Light Co. 81/03/10 ip. 08079-172.
- BIO3310804 Ltr to all licensees of operating plants, applicants for (
  & holders of CPs forwarding SECY-Bi-II9 re info necessary to establish environ qualification of safety-related electrical equipment EISENMUT.O G. Division of Licensing 81/03/10 App.
- 8103170427 Comments on NUREO-0743. DES. re steam generator repair at facilities Open storage should be held onsite as precaution for over-degradation of steam generator. DOMERY-0928404101.
- B103230318 Bubmits add1 info no steam generator repair including disposal of spent resins from condensate polishing demineralizer, filling & grading of area within security fence & steam generator lower assembly shipment UHRIQ-R E Florida Power & Light Co. B1/03/13 4pp. 07977 350
- 8103310329 Forwards safety evaluation by Ofc of Nuclear Reactor Regulation documenting analysis that radiological effluent releases during plant operations will conform u/dose design objectives.

  GDLDBER9.B C Hearing Branch 2. 81/03/30. Ip. 08079 107
- --9103310335 Sefety evaluation documenting analysis that radiological effluent releases during plant operations will conform undoes dueign objectives.
   Geffice of Nuclear Reactor Regulation, Director 81/03/27 10pp. 09379 10B
- G Inspection reports. IE Buildtins & correspondence
- 8103120829 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required. D'REILLY.J.P. Region 2. Atlanta. Office of the Director 80/12/8 ip 07906.015
- 8103030293 Forwards IE Insp. Repts 50-250/80-33 & 50-251/80-32 on 801001-31. No noncompliance noted. LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/12 2pp 07790.344
- --Bi03030306 IE Insp Repts 50-250/80-33 & 50-251/80-32 on 801001-31 noncompliance noted Hajor areas inspected licensee implementation of TMI task action plan Cotegory A item requirements & surveillance test observations.

  IONATORISAL J. MARSH.M.C. Region 2. Atlanta, Office of the Director MARTIM.R.D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 81/01/07 Spp. 07790.346

- B103090792 Forwards 1E Mgt Meeting Repts 50-250/80-31.50-251/80-29. 50-335/80-33 & 50-389/80-14 on B01029 No noncompliance noted. O'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/02/03 2cs 07848:262
- --Bi03090766 IE Mgt Meeting Repts 50-250/80-31.50-251/80-29.50-335/80-33 \$ 50-389/80-14 on 801029 to discuss results of evaluation of util regulatory performance LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/02 21pp 07848 264
- 8103130209 Forwards [E. Insp. Rept. 90-251/80-36 on 801229-31 No noncompliance noted CEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B1/02/06 2pp 07908-346
- --B103130217 [E (nep Rept 90-251/80-35 on B01229-31 No noncompliance noted Major areas inspected containment integrated behave rate testing. BROOMS E H Region 2. Atlanta. Office of the Director GUICK. D Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/06 3pp 07908 342
- B103020291 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty 'No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B1/02/09
- 8103040742 Responds to 1E Bulletin 80-11 Adequary of 60 masonry walls has been confirmed by re-evaluation Remaining 37 walls scheduled for re-evaluation completion by Mar 1981 UHRIGAR E Florida Power & Light Co 81/02/11 1p. 07810 124
- 8103040164 Forwards IE Info Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/1006830 72" No written response required D'ARE(ELY.J P. Region 2. Atlanta. Office of the Director 81/02/12 1a 07813 001
- 8103230407 Forwards response to Buppl 3 of IE Gulletin 79-018, "Environ Qualification of Class IE Equipment" & updates 800703 response to bulletin New component evaluation sheets & revised master list pages encl.

  URRIO.R E. Florida Power & Light Co. 81/02/12 28pp 07979 247
- B103130090 Forwards request for add1 info re IE Bulletin 80-06 response. Response should be submitted within 45 days VAR9A.8.4 Operating Reactors Brench 1 61/02/23. 3pp 07912-009
- 9:03:6069 Forwards IE Circular Bi-03. "Inoperable Belsmic Monitoring Instrumentation" No response required. O'REILLY-J P Region 2. Atlanta, Office of the Director 8:/03/02
- 8103170028 Forwards revised IE Bulletin 81-01, "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements 8 REILLY, J. P. Regian 2, Atlanta, Office of the Director. 81/03/04 to.
- B103190282 Ack receipt of B10224 ltr informing NRC of steps taken to correct violations noted in IE linep Repts 30-250/80-36 & 50-251/80-34.
  LEWIS.R.C. Region 2: Atlanta: Office of the Director B1/03/10 ip. 07965:321.
- --Bi03190294 Responds to NRC 810130 ltr re violations noted in IE Insp. Repts 50-250/80-36 & 50-251/80-34. Corrective actions: pipe support returned to original configuration & insulation reinstalled. No proprietary info.
  UHRIG.R.E. Florida Power & Light Co. 81/02/24. Spp. 07965:322
- --8103190300 Forwards IE Insp Repts 50-250/80-36 & 50-251/80-34 on 801101-30 & notice of violation. LEWISR C. Region 2. Atlanta. Reactor Operations Nuclear Support Bronch. 81/01/30. 2pp. 07965:327.
- --8103190304 Notice of violation from insp on 801101-30.

   Region 2, Atlanta, Defice of the Director 81/01/30. ip 07465:324.
- --6103190312 IE Insp. Repts 50-250/80-36 & 50-251/80-34 on 801101-30 Noncompliance noted: failure to fully restore minor portions of safety-related sys to normal conditions following maint. IGNATONIS.A.J., MARSH.M.C. Region 2, Atlanta, Diffits of the Director. JULIAN.C. A Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 81/01/29. 6pp. 07965:330.

- 8103200271 Faruards IE Info Notice 81-06. "Failure of ITE ( Circuit Breaker ' No response required O'REILLY J P Region 2. Atlanta. Office of the Director 1p 07969 007
- 8103240241 Act receipt of 810303 Itr informing NRC of step carrect violations noted in IE insp Hepts 30-290/80-33 & 50-291/80-33 Finding E.re control of keys. locks & combinations, remains open pending security plan revision LEWIS.R C Region 2. Atlanta, Office of the Director & In 0.7980 280
- ~-8103240249 Responds to NRC 810206 Itr re violations note Repts 50-290/80-35 & 50-291/80-33 Corrective actions uithheld (ref 10CFR2 770) UMRIG-R E Florida Pawer & Light Co 81/03/03 Ip
- --8103240257 Forwards IE Insp Repts 50-250/80-35 & 50-251/8 801201-05 & notice of violation Notice of violation with (ref 10CFR2 790) KERNA-W B Region 2. Atlanta. Gafeguards Branch 81/0 07980 262
- --8103240251 IE Insp Repts 50-250/80-35 & 50-251/80-33 on 6 Noncompliance noted failure to maintain surveillance of escorted vehicle & to search all areas of vehicle Detainstell (ref 10CFR2 790)
  TILLMAN.A. PERNY.C D. Region 2. Atlanta, Office of the MCGUIRE.D R. Region 2. Atlanta, Eafeguards Granch Bl. 20p. 07980 264
- 0103200019 Forwards IE Info Notice 81-05. 'Degraded DC 8ys Palisades' No response required O'REILLY-J P Region 2. Atlanta, Office of the Director ip 07969 003
- R Periodic operating reports & related correspondence
- 8103110711 Furvards "Radioactive Effluent Release Data Juj-"Environ Radiological Monitoring Program Summary, Dade County-FL, Juj-Pec 1780 " UHRIO, R E Florida Power & Light Co 81/03/02. 1p 07
- --B103110714 "Radioactive Effluent Release Data, Jul-Dec 198 \* Florida Power & Light Co 81/02/21 15pp 07883 (
- --8103110719 "Environ Radiological Monitoring Program Sucma County, FL. Juli-Dec 1980 " \* Florida Power & Light Co 81/03/07 13pp 07885 j
- 8103130350 Forwards monthly operating repts for Feb 1981 SCHM10T.A D Florida Power & Light Co 81/03/07 Ip
- --B103130354 Nonthly operating repts for Feb 1981 CHILSON, V T Florida Power & Light Co B1/03/07

9pp

- T Hearing transcripts on non-antitrust matters
- 8103270498 Transcript of B10324 hearing in Homestead.FL re omends to facility operating rights.permitting steam generator repairs.Pp 1-208 \* Atomic Safety and Licensing Board Panel 81/03/24 2 08032.078.
- U. Congressional/Executive Correspondence
- Bi03270110 Responds to request for rept on possible add1 in to NRC licensing process Logislation allowing interim operations in advance of hearing completion would reduce delay in licensing process HENDRIE J M. Commissioners. 81/03/12. Spp
- --BIG3270947 Eubmits recommendations re scheduling.personne hearing mgt for QL proceedings.Panel must obtain exempt from hiring freeze for two recently appointed chairmen. COTYER.B.P. Atomic Safety and Licensing Board Panel. 33pp.

### V. Operator Examinations

B103160299 Orants util 910112 request for 1-month extension 1980-81 licensed operator requalification program COLLINS.P. F. Operator Licensing Branch. 81/03/06. 1p

- DOCKET 50-232 UNIV OF NEW MEXICO RESEARCH REACTOR P. Operating license stage documents & correspondence
- 8103030164 Forwards revised NRC Region 4 organization chart.effective SEYFRIT, N V Region 4. Dallas, Office of the Director 81/02/17
- O Inspection reports. IE Bulletins & correspondence
- 8:03200219 Forwards 1E Circular 8:-02, "Performance of NRC-Licensed upacuziv romands is Circular 81-02. "Performance of NGC-licensed Individuals While on Duty 'No written response required SEYFRILK V Region 4. Dallas, Office of the Director 81/02/09 07972 657
- DOCAET 30-254 QUAD-CITIES STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8103120769 "Simulation of Qual Cites 1 Cycle | Operation W/ARMP Code oya (OAINOS.D . XOHJI.F . LAI. J. Broothaven National Laboratory FIN A-3308 HNL-N.BFG-27019 83/06/30 6toc 07703-060
- F. Security, medical. emergency & fire protection plans
- HIG1080051 Releases public version of util draft emergency plan NURES-0654 info entl FELTON. J M Division of Rules and Records 80/12/02 18pp. 07416 038
- --8101230543 Forwards public version of draft emergency plan for generating stations Commonwealth Edison Co 83/04/24 3pp 04837 L69
- --BIOLOSDOAM Public version of draft e-ergency plan for generating • Commonwealth Edison Co 80/07/31 150co 07416 056
- 0101080003 Releases public version of util revised draft emergency plan
  FELTON, J. N. Division of Rules and Records 80/12/03 to 07417 001
- --Bi01220258 Forwards public version of util revised draft emergency plan PEDPLES D L Commonwealth Edison Co 80/05/04 2pp. 09370 009
- --8101080014 Public version of draft emergency plan annex Commonwealth Edison Co 80/07/31 48pp 07417 C 07417 002
- --8101080019 Public version of Revision 1 to graft energency plan a Componeealth Edison Co. 80/07/31 139pp 07417 051
- 8103090032 Forwards Suppl 2 to fire protection safety evaluation for previously unresolved open items Also forwards listing of current status of all items identified as requiring action during fire protection review IPPOLITO, T A Operating Reactors Branch 2 81/02/12 2pp 07852 182.
- --BI03090037 Suppl 2 to fire protection safety evaluation for previously unresolved open items

  # Operating Reactors Granch 2. 81/02/12. 4pp. 07852-184
- 0103180264 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 Pire protection rule EISENHUT.D.9 Division of Licensing 81/02/20. L3pp
- BIO331033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements Mrd enci
- 8103260123 Concurs w/801217 request to Install two-way headest jacks on specified emergency notification sys & health physics telephones provided that use will be discontinued if communications quality unacceptably degraded xEPPLER: 9. Region 3. Chicago. Office of the Director. 81/03/17.

- --8103260137 Submits location for installation of one-way heads on emergency notification sys & health physics network per 801119 request Requests concurrence by 810201 RAUSCH, I J Co-monwealth Edison Co 80/12/17
- 8:03250685 Releases public version of implementing procedures f seer cancul clan FFITOW, J.M. Division of Rules and Records 81/03/19 In
- -- Bio3250692 Forwards public version of energency plan implemen procedures for corporate command ctr. environ director & procedures for components command ctr.environ director & plant-specific procedures
  DEL, ECOROCL & D. Commonwealth Edison Co. B1/02/27. App
- --- Rings 50702 Putlic version of emergency plan implementing proc correcte command ctr.environ director & plant-specific procedures. + Commonwealth Edison Co 81/02/27 1400mg
- 9 Adjudicators correspondence
- 8101300233 Forwards NRC 810813 orders for nod of licenses & gra extension of exemption.Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50 JPPOLITO TA Operating Reactors Branch 2 81/01/13 3pp
- --Bi01300259 Order modifying license & granting extension of exticensee must reassess suppression pool hydrodynamic loads complete mads to meet Deneral Design Criterion 50 by 921231 EISENNUT.D O Division of Licensing 81/01/13 7pp 078
- 1 Financial information
- 9103310613 Forwards quarantee of payment of deferred premiums f DSTER.J Commonwealth Edison Co 81/03/27 1p
- --Bi03310620 Forwards Annual Rept for CY80 & statement of inter flow projected for 1981 % actual for 1980 per provisions of IOCFR140. Chapter 1. Bection 140 21 & NRC 770613 itr NEXON-H H Commonwealth Edison Co 81/03/27. App.
- J Insurance & indemnity information
- 8103090581 Forwards Endorsement S to NELIA Binders E0-1.EB-2.EB E8-29, E8-30, E8-42, E8-43 & MAELU Binders X8-1, X8-2, X8-3, x8-29, x8-30, x8-42, x8-43 DSTER, J Commonwealth Edison Co 81/03/02, 1500
- 8103090618 Forwards Endorsement 67 to NELIA Policy NF-187 & End 95 to MAELU Policy MF-54 OSTER, J. Commonwealth Edison Co. 81/03/02 3pp. 07844-326
- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants Ots & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREG-0612 Forwards NRC position reinterim actions & request for addl info.

  EISENHUT, D. O. Division of Licensing. 80/12/22. 30pp
- 8:01300259 Order modifying license & granting extension of exer Licensed nust reassess suppression pool hydrodynamic loads & complete mode to meet Conoral Design Criterion 50 by B21221 EEENHUI.D C. Division of Licensing 81/01/13 7pp. 07586
- 8103190387 Ltr to all licensees of operating plants & applicant DLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed invalve cold shutdown replacement parts & NUREO-0737.
  EISENHUT D.O. Division of Licensing. 81/01/19. App.
- 8103240290 Ltr to all BWR licensees forwarding Suppl 1 to gener safety evaluation on BWR scram discharge sys. Summarizes remevaluation of interim measures recommended per 801201 safety evaluation EISENHUT, D. O Dis Division of Licensing 81/01/23. 2pp.
- 8103120014 Ltr to all licensees of operating plants.CP holders applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-I, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads.
  EISENHUT.D.G Division of Licensing. 61/02/03 6pp.

- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates util be net EISENMUF. D G Division of Licensing 81/02/18 12pp
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216 KEPPLER, J G Region 3. Chicago, Office of the Director 81/02/20
- Bio3250024 Ltr to all power reactor licensees & license applicants re MUREG-0519 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISENHUT D O. Division of Licensing 81/02/20 Bpp
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2) Requests applicants on the receive of collections of the applicant of the station blackout event & promptly implement emergency procedures EISENHUT.D.O Division of Licensing 81/02/25 Spp
- BiO3170225 Ltr to all BMR licensees (except Humboldt Bay & LaCrosse) requesting review of ABME Code Class | & 2 pressure boundary piping, safe ands & fitting matl per guidelines of encl Revision 1 to NUMEG-0313 Model Tech Specs only encl EISENHUT, D. G. Division of Licensing 81/02/26 3pp
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 % 3/4 4-6 re surveillance requirements for ASME Code Class 1.2 % 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements.
  • General Electric Co 81/02/26 4pp.
- B103230B13 Generic Ltr B1-06 to all CP holders & GL applicants re 10CFRSO 71(e). "Periodic Updating of FSARs." effective 800722.info re FSAR legal status.format & content encl E1SCHHUT, D O Division of Licensing 81/02726 10pp
- 8103030B60 Forwards status surnary for NUREO-0737 items to which util committed to respond by 810301 Long-term program under intensive Internal review Program util be submitted by ABEL. J. S. Commonwealth Edison Co. 81/02/27 3pp 65067 351
- 8103030188 Forwards add1 info re containment purge & vent valve operability, in response to NRC 801202 ltr.

  JANECEK-R. F. Commonwealth Edison Co. 81/02/27 20pp
- 8100310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D.O. Division of Licensing, BI/03/10 App
- 8103180517 Informs NRC that util will continue to require full radiation training for NRC personnel entering radiation areas at fecilities, pending further NRC communications. TRAMM.T.R Communumenth Edison Co. 81/03/11. 1p.
- 8103200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of CE-1-A.Revision to re GA program. Revisions reflect ABME winter addenda code changes, changes made per ABME survey & larifications & corrections TRAMM.T.R Commonwealth Edison Co 81/03/16. 1p.
- --B103200369 Revised abstract & Pages 2-2, 4-2, 4-3, 7-2 & 18-2 of Revision \* Commonwealth Edison Co. CE-1-A R16. 81/03/16 600.
- BiO3270095 Bummary of BiO304 meeting w/Mark I owners group & QE in Batheads.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREO-0661. Bilde presentation & list of attendees and l. ORIMES.C.I. Licensing Branch 3. 81/03/16. 3pp.
- 8103260149 Forwards preliminary results of NRC review of environ qualification of safety-related electrical equipment at facility. Identified deficiencies & ramifications should be reviewed & overall findings submitted. NOVAK.T.M. Assistant Director for Operating Reactors. 81/03/17. 3600
- BIO3240198 Requests clarification of constraints placed on BWR fuel exposures per 801112 BER. Requirement in conflict w/generic NRC approval of operation received by GE in Nov 1980 ltr. Util estumes previous commitment no longer applicable. JANECEK.R.F. Commonwealth Edison Co. 81/03/19. 2pp. 07990:342

- 8103261150 Forwards Amends 64 % 58 to Licenses DPR-29 & DPR-30. respectively & notice of issuance & availability
  IPPCLITO.T A Operating Reactors Scanch 2 61/ B1/03/19 3no 08035 265
- ~~BiO3261155 Amends 64 & 58 to Licenses DPR-29 & DPR-30 respect adding license conditions to include guard training &
  - qualification plan IPPOLITO, T. A. Operating Reactors Branch 2, 81/03/19 4pp 08035 268
- ---8103261161 Notice of Issuance & availability of Amends 64 & 5 Licenses DPR-29 & DPR-30-respectively IPPOLITO T A Operating Reactors Branch 2 81/03/19 2pp 08039-272
- 8103300477 Requests amend to Licenses DPR-29 & DPR-30 Amend chall Tech Space to modify spent fuel storage racks to provide addl storage capability

  JANECEK.R F Commonwealth Edison Co. 81/03/26. 2pp. 08057
- --8103330479 Proposed Tech Specs 5 0 revisions re design feature \* Commonwealth Edison Co 81/03/26. 3pp. 08057-251
- --8103330487 'Spent Fuel Pool Mod for Increased Storage Capacite 10350000 Photo received the for increased Storage Capaciti Licensing rapt on high density spent fuel racks \* Commonwealth Edison Co. SINGH.K.P. Joseph Dat Corp. It Black & Veatch, Southern Science Applications, Inc., Div. It B1/03/31 Bopp. 08057 254
- G. Inspection recorts. IE Bulletins & correspondence
- 8103050387 Forwards IE Insp Rept 50-254/80-30 on 801219-21 No noncompliance noted
  NETBHIANR F Region 3. Chicago, Reactor Operations Nucleer S
  Brench B1/01/13 2pp 07824 274
- --8103050394 IE Insp Rept 90-254/80-30 on 801219-21. No noncompli noted Major areas inspected control rod drive scram time
- tests 3 determination of reactor shutdown margin CHOULES.N.C. LANKSBURY.R. Region 3. Chicago. Diffice of the Director STREETER.J.F. Region D. Chicago. Reactor Operat. Nuclear Support Branch. 81/01/12. 3pp. 07824.275 8103050880 Forwards IE Imag Repts 50-254/80-31 & 50-265/80-31 or
- BOI230 No noncompliance noted.
  FIBHER, W. L. Region 3. Chicago, Fuel Facility & Materials Bafa Branch B1/01/16 2pp 07829.075 --8103030383 12 Inep Repts 50-254/80-31 & 50-265/80-31 on R01230
- 103030383 12 Inep Repts 30-234/80-31 & 30-285/80-31 on 801236 moncompliance noted Major areas Inspected environ protection including observation of damage done by discharge canel overflow & corrective action taken by licensee. UESTHANNM J. PAPERIELLO.C.J. Region 3. Chicago, Office of Director 81/01/15 2pp. 07829:077.
- 8103090264 Forwards IE Insp Repts 50-254/80-27 & 50-265/80-28 or B01123-B10107. No noncompliance noted HEIBHMAN.R F Region 3. Chicago, Reactor Operations Nuclear S Branch. B1/01/21 2pp 07845.324.
- --8103090272 IE Insp Repts 90-254/80-27 % 50-265/80-28 on 801129
  No honcompliance noted Major areas inspected licensee action on previous insp findings meeting d/local officials refuel CHRISBOTIMOS, N. CUPONT, 9. 0. SPESSARD, R. L. Region 3. Chica Office of the Director. 81/01/20. 8pp. 07846.326.
- 8103240711 Responds to Buppl 3 of IE Bulletin 79-018, "Environ
- Qualification of Class IE Equipment. " Suppliers have been contacted to provide qualification of acoustic monitors on relief & safety valves.
  ABEL, J. B. Commonwealth Edison Co. B1/02/02 3pp. 07989 212
- 8103020119 Forwards TE Circular 81-02. "Performance of NRC-Licer Individuals While on Duty " No written response required MEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/4
- B103160937 Forwards IE Insp Repts 50-254/B1-01 & 30-265/B1-01 or B10107-0207. No noncompliance noted. HEIBHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear & Branch. B1/02/10. 2pp. 07915:100.
- --8103160944 IE Insp Repts 50-254/81-01 & 50-265/81-01 on 810103 ontcompliance noted Major areas inspected NURED-0737 followup, monthly maint observation, LER followup, plant acrama by operational safety verification CHRIBSOTIMOS, N. DUPONT, B. O. SPESSARD, R. L. Region 3. Chica Office of the Director. 81/02/10. 14pp 07915:102

8103200284 Forwards technical info.codating 810202 response to IE Sulletin 80-17, Supp 4. "Failure of Control Rods to Insert During Scrap at BUR" (1/o encl RAUSCH: I' J Componwealth Edison Co 81/02/11 2pp 07971 169

610304025) Forwards 12 Info Notice 81-03. "Checkinst for Licensess UNIVERSITY TO THE TOTAL ON THE TOTAL CANDIDATE TO THE TOTAL CONTINUES OF SIGNIFICANT EVENTS IN ACCORDANCE MAINTERS TO THE TOTAL CANDIDATES OF THE TOTA

KEPPLER, J. G. Region 3. Chicago, Office of the Director 81/02/12 200

8103036302 Forwards Suppl 5 to IE Bulletin 80-17. 'Failure of Control Rods to Insert During Stram at SWR' No written response

MERPLER, J. G. Region 3, Chicago, Office of the Director 81/02/13 220

8103t60373 Forwards -onthly status rept re evaluations performed in response to IE Bulletin 79-14. "Seismic Analysis for As-Duilt Gafety-Rolated Piping Sys." Tables listing ercessive pipe stresses encl JANECEX.R F. Compor

8103160494 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No response required.

KEPPLER, J. G. Hegion 3. Chicago, Office of the Director. B1/03/02

8103:70371 Responds to IE Bulletin 81-01. "Surveillance of Mechanical Shubbers " No Nuclear Safeguards Corp shubbers have been

Jake CEA, R. F. Commonwealth Edison Co. 81/03/02 2p

8103160894 Forwards revised IE Bulletin B1-01. 'Surveillance of

Mechanical Emubbers. Wideorracted Pages 5 & 6 Change in identification of facilities WICPs to which bulletim is applicable dues not affect util requirements. Region 3. Chicago, Office of the Director 81/03/04 KEPPLER J. G

8103200394 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required KEPPLER. J. 9. Region 3. Chicago. Office of the Director... 81/03/11 200

8103200595 Forwards (E. Info Notice 81-05, "Decraded DC 84% at OBZODOWD Forwards to into Reside William Degrees 50 59. 5. Paisades. No action required KEPPLER. J. O. Region D. Chicago, Office of the Director. 81/03/13 200

8103200249 Forwards IE Info Notice 81-07, "Potential Problem W/Mater-Soluble Purge Dam Hatla Used During Inert Gas Wetding." No response required

KEPPLER, J. G. Region 3. Chicago, Office of the Director 81/03/16

8103241193 Responds to IE Bulletin 80-25, "Operating Problems H/Target Rock Safety Relief Valves at BURs " Engineering review of LaSalle safety relief valve pheumatic supply sys still in progress Mods will be completed prior to fuel loading.
RAUSCH.T J. Commonwealth Edison Co. 81/03/19 702.

B1032704B4 Confirms info in B00610 response to 1E Bulletin 80-06. "Engineered Bafety Feature (ESF) Reset Controls " Valves 2301-64.65,29 & 30 close on MPCI sys initiation MPCI auxiliary oil pung will not deplete power source
JAMECER, R F Communicatif Edison Co 81/03/20 4pp. 08046 221.

B103270663 Forwards summary of findings re-ultrasonic insps of LP-2. LP-8 & LP-C rotors Physical properties for wheels w/indications will be submitted to NRC by GE.par existing proprietary agreement.

JAMECEA, R.F. Commonwealth Edison Co. 81/03/20. 3sp. 08043 001.

A. Persodic operating reports & related correspondence

B103020373 Forwards "Effluent & Maste Disposal Semiannual Rept. 1980." KALIVIANAKIS.N. Commonwealth Edison Co. 81/02/09 1p. 07785-222,

--8103020381 "Effluent & Wasto Disposal Seniannual Rept.1980."

\* Commonwealth Edison Co. 80/12/31 21pp. 07785:223

8103030792 Forwards occupational radiation exposures rept for 1980. BITEL, J 8 Commonwealth Edison Co 81/02/25

--8103160666 Konthly operating repts for Feb 1981
• Comprisellth Edison Co. 81/03/02 ip 0 07914 27A

Bigg170355 Forwards contilly operating repts for Feb 1981 07004 057

--8103170374 Monthly operating repts for Feb 1981 TUPBS, R. Componwealth Edison Co. 81/03/02 21on 07924 058.

S Reportable occurrences. LERs & related correspondence

8103100497 Forwards LER 81-005/01T-0 MALIULAKAKISHI Commonumealth Edison Co. BI/03/02 in 07862-295

--3103199506 LER 81-005/017-0 on 810220, during testing, three of four condenser low vacuum scram suitches found outside setting per Tech Sper 3 1-3 Caused by instrument setpoint drift Ail switches recalibr CLARK.D 9. Componeealth Edison Co. 81/03/02 200. 07862: 296.

8103170369 PNO-III-81-023 on 810228 facility shot down to investigate step increase in unidentified leakage in druwell Caused bu packing leaks in reactor feedwater ploing theck valve Parking leaks in reactor resudator pipin Further repairs to be conducted. CHRISSOTINDS.N., REIMANN.F.W., KNOP.R.C. of the Diroctor 81/03/02 lp 07924 Region 3. Chicago. Office 07924 083

8103270618 Forwards LER 81-006/03L-0 MALIVIANAKIS.N Commonwealth Edison Co 81/03/09 15 08043 241

--8103270631 LER 81-006/03L-0. on B10302, flexible air line to Tardet fic; TO 32/0631 LEN BI-006/01L-0 on bigguez-rietble air line to lamain steam safets/reliof valve found broken during routing insp of dru-ell Caused by improper installation of flexible air line for line replaced w/longer one MCMCENPALL.E Commonwealth Edison Co 81/03/09 3pp 08 00043:242

8103190511 PNU-III-81-031 on 810312 unplanted airborne activity was released to Unit 1 reactor blog Caused by reactor blog equipment drain tank being inadvertently pressurized Workers equipment train tent being indepertently presenting. Workers evacuated & monitored Activity level returned to normal.

CHRISSOTIMOS.N., BOYD.D.C., KIIJP.R.C. Region 3, Chicago, Diffice of the Director 81/03/12 ip 07965 224

8103190639 PNG-111-81-031A on 810312, unplanned airborne activity released to reactor bldg Caused by reactor bldg equipment drain tank inadvertently pressurfised during reactor waste cleanup sys startup Whole body counts takon CHRISSDIINOS.N. BOYD.D. KNOP.R. Region 3. Chicago, Diffice of the Director. 81/03/13 1p 07764:083

V Operator Examinations

8103030769 Forwards supplemental info re shift tochnical advisor training.per NUREC-0737, Itom I. A. 1.1 (3). Info includes response to training requirements for shift control room engineers & projected schedule for training completion. ABEL. J B. Commonwealth Edison Co. 81/02/24. App.

Bi03090140 Forwards list of shift control room engineers meeting training & education requirements by dates indicated. Many engineers completed training by 810101. Target date for completion of training is mid-1981.
ABEL. J. 8. Commonwealth Edison Co. 81/02/24. 4pp

8103200374 Forwards supplemental info re long-term shift technical advisor gragram.including candidate qualification selection criteria.training plans & bases for phase-out of shift technical advisor program mendated by NUREO-0737.

ABEL.J. S. Gom-onwealth Edison Co. 81/03/17. 19pp.

DOCKET SO-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

Bi03040312 Forwards summary of staff requirements to resolve open items & FR notice re fire protection features. Applicable provisions of App R. effective 810217. discussed. W/o encl. ESERNMUT. D. G. Dutsion of Licensing 80/11/24 4pp. 07820 OB1



implementation of alternative safe shutdown sys CRUTCHFIELD.D Operating Reactors Branch 5 Bi/02/10 3pp 07949 198

- --BiO3090762 Euppl 2 to 780901 fire protection safety evaluation.
  supporting Amend 64 to License DPR-20
   Office of Nuclear Reactor Regulation. Director 81/02/10 7pp A2019 707
- BiO3180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info resets shotdown capability for compliance w/BD1119 fire
- acotection rule EIBELLUT D 9 Division of Licensing, 81/02/20 13pp
- 8103310338 Ltr to all licensees of operating clants & holders of CPs
- 8103230636 Forwards plan for achieving compliance w/new fire protection Disastable refusers plan for activering Compliance where the programmes Alternate shutdown (aspability will be installed Emergency lights will be modified or replaced to provide 8-h operation in areas necessary for shutdown safety WCRESON.3 D. Consumers Power Co. 81/03/19 17pp 07977 021

#### O Adjudicatory correspondence

- 8103103015 Discovery rept per ASLB 80022? memorandum & order NRC deposed F Leckio on 810209 & util will file answers to NRC third round of interrogatories during whi of 810316 Discovery suspended until possibility of settlement is determined MQUHIFR E Office of the Executive Logal Director 81/03/05. 2pp 02042, 128
- BIO3181130 Forwards order confirming short & long-term actions to upgrade regulatory performance of facility GRELLO,V Director's Office, Office of inspection and Enforcement STELLO.V Director's Offic BL/03/09 2pp 07953 136.
- -- 0103101135 Order confirming licenses actions to upgrade facility performance by reinstructing personnel who perform safety related work & restricting overtime for licensed operators BTELLO. V Director's Office Of Inspection and Enforcement B1/03/07. 11pp. 07993:138

## I Financial information

- 8103160528 Forwards Annual Financial Rept 1980 in. 07917:152. PERRY, P. A. Consumers Power Co. B1/03/11.
- --8103160538 Annual Financial Rept 1980. Consumers Power Co 81/02/13 28pp 07585.001.
- J. Insurance & indemnity information
- 8103240423 Forwards Endorsement 5 to ANI Ginder E0-20 & Endorsement 5 to MAELU Sinder XB-20. IRELAND, J. II. Consumers Power Co. 81/03/18 4pp 07981 348.
- P. Operating license stage documents & correspondence
- 0103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re interim actions & request for eddl info EISENHUT, D. O. Division of Licensing. 80/12/22 30pp.
- B103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown-replacement parts & NUREO-0737 EIGENHUT.D. G. Division of Licensing. 81/01/19 6pp.
- 8103090297 Forwards Amend 63 to License DPR-20, safety evaluation & notice of issuance & availability.
  CRUTCHFIELD.D. Operating Reactors Branch & Bi/Oi/22. 2pp 07849.069

CRUTCHFIELD.D Operating Reactors Dranch 5 81/01/22 19pp --8103090267 Environ protection plan (nonradiological) for facility

encl environ protection plan

07H49 07L

- --8103090270 Safety evaluation supporting Arend 63 to License DPR-6 Office of Nuclear Reactor Regulation. Director 81/01/22
- -- B103090275 Notice of Issuance & availability of Amend 63 to Lice CRUICHFIFID.D Operating Reactors Branch 5 81/01/22 200.
- 8103120014 Ltr to all licensees of operating plants.CP holders & Cl applicants.orcept Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads EISENHUT.D G Division of Licensing 81/02/03 6pp
- 8103090725 Forwards "Environ Qualification of Safety-Related Elect Equipment. " partial review Written response required LAIMAS. & C. Assistant Director for Safety Assessment 81/02/10 400 07844 196
- --Bi03090731 'Environ Qualification of Safety-Related Electrical Equipment, partial review

  \* Office of Nuclear Reactor Regulation, Director 61/02/10 18pp 07844 200
- 8103090739 Forwards Amend 64 to License CPR-20. Suppl 2 to fire protection safety evaluation & notice of issuance & availability Aiso reviews 790928 request for deferral implementation of alternative safe shutdown sys CRUTCHFIELD.D Operating Reactors Branch 5 81/02/10 07849 198
- -- A103090757 Amend 64 to License DPR-20. incorporating Suppls 1 & 2 fire protection safety evaluation
  CRUTCHFIELD, D Operating Reactors Branch 5 81/02/10 2pp. 07849 201
- ---8103070762 Suppl 2 to 780701 fire protection safety evaluation, supporting Amend 64 to License DAR-20.

   Office of Nuclear Reactor Regulation, Director. 81/02/10. 07849 203
- --8103090765 Notice of issuance & availability of Amend 64 to Lice CRUICHFIELD.D Operating Reactors Branch 5 81/02/10 2pp. 37849 210
- 8103300160 Ltr to all operating PWR licensees requesting info on auxilion.cr to all upracting run illeniers requesting info auxilior, feeductor sys selsmic design Forwards request for addl info list of actions requested of licensees w/o selsmically qualified sys & results of NRC walkdowns. CIBENHUT.D O Division of Licensing 81/02/10 13pp
- B103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A 12 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be net EIBENHUT.D.O. Division of Licensing 81/02/18 12pp
- 8103090240 Forwards organizational charts depicting NRC Region 3 reorganization offoctive 810216 KEPPLER. J O Region 3. Chicago. Office of the Director 81/02/ KEPPLER J 0 Re 20p. 07852.044
- 8103250024 Ltr to all power reactor licensees & license applicants NUREO-0619 critoria Footnote 2 in Table 2 contains error due to leakage testing deletions Licenseo may submit analysis to justify use of existing low flow controller EISENHUT.D.O Division of Licensing. 81/02/20 Spp.
- 8103110217 Forwards request for add1 info on C-E owner's group submittal on "RCS Asymmetric Loads Evaluation Program." final rept includes generic & plant-specific requests CRUTCHFIELD. Operating Reactors Branch 5 81/02/23. 27p 81/02/23. 27pp 07885: 155

- gas effluent monitor, sampling analysis of plant effluents 6 upgrade energency support facilities PROST.5 R Consumers Pewer Co. 81/02/25 8pp. 07783-056
- BiG3:30266 Founds Amends 41 t 65 to Licenses DPR-6 to DPR-20. respectively 5 notice of issuance & availability CPUTCHFIELD.D Operating Reactors Branch 5 81/02/25 4pp. 07212 181
- --Bi03130275 Amends 41 & 65 to Licenses DPR-& & DPR-20-respectively.
  Including requirement to maintain guard training &
  qualification plan & for full implementation unithin 60 days
  CRUICHFIELD.D. Operating Reactors Granch 5 81/02/25 App
  27412 185
- --B1031302BO Notice of issuance h availability of Amends 41 % 65 to Licenses DPR-6 & DPR-20, respectively CRUICHFIELD: D. Operating Reactors Branch 5 81/02/25 2pp 07912 189
- E:03230933 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2), Requests util review to determine capability to mitigate station blackout event t promptly implement energency procedures EISENNUT.D G Division of Licensing 81/02/25 5pp
- 8103230813 Generic Ltr 81-06 to all CP holders & DL applicants re 1CCFR90 71(e). Periodic Updating of FSARs." effective BC0722 1-fo re FSAR legal status format & content encl RIEECH-UT. D G Division of Licensing 81/02/26 10pp.
- 8103129265 Forwards revised final evaluation of Topic VIII-2 originally submitted E00919, re input to integrated safety assessment for diesel generators
  CRUICHFIELD. D. Operating Reactors Branch 5 81/02/27. Tipp 07900 098
- 8103;20274 Forwards for comment draft evaluation of SEP Topic III-2 re wind & tornedo loadings Response requested within 30 days of litr receipt CRUICHFIELD. D.M. Operating Reactors Branch 5 81/02/27 10pp 07900 087
- 8103090391 Responds to ARC 801212 request for add1 info re adequacy of station electric distribution sys vallages Contactors on Class IE notor control ctrs are rated 150 volts to 60 volts continuous operation
  FPCST.S R Consumers Power Co. 81/03/03. 51pp
- B103100469 Comments on DDE 8(0130 ltm to Eisenhut me reliability & cost impact of shutdown Use of caperity factor based on 1980 performance inappropriate Unit out of swc for refueling & mod during CY60 per NRC requirements.

  PEINS. 9 L. Consumers Power Co. 81/03/05 2pp. 07586:001
- Q103181130 Forwards order confirming short & long-term actions to upgrade regulatory performance of facility.
  STELLOV Director's Office. Office of Inspection and Enforcement Q1/Q3/Q9 2pp. 07953-136
- --Bi0318i135 Order confirming licensee actions to upgrade facility performance by resinstructing personnel who perform safety-related work & restricting overtine for licensed operators STELLO.V Director's Office. Office of Inspection and Enforcement, 81/03/09 11pp 07953 138
- B103:10735 Forwards evaluation of SEP Topic V-5 re reactor coolant pressure boundary leakage detection Requests info redifferences between as-built fecility & licensing basis within 30 days CRUTCH-FILD. 0 Operating Reactors Branch 5 81/03/10 10pp 07885;015
- 8103310804 Ltr to all licensess of operating plants, applicants for Ols & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUI.D. G Division of Licensing. 81/03/10 App

- locating.were verified against climatological data recorded for Benton Marbor FAA weather station VINCENT.R A Consumers Power Co 81/03/11 App. 07917 123
- 8:03160517 Forwards draft evaluation of SEP Topic VI-1, "Organic Matte t Post-Accident Chemistry ' Util should advise of differences between as-built facility to licensing basis within 30 days CRUTCHFIELD, D. Operating Reactors Branch 5 81/03/12 9pp 07921 122
- 6103190111 Confirms telcon re 810320 meeting w/Ofc of Nuclear Reactar Regulation to discuss items re upgrading licensee OA tapical rept. HOFFPNAL-D P. Consumers Power Co. 81/03/16 2pp. 07964-150
- B103230512 Advises that SEP Topic III-4 B re turbine missiles has been made generic due to multi-plant cracking problem at plants u/Kestinghouse low pressure turbines.
  CRUICHFIELD. D Operating Reactors Branch 5 B1/03/16 4pp 07979 338
- B103270755 Requests payment of class III fee for 801112 application requesting relief from 1974 ASME Boiler & Pressure Vessel Code
  DIGOS.R M. License Fee Management Branch 81/03/20. 1p.
- B103270696 Forwards draft safety evaluations of SEP Topics XV-1.XV-2.XV-3.XV-4.XV-5.XV-7.XV-7.XV-7.XV-9.XV-9.XV-10.XV-12.XV-14.XV-15.XV-17.XV-18.XV-9.XV-16.XV-12.XV-14.XV-15.XV-16.XV-17.XV-17.XV-19.XV-10.XV-10.XV-17.XV-19.XV-10.XV-10.XV-17.XV-19.XV-20.XV-10.XV-17.XV-19.XV-20.XV-10.XV-17.XV-19.XV-20.XV-10.XV-10.XV-17.XV-19.XV-20.XV-10.
- 8103310405 Forwards response to NRC 810119 ltr transmitting NUREO/CR-1833, "Seismic Review of Palisades Nuclear Power Plant Unit 1" Comments re SEP Topics 111-6 & 111-11, "Beismic Review" and VINCENT, R A. Consumers Power Co. 81/03/27 | 1100 | 08075-149.
- 9 Inspection reports. IE Bulletins & correspondence
- B103020125 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. XEPPLER.J G Region 3, Chicago, Office of the Director. 81/02/09. 2pp 07788 026.
- 8103190262 Forwards IE Insp Rept 30-255/80-20 on 801103-26, [201-05 & 810116 & notice of violation KEPPLER, J. 9 Region 3. Chicago, Office of the Director. 81/02/11 2pp 07956-012.
- --8103190268 Natice of violation from insp on 801103-26,1201-05 & 810116 KEPPLER, J 0 Region 3, Chicago, Office of the Director. 81/02/09 5pp. 07956-014
- --Bi0319027B 1E Imsp Rept 50-253/80-20 on B01103-26, 1201-05 & B10116 Noncompliance noted procurement documents did not ref applicable regulatory requirements or necessary OA program requirements. BAMER.X R Region 3. Chicago, Reactor Operations Nuclear Support Branch. JACKIW.I.N. SCHULZ.R.D. Region 3. Chicago. Office of the Director B1/02/06 31pp 07956-020
- 8103040295 Forwards IE Info Notice Bi-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CFR90 72" No written response required. REPPLER.J.O Region 3. Chicago. Office of the Director. 81/02/12. 2pp. 07815.257
- 8103160662 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines" No response required KEPPLER.J & Region 3. Chicago. Office of the Director B1/02/27. 2pp. 07914.255.
- 8103160508 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/03/02
  2pp. 07916-006
- 8103160890 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Enubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  KEPPLER. J. 9. Region 3. Chicago, Office of the Director 81/03/04 1p 0/915-047.

- Palisades 'No action required KEPPLER. J G. Region 3. Chicago. Office of the Director Gi/O3/13 200 07966 173
- 8100200260 Forwards JE Info Notice 81-07, 'Potential Problem L/Water-Solutic Purge Dan Matik Used During Inert Cas Helding 'No response required KEPPLER. J O Region 3. Chicago. Office of the Director. 81/03/16 20a 07970 349
- BIO3250157 Ack receipt of 810309 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-255/80-20.
  INCIBERTAN, F Region 3. Chicago. Office of the Director 81/03/19 1p 07996 019
- --8103250163 Responds to MRC 810211 ltr re violations noted in IE [nsp Rept 50-255/80-20 Corrective actions procedure re processing of nonconforming mail reviewed w/QC staff & conditional release tag will be changed FROST.5 R Consumers Power Co 81/03/09 17pp 07996-020
- R Periodic operating reports & related correspondence
- 8103040763 Forwards "Radinactive Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1980"
  VINCENT, R.A. Consumers Power Co. 81/02/27 10. 07813-049
- --B103040769 'Radioactive Effluent & Waste Disposel Semiannual Rept.
  \_Vi-Dec 1980 "
   Consumers Power Co. 81/02/27 9nn 07813 050
- BiO3130367 Forwards monthly operating rept for Fob 1981
  VANDENBERG.D. Consumers Power Co. BL/03/06 in 07911:141
- --8103130371 Monthly operating rept for Feb 1981.
  PETERSON.D Consumers Power Co 81/03/02 3pg 07911-142
- 9. Reportable occurrences. LERs & related correspondence
- Bi03040042 PNO-III-81-009 on Bi0117, several gaseous releases occurred Caused by slight pressurization during periodic letdown while manually activated degasifier pumps not operating RMETER, L. FISHER, H L. Region 3, Chicago, Office of the Director 91/01/19 2pp. 07816 392
- 8103030768 Forwards updated LER 81-002/03L-1 FR097.8 R Consumers Power Co 81/02/26 ip 07797:394
- --Bi03030791 Updated LER Bi-002/03L-1. on Bi010B determined that 125 volt DC distribution panel D21A mounting did not most saismic restraint criteria. Caused by engineering judgment error Frame holding panel modified by adding bracos \* Consumers Power Co. Bi/02/26 ip 07797: 355.
- B103030806 Forwards LER 81-609/03L-0. FROBT, B R Consumers Power Co. B1/02/26. Ip. 07797.338
- --8103030Bi0 LER 81-009/03L-0:on 8101(5.power conversion sys sample revealed dose equivalent I-131 to be in escass of Toch Spac. Caused by low level cladding feiture combined w/transient conditions following plant trip
  4 Consumers Power Co. 81/02/26. Hipp.
- B103040681 Forwards LER 81-010/03L-0. FROST, S.R. Consumers Power Co. 81/02/27 1p. 07811:341.
- --Bi03040686 LER 81-010/03L-0: on Bi0209, primary indicating position datalogger became inoparable Caused by failure of mercury—wetted relay in gain selection portion of input amplifier of A/D converter Relay replaced.

   Consumers Power Co. 01/02/27. ip 07811:342.
- B103120439 EN-B1~009: on B10309, confirmatory order issued to licensee reactions to upgrade facility performance Order permits continued operation per provisions of B10109 immediate action ltr.
  RIEBLAND, J. I., THOMPSON, D. Director's Office, Office of Inspection and Enforcement B1/03/09 2pp.
- 8103270677 Forwards updated LER 79-038/03X-1.
  VINCENT.R.A. Consumers Power Co. 81/03/13. 1p. 08043:273

- 8103260004 Confirms Blo318 meeting w/otil in Olen EllynilL to disc Bl0106 125-volt of battery bank breaker mispositioning event. KEPPLER J G Region 3. Chicago. Office of the Director Bl/03/ in 09040 371
- 8103240412 Forwards NPDES noncompliance notification per Tech Spec HOFFMAN.D.P. Consumers Power Co. 81/03/18 Lp. 07987-350.
- ---B103240418 indees noncompliance notification on B10228 daily aver 3 grease concentration ecceeded daily average 2 max limitations Cause identified & corrective actions taken as reported in util 810213 & 0303 repts FOBEB:R L. Consumers Power Co. B1/03/16 ip 07987 391

## V Operator Examinations

- 8103310470 Discusses NRC concerns reliack of mechanism to inform personnel about industry problems such as St Lucle incident. IE Circular 80-15 Mechanism explained in 801217 response to NUREC-0737 & at 810214 meeting No further changes needed FROST.S R Consumers Power Co. 81/03/25 ip
- DOCKET 30-259 BROWNS FERRY NUCLEAR POWER STATION. UNIT 1

  F. Security. medical, emergency & fire protection plans
- G103180264 Ltr to all power reactor licensees u/plants licensed pr to 790101 Forwards NAC position & request for addl info re safe shuldown capability for compliance u/CO1117 fire protection rule FISEPHAULD & Division of Licensing 81/02/20, 13up
- Bio3040717 Informs that liteness will conduct emergency preparedne exercises Bept 1981 for Browns Ferry & Mor 1982 for Hotts Bar.par Bio130 request Exercise scenarios will be provided four wis before schoduled exercise MILLE.LM Tennessee Valley Authority Bi/02/25 ip 07812 2
- 8103060336 Forwards addl info re guard training & qualification pl Encl withheld (ref 10CFR2 770). MILLS.L M Tennessee Valley Authority 81/02/26 ip 07837 C
- B103100668 Requests that encl emergency planning info be made publiavailable N/g encl.

  BDUDER.J L. Division of Rules and Records B1/02/27 ip

  07865:310.
- 8103160133 Forwards add1 revisions nacessary to find 810123 safeguentingency plan acceptable Response requested within 30 days
  IPPOLITO,T A Operating Reactors Branch 2 81/03/02 4pp
  07919-324
- B103310338 Ltr to all licensees of operating plants & holders of C forwarding NUREC-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. I/A encl EIBENHUT.D Q. Division of Licensing 81/03/05 &pp.
- B103170194 Forwards revisions to physical security plan Encl within trof 10CFR2 770)
  MILLEAL M Tennessee Valley Authority 81/03/09 ip. 07935:3
- 8103260239 Requests exemption from App R fire protection requirements as safe shutdown capability, emergency lighting & oil collection sys for reactor coolant pumps. Responds to NRC 801124 & 810220 ltrs to all PMR licensees.

  MILLS.L.M. Tennessoe Valley Authority 81/03/18 2pp 08037.
- BIO3270512 Requests relief from commitment re installation of light sit signs in response to NRC BIO204 request Externally illuminated directional exit-type signs are adequate. MILLS.L.M. Tennessee Valley Authority BI/03/20 2pp 08046

#### Q. Adjudicatory correspondence

B103130451 Order setting B10410 prehearing conforence to discuss petitioners' standing to intervene Petitioners must file supple to petitions no later than 18 days prior to conference. Histing contentions sought to be liftipated. GROSBMAN.H. Tennessee Valley Authority. 81/03/10. 4pp 0791

- G103250121 Repl, to 1 Paul.A Jobe 1 M Hall & H Fenn.R Hudgens & T fhornton petitions to intervene Util objects to ASLB considerations of getistions for lack of proper six Petitions should be denied if considered Certificate of Six encl paus GR.H.S. MALLACF.L.E. BURGER.U.F. Tennessee Valley Authority G1/03/13 Tap. DBCH 755
- 8:00279467 Notices of appearance in license amend proceeding Certificate of Sky encl LAYERTY, J. H. Hearing Branch 1 LEHIS, S. H. Hearing Branch 2 BIY03724 App 08034 145
- J. Ensurance & indemnit, information
- 8103060339 Forwards Endorsements 4 to MAELU Binders XB-38-XB-39 & xB-40 FIELDER: J. Marsh & McLennan, Inc. . 15 & M Nuclear Consultants, Inc. Div. 81/21/27 7pp. 07840-225
- 8103060369 Forwards Endorsement 44 to MAELU Policy MF-65 FIELSER, J. Marsh & McLennan, Inc., M.& M. Nuclear Consultants, Inc. U.v. 81/01/29 | Pag. 07840 226
- 8103110516 Forwards Endorsecent 5 to MAELU Binder x0-38.X8-39 & x8-40 FIELDER-J Marsh & Millerman-Int . H & H Nutlear Consultants inc Div 81/03/06 7pp 07878 218
- P. Operating license stage ducuments & correspondence
- Bio3199732 Lins to all licensees of operating plants applicants for OLS & holders of CPs recontrol of heavy loads Requests review per guidelines in NURGE 0-612 Forwards NRC position reinterin actions & request for addlinfo EISENAPTO D. D. Division of Licensing 80/12/22 3000
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs re grogram for environ qualification of safety-related plactrical equipment Items addressed involve cold stutzo-in-replacement parts & NUREG-0737.
  ESSEMMUTOD O Division of transing 81/01/19 App
- 6103240290 Ltr to all RHR licensess forwarding-Suppl 1 to generic safety evaluation on BMR scram discharge sys. Suntanties re-seveluation of interim deatures recommended per Boli201 safety evaluation.

  Ejectivity. D. O. Division of Licensing 81/01/23 2pp
- @103120014 Ltr to all licensees of operating plants CP holders & QL applicants, except indian Point 2 & 3. Zion 1 & 2 & 3Hi-1, forwarding inadvertently omitted pages from NRC 801222 request for addition to control of heavy loads EISCHMUT.0 @ Division of Licensing 81/02/03 6pp
- GIOBIODES Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support factilities Requests confirmation within 45 days that implementation of dates will be net EISCEMUTED Q Division of Licensing 81/02/18 t2pg
- 8103050037 Notification of cuntract execution "Environ Assessment of Low Leval Maste Storage at TVA Browns Ferry Nuclear Plant in Limestone County, GA: " awarded to Briente Applications, Inc HAJRSTON.C A., EDGEMORTH.F J Technical Assistance Contracts Branch FIN B-7319-1 81/02/20 12
- --8103050074 Contract "Environ Assessment of Low Level Waste Storage at TVA Browns Ferry Nuclear Plant in Limestone County,OA." avarded to Science Applications, Inc FINDLEY, D.E. Science Applications. Inc MATTIA.H. J. Administrative Contracts Branch FIN B-7319-1 81/02/20 [Opp.
- 8103250024 Ltr to all power reactor licensers & license applicants re NUREC-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENRUT.D G Division of Licensing. 81/02/20 Spp.
- 8103020510 Forwards tabulation of chlorine residual in raw cooling water sys for periods 760516-0605 & 761003-23 per ETS Section 4 1 3 Data indicates that weekly sampling is adequate to deronstrate compliance w/spec.

  MILLS-L M Tennessee Valley Authority 81/02/23 3pp 07786.058.
- BiO3130020 Forwards Amends 67.63 & 39 to Licenses DPR-33.DPR-52 & DPR-68 respectively 8 safety evaluation IPPDLITO.1 A Operating Reactors Branch 2. 81/02/24. 2pp 07907 153

- --BIO3130029 Amends 67.63 & 39 to Licenses DPR-33. DPR-52 & DPR-68, respectively, modifying cases for scram insertion times by specifying 290 milliseconds as time period to be used in analytical treatment of transients
  [PPS\_ITO.T A Operating Reactors Branch 2 81/02/24 37pp 07957 155
- ---8103133036 Safety evaluation supporting Amends 67.63 & 39 to Escenses
  IPR-33.DPR-52 & DPR-68, respectively.

   Office of Nuclear Reactor Regulation, Director 81/02/24 3pp
  07807 199
- Bi03230030 Ltr to all licensees of operating nuclear power plants & applicants for GLs (except St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement energency procedures FISEFRAUTO 0 0 Division of Licensing BI/02/29 5pp
- 0103170225 Ltr to all BHR licensess (except Humboldt Bay & LaCrossel requesting review of ASME Code Class I & 2 pressure boundary ciping, safe ends & fitting rath per guidelines of encl Revision 1 to NUMEG-0313 Model Tech Specs only encl EISENHUT.D O Division of Licensing 81/02/26 3pp
- --BiO3170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4 II surveillance requirements for ASMC Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements segments Electric Co. 81/02/26 4 App.
- 8103130108 Forwards Azands 68.64 & 40 to Licenses DPR-33.0PR-52 & DPR-68 respectively, safety evaluation & notice of issuance & availability IPPOLITO T. A. Licensing Branch 2 81/02/27 2pp
- --BIO3130118 Amends 68.64 & 40 to ticenses DPR-33.DPR-52 & DPR-64, respectively, clarifying calibr requirements for local power range monitors, reducing pressure at which scram time surveillance testing is conducted & removing startup test IPPCLITO.Y A Licensing Branch 2 81/02/27. 3Dpp
- --8103130125 Safety evaluation supporting Amends 68.64 & 40 to Licenset DPR-33.0FR-52 & DPR-68.respectively
  • Office of Nuclear Reactor Regulation, Director 81/02/27 Spp
- --8103130131 Notice of issuance & availability of Amends 60.64 & 40 to Litenses DPR-03.DPR-52 & DPR-60.respectively fPP0L170,T A Licensing Branch 2 81/02/27 2pp.
- 8103110414 Application for amend to Licenses DPR-33, DPR-52 & DPR-AH submitted as proposed changes to Tech Specs for operability & surveillance requirements for continuous level monitoring sys on stram discharge volume.per 16 3011eth 80-17, Buppl 4 MILLS.L M Tennessee Valley Authority 81/03/03. 4pp. 070372 2000
- --8103110440 Tech Spec 3 2 % Tables 3 2.F & 4.2 F for instrumentation surveillance.
   Tennessee Valley Authority, 81/03/03 18pp. 07872 271
- 8103100325 Advises that Tech Specs for NUREO-0737 items will not be submitted until receipt of further guidance from NRC. MILLS:L K Tennessee Valley Authority. 81/03/04. 1p 07865 06'l
- 8103100601 Forwards request for amend to Licenses DPR-DD, DPR-DD & DPR-68 MILLS(L # Tennessee Valley Authority, 81/03/04, 2pg, 07863;074
- --Bi03100693 Request for amend to Licenses DPR-33 DPR-32 & DPR-60, interchanging initiation logic for CO-2 fire protection sys & water spray sys in cable spreading from to make water spray primary sys & CO-2 sys member backup sys.

  Tennessee Valley Authority. 01/03/04. 1p. 07863.094
- 8103190209 Forwards Amends 69,65 & 41 to Licenses DPR-33.DPR-52 & DPR-68.respectively & notice of issuance & availability. IPPCLITO.T.A Operating Reactors Branch 2. 81/03/06 3pp
- --8103190299 Amends 69.65 % 41 to Litenses DPR-33.DPR-52 % DPR-60. respectively deleting ETS Sections 2 1.2 2.3.1.2.5.4. 5.6 3 b.5 7.1.c % changing tibles in Administrative Controls Section 5 0

  IPPOLITO.T. A Greating Reactors Branch 2 81/03/06 6Bpp
- --8103190269 Notice of issuance & availability of Amends 69.68 & 41 to Licenses DPR-33,DPR-52 & DPR-6B,respectively. IPPOLIYO.T. A Operating Reactors Branch 2, 81/03/06 2pp.

- 8103300499 Act receipt of 801020 request for reconsideration of Amends 60.55 & 32 to Licenses DPR-33.DPR-32 & DPR-68.respectively. authorizing temporary storage of low level reducate Ltr to be treated as IOCFR2 206 request H/FR notice DENIGN.H R Office of Nuclear Reactor Regulation, Director 81/03/06 32; 08098 049
- --BIQ3300500 Notice of receipt of 801028 request for action under 10CFR2 2C6 by Huntsville Chapter of Safe Energy Alliance of AL Requests reconsideration of certain amends to facility CLs.permiting temporary storage of low level radwaste DENION.H B. Office of Nuclear Reactor Regulation. Director DENTON H R Dffice of Nu B1/03/04 to 08058 052
- B103160593 Requests approval to install automatic dump scram sys in Units 1 % 2 on 810410 & 0417, respectively MILLE.L M Tennessee Valley Authority 81/03/10 ip 07917 198
- BIDGG10804 Ltr to all licensees of operating plants applicants for O<sub>m</sub>s 5 holders of CPs forwarding SECY-BII-119 re info necessary to establish environ qualification of safety-related electrical ecutoment EISENHULD C Division of Licensing 81/03/10 App
- 81031705B3 Forwards revised response to Item 19, correcting error in MILLS.L M Tennessee Valley Authority. 81/03/11 2pp 07929 345
- 9103170520 Discusses reinstatement of temporary relief from 5 F reservoir temp rise limit at facilities Requests mod of variance to allow full operation of facilities w/8 5 F river temp rise limitation EL-ABHRY.M T Tennesses Valley Authority 81/03/12 2pp 07930 114
- 8103231095 Informs that util 801215 & 810203 commitments do not most criteria Requests completion of mods by 821231. Dasign must include ARC diverse instrumentation criteria from 801201 generic SER on BMR scram discharge sys.

  #PPOLITO.T A Operating Reactors Branch 2 81/03/12. 2pp 07973 010
- B1032600B3 forwards preliminary results of NRC review of environ qualification of safety-related electrical equipment at facility lientified deficiencies & ramifications should be reviewed & overall findings submitted NOVAH.T.K. Assistant Director for Operating Reactors. B1/03/16 69ap. 08039.170.
- 8103270095 Surrary of Bi0304 meeting w/Merk I owners group & OE in Bethesda.HD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per !ANREO-0661 Bide presentation & list of attendees enci. GRIMES.C I Licensing Stanch 3. 81/03/16 5pp
- 810323054B Forwards add1 request for relief from ASME Section 11 exam requirements to RHR heat exchangers.
  MILLS.L.H. Tennesses Valley Authority 81/03/17. 2pp.
- 8103240341 Forwards util response to NUREO-0737 Item III.D 3 4 recontrol room habitability requirements. Chemicals stored analte in quantities greater than 100 lb will not affect control room on rupture of single largest container. MILLS-L M Tennessee Valley Authority. 81/03/17. 4pp. 07990:137
- 8103250673 Advises of planned site visit to obtain first-hand info re Unresolved Safety Issue A-44. "Station Discrete". Visit is tentatively scheduled for 810324 to coincide w/emergency diasel generator testing schedule. Branch 2 81/03/17. 4pp. 08000.250.
- 9 Inspection reports. IE Bulletins & correspondence
- 8102280484 Forwards IE Info Notice 81-01, "Possible Failures of 9E Type HFA Relays." No response required. O'REILLYJ P. Region 2. Atlanta, Office of the Director. 81/01/16. 07775.298
- 8103100045 Forwards IE insp Repts 50-259/80-44.50-260/80-41 & 50-276/80-40 on 801124-21. No noncompliance noted. LEWIS.R C. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 81/01/26. 2pp. 07855:111.
- --8103100053 IE Insp Repts 50-259/80-44.50-260/80-41 & 50-296/80-40 on RUJIVOUSS IE Insp Nepts 50-297/80-44,50-260/80-41 & 50-296/80-801124-27. No noncompliance noted Major areas inspected: MSIV testing & pipe support & restreint sys.

  BRODKB.E.H. Region 2. Atlanta, Office of the Director QUIC Region 2. Atlanta, Feator Derations Nuclear Support Branch BI/01/21 4pp. 07855 113. QUICK, D

- 8103020277 Forwards 16 Circular 81-02. Performance of NRC-License Individuals While on Duty "No written response required O'REILLY, J P Region 2- Atlanta. Defice of the Director BI/O2 14 07785 340
- 8103040802 Forwards monthly status rept for work re IE Bulletin 79 as of 810201 Rept includes drawing configuration insp.pipe support insp.floor & wall penetration insp & valve insp. MILLS.L M Tennassee Valley Authority 81/02/10 30pp 07610
- B103040156 Forwards IE Info Notice 81:03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/IOCFR50 72 " No written response required D'REILLY.J P. Region 2. Atlanta. Office of the Director 81/02 1p. 07812-342
- 8103050015 Forwards Suppl 5 to 1E Bulletin 80-17. 'Failure of Cont Rods to Insert During Scram at 8WR' No written response required of Region 2. Atlanta. Office of the Director 81/02 ip 07828 009
- 8103150682 Forwards 1E Info Notice 81-04. "Cracking in Main Steam Lines: "No response required O'REILLY, P. Region 2. Atlanta. Office of the Director 81/02 1p. 07914-317
- B103160516 Forwards IE Circular 81-03, 'Inoperable Reismic Monitor Instrumentation' No response required AEPPLER.J. O Region 3. Chicago, Office of the Director. 81/03/0 10 07916 338
- 8103170085 Provides addl info re IE Bulletin 80-15, "Possible Loss Emercency Notification Sys (ENS) w/Loss of Offsite Power' Util expects to complete required mods at Browns Ferry by 810427 & at Sequeyah by 810421. MILLS. It Tennessee Valley Authority 81/03/03 ip 07928 0
- B103180886 Describes content of encl to 801031 util responses to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment"
- MILLS, I.M. Tennessee Valley Authority 81/03/03 2nn 07954 (
- 8103120744 Ack receipt of 810205 ltr informing NRC of steps taken correct violations noted in IE insp Repts 50-259/80-40. 93-260/80-35 % 50-296/80-34 LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Suppor Branch 81/03/04 1p 07905 273
- --8103120749 Responds to NRC 810109 ltm re violations noted in IE Repts 50-259/80-40.50-260/80-35 & 50-296/80-34 Corrective actions fuel handling stopped while control rod inserted Procedure written for unloading control cells MILLS.L M Tennessee Valley Authority. 81/02/05. 5pp. 07905 274
- --A103120794 Forwards IE Insp Repts 50-257/80-40, 50-260/80-35 & 50-276/80-3) on 801001-31 & notice of violation O'REILLY. P Region 2. Atlanta. Office of the Director 81/01/97 2pp 07905.279
- --8103120760 Notice of violetion from insp on 801001-31.

  \* Region 2, Atlanta. Office of the Director 81/01/09. 2pp
- --8103120770 IE 1nsp Repts 50-259/80-40,50-260/80-35 & 50-296/80-3 [03120770 IE Insp Nepts 30-259/80-40-30-250/80-35 & 50-296/80-35 &
- 8103170011 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ("ARICLY.) P Region 2. Atlanta. Office of the Director 81/03 ip 07924:086.
- 8103130739 Forwards 1E Enforcement Meeting Ropts 50-259/81-04. 50-260/81-04 & 50-296/81-04 on 810211, re facility fire protection/prevention program
  O'REILLY-J.P. Region 2. Atlanta, Office of the Director. B1/03
  1p. 07912-061.
- --8103130741 IE Enforcement Heeting Repts 50-259/B1-04,50-260/B1-0 50-296/B1-04 on 810211. Areas discussed fire protection & prevention program at facility.

  MILLER.H H. Region 2. Atlanta. Office of the Director
  CONLON.T.E. Region 2. Atlanta. Reactor Construction & Enginee
  Bupport Branch. 81/03/02 4pp. 07912.062

032406B1 1E loss Repts 50-259/80-47.50-260/80-37 % 50-296/80-41 on B01201-31 Noncompliance noted failure to have tonus access strield plugs installed as required by safety analysis BULLIVAN.9 F., CHASE.J H. Region 2. Atlanta. Office of the Director Dates.H C. Region 2. Atlanta. Reactor Operations Nuclear Support Pranch B1/02/25 1tpp 07983 206

1270680 Forwards IE Insp Repts 50-259/81-03.50-260/81-03 & 1-298/81-03 on 810101-31 & notice of violation
1415.8 C Region 2: Atlanta. Dffice of the Director 81/03/10
p - -38045 189

03270089 Notice of violation from insp on 810101-31.

Region 2. Atlanta, Office of the Director 81/03/10 2pp
08045-191

03270104 IE Insp Repts 90-209/D1-03.50-260/D1-03.50-276/B1-03 on BIO101-31 Nancompliance moted secondary containment not caintained t nacioactive contaminated ladder found in clean area.

Telan area Sull Vanu R F. CHASE. J H. PAULK.O L. Region 2. Atlanta. Office of the Director Bi/03/69 10pp 08049 193

1200197 Forwards IE Info Notice 81-06. "Failure of ITE Model K-690 roust 3reater " No response required REILLY, JP Region 2. Atlanta, Office of the Director G1/03/11 07988 319

2200003 Forwards IE Info Notice 81-05. "Degraded D2 9ys at Illsades" No response required REILLY. 19 Region 2. Atlanta, Office of the Director 81/00/13 ... 07969 068

1261211 Responds to IE Bulletin 79-18. 'Audibility Problems countered on Evacuation of Personnel From High Noise 'eas' 'New speakers having appropriate design & power pting in high noise areas will be installed by Fe) 1982 (LUSLL M Tennessee Valley Authority 81/03/13 2pp.

0270044 Responds to IE Bultetin Bi-Oi. "Surveillance of Mechanical Nubbers." Engoing inso in progress, Requests exemption from [3] testing until neit scheduled refueling outage Estimates net 200 manhours will be required to implement actions.

CLS,L M. Tennessee Valley Authority 81/03/13 12pp.

P190524 EN-81-010 on B10320 notice of violation & proposed consistion of civil penalties will be issued Action based on leged noncompliance re fire protection program (RBER, 0, THOMPSON D. Director's Office, Office of Inspection and office-ont B1/03/17 Ip 07755 124

1261180 Responds to IE Bulletin 80-25, "Operating Problems H/Target ock Safety Relief Valves at BMRs " Thirty-nine GE two-stage orget Rock valves in use Testing of valves will be initiated during neit refueling shutdown LLB.L M. Tennessae Valley Authority 81/03/18, Spp. 08040:259.

1261156 Discusses IE insp on 810106-09 \$ 20-23 & forwards notice of plation & notice of proposed imposition of civil penalty ELLO.Y Birector's Office. Office of Inspection and Enforcement 703/20 2pp 08035:274.

03261166 Notice of violation & proposed imposition of civil penalties in amount of \$50,000 from insp on 810106-09 & 20-23 Arees of noncompliance moted in fire protection program STELLO.V. Director's Office Office of Inspection and Enforcement. 81/03/20 4pp 08035.276

- --8103170550 Monthly operating repts for Fab 1981 IHOM.T. Tennessee Valley Authority. NI/03/01 40pp 07933-304
- S Reportable occurrences. LERs & related correspondence
- BiO3240413 RQ 50-259/8103 on BiO124, during normal operation, notification was received that i-inch went line on scram discharge volume not solenically qualified Caused by renembermance to design requirements Rostraints installed ABERCROPOIE.H Tennesseo Valley Authority B1/O1/27 ip O3966 O01.
- 8103240433 RQ 90-259/8105 on 810131 during normal operation pN of reservoir was in excess of discharge limit Cause unknown Discharge of demineralizer regainerants was stopped, Raw water samples were taken & analysed for pN. APERCROM31E, H. Tannossee Valley Authority. 81/02/02. Ip 03966 001.
- 8103110607 Forwards LER 81-007/03L-0. GREEN.R J. Tennessee Valley Authority 81/03/Q6. 1p. 07882-356
- --B103110613 LEW 81-007/03L-0 on B10210 during fire door inspirite door damper (300x 472) Not closed Caused by paint buildup in operating mechanism Damper closed 5 other dampers insported Procedure for insp 6 preventive maint will be written Tennessee Valley Authority. B1/03/06 2pp. 07882.357.
- 8103120473 PNO-11-91-021 on B10306, contere inadvertently vented radioactive page, into turbine bldg. Personnel evacuated & sample line isolated No personnel evacuated & sample line isolated No personnel evacuated averesposed. MRAY. J R HOSEY, C M Region 2. Atlanta, Office of the Director 81/03/09. 1p 07901 247
- 81C0160795 Forwards LER 81-008/017-0 GREEN.H J. Tennessee Valley Authority. 81/03/09. 1p 07914:147
- ~-8i03i60757 LER Bi-008/01F-0 on Bi0226, secondary containment integrity lost when exterior equipment access door 229 & interior personnel door 228 opened simultanedualy. Caused by lack of interlocks between doors, interlocks to be installed.

  \* Tennessee Valley Authority. 81/03/09, 2pp 07914:148.
- 8103240452 Forwards LER 81-009/01T-0. OREEN:H J Tennessee Valley Authority 81/03/17. 1p 07984.314
- --Bi03240458 EER-Bi-009/01T-0 on Bi0304:IE info Notice 80-45 evaluation determined that reactor protection sys for Units 2 % 3 were deficient upon loss of power w/subsequent restoration Caused by design deficiency Caution added to instructions.

   Tennessee Valley Authority. Bi/03/87. 2pp. 07984-315
- 8103310781 Forcards LER 81-010703L-0 GREEN.H J. Tennessee Valley Authority. 81/03/25 Ip. 08051:112.
- --8103310739 LER 81-010/03L-0: on 810302, continuous air monitor I-RH-90-250 for reactor/turbine bldg ventilation exhaust decisted inoperable. Caused by water in earple line due to condensation. Instrument repaired, tested & returned to svc. e Tennessee Valley Authority. 81/03/28, 2pp. 08061-113

- DOCKET 50-260 BADWINS FERRY NUCLEAR PCHER STATION. UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8103;80264 Lir to all power reactor licensees u/plants licensed prior to 700;03 Forwards NRC position & request for add linfo re safe shutdown capability for compliance u/B01119 fire protection rule ELERNAUT.D Q Division of Licensing 81/02/20. 13pc
- 8)03040717 Informs that licenses will conduct emergency preparedness exercises Sept 1981 for Browns Ferry & Mar 1982 for Hatts Bar.per 810130 request Evercise scenarios will be provided four with before scheduled exercise MILLS.L.M. Tennessee Valley Authority 81/02/25 ip. 07812 269
- B103C60335 Forwards add1 info re guard training & qualification plans Encl withheld (ref 10CFR2 790) HILLS,L H Tennessee Valley Authority, 81/02/26 ic. 07837 0A3
- 8103]60133 Forwards add1 revisions necessary to find 810123 safeguards contingency plan acceptable Response requested within 30 days.

  IPPOLITO T A Operating Reactors Branch 2. 81/03/02 4pp 0.7919 324
- 8103310338 Lir to all licensees of operating plants & holders of CPs forwarding NUREG-0696. 'Functional Criteria for Emergency Response Facilities 'Criteria describe acceptable method for meeting NRC requirements M/o encl EISENHUT.D O Division of Licensing 81/03/05 App
- B103170194 Forwards revisions to physical security plan. Encl withheld (ref 100FR2 790)
  MILLS, L. H. Tennesset Valley Authority 81/03/07 lp 07935:317
- 8103260239 Requests exemption from App R fire protection requirements re-safe shutdown capability, smergency lighting & oil collection sys for reactor coolant pumps Responds to NRC 801124 & 810220 itrs to all PiR licensees.
  MILLS.L M Tennessee Valley Authority. 81/03/18. 2pp 08037.167
- 8103270912 Requests relief from commitment re installation of lighted exit signs in response to NRC 810204 request Externally illuminated directional exit-type signs are adequate MILLS.L H Tennessee Valley Authority. B1/03/20. 2pp. 08046-229
- Q Adjudicatory correspondence
- B103130451 Order setting B10410 prehearing conference to discuss patitioners' standing to intervene.Patitioners must file suppls to patitions no later than 13 days prior to conference-listing contentions sought to be litigated.
  ORGGBMAN.H Tennesse Valley Authority. B1703/10 4pp. 07911 267
- 8103260121 Reply to T Paul,R Jobe & M Hall & H Fenn.R Hudgens & T Thornton petitions to intervene. Util objects to ABLB considerations of petitions for lack of proper svc.Petitions should be denied if considered. Certificate of Svc encl. SANGER.H B., HALLACE.L. E., BURGER.J.F. Tennessee Valley Authority. B1/03/13. Spp. 08041:295.
- 8103270467 Notices of eppearance in license amend proceeding. Certificate of Byc enc.i. LAVERTY.J.H. Hearing Branch I. LEMIS.S.H. Hearing Branch 2. 81703724, 4pp. 08034:146.
- J Insurance & indemnity information
- 8103060339 Forwards Endorsements 4 to MAELU Dinders X8-38.X8-39 & X8-40.
  FIELDER-J. Moreh & McLennen.Inc., M & M Nuclear Consultants.Inc. 81v 81/01/27. 7pp. 07840:225.
- B103060368 Forwards Endorsement 44 to MAELU Policy MF-66. FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 81/01/29. 2pp. 07840: 236.
- B103)10616 Forwards Endorsement 5 to MAELU Binder XB-38.XB-39 & XB-40. FIELDER, J. Marsh & McLennan.inc., M & M Nuclear Consultants, Inc. Div. B1/03/06. 7pp 07878.218.

## P Operating license stage documents & correspondence

- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in hURFG-0612 Forwards NRC position reinterim actions & request for addline
- BIO3190087 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREC-0737 EISENBUT.D O Division of Licensing 81/91/19 App
- Bio3240290 Ltr to all BWR licenses forwarding Suppl 1 to generic safety evaluation on BWR scran discharge sys Summarizes re-evaluation of interim neasures recormended per 801201 safety evaluation EISENHUT. D O Division of Licensing 81/01/23 2pp
- B103120014 Ltr to all licensees of operating plants.CP holders & UL applicants.e:cept Indian Point 2 & 3. Zion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from MRC B01222 request for addl info re control of heavy loads EISEDHUT.D Q. Division of Licensing B1702703 &pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMT Action Plan Item III.A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met.
  EISENHUT.D 0 Division of Licensing 81/02/18 12pp
- 8103033670 Application to arend License DPR-52.changing Tech Specs remove refs to power spiking penalty for 818.8188 & P8188 fuel Class II amend fee encl MicLS.L M Tennessee Valley Authority 81/02/20 2pp 07798 2
- --B103030674 Proposed Tech Specs Sections 3 5 J & 4 5 J re linear h generation rate surveillance requirements & limiting conditions for operation Justification enci a Tennessee Valley Authority B1/02/20 Spp 07798 248
- B103030057 Notification of contract execution "Environ Assessment Low Level Waste Storage at TVA Browns Ferry Nuclear Plant in Limestone County, On." avanded to Becence Applications. Inc MAIRBION.C A. EDGEMORTH.P J Technical Assistance Contracts Bra FIN B-7319-1. B1/02/20 1p
- --8103050074 Contract: "Environ Assessment of Low Level Waste Stora TVA Browns Ferry Nuclear Plant in Limestone County, OA," awarded to Science Applications, Inc FINDLEY, D. & Science Applications. Inc MATTIA, M J Administrative Contracts Branch. File 8-7319-1 81/02/20. 10p
- 8103250024 Ltr to all power reactor licensees & license applicants NUREO-0617 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may subnit analysis to justify use of existing low flow controller ETSENHUT. D O Division of Licensing B1/02/20. Bpp.
- Bi03020510 Forwards tabulation of chloring residual in raw cooling water sys for periods 760516-0605 & 761003-23.por ETB Section 4 1 3 Data indicates that weekly sampling is adequate to demonstrate compliance u/spec MILLS.L M. Tennesse Valley Authority. Bi/02/23. 3pp. 07785 0
- 8103130020 Forwards Amends 67:63 & 39 to Licenses DPR-33:DPR-52 & DPR-68:respectively & safety evaluation IPPDLITD.T. A Operating Reactors Branch 2. 81/02/24. 2pp 07907-153
- --BIO3130029 Amends 67.63 & 39 to Licenses DPR-33, DPR-52 & DPR-6B, respectively, modifying bases for scram insertion times by specifying 290 milliseconds as time period to be used in analytical treatment of transients.

  [PPOLITO.T.A. Operating Reactors Branch 2. B1/02/24 37pp. 07907.155
- --B103130036 Safety evaluation supporting Amends 67.63 % 39 to Lice DPR-33.DPR-52 & DPR-68-respectively will office of Nuclear Reactor Regulation, Director. B1/02/24.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 8t Lucis Units 1 & 2). Requests util review to determine capability to mitigate station blackout event 8 promptly implement emergency procedures EISENHUT, D. G. Division of Licensing. 81/02/25. 5pp.

- Bj03170225 Ltr to all BUR licensees letcept Humboldt Bay & LaCrosse)
  requesting review of ASMC Code Class 1 3 2 pressure boundary
  plping:safe ends 5 fitting natl per gouldlines of encl
  Revision 1 to bJRE0-0313 Mode! Tech Specs analy encl
  EISEMHUT.D 9 D:vision of Licensing 81/02/26 3cp
- -- Bi03170255 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4-8 respirellance requirements for ACME Code Class 1.2 % 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements & General Electric Co. 81/02/25 499
- S10313010H Forwards Aments 68.64 & 40 to Licenses DFR-33.0PR-52 & DFR-48 respectively, safet, evaluation & notice of issuance & availability (FFQUITO T A Licensing Stanch 2 81/02/27 2pp
- -- 3103130125 Safety evaluation supporting Arenda AB.64 & 40 to Licenses DRR-33.DRR-52 & DRR-68 respectively • Office of Nuclear Reactor Regulation. Director 81/02/27 3pp
- --G103130131 Notice of issuance & evailability of America 68.64 & 40 to Licenses DPR-33.DPR-52 & DPR-68.respectively IPPDLITD.TA Licensing Branch 2 BI/02/27 2FP
- B103;;0414 Application for amend to Escenses DPR-03. DPR-52 & DPR-68 submitted as proposed changes to Tech Specs for operability & surveillance requirements for continuous level monitoring sis on scram discharge volume.per IE Bulletin B0-17. Suppl 4 MILLS.L M Tecressee Valley Authority 81/03/03 4pp. 07872 288
- ~-Bi03110440 Tech Spec 3 2 % Tables 3 2 F & 4 2 F for instrumentation surveillance • Tennessee Valley Authority B1/03/03 LOpp 07872 291
- Bj03106325 Advises that Tech Specs for NUREO-0737 ;tems uill not be submitted until receipt of further guidance from NRC MILLS-L M Termossee Valley Authority 81/03/04, 1p 07865:063
- B)03100601 Forwards request for amend to Licenses BPR-33.0PR-52 & DFR-88 MILLS.L H Tennessee Valley Authority, 81/03/04 2pp 07853.092
- --B103103603 Request for amend to Licenses DPR-33.DPR-52 & DPR-68, interchanging initiation logic for CG-2 fire protection sys & water spray sys in cable spreading room to make water spray primary sys & CG-2 sys manual backup sys = Tennessee Valley Authority 81/03/04. Ip 07863 094
- B103190249 Forwards Amends 69.65 % 41 to Licenses OPR-33.0PR-52 & DPR-68.respectively % notice of issuance & availability. IPPOLITO.T A Operating Reactors Branch 2 81/03/06 3pp
- --B103190297 Amenda 69,65 & 41 to Licenses DPR-33 DPR-52 & DPR-68, respectively, deleting ETB Bections 2,1,2,2,3,1,2,5,4, 5 6 3 6,9,7 1 c & changing titles in Administrative Controls Section 5 0

  IPPOLITO, T A Coperating Reactors Branch 2 81/03/06 68pp.
- --B103190269 Notice of issuance & evallability of A-anda 69.65 & 41 to Licenses DPR-33, DPR-52 & DPR-68, respectively IPPOLITO, T. A. Operating Reactors Branch 2 81/03/06 2pp
- 8103300495 Act receipt of 801028 request for reconsideration of Amends 60.55 t 32 to Licenses DPR-33.0PR-52 t DPR-68, respectively, authorizing temporary storage of low level radwaste. Ltr to be treated as 10CFR2 206 request M/FR notice. DENTON.H R Office of Nuclear Reactor Regulation. Director. 81/03/06 3pp 08038 049.
- --0103300500 Notice of receipt of 801020 request for action under 10CFR2-206 by Auntsville Chapter of Safe Energy Allance of AL Requeste reconsideration of certain amends to facility Ols.permitting temporary storage of low level raduaste DENTON. H.R. Office of Nuclear Reactor Regulation. Director, 81/03/06 by Q8059-052.
- 03:03160593 Requests approval to install automatic dump scráp sus in Units I & 2 on 810410 & 0417, respectively. MILLS.L M Tennessee Valley Authority 81/03/10 tp. 07917 198

- 0103310804 Ltr to all licensees of operating plants, applicants for GL thelders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related ejectrical equipment FISEMINUT.D C Division of Licensing 81/03/10 App
- 8103170583 Forwards revised response to Item 15.correcting error in encl of 810210 Itr re weld failures
  MILES.L M. Tennossee Valley Authority. 81/03/11 2pp 07929-345
- 8:03:79520 Discusses reinstatement of temporary relief from 5 F reservoir temp rise limit at facilities Requests mod of variance to allow full operation of facilities w/8 5 F river temp rise limitation
  EL-ASHRY.M. F Tennessee Valley Authority 81/03/12 2pp 07970-113
- E103231095 Informs that util 801215 & 810203 commitments do not meet criteria Requests completion of mots by 821231 Design must include NRC diverse instrumentation criteria from 801201 generic SER on BNR scram discharge sys ippCLITG.T.A. Operating Reactors Granch 2 81/03/12 2pp 02273 010.
- BIO3260083 Forwards preliminary results of NRC review of environ qualification of safety-related electrical equipment at facility identified deficiencies & ramifications should be reviewed & overall findings submitted (EDVAK-T M. Assistant Director for Operating Reactors. 81/03/16
- 8103270095 Surnary of 810304 meeting u/Mark 1 owners group & GE in Bethesda.MD re supplementary tests conducted in full-scale test facility & resolution of autstanding Mark I issues per MARCO-0651 Bitse presentation & list of attendeds encl CRIMES.C I Licensing Branch 3 81/03/16. Spp
- BIO323054B Forwards add1 request for relief from ASME Section 11 electron requirements re RHR heat electrongers
  MILLS.L.M Tennessee Valley Authority BI/03/17 2pp
- Bi03240341 Forwards with response to NuREO-0737 Item 111 0 3 4 recentral room habitability requirements. Chemicals stored onsite in quentities greater than 100 ib will not affect control room on rupture of single largest container MILLS. L.M. Jennessee Valley Authority. Bi/03/17. 4pp 07990: 13.
- 8103250673 Advises of planned site visit to obtain first-hand info re Unresolved Safety Issue A-44, "Station Blackout." Visit is tentatively scheduled for B10324 to coincide w/mmergency diesel generator testing schedule. IPPOLITO.T A Operating Reactors Branch 2 81/03/17. App 08000 250
- O Inspection reports: IE Bulletins & correspondence
- 8103100045 Forwards 1E insp Repts 50-259/80-44.50-260/80-41 & 50-276/80-40 on 801124-21.No noncompliance noted. LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/26 2pp 07855:111
- --Bi03i07053 (E Insp Repts 50-289/80-44:50-260/80-41 t 30-296/80-40 e B01124-27.No noncompliance noted Major areas inspected MGIV testing & pips support & restraint sys RROMS.E H Region 2: Atlanta. Office of the Director. GUICK-D Region 2: Atlanta. Reactor Operations Nuclear Support Branch. B1/01/21 App 07855-113
- 8103020277 Forwards 1E Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty" No written response required. D'REILLYJ P. Region 2. Atlanta. Office of the Director. 81/02/0' ip. 97785-348.
- B103040802 Forwards monthly status rept for work re IE Bulletin 79-14 as of B10201 Rept includes drawing configuration inspiring support inspiritually penetration inspired in
- B103040156 Forwards IE Info Notice B1-03, "Checklist for Licensees Making Notifications of Significant Events In Accordance W/100FR80 72" No written response required O'REILLY.J.P. Region 2: Atlanta, Office of the Director. 81/02/11 pp. 97812-342
- 8103050015 Forwards Suppl 5 to IE Bulletin BO-17. "Failure of Control Rods to Insert During Scram at SUR." No written response required.
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/02/11.
  1p. 07828-009

- 8103160682 Forwards IE Info Notice 81-04. 'Cracking in Main Steam Lines.' No response requires D'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/02/27 (p. 97914-319
- G103160516 Forwards IE Circular 81-03, "Inoperable Seismic Munitoring Instrumentation " No response required XEPPLER, J.G. Region 3, Chicago, Office of the Director 81/03/02
- 8103170085 Provides addition or IE Bulletin 80-15. "Possible Loss of Emergancy Notification 6ys (ENS) w/Loss of Offsite Power"

  Util expects to complete required mode at Browns formy by 810421 MILLS-L M Tennessee Valley Authority 81/03/03 1p. 07928 032
- 8103180886 Describes content of enci to 801031 util responses to IE Builetin 79-018. "Environ Qualification of Class IE Equipment."

MILLS.L M Tennessee Valley Authority. BI/03/03 2pp 07934 007

- 8103120744 Ack receipt of 810205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-259/80-40, 50-260/80-35 & 50-296/80-34

  LEMIS.R.C. Region 2. Atlanta, Resistor Operations Nuclear Support Branch 81/03/04 ip 07905-273
- --8103120749 Responds to NRC 810109 itr re-violations noted in IE Insp. Repts 90-259/00-40.50-260/80-35 % 50-294/80-34 Corrective actions fuel handling stopped while control rod inserted Procedure written for unloading control cells. HTLLS.L M Tennossee Valloy Authority. 81/02/05 5pp. 07905.274
- --8103120754 Forwards IE Insp Repts 80-259/80-40,50-260/80-35 & 30-296/80-34 on 801001-31 & notice of violation.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director 81/01/09. 2pp 07905.279
- --B103120760 Notice of violation from insp on B0100]-31
   Region 2. Atlanta, Office of the Director. 81/01/09 2pp
  07903-281.
- --DID3120770 IE Insp Repts 50-259/80-40, 50-260/80-39 % 50-296/80-34 on B01001-31. Noncompliance noted failure to have all refueling interlocks operable during refueling operations Fuel assemblies loaded winne control rod withdrawn. SULLIVAN.R F., CHABE, J. M. MARSH.R. J. Region 2. Atlanta, Office of the Birector. B1/01/09 14pp. 07905-283
- 8103170011 Forwards revised [E Bulletin Bi-Oi, "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6 Change in identification of facilities u/CPs to which bulletin in applicable does not affect util requirements
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. Bi/O3/04.

  1p. 07924 086
- 8:03130739 Ferwards IE Enforcement Moeting Repts 50-259/B1-04, 50-260/B1-04 & 50-296/B1-04 on B10211.re facility fire protection/prevention program UfREILLY.J.P. Region 2. Atlanta. Office of the Director. B1/03/05, ip 07912:061
- --8103130741 IE Enforcement Moeting Repts 50-259/81-04.50-260/81-04 to 50-276/81-04 on 810211 Areas discussed fire protection & prevention program at facility.

  MILLER.W.H. Region 2. Atlanta, Optice of the Director.

  CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Oranch. Bi/03/02 4pp. 07912-062
- BIO31608B3 Provides supplemental response to Suppl 4 to IE Sulletin BO-17: "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BMR " Appropriate procedures have been developed in response to builtin HILLBL M. Tennessee Valley Authority. B1/03/05. 2pp. 07915:242.
- 8103260477 Forwards monthly status rept of work as of 810301 re IE 8ulietin 79-14, "Unauthorized Procurement & Distribution of Xe-133." MILLS:L.M. Tennesses Valley Authority, 81/03/09, 29pp. 08037:173.
- 8103240655 Forwards 1E Insp Repts 50-259/80-47,50-260/80-37 & 50-296/80-41 on 801201-31 & notice of violation. LEWIS,R.C. Region 2, Atlanta, Office of the Director. 81/03/10. 2pp. 07983,202.
- --8103240666 Notice of violation from insp on 801201-31. • Region 2. Atlanta, Office of the Director. 81/03/10 2pp. 0783:204.

- --8103240481 lE insp Repts 50-259/80-47.50-260/80-37 % 90-296/80-41 B01201-31 Noncompliance noted failure to have torus access shield plugs installed as required by safety analysis BULLIVAN.R.F. CHASE.J W. Region 2. Atlanta. Office of the Director DANCE.H.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/25 11pp 07983 206
- B1032700B0 Forwards IE Insp Repts 50-259/B1-03.50-260/B1-03 & 50-296/B1-03 on B10101-31 & notice of violation LEWIS.R C Region 2. Atlanta. Office of the Director B1/03/10 2pp 08945 189
- --8103270089 Natice of violation from insp on 810101-31

   Region 2, Atlanta, Office of the Director 81/03/10 2pp
- --BIC3270104 IE Insp Repts 50-259/B1-03.50-260/B1-03 & 50-296/B1-03 BIO101-31 Noncompliance noted secondary containment not maintained & radioactive contaminated ladder found in clean area SULLIVAN.R F , CHASE.J W . FAULK.C L Region 2. Atlanta. Office the Director B1/03/09 10pp 08045
- 8103200197 Forwards IE info Notice 81-06. 'Failure of ITE Model K-60 Circuit Breaser' No response required.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/1 ip 07968 319
- 8103200003 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades" No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 81/03/11 p. 07949 068
- 8103261211 Responds to IE Bulletin 79-18. "Audibility Problems Encountered on Evacuation of Personnel From High Noise Areas " New speakers having appropriate design & power rating in high noise areas will be installed by Feb 1982. MILLB.L.M Tennessee Valley Authority 81/03/13 2pp
- BiO3270044 Responds to IE Builetin Bi-O1. "Surveillance of Mechanical Shubbers" Engaing insp in progress Requests elemption from addit testing until next scheduled refueling outage Estimates that 200 manhours will be required to implement actions MILLS.L M Tennessee Valley Authority 81/03/13 12pp
- 8103190924 EN-81-010 on B10320, notice of violation & proposed imposition of civil penalties will be issued Action based on alleged noncompliance re fire protection program DARBER, 0 . THOMPSON, 0 Director 's Office, Office of Inspection and Enforcement 81/03/17 ip. 07955 124
- 8103261180 Responds to IE Bulletin 80-25. "Operating Problems H/Targa Rock Bafety Relief Valves at BuRs." Thirty-nine OE tup-stage Target Rock valves in use Testing of valves uill be initiated during nert refueling shutdown MILLS.L.M. Tennessee Valley Authority. 81/03/18 5pp. 08040.255
- B103261156 Discusses IE insp on B10106-09 & 20-23 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO.V. Director's Defice, Office of Inspection and Enforcement. B1/03/20 2pp 08035.274.
- --8103261166 Notice of violation & proposed imposition of civil penal in amount of \$50.000 from insp on 810106-09 & 20-23 Areas of honcompliance noted in fire protection program STELLO.V. Director's Office of Inspection and Enforcement 81/03/20. 4pp 08035 276.
- --BIDQ261177 Notice of deviation from insp on BIDI06-09 & 20-23 floncompliance noted several doors in control bay portion of plant have not been changed to approved type fire doors & unapproved valves provided for HPCI sprinkler sys. Director's Office of Inspection and Enforcement 81/03/20. Ip 08035-280.
- R Periodic operating reports & related correspondence
- BiO3050497 Forwards "Annual Operating Rept. 1980." MILLB.L M. Tennessee Valley Authority. 81/02/27. 1p. 07824: 140
- --Bi03050511 "Annual Operating Rept.1980" 
  \* Tennessee Valley Authority. RH-BI-1-BF-1 B1/02/27. BOpp. 07824:141
- B103;70546 Forwards monthly operating repts for Feb 1981. ABERCROHBIE, H Tennessee Valley Authority B1/03/10. ip. 07933, 303.

- --Bi03170350 fionthly operating repts for Fab 1981 THOM. T. Termessee Valle, Authority. 81/03/01 40pp 07933.304
- 5 Reportable occurrences. LERs & related correspondence
- 6103060314 RD on 801205.2/unit in operation.RPR heat eichanger 20 was removed from syd due to leakage Cause is undetermined Surveyllance testing was performed per Tech Specs ABERCROMBIE.X Tennessee Valley Authority 80/12/09 in 07586 001
- 8103170540 Forwards LER 81-908/05L-0 GREEN:H J. Terrestee Valley Authority 81/03/10 tp 07729 240
- ---B103170549 LER 81-008/03L-0:on 810220, reactor core isolation cooler turbine trip & throttle valve closed & Lould not reopen. Caused by overload heater relay Relay replaced -- Tennessee Valley Authority B1/03/10 2pp 07929 341
- 9103250299 Forwards LER 81-009/03L-0 GREEN.H J. Tennessee Valley Authority 61/03/20 1p 07996-347
- --8103250315 LER 81-009/03L-0 on 810302 recirculation motor generator sets 28 1 2A tripped Caused by resistance temp detector operating 2A-K458 relay & tripping 28 set 8et 2A PT fue compartment compartment correct trircult interrupted by Tennessee Valley Authority 81/03/20. 2pp 07996 348
- 8103319591 Former4s LER 61-010/03L-0 GREEN.H J Tennessee Valley Authority 81/03/25 15 C8062:210
- --8603310594 [ER 81-010/03L-0 on 810305.during normal operation, special instruction 4 1 8.2 was not performed Caused by personnel error Personnel cautioned to perform instructions as scheduled

  Tennessee Valley Authority 81/03/25 2pp 08062:211
- SDCKET 50-261 H B ROBINSON PLANT, UNIT 2

  F Security, matical, energency & fire protection plans
- 8103031075 Notification of 810223 meeting w/util to discuss emergency planning & early warning sys for facility NEIGH3URS.D Operating Reactors Branch 1 81/02/12 2pp 02797 035
- BIO31B3264 Ltr to all comer reactor licenses w/plants licensed prior to 790101 Forwards NRC position & request for addlinfore safe shutdown capability for compliance w/801119 fire protection rule.
  EISENHUT. D.O. Division of Licensing 81/02/20 13pp
- BiO310D101 Requests that encl emergency planning info be made publicly available Wo encl SOUDER. J L. Division of Rules and Records BI/02/27. 1p 07833-176
- 860310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0596. "Functional Criteria for Emergency Response Pacificial "Criteria describe acceptable method for meeting NRC requirements W/o encl. EISEKINUT.D O Division of Licensing 81/03/05 6pp.
- B103240407 Requests exercision from requirements of 10CFR50.48 & App R to 10CFR50.including installations of fire supression sys in control room & lube oil collection sys imposition of 10CFR50.48C schedules will create risk of sefety degradation UTLEY.E. E. Carolina Power & Light Co. 81/03/11. 39pp. 07989.130.
- 8100230169 Requests additinfo to continue review of guard training & qualification plan Response requested within 30 days of receipt of 1tr Encl withheld (ref 10CFR2 790). Wo encl VARQA.B A Operating Reactors Branch 1. 81703712. 2pp. 07974 331
- B103190123 Releases public version of emergency procedures FELTON J. H. Division of Rules and Records B1/03/16 Ip. 07806.001.
- --8103190130 Forwards public version of operating manual, Vol 13.8gok 2, energency procedures.

  UTLEY, E. E. Carolina Power & Light Co. 81/02/23 1p. 07806-001

- --8103190136 Public version of operating manual.Vol 13.Book 2.bnergenc, procedures includes emergency classifications & control. emergency action.emergency facilities & equipment & training ejercises & drills (RQCRER, \$ Carolina Power & Light Co 81/02/20 400pp 07894.00)
- 8103240352 Informs that elemption request due filed 810311 seeking extension until 810701 for providing plans-schedules & jestign descriptions for alternative or dedicated shutdown sys Required erergency lighting sys has been installed UTLEY.E.E. Carolina Power & Light Co. 81/03/19 2pp 07981.334
- B103303478 Requests that encl emergency planning info be made conspicurusly available to public Great public interest anticipated M/o encl SCUDER. J. L. Division of Rules and Records. B1/03/24. Ip. 00057-170
- J Insurance & indemnity information
- 6103190494 Forwards Endorsement 5 to MAELU Binder EB-21
  PARHAM.C D. Carolina Power & Light Co. 81/03/12. 200 07965 221
- P Deprating license stage documents & correspondence
- 8(03):90732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re-interir actions & request for addl info FISENHULD O Division of Licensing 80/12/22 30pp
- B1031903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment I tems addressed involve cold shutdown replacement parts & NVREQ-0737 EIGENIUM D O Division of Licensing B1/21/19 dap.
- BiO3120014 Ltr to all licensees of operating plants CP holders & Ct. applicants, except indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC BO1222 request for add1 info re control of heavy loads. EISENBUT, 0 0 Division of Licensing. Bi/02/03 App.
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys selsmic design. Forwards request for add1 info.tist of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISENHUT.D.Q. Division of Licensing. 81/02/10. 13pp.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A.1.2 re upgrade of smergency support facilities, Requests confirmation within 45 days that implementation dates will be met.

  EISENHULD 0 Division of Licensing 81/02/18. 12pp
- 6103250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller. EISENHUT.D 0 Division of Licensing. 81/02/20. 8pp.
- BiO310193 Forwards "Equipment Evaluation Rept by Dfc of Nuclear Reactor Regulation for Carolina Power & Light Co. HB Robinson.Unit 2." partial review Written response required. NOVAK.T M Assistant Director for Operating Reactors. B1/02/23 3pp. 07884:250
- --8103110200 "Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for Caroline Power & Light Co.HB Robinson, Unit 2." partial review. • Office of Nuclear Reactor Regulation, Director. 81/02/23. 25pp 07884 253
- B103020443 Responds to NRC 801031 request for info re containment sumps £ insulation. Applicable portions of design drawings 9-190267 £ 190371 detailing RHR recirculation sump arrangement & associated piging enci UTLEY.E.E. Carolina Power & Light Co 81/02/24. 31pp. 07789 131.
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie.Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EIBENHUT.D.Q. Division of Licensing. 81/02/28. 5pp.

- 8103030752 Clarifies util 801215 position re NUREG-0737 Item I A 1 3 re limitations on overtime required of licensed operators Util limitations on overtime required or literaged operators util maintains that normal facility manning policies neet NRC guidance Addl limits will create administrative burden. UTLEY.E.E. Carolina Power & Light Co. 81/02/26 Spp. 07796 079
- 810311C061 Burmary of 810219 meeting w/util in Bethesda MD to discuss app R procedural & technical questions Util plans to file exemption requests for relief from 10CFR50 48 & from certain and requirements Agenda & list of attendees encl MARINDIA J. N. Operating Reactors Branch 2 81/02/26. 4pp
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re-1005R80 71(a). "Periodic Updating of FSARs," effective 800722. Info re FSAR legal status, format & content encl. EIBENHUT, D. O. Division of Licensing 81/02/26
- 8103050695 Responds to Items II D 1 3.11 F 2 3 & III A 2 2 of NUREO-9737, "Cierification of TMI Action Plan Requirements," per NAC 010219 & 26 requests UTLEY.E E Carolina Power & Light Co 81/03/02 2pp. 07832.024
- 8103090582 Bubmits final design & deviation details from NUREO-0737 Item 2 F 1 "Addi Accident Monitoring Instrumentation." per 801215 commitments Design basis & calibr for high range UTLEY, E.E. Caroline Power & Light Co. 81/03/03. 2pp. 07850.140
- 8103110638 Remits check for balance due for Class III application fee to amend License DPR-23.in response to NRC 810211 ltr. UTLEY-E E. Caroline Power & Light Co. 81/03/03 lp. 07887 104.
- G103110403 Responds to NRC G10113 Itr requesting add1 info on adequacy of electrical distribution sys voltage Issue closely related to degraded grid voltage issue which has been closed by NRC. Requests meeting during who of B10314 to clarify info needed. UILEY.E.E. Carolina Power & Light Co. 81/03/04. 1p. 07873-345
- 8103130369 Responds to deficiencies noted in NRC 010223 partial review 103130369 Responds to deficiencies noted in NRC U10223 partial revie: of environ qualification of sefety-related electrical equipment. Util will provide addl info re submergence. chemical spray & aging when specific concerns are clarified. UTLEY, E.E. Carolina Power & Light Co. 81/03/09. 4pp. 07908, 118
- 8103160143 Responds to 770429 & 0823 ltrs re proposed mode to controls for certain critical ECCS motor operated valves Mode to valve motor control circuits are acceptable Requests valve turveillance requirements per encl Tech Spec. VAROA B A Operating Reactors Branch 1 91/ B1/03/09 4pp. 07921-222
- --8103160180 Tech Spec 4.5.2 for ECCS surveillance requirements, Page
  - Carolina Power & Light Co. 76/03/15. 1p. 07921-225
- 8103170003 Notifies that design of valve control satisfies requirements of EICBS BTP 10 of SRP. Bubmits lists of valves required for emergency lang-term cooling of core & valves not satisfying single failure criterion. VARGA, H.A. Operating Reactors Branch 1. 81/03/09 2pg. 07939.281.
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical anutoment. EISENHUT-D O Division of Licensing, 81/03/10, 6pp.
- 8103240210 Forwards nonradiological environ protection plan for facility. Includes revisions to NRC draft in order to make reporting & monitoring requirements consistent w/NFDES neralt & EPA UTLEY-E E. Carolina Power & Light Co. 81/03/17. 1p. 07982:242.
- --8103240218 Nonradiological environ protection plan for facility. \* Carolina Power & Light Co. 01/03/17. Opp. 07902:243.
- 8103230591 Forwards QA program reflecting organizational changes, including creation of corporate QA dept & const of records storage facility at Brunswick QA program evailable in Central Files only. UTLEY.E.E. Carolina Power & Light Co. 81/03/18. 2pp. 07972.184.
- G. Inspection reports. IE Bulletins & correspondence
- 8103180410 Forwards Revision 2 to 90-day response to Suppl 3 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Safety relief valve position indication is only THE action plan equipment installed at Brunswick. FURR.B.J. Carolina Power & Light Co. 81/01/30. 2pp. 07944:118.

- ~-Bio3180425 Forwards response to addit data requests of Suppl 3 to IE Sulletin 79-01B. Environ Qualification of Class IE Equipment " Util does not plan to test or replace nonsafetygrade equipment FURR. D J Carolina Power & Light Co 81/01/30 [8cp 07944 12
- B103230297 Forwards Revision 3 to 90-day rept in response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." Items on master list located in control room & environs will not kave qualifications sheets FURR. B. J. Carolina Power & Light Co. 81/02/05. 2pp. 07979-118
- 8103020186 Forwards [E Circular 81-02, "Performance of MRC-Licensed Individuals While to Incular BI-OZ. "Performance of NRC-Licensed Individuals While on Duty "No written response required O'REILLY.J P Region 2. Atlenta, Office of the Director BI/O2/O9 Ip 07785 296
- 8103180284 Forwards 1E Insp Rept 30-261/80-38 on 801215-19 No 103180204 Forwards 12 Insp Rept Surgarizou-30 on Guigis-17 Mg noncompliance noted LEWIS-R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. BI/02/10 2pp 07944 205
- --8103180296 IE Insp Rept 50-261/80-38 on 801215-19 No noncompliance noted Major areas inspected it bulletins & circulars, reactor operations review & open & unresolved lines HARDIN.A K Region 2. Atlanta. Office of the Director KELLOGG.P J Region 2. Atlanta. Reactor Operations Nuclear Suppo Branch B1/02/10. 4pp 07944 207
- 8103200031 Forwards IE Insp Rept 50-261/80-37 on 801208-12 No noncompliance noted
  LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support
  Branch. Bi/02/11 2pg 07%69 098
- --8103200038 IE Insp Rept 90-261/80-37 on 901208-12 No noncompliance noted Major areas inspected general plant operations & followus inso of outstanding items ROOKS, E.M. Region 2. Atlanta. Office of the Director. QUICK Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/10 3pp 07969 100
- 8103040174 Forwards JE Info Notice 81-03, "Checilist for Licensess Haking Notifications of Significant Events In Accordance
  W/10CFR50 72 " No written response required
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/02/12 1p. 07013 013
- 8103060233 Responds to IE Bulletin 81-01. "Surveillance of Mechanical Snubbers " No mechanical snubbers in use at facility FURR.B J. Carolina Power & Light Co. 81/02/18 1p 07839-305.
- 8103070413 Ack receipt of 1E Insp Repts 50-400/81-01.50-401/81-01. 50-402/81-01 & 80-403/81-01 on 810106-09 No proprietary info HOWE, P. W. Carolina Power & Light Co 81/02/18 1p
- --BI03090422 Forwards 1E Insp Repts 50-261/B1-01. \$0-324/B1-01. \$0-325/B1-01. 50-400/B1-01. 50-401/B1-01. \$0-402/B1-01 & 50-403/B1-01 on Bi0106-09. No noncompliance noted MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineerin Bupport Branch. 81/02/09. 2pp
- --BI03090430 IE Insp Repts 50~261/B1-01.50-324/B1-01.50-325/B1-01.50-400/B1-01.50-401/B1-01.50-402/B1-01 & 50-403/B1-01 on BI0106-09 Not appared lance noted Major areas inspected closeout of previously identified enforcement matters BROWNLEE.V.L. Region 2. Atlanta. Office of the Director B1/02/09.
- 8103050141 Ack receipt of 810205 ltr informing NRC of steps teken to correct violation noted in 12 Inap Rept 50-261/80-30. LENIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/19. ip 07827.332.
- --gigg5050154 Responds to NRC 810113 ltr re vialations noted in IE Ins Rept 50-261/80-30. Corrective actions:existing procedures will receive review & changes initiated as necessary to cover handling reducts outside auxiliary bldg. STARKEY, R B Carolina Power & Light Co. 81/02/05 2pp. 07827:333
- --8103050160 Forwards IE Insp Rept 50-261/80-30 on 800930-1009 & noti of violation LEMIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. B1/01/13 2pp. 07827-333.
- --8103050164 Notice of violation from inep on 800930-1009. \* Region 2. Atlanta, Office of the Director 81/01/13 lp 07827: 337.

- 8103160708 Forwards IE Info Notice 81-04. Gracking in Main Steam Unes " to response required O'REILLY. J P Region 2. Atlanta, Office of the Director 8:/02/27 is 07914 083
- GIGRIAO709 Enguards IE Info Notice 81-04. Crecking in Main Steam Lines "No response required of the Director 81/02/27
- 6103160718 Forwards IE Info Notice 81-04. 'Cracking in Main Steam iogiauvia romands (E Info No Lines " No response roquired C-REILLY, J.P. Region 2. Att. (p. 07914-100 Region 2. Atlanta, Office of the Director 81/02/27
- 3103160659 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No response required CREILLY, J.P. Region 2. Atlanta, Diffice of the Director. 81/03/02; p. 07914-242
- 9103163782 Ack receipt of 810213 ltr informing NRC of steps taken to correct violations noted in LE into Rept 50-261/80-36. He add into provided to change finding LEWISR C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 61/03/62 ip 07914 153
- --8103160785 Responds to NRC 810119 ltm re violations noted in IE Insp. Rept 90-261280-36 Corrective actions operating procedure for subcomming matter established & procedure for use of steam tatles added STARKET, R.B. Carolina Power & Light Co. 81/02/13. 3pp
- --B103160790 Forwards &E Insp Rept 50-261/80-36 on B0\$104-07 & motices of violation & deviatson LEMES.R C Region Z Atlanta. Reactor Operations Nuclear Support Branch. 81/01/19 2pp 07914:157
- Region 2. Atlanta. Office of the Director. 81/01/19 IP 07914 159
- --9103160794 Notice of deviation from insp on 801104-07 # Region 2. Atlanta. Office of the Director 81/01/18 ip 07914 160
- --Bi03160800 IE Insp Rept 50-261/80-36 on 801104-07 Nancompliance noted no procedure grepared for operation of subcooling meter & no description provided on use of steam tables in licensee emergency instructions
  HARDIN.A.X. Region 2. Atlanta, Office of the Director
  KELLCGG.P.J. Region 2. Atlanta, Reactor Operations No.
- 8103170062 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required O'REILLY-J P Region 2, Atlanta. Office of the Director. 81/03/02. 1p. 07937:185
- 8103170093 Forwards revised IE Bulletin Bi-Di. 'Surveillance of Mechanical Snubbers, w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements D'REILLY, J.P. Region 2. Atlanta, Office of Region 2. Atlanta, Office of the Director. 81/03/04 10 07935 286
- 8103160260 Forwards 1E Insp Rept 50-261/81-04 on 810209-12, No nancompliance noted LEWIS.R C Region 2. Atlanta, Office of the Director 81/03/06 2pg. 07944.202.
- -- 8103180272 [E Insp Rept 50-261/81-04 on 810209-12 No noncompliance noted Major areas inspected: vital area berriers, lighting, escorts, unresolved Item 78-14-02 & IE bulletins, circulars & notices Details withheld fref 10CFR2 790).
  TOBIN: U , MCGUIRE.D Region 2, Atlanta, Office of the Director B\$/03/06. ip 07944-204
- 8103130512 Forwards revised "Inservice Insp Program " Program will be implemented 810401. UILEY,E E Carolina Power & Light Co. 81/03/10 1p. 07954 221.

200 07984 219 ~-8103240815 Notice of violation from insp on 810217-20.

LEWIS.R C Region 2. Atlanta. Office of the Director 81/03/10

- . Region 2, Atlanta, Office of the Director 81/03/10 ip
- --B103240B2R IE Insp Rept 90-261/81-09 on B10217-20 Noncompliance noted failure to provide written procedure for recovery from inadvertent safety injection actuation
  JAPE.F. tHEISE.B. JULIAN.C. Region 2. Atlanta. Diffice of the
  Director BI/03/10 5pp 07984 222
- 8103200301 Forwards IE Info Notice 81-06. 'Failure of ITE Model K-600 Circuit Breater' No response required O'REILLY J.P. Region 2. Atlanta. Office of the Director. 81/03/18 15 07969-034
- Palisades " No response required.
  D'REILLY.J P Region 2. Atlanta, Office of the Director 81/03/13
  jp. 07965-282 0102190971 Forwards IE Info Natice 81-05, Degraded DC Sys at
- 8103310525 Act receipt of 810302 ltr informing NRC of steps taken to carrect violations noted in IE Insp Rept 50-261/81-02 LEWIS R C Region 2. Atlanta. Office of the Director 81/03/19 10.
- --Bi03310629 Responds to NRC Bi0205 itrine violations noted in IE Insp. Rept 50-261/81-02 Corrective actions completed upgrading of core cooling monitor w/both channels powered from permanent power supply BTARKEY.R 3 Carolina Power & Light Co. 81/03/02 Spp
- --8103310635 Forwards IE Insp Rept 80-261/81-02 on 810105-09, notice of violation & notice of deviation LEMIS.RC Region 1. Philadelphia. Reactor Operations Nuclear Support Branch Bi/O2/O3. 2pp
- --- 8103310641 Notice of violation from insp on 810105-09 Region 2. Atlanta, Office of the Director. 81/02/05. Ip.
- --B103310646 Notice of deviation from insp on 810105-09. Region 2. Atlanta, Office of the Director. 81/02/05
- IL Insp Rept 50-861781-02 on BIVIDS-OY NORCOMPITANCE NOTE Patiure to control nonconforming Items & to identify Instrumentation to which quality stds apply. MCCDVALD. J Region 2. Atlanta. Office of the Director. RELLOGO.P J Region 2. Atlanta. Reactor Operations Nuclear Buppor Branch B1/02/05 4pp

-- 8103310654 IE Insp Rept 50-261/81-02 on 810105-09 Noncompliance note

- 8103310946 Forwards description of steam generator outage eddy current inapprogram which with has committed to purform prior to exceeding six effective full power months of operation from B01025 Gutage scheduled to commence 810509. UTLEY: E E Caroline Power & Light Co 81/03/25 17pp. 08 B1/03/25 17pp 08057; 173
- R. Periodic operating reports & related correspondence
- 8103060321 Forwards "Effluent & Waste Disposal Bemiannual Rept. 1980. "
  STARKEY, R. B. Carolina Power & Light Co. 91/02/27. 1p.
- --8103060328 "Effluent & Waste Disposal Semiannual Rept. 1980."
   Carolina Power & Light Co. 81/02/27. 81pp.
- 8103110479 Forwards "Annuel Operating Rept.1980." BTARKEY,R B. Carolina Power & Light Co. 81/03/05. ip. 07869:355
- --BiO3/10483 "Annual Operating Rept. 1980." \* Carolina Power & Light Co. 81/03/05 5pp. 07586.001.
- 8103170380 Forwards monthly operating rept for Feb 1981 STARKEY, R B. Carolina Power & Light Co. 81/03/10. 07933 248 10
- --8103170388 Monthly operating rept for Feb 1981.
  WATFORD, M. Carolina Power & Light Co. 81/03/03 3pp. 07933: 24

- S. Reportable occurrences. LERs & related correspondence
- B103060763 RO on 801127.RCS primary to containment atmosphere leak developed which exceeded Tech Spec limits Caused by packing leak on Valve CVC-311 Cold shutdown commenced to atop leakage & permit repair STARKEY, R B Carolina Power & Light Co 80/11/28 pp. 07836 111
- 8103066826 RO on 801212.868 primary leak developed which exceeded Tech Spec limits Caused by packing leak on valve RHR-790 Leakage was stopped by opening valve & placement on back seat. STARKEY.R B Cerolina Power & Light Co 80/12/15 1p 07836 130
- B101300569 RO on 810114-both channels of heat trace for both boric acid transfer pumps determined inoperable in violation of Tech Spec 3 2 3 C. Caused by misleading step in procedure for taking pump out of 5vc BTARKEY, R B. Carolina Power & Light Co. 81/01/15 Ip 07584 107
- 8103050546 Forwards LER 81-007/01T-0. STARKEY, R B Carolina Power & Light Co 91/02/27 1p. 07829-006
- --B103050559 LER B1-007/01T-O on B10213.shift in peak clad temps was determined from preliminary analysis of ECCS model used for LOCA analysis Caused by potential modeling arror by Westinghouse Complete reanalysis of event will be made. STARKEY.R B Carolina Power & Light Co B1/02/27. 2pp 0279-027.
- B103350551 Forwards LER 81-006/03L-0 STARKEY, R B Caroline Power & Light Co. 81/02/27. in 07829 009
- --BI03050562 LER BI-006/03L-0 on Bi0129-fire protection valve FF-248 Patled to close upon receipt of spurious Phase A containment isolation signal Caused by tripped motor operator breaker due to personnel error % inadequate installation procedure BIARKEY, R B Carolina Power & Light Co. BI/02/27. 3pp. 07829-010
- 6103190372 Forwards LER 80-008/03L-1 BTANKEY.R B Carolina Power & Light Co 81/03/16 to 07965 184
- --Bi03i90384 LER R0-008/03L-1 on 800406 pressure transmitter failed to full output during narmal operation. Cause undetermined because instrument was returned to normal operation before thorough investigation. Investigation closed.
  BIARKEY.R. B. Caroline Power & Light Co. 81/03/16 4pp. 07965 183
- COCKET 50-262 BRIGHAM YOUND UNIV RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- @103030175 Forwards revised NRC Region 4 organization chart.effective B10227. SEYFRIT.K V. Region 4. Delles. Office of the Director. B1/02/17
- Q. Inspection reports. IE Bulletins & correspondence
- G103200861 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. BEYFRIT.K.V. Region 4. Dallas. Office of the Director. 91/02/09. 19 07967.189.
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATINO PLANT
  F. Security, medical, emergency & fire protection plans
- 8103040940 Approves request for extension of completion of cable spreading room halon sys installation.upgrading of fire barrier seals k replacement of linen fire hose until end of 1981 maint outage. PR notice enci. DENTCN.H R. Office of Nuclear Reactor Regulation, Director 81/02/13. 2pp. 07812:228.
- --Bi03040950 Notice of extension until Billi17 for completion of cable spreading room installation, upgrading of fire barrier seals & replacement of linen fire hose.

  CABELE 0 Office of Nuclear Reactor Regulation, Director.

  81/02/13 1p. 07812:231.
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance u/801119 fire protection rule EISENHUT.D.O. Division of Licensing. 81/02/20. 13pp.

- BiO3100099 Requests that encl emergency planning info be rade available. N/o encl SOUDER, J L Division of Rules and Records B1/02/27 1p. 02993 179
- B10331033B Ltr to all licensees of operating plants & holders forwarding NUREG-0696. "Functional Criteria for Energency Response Facilities " Criteria describe acceptable method for meeting NRC requirements U/o encl
  EISSENHUT. D O Division of Licensing 81/03/03 App
- 8103170192 Forwards Revision 10 to security plan Revision with tref 100FR2 790). MAYER-L O Northern States Power Co 81/03/13 ip 07935
- 9103230803 Provides plans & schedules for meeting fire protect criteria.per NRC 801124 ltr Portions of operational GA program encl MAYER.L.O. Northern States Power Co. 81/03/19 36pp. 079
- I Financial information
- BIO3200215 Forwards Annual Financial Rept 1980 BRUSVEN.A D Northern States Power Co BI/03/17 40pp 0
- --8103200222 Annual Financial Rept 1980 MCCARTHY.D. LARSON.C. Northern States Power Co. 81/03/1 07988:222
- J Insurance & indemnity information
- 8103030710 Forwards Endorsement 47 to MAELU Policy MF-51 JOHNBOW.R 0 Northern States Power Co. 81/02/24 2pp 07:
- 8103030735 Forwards Endorsement 41 to MAELU Polity MF-68 JOHNSON R G. Northern States Power Co. 81/02/24 2pp. 07:
- 8103030737 Forwards Endorsement 4 to MAELU Binder XB-17
  JOHNSON, R. G. Northern States Power Co. B1/02/24 3pp. 077
- 8103170343 Forwards Endorsement 5 to NELIA Dinder EB-17 & MAELU XB-17. JOHNBENN R Q Northern States Power Co 81/03/10 4pp 07
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants
  OLs & holders of CPs re-control of heavy loads. Requests
  review per guidelines in NUREG-0612 Forwards NRC position reinterim actions & request for addl info
  EISENHUT, D. O. Division of Licensing. 80/12/22 30pp.
- DIG3190397 Ltr to all licensees of operating plants & applicant OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737 EIBENHUT-D O. Division of Licensing BI/01/19 App
- 8103240290 Ltr to all BNR licensess forwarding Suppl 1 to gener safety evaluation on BNR scram discharge sys Summarises re-evaluation of interim measures recommended per 801201 safety evaluation EIBENHUT D.O. Division of Licensing 81/01/23 2pp.
- 8103120014 Ltr to ail licensees of operating plants,CP holders applicants,except Indian Point 2 & 3,2ion 1 & 2 & TMI-1, forwarding inadvertantly unlitted pages from NRC 801222 request for add info re control of heavy loads EISENHUT.D.O. Division of Licensing. 81/02/03. 6pp
- 8103040211 Forwards Amend 1 to License DPR-22, Suppl 1 to safety evaluation & notice of issuance & availability. IPPOLITO, T A Operating Reactors Branch 2. 81/02/12. 2pp 07813:155.
- --8103040224 Amend 1 to License DPR-22 revising conditions re-caffecility mods for fire protection.

  IPPOLITO.T.A Operating Reactors Branch 2. 81/02/12. 2pp.
  07813-157.
- --Bi03040232 Suppl 1 to safety evaluation supporting Amend 1 to ppR-22
  + Office of Nuclear Reactor Regulation, Director. 81/02/1 16pp. 07813, 159.

- B103050126 Forwards Tech Spec Page 147 for App A to Litense OFR-22. Tracvertently colitted from 810109 issuance when issued IPPOL(13.1 A Cperating Reactors Spania 2 81/02/12 2pp 07827 311
- ~-BIO3950133 Page 447, inadvertently chitted from App A to License DPR-22 • Operating Reactors Branch 2 81/02/12 1p 07827, 313
- BIODI60669 Ltr to all operating plants & CP holders forwarding clarification of IMI Action Plan Item III A 1,2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met.
  EISERHUT.D Q Division of Licensing 81/02/18 12cp
- 8103090176 Forwards organizational charts depicting NRC Region 3 reorganization effective B10216 MEPPLER.J O Region 3. Charago. Office of the Director 81/02/20 2pp. 07852 105
- 8103250024 Ltr to all power reactor licensees & license applicants re AUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing law flow controller. ELECHARIO 2 Division of Licensina 81/02/20 800
- BiO3110753 Forustes phase 2 corrected acceleration, velocity & displacement craces for three largest strong motion recordings from accelerograph at reservoir Describes methods used to calculate stress drop & source parameters FLETCHER.J B Interior. Dept of. Geological Survey 81/02/24 19pp 07972-241
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie Units ( & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT.D O Division of Licensing B1/02/35. Spp.
- B103030758 Requests exemption from requirements of Section III J.
  "Emergency Lighting." of App R to 100FR50.as essential
  lighting sys supplied under loss of normal ac source by
  diesel generators or 1AR transformer
  MAYER.L D. Northern States Power Co. 81/02/26 3pp. 07789 017
- Rio3170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrasse) requesting review of ASPE Code Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of enci Revision 1 to NUECG-0313 Model Tech Specs only encl EISENWI.D C Division of Licensing 81/02/26 3pp
- --8103170266 Model Tech Space Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ASHE Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements. • General Electric Co. 81/02/26 4pp
- B163090447 Expresses concerning 820430 completion date for mode no Mark 1 containment long-term program Request to amend completion date may be necessary MAYER.L.O. Northern Brakes Groven Co. 81/02/27 250 07846 187

isfy TMI

7865: 329

- --8193130675 Notice of issuance & availability of Amend 2 to License DPR-22 IPPCLITG.T A. Operating Reactors Branch 2 81/03/02 2pp 0793-245
- B103310B04 Ltr to all licensees of operating plants applicants for (i.e. b. holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment.
  EISENBUILD 0 Division of Licensing. B1/03/10 6pp
- 8103240253 Advises that analysis of adequacy of station electric distribution sys voltages has been deferred until Apr refueling outage.per B10130 ltr MAYER.L D Northern States Power Co 81/03/16 lp 07990.327
- 810326114B Forwards preliminary results of IRC review of environ qualification of safety-related electrical equipment at facility Identified deficiencies & ramifications should be reviewed & overall findings submitted NOVAN-I H Assistant Director for Operating Reactors. 81/03/16-2800 08037-09
- Bi03276095 Surmary of Bi0304 meeting w/Mark I owners group & OE in Bathseds.MD re supplementary tests conducted in full-scale test factity & resolution of outstanding Mark I issues per NUREQ-0661 Slide presentation & Ilst of attendees encl ORIMES.C I Licensing Branch 3. 81/03/16 Spp
- 8103270760 Requests payment of Class III fee for 810226 application requesting relief from 100FR50 App R. Bection III J. DIGOS.R M. License Fee Management Branch. 81/03/20 lp. 08044 316
- 8103300149 Forwards NEDE-20179-4P. Buppl 4. "Monticello Nuclear Cenerating Plant. Unit 1. SRP-II Bundle Submittal Segmented Test Rod Bundle." Encl withheld (ref 100FR2 790). Rept available in Central Files only MAYER. L. D. Northern States Power Co. 81/03/24 1p. 08055 153
- 8103500388 Responds to 810316 ltr reviewing environ qualification of factifity safety-related electrical equipment Factifity operation may safety continue white environ qualification deficiencies being resolved MYKRILO Northern States Power Co. 81/03/27 2pp. 08037 244
- B103310234 Notifies that 810401 scheduled implementation of NUREO-OZH.

  Item 1.C. 5. "Feedback of Operating Experience." cannot be satisfied per 801230 commitment implementation of all unities procedures will be completed by 810701 MAYER. O. Northern States Power Co. 81/03/27 in 08062 121
- Q Imagestion reports. IE Bulletins & correspondence
- B103050337 Forwards IE Insp Rept 50-263/80-20 on B01101-30 & notice of violation.

  HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. B1/01/20 2pp 07826:075
- --8103090342 Notice of violation from insp on 801101-30. HEISHMAN.R.F. Region 3. Chicago: Reactor Operations Nuclear Support Branch 81/01/20 2pp. 07826-077.
- --8103050349 IE Insp Rept 50-269/80-20 on B01101-30 Noncompliance noted failure to meet requirements of operational QA plan reprocurement matt shelf life & main of rotational electrical equipment in stock
  BROWN, C H., MA0150N.A.L., LITTLE-U.A. Region 3, Chicago, Office of the Director. 81/01/16 8pp. 07826-079.
- 8103130677 Forwards IE Mgt Meeting Repts 50-263/80-21.50-262/60-21 & 90-306/80-21 on 801121.

  KEPPLER J O. Region 3. Chicago. Office of the Director. 81/01/20 200 07913.267.
- --8103130679 IE Mgt Meeting Repts 90-263/80-21.50-282/80-21 & 50-306/80-21 on 801121. Areas discussed: regulatory performance of activities at facilities per systematic assessment of licensee performance program.

  HEISHMAN.R.F. Region 3. Chicago: Reactor Operations Nuclear Support Branch 81/01/13 16pp. 07913:269.
- 8103130294 Forwards 1E Insp Rept 80-263/80-21 on 801201-31 No noncompliance noted. HEIBMMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 81/01/30 2pp. 07912.170

the Director 81/01/30 Spp 07912 172

8103090698 Forwards IE Insp Rept 50-263/81-01 on Bi0114-16 No noncompliance noted FISHER.W L Region 3. Chicago. Fuel Facility & Materials Bafety Branch B1/02/06 2pp 07846 008

- --Bi03090704 IE Insp Rept 50-263/81-01 on 810114-16 No noncompliance noted Major areas inspected administrative & mgt control sys. 04 & control in sampling & analytical measurements & implementation of radiological environ monitoring program OUESTMANN.H J. NICHOLSON.N A. PAPERIELLO.C J. Region 3. Chicago. Office of the Director 81/02/04 4pp 07846 010.
- \$103020067 Forwards JE Circular 81-02. 'Performance of NRC-Licensed Individuals While on Duty "No written response required MEPPLER. J O Region J. Chicago. Diffice of the Director 81/02/09 2no 07787 290
- 8103040272 Forwards IE Info Notice 81-03. 'Checkisst for Licenseas Making Notifications of Significant Events In Accordance W/IOCFRSD 72 "No written response required KEPLER. J O Region 3. Chicago. Office of the Director 81/02/12 250 07813 307
- 8103030262 Forwards Suppl 9 to IE Bulletin 80~17. "Failure of Control Rods to insert During Scram at 8HR 'No written response required \*\*EFPLER.J.O. Region 3. Chicago. Office of the Director 81/02/13 2pp. 07790 305
- 8103160521 Forwards IE Circular 81-03. Inoperable Selamic Monitoring Instrumentation." No response required KEPPLE9. 0 Region 3. Chicago. Office of the Director 81/03/02 2>> 07916-318
- 8]03120840 Forwards request for addl into re response to JE Bulletin 83-(i. "Masonry Mail Design " info needed within 60 days to complete revious JPPOLITO, T A Operating Reactors Branch 2 81/03/03 4pp
- BIO3260607 Responds to Revision 1 to IE Bulletin 79-26. "Boron Loss From BMR Control Blades." Util & EPRI are participating in program to investigate feasibility of using nondestructive era-fination technique to monitor control blades. OILBERTS. D.E. Northern States Power Co. 81/03/03. 1p. 08040.291
- BiO3160978 Forwards revised IE Bulletin Bi-O1. "Surveillance of Mechanical Shubbers." w/corrected Pages 5 & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements KEPPLER. J. C. Region 3. Chicago. Office of the Director. Bi/O3/O4 to 07918 001
- BiO319065: Responds to IE Bulletin Bi-Ot. "Surveillance of Mechanical Snubbers." Once each refueling cycle.two mechanical snubbers will be visually examined & tested for operability OlleBERTS.D E. Northern States Power Co. Bi/O3/O9. 2pp 07934.359
- 6103200440 Ack receipt of 810212 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/80-20. First item of nancompliance withdrawn F-EISHMAN, R.F. Region J. Chicago, Reactor Operations Nuclear Support Branch. 81/03/09. 2pp. 07966;346.
- --BI03200446 Responds to NRC BI0121 ltr re violations noted in 1E Insp Rept 50-263/B0-20. Corrective actions: instructions delineating disposition of O rings which have exceeded their shelf life will be written 01LBERTS.D.E. Northern States Power Co. B1/02/12. 3pp 07966:348
- 8103200391 Forwards IE Info Notice 81-06, "Failure of ITE Model K-600 Circuit Breaker." No response required. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 81/03/11 2pp. 07972.132
- 8103200693 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No action required. XEPPLER.J.O Region 3, Chicago, Office of the Director 81/03/13. 2pp. 07966-128

8103240771 Forwards IR Insp Rept 50-263/81-03 on 810209-13. App Anotice of violation withheld (ref 100FR 2770) to response required NORELIUS.C. Region 3. Chicago. Office of the Director 81/03/2pp 07983 353.

- --8103240781 IE Insp Rept 50-263/81-03 on 810209-13 No noncomplia noted Major areas inspected security plans security program audit 5 security Organization Details withheld (ref 10CFR2 790) KNICELEY.J R. PIRTLE.G L. Region 3. Chicago. Office of the Director CREED.J R. Region 3. Chicago. Safeguards Branch 81/03/04 2pp 07903 355
- BiO3250131 Responds to IE Bulletin BO-25. 'Operating Problems H/T Rock Safety Relief Valves at BMRs' No subj valves installed at plant Procedures revised to assure that overhaul requirements completed prior to returning valve to svc OILBERTS.D.E. Northern States Power Co. 81/03/17 3pp. 0799
- R Periodic operating reports & related correspondence
- BiO302043B Forwards effluent & waste disposal sectionnual rept for Dec 1980 MAYER, D. Northern States Power Co. 81/02/27 ip. 07754 10
- --8103020444 Effluent & Laste disposal semiannual rept. Jul-Dec 19
  4 Northern States Power Co. 81/02/27 13pp 07784 105
- B103030587 Forwards "Annual Operating Rept. 1980 " Covers occupati exposure: changes, tests it experiments & safety valve & relief valve failures & challenges MAYER.L O Northern States Power Co 81/02/27 ip 07793 is
- --B103030594 'Annual Operating Rept.1980 ' Covers occupational exchanges tests & experiments & safety valve & relief valve failures & challenges

  \* Northern States Power Co 81/02/27 14pp 07793 114
- 8103190478 Forwards monthly operating rept for Feb 1981 MAYER.L O Northern States Power Co 81/03/13 ip 07965 20
- --B103190485 Manthly operating rept for Feb 1981 MYRABO A L. Northern States Power Co. 81/03/10. 4pp 0796
- 8103270673 Forwards annual rept. "Radiological Environ Monitoring Program 1980 " WARDLE C Northern States Power Co 81/03/25 ip 08046 263
- --BI93270679 Annual rept. "Radiological Environ Monitoring Progra-HUEBICER.L G. Northern States Power Co. B1/02/23 54pp 08044 264
- 8 Reportable occurrences, LERs & related correspondence
- B103030335 Pt.O-III-B0-205 licenses extended planned shutdown to s days for maint t various plant mode Restart will be B01110 BRGMN.C H . LITTLE.W S . HEISHMAN.R F Region 3. Chicago. Offi the Director B0/11/06 ip 07790 266
- Bi03020591 Pk0-III-Bi-020 on Bi0224.following loss of air supply, reactor thipped from 78% power. Caused by shutdown of one operating air compressor & stuck open check valve. Air compressors were restored to svc BROWN.C H. LITTLE.W S. FIORELLI.O. Region 3. Chicago, Office the Director. Bi/02/24 2pp 07783 029.
- 8103050618 Forwards LER 81-001/03L-0 MAYER, L. O. Northern States Power Co. 81/02/25 1p 07829:13
- --B103090622 LER B1-001/03L-0 on 810126 outboard HPCI steam supplies alation valve failed to close Caused by open circuit due to open motor operator limit & torque switches Limit switch reset to close prior to backseating valve MOJCHOUSKI. A Northern States Power Co 81/02/25. Ip. 07809-138
- 8103130463 RD on 810304.Fisher Controls informed util of error in original design calculation significantly reducing mar stress mergin in shaft to min yield strength of shaft matl for type 9200 butterfly valves.Caused by human error SHAMLA-M. A. Northern States Power Co. 81703705 ip. 07911:3

- 8103230766 Forwards LER 81-003/017-0 MAYRR.L 3 Northern States Power Co 81/03/18 to 07974 167
- --Bio3230777 LER Bi-003/017-0 on Bio304-viil intified of reduced design margin for ray shaft stress to min yield strength of shaft mail for tortainment purge b vent valves Caused by design error in Fisher type V200 butterfly valves GCRANSON. 9 A Northern States Power Co. Bi/03/18 is 0.2974 1AB

DUCKET 50-264 DEW CHEMICAL CD
P. Operating license stage documents & correspondence

- 8103090119 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216 AEPPLER J 9 Region 3. Chicago. Office of the Director 81/02/20 2nn 07850 069
- O Inspection reports: IE Bulletins & correspondence
- B103090100 Forwards IE Insp Rept 50-264/81-01 on B10132-14 No noncompliance noted h€15MMAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch B1/01/23 2pp 0/849 t60
- --Bi03090105 IE trsp Rept 50-264/81-01 on Bi0112-14 No noncompliance noted Major areas inspected records,logs & organization revise & audit functions, requalification training, surveillance & raint & experiments RIDGWAY. R R B070.0 C Region 3. Chicago. Office of the Director B1/01/23 Spp 07849 162

OCCRET 50-265 QUAD CITIES STATION, UNIT 2 F. Security, medical, emergency & fire protection plans

- BIOLOBOO91 Releases public version of util draft emergency plan MUREG-0654 info encl FELTON J M Division of Rules and Records 60/12/02 18pp
- --8101230543 Forwards public version of draft emergency plan for generating stations PEDPLES.D L. Commonwealth Edison Co. 80/04/24 3pp. 04837-169
- --8101080069 Public version of draft emergency plan for generating stations

   Commonwealth Edison Cn. 80/07/31 150ne
- BioloB0003 Releases public version of util draft emergency plan FELTOMAU M. Division of Rules and Records B0/12/03. tp
- --6101220259 Forwards public version of util revised draft energency plan w/station annerses
  PEDPLES D L. Commonwealth Edison Co. 80/06/04 2pp. 05370 005
- --Biol 080014 Public version of draft energency plan annex.

  d Commonwealth Eddson Co 60/07/31 48pp 07417:002
- --8101080019 Public version of Revision 1 to draft emergency plan \* Commonwealth Edison Co. 80/07/31 139pp
- 8103090032 Forwards Suppl 2 to fine protection safety evaluation for previously unresolved open items Also forwards listing of current status of all items identified as requiring action during fire protection review.

  IPPCLITO.T A Operating Reactors Branch 2. 81/02/12 2pp. 07852 182.
- ~~8103090037 Suppl 2 to fire protection safety evaluation for previously unresolved open items.
  # Operating Reactors Branch 2 81/02/12. 4pp 07852 184
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101. For Lards NRC position & request for addl info re safe shutdown capability for compliance w/601119 fite protection rule EISENHUT. D 9 Division of Licensing. 81/02/20. 13pp.
- Bioggsogs Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Energency Response Facilities." Griteria describe acceptable method for meeting NG2 requirements N/o enci

- 8103260123 Concurs w/801217 request to install two-way headset journal specified emergency notification sys & health physical telephones provided that use will be discontinued if communications quality unacceptably degraded KEPPLER, J. G. Region 3. Chicago, Diffice of the Director 01/03 to
- -- 8103260137 Submits location for installation of one-way headse on energency notification sys & health physics network per 801119 request Requests concurrence by 810201 pauschit I. Companyealth Edison Co. 80/12/17. 200
- 8100230665 Releases public version of implementing procedures for energency plan FELTCM.JR Division of Rules and Records 81/00/19 ip
- --BIOD250692 Forwards public version of emergency plan implement procedures for corporate command ctr. environ director & plant-specific procedures DELGEORGE, L D Commonwealth Edison Co B1/02/27 2pp
- ~-BI03250702 Public version of energency plan implementing proce corporate command ctr.environ director & plant-specific procedures • Commonwealth Edison Co. B1/02/27 1400pp.

#### O Adjudicatory correspondence

B101300267 Order modifying license & granting extension of exemp Licensee must reassess suppression pool hydrodynamic loads & complete mods to met General Design Criterion 50 by 821231 EISET#WJT.0 0 Bivision of Licensing 81/01/13. 7pp 07502:

#### 1 Financial information

- BiO3310613 Forwards guarantee of payment of deferred premiums for per NRC request DSTER. J. Componwealth Edison Co. 81/03/27 1p.
- --8103310520 Forwards Annual Rept for CY80 & statement of interm. flow projected for 1981 & actual for 1980 per provisions of 10CFR140. Chapter 1. Section 140 21 & IRC 770615 ltr NEXDN.H H. Commonwealth Edison Co. 81/03/27 App
- J Insurance & indomnity information
- 8103090581 Forwards Endorsement 5 to NELLA Binders EB-1.88-2.85-5 EB-29.88-30.89-42.88-43 & MARLU Binders xB-1.XB-2.XB-3, xB-29.xB-30.XE-42.XB-43 ESFER.J Commonwealth Edison Co. 81/03/02 15pp.
- P Operating license stage documents & correspondence
- Bi03j90732 Ltrs to all licensees of operating plants, applicants. Oh,s & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-Obl2 Forwards NRC position re-interim actions & request for addl info EISENHULD O Division of Licensing. 80/12/22. 30pp
- BIOI300233 Forwards NRC BIOII3 orders for mod of licenses & gran extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Dasign Criterion 90.

  IPPOLITO.T.A. Operating Reactors Branch 2 81/01/13. 3pp.
- --8101300267 Order modifying license & granting extension of exe-Licensee rust reasess suppression pool hydrodynamic loads & complete mods to neet General Design Criterion 50 by 821231 E18EMBUT.D.O pivision of Licensing 81/01/13. 7pp 07583
- 8103190387 Ltr to all licensees of operating plents & applicants OLs % holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown replacement parts & NUREO-0737. EISENHUT, D. Q. Division of Licensing. 81/01/19 6pp.
- 8103240290 Ltr to all BMR itensees forwarding Suppl 1 to generic safety evaluation on BMR scram discharge sys. Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation.
  EISENHULD 0 Division of Licensing. 81/01/23. 2pp.
- 8103120014 Ltr to all licensess of operating plants.CP holders & applicants.eccept Indian Point 2 & 3.2ion 1 & 2 & TMI-1. Forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D.9 Division of Licensing. 81/02/03. 6pp

- 8103160469 Ltr to all operating plants & CP holders forwarding clarification of IMI Action Plan Item III A 1.2 re upgrade of energency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.0 0 Division of Licensing 81/02/18 12pp
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 REPPLEM, J.O. Region 3. Chicago. Office of the Director 81/02/20
- Bi03250024 Ltr to all power reactor licensees & license applicants re NAREQ-0619 criteria Footnote 2 in Table 2 contains error due to laskage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISENHUT.G O Division of Licensing 81/02/20 Bpp
- 8103230030 Ltr to all licensees of operating nuclear power plants tapplicants for Ots (except 8t Lucie.Units 1 & 2) Requests util review to determine capability to nitigate station blackout event & promptly implement emergency procedures EISENHVI-D O Division of Licensing 61/02/25 Spp
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ADME Code Class 1 & 2 pressure boundary piping, safe ends & fitting matt per guidelines of ent? Aevision I to NUREO-0313 Model Tech Specs only enci E16ENHUT.D Q Division of Licensing 81/02/26 3pp
- --8193170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re surveillance requirements for ABME Code Class 1,2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements • Owners! Electric Co. 81/02/26 4pp
- 8103230813 Generic Ltr 81-06 to all CP holders & CL applicants re-IOCFR80.71(e). "Periodic Updating of FBARs." effective 800722 Info re FBAR legal status.format & content encl E15EANNUT.D.O Division of Licensing 81/02/26
- 8:03050158 Forwards add1 info re containment purge & vent valve operability in response to NRC 801202 ltr AMRCEN.8 F Commonwealth Edison Co 81/02/27. 20pp.
- 8100310B04 Ltr to all licensees of operating plants applicants for ULs & holders of CPs forwarding SECV-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENVULD 0 Division of Licensino. 81/03/10 Ann
- B103180517 Informs NRC that util will continue to require full radiation training for NRC personnel entering radiation areas at facilities, pending further NRC communications TRAMN.T R Commonwealth Edison Co. B1/03/11 ip.
- 8103200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 16-2 of CE-1-A.Revision 16 re GA program Revisions reflect ABME winter addenda code changes, changes made per ABME survey & clarifications & corrections.

  TRAMN.T R Commonwealth Edison Co. 81/03/16. 1p.
- --8103200359 Revised abstract & Pages 2-2, 4-2, 4-5, 7-2 & 18-2 of Revision 16 to 8A program 
  \* Commonwealth Edison Co. CE-1-A Ri6. 81/03/16 6pp
- B103270095 Summary of \$10304 meeting w/Mark I owners group & OE in Betheeda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding tark I issues per NMR60-0661. Sito by restation & list of attendees enci. ORIMES.C.I. Licensing Branch 3. 81/03/16 9pp
- G103260149 Forwards preliminary results of NRC review of environ qualification of safety-related electrical aquipment at facility. Identified deficiencies & ramifications should be reviewed & overall findings submitted.

  NDVAKET.M. Assistant Director for Operating Reactors. 81/03/17.36pp.
- B103230518 Forwards approved version of NEOD-24297-A, "Generic Info for Barriet Fuel Demonstration Bundle Licensing" Ltr of acceptance & requested add1 info encl.

  ENGEL-R.E. General Electric Co. B1/03/19. ip. 08023:218

- --8103230527 "Generic Info for Barrier Fuel Deconstration Bundle Licensing approved version \* Oeneral Electric Co NEOU-24259-A 81/02/28 IMOpp 08023 219
- 8103240198 Requests clarification of constraints placed on BhR fuel exposures per 801112 BER Requirement in conflict w/generic NRC approval of operation received by GE in Nov 1980 ltr Util assumes previous commitment no longer applicable JANECEN.R F Commonwealth Edison Co 81/03/19 200
- 8103261150 Forwards Amends 64 & 58 to Licenses DPR-29 & DPR-30. respectively & notice of issuance & availability IPPOLITO. T A Operating Reactors Branch 2 81/03/19 3pp 06035 265
- --8103261155 Arends 64 % 58 to Licenses DPR-29 & DPR-30, respectively, adding license conditions to include guard training & qualification plan
  [PPOLITO.T A Operating Reactors Branch 2 81/03/19, 4pp 08035 268
- --8103261161 Notice of issuance & availability of Arends 64 & 98 to Licenses OPR-29 & DPR-30.respectively IPPOLITO.T A Operating Reactors Branch 2 81/03/19 2pp 08035-272
- 8103300477 Requests amend to Licenses DPR-27 & PPR-30 Amend changes Tech Specs to modify spent fuel storage racks to provide addl storage capability JANECEK.R.F. Cormonwealth Edison Co. 81/03/26 2pp. 03057 249
- --8103300479 Proposed Tech Specs 3 0 revisions re design features \* Commonwealth Edison Co 81/03/26 3pp 08057 251
- --Bi03300487 'Spent Fuel Pool Mod for Increased Storage Capacity."

  licensing rept on high density spent fuel racks

  # Communicalith Edison Co. SINOM K.P. Joseph Gat Corp. IURNER, S

  Black & Veatch, Southern Beience Applications, Inc. Div. TM-600

  Bi/O3/31 85pp. 08057 254
- O Inspection reports. IE Bulletins & correspondence
- 8103050580 Forwards 1E Insp Repts 50-254/80-31 & 50-265/80-31 on 801230 No noncompliance noted. F18HER.W L. Region 3. Chicago. Fuel Facility & Materials Safety Branch 81/01/16 2pp 07829 075
- --GIOJOJOSOS IE Insp Repts 50-294/80-31 % 30-265/80-J1 on 801830 No noncompliance insted Major areas inspected environ protection including observation of damage done by discharge canal overflow & corrective action telen by licensee OESTMAIN.M J. PAPERIELLO.C. J. Region J. Chicago, Office of the Director. B1/01/15 2pp 07829 077
- 8103090264 Forwards [E Insp Repts 50-254/80-27 & 50-269/80-28 on 60125-810107 No noncompliance nated HE[BHMAN R F. Region 3 Chicago, Reactor Operations Nuclear Support Branch. 81/01/21 2pp 07846 324
- --Blogopo272 [E Insp. Repts 50-254/BD-27 & 50-265/BD-28 on Boll25-Blolo7 No noncompliance noted Major areas inspected licenses action on previous insp findings.meeting w/local officials, refuel activities & LERs. CHRISBOILHOOS.N., DUPONT.S 0 , SPESSARD.R L Region 3. Chicago. Office of the Director. Bl/01/20 Spp 07846-326
- 8103240711 Responds to Suppl 3 of 1E Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Suppliers have been contacted to provide qualification of acoustic monitors on relief % safety valves ABEL. J. 6 Commun
- 8103020115 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Outy." No written response required. KEPPLER, J. D. Region 3. Chicago, Office of the Director. 81/02/09 2pp.
- 8103160937 Forwards IE Insp Repts 80-254/81-01 & 30-265/81-01 on 810107-0207. No nencompliance noted. HEISHHAN.R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 81/02/10 2pp. 07915.100
- --Bi03160944 IE Insp Repts 50-294/Bi-01 & 50-265/Bi-01 on Bi0107-0207 N noncompliance noted Major areas inspected NUREO-0737 follows, monthly maint observation. LER follows, plant scrams & operational safety verification. CHRIBGOTIMGS.N., DUPONT.S & SPESBARD.R L. Region 3, Chicago, Office of the Director BI/02/IO. 14pp 07915-102

- 0103200284 Forwards technical sinfo.updating 810202 response to IE Bulletin 80-17. Supp 4. Failure of Control Rods to Insert Buring Ecram at 848 - W/o ercl MALSON T J Compnissalts Edison Co 81/02/11 2pp
- BIDDO40251 Forwards IF Info hotice B1-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/100FR50 72" No written response required PEPPLER. J G. Region G. Chicago. Office of the Director B1/02/12
- 8103030302 Forwards Suppl 5 to 18 Suitetin 80-17. "Failure of Control Rods to Insert During Scram at BUR" No written response required #EPPLER.J.S. Region 3. Chicago, Office of the Director 81/02/13 2cm
- 8103160373 Forwards monthly status rept relevations performed in response to IE Bulistin 79-14. "Seisnic Analysis for As-Built Safety-Related Piping Bys Tables Listing sicessive pipe stresses encl JANECENN R. F. Commonwealth Eduson Co. 81/02/25. 19
- 0103160494 Forwards IE Circular 81-03. "Insperable Seistic Monitoring Instrumentation." No response required #EPPLER. J. G. Region 3. Chicago, Office of the Director 81/03/02
- Bioli70371 Responds to IE Builetin Bi-Ol. "Surveillance of Mechanical Snubbers" No Nuclear Safeguards Corp snubbers have been installed or will be installed on safety-related sys JANCCEX.R F. Comportmenth Edison Co. 81/03/02 Zpp
- BIOG166894 Forwards revised IE Guiletin Bt-01. "Surveillance of Mechanical Snubbers." W/corrected Pages 5 & 6 Change in identification of facilities W/CPs to \_hich bulletin is applicable joes not affect util requirements XEPPLSR-J C Region 3. Chicago. Office of the Director B1/03/04 in
- 8103203374 Forwards fE info Notice 81-06. 'Failure of life Model M-600 Circuit Breaker " No response required MEPPLER J C Region 3. Chicago, Office of the Director 81/03/11 Zac
- 8103203695 Forwards IE Info Notice 81-05, "Degraded DC 84s at Palisades No action required KEPPLER. J 0 Region 3. Chicego, Office of the Director 81/03/13
- 8103200269 Forwards IE Info Notice 81-07. "Potential Problem M/Water-Soluble Purge Dar Metls Used During Inert Gas Helding ' No response required KEPPLER. J G Region 3. Chicago. Office of the Director 81/03/16 20p
- 8103261193 Responds to IE Bulletin GD-25. "Operating Problems W/Target Rock Bafety Retief Valves at BWRs " Engineering review of LaSalle safety relief valve prevments supply sys still in progress Mods will be completed prior to fuel loading.

  RAUSCH.T. J. Commonwealth Edison Co. 81/03/19 7pp.
- #3103270484 Confirms info in 800610 response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Valves 2301-64-65-29 % 30 close on HPCI sys initiation HPCI autiliery oil pump will not deplete power source JAM-ECEX.R F Commonwealth Edison Co. Bi/03/20 4pp.
- R Periodic operating reports & related correspondence
- 8103020373 Forwards "Effluent & Haste Disposal Bentannual Rept.1980." KALIVIANAKIS.N. Commonwealth Edison Co. 81/02/09 ip 07785-222
- --8103020381 "Effluent & Waste Disposal Semiannual Rept.1980." # Corronwealth Edison Co 80/12/31 2ipp 07789 223
- BIO3030792 Forwards occupational radiation espasores rept for 1980 BITEL, J.S. Commonwealth Edison Co. BI/02/25 1p
- --8103030907 Occupational radiation exposures rept for 1980 • Communication Edison Co. 81/02/29. 3pp
- BiO3160697 Forwards monthly operating repts for Feb 1981. #ALIVIANAKIS.N Commonwealth Edison Co 81/03/02. lp. 07914:235
- --B103160666 Monthly Operating repts for Feb 1981. \* Commonwealth Edison Co 81/03/02. 1p 07914-236

- BIG3170355 Forwards monthly operating repts for Feb 1981.

  KALIMFARAXIS.N Commonwealth Edison Co. B1/03/02 1p. 07924 05
- --8103170374 Monthly operating repts for Feb 1981 TU389.R Commonwealth Edison Co 81/03/02 21pp 07924 050.
- S Reportable occurrences, LERs & related correspondence
- 8:03040474 PNO-III-80-I80 on 801009, shall oil fires occurred Caused raint on HBIVs values operated withheattle value protective caps recoved, allowing oil to feet past packing & spray onto tot steam line fires estinguished Haint completed CHRISSOTIMOS.N. SPESSAFO.R.L. REIMANN.F. Region 3. Chicago. Off of the Director 80/10/06 2pp 07811 394
- 8103030592 Forwards updated LER 80-035/03L-1 VALIVIANAKIS.N Commonwealth Edison Co 81/02/13 1p. 07793 1a
- --BI03030598 Updated LER 80-035/03L-1 on BI0126, drywell equipment dr surp outboard isolation valve AO-2-2001-16 exhibited erratic closure time Caused by sediment in valve restricting movement Valve cleaned WUNDERLICH, J.R. Commonwealth Edison Co. 81/02/13 2pp 02793 129
- 8103100377 Forwards LER 81-004/01T-0 PALIVIANAVIE.N Communication Edison Co. 81/03/02 Ip 07865.03
- --BIO3100084 LER B1-004/017-O on B10220, four law condensor vacuum suitches tripped in excess of Tech Specs during test Caused by setpoint drift Switches recallbr ROPACE.J J Commonwealth Edison Co. 81/03/02 2pp. 07869 Of
- V Operator Examinations
- 8103030769 Forwards supplemental info rq shift technical advisor training.per NUREG-0737. Item I A 1.1. (3) Info includes response to training requirements for shift control room engineers 5 projected schedule for training completion ABELUS Commonwealth Edison Co. 81/02/24 4pp
- 8103050140 Forwards list of shift control room ungineers meeting training & education requirements by dates indicated. Many engineers completes training by 810101. Target date for completion of training is mid-1981
  ABEL, J.S. Commonwealth Edison Co. 81/02/24. App
- 8103200974 Forwards supplemental info re long-term shift technical advisor program including candidate qualification, solection criteria, training plans & bases for phase-out of shift technical advisor program mandated by NNREO-0737.

  ABEL. J S Commonwealth Edison Co 81/03/17 19pp
- DJCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- BiO3240688 Approves BiO120 request for extension of data to install emergency diesel generator remote panels for fire protection sys. Fire detector installation datas meet requirements of BO1021 fire protection safety evaluation FR notice encl. DENTON.H R Office of Nuclear Reactor Regulation. Director. Bi/O2/13 3pp 07982-274
- --8002240702 Notice of extension until Billi7 for installation of energency dissel generator renote panels for fire protection sys.

  CASE. 8 Office of Nuclear Reactor Regulation. Director.
  Bi/02/13 Ip 07982 277.
- 8103180264 Ltr to all power reactor licensees w/plants licensed pri to 790101 Forwards NRC position & request for add1 info re safe shutdown capability for compliance w/801119 fire protection rule. EISENMUT.D Q Division of Licensing. 81/02/20. [3pp
- BIC3090052 Forwards request for add1 info re security guard training qualification Response requested within 45 days of receipt of ltr.

  CLARK.R.A. Operating Reactors Branch 3 81/02/23 3pp. 07852
- B103090546 Responds to NRC 801021 & B10122 requests for add1 informative protection safety evaluation suppl App R and requirements are narrow in scope & do not assure that increased plant safety will be achieved FAY.G W. Wisconsin Electric Power Co. 81/03/02. 30pp. 07848:2

- Bio3310338 Ltr to all licensees of operating plants & holders of CPs forwarding NuREG-06%6. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISELHUT, D.O. Division of Licensino BI/03/03 App
- B103100190 Forwards add1 info re safeguards contingency plan Encl withheld (ref 10CFR2 790) BJRSTEIN.8 Wisconsin Electric Power Co 81/03/06 ip 07867 298
- 8103250164 Responds to util BIO218 ltr re emergency response facilities at plant. Requests review of proposed facilities per enc! MUREG-0696 Revisions espected re functions of technical support ctr & emergency operations facility M/o enc!. SEELLO.V. Director's Office. Office of Inspection and Enforcement 61/03/16. 1p 07996 072
- --Bi03250166 Summarizes cuments on emergency operation facility requirements as part of overall emergency preparedness upgrading Habitability requirements depend inappropriate Suggests facility be located at site BURSTEIN. S. Wisconsin Electric Power Co. Bi/02/18 3pp 07984-073
- 9103250093 Provides info re fire protection mods at facilities Items addressed Later damage protection, fire barriers, ventilation sys control cables, dissel generator air intake structure b containment bldg fire stops
  FAY. C. W. Hisconsin Electric Power Co. 81/03/18 5pp. 65144 105
- BIO3260657 Forwards fire protection exemption request BURSTEIN.B. Wisconsin Electric Power Co 81/03/18 1p 08037 330
- --Bi03260&67 Requests extension of schedule dates in new fire protection regulations Requests exemption from requirement forbidding shift supervisor to belong to fire brigade Provides basis for both requests

  BURBIEIN.S. Wisconsin Electric Power Co. 81/03/18. 9pp
  08037-331
- 8)00270430 Requests exemption from neuty enected fire protection regulations, extending implementation dates & deleting requirement that shift supervisor must be fire brigade member Bihedule requirements are unrealistic & unattainable. SURBIEIN-8 Wisconsin Electric Power Co 81/03/1B 9pp 08044-138
- Bio331021B Forwards change to modified amended security plan Continued observation program replaces medical & psychological evaluation Enct withheld (ref 10CFR2.790).

  SURBITEIN.S. Misconsin Electric Power Co Bi/03/24 ip 08079:118
- J Insurance & indemnity information
- 8103160724 Forwards Endorsements & to NELIA & MAELU Binders EB-18 & 19 & X8-18 & 19 respectively DENDAS-W J. Hisconsin Electric Power Co. 81/03/09 Spp 07918-299
- P Operating license stage documents & correspondence
- B103190732 Lirs to all licensess of operating plants applicants for CLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position reinterin ections & request for addl info.

  EIBENHUT.D.G Division of Licensing. B0/12/22. 30pp.
- B103190397 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown.replacement parts & NUREO-0737 EISENHUT, D. G. Division of Licensing. 91/01/19. 6pp.
- BiO3120014 Ltr to all licensees of operating plants, CP holders & OL applicants except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addition or control of heavy loads.

  EISENHUT, D.O. Division of Licensing. 81/02/03. App.
- 8103300160 Ltr to all operating PHR licensees requesting info on auxiliary feedwater sys selemic design Forwards request for addl info list of actions requested of licensees w/o selemically quelified sys & results of NRC welkdowns EIBENHUT, 0.0 Division of Licensing. 81/02/10. 13pp.
- Bi03090136 Responds to Bi0116 ltr re radiological health & safety aspects concerning possible steam generator replacement. No alternatives affect kinds of routine radionuclides released Lists estimates of occupational radiation exposure. W/o encl. CLARK-R. A. Operating Reactors Branch 3. Bi/02/11. 5pp. 07848.291

- 8103160269 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A | 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENAUT. D G Division of Licensing 81/02/18 12pp
- 8103100237 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 KEPPLER: J Region 3. Chicago. Office of the Director 81/02/2 200 07865 229
- BIO3250024 Ltr to all power reactor licensees & license applicants MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing celetions Licensee may submit analysis to justify use of eristing low flow controller EISENHUT, D G Division of Licensing B1/02/20 8pp
- 8103030814 Forwards control room habitability evaluation rept in response to NUREC-0737. "Clarificatin of TMI Action Plan Requirements " Refs 801223 & 810109 responses FAY. C. M. Wisconsin Electric Power Co. 81/02/23 15pp 07795 1
- 8103040605 Requests response on behalf of MI Public Svc Commission encl MI Environ Decade ltm re costs of operating facility w/radioactive crud buildup % reactor vessel embrittlement verbal comments needed by 810227/wcitten comments by 810312 MENDL.J E Misconsin. State of 81/02/23 3pp 07811 360
- 8103030689 Forwards add1 info for Tech Spec Change Request 28,re Apcontainment testing requirements.per Biol27 request FAY.C.W Wisconsin Electric Power Co. 81/02/25 6pp 07789 12
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUI.D O Division of Licensing 81/02/25 Spp
- BiO3180808 Responds to 810923 request for info re-costs of operatin factlify U/radioactive crud buildup & reactor vessel embrittlement No cost info available Forwards pages from NRC 1979 Annual Rept re-reactor vessel embrittlement CLARK. R A Operating Reactors Branch 3 81/03/03 5pp 07944.
- BiO30903B) Forwards TR-ESE-411. "Steam Generator Crevice Flow Test WI Electric Power Co ' Verifies analysis no leakage characteristics of simulated tube defects in tube sheet crevice Rept available in Central Files only FAY.C W Risconsin Electric Power Co 81/03/04 2pp 07851 00
- 8103100470 Discussos NUNEG-0737 schadule requirements provided in licensee 801223 ltr. in response to /RIC request for clarification re accident monitoring training for mitigating core damage t reactor vessel level sys FAY.C W Wisconsin Electric Power Co 81/03/04 2pp 07865 06
- 8103310804 Ltr to all licensees of operating plants applicants for 5 holders of CPs forwarding SECY-81-117 re info necessary to establish environ qualification of safety-related electrical equipment EISEMHUI.D C Division of Licensing 81/03/10 opp.
- Bi03310473 Forwards procedures for hydraulic snubber surveillance & testing; per 810313 request FAY.C W Wiscensin Electric Power Co B1/03/24 ip 08062 335
- --B103310479 "Hydraulic Snubber Burveillance & Maint Program."

  Wisconsin Electric Power Co. 77/05/05 7pp 08062 336
- --B103310479 "Unit 1 & Unit 2 Containment Hydraulic Hanger Insp " • Wisconsin Electric Power Co 78/10/09. 7pp. 08062 343
- G. Inspection reports. IE Bulletins & correspondence
- 8103020690 Forwards IE insp Repts 50-266/80-23 & 50-301/80-23 on 801217-18. No noncompliance noted FIORELLI, 0 Region 3. Chicago, Reactor Construction & Engineerin Support Branch. 81/01/07 2pp 07782 035
- --8103020701 lE Insp Repts 50-266/80-23 & 50-301/80-23 on 801217-18 noncompliance noted Major areas inspected 0A/0C program, IE Sulletin 79-03A activities & revieu & evaluation of nondestructive examination data & repts of inservice insp MARD. K. D. Region 3. Chicago. Office of the Director. DANIELSON. D. H. Region 3. Chicago. Reactor Construction & Engineering Support Branch 81/01/07 3pp 07782.037.

- 8103100685 Forwards IE Insp Repts 50-266/80-22 % 50-301/80-22 on 801291-31 & notice of violation s@ISMMALR F Region 3 Chicago. Reactor Operations Suclear Support Branch 81/01/22 20c 07652 138
- --BiG31008B9 Notice of violation from inst on B01201-31 FEISHCAN R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch B1/01/22 1p 07Eo2 140
- --Mi03100599 IE insp Repts to-264/80-22 /, 50-301/80-22 on 601201-31 Hancompliance nated failure to obtain red taseline data (allowing internuction in reducting activities GULDEMOND M.C., HACUSER L., KARVICKER F. Region 3, Chicago, Office of the Oi-ector 01/01/21 Spp 07862 141
- 9103230309 Enrvaris update to 801030 response to Suppl D of IE Bulletin 75-018. "Environ Qualification of Class IE Equipment" Master list of electrical equipment; component evaluation worksheets 1 svc condition profiles encl FAY: C.W. Bussonsin Electric Pager Co. 81/01/20. \$30pp. 07979-122
- BigGo20131 Furwards If Circular 81-02. "Ferformance of NRC-Licensed Individuals While on Duty ' Ha written response required REPPLER J G Region 3. Chicago. Diffice of the Director 81/02/09 (St. 07787-35)
- BiO3040279 Forwards [E Info Notice Bi-O3, 'Checklist for Licensees Making Notifications of Significant Events In Accordance 1/100FR50-72 No written rosponse required AFFPLER, J. G. Region 3. Chacago. Office of the Director 81/02/32 2pg 97813-218
- 6:03200035 Responds to IE Builetin BI-01. "Surveillance of Mechanical Shubbers" No mechanical shubbers installed on safety related sys Safety-related shock suppressors or shubbers installed are hydraulst units. FAY.C.N. Wisconsin Clettric Power Co. 81/02/12 ip 07972-075
- Alogo20061 Responds to 801218 5-23 ltrs 5-801224 discussion re-steam generator tute insp Corrects Item 4 of 801218 ltr re-cperating conditions Results of next insp should be substituted for review prior to plant startup CLARK, R.A. Operating Reactors Branch 3 81/02/13 3pp 07785-022
- E))O3240214 Forwards )E insp Repts 50-266/83-01 & 50-301/RI-01 on RI0102-30 No noregopitance noted FEISHMAN R F Region D. Chatago, Office of the Darector B1/02/19 2pp 07980 240
- --BIO3240226 IE Insp Repts 50-266/BI-OI & 50-301/BI-OI on BIOI02-30 No noncompliance noted Major areas inspected following on items of noncompliance, operational safety verification & contilly maint observation GULDEMCYO. W O. HAGUE.R L. WARNICK.R F. Region 3. Chicago. Office of the Director GI/O2/I3 12pp 07980.242
- B103110307 Provides clarification of B10105 response to IE Bulletin 80-24. "Prevention of Darage Due to Hater Loakage Inside Containment." Te instrumentation available on containment syc water piping FAY.C N. Wisconsin Electric Power Co. 81/02/20. 2pp. 07883-188
- 0103160676 Forwards IE Info Notice 01-04, "Cracking in Main Steam Lines" No response required KEPPLER.J.G. Region 3. Chicago: Office of the Director 81/02/27 Ip 97914-394
- B103179030 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required MEPPLER. J. 3. Region 3. Chicago. Office of the Director 81/03/02 2pp 07939 157
- 8103160888 Forwards revised IE 3ulletin 81-01. "Surveillance of Machanical Shubbers." U/corrected Pages 5 & 6 Change in identification of faculities w/CPs to which bulletin is applicable does not affect util requirements. MEPPLER. J. G. Region 3. Chicago. Office of the Director 81/03/04 ip 07915-038
- 8103230823 Responds further to IE Bulletin 80-C6. "Engineered Safety Feature (ESF) Reset Controls" per NRC 810205 request Describes control room ventilation sys mods & reset test results Relay coil added parallel to solenoid vake FAY. C M. Misconsin Electric Power Co. 81/03/10. 29p. 07978-305.
- 8103200371 Forwards 1F Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required

- B103200628 Ack receipt of 810213 ltr re recent steam generator tube insp & plans for subsequent insps nert steam generator insp cutage is scheduled for Jul 1981 Util plans to install 10-12 demanstration sleeves in steam generators in Jul FA/C W. Wisconsin Electric Power Co. 81/03/13 ip 07971 249
- 8103200684 Forwards IC Info Notice 81-05. "Degraded DC Bys at Palisades." No action required MEPPLER, J.G. Region 3. Chicago, Office of the Director BI/03/13, 200 07965-118
- B103200349 Forwards IE Info Notice B1-07. "Potential Problem WHater-Soluble Furge Dam Matla Used Oursing Inart Qua Helding." No response required XEPPLER. J. & Region 3. Chicago. Office of the Director B1/03/44 2pp 07966-314
- R Periodic operating reports & related correspondence
- 8(03130588 "Semiannual Monitoring Rept.Jul-Dec 1980 '
  Wisconsin Electric Pawer Co 80/12/31, 14pp 07907 090
- 8103050627 Furnards "Sensannual Monitoring Rept.Jul-Dec 1980 " Conceptant releases, new fuel receipts, environ radiological -onitoring & leak testing of sources 644.0 W Wisconsin Electric Power Co. 81702727. Ip 07848 239
- --BIO3090636 "Semiannual Munitoring Rapt. Jul-Doc 1980 " Concerns ploreleases, new fuel receipts, environ radiological monitoring & leak testing of sources & Wisconsin Electric Power to 81/02/27 41pp 07848 2465
- B103100331 Forwards "Annual Results & Data Rept 1980" FAY. C.R. Hisconsin Electric Pawer Co. 81/02/27 ip. 07864.223
- --BiO3100335 'Annual Results & Data Rept. 1980 "

   Misconsin Electric Power Co 81/02/27 93pp 07864 22/
- 8103170320 Forwards monthly operating ropts for Feb 1981 FAYLC W. Wisconsin Electric Power Co. 81703/10 ip 07923:311
- --BIO3170324 Monthly operating ropts for Feb 1981 FAY.C W Misconsin Electric Pawer Co 81/03/04 Bpp 07/32.1

# V. Operator Examinations

07865 313

- 8103090370 Responds to NURES-0737 re qualification & braining of ducall technical advisor Compares facility training program & inst of Nuclear Power Operations document Sections 9 0 & 6 0 Training program to be completed by 810301.

  FAY.C W. Wistonsin Electric Power Co. 81/02/26 4pp 07650 12
- --8103090574 "Duty Technical Advisor Training Program "

   Wisconsin Electric Power Co 91/02/18 10pp 07850 130
- DCCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plane
- 8803180264 Ltr to all power reactor litensees w/plants litensed proto 79010; Forwards NRC position & request for add1 info resails shutdown capability for compliance w/801119 fire protection rule.
  EISEMPUT.D.O Division of Litensing 81/02/20, 1300.
- B103100680 Requests that excl emergency planning into be mode public available (4/o encl 500DER. J. t. Division of Rules and Records 81/02/27 ip
- 8103160492 Forwards energency plan & implementing procedures Also forwards state & local emergency plans. NRC has not reviewed previous plan submittals W/o encl WAREMBOURG. D. Public Service Co. of Colorado 81/02/27 2pp. 07921.143
- B103310338 Ltr to all licensees of operating plants & holders of CF forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements V/o encl EISENHUT, D.G. Division of Licensing 81/03/05. 6pp.

- 8103180785 Responds to N9C 810211 ltm re revised util security plan-App 8, guard training & qualification submittal Informs that 810313 deadline for revisions & addl info will not be net 8.5mittal expected by 810320 HAREMBOURS.D Public Service Co. of Colorado 81/03/11 ip
- B10319C056 Forwards Revision 5 to security plan Revision withheld (ref 10CFR2 750)
  WAREMBOURD, D Public Bervice Co of Colorado 81/03/11 1p
- B103300067 Forwards revised goard training & qualification plan Plan withheld (ref 1005R2 790) HAREMBOURD, D. W. Public Bervice Co. of Colorado (81/03/20) (p. CR053.052
- 8)00300171 Releases public version of emergency plan FELTON,J M. Division of Rules and Records 81/03/25 1p 07806:001
- --Bi03300174 Forwards public version of State of CD radiological emergency response plan Draft 3 of util emergency plan implementing procedures & Weld County, CD, emergency response plan.

  > Public Service Ca of Colorado 81/03/18 lp 07806-001
- --8103300172 Public version of State of CD radiological emergency response plan. Draft 3 of util emergency plan. implementing procedures & Weld County. CD. emergency response plan Public Service Co of Colorado 80/04/30 1250pp 07806 C01

### H General correspondence

C100290414 Responds to 801226 ltr to Senator Hart re history of gas cooled reactors./RC goals & purpose & excessive noise & banging at facility Sintlar concerns addressed at ACRS B10127 reeting NRC comments encl HtLLER./ R Btandardiration & Special Projects Oranch B1/03/17 5pp. 07997 260.

#### [. Financial information

- 6103160699 Forwards Annual Financial Rept 1780
  HAREMBOURG, D Public Service Co of Colorado 81/03/11 1p
  07918:001
- --B103160703 Annual Financial Rept 1980 PERSON-R T . WALKER.R F Public Service Co. of Colorado B1/02/05 52pp 07918 002.
- P Cperating license stage documents & correspondence
- BLO3:90387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related ejectrical equipment Items addressed involve cold shutdown, replacement parts & NUREO-0737 ECSENHUT. 0 0 Division of Licensing 81/01/19. 6pp
- 8103120014 Ltr to all licensees of operating plants, CP holders & OL applicants.except Indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertently unlitted pages from NRC 801222 request for add1 info re control of heavy loads EISECHMUT.D.9 Division of Licensing 81/02/03 6pp
- 8103040961 Forwards revised NRC Region 4 organization chart.effective 810227 SEYFRIT K V Region 4. Dallas. Office of the Director 81/02/17. 2pp.
- 8103160669 Ltr to all operating plants t CP holders forwarding clarification of TMI Action Plan Item III.A.1.2 re upgrade of emergency support facilities. Requests confirmation within 43 days that implementation dates will be met ETBERHUT.D 0. Division of Licensing 81/02/18. 12pp.
- 8103030744 Responds to CO PIRO questions re facility. Util has not experienced problems w/fuel particle coatings MAREH80URG.D W Public Service Co. of Colorado. B1/02/20. Spp 07796 072.
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENHUT, D O Division of Licensing 81/02/20. 8pp.

- BiO3030741 Responds to Professor Rea B31226 ltm re facility Core meltdown is not possible at facility Util has provided justification to NRC re relief or 15-minute time limit for public motification. HAREMBOURD, D.W. Public Service Co. of Colorado. B1/02/23 5pp.
- 8103030843 Forwards additinfo he reactor core primary coolant bypass fractions & comparison of predicted vs measured core region outlot temps before & after experience of core region outlet temp redistribution.per NRC 810210 request. W/o encl SWART.F E Public Service Co of Colorado 61/02/23 1p 07795 223
- 6103230030 Ltr to all licensees of operating huclear power plants & applicants for NLs (except St Lucie-Units 1 & 2) Requests util review to determine capebility to mitigate slation blackout event & promptly implement energency procedures FISCENHUT.D G Division of Licensing 81/02/25 5mg
- 8102030703 Forwards response to NUREO-0737 Item III A 2 remeteorological sys 7 dose calculation method Util will procure replacement wind instrumentation for reactor bids MAREMEDURG, D.K. Public Service Co. of Colorado
- B103110954 Notifies that B01222 ltr.transcritting NJREO-0612. Control of Heavy Loads. Trequest for addl info.not received Requests guidance for response 5 encls. if applicable MAREMBOURO.D II Public Service Co of Colorado B1/03/02 Ip 07897-794
- 8103200021 Informs that staff functions of Region 4 reassigned, effective 810227 G. Majsen.Chief of Roactor Projects Branch designated as principal contact & recipient of correspondence re reactor const & operation activities SEYFRIT.K V Region 4. Dallas, Office of the Director 81/03/09 to 07766 182
- B10317J007 Notifies that payment for Class 3 fee re 800905 request for cremption from requirements of 10CFR25 & 10CFR95 will be refunded fee per 10CFR170 22 not applicable to request MILLER.II D Liceuse Fee Management Branch B1/03/10 ip 07939 283
- B103310804 Ltr to all licensees of operating plants, applicants for OLs 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment FISFPHULD O Division of Licensina 81/03/10 600
- 8103240476 Forwards proposed revisions to Tech Specs 3 1 3 1.3 1 3 4 8 last paragraph of page 3 1-7 Format request for amed will be made after safety committee approval received. MAREMBOURO, D. Public Service Co. of Columbia 81/03/16 tp. 07990-195.
- --Bi032404BO Proposed revisions to Tech Specs 3 i 3 1 for power-to-flow ratio between 1 i7 % 2 5.3.1 3 4 for power-to-flow ratio less than 1 i7 % Page 3 i 7.1ast paragraph

  # Public Service Co of Colorado 81/03/16 9pp 07990 196
- 8103240838 Forwards Ahand 23 to License DPR-34, safety evaluation & notice of issuance & availability.

  MILLER, J. R. Standardization & Special Projects Branch 81/03/16
  3pp 07984, 247
- --BIO3240B44 Amend 23 to License DPR-34 extending min sample flow limits to cover reactor power range of 70-100% defining times to start depressurisation & extending core residence time of fuel test elements
  MILLER. J. R. Blandardization & Special Projects Branch 81/03/16
  20pp 07789 250.
- --Bi03240B47 Safety evaluation supporting Amend 23 to License DPR-34 \* Office of Nuclear Reactor Regulation, Director Bi/03/16 30pp 07984,270
- --8103240852 Notice of issuance & availability of Amend 23 to License DPR-34 MILLER.J. R. Standardization & Special Projects Branch 81/03/16. 3pp. 07984-300
- O. Inspection reports: IE Bulletins & correspondence
- B103031094 Forwards IE Mgt Meeting Rept 50~267/80~23 on B01119 No noncompliance noted MADSEN.9 L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. B0/12/04 2pp. 07797.039

- 9103:80433 Forwards IE Insp Rept 90-267/80-25 or G01201-31 & notice of violation MADBEN.3 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 61/61/29 2:00 07943-042
- --Bio3180436 Notice of violation from insp on B01208-31 MADSEM, 6 L. Region 4. Dallass, Reactor Operations Nuclear Support Branch B1/01/22 to 07943 044
- -8103180443 IE Insp Rept 50-267/80-25 on 801201-31 Noncompliance noted failure to perform surveillance within specified time persod for fuel storage facility cooling sys flow indicators & flow & temp alarms
  DICKERSCHIM W. PLUMLEE OL. WESTERMANT F. Region 4. Dallas.
  DIFFICE of the Director 81/01/22 7pp 07943-045
- 8103090009 Ack receipt of 810109 for re-violations noted in IE Insp. Rept. 50-267/80-17 Pending approval of proposed elevator and intesting corrective actions are acceptable. MELLY-J.A. Region 4. Dallas. Office of the Director. 81/02/06 lp. 07897 028
- --8103050013 Forwards response to viciations noted in IE Insp. Rept 30:267/80-17 Gummary of meeting to discuss physical security plan uill be sent by 810201 Response withreld fref 100FR2 7701 HILLEM.C.K. Public Service Co. of Coloredo. 81/01/09 ip 33027 029
- 8100200349 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals Unite on Duty " No written response required BEYFRIT.K M. Region 4, Dallas, Office of the Director 81/02/09 Ip 07965-338
- 8103160398 Forwards [E Info Notice BI-03 "Checklist for Licensees Making Notifications of Bignificant Events in Accordance WildCRR50 72 "No response required SEYFRIT.K V Region 4. Dallas. Office of the Director B1/02/12 Ip 07915 262
- 8103160642 Forwards IE Info Notice 81-04. 'Cracking in Main Steam Lines' 'No response required SEYFRIT.K V Region 4. Dallas, Office of the Director 81/02/27. 1p. 07917 104
- 010317005% Forwards 1E Circular 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required. SEYFRIT.K V Region 4. Dallas, Office of the Director 81/03/02. 1p. 07739 173
- 8103110787 Ack receipt of 810121 ltr informing NRC of steps taken to correct violations moted in IE insp Rept 50-267/80-24. PADERN 9.1. Region 4. Dallas. Reactor Diperations Nuclear Bupport Branch 81/03/03 in 07876 355
- --BIO3110792 Responds to NRC 801216 ltr re-violations noted in IE Insp. Rept 50-267/E0-24 Corrective actions deviation prepared to correct error in sketch. Project engineering personnel will review problem.
  LEE.OR R. Public Service Co. of Colorado. Bi/O1/21 lp. 07876-07
- 8103270286 Updates info re admittance of NRC personnel to facility Forwards lists of regional inspectors (#/o encl. SEYFRIT.K V. Region 4. Dallas. Office of the Director 81/03/03 2pp 08344 184
- B10316CB38 Forwards revised IE Bulletin 81-01. "Burveillance of Pectanical Enubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  SEYFRIT.K V Region 4. Dallas. Office of the Director. 81/03/04 is. 07914 197.
- 8103230174 Forwards 1E Info Notice 81-07. "Potential Problem N/Water-Boluble Purge Cam Matls Used During Inert Gas Welding." No response required. 
  EEYFRIT. K V. Region 4. Dallas. Office of the Director BI/03/16. 
  1p 07977 212.
- 8103240193 Forwards IE Insp Rept 80-267/61-07 on 810223-25 No noncompliance noted. DROWN.O.D. Region 4. Dallas. Office of the Director. 81/03/18 2pp. 07980 237

- R Periodic operating reports & related correspondence
- 8103050303 'Rept of Changes Tests & Experiments not Requiring Prior Commission Approval Per 10CFR50 59(a).1980 "
  Public Service Co. of Colorado 80/12/31 97pp 07827 109
- 8103060284 Forwards "Environ Radiation Surveillance Program Surmary Rept. Jul-Dec 1980" SWAYT, F. E. Public Service Co. of Colorado 81/02/27 (p. 07839-385)
- T-B103060291 'Environ Radiation Surveillance Program Bummary Rept, Jul Dec 1980 'CHASON, J E., SCHLEIGER, T E., SWART, F E., Colorado State Univ. B1/02/26 1673c 07840 CO1
- 8103090276 'Annual Operating Rept 10,1980 "
   Public Service Co. of Colorado... B1/03/04 ... 50pp. 07832 146...
- 9103100481 Forwards "Initial Approach to Power Tests (8-Series)"for period ending 810222 WARENGOUNG. D. Public Service Co. of Colorado. 81/03/09. ip 07847-223
- --Bi03100483 "Initial Approach to Power Tests (8-Beries)."

  \* Public Service Co. of Coloredo. Bi/03/05 2pp. 07867 224
- 8103100604 Forwards monthly operating rept for Feb 1981 MAREMBOURD. D. Public Service Co. of Colorado. 81/03/05. ip 07863-086
- --8103100606 Montaly operating rept for Feb 1981. OARK J U Public Service Co of Colorado 81/03/01. Spg. 07863-087
- B103050609 'Annual Operating Rept. 1980. "
   Public Service Co. of Colorado B1/03/06. 50pp 07837. 188
- S Reportable occurrences. LERs & related correspondence
- B103020431 PND-TV-B1-006 on B10223 hot reheat temp scram occurred, releasing minute amount of radioactivity into reactor bldg Caused by frequency swings on grid sys. State of CD was notified.

  LESTERMAN.T.F., MADSEN.O.L. Region 4. Delles. Office of the Director B1/02/24. 1p. 07784:118
- 8103030671 Forwards LER 81-012/02L-0 MAREMOURD, D Public Service Co of Colorado 81/02/26. 4pp 07791:289
- --8103030677 LER 81-012/03L-0 on 810127, six of twelve steam pipe rupl (pipe cavity) of transmic noise channels had unacceptably low response to known noise source during test. Caused by microphone 1/or transmitter gain reduced to stop tripping QAHM. J. A. Public Service Co. of Colorado. 01/02/26 ip 07791:273
- 8103100579 Forwards LER 81-016/03L-0 WAREMBOURGO.D. Public Service Co. of Colorado. 81/03/03. Sec. 07882-326.
- --8103100582 LER 81-016/03L-0 on 810213 discovered that 3 of 12 hels. circulator seal malfunction pressure differential switch units had trip point outside limits Caused by dirt accumulation in electrical switches Switches readjusted GAHM.J W Public Service Co. of Colorado. 81/03/03. [p. 07862-33]
- 8103310737 Forwards LER 81-014/03L-0 Detailed summery also encl. MAREMBOURG, D. Public Service Co. of Colorado. 81/03/03. Spp. 08061: 080.
- --8103310744 LER 61-014/03L-0:on 810104, instrument air compressors 10 IA aut of eye. leaving only compressor IB in eye. Caused by compressor IC tripping on high discharge air temp & compressor IA being cleared out for insp & repairs.

  OAIM. J. W. Public Service Co. of Colorado 81/03/03. ip 08061-085.

- 8103110524 Forwards LER 81-015/03L-0 Detailed event analysis encl LAREM9BUNG.D Public Service Co of Colorado 81/03/06 1p 07872 268
- --E103110527 LER 81-015/03L-0 on 810204-0220, plant operated in degraded mode on hime occasions Causes include increased oxidant outgassing after power increase 5 moreture introduced into primary coolant as part of approved test QAMM. J. W. Public Service Co. of Colorado. 81/03/06. 9pp 07072-277
- 8103300294 PND-IV-01-010 on 810321, during test for turbine generator power load imbalance, turbine trip occurred causing increase in 1cop 2 steam generator ponetration interspace helium lealage. Cause not stated Power reduced to zero MESTERMAN, I.F., MADSEN, O.L. Region 4. Dallas, Office of the Sirector 81/03/23. 1p 08059 280

## V Operator Exeminations

- 8103040634 Responds to NUREO-0737 re Tril action plan requirements. Release of plant sys or equipment for maint or surveillance testing is controlled by sonior operators Procedures provide for equipment & worker protection. HAREHBOURG. D. W. Public Bervice Co. of Coloreda 81/02/27 4pp 07815; 828.
- OCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

  F. Sacurity, redical, emergency & fire protection plans
- BiO31B3264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards ARC position & request for addl info research shutdown capability for compliance u/80(1)19 fire protection rule
  EIBERHUUT.D D Division of Licensing 81/02/20 1300.
- 8103120643 Ack receipt of 801117 ltr re change to security plan Concurs wicharge tontained in encl Encl withheld (ref 100FR2 790).

  FEID: R. W. Departing Reactors Branch 4. 81/03/04 2pp. 07906 132.
- 0103310330 Ltr to all licensess of operating plants & holders of CPs forwarding NVREG-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements MVo encl EISENHUT.D.O Division of Licensing. 01/03/05 6pp
- BiO31501B1 Releases public version of implementing procedures for energency plan.
  FELTON-J M. Division of Rules and Records. B1/03/12 1p. 07806:001
- --Di03160187 Forwards public version of implementing procedures for seargency plan. PARKER: U.O. Duke Power Co. 81/03/02 ip 07806: 001.
- --81031&0196 Public version of implementing procedures for emergency plan. Includes load rejection turbine & reactor trip, loss of reactor coolant & boron dilution
  # Duis Power Co. 81/03/02. 330pp 07806:001.
- 8103200611 Advises that proposed updated Tech Spec for fire protection program will be submitted by 810416.in response to NRC 001001 request.
  PARKER-N.O. Duke Power Co. 81/03/16. ip. 07971:255.
- 6303261212 Requests that entl emergency planning info be placed in LPDR M/o 8103160109 8000ER.J.L. Division of Rules and Records. 81/03/24. ip 08040:247.

#### 1 Financial information

- 8103310549 Forwards Annual Financial Rept 1980, annual certified financial statements, 1981-83 financial forecast & util statement re available funds to satisfy liability Info guarantees retrospective premiums per 10CFR140.26. THIES.A.C. Dute Power Co. 81/03/24. 1p. 08075:100.
- --B103310638 Annual Financial Rept 1980 including financial statements 1981-83 financial forecast & statement re sources of available funds to satisfy liability HARN-C , LEE. W. B. Duke Power Co. B1/02/13. Sipp. 08075:101.

- P Operating license stage documents & correspondence
- 8010230589 Surrary of 800821 meeting L/BAW reactor cuners group re abnormal translent operating guidelines program VISSIMO.0 Operating Reactors Branch 4 80/09/30 29pp 05/87 236
- --B103230355 Draft Atnormal Transient Operating Guidelines.Part 1 -Adequate Core Cooling Reactor Trip/Forced Shutdown HALLMAN, D.A. TWILLEY.P.C. WALTERS.J.F. Babcock & Wilcon Co 80/07/30 54<sub>2p</sub>
- --8103230375 Draft Abnormal Transient Operating Guidelines.Part 2. V Fundamentals of Reactor Control for Abnormal Transients MAPIM.D A. SWANSDY.E. CARTER.L R. Babcock & Hilcor Co 80/07/30 150pp
- --8103230306 Draft Abnormal Transient Operating Ouidelines.Part 2.v Discussion of Selected Transients HAPIN.D A . SHANSON.E . CARTER.L R Babcock & Hilcox Co SO/97/30 123pp
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREG-0012 Forwards MRC position re interim actions & request for addl info EISENHUT. D.O. Division of Licensing 80/12/22 30pp
- B103190087 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment (tems addressed involve cold shutdown.replacement parts & NUREG-0737 EISEKHUT.D.O Division of Licensing B1/01/19 600
- 8102270389 Summary of 801216 meeting u/81W owners group re abnormal transient operating guidelines (ATO3) program & TMI Action Item II i. 3.30, small break LCCA models List of attendees & viewgraphs enc!

  THROM.E O Reactor Systems Branch 81/01/30 30pp
- BiO3120014 Ltr to all licensees of operating plants CP holders & QL applicants except Indian Point 2 & 3.2ion 1 & 2 & THI-1, forwarding inadvertently chitted pages from NRC B01222 request for add1 info re control of heavy loads EISENHUT.D O Division of Licensing B1/02/03 App.
- 8(0305019) Forwards request for add1 info re seismic design to comp review of standby shutdown facility REID.R.N. Assistant Director for Licensing. 81/02/09 4pp 07825:170
- 8103030893 Forwards Amends 93.93 & 90 to Licenses DPR-38, DPR-47 & DPR-35, respectively, safety evaluation & notice of issuance & availability.

  REID.R.W. Operating Reactors Branch 4 81/02/10 2pp 07800 3:
- --Bi03030899 Amends 93.93 % 90 to Licenses DPR-3B.DPR-47 & DPR-55, respectively, revising Tech Specs to support operation at Unit 3 at full rated power during Cycle 6.
  REID.R. W. Operating Reactors Branch 4 81/02/10 28pp.
  07800:350.
- --8103030914 Safety evaluation supporting Amends 93,93 & 90 to Lice DPR-38,DPR-47 & DPR-55, respectively • Office of Nuclear Reactor Regulation. Director 81/02/10. 07801:016
- ~-8103030923 Notice of issuance & availability of Amends 93.93 & 90 Licenses DPR-38, DPR-47 & DPF-55, respectively. REID.R.W. Operating Reactors Branch 4. 81/02/10. 2pp 07801:025.
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design. Forwards request for addl info. list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISENHUT. D. O Divisson of Licensing 81/02/10 13pp
- 8103160667 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Iten 111. A. 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met. EIBENHUT. D. 9 Division of Licensing. 81/02/18 12pp.
- 8103090018 Advises of review of util 801208 response to NRC 800701 requesting info on fuel assembly holddown spring failures Requests commitment to perform surveillance testing on holddown springs in core during next refueling outage REID, R. W. Operating Reactors Branch 4 81/02/20. 2pp. 07849: 2

- 0102230024 Ltr to all power reactor licensees & license applicants re MREG-0619 criteria Factrate 2 in Table 2 cantains error due to leakage testing felections Licensee ray subout analysis to justify use of existing low flow controller EISENANT-C C Osympton of Licensing 81/02/20. Bpp
- 6103390899 Generic itr to all 884 licensees he capability of small break LGCA hodel to predict small break behavior Fost-test evaluations of L-4-1 & 6-07-100 predictions requested for symmetrial ty 8104401 Registal Capabina Reactors Branch 4 81/02/24 3nc 07844 233
- 91031:0784 Forwards request for add1 info re util 79:221 & 300723 responses to recommendations contained in BAM-1564. "Integrated Control Sys Reliability Analysis : Analysis of consequences of study open turbine types valve is required REIO.R W. Openating Reactors Branch 4 81/02/25 8pp 07877 328
- BIC3230033 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie-Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement energency procedures EESIMUT.D 0 Olyssion of Licensing 81/02/25 529
- 9103120862 Forwards 810109 request for add1 info ne 8½W 177 fuel assently puners group submittal on asymmetric LOCA loading Response requested uithin 60 days REID.R W Operatin) Reactors Branch 4 81/02/26 2pp 07904.001
- B103230B13 Generic Ltr B1-05 to all CP holders & CL applicants re ICCFR50 71(e). Periodic Updating of FSARs," effective BC0722 Info re FSAR legal status, format & content encl ECSECHULD 9 Division of Licensing 81/02/26 10cp
- 8:03120029 Act receipt of 800211 response to 79082! Info request to 85H reactor surers group Requirements of Thi Action Plan Item II K 2 19. 3erchmark Analysis of Sequential Auxiliary Feedwater Flow Fulfills request Safety evaluation end REIO.R & Operating Reactors Branch 3 81/02/27 2pp 07903 021
- --8103120245 Safety evaluation reliten 1) A 2-19 "Benchmart Analysis of Sequential Ausiliary Feedwater Flou" for B&H reactor plants intent of Action Item II K-2-19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program + Office of Nuclear Reactor Regulation. Director 81/02/27 2pp 07903-023
- 8103120276 Act receipt of 800205 response to 790821 info request to B&W reactor coners Requirements of TMI Action Plan Item II x 2 19. "Jenchmark Analysis of Sequential Auriliary Feedwater Flow." fulfills request Safety evaluation encl REID.8 x Operating Reactors Branch 3 81/02/27 29p 07906 137
- --B10312030B Safety evaluation to TMI Action Plan Item II % 21 19.

  "Benchmark Analysis of Sequential Auxiliary Feedwater Flow"
  for BSW plants Intent of Action Item II % 219 accessished
  by results provided by CRAFT-2 similar to TRAP-2 program

  OFFICE of Nuclear Reactor Regulation, Director B1/02/27. 2pp
  07906 139
- B103120789 Discusses compilance w/TM1 Action Plan Item I1 K 2 19.
  "Beacheart Analysis of Sequential Autiliary Feedwater Flow "
  More rigorous assessment is being performed under Item
  I1. K 3 30 Item is resolved Safety evaluation encl.
  REIO.R W. Operating Reactors Branch 4. 81/02/27 2pp 07904 227
- BIO3090193 Notification of BIO402-03 meeting w/8kH coners group in Bethesde.MD to discuss responses to NSC BIO109 ltr re dsymmetric LOCA loadings. VISSING.O Operation Reactors Branch 4 BI/03/02 2pp 07848-341
- 8103120261 Ack receipt of 800630 response to 796821 shee request to B&W reactor gamers group Requirements of IMI Action Plan Item III x 2.19. 'Benchmark Analysis of Sequential Auriliary Feedwater Flow.' Fulfills request 8
- --8103120270 Safety evaluation re IM1 Action Plan Item II K 2.19.
  "Benchmark Analysis of Sequential Ausiliary Feedwater Flow."
  Intent of Action Item II K 2 19 accomplished & results
  gravided by CRAFT-2 similar to TRAP-2 grogram
  # Office of Nuclear Reactor Regulation. Director 81/03/02 2pp.
  07704.353
- 8103090640 Advises that response to request for add1 info re emergency feeduater sys will be submitted by 810403 PARKER.W (I Dute Power Co. 81/03/03 Ip 07844 289

- BIO3110321 Advises that analyses of liquid & gaseous radwastes and performed by Teledique Isotopes, per schedule requirements of Tech Epecs 3 9 B & 3 10 9, satisfying Tech Epec 6 4.1 Betailed review of vendor analysis procedures unnecessary. PAPLER, N.D. Eute Power Co. BI/O3/O3 2pp. 07872,319
- 8103170390 Forwards safety evaluation on TMI Action Plan Item 11 A 2 19. "Benchmark Analysis of Sequential Auxiliary Fedulator Flow" for DSM reactor plants Util found in compliance wilten MEIDLR W. Discreting Reactors Granch 4 01/03/04 2pp.
- --BiO3170571 Safety evaluation re TMI Action Plan Item II K 2 19.
  "Benchmark Analysis of Sequential Feedwater Flow" for D&W
  reactor plants.
   Office of Nuclear Reactor Regulation. Director 81/03/04 App
- B)03120438 Forwards proposed tech Specs for upgrade of enticipatory reactor trip sys
- 8103160993 Notifies that existing Tack Specs re heat removal capabilit during all nodes of operation resolved concerns re 800924 ltr & 800606 response to IE Bulletin 80-12. "Decay Heat Removal Sys Operability "Recoval Sys Operability "820027. JF Operating Reactors Branch 4 81/03/09 2pp. 07921.145
- 8103310834 Ltr to all licensees of operating plants applicants for this tholders of CPs forwarding SECY-81-117 re info necessary to establish environ qualification of safety-related electrical equipment [ISCIMMUT.O G Division of Licensing 81/03/10 6pp
- Bio3170454 Responds to NRC 810220 request for util commitment to surveillance of fuel assembly holddown springs in facility cores Documents util plans to inspect fuel assemblies for broken holddown springs during upcoming refueling nutages PARKER, W O Dute Power Co 81/03/12 2pp 07934:337
- B10324009B Requests remission of license amend fee in connection w/ issuance of Arands 92.92 & 9B to Licenses DPR-3B, DPR-47 & DPR-55, respectively DERS-55, respectively DERS-58, respectively B1009.8 License fee Management Branch. B1/03/17. 1p. 07/61/ WHZ
- 8103230644 Application to amend OLs, revising License Condition SE to authorize completion of rods identified in Table 3 i of NRC 780811 fire protection safety evaluation. Supporting jocumentation encl PARKER, W.O. Dute Power Co. 81/03/18. 11pp. 07977 009
- 8103240332 Forwards revised responses to Questions 4 & 11.addressed to util 801113 ltr.per NRC Bl0315 request for addl clarification on reload design methodology technical rept PARKER.W D Dute Power Co. 81/03/18 3pp. 07990-134
- 8103240393 Forwards "Evaluation of Transient Nuclear Instrumentation Power Range Flux Error," in response to NRC 810114 ltr. PARKER, N O Dute Power Co 81/03/19. 1p 07990. 184.
- --8103240398 "Evaluation of Transient Nuclear Instrumentation Power i flux Error " # Dute Power Co 81/03/19, 33pp. 07990:185
- 8103270704 Requests meeting w/NRC to discuss issue of mild environs per Commission 800523 memo & NRC 801024 order by 810415. Response should be received by 810401. PARKER W 0 0 046 Power Co 81/03/19. 1p. 08047:119.
- 8103270684 Informs that BBM owners group submitted BAM-1911P, "Irrediation-Induced Reduction in Chargy Upper Shelf Energy of Reactor Vessel Welds" to fulfull submittal requirements of 10CFR90.App 6.
  PARKERLH.O Duke Power Co. 81/03/23. 1p. 08043:301.
- --BIO3270693 Forwards BAW-1511P, "Irradiation-Induced Reduction in Charpy Upper Shelf Energy of Reactor Vessel Weids " Describes implementation predictive methodology to determine svc life of reactor vessels W/o encl. TAYLDR.J.H Babcock & Wilcox Co. B1/03/12. 2pp. 08043.30W

- G Inspection reports. IE Bulletins & correspondence
- 8103170103 Forwards Revision & to 90-day response to 1E Oulletin 79-01B. "Environ Gualification of Class IE Equipment" Revision addresses environ qualification of electrical equipment needed to achieve hot & cold shutdowns IHIES, & C. Duke Power Co. 81/01/30 140300 08047 211
- 8103020203 Forwards 1E Circular 81-02. "Performance of NRC-Licensed individuals White on Duty " No written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 81/02/07 Lp 07785 306
- 8:03030082 Supple previous responses to LE Bulletin 80-11 Forwards schedule for completion of masonry wall re-evaluation Parallel path program will be followed for walls which do not comply w/long-term acceptance criteria PARKER.W O Duke Power Co 81/02/09 2pp. 07808 200.
- BiO3040167 Forwards IE Info Notice Bi-O3. "Checklist for Licensees Haking Notifications of Bignificant Events In Accordance W/10CFR50 72 " No written response required. D'REILLY, J P. Region 2, Atlanta, Office of the Director Bi/OZ/12 ip 07813.007
- 8103160725 Forcards IE Info Notice 81-04. "Cracking in Main Steam Lines." No response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. B1/02/27 1p. 07914 110.
- 8103160651 Forwards IE Circular 81-03. 'Inoperable Gaismic Monitoring Instrumentation." No response required D'REILLY, J.P. Region 2, Atlanta. Office of the Director 81/03/02 (p. 07917 (2)
- BI03120828 Ack receipt of 810211 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Repts 50-270/80-27, 50-287/80-24 & 50-269/80-31.
  LEMIB.R.C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B1/03/04 ip 07903 338.
- --Bi03i20B36 Responds to NRC Bi0i20 ltr re violations noted in IE Health Physics Appraisal Repts 30-270/80-27,50-287/80-24 & 50-269/80-31 Corrective actions:more sensitive probes placed at high-vol personnol traffic RCA exits.
  PARMER.N 0 Duke Power Co. 01/02/11, 4pp 07905:339
- --8103120841 Forwards IE Health Physics Appraisal Repts 90-270/80-27. 30-287/80-24 & 30-269/80-31 notice of violation & significant appraisal findings. O'REJLLY-J.P. Region 2. Atlanta, Office of the Director. 31/01/20 4pp 07903-343
- --8103120843 Notice of violation from health physics appraisal on 800908-19. • Aegion 2. Atlanta. Office of the Director. 81/01/08. ip 07905:347.
- ~-8103120848 IE Health Physics Appraisal Repts 50-270/80-27.50-287/80-24 & 50-269/80-31. Noncomplience noted. Failure to follow written procedures & to perform safety analysis prior to making changes to facility.
  HJBEY.C M Region 2. Atlanta. Office of the Director. OIBBON.A F. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 81/01/08. 29p. 07905-348.
- 8103160851 Provides supplemental response to IE Bulletin 80-11.

  'Masonry Hall Design." Two masonry walls in Unit 1 reactor bldg are adequate for all design loadings.
  PARKER.W.O. Dute Power Co. 81703704 2pp. 07915-230.
- 8103170041 Forwards revised IE Bulletin 81-01. "Burveillance of Machanical Snubbers." w/corrected Pages 5 & 6. Change in Identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 81/03/04.

  Ip. 07937:167.
- 8103110576 Responds to NRC evaluation of 801031 Revision 5 response to IE Bulletin 79-018. Requests further clarification of response items classified as deficient Deficiencies would not adversely affect plant operation.

  PARKER, W. D. Duke Power Co. 81/03/03 3pp. 07885:053.
- 8103260492 Advises that review of interim mode showed deviation from sthedule in 790612 response to IE Bulletin 79-01. "Environ Qualification of Class IE Equipment." NRC will be informed of new mod schedule upon receipt of replacement equipment, PARKER, M.O. Duke Power Co. 81/03/05. 1p. 08037:202.

- B103200281 Forwards IE Info Notice 81.06. 'Failure of ITE Model K-600 Circuit Breaker "No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03/11 to 07969 016
- 8103240611 Ac) receipt of 810306 ltr informing ARC of steps taken to correct violations noted in 1E Insp Repts 30-269/80-3B. 50-270/80-38 & 90-287/80-32 LEWIS.R C Region 2. Atlanta. Office of the Director 81/03/11 p 0788
- --8103240628 Responds to NRC 810211 ltr re violations noted in IE Insp Repts 50-267/80-38.50-270/80-35 4 50-287/80-32 Corrective actions stopped spill.jecontaminated area & counseled personnel about procedures No proprietary info PARKER.N O Duke Power Co 81/03/06 3:p 07983 188
- --BIO3240633 Forwards IE Insp Repts \$9-269/80-39.50-270/80-35 & 50-287/80-32 on 801201-31 & notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 81/02/11 2pp 97883 191
- --Bi03240640 Notice of violation from insp on B01201~31 • Region 2. Atjanta. Office of the Director B1/02/JJ jp 07983 193
- --8103240448 IE Insp Repts 50-249/80-38.90-270/80-35 & 50-287/80-32 on B01201-31 Noncompliance noted interim radwarte sus was operated w/o adequate procedure resulting in radioactive spill.

  ORDERS W T . JAPE F . MYERS D D . Region 2. Atlanta . Diffice of the Director . B1/02/11 . Bpp. 07983 194.
- B10317076B Notification of B10324 meeting w/util in Bethesda.PD to discuss proposed inservice insp scheduled during June 1981 refueling shutdown MAGNER.P C. Operating Reactors Branch 4 B1/03/13 2pp
- 8103200313 Forwards IE Info Notice 81-05. 'Degraded DC Sys at Palisades' 'No response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/13 ip 07969 072
- 8103240704 Ack receipt of 810206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-39, 50-270/80-34 & 50-287/80-30 LEMIS.R C Region 2, Atlanta. Office of the Director. 81/03/18 lp 07983
- ~-8103240712 Responds to NRC 810210 ltr re violations noted in IE Insp. Repts 50-269/80-39, 50-270/80-34 & 50-287/80-30 Corrective actions reinspected ref welds using proper calibr & cautioned all R&W inspectors to document calibr & inspectors RAKKER.N D. Duke Power Co. 81/03/06 3pp 07783 310.
- --B103240722 Forwards IE Insp Repts 50-269/B0-39.50-270/B0-34 & 50-207/B0-30 on B0/215-18 & 810109-08 & notice of violation MURPHY.C.E. Region 2. Atlanta: Reactor Construction & Engineering Bupport Branch 81/02/10. 2p 07983 313
- --B103240776 Notice of violation from inep on B01215-18 & B10105-09 • Region 2. Atlanta. Office of the Director 81/02/10 lp
- --8103240785 IE Insp Repts 50-269/80-39, 50-270/80-34 & 50-287/80-30 on 801215-18 & 810105-08 Noncompliance noted activities affecting quality not being accomplished per procedures release records of pipe welds.

  ECONOMOS N. Region 2. Atlanta. Refion 2. Atlanta. Office of the Director HERDT.A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/09 10pp. 07983:316.
- Bi03310913 Responds to IE Builetin BI-Oi, "Surveillance of Mechanical Snubbers." No INC snubbers identified in bulletin are in use at facility. Unit 3 inaccessible mechanical snubber insp completed Bi020, All snubbers were clean.
  PARKER, M. D. Duke Power Co. B1/03/20. 1p. 08058.147.
- R Periodic operating reports & related correspondence
- 8103090278 Forwards "Semiannual Effluent Release Rept. Jul-Dec 1980 " PARKER. W. O Duke Power Co 81/02/27 ip. 07850 322.
- --8103090285 "Bemiannual Effluent Release Rept. Jul-Dec 1980."

  8 Dute Power Co. 81/02/19 5pp 07850.323.

- DOCKET 90-270 OCCURE MUCLEAR STATION, URIT 2

  F. Security, medical, energency & five protection plans
- 8103120643 Ack receipt of BOILLY ltr te change to security plan Concurs w/change contained in encl Encl withheld (ref 100FR2 790) REID-R U. Operating Reactors Branch 4 81/03/04 2pp 07906 I32
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding "UREG-06%". "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements U/o encl programments U/o enc
- 8103160181 Releases public version of implementing procedures for energency plant FELTON JM Division of Rules and Records 81/03/12 1p 07806-001
- --8103160189 Forwards public version of implementing procedures for e-ergercy plan parker.u G. Oute Power Co. 81/03/02 ip 07896-001

- 8103261212 Requests that encil emergency planning sinfo be placed in LPDR M/o 8103160169. SQUEER-J.L. Division of Rules and Records 81/03/24 ip 05040-247

#### 1 Financial information

- 9103310549 Forwards Annual Financial Rept 1980 annual certified financial statements. 1981-83 financial forecast & util statement re available funds to satisfy liability Info guarantees retrospective preniums per 100FR140 26. THIES.A.C. Dute Power Co. 84703/24 12 06075 100
- --Bi03310638 Annual Financial Rept 1980, including financial statements. 1981-83 financial forecast & statement re sources of available funds to satisfy liability. HORM: C. LEE-M.S. Duke Power Co. B3/02/13 Sipp. 08075:101
- P Operating license stage documents & correspondence
- 8010230589 Summary of 600821 meeting u/8&U reactor owners group reabnormal transient operating guidelines program. VISBNO-0 Operating Reactors Branch 4 80/09/30 29ep 06787:236
- BiO3190732 Lite to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-O612 Forwards NRC position re-interim actions & request for add1 infd CISENHUT. D O Division of Licensing. BO/12/22 30pp.
- 8:03:90387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737. ETERIMUT. & O Division of Licensing. 8(70)/19. dpp
- 8103120014 Ltr to all licensees of operating plants,CP holders & OL applicants.except Indian Point 2 & 3,Zion 1 & 2 & TMI-1, forwarding inadventently unitted pages from NRC 801222 request for add1 info re control of heavy loads EISENHUT.O 2. Division of Licensing. 81/02/03. App.
- 8103030151 Forwards request for add1 info re seisric design to complete review of standby shutdown facility
  REJD.R.M. Assistant Director for Licensing. 81702709, 4pp. 07825-170

- 8103030893 Forwards Amends 93.93 & 90 to Licenses DPR-38.0PR-47 & PPR-59.respectively, safety evaluation & notice of issuance & availability PFID.R W Decating Reactors Branch 4 81/02/10 2pp 07000 347
  - PEID,R W. Departing Reactors Branch 4 B1/02/10 2pp 07()00 34
- --BIOJOBCB99 Arends 93.93 % 90 to Licenses DPR-38.DPR-47 & DPR-55, respectively, revising Tach Specs to support operation at unit 3 at full rated power Juring Cycle 6 REID.R & Operating Reactors Branch 4 BI/02/10 28pp 07800-350.
- --Bi03030314 Safety evaluation supporting Amends 93.93 & 90 to Liceress DPR-33.DPR-47 & DPR-55.respectively.

   Office of Nuclear Reactor Regulation, Director B1/02/10. 96:
- --Bi03020923 Notice of issuance & availability of Amends 93.93 & 90 to Licenses DPR-38. DPR-47 & DPF-55 respectively REIO.R.M. Operating Reactors Branch 4 Bi/02/10. 2pp 07801-025
- B103330160 Ltr to all operating PMR licensees requesting info on auriliars, feedwater sys seismic design Forwards request for addition. List of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISEN-UT.D O Division of Licensing 01/02/10. 13pp
- 0103140069 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of embrgoncy support facilities Requests confirmation within 45 days that implementation dates will be mot EISENHUT, 0 0 Division of Licensing. 81/02/18 12pp.
- B103090018 Advises of review of util 801208 response to NRC 800701 ltr requesting info on fuel assembly holddown spring failures Requests commitment to perform surveillance testing on holddown springs in fore during heat refueling butage REID, R.W. Operating Reactors Branch 4. 81/02/20. 2pp. 07049 272.
- 8103250024 Ltr to all power reactor licensees & license applicants re INREC-0519 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISENMUT.D 0 Division of Licensing, 81/02/20 App.
- 8103090699 Generic ltr to all B&W licensess re capability of small break LDCA model to predict small break behavior. Post-test evaluations of L-4-1 & S-07-i0D predictions requested for submittal by 310401 REID, R.W. Operating Reactors Branch 4. 81/02/24. 3pp.
- B103110784 Forwards request for additinfo he util 791221 & 800723 responses to recommendations contained in BAH-1964. "Integrated Control Sys Reliability Analysis "Analysis of consequences of stuck open turbine bypass valve is required REID.R M. Operating Reactors Branch 4. B1/02/25. Spp. 07077 720
- Bi03230030 Ltr to all licenses of operating nuclear power plants to applicants for DLs (except 8t Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event t. promptly implement emergency procedures. EIBENHOT.D.Q. Division of Licensing. Bi/02/25. Spp.
- 8103120862 Forwards 810109 request for add1 info re B&W 177 fuel assembly owners group submitted on asymmetric LOCA loading Response requested within 60 days. REID.R W. Operating Reactors Brench 4 81/02/26. 2pp. 07904:001
- 8103230813 Generic Ltr B1-06 to all CP holders to OL applicants ro 16CF630 71(e). "Periodic Updating of FSARs." effective B00722 Info re FBAR legal status.format & content encl. Ef8ENHUT.D.O Division of Licensing. 81/02/26. 10pp.
- 8103120229 Ack receipt of 800211 response to 790821 info request to Bi reactor owners group. Requirements of IMI Action Plan Item II K. 2-19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flou." fulfills request. Safety evaluation encl. REID. R. M. Operating Reactors Branch 3. 81/02/27. 2pp. 07903 021
- --BI03120245 Safety evaluation relitem II.K.2.19 "Benchmark Analysis of Sequential Auxiliary Feedwater Flow" for B&W reactor plants.

  Intent of Action Item II.K.2.19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program.

  \*\* Office of Nuclear Reactor Regulation, Director. 81/02/27 2pp 07903.023
- 8103120296 Ack receipt of 800205 response to 790821 info request to 80 reactor owners. Requirements of TMI Action Plan Item
  11.K. 2.19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow." fulfills request. Before walustion encl.
  REID.R W. Operating Reactors Branch 3 81/02/27. 2pp. 07906:137

# **DOCKETED ITEMS**

- "-BIOJ12030B Safety evaluation re THI Action Plan Item II K 21 19.
  "Bench-ark Analysis of Sequential Acciding Feedwater Flow"
  for B&W plants Intent of Action Item II K 2 19 accomplished
  & results provided by CRAFT-2 similar to TRAP-2 program

   Office of Nuclear Reactor Regulation, Director. B1/02/27. 2pp.

  Oppod-139
- 9103120769 Discusses compliance w/TMI Action Plan Item II K 2 19, "Benchmark Analysis of Sequential Ausiliary Fredwater Flow." More rigorous assusament is being performed under Item II K 2, 30 Item is resolved Bafety evaluation and REIO.8.W Operating Reactors Branch 4 B1/02/27 2pp 07904 227
- D10309D193 Notification of B10402-03 meeting w/B&W owners group in Bethesde.MD to discuss responses to NRC B10109 ltr re asymmetric LOCA loadings VISBING.0 Operating Reactors Branch 4 B1/03/02 2pp 07848:341
- 6(0312024) Ack receipt of 800630 response to 790821 info request to 8&W reactor oursers group Requirements of IMI Action Plan Item II K. 2 19. "Benchmark Analysis of Bequential Auxiliary feedbater flow," fulfills request Bafety evaluation encl REID:R W Operating Reactors Branch 4. 81/03/02. App 07904 349
- --BIO3120270 Bafety evaluation re TM1 Action Plan Item 1I K 2 19.
  "Benchmark Analysis of Sequential Auxiliary Feedwater Flow "
  Intent of Action Item II K 2 19 accomplished & results
  provided by CRAFT-2 similar to IRAP-2 program

   Office of Nuclear Reactor Regulation, Director BI/03/02. 2pp
  07904 393
- 8103090640 Advises that response to request for add1 info re emergency feedwater sys will be submitted by 810403 April 1984 Dec 2000 PARKER D Duke Power Co. 81/03/03. 1p 07844:289.
- 0103110321 Advises that analyses of liquid & gaseous radwastes are performed by Teledyne Isotopes, par schedule requirements of Tech Opecs 3 9 8 & 3 10 9 satisfying Tech Opec 6 4 1 Datalied review of wonder analysis procedures unnecessary PARMERAW 0 Duke Power Co. 81/03/03 2pp. 07872-319.
- 0103170390 Forwards safety evaluation re TMI Action Plan Item II.K. 2 19. "Benchmark Analysis of Bequential Auxiliary Feedwater Flow" for BBW reactor plants Util found in compliance Wittem REID.8 W. Operating Reactors Dranch 4 81/03/04 2pp. 07925 246
- --BiO317067: Bafety evaluation re TMI Action Plan Item II.K 2.19, "Benchmark Analysis of Bequential Feedwater Flow" for D&W reactor plants.

  # Diffice of Nuclear Reactor Regulation. Director #81/03/04 2pp 07929:248
- 8103120438 Forwards proposed Tech Bases for upgrade of anticipatory reactor trip sys.
  PARKER.H. C. Duka Power Co. 81/03/05. 3pp. 07901:224
- ~-BIO3120445 Proposed Tech Spec Pages 3.5-3.3 5-4.3.5-5.4.1-7 & 4 1-8 re upgrade of anticipatory reactor trip sys 4 Byte Power Co. B1/03/04 5pp 07901-227.
- 8103160973 Notifies that existing Tech Specs re heat removel capability during all modes of operation resolved concerns re 800924 its & 800606 response to IE Bulletin 80-12, "Decay Heat Removal Sys Operability."

  810LZ, J. F. Operating Reactors Branch 4 81/03/09, 2pp. 07921, 145.
- Sg00310804 Ltr to all licensess of operating plants applicants for OLs & bolders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  ETBENKUT.D 0. Division of Licensing. B1/03/10. App.
- B103170454 Responds to NRC 810220 request for util commitment to surveillence of fuel essembly holddown springs in facility cores. Documents util plans to inspect fuel assemblies for broken holddown springs during upcoming refueling outages. PARKER.N.D. Duke Fower Ca. 81/03/12. 2pp. 07934:037.
- 8103240098 Requests remission of license amend fee in connection w/ issuence of Amends 92.92 & 98 to Licenses DPR-38.DPR-47 & DPR-53.respectively.
  DIGOS.R. License Fee Management Branch. 81/03/17, 1p. 07989-282.

- 9103240332 Forwards revised responses to Questions 4 & 11 addressed a util 801113 itr.per MRC 810316 request for addition on reload design methodology technical rept PARKER.N 0 Duke Power Co 81/03/18 3pp 0790 134
- BIO3240393 Forwards 'Evaluation of Transient Nuclear Instrumentation Power Range Flux Error,' in response to NRC 810114 ltr PARKER, H. D. Duke Power Co. 81/03/19 lp. 07990 184
- --8103240398 "Evaluation of Transient Nuclear Instrumentation Power R. Flux Error " • Dute Power Co. 81/03/19 33on 07990 185
- BIO3270704 Requests meeting U/KRC to discuss issue of mild environs per Commission 800523 mero t KRC 801024 order by 810415 Response should be received by 810401 PARKER.W D. Dute Power Co. 81/03/19 ip. C8047 119
- 8103270694 Informs that BWW owners group submitted BAW-1911P.

  "Irradiation-Induced Reduction in Charpy Upper Shelf Energy of Reactor Vesset Helds" to fulfull submittal requirements of 10CFR90. App 0

  PAPKER.W 0 Duke Power Co 81/03/23 in 08043 301
- --Bi03270693 Forwards BAK-1511P. "Irradiation-Induced Reduction in Charpy Upper Shelf Energy of Reactor Vessel Helds "Describes implementation predictive methodology to determine sec life of reactor vessels H/o encl.

  TAYLOR.J H Babcock & Wilco: Co 81/03/12 200. 08043 302
- G Inspection reports. IE Bulletins & correspondence
- 8103170103 Forwards Revision & to 90°day response to IE Bulletin 77-018. "Environ Qualification of Class IE Equipment " Revision addresses environ qualification of electrical equipment needed to achieve hot & cold shutdowns THIEB.A C Duke Power Co. 81/01/20 1600pp 08047 211
- Bi03020203 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty." No written response required.

  D'REILLY, J.P. Region 2. Atlanta. Office of the Director. 81/02/09 ip.
- BiO3030082 Suppls previous responses to IE Builetin 80-il forwards schedule for completion of masonry wall re-evaluation Parallel path program will be followed for walls which do not comply w/long-term acceptance criteria PARKER-W 0 Duke Power Co 81/02/09. 2pp. 07808 200
- 8103040167 Forwards IE Info Natice 81-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance WildCFR50 72." No written response required O'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/02/12 ip. 07813-007
- 8103160725 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required. O'REILLY-J P. Region 2. Atlanta, Office of the Director. 81/02/27 1p. 07914:110.
- 8103[6065] Forwards IE Circular Bi-03, "Inoperable Beismic Monitoring Instrumentation " No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director Bi/03/02 ip.
- BiO3120828 Ack receipt of BiO211 itr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Repts 50-270/80-27, 80-287/80-24 & 50-269/80-31.

  LEWIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. Bi/03/04. 1p. 07905.338.
- --Bi03120836 Responds to NRC 810120 ltr re violations noted in IE Heal Physics Appraisal Repts 50-270/80-27,50-287/80-24 & 50-267/80-31. Corrective actions: more sensitive probes placed at high-vol personnel traffic RCA exits. PARKER,M.O. Duke Power Co. 81/02/11. 4pp. 07905.339
- --8103120841 Forwards IE Health Physics Appraisal Repts 50-270/80-27.
  50-287/80-24 & 50-269/80-31. notice of violation & significant appraisal findings.
  O'REILLY, J. P. Region 2. Atlanta. Office of the Director 81/01/20. 4pp. 07905.343.

--B103120843 Notice of violation from health physics appraisal on

s Region 2. Atlanta, Office of the Director. 81/01/08 1p.

800908-19.

9103230644 Application to amend QLs, revising License Condition 35 to authorize completion of mode identified in Table 3.1 of NRC 35041 fire protection safety acquired in Supporting

- --BIORIZOB48 IE --maith Physics Appreisal Repts 50-270/80-27.50-287/80-24 t 50-269/80-31 Noncompliance noted failure to follow unstten procedures & to perform safety analysis prior to making changes to facility.

  HISEY.C M. Region 2. Atlanta. Diffice of the Director GIBBON.A F. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 81/01/08 29pp 07905 348
- 8103160831 Provides supplemental response to IE Bulletin E0-11.
  Masonry Hall Design " Two masonry calls in Unit I reactor
  hidg are adequate for all design loadings
  PARER. II U Cute Power to B1/03/04 2pp 07915 230
- B10317C04) Forwards revised IE Bulletin B1-01. 'Surveillance of Machanical Southers.' W/corrected Pages 9 & 6.Change in identification of facilities U/CPs to which bulletin is applicable does not affect util requirements. O'REILLY, U.P. Region 2 Atlanta, Office of the Director 81/03/04
- B103110676 Responds to NPC evaluation of B01031 Revision 5 response to 1E Bulietin 79-018 Requests further clarification of response items classified as deficient Deficiencies would not adversely affect plant operation PANKER, U.O. Duse Power Co. B103/05 30p. 07885-093
- 8J03260492 Advises that review of interim mads showed deviation from schedule in 793612 response to 1E Bulletin 79-01. "Environ Qualification of Class IE Equipment 1 NRC will be informed of new mod schedule upon receipt of replacement equipment PARKER.W Q Duke Power Co. 81/03/05 1p 06037-202
- BiD3203281 Forwards IE Info Notice Bi-06. 'Failure of ITE Model K-660 Circuit Breater' No response required G'REILLY P Region 2. Atlanta. Office of the Director 81/03/11 to 07949 016
- 8103240611 Ack receipt of 810306 ltr informing ARC of steps teken to correct violations noted in 18 lnsp Repts 50-269/80-38, 50-270/80-38 t 90-287/80-32 LEWIS.R C Region 2. Atlanta. Dffice of the Director. 81/03/11 p 07983
- --BIO3240628 Responds to NRC BIO211 ltr re violations noted in IE Insp Repts 90-269/80-38.50-270/80-35 & 50-287/80-32 Corrective actions stopped spill/decontaminated area & counseled personnel about procedures No progrietary info PARMER.N D Duke Power Co. 81/03/06. 3pp. 07983: 188
- --B103240635 Forwards IE this Repts 50-269/80-38.50-270/80-35 & 50-287/80-32 on 801201-31 & notice of violation LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/11 20p 07983:191
- --Bi03240648 IE insp Repts 50-269/80-38.50-270/80-35 & 50-287/80-32 on B01201-31 Noncompliance noted interim radiaste sys was operated u/o adequate procedure, resulting in radioactive spiil.

  CRDERB. W.T... JAPE, F. MYERS. D.O. Region 2, Atlanta, Office of the Director B1/02/11 Spp. 07983 194
- B103200013 Forwards IE Info Notice B1-05. "Degraded DC Sys at Palisades." No response required OfREILLY, J.P. Region 2. Atlanta, Office of the Birector. B1/03/13 ip.
- 8103240704 Ack receipt of 810305 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-289/80-39. 50-279/80-34 & 90-287/80-30 LEWIS.R.C. Region 2. Atlanta. Office of the Director. 81/03/18 lp. 07983 309
- --8100240712 Responds to NRC 810210 ltr re violations noted in IE Insp Repts 50-269/80-39.50-270/20#34 & 50-287/80-30 Corrective actions reinspected ref welds using proper callor & cautioned all 85M inspectors to document callor & insps. PARKERIM O. Duke Power Co. 81/03/04 3pp. 07983:310.
- ---Bi03240722 Forwards IE insp Repts 50-269/80-39,50-270/80-34 & 50-287/80-30 on 801219-18 & 810103-08 & notice of violation MURPHY-C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 81/02/10 2pp. 07983-313
- --8103240785 IE Insp Repts 50-267/80-37.50-270/80-34 & 50-287/80-30 on B01215-18 & B10105-08 Noncompliance noted:activities affecting quality not being accomplished per procedures re-exam records of pipe celds.

  ECCNOMES N Region 2. Atlanta, Diffice of the Director. HERDT A R Region 2. Atlanta, Construction & Engineering Support Brench. B1/02/09. 10pp. 07983 316.

- 8103316913 Response to IE Bulletin 81-01. "Surveillance of Mechanical Snubbers " Rc INC snubbers identified in bulletin are in use at facility Unit 3 inaccessible mechanical snubber inspeconpleted 810220 All Snubbers were clean PARKER, N.D. C. 14 Payer Co. 81/03/20 in 08038-147
- R Periodic operating reports & related correspondence
- 8103390278 Forwards "Seniannual Effluent Release Rept. Jul-Dec 1980 PARKER H D Duke Power Co 81/02/27 to 07890 322
- --8103090285 Serjannual Effluent Release Rept. Jul-Dec 1980. "
   Date Power Co. 81/02/19 Spp. 07850 323.
- DOCKET 90-271 VERMO:NT YANKEE NUCLEAR POWER STATION

  F Security, medical, emergency & fire protection plans
- 8:03030617 Notifies of change re issuance of NDAA receivers for homes in lieu of recommendations stated in Analytical Bys Engineering Corp study.per meeting w/FEMA & States of MS.VT & NH KAY.J A Vensee Atomic Electric Co 81/02/10 lp. 07794 178.
- 8:03:80264 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NPC position & request for addl info resafe shutdown capability for compliance u/B01119 fire protection rule EIEEMAUT.D 0 Division of Licensing 81/02/20 13pp
- 8103110798 Forwards request for add1 info re util 790817 guard training & qualification plan Commitments to meet requirements of NGREO-0574 must be incorporated in appropriate worksheets

  IFPGLITO.T A Operating Reactors Branch 2: 81/02/25 App. 07877.312.
- BIO3100765 Releases public version of emergency plan for facility FELTON.J M Division of Rules and Records 81/03/03. 1p 02806-001
- --8103100770 Forwards public version of draft emergency plan for facility. Includes draft States of VT & NH radiological response plans local plans for four VI cities five NH cities is seven HA cities. SMITK-R.L. Vermont Vankee Nuclear Power Corp. 81/01/02 2pp 07806 001
- ---Bi0310077B Public version of draft emergency plan for facility. Includes draft States of VT & NY radiological response plans, local plans for four VT cities. Five NH cities & seven MA cities.

   Vermont Yantee Nuclear Power Corp 81/01/02. 1000pp. 07804 001.
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0676. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements H/o encl. EISENHUT.D 0 Division of Licensing. 81/03/05. App.
- G103300475 Requests that encl emergency planning info be made conspicuously available to public Great public interest anticipated.4/o encl. SOUDER: J L. Division of Rules and Records 91/03/17. [p. 08038:126
- 8103200212 Provides info re-compliance w/revised 10CFR30.48 & naw App R to 10CFR30. Includes fire protection of safe shutdown capability, fire brigade & energency lighting.
  HEIDERLE H. Vermont Yankee Nuclear Power Corp. 81/03/18. 3pp. 07970.244.
- 8103310619 Notification of 810330 meeting w/util in Bethesda.MD to discuse post-TMI requirements for emergency operations facility.

  ROONEY, V. L. Operating Reactors Branch 2 81/03/25, 2pp. 08041:028.

### H General correspondence

8103110117 Responds to ltr re comment on reported shipment of low level waste w/tapad-over hole in side of drum Package had sadied inner liner.No leakage or loss of conteinment took place. DO 80-36 re facility encl. W/o encl. STELLO.V. Director's Office. Office of Inspection and Enforcement. 81/02/27. 2pp. 07084:309

- --2103110124 Requests order % indepth investigation into allegations of unsafe maint practices % sloppy handling of wastes PRIESI.N Affiliation Unknown 91/01/31 1p 07884 311.
- 8103110739 Responds to recent litr re reported shipment of low level waste drum w/tapad-over hole on side Since sealed inner liner provided to leakage or containment loss occurred no violation of NRC packaging requirements took place STELLO.V Office of Inspection & Enforcement. Office of the Director 81/02/27 2pp 07073 334
- B103181019 Responds to B00216 ltr requesting full public investigation of safety violations & repair costs for facility Encl Decision DD 80-36 addresses similar concerns W/a encl STELLD-V Director's Office. Office of Inspection and Enforcement B1/03/12 2pp. 07954 162
- --BIO3181025 Requests full public investigation of safety violations & repair costs at facility MARAONITZ, P. M. Affiliation Unknown BO/02/16 1p 07954 164
- 8103181032 Responds to ltr requesting full public investigation of safety violations & repair costs for facility Encl Decision DD 80-36 addresses similar concerns W/o encl STELLD.V Director's Office. Office of Inspection and Enforcement. B1/03/12 2pp. 07934-160
- --BiggiBigg Requests full public investigation of safety violations at facility HOVE.8 Affiliation Unknown Bi/03/12 is
- B1031B1042 Responds to 810209 ltr requesting full public investigation of safety violations & repair costs for facility Encl. Decision DD 80-36 addresses similar concerns W/o encl. STELLO.V Director's Office. Office of Inspection and Enforcement 81/03/12 2pp 07954 108
- --81031B1091 Requests full public investigation of safety violations & repeir costs at facility.
  HMMPARY,M J Affiliation Unknown B1/02/09. 1p. 07994:110
- 8)03)81059 Responds to 1tr requesting full public investigation of sefety violations & repair costs for facility Encl Decision DD 80-36 addresses similar concerns U/o encl. STELLOV. Director's Office. Office of Inspection and Enforcement 81/03/12 2pp 07954-137
- J. Insurance & indemnity information
- B103130389 Forwards Endorsement & to NELIA Binder EB-32 & MAELU Binder XB-32
  CAREY.H.H. Vermont Yankee Nuclear Power Corp. B1/03/09 4pp
- Bj033i0471 Forwards Endorsement 7 to NELIA Binder EB-32, Endorsement 56 to NELIA Policy NF-189 & Endorsement 45 to MAELU Policy NF-56.
  CAREY, M W Vermant Yenkee Nuclear Power Corp. Bi/03/25 &pp. 08059:287
- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position re interim actions & request for addl info. ELEENMUT.D.O Division of Licensing. 80/12/22. 30pp.
- 8103190387 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737.
  EIBENHUTD, O. Division of Licensing 8101/19. 6pp.
- B103240270 Ltr to all BWR licensess forwarding Suppl 1 to generic safety evaluation on BWR scram discharge sys Summaritas re-exclusion of interim measures recommended per 801201 safety evaluation.
  EISENEUT.D.Q. Division of Licensing. 81/01/23 2pp
- BIO3120014 Ltr to all licensess of operating plants, CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC BO1222 request for add] info re control of heavy loads.

  EISENHUT.D. Q. Division of Licensing. 81/02/03. 6pp.

- 8103160369 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 12 re upgrade of emergency support factlities Requests confirmation within 45 days that implementation dates will be ret EISENHUT.D G Division of Licensing 81/02/18 12pp
- 8103110412 Forwards 'Portial Review Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for VT Yankee Atomic Power Co. VT Yankee Atomic Power Station 'Unitten response requested NDVAK.T M Assistant Director for Operating Reactors 81/02/20.
- --8103110416 'Partial Review Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for VI Yankee Atomic Power Co, VI Yankee Atomic Power Station " \* Office of Nuclear Reactor Regulation, Director \$11/02/20 23pp. 07884 072
- 8103250024 Ltr to all power reactor licensees & license applicents re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subcrit analysis to justify use of existing low flow controller EISEMHUTD 9 Division of Licenseins 81/02/20 Ros
- 8103030777 Forwards minutes of 810128~29 meeting w/NRC re BuR reload licensing methods BMITH,R L Vermont Yankee Nuclear Power Corp 81/02/25 5pp 03708 004
- 8103230030 Ltr to all licensees of operating nuclear power glants & applicants for OLs (except St Lucie Units 1 % 2) Requests util review to determine capability to mitigate station blackout event & promptly (mplement emergency procedures EIBENHUT.D 0. Division of Licensing 81702/29 Spp
- BIO3110BIB Confirms BIO302-06 engineering analysis for purpose of identifying vital equipment at site NRC contractors require access to both facility info & areas.

  IPPOCITO A Operating Reactors Branch 2. BI/02/26 3pp 02/3/A 359
- 8103170225 Ltr to all BMR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends & fitting math per guidelines of encl Revision 1 to NUREO-0313 Model Teth Specs only encl EISECHHUI.D 9. Division of Licensing. 81/02/26 3pp.
- --8103170266 Model Tech Space Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ASME Code Class 1,2 & 3 components & RCS operational leakage limiting conditions for aperation & surveillance requirements. \* Operal Flettric Co 81/02/26 4pp
- B103110024 Forwards safety evaluation supporting reactor bidg crane mods re-shipping cash lifting device per B10211 ltr IPPOLITO.T A. Operating Reactors Branch 2 B1/03/02 3pp 07885-007.
- --8103110028 Safety evaluation supporting reactor bldg crane mods re shipping cask lifting device to be used w/CN9 4-45 cask. \*\* Diffice of Nuclear Reactor Regulation, Director 81/03/02 2pp 07885-010
- 8103130079 Confirms agreements reached in 810220 telcon re NRC 810109 order for BWR scree discharge sys Needed equipment procurement will be expedited. Pressure setpoint 5 time delay for turbine antimotoring will be changed IPPOLITO.T. A Operating Reactors Branch 2 81/03/02 3pp. 07912-014
- 8103190206 Forwards Amend 63 to License DPR-2B, eafety evaluation & notice of issuance & availability. IPPOLITO, T.A. Operating Reactors Branch 2 81/03/02. 3pp. 07965-048
- --8103190216 Amend 63 to License DPR-28, incorporating TMI-2 lessons learned Category A requirements re valve position indication, containment isolation, iodine monitaring & emergency power supply/inadequate core cooling. IPPDLITD.T.A. Operating Reactors Branch 2 81/03/02. iOpp. 07965.051.
- --Bi03190232 Safety evaluation supporting Amend 63 to License DPR-28 • Office of Nuclear Reactor Regulation, Director. B1/03/02 4pp 07945.041.
- --B103190247 Notice of issuance & availability of Amend 63 to License DPR-2B.
  IPPOLITO, T A. Operating Reactors Branch 2 81/03/02. 2pp 07965:065.

- 81/33180265 For arise request for addl info re-containment purging during normal plant operation info requested within 45 days IMPCLITOLT A Operating Reactors Branch 2. 81/03/03 5pp 07/944 060
- 8103100341 Discusses preliminary results of NRC review of environ qualification of safety-related electrical equipment Based on evaluation of identified deficiences contained in 810220 ltr.-safe operation is assured FETER.L.H. Vermont Yankee Nuclear Power Corp. 81/03/04 1p. 07067-072
- B103120799 Requests that 801014 & B10127 commitments re GHR scram discharge sys be modified to comply L/821231 mod completion date & diverse instrumention design criterion Revised Tech Specs may be required prion to operation L/modified sys. [PP0\_ITO.F A. Operating Peactors Granch 2 81/03/06 3pp 02905 010
- --BIO3130359 Operational QA program Revision 9, re-duties & responsibilities of personnel Involved in establishing & executing operational QA program MARTIN, R. L., PIAE, D. B., MODOY, D. E., Yankee Atomic Electric Co. B1/03/99 433p 07907:105
- 9103160568 Provides add1 clarification re-constituents to Iters II N 3 3.11 N 3 30.711 A 2.111 D 3 4 & I.A 1 3(1). Plant procedures now include prompt & annual reporting requirements SMITH.R L. Vermont Yankee Nuclear Power Corp. 81/03/10. 2pp. 07917-146
- 8100310804 Ltr to all licensess of operating plants applicants for DLs & holders of CPs forwarding SECY-81-119 rs info necessary to establish snyiron qualification of safety-related electrical equipment. EISEMENT, D. G. Division of Licensing. 81/03/10 App.
- 0103199373 Requests submittal of review fee for proposed change to Reload 7. submitted 830819. MILLER.W Q License Fee Hanagement Branch 81/03/11 ip 07965 119
- 8103190166 Forwards Amend 64 to License DPR-28 safety evaluation to motice of issuance & availability. IPPOLITO, T. A. Operating Reactors Branch 2 BI/03/II 1p
- --8103190172 Amend 64 to License DPR-28, changing Tech Specs to permit performance of stability & recirculation pump trip tests permittl 1810212 submittal pPPOLITO, F. A. Operating Reactors Branch 2 81/03/11. 2100
- --BiO3190175 Safety evaluation supporting Amend 64 to License OPR-28 • Office of Nuclear Reactor Regulation, Director. 81/03/11. 7pp
- --G103190181 Natice of issuance & availability of Amend 64 to License DPR-28 IPPDLITO, T.A. Operating Reactors Branch 2. 81/03/11 2pp.
- 8103270099 Burnary of 810304 meeting w/Hart I owners group & 9E in Bethesda.HD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREO-0561 Slide presentation & list of attendees encl. GRIMEB.C I Licensing Branch 3 81/03/16 Spp
- B103230462 Requests exemption from requirements of Item 3.2 4 of 601124 1tr per 10CR50 48 to allow continued operation in present mode. Licensee not required to maintain inerted containment atmosphere MRSGLAIS.L.D. Vermont Yankee Nuclear Power Corp. 81/03/17 2pp. 07977. 272
- 8103310206 Forwards YAEC-1238. "Methods for Analysis of BURs Steady State Core Physics," describing methods to be used to perform safety evaluation of Reload B at facility. SMITH-R.L. Vermont Yankes Nuclear Power Corp. 81/03/26. Ip 08060-236.
- ~-8103310214 "Methods for Analysis of BWRs Steady State Core Physics " VERPLANCK,D M., P\$LAT,E E., GLIFER,B,C. Yantee Atomic Electric Co. YAEC-1298 81/03/24 137pp. 08060:237.

- Q Inspection reports. IE Bulletine % correspondence
- 0103040345 Forwards 1E Insp Rept 90-271/80-18 on 801202-04 No rancompliance noted CARLSON.R T Region 1, Philedelphia. Reactor Construction & Engineering Bupport Granch 80/12/31 2pp 07820 141.
- --8103040355 IE Insp Rept 50-271/80-18 on 801202-04 No noncompliance noted Hajor areas inspected fire barrier panetration mode & fire areas in electrical penetration seals MOLTAY.P. EDITETER. 50 Region 1. Philadelphia. Reactor Construction & Engineering Eupport Branch 80/12/30 3pp
- 8103100229 Responds to IE Bulletin 80-17. Suppl 4. "Failure of Control Rods to Insert During Screm at BMR." Sys consists of sensor, transmitter-lain unit 5 remote 6 local indicators Sensing cevice is capacitance probe (EIDER.L H. Vermont Yankee Nuclear Power Corp. 81/01/30 8pg 07863 215
- B103180092 Forwards IE Insp Rept 80-271/81-01 on 810103-05 No moncompliance noted CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 81/01/30 2pp. 07943.316
- --Bi03160098 IE Insp Rept 50-271/81-01 on Bi0103-09 No noncompliance noted Major areas inspected; cause of failure of portion of piping connecting waterbox of last regenerative heat exchanger to first honoregenerative heat exchanger REYNOLDS.S D Region 1. Philadelphia, Office of the Director. IRPP.L E Region 1. Philadelphia, Reactor Construction & Engineering Support Brench. Bi/01/26 7pp. 07945-318
- B10323086: Responds to IE Bulletin B1-01. "Surveillance of Mechanical Snubbers " No such snubbers used or planned for use at facility CONNAY, W.F. Vermont Yankee Nuclear Power Corp. B1/02/10 ip 07977-061
- 8103040223 Forwards IE Info Notice Bi-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/10CFR50 72" No written response required CRIER.B H. Region I. Philadelphia. Office of the Director. Bi/02/12. Ip 07813 189
- 8103190846 Act receipt of B10130 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/80-15 BRUNNER.E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 61/02/12 ip 07964
- --BIO3190855 Responds to NRC 810108 ltr re violations noted in IE Insp Rept 50-271/80-15 Corrective actions high radiation area barricaded & posted & scram discharge headers hydrolyzed to reduce dose rates CONHAY.W.F. Vercont Yankes Nuclear Power Corp. B1/01/30. 2pp 07964-275.
- --8103190863 Forwards IE Insp Rept 50-271/80-15 on 800915-1017 & notic of violation BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 81/01/08. 2pp. 07964.277.
- --B103190B70 Notice of violation from insp on B00915-1017.

   Region I. Philadelphia. Office of the Director. B0/12/04. Ip 07954:279
- --8103190879 IE Incp Rept 90-271/80-15 on 800919-1017. Noncompliance noted failure to barricade & post area as a high radiation area.

  COLLINS. S. J. FOLEY: T. F. SABBANI. A. Region 1. Philadelphia. Office of the Director. 80/12/04 29pp. 07944:280.
- 8103030%3 Forwards Suppl 5 to 1E Builetin 80-17, "Failure of Control Rods to Insert During Stram at BMR." No written response raquired. GRIER, B H Region 1, Philadelphia, Office of the Director. BI/02/13 1p 07790 309
- Bi03200195 Forwards IE Info Notice Bi-04. "Cracking in Main Steam Lines " No response required GRIER. B.H. Region I. Philadelphia, Office of the Director. Bi/02/27. 1p 07972-036.
- 8100200163 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation." No written response required. GRIER, B.H. Region 1, Philadelphia, Défice of the Director. 81/03/02 1p. 07971: 361.

- 6103207034 Forwards revised IE Bulletin 81-01. 'Burveillance of Mechanical Shubbers." W/corrected Pages 3 & 6 Change in igentification of facilities W/P to which bulletin is applicable does not affect util requirements SRIER.B.H Region 1. Philadelphia, Office of the Oirector B1/03/04 to 07968 198
- 8103130363 Fulfills 801023 commitment to advise NRC of fuel insp program for 1981 refueling outage OE formal recommendation will be delayed for several months fuel insp plans with be available 60 days prior to Oct 1981 refueling outage SMITHER L Vermont Yankse Nuclear Power Corp. 81/03/06 1p 07707:149
- 9103200282 Forwards IE Info Notice 81-06. "Failure of ITE Hodel K-600 Circuit Brealer" No response required ORIER.B H Region I. Philadelphia. Office of the Director 81/03/11 p 07969 019
- R. Periodic operating reports & related correspondence
- 8:03170555 Forwards "Effluent & Waste Disposal Bemiannual Rept Smith R L Vermont Yantee Nuclear Power Core 81/03/10 in
- --BIO3170561 "Effluent & Waste Disposal Semiennual Rept.Radiological Impact on Man for Jul-Dec 1780." « Vermont Vankee Nuclear Power Corp. 81/03/10. 93pp
- 8103300319 Forwards "Annual Operating Rept for 1981" SMITH R L Vermont Yankee Nuclear Power Corp 81/03/23 1p 00057-156
- --8103300324 'Annual Operating Rept for 1981 "
   Vermont Yankee Nuclear Power Corp. 81/03/23 9pp 08057:157
- S Recortable occurrences, LERs & related correspondence
- 8103030851 Forwards LER 81-006/03L-0 MURPHY. W P Vermont Yankee Nuclear Power Corp 81/02/25 1p 07798.011.
- -- B103030896 LER 81-006/03L-0: on B10127, ATMB/recirculation pump trip high pressure trip points from PT-2-3-568m, 56Cm & 560m tripped
  - above Tech Spec level during surveillance testing per operation procedure 4342 Caused by instrument drift. MURRHY, H P Vermont Yanke Nuclear Power Corp 81/02/25 ip 07798 012
- B103090548 Forwards LER 81-007/03L-0 HURPHY, W.P. Vermont Yankee Nuclear Power Corp. 81/03/04 1p. 07849-256
- 8103240530 Ferwards LER 81-008/03L-0 MURPHY. R. P. Vermont Yenkee Nuclear Power Corp. 81/03/20 1p.
- --B103240532 LER 81-008/03L-0: on B10218, reactor core isolation tooling pump tripped. Caused by electrical cable connector detaching from EGR. Connector replaced. MURPHY, N. P. Vermont Yankee Nuclear Power Corp 81/03/20. 1p. 07984 344
- DOCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans Bi01070330 Releases public version of util emergency plan FELTON-J M. Division of Rules and Records. 80/12/01. 1p
- --8101220627 Forwards public version of emergency plan. LISR1221,F.P. Public Service Electric & Gas Co. of New Jersey. 80/07/17. ip. 06171:299
- --Bi01070333 Public version of emergency plan.
   Public Bervice Electric & Oas Co. of New Jersey. B0/07/12, 330pp. 07401:229

B103050336 Releases public version of emergency plan for facility. FELTON, J. N. Division of Rules and Records. 81/02/17. ip.

8103020140 Approvas proposal to suppl five-man fire brigade w/addl member until all brigade members receive full training or unt (1 B10131 VAROA, S. A. Operating Reactors Branch 1. 81/01/23. 2pp. 07784:345.

- --Diggooglaf Forwards public version of revised emergency plan.in response to NRC request for addl info MITTL.R L. Public Service Electric & Gas Co. of New Jersey Bi/O1/30 4pp 07806-001
- --B10305035! Public version of revised energenty plan Public Service Electric & Qas Co of New Jersey BI/01/30
- 8103180264 Ltr to all power reactor licensees u/plants licensed prior to 790101. Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 fire protection rule EISENHUT, D.O. Division of Licensina B1/02/20 13an
- 8103100080 Requests that ench emergency planning info be made publicly available U/o 8102130532 SQUDER, J.L. Division of Rules and Records. 81/02/27 1p 07653.169
- 8103100083 Requests that encl emergency planning info be made publicly avaliable U/o 8102130064 SQUDER.J L Division of Rules and Records \$1/02/27. Ip 07853 170
- 8103160264 Ack receipt of 800323 ltr transmitting mode to util security plan Comments & review guideline withheld (ref 100FRR 790) Orants extension until 810316 to provide add1 info on guard training program
  VARGA, B.A. Querating Reactors Branch 1 Bi/03/03. ip 07921 252
- B10331033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements 11/0 enc1. EIBENHUT.D.O. Division of Licensing. 81/03/09. App.
- 8103261099 Forwards emergency planning info for placement in LPDR W/o 8103050344. SOUDER, J. L. Division of Rules and Records. @1/03/11 1p
- BiO317027i Forwards Submittal 2 of security training & qualification plan. Plan withheld fref 10CFR2 790)
  UDERITZ.R.A. Public Service Electric & Oas Co. of New Jersey
  01/03/13. ip 07939:213.
- Bi03240604 Discusses evaluation of 801031 fire test rept. "Cable Tray Fire Test 3M Fire Barrier Gys " Bys exhibits equivalent or better characteristics than Kaowool & can provide acceptable fire barrier for cable trays & cables TEDESCO.R. L. Assistant Director for Licensing 81/03/18 2pp 07000-100
- 8103230713 Bubmits info me fire protection program backfit iten compliance w/10CFR30, App R.
  M17TL/R.L. Public Bervice Electric & Das Co. of New Jersey.
  B1/03/19 ipp. 07977-344
- 8103310351 Forwards revised pages for escurity training & qualification plan Encl withheld tref 1005R2 7901 UDERITZ:R A. Public Bervice Electric & Oas Co. of New Jersey 81/03/24. ip. 08079 150
- G Adjudicatory correspondence

08040 270

- 8103050699 Forwards util 810224 ltr to NRC noting minor editorial errors & providing clarification re procedural steps for spent fuel rack replacement per safety evaluation suppl in support of OL Amend 33. Related correspondence. WETTERHAHN.N.J. Conner, Moore & Corber. 81/02/26 2pp. 07827: 293.
- --8103050698 Discusses minor editorial errors & provides clarification procedural steps in safety evaluation suppl in support of Amend 33 Related correspondence. MITTL-R.t.. Public Service Electric & Oas Co. of New Jersey B1/02/24. 3pp. 07829: 295.
- 8103030573 Brief opposing Lower Allens Creek Township 801104 exceptions & AC & EC Coleman B01111 exceptions. ABLB 801024 decision should be affirmed MODRE, J.E. Hearing Branch 2. 81/02/27 65pp. 07793:236.
- --8103030577 Notice of finality of Commission action w/regard to final generic FES on handling & storage of spent light water power reactor fuel (NUREO-0579). Certificate of Svc and CHILK.8 J Office of the Secretary of the Commission 81/02/27 CHILK 8 J Offi 4pp. 07793.301

- B1031B3617 Notice of B10430 oral argument in Bethesda.M3 on appeals of Tourship of Lower Alloways Creek & AC & EG Coleman from ASLB B01027 initial decision RISH-DP.C J. Atomic Safety and Licensing Appeal Panel B1/03/12 ic 07947 285
- 8103180638 Order scheduling 810430 order argument on aspeals of Tounship of Louer Alloways Creek 5 AC 5 EG Coleman from ASER E01027 initial decision in Bethesda.if0.

  BISHCP.C U Aconic Safety and Licensing Appeal Panel 81/03/12 20: 07947 321

## H General correspondence

- @100260691 Expresses concerning NAC fasture to expedite action on completed 2/or ready-to-operate facilities Also expresses concerning intervenor groups which receive indirect govt funding. Tallabolus action action under the second action of the second action o
- B103260819 Urges NRC to espedite full power iscensing of facilities to restart of TM1-1. Concern for safety & careful review of licensing process has gone beyond reascrable caution TALIMAD1. J W. Affiliation Unknown 81/03/21 1p 08037.346

## ) Financial information

- 8103170584 Forwards Annual Financial Rept 1980 BRADLEY, E. J. Philadelphia Electric Co. 81/03/13 7pp
- --8103170596 Annual Financial Rept 1980

   Public Service Efectric & Cas Co of New Jersey 81/02/16
  5200
- --B103170515 Annual Firancial Rept 1980
   Atlantic Electric of Neu Jersey. 81/03/13. 40pp
- B103180537 Forwards Annual Financial Repts for 1960 & surrary of projected internal cash flow statement for 1981, SCHNETOZER F. W. Public Service Electric & Oas Co. of New Jersey, 81/03/13, 700.

# J. Insurance & incernity information

- G103060362 Forwards Endorsement 8 to MAELU Binder X8-60 \$ Endorsement 3 to MAELU Binder X8-72 CORREA-M A Marsh & McLennon-Inc. . M & M Nuclear Consultants.Inc 01v 81/01/27, 5pp. 07840 233
- 8103060515 Forwards Endorserent 43 to NELIA Policy NF-230, CORREA.M A. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. DIV 81/02/23 29p. 07836-228
- B103090807 Forwards Endorsements & % 4 to NEL1A Binders EB-80 & EB-72, respectively CORREAM A. Public Service Electric & Gas Co. of New Jersey B1/02/27 3pp. 07844 151.
- B103110712 Forwards Endorsement & to MAELU Binder XB-&0 & Endorsement 4 to MAELU Binder XB-72 CORREA.M A. Marsh & McLennan.Inc , IS & M Nuclear Consultants.Inc DIV. 81703706 3pp 07885 128.

## P Operating license stage documents & correspondence

- BiO3110373 Informs that S-3 narrative currently used in OL issuances may have to be modified based on forwarded zero M/o encl. MIRAGLIA.F. J. Licensing Branch 3. 80/12/19. Ip 07884:143
- 8103190732 Litrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREG-O612 Forwards NRC position re interim actions & request for addl info.

  EISENHUL, D. 9 Division of Licensing. 80/12/22 30pp.
- B102270565 Notification of contract elecution Mod 2 to "Environ Monitoring Program M/Commonwealth of PA" Contractor Commonwealth of PA

  3AISDEN.L. Research Contracts Branch FIN B-5111 81/01/07 1p. 07772:351

- 8103190387 Ltr to all licensees of operating plants & applicants Dis & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737 ETSCHerf. D. 9. Division of Licensing Bi/01/19 6pp.
- 9103120014 Ltr to all licersees of operating plants CP holders & applicants except Indian Point 2 & 3,2ion i & 2 & TMI-1, for Landing inadvertently omitted pages from NRC 801222 request for addline recontrol of heavy loads EISCHMID 9. Division of Licensing 81/02/03 opp
- BIO3300160 Ltr to all operating PWR litensees requesting info on auxiliary feedwater sys seismic design Forwards request for addl info list of actions requested of licensees w/o seismically qualified sys & results of NRC validouns EISENMUT. D. 9 Division of Licensing BI/02/10 I3pp.
- BIOJO46870 Submits summany of decisions reached at 791116 meeting 791119 site visit re containment sump pump capability to operate effectively in post-LDCA recirculation mode VAROA.S A Operating Reactors Branch 1 81/02/13 4pp 0781
- 810303004 Forwards application to emend License DPR-70 % propose gac changes Trip of main Feedwater pumps starts motor driven auxiliary Feedwater pumps only UDERITZ. R A Public Service Electric & Oas Co of New Jersey BI/02/17 2pr 07790:181
- --BIO303000Y Application to amend Literse CPR-70-changing Tech 9; reflect NUREO-0578 re TMI-1 Lessons Learned Category A items BCHNEIDER:F W Public Bervice Electric & Gas Co. of New Jers 81/02/17 App 07790 183
- --8103030012 Proposed Section 3 Tech Spec changes for facility.Li conditions encl • Public Bervice Electric & Gas Co of New Jersey B1/02/17 37cm 07790 187
- B:0316C669 Lir to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A.1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met.
  EIBERHUIT D.O. Division of Licensing 81/02/18. 12pp.
- BIO3250324 Ltr to all power reactor licensees & license applicant NAREO-Cal? criteria.Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISEGAUT, D. O. Divesion of Licensing. BI/02/20. App
- B103060439 Requests addl payment re 801120 application for organizational changes to Tech Spece. Class III fee required for Unit I MILLER. U.O. License Fee Hanagement Branch. 81/02/23 1p 07835 249.
- 810311022: Forwards "Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for Public Svc Electric & Oas Co. Balen Unit L." partial review. Written response required. NDVAK. T.M. Assistant Director for Operating Reactors. 81/02/53p. 07884 165.
- --8103110227 'Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for Public Svc Gas & Electric Co.Salam Unit 1." • Office of Nuclear Reactor Regulation. Director 81/02/23 25pp. 07884:165
- BiO3110785 Notifies that util 791029 response to inadvertent safe injection during surveillance testing adequately addresses NRC concerns Matter is resolved. VAROA, 8 A Operating Reactors Branch I 81/02/24. 2pp. 0787
- BIO3230030 Ltr to all littensees of operating nuclear power plants applicants for QLs (except St Lucie Units 1 & 2). Requests util review to determine capability to mitigate station blactout event & promptly implement emergency procedures. SISENRUT. D. 9 Division of Licensing 01/02/25. Spp.
- B103050695 Forwards util B10224 ltr to NRC noting minor editorial errors & providing clarification re-procedural steps for spent fuel rack replacement per safety evaluation suppl in support of CL Amend 33 Related correspondence METTERHAHN.M J. Conner. Moore & Corber. 81/02/26. 2pp. 0782
- --910309069B Discusses hinor editorial errors & provides clarific procedural steps in safety evaluation suppl in support of Arend 33 Related correspondence.
  HITTL.R.L. Public Service Electric & Gas Co. of New Jersey.
  B1002/24. 3pp. 07027:295

- B103170136 'Inservice Testing Program Balen Nuclear Generating Station. Unit 1.' safety evaluation for 790501-801201. FEHRINDER J M . ROCKPOLD H C E060 Idaro. Inc FIN A-6258 B103170136 B1/02728 60pp 07937.039
- 8103050208 Forwards measured leakage rates for sys outside containment likely to contain radioactive matl. in response to NRE6-0578 . Item 2. 1 6 a. MITTL R L Public Service Bi/03/02 3pp 07027 041 Public Service Electric & Gas Co. of New Jersen
- 8103110379 Responds to NRC 810223 list of deficiencies to environ
- 103110379 Responds to NAC BIO223 list of deficiencies re environ qualification of safety-related electrical equipment Review of equipment performed per NUREO-0988 & 16 Bulletin 79-018 Facility can continue to operate in safe manner. SCHNEIDER: F W Public Service Electric & Gas Co of New Jersey 81/03/06 2pp 07872.309
- 8103160468 Forwards add1 amend fee to cover fee discrepancy caused by reclassification of amends per NRC 810220 1tr 8CHNEIDER F. H. Public Service Electric & Oas Co. of New Jersey. 81/03/06 1p 07917 359.
- --8103160471 Describes procedures for processing Itra w/checks received directly by License Fee Mgt Branch
- DIGOS.R License Fee Management Branch 81/03/13 1p 07917-360
- 8103250307 Forwards Amend 34 to License DPR-70, safety evaluation & VARIAN. A Deprating Reactors Branch I BI/03/06 3mp 07995 290
  - -810325031| Amend 34 to License DPR-70, revising radiological Tech Specs to incorporate new requirements re reactor decay heat
- removal capability
  VAROA-B A Operating Reactors Branch 1 81/03/06 15pp 07995 203 --8103250316 Bafety evaluation supporting Amend 34 to License DPR-70
- Office of Nuclear Reactor Regulation, Director 81/03/05 3pp 07793 308 --B103250318 Notice of Issuance & availability of Amend 34 to License VARDA, B A Operating Reactors Branch 1 81/03/06 2pp.
- 07995-311 8103250424 Advises of review of deficiencies identified in NRC 810223 ttr. Fully qualified replacement equipment will be installed by 820500 per 801024 order for mod of license re environ qualification of safety-related electrical equipment
- SCHNEIDER, F. W. Public Borvice Electric & Cas Co. of New Jerson 81/03/06 ŧρ. BiO3i60519 Forwards application for amend of License DPR-70 consisting of proposed changes to App A Tech Riecs to containment cooling sys fan coil units. Class III amend fees encl UDERITZ.R A Public Service Riectric & Qas Co of New Jersey.

B1/03/09. 1p 07915.155

- --Big3160525 Application for amend to License BPR-70 consisting of proposed changes to App A Tech Space re containment cooling sys fen coll units BCHNCIDER.F.M. Public Bervice Electric & Gas Co. of New Jersey. 81/03/09. 3pp. 07915:155
- --8103160531 Proposed changes to App A Tech Specs 3 6.2 3 & 4.6 2 3 re containment cooling sys \* Public Service Electric & Gas Co. of New Jersey. B1/03/09 200. 07915:159.
- G103310804 i.tr to all licensees of operating plants applicants for DLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment. EIBENHUT, D. G. Division of Licensing B1/03/10. App.
- 8103250626 Forwards revised Tech Spec Pages 6-5,6-6,6-10 & 6-16, implementing 801024 order for OL mod re environ qualification of safety-related electrical equipment. Changes mandated by order were not included in original issuance. VARQA, B. A. Operating Reactors Branch 1. 81/03/11 3pp 07998-341.
- --8103280632 Revised Tech Spec Pages 6-5.6-6.6-15 & 6-16.including changes mandated by 801024 order for OL mod re environ qualification of safety-related electrical equipment Operating Reactors Branch 1. 81/03/11. 4pp. 07998:344.

- 8103180564 Forwards proposed Tech Specs for implementation of degrat grid voltage design mods, in response to MRC 810119 request MITIL, R. 4. Public Service Electric & Gas Co. of New Jersey 81/03/12. 1p 07953 236
- -- 8103180568 Progosed Tech Specs Tables 3, 3-3, 3 3-4 & 4 3-2 re engin coloured required tech open laber 3.17.4 3-9 & 4 3-8 Pe i safety feature actuation sys instrumentation, trip setpoints & surveillance requirements, respectively \* Public Service Electric & Oas Co. of New Jersey - 81/03/ 07953 237
- O Inspection reports, IE Bulletins & correspondence
- HFA Relays The response required
  ORIER.B N Region 1. Philadelphia. Uffice of the Director.
  91/01/16 1p 07745 29: 81031900B5 Forwards IE Insp Repts 90-272/80-32 & 50-311/80-22 on

Bi03020137 Forwards IE Info Notice Bi-Oi, "Possible Failures of GE T

- 031106-1231. No noncompliance noted. BRUNNER, E.J. Region I. Philadelphia, Reactor Operations Mocloar Support Branch B1/01/21 2pp. 07980-324
- --8103190098 16 1040 Repts 90-272/00-32 % 50-311/80 22 on 801116 123 noncompliance noted Major areas inspected; following of licenses events & previous insplitems.comformance w/fuch
- Specs & uperating parameters & log & incord rovious
  Specs & uperating parameters & log & incord rovious
  MORRHOLM.L. J. HILL.W M. Region 1. Philadelphia. Defice of the
  Director KEIMIG.R R. Region 1. Philadelphia. Reactur Uperatin
  Nuclear Support Branch 81/01/20 17pp 07780 326
- 8103060464 Buppls 790706.0924 & 1005 responses to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Tension & shear loads on Hill bolts are loss Anchor Boils " Tension & shear loads on Hills boils are less than specified mai SCHWEIDER F W. Public Service Electric & Oss Co. of New Jersey B1/01/23 2pp 07836 000
- 6103060471 Sucata 791205 response to IE Bulletin 79-02. Revision 2.
  - 8103100636 Inmediate Action Ltr 81-03 forwarding corrections discuss in Biology teleon re violation of physical protection program, Corrections withheld tref 100FR2 790) (RIER.B.H. Region I. Philadelphia. Office of the Director Ol/Ol/20. tp. 07063-029
- 8103240736 Requests extension until 810207 to respond to Suppl 3 of IE Bulletin 79-010. "Environ Qualification of Class IE Equipment." re-equipment required to achieve & meintain cold shutdoun.
- 8103190892 Ack receipt of 801201 & 19 ltrs informing NRC of steps to correct violations noted in IE Insp Repts 50-272/80-27 & to terrect violations moved in a line of the construction to the c

SHOULDERITZ-R A. Public Service Electric & Oas Co. of New Jersey. 81/01/30 2pp 07990 022

- --B103190903 Responds to NRC 801105 ltm re-violations noted in IE in Repts 30-272/80-27 & 90-311/80-20 Corrective actions fire brigade members trained & individual designated to perform surveillance for fire barriers to identify deficiencies. SCHNEIDER F H. Public Bervice Electric & Oas Co. of New Jersey.
- SCHNEIDER F W. 80/12/01 Jpp 8103270782 Forwards JC Insp Rept 50-272/80-33 on 801208-12.No
- BRUNKER.E. J. Region t. Philadelphia, Reactor Operations Nuclear Support Branch. 81/02/04. 2pp. 08034:078
- --8103270788 IE Insp Rept 50-272/80-03 on 801208-12.No noncompliance noted. Major areas inspected administrative controls for surveillance procedures, surveillance testing & inservice insp program. CHUNO, J. W., SHAUB.E.T. Region 1, Philadelphia, Office of the Director OREENMAN.E.G. Region 1, Philadelphia, Raactor Operations Nuclear Support Branch, 81/01/30, 14pp 08034.01 14pp 0B034.0B0
- 8103240950 Forwards Revisions 2 & 3 to util response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "Requests that proprietary Westinghouse info be withheld GCHNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey. B1/02/11. 3pp 07989 118

- 8103040189 Forwards 1E Info Notice 81-03. "Crecklist for Licensees Making Motifications of Significant Events in Accordance W/10CFRSO 72." No written response required GRIER.B.H. Region 1. Philadelphia. Office of the Director B1/02/12. Ip 07813 031
- 9103040161 Discusses IE insp on 801007-09 % 14-17 & forwards notice of violation & proposed imposition of civil peralty losp examined circumstances ne 801004 personnel contamination event & 801010 personnel exposure event 5TELLO.V Director's Office Office of Inspection and Enforcement 81/02/18 30s 07820 152
- --810304018) Nutice of violation from insp on 801007-09 & 14-17 % proposed imposition of civil penalty in amount of 490.000 Items of noticongliance involve personnel entry through fuel transfer tube on 801004 \$ 801010 reactor wassel pump insp 376LLO.V Director's Office. Office of Inspection and Enforcement 81/02/16 Spp. 07820 155
- H103200199 Forwards (E Info Notice 81-04, "Cracking in Main Stean Lines." No response required GRIER, B N Region i. Philadelphia, Office of the Director 81/02/27 ip 07972 040
- 8:0320020B Forwards IE Cercular B1-03, 'Inoperable Seismic Monitoring Instrumentation " No written response required ORIER B.H Region 1, Philadelphia, Office of the Director 81/03/02 tp 07966 197
- BIO3200095 Forwards revised IE Bulletin BI-O1. Surveillance of Mechanical Shubbers." Wecorrected Pages 5 & 6 Change in identification of faculities w/CP to Union bulletin is applicable does not affect util requirements. GRIER. IH. Region 1. Philadelphia. Office of the Director Bi/03/04. 1p. 07969 047.
- B103203154 Forwards IE Info Notice 81-06. Failure of ITE Model X-600 Circuit Breaker " No response required OMIERA B H Region 1. Philadelphia. Office of the Director B1/03/11 1p 07968 292
- R Periodic operating reports & related correspondence
- E103060547 Egrwards interim "Semiannual Radioactive Effluent Release Rept," Jul-Dec 1980 surmarizing liquid & gaseous releases & solid waste shipments from facility.

  HITTLER L. Public Service Electric & Oas Co. of New Jersey 81/03/02 p. 07839 186
- --Biggonosse 'Semiannual Radioactive Effluent Release Rept," interim rept for Jul-Pec 1980 e Public Service Electric & Gas Co. of New Jersey (RERR-91, 81/03/31 47pp 07839 187
- 8103170313 Forwards monthly operating rept for Feb 1981. MIDURA,H J. Public Service Electric & Oas Co. of New Jersey 81703741. Ip.
- --Bi03170315 Conthly operating rept for Feb 1981 MILLER, L. M. Public Service Electric & Oas Co. of New Jarsey, 01/03/11 25pp
- 9 Reportable occurrences. LERs & related correspondence
- B103030772 Forwards LER B1-011/03L-0.

  UDERITZ.R.A Public Service Electric & Qas Co. of New Jersey,
  B1/02/19 ip 07791.327
- --B103030775 LER B1-011/03L-0 on B10127, svc Jater line to containment fan coil unit li found leaking Caused by leaking weld connecting spool piece to valve 119857 Weld reworked & spool piece replaced.

  BIELLE W. J. Public Service Electric & Oes Co. of New Jersey.
  B1/02/19. 2pp. 07791:32B
- 8103030678 Forwards LER 81-015/03L-0 UDERITZ-R A Public Service Electric & Gas Co of New Jersey. 81/02/26. 2pg 07791:224
- --Bi03030682 LER 81-015/03L-0: on Bi0205, rod position indicator for rod 201 indicated that rod had dropped Caused by loosely connected Amphenol screw connector on rod position indicator cable Connection secured BIEELE, W J. Public Bervice Electric & Oas Co. of New Jersey. Bi/02/26 lp. 07791:276

- \$103030762 Forwards LER 81-015/03L-0 UDERITZ.R A Public Service Electric & Gas Co. of New Jersey 81/02/24 20a 07791 323
- --BI03030767 LER B1-016/03L-O on B10207, rod position indicator for rod 2D1 indicated that rot had dropped Caused by rod position indicator cable ration loose contact at reactor head connection due to spreading of pins. Cable replaced. STECLE, U Public Service Electric & Oas Co. of New Jersey B1/02/20 2pp 07791 325
- 8103090554 Forwards LER 81-018/03L-0 LDE9172.R A Public Service Electric & Oas Co. of New Jersey. 81/02/27 2pp 07845 314
- --9103090555 LER 81-018/03u-0 on 810214, cooling water leak found on diesel generator fA Caused by cracked hipple connecting jactet water valve 10A45A 5 jactet water pipe. Nipple replaced STEELE. IJ Public Service Electric & Gas Co. of New Jersey. 81/02/27 2010 07845 317
- 8103100509 PMO-1-E1-030 on 810301 unit tripped from 100% power Caused by steam generator low level after feed pump 11 trip, because of low section pressure due to heater drain pump vibration. Shutdown extended for repairs 3 test per IE Bulletin 81-01. MORRHOUNL, KEIMIO.R. OREENMAN.E. Region 1. Philadelphia, Office of the Director 81/03/03. 2pp 07867-213
- 8103170337 PND-1-81-039 on 810311 airborne activity in auxiliary bldg increased & remained at approx 1 5 E-7 uci/milliliter. Caused by leakage from waste gas compressor small Licensee declared alort per emergency plan MORRHOLM-L., GREENMAN.E., KEIMIG.R. Region 1. Philadelphia, Office of the Director 81/03/11. 2pp. 07924 031
- B103310626 Forwards LER B1-007/01X-1 Detailed event analysis encl. UDERITZ-R A Public Service Electric & Gas Co of New Jeresy. B1/03/20 4pp 08061-031
- --8103310632 LER 81-007/01%-1 on 810119, throttling valves 148J16, 118J10
  128J138 & 138J138 found out of position Caused by procedura
  inadequacy & personnel error. Valves moved to correct
  positions & procedures changed.
  STEELE U J Public Service Electric & Gas Co. of New Jersey.
  81/03/20 1p 08041.039
- BID3310711 Forwards LER B1-019/03L-0. Detailed event analysis enci.
  UDERITZ.R A. Public Bervice Electric & Oas Co. of New Jersey
  B1/03/20 3pp. 08041-070.
- --Bi03310718 LER 8[-019/03L-0 on Bi0221.panel IRP5 for waste gas compressor showed fire alarm annunciation.but no audible alarm heard Caused by impedance mismatch created by unknown sources. Amplifier in tone generator unit adjusted.

  STEELE.U. Public Bervice Electric & Oas Co. of New Jersey.
  Bi/03/20 ip 09061 073.
- B103310724 Forwards LER B1-021/03L-0 Detailed event analysis encl. UDERITZ-R A Public Service Electric & Oas Co of New Jersey. B1/Q3/20. 209 08061:077
- --Bi00310730 LER 81-021/03L-0. on Bi0227/boric acid tanks 11 & 12 declared inoperable. Caused by loss of level indication for both tanks due to sensing lines plugged w/boric acid. Transmitter sensing lines cleaned STEELE.W J. Public Service Electric & Oas Co. of New Jersey. 81/03/20 1p. 08061-079.
- V Dperator Examinations
- 8103230401 Forwards names of personnel for reactor operator license renewal. B Connor, A Foebner & F Kaminsti have completed all espects of requalification program.

  SCHNEIDER.F. M. Public Service Electric & Gas Co of New Jersey.

  81/01/13 4pp. 07980-358.
- DOCKET 50-273 BEZNAU NUCLEAR STATION, UNIT
  P Operating license stage documents & correspondence
- 8103190145 Notification of 810316 meeting w/near-term OL applicants in Bethesda, MD relinfollogued to be submitted on environ qualification of electrical equipment prior to site visit & NRC review.

  BURNECL, S. Licensing Branch 2. 81/03/12. 15pp.

proting license stage documents & correspondence

10150 Forwards revised MRC Region 4 Organization chart.effective 127 Rill, K.V. Region 4. Dallas. Uffice of the Director - 81/02/17

spection reports. IE Bulletins & correspondence

00337 Forwards 1E Circular 81-02. "Performance of MRC-Licensed (viduals Maile on Duty " No written response required (RII.K V Region 4. Dallas. Office of the Director. 81/02/09 07966.284

1 90-275 DIABLO CANYON MUCLEAR POHER PLANT, UNIT 1
Discation/construction stage documents & correspondence

90732 Lirs to all licensees of operating plants.applicants for & helders of CPs re control of heavy loads Requests lew per guidelines in NUREG-Obl2. Forwards NRC position rerrim actions & request for addl info ENNOT.D O Division of Licensing 80/12/22 30pp

00204 Provides guidance for meeting target schedules for OL leus.Periodic mgt meetings to assure appropriate ignment of resources & prompt resolution of outstanding les recommended ISCO.R.L. Assistant Director for Licensing 81/01/14 dop

PO387 Ltr to all licensoes of operating plants & applicants for & holders of CPs re program for environ qualification safety-related electrical equipment litems addressed solve cold shuldown raplacement parts & NUREO-0737 NHOT.D O Division of Licensing 01/01/19 App

20014 Ltr to all licensess of operating plants.CP holders & D. Licants, except indian Point 2 & 3,2ion 1 & 2 & TMI-1, serding inadvertantly amitted pages from MRC 801222 sest for addl info re control of heavy loads (MBH). Bit for a ddl info re control of heavy loads (MBH).

DOBIO Responds to NHC 771005 request for add1 info re potential ins in steam generator water level measurements due to iron temp effects on level ref logs Calculations showing inred error setpoint for low-low trip function end uE.P.A. Pacific Jas & Electric Co. 81/02/19 3pp 07828 184

00024 Ltr to all power reactor licensees & license applicants re 09-0619 criteria Footnote 2 in Table 2 contains error due leakage testing deletions Licensee may submit analysis to lify use of existing low flow controller CHHUT.D O. Division of Licensing. 81/02/20 8pp

30030 Ltr to all licensees of operating nuclear power plants & licents for DLs (except St Lucie, Units 1 & 2) Requests : review to determine capability to mitigate station : teout event & promptly implement emergency procedures.
NHUT.D.G. Division of Licensing 81/02/25. 3pp

0279 Submits supplemental responses to specific action plan pirements. Includes info re RCB vents, post-accident ling capability, training for mitigating core danage, NBBB for review of test procedures & shift technical advisor. JE,P.A. Pacific Gas & Electric Co 81/02/26. 32pp. 07839.323

19813 Ceneric Ltr 81-06 to all CP holders & DL applicants ru 1850, 71(e), "Periodic Updating of FSARs," effective 122 Info ru FBAR legal status, format & content encl 1840F.D.G. Division of Licensing 81/02/26 10pp.

00273 Forwards info re potential net positive suction head lems u/RHR pump when taking suction on containment sump. IE:P.A. Pacific Gas & Electric Co. 81/03/03. Spp. 07831:309

0862 Forwards 147 mailgrams & lirs addressed to secretary inds. W/o lirs. Authors & addresses listed. kNCOURT.8. Energy, Dept. of. 81/03/03. 6pp. 08036.289.

0817 Forwards request for add1 info re Itams 260.11 through 16 delineated in 810122 OA program Review of Table 4, "Classification of Structure.8ys & Components Diablo Canyon." identified deficiencies in Itam 260.17. SCO.R L. Assistant Director for Licensing. 81/03/06. Spp. 5:021. broakwaters protecting plant intake structure Response
needed for completion of review
TEDESCO.R L. Assistant Director for Licensing Bi/03/09 Bpp
08035-310

- B103120656 Forwards Westinghouse burst 5 blockage calculations in response to IRC 791109 ltm re-fuel rod #odels used in LOCA ECCS evaluation models Current Westinghouse codels are conservative & complex w/105FR50.Aps & CRANE.P A Pacific Oas & Electric Co B1/03/10. Hep 07906-278
- 8103170942 Notifies of rept to be prepared by 810715 re adequary of safety-related masonry wells flept will address identification design review. Structural Engineering Branch design criteria. defitiencies & implementation schedule CRANE.P A Pacific Gas & Electric Co. 01/03/12 2pp 07930 129
- B103190145 Notification of ()10316 meeting w/near-term Et applicants in Bothesde.MD re into required to be submitted on environ qualification of electrical equipment prior to site visit & MSC review BVRMELL-B Licensing Branch 2 81/03/12 15pp 07945 004.
- 8103300087 Forwards add1 info requested by LAC 800827 ltr re application for OL Submittal addresses main feeduater & steam plping feeduater isolation valves FCV-441.FCV-44, penetration sleeves 5 flued head & equipment hatch CRANE.P A. Patific Gas & Electric Co. 81/03/12 53pp.
- 8)03170403 Submits responses to Questions 3 & 4 in NRC 800827 ltm restress corression creating & Cumbine missiles.

  CRANES PA Pacific Oss & Electric Co. 81/03/13 3pp. 07934 334
- 8103170619 Requests acknowledgment of receipt of Mestinghouse corments re-energency procedures which were discussed at 810311 cauting w/MRC Procedures will be consistent w/Mestinghouse ref-energency operating instructions
  CRANE.P A Pacific Oas & Electric Co. 81/03/13 2pp 07925-170
- 8103170669 Provides requested info re NUNEO-0737 Items If B 3. postaccident sampling capability. II D. 1. testing of reactor relief & safety valvos. II R 2. orders on BbH glants. II R. 3. final BbC task force suggestions & III. D. 1. sys integrity CRANE.P. A. Pacific Gas & Electric Co. 81/03/13 17pp 07929 121
- 8103200527 Responds to B10306 request for add1 info re QA/QC program requirements CRANELP A Parific Oas & Electric Co. 81/03/IB. 3pp 07972.160
- 8103230332 Forwards Suppl 1 to 'Diable Canyon Unit I Rediction Shielding Review," in response to Part II 8 2 of NUREG-0737 CRANE, P. A. Pacific Gas & Electric Co. 81/03/19 20p. 07977 109
- --Bi03230335 Buppl I to "Diable Canyon Unit I Radiation Shielding Review" \* Pacific Gas & Electric Co. Bi/03/17 13ap 07977.111
- 8103240386 Forwards response to NRC request for add1 clarification of util 810206 submittel he flow II.F.2 of NVREO-0737 concerning inadequate cora cooling CRANE, P.A. Facific 00% & Electric Co. 81/03/19. 3pg. 07987.345
- BIO3300311 Forwards status of Westinghouse review of util low power test program, power ascension procedures & emergency procedures re Task Action Plan Item 1.C 7.Reviews will be completed prior to operation above 5% full power CRANE.P.A Pacific Gas & Electric Co. 81/03/26 2pp. 08055 134
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 810320000B Forwards Suppl 12 to SER NUREO-0525, "BER Re Operation of Diablo Canyon Nuclear Power Plant, Units 1 & 2." Suppl delineates evaluation of all TMI-2 retters for operation at power levels not to exceed 5% of rated full power. MIRAGLIA, F. J. Licensing Branch 3. 81/03/04. app. 07971;029.
- BJ03230112 Forwards list of open issues for which util submitted infobut no BER input has been received. Encl 2 identifies (sause for which util must provide info & expected submittal dates, BUCKLEY.R Licensing Branch 3.
- 8103180664 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT. UNITE 1 & 2 Docket Nos. 50-275 and 50-323 (Pacific Oas and Electric Company) + Office of Nuclear Reactor Regulation, Director. NUREO-0679 812 81/03/31. 54pp Available at NITE +3.75 08024 291

- F. Security, reducat, emergency & fire protection plans
- DIDDDIODDE Litr to all licensees of operating plants & holders of CPs forwarding NUREG-OSPS. "Functional Criteria for Emergency Response Facilities." Griteria fescribe acceptable method for meeting NRC requirements M/o encl. EISERWILLD 9. Division of Licensing. BI/O3/65. 627
- @103660130 Forwards responses to MRC 810101 comments on Revision 10 of security plan Responses withheld linef 1005R2 7903 Hitsten response required CRAHE.P A Pacific Gas & Electric Co. 81/03/12 1p. 07921 134
- Bio3170463 Advises that previously subnitted state rediclogical plans do not next regulatory requirements, per NUREC-0737 Plans are still in full force & effect Revision 2 of emergency plan has been sithilited & is supplemented by 810313 its CRANE.P A Pacific Oas 7 Electric Co 61/03/12 &p 07925 244
- 8103170933 Responds to ARC 801216 request re evaluation of potential santiquate effects in emergency response plans Evaluation results will be incorporated in emergency plan prior to operation above 5% power ERAME, P.A. Pacific Oas & Electric Co. 81/03/13 ip 07930 120
- BIOD240426 Forwards info re fire protection program at facility-per Sections III 6. III J 5 III d of App R to ICCFR50 Util 4:11 intrease capacity of reactor contant gump oil collection sys 5 perform setsmic evaluation CHANE.P A Pacific Oas & Electric Co 81/03/20 3pp 07987 352
- 8103310645 Forwards discussion of site specific meteorological factors subhitted in response to NRC request for info re upgraded meteorological program for energency preparedness per criterial in NREGO-0554.App 2 ActionalEdgement requested CRAME.P A Pacific Gas & Electric Co. 81/03/27 App. 08075-202

#### G Adjudicatory correspondence

- 8103:10674 Order granting extension until 8102:3 for Commission to decide whether to review ASLAB 801233 order CHILK, S.J. Office of the Secretary of the Commission 81/02/09. 1p. 07887-093
- Bigg110371 Order granting extension until Bio220 for Complession to decide whether to review AGLAB 601230 order CHILK.S J Diffice of the Becretary of the Commission 81/02/12 bp 97686 129
- 8103120633 Order affirming ASLAS 801230 decision chastising Sovernor Brown counsel, HM Brown & LC Lampher, For conduct in praceeding Conduct was ill-considered & constituted extremely poor judgment Sanitized order encl.

  CHILK S J Defice of the Secretary of the Cormission 81/02/20 30s.
- --BIO3120637 Sanitized order denying applicant gral motion to consider whether to allow Governor Brown counsel to continue in proceeding Protective order under which facility security plan released violated No sanctions imposed.

  BISHOP.C J. Office of the Secretary of the Commission. 80/12/31
- B103050554 Joint Intervenors' interrogatories directed to util requesting info re Contentions 4,5.11.13 & 24 Certificate of Gyc encl. Related correspondence REYNOLDS-J R San Luis Obispo Mothers for Peace. REYNOLDS-J R Center for Law in the Public Interest. B1/02/23 £5pp 07629 036
- 6103050564 Joint Intervenors' interrogatories directed to NRC requesting info re Contentions 4,5.11.13 & 24 Certificate of Svc encl Related correspondence REYNOLDS.J R. San Luis Obisso Mothers for Peace. REYNOLDS.J R. Center for Law in the Public Interest 81/02/23 15pp 07829:050.
- 8103050842 Objections to ASLB 810213 prehearing conference order admitting Joint Intervenors' Contentions 4, 5, 11, 13 ± 24 Mere mention in NURGO-0737 insufficient to make issue ASLB used urong std for reopening records M/Certificate of Svc. CRAMELP A Pacific Oas & Electric Co CEMR.A G Shell & Hilmer NORTON, B Bruce Norton 81/02/23 7pp 07828-161.
- B103020400 Responds to Cormission B10220 order criticizing CA Governor Brown counsel. Order was misleading, grossly generalized & conveys felse impressions about counsel conduct. Transcripts should be publicly available & for should be sent w/order. BROWN.H H. LANPHER-L C. Calafornia. State of 81/02/26 5pp. 07702:178

- 8103130484 Responds to DS Fleischater 810219 ltr re-util rerusal to permit 8 Silver to tour facility As party to proceeding. Silver rights to tour facility are governed by NAC discovery regulations Related correspondence CRANES.P.A. Pacific Gas & Electric Co. 81/02/26 p. 07910 048
- B103030557 Response supporting NRC B10223 request for directed certification to clarify CLI-80-42 Briefs should be filed 21 days after certification & reply briefs 10 days later certificate of Svc encl REYNCLOS, J.R. Center for Law in the Public Interest. FLEIRCHAKER, D Fleischaker, D B 81/02/27 Spp 97793.210
- 6103030883 Forwards objections to ASL3 B10213 under NUREO-07:37 does not apply to licenses to load fuel 5 conduct low power tests. Requests relief from thers LLL A 1 1 5 fll A 2 requiring compliance w/App E to 1000f850 prior to fuel load FURBUSH H Pacific Gas & Electric Co. 81/02/27 2pp. 07796 219 FURBUSH H Pacific Gas & Electric Co.
- --Bi03030888 Gbjects to ASER Bi0213 order admitting Joint Intervenors' Contentions 4.5.11.13 & 24 Good cause was not demonstrated Record should only be reopened for significant new evidence that affects setision GRANE.P A Pacific Gas & Electric Co GEMR.A C. Snell & Wilmer REPTON.G Bruce Norton 81/02/25 5pp 07796 221.
- --B103030894 Forwards FEMA/NRC interior agreement on criteria for lust power testing at new commercial nuclear facilities. Public health & safety is adequately protected if facility is judated in state receiving provinus concurrence or interior of the facility is provinus concurrence. RYAN.R Federal Emergency Management Agency B1/02/27 Rpp 07776: 226
- B103130496 First set of interrogatories & requests for production of documents directed to Dovernor Brown requesting info re Contentions 4.5.11.13 & 24 & witnesses to be called Certificate of Svc encl Related correspondence CEHR.A C Pacific Oas & Electric Co. QEMR.A C Buell & Wilmer B1/02/27 1599 07913.096
- 8103130500 First set of interrogatories & requests for production of documents directed to Joint Intervenors requesting info re-Contentions 4.5.11.13 & 24 & witnesses to be called Centificate of Bvc encl Related correspondence 0249. A C Pacific Oas & Flectric Co. GEHR. A C Bnell & Wilmer. 81/02/27 1839 07913 038.
- 8103050674 Submits list of cases going to hearing during 1981 in thich emergency preparedness contentions have been raised by one or rore parties (MRISTERBOURY.E Hearings Division 81/03/04 2pp 07827 262
- Bi03180032 Response to Joint Intervenors' interrogethries he emergency plans Affirmations of preparation by PS Tam.RO Fitzpatrick.

  SO Mackey: I Huang: Fior.EG Heminger: J McMillen & BC Nuckley encl Prof qualifications also encl

  JONES. B. W. Hearing Branch 2 81/03/05 87pp 07941.352
- --Blo31Blo30 Forwards interim agreement on criteria for low power tests of now cornercial nuclear facilities. FEMA/NRC steering cornities considers criteria Adequate & can serve as interim basis Certificate of Svc encl CRIMES.B K Emergency Preparadness Task Force. RYAN.R. Fuderal Emergency Management Agency 80/01/06 3pp 07942 077
- 8103120560 Response opposing util 810226 request for directed certification, review of ASLO 810213 order & review of entire O., proceeding Request overbroad, ill-defined & u/o legal basis Certificate of Svc enci REYNOLOS. J.R. San Luis Obispo Mothers for Peace REYNOLDS, J.R. Stenic Shoreline Preservation Conference, Inc. REYNOLOS, J.R. Cents for Law in the Public Interest. 81/03/07 lipp 07904.233
- ---BIO3120574 Discusses Furbush BiO227 ltr to Denton requesting relief from same smergency response planning requirements Joint intervenors appear request. Emergency planning is issue of admitted contention to be decided in proceeding REYNOLDS. J. Center for Law in the Public Interest B1/03/09 5pp 07904.244
- B103130557 Opposes util B10227 request for relief from certain emergency response planning requirements contained in NUREQ-0737. "Clarification of TMI Action Plan Requirement." Emergency planning is subj of admitted contention REYNOLDS. J. R. Center for Law in the Public Interest B1/03/09 Spp. 07908 292.
- Bio3180566 Response on behalf of Covernor Drown supporting NRC 810223 request for directed certification of certain issues. Deposes util 810226 similar request Issue to need for EIA should be directly certified. W/Certificate of Bvc GEORGIOU. B 8 . LANPHER. L C . California. State of. LANPHER. L C . Hill. Christopher & Phillips . 81/03/09 . 13pp. 07953.038.

- 8103120353 Forwards responses to Blate of CA Governor Brown 810220 interrogatories & document production requests directed to IRC.

  ACUES.R W. Hearton Branch 2 81/03/10 in 07901 190
- --8103120373 Response to CA Opvernor Brown 810220 interrugatories & request to produce re amergency planning Objects to Document Request 2 as being overly broad If document request is more specific.NRC will comply Certificate of Svc encl JONES.B W. Hearing Oranch 2 TAM.P. B. Erergency Preparedness Licensing Or (after 801119 see ISE) 81/03/10 8pp 07901 191
- B103130406 Order directing NRC to provide status rept on issuance date of Buppl 12 to SER
  DOMERSE B Atomic Safety and Licensing Doard Panel B1/03/10 | IP
  0.7911 202
- B103200578 Answers to CA Governor Brown B10220 interrugatories & document production requests re util.state & local emergency response plans Objects to document production request Certificate of Bvc enci Related correspondence NORTON.B. GEHRAC C. FURBUSH.M H. Pacific Gas & Electric Co 81/03/11. 7pp 07969 260
- B103180848 Response to ASLB 010310 request for status rept on issuance of SER. Suppl 12 Document issued on 810304 Buppl 13 or 14 to be issued by 820331 One suppl to deal w/non-fMI issues & other will deal w/TMI issues & ertificate of 8vc encl JONES. B W. Hearing Branch 2 81/03/16 Jpp 07953 214
- 8103190637 Notice of ASLB reconstitution JF Walf chairman GO Bright & JR Kline members COTTER B.P. Atomic Bafety and Licensing Buard Penel. B1/03/16 2pp. 07964.081
- 8103230715 Answers to Joint Intervenors' 810223 interrogatories re Contention 4.FBAR.SER.emergency planning regulations & public evacuetions Certificate of Svc encl Related correspondence MORTON.B. 9EHR.A C. FURDUSH.M H Pacific Gas & Electric Co 81/03/16. 1030p. 07973 224
- 8103260626 Clarifies util position as represented in Joint Intervenors response to util request for directed certification No further hearing necessary re-util motion to load fuel & conduct low power tests
  GRANE, P. A. Pacific Oas & Electric Co. 81/03/16 ip. 08041 108
- B103260720 Responds to NRC B10224 request for admissions by joint intervenors re-facility low power test proceeding.
  Certificate of Buc enci Related correspondence.
  REYMOLDBJ R Sen Luís Obispo Hothers for Peace REYMOLDBJ R
  Center for Law in the Public Interest B1/03/16 6pp 0B041 073
- 8103260750 Joint Intervenors response to NRC 810224 interrogatories recore exit thermocouples & saturation meters-reactor vessel water levels, inadequate core cooling & emergency planning issues Certificate of Svc enci. Related correspondence REYNOLDB.J.R., FLETSCHAKER.D., Affiliation Unknown. REYNOLDB.J.R., Conter for Law in the Public Interest. 81/03/16. 22pp 08036-027
- BIO32607BB Response to NRC requests for admissions & interrogatories re reactor pressure vessel water level, one will thermocouples & emergency procedures for inadequate core cooling W/affidavits & Certificate of Svc. Related correspondence BROWN.H H , OEOROIDU. B. B. California. Histo of BROWN.H H Hill.Christopper & Phillips. B1/03/16. Sopp. OB036-095.
- BiO3190616 Request for corrections of misinterpretation of revised policy statement by accepting certification on clarifying statement. ASLB illegally constricted intervenors' rights to challenge sufficiency of TMI-related safety requirements MEIBB.E.R. Union of Concerned Belentists. MEIBB.E.R. Harmon & Weiss. 81/03/17 9pp 07963:276
- ~-Bi03190622 Request to address Commission as anicus curiae in support of requests for certification filed by Joint Intervenors & CA Governor Brown to urge Commission to correct ABLB error.

  Certificate of Svc enci.

  HEIBS: E. R. Union of Concerned Acientists. HEIBS: E. R. Harmon & Weiss. 91/03/17. 5pp 07963:285
- B103266845 Request to compel util to answer interrogatories under oath. NRC regulations require such action. Failure to comply creates problems wienswers at trial Wyroro qualifications & Certificate of Bvc.Related correspondence GEOROIOU-8.S., LANPHER.L.C. California, Btate of LANPHER,L.C. Hill, Christopher & Phillips. 81/03/17. 17pp. 08036:239

- 8103193052 Correction to 810316 rept in response to ASLB 810310 or re issuance of Supple 13 & 14 issuance date should be B10331 not 82031 Cortificate of Svc enct JCHEB.B W. Hearing Branch 2 81703718 3pp 07964 117
- 8103200399 Response to util 810326 motion for directed certification ASLB 810213 ruling re litigation of Joint Intervenors' contentions Complesion should direct certification & reverse ASLB rulings admitting contentions U/Certificate of Svc CLMSTEAD.W J. Hearing Branch & JCMES.B W. Hearing Branch 2 81/03/18 30pp 07970 023
- 8103260366 Informs of Joset Intervenor desire & intention to be hed on merits of issues raised by NAC & PSE 810227 & 26 requests for directed certification Review of 810401 substantive response espected prior to decision FLEISCHAKER.D. REYNOLDS.J.R. Center for Law in the Public Intel 81/03/27 2pp 05041 056
- B100260807 Natification that Governor Brown will submit brief discussing menits of util 7 URC B10226 5 0018 submittate. respectively Brief will be filed to assure opportunity to be heard on safety-related issues M/Certificate of Bvc. BROWN.HH California. State of BROWN.HH Hill.Christopher Phillips B1/03/23 Spp 08036 202
- 8103270181 Suppl to NRC 810316 response to Joint Intervenors' interrogatories BNUL ongoing research may bear on listed interrogatories Certificate of Svc encil JONES, B W. Hearing Branch 2. 81/03/25. Upp. 08045-318
- 8103270460 Errata to NRC response to Joint Intervenors' interropatories Certificate of Svc encl JONES 8 W Hearing Branch 2 81/03/25 4pp C8034 140
- H General correspondence
- 8103200583 Urges startup of facilities H1001MB-C Affiliation Unknown 81/02/10 ip 07985 001
- 8103200585 Urges startup of facilities PRINCE C Affiliation Unknown 81/02/12 lp 07585 001
- BIO3200699 Urges administration to adopt policy to expedite licens of nuclear power plants & to appoint strong chairman to enforce pulscy ALQUIST.A E . AYALA.R 6 . DDATWRIGHT.D E California. State of BI/02/12 3pp 07970 GQI.
- B103270469 Supports facility UL application
  ALBRICHER L. Affiliation Uninoun 81/02/12 to 00043.090.
- BIO3160295 Urges startup of facilities
  RDMERG.L V Affiliation Unknown B1/02/13 Ip 07918.362.
- 8103300321 Ten litrs urging startup of facilities. NELSCN:0 0 Affiliation Unknown 81/02/13 lipp
- 8103260814 Corments on NRC performance re French nuclear industry | HALKER, C.J. Affiliation Unknown 81/02/18 1p. 08041 072
- 8103270444 Package of 121 mailgrams from citizens supporting facil startup. MURPHY.N. Affiliation Unknown 81/02/18. 121pp.
- 8103200486 Urges that NRC grant OLs u/o delay Applicant has not al safety-related & salamic requirements Plants are needed for electrical power generation. STEFAMETTI.H J Affiliation Unknown 81/02/19 p 07985 001
- BIO3200600 Supports licensing of plants
  BRADSHAW J. Affiliation Unknown BI/02/19 ip 07971:260.
- B103170492 Urges startup of facilities REHB05K:C.R. Affiliation Unknown. B1/02/20. 1p 07585.001
- 8103200463 Supports plant operation BRAGHETTA, L. H. Affiliation Unknown 81/02/20 tp. 07587.001
- 8103200502 Urges that NRC grant OLs w/o delay Applicant has met safety-related & soismic requirements Plants are needed for electrical power generation VDLLE, H Affiliation Uninown 81/02/20 ip 07985.001
- 8103179617 Supports license issuance LEWON.R. Affiliation Unknown 81/02/23 ip.

Affillation Unifoun 81/02/23 1p TORRICE, R A . TERRICE E 0/585 001

- 8163200544 Urges startup of \*actilities \* Affiliation Uninoun 01/02/23 1p 07985 001
- 0103040230 Responds to F314 request for A Denton 771010 mend to supporting documents Forwards documents listed in App A Rept entitled "Humbord Ray Power Plant Site Ovolog." le available in ODR investigation" FELTON, J.M. Division of Rules and Records - 81/02/24 200
- B1001700B4 Urges startup of facilities
  USFATLEY a O Addition Unknown 81/02/24 tp 07585 001
- 8103170500 Comments that facility should be started up Safet, & seismic requirements have been net SCHRORDER, M.E. Affiliation Uninoun 81/02/24 1p
- 8103200467 Supports plant operation 5417H. 3 Affiliation Uninnun 81/02/24 sc 07587 001
- 8103200471 Supports facility operation FINCR.L Affiliation Unineur 81/02/24 1c 07971 263
- B103230711 Opposes granting of DL Planned site within 2.5 miles of Hosgri fault Affiliation Unknown 61/02/24 1p 07977 343 BARCLAY, E
- BiO3200474 Supports plant operation ROJERG. D H Affiliation Unknown Bi/02/26 ip 07971 262
- BIO3200939 Urges startus of facilities WILLARD C. Affiliation Unanoun 81/02/26 is 07989 COI
- BIO3110470 Forwards Orange County Charber of Commerce 810227 resolution Favoring traediate licensing of facilities IRUHILL-L D. Orange County. CA. 81/02/27 2pg. 07882 159
- 8103120855 For parts FOIA request for documents to Abalane Alliance. 7/0806 jemonstration at Can Onofre nuclear plant & 780806 demonstration at Diable Canyon nuclear plant KGEMLER. W. R. Justice. Dept of 81/02/27 2pp 07904: 344
- Olio3200493 Urges that IRC prant Ols w/o delay Licensoe has net safesty-notated & seismic requirements Plants are needed for electrical power generation.

  CUMMINOS.F.E. CLANGER H. PHILLIPS: T.J. Affiliation Uniteduced DI/OZ/27 Ip. 07589 CO1
- H10320C498 Urges that HRC grant CLs u/o dalay. Applicant has mat safety-malated & saismic veguinaments Plants are nocded for olectrical power generation QUILFCLV . COCLEY.F.M . MARTINE J. Affiliation Unknown 81/02/27 GUIL FC 1. V . COC
- B103200548 Urges startup of facilities RURRAY-H , MORSE.A E Affiliation Uninoun. 81/02/27 1p 03489-001 07585: 001
- B103200552 Urgss startup of facilities WEBB.A.J. Affiliation Unknown B1/02/27 1p 07599 001
- 8103200533 Urges that NRC grant Ocs for facilities w/o delay.due to need for electrical energy BLOWERS,L Affiliation Unknown 81/02/28. 1p 07585 001
- BIOG17058B Deposes delayed restart of facility BROWN, F. Affiliation Unknown 81/03/02 I
- B103170496 Urges that NAC grant facility OL Facility has met all afety & seismic requirements & is needed to provide alectrical energy in critical yrs sheed (BEJARANG). R affiliation Uniform BI/03/03. 1p
- B103170490 Urges startup of facilities
  TYLER. P.J., PHILLIPS.R.C. Affiliation Unknown. 81/03/03. 1p 07585:001.
- B103170801 Expressor admiration for Absance Requests autograph CZINOMBKY, L. Affiliation Uninoun. 81/03/03 1p 07585 CO1.

ac \$1 v1 \$ 6 \$ LAMBLE R Affiliation Uningun 81/03/03 1p

ACTIONS & HOOMPOUTABLE IIVELDI

- p103200514 Urges that NRC grant CLs w/o delay Applitant has not safety-related & selsoic requirements Plants are needed for electrical power generation CCRDAAY, D. A. Affiliation Unknown 81/03/03 Ip 07585 001
- eio3200586 Unges startup of facilities POX.t. A Affiliation Unknown B1/03/03 ip 07585 001
- B10311034B Supports TMI-1 restart & licensing of other facilities SHERHCOO.C L Affiliation Unknown 81/03/04 lp 07885 283
- 8103160514 Expresses shock to delays in licensing new nuclear plants iodioovit ciprosses shock to delays in licensing new nuclear Cormissioners responsible for Jelays ALLEIN C R Affiliation Uninoun B1/03/09 ip 07944 261
- 8103120852 Responds to FDIA request for socuments to Abalane Allience
- 103120852 Responds to FDIA request for Jacuments re Abalone 770806 demonstration at Ban Onofre nuclear plant & 780806 demonstration at Diablo Canyon nuclear plant forwards EQ Case 770203 itr to Southern CA Edison Co FELICULU H. Division of Rules and Records 81/03/10. 1p
- 9103260929 Urges expeditious licensing of util to load fuel & assump full power operation Util has accomplished all retrofitting measures State of CA needs 20% power increase that facilities could supply CURB. H. California, State of. 81/03/11 in 08037 342
- 8103203932 Urges granting of OL to facility ALBRECHIAR O . M.LEN.U.C. Affiliation Unknown 81/03/16 1p
- 0103260808 Urges restort of facilities Emviron.political.economical & sociological demage caused by needless shubdowns are incoasurable DUNHAMAR & Affiliation Unknown. 81/03/19
- 8103260691 Expresses concern re NRC failure to expedite action on completed \$/or ready-to-operate facilities Also expresses concern re intervenor groups which receive indirect govi funding FALNAOL. J II Affiliation Unknown 81/03/21 1p
- 8103260819 Urges NRC to expedite full cower licensing of facilities & restart of Int-| Concern for safety & careful review of literating or later to the literature of Int-| Concern for safety & careful review of literating process has gone beyond reasonable caution TALNAGI.J # Affiliation Unknown. 81/03/21. 10 08037.346
- P. Operating license stage documents & correspondence
- B103310804 Ltr to all licensees of operating plants applicants for OL 3 holders of CPs forwarding SECY-81-119 re info nocessary to establish environ qualification of safety-related electrical equipment EISENHUT, D.Q. Division of Licensing. 81/03/10. 6pp
- G Inspection reports. IE Bulletine & correspondence
- 8:03030489 Forwards IE Insp Repts 50-275/80-23 & 50-323/80-12 on CO1201-31 No noncompliance noted CREGS.JL Reactor Operations Nuclear Support Brench 81/01/13 2pp
- --0103030498 IE imap Repts 50-275/80-23 % 50-323/80-12 on 801201-31 No noncompliance noted Major areas inspected, prespectational testing, plant tour, operating staff training, fuel eterage & volumber training.
  YOUND-T. BARACLIO.M. Region 5. Ban Francisco. Office of the
  Director STERNDERG.O M. Region 5. San Francisco. Reactor
  Operations Nuclear Support Dranch 81/01/08. 4pp.
- 8103180519 Forwards 1E Insp Repts 50-275/81-01 & 50-323/81-01 on RECHB. J L Region 5. Sen Francisco. Reactor Operations Nuclear Support Branch 81/02/06 2pp 07949 318
- --8103180523 IE Insp Repts 50-275/81-01 & 50-323/81-01 on 810101-31.1 noncompliance noted. Major areas inspected preoperational testing, plant tour, fire prevention protection & IE bulletin/ circular follows: Region 5, Ban Francisco, Office of the YOUNG T., BAOAGLEO. M. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch. 81/02/06. 5pp. 07949-320.

- 8103020096 Forwards TE Circular Bi-02. "Performance of NRC-Licensed Individuals Unite on Outy ' No written response required ENGELKEN.R H. Region 5. San Francisco. Office of the Director Bi/02/09. 1p 07787 342
- B103160636 Forwards IE Info Notice B1-03 "Checklist for Lirensees Haking Notification of Bignificant Events in Accordance H/10CFR90 72 "No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director B1/
- B103160661 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines" No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 81/02/27. 1p 07914 250
- 8103174023 Forwards IE Circular B1-03. "Inoperable Seismic Munitoring Instrumentation " No response required ENGELKEN, R H. Region 5. Gan Francisco, Office of the Director 81/03/02 1p 07939 149
- 8103160852 Forwards revised IE Bulletin Bi-Oi. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ENMELKEN.R H. Region 5. San Francisco. Office of the Director Bi/O3/04 Ip. 07914 209
- B103200292 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required ENGELKEN, H Region 5, San Francisco, Office of the Director 81/03/11 ip 07968:340
- 8 Reportable occurrences. LERs & related correspondence
- B103020514 Interim deficiency rept re 6-s delay in containment spray pump start after high-high pressure signal during LDCA. initially reported B01204 Starting sequence will be changed Final rept due after design of modified starting scheme CRANE.P.A. Pacific Cas & Electric Co. 81/01/19 2pp
- 8103180489 Final deficiency rept re Hagan Model 118 low level amplifiers indicating improper output voltages, initially reported on 810206. Transistors 2N699 in Location 614 will be replaced. Technical analysis encl.
  CRANS.P.A. Pacific Oas & Electric Co. 81/03/09 16pp
- Bi033004B0 Board notification re facility breakwater damage on 810127.

  Damage to be further inspected by NRC Bafety implications to be determined following discussions w/epplicant & consultant

  TEDESCOR. R.L. Assistant Director for Licensing. 81/03/18 3pp. 08057:173
- U. Congressional/Executive Correspondence
- 8103200456 Requests info re Commission position on licensing procedures
  8A1LEY.D. House of Rep. 81/02/18. ip. 07971.264
- 8103240091 Forwards fourth monthly status rept to Congress for B10115-0219. Rept discusses actions taken on licensing reviews of new facilities. Rept will be amended to include add info requested on B10217.

  KANMERER, C. Office of Congressional Affairs. B1/02/27. Opp. 07000-110
- 8103270110 Responds to request for rept on possible add1 improvements to NRC licensing process. Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process.

  MENORIE, J. M. Commissioners. 81/03/12. 5pp 08043:329
- --8103270931 Submits recommondations to expedite impacted OL hearings Code should include set of TMI-related OL requirements. ASLAB decisions on fuel loading & low power testing should be immediately effective BICKMIT.L. Office of the General Counsel 81/02/23. 10pp. 08043:344.

#### V Operator Examinations

#103020579 Bubbits info re shift technical advisor.operator of qualification 5 050 Tasi Farce recommendations in response to NRC request Supportive documentation encl Related correspondence
CRANE.F A Pacific Cas & Electric Co. 01/02/13 23pp

DOCKET 30-876 GEORGIA TECH RESEARCH REACTOR

- B103020149 Forwards IF Corcular B1-02. "Performance of NRC-Li Individuals While on Duty 'No written response required D'REILLY. J P. Region 2. Atlanta. Office of the Director Ip. 07788 059
- DOCKET 50-277 PEACH BOTTOM AIGHTC POLER STATION. UNIT 2

  F. Security, modical, amorgancy & fire protection plans
- BiO3180264 Ltr to all power reactor licensees w/plants licens to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 fire protection rule EISEMBUT.D 9 Division of Licensing 81/02/20 13pp
- BIO3310336 Ltr to all licensees of operating plants & holders forwarding NUREG-0696. "Functional Criteria for Energyncy Response Facilities" Criteria describe acceptable method for meeting NRC requirements U/o encl EISEN-UT.D G Division of Licensing 01/03/09 App
- 8103130247 Forwards revised safeguards continguncy plan Plan (ref 100FR2 799) BRADEY,E J. Philadelphia Electric Co. 81/03/10 3op. 0
- 0103200478 Requests concurrence that existing facility fire history requirements per loch Spec 4 14. A 4 d identify proper testing pressures to comply 6/10CFR50 4B & 10CFR50. App R DALTRUFF.8 L. Philadelphia Electric Co. 81/03/12 20p
- 8103170168 Forwards revised plant security personnel training qualification plan Plan withheld (ref 100FR2 7901 Affidavit for withholding encl BRADLEY.E J. Philodelphia Electric Co. Bi/O3/16 3pp. 0
- B103290285 Submits response to 10CFR50. App R re fire protecti program Bi: marked-up oversite drawings encl Aperture cards are available in PDR DALTROFF.B L Philadelphia Electric Co B1/03/20 14pp 08022. 213
- 1 Financial information
- 8103170584 Forwards Annual Financial Rept 1980 BRADLEY, E.J. Philadelphia Electric Co. 81/03/13 7pg.
- --BIO3170596 Annua) Financial Rept 1983

  4 Public Bervice Electric % Gas Co of Now Jersey 81/0
  32pp
- --9103170606 Annual Financial Rept 1980 + Philadelphia Electric Co. 81/03/13 46pp
- --8103170616 Annual Financial Rept 1980.
  \* Atlantic Electric of New Jersey 81/03/13 40gg.
- --8103170626 Annual Financial Rept 1980.

  \*\* Delmarva Power & Light Co | 81/03/06 | 40np
- J Insurance & indomnity information
- B103170560 Forwards Endorsements 90 & 91 to NELIA Policy NF-1 Endorsements 46 & 47 to MAELU Policy MF-67. Endorsement 4 to NELIA Binders EB-8 & EB-9 & Endorsement 4 to MAELU Binders XB-8 & XB-9 BRADLEY.E J Philadelphia Electric Co 81/03/12 11pp

- P. Operating license stage documents & correspondence
- 8103190732 Lins to all licensees of operating plants, applicants for OLs tholders of CPs reconstruct of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position reinterin actions the request for add
- 8102270565 Notification of contract execution Mod 2 to "Environ Monitoring Program M/Commonwealth of PA " Contractor Commonwealth of PA " Contractor Commonwealth of PA SAISEN L. Research Contracts Branch FIN 8-51:1 81/01/07 ip
- --Bio2270590 Mod 2 adding TLD monitoring around facilities & increasing anount of contract to "Environ Monitoring Program W/ Commonwealth of PA"

  GERUSAY: I Pennsylvania, State of MORICY, K V Research Contracts Brench FTM 8-511[ 81/01/07 4pc 07772 352
- B103190397 Etr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutcown, replacement parts & NUREO-0737 EISENMUT, D.O. Division of Licensing 81/01/19, 6pp
- Fil03120014 Ltr to all licensees of operating plants CP hoiders & U\_applicants except indian Point 2 & 3.2ion | & 2 & TMI~I. forwarding inadvertently unitted pages from NGC E01222 request for addl info re control of heavy loads EISENHUT.D G. Division of Licensing. B1/02/03 App
- 8103160669 Lin to all operating plants & CP molders forwarding clarification of IMI Action Plan Item III A. I 2 no upgrade of emergency support facilities Requests confirmation within 45 page that implementation dates will be mot EISENMUT.0.9 Division of Licensing 81/02/18 12pp
- 8103020268 Requesty add1 Class IV & I fees for review of safety issues involved in 800915 Tech Spec change request HOLLOW4Y-C J. License Fee Management Branch. 81/07/20 ip 0/784-272
- 8103230024 Ltr to all polar reactor licenses & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of elicting low flow controller EISER-MUT.D O Division of Licensing 81/02/20 8pp
- 6103020649 Responds to NRC 810122 request for odd1 info re util 760812 request for exemptions from requirements of containment leakage testing Response util be provided by 810515 DALTROFF, S. L. Philadelphia Electric Co. 81/02/25. 1p. 07782: 128
- 8103160458 Forwards preliminary results of review to seviron qualification of safety-related electrical equipment Util most respond www.ritten statement that facilities can be safety operated MDVAK. I N Assistant Director for Operating Reactors 31/02/25 33pp. 07916 225.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for Oile (except St Lucie Units 1 & 2) Requests util review to determine capability to mixigate station blackout event & promptly implement emergency procedures EISEIMULO O. Division of Licensing 81/02/25 3pp.
- BiO3170225 Ltr to all SHR licensess (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends \$ fitting metl per guidelines of encl Revision I to NUREC-0313 Model Tech Specs only encl EISENMUT. 0 O Division of Licensing Bi/02/26 3pp
- --GE03170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/6 4-7 % 3/4 4-8 re surveillance requirements for ASME Code Class 1,2 % 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements e General Electric Co Bt/02/26 4pp
- B103230973 Notifies of issuance of NUREG-0757, "Radon Releases From U Mining & Milling & Calculated Health Effects," which contains new info potentially relevant & nat1 to ABLAB proceedings
  TERRY.O. A. Bivision of Fuel Cycle & Hateria) Safety. B1/02/26
  279. 08022.227
- B103240290 Ltr to all BMR licensees forwarding Suppl 1 to generic safety evaluation on BMR scram discharge sys Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation.

  EISENHUT.D O Division of Licensing 81/01/23. 2pp

- BiO31:2640 Responds to BiO225 preliminary results of NRC review of in re environ qualification of safety-related electrical equipment Util review of environ qualification documents concludes that App A of B01031 itr remains valid DA\_IRG=F.S L Philadelphia Electric Co B1/03/06 3pp
- 8103160650 Notifies that util BOIRI6 commitments to BUR scram dischars
  sys long-term mode do not satisfy GRC criteria Design must
  include criterion on diverse instrumentation
  REID.RW Operating Reactors Branch 6 81/03/06 200 07915 205
- B103130507 Forwards add1 info re reactor protection sys power supplyper LRC B10121 request Three oversize drawings encl Apenture cards are available in FDR DALTROFF. S L Philadelphia Electric Co. 81/03/09 9pb.
- 8103310804 Ltr to all licensees of operating plants applicants for CL bholders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment EISEMBULT 0 0 Division of Licensina 81/93/10 app
- B103200520 Submits response to I tem II K 3 3 of NRC 800507 ltr, requiring annual rept of challenges to primary coolant systafety & relief valves Describes B01217 challenge involving four relief valves
  DALTROFF. S L Priladelphia Electric Co 01/03/13 2na 07970 24
- B103270095 Survey, of B10304 meeting w/Mark I owners group & OE in Bethesda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NARCO-0661 Blide presentation & list of attendess enci. ORIMES.C I Licensing Branch 3 B1/03/16 5pp
- 8100270403 Forwards application for amend of Licenses DPR-44 & DPR-96 requesting changes to Tech Specs
  BRABLEY.E. J. Philadelphia Electric Co. 81/03/24. 1p. 08043 049.
- ~~B103270414 Application for amend to Licenses DPR-44 & 96, requesting changes to Tech Specs re surveillance requirements & limiting tousitions for operation applicable to shock suppressors on safety-related sys Certificate of Svc encl. DALTROFF.S L. Philadelphia Electric Co. B1/03/24. App. ORDAY ORD
- --8103270424 Tech Specs 3 ii.D re limiting conditions for operation & 4 ii.D for surveillance requirements re shock suppressors on safety-related sys.

   Philadelphia Electric Co 81/03/24. 3ipp. 08043 096
- O Inspection reports, IE Bulletins & correspondence
- BIO3180223 Responds to Suppl 3 of IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Temp profile for saturated steam test.LDCA profile & TMI mods included. DALTROFF, 8 L. Philadelphia Electric Co. 81/01/30 55pp 07952 217.
- 8103200330 Responds to IE Bulletin 80-17. Buppl 4. "Failure of Control Rods to Insert During Screm at BMR" Calibr & testing of continuous monitoring sys were performed by facility instrument technicians Personnel qualification data encl DALTROFF, B L. Philadelphia Electric Co. 81/01/30. 11pp 07971:057.
- B103180157 Act receipt of 810126 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-277/80-32 & 50-270/80-24 BRUNNER.E J. Region i. Philadelphia. Reactor Operations Nuclear Support Branch 81/02/06 ip 07943-266
- --8103180164 Responds to NRC B10107 ltr re violation nated in IE Insp. Repts 50-277/80-32 % 50-278/80-24 Corrective actions, revised grocedures posted.
  DALTROFF, S. L. Philadelphia Electric Co. 81/01/26. 2pp. 07943 267.
- --BI03180172 Forwards IE Insp Repts 50-277/80-32 & 50-278/80-24 on B01001-1107 & notice of violation BRUNNER.E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Brench. 81/01/07, 2pp. 07943-269.
- --BiO3180177 Notice of violation from insp on 801001-1107.

  \* Region 1, Philadelphia, Office of the Director 81/01/09. ip 07943.271.

pi80186 IE jnap Repts 50-277/80-32 & 50-278/80-24 on 801001-1107 incompliance noted outdated procedures pusted at emergency juiddum panels

iutourr panels NAGILL.C J., BLOUGH.A R. Region 1. Philadelphia. Office of the Trector MCCABE.E.C. Region 1. Philadelphia. Reactor Operations Iclear Support Branch 81/01/09 29pp 07943 272

0452 Provides info re proposed support mods to one primary ainment atmospheric control line on each unit in area of ation valves Design & installation will be completed by

NEY.M J Philadelphia Electric Co Bi/02/11 2pp 07836 028

D187 Forwards 1E Info Notice \$1-03. 'Checklist for Licensees ing Notifications of Bignificant Events in Accordance DCR850 72 " No written response required R.B H Region 1. Philadelphia. Office of the Director 12/12 1p 0/813 037

1039) Forwards Suppl 9 to 1E Bulletin 80-17. 'Failure of Control to Insert During Scram at BWR " No written response tired

R.B H Region 1. Philadelphia. Office of the Director 12/13 1p 07808 233

0164 Forwards IE Info Notice 81-04, "Cracking in Main Steam .s." No response required R.O.H. Region L. Philadelphia. Office of the Director 12/27 1p. 07972 008

0217 Forwards 1E Ctrcular 81-03. "Inoperable Setemic Monitoring rumentation" No written response required (R.B.H. Region I. Philadelphia. Office of the Director (3702 ip 07966.202

19033 Forwards revised IE Bulletin B1-01, "Surveillance of Antical Gnubbers." u/corrected Pages 5 & Change in thiffication of facilities w/CP to which bulletin is icable does not affect util requirements. R.B. II Region 1, Philadelphia, Office of the Director 13/04 | p 07968-186

0129 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 uit Breaker." No response required ... R.B.H. Region L. Philadelphia, Office of the Director 3/11. 1p. 07971 332.

iodic operating reports & related correspondence

0216 Forwards "Semiannual Effluent Releases Rept 10-Dec 1780." N.W.M. Philadelphia Electric Co. 81/02/26 1p. 07586 001

1050222 "Bemiannual Effluent Releases Rept 10.Jul-Dec 1980." LRICH W.T. Philadelphia Electric Co. B1/02/26 9pp 1827 044

ortable occurrences. LERs & related correspondence

0651 LER BI-009/03L-0 on Bi0126, diesel cardox fire protection E-3 failed to Initiate automatically during testing ed by microswitch in electromanual pilot control valve noid circuitry being stuck open preventing initiation. EY.M.J. Philadelphia Electric Co. Bi/02/18. 1p. 07811:337.

0623 Forwards LER 81-010/03L-0 EY.M.J. Philadelphia Electric Co. 81/03/02. 2pp. 07862:344

100626 LER 81-010/03L-0: on 810127 drywell radiation monitor found to feve during full operation. Caused by no sample flow rough sys due to manual sample/purge valve dislodged from rmal sample position. Walve returned to position.

ONEY, M. J. Philadelphia Electric Co. 81/03/02. 1p. 07862-346.

0491 PND-I-B1-032 on B10304. Chicago Bridge & Iron Co sheet metal ere setablished orderly picket lines on site access

ere established orderly picket lines on site access sounced by township Staffing of licensed shift personnel fied.
ILL,C., GREENMAN.E.G., KEIMIO.R.R. Region I, Philadelphia. ce of the Director. 81/03/04. 2pp 07867:219

0624 LER 81-012/03L-0-pn 810202, main steam line monitor D cated low level radiation resulting in trip setpoint e Tech Spec ifmit Caused by instrument zero drift. tor calibr & returned to evc. EV, M. J. Philadelphia Electric Co. 81/03/04. 1p

- a103100630 LER 81-015/03L-0 on B10203 main steam line monitor A indicated low level radiation resulting in trip setocint above Tech Spec limit Caused by instrument zero drift Panitor calibr & returned to svc CODMEN J Philaselphia Electric Co B1/03/04 is
- 8103310642 LER BI-016/03L-0 on 910225 reactor core isolation cooling trip throatile valve would not raset in normally open position using Limitorque operator, following manual trip Caused by worn worm gear in trip throatile valve operator COOMEY, M.J. Philadelphia Electric C.S. 81/03/23 pp.
- BIO3300342 LER BI-017/03...O on BIO318.all inboard sample isolation valves. 6V-2671A-SV26710. closed Caused by short in coil of dyno-type salenoid valve SV-2671A. union blew common fuse in control circuit for all seven valves CDOXEY. M J Philadelphia Electric Co BI/03/24 (p

### V Operator Examinations

8103120367 Responds to NUREC-0737 re-shift manning requirements Submits clarification to util B01222 lth re-facility overtime policy DALTROFF, B L. Philadelphia Electric Co. 81/03/10 2pp. 07904-356

BOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F. Becurity, medical, emergency & fire protection plans

G103180264 i.tr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info resafe shutdown capability for compliance w/801119 fire protection rule FIFFIHAT. N B Division of Licensina 81/02/20 13pp

8103310338 Ltr to all licenses of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements 474 encl

BIOBIBO242 Forwards revised safeguards contingency plan Plan withheld (ref 10CFR2 790)
BRADLEY, E. J. Philadelphia Electric Co. Bi/OB/10 | Jpp. | D7908 360

BIO320047B Requests concurrence that existing facility fire hase testing requirements per Tech Spec 4 14.A.4 d identify proper testing pressures to comply w/10CFR30 48 & 10CFR30.App R
DALTROFF.8 L Philadelphia Electric Co. BI/03/12 2pp 07970 247

8103190168 Forwards revised plant security personnel training & qualification plan. Plan withhold (ref 1005R2 790) Affidavit for withholding encl
BRADLEY.E.J. Philadelphia Electric Co. 81/03/16 3pp. 07963:089

0103250285 Bubmits response to 10CFR50.app R re fire protection program Six merted-up oversize drawings encl. Aperture cards are evallable in PDR DALTROFF.B L. Philadelphia Electric Co. BI/03/20 14pp. 08022-213

#### 1 Financial information

8103170584 Forwards Annual Financial Rept 1980 BRADLEY, E.J. Philadelphia Electric Co. 81/03/13 7pp

--Bi03170596 Annual Financial Rept 1980 • Public Service Electric & Gas Co of New Jersey. Bi/02/16 52pp.

--8103170696 Annual Financial Rapt 1980 # Philadelphia Electric Co. 81/03/19. 46pp

--8103170416 Annual Financial Rept 1980
Atlantic Electric of New Jersey. 01/03/13 40pp

--B103170626 Annual Financial Rept 1980 \* Delmarva Power & Light Co 81/03/06 40pp.

- .) Insurance & indemnity information
- 8103170363 Forwards Endorsements 90 & 91 to NELIA Policy NF-140. Endorsements 46 & 47 to MAELU Policy KF-67. Endorsement 4 to MELIA Dinders E3-8 & E8-9 & Encorsement 4 to MAELU Binders x8-8 5 XB-9 GRADLEY/E J. Philadelphia Electric Co. 81/03/12 | Hop. 07933-051
- P. Operating license stage documents & correspondence
- B103190732 Line to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position to interin actions & request for addl info rigenant. D G Division of Licensins 80/12/22 30pp
- BiO2270565 Notification of contract procution Mod 2 to "Environ Monitoring Program W/Commonwealth of PA" Contractor Commonwealth of PA Research Contracts Branch FIN 8-5111 81/01/07 to
- --Bio2270590 Mod 2, adding TLD conitoring around facilities to increasing amount of contract to "Environ Monitoring Program 4/ Commonwealth of PA" GENUSKY. T.M. Pennsylvania. State of F3% (1-5):11 81/01/07 4;p
- 3103190397 Ltr to all licensees of operating plants & applicants for Out & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts 5 NUREO-0737 EISEN-UT. D 0 Division of Licensing 81/01/19 6pp
- 810312C014 Ltr to ail licensees of operating plants CP holders & III applicants except indian Point 2 & 3.71on | & 2 & TMI-1. applicance, except indian moins a willing forwarding innovertently untited pages from the 801222 request for addt info re control of hoday loads EISENHULD D.O. Division of Licensing 81/02/03 App.
- BIO3169669 Ltr to all operating plants & CP holders forwarding 103160669 Ltr to all operating plants & th nuters returned to clarification of TMI Action Plan Iten III A 12 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation dates will be met ERECHUIT. D. O. Dutsion of Licensing 81/02/10 12pp
- 8103020268 Requests add1 Class IV % I fees for review of safety issues involved in 800915 Tech Spec change request HOULGHAY C V License Fee Management Branch 01/02/20 16 07784 272.
- 8103230024 Ltr to all power reactor licensees & license applicants re NUREO-0619 critoria footnote 2 in Table 2 contains error due to leakate testing deletions Licensee may sub-it analysis to justify use of existing low flow controller.
  EISENHUT.D Q Division of Licensing 01/02/20 Upp
- 8103020645 Responds to NRC 910122 request for add1 info re util 7A0912 request for exemptions from requirements of containment learange testing Response will be provided by 810515 DALTROFFIG. L. Philadelphia Electric Co
- 8103160458 Forwards preliminary results of review re environ qualification of sefety-related electrical equipment Util must respond w/written statement that facilities can be safely operated NOVAN. T N Assis 30pp 07916 223 Assistant Director for Operating Reactors 81/02/25
- 8103230930 Ltr to all licenses of operating nuclear power plants & applicants for GLs (except 8t Lucie Units | & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement errogency procedures EISERHUT.D.Q. Division of Licensing. 81/02/25 Spp
- 8103170225 Lie to all BWR licensees (except Humboldt Bay & LeCrosse) INSTINUED LET TO ALL HOME Excellents the control of the control of AS-E Code Class 1 & 2 pressure boundary piping safe ends & fitting mail per guidelines of encl Revision 1 to AUREP-0313 Model Tech Baccs only encl EISENBUT, D. O Division of Licensing. B1/02/26 3pp
- --B103170266 Model Tech Spece Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re surveillance requirements for ABNE Code Class 1,2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements \* General Electric Co. 81/02/26. 4

U Mining & Milling & Calculated Health Effects." which contains new info potentially relevant & catt to ASIAB proceedings. struct G A Division of Fuel Cycle & Material Markety - 01/02/26

minageneral Eventure of

- 2co 08022 227
- 0103240290 Let to all SW4 licensees forwarding thippl I to generic safety evaluation on Bod scran dischange sys formations in evaluation of interim measures incommended per fittled. safety evaluation EIBERHALD O Division of Licensina BU/01/24
- DIDDITORAD Response to Bio223 profiningly results of NHC review of the re-environ qualification of safety-related electrical equipment Util review of unvivo qualification decorants concludes that App A of 101001 for remains valid pACTROYCR. L. Palladelphia Electric Co. HIVORYON. App.
- 8103160650 Notifies that util 891216 commitments to BUR screen flacher; indicional deserves that acti middle commitments to middle stead sys lang-tore would do not eatisfy IRRC criteria Dusign most include criterion on diverse instrumentation IRCID:A.R. Operating Reactors Deanch 4 HIZONON Dep 07914 202
- D100100507 Forwards add1 info re reactor protection sys power supply, par IMC B19121 request three oversize drawings encl Aperture cards are available in PDR DALTROFFIS L Philadelphia Clectric Co. 81703709 - Yun
- 0103310804 Ltr in all licensees of operating plants, applicants for Dis 5 holders of CPs forwarding ECY-DI-LIV to Info necessary to establish environ qualification of safety related electrical acutoment. CISCULT. O Otvision of Licensing DIVON/10 App
- BIONEOUSE Bubmits response to Item II K it is of AMC HOOMBY Ite. requiring annual rept of challenges to primary coolant sus-safety & relief valves Describes BD1217 challenge involving four relief valves Philadelphia Clectric Co. Bl/Oi/CD. 2pp. 07970 44 CAUTROFFER
- 0103270095 Sulmany of 810304 meeting office I coners group & GL In Hatherda. Mi re supplementary tests conducted in full state test facility & resolution of outstanding Mark I issues par MARCO-OAGI Hilde presentation & list of attendage entit ORIGINAL OF THE STATE OF THE ST
- D10327040's Forwards application for amond of ticycoms DPB 44 % PPB 96 CHARGE TO THE CHARGES TO TECH THE CE TO THE CONTROL OF T
- -01103270414 Application for amond to Licenses DM 44 & 36, requesting changes to fech Spece te surveillance requirements & configure to seek upset to anything to equivaments to timiting conditions for operation applicable to short suppressors on earsty-related sys Cartificate of Net enil DALTHOFF, D.L. Philadelphia Flectric Co. HEZELZA Spp. 00043-050
- -- 01032/0424 Tech Space 3 II D to IImiting conditions for operation & 4 II D for surveillance requirements to shock suppressors on sefety-related sys Philadelphia Clectric Co. 81703724 Hpp. 00840 056
- O Inspection reports, IE Notletins & correspondence
- 0103100223 Responds to Goppl 3 of IE Bulletin 79-018. "Inviron Ovalification of Class IE Equipment " Temp profile for saturated steam test-LUCA profile & this made included OALTROFF-B L. Philadelphia Electric Co. BI/01/10. 33pp 02952.217
- BIO3200330 Responds to IE Bulletin BO-17-Buppl 4. "Failure of Control NOUSCOLIO Responde to IR Bulletin HO-17. Huppi 4. "FAiling of Rods to Insert buring Otram at BNA" Calibr to testing of continuous moistoring sys were performed by facility instrument techniciens Personnel qualification data encl DALIROFF.B L. Philadelphia Electric Co. 81/01/210. 31p 07971 057
- 8103;80107 Ack receipt of 810126 for informing NHC of steps taken to correct violation noted in IE lasp Repts 30-277780-02 & COURTERS VILLES ON THE COURTERS OF THE COURTER OF THE C
- --8103180164 Responds to NRC 810107 ltr re-violetion noted in 16 Insp. Repts 50-277780-32 5 50-278/80-24 Corrective actions revised procedures posted DALTROFFIS L. Philadelphia Clectric Co. 81/01/26 200 07743.267

- --Bio3180172 Forwards IE Insp Repts 90-277/80-32 % 90-278/80-24 on BO1001-1107 & notice of violation BRUINER,E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 81/01/07 2pp 07943 249
- --8103180177 Notice of violation from insp on 801001-:107

   Region 1. Philadelphia. Office of the Director 81/01/05 lp 07843-271
- --BIO31801B6 1E Insp Repts 50-277/80-32 \$ 50-278/80-24 on BO1031-1107 Noncompliance noted outdated procedures posted at emergency shutdown panels COHOILL, C.J., BLOUGH, A.R., Region 1. Philadelphia, Office of the Director MCCAUE, C. Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch B1/01/05 29pp 07943, 272
- 9103060452 Provides info re proposed support mods to one primary containment atmospheric control line on each unit in area of isolation valves Design & installation will be completed by 810311 COUNEY.M J. Phyladelobia Electric Co. 81/02/11 200. 07936 028
- B103040187 Forwards IE Info Notice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events in Accordance W/10CFR59 72" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 81/02/12 ip 07813 037
- 8103030391 Forwards Suppl 5 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Stram at BMR "No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 81/02/13 1p. 07808 23J
- 8103200164 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines " No response required GRIER.8 H. Region 1. Philadulphia, Office of the Director B1/02/27 1p 07972:008
- BiO3200217 Forwards IE Circular 81-03, "Inoperable Sejamic Monitoring Instrumentation." No written response required GRIER.B.H. Region I. Philadelphia, Office of the Director 81/03/02. 1p 0.7966-202
- 8103200033 Forwards revised IE Bulletin Bi-Ol. "Burveillance of Mechanical Bnubbers:" w/corrected Pages 5 % 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements. ORIER.8 II. Region I. Philadelphia. Office of the Director. 81/03/04. Ip 07960 186
- BIO3200129 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required GRIER.D H. Region 1. Philadelphia. Office of the Director BI/03/11 1p 07971 332
- R. Periodic operating reports & related correspondence
- 8103050218 Forwards "Semiannual Effluent Releases Rept 10. Jul-Dec 1980." ALDEN.M. Philadelphia Electric Co. 81/02/26. in 07586 001
- --8103030222 "Semiannual Effluent Releases Rept 10 Jul-Dec 1980." ULLRICH: N.T. Philadelphia Electric Co 81/02/26 9pp 07827: 044
- 8. Reportable occurrences. LERs & related correspondence
- 8103110654 Forwards LER 81-008/01T-0. CODNEY.M.J. Philadelphia Electric Ca. 81/02/25. 3pp 07887.089
- --8103110458 LER 81-008/01T-0:on 810211, main isolation valve on loop 8 mistakenly isolated instead of loop A valve during installation of test connection to 1-inch containment atmospheric dilution line. Caused by wrong valve designation. COUNEY, M. J. Philadelphia Electric Co. 81/02/25. 1p. 07887-092.
- B103100491 PNO-1-B1-032: on B10304. Chicago Bridge & Iron Co sheet metal workers established orderly picket lines on site access roads owned by township. Staffing of licensed shift personnel vertified.

  CCHOTLL.C., OREENMAN.E.G., KEIMIO.R.R. Region 1, Philadelphia-Office of the Director. B1703704. 2pp. 07867: 219.
- 8103100621 LER 81-007/03L-0: on 810206, main steam line munitor A indicated low level radiation resulting in trip setpoint above Tech Spac limit. Caused by instrument zero drift Monitor calibr & returned to svc. CDONEY, M.J. Philadelphia Electric Co. 81/03/04. ip.

- 8103110495 LER 81-009/03L-0 on 810216 during surveillance test of 1 of 3-5 gpr found on oil supply line to HPC1 turbine manual/ overspeed trip mechanism Caused by ruptured diaphragm in oil line pressure control valve VC-210 CORNEY, M.J. Philadelphia Electric Co. 81/03/05 in 07586 001
- B103110729 LER B1-010/03L-0 on B10214 & 25.bluum control fuse render RHR logic sys A imperable during full sower operation. Caused by internitions ground on indicating lamp on control panel indicating light isolated CODMEY.M J. Philadelphia Electric Co. 81/03/05 ip
- 8103;70354 PRO-1-81-034 on 810310.contents of 55-gailon drum used to catch radioactive drains flowed into storm drain sys before drains were plugged Caused by coalling water supply waive not tightly shut when draining lube oil cooler COMPILLO, MEINIO, R.R., MCCABE, E.C. Region L. Philadelphia, Offic of the Director B1/03/10 2pp 0/924-055
- BiOJJ00J09 LER 81-C06/03:-0 on BiO227, core spray logic sys 8 failed Caused by blown fuse due to grounded lug bis care spray pump circuit breaker. D latch check switch Circuit breaker replaced 8 lug on grounded circuit breaker repositioned CCDMEY. BJ Philadelphia Ejectric Co BIOJZ2J Ip

## V Operator Examinations

B103120367 Responds to NU#E0-0737 re shift manning requirements Submiclarification to util 801222 ltr re facility overtime policy DALTROFF, 5 L. Priladelphia Electric Co. 81/03/10 200 07904 3

DOCKET 50-280 SURRY POWER STATION. UNIT I

F. Security, nedical, energency & fire protection plans

- 8103180264 Ltr to all youer reactor licensees u/plants licensed prio to 790101 Forwards NRC position 5 request for add1 info re safe shutdown capability for compliance u/901119 fire protection rule ELEGENEWICD 0 Division of Licensing 81/02/20 1300
- Bio3040366 Supple 801215 response to RVREO-0737 re emergency preparedness Rept will not be completed until BiO415 Backup mateorological tower signals at facilities & strip chart recorders at Burry will not be installed until 810801 SYLVIA.8 R Virginia Electric & Power Co Bi/02/27 2pc 07820.149
- B10331033B Ltr to all licensees of operating plants & holders of CPs forwarding NVREO-0696. "Functional Criteria for Energency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/A enci.
  EISENHUT.D 9. Division of Licensing. 81/03/09. 6pp.

### 3 Insurance % indemnity information

- B103060312 Forwards Endorsement 45 to MAELU Policy HF-57
  HAJRFIELD, N. J. Marsh & McLernen, Inc., H & M Nuclear Consultants, I
  Div 81/01/27 2pp 07836:352
- P Operating license stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-O612 Forwards NRC position re-interia actions & request for add1 info EISENHUT.D 9 Division of Licensing 80/12/22 30pp
- 8103190397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown.replacement parts & NUREG-0737.
  EISENHUT.D 0 Division of Licensing. 81/01/19 App
- BiO3120014 Ltr to all licensess of operating plants CP holders & QL applicants, except Indian Point 2 & 3-Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC B01222 request for addl (nfo re control of heavy loads EIBENHUT, D G. Division of Licensing, B1/02/03 6pp
- B103030452 Forwards Amend 64 to Licenses DPR-32 & DPR-37, safety evaluation 3 notice of issuance & availability.

  VAROA, B. A. Operating Reactors Branch I B1/02/09. 2pp.

- DPR-37 . Office of Moclear Reactor Regulation, Director - B1/02/09 - 200
- --8103030476 Notice of issuance & availability of Amend 64 to Licenses DPR-32 & DPE-37 VAROA. B.A. Operating Reactors Branch 1 81/02/09 2pp
- B103040229 Forwards Amend 65 to Literise DPR-32 & notice of issuance
- VAROA.S A Operating Reactors Branch 1 81/02/10 3pp 07813 201
- --8103040243 Amend 65 to License DPR-32 incorporating steam generator inservice increase to the contents & reactor & secondary collant inding restoactivity contentrations into Tech Speck & deleting previous conditions VARGA. S.A. Operating Reactors Branch 1 81/02/10 25pp 07813 204
- --BiO3040249 Notice of issuance & availability of Amend 65 to License GPR-32 Ocerating Reactors Branch | B1/02/10 WARDA G A 07813 225
- RIDGRODIAD Lin to all grenating PWR licenses requesting info on 103300160 Etr to ail operating red licensums requesting invo-autiliary feedwater sys soismic design For-ards request for add info. list of actions requested of licensums w/o setsmically qualified sys % results of NRC walkinums ETBETHAUT.D Q Division of Licensing R1/02/10 13pp
- HIO3150569 Etr to all operating plants & CP holders furwarding clarification of TMI Action Plan Item III A 1 2 re operado of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENMUT.D 9 Division of Licensing 81/02/10
- 810225002) Lin to all power reactor licensees & license applicants re NARE9-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of elisting low flow controller EISE(HJT.D.C. Olysion of Licensing 81/02/20 App
- 8103110448 Informs that Amends 63 & 63 to Licenses DPR-32 & DPR-37. respectively, centain typographical error incorrectly referencing License Paragraph 3 k be added instead of 3 L Corrected amends entl
  VAROA.8 A Operating Reactors Branch | 01/02/24 2pp 0/072 202

11

- --8103110455 Corrected Amends 63 & 63 to Licenses DPR-32 & MPR-37, respectively-adding Paragraph 3 L re implementing & maintaining nuclear security personnel training & qualifications program VARGA, 8 A Operating Reactors Branch | BO/12/18 4pp 07872 284
- 8103050495 Forwards Amends 66 & 65 to Licenses DPR-32 & PPR-37. respectively, safety evalutation & notice of issuance & availability VARGA.S A Operating Reactors Branch 1 81/02/29 2pp. 07029 039
- --8103050502 Amends 66 & 65 to Licenses DPR-32 & DPR-37, respectively, allowing increase in enrichment for new & spent fuel VARQA.B A. Operating Reactors Branch 1 81/02/25 Upp 07825 037
- --Bi03050506 Safety evaluation supporting Amends 56 & 55 to Licensee DPR-32 & DPR-37, respectively # Office of Nuclear Reactor Regulation. Director 01/02/25 3pp

07829 045

- --B103050512 Notice of issuance & availability of Amends 66 & 65 to Licenses DPR-32 & DPR-37, respectively VAROA, 5 A Operating Reactors Branch 3 81/02/29 2pp 07825 048
- 8103230030 Ltr to all licenses of operating nuclear power plants & 103230030 Ltr to all licensess of operating nuclear power-applicants for OLs (except St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement energoncy procedures EISENHUT. 0 0 Division of Licensing 81/02/25 3pp
- 8103040333 Forwards responses to NUREO-0737 [ter II K 3 [7, completing ECCB outage info BYLVIA-B R Virginia Electric & Power Co B1/02/27 18pp 07820 163

GEORGE OF FOR Control Rod Reactivity Morth Determination by Hud Hoap Tochnique " manana MILLER, W.O. | License Fee Management Branch 97200 304

02BA3 194

- 0103100420 Responds to NURLG-0737, North Anna mosts dedicated hudro control ponetration requirements Requirements do not apply to Sorry Design changes are being Jevelaped to add remate perated isolation valves BYLVIA, 3 R Virginia Electric & Pages Co. UIVO.VOS
- BioD3:iOB:4 its to all licensees of operating plants applicants for 8 holders of CPs for adding SECY-Bi-119 to info necessary to establish environ qualification of safety related electrical nautoment EISEMBLE D O Division of Literating HIVO'NIO App
- 0100230637 Informs of delay in submittal of literam amend applicat to incorporate SIG to inservice surveillance requirements for southers, per 290 200120 request helay due to need for BTS format revision Application will be submitted by 110420 SYLVIA, 8 C. Virginia lighteric & Puwer Co. HI/O1/17 Ip 62977 BOB
- DE00260379 Advises of error in monthly operating repts for facility Roycest Figure for time 3, Design Electrical Rating, is Just Recessary corrections should be rade to MURO 0020 SHIVIA D.R. Virginia Electric & Power Co. 01/03/17 Ip 00007 301
- SIGNOIDS Chewards into re-effects of estended fuel buckings on industrial invarias into the affects of estanded fuel buttings in accident source terms & Indine spiking, in response to RHC verbal request, supplementing BODSID & HILD HOA little re proposed Tack Hyer changes to increase enrithment level Stylvia, B.A. Virginia Listete's & Power Co. 01703726. Elpp 00075 217
- o Inspection reports. It Bulletins & correspondence
- OLGANDON'S Followerds Revision N to response to II Bulletin 79 Oll. "Environ Qualification of Class IE Equipment" & BRC 1800807 arder for mad of license BYLVIA-D R Vinginia ( lectric & Power Co. 100/12/0) ACO TROLE
- 8103040807 Firewards 16 Insp Repts 20 280700 42 \$ 50 201700 46 on 0012031-05 No noncompliance noted POMPHIC C Region 2. Atlanta. Beactor Construction & Engineers Support Branck - DI/OI/26 to 0/HIE 165
- --8100040814 If Inar Repta to 200700 42 & 50 201700 44, on 001201 0 noncompliance noted Major areas inspected fullnump on 11. Bulletin HO II so measury wall design & status of const for steam generator replacement LERAMALJ J Region 2. Atlanta. Diffice of the Director CONLOR. T E. Region 2. Atlanta. Reactor Construction & Enginee Gopport Branch - BI/01/20 | 3pp 0/012 166
- 0103120441 Forwards It Insp Repts 50-200701-01 & 80 201701 Of pri beden sammilgmeanan ch vo-doing MUMPHY.C.C. Region 2. Atlanta, Reactor Construction & Engineers Support Drauch - 81/02/04 - 2pp - 87905 135
- -- 0103120448 IE Inap Repts 50-200781-01 & 50 201781-01 on 01010A 0 noncompliance noted Hajor areas impected Unit 1 stamper of moncompliance noted Hajor areas impected Unit 1 stamper generator repair & safety guide feedwater notice wolding records 2 Unit 2 inservice Into page 10 feed to 1 Unit 2 inservice Into Pffice of the Director HERDT. Region 2. Atlanta. Office of the Director HERDT. Region 2. Atlanta. Pactur Construction & Engineering Support Branch (1/02/03) 5pp 07905 137 HEADY.
- BIO3020177 Forwards IE Circular 81:-02. "Performance of NRC-License Individuals Unite on Duty." No written response required O'REILLY-J.P. Region 2. Atlanta. Office of the Director. #11/04 Lp 07785 291
- 8103190321 Forwards IE Insp Repts 50-280/80-44 & 30-281/80 48 on B01201-24 No noncompliance noted LEMB.R C. Region 2. Alianta: Reactor Operations Nuclear Buppor Dranch B1/02/11 2pp 07934-315

19032B IE Insp Repts 50-280/80-44 & 50-281/80-48 on 801301-24 No neggellance noted Major areas inspected operations & erating records plant mode & maint periodic testing & ant security

ant security RKE.D J. Region 2. Atlanta, Office of the Director LLCGC.P.J. Region 2. Atlanta, Reactor Operations Nuclear Support anch. B1/02/11 4p. 07954 319

0149 Forwards IE Info Notice 81-03. "Checklist for Licensees DIAY Forwards in Inter Notice Willows "Checklist for Licensees in Rocardance of Significant Events In Accordance CFR50 72 " No written response required ILLY.J P. Region 2. Atlanta. Office of the Director 81/02/12 07820 033

0713 Forwards 15 Info Notice 81-04, "Cracking in Main Steam s "No response required ILLY, J P Region 2, Atlanta, Office of the Director 81/02/27 07914 0BB

0564 Forwards IE Circular 81-03. 'Inoperable Seismic Monitoring rumentation'' No response required ILLY.J.P. Region 2. Atlanta. Office of the Director. 81/03/02 07916-343

0067 Forwards revised IE Bulletin Bl-Oi. "Surveillance of anical Snubbers." w/corrected Pages 5 & 6 Change in tification of facilities w/CPs to which bulletin is icable does not affect util requirements ILLY, J.P. Region 2. Atlanta, Office of the Director - 81/03/04 07939 189

0700 Ack receipt of B10119 ltr informing NRC of staps taken to ect violations noted in IE Health Physics Appraisal s 5)-280/80-29 \$ 90-281/80-33 S.R.C. Regian 2- Atlanta. Reactor Operations Nuclear Support th. 81/03/05 Ip 07912 072

130709 Responds to NRC 801218 Itr re violations noted in IE Health ysics Apprelsal Repts 50-280780-29 & 50-281780-33 rrective actions lead blankets immediately removed from reging pump piging & valves & supports insecuted supports insecuted .VIA.B.R virginia Electric & Power Co 81/01/14 lipp 712.073

130708 Forwards IE Health Physics Appraisal Repts 50-280/80-29 & -281/80-33, notice of violation, App 3 & significant praisal findings, App A

SEILLY J.P. Region 2. Atlanta. Office of the Director 12/18 Jpp 07712 084

130711 Notice of violation from health physics appraisal on 0805-15. Region 2. Atlanta, Office of the Director 80/12/09 400 12 000

130716 IE Health Physics Appraisal Repts 50-280/80-29 & -281/80-33 Noncompliance noted temporary lead shielding nikets wrapped around discharge piping of Unit I A.B & C orging purps Degamization chart encl ADDBKIR W., PUCKETTIJ M. WRAYJ R. Region 2. Atlanta Office the Director 00/12/09. 43pp 0/912 091

0314 Forwards IE Info Notice 81-06. 'Failure of ITE Model K-600 off Breaker." No response required ILLY, J.P. Region R. Atlanta, Office of the Director... 81/03/11 07969 010

N315 Ack receipt of 010303 ltr informing NRC of steps taken to ict violetions noted in IE Insp Repts 50-200/80-43 & 11/80-47

ORC. Region 2: Atlanta. Office of the Director 81/03/12

240322 Responds to NRC 810206 ltr re violations noted in IE Insp ts 50-280/80-43 % 50-281/80-47 Corrective actions leaks Unit 2 saleguards bldg noof repaired electrical cables ed & U bolts replaced or tightened. VIA.8 Virginia Electric & Power Co 81/03/03. 5pp. 86: 338.

240324 Forwards IE Insp Repts 50-280/80-43 & 50-281/80-47 on 112-26 & notice of violation. EILLY, J.P. Region 2, Atlanta, Office of the Director. 02/06. 2pp 07986:343.

40334 Notice of violation from Insp on 801112-26. Region 2. Atlanta. Office of the Director. 81/02/06. 2pp. 86:345.

- --8103240342 IE Insp Repts 50-280/80-43 % 50-281/80-47 on 801110-26 Noncorpliance noted leakage found in Unit 2 safeguards bldg Rasidual heat renoval piping had broken floor support & numinum neat removal piping had broken floor support \$
  U-bolt pipe supports were loase-niseing or broken
  SURME,D J Region 2. Atlanta, Office of the Director
  MELLOSO P J Region 2. Atlanta, Reactor Operations Nuclear Support
  Branch BI/02/06 Epp 07980 317
- Palisades 'No response required Greiter of the Director B1/03/13 ip 07969 094 BIO3200030 Forwards IF Info Notice 81-05, "Degraded DC Sys at
- B103270053 Forwards 1E (nep Repts 50-280/81-05 & 90-281/81-05 on B10209-12 t notice of violation LEWIS.R C Region 2. Atlanta. Office of the Director 81/03/13 200 08045 160
- --8103270056 Notice of violation from insc on 810209-12 Region 2, Atlanta, Office of the Director 81/03/13 1p. 09049 182
- ~-8103270072 IE Insp Repts 50-280/81-05 & 50-281/81-05 on 810209-12 ivaeruvre it insp meets 50-280/81-05 & 50-281/81-05 on 810209-12 Noncompliance noted radiographic films not in compliance W/film density requirements EAJACL, D. HERDTIA R. Region 2. Atlanta, Office of the Director BI/03/09 6pp 08045 183
- 8103310828 Act receipt of 810313 ltr informing NRC of staps taken to correct significant appraisal findings & violations noted in IE Insp Repts 90-280/80-29 & 50-281/80-33 LEWIS, R.C. Region 2. Atlanta. Office of the Director ip 38061 086
- R Periodic operating reports & related correspondence
- BiO3060307 Forwards "Ropt of Redicactive Effluents" & "Radiological Environ Monitoring Rept." CVO annual repts for facility W/o "Ropt of Radioactive Effluents" SYLVIA. B R Virginia Electric & Power Co 81/02/27 (p 07837 339
- --B103060316 'Redicingical Environ Monitoring.CY 80 "
  MDHL.K A. CHANDRASEKARAN Eberline Instrument Corp B1/02/23
  75pp 97837 336
- 8103170333 Forwards monthly operating repts for Feb 1981 SYLVIA:B R Virginia Electric & Power Co 81/03/13 In 07923 350
- --8103170338 Monthly operating repts for Feb 1981 DUNN-8 D Virginia Electric & Power Co 81/03/05 42pp 07923 351
- S Reportable occurrences. LERs & related correspondence
- 8103040479 PNO-11-81-019 on B10223 & 24.during steam generator NUJOUNTY PROFILED OF ON BLOCKE & 24, ouring steen generator replacement outego, ultrasonic ling detected linear defect in base metal on pipe in 30-inch main steam line of steam generators A.B. & C. Cause under linestigation SHYMLOCK.M. DANCE.H. Region 2. Atlanta. Office of the Director. 81/02/25 2pp 07812 340
- 8103130470 Forwards LERs 81-014/03L-0 & 81-019/03L-0 & updated LER. 80-063/01X-1 WILSON, J.L. Virginia Electric & Power Co. 81/03/09. 1p. 07913:092
- --B103130477 Updated LER B0-063/01X-1 on B01117 Vascomar cap screw in steam generator A leveling pads brots during disassembly Caused by stress corrosion cracking Borews replaced WILEGU.J.L. Virginie Electric & Power Co. B1/03/09 2pp. 07913.097.
- 8103170579 Forwards LER 81-001/017-0 WILSON, J. L. Virginia Electric & Power Co. 81/03/11 1p.
- --- 8103170585 LER 81-001/01T-0. on 810225. w/onit defueled for steam generator replacement routine testing exam of loop A main steam piping revealed linear Indications Caused by corrosion pitting Subj areas will be repaired.

  WILSON.J.L. Virginia Electric & Power Co. 81/03/11. 3pp 07939.245

- 0103231090 Part 2: rept.originally reported 790529 re steam generator feet polt hole discrepancies Corrogian removed Austed & galted threads cleaned by running helical tap into bolt holes prior to new relicois installation SYLVIA.3 R. Virginia Flectric & Power Co. 01/03/11 Jps 07973-012
- 8103240514 Forwards updated LER 80-052/03x-1 WILSCRUT Virginia Electric & Puwer Cii 81/03/19 Ip 07984 338
- 9103310535 Forwards LER 81-004/03L-0 WILSON J L. Virginia Electric & Power Co. 81/03/27 36 CRC81 211
- --8103310582 LER 31-004/03.-0 on B10225 radiation resistor resorder RR-1/5 found to be printing erratically Caused by loose goer on balance materializing drive cable to also Bet scraw on drive gear tigstened 5 unit returned to set 61500.0 L vinginia flectric & Power Co B1/03/27 2pp 00001 212
- DOCKET 50-251 SURRY POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 6103180264 Litrito all power reactor licenses u/plants licensed prior to 790101 Forwards 190 position & request for addlinfo resafe shuddown capability for compliance u/801119 fire protection rule EISERHRUT, D.C. Division of Licensing 81/02/20 13pp
- B103040366 Supple C01215 response to NUREC-0737 re energency preparedness kept will not be completed until B10415 Backup esteorological tower especial statectisties & strip chart recorders at Surry will not be installed until B10801 SYLVIA-D R Virginia Electric & Power Co. 81/03/27 2pp 07820 149
- 8103310338 Ltr to all licensoes of operating plants & holders of CPs forwarding NURFG-0696. "Functional Criteria for Emergency Response Factitisies " Criteria describe acceptable method for meeting NRC requirements NPO encl EISENHUT. D 0 Division of Licensing 81/03/03 622
- J Insurance & indemnity information
- B103060312 Forwards Endorsement 45 to MAELU Policy MF-57
  HAIRFIELD X J. Marsh & McLennan, Inc., M & M Nuclear Consultants. Inc.
  DIV. 81/01/27 2pp
- P Operating license stage ducurents & correspondence
- 9103190732 Litrs to all licensess of operating plants, applicants for DLs & holders of CPs re-control of heavy loads Requests review per guidelines in NORCO-0612 Forwards NRC position re-interim actions & request for addlinfo EISENMUT.D 0 Division of Licensing 80/12/22 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related objectrical equipment leams addressed involve cold shutdown, replacement parts & NuREC-0737.

  EISEN-MUT. D. G Division of Licensing 01/01/17. App
- B103120014 Lir to all licensess of operating plants.CP holders & CL applicants.ercept Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvertently dmitted pages from NPC 801222 request for add1 info re control of heavy loads. EISENHUT.D O Division of Licensing 81/02/03 6pp
- B103030452 Forwards Amend 64 to Licenses DPR-32 & DPR-37, safety evaluation & notice of issuance & availability VARQA+S A Operating Reactors Branch 1 81/02/09 2pp
- --B103030463 Amend 64 to Licenses DPR-32 & DPR-37, revising Tech Operation incorporate clarification of definition of operable & adding general limiting conditions for operations VAROA.S A Operating Reactors Branch | B1/02/09 30pp.

- --Biogono470 Eafet, evaluation supporting Amend A4 to Licenses DPR ... BPR-37 • Office of Nortean Reactor Regulation, Director ... HIVD2709 ...
- BIO3030476 Natice of Issuance & availability of Arend 54 to Citebra OPR-32 & CPF-37 VAR9A-5 A - Uperating Reactors Drench L - H1702707 - 32p
- BIOGRAPH Ltr to all operating PMM licensess requesting into on auxiliary feeduator sys serents design Formaris request for add into list of actions requested of licensess win setancially qualified sys & results of NMC walkdowns CISCHMUT.N G Division of Licenseing HIVOW/IO lipp
- DIO3160669 Ltr to all operating plants & CP holders forwarding clarification of tel Action Plan Item III A 1 2 re upgrade of energency support facilities Requests confirmation within 43 days that implementation dates will be net DISCHMULD O Bivision of Licensing 81/02/10 12pp
- 0103230024 Ltr to all power reactor licensees & license applicants of NUMEQ-CATY criteria Fouthous 2 to table 2 contains error due to teakage testing detections ticensee and entmit analysis to justify use of exteting low flow controller EISEMEDID 9. Division of alcensing. HIZOZZO Upp.
- 0103110440 informs that Amends 70 & 20 to typeness NPR-32 & DPR-37, respectively, contain typographical error incorrectly referencing license Paragraph 3 & be added instead of 3 to Corrected arends encl.

  Corrected arends encl.

  VANCA-8 C (learneting Reartors Branch 1 04702/24 2pp 07072 -
- HIBOLITOADD corrected Amends hit to it to the DER 12 to BER 17. respectively, adding Paragraph 7 to re implementing to maintaining nuclear security personnel training to qualifications program VAROA 0 A Operating Beauties Diench 1 DD/12/11 App. 070/2-2014
- B10.000495 Furnance Asends &A. & &5 to Licenses BPA DE & DPA DA. cospectively, eafety evalutation & untice of lessance & availability
- availability
  VARQA.S.A. Operating Reacture Branch t 01/02/20 Upp 0/04/20 C
- -- ONDOISSOUR Amends AS & AS to ticenses DPR-32 t NPR-32 treeps.tively allowing increase in envicement for new 6 spent fuel VAROA.9 A uperating Reactors Branch 1 01202/25 Upp 02025-032
- -D103050506 Safety evaluation topeorting Amends && & 65 to Econes.

  DPR-32 & DPR 17. respectively

  w. Office of Nuclear Reactor Regulation. Director. B1704725
- G/023 045
- W-HOU050512 Rotice of issuance & availability of Amenda AA & AS to Liceuses BPR 32 & UPR 32 respectively VAROA, B A - Operating Reacture Branch 3 - HEZO2725 - 2pp 07125-040
- 0103230030 Ltr to all licensees of operating nuclear power plents & applicants for (R's fercept St Lucis Units 1 & 2) Requests util review to determine capability to mitigate station blackout event b promptly implement emergency procedures EISERHUT, D. 0. Hivision of Licensing (BI/02/25) Spp.
- Bio3040033 Forwards responses to MOREO-0737 Stem 11 K 3 17-tumpletts ECCH outage info STLVIAL D R Virginia Electric & Power Co - HIZO2ZZZ - IMpp 07020 163
- BIOD120023 Notifies of fee required for review of VEP-FRD 34. "Control Rud Reactivity Worth Determination by Rod flwap Technique" HILLER. W.D. License Fee Hanagement Branch (81703702 ip 07900-304
- BIDDIO0420 Responds to NURCO 0737 North Anna meets dedicated hydrogonization penetration requirements Requirements do not apply to Burry Design changes are being developed to addiremote operated isolation valves
  BYLVIA:B.R. Virginia Electric & Power Co. BI/03/05 ip
  07863.175

- 8103310804 Ltr to all licensees of operating plants applicants for CLs tholders of CPs porwarding SECY-81-119 re infu necessary to establish environ qualification of safety-related electrical equipment presentution of CLs and Park to CLS
- 8103260246 Forwards Amend 66 to License DPR-37. safety evaluation to notice of issuance to availability VARQA. 8 Operating Reacture Branch ( 81/03/16 2p; 08042 004
- --8103260260 Amend 66 to License DPR-37, providing one time 30-day extension for visual insp surveillance requirement for inaccessible snubbers VARGA. B A Operating Reactors Branch 1 Bi/03/16 4pp 080402 006
- --8103260269 Safety evaluation supporting Arend 66 to License DPR-37

   DFFIce of Nuclear Reactor Regulation, Director B1/03/16 2pp
- --Bi03260280 Notice of issuance & availability of Amond 66 to License CPR-37 VARGA:S.A. Operating Reactors Branch 1 81/03/16 2pp
- 8103230637 Informs of delay in submitted of license amend application to incorporate STG re inservice surveillance requirements for smubbers, per NRC 601120 request. Delay due to need for STG format revision Application will be submitted by 810420 SYLVIA.8 R Virginia Electric & Power Co 81/03/19. 1p 07977 020
- B103280379 Advises of error in monthly operating repts for facilities Correct figure for Line 3. Design Electrical Rating. is 700 Necessary corrections should be made to NNEGO-0020. SYLVIA-B R Virginia Electric & Power Co H1/03/19 1p 08037, 351
- 8103310965 Forwards info re affects of extended fuel burnups on accident source terms & Lodine spiking. In response to NRC verbal request supplementing 800919 & 810306 ltm reproposed Tech Spac changes to increase enrichment level SYLVIA-B R Virginia Electric & Power Co 81/03/26 13pp 08075-217
- G. Inspection reports, IE Bulletins & correspondence
- 8103250656 Forwards Revision 2 to response to IE Oulletin 79-01B. "Environ Qualification of Class IE Equipment" & NRC 000027 order for mod of license SYLVIA.B R Virginia Electric & Power Co 80/12/01. 51pp. 07997 026
- 8103040B07 Forwards IE Insp Repts 50-280/80-42 & 50-281/80-46 on B01203-05 No noncompliance noted.

  KURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch B1/01/20 Ip 07812 165
- --Bi03040B14 IE Insp Ropts 30-280/B0-42 & 50-281/B0-46 on B01203-05 No noncompliance noted Major areas inspected following on IE. Bulletin B0-11 re mesonry wall design & status of const for steam generator replacement LENAHAN, J. Region 2. Atlanta, Office of the Director CONLDN.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Granch B1/01/20 5pp. 07812 166.
- 8103120441 Forwards IE Insp Repts 90-280/81-01 & 50-281/81-01 on B10106-09. No noncompliance noted. MXRPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/04. 2pp. 07905:135.
- ~-8103120448 IE Insp Repts 50~230/81~01 & 50~281/81~01 on 810106~09 No noncompliance noted Major areas inspected: Unit 1 steam generator repair & safety guide feedwater notile welding records & Unit 2 inservice insp rept.

  BLAKE.J.J. Region 2. Atlanta, Office of the Director. HEROT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/02/03. Spp. 07905:137.
- Si03020177 Forwards IE Circular B1-02, "Performance of NRC-Licensod Individuals While on Duty." No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director G1/02/09 to.
- 8103190321 Forwards 1E Inep Repts 50-200/80-44 & 50-281/80-48 on 801201-24 Na noncompliance noted. LEMIS.R.C. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 81/02/11. 2pp. 07954:317.

- \*\*-8103190328 IE Insp Ropts 50-260/80-44 & 90-281/80-48 on 801201-24 noncompliance noted Major areas inspected operations & operating records, plant mode & maint-periodic testing & plant security BURKE, D J. Region 2. Atlanta. Office of the Director XELLOGO, P. J. Region 2. Atlanta. Reactor Operations Nuclear Supp Branch 81/02/11 4pp. 07954-319
- B103040149 Forwards IC Info Notice B1-03. 'Checklist for Licensess Making Notifications of Significant Events In Accordance W/1007850 72 'No written response required O'REILLY.J P. Region 2. Atlanta. Diffice of the Director B1/02/1: no. 07829 033
- 0103160713 Forwards IE Info Natice 81-04. "Cracking in Main Stear Lines " No response required U'REILLY.J P. Region 2. Atlanta. Office of the Director 81/02/2 1p. 07914-088
- B103160964 Forwards IE Circular B1-03. 'Inoperable Geismic Monitorin Instrumentation' No response required. D'REILLY, J.P. Region 2. Atlante, Office of the Director B1/03/0
- 8103170067 Forwards revised IE Bulletin B1-01. "Surveillance of Pechanical Shubbers." w/corrected Pages 5 % & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. O'REILLY-J P. Region 2. Atlanta. Office of the Director 81/Q3/0-16
- B103130700 Ack receipt of B10119 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Repts 30-280/80-29 % 50-281/80-33 LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/03/06 Ip 07912 072
- --BIO3130705 Responds to IRC 801218 ltr re violations noted in 1E HePhysics Appraisal Repts 30-280/80-29 5 50-281/80-33
  Corrective actions lead blassets incodiately renoved from
  Charging pump spiring 5 valves 5 supports inspected.
  SYLVIA-8 R Virginia Electric 5 Power Ca 81/01/19 11pp
  07912-073
- --810313070B Forwards IE Health Physics Appressa) Repts 50-280/80-27 50-281/80-33 notice of violation.App B & significant appraisal findings.App A CREILLY.JP Region 2. Atlanta. Office of the Director 80/12/18 3pp 07912 084
- --8103130711 Notice of violation from health physics appraisal on 800809-15

  # Region 2. Atlanta. Office of the Director 80/12/09 4pp 07912.088
- --8103130716 IE Health Physics Appraisal Repts 50-280/80-29 % 90-281/80-33 Noncompliance noted temporary lead shielding blankets wrapped around discharge plaing of Unit I A.B & C tharging pumps Organisation thert encl ZAVADOSKI,R K. PUCKETT. JR J. Region 2. Atlanta, Office of the Director. 80/12/09 43pp 07912.091
- 8103200314 Forwards 1E 1nto Notice B1-05. 'Fallure of ITE Model K-600 Circuit Broaker' No response required.

  B'REILLY J P Region 2: Atlanta, Office of the Director B1/03/1.

  1p 07949 040
- 8103240315 Ack receipt of B10303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-43 & 50-281/80-47 LENIS.R C. Region 2. Atlanta. Office of the Director 91/03/12 lp. 07986 337
- --8103240322 Responds to NRC 810206 ltr re violations noted in 1E Inc Repts 50-280/80-43 & 50-281/80-47 Corrective actions: leaks in Unit 2 safeguards bidg roof repaired electrical cables dried & U bolts replaced or tightened SYLVIA.E R Virginia Electric & Power Co 81/03/03. Spp 07986-338
- --8103240324 Forwards IE insp Repts 50-280/80-43 t 50-281/80-47 on 801112-26 t notice of violation O'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/02/06 2pp 07986 343
- --8103240334 Natice of violation from insp on 801112-26

  \* Region 2. Atlanta, Office of the Director. 81/02/06. 2pp.
  (7986-345

- --B103240342 IR Insp Repts 50-280/80-43 & 50-281/80-47 on B01110-26 Noncompliance noted leakage found in Unit 2 safeguards bldg Realdual heat removal piping had traken floor support & U-bolt pipe supports were loosen-missing or broken BurME.D J Region 2. Atlanta. Office of the Director MELLOSS.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/06 Upp 07988 347
- 0103200030 Forwards 1E Info Notice 81-05. 'Degraded BC 89s at Palisades 'No response required D'REIGLY-J P Region 2. Atlanta. Office of the Director 81/03/13
- 8103270053 Forwards IE Irsp Repts 50-280/81-05 & 50-281/81-05 on 810209-12 & notice of violation LEWIS-R C Region 2. Atlanta. Office of the Objector 81/03/13 2pp 03045 180
- --8100270056 Notice of violation from insp on 810269-12

   Region 2. Atlanta. Office of the Director 81/03/13 (a) 08045-182
- --8193270072 IE Insp Repts 50-280/81-05 t 50-281/81-05 on 810209-12 Noncompliance moted radiographic files not in compliance w/file density requirements ZAJACL D. HERDT.A R. Region 2. Atlanta. Office of the Director 81/03/09 App. 08045 183
- 8103310828 Act receipt of 810313 itr informing NRC of steps taken to correct significant appraisal findings & violations noted in IE loss Repts 50-280/80-29 % 50-281/80-31 LEMPS, RC Region 2. Atlanta. Office of the Director 81/03/26 tp. 08061 086
- R Periodic operating reports & related correspondence
- 8100060907 Forwards "Rept of Radioactive Effluents" & "Radiological Environ Monitoring Rept." CYBO annual repts for facility W/c "Rept of Radioactive Effluents" SYLVIA: 0 R - Virginia Electric & Power Co - 81/02/27 - Ip 07/03/335
- --8103020336 "Radiological Environ Monitoring.CY 80
  KCHL.K A. CHANGRASEKARAN Eberline Instrument Corp. 81702723
  75cc 07837 836
- 8103170333 Forwards northly operating repts for Feb 1901 SYLVIA.3 R Virginia Electric & Pawer Co. R1/03/13 1 07923 330
- --8103170338 Monthly Operating repts for Feb 1781

  DUNNIS B Virginia Electric & Power Co 81/03/05 43pp
  07923 351
- 5 Reportable occurrences. LERs & related correspondence
- B103060593 Forwards LERs 81-005/03L-0, 81-008/03L-0 & B1-017/03L-0 WILBOW, J L Virginia Electric & Power Co B1/03/02 Ip 07837 174
- --8103060596 LER 81-005/03L-0 on B10204.air motors for preferred start 2 of evergency diesal generator 3 found engaged to flycheel Caused by air leakage through solenoid valve Butenoid & air motors replaced WILSON. U. Virginia Electric & Power Co. 81/03/02 2pp 07837 175
- --BIO3060600 LER 81-0CG/O3L-0. on 810206, output amperage for RM-CC-106 reduced in nonconservative direction Caused by failed revolvindicator module in auxiliary blog Module toolated & RM-CC-106 recalibr Monitor will be repaired WILSON. J L Virginia Electric & Power Co 61/03/02 2pp 07837. 177
- --8103060502 LER B1-017/03L-0 on B10210 internediate range channel N36 high level trip setpoint found in excess of Toch Spec Caused by setpoint drift Setpoint adjusted \* Virginia Electric & Power Co. B1/03/02 2pp 07837-179.
- B103100635 Forwards LER 81-010/03L-0 WILSO:A.J. Virginia Electric & Power Co B1/03/06 1p 07862.350
- --B103100639 LER B1-010/03L-0 on B10209, ave water pump, 2-S4-P-10B, developed low discharge pressure. Caused by eel lodged in topeller. Eel removed & pump returned to sve NILSON. J. L. Virginia Electric & Power Co. B1/03/06. 2pp 07862 351

- #103130470 Forwards (EMs #1:014703L=0 & #1:014703(-0 & updated t18 mo-os3701-1 #118f(2.3 t Virginia Electric & Power Co #1703709 tp 07913 992
  - -8103130472 LER 81-014703L-0 on D10212-RM LC-10A alarm setpoint foun outside tach Spoc Caused by personnel error Notpolists reset 81LECS-U L Virginia (Jectric & Power Co. 111703709). App. 07913-0794
- --0100100475 LFR BI-017700L-0 on BI0210, ampliedings for heat tracing panel 9, circuit AA wore low Caused by excessive heat Heat tracing replaced WILDCS-0.L Virginia Clectric & Power Co. BI7703709 App. 07913-079
- 0103190651 Forwards tER 01-0207000-0 HLSCOLJ L - Virginia Electric & Power Co - (01701716 - 1p 07963-067
- -8103190694 LER 81 020/03L-0 on B10223 during full power RR Cr. 10% a thigh alarm lights energized w/n initiating required automatic action Coursed by failed card in alarm circuit Card replaced 5 tested WILSON J. Virginia Electric & Power Co. WIZD VIA . App. 07963-048
- DUCKET 30-202 PRATRIE THEAND NGCLEAR STATISHE UNIT 1
- F. Security, medical, emergency & fire protection plane
- DIOLO70540 Releases public version of util upgraded emergency plant FELICH, J.B. Division of Rules and Recurds 100712701. Ip 07404-001
- -8101070352 Public version of appraded emergency plan
   Northern States Power Co. 80703715 103pp. 07404-002
- HIGHOROUPA Releases public version of util deaft emergency plan EEC.TO%, J. H. Olvisjon of Rules and Hecords (HO/TE/O) IP
- ~- (HODI7COO) Forwards public version of draft emergency plan MAYER 1 D Northern Diales Power Cu 797137.11 ip 01443-292
- -- H101000203 Public version of draft energency plan 4 Northern Blates Power Co. 79/12/31 Adep
- 8103050246 Approves B10209 request for extension of installation date of fire pump encil & related day tank curbing to B10501 in notice encil
  DENTON IR R. Office of Nuclear Reactor Regulation. Director B1702/13 Opp. 07802 112
- --0103050207 Notice of extension of installation date of fire pump en related day tank curbing to 010601 CASE.E 9 Office of Nuclear Reactor Regulation. Director Bi/02/13 ip 07038 115
- DIDDOSONO Releases public version of revised emergency plan-FCLTON. J.M. Division of Rules and Records (\$1702/17 1p 07006-03)
- --8103050307 Forwards public version of revised emergency response pl in response to MRC U01114 ltr Alert & notification status rept encl HAYER, U Northern States Power Co. U1/02/06. Jpp
- --BIO0050313 Public version of revised emergency response plan \* Northern States Power Co 81/02/28 000pp 0780A 001
- 0103100264 Ltr to all power reactor licensees w/plente licensed prior to 790101 Forwards ARC position & request for addition of compilance w/801119 fire protection rule

  EIDERHUUT-D O Division of Licensing 01/02/20 13pp

sponse Facilities "Criteria describe acceptable method sponse ractities "Criteria asseride acceptable me r meeting ARC requirements N/a encl SENAUT.D O Division of Licensing B1/03/05, App

130228 Forwards Revision 3 replacement page to "Emergency eparedness-Evacuation Time Estinates," dtd Apr 1980,per 1209 request YRR.L O Northern Status Power Co 81/03/[1 1p 07907 084

03130234 Revision 3 to "Evecuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant " • Northern States Power Co. 81/03/11 2pp 07907-089

261052 Forwards emergency planning info for placement in LPDR W/o 03050301

Division of Rules and Records 81/03/11 10 UDER. J.L. 040. 271

180529 Requests extension of schedule requirements of incerso. ctions 50 48 (c)(2).(c)(3). & (c)(5) re completion of Ann fire protection mode

YER.L D. Northern States Power Co. 81/03/13 App. 07943 355

240354 Advises to implementation of fire protection mode not evipusly accepted by NRC Evaluation of emergency lighting s will be completed by BI(II7.DII collection sys mude for actor coolant pump are scheduled after B10816 yER.L D Northern States Power Co DI/O3/19 3pp 07990 142

inancial information

200215 Forwards Annual Financial Rept 1980 UBVEN. A.D. Narthern States Power Co. 81/03/17 40pp. 07968:221

03200222 Annual Financial Rept 1980 MCCARTHY, D., LARBON, C. Northern States Power Co. 81/03/17. [o 07968 222

nsurance & indemnity information

030730 Forwards Endorsement 4 to MAELU Binder x8-36 H/o Endorsement to MAELU Binder x8-37 HNBON.R. G. Northern States Power Co. 81/02/24. 3pg 07796 057.

170350 Forwards Endorsement 5 to MELIA Dinders E8-36 & E8-37 & ELU Binders X0-37 & XB-36. 4480N.R Q. Northern States Power Co. 81/03/10. 7pg 07924 048

perating license stage documents & correspondence

190732 Ltre to all licensees of operating plants applicants for a 3-halders of CPs re control of heavy loads. Requests view per guidelines in NUREO-0612 Forwards NRC position re terim actions & request for addl info SENHUT, D. O. Division of Licensing, 80/12/22, 30pp

190387 Ltr to all licensees of operating plants & applicants for s & holders of CPs re program for environ qualification safety-related electrical equipment, items addressed volve cold shutdown replacement parts & NUREO-0737. SENHUT-D O Division of Licensing 81/01/19. App

120014 Ltr to a]] licensees of operating plants,CP holders & OL licents.except Indian Point 2 & 3,7ion 1 & 2 & TMI-1, warding inadvertently omitted pages from NRC 801222 quest for add1 info re control of heavy loads. ERMUT.D.G. Division of Licensing. 81/02/03. App.

300160 Ltr to all operating PWR licensees requesting info on illary feadwater sys selsmit design forwards requesting the citiany feadwater sys selsmit design forwards request for li info. list of actions requested of licensees w/o semically qualified sys & results of NRC uelkdowns. SENHUT, D Q Division of Licensing 81/02/10 13pp

.60649 Ltr to all operating plants & CP holders forwarding prification of TMI Action Plan Item III.A 1.2 re upgrade emergency support facilities Requests confirmation within days that implementation dates will be met. ERNHUT.D.O Division of Licensing. 81/02/18. 12pp.

90176 Forwards organizational charts depicting NRC Region 3 rgenization, effective 810216. PLER.J. 9 Region 3, Chicago, Office of the Director. 81/02/20. 07852.104.

to leakage testing Seletions Licensee may submit amelysis to justify use of existing low flow controller EISE(MAYL) O Division of Licensing 01/02/20 App

KUNEG-NATY CLICACIA PROTOCEO - 10 IASTA - CONCAINS

- 8103050519 Forwards Amends 40 % 39 to Licenses DPR-42 & DPR-60.
  respectively & notice of issuance & availability
  CLARK.R A Decrating Reactors Branch 3 81/02/25 3pp 07825 092
- -- 8103050527 Amends 45 & 39 to Litenses DPR-42 & DPR-60, respectively. adding requirement to maintain safeguards contingency plan to be implemented within 30 days & guard training & qualification plan within 60 days CLARM.R A Operating Reactors Branch 3 81/02/25 App. 07825 055
- --BIO3050522 Notice of issuance 3 availability of Amends 45 & 39 to Licenses DPR-42 & DPR-60, respectively CLARA:R A Cycrating Reactors Beanch 3 81/02/25. 2pp 07825 059
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for Districtionses or operating noticer power applicants for Districtions St. Lucis. Units 1 & 2) Requests util review to determine capability to mitigate station blockout event & promptly implement emergency procedures EISE(AMUI.D 0 Division of Licensing 81/02/25 Spp
- 8]03]33]40 Forwards Amends 46 & 40 to Licenses DPR-42 & DPR-60, respectively & notice of issuance & availability CLARK.R A Licensing Branch 3 81/03/02 3pp 07907 298
- --Bi03130146 Amends 46 \$ 40 to Licenses DPR-42 & DPR-60, respectively, incorporating new requirements for instruments & equipment & shift manning, resulting from NRC assessment of TNI-2 CLARA.R A Dograting Reactors Branch 3 81/03/02. 32pp 07707.301
- --8103130150 Notice of issuance % availability of Amenda 46 % 40 to Licenses DPR-42 & DPR-60, respectively CLARM, R. A. Diperating Reactors Branch 3 81/03/02 2pp 07907 223
- 8103170158 Forwards responses to NRC 801109 questions to fuel storage facility and Earlier responses were forwarded 801121-810114 MAYER-L O Northern States Power Co 81/03/10 20pp 07925 274
- 8103310804 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs forwerding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D. O. Division of Licensing. B1/03/10 App
- 8:03310616 Forwards BNL review of util analysis of alternate safe shutdown capability for facility originally submitted 791022 Concurs w/BhL conclusion that proposed mods do not cost USC criteria CLARK, R.A. Operating Reactors Branch 3 81/03/23, 2pp 08059 165
- 8103310178 Informs that implementation of NUREG-0737, post-Tml Item i & 5 requirement, will be delayed until 810701 due to mgt procedures being written in series rather than in parallel Procedures build on requirements per higher level directive MAYER.L O Northern States Power Co 81/03/27 ip 08062 318
- Q. Inspection reports. IE Bulletins & correspondence
- 8103090794 Forwards IE Insp Repts 50-282/80-20 & 50-306/80-20 on #801201-31 No noncompliance noted.

  HEIBHMAN.R F. Region 3- Chicago, Reactor Operations Nuclear Support Branch. B1/01/20. 200 07849 230
- --8103090797 IE insp Repts 50-282/80-20 & 80-306/80-20 on 801201-31 No noncompliance noted Major areas inspected plant operation, maints surveillance, security & IE bulletin Followp.
  FEIERABERIO. C. D. BURGESB. B. L. LITTLE, U. S. Region 3, Chicago, Office of the Director 81/01/20 ip. 07849 232.
- D103130677 Forwards IE Mgt Meeting Repts 50-263/80-21,50-282/80-21 & 50-306/80-21 on B01121 KEPPLER.J Q Region 3. Chicago, Office of the Director 81/01/20 2pp. 07913-267.

- 90-304/80-21 on 801121 Areas discussed regulatory performance of activities at facilities per systematic assessment of licensee performance program REISHMAN, R.F. Region 3. Chicago, Reactor Cherations Nuclear Support 2 canth. 81/01/13 16pp 07913 269
- BIO3D2OCB3 Responds to 16 Builletin BinOl No snubbers of type described are in use or planned for use in safety-related syst. Off.BERTS.D E. Northorn States Power Co. 81/02/06. 2pp. 07785-020
- 9103020067 Forwards IE Circular Blm02. 'Performance of NRC-Licensed Individuals While on Dut, 'ho written response required AEPPLER. J G Region 3. Chicago. Difice of the Director 81/02/09 2pp 07787 290
- 9103049272 Forwards IE Info Notice B1-00. 'Checklist for Licensees Maling Lotifications of Significant Events In Accordance M/100FR50-72" 'No written response required MEPPLER, J.G. Region D. Chicago, Office of the Director 81/02/12. 2pg 97813-307
- 3:03190049 Forwards JE Insp Repts 50~282/81-02 & 50-306/81-02 on 810101-31 in mencaptisance noted HEIEHMAN,R F Regson 3. Chicago, Reactor Operations Nuclear Support Branch 81/02/12 2pp 07964 102
- --BIO3190058 1E Insp Repts 90-282/81-02 1 50-306/81-02 on BI0101-31 No noncompliance robus Major areas inspected plant operation, maint surveillence security, radiation protection & following on IE bulletins FEIERAGENO.C D., SURDESS, B.L., LITTLE, W.S., Region D. Chicago, Office of the Director BI/02/11 opp 07964-104
- 3103160705 Forwards 1E Info Notice 61-04, 'Cracking in Main Steam Lines." No response required KEPPLER.J G Region 3, Chicago, Office of the Director 81/82/27 2pp 07914 076.
- B103160521 Forwards IE Circular B1-03. "Inoporable Beismic Monitoring Instrumentation" No response required PEPPLER./ O Region 3. Chicago, Office of the Pirector 81/03/02 2p; 07916:318
- 3103160978 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Enubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements XEPPLER. J G Region 3. Chicago. Diffice of the Director 81/03/04 p. 07915 001
- 310320038) Forwards (E Info Notice 81-06. "Failure of ITE Model M-600 Circuit Brooker" No response required AEPPLER.J.O. Region 3. Chicago. Office of the Director D1/03/11 2pp. 07972 133
- 8103200693 Forwards IE Info Notice 81-05, 'Degraded DC 64s at Palisades.' No action required KEPPLER.J.O. Region 3. Chicago, Office of the Director 81/03/13 2pp. 07966 128
- BiO3200333 Foruards is info Notice Bi-07. 'Potential Problem
  WWater-Soluble Purge Dar Matis Used During Inert Gas
  Wolding.' No response required
  XEPPLER.J O. Region 3. Chicago, Office of the Director. Bi/03/16
  2pp. 07966.280
- . Periodic operating reports & related correspondence
- 0103030565 Forwards "Annual Operating Rept. 1980 ' Covers occupational exposure: changes, tests & experiments & safety valve & relief valve failures & challenges (MAYER. D. Northern States Power Co. 81/02/27 ip 07793,215.
- twicking a Monthern oraces notes to \$1,0555. 1b 05543'512'
- -8103030979 "Annual Operating Rept,1980." Covers occupational esposure, changes, tests & asportments & sefety valve & relief valve failures & challenges \* Northern States Power Co 81/02/27 12pp. 07793 216
- 3103030828 Forwards "Effluent & Waste Disposal Semiannual Rept for Jul-Dec 1980." MAYER.L O Northern States Power Co. 81/02/27 12 07793 177
- -9103030835 "Efficent & Wasto Disposal Gemiannual Rept for Jul-Dec 1980 " • Northern States Power Co. 81/02/27 9pp. 07795.178
- 003100356 Forwards nonthly operating repts for Feb 1981. MAYER, L. O. Worthern States Power Co. 01/03/09 ip 07064 361.

- 97865 CO1.
- 0103270477 Forwards "Annual Radiation Environ Monitoring Program, 1980 WARD-E C Northern States Poter Co 81/03/25 ip 08043 091
- --8103270462 'Annual Radiation Environ Monitoring Program, 1980 "
  HUED:ER. L G Haialton Environmental Sciences Corp 81/02/26
  34pp 08043 092

HJISTAD, A A Horthern States Power Co. 81/03/01 Boo

- 8103310209 Forwards revised Page 1 of "Effluent & Waste Disposal Semjannual Rept." reflecting correct reporting period of Jul-Dec 1989 TAYERLO. Northern States Power Co. 81/03/27 Ip. 08062-319
- --8103310357 Revised Page 1 of 'Effluent & Waste Disposal Schlannual Rept.Jul-Dec 1960 " • Northern States Fouen Co. 81/03/27 | 12 08062-320
- DOCKET 90-284 IDAHO STATE UNIV RESEARCH REACTOR
- 3. Inspection reports: IE Bulletins & correspondence
- B103200857 Forwards 1E Circular B1-02, 'Performance of NRC-Licensed Individuals While on Duty " No written response required SEYRRITAK V Region 4. Dallas. Office of the Director 81/02/09 1b. 07947 183
- DECKET 90-285 FORT CACHOUN STATION. UNIT 1
- F. Security, medical, emergency & fire protection plane
- 8103240)08 Submits 1981 program for energency preparadness drills & electises.per NRC 001223 request USVES.N C Dagaba Public Power District. 81/01/23 2pp 07987 277
- 0103090715 Discusses util 010127 response to NRC 001117 & 24 ltrs reopen items in fire protection program Proposed method of flushing aprinkler sys is acceptable. Alternate shutdown design remains outstanding itsue

  CLARK.R A Operating Reactors Brench 3 01/02/10. 2pp 07829 065
- 8103180264 Ltr to all power reactor licensess w/plants licensed prior to 790101 Powerds MRC position & request for addl info reserve shutfoun capability for compliance w/801119 fire protection rule EL8EMHULD O. Division of Licensing. 81/02/20 13pp
- 8103310338 Lin to all licensess of operating plants & holders of CPs forwarding NUREO-0656. Functional Criteria for Emergency Response Facilities. "Criteria describe acceptable method for meeting NRC requirements. W/o enc! EISENHUTED O Division of Licensing. 81/03/05 6pp
- 8103170716 Forwards interim rept re-post-fire shutdown capability at facility Licenses should verify that existing Tech Specs for boric acid concentration are adhered to w/absonce of heet tracing CLARK,R A Operating Reactors Branch 3 81/03/09. App. 07930-149
- 8103240505 Advises that existing fire protection sys meets 10CFR50-App R requirements Add! supporting documentation will be submitted by 810327 JGNES, & C Desha Public Power District. 81/03/19 ip. 07981:313.
- J insurance & indemnity information
- 8103040508 Forwards Endorsement 43 to MAELU Policy MF-63 PETERSEN.H.E. Dmahn Public Power District 81/02/26. 2pp. 07810 060.
- P. Operating license stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants, epplicants for CLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position re-interim actions & request for addition.

  EISENWYF, D. G. Division of Licensing 80/12/22 30pp.
- BiO3190387 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown, replacement parts & NUREO-0737.

  EISENHUT.D 0 Division of Licensing Bi/OI/19, App.

20014 Ltr to all licensees of operating plants.CP holders & U\_icants.except indian Point 2 & 3.Zion 1 & 2 & TM1-1.
Anding inadvertently amitted pages' from NRC B01222
rest for add! info re control of heavy load:
NHUT.D O Division of Licensing 81/02/03 App

10871 Forwards Amend 55 to License DPR-40 & notice of issuence & lability K.R.A. Operating Reactors Branch 3 81/02/10 3pp 07789-297

030870 Amend 56 to License DPR-40.adding addl assurance of Hiable decay heat removal availability ARK.R A Operating Reactors Branch 3 B1/02/10 10pp 7789-300

1030885 Notice of issuance & availability of Amend 56 to License 04-4P Operating Reactors Branch 3 81/02/10 2pp

A9K,R A 789:310

10160 Ltr to all operating PWR licensees requesting info on Used to all operating that Iconsees requesting into liary feedwater sys seismic design Forwards request for info.list of actions requested of licensees u/o micelly qualified sys & results of NRC walkdowns NMVT.D D Division of Licensing B1/02/10 13pp

0282 Forwards revised NRC Region 4. organization chart effective

RITAK V. Region 4. Dallas. Office of the Director 81/02/17

0269 Ltr to all operating plants & CP holders forwarding ification of TMI Action Plan Item III A 1 2 re upgrade mergency support facilities Requests confirmation within ays that implementation dates will be met (NHUT) D Q Division of Licensing. 81/02/18 12cp.

0077 Forwards safety evaluation suppl re automatic initiation of liary feedwater sys & implications to positive tivity feedback resulting from steam line break dent Proposed method & analysis acceptable K.R.A. Operating Reactors Branch 3 81/02/20 2pp 07866 007

1000B& Bafety evaluation supporting automatic initiation of #lliary feedwater sys & implications to positive activity feedback resulting from steam line break cident.

Operating Reactors Branch 3. 81/02/20 9pp. 07866.009

0024 Ltr to all power reactor licensees & license applicants re 0-0519 criteria Footnote 2 in Table 2 contains error due sekage testing delstions Licensee may subnit enalysis to lify use of existing low flow controller MHUT.D.O. Division of Licensing 81/02/20 8pp.

0217 Forwards request for addl info on C-E owner's group ittal on "RCB Asymmetric Loads Evaluation Program." I rept Includes generic & plant-specific requests CHPIELD.D. Operating Reactors Branch 5 DI/02/23. 27pp 5-155

0622 Forwards updated description of operational QA program which reades 781229 submittal re-administrative changes & gee for applicability to regulatory documents. S.W.C. Omaha Public Power District. 81/02/24 37pp 4:141.

0030 Ltr to all licensees of operating nuclear power plants & icants for DLs (except St Lucie, Units 1 & 2). Requests review to determine capability to mitigate station fout event & promptly implement emergency procedures NHUT, D Q: Division of Licensing. B1/02/25. 3pp.

0540 Forwards addt info re schedules & programs re THI Action Tasks 1.C.6.II.B.2 & II.F.2 & supplements util HOI212 & ltrs. "Inadequate Core Cooling Detection Bys Bummary ," encl.

B. H. C. Omeha Public Power District, 81/02/27, 5pp. 07848.165

090541 "Inadequate Core Cooling Detection Bys Bummary Status Rept." Omaha Public Power District. 80/12/31. 38pp. 07848.171

0281 Forwards add1 info to 810130 ltr re ability of solenoids on es HCV-238 & HCV-239 to survive submergence & ription of program to solve Conex instrument & cable tration propolem Distribution sheet encl.

B.W.C. Omaha Public Power District. 81/02/27. 4pp 08044.186.

8103200076 Informs that staff functions of Region 4 reassigned.
effective 810227 GL Madsen.Chief of Heactor Projects Branch.
designised as principal contact & recipions of
correspondence to reactor const & coeration activities SEYFRIT.K V Region 4. Dollas. Office of the Director BI/03/09 ip 07969 019

8103200032 Advises that mode he simultaneous hot & cold leg injections for long-term cooling are acceptable Mods do not involve significant hazards tobsideration Requests mods Implementation schedule within 60 dais CLARA, R A Operating Reactors Branch 3 81/03/10 200 07971 021

8103310804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of nafety-related electrical EISENHUT.D Q Division of Licensing 81/03/10 6pp

8103270400 Forwards application to amend License DPR-40 to upgrade surveillance requirements for hydraulic snubbers Certificate of Byt encl UNDOUTER J. LAMO, H.R. LETHY, A.C. LeBoeuf, Lamb, Lotby & MacRae 91/03/29 25p 08044-147

--BIO3270407 Application to arend Excense DPR-40.upgrading surveillance requirements for hydraulic snubbers
JONES-W C Draha Public Power District B1/03/23 2pp
08044 147

--8103270416 Proposed changes to Sections 2 0.3.0 & 5 0 Discussion. comparison of 815 w/proposed Tech Specs & justification for Class III classification encl \* Cmaha Public Power District 81/03/29 26nc 08044 151.

B103310441 Forwards application for OL amend & Certificate of Eve Amend upuld change Tech Epics to increase required shutdown margin for cold shutdown conditions

\* LePoeuf, Lamb. Leiby & MacRae. 81/03/30 2pp 08062-325

--8103310446 Requests License DPR-40 be amended to increase required shutdown margin for cold shutdown conditions UDNES.W.C. Oraha Public Power District 81/03/27. 2pp 08095 351

--8103310451 Proposed Tech Specs 2 O revisions to limiting conditions for Omaha Public Power District. 81/03/27 4pp 08062, 329

@ Inspection reports. IE Dulletins & correspondence

8103050648 Forwards IE Insp Regts 50-285/80-24 on 801201-31 No noncompliance noted
MADBEN-9 L. Region 4. Dallas, Reactor Operations Nuclear Support
Branch. 81/01/19 2pp 0/828 173.

--8103050650 IE Insp Rept 50-285/80-24 on 801201-31 No noncompliance noted. Major areas inspected operational safety verification, surveillance testing, radwaste shipment & radiation work cermit review
RELLEY.D.L., HUNNICUIT.D M Region 4. Dailes. Office of the
Otrector 81/01/16 4pp 07828 179

B103180240 Forwards supplemental info re util B01031 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." Schedule for THI task submittals & rept re cable splice qualification encl JOHES.W C. Oneha Public Power District. B1/01/30 100pp. 07952: 271

8103200393 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. SEYFRIT.K V. Region 4. Dallas. Diffice of the Director. 81/02/09 15 07966 318.

8103160313 Forwards IE Info Notice 81-03 "Checklist for Licensees Making Notifications of Bignificant Events in Accordance
W/10CFR50 72 " No response required.
SEYFRIT.K V Region 4. Dallas. Office of the Director. 81/02/12 10 07922.028

8103100059 Ack receipt of 810121.30 & 0206 1trs informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-289/80-16 BEYFRIT.K V. Region 4. Dallas. Office of the Director. 81/02/24 ip. 07855.117

- --8103100070 Responds to NRC 801212 ltr re violations nated in IE Insp. Rept 50-289/80-16 Corrective actions technician accomplated required hours new technician trained 5 sys established to docurent health physics technical qualifications JGRES.N C. Graha Public Power District. 81/02/06 409 07855-518
- --0103100091 Responds to NRC 801097 ltr re violations noted in IE Insp. Rept \$0-285/80-16 Corrective actions organisational change to be made-addl employees hired-revised program for sechnicians 8 unil study beta dosineters & spectrums UNICES. V. C. Quata Public Power District 81/01/30. 10pp 07895-122
- 0103150544 Forwards IE Info Notice 81-04. 'Cracking in Hair Steam Lines' 'No response required SEYFRITALY Region 4. Dallas. Office of the Director U1/02/27 IC 07917 [09
- 9103170053 Forwards IE Circular B1-03. Inoperable Reismic Munitoring Instrumentation. No response required SEYFRIT.X V. Region 4. Dallas. Office of the Director. B1/03/02 is 07939-177.
- B103270292 Updates info re admittance of MRC personnel to facility Forwards lists of regional inspectors H/o encl SEYFRIT.K V Region 4. Dallas. Office of the Director. 81/03/03 2pg 08944 182
- BiO3160841 Forwards revised 1E Bulletin 81-01. "Burvelllance of Mochanical Brubbers." w/corrected Pages 3 & a Change in identification or facilities ow/CPs to which builetin is applicable does not affect util requirements
  SEYFILL V Region 4. Dallas. Office of the Director 81/03/04
  ip 07914 197
- 8103233192 Ack receipt of 810228 ltr informing MRC of steps taken to correct violations noted in IE Insp Rept 90-285781-02 MADSEN.9 L. Region 4. Vallas. Office of the Director (11/03/10) ip 97977 173
- 8103230167 Forwards IE Info Notice 81-07. "Potential Problem W/Nater-Solutie Purge Dar Matla Used During Inert Gas Wolding." No response required SEYFRITA V Region 4. Dallas. Office of the Director. U1/03/16 to 0.7977-203
- R Periodic operating reports & related correspondence
- 8103030844 Forwards, "Annual Rept for Toch Gpec Section 5 7 1 b. Jan Dec 1980." 1 'Seni-Annual Rept for Fech Spec Section 5 7 4 t App B. Jul-Obc 1980." JCNES.W C D-aha Public Power District 81/02/25 ip 0/7/III 0(II
- --BI03030852 'Annual Rept for Fech Spec Section 3 9 1 b Jan-Dec 1700." & "Sent-Annual Rept for Tech Spec Section 3 9 4 & App B.
  Jul-Dec 1780 "
  - # Cmaha Public Power District. 01/01/25 150pp 07768 002
- BIO3120350 Forwards data sheets & surmary tables for adult fishery study efforts for Apr & June 1978 & Nov 1979 & "Ther-41 impact Study Final Burmary Rept. [972-77" Info available in Central Files only
  JCNES.W C Omana Public Power District B1/03/05 Ip 07904 226
- DIODIBO512 Forwards monthly operating cept for Feb 1781

  JDNES.W C Dmaha Public Power District 81/03/10 ip 07949 307
- --BIO3180316 Monthly operating rept for Feb 1981 PATTERSON.T L. Omaha Public Power District. 81/03/10 10pp 07049 30R

- 3 Reportable occurrences, they be related correspondent
- #HEXIOUSED PAL-LY-UL DB2 on Higher Local translation manager imported that it is contractor exployee assigned to UK translated manager translation of accident lumping resembed individual was caused by PA for violating parallel facility todge policed (Filly J. Hegion 4. Dailes, Affice of the Director 111 117/113 1p 07055-307

#### v (Iperator Examinations

- H103030093 Confirms B10205 taleon to H10212 Secting to Allington II a Implementation of training programs at famility PACSIN-3 I Region A. Hallass Resitor Operations for less Support Branch 81702711 ip 07027 030
- DUCKET 50 206 INDIAN COINS STATION. COIL O
- 1. Socurity, modical, emergency ! fire protection plane
- SIDEMANDA Approves esquest for estension for contestion of automatic carbon dioxide suppression systematic Dioxif for notice of extension and PANIMARIA SMILES of Doctor Heacter Degulation. Director UL/DZ/LI. 2pp. 07/04 2/81
- BIOSECTOR Cottee of extension for completion of automate cachon JIOSES appression systematic BioSET CASES Of Office of teclose Persite Regulation Director BIOSECTOR OF MEMORY
- HIBTHNOODS to the all lower reactor transfer companies to enter the authorized the position of engineer for additional emploisting for compliance colority five protection colories. By the protection colories and the entering the colories of the entering the colories.
- HIO/BO096 Lumwards security place Place withhold (certificity) P201 HIRBY, Q.T. Prop. Authority of the State of free risks. HI 12224 Spp. 07017 131
- HIGHHOUSH Its to all licensess of operating plants to holders of the forwarding holder holder. Too thouse cities to for bosequing despite facilities. I fitterial describe acceptable method for mobiling hid sequitements the end.

  Fitterial Description of the entire of the entry.
- BIOSEAGING Degreets greenston from tryterestation sched to of for protection regulations insoffs less time to exact the repulation of the schedule for paymentation date of Dituzio reguested Required date is 410-419

  BAYBLUP Power Authority of the State of Decrees of the Dituzion of the State of Stat
- HIGH260392 Responds to High-H & PV 1ts sapressing solvers bhat had adopt sergency sepands plans for facility solvers or signatures of four condition on plans had to be required. High-entation except for also to notification age 3Hith V Director's High-entation of Price of Proposition and Comment GCO3729 3pc CMS-G 446
- O Adjudicatory cheratonnamies
- 8103050140 Corrects tycographical error to Dio. of its or easiest At. An conclusion VARGA-0 A. Operating Resitors Branch 1. Blood 15. to 07040 -77
- HID3030707 Forwards application for amend to C.s adding contacting to environ protection plan necessary to permit inclinentiation settlement appropriate conductor conting eye class [ 6 2] amend fees end;

  BANE J.P. Power Authority of the litate of New York. Hit officer
- -: MICONOMICAL MORNING sucking order deleting from the existing requirement for termination of uperation of coults withough coulting Draft stipulations is afficulting and the system of the Michael State of the Martis of the State of Howard State of Howar

040483 Request for order dejeting OL requirement for termination of eration of units w/once-through cooling le motion granted. 
ttlevent agreement cruld te initiated allouing facility 
be equipped w/circulating water pumps t screens 
ANDENBERG. B Consolidated Edison Co of New York PRATT. C M 
wer Authority of the State of New York 81/02/27 12pp 
310 071

03040736 Stipulation among listed parties that plant may be operated Dronte-through cooling sys until 800915 at which time plant Ull operate Drapproved closed-tycle cooling sys Certificate

of Svc enci vplot.H H Consolidated Edison Co of New York OALLD.J NRC -No Detailed Affiliation Given \* New York. Btate of 74/12/01 200P

230065 Response supporting licensee 810227 motion for order leting certain provisions from facility licenses, directing 0113 stipulation be superseded & directing termination of nding actions re condenser cooling sys DRE.JE Hearing Branch 2 01/03/19 9pp 07978 244

03230074 Affidavit no technical aspects of settlement agreement All environ concerns have received addithorough exam. Agreement represents resolution of environ dispute frof qualifications & Certificate of Svc enci BILLUPS.C.W. Environmental Engineering Branch 81/03/19 8pp

07978 292

## enetal torrespondence

- 020068 FDIA request for documents re methodology,assumptions,data procedures used by task force on interim operation of clifty
  1.11ty
  1.7.R.R. New York Univ. 111/01/27 2pp. 07783:042.
- 020064 Responds to FOIA request for documents re methodology. numptions.date & procedures used by task force on interim gration of facility.Lists three documents which have been blished Unpublished documents will be forwarded. LTON.J.M. Division of Mules and Records 81/02/24 ip LTON, J. M 783 041.
- 130441 Responds to 810119 request for info needed to respond to isowas reagones to BIVIID request for info needed to reap nationent concern re deristion not to shot down facility as force concluded design did not warrant shutdown during .B hearing ASLB recommendations due 82010B CRUTIL Office of the General Counsel 81/02/20 2pp 711.244.
- 03130444 Forwards constituent 8 Jones 810110 itr re failure to shut down facility for response AlbiAMSA Senate D1/01/13 2pp 07911-246
- 040641 Informs that unsite safety review group will now rept to neger of nuclear operations instead of senior vice esident of nuclear generation. YNE.J.P. Power Authority of the State of New York. 01/02/26 p. 07819.124.
- perating license stage documents & correspondence
- 010587 Forwards tabular summary of comments & comments received refractor's decision & Commission review of shutdown of illities.

  KHNITL Office of the General Counsel SECY-80-168 80/03/20.

  DD: 07972:257.
- 190732 Ltrs to all licensees of operating plants applicants for s & holders of CPs re control of heavy loads Requests view per guidelines in NUREO-0612 Forwards NRC position re terim actions & request for add1 info. SENMUT.D.O Division of Licensing. 80/12/22 30pp.
- 1903B7 Ltr to all licensees of operating plants & applicants for & holders of CPs re program for environ qualification safety-related electrical equipment. Items addressed yelva cold shutdown-replacement parts & NUBEO-0737. BEHHUT.D G. Division of Licensing Bi/Oi/19 App.
- 20014 Ltr to all licensees of operating plants.CP holders & OL licents.except Indian Point 2 & 3.Zion 1 & 2 & TMI-1. warding inadvertently onitted pages from NRC B01222 uest for add info re control of heavy loads. SENHUT, D. Q. Division of Licensing. 81/02/03. App.
- 00160 Ltr to all operating PWR licensees requesting info on diliary feedwater sys seismic design Forwards request for li info-list of actions requested of licensees w/o smically qualified sys & results of NRC walldowns BENHUT-D.Q. Division of Licensing. 81/02/10. 13pp

- 8103]60669 Ltr to all operating plants & CP holders forwarding clarification of 1MI Action Plan Iten III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.D O Division of Licensing 81/02/18 12pp
- 8103620491 Application to amend License OPR-64. in response to NAC 103020491 Application to amend License OPR-64.in response to NGC 790306 request for proposed Tech Specs re facility fire protection foods. Proposed Tech Specs will be implemented 810217 w/n prior Commission approval JAYNE. J P. Power Authority of the State of New York 81/02/20 2pp 07703 102
- -- 8103020495 Proposed Tech Specs 3 14 t 4 12 for fire protection & detection sys

  \* Power Authority of the State of New York 81/02/20 15pp
- 8103030955 Forwards application for arend to License DPR-64 to detete four containment isolation valves modified for automatic operation in response to IK/REG-0737 Proposed Tech Spec change & safety evaluation enc! BAYNE, J.P. Power Authority of the State of New York 81/02/20 200 07803 166
- --BI03030560 Application for amend to Tables 3 6-1 \$ 4 4-1 of DL App A to delete four containment isolation valves & add two new Containment isolation valves, respectively

  BAYNE, J. P. Power Authority of the State of New York 81/02/20 10 07803 168
- --8103030567 Proposed change to Tech Spec Tables 3 6-1 & 4 4-1 of CL App A Bafety evaluation entl

  \* Power Authority of the State of New York. 81/02/20 Opp 07800 169
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria. Footnote 2 in Table 2 contains error dus to leakage testing Seletions Licensee may submit analysis to justify use of existing low flow controller EIGENHAVI.D O Division of Licensing 81/02/20 Opp
- 8103090090 Requests date for meeting between NRC & util to discuss age interaction study Response requested within 1 wk of date of NOVAR-T.M. Assistant Director for Operating Reactors. 81/02/24 4pp 07852 131
- 8103040525 Ack receipt of NRC 810211 preliminary results of electrical equipment environ qualification review Facility in shutdown for repairs to main turbine generator Licensee to submit statement supporting safe operation per NRC GLO211 ltr DAYNE, J P Power Authority of the State of Nou York 61/02/25 20p 07810 058.
- B103040660 Forwards response to Items j.s.m 5 p to IRC B01031 itr recontrol room human factors review item f was erroneously included in B01212 response to Items 6 through g 5 i Item f requirement confleted B10217 BAYNC. J P Power Authority of the State of New York. B1/02/29 6pp. 07815-105
- 8103230030 Ltr to all licensees of operating nucloar power plants & applicants for DLs fexcept St Lucie.Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. FISENHUT.D Q Division of Licensing. 81/02/23 Spp.
- B103230B13 Generic Ltr 81-06 to all CP holders & DL applicants re 10CFR50.71(e), "Periodic Updating of FBARs," effective B00722 Info re FBAR legal status, forcat & content encl. E1BENHUT.D O Division of Licensing 81/02/26 10pp.
- 8103030707 Forwards application for amend to CLs.adding nonradiological environ protection plan netwasary to permit implementation settlement agreement re condenser cooling sys Class I & [f] amend fees encl
  BAYNE, J. P. Pouer Authority of the State of New York
  Consolidated Edison Co. of New York B1/02/27. 2pp 07797-232
- --8103030712 Application to amend Licenses DPR-5, DPR-26 & DPR-64, adding nonradiological environ protection plan necessary to permit implementation of settlement agreement re condenser cooling BAYNE J. P. Power Authority of the State of New York D'TOOLE J.D. Consolidated Edison Co. of New York 81/02/27, App. 07799-234

SvC re rotion & B10227 application to amend OL enci PRATT.C M Power Authority of the State of New York BRADENSURG B L Consolidated Edison Co. of New York B1/02/27 37pp 07900 109

G3340697 Submits revised responses to 801880 ltm #8 post-IKI requirements Containment isolation dependability, containment water level monitor & control moc habitability discussed Supplemental info to AUREG-0787 encl OMERICAL INFO to NUMEG-0737 encl C.J.P. Power Authorst, of the State of New York 81/02/27 07810 047 BAYNE. J P

0.0

ngionger Resonnts to 810211 equipment evaluation rept he environ 2:1 07939 020

OBBIOSCH Ltr to all licensees of operating plants, applicants for DLs 5 holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical 100-01100

EISENHUT, D.C. Division of Licensing, 81/03/10 622

03170274 Forwards corrected affidevits of svc to replace affidavits in 801010 ftr & in two ltrs did 801219
D\*TOCLE.J D — Consolidated Edison Co — of New York — 81/03/12 — 8pp 07734 229

03240523 Forwards conceptual design description of ATKB mitigating sys actuation circultry required by Item C 4. App A of 800211 confirmatory order

BAYNE, J.P. Power Authority of the State of New York. 81/03/16

02982 747

03270764 Advises that protetilistic safety analysis rept will be available June 1981 BAYNE. J.P. Power Authority of the State of New York. 0'100LE. J.D. Consolidated Edison Co of New York 81/03/23. 2pp 08043.193

03310487 Forwards "Habitability Study for Control Room." per BAYNE J P Pauer Authority of the State of New York. 81/03/23. 1p 06079 042.

8103310491 "Habitability Study for Control Room

• Power Authority of the State of New York
08079 043 80/03/23 2506

& correspondance

JESS OF GE TUDE

tor

9. No

er Lear

liante

Nuclear

8103110526 Act receipt of 801219, 910116 & 23 steps taken to correct violations noted in IE Insp Rept 50-205/60-11 SUPPLIES OF Region 1, Philadelphia, Evel Facility & Materials Gofety Brench 81/01/30 ip 07877 170

--B103110528 Supple response to NRC 801125 ltr re violations noted in IC les Rept 50-286/80-11 Corrective actions util will review nonradiological environ monitoring procedure changes before non-actiongital by Con Ed. effective 010202 JULLAS 8 Power Authority of the State of New York 01/01/23 2pp 07977 179

-- 8103110532 Advises that util will submit revised response to NRC 1801125 1031103:2 Advisos that Util Elli Subility 10123

IULLA B S Power Authority of the State of New York | 11/01/16 12. 07877 181

-- 8103110534 Responds to RRC 801125 Itr re violations noted in IE Insp Rept 50-206/00-11 Corrective actions paraonnal reinstructed re required analyses of drinking water & SUTTACE late water samples
2ULLA.S 8 Power Authority of the State of New York | UO/12/19
4pp | 07877 162

--3103110537 Forwards IE losp Rept 90-206/80-11 on 600721-0806 & motice of violation GRIER B.H. Region t. Philadelphia, Office of the Director. BO/11/23 3pp 07877 186

-- 8103110939 Notice of violation from these on 800721-0008. \* Region L. Philadelphia. Office of the Director 80/11/04 200 07827 169

--BI03110542 IE Insp Rept 50-286/80-11 on 800721-0808 Noncompliance noted failure to perform Sr-90 analyses of drinking water & late water samples JACKBON T J. Region: ALCHOMATER SUMPLES
JACKBON T J. Region I. Philadelphia. Défice of the Director
BORES.R J. Region I. Philadelphia. Fuel Facility & Materials
Bafety Branch B0/11/04 21pp 07877 191

8103050432 Clarifies 800912 response to 1E Bulletin 80-20. "Failure of novowing vierities downer response to it Bulletin BU-20, Westinghouse Type N-2 Spring Return to Neutral Control Buticks " Buitch testing will be conducted when plant is above cold shutdown condition BROWS.J.C Power Authority of the State of New York 81/02/10 1p 97836:014.

8103060443 Responds to IE Guiletin Bi-Oi, "Burveillance of Mechanical BRONS, J. C Power Authority of the State of New York. 81/02/11. 1p 07836: 021

8103040233 Farvards IE Info Notice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events in Accordance W/10CFR90. 72 "No written response required. GRIER. B.H. Region 1: Patladelphia. Office of the Director 81/02/12 | 1p. 07813:244.

8103200205 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines "No response required. GRIER.B H. Region I. Philadelphia: Office of the Director. BI/02/27 ip 07972 043

8103200210 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No written response required. GRIER.B H. Region I. Philadelphia. Office of the Director 81/03/02 ip 07966-198

- 8103200103 Forwards revised IE Bulletin Bi-O1. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements ORIER.B H. Region 1. Philadelphia. DPPice of the Director 81/03/04 lp 07969 096
- B103200152 Forwards IE Info Notice B1-06. "Failure of ITE Model K-609 Circuit Breaker" No response required GRIER.B H. Region 1. Philadelphia. Office of the Director B1/03/11 lp 07969 209
- 810327J669 Forwards clarification of util 800617 response to Item 3 of IE Bulletin 80-06 re reset of engineered safety features controls
  3AYNE.J P Power Authority of the State of New York 81/03/23
  4pp 08042 360
- A Periodic operating reports 5 related correspondence
- 8102250439 Forwards "Hudson River Ecological Study in Area of Indian Point:" 1979 annual rept. Affidavit of svc encl D'TODLE.J D. Consolidated Edison Co. of New York 81/02/20 App. 07749.001
- --8102270774 'Hudson River Ecological Study in Area of Indian Point.' 1979 annual rept • Texas Instruments, Inc. 81/02/20 190pp. 07767:001
- 8103100517 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1980 " O'TODLE.J D. Consolidated Edison Co. of New York 81/03/01 ip 07887:165
- ~-BIO3100518 "Effluent & Wasto Disposal Semiannual Rept.Jul-Dec 1980 "

  © Consolidated Edison Co of New York 81/03/01 43pp
- 810310062? Forwards "Effluent & Weste Disposal Banishmual Rept. Jul-Dec 1980 " Revised Tables IA & 18 to first & second querter 1980 semishmual rept ent! BRONS-J.C. Power Authority of the State of New York 81/03/02 1p 07863:031
- --8103100627 "Effluent & Waste Disposal Schiannual Rept.Jul-Dec 1980 "
   Power Authority of the State of New York. 81/03/02 43pp
  07863-032
- --Bi00100634 Revised Tables IA & 28 to "Effluent & Haste Disposal Bemiannual Rept. Jan-June 1980" Power Authority of the State of New York. 81/03/02. 3pp. 07863:075.
- 8103160683 Forwards monthly operating rapt for Feb 1981. BRONS, J. C. Power Authority of the State of New York. B1/03/13  $\,$  1p 07914, 324.
- --BI031606B7 Monthly operating rept for Feb 1981. CDNNELL.C. Power Authority of the State of New York. 81/03/01 6pp. 07914 329
- 8 Reportable occurrences, LERs & related correspondence
- 8103030808 Forwards info re security plan. Info withheld (ref 100FR2.790) BERRY, 9.T. Power Authority of the State of New York. 81/02/24, 2pp. 07788: 332
- 8103030803 PNS-1-81-005: on 810225.Con Ed customer svc representative received bomb threat by telephone. Corporate ofc & facilities notified Bomb searches initiated w/negative results No further action enticipated MCKEDWN.L. DYNER, J. H., DEVLIN.J. W. Region 1. Philadelphia. Office of the Director 81/02/26 1p. 07788:334.
- B103030842 PNO-1-81-005:on B10225, customer svc representative received bamb threat by telephone Util corporate ofc notified & bamb search initiated Results negative. MCKEGNNL M., JOYNER, J. H., DEVLIN, J. W. Region 1, Philadelphia, Office of the Director. B1/02/26 2pp 07795:173
- 8103260915 Forwards LER 81-003/03L-0. BRONS, J. C. Power Authority of the State of New York. 81/03/23. 1p. 08041:034.

- --8193266527 LER 81-003/03c-0 on 810223, snubber RC-R-344-5-H failed fock up in extension position Cause not stated Enubber replaced Investigation to follow GUMSLE.F W. Power Authority of the State of New York 81/03, no 8241-03.
- DOCKET 30-287 OCC.EE NUCLEAR STATION. UNIT 3

  F. Security. Georgial. emergency & fire protection plans
- 8103(80264 Ltr to all power reactor licensees u/clants licensed puto 790(0) Forwards NRC position & request for add info resafe shutdown capability for compliance u/80(1)9 fire protection rule ETSCHUMU.0 9 Division of Licensina 81/02/20 1300
- 8103120643 Ack receipt of B01117 ltr re change to security plan Co Withange contained in each Each withheld (ref 100FR2 790) REID.R W Operating Reactors Branch 4 81/03/04 2pp 07906
- 8103310338 Ltr to all licensess of operating plants & holders of (forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting FRC sequirements I//o encl
  E15ENHUT.D 0 Division of Licensing 81/93/05 app
- B103160181 Releases public version of implementing procedures for accergency plan.
  FELTON. J M Division of Rules and Records 81/03/12 1p 07806 001
- --BIO3160187 Forwards public version of implementing procedures for energency plan PARKER.H D Duke Pawer Co 81/03/02 ip 07806-00[
- --Bi03i60196 Public version of implementing procedures for emerger plan. Includes load rejection, turbline & reactor trip, loss of reactor coolant & boron dilution + Dute Fouer Co. 81/03/02 350pp 07806.001
- B103203611 Advises that proposed updated Toch Spec for fire protecting multi be submitted by 810416 in response to ARC B01001 request ARCHARCE B01001 request Duke Pawer Co. B1/03/16 to. 07971 299.
- B103261212 Requests that encl emergency planning info be placed in LPDR.W/o B103160167. SQUDER.J I. Division of Rules and Records B1/03/24 ip DB040.247
- 1 Financial information
- BiO3310549 Forwards Annual Financial Rept 1980, annual certified financial statements, 1981-83 financial forecast % util statement re available funds to satisfy liability Info guarantees retrospective premiums per 10CFR140 26 THIES.A C Duse Power Co 81/03/24 1p 08079-100
- --B103310638 Annual Financial Rept 1980 including financial states 1981-83 financial forecast & statement re sources of available funds to satisfy liability HORN.C., LEE.W.B. Duke Power Co. 81/02/13 51pp 08075 10
- P. Operating license stage documents & correspondence
- 8010230589 Summary of B00821 meeting w/B&W reactor owners group reabnormal transient operating guidelines program VIBBING.0 Operating Reactors Branch 4 80/09/30 29pp 06/87:236
- 8103190732 Litts to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREO-0612. Forwards NRC position re-interim actions & request for addl info EISENHUT, D.Q. Division of Licensing. 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737.
  EISENMUT.D Q. Division of Licensing 81/01/19. Opp.
- B103120014 Ltr to all licensees of operating plants.CP holders & applicants, except indian Point 2 & 3,71on 1 & 2 & TMI-1, forwarding inadvertently emitted pages from NRC 801222 request for add] info re control of heavy loads.
  EIBENHUT.D O Division of Licensing. 81/02/03. 6pp.

- ---8103030923 Notice of Issuance & availability of Amends 93.93 & 90 to Licenses DPR-39, BPR-47 & DPF-95 respectively REIO.R W. Sperating Reactors Branch 4 01/02/10 2cp 07801-025
- 8103300160 Ltr to all corrating PMF licensees requesting info on auxiliary Reeduator sys seismic desting Forwards request for add1 info-list of actions requested of licensees and seismically qualified sys & results of 1880 walkforms EISEMPHILD Q Division of Licenseing 81/02/10 13pp
- Ol03160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EIRCIAIUT, D Q Division of Licensing 81/02/10 12pp
- 810307001B Advises of review of util 801808 response to NAC 800701 ltr requesting info on fuel assembly halddown spring failures Requests conmitment to perform surveillance testing on holddown springs in core during next refueling outage REID.R W Operating Reactors Branch 4 81/02/20 2pp 07849 272
- 8103250024 Ltr to all power reactor licensees & license applicants re AMREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT, P 9 pivision of Licensing 81/02/20 Upp
- 8103070699 Generic its to all BBW licensees se capability of small break LUCA model to predict small break behavior Post-tost evaluations of L-4-1 & S-07-10D predictions requested for submittal by 810401
  REIDER W Depending Reactors Branch 4 81/02/24 3pp
- G103110784 Forwards request for add1 info re util 791221 & B00723 responses to recommendations contained in BAU-1564.
  "Integrated Control Sys Reliability Analysis." Analysis of consequences of stock open turbine bypass valve is required.
  REID.R W. Operating Reactors Branch 4 B1/02/23 8pp 07877 328
- BiO3230030 Ltr to all licensess of operating nuclear power plants & applicants for CLs (except Bt Lucie. Units 1 t 21 Requests util review to dotermine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT, D O Division of Licensing 81/02/25. Spp.
- 8103120862 Forwards 810109 request for add1 info re BSH 177 fuel assembly numers group submittal on asymmetric LDCA loading. Response requested within 60 days REID, R U Dereting Reactors Branch 4. B1/02/26. 2pp 07904.001
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re IOCFR50 71(e), "Periodic Updating of FSARs," effective BOO722 Info re FSAR legal status, format & content encl. EISER/WUT.D G Division of Licensing 81/02/26
- 8103120229 Ack receipt of 800211 response to 790821 info request to B&W reactor owners group Requirements of TMI Action Plan Item 11 K. 2 19. "Genchmark Analysis of Bequential Auxiliary Feedwater Flow," fulfills request Safety evaluation enct REID.R M Uperating Reactors Branch 3 81/02/27 2pp. 07903:021.
- --Biggl20245 Safety evaluation to Item II.K 2.19 "Benchmark Analysis of Bequential Autiliary Feedwater Flou" for B&W reactor plants Intent of Action Item II K 2.19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program a Office of Nuclear Reactor Regulation. Director 81/02/27. 2pp. 07903 023

- #3 PUR PUNER PLANT POUR POUR D. J. MOTOR D. J. HATCRED B. HANDAR LABORATOR LAB - L. P. A. 1041 NUREO/CH-1809 VOZ. ULZOZ/GD. 2000p. ACARTAETA AC MITH.
- 8103050460 Forwards currented liquis > 5 % of for Amenda viryleyo to Ligense Dek 55 issued Hiddio Entrection requested PANNERS B. Dube 1000 C. MICOLOGY, type 12012 117

- Big3070173 Notification of Big402 DI meeting willish recent group in Dethesds.MD to discuss responses to 275 min/02 ptr reasons the sectors Branch 4 min/02 22 25pp 0.2040 441
- 0100120261 Ark receipt of BOOK O response to 72.0031 into request to DEN textor camers group Requirements of 1001 Arking Plan 1800, if R 2 19. "Benchmark Analysis of Degreetiel Artilier; Feedwater Flow." Fulfills request bafet; e.eloation and REINR W. Cherating Restors Branch 4. (12.01002 Apr. 0.2004 142)
- -- (8103120270 Hafety evaluation is 181 Action Plan Live 11 P 2-17
  "Benchmark Analysis of Hegmential Annilsary Leadwater Closintent of Action live 11 R 2-17 anninglished to comits
  provided by CRALL 2 shellar to TRAN 2 groupses

  \* Defice of Nuclear Residue Regulation, Director (1) P1 P2 222

  \*\*Open 182
- BIO3090640 Advises that response to request for adultantonic energency feedwater sys will be submitted by Hinder PARKER B. Duke Puber CO. HI/H/4/4 by 17/14/4 cu/
- 0103110321 Advises that analyses of liquid 6 gasanne radvastes are performed by Teledyne Isotopes, per schadule requirements of Tech Opecs 3 9 0 5 3 10 9 castisfying feet lipe. A 4 5 Petatisfy review of vendor analysis procedures concerns any PARKER, M. O. Dute Power Co. 01/0/2011 200 11/11/2 112

- BIODIRDADB Forwards proposed Tech Space for upgrade of entirinatory reactor trip eqs PARKER.W.D. Duke Power Co. 81/03/06 (Upp. 07/01 wid.
- --BIO3120445 Proposed Tech Opec Pages [1 5 ], [ 5 4, [ 7 5, 4 ] 7 6 4 ] H re upgrade of anticipatory reactor trip ays a Dute Power Co. BI/ON/Oh. Spp. (I/M)] Du/
- B103160993 Notifies that existing Terh Upecs re hees removel capability during all modes of operation resolved concerns re B19924 it & B05606 response to IE Bulletin 00 La. Therey Heat Removal Bus Operability BICL2/JF Operating Reactors Branch 4 UI/0,009 app 07921 143
- B103310804 Ltr to all licensees of operating plants, applicants for its tholders of GPs forwarding SECY-B1-119 re info necessary to extablish environ qualification of safety related electrical
- equipment
  EIGENHUT, D.Q. Division of Licensing #11/0//10 App



170434 Response to NRC 810220 request for util commitment to rveillance of fuel assembly holddown springs in facility res Documents util plans to inspect fuel assemblies for oten holddown springs during upcoming refueling outages RPER.H Q Duke Power Co 81/03/12 2pp 07934 337

240078 Requests remission of license amend foo in connection w/ swance of Amends 92.92 & 98 to Licenses DPR-38.DPR-47 & R-95.respectively GGB.R License Fee Management Branch 81/03/17 Ip 07989 282

230644 Application to amend Ols.revising License Condition 3E to thorize completion of mods identified in Table 3 1 of NRC 0811 Fire protection safety evaluation Supporting OBIL FIFE PROTECTION OF CO. BIVO3/18 (Ipp. 07977 009.

240332 Forwards revised responses to Questions 4 & 11-addressed in 11 B01113 Itm.per NRC B10316 request for edd1 ariffication on reloed design methodology technical rept. RKER.H O Dute Power Co B1/03/18 3pp 07990:134

240393 Forwards "Evaluation of Transient Nuclear Instrumentation war Range Flu: Error: " in response to NRC 810114 ltr RKER.W O Duke Power Co 81/03/19 1p 07990 184

03240378 "Evaluation of Transient Nuclear Instrumentation Pawer Range Flux Error. Duke Power Co. 81/03/19 33np 07990 185

270704 Requests meeting w/NRC to discuss issue of mild environs r Commission 800523 memo & URC 801024 order by 810415 sponse should be received by 810401 RKER.W O Duke Power Co 81/03/19 ip 08047 119

270584 Informs that B&W owners group submitted AAM-1911P. rradiation-Induced Reduction in Charpy Upper Shelf Energy Reactor Vessel Welds" to fulfull submittal requirements | IOCFR50, App G RKER.W D Duke Pawer Co BI/03/23 Ip 08043 301

03270693 Forwards BAM-1811P. "Irradiation-Induced Reduction in Charpy Upper Bhelf Energy of Reactor Vessel Helds ' Describbs implementation predictive methodology to determine syc life of reactor vessels M/a encl TAYLOR, J. H. Dabcock & Wilcox Go. 81/03/12. 2pp. 08043:302

nspection reports, IE Gulletins & correspondence

170103 Forwards Revision 6 to 90-day response to 18 Bulletin 170103 romans revision o to vocay response to 18 Buil -018. "Envison Gualification of Class IE Equipment." vision addresses environ qualification of electrical uipment needed to achieve hot & cold shutdowns IEB.A C. Duke Power Co. 81/01/79. 1600pp. 08047:211

020203 Forwards IE Circuler 81-02, "Performance of NRC-ticensed dividuals Hbile on Duty." No written response required REILLY, J.P. Region 2, Atlanta, Office of the Director. B1/02/09 07785:305

030082 Supple previous responses to IE Bulletin 80-11 Forwards hadule for completion of masonry wall re-evaluation. rallel path program will be followed for walls which do t comply w/long-term acceptance criteria RKER,W.O Duke Power Co 81/02/09. 2pp. 07808.200

040147 Forwards 1E Info Notice 81-03. "Checklist for Licensees king Notifications of Significant Events in Accordance 10CFR90.72." No written response required REILLY, J. P. Region 2. Atlanta, Office of the Director 81/02/12. 07813-007.

i60725 Forwards IE Info Notice Bi-O4, "Cracking in Main Steam nes." No response required. REILLY,J.P. Region 2, Atlanta, Office of the Director. 81/02/27. . 07914: Ito

160651 Forwards IE Circular Bi-O3, "Inoperable Beismic Monitoring strumentation." No response required. REILLY₁J.P. Region 2. Atlanta, Office of the Director. 81/03/02

120828 Ack receipt of 810211 itr informing NRC of steps taken to rrect violations noted in IE Health Physics Appreisal pts 50-279/80-27.50-287/80-24 & 50-269/60-31 US.R C. Region 2. Atlanta. Reactor Operations Nuclear Supportance. 81/03/04. ip. 07903:338.

- --8103120836 Responds to 1:90 Bio120 ltr re violations noted in IE Health Physics Appraisal Repts 50-270/80-27.50-287/80-24 & 50-269/80-31 Carrective actions more sensitive probes placed at high-vol personnel traffic 90A eyits PARKER.U G. Oute Pauer Co. 81/02/11. App. 07905.039
- --BIGG120841 Forwards 1E Health Physics Appraisal Repts 50-270/80-27. 50-287/89-24 & 50-269/80-31 notice of violation & significant appraisal findings
  PrEttLY. J.P. Region 2. Atlanta, Office of the Director
  81/01/20. 4cp. 07905-343
- --8103120843 Notice of violation from health physics appraisal on unuvous-19

  \* Region 2. Atlanta. Office of the Director Bi/Oi/OB to 07905-347
- ~~8103120048 IE Health Physics Appraisal Repts 50-270/80-27, 50-287/80-24 \$ 50-249/80-31 Moncompliance noted failure to follow 3 DU-24Y/83-31 Noncompliance noted failure to follow unitten procedures & to perform safety analysis prior to nating changes to facility HOSEY.C M Region 2. Atlanta, Office of the Director OIB! Region 2. Atlanta\_Fuel Facility & Naterials Bafety Branch QUESTIN A F 81/01/08 27pp 07905 348
- 8103160851 Provides supplemental response to IE Bulletin 80-11. "Masonry Wall Design." Two masonry calls in Unit 1 reactor bidg are adequate for all design loadings PARKER. N.O. Dake Power Co. 81/03/04 2pp. 07915-230
- 8103170041 Forwards revised 1E Bulletin 81-01, 'Surveillance of tostrough forwards revised to buildering 1970; "Surveillance of Mechanical Boubbers," w/corrected Pages 5 & Change in identification of facilities w/CPs to which builderin is applicable does not affect util requirements.

  Office LLY.J. P. Region 2. Atlanta, Office of the Director 81/03/04
- 8103110576 Responds to NRC evaluation of 801031 Revision 5 response to 1031105/6 Responds to NRC evaluation of BD1031 Revision 5 to IE Builletin 79-018 Requests further clarification of response thems classified as deficient Deficiencies would not adversely offect plant operation PARKER W O Duke Power Co B1/03/05 3pp 07885 053
- 8103260492 Advises that review of interim mods showed deviation from schodule in 790612 response to 16 Bulletin 79-01. 'Environ Qualification of Class 16 Equipment 'NRC will be informed of new mod schedule upon receipt of replacement equipment PATKER.W Q Duke Power Co 81/03/05 1p 08037 202
- 8103200281 Forwards 1E Info Notice Bi-Ob. Failure of ITE Model K-600 Circuit Breaser "No response required
  O'REILLY-J P Region 2. Atlanta, Office of the Director 81/03/11
  1p 07965-016
- 0103240511 Ack receipt of 810305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-38. 50-270/80-35 % 50-287/80-32 LEMIS.R C Region 2. Atlanta. Office of the Director 01/03/11 ip 07983
- --B103240628 Responds to NRC 810211 ltr re violations noted in IE Insp Repts 30-267/BO-38,50-270/80-35 & 50-287/80-32 Corrective actions slopped spill.decontaminated area & counseled personnel about procedures.No proprietry info PARKER.N O Dute Power Co B1/03/06 3pp. 07903.188
- --8103240635 Forwards IE Insp Repts 50-269/80-38.50-270/80-35 & 50-287/80-32 on 801201-31 & notice of violation LEMIS.R.C. Region & Atlanta. Reactor Operations Nuclear Busport Branch 61/02/11 2pp. 07983-191
- --8103240648 IE Insp Repts 50-269/80-38-50-270/80-35 & 50-287/80-32 on B01201-31 Noncompliance noted: interim radwaste sys was operated w/o adequate procedure resulting in radioactive DRDERS, W. F., JAPE, F. MYERS, D. O. Region 2, Atlanta, Office of the Director. B1/02/11 Spp. 07983.194
- 8103200013 Forwards IE Info Notice 81-09, "Degraded DC Bus at O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/03/13.
- 8103240704 Ack receipt of 810306 ltr informing NRC of steps taken to correct violations noted in 1E lnsg Repts 50-269/80-39, 50-297/80-34 & 50-297/80-30 LEWIS, R. C. Region 2. Atlanta, Office of the Director. 81/03/18. 10. 07983 309

- --8102740712 Responds to NRC 810210 ltr re-violations noted in IE. Insp. Repts 50-269760-37.50-270760-34 & 50-287780-30 Corrective actions reinspected raf colds using proper calibr becautioned all Bbs. inspectors to document calibr b cautioned all Bbs. inspectors to document calibr b chaps PARKER.N O Dube Puler Co. 81703706 3pp. 07983-310
- --8103240722 Forwards IE Insp Repts 50-267/80-34, 50-270/80-34 & 50-287/80-30 on 601215-18 & H10105-08 & notice of violation MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/02/10 2ap 07933 313
- -- 8103240776 Vetice of violation from insp on 801219-10 & 810105-08 • Region 2. Atlanta. Office of the Director 91/02/10 lp
- --Bit32407B3 1E Insp Repts 30-269/80-37.50-270/80-34 & 30-207/80-30 on 801215-18 & RIO105-88 koncompliance noted activities affecting quality not leing accomplished per procedures re star records of pipe celds ECO/OMO3.N. Region 2. Actiants. Office of the Director HdRDLA Region 2. Actiants. Region 2. Actiants. Region 2. Actiants. Region 3. Actiants. Region 3. Actiants. Region 3. Actiants. Region 4. Actiants. Region 5. Actiants. Region 5. Actiants. Region 5. Actiants. Region 6. Bit 202/09 10pp 07593-316
- 8103310913 Responds to IE Nulletin 81-01. "Surveillance of Mechanical Brubbers : No INC southers identified in bulletin are in use at facility Unit 3 inaccessible mechanical snubber losp completed 810220 All snubbers cere clean PARKER, NO Dise Power Co Bir03/20 to 08058 147
- 9 Periodic operating reports & related correspondence
- 8103070278 Forwards "Semiannual Effluent Release Rept. Jul-Dec 1980 " PARKER, W. G. Duke Power Co. 81/02/27 ip 07890 323
- --CI03090285 "Semiannual Efficient Release Rept. Jul-Dec 1980" \* Duse Power Co 81/02/19 5pp 97850-323
- 6 Reportable occurrences. LERs & related correspondence
- 3103110491 Forwards LER 81-002/017-0 PARKER, N. O. Duke Power Co. 81/03/04 4pp 07872 196
- B103110502 LER B1-002/017-O on B10204.saveral closure studs on reactar coolant pump 3A1 were discovered w/corroston wastage in pump closure area Caused by toalsage from closure gaskets Blud replaced JOHES, J L Dute Power Co B1/03/04 4pp 07872 200
- COMET 50-288 REED COLLEGE PERSEARCH REACTOR
  Inspection reports, 1E Bulletins & correspondence
- 3103020018 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals Uhile on Duty" No written response required ENGELKEN R M. Region 3. San Francisco. Office of the Director B1/02/09 1p 07787 197
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION. UNIT 1

  F. Security, medical, emergency & fire protection plans
- BiD3180264 Ltr to all power reactor licensees u/plants licensed prior to 770101 Forwards NRC position & request for addl info resafe shutdown capability for compliance u/R01117 Pire protection rule EISE(MHJI.D 9 Division of Licensing, 81/02/20 13pp
- B103100038 Requests that encl emergency planning into be rade publicly evailable U/o encl.
  SCUDER-J L. Bivision of Rules and Records. 81/02/27 ip 07833-172
- 8103240411 "Evacuation Time Estimates for Plume Exposure Pathway Evacuation Plume Zone at THI Nuclear Generating Facilities." Related correspondence 

   Parsons. Brinterhoff, Guada & Douglas, Inc. 81/03/03. 171pp. 07937:001
- 8103130522 Forwards testinony re health physics [save 4 (CLI-80-5) in rostert proceeding Certificate of Svc encl 8LAME, E.L. Bhaw. Pittman. Potts & Troubridge 81/03/04 6pp 07913.115

- -BIO312034/ Supercrises along taxon to Entrace tadichagical controls program to resource to Coller health regards evaluation rept & notice of violation ARRIBOR C. Materpolitan Idiano to 1925-2016. App. 0274.6 Material
- BIO3130592 Responds to first \$1 its a set footh to health progenits evaluation as requiring corrective action prior to restart ANAIHLE C. Detropolitan Litten to BO2222 to Ppp. 0791 (464
- B103120557 Provides responses to 44 remaining stems set forth to health physics evaluation as requiring resolution grade to restart ARMZID.R C. Metropolitan 1-fison to - U1702702 - Upp. - 07913-171
  - UIOTIDORA Hoppis BOIRTA DE ILORDE expresses to COLLEA health plysics evaluation includes liens on the on 19, on 14 to on in ARMIDIA C. Estropolitan Loison to UI/2022 2pg 07713 179
- 0103310358 The to all licensess of operating glants & holders of the forwarding RUMIO ORNA. Trunctional distance for Legigency Response facilities fritteria describe acceptable exthod for resting that requirements MAC or or temperature and acceptable policy of the second of the s
- BID5190690 Summary of HIGGS resting whole is status of 1911 I emergency plan 5 implementation schedule improved plan will be mudified fullowing installation 5 install testing of eye implementation schedule end implementation schedule end important to 19170 PATE TO THE OWNER OF THE OWNER OWNER OF THE OWNER OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER O
- \$110.1200.233 Releases public version of implementing proceedings for emergency plan.

  FILTER J B fivesion of Unies and Becords \$122.53235 bp 07606-001
- - #119329025.) Public version of implementing procedures for emergency plan includes unusual event-alert, site 6 general emergency & uffects dose projections Metropolitan filson to 81203001 450pp 07005 031
- BIOREADAY Forwards response to App D of 10032800 to discussion features for facility Updated summany of tequiterents to resolve Open Stems entitle additional required to entere adequate fire projection MARIALIS D. Metropolities to 103800 Co. 103703737 Jpp. 107037 5.55
- Big03300473 Requests that end temergency planning total be placed to IPBR M/O 01003200247
  BRUDIR Jt. Division of Roles and Records 01/0/0/20 1g 00098 125
- 9 Adjudicatory correspondence
- ---
- DIGGO2004D Forwards DE Wasdelas (001010 Associated on the restant feating PIECHOUT, D.Q. Division of Licensing HOVIIVAN IS
- --8103020044 Forwards Di Basdetas differing prof opinion to resters hearing MURIEY-TE Office of Nuclear Regulatory Research. Director 00711794 to
- ---BIO3020032 Disagrees w/Commission biJ314 response to Dispit like se reactor control sys failures Commission position as premised on arronsous assumption that safety sys will mitigate control sys failures at any power BABDEMAS D. Liperimental tast Heactor Hafety Hassarih Branch U0/03/20 7pp
- B103200449 Requests permission to make limited appearance statement et restart hearing Asquests notification re-date & time FREEDMAN-P D Affiliation Unknown H3/13/19 19 17/22 17/2
- 8103200629 Requests permission to make limited appearance statement at

- 00414 Requests permission to make limited appoarance statement 210305 or 11 restant hearing in Harrisburg,PA /EY,E M. Affiljation Unknown 81/01/1⊋ ip 07987 00:
- 305 at TMI-1 restart hearing Requests notification of when appearance statement will be schoduled (8.8. Aftiliation Unknown 81/01/13 1p 07587 00)
- 0612 Requests permission to make limited appearance statement on 105 at Cormission bearings to mate ilmited appro 11CK-0 Affiliation Unknown 91/01/18 [p 07585 001
- 00617 Requests permission to make limited appearance statement at hission B10305 or li hearings re TMI-1 restart FR.A. Affiliation Unknown B1/01/19 1p 07589 001
- 00477 Requests permission to make limited appearance statement 10305 evening restant hearing Requests two was advance ice of date Unges evening hearings be scheduled to mmadate working people 37, J. B. Affiliation Unknown 81/01/27 in 07587 001
- 0497 Requests to make limited appearance statement at restart ing H. D.
- Affiliation Unknown GMITH, B Pennsulvania, State of 2/06 10. 07970 357
- 00223 Notification of contract psecution "Analysis & Testimony on : Estimate Reasonableness TMI-1 Restart." awarded to :ear Energy Svcs.inc :BION.C . EOGENGRIH.P J Technical Assistance Contracts Branch -03-B1-119 B1/02/10 ip 07849 023
- 090229 Contract "Analysis & Testimony on Cost Estimate Assonableness TMI-1 Restart." awarded to Nuclear Energy cs.inc MPER.R.R Nuclear Energy Barvice, inc MATIIA,M J Ministrative Contracts Branch NRC-03-81-115 81/02/10 12pp 1649 024
- 0428 Informs that HJ Manion of Nuclear Energy Svcs.Inc will yze cleanup cost estimate & tastify on NRC behalf at eart hearing.Requests conperation re provision of addi ills & bactground info R W Operating Reactors Branch 4 81/02/11. ip 07811-357
- 0372 Submits limited appearance statement vahemently opposing lity restart. ERT.R.B. Affiliation Unimown 81/02/17, 200 07585 001
- 0560 Memorandum informing that evidentiary hearings on adequacy
- rouse removancem informing that evidentiary hearings on admistib energency preparedness at TMI will begin on Bio303 farriaborg, PA Bvc list encl.
  ER.R.E. Shaw, Pittman, Potts & Trowbridge 81/02/19 3 Shaw, Pittman, Potts & Trombridge 81/02/19 3pp
- 0480 Advises of plans to offer limited appearance statement re osed restort of facility (ffiliation Unknown. 81/02/20. ip 07968 045
- 0341 Requests 810208 itr be entered as limited appearance ement in restart proceeding. INOBILL.D. Affiliation Unknown 81/02/22. ip. 07599:001
- 0047 Forwards FEMA testimony by FJ Bath & VE Adler on certain the emergency planning contentions.FEMA testimony on ining offsite contentions to be filed by 810316. eacl. J.R. Hearing Branch 1. 81/02/23. 1p 07889:206
- 0439 Response to ASLB B10209 memorandum & order re clarification wargency planning issues & status of negotiations.
  ificate of Svc enci.
  ER.R.E. Metropolitan Edison Co. ZAHLER.R.E. Shaw, Pittman,
  s & Troubridge. 81/02/24. 18pp 07782:328.
- O619 Brief, in form of pleading proposing that ABLB make listed ngs on emergency planning issues Emergency plans must ly w/NUREQ-0694 & gain FEMA approval prior to restart. ificate of Svc encl.
  FORD, O.P. Anti-Nuclear Group Representing Voct.
- 07829: 127.

- 8103090700 Advises that Newberry TMI Stepring Committee withdraws contentions. Newberry Met Ed 1-7. also thown as EP-19(a)-(f), due to financial considerations CLHNINGHAM. J D For. Farr & Cunningham 81/02/24 Ip 07585 For Farm & Conningham 81/02/24 ip 07585 001
- 8103180483 Requests to make limited appearance statement at restart hearing Expresses concern re Unit 2 cleanup & opposition to White t being reupened Response requested
  MINTCH.M Affiliation Unincom BI/02/24 to 07945 052
- 8103070989 Memorandum & order denying Antinuclear Oroup Representing York 810205 request for adoption of Sholly energency planning withdraum contentions Denial will not preclude consideration of points differing from admitted contentions SMITH. I W. Atomic Safety and Licensing Board Panel 81/02/25. 7pp 07782-074
- 8103180447 Explains that Newberry TMI Steering Committee did not file brief on four issues as ASLB ordered because of financial problems Failure to file brief was not indifference to CURNINGHAM, J.D. Fox. Farr & Conningham 81/02/25 1p.
- 8103180757 Requests permission to address 810305 public session on issues involved in restart of TMI at William Penn Museur. Harrisburg.PA 5X18BE.W W. National Quesum Co. 81/02/25 10 07954 104
- 8103200606 Requests permission for PA Rural Electric Association to present oral testinony at 810395 public hearing re-facility MOWATT.W.F. Affiliation Hokogup Ht/02/25 in 07971 256
- 8103040591 Notification of contract execution. Mod 2 to "Furnishings for ASLB TMI-1 Restart Hearing" Contractor Cole & Co. CCLEMAN. R M. Administrative Contracts Branch NRC-10-80-717 B1/02/26 Ip 07811 328
- --8103040591 Mod 2, exercising option to extend rental persod of Orouga NRC-10-80-719 BI/02/26 2pp O'Bit 32\*
- 8103200450 Requests that representative of Manufacturers' Association of Berks County be permitted to make limited oral appearance at 810300 restart hearing FIELD:MP Affiliation Unknown 81/02/27 tp 07971:265
- 8103200602 Requests permission for Labelon Stock Foundry representative to make statements re-restart at 810303 public hearing MELLINGER. C.W. April (ation Unknown 81/02/27 lp 07971 259
- 8103200441 Requests permission to make limited appearance statement at Blo305 restart hearing in Harrisburg.PA If permission denied requests that lir by accepted as apposition statement FERRA A A Affiliation Unknown 81/02/28, 200 07972:157
- 8103130450 Request that EB Patterson 810226 affidavit be marked for identification as licensee whibit & be received into evidence Certificate of Svc encl DAXTER.T.A. Metropoliten Edison Co BAXTER.T.A Shaw, Pittmen. Potts & Trombridge 81/03/02 Apr. 07911.258
- --BIO3130452 Affidavit re UCS Contention 10 asserting that Section 4 16 of IEEE Std 279-1968 requires that safety sys must be dasigned so that no operator action can prevent completion of sefety function once initiated PATTERBON.E B Metropolitan Edison Co. 81/02/26 3pp. 07911:264
- 8103190456 Requests to make limited appearance statement at 810305 public hearing Copies of remarks will be available for DOND. J. M. Easton, PA 81/03/02 1p. 07965:093
- 8103130455 Request for order directing NRC to provide all parties w/all info obtained re power operated relief valve, to explain why NRC failed to produce info & to file testimony re restart prior to PORV test completion. W/Certificate of Svc. WEISS, ER Union of Concerned Scientists. WEISS, ER. Sheldon, Harmon & Neiss 81703703. 7pp. 07913 102.
- 8103110561 Memorandum & order that intervenors are to coordinate participation on offsite emergency planning issues by
- 0653 Response to ABLE 810209 memorandum & order re emergency

- Bion200599 Requests permission for PA Natl Turf Club. Inc representative U Shiers of Gatter 6 Diehl. to appear at Biogod public rearing programmed. U J. Artillation Uniscon Bi/03/04 ip 0/971 261
- 6103110339 Forwards J Levendusty affidavit in support of confidentiality request per ICCFR2 750 Affidavit prepared in accordance uting 810122 ftm to Met Ed Affidavit withheld inef 10CFR2 760 BATH. J N Carella, Bain. Silfilan & Rhodes 81/03/05 lp C7827 103
- 8103180530 Testimony on Anti-Nuclear Group Representing York Contention III Billi-requiring predistribution of thyroid Stacking agent Refeted correspondence EE:EA.U Anti-Nuclear Group Representing York 81/03/C6 19pp 07747 286
- --8103182027 Reviews EPRI evaluation re-potential conservatisms & ranges of uncertainty in MESH-1400 analysis of jodine release for TPLB sequence More research required Prof qualifications & Certificate of S.c. enc)

  (EMMINOR B. Nattelle Memorial Institute, Columbus Latoratories 30/08/05 1329 07547-325
- RIO3190628 Joint statement on energency planning contentions Before restart, reasonable progress towards emergency & response plan compliance must be shown M/Centificate of Svc ACLER.R M Pernsylvania. State of GRAY. J R Hearing Branch 1 ZANER.R E Metropolitan Edison Co 81/03/06 5pp 07963 311
- 8103253422 Advises of inability of J Shyers of Oatter & Diehl to attend 910305 hearing at William Penn Museum Requests that Shyers be placed on agenda for 810311 neeting SHUMAKER. J Affiliation Unknown 81/03/06 tp 08000 315
- GIO225341) Requests that Board consider another evening opportunity for public testimony to allow concerned citizens unable to raise questions at 810305 meeting to speak ARCOLOL E. Affiliation Uninoun. 81/03/07 ip 08000.362
- 8103120259 Informs that NRC will file testimony an remaining mgt cepability issues on or tefore whof 810316 Testimony on design mod will be during was of 810316 & 23 Mgt capability issues will begin around 810331 SWANSON.D T Hearing Branch 1 81/03/09 250 07900 198
- --Bi03120263 Responds to 810130 ltr re info flow during TN1-2 accident Agrees winnestigation conclusion that conflicts of info did not result from Lying Withholding of info was not intential HEIDRIE. J M. Commissioners 81/02/20 3pp 07900/209
- --Bi93120272 Responds to Bi0130 ltr re info flow during TMI-2 accident Failure of important info to reach tRC was inexcusable Util motives are questionable New legislation not required Regulations modified to impose clear reporting duties BRADFORD.P A Craissioners BI/O2/24 3pp 07903 212
- --8103120289 Responds to request for personal views re info flow during TMI-2 accident Persons in charge were unoware of or did not understand indications of core damage & gross degradation Recommended enforcement actions inconsistent w/facts MICHELSON.C. Director's Office. 81/02/20 3pp 07900 219
- BIO3190634 Menorandum of law that St Lucie decision.ALAB-603 should not be applied to require quantitative assessment of probability of failure of fifty of the second second second second second circumstances exist BAXIER.TA Metropolitan Edison Co. BAXIER.TA Shaw. Pittman. Potts & Troubridge 81/03/09 13pp 07953 347.
- --B103190641 Second supplemental testimony in response to ASLB Question 6 re emergency feedwater reliability No sound basis exists to postulate unusually high challenge rate to or probability of failure of TMI-1 sys Kyprof qualifications.

  XEATEN.R W Metropolitan Edison Co 81/03/09. 16pp 07964-001.
- --BiO3190646 Testimony re-ecceptability of feedwater transients referenced in NUREO-0360. Friends of the Earth Contention IIIs Feedwater transients not discussed in NUREO were those where sys response was not unusual Certificate of Svc encl RUBIN. P. Procedures & Test Review Branch NOVAK. T. M. Assistant Director for Operating Reactors. BI/O3/II 7pp 07944-017
- 8103200565 Requests to make limited appearance statement at THI-I restart hearings
  CARE.W.J. Affiliation Unknown 81/03/09, ip

- DIO3200737 Respanse to ASLB request for evidence that consideration of control room operator fatigue is epipopriate Certificate of Svc encl Related correspondence AH(001.0 M Affiliation Unknown H1/03/10 22pp. 07967 333
- B1D3290236 Requests apportunity to present statement at realant nearing insufficient time was available at 810309 public nearing insufficient time was available at 810309 public nearing insufficient Uninown B1/03/10 1p
- B103180556 Dajection to tentative testimony schedule received B103D9 Tentative schedule was drafted to accompdate NRC & licensee U/o consulting UCS Alternative outlined WEISS.E R. Union of Concerned Scientists WEISS.E R. Itarmon & Weiss B1/03/12 lipp. 07953 021
- 8103180604 Answer opposing licensee 810302 motion for EB Patterson affidavit to be introduced into evidence Affidavit contains inherently unreliation monorotative b projudicial heareay statements Certificate of Soc encl
  WEISS-E R Union of Concerned Scientists WEISB, E R. Hermon & Weiss 81/03/12 Spp 07953 C63
- 8103180605 Memorandum & order denying admission of J Beyes testimony offered by Anti-Nuclear Oracy Representing York in support of Contention VID: Testimony Pails to provide info matl to class 9 or hydrogen control issues as admitted.
  SMITH. I W. Atomic Gafety and Licensing Board Panel 81/03/12 7pp 07953 068
- B103200715 Reply brief in response to ASLB 810324 request. ABLB should judge adequaty of total emergency planning effort at TMI-1 according to stds set forth in licensee. MRC & PA B10306 joint statement Certificate of SV entl ADLER.R W Pennsylvania. State of B1/03/12 & 6pp 07967 263
- 8103200720 Gubmits final page of licensee radiation protection plan. Attachment I to licensee prepared testimony on health physics entitled "Figure I TMI-I Radialogical Controls Organization" Page Indvertently omitted Wencl GLAKE.E.L. Shaw. Pittman. Potts & Troubridge 81/03/12 4pp 07967-271
- 8103230243 Requests to make limited appearance statement during hearing to restart of facility RCMAND-FR Affiliation Unknown 81/03/14 Ip. 07946 123
- 8103200547 Requests permission to make limited appearance statement on 810305 at Thi-1 restart hearing Requests notification of date t time when appearance statement will be scheduled HMSSLER, Affiliation Unknoun 81/03/16 1p
- B103240543 Certifies B10316 svc of RR Dynes testimony on principals of emergency planning, M Levenson testimony on estimates of accident consequences & DE Podwal, AE Schaufler & RE Royan testimony Related correspondence. ZAHLER:R E. Metropolitian Edison Co. 81/03/16. Upp. 07904-353
- Bi03250267 Requests opportunity to present onel arguments before ABLB re facility restart Expresses gratitude for efforts to obtain input from various segments of population DO::D.J.M. Easton. PA. Bi/O3/16 ip 07997-274.
- 8103250433 Ack receipt of B Motholt testimony in support of Environ Coalition on Nuclear Power contentions Not possible to bind testimony into transcript due to page size B Motholt notified.

  MORAND M Atomic Safety and Licensing Board Panel 81/03/17. Ip. 08022.211
- 8103250434 Informs that public hearing on TMI-1 restart proceedings scheduled for 810311 cancelled.

  MORAN.D M. Atomic Safety and Licensing Board Panel. 81/03/17. ip. 08022.212
- B103260763 Notice of appearance in proceeding Certificate of Bvc encl STRAUBE, N Pennsylvania, State of 81/03/17 Jpp 08036:067
- B10319053B Forwards RR Keimig & DR Haverkamp B10317 testimony responding to ASLB questions re auditability of maint practices & TM1 Alert Contention 5 on reint at TM1-1.

  At Allen B10313 meno to DT Swanson also encil
  SKANSON, D. T. Mearing Branch 1. B1/03/18 2pp. 07955 137.

3190353 Discusses Region 1 review of completeness of record on issue first competence in event TM1 Alert on other parties do not amplete depositions No NAC requirements violated or afety significant concerns uncovered ZIMIO.R R Region 1. Philadelphia. Office of the Director 1703/13 Zpp 07955 214

3190561 Discusses concerns raised in TMI Alert depositions Areas of SITUDE Discusses concerns raised in TMI Alert depositions ( realest emphasis are processing maint work orders baction f orders estensive overtire plant components tests radwaste perations 2, temporary repairs W/Certificate of Bvc HRISTOPHER, R NRC - No Detailed Affiliation Olven 80/07/1 pp 07955 216

50232 Discusses Bi0311 itr re limited appearance tements.ASLB ujil take advice under consideration FM, I W. Atomic Safety and Licensing Board Panel - 81/03/18 - 1p 01 298

3290238 Resuests scheduling of addl public evening sessions to comodate people wishing to make limited appearance tatements ASLB should offer B Bmith apology & apportunity address Scard JBSLER, D.E. Affiliation Unknown 81/03/11 15 08001 299

50241 Discusses 810318 ftr re limited appearance statements ASLB t take advice under consideration
Thil W Atomic Safety and Ligensing Board Panel 81/03/18 to 6.201

0250245 Requests scheduling of add1 public evening sessions to comodate people wishing to make limited appearance catements Public was misinformed about hearing date & ould be heard ÆTROM. B. Three Mile Island Public Interest Resource Center 1/03/10. 1p. 07996-202

30404 Requests opportunity to comment on restart of TMI-1 30N.P. League of Women Voters of Greater Yark.PA 81/03/18 lp 300:361

80696 Forwards DR Neely testimony re-ASLB question on health lics program & Buppl 2 to NRC Trij-1 restart evaluation 180-06801 Certificate of Bvc enc; 1800-08 T Hearing Branch L. 81/03/20. 3pp 07973 100.

9230672 THI-: RESTARY Evaluation of Licenses's Compliance W/Short & ing Tarm Items of Section II of NRC Order Dated August 9.
179. (Net Ed et al.Thres Mile Island Nuclear Station.Unit I. incket 30-289)

Office of Nuclear Reactor Regulation, Director. NUREG-0680 902
11/03/31 20pp 07973 103

1230678 Testimony re ASLB questions of health physics program paguoro lestimony re AULB questions of health physics prograil corrective actions 8 commitments in response to items 1 noncompliance 8 significant findings are satisfactory of qualifications enci ELLY, D. R. Performance Appraisal Section 81/03/19 100pp 1973-124

0437 Order denying util 801201 request for restart prior to ring completion & deferring request to modify 800702 & orders.Orants 810203 motion.permitting hot functional ling & strikes financial qualifications issue W.B. J. Diffice of the Secretary of the Commission 81/03/2: Office of the Secretary of the Commission 81/03/23

eral correspondence

07995: 351

0929 Bupports facility restart. |OFER+M. Affiliation Unknown. 80/02/27 2pp. 07986:001.

0617 Opposes facility restart.Psychological stress.hydrogen rol & managerial & financial issues have not been dealt \ operly. LER.D. Affiliation Unknown. 81/01/13. ip. 07963:279

0590 Urges restart of facility NRC should expend resources in lating & licensing nuclear facilities: STYK,J Affiliation Unknown. 81/02/03. Ip 07996.059

0612 Bupports fætility restært. NBLABT.F.R. Affiliætion Unknown. Ø1/02/03. 4pp. 07986:001.

0286 Forwards AD Southworth 810206 ltr supporting facility art.Requests statements be investigated & info for reply rned. 0:C.W. House of Rep. 81/02/13, 1p. 07923:216.

BIO3180950 Urges that facility be returned to svc to alloviate dependence on Poreign oil LOUGHRAY.J J. Affiliation Unknown 81/02/17 ip 07944 268

8100200550 Requests opening of facility to prevent dependence on FANELLO-L Affiliation Unknown 81/02/20 to 07968 047

8103170592 Urges that NRC not allow restart of TMI-1 until all hearings tompteted to proceeding to findings published HITCHCOCK.M J. Affiliation Unknown 81/02/21 Ip 07929 347

8103180628 Opposes facility restart VDN ZELLEN.8 & Affiliation Uninoum 81/02/21 Ip 07954 189

Bio3170366 Opposes restart of TMI-1 Residents have suffered enough FALILIR. Affiliation Uninown 81702722 ip 07923 198

BIO3170603 Protests proposed facility restart Opposes placing economic priorities above safety & environ concerns
DAVIDSON: J Affiliation Unknown 81/02/22 in

BIO3180383 Opposes restart of TM1-1 until TM1-2 has been cleaned up ENSINGER.S Affiliation Unknown BI/02/22 Is

B103170395 Deposes facility restart
GARFIELD P Affiliation Unknown 81/02/23 to 07989 001.

8103170598 Urges NRC not to restart Titl-1 Residents have had enough stress & onliety in last two yes due to Titl accident REYNOLDE.A Affiliation Unknown 81/02/23 1p 07585 001

8103180709 Protests proposed restart of unit Expresses concern re danger to public safety & health
LASSELLE.M. Affiliation Unknown 81/02/23 is

B1031B076B Requests that NRC restart TH1-1 RCOERS.R C Affiliation Unknown B1/02/23 tg 07954 (05

8103203554 Urges restart of facility
0:AMBRUC50.0 S Affiliation Unknown 81/02/23 Ic 07968 048

8103200559 Opposes restart of facility Psychological stress to local citizens outwelghs economic benefit BARR.R A Affiliation Unknown 81/02/23 Ip 07970 251

8103200409 Opposes reopening of underaged facility until waste removed from damaged Pacility SHOMBERT.E Application Unknown 81/02/23 ip

8103200629 Urges opening of facility
BENEDICT.M Massachusetts Institute of Technology D1/02/23. Ip. 0776E 050

BIO3170327 Opposes restart of Tril-1 TOPOLEXI.E., TOPOLEXI.J., TOPOLEXI.A Affiliation Unknown B1/02/24 ip 07939 273

8103170357 Opposes reopening of TMI-1 & -2 Implementation of evacuation plan inadequate. \* Affiliation Unknown 81/02/24. 1p

B103170367 Opposes restart of TMI-1.use of radioactive scrap for consumer products & proposal to spread cost of TMI-2 cleanup by increased util rates DEFARRARI.0. DEFARRARI.A Affiliation Unknown 81/02/24. Ip. 07939 269

8103170398 Opposes facility restart due to absence of evacuation RUSCAVOER, M.E. Affiliation Unknown. 81/02/24. 1p 07585-001

8103180999 Requests that facility remain shut down NEWTON: M. Affiliation Unknown B1/02/24 1p

B103180575 Requests that util be allowed to restart facility.

FINN.C., FINN.B. Affiliation Unknown 81/02/24. ip. 07944 270

8103180774 Expresses concern on behalf of Reading Industries re cost of electricity in area Restart of undamaged reactor would alleviate burden STROUCE, R. A Affiliation Unknown 81/02/24 1p

- highliogh Forwards of 6 pm Holler Bible? Its opposing facility restart for review 6 consideration (CCCC105.9 miles of Rep. 81/02/25 1p. 07923-214
- #10317-3375 Busports facility restart based on economic reasons SROHLR D Affiliation Shiroup 81/02/25 292
- 8103170497 Urges permanent shutdown of facilities [AVIS-3] Affiliation Uninch 81/02/25 Ip 07939 276
- 8103190497 Supports facility restart PumpCK.W.B. Affiliation Univolum 81/02/25 ip 07965 202
- 6103190510 Supports early restart of Unit 1 & continuation of Cleanup of Unit 2
- BIODI70345 Urges restart of TMI-1
  FORTE & P. Affiliation Urthough 81/02/25 to 07585 001
- 8103190397 Supports facility restant DDDH.JE Affiliation unancan 81/02/26 to 07965 191
- 8103190458 Expresses apposition on behalf of LH Weaber Son.Inc.re plant shutton due to economic reasons Requests ASLB rule in favor of restart

  EARER, G. Affiliation Unito.n. 81/02/26 1p 07965 147
- BIG3190593 Urges that util be granted right to restart facility u/o further delay, due to high energy costs to customers Nuclear energy for electric generation is economical & safe NCRATES K B Affiliation Uninown BI/O2/26 1p 07995 060
- G103190597 Eigresses concern over delay in facilit, restart Facility was not damaged during TMT incident Custamers & stockholders are carrying heaviest burden MARTIKI CM Affiliation Unknown 81/92/26 to 07587 001
- 8103192630 Supports facility restart on tehalf of citizens of Borough of Myerstock.PA 19641-8 M Affiliation Uninc.n 81/02/26 16 07955 200
- 8103190635 Supports facility startup SNYDER: G F Panufacturers Association of York-PA 81/02/26 Ip 07965-227
- B103200512 Requests ARC expedite permit to reopen facility WILLARD. C. Affiliation Uninous 81/02/26 ip
- B103200939 Urges startup of facilities WILLAGO.C.L. Affiliation Unknown B1/02/26 Ip 07585 001
- 8103200605 Opposes facility restart BOMORER B. BERGER, B. Affiliation Unknown BI/02/26 lp 07971 257
- 8103170363 Urges NRC to teep TMI-1 shutdown BENTLEY.8 G Affiliation Unknown BI/02/27 1p
- 8103190007 Advises that rescheduling of 810306 Juncheon/meeting for Lancaster & Lebanon Chambers of Commerce to 810617 is acceptable Requests vieugraph projector for use during talk HEHORIE.J H Commissioners 81/02/27 tp 07960 106
- --B103190009 Advises that luncheon/meeting w/Lebanon & Lancaster Chambers of Connerce has been rescheduled for B10617 Requests attendance MALKER.R S House of Rep. B1/02/23 1p. 07960 107.
- BIO3190400 Supports facility restart RILEY-R C Affiliation Unknown 81/02/27. 19 07965 192
- 8103190473 Favors expedited restart due to economic situation. MAULE. B L. Lebanon County. PA 81/02/27 ip 07965-148
- B103200482 Opposes restart Safety of people not politics, should govern future of nuclear power PARSON. C. H. Affiliation Unknown 81/02/27. Ip 07968:046
- B103200603 Opposes facility restart. SHARP.J Affiliation Unknown 81/02/27 ip. 07971:258

safety of residents CCHANLL Affiliation Uningon 81/02/28 lp

G103170347 Urges ARC to isep TMI-1 shutdown First priority must be

- B:C3170650 Opposes facility restart SCHRADER,D. Affiliation Unknown 81/02/28 1p. 07985-001
- 8103190406 Supports facility restart
  PHILLIPS F Affiliation Unknown 81/02/28 ip 07965 193
- Bi03190422 Supports facility restart
  DEVLIN.C M Affiliation Unknown 81/02/28 1p 07986 001
- G103190441 Requests that vote in favor of restart be considered at ASLB 810305 hearing BLECHER.K A Affiliation Unknown 81/02/28 1p 07465 146
- 9103190447 Urges TRI-1 restart.

  COX.F. Affiliation Unknown 81/02/28 ip 07586 001
- 8103190459 Supports facility restart LEE, M.V. Affiliation Unknown 81/02/28 1p 07965 203
- 8103190465 Supports facility restart
  SAXQN.H J Affiliation Unknown 81/02/28 tp. 07586 001
- 9103190489 Urges that facility not be permitted to restart due to threat posed to public health & safety Commission must resist pressures from utils MICHELSCHIA Affiliation, Unknown 81/02/28 [p
- 8103190499 Favors restart 703ER.E A Affiliation Unknown 81/02/28 ip 07587 001
- B103190518 Urges restart of TMI-1.due to excessive electrical costs MERKEL.L. 5 Affillation Unknown 81/02/28 lp
- BIO3190523 Endorses Unit 1 startup YCUNO, W 0 Affiliation Uninown B1/02/28 Ip
- 8103190539 Supports facility restart STOCKER.9 P Affiliation Unknown 81/02/28 2pp 07586.001
- 8103190578 Urges restart of TMI-1.due to excessive electrical costs. RRUK.S J. Affiliation Unknown 81/02/28 tp. 07587-001
- B103190675 Urges NRC to facilitate restart of TMI-1 As soon as possible MCLLEMBACH D M Affiliation Unknown B1/02/28 ip 07465 170
- B103190696 Urges restart of TM1-1 as soon as possible.

  HARMOND, H K. Affiliation Unknown. B1/02/20. 1p 07086 001
- BiD0200614 Opposes facility restart MCKINNEY.R Application Unknown 81/02/28. ip. 07887 001.
- 8103200635 Opposes restart of plant 00310N:S Affiliation Unknown 81/02/28 1p 07387:001
- 8103170477 Opposes restart of IMI-1.
  MARTIN. 9 8 Affiliation Unknown 81/03/01 1p
- 8103190373 Urges irmediate restart of facility Expresses concern rehigh electric rates 8100.4 A Affiliation Unknown 81/03/01. 16 07884-001
- B103190396 Supports restart of TM[-1. STEPHENB.W.F Affiliation Unknown 81/03/01 1p. 07965 102.
- 8103190410 Urgas TM1-1 restart BCMEIN.C.W Affiliation Unknown. 81/03/01 ip 07984:001.
- 8103190431 Supports facility restart TROY: C T. Affiliation Unknown 81/03/01. Lp 07965.201.
- BIO3190472 Supports facility restart.

  BEROMAN, B H. BERGMAN, H K. Affiliation Unknown. B1/03/01. 1p
  07955.204.
- B103190475 Supports restart of TM1-1. LAUCHS.J R. Affiliation Unknown. B1/03/01. Ip 07586:001

190490 Endorses Unit I startup to enable util to decrease purchase electricity from neighboring companies & lower customer tes I.F. Affiliation Uninoum 81/03/01 10 07586 001

90540 Urges favorable decision re Unit 1 restart Higher util bills ed as reason for endorsement

90541 Urges that Unit I be put on line to lower high util hills people on fixed incomes LEG. J.F. Affiliation Unknown 81/03/01 ip 07587 001

90546 Bupports restart Affiliation Unknown BI/03/01 In GARD, J

90557 Comments on facility restert Solar heat & electricity ored over nuclear power Unit should not be restarted Affiliation Unknown 81/03/01 tp 07587 001

90575 Uiges that Unit 1 be returned to operation Shutdown places my financial burden on util & custoners RD-ME Affillation Unknown 81/03/01 p.

90625 Opposes facility restart ST.O Affiliation Uninown 81/03/01 2pp

00488 Supports restart of TMI-1 Nuclear power essential for

d of country Affiliation Unknown 81/03/01 1p

00515 Urges TM[-1 restart DERSON.J.E. Affiliation Unknown 81/03/01 to 07597 001

00946 Opposes restart of facility WARTZ.J. Affiliation Unknown 81/03/01 ip

00573 Opposes facility restart Energy not worth risk (E9.8. Affiliation Unknown 81/03/01. Ip

00527 Claims that media & press presented false picture of TMI. gests NRC listen to knowledgeable scientists NOR.8 H. Affiliation Unknown 81/03/01 1p 07587.001

6049: Requests denial of request to restart facility 8CO.D C. Coalition for Nuclear Power Plant Postponement 03/02 | 19 | 07036-243

70327 Opposes nestart of THI-1 ELL:P J - Affiliation Unknown. 91/03/02 - Ip. 07989 001.

70494 Requests that facility be restarted to halt steep rise in ctricity rates NN.F. Affiliation Unknown 81/03/02, 1p 07585 001

70443 Opposee facility restant. ZNANBKI/J Affiliation Unknown, B1/03/02, 2pp. 07925:153

90379 Requests that ASLB favorably consider restart of TMI-1 ORICH.R.C Affiliation Unknown 81/03/02 10 07965:103

90389 Urgs immediate restart of facility Cites high util bills & to of manpower & equipment Expresses faith in util formance.

EL.W J. Affiliation Unknown 81/03/02 1p. 07586-001

70403 Urges immediate startup of facility. Expresses concern re-reased electricity rates News Itam re-Mount Bt Helens SCYDD, J K Affiliation Unknown 81/03/02. 1p 07586.001

90435 Favors restart due to facility track record & need for addl ctricity TAOIRDNE.T Pennsylvania, State of. 81/03/02 ip. 07965 145

9046B Forwards resolution on TMI-2 & revised resolution on TMI-1. behalf of Chamber of Commerce. Supports facility restart revised TMI-1 resolution.

MM.A.F. Berks County, Leesport, PA. 81/03/02. 2pp 07965-267

70474 Opposes facility restart ES.D. Affiliation Unknown 81/03/02 2pp. 07586.001 8103190481 Urges ASL3 to authorize restant of TMI-1 Coal-fired plants produce acid lain that destroys vegetation 6 fish
DEETER.H t. Affiliation Unknown 81/03/03 1a

BIO3190489 Urges restart of IMI-1 CREOAR.K 0 Affiliation Unknown 81/03/02 1p 07965 149

8103190499 Expresses concernive dela, in facility restantidue to need for more energy & current high oil prices.

• Affiliation Unknown | 81/03/02 | 17

B103190501 Urges on behalf of Whitmover Labs. Inc restart of TMI-1 w/o bupassing safe operating procedures Cust of electric power should be lower willie, D. J. Affiliation Unknown 81/03/02 Tp 07965 154

8103190504 Requests that ASI8 authorize restart of TMf-1 8ARTHLE L. Affiliation Unknown 81/03/02 Lp 07587 001

8103190507 Supports prompt restart of TM[-1 IRCOP.C.L. Affiliation Unknown 81/03/03 in 07587 COL

8103190509 Supports timely restart of TM1-1 Operation of Unit 1 during 1980 would have saved hose large sums in util costs PAISLEY, T.C. Lebanon Valley General Hosp Lebanon, PA - BI/03/02 15 07765 195

BIO3190512 Recommends that facility be activated as suon as possible Shutdown has caused higher electrical costs DICKSOW D.M. Affiliation Unknown BI/03/02 ip

BIO3190931 Endorses Unit | startup for survival of util ALBRIGHT C L Affiliation Uninous BI/03/02 |p 07987 001

8103190544 Requests that ASLB permit restart of IMI-1 HICKERNELLIH E Affiliation Unknown 81/03/02 ip 07965 051

BIGG190548 Daposes restart of facility
BRAUN-R A Affiliation Unknown 81/03/02 ip 07965 090

B103190551 Opposes restart of facility

\* Affiliation Unknown B1/03/02 ip 07965.089

8103190834 Requests reopening of facility DICUS.M J . DICUS.W J Affiliation Unknown 81/03/02 1p 07765 ORB

8103200416 Opposes proposed restart of facility Cites expert testimony & health & safety considerations
BORKER.R A Affiliation Uningum. 81/03/02 ip 07987.001

B103200507 Opposes Unit I restart Atomic energy is unsafe Analety re-possible atclosent a lack of sefe disposal expressed BIRK.A J Affiliation Unknown B1/03/02 1p

8103200535 Dpposes TMI-1 restart
BREITHAUPT. 0 L Affiliation Unitnoun 81/03/02 10 07972 165

8103200556 Urges restart of TM1-1 OQLE.H.G., OQLE.S.A. Affiliation Uninown 81/03/02 to 07948-082

9103200667 Urges early restart investigation & decision by NRC has been delayed too long.
STUEBNER, V.F. Affiliation Unknown 81/03/02 in

8103170654 Comments that delaying of TMI-1 restart constitutes natl scandal Also believes Diablo Canyon should be licensed. COHN.W.E. Affiliation Unknown. 81/03/03. 2pp

8103190380 Urges immediate startup of facility after thorough safety check & corrective action
LivingaRT, A. Affiliation Unknown. 81/03/03 ip. 07584:00#

B103190394 Urges restart of TM1-1. EVANS-R. Affiliation Unknown. 81/03/03. 1p. 07586.001.

Bi03190424 Favors restart of TMI-1 on behalf of Brandywine Recycler's. Inc due to Met Ed extra charges for power resulting in acconduct havoc for many businesses.

DIXON, F. J. Affiliation Unknown 81/03/03. Ip

B103190438 Requests opening of facility w/o delay EHNTHOLTER, Affiliation Unknown 81/03/03 ip. 07965.094

- oregrey and deficiation changes Biviaxos ip 07585 001
- Hir 33 41467 unges unnotiate restant of fatility Expresses concern re ting talls, continue of the co
- AIOJ190483 Capases restart of facility-die to inadequate evacuation plans infairness to public upritions 5 MMC apparent sizentation toward muclear advocacy Objects to burden of proof to justify why facility should not be restarted #104/ER.T.T. Affiliation orknown 81/03/03/3 200 07956 067
- H103190515 Requests immediate restart of TMI-L & subsidies for moving people from visinity of facility
  njewby w Affiliation Union 81/03/93 is 07965 092
- 0103140319 Supports facility restant SAUER A.R. Affiliation Uninc.1 81/03/00 Epc 07965 255
- Bio3i90581 Urges restant of IMI-1 IAIER C. Affaliation Colocum 81/03/03 IP
- 8:03:905u3 urges continued shuttown of facility, our to Unit 2 accident
   Affiliation untroun 80/03/03 19
- 6:63263315 Gammaes restart fMIG Affiliation Univien 81/03/03 to 07585 001
- 8103200490 Strongly apposes Unit 1 restant Complete facility shutdown J/alternate coal power favored
  Fix.H. Fix.J. Fix.R. Affiliation Unincom. 81/03/03 in
- 8:03200523 Suggests that 690 have control of nuclear safety to ecological studies Water from TM) should not be durated in COSCAM-E G Affiliation Uninoun 81/03/03 256 07587 001
- 8103200624 Corrents by Brandywire Recyclers Inc on facility restart DIACY, F. J. Affiliation Uninoun 81/00/03 to 07971 291
- 8103119348 Bupports TMI-1 restant & licensing of other facilities SHERHOOD, G L Affiliation Uninoun 81/03/04 10 07685 283
- BIO3179352 Urges NRC to keep TMI-2 in operation & TMI-1 reopened BCRY50VR12-1 A Affiliation Unknown BI/03/04 Ip
- 8103170405 Supports facility restart based on economic reasons PDVALCIK.U Affiliation Uninoum 81/02/04 2pp 07585-001
- BIO3IBO558 Ltr authored by Tate Action.orging shareholders to support restart of TM[-1 Noclear power is safe.inespensive \$ needed.
  EGRIS.N R Affiliation Unknown 81/03/04 2pp 07953 233
- 8103180648 Responds to litr requesting federal aid to especite cleanup of Busqueharna River following THI accident Delays are due to development of cleanup methodology rather than insufficient funding FCEGE. W H HHS. Dept of US Public Health Service 81/03/04 1p 07954 183
- 8103190433 Requests opening of facility MEIDNER.S Affiliation Uninoun 81/03/04 ip 07586-001
- 8163190473 Bugperts facility restart Considerable amounts of money uculd be saved by placing facility back into svc
  DELANO.8 J. Affaliation Unknown 81/03/04 1p. 07965-266
- 8103190479 Supports facility restart Non-nuclear energy sources cause more deaths than nuclear power MILLEVILLE.D P Affiliation Unknown 81/03/04 1p 07965 265
- 8103190497 Supports facility restant Other sources of energy cause adverse health offects CAMPBELL-R M Massachusetts Voice of Energy. 81/03/04 ip 07965 260
- 8103200420 Apposes proposed restart of facility until safe means of nutjear waste disposal found TUCKER.H Affiliation Uninoun 81/03/04 Ip 07587 001

- BIO3203922 Requests info re TMI financial condition Hopports restar GAUSEWITZ-C Affiliation Uninous GI/03/04 Ip 079/1 020
- BIO3190469 Urges restart of Unit 1 & cleanup of Unit 2 Hiddletoun, Farea badly needs electricity produced by facilities DVERDEER.E 9 Affiliation Unino.s G1/03/03 2ep 07956 OAS
- B103190486 Opposes facility restart ALLEN.J V Affiliation Unincon B1/03/09 Ip 0/986 G01
- 8103190585 Urges permanent shutdown of THI-L BERG.8 Affiliation Unknown 81/03/09

ALDEM M S Affiliation Unknown 81/03/04 1p

- 8103200620 Corrects by Pennfield Corp re facility restart Util has inserved comments by reprinted Corp to racillity to learned lessons from accident Bupports restart BRECKERTIDGE, Pennfield Corp 81/03/05 Ppp 62971 993
- 8103200621 Supports facility restart, w/adequate safeguards EDAIN.T.J. Affiliation Uninc.n. 81/03/00 16 079/1 292
- 8103200433 Suprocts Pacifity restart BANKEY, J AFFILLATION UNFROWN 01/09/06 10
- BIO3200437 Supports facility restart
  MARW30D.F C Affiliation Unknown BI/03/06 ip 07971 266
- ALDS200527 Obooses INC restart DIEHL, C.D. Affiliation Unknown 81/03/06 Ip 07971 300
- B103200534 Daposes Int restart RCBERTS D O Affillation Unknown 13703/06 1p 62505-001
- BIO3250366 Requests addl public hearing on facility restart to accordate various community concerns
  ARNOLD.L E Affiliation Univolum BI/03/0/ In 0.2022 170
- 8103270692 Requests decormissioning of facilities, doe to serious Violations & rists of radiation
  PIPER, D.L. Affiliation Unknown 81/03/08 [p.
- 8103180519 Expresses shock to delays in ficensing new nuclear plant-Cormissioners responsible for delays

ALLEN.C.R. Affiliation Unknown 81/03/09 16 07944 261

- 8103189692 Contents that federal aid should be granted to expedite cleanup & hazard removal for people downstream along Susquehanna River BURNS.R O Affiliation Unknown B1/00/09 1p 07984 179
- 8103190460 Supports facility restart ZEIDLER, W.F. Affiliation Uninoum 81/03/07 Ip 07965 269
- 8103170514 Commonts that approved evacuation plans & niher safeguer: are needed before facility restart REINHARD. A Affiliation Unknown 01/03/07 1p 07965 257
- B103190620 Deposes facility restart JONES J Affiliation Unknown. B1/03/09 ip 07806 001
- 8103190638 Supports restart of plant LOUS-E.M. Affiliation Unanoun 81/03/09 Rpp
- B10320D442 Opposes Pacifity restart BERKE.M. Affiliation Unknown 81/03/09 1p 07507 001
- 8103200459 Opposes Pacifity restart. AMES, A E Affiliation Unknown 81/03/09 Ip 07507, 001.
- BIO3200630 Opposes restart of plant BROADHURST.M.E. Affiliation Unknown. BI/03/09. ip 07507 001
- 6103180446 Forwards NUREO-0689, "Potential Impact of Licenses Defaul on Cleanup of TMI-2 " Final programmatic EIS re disposal & decontamination of raduates prepared Tril-1 restart to be decided after ABLD hearing termination
  DENTOD: H R. Office of Nuclear Reactor Regulation, Director. DENTON H R. Office of No. 81/03/10. 1p 07953 049

eanup costs & IMI-1 restart EMSTAD.8. A. Business. Industrial. & Professional Association /02/20 3pp 07953 101

0483 Questions safety & feasibility of TMI~1 restart teside TMI-2 owns absenting sarety a leastillity or interse nup operation Cites atmosphere of intense public ting b warns of catastrophic consequences of any ificant accident ENAN.W Affiliation Unknown. B1/03/16 lp

0413 Supports facility restart .H.A. Affiliation Unisown - 81/03/16 - 1p - 07586-001

0925 Bugports facility restart orks County Chamber of Consonce - 81/03/16 - 1p - 07965-237

0387 Oraup of ltrs re facility restart One comment on proposed s 100FR30.32,70 & 150 re smelted alloys encl LTPS.J.H. PIERNOJ.J. KRÉNEN.B. Affiliation Unknown 81/03/16

OBOB Urges restart of facilities Environ, political economical & obdo viges restait of recriticies chorion politic ological damage caused by needless shutdowns are asurable AM.R.B. Affiliation Unknown - 81/03/19 - 1p

0702 Responds to ltr submitted on behalf of CP Baith re restart nit | & cleanup of Unit 2 Final ETS on Unit 2 concludes existing methods are adequate to perform cloanup ASLB sion on restart will be made in late 1981 ERER.C. Office of Congressional Affairs | BI/03/19 | Ip 7-049

0703 Expresses concern re startup of facilities BITT,M M Affiliation Unknown 81/03/20 ip.

DBIS Urges NRC to expedite full power licensing of facilities & art of TMI-1 Concern for safety % careful review of nsing process has gone beyond reasonable caution AQL.J.W. Affiliation Unsnown 81/03/21 1p ( 08037 346

ancial information

OBA? Bubmits rapt for Jan 1981 of progress made toward curtailing expenditures to remain within credit available through ng 1981 Combination of factors reduced noed to borrow & it available

KAMP.H. Metropolitan Edison Co. 81/02/18 600 07939 022

0628 Forwards response to item 7 of KRC 800811 request for addi-ncial info & revised final responses to Questions 5 & 6 re-variation of operating & maint costs w/plant city factor will be provided later. LL.H D. Hetropolitan Edison Co. 81/02/26 23pp. 07794 118

OCR2 Hotifies that primary contact for cleanup cost estimates be OE Myers. LL.H.D. Metropolitan Edison Co - 81/03/09 - 1p. 07904-355.

rating license stage documents & correspondence

0589 Bunmary of 800821 meeting w/B&W reactor owners group re-rmal transient operating guidelines program. ING.G. Operating Reactors Branch 4 - 80/09/30. 29pp

0040 Forwards DE Basdokas 801010 memorandum re restart hearing MHUT. D. O. Division of Licensing. 80/11/26 1p.

020044 Forwards DL Basdekes differing prof opinion re restart aring RLEY.T.E. Offico of Nuclear Regulatory Research, Director /11/04. ip.

020047 Bubmits position on safety implications of control sys & ant dynamics & relevance to restart hearings. In response 801010 request Safety sys will not mitigate control sys llures at any power. Biperimental Past Reactor Bafety Research Branch 710/10. 2pp.

BASOBINAS.D.L Experimental Past Reactor Safety Research Dranch BNO93020 720

- 8103190732 Line to all licensees of operating plants, applicants for Ole & holders of CPs is control of heavy foods Requests review per guidelines in NJREG-Obi2 Forwards NRC position re interim actions & request for addition EISENMUT, D. G. Division of Licensing 80/12/22 30pp
- 8101150319 Discusses followup study re segradation of internal apportenences in LER piping during normal plant operation & potential effects when degraded apportenances are subjict accident loads Recommends broad review of recurrent problems DROWN E J Director's Office 80/12/24 4pg
- 810319038/ Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification one addesy-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737 EISEN-WI.D G Division of Licensing 81/01/19 Epp
- 8103040667 'Degraded Orid Protection for Class JE Power Sys, IMI Nuclear Station. Unit 1." technical evaluation rept CLEVELAND. C.J. EG&O Idahu. Inc. FIN A-6429 8103040667 81/01/31 1102 07816 017
- GIG3120014 Ltr to all licensees of operating plants.CP holders & QL applicants, except Indian Point 2 & D.Zion 1 & 2 & INI-1. forwarding inacvertwintly chitted pages from ARC 801222 request for addl (info re control of heavy loads ESESNHJ). D O Division of Licensking 81/02/03 App
- 8103050725 Aivises of completion of review of 800630 rept submitted in response to MRC 791121 request for info re loading on steam generator tubes induced by slug flow Item 11 K 2 15 is resolved. REID,R W Operating Reactors Branch 4 81/02/09 4pp 07829 067
- B103300160 Ltr to all uperating PWR ticensees requesting info on auciliary feedwater sys soismic design. Forwards request for addl info. list of actions requested of licensees w/o seismically qualified sys t results of ARC welldowns EISENRUT. D C Division of Licensing 81/02/10 13pp
- 8103100642 Requests response to ACRS 601211 ltr re pruposed restart status review Response should be submitted within 30 days REID.R.W. Operating Restors Branch 4 81/02/11 5pp 07843 01 07843 019
- 810316069 Etr to all operating plants 3 CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met.

  EISENMUT.D 9 Division of Licensing 81/02/18 12pp
- 8103290024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leatege testing detations Licensee may submit analysis to justify use of pristing low flow controller EISENHUT.0 0 Division of Licensing. 81/02/20 Bpp
- B103090699 Generic ltr to all B&W licensess re capability of small break LCCA model to predict small break behavior Post-test evaluations of L-4-1 & 8-07-100 predictions requested for submittal by B10401 REID.R.W. Operating Reactors Dranch 4. 81/02/24 3pp
- 8103060130 Requests add1 Info re util 800626 request for permission to use TEDA-R & GMR-1 canisters for protection against particulate radionuclides Util must submit acceptable testing program & test data prior to use of canisters BARREIT.L. H. TMI Program Office 81/02/25 5pp 07839:042
- 8103110398 Forwards "Equipment Evaluation by Ofc of Nutlear Reactor Regulation for Net Ed. IMI-1." partial review Written response requested NOVAK, T. M. Assista 5pp 07884.045. Assistant Director for Operating Reactors 81/02/25
- equipment Evaluation by Oft of Nuclear Reactor Regular Mot Ed. TMI-1." partial review.

  • Office of Nuclear Reactor Regulation, Director 81/02/25
  25pp. 07684:100.
- 8103120085 Requests monthly progress repts to easist NRC w/scheduling & planning of evaluations % insps REID.R W Operating Reactors Branch 4 81/02/25 4pp 07900-334

- Officials for the all licensees of operating nuclean power plants 5 applicants for CLs (except 5) bucke. Units 1 & 21 Requests that review to determine capability to nitigate station classoft event to promptly implement engaged, procedures gradebungs 0 & 0.11ston of wicensing 81/02/25 350
- --GiC3120745 Safet, evaluation me item 11 x 2 ig. Benchmark Analysis of Sequential Austrian, Feeduater Flour for BSW reactor plants intent of Action litem [[ x 2 ig accomplished 5 results provided by GRAIT-2 similar to TREP-2 gargam w Office of Nuclear Reactor Regulation. Director 81/02/27 22p
- 6103120275 Act receipt of 800275 response to 790921 info request to 8&H 10310372 Act recest of BUNE 10 response to 79084 throft reactor curers Requirements of THI Action Plan Item II # 2 19. Serctions Analysis of Sequential Ausiliary Feed. attention of Fulfills request Safety evaluation end FCIO.8 # Cyrrating Reactors Branch 3 81/02/27 2pp
- -- 0:03150308 Safety evaluation to TM1 Action Plan Item II X 21 19. DUSTIONING Makety evaluation me uni action man icen il Action appropriate and provided appropriate Autiliary Feeduater Flow for 25th plants intent of Action Iten II K 2 19 accomplished to results provided by CRAFF-2 similar to TRAP-2 program — Office of Muclear Reality Regulation. Director — 81/02/27 B1/02/27 2gp
- 6:03120767 Discusses compliance w/TMI Action Plan Item 11 % 2 17. Beathmans Analysis of Sequential Autiliary Feedwater Flow Marchars Analysis or bequerical Autiliary recounter references rigorous assessment is being performed under Stem II x 3 30 Item is resolved Safety avaluation encl REID. P. A. Operating Reactors Stanch 4 8(/02/27 200
- BIG006G520 Advises that procedures for inadequate core cooling & control is provided by B10401 & control of the provided by B10401 Metropolitan Edition Co 81/02/28 2pp 07826 204
- 8103093193 Notification of 316462-03 resting WBSW owners group in Cethesda MD to discuss responses to NPC BIOIOF jtr re asymmetric LOCA loadings VISSING C Operating Reactors Branch 4 81/03/02 2pp
- G103120761 Act receipt of 800610 response to 790821 info request to B&W reactor curers group Requirements of INI Action Plan Item II A 2 19. Benchmart Analysis of Sequential Auxiliary Feedwater Ficu. Fulfills request Sairety evaluation encl PEID-R M Operating Reactors Branch 4 81/03/02 4pp
- --8103120270 Safety evaluation to TMI Action Plan Item 11 H 2 19. "Benchmark Analysis of Sequential Austitary Feedwater Flow Intent of Artian Item II K 2 19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program

  • Office of Nuclear Reactor Regulation, Director 81/03/02 2pp
- 103060628 Responds to NUREG-0737. Item 11 D 1 re safety & relief valves 6 piping, block valves 5 ATAS tessing Util endorses EPRI safety t relief valve test program for templiance UV/NUREO-0578 MJKILL.H D. Metropolitan Edison Co. 81/03/03 2pp 07838 346
- 8103130522 Forwards testimony re health physics Issue 4 (CLI-80-5) in restart proceeding Certificate of Sic encl BLAME, E.L. Shaw, Pittman, Potts & Trombridge 81/03/04. opp 07913 115
- --8103130538 "(Mi-1 Radiation Protection Plan" POTTS-W E . HENARD.R W Metropolitan Edison Co 80/08/28 23pp
- --B103/30547 Summarises steps taken to improve radiological controls program in response to 801126 health physics evaluation rept & notice of violation ARMOLD R C Metropolitan Edison Co 80/12/16 4pp 07913 160
- B103170393 Forwards safety evaluation re TMS Action Plan Stem IS K 2 19. "Benchmark Analysis of Sequential Ausiliary Feedwater Flow" for BSW reactor plants Util found in compliance w/item
  REID.R W Operating Reactors Boanch 4 81/03/04, 2pp

--Bi03170671 Safety evaluation re TMI Action Plan Item II K 2 19.

- 8103160248 Forwards corrected Page 3-71 to Acend 61 of License DPR-50 re safety-related snubbers, transmitted by H10126 ltr REID.R W Cycrating Reactors Branch 4 01/03/09 4 A2921 347
- --8103160254 Corrected Page 3-71 to Amend 61 to License DPR-30 no safety-related enubbers
  Derating Reactors Branch 4 81/03/09 1p 07921 251 safety-related enubber
- 8103139343 Notification of 810313 meeting w/util in Bathasda.MB to 103130343 Notification or Bludis meeting would in bethason, no to discuss implementation of NU4EO-0737 requirements. SILVER.H. Operating Recitors Scench 4 B1/03/06 Spp. 07912, 148
- B103160281 Forwards list of open items in NUREO-06BO Requests further OJIOUZBI Forwards fist of open items in Number-body Requests Further documentation or commitment date for submittals REID.R W. Operating Reactors Branch 4 HI/03/06 Spp. 07921 308
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related ejectrical equipment ELECTION D Division of Licensing 01/03/10 6pp
- 8103160719 Submits further justification for Tech Boece Change Request ivilovity avoidits rupther justification for lesh upect chair 90 re reactor vessel internal vent valves Change requested mod to permit Cycle 5 operation w/o reperformance of HAMILLAND Metropoliten Edisan Co Mi/OM/11 2pp A20 (0.002
- 8103230619 Forwards Amend 24 to restart rept HUNILL. H D. Metropolitan Edison Co. 81/03/18 lp 07079 326
- --B103230620 Amend 24 to restart rept.

  \* Metropolitan Edison Co | B1703/18 | 2pp | 07979 327.
- 8103270684 Informs that 954 numers group submitted flaw-1511P.
  "Irradiation-Induced Reduction in Charpy Upper Bhelf Energy
  of Reactor Vessel Welds" to fulfull submittal requirements of IGCFR50, App 0 PARKER. W O Duke Power Co 81/03/23 1p
- --8103270693 Forwards BAN-1511P. Irrediation-Induced Reduction in Charpy Usper Shelf Energy of Reactor Vessel Helds." charpy upper breit thorry or neactor vessel Melos."
  Describes implementation predictive methodology to determine set life of reactor vessels M/o encl TAYLOR-J H Babcock & Wilcon Co 81/03/12 App.
- 8103310905 Requests extension to 810415 for submittel of Tech Spec change request for snubber surveillance mode in response to NRC 801120 request
- HUNELL, H.D. Metropolitan Edison Co. 81703726. 1p. 08059: 202
- B103310601 Forwards response to ARC 810109 itr re asymmetric LOCA loads. Technical review meeting requested for 810402-03 to resolve approx 60 questions by cross referencing dockated HUXILLIH D. Metropolitan Edison Co. 81/03/26 2pp. 08078 210
- --8103310602 Founds revised pages to BBH 74-1122501-00 operating guidelines for small breaks, which updates util 810283 ltr 5pp. 00079 212 HJAILL, H D Hetropolitan Edison Co 01/03/26
- 8103270679 Forwards corrected 810318 Tech Spec Page 5 2-69 Metropolitan Edison Co 81/03/27 Ip 08042 358
- --8103270603 Corrected Tech Spec Page 5 2-65 » Metropolitan Edison Co 81/03/27 ip 1p. 08042-359.
- 9 Inspection reports. IE Bulletins & carrespondence
- 8103050251 Ack receipt of 801224 1tr informing NRC of delay in implementing corrective actions per IE Insp Rept 50-287/80-24 Ltr to be withheld (ref ICCFR2 790) MARTIN.U.Q. Region 1. Philadelphia, Bafeguards Branch 81/01/19. IP 07825:250
- 8103180204 Forwards 1E insp Rept 50-287/80-31 on 801216-19 No nancompilance noted. CARLSON,R F. Region i. Philadelphia, Reactor Construction & Engineering Support Branch 81/01/20. 2pp. 07945.289
- --8103180216 IE Insp Rept 50-289/80-31 on B01216-19 No noncompliance noted Major areas inspected Unit 1 res

0288 Forwards IE Insp Rept 50-289/81-02 on 810105-09 No orgitance noted
ampliance noted
SDN.R T Region 1. Phylodelphia. Reactor Construction &
nearting Suypoort Branch 31/01/23 2pc 07954 287

190297 IE 1050 Rept 50-259/81-02 on 810105-09 No noncompliance start program on electrical & instrumentation documents & set of Hajor areas inspected work activities & records re start to one webs inspected with a thinguage who noncomb! start program on electrical & Instrumentation documents & tare high pressure safety injection tross connections \$55ANL A D Region 1. Philadelphia. Office of the Director RETER. 5 D Region 1. Philadelphia. Reactor Construction & gineering Support Branch 81/01/20 App 07954 209

Olli Forwards response to IE Bullotin 79-018, Suppl 3, "Environ ification of Class IE Equipment" includes raster list quipment & qualification sheets & qualification sheets LLIND Metropolitan Edison Co 81/01/30 App 07939 029

0239 Forwards IE Info Notice 81-03. "Checklist for Licensees ng Notifications of Bignificant Events in Accordance CFR50 72 " No written response required R.D H. Region 1. Philadelphia. Office of the Director 2/12 1p 07813 256

0186 Forwards 16 Info Notice 81-04. "Cracking in Main Steam s "No response required R.B.H Region 1. Philadelphia. Office of the Director 2/27 ip 07972 030

0220 Forwards IE Circular B1-03. "Inoperable Beismic Munitoring rumentation" No writton response required R.B H Region 1. Philadelphia. Offico of the Director 3702 1p 07945 204

Oli2 Forwards revised [E Gulletin Gl-Ol. 'Surveillance of Ulla Forwards revised IE Bulletin B1-01. 'Surveillance anical Snubbers.' w/corrected Pages 9 t & Change in tiplication of facilities w/CP to which bulletin is icable does not affect util requirements R.B.H. Region 1. Philadelphia. Office of the Director 3/04. Ip 07969 062

0893 Forwards IE Info Notice 81-06. "Failure of ITE Mudel K-600 u(t Brecker' No respunse required R.B.H. Region 1. Philadelphia, Office of the Director 3/11 | 19 07969 031.

iodic operating reports & related correspondence

0758 Formards "Effluent & Waste Disnosal Remiannual Rept. Jul-Dec . LL.H D. Metropolitan Edison Co. 81/02/28 to. 07810-129

040767 "Effluent & Waste Disposal Somiannyal Rept. Jul-Dec 1980 " Metropolitan Edison Co. 81/02/28. 34pp 078[0:130

0365 Forwards "Annual Operating Rept 1981" LL.H D - Metropolitan Edison Co. - 81/02/28. - Ip - 07865-046

100370 "Annual Operating Rept. 1980." Metropolitan Edison Co 81/02/28 3pp. 07865:047

0992 Forwards "TMI Aquatic Rtudy, Monthly Rept for Jen 1981," ared by Ichthyological Associates, Inc for Met Ed T.T.R. General Public Utilities - OPU Service Corp. 81/03/05. 07867:279

100394 "TM! Aquatic Study, Monthly Rept for Jan 1981." RDACCI.G.A. | [chthyological Associates, Inc. | 81/03/99. | 14pp. 867:280.

0561 Forwards monthly operating rept for Feb 1981. LLIH D. Motropolitan Edison Co. B1/03/13 ip 07953.032

180565 Monthly operating rept for Fab 1981. TCHELL-D.O. Metropolitan Ediaon Co. 81/03/19. Spp. 07953.033.

ortable occurrences, LERs & related correspondence

0586 Forwards LER 81-002/03L-0 LL.H D. Metropolitan Edison Co. 81/03/03 1p 07837 170

MITCHELL D.S. Metrosolitan Edison Co. 81/03/02. 3pp.

- --Bi03170573 LER Bi-D03/03L-V on 810210 new penetration in fire wall between engineered safeguards actuation sys. fire area CD-3C & relay room, fire area CD-3D. Found necessary for new cable routing for mode on containment isolation RM-5C MITCHELL.D O Metropolitan Edison Co 81/03/12 3pp 07935-320

07837 170

- --B103170552 LER 80-013/03:-1 on B00715 pressurizer code safety valve. RC-RVID. Lifted telow Tech Spec limits Cause not determined Addi tosting planed to verify site heated nitroyen test procedure yields results comparable to steam pop test MITCHELL.D G Metropolitan Edison Co 81/03/13 2pp 07933-301
- T Hearing transcripts on non-outiltust matters
- H103020557 Testimony re Asmost Contention 4 on biological effects of TMI accident Certificate of Svc encl Related correspondence MOLHOLT. 3 Affiliation Unknown 81/02/23 5400
- 8103090671 Forwards DC Smith % UN Lothrop testimony re-offsite emergency planning of PA Emergency Planning Agency & PA Dapt of Nealth Tostimony of PA Dapt of Agriculture & PA Dapt of Environ Resources will follow shortly ADLER, R. R. Pennsylvania, State of 81/02/23 1a 07829 255
- --8103050679 Testimony to affisite emorgency planning of PA Emorgency Planning Agency 5 PA Dept of Health Contains explanation of State of PA organization of contentions Prof qualifications SMITH.D.C. LOTHROP.J.N. Pennsylvania. Btate of 01/02/23 App. 67829 25A
- 8103050709 Testimony re Contentions EP-5B.EP-5E, EP-11.EP-18C & EP-18E Corrects & clarifies inconsistencies between Oureau of REILLY: A Pennsylvania State of 81/02/23 22pp 07820 012.
- B)03)10453 Transcript of 810224 restart hearing in Harrisburg, PA Pp 13. 922-13. 656

  \* Atomic Safety and Licensing Doard Panel BI/D2/24 136pp 02871 070
- 8103110368 Transcript of 810225 restart hearing in Harrisburg. PA Pp. 13.657-13.716

  Atomic Bafety and Licensing Board Panel - 81/02/25 - 60pp 07886. 133.
- 8103080620 Festimony responding to energency plan Contention 18(E) on lack of criteria for reactivation &/or use of previously contaminated property equipment. Poolstuffs & water Criteria & guidance to public are included Prof qualifications encl CORDIN.L. C. Pennsylvania, State of. 81/02/26 6pp 07829 139.
- B103090623 Testimony opposing energency plan Contentions 2.4(A) & 5(G), asserting plans do provide for livestock care placing emphasis on use of shelter & protected feed/water Prof qualifications encl VAN BUSKIRK,M . CABLE.J. W. Pennsylvania, State of 81/02/26. 14pp 07829 145
- BIO3110298 Transcript of BIO303 restart hearing in Harrisburg.PA Pp 13,717-13,934 \* Atomic Safety and Licensing Board Panel: 81/03/03 218pp
- 8103110459 Transcript of 810304 restart hearing in Harrisburg, PA Pp 13, 935-14.175 « Atomic Safety and Licensing Board Panel 81/03/04. 242pp
- BiO3130522 Forwards testimony re health physics Issue 4 (CLI-80-5) in restart proceeding Certificate of Svc encl BLAKE.E.L. Shaw. Pittman. Potts & Troubridge 81/03/04 6pp 07913.115.

- --BIODIBJOOP Testinomy of R Heward-WE Potts.RA Knief.U4 Brasher & R Diblet to CLI-80-5 Issue 4. Intervenor Sholly Contention 14c & related ASLB questions to health physics program HEWARD.R . POITS WE . ANIEF.R A Metropolitan Edison Co BI/OS/O4 | 16pp | 07913 121
- --Bi03130538 \*FM1-1 Radiation Protection Plan \*\*
  POTTS W.E., MEWARD, R.W. Metropolitan Edison Co. 80/08/28 23pp
  07913 136
- --BIC3130547 Summarijes steps taken to improve radiological controls program in response to 801126 health physics evaluation tept throtice of violation ARLCLOR Cometropolitan Edison Co. 80/12/16 4pp. 07913-160
- --BIO3130552 Responds to first 13 items set forth in health physics evaluation as requiring corrective action prior to restart ARROLD, R.C. Metropolistan Edison Co. 80/12/30 7pp 07713 164
- --BiO3133557 Provides responses to 44 remaining items set forth in health anysics evaluation as requiring resolution prior to restart ARISED, R.C. Metropolitan Edison Co. 81/02/02 Spp. 07913 171
- ~-8193130363 Supple B012(6.3) & B10202 responses to B01126 health physics evaluation includes items 22-16, 22-19, 22-34 & 22-36 ARNOLD, R. C. Metropolitan Edison Co. B1/02/27 2pp 07913 179
- 8103[1039] Transcript of 810305 restant hearing in Harrisburg.PA Pp 14.382-14.495 Evening session \* Atomic Safety and Licensing Board Panel 81/03/05 12:pp 03873 200
- 6103(10444 Transcript of 810305 restart hearing in Parriaburg.PA Pp 14.176-14.281 \* Atomic Safety and Cicensing Board Panel 81/03/05 207pp 07870 224
- B303110467 Transcript of 810306 restart hearing in Harrisburg.PA Pp 14.496-14.609 • Atomic Safety and Licensing Board Panel 81/03/06 llapp 07072 022
- 8103180630 Testirony on Anti-Nuclear Group Representing York Contention III 8(D) requiring predistribution of thyroid blocking agent Related correspondence BEYEA. J. Anti-Nuclear Group Representing York 81/03/06 19pp 07947 286
- --8103189537 Reviews EPRI evaluation re potential conservations 5 ranges of uncertainity in MASH-14GD analysis of iodine release for IMLB sequence More research required. Prof qualifications 5 Certificate of Svc enci. DENNIA2.R B Sattelle Memorial Institute. Columbus Laboratories 80/08/05 13pp 07947:305
- 8103190634 Memorandum of law that 5t Lucie decision. ALAB-603, should not be applied to require quantitative assessment of probability of failure of India decay heat removal sys since no special circumstances eries BAXTER. TA Shau, Pittman. Potts & Troubridge B1/03/09 13pp 07963-347
- --Bi03190441 Second supplemental testinony in response to ASLB Question 6 re emergency feedwater reliability. No sound basis exists to postulate unusually high challenge rate to or probability of failure of TMI-1 sys. Wyrof qualifications AEATEN, R. W. Metropolitan Edison Co. 81/03/09 16pp 07964 001
- 8103170200 Transcript of 810310 restart hearing in Harrisburg.PA Pp 14. 619-14.839

   Atomic Safety and Licensing Board Panel 81/03/10 227pp 07934:001
- B103209504 Supplemental testimony in response to ASLB question & UCS Contention 12 on relocation of squipment in TMI-1 reactor blidg due to flooding concerns engendered by TMS accident. Myprof qualifications & Certificate of Svc CREKFSERGER.D Metropolitan Edison Co. 81/09/10 12pp 07970.358
- 8103170213 Transcript of 810311 restart hearing in Harrisburg-PA Pp 14:836-15:073.

   Atomic Safety and Licensing Board Panel 81/03/11. 330sp. 07974:001
- B103200108 Forwards BF Ross testimony on reactor water level instrumentation & integrated control sys failure modes & effects analysis & J. Hermeil & J. Curry supplemental testimony on emergency feedwater sys reliability.

  CUTCHIN.J. M. Presing Branch 3 B1/03/11 2pp 07970 261

- --8103203114 Testimony re-reactor water level instrumentation Contention 7. Shelly Contention 6(b) % Anti-Nuclear Group Representing York Contention 3(b) Prof qualifications en ROSS, D. F. Division of Systems Integration 81/03/11 07970-263
- --BIO3200313 Testimony re integrated control sys failure mo analysis Prof qualifications end! ROSS.D.F. Division of Systems Integration B1/03/11 07970-278
- --Bioggooi19 Supplemental testimony re energency feeduater reliability.ASLB Question & Energency feeduater sys w/m to be implemented by restart would be sufficiently reli to allow restart Wyprof qualifications WERNIEL. J. Ausiliary Systems Branch CURRY. J. Probab Analysis Staff (Pre 801119) BI/03/11 5opp 07970-2
- 8103170204 Transcript of 810312 restart hearing in Harrisbu Pp 15.074-15.313 \* Atomic Safety and Licensing Board Panel 81/03/12 2 07935 001
- B103230843 Supplemental testimany on UCS Contention 4 re conpressurizer heater to diesel generator. In response to ASLI request for further info Prof qualifications & Certification 5 Sec enc.)
  HARTMAN. C. . TORCIVIA. J. A. Metropolitan Edison Go 81/03.
  07974-201
- 8103200658 Forwards VE Adler % FJ Bath testimony re content offsite energency proparedness & S Chestnut & FJ Bath testimony re contentions on positis/offsite energency preparedness OPAY-JR Hearing Branch 1 81/03/16 1p 07969:[13
- GPAY.J.R. Hearing Branch 1 81/03/16 lp 07969:113
- --BIO3260666 Joint testimony on contentions re ensite/offsi preparedness Discusses licensee provisions for transfer info on emergency & plant conditions to State at PA & n for evacuation time estimate study W/Certificate of Svc CHESTHUT.S Emergency Preparedness Licensing Dr Cafter 1861 Bath.F.J. Foderal Emergency Management Agency 25pp 07769 114
- --B103200675 Testimony on contentions to afficite emergency of Discusses protective action decisions, public warning & emergency instructions, implementation of protective act post-evacuation support & emergency response funding. ADLER, V.E. BATH.F.J. Federal Emergency Management Age: 81/03/16 70pp 07969 139
- B103240540 Testimony of RR Dynes-American Sociological Asso principles of planning for emergencies Related correspondence. DYNES-RR American Sociological Association B1/03/16 07906-251
- 9103240601 Testinony on realistic estimates of consequences accidents for use in energency planning Natural phenomena act to reduce arount of radioactivity released during accident. H/prof qualifications Related correspondence LEVENSON.M Metropolitan Edison Co. LEVENSON.M Bechte Corp (subs of Bechtel Corp.) 81/03/16 30pp 07983:
- 8103250191 Transcript of 810317 restart hearing in Harrisbu Pp 15.314-15.331 # Atomic Safety and Licensing Board Panel. 81/03/17. 2 07993.077.
- 810319053B Forwards RR Keimig & DR Haverbamp B10317 testimo responding to ABLB questions re-auditability of maint practices & TMI Alert Contention 5 on raint at TMI-1. JR Allen B10313 memo to DT Buanson also encl SWANSON D. T. Hearing Branch 1. 81/03/18 2pp. 07959 t.
- --BIODI90543 Testimony in response to ASCB questions re aud maint practices in sample yr 1978 & currently, Acceptabl maint program is established, including overall maint sy auditability of maint-related records. KEIMIG.R R. HAVERHAMP D.R. Region I. Philadelphia, Df Director BIODI7 37pp 07955:139.
- --8103190550 Testimony in response to TMI Alert Contention TMI-1 Licensee has not pursued course of conduct that w demonstrate lack of technical qualification to operate w/o endengering public health & safety. KEIMIO.R R , HAVERKAMP.D.R Region 1, Philadelphia, Of Director. 81/03/17. 35pp. 07935:176

- --Bij3190553 Discusses Region I review of completeness of record on issue of mgt competence. In event THI Alert or other parties do not complete depositions No NRC requirements violated or safety significant Conterns uncovered KEIMIO.R R. Region 1. Philadelphia. Office of the Director 81/03/13 2pp 07935 214
- --Bio3190561 Discusses concerns raised in TMI Alert depositions Areas of greatest emphasis are processing maint work orders backlog of orders estensive evertime, plant components tests, radwaste operations & temporary repairs. H/Certificate of Svc CRRISTOPHER: R. NRC No Detailed Affiliation Given 80/07/11 11pp 07955 216
- 8103250217 Transcript of 810318 restart hearing in Harrisburg, PA Pp 15.532-15.748 \* Atomic Safety and Licensing Soard Panel 81/03/18 218pp 08000 001
- 8103280199 Transcript of 810319 restart hearing in Harrisburg, PA. Pp 13:749-15:939.

  \* Atomic Safety and Litensing Board Panel 81/03/19 206pp 07995 148
- BIO3230656 Forwards DR Neely testimony re ABLB question on health physics proprem is Suppl 2 to NRC TMI-I restart evaluation (NUREG-0680). Certificate of Svc encl SHANBOULD T Hearing Branch I BI/03/20 3pp 07973 100
- --B103R30678 Testimony re ASLB questions of health physics program Util corrective actions & commitments in response to items of noncompliance & significant findings are satisfactory Prof qualifications encl IEEELY.D R Performance Appraisal Section 81/03/19 100pp. 02973-124
- 8103290208 Transcript of 810320 restart hearing in Harrisburg, PA Pp 15:954-16:045 • Atomic Safety and Licensing Board Panel 81/03/20 95pp.
- 8103260746 Testimony to inadequate planning for livestock evacuation to care in event of nuclear accident at facility. Related correspondence
  WEBER.R. LYTLE-P.M. FISHER-J.K. Affiliation Unknown 81/03/20
  6pp. 08036:023
- Bi0324057B Forwards HT Peterson testimony on Environ Coalition on Nuclear Power Contention 2-33 Testimony is late filed but should be accepted Ample time remains before keering & testimony will contribute to complete record GRAY, J.R. Hearing Branch L. Bi/03/23 2pp 07986-129
- --8103240586 Testimony re Environ Coalition on Nutlear Power Contention 2-33 Protective action guide for milk ingestion is based on infant not fetus, because infant was critical segment of population Wyprof qualifications & Certificate of Svc PETERSON-H. T. Radiological Health Standards Branch 81/03/23. 7pp. 07984:131
- B103270908 Transcript of 810324 restart hearing in Harrieburg-PA Pp 16.046-16.245.

  \* Atomic Safety and Licensing Board Panel. 81/03/24. 202pp 08033-167
- 8103310367 Transcript of 810328 restart hearing in Harrisburg.PA. Pp 16.247-16.485 Health physics evaluation.DR Neely testimony 5 prof qualifications encl # Atomic Safety and Licensing Board Panel. 81/03/25. 240pp.
- 8103310345 Transcript of 810326 restart hearing in Harrieburg-PA. Pp 16.486-16.510.

  \* Atomic Sefety and Licensing Board Panel 81/03/26 26pp 08079 [5]
- B103310361 Transcript of 810327 restart hearing in Harrisburg.PA Pp 16.511-16.606 \* Atomic Bafety and Licensing Board Panel 81/03/27. 100pp

### V. Operator Examinations

B103270691 Forwards shift technical advisor long-term program, to fulfill B10123 commitment to Item I.A.1.1 of NUREO-0737.

HUKILL, H. D. Metropolitan Edison Co. B1/03/19 12pp. 08042.346

- BECKET 50-293 PILORIM NUCLEAR POWER STATION, USIT 1

  F. Becurity, Addical. Greegency & fits protection plans
- B:031803A4 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addlinfore safe shutdown capability for compliance u/B01119 fire protection rule
  FISENMENT.D C. Division of Licensing 81/02/20 13cc
- B103130086 Ack receipt of G00320 & 0516 ltrs transmitting Revision 5 security plan Changes consistent w/100FR50 54(p) IPPGLITO. T A Operating Reactors Branch 2 81/03/02 2pp 07912-012
- 0103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. W/o enci EISE[HHUT.D 9 Division of Licensing 81/03/09 App
- B103230654 Requests extension of deadline for implementation of NRC fire protection regulations <10CFR99, App R) from G10319 to 1031 Action plan re implementation of Section III(0) of App R enct Aperture card is available in POR MCR181.4 V Joston Edison Co. 81703799 7pp 07974:039
- B103200267 Releases public version of draft implementing procedures frenchercy plan FELTON-U II Division of Rules and Records 81/03/17 (p. 07806-00)
- --0103200272 Forwards public version of draft implementing procedures emergency plan in response to NRC 801113 itr MCRISI.A V Boston Edison Cu B1/02/26 ip 07006 001
- --8103290280 Public version of draft implementing procedures for emergency plan includes medical treatment, unusual event, after class, site & general emergency & activation of emergency organization 
  \* Boston Edison Co. 81/03/01 325;p. 07806-001
- 8103300472 Requests that encl emergency planning info be placed in LPDR W/o 8103200272.
  SOUDER-J L Division of Rules and Records 81/03/26 ip OROSE 124
- I Financial information
- 8103190051 Annual Financial Rept 1980 \* Boston Edison Co 81/03/18 44pp 07585 001
- J. Insurance & indomnity information
- 8100030630 Forwards Endorsement 43 to MAELU Polity MF-58 FCULSHAM.P A Boston Edison Co 81/02/24 2pp. 07795 024
- P. Operating license stage documents & correspondence
- 0103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs to control of heav, loads Requests review per guidelines in NVREO-0612 Forwards NRC position to interim actions 5 request for addl info ETECHHUT.D & Division of Etcensing 80/12/22 30pp. 07764-024
- B1031903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shuddown-replacement parts & NUREO-0737.

  EISENHUT. D. O Division of Licensing B1/01/19. App
- 8103240290 Ltr to all BHR licensees forwarding Suppl 1 to generic safety evaluation on BHR scram discharge sys. Summarlies re-evaluation of interin measures recommended per 801201 safety evaluation EISENHULD O Division of Licensing. 81/01/23. 2pp. 07986:312
- 8103120014 Ltr to all licensess of operating plants, CP holders & GL applicants, except Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for addlinfore control of heavy loads.

  EISEMHUT, D.O. Division of Licensing. 81/02/03 6pp
- 8103040229 Forwards request for add1 info re bypass & reset of angineered safety features. IPPOLITO.T A Operating Reactors Branch 2 81/02/12 Spp. 07820.042

- G103:20050 Requests add1 wife re adequaty of station electric cistribution six voltages within 60 days [PPOLITO A Operating Reactors Granch 2 91/02/12 3pp 07996 344
- DIGBLOCKS Ltr to all operating plants & CP holders forwarding clarification of Inflaction Fian Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be not EISEMHUT.D 9 Division of cicensing 81/02/18 12pp
- aiO3120027 Forwards sofet, evaluation re ATM3 recordulation pump thip billternate red insertion sys Evaluation documents Tech. Specs affected by Amena 42 to Du & 810124 telcon re power supplies 3 inverters improved to Amena 42 to Du & 810124 telcon re power 1000110.1 A Operating Resolves Branch 2 81/02/19 2pp 02910 297
- -8103120312 Safety evaluation re ATMS recirculation pump trip be afternate not insertion sys Evaluation cocuments Tech Specs affected by Amend 42 to D. & BIDI21 telson re power supplies & inverters [PPOLITO. I A Operating Reactors Branch 2 81/02/19 4pp 17503 360
- 8103250074 Ltr to all sour reactor licensees & license applicants re fameG-CalP criteria Footnote 2 in Table 2 contains error due to leatage testing feletions Licensee had submit analysis to justify use of existing low flow controller EISECHNUT.D S Givision of Licensing 81/02/20 8pp
- Bio3230000 tir to all licensums of operating nuclear power plants \$
  applicants for CLs (eccept 9t Lucia, units 1 & 2) Requests
  util review to determine capability to nitigate station
  blactious event & promptly implement emergency procedures
  EjspinkUI.0 () Division of Licensing BI/02/25 5pp
- B103170229 ttr to all BMR licersees (except Humboldt Bay & LaCrosso) requesting review of ASME Code Class 1 % 2 pressure boundary piping, sade ends & ditting nati per guidelines of enci. Revision 1 to AMERICA 2018 Model Tech Specs only enci. EIDERHUT, P. G. Division of Licensing B1/02/26 Jpp 07934 319
- -UIO3170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4-8 re jurveillance requirements for ASME Code Class 1.2 % 3 components % RCG operational leatage limiting conditions for operation % surveillance requirements # Gareral Electric CC 81/02/26 4pp 07934 318
- (03230813 Generic Ltr B1-06 to all CP holders & CL applicants re (007850 71(e). 'Periodic Updating of FSARs.' effective 803722 Info re FSAR legal status.format & Content such EISE(HUT.D O Division of Licensing 81/02/24 10pp
- 8103390586 Forwards addl info & commitments is NUAEG-0737. Items I C 6. II B 2. It F I & It K 3 27 includes design review of plant shielding, nible gas effluent monitors & indine & particulate sampling FERRITION J Boston Edison Co 81/02/27 14pp 07890. 172
- BiO3100386 Forwards add) info re containment vent & purge valve operability, in response to B01210 itr
  momissia. V goston Ecisen Co. 81/03/04 5pp 07865 200
- B103100592 Informs that milk samples will be obtained from 9 Whisple Location is approx 2 miles from facility Whipple has approx 19 cous MORISI.A V Boston Eisson Co 81/03/04 lp 07863 096
- B103180009 Forwards Tech Spec Page 5a to Amend 42 to License DPR-35. inadvertently o-itted on 800512 amend issuance IPPDLITO.T A Operating Reactors Granch 2 81/03/04 2pp 07943-324
- --Bi031800f0 Page 5a to Amend 42 to License EPR-35 Tech Specs. inadvertently gmitted on 803512 amend issuance • Operating Reactors Branch 2 81/03/04 ip 07943 326
- 8103120812 Requests that 801113 \$ 810213 commitments or BWR scram discharge sys be modified to comply u/821231 and completion date & diverse instrumentation design criterion Revised Tech Specs may be required prior to operation wandlised sys. IPPOLITO.TA Operating Reactors Branch 2 81/03/06 2pp. 07905 015
- 8103313804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EFSENHUT.D 9. Division of Licensing 81/03/10. 6pp.

- F:103190928 Application to change Tech Specs per IMI Category A lessons learned (HUREG-0578) CDRRY.A F Buston Edison Co 81/03/16 ip 07955 130
- --Bi03190b33 Proposed Tech Spec changes per TMI Category A lessons learned (NJRE0-057B) New provisions added for operation & surveillance requirements for safety & relief valve positioning monitoring instrumentation Table 6 2-1 revised & Boston Edison Co. 81/03/16 6pp 07995 131
- BIC3276095 Surmary of BIO304 meeting w/Mark I duners group & GE in Dethesde.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MUREO-0651 Slide presentation & list of attendees enci CHINGS.G I Licensing Branch 3 81/03/16 Spp
- BIO3230487 For Jeros status of engineering efforts as of 810313 & estimate for completion per 1005830.App R schedular requirements Specific ejergiton request details encl MCRIBILA V 30ston Edison Co 81/03/18 38pp 07977 303
- G. Inspection reports, IE Bulletins & correspondence
- 8103020135 Forwards IE Info Notice 81-01. "Possible Failures of OE Type HFA Relays" No response required GRIER:DH Region I. Philadelphia. Uffice of the Director 81/01/16 ip 07789 ≧62
- B163060278 Clarifies B01205 response to IE Bulletin B0-21. "Valve Yores Supplied by Malcolm Foundry Co. Inc." No parts cast by foundry in use of planned for use in safety-related ays MDRISI.A V Boston Edison Co. 81/01/23 12 07839 322.
- B103090724 Ack receipt of B1010B ltr on results of survey relacted control at vital agors Correctable problem identified w/RHR valve room door A Corrective actions will be reviewed at next insplutii ltr withheld (ref 10CFR2 790) MARTIN.W G. Region I. Philadelphia, Safeguards Branch B1/01/27. 1p. 07844 223
- B103180622 Forwards Suppl 1 to util 801027 response to IE Bullotin 70-01B. Environ Qualification of Class IE Equipment \* Additesting of accustic monitoring devices for relief valve indication monitors util be completed by 810401 MSR151.6 V 30ston Edison Co. 81702703 Spp. 07953 352.
- 8103060476 Response to IE Builetin 80-17.9uppl 4. Failure of Control Rods to Insert During Scram at BMR " Info provided re bench test & operability test of continuous monitoring syspects of the Rods of Scram and Scram Ports of Scra
- B103100030 Confirms B10304 mpt meeting at facility to discuss regulatory performance No response required Agenda encl CRIER.B H Region 1. Philadelphia. Office of the Director B1/02/06 2p. 07865 068
- 8103040214 Forwards IE Info Notice B1-03, "Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CfR50 72 \* No written response required. CRIER 8 H Region 1, Philadelphia, Office of the Director 81/02/12 1p 07813 177
- Bi0303027: Forwards Suppl 5 to 1E Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BHR" No written response required. GRIER.B H Region 1. Philadelphia. Office of the Director. Bi/02/13 ip 07790 319
- 8103200070 Responds further to 1E Bulletin 79-27. "Loss of Non-Class 1E. Instrumentation & Control Power Sys Bus During Operation "
  Submits schedule for completing circuit by circuit review of instrument & control buses & implementing procedure mode mgR181.4 V Boston Edison Co 81/02/17 p 07948: 204
- 8103200192 Forwards 1E info Notice 81-04. 'Cracking in Main Steam Lines' 'No response required ORIER.B.H Region 1. Philadelphia. Office of the Director 81/02/27. 1p 07972-032
- 8103200128 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No whitten response required. GRIER.8.H. Region 1, Philadelphia. Office of the Director 81/03/02. 1p. 07971:339.
- B103200076 Forwards revised IE Bulletin 01-01, "Burveillance of Mechanical Snubbors." w/corrected Pages 5 & 6 Change in identification on fectilities w/CP to which bulletin is applicable does not affect util requirements CRIER.8.H Region 1. Philadelphia. Office of the Director 01/03/04 p 07968 207

- 8103200302 Forwards 1E Info Notice 81-06. "Failure of ITE Model K-500 Circuit Breaker" No response required GRIER.8 H. Region 1. Philadelphia. Office of the Director 81/03/ti. ip 07969-037
- A Periodic operating reports & related correspondence
- 8(03230542 Forwards monthly operating rept for Feb 1981 MACHON.R D Boston Edison Co 81/03/09 ip 07974 100
- --8103230551 Monthly operating rept for Feb 1981 WHITNEY, 0 G Boston Edison Co 81/03/09 bpp 07974 101
- 8103240213 Forwards "Radioactive Effluent & Waste Disposal Rept. Including Radiological Impact on Humans-Jul-Dec 1980 " MGRISI.A V. Boston Edison Co. Bt/03/19 tp. 07990.026
- --8103240221 "Radioactive Effluent & Naste Disposal Rept. Including Radiological Impact on Humans, Jul-Dec 1980 "
  BOHMAN, C. E., SOMDON, Y.L. Boston Edison Co. 81/03/01 72pp
  07990:027
- S Reportable occurrences, LERs & related correspondence
- Bi03090074 Confirms Bi0209 telcon re Bi0317 resin spill event Condensate demineralizer resin additions will not be conjugated again until condensate sys operating procedures include prerequisites precautions & check-aff lists QRIER.B.H Region I. Philadelphia. Office of the Director B1/02/10 2pp. 07832 134
- 8103020548 Forwards LER 81-003/03L-0 MACHON, R. D. Boston Edison Co. 81/02/23. 1p. 07782-397
- --8103020553 LER 81-003/03L-0. on 910123, heat detector failed in diesel generator A room Detector alarm could not be reset Cause not stated. Jumper added to eliminate alarm on control room panel C-114 until sys repaired Detector replaced & jumper removed MCLOUGHCIN, M T Boston Edison Co 81/02/23, 10 07782 358
- 8103030570 PND-1-81-028 on 810225 physical location of ATMS alternate rod invertion solenoids identified as potential for LGCA to loss of primary containment during ATMS Caused by possible JOHNBON, J., KEIMIO, R., MARTIN, T. Region i, Philadelphia, Office of the Director 81/02/26 2pp 07795:206
- 8103030711 PNO-1-81-028 on 810225 physical location of ATMS alternate rod insertion solenpids in scram discharge air header found to allow insertion of control rods u/o scram discharge vol vent & drain velves closing.LOCA may result

  JOHNSDN.J., WEIMIG.R., MARTIN.T. Region 1, Philadelphia, Dffice of the Director. 81/02/26 2pp. 07795:215
- 010309051B Forwards LER 01-005/03L-0 MACHON, R. D. Boston Edison Co. 81/03/02 1p. 07844:357
- --8103090523 LER 81-005/03L-0: on 810202, unidentified reactor drywell coolant leakage rates measured above Tech Spec level Couse not stated. Recirculation pump suction valves A & B & discharge valves backseated. MCLOUGHLIN, M T Boston Edison Co 81/03/02 1p 07844 358
- 8103090624 LER 60-006/01X-0: on 810219, review of alleged omission in scheduling of 11 once per cycle instrumentation verified oversight. Caused by misinterpretation of special circumstances which must be applied to testing definition. MCLDUGHLIN.M.T. Baltimore Gas & Electric Ca. 81/03/03. 07844: 301
- 8103200700 Forwards LER 81-004/01T-0. MACHON, R. D. Poston Edison Co. B1/03/10. 1p. 07970:004.
- --Bi03200704 LER 81-004/017-0:on 810225, review indicated that if backup screm solenoids failed actuation of ATHS sys would prevent closure of screm discharge vol vent & drain valves violating primary containment. Causa due to oversight in design. MCLOUGHLIN, M.T. Boston Edison Co. 81/03/10. 2pp. 07970:005.
- 8103240376 PNU-1-81-036: on B10317.prior to start of day shift members of security organization called in sick. Cause of "sick out" unknown but licensee understands work force displeased w/ Change to rotating shift assignments.

  DEVLIN.J.W., JOYNER,J.H., BRUNNER,E.J. Region 1, Philadelphia.

  Office of the Director. 81/03/17. 2pp. 07986:336.
- BI03270413 Forwards LER 81-007/03L-0. MACHON R. D. Boston Edison Co. 81/03/19 1p. 08043: 239.

- --8103270626 LER 81-007/03L-0 on 810217 reactor coplant leak detects air sampling sys declared inoperable Caused by blown fuses Fuses reclaced Pump will be rebuilt MCLCUON ILL N T ROSton Edison Co. RL/03/19 to 08043 240
- U Congressional/Executive Correspondence
- 8103270110 Responds to request for rept on possible addl improvement to NRC licensing process Legislation allowing interim grerations in advance of hearing completion Egyld reduce delau in licensing process HENDRIE-J II Commissioners. 81/03/12 5pp
- --8103270947 Submits recommendations re-scheduling.personnel resource from hiring freeze for two recently appointed chairmen

  COTTER.B P Atomic Refety and Licensing Boars Panel GI/02/25 3300 08043 359
- DOCUET SO-294 MICHIGAN STATE INTO DESEABLE REACTED F. Security, medical, emergency & fire protection plans
- 8103260929 Forwards revised physical security plan Plan withheld (ref 10CFR2 790) WILKINSDILRE, CARRICK, J. Michigan State Univ. 81/03/13 16 08034 232
- 1 Financial information
- 8103100446 Requests copy of NRC 780713 ltr requesting financial considerations about continuing operations of facility
  GRIDER.H.G. Michigan State Univ. 81/03/04 Ip. 07867-229
- P Upgrating license stage documents & correspondence
- 810306D445 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/02/20 21n 07836 022
- G. Inspection reports. IE Bulletins & correspondence
- 8103026046 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 81/02/09 2pp. 07787 239
- DOCKET 30-295 ZION NUCLEAR POWER STATION, UNIT 1 F Becurity, medical, emergency & fire protection plans
- 8:01080051 Releases public version of util draft emergency plan NUREG-0654 info encl FELTON-J M Division of Rules and Records. 80/12/02 18pp.
- --8101230543 Forwards public version of graft emergency plan for generating stations PEOPLEB. D.L. Commonwealth Edison Co. 80/04/24 3pp. 04837.16
- --8101080069 Public version of draft emergency plan for generating stations
  + Commonwealth Edison Co 80/07/31 150pp
- 8101080003 Releases public version of util draft emergency plan FELTON, J M Division of Rules and Records 80/12/03 lp.
- --8101220258 Forwards public version of util revised draft emergency w/station annexes PEOPLES, D. L. Commonwealth Edison Co. 80/06/04, 2pp 05370:00
- --810(080019 Public version of Revision 1 to draft emergency plan. \* Commonwealth Edison Co 80/07/31 139pp
- --Bi010B0039 Public version of draft energency plan annex \* Commonwealth Edison Co. 80/07/31. 37pp 07417-294.
- 8103180264 Ltr to all power reactor licensees u/plants licensed prio to 790101. Forwards NRC position & request for add1 info re safe shutdown capability for compliance w/801119 fire protection rule EJSENHUT, D. Q. Division of Licensing. 81/02/20. 13pp

- C103310338 Ltr to all licensees of operating plants & holders of CPs forwarding 1.JRE9-C696 Functional Griteria for Emergency Response Facilities Criteria describe acceptable method for neeting MRC requirements W/o ercl EISELWIJL D C Division of Licensing B1/03/05 App
- BIG3260123 Concurs w/B01217 request to install two-way headset jacks on specified energency notification sys & health physics telephones provised that use will be discontinued if communications quality unacceptably degraded MEPPLER, J.G. Region 3. Chicago. Office of the Director 81/03/17
- --G103260137 Submits location for installation of one-way headset jacks on energency notification sys & health physics network per B31119 request Requests concurrence by 810201 RAUSCH.T.J. Commonwealth Edison Co. 60/12/17 2pp
- BIC3230793 Provides review of plans, schedules & design descriptions refire protection rods Responses to open items per NRC 790101 ite encl
  IRAMAIR R Companyealth Edison Co. 81/03/18 App. 07976-347
- 8103259685 Releases public version of implementing procedures for emergency plan FELION. J. B. Dyvision of Rules and Records 81/03/19 12
- --BIO3250692 Forwards public version of emergency plan implementing procedures for corporate command oth environ director & plant-wpecific procedures
  DECOGNAGE. D Commanuelth Edison Co. B1/02/27 200
- --8103250702 Public version of emergency plan implementing procedures for corporate command ctr.environ director & plant-specific procedures

   Commandath Edison Ca B1/02/27 L400aa

## 9 Adjudicatory correspondence

- 8103230547 Notifies that time provided by NRC regulations to NRC review of Director's Decision (DD-D1-2) in doctet has expired NRC decision declining review became final agency action on B10317
  CMEM.S. J. Office of the Secretary of the Commission B1/03/19 to 37977 082
- 7103270721 Pesponds to 810218 itr denying Pollution & Environ Problems, inc 800417 polition to suspend Arends 52 & 49 to rerack & compact faculity spont Puel 2001 Contends that politions to NRC not given due consideration 90100.0 Pollution Environmental Problems 81/03/22. 4pp

## H General correspondence

- 6103040889 Responds to 810126 request re E Tophan concern about siting of facilities near minor fault Plant designed to withstand earthquake ground motion larger than ever recorded within 200 miles of site DIRCKS-N. J. Office of the Erecutive Director for Operations 81702719 200
- --8103040699 Forwards 810109 mero re E Tophan concerns about facility location near minor geologic fault Requests response. ASPIN.L. House of Rep 81/01/28 2pp.

## t Financial information

- B103310613 Forwards guarantse of payment of deferred premiums for 1981 per NRC request OSTER. J Commonwealth Edison Co. B1/03/27. 10.
- --BI03310520 Forwards Annual Rept for CY80 & statement of internal cash flow projected for 1985 & actual for 1980 per provisions of 100FR140.Chapter 1.Section 140 21 & MRC 770615 ltr NEXCH-H H Commonwealth Edison Co 81/03/27. App.

## J Insurance & Indemnity information

8103090581 Forwards Endorsament 5 to NELIA Binders EB-1, EB-2, EB-3, EB-29, EB-30, E3-42, EB-42 & MAELU Binders XB-1, XB-2, XB-3, XB-29, XB-30, XB-42, XB-43 
OSTER, J Commonwealth Edison Co. B1/03/02 
[5pp.

## P Operating license stage documents & correspondence

- 0103150732 tirs to all litensess of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUAEO-0612 Forwards NRC position re interin actions & request for addl info FISETHUT.D 0 Division of Licensing 80/12/22 30pp.
- BiD3190387 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown, replacement parts & NUMEG-0737 EISENHUT, D 0 Division of Licensing B1/01/19. App.
- 8103100106 "Safety Evaluation of Inservice Testing Program for Pumps & Valves at Zion Units 1 & 2 for Period 780117-790916 "
  RCCHHOLO.H C . FEHRINDER.J H EQUO Idaho. Inc. FIN A-6258 8103100106 81/01/JI 60pp 07895 136
- BIO3120014 Ltr to all licensess of operating plants.CP holders & QL applicants except Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC BOI222 request for add1 info re control to f heavy loads EISEN-UT.D Q Division of Licensing BI/02/03 6pp
- 8103050632 Ack receipt of 810122 itr providing addl info requested in MRC 801120 itr FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 81/02/09 ip 07829 1/3
- --Biog050638 Forwards add1 info re testing of facility steam generator southers reported in 801015 ltr IRAMN.T R Componwealth Edison Co. 81/01/22 3pp. 07829:174
- 8103300160 Ltr to all operating PMR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for additions of actions requested of licensees w/o seismically qualified sys & results of NRC walldowns.
  EISENHUT.D. O Division of Licensing. BI/02/10 13pp
- 8103030540 Requests changes to Licenses DPR-39 & DPR-48 & Yech Spec App A to incorporate requirements for continued inclementation of TMI-2 Lessons Learned Cetegory A items. Application is fee exempt TRANM-T R Commonwealth Edison Co 81/02/17. 4pp. 07803:174
- --Biggo3545 Tech Spec Change Bi-1 re emergency power supply requirements valve position indication, instrumentation for inadequate core cooling & containment isolation & Commonwealth Edison Co. BI/02/17 20pp. 07803:178.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates util be met.

  EISENHUT-D.O. Division of Licensing. 01/02/18. 12pp.
- 8103200781 Forwards notice of Director's decision per 2 206 in response to 800417 petition requesting that Director of Dfc of Nuclear Reactor Regulation suspend DL Amends 52 & 49 to Licenses DPR-39 & DPR-48 respectively.

  DENION-H B. Office of Nuclear Reactor Regulation, Director. 81702748. 2pp
- --Bi03200786 Notice of issuance of Director's decision under 10CFR2.206. DENTON.H.R Office of Nuclear Reactor Regulation. Director. 81/02/18. 2pp.
- --B103200795 Director's Decision B1-2 denying Pollution & Environ Problems, Inc B00417 request for immediate suspension of license to permit reracking & compaction of spent fuel pool. DENION.H.R. Office of Nuclear Reactor Regulation, Director. B1/02/18 10pp.
- --8103200803 Initial Decision authorizing Director of Ofc of Nuclear Rector Regulation to make appropriate findings in accordance W/NGC regulations & to issue appropriate OL amend authorizing requested spent fuel storage rack raplacement. LITTLE-L-M REMICK.P. J. WOLF.J.F. Atomic Safety and Licensing Board Panel. 80/02/14. 102pp.
- B103100214 Forwards organizational charts depicting NRC Region 3 reorganization, effective B10215.

  KEPPLER. J. O. Region 3. Chicago, Office of the Director. B1/02/20.
  2pp.

- g103230024 Ltr to all power reactor licensees & license applicants re IOUZDUUZM LET TO AII power roactor licensees & license applice MUREO-O619 criteria Footnote 2 in Table 2 contains error dut to leakage testing deletions Licensee may submit analysis to to leakage testing offerious Literage may submit and justify use of existing low flow controller propriet in the property of the controller property of the
- 8103130073 Forwards revised Tech Spec Page 35 which contained error in original 810114 submittal w/DL Amends 60 & 57 VARQA.S A Operating Reactors Branch 1 81/02/24 2pp 07912.017
- --Bi03130078 Revised Tech Spec Page 35

   Operating Reactors Branch 1. BI/02/24. ip 07912:019
- BIO3230030 Ltr to all licensees of operating nuclear power plants & applicants for GLs (ercept Bt Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EIBENHUT, D G Division of Licensing 81/08/25 Opp.
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR50.71(e). "Periodic Updating of FSARs." effective 800722:Info re FSAR legel status.fornat & content encl EISENUUT.D G Division of Licensing 81/02/26.
- 8103030860 Forwards status summary for NUREG-0737 stems to which util committed to respond by 810301 Long-term program under intensive internal review Program will be submitted by B10316 ABEL, J.S. Commonwealth Edison Co. 81/02/27. 3pp.
- 8103040701 Provides written statement supporting continued safe operation re environ qualification of electrical equipment. Continued operation justified

  ARFI. J R Commonwealth Edison Co. 81/02/27 2no 07810 049
- 8103090593 "Evaluation of Operation of Zion Station Units 1 & 2 W/One Loop Isolated. LYDN, R.E. E080 Idaho, Inc. FIN A-6267. 8103090593. 81/02/28 15pp. 07845.334.
- 8103130241 Submits supplemental info to 810204 transmittal re use of rod-schenge technique for rod worth measurements Discusees corrective actions for tests not meeting design criteria referenced in Bi0211 & 0306 ltrs.

  TRANM.T.R. Commonwealth Edison Co. BI/03/09. 3pp. 07907 087.
- 8103170509 Forwards Procedura 188 13. "Tendon Surveillance Test Procedures:" in response to NRC 801125 generic request. TRAMM.T.R. Commonwealth Edison Co. 91/03/06. 1p. 07930:095.
- --8103170312 Procedure TSS 13, "Tendon Burveillance Test Procedures" 
  \* Commonwealth Edison Co. 80/07/29, 16pp. 07930.096
- 8103170496 Notifies of change in schedule for probabilistic risk assessment study completion. Detailed documentation & technical reviews will assure lasting rept significance. Rept availability expected in June 1981. TRAMM-T.R. Commonwealth Edison Co B1/03/10. 1p. 07922-065.
- 8103310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equinment EIBENHUT, D. Q. Division of Licensing. B1/03/10. 6pp.
- Bio3180517 informs NRC that util will continue to require full radiation training for NRC personnel entering radiation areas at facilities, pending further NRC communications. TRAMM. T. R. Communwealth Edison Co. 81/03/11. 1p.
- 8103230852 Discusses review of util 810204 request for approval of rod exchange technique for rod worth measurements & 810304 add1 info re ramedial actions Rod exchange technique acceptable, provided util submits data from first use of technique.

  VARGA.S.A. Operating Reactors Branch I. 81/03/12. 3pp. 07974:350.
- B103230886 Forwards info & drawing re bypess & reset of engineered safety features, in response to NRC 801015 ltm. Aperture card available in PDR. TRAMM. T. R. Commonwealth Edison Co. 81/03/13. 6pp. 07974:071.
- 8103200351 Forwards revised abstract & Pages 2-2,4-2,4-5,7-2 & 18-2 of CE-1-A, Revision 16 re GA program. Revisions reflect ABME winter addends code changes changes made per ABME survey & clarifications & corrections. TRAMM. T. R Commonwealth Edison Co. 81/03/16. 1p.

- 16 to GA program

   Commonwealth Edison Co. CF-1-A RIA 81/03/16 600
- BIO32AG099 POTENTIAL SEISMIC STRUCTURAL FAILURE MODES ASSOCIATED WITH 103280095 PULENTIAL BETSHIR STRUCTURAL FATEURE HOUSE ABSOLUTE THE ZICH HUCLEAR PLANT CAMPBELL R D , WESLEY D A Laurance Livernore Laboratory F A-0126 NUREO CR-1704 B1/03/31 60pp. Available at NTIS. 08028.014

--8103200369 Revised abstract & Pages 2-2,4-2,4-3,7-2 & 18-2 of Revision

- G Inspection reports, IE Bulletine & correspondence
- B103240711 Responds to Suppl 3 of IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" Suppliers have been contacted to provide qualification of acoustic conitors on relief & safety valves
  ABEL-J S Commonwealth Edison Co 81/02/02 3pp
- 8103020115 Forwards 1E Circular 81-02, "Performance of NRC-Licensed individuals While on Duty " No written response required. KEPPLER, J. D. Region 3. Chicago. Office of the Director 81/02/09
- 8103200366 Forwards [E. Insy Repts 50-295/80-24 & 50-304/80-26 on 801210-11 & 810122 & notice of violation FIGRELLI, O. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 81/02/09 2pp 07967 036
- --9103200969 Notice of violation from insp on 801210-11 & 810122 FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/02/07 1p. 07967 038
- --8103200572 IE Insp Repts 50-295/80-24 & 50-304/80-26 on 801210-11 & 010122. Noncompliance noted audit of SNEC inadequate because of fellure to identify BMEC myt exampting personnel from required training w/o written justification YIN-1 T. Region 3. Chicago. Office of the Director. DANIELSON. DH. Region 3. Chicago. Reactor Construction & Engineering Support Branch 01/01/30 Spp 07967 039
- 8103040251 Forwards IE Info Notice 81-03, "Checklist for Licensees (Adjust) Forwards it into Notice 51-03. Checking the titembers
  MAKing Notifications of Dignificant Events in Accordance
  M/(OCFR50, 72 " No written response required
  KEPPLER.J Q Region 3. Chicago, Office of the Director. 01/02/12 200
- 8103160373 Forwards monthly status rept re evaluations performed in response to IE Bullatin 79-14, "Beismic Analysis for As-Built Bafety-Related Piping Bys. " Tables listing excessive pipe stresses encl.

  JANECEK.R F Commonwealth Edison Co 81/02/25 ip
- 8103160695 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required KEPPLER.J. O. Region 3. Chica 2pp 07914:092 Ragion 3. Chicago. Office of the Director 81/02/27.
- 8103160494 Forwards 1E Circuler 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 01/03/02. 200
- 8103170371 Responds to 1E Gulletin 81-01. "Surveillance of Mechanical Enubbers." No Nuclear Safequerds Corp snubbers have been installed or will be installed on safety-related sys.
  JAKECEK-R F Commonwealth Edison Co. 81/03/02 2pp.
- 8103160B94 Forwards revised IE Bulletin 81-01. "Burveillance of 103160099 Foundrys revisod in Oblietin UF-01. "Surveillance or Mechanical Snubbers," w/corrected Pages 5 & & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. KEPPLER.J. O. Region 3. Chicago. Défice of the Director. 81/03/04
- 8103160630 Forwards supplemental info re IE Bulletin 80-06. "Engineered Bafety Feature Reset Controls." All mods completed Testing performed w/all equipment in actuated position.
  TRAMM T.R. Commonwealth Edison Co. 81/03/10. 3pp. 07917 128.
- 8103200394 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required.
  KEPPLER, J. G. Region 3. Chicago, Office of the Director 81/03/11. 2pp.
- 8103200695 Forwards 1E Info Notice 81-05, "Degraded DC Bys at Palisades." No action required. KEPPLERJ G. Region 3. Chicago, Office of the Director. 81/03/13.

- B103200269 Forwards [E. [nfo Notice B1-07. 'Potential Problem Wildster-Spinole Purge Car Matia Used During Inert Gas melding "No tesponse regulared rePPLER. J. D. Region 3. Chicago. Office of the Director B1/03/16
- A Pariodic operating reports & related correspondence
- GIGGGGGGF7 Forwards rept of radioactive effluents.1980 GRAESSER.X L Cormonwealth Edison Co. 81/02/04 lp 07783 073
- --8103073404 Rept of radioactive efficients, 1980 • Commonwealth Edison Co - 81/02/04 - 37pp - 07783 074
- 8103030792 Forwards occupational radiation exposures rept for 1980 BITEL.J 5 Corronwealth Edison Co 81/02/29 Ip
- 8163100349 Forwards monthly operating repts for Feb 1981 GRAEDSER X L. Commonwealth Edison Co. 81/03/05 12 07864 349
- --B103120351 Monthly operating repts for Feb 1981 COOK. J M. Companyaith Edison Ca. B1/03/05 | Hpp. 07864 350
- S. Reportable occurrences. LERs & related correspondence
- 8103040445 PN3-III-80-237 on 801225 unplanned gameous release occurred suring transfer of waste gas to holdup tank Caused by leaking valve investigation continuing LOVENDALE P. FISHER N. L. DAVIS.A. B. Region 3. Chicago, Office of the Director. 80/12/29 1p. 07811-353
- 2103020496 Pr.O-III-81-021 on 810223 received notification that OAD will begin conducting comprehensive enalysis of comparative costs re upgracing safety at utils to reduce danger to nearby population ctrs Study will be completed in FYBI MENJZER.N 0 . HIND. J.A. Region 3. Chicago. Office of the Director 81702/24 2pp 07785 100
- BIG3020597 P.NS-111-81-004 on BIG224.two equipment operators were arrested & charged u/possession &/or use of controlled substances individuals were suspended & access authorization to site was revoted Shift monitoring in progress MCRELIUS.C E. MARABITO.R Region 3. Chicago. Office of the Director BI/02/24 1p 07782 093
- 3103100593 Forwards LER 81-005/03L-0 ORAESSER.W L Commonwealth Edison Co. 81/03/05 ip. 07862 340.
- --SIO3100596 LER Bi-005/63L-O on Bi0204.shift angineer discovered that two hydrogen recorbiners not interchangeable as implied in FSAR Caused by 3-inch to 4-inch reducer that was welded on discharge piging making recombiners not identical DINGEGLI.8 L Commonwealth Edison Co Bi0/03/09. Ip. 07862 341.
- 8103170358 PhD-111-81-025 on 810306, received telcon re failure of containment integrated leak rate test Cause traced to excessive leakage in personnel air lock, portions of IMI sample sys & TMI wide range pressure gauges XCMLER, J. KHOP.R.C. Region 3, Chicago, Office of the Director 81/03/06 1p 07924 079
- 8103170521 Forwards LER 81-004/03L-0 GRAESSER.R L. Commonwealth Edison Co. 81/03/06. Ip. 07925:189.
- ~-8103170528 LER 81-004/03...-0 on 810204-during surveillance,RhR miniflow control valve IFIC-bilA switch failed & uduld not trip.
  Caused by out-of-tolerance micro switch Switch was recalibr Similar switches are being checked PANAGOS.A Commonwealth Edison Co 81/03/06 lp. 07925.190
- B103170365 PRO-111-81-028 on 810309 resident inepector notified of intent to replace boron injection tank Caused by leakage in manuay liner & pipe notife liners Replatement of tank to estend current outage for approt 4 bys ROMLER.J NETSLER.J KNOP.R C. Region 3. Chicago. Office of the Director 81/03/09 2pp 07924.081
- 8103310548 Forwards LER 81-005/03L-0 ORAESSER, X L Commonwealth Edison Co. 81/03/20 16 08081 220

- --8103310558 LER Bi-006/03L-0 on 810228 fire sum; radiation monitor DRT-FR29 high alarmed Caused by break in salder joint in high voltage circuit of conitor Joint repaired motor functionally tested & returned to svc AKER.R E Componeealth Edison Co. 81/03/20 ip 08081 221
- V Operator Examinations
- 8103030769 Forwards supplemental info re shift technical advisor training per NUREO-0737. Item I A I 1 (3) Info includes response to training requirements for shift control room engineers & projected schedule for training completion.

  ABELUS Componwealth Edison Co. 81/02/24 4pp
- BIG3050140 Forwards list of shift control room engineers meeting training & education requirements by dates indicated Many engineers completed training by BIG101. Target date for completion of training is rid-1981.

  ABEL. J S Communealth Edison Co BI/02/24 4pp
- 8)03200574 Forwards supplemental info re long-term shift technical advisor program including candidate qualification selection criteria, training plans & bases for phase-out of shift technical advisor program mandated by NUREG-0737 ABEL.J. S. Commonwealth Edison Co. 81/03/17 19pp
- COCKET 30-276 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- 8103180264 Ltr to all power reactor licenses u/plants licensed prior to 770101. Forwards NRC position & request for addl info resafe shutdown capability for compliance w/801119 fire protection rule EISENMAT.D.Q Division of Licensing 81/02/20 13pp
- B103040717 Informs that licensee will conduct emergency preparedness exercises Bept 1981 for Browns Ferry & Mar 1982 for Watta Bar.per 810130 request Exercise scenerios will be provided four whs before scheduled exercise MILLS.L M. Tennessee Valley Authority 81/02/29 ip 07812 269
- BiO3060335 Forwards addl info re quard training & qualification plans Encl withheld tref IOCFR2 740) MILLS-LM Tennessee Valley Authority 81/02/26 ip 07837 063.
- B103160133 Forwards add1 revisions necessary to find B10123 sefeguards contingency plan acceptable Response requested within 30 days.

  IPPDLITO,T A Operating Reactors Branch 2 81/03/02. 4pp 07919 326
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Energency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl EISERHVI.D & Division of Licensing 81/03/05. App.
- BIO3170194 Forwards revisions to physical security plan Encl withheld (ref 100FR2.790)
  MILLS-L H Tennessee Valley Authority 81/03/09 tp. 07935:317
- 8103260239 Requests exemption from App R fire protection requirements re-safe shutdown capability, emergency lighting & oil collection sys for reactor coolant pumps Responds to NRC 801124 & 810220 ltrs to all PUR ligensess.

  MILLS.L.M Tennessee Valley Authority. 81/03/18. 2pp. 08037:167.
- 8103270512 Requests relief from commitment re installation of lighted outs signs in response to NRC 810204 request Externally illuminated directional sitt-type signs are adequate.

  MILLS-L.M Tennessee Valley Authority. 81703720. 2pp. 08046:225.
- Q. Adjudicatory correspondence
- 8103130451 Order setting 810410 prehearing conference to discuss petitioners' standing to intervens. Petitioners must file suppls to petitions no later than 15 days prior to conference. listing contentions sought to be li
- 8103260121 Reply to T Paul, R Jobe & M Hell & H Fenn, R Hudgens &

70467 Notices of appearance in license amend proceeding tigicate of Svc encl ERTY-J H Hearing Branch | LEWIS-8 H Hearing Brunch 2 03/24 App 06034 146

surance & indemnity information

60339 Forwards Endorsenents 4 to MAELU Binders XB-38,XB-39 & 40 LDER.J Marsh & McLennan.Inc . M & M Nuclear Consultants,Inc 81/01/27 7pp 07840 229

60369 Forwards Endorsement 44 to MAELU Policy MF-66 LDER-J Marsh & McLennan.Inc . M & M Nuclear Consultants.Inc 81/01/29 2pp. 07840 236

erating license stage documents & correspondence

90732 Lits to all licensees of operating plants applicants for & holders of CPs re control of heavy loads. Requests lew per guidelines in NUREO-0612 Forwards NRC position re erim actions & request for addl info ENHUGOO Division of Licensing 80/12/22. 30pp

90387 Ltr to all licensees of operating plants & applicants for & holders of CPs re program for environ qualification safety-related electrical equipment ltems addressed olve cold shutdown.replacement parts & NOREO-0737

ENHUT D G. Division of Licensing. 81/01/19 App

40290 Ltr to all BMR licensees forwarding Suppl I to generic ety evaluation on BMR scram discharge sys Summarizes evaluation of interim measures recommended per 801201

etu evaluation ENHITID Q Division of Licensing 81/01/23 Zan

20014 Ltr to all licensees of operating plants CP helders & OL licents except Indian Point 2 & 3.2ion | & 2 & TMI-i, warding inadvertently omitted pages from NRC B01222 uest for add! info re control of heavy loads ENRUT D.O. Division of Licensing. 81/02/03 6pp

60669 Ltr to all operating plants & CP holders forwarding rification of TMI Action Plan Item III.A 1.2 rs upgrade emergency support facilities. Requests confirmation within days that implementation dates will be met. ENHUT.D. 0 Division of Licensing 81/02/18 12pp

50097 Notification of contract execution: "Environ Assessment of Laval Maste Storage at TVA Browns Ferry Nuclear Plant in extens County, QA. " awarded to Science Applications, Inc RSTON.C.A. Technical Assistance Contracts Branch. FIN 8-7319-1

02/20

3090074 Contract "Environ Assessment of Low Level Waste Storage at VA Browns Ferry Nuclear Plant in Limestone County, GA. warded to Science Applications, Inc. INDLEY, D.E. Science Applications, Inc. FIN D-7319-1 81/02/20.

30024 Ltr to gil power reactor licensees & license applicants re 19-0619 criteria.Footnote 2 in Table 2 contains error due to-color tritogram rootines Licensee may submit analysis to tally use of existing low flow controller.

ENHUT, D. C. Division of Licensing. 81/02/20 Bpp.

20510 Forwards tabulation of chlorine residual in raw cooling er sys for periods 760516~0605 & 761003-23, per ETB tion 4.1.3, Data Indicates that weekly sampling is quate to demonstrate compliance w/spec.
B.L.M Tennessee Valley Authority. 81/02/23. 3pp. 07785-058

30020 Forwards Amends 47.63 & 39 to Licenses DPR-33.DPR-52 & -68.respectively & safety evaluation. DLITO.T.A. Operating Reactors Branch 2. 81/02/24. 2pp. 37:153.

3130029 Amends 67.63 & 39 to Licenses DPR-33.0PR-52 & DPR-68. sspectively, modifying bases for screen insertion times by sectifying 290 milliseconds as time period to be used in secifying 290 milliseconds as time period to be used in section of the period of transients. PPOLITG. T.A. Operating Reactors Branch 2. 81/02/24, 37pp. 2907:155.

3130036 Bafety evaluation supporting Amends 67.63 & 37 to Licenses PR-33,DPR-52 & DPR-68,respectively. Office of Nuclear Reactor Regulation: Director: 81/02/24. 3pp 07907:192.

9103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blactout event & promptly implement energency procedures. EISENHUT-D O Division of Licensing. 81/02/23 Spp.

8103170225 Ltr to all 3MR licensees (e)cept Humboldt Bay & LaCrosse) requesting review of ASPE Cote Class ( & 2 pressure boundary piping, safe ends & fitting metl per guidelines of encl Revision I to NUMEC-0313 Model Tech Specs only encl EISENHUT.D G Division of Licensing 81/02/26 3pp

--BIO3170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4-() in surveillance requirements for ABMC Code Class 1.2 % 3 components & RCS operational leakage limiting conditions for aperation & surveillance requirements

# General Electric Co 81/02/26 4

8103130108 Forwards Amends 68.64 \$ 40 to Elicenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availabilitu IPPOLITO, T A Licensing Branch 2 81/02/27 200

--8103130118 Amends 68.64 t 40 to Licenses DPR-33.DPR-52 t DPR-68. TO STANDARD THE PROPERTY OF TH

--8103130125 Safety evaluation supporting Amends 60.64 & 40 to Escenses DRR-33.DRR-52 & DRR-60 respectively \* Office of Nuclear Reactor Regulation, Director 81/02/27, 5pp

--BiO3130131 Notice of issuance & availability of Amends 68,64 & 40 to Licaness DPR-33, DPR-52 & DPR-68, respectively IPPOLITO. TA Licansing Branch 2 81/02/27, 2pp

8103110414 Application for amend to Licenses DPR-33 DPR-52 & DPR-60 submitted as proposed changes to Yech Specs for operability Surveillance requirements for continuous level nonitoring sys on scram discharge volume.per IE Bulletin 80-17, Suppl 4 MILLS.L M Tennessee Valley Authority, 81/03/03 4pp. 07872 200 --6103110440 Tech Spec 3 2 % Tables 3 2 F & 4 2 F for instrumentation

\* Tennessee Valley Authority 81/03/03 18pp 07872 291

BIO3100325 Advises that Tech Specs for NUREG-0737 items will not be authorited until receipt of further guidance from NRC MILLS.L. H. Tennessee Valley Authority BI/03/04. Ip 07865 063

8103100601 Forwards request for amend to Licenses DPR-33. DPR-52 & MILLS-L M Tennesses Valley Authority 81/03/04 2pp. 07863.072

--Bi03103603 Request for amend to Licenses DPR-33, DPR-52 & DPR-6B, interchanging initiation logic for CO-2 fire protection sys & water spray sys in cable spreading room to make water spray primary sys & CO-2 sys manual backup sys.

Tennessee Valley Authority, 81/03/04 1p 07863:094

D103190249 Forwards Amends 69.65 & 41 to Licenses DPR-33.DPR-52 & OPR-68.respectively & notice of issuance & availability
IPPOLITO, T.A. Operating Reactors Branch 2 81/03/06 3op

--BIO3170259 Amends 69:65 & 41 to Licenses DPR-33, DPR-52 & DPR-68, respectively, deleting ETS Sections 2 1.2 2.3.1 2.5.4. 5 6.3.6.5 7 1.c & changing titles in Administrative Controls

Section 5 0
IPPOLITO, T.A. Operating Reactors Branch 2 81/03/06. 6800.

--8103170269 Notice of Issuance & availability of Amends 69.65 & 41 to Licenses DRR-33, DRR-52 & DRR-68-respectively. IPPOLITALTA Operating Reactors Branch 2, 81/03/06, 2pp

B103300495 Ack receipt of 801028 request for reconsideration of Amends 60,55 & 32 to Licenses DPR-33, DPR-52 & DPR-60, respectively, authorizing temporary storage of low level raduaste. Ltr to be treated as IOCFR2 236 request W/FR notice.

DENTON, H. R. Office of Nuclear Reactor Regulation, Director.
B1/03/06 3pp 08058-049

~-B10330550 Notice of receipt of 801028 request for action under 10CFR2, 206 by Huntsville Chapter of Bafe Energy Alliance of AL. Requests reconsideration of certain amends to facility DELs.permiting temporary storage of low level raduaste.
DENTON.H.R. Office of Nuclear Reactor Regulation, Director.
81/03/06. 1p. 08058:052

- 0103310834 Ltr to all licensees of operating plants applicants for Dus ivositoom tir to all licensees or operating plants, applicants 5 holders of CPs forwarding SECY-81-119 ne info necessary to metablish environ qualification of safety-related electrical equipment
  FISENHUT.D C Division of Licensing 81/03/10 6;p
- 9103170583 Forwards revised response to Item 15. correcting error in encl of 810230 ltr re weld failures
  Mill S. H. Tennessee Valle, Authority 81/03/11 2pg 07927.345
- 8103170520 Discusses reinstatement of temporary relief from 5 F reservoir temp rise limit at facilities Requests mod of variance to alicu #vll operation of facilities u/G 5 F river tend rise limitation EL-AGHRY.M T. Ternessee Valley Authority 81/03/12 2pp 07020 114
- 8103231095 Informs that util 801215 & 810203 cormitments do not meet stateria Requests completion of mode by B21231. Design must criteria requests (completion or most by Baledi. Design abstinctude 1180 diverse instrumentation criteria from 801201 generic SER on 848 scram discharge sys (PPOLITO, T.A. Operating Reactors Branch 2 81/03/12 2;p
- B103260083 Forwards preliminary results of NAC review of environ qualification of safety-related electrical equipment at qualification or safety-related electrical equipment at facility lightified deficiencies & ranifications should be reviewed & overall findings submitted ADVAN. T.K. Assistant Director for Operating Reactors. 81/03/16 60pp 08039 170
- B103270095 Summary of B10304 meeting u/Mark I owners group & GE in 103270095 Surmary of BIO304 meeting C/Mark I olders group or BetheedarMD re supplementary tests confucted in full-scale test facility & resolution of outstanding Mark I issues por MARED-Obbi Blide presentation & list of attendees encl ORIMEE.C I Licensing Branch 3 B1/03/16 5pp
- 8103230948 Forwards addit request for relief from ASME Section 11 exam requirements re RHR heat exchangers
  MILLS.L M Tennessee Valley Authority 81/03/17 2pp
- 8103240341 Forwards util resconse to NUREG-0737 Item III D 3 4 re control room habitability requirements Chemicals stored onsite in quantities greater than 100 lb Lill not affect control room on rupture of single largest container HILLS.L M Tennessee Valley Authority BI/03/17. 4pp 07990 137
- 8103290673 Advises of planned site visit to obtain first-hand info re Unresolved Safety Issue A-44. "Station Blackout " Visit is tentatively scheduled for 810324 to coincide w/emergency tentactively screenies for Biose to Collective Greening Bicky Clearly generator testing schedule

  IPPOLITO.T A Operating Reactors Branch 2 81/03/17. 4pp 09000 250
- à Inspection reports. IE Bulletins & correspondence
- 8103106045 Forwards IE linep Repts 50-259/80-44.50-260/80-41 & 50-296/80-40 on 801124-21 No noncarpliance noted. LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Stanch 81/01/26 2pp 07855 111
- --8103100053 IE Insp Repts 50-259/80-44.50-260/80-41 % 50-296/80-40 pm 801124-27 No noncompliance noted Major areas inspected MSIV testing & pipe support & restraint sys. BROOKS, E. H. Region 2. Atlanta, Office of the Director. GUICK, D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. B1/01/21 4op 07895 113
- 8103120429 Farmands SE Jose Rept 50-276/80-38 on 801202-05 No. nancerpliance noted HARPHY.C.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/04 2pp. 07905 130
- --8103120436 IE Insp Rept 50-296/80-38 on 801202-05 No noncompliance noted Major areas inspected inservice insp data for pumps, reactor vessel fatigue useage factors & inservice imp work & procedures
  DIRARD.E M Region 2. Atlante. Office of the Director. HERDT.A R
  Region 2. Atlante. Reactor Construction & Engineering Support
  Branch. B1/02/03 3pp. 07903-132
- Bi03020277 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals Haile on Duty" No written response required D'ÆELLV.J P. Region 2. Atlanta. Office of the Director. 81/02/09
- B103040802 Forwards monthly status rept for work re IE Bulletin 79-14. as of 810201 Rept includes drawing configuration insp.pipe support insp.floor & wall penetration insp & valve insp. MILLS.L M Tennessee Valley Authority 81/02/10. 30pp 07810:087.

- 8103040156 Forwards IE Info Notice 81-03. 103040136 Forwards in into water of the Matting Notifications of Bignificant Events In Accordance Matting Notifications of English the Matter response required UTGCFRO 72 " No written response required DTGCFRO 72 " No written response required DTGCFRO 72 " No written response required DTGCFRO 72" No writen response required DTGCFRO 72" No written response require 15 07812 342
- Bio3050015 Forwards Suppl 5 to 16 Bulletin 80-17, "Failure of Content Rods to Insert During Scram at BWR " No written response Region 2. Atlanta, Office of the Director - 81/02/17 DIREILLY. J.P.
- 8103160682 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines "No response required O'ReilLy. Pracking in Main Lines "No response required O'ReilLy.J P Region 2. Atlanta, Office of the Director ip 07914 319

10 07026 009

- 8103160916 Forwards IE Circular 81-03. "Inoperable Sejamic Monitorina Instrumentation' No response required with Director. 81/03/02 wfPPLER.J Q Region 3. Chicago. Office of the Director. 81/03/02
- Bio3170085 Provides add1 info re IE Bulletin 80-15, "Possible Loss of Energency Notification Sys (ENG) w/Loss of Offsits Power" Util espects to complete required mode at Oromas Ferry by 810427 & at Sequeyah by 910427 Bi
- 8103180986 Describes content of encl to 801031 util responses to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment " MILLS L M Tennessee Valley Authority. 81/03/03 2pp 07954:007.
- BIO3120744 Ack receipt of 810205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-259/80-40, 50-260/80-35 5 50-295/80-34 LEWIS-R C Region 2- Atlanta, Reactor Operations Nuclear Support Branch
- --B103120749 Responds to NRC B10109 ltr re violations noted in IE Insp Repts 50-259/80-40:50-260/80-35 % 50-296/80-34 Corrective neps 30-237-00-90 00-007-00-33 & 30-270-00-34 corrective actions fuel handling stopped while control rod inserted Procedure uniten for unloading control cells.

  MILLS.L.M. Tennessee Valley Authority 81/02/05. 5pp. 07905 274
- --8103120794 Forwards IE Insp Repts 50-259/80-40, 50-260/80-35 & 50-296/80-34 on 801001-31 & notice of violation.

  OREILLY, J. P. Region 2. Atlants, Office of the Director.
  B1/01/09 2pp 07905 279
- --8103120760 Notice of violation from insp on 801001-31. Region 2. Atlanta. Office of the Director 81/01/09 Zep. 07905, 281
- --BI03120770 IE insp Repts 50-259/80-40.50-260/80-35 & 50-276/80-34 on B01001-31 Noncoroliance noted failure to have all refueling interlocks operable during refueling operations. Fuel assemblies loaded Urane control rod withdrawn. SULLIVAN.R.F. CHASE.J W. MARSH.R.J. Region 2. Atlanta, Dffice of the Director 81/01/09. 14pp. 07905:283.
- 8[03170011 Forwards revised [E Bulletin B]-01. "Surveillance of Mechanical Snubbers, "w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, P. Region 2, Atlants, Dffice of the Director. B1/03/04 lp 07924 086
- 8103130739 Forwards IE Enforcement Meeting Repts 50-289/81-04, 50-260/81-04 & 30-296/81-04 on 810211.re facility fire protection/prevention program.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/05. 07912:061.
- --B103130741 IE Enforcement Meeting Repts 50-259/81-04.80-260/81-04 & 50-296/81-04 on 810211. Areas discussed: fire protection & prevention program at facility.
  MILLER.W.H. Region 2. Atlanta. Office of the Director.
  CONLON.T.E. Region 2. Atlanta. Reactor Construction & Engineering
  Support Branch. 81/03/02 4pp. 07912:062.
- 8103160883 Provides supplemental response to Suppl 4 to IE Bulletin 80-17. "Failure of 75 of 183 Control Rods to Fully Insert During Scram at BUR." Appropriate procedures have been developed in response to bulletin. MILLS.L.M Yennessee Valley Authority. 81/03/05. 2pp. 07915:242.

0477 Forwards monthly status rept of work as of 810301 re IE etin 79-14. "Unauthorized Procurement & Distribution of . .

2. M. Tannossee Valley Authority 81/03/09, 29np. 08037 173

0655 Forwards IE Insp Repts 50-259/80-47.50-260/80-37 & 76/80-41 on 801201-31 & notice of violation 6.R C Region 2. Atlanta, Office of the Director 81/03/10 07983 202

14066 Notice of violetion from insp on B01201-31. Region 2. Atlanta, Office of the Director. B1/03/10. 2pp. 183.204

40681 IE Insp Repts 50-259/80-47, 50-260/80-37 & 50-296/80-41 un 201-31 Noncompliance noted: failure to have torus access EQUI-JI NONCOMPIIANCE NOTES: FAILURE to neve torus accessible planting installed as required by safety analysis LIVAN.R.F., CHASE.J.W. Region 2. Atlanta. Defice of the sector DANCE.H.C. Region 2. Atlanta. Reactor Operations lear Support Branch. 81/02/25. 11pp. 07983:206.

1080 Forwards IE Insp Repts 50-259781-03.50-260781-03 & 16781-03 on 610101-31 & notice of violation.

B.R.C. Region 2: Atlanta, Office of the Director. 81703710. 08045 189

. 170087 Notice of violation from inep on 810101-31 Region 2, Atlante, Office of the Director. 81/03/10. 2pp 49.191

70104 TE Inam Repts 50-259/81-03.50-260/81-03 & 50-296/81-03 on 101-31 Noncompliance noted secondary containment not ntained & radioactive contaminated ladder found in

en area. LIVAN.R.F., CHABE.J.W., PAULK.O.L. Region 2, Atlanta, Office of IVAN.R.F., CHABE.J.W., PAULK.O.L. Region 2, Atlanta, Office of

ol97 Forwards IE Info Notico 81-06, "Failure of ITE Model K-600 it Breaker." No response required. LLV.J.P. Region 2, Atlanta, Dffice of the Director. B1/03/11. 07968:319

003 Forwards IE Info Notice B1-05. "Degraded DC Bys at ades. "No response required.
LLY.J.P. Region 2. Atlanta. Office of the Director. Bi/03/13.

211 Responds to 16 Bulletin 79-18. "Audibility Problems intered on Evacuation of Personnel From High Noise." New speakers having appropriate design & power g in high noise areas will be installed by Feb 1982. L. M. Tennessee Valley Authority. 81/03/13. 2pp.

044 Responds to IE Bulletin B1-D1, "Surveillance of Mechanical V44 Kesponds to It Bulletin B1-O1, "Burvelilance or neclets "Ongoing insp in progress Requests exemption from testing until next scheduled refueling outage.Estimates 200 manhours will be required to implement actions.

LLM. Tennessee Valley Authority. B1/03/13. 12pp.

524 EN-81-010 on 810320 notice of violation & proposed ition of civil penalties will be issued Action based on ad noncompliance re fire protection program.

R.O. Director's Office. Office of Inspection and Enforcement.

/17. ip.

180 Responds to IE Bulletin 80-25, "Operating Problems W/Target Bafety Relief Valves at BURs." Thirty-nine OE two-stage t Rock valves in use Testing of valves will be atted during next refueling shutdown. L.M. Tennessee Valley Authority. 81/03/18. 5pp. 08040:259.

194 Discusses IE inep on 810105-09 & 20-23 & forwards notice of tion & notice of proposed imposition of civil penalty. 0.V. Director's Defice, Office of Inspection and Enforcement. /20. 2pp. 08035:274.

61166 Notice of violation & proposed imposition of civil penalties amount of \$80,000 from insp on \$10106-09 & 20-23. Areas of compliance noted in fire protection program. LLG.V. Director's Office. Office of Inspection and Enforcement. /03/20. 4pp. 08035:276.

61177 Notice of deviation from insp on 810106-09 & 20-23. compliance noted several doors in control bay portion of nt have not been changed to approved type fire doors & pproved valves provided for HPCI sprinkler sys. Director's Office, Office of Inspection and Enforcement, 03/20. 1p. 08035:280.

- R Periodic operating reports & related correspondence
- 8103050497 Forwards "Annual Operating Rept. 1980 "
  Mild S.L. M. Tennessee Valley Authority, 81/02/27 10 07824, 140
- --8103050511 "Annual Operating Rept. 1980" \* Tennessee Valley Authority. RH-81-1-8F-1 81/02/27. 80pp. 07824:141
- 8103170546 Forwards nonthly operating repts for Feb 1981.
  ABERCROMSIE H Tennessee Valley Authority 81/03/10. Ip.
- --8103170350 Monthly operating repts for Feb 1981.
  THOM: T Tennessee Valley Authority 81/03/01, 40pp. 07933.304.
- A Reportable occurrences, LERs & related correspondence
- 8103240478 Forwards LER 80-056/03L-0.
  OREEN,H 3 Tennesse Valley Authority. 81/01/13 ip. 07984:329.
- --B103240484 LER 80-056/03L-0 on 801215 during refueling diesel generator voltage available relay found dropped out. Caused by open wire in cable Cable replaced. \* Tennessee Valley Authority. 81/01/13. 2pm. 07984:330.
- 8103240461 Forwards LER 80-057/03L-0 ORFEN.H J. Tennessee Valley Authority, 81/01/16, 1p. 07984,325.
- --8103240468 LER 80-057/03L-0 on 801223 continuous air monitor dispenses the government of the second secon personnel cautioned # Tennessee Valley Authority: 81/01/16. 2pp. 07984:326.
- B103020524 Forwards LER B1-008/03L-0.

  OREGN.H J Tannesses Valley Authority. B1/02/24 Ip. 07762 349.
- --B10302032B LER B1-008/03L-0: on B10202.RHR pump found inoperable. Caused by loose pump 3D breaker trip adjustment rut &'adjustment change.causing breaker to trip free on attempting to close. Breaker replaced. Adjustment locknot tightness checks added. \* Tennessee Valley Authority. 81/02/24 2pp. 07782; 350.
- 8103040639 Forwards LER 81-009/03L-0.
  OREEN.H.J. Tennessee Valley Authority. 81/02/27. 1p. 07811:331.
- --8163040643 LER 81-009/03L-0.on 810203 diesel generator 3C failed to stop within appropriate time Dissel shut down & on estempted restart failed two out of three times Failure to stop caused by relay failure. Cause of inoperability unknown.

  Tennessee Valley Authority. B1/02/27. 2pp. 07B11: 332.
- 8103100508 Forwards LER 81-010/03L-0. GREEN, H.J. Tennesses Valley Authority. 81/03/08. 1p. 07862:308.
- --B103100516 LER B1-010/03L-0: on B10213, drywell high pressure switch 3-P8-64-98C found above Tech Spec limit. Caused by setpoint drift. Buitch recalibr & will be replaced.

  Tennessee Valley Authority. 81/03/06. 2pp. 07862:307.
- 8103230792 Forwards LER 81-012/03L-0.

  OREEN, H. J. Tennessee Valley Authority. 81/03/13. 1p. 07974:043.
- --Bi03230798 LER Bi-012/03L-0 on Bi0224 stram discharge level switch (25 gallon) found 0.4% above setpoint during performance of Bi 4.1.A-B. Caused by model BL-305-ET-X level switch. 3-L8-85-45E, setpoint drift.Buitch recalibr.

  \* Tennessee Valley Authority. Bi/03/i3. 2pp. 07974:044.
- 8103240548 Forwards LER 81-011/03L-0. OREEN-H J. Tennessee Valley Authority. 81/03/18. lp. 07984:358.
- --8103240549 LER 81-011/03L-0: on 810224; coupling damage was found on 3DA RMOV Bd MG set. Caused by miselignment & loss of lubricant. Coupling seal found separated. MG set realigned, coupling replaced & all other set couplings repaired.

  ### Tennessee Valley Authority. 81/03/18. 2pp. 07984: 359.

DOCKET 30-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

S103170622 Advises of two organisational changes in Nuclear Engineering Ospt PJ Turinsty, replaces TS Elianan as dept head RO Cockrell replaces JR Bohannon as Director of Nuclear Reactor Program Requests appropriate changes to healting lists COCKRELL.R Q North Carolina State Univ 81/03/12 1p 07925 166

# Q Inspection reports. IE Bulletins & correspondence

8103020156 Porwards IE Circular Bi-02. "Performance of NRC-Licensed Individuals While on Duty" No written response required O'REILLY.JP Region 2. Atlante. Office of the Director 81/02/09 ip 07788 065

DOCKET 50-298 COOPER MUCLEAR STATION

F. Becurity, medical, emergency & fire protection plans

BiO3130132 Porwards Revision 10 to physical security plan. Revision withheld (ref IOCPR2 790) PILANT. JM hybrasta Public Power District Bi/02/19 ip 07911 358

8103180264 Ltr to all power reactor licenses w/plants licensed prior to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance u/801119 fire protection rule EISENHUT.D C Division of Licensing 81/02/20 13pp

B103050649 Discusses enrightcy preparedness meteorology program requirements.per NUREG-0554 Hethods to be used for meteorological program will not be detailed pending NRC clarification on requirements at worlshops in Mar 1981 PILANT.J.M. Nebracka Public Power District B1/03/01 2pp. 07825-063

B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for neeting NRC requirements W/o encl EISENHUT.D 0 Division of Licensing. 81/03/05 6pp.

8103250120 Requests extension of schedule requirements for submitting plans & schedules per 10CPR80 48(c)(5) for Itome III 9 & III J re fire protection. Also requests ecomption for safe shutdown capabilities & toll implementation schedule PILANT. J M. Nebrasta Public Power District. 81/03/18. Spp. 07998 281

#### @ Adjudicatory correspondence

G100310426 Forwards and of order for license mod.per util request.
Implementation date for automatic air header dump sys is changed from B10409 to B10426 Order is being forwarded to FR for publication.
IPPOLITO.T A Operating Reactors Branch 2 B1/03/1B. 2pp.
08039-296.

--BIO3310432 Order modifying BI0109 order requiring automatic air header dump sus to be implemented by BI0409 New implementation data is BI0426 EISCN-WIT, D.O. Division of Liconsing. BI/03/18. 3pp. 08059:298

# P Operating license stage documents & correspondence

8103170732 Ltrs to all licenses of operating plants, applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NNREO-0612. Forwards INSC position re interim actions & request for add1 info.

EIBENHUT.D.9. Division of Licenseing 80/12/22. 30pp.

8103190387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve Cold shutdown-replacement parts & NUREO-0737. EISENNUT.D.O. Division of Licensing. 81/01/19. app.

BIO3240290 Let to all BWR licensees forwarding Suppl 1 to generic safety evaluation on BMR screw discharge sys. Summarises re-evaluation of interim measures recommended per Bol201 safety evaluation. BlockHUT. D. O Division of Licensing. 81/01/23. 2pp.

8103030992 Forwards Amend 67 to Literage Den 40, salinty notice of issuance t availability IPPCLITO.T A Operating Reactors Branch 2 81/01/30 3pp 07798 016

- --BIO3031606 Amend 67 to License DPR-46 establishing max average planar linear heat generation rate limits for 7x7 & 8x8 fuel asserblies for exposure values beyond current Tech Spec 14cits.

  IPPOLITO.T A Operating Reactors Branch 2. BI/01/30 Spp 07788 019
- --Bi03031018 Safety evaluation supporting Amend 67 to License DPR-46

   Office of Nuclear Reactor Regulation. Director 81/01/30 Sep.
  07798-024
- --8103031024 Notice of issuance & availability of Amend &7 to License DAR-46 IMPOLITO, T A Operating Reactors Branch 2 81/01/30 2pp 02798 029
- 8103120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3.7ion 1 & 2 & 7M1-1, forwarding inadvertently mitted pages from HRC 801222 request for addition or control of heavy loads EISENHUT. 0 9 Division of Licensing 81/02/03 6pp
- 8103090139 Forwards Tech Spec Pages 211 & 211a which were unitted from 810130 Amend 67 to OL Proposed amend pages (nadvertently sent IPPOLITO, T A Operating Reactors Branch 2 UI/02/10 2pp 07827 328
- --B103050143 Pages 211 & 211a onitted from B10130 Amend 67 to OL • Operating Reactors Branch 2. 81/02/10. 2pp 07827: 330
- 8103040936 Forwards revised NRC Region 4 organization chart-effective 810227. SEYPRIT.K. V Region 4, Dallas, Office of the Director. 81/02/17. 20a. 07505:001.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A 1.2 re upgrade of ecergency support facilities Requests confirmation within 45 days that implementation dates will be met ETEENHUT. D. O. Division of Licensing 81/02/18. 12pp.
- 6103296024 Ltr to all power reactor licensees & license applicants re NUREG-0619 criteria Footnote 2 in Table 2 contains error due to teakage teating deletions Licensee may submit analysis to justify use of existing low flow controller. EIBERHUT.D.O Division of Licensing 81/02/20. Spp.
- 8103100409 Forwards Amend 68 to License DPR-46, safety evaluation & notice of issuance & availability.

  IPPOLITO, T.A. Deparating Reactors Branch 2. 81/02/23. 2pp.
  07884:186
- --8103100414 Amend 68 to License DPR-46 making administrative changes & incorporating TMI-2 lessons learned including emergency power supply/inadequate core coaling valve position indication & containment isolation.

  1PPOLITO.T. A Operating Reactors Branch 2. 81/02/23 17pp 07864:188
- --Bi03100417 Safety evaluation supporting Amend &B to License DPR-46
   Office of Nuclear Reactor Regulation, Director. 01/02/23 3pp
  07844-208
- --B103100422 Notice of issuance & availability of Amend 6B to License DPR-46. iPPOLITO, T. A. Operating Reactors Branch 2. Bi/02/23 2pp. 07864:210.
- 8103130193 Forwards Amend 69 to License DPR-46 & notice of issuance & availability.

  IPPOLITOL T A Operating Reactors Branch 2. 81/02/25. 3pp.
- --8103130200 Amend 69 to License DPR-46 requiring guard training \$ qualification plan implementation within 60 days of Commission approval.

  IPPOLITO.T.A. Operating Reactors Brench 2 81/02/25, 2pp. 07/98:335.
- --BIO3130205 Notice of issuance & availability of Amend 69 to License ppR-44.

  IPPOLITO, T. A. Operating Reactors Branch 2 B1/02/25. 2pp. 07908:337

- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie.Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergancy procedures EISENBUT D Division of Licensing BI/02/25 Spp
- 8103170225 Ltr to all JWR licenses (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure haunders requesting review or Auric Look Liess 1 & 2 pressure bo piping, safe ands & fitting mat) per guidelines of anci Revision 1 to NAREO-0313 Model Tech Opecs only enci EISENHUT. D D. Division of Licensing 81/02/20 3pp
- --- 8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re rusivezon munes (etc. specs rages 3/4 0°2,3/4 0°3,3/4 4°7 & 3/ surveillance requirements for ABUE Code Class 1.2 & 3 components % RCS operational leakage limiting conditions for operation & surveillance requirements
  # General Flectric Co. 81/02/26 Jon
- B103050493 Forwards revised response to NUREO-0737. "Clarification of TMI Action Plan Requirements." Response covers Items I C 6. 11 D 3(P), II F 1(P), II K 3 3 & II K 3 27 PILANT, J.M. Nebraska Public Power District 81/02/27 3pp 07832 104
- B103090490 Requests that refund of Class II fee for B0050B proposed change to ETS be applied directly as payment for 010223 request for changes to ETB

  PFLANT, J M Nobrasia Public Power District 81/03/02 ip 07826 107
- 8t03120835 Forwards request for add1 info re containment purging during normal plant operation mechanical operability demonstration info needed within 60 days to complote review of 791218 commitment to comply w/790927 long-term requirements iPPQLITO.T A Operating Reactors Branch 2 81/03/03 Spp normal name on the complete of the comp
- 8103160418 Requests revision of License DPR-46 to allow operation 19310041B Requests revision of License DPR-45 to allow operat: Pollowing sixth refueing Forwards Eupplemental Reload Licensing Bubmittal for Cooper Nuclear Blation i.Reload 6.' Jan 1981. 5 proposed Tech Spacs changes PILANT.J.M. Nebraska Public Power District (1/03/05. 3pp 0791B IBA
- -- @103160423 Proposed Changes to Tech Specs re operation following sixth Nebraska Public Pouet District - 51/03/09 - 900 - 07918-159
- --8103160428 "Supplemental Reload Licensing Submittal for Cooper Nuclear Station Unit 1.Reload 6 " ZARBIS.W A. ENGEL.R E. General Electric Co. Y1003J91A17 81701/31 31pp. 07918 178.
- 8103120022 Requests that 801219 commitments to DHR scram discharge sys be modified to comply widiverse instrumentation design criterion. Response required within 30 days. IPPOLITO, T.A. Operating Reactors Branch 2 81/03/06. 2pp. 07905.039
- Bio3120032 Forwards request for addl info re adequacy of station electric distribution sys valtages per 790808 request. Response required within 49 days. IPPOLITO, T. A. Operating Reactors Granch 2 81/03/06 4pp. 07905.041
- Bi03200100 Informs that staff functions of Region 4 reassigned, effective Bi0227 OL Modsen. Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondence re-reactor const & operation activities. SEYFRIT.K.V. Region 4, Dallas, Office of the Director. 81/03/09. pp. 07769:053
- B103190559 Forwards Class II fee for extension of implementation data for NRC order is control and driveline air header dump. PILANT.J.15 Nobraska Public Power District. B1/03/10 ip. 07965: 087
- 8103310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment. EIBENHUT, D.O. Division of Licensing. 81/03/10. App.
- 8103270099 Surmary of 810304 meeting w/Mark I owners group & GE in Bethesda-MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MARG-0661.51(de presentation & list of attendess onch. ORIMES.C. I. Licensing Branch 3. 81/03/16. 5pp.

- 8103260959 Forwards updated list of matts needed for assessment of iosecopy romands updated rist or mates needed for assessmi impacts of facility operation Requests that util provide contractor,Environ Science & Engineering.u/available items 1990LITO.T A Compating Reactors Branch 2 81/03/18 3nn
- 8103310426 Forwards mod of order for license mod.per util request implementation date for automatic air header dum; sys is changed from 810409 to 810426 Order is being forwarded to FR for publication IPPOLITO, T A Operating Reactors Branch 2 81/03/18 2no
- --8103310432 Order modifying 810109 order requiring automatic air head dump sys to be implemented by 810407 New implementation date 15 B10426 EIBENHULD 0 Division of Licensing 81/03/18 34p. 08059.298
- Q Inspection reports, IE Bulletins & correspondence

000000

- B103230031 Forwards Suppl 4 to IE Sulletin 80-17. "Failure of Control Rods to Insert During Screw at BWR " Written response repulred Region 4. Dallas, Office of the Director. 80/12/18
  - 1g. 07978 025
- BIO3090463 Forwards IE Bulletin 80-25. "Operating Problems w/Target Rock Safety-Reilef Valves at BWRs." Espended ranpower estimates for rept rovine. preparation required per bulletin requested. SEYFRIT K V Region 4, Dallas, Office of the Director. 80/12/19. Ip 07847 292
- 8103261091 Forwards Revision 1 to response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." Revision addresses resolution of outstanding issues & other NAC concerns & deletes unnecessary equipment from master list.
  P[LANT, J. M. Netraska Public Power District. B1/01/29 75000
- 8103200331 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While an Duty "No written response required.
  SEYFRIT.K V Region 4, Dallas, Office of the Director. Bi/Q2/09. 1g 07966 274
- 8103160305 Forwards 1E Info Natice 81-03 "Chacklist for Licensess NATIONAL TOTAL TOT Ip. 07921 338
- 8103200899 Forwards Suppl 9 to IE Builetin 80-17. "Failure of Control Rods to Insert During Scram at BWR," to inform of actions no longer required No written response required SEYFRIT, K V Region 4. Dalles. Office of the Director B1/02/13. In D7967 226
- 8103170657 Forwards 1E Circular 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required.
  SEYFRIT.K V. Region 4, Dellas, Office of the Director. 81/03/02. SEYFRIT, K V. F
- 8]03:10778 Ack receipt of 810206 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/80-17. Provides commands to be considered during revision of MADBEN.G L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. B1/03/03 2pp 07876:350
- --BIO3110782 Responds to NRC BIO119 ltr re violations noted in IE Insp Rept 30-298/80-17 Corrective actions equipment control procedure will be revised to provide for independent control of equipment tagging.
  PILANT, J. M. Nebraska Public Power District, 81/02/06. 3pp. 07876: 352.
- Big3270300 Updates info re admittance of NRC personnel to facility. Forwards lists of regional inspectors N/o enci. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 81/03/03 08044.180 200
- 8103140842 Forwards revised IE Bulletin 81-01. "Burvetllance of Mechanical Bnobbers:" w/corrected Pages 9 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements BEYFRIT.K V. Region 4: Dallas: Office of the Director. B1/03/04. 1p. 07914:201.

- BIO3230170 Forwards IE Info Notice BI-07. "Potential Problem W/Water-Soluble Purge Dam Matls Used During Inert Gas Melding " No response required SEYRIT.K V Region 4. Dellas. Difice of the Director BI/03/16 in 07977 204
- A Periodic operating reports & related correspondence
- 8103030491 Forwards "Annual Operating Rept. 1980" PILANT. J M. Nebrasta Public Power District. 81/03/01 1p 07/99-302
- --Bi03030300 "Annual Operating Rept. 1980 "
   Nebraska Public Power District Bi/03/01 [2pp 07795 303
- 8103130375 Forwards "Semiannual Operating Rept Radioactive Effluents. Jul-Ogo 1980 " PILANT.J M Repressa Public Power District 81/03/01 2pp
- --8103130379 "Semiennual Operating Rept Radioactive Effluents, Jul-Dec 1983 " • Nebreske Public Power District 81/03/01 25929.
- 8103093504 Forcards monthly operating rept for Feb 1981 LESEOR-L C Nebraske Public Power District. 81/03/02 1p 07847 358
- --B103090506 Honthly operating rept for Feb 1981 BALLINGER, P. L. Nebraska Public Power District 81/03/02 Spp. 07847 359
- 8103260167 Forwards "NE Public Power District.Cooper Nuclear Station Annual Environ Operating Rept. Vol II - Radiological Environ Radiation Monitoring Program. Jan-Dec 1980." PILANT.J M. Nebraska Public Power District 81/03/13. Ip 08039.070.
- --Bi03260175 "NE Public Power District.Cooper Nuclear Station, Annual Environ Operating Rept, Vol. II - Radiological Environ Radiation Monitoring Program, Jan-Dec 1980 " MARTIN, J.D. Teledyns Isotopes, 81/03/13 92pp. 08039:071.
- B103260770 Forwards "Annual Environ Operating Rept Nonrediclogical, Jan-Dec 1980," Vol I PILANT, J H. Nebrasta Public Power District. 81/03/18. Ip. 08034-080
- --8103260775 Vol 1 to "Annual Environ Operating Rept.Nonradiological. Jan-Dat 1980 " • Natrasta Public Power District. 81/03/18. 10pp. 08036.081.
- DOCKET 90-301 POINT BEACH NUCLEAR PLANT. UNIT 2

  F. Security. medical, emergency & fire protection plans
- 8103240688 Approves 810120 request for extension of data to install amangency diesel generator remote panels for fire protection sys Fire detector installation datas seet requirements of B01021 fire protection sefety evaluation.FR notice and DENTON.H R. Office of Nuclear Reactor Regulation, Director. 81/02/13. 3pp 07982:274.
- ~-9103240702 Notice of extension until Bill17 for installation of pmergency diesel generator remote panels for fire protection tys.

  CABC.E. 0 Office of Nuclear Reactor Regulation. Director. B1/02/13. 1p. 07982-277
- 8103180264 Ltr to 411 power reactor licensees w/plants licensed prior to 790101. Forwards NRC position & request for addl info resets shutdown capability for compliance a/801119 fire protection rule EISENHUT. D. Q. Division of Licensing 81/02/20 13pp.
- B103070052 Forwards request for add1 info re security guard training & qualification.Response requested within 45 days of receipt of ltr.
  CLARK.R.A. Operating Reactors Branch 3 B1/02/23. 3pp. 07852:166.
- Bi03090546 Responds to NRC B01021 & B10122 requests for add1 info refire protection safety evaluation suppl. App R mod requirements are narrow in scope & do not assure that increased plant safety will be achieved.

  FAY. C. W. Wisconsin Electric Power Co. B1/03/02. 30pp. 07848-209.

- BIOJ31033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements W/o encl EISEMWIT.D.O Division of Licensing B1/03/05 app
- 8103100190 Forwards add1 info re sefeguerds contingency plan. Enc1 withheld tref 100FR2 790)
  RURBIEIN.S. Wisconsin Electric Pawer Co. 81/03/06 1p 07867 298
- 8103250164 Responds to util B10218 ltr re emergency response facilities at plant Requests review of proposed facilities per enci MUREG-0656 Revisions expected re functions of technical support ctr & emergency operations Pacility M/o enci. STELLO-V. Director's Office. Office of Inspection and Enforcement B1/03/16 1p. 07976 072
- --BI03250166 Summarizes comments on emergency operation facility requirements as part of overall energency preparadness upgrading Habitability requirements deemed inappropriate Suggests facility be located at site BURBIEIN.S Wisconsin Electric Power Co 81/02/18. 3pp 07994-073
- Bi03250393 Provides info re fire protection mode at facilities lives addressed water damage protection fire barriers ventilation sys control cables diesel generator air intake structure & containment bldg fire stops
  FAY.C. M. Misconsin Electric Power Co. B1/03/18. Spp. 65144 105.
- B103260697 Forwards fire protection exemption request.

  BURGIFFILE Wisconsin Electric Power Co. 81/03/18 1p. 08037:330
- --8103260667 Requests extension of schedule dates in new fire protection regulations. Requests exemption from requirement forbidding shift supervisor to belong to fire brigade Provides basis for both requests.

  BURSTEIN. S. Wisconsin Electric Power Co. 81/03/18. 9pp. 00037-331
- Bi03270430 Requests exemption from newly enacted fire protection regulations, estanding implementation dates to deleting requirement that shift supervisor must be fire brigade member. Bihedule requirements are unrealistic to unattainable. BURBTEIN.B. Wisconsin Electric Power Co. 81/03/IB 9pp. 00044-138
- 810331021B Forwards change to modified amended security plan. Continued observation program replaces medical & psychological evaluation. Encl withheld (ref IGCFR2.790)
  BURBETIN.B. Misconsin Electric Power Co. Hi/O3/24. Ip. 08079 118.
- J. Insurence & indemnity information
- BiO3160724 Forwards Endorsements & to NELIA & MAELU Binders EB-18 & 19 & XB-18 & 19 respectively DWNDAS-W J. Wisconsin Electric Power Co. 81/03/09. Spp. 07918: 299
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for DLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREO-0612. Forwards NRC position re-interim actions & request for addl info.

  EISENHUT.O. O. Division of Licensing. 80/12/22. 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLe & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREG-0737 EISENBUT. D.O. Division of Licensing. 81/01/19. dpp.
- 8103120014 Ltr to all licensess of operating plants CP holders & GL applicants except Indian Point 2 & G. Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads. EISENHUT, D. 9. Division of Licensing. 81/02/03. 6pp.
- BiO3300160 Ltr to all operating PNR licensees requesting info on auxiliary feedwater sus seismic design Forwards request for add info list of actions requested of licensees w/o seismically qualified sus & results of NRC walkdowns. EISENHUT.D.Q. Division of Licensing. BI/02/10. 13pp.
- Bi03090i35 Responds to Bi0ii6 ltr re radiological health & safety aspects concerning possible steam generator replacement. No elternatives affect kinds of routine radionuclides released. Lists estimates of occupational radiation exposure. W/o encl. CLARK/R.A. Operating Reactors Branch 3. Bi/02/ii. 3pp. 07848:291

PPLER. J G Region 3. Chicago, Office of the Director 81/02/20 07865 225 n

250024 Ltr to all power reactor licensees & license applicants re REP-0619 criteria Footnote 2 in Table 2 contains error due . Jeakage testing deletions. Licensee may submit analysis to stify use of existing low flow controller. SENHUTID Q. Division of Licensing B1/02/20. Bpp

030814 Forwards control room habitability evaluation rept in sponse to NUREO-0737. 'Clarificatin of TMI Action Plan quirements " Refs 801223 & 810109 responses. Y.C.H. Histonsin Electric Power Co. 81/02/23 15pp. 07799:188

030689 Forwards addl info for Tech Spec Change Request 2R.re App J ntainment testing requirements.per 810127 request Y.C.W. Wisconsin Electric Power Co. 81/02/25. App. 07789.129

230030 Ltr to all licensees of operating nuclear power plants & plicants for CLs (except St Lucie Units 1 & 2). Requests il revieu to determine capability to mitigate station acknot event & promptly implement emergency procedures. SENHUT. D Q Division of Licensing. Bi/02/25 3pp

100470 Discussos NUREG-0737 schadule requirements provided in censes 801223 ltr.in response to NRC request for ariffication re-accident conitoring, training for mitigating re-damage & reactor vessel level sys Y.C.W. Hisconsin Electric Power Co. 81/03/04. 2pp. 07865.068

310804 Ltr to all licensees of operating plants applicants for Ols holders of CPs forwarding SECY-Bi-119 re info necessary to tablish environ qualification of safety-related electrical uipment. SENHUT, D.O. Division of Licensing. 81/03/10. Opp.

300177 Application for amend to License DPR-27.permitting waiver of op & governor valves test for Apr 1981.Valves last tested 810308 Facility to be taken out of svc 810416 for fueling outage.Class 3 amend fee encl.
ABTEIN-8 Wisconsin Electric Power Co. 81/03/23. 2pp. 053.018.

310473 Forwards procedures for hydraulic snubber surveillance & sting-per 810313 request Y.C.W. Wisconsin Electric Power Co. 81/03/24. 1p. 08062:339

03310475 "Hydraulic Snubber Burveillance & Maint Program." \* Wisconsin Electric Power Co. 77/05/05. 7pp 08062:336.

03310479 "Unit 1 & Unit 2 Containment Hydraulic Hanger Insp." # Wisconsin Electric Power Co - 78/10/09. 7pp. 08062:343.

nspection reports. IE Bulletins & correspondence

020690 Forwards IE Insp Repts 50-266/80-23 & 50-301/80-23 on 1217-18 No noncompliance noted.

DRELLI-0. Region 3. Chicago. Reactor Construction & Engineering poort Branch. B1/01/07 2pp. 07782:035.

03020701 IE Insp Repts 50-266/80-23 & 50-301/80-23 on 801217-18 No 03020701 IE Insp Repts 50-264/80-23 & 80-301/80-23 on 8012: noncompliance noted Major areas inspected: GA/GC program. IE Bullstin 79-03A activities & review & evaluation of nondestructive examination data & repts of inservice insp WARD. K. D. Region 3. Chicago. Office of the Director. DANIELBON, D. H. Region 3. Chicago, Roactor Construction & Engineering Support Branch. 91/01/07. 5pp. 07782:037.

100605 Forwards IE Insp Repts 50-266/80-22 & 50-301/80-22 on 1201-31 & notice of violation. ISHMAN.R.F Region 3. Chicago, Reactor Operations Nuclear Support anch. 81/01/22 2pp 07862-138.

03100689 Notice of violation from insp on 801201-31. HEIBHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 01/01/22 1p. 07862:140.

Mester list of electrical equipment.component evaluation worksheets & syr condition profiles encl FAY C.W. Wisconsin Electric Power Co. 81/01/30 130pp 07979 122

- 8103020101 Forwards [E Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. KEPPLER J O Region 3. Chicago, Office of the Director. 81/02/09. 202 07787 383.
- 8103040279 Forwards IE Info Notice 81-03, "Checklist for Licensess Making Notifications of Significant Events In Accordance W/10CFRSO 72 " No written response required.
  KEPPLERLY 0 Region 3. Chicago, Office of the Director. 81/02/12. 2pp 07815 218
- 8103200039 Responds to IE Bulletim 81-01, "Burveillance of Mechanical Shubbers " Na mechanical shubbers installed on safety-related sys Safety-related shock suppressors or shubbers installed are hydraulic units.

  PAY.C.W. Historian Electric Power Co. 81/02/12. tp. 07972:075
- 8103020061 Responds to 801218 & 23 ltrs & 801224 discussion re steam apparator tube insp. Corrects Item 4 of 801218 ltr re generator tupe insp.corrects item s or dukin it reoperating conditions Results of next insp should be
  submitted for review prior to plant startup.
  CLARK.R.A. Operating Reactors Branch 3 81/02/13 3pp. 07785:022.
- 8103240214 Forwards IE losp Repts 50-266/81-01 & 50-301/81-01 on B10102-30. No noncompliance noted. 1E19HMMN R.F. Region 3. Chicago. Office of the Director. B1/02/19. 2pp 07980.240.
- --8103240226 IE Inep Repte 50-266/81-01 & 50-301/81-01 on 810102-30. No noncompliance noted Major areas inspected; followup on items of noncompliance, operational safety verification & monthly maint observation. main: Doservacion. QULDEMOND,W.O. HAGUE,R L., WARNICK,R F. Region 3: Chicago, Office of the Director - 81/02/13. 12pp. 07980:242.
- 8103110307 Provides clarification of 810105 response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment:" re instrumentation available on containment sec water piping FAY.C.W. Hisconsin Electric Power Co. 81/02/20, 2pp. 07885:188
- 8103160676 Forwards IE Info Notice 81-04, "Cracting in Mein Steam Lines." No response required. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 81/02/27, 1p. 07914:304.
- 8103170030 Forwards IE Circular 81-03, "Inoperable Beismic Monitoring Instrumentation." No response required. KEPPLER.J D. Region 3, Chicago, Office of the Director. 81/03/02. 2pp 07939:157
- 8103160888 Forwards revised IE Bulletin 81-01, "Burveillance of ivalousse remarks revised IE Bulletin 81-01. "Burveillance of Mechanical Buybbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. REPPLER, J. G. Region 3. Chicago. Diffice of the Director. 81/03/04. ip 07915-038
- 8103230823 Responds further to IE Bulletin 80-06, "Engineered Bafety Feature (EBF) Reset Controls" per NRC 810205 request. Describes control room ventilation sys mode & reset test results Relay coil added parallel to solenoid valve FAY.C.W: Wisconsin Electric Power Co. 81/03/10. 2pp. 07978:305. 2nn 07979-305
- 8103200371 Forwards IE Info Notice 81-04, "Failure of ITE Model K-600 Circuit Breater." No response required.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director. 81/03/11. 200. 07972:121.
- 8103200684 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No action required. KEPPLER.J. 9. Region 3. Chicago. Office of the Director. 81/03/13. 2pp. 07966:118.
- 8103200349 Forwards IE Info Notice 81-07, "Potential Problem W/Water-Soluble Purge Dam Matls Used During Inert Gas Welding." No response required.
  KEPPLER.J. G. Region 3, Chicago, Office of the Director. 81/03/16.
  2pp. 07966:314.

- B103260461 Forwards [E lasp Repts 50-206/B1-03 & 50-301/B1-03 on 810210-13 & notice of violation Notice of violation uithheld (ref 10CFR2 793)
  MORELIUS.C E Region 3. Chicago, Office of the Director Bi/03/16 1p 08040 032
- --B103260474 IE Insp Repts 50-206/B1-03 & 50-301/B1-03 on B10210-13
  Details withheld tref 10cr82 790;
  CREED. J. R. Region 3. Chicago, Bafeguards Branch MADEDA. T. J. Region 3. Chicago, Office of the Director 81/03/10 ip
- R Periodic operating reports & related correspondence
- 8103130288 "Semiannual Monitoring Rept. Jul-Dec 1980 " • Wiscomein Electric Power Co. 80/12/31 14pp 07907 090
- 8103390629 Forwards 'Semiannual Monitoring Rept. Jul-Dec 1930' Concerns plant releases new fuel receipts environ radiclogical monitoring & least testing of sources FAY. C. M. Histonian Electric Power Co. 81/02/27 1p 07848 239
- --Bi03090634 "Semiannuel Monitoring Rept. Jul-Dec 1980 ' Concerns plant releases.new fuel receipts.environ radiological monitoring & jest testing of sources • Mitconsin Electric Power Co 81/02/27 41pp 07848 240
- 8103100331 Forwards "Annual Results & Data Rept 1980"
  FAY.C.W. Misconsin Electric Power Co. 81/02/27 ip. 07864 225
- --B103100335 "Annual Results & Data Rept. 1980 '
  4 Historyin Electric Power Co B1/02/27 9500 07864.227
- 8103170320 Forwards monthly operating repts for Fet 1981.
  FAY.C W. Histonsin Electric Power Co. 81/03/10 1p 07923 311
- --BIG3170324 Monthly operating repts for Feb 1581 FAY, C.W. Misconsin Electric Power Co. 81/03/04 Bpp. 07923:312

#### V. Operator Elacinations

- BIOGO90570 Responds to NuREO-0737 re quellification b training of duty & call tachnical advisor Compares facility training program b inst of Nuclear Power Operations document Bections 5.0 & 5.0 Training program to be completed by 810301 FAV. CW Misconsin Electric Power Co. 81/02/26 4pp. 07850.126
- ---B103090574 "Duty Technical Advisor Training Program"

   Wisconsin Flactric Power Co. B1/02/18 10pp. 07850 130
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT. UNIT 3
  F. Security. medical, emergency & fire protection plane
- 8103180264 Ltr to all power reactor licensess w/plants licensed prior to 790101. Forwards ARC position & request for addlinfo resafe shutdown capability for compliance w/80119 fire protection rule EISE/MPVI.D.Q Division of Licensing 81/02/20. 13pp.
- B103030747 Requests delay until B10415 to respond to NRC B10130 request for addl info re safeguards contingency plan at facility.

  BAYHARD-P Y Florida Power Corp. B1/02/24. lp. 07796:077
- 8103100105 Requests that encl emergency planning into be made publicly available W/o encl SOUDER-J L. Division of Rules and Records 81/02/27. 1p. 07693-177
- 8103310339 Ltr to all licensees of operating plants & holders of CPs forwarding MUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria destribe acceptable method for meeting NRC requirements M/o sncl EISENHUT.D.O. Division of Licensing 81/03/05 app
- B103120B11 Forwards request for add1 info re 770B17 physical security, training & qualification plan. Response required within 30 days. Info request withheld (ref 10CFR2 770).

  REID.R W Operating Reactors Brench 4 81/03/06 2pp. 07905-013.
- 8103230649 Forwards plan & schedule for achieving compliance w/new fire protection guidelines.

  BAYMARD PY Florida Power Corp. 81/03/19. 8pp. 07977:001.

- B103060345 Forwards Endorsement 4 to MAELV Binder XB-35 FIELDER, J Morsh & McLennen, Inc., H & M Nuclear Consultants, Inc DIV 81/01/28 3ap 07840 229
- BIO3110451 Forwards Endorsement 5 to MAELU Binder XB-35 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. DIV BI/03/06 3pp 97882 145
- P Operating license stage documents & correspondence

J Insurance & insumnity information

- B010230589 Surmary of B00821 meeting w/RtW reactor owners group re abnormal transient operating guidelines program VISSIND: 0 Operating Reactors Branch 4 B0/09/30 29pp
- 8103190732 Ltrs to all licensues of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NAREG-0612 Forwards NRC position re interim actions t request for add info EISCH-UT.D Q Division of Licensing 80/12/22 30pp
- BID1150319 Discusses followup study re degradation of internal apportenances in LWR piping during normal plant operation & potential effects when degraded apportenances are subj to accident loads Recommends broad review of recurrent problems BROWN.E.J. Director's Office BO/12/24 App
- B1031903B7 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown, replacement parts & MUREO-0737 FIRENWUT, D 0 Division of Licensing B1701/19. App.
- 8103120014 Ltr to all licensees of operating plants.CP holders & GL applicants.ercept indian Point 2 & 3.2ion 1 & 2 & TMI-1. forwarding inadvertently unlitted pages from NRC 801222 request for addl info re control of heavy loads FIGERINUT,D & Division of Licensing 81/02/03 & pp
- 8103390160 Ltr to all operating PMR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for addition its of actions requested of licensees w/o seismically qualified sys & results of NRC walldowns E18EMHUT.D Q. Division of Licensing 81/92/10, 13pp
- B103160469 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation dates will be not EJEENMIT.O.G. Division of Licensing 81/02/10 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may aubmit analysis to justify use of existing low flow controller EISENHUT.D.O Division of Licensing 81/02/20 Upp.
- 8103060300 Requests commitment to perform surveillance of fuel assembly holddown springs in core during next refueling outage & to rept any spring failures noted Commitment should be submitted within 30 days REID.R W Operating Reactors Branch 4 81/02/23 2pp 07836 354
- BIO3110423 Forwards "Partial Review Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for FL Power Corp. Crystal River Unit 3." Written response required.
  MOVAK T.M. Assistant Director for Operating Reactors BI/02/23
  3pp. 07884-029.
- --BIO3110429 "Partial Review Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for FL Power Corp.Crystal River Unit 3." # Office of Nuclear Reactor Regulation, Director B1/02/23 250p. 07884,032
- Bi03090299 Generic ltr to all B&W licensees re capability of small break LOCA model to predict small break behavior.Post-test evaluations of L-4-1 & B-07-10D prodictions requested for submittal by Bi0401 REID.R W Operating Reactors Branch 4. 81/02/24. 3pp. 07844:233
- 8103120488 Forwards 3raft environ protection plan. Amend 37 to License DPR-72 & notice of issuance & evaluability REID.R.H Operating Reactors Branch 4 81/02/29, 3pp. 07905:193
- --B103120490 Draft environ protection plan (nonrediological) for facility.
  # Florida Power Corp. 81/02/25 12pp. 07905.196.

onflict w/new EPA environ study requirements EID.R W. Operating Reactors Branch 4 81/02/29 17pp 17905-230

3120496 Natice of issuance & availability of Amond 37 to License PR-72 

30030 Ltr to all licensees of operating nuclear power plants & licents for OLs (except St Lucie. Units 1 & 2) Requests 1 review to determine capability to ritigate station chout event & promptly implement emergency procedures EIMULD 0 Division of Licensing 81/02/23 5pp.

10176 Forwards 010109 request for add1 info re 8&W 177-FA numers ups submittal on asymmetric LOCA loading Response should submitted within 60 days
D.R.W Operating Roactors Bianch 4 81/02/26 2pp 07884 290

JOBIJ Generic Ltr Bi-O6 to all CP holders & OL applicants re FRSO 71(e). "Periodic Updating of FBARs." effective 722 Info re FBAY legal status format & content encl ENNUT.O 9 Division of Licensing BI/02/26 10pp.

10781 Forwards request for addl info re NUREO-0731, Item 11 E i 2 emergency feedwater upgrade. Util must verify rated acity & design recirculation flow rate of emergency dwater pumps n.R.W

Operating Reactors Oranch 4 81/02/27 App 07877 324

20229 Ack receipt of 800211 response to 790821 info request to B&W ctor owners group Requirements of TMI Action Plan Item K. 2 19. 'Benchmark Analysis of Bequential Auxiliary dwater Flow.'' fulfills request Safety evaluation encl D.R.W. Operating Reactors Branch 3. 81/02/27. 2pp

3120245 Gafety evaluation re Item II K 2 19 "Benchmark Analysis of equential Auriljary Feedwater Flow" for D&W reactor plants ntent of Action Item II K 2 19 accomplished & results rovided by CRAFT-2 similar to TRAP-2 program Office of Nuclear Heactor Regulation, Director 81/02/27 2pp

20296 Ack receipt of 800205 response to 790821 info request to B&W ctor owners Requirements of TMI Action Plan Item K 2 19. "Jenchmark Analysis of Bequential Auriliary dwater Flow." fulfilis request Safety evoluation enci D.R W Operating Reactors Branch 3 81/02/27. 2pp

3120338 Safety evaluation to TMI Action Plan Item II K 21 19. Jizusus darety evaluation for Inf. Action Fian Item II K.21 17.
Benchmark Analysis of Sequential Auxiliary Feedwater Flou<sup>\*</sup>
or BEU plants intent of Action Iten II K.2.19 accomplished
results provided by CRAFT-2 similar to TRAP-2 program
Diffice of Nuclear Reactor Regulation. Director 81/02/27 2pp

20789 Discusses compliance w/TML Action Plan Item II K 2 19, kV/DY biscoses compliants w/HI Action Fish item II w nchmark Analysis of Sequential Ausiliary Feedwater Flow e rigorous assessment is being performed under Item K.3.30 Item is resolved Bafety evaluation enci D.R.W. Operating Reactors Dranch 4 81/02/2/ 2pp

90193 Notification of 810402-03 meeting w/8&W owners group in heada. MD to discuss responses to MRC 810109 ltr re nmetric LOCA loadings BING-O Operating Reactors Branch 4. 81/03/02. 2pp

70293 Resubmits oversize drawing re progosed alternate safe tdown capability mod Aperture card in PDR NARD.P.Y Flor(da Power Corp. 81/03/02. 1p. 07846-220

2026) Ack receipt of 800630 response to 79082% info request to D&W tor owners group. Requirements of TMI Action Plan Itam K.2.19. "Benchmark Analysis of Sequential Ausiliary Swater Flow." fulfills request Safety evaluation enci. D.R.W. Operating Reactors Branch 4. BI/03/02. 4pp.

0120270 Safety evaluation re TM1 Action Plan Itam II N.2 19. Benchmark Analysis of Sequential Auxiliary Feeduater Flow." Itah of Action Itam II.N.2 19. accomplished & results rovided by CRAFT-2 similar to TRAP-2 program Office of Nuclear Reactor Regulation. Director. 81/03/02. 2pp

50003 Forwards Tech Spec Change Request 51 Revision 2 which presedes 800423 submittal re-organizational changes. Lificate of Svc encl.
VARD.P V. Florida Power Corp. 81/03/03. App. 07837-288.

# Floride Power Corp 81/03/03 7pp 07837 294

BIO3060512 Application for amend to License DPR-72 changing Tech Boecs 103060512 Application for amend to License DPR-72 changing fect to reflect changes in offsite organization for Pacility mgt t technical support Certificate of Bvc encl. BAYNARD P y Florida Power Corp 81/03/03, 6pp 07037 280.

- --8103060514 Revised Tech Specs re facility organization
  # Florida Power Corp. 81/01/03 Pag. 07837:286
- 8103100387 Provides submittal schedules for proposed upgrade to emergency feedwater sys.NURE0-0737 Item II E 1 2 in response to NRC 810128 Itr BAYNARD.P Y Florida Power Corp. 81/03/03 2pp. 07867 247
- 8103170390 Forwards safety evaluation re TH1 Action Plan Item II K 2 19. "Benchmark Analysis of Sequential Auxiliary Feodwater Flow" for N&W reactor plants. Util found in compliance J/Item REID.R W. Operating Reactors Branch 4 81/03/04 2pp. 07925 246.
- --8103170671 Safety evaluation re TMI Action Plan Item II K 2 19. "Benchmark Analysis of Sequential Feedwater Flow" for B&W reactor plants \* Office of Nuclear Reactor Regulation, Director 81/03/04, 2pp. 07929-248
- 8103110699 Bubmits Nuclear Bafety Task Force recommendations which will be resolved in 1981 Schedule & resources estimate 1981 for resplittion of recommendations in Category 7 will be submitted by 810417 CAYNARD V Florida Power Corp 81/03/06 4pp 07885.047
- BIO3120301 Responds to NRC 810223 [tr requesting review of deficiencies (D3)[030]) Hesponds to NNC Blo23 it requesting review or deric re environ qualification of safety-related electrical equipment Continued operation is safe & warranted. PANCOCK J A Florida Power Corp. 81/03/06. 3pp. 07900.345.
- 8103310804 Ltr to all licensees of operating plants.applicants for CLs & holders of CPs forwarding BECY-BI-119 re info necessary to patablish environ qualification of safety-related electrical FISENHUL, D. O. Division of Licensing 81/03/10 Ann
- BiO3170460 Notifies that util will provide formal response to NRC BiO109 request for addl info re B&U 177-FA owners group generic submittal on asymetric LOCA loadings by Jul 1981. BAYNARD.P. y Florida Power Corp 61/03/11. 2pp. 07934 341.
- 81033(0392 Bubmits results of study conducted by util & B&W re nuclear instrumentation induced error transients induced flux measurement prior does not compromise safe operation of Facility.
  BAYNARD P. Y Florida Pawer Corp. 81/03/20. 6pp 08075.163
- 8103270684 Informs that B&W owners group submitted BAM-1311P, "Irradiation-Induced Reduction in Charpy Upper Bhelf Energy of Reactor Vessel Welds" to fulfull submittal requirements of 10CRR50.App 0 PARKER.W. O Dyke Power Co 81/03/23 ip
- --BI03270693 Forwards BAIT-1511P. Irradiation-Induced Reduction in Charpy Upper Bhelf Energy of Reactor Vessel Welds " Describes implementation predictive methodology to determine syc life of reactor vessels W/o encl TAYLOR.J H. Babtack & Wilcox Co. 81/03/12 2pp
- Q inspection reports. IE Bullatins & correspondence
- 8103060293 Forwards IE Mgt Heeting Rept 50-302/80-37 on 801030 0'REILLY.J P Region 2. Atlanta, Office of the Director. 81/01/30 lp. 07837.001
- --Bi03060303 IE Mgt Meeting Rept 50-302/80-37 on 801030 Util performance considered acceptable. Major areas discussed results of NRC evaluation of util regulatory performance as concluded in systematic assessment of licensee performance program. LEWIB.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/01/26. 9pp 07837:002.
- 8103020193 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/02/01p. 07785:301 81/02/09

- Biosovor43 Act receipt of 801205 & uncated itrs informing NRC of steps taken to correct violations noted in IE lines Rept 50-302/80-36 MARRY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/02/69 ip 07812 142
- --Bi03040747 Supply response to ARC B31112 ltr re violations moted in 1E Insp Rept 50-302/80-36 Corrective actions all plant personnel advised by mpt nend that all plant procedures shall be strictly adhered to HANCOCK J A Florida Power Corp B1/02/09 1; 07812 143
- --Bi03040752 Act receipt of B01203 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-302/80-35 Supplemental response by B10120 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B1/01/05 ip 07812 144
- ---B103040759 Responds to NRC B01112 Itr re violations noted in IE Insp. Rept 50-302760-36 Corrective actions ions survey workshoets investigated & all recoverable worksheets filed w/data sheets Personnel admonished to follow procedure HAYCOCK J.A. Florida Power Corp. 80712765 2pp. 07812 145
- --8103040762 Forwards IE Insp Rept 50-302/80-36 on 800929-1001 & notice of violation MARPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/11/12 2p 07812-147
- --8103040766 Natice of violation from insp on 600927-1001
  Region 2. Atlanta. Office of the Director 80/11/07 2pp
- --Bi03040770 IE Irsp Rept 50-302/80-36 on 800929-1001 Nonce-pliance noted failure to perform done surveillance & tendon surveillance in accordance J/procedures LENAHAN, J. Region 2. Atlanta, Office of the Biractor CON\_ON.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/11/07 opp 07812 151
- Bi03040133 Forwards |E info Notice Bi-03, "Checklist for Licensees Making Notifications of Significant Events in Accordance H/10CFR50 72 " No written response required O'REILLY,J.P. Region 2. Atlanta. Office of the Director Bi/02/12
- 8103040104 Advises that auriliary bldg fire water supply has been re-evaluated Necessary hookups for addi fire water supply line from control complex util be provided fire learnest for schedule will be determined after evaluation HANCOCK. JA florice Power Corp 81/02/13 [p 07809 295.
- --BIO3040111 Forwards JE Insp Rept 50-302/80-40 on 801202-05 No noncompliance noted MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/02/09 2pp 07809 296
- --8103040(20 IE Insp Rept 50-302/80-40 on 801202-05 No noncompliance noted Major areas inspected fire protection & prevention MILLER. W.H. Region 2. Atlanta. Office of the Director (Ghion.T.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/09 IIpp 07809 298
- 8103060247 Responds to IE Bulletin 81-01, "Burveillance of Mechanical Snubbers" No rechanical snubbers in use or planned for use at facility BAYNABD, P.Y. Florida Power Corp. 81/02/19 200 07839.313
- BAYNARD P Y. Florida Power Corp. 81/02/19 2pp. 07839.313
- 8103160722 Forwards IE Info Notice 81-04, 'Cracking in Main Steam Lines " No response required G'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/02/27 1p. 07914-105
- 0103160645 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation" No response required DiREILLY, J.P. Region 2. Atlanta. Biffice of the Director B1/03/02 tp 07917 114
- BiO3170039 Forwards revised IE Builetin Bi-O1, "Burveillance of Mechanical Snubbers," w/corrected Pages 5 t 5 Change in identification of facilities w/CPU to which builetin is applicable does not affect util requirements

  D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/03/04 ip 07939.183
- 8103160903 Ack receipt of 810225 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 50-302/80-38 LEMIS.R C. Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 81/03/09 lp. 07915 074

- --BI03160905 Responds to NRC 8(0129 ltr re-violations noted in IE Insp Rept 50-302/B0-3B Corrective actions Unusual Operating Event Rept 80-12 written evaluating incident & recommending craft improvement training HANCCCK.J A Florida Power Corp. 81/02/29 3pp. 07915 079
- --8103160907 Forwards IE Insp Rept 50-302/80-38 on 801004-1103 & notice of violation LEHIB.R C. Region 2. Atlanta. Reactor Operations Nuclear Support
- --8103160909 Notice of violation from insp on 801004-1103

  + Region 2. Atlanta. Office of the Director 81/01/07 2pp
  0.7913-080
- --8103160911 IE Insp Rept 90-302/80-38 on 801004-1103 Noncompliance noted reactor bidg purge not secured during inoperability of conitor & reactor bidg purge valves not deactivated following closure.

  STETMA.T.F., SMITH.B.W. Region 2. Atlanta, Defice of the Director. MARTIN,R.D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 81/01/07 13pp 07915-082
- 8103200278 Forwards IE Info Notice 81-05. "Failure of ITE Model K-600 Circuit Breater." No response required O'REILLY.JP Region 2. Atlanta. Office of the Director 01/03/11. 10: 07969 013
- 8103190880 Forwards IE Info Notice B1-05, 'Degraded DC Bys at Palisades," No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 61/03/13 Ip. 07965 286
- 8103310798 Ack receipt of 800225 ltr informing NRC of steps taken to correct violations noted in IE Josp Rept 50-302/80-41. LEWIS-R C Region 2. Atlanta. Office of the Director. 81/03/25. to 80802 293
- --B103310607 Forwards IE Insp Rept 50-302/80-41 on 801207-13 & notice of violation Notice of violation withheld (ref 10CFR2 790).

  KERNAR Ragion 2, Atlanta Bafeguards Branch 81/02/03 2pp 08062 294
- --8103310820 IE Insp Rept 50-302/80-41 on B01207-13. Noncompliance noted intrusion detection sys unable to detect panetration at two locations & failure to test alarm zone Details withheld iref 100FR2. 790)
  MODRE D E : HOWELL J C : MCGUIRE D R : Region 2. Atlants : Office of the Director : B1/02/02 200 08062 296
- R Periodic operating reports & related correspondence
- 8103030040 Forwards effluent & vaste disposal semiannual rept for Jul-Dec 1980 HANCOKA J. A. Florida Power Corp. 81/02/27 1p. 07790 112.
- --B103030047 Effluent & waste disposal semiannual rept for Jul-Dec 1980 \* Florida Power Corp. 81/02/28. 62pp. 07790.113
- 8103040589 Forwards 'Annual Operating Rept.1980 " Includes personnel exposure, reactor vessel math surveillance capsules, production facility changes, tests & experiments & steam generator inservice insp. B4YNARD, P. Y. Florida Power Corp. B1/02/27. 2pp. 07817:001.
- --Bi03040594 "Annual Operating Rept 1980 " includes personnel exposurereactor vessel math surveillance capsules, production facility changes, tests & experiments & steam generator (nservice insp. \* Florida Power Corp. 81/02/27 62pp. 07817:003.
- 8103230737 Forwards monthly operating rept for Feb 1981. BAYNARD P V. Florida Power Corp. 81/03/13, 2pp. 07974:157.
- --8103230739 Monthly operating rept for Feb 1981 CULVER.M.W. Florida Power Corp. 81/03/02. 4pp. 07974:189.
- B. Reportable occurrences. LERs & related correspondence
- B103060B18 RQ on B01215, while investigating source of leakage in southwest corner of plant beam. Fire Bvc Valva FBV-107 was closed for approx 2-h. Continuous fire watch was not established within 1-h. Detailed rept to follow. PQOLE.D C. Florida Power Corp. 80/12/15. 1p. 07586:001.
- B103090910 Forwards LER 81-003/01T-1.
  HANCOCK-J. A. Florida Power Corp. 81/02/27, 1p. 07845:299.

- --gj03090513 LER gj-003/017-) on 810129 containment isolation valves AHV-1C & ID found inoperable due to excessive leakage during surveillance test Caused by low ambient temp effects during purge conditions Dosign Change implemented HERNANDEZ.V.A. Florida Pouer Corp. 81/02/27 200. 07845 300
- 8103090559 Forwards LER 81-008/03L-0 HANCOCK J A Florida Power Corp. 81/03/04 1p 07845 260.
- --BI03090555 LER BI-008/03L-0 on Bi0204 during charcoal testing filter sys AMFL-2D methyl lodids removal efficiency was 92 14%. Caused by atmospheric pollutants & normal air flow Charcoal cells replaced w/new impregnated charcoal HERNAMBEZ-V A Florida Power Corp 81/03/04. 2pp. 07845 261
- 8103110551 Forwards LER 81-011/017-0 HANCOCK, J. A. Florida Power Corp. 81/03/06 1p 07875 327
- --BIO3110553 LER BI-011/01T-0: on BIO306.per IE Bulletin 79-01B.
  containment isolation valves CAV-1.3.4.9 & 126 were found
  incapable of meeting environ submergence qualification
  Caused by potential electrical short due to flooding
  LOBD.W O Floride Power Corp BI/03/06 to 07875 328
- 8103160592 Forwards LER 80-098/03L-0 HANCOCK, J. A Floride Power Corp 81/03/10 1p 07914:338
- --8103160701 LER 80-058/03L-0 on 800806. decay heat pump A discharge throttle valve would not control flow in automatic. Caused by air in controller sensing line. Sensing line vented HERNANDE?. V A Florida Power Corp 81/03/10. 2pp 07914 337
- 8103160697 Forwards LER 81-009/03L-0 HANCOCK.J A Florida Power Corp 81/03/10 1p 07914:059.
- --BIO3160707 LER BI-009/03L-0 on BIO209.RCB drain tank level indication was erratic & prevented leak rate surveillance. Caused by vapor condensation in instrument sensing lines, Lines blown down.

  HERMANDEZ-V A. Florida Power Corp. BI/03/10 2pp. 07914-060.
- 8103170971 Forwards LER 80~036/03L~1 HANCOCK, J.A. Florida Power Corp. 81/03/10 Ip. 07935.326
- --8103170576 LER 80-036/031-1 on 800827. DHV-1;1 decay heat pump D discharge throttle valve would not flow in automatic during operability of boron injection sources & pumps test 8P-320 Caused by air in sensing line Bensing line vented & checked HERMANDEZ-V. A Florida Power Corp 81/03/10 2pp 07935:32
- 8103170547 Forwards LER 81-004/03L-1 HANCOCK J A Florida Power Corp 81/03/11 1p 07933:343.
- --8103170953 LER 81-004/03.-1 on 810119, containment isolation valve CAV-2 indicated both open & closed & CAV-126 indicator failed to actuate in closed position. Cause of CAV-2 failure unknown Cause of CAV-126 failure due to defective breaker. HERNANDEZ.V A Florida Power Corp 81/03/11 2pp. 07933:344
- B103170492 Forwards LER 81-010/03L-0. HANCOCK-J. A Florida Power Corp. B1/03/13 1p 07935:259.
- --8103170486 LER Bi-010/03L-0. on Bi0217 after routine shutdown.RCB sampling revealed that dose equivalent I-131 exceeded Tach Specs Caused by leaking fuel & anticipated dose equivalent judine transient. Purification flow increased HERNANDEZ, V.A. Florida Powor Corp. 81/03/13. 14pp. 07935 260.
- 8103240539 Forwards LER 81-012/03L-0. HANCOCK.J.A Florida Power Corp 81/03/19. 1p 07984.350
- --BI03240541 LER 81-012/03L-0, on 810219. Limitorque-operated containment icolation valves MUV-260 & 261 Failed to close. Gause unknown Torque switch MUV-261 replaced & operability restored on BI0324. Investigation continuing. HCRMANDEZ, V. A. Fibrida Power Corp. B1/03/19 2pp. 07984.351.
- 8103240304 PNB-II-81-004 on 810319, thirteen individuals arrested by County Bheriff Dept in marshland vicinity of site No indication that group poses threat to site FDI investigating incident.

  TDBIN.M., MCCUIRE.D. Region 2, Atlanta, Office of the Director.
  B1/03/20. 1p 07985:333
- 8103240534 Forwards LER 81-011/01T-1.

  HANCOCK, J. A. Florida Power Corp. 81/03/20. 1p. 07984: 347

- --B103240536 LER B1-011/017-1 on B10306 containment isolation valves CAV-1.3.4.5 & 126 found incapable of meeting environ qualification during evaluation of IE Bulletin 79-018. Caused by potential electrical short due to flooding after LOCA HERNANDEZ, V A Florida Power Corp B1/03/20 2pp 07984 348
- DOCKET 59-304 ZION NUCLEAR PEHER STATION, UNIT 2

  F Security, medical, emergency & fire protection plane
- B1010B0051 Releases public version of util draft emergency plan. MRE0-0554 info encl. FELTON.J.M Division of Rules and Records 00/12/02 18pp.
- --8101230943 Forwards public version of draft emergency plan for generating stations. PEOPLES.D.L. Commonwealth Edison Co. 80/04/24. 3pp. 04837:16
- --Bi010B006B Public version of draft emergency plan for generating stations Commonwealth Edison Co. 80/07/31 150pp
- BIO1090003 Releases public version of util draft emergency plan FELTON J.M. Division of Rules and Records. 80/12/03. 1p.
- --BIO122029B Forwards public version of util revised draft emergency w/station annexes
  PERPLES D. L. Componies 1th Edison Co. BO/06/04 2nd. 05070.00
- --8101080019 Public version of Revision 1 to draft emergency plan.
  \* Commonwealth Edison Co. 80/07/31 139pp
- --8101080039 Public version of draft emergency plan annex.

  « Commonwealth Edison Co 80/07/31. 37pp 07417:294
- 8103180264 Ltr to all gower reactor licentees u/plants licensed prior to 790101. Forwards NRC position & request for add1 info re safe shutdoon capability for compliance u/B01117 fire protection rule EIEENHUT.D 0 Division of Licensing. 81/02/20. 13pp.
- Bi03310338 Ltr to all licensums of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements NI/o encl.

  EISENMUT.D.O Division of Licensing 81/03/09 App.
- Bi03260123 Concurs u/B01217 request to install two-way headset jacks specified emergency notification sys & health physics telephones provided that use will be discontinued if communications quality unacceptably degraded.

  KEPPLER, J. Q. Region 3. Chicago. Office of the Director. Bi/03/17.
- --B103260137 Submits location for installation of one-way headset jac on smergency notification sys & hoalth physics notwork per B01119 request. Requests concurrence by B1020 RAUBCH.T.J Commonwealth Edison Co. B0/12/17. 2pp
- 8100200793 Provides review of plans schedules & design descriptions of fire protection mods. Responses to open items per NRC 790101 trained. TRAFM, I R. Commonwealth Edison Co. 81/03/18 6pp 07976:347.
- 8103250685 Releases public version of implementing procedures for emergency plan. FELTON.J.M. Division of Rules and Rocords. B1/03/19. 1p
- --BI03230692 Forwards public version of emergency plan implementing procedures for corporate command ctr.environ director & plant-specific procedures DELOEDROF, L. O. Commonwealth Edison Co. 81/02/27. 2pp.
- --Bio3250702 Public version of emergency plan implementing procedures corporate command ctr.environ director & plant-specific procedures.

  + Commonwealth Edison Co. 01/02/27. 1400pp.
- Q. Adjudicatory correspondence
- 8103200781 Forwards notice of Director's decision per 2, 206 in response to 800417 patition requesting that Director of Ofco of Nuclear Reactor Regulation suspend (L. Amends 92 & 49 to Litenses DRR-37 & DPR-48, respectively.

  DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 81/02/18, 2pp.

- GS03230547 Notifies that time provided by ARC regulations re NRC review of Director's Decision (CD-81-2) in soctet has expired NRC decision declining review became final agency action on Bi0317 CHILM: SJ Office of the Secretary of the Commission Bi/03/19 to 07977 082
- 8103270721 Responds to 810218 Itr denying Pollution & Environ Problems. Inc 800417 petition to suspend Amends 52 & 49 to rerack & compact facility spent fuel pool Contends that petitions to MRC hot given due consideration 001000.0 Pollution Environmental Problems 81/03/22 App

### H General correspondence

- B103040889 Responds to B10126 request re E Tophan concern about siting of facilities near minor fault Plant designed to withstand earthquate ground motion larger than ever recorded within 200 miles of site DIRCKS.MJ Ceffice of the Executive Director for Operations B1/02/19 2pp
- --8103040999 Forwards 810109 memo re E Tophan concerns about facility location near minor geologic fault Requests response ASPIN.L. House of Rep. 81/01/26 29;

### [ Financial information

- B103310613 Forwards guarantee of payment of deferred premiums for 1981 per NRC request DITER. J. Componisalth Edison Co. 81/03/27 1p
- --BI03310520 Forwards Annual Rept for CY80 & statement of internal cash flow projected for 1981 & actual for 1980 per provisions of 10CFR140: Chapter 1. Bection 140 21 & NRC 770615 ltr NEXCN\_H H Componeed the Edison Co. 81703727 65c

### J. Insurance & indemnity information

- B1030905B1 Forwards Endorsement 5 to AELIA Sinders E8-1.E8-2.E8-3. E8-29.E8-30.E8-42.E8-43 & MAELU Binders x8-1.x8-2.x8-3. x8-29, x8-30.x8-42.x8-43 GSTER.J Comported the Edison Co 81/03/02 15pp
- P. Operating license stage documents & correspondence
- Bi03190732 Line to all licensess of operating plants, applicants for OLs & holders of CPs to control of heavy loads, Requests review per guidelines in NUREO-O612 Forwards NRC position reinteria actions & request for addl info EISENHUT.D O Division of Licensing B0/12/22 30pp
- BIO31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPS reprogram for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown replacement parts & NUREO-0737. EISENNYT. D 0 Division of Licensing 81/01/19 App.
- 8103100105 "Safety Evaluation of Inservice Testing Program for Pumps & Valves at 7ion Units 1 % 2 for Period 780117-790916."
  ROCKHOLD.H C . FEHRINGER.J M EGGO Idebo. Inc. FIN A-6258.
  810310010016 81/01/31 60pp 07835 136
- Bio3120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.2ion 1 & 2 & IMI-1, forwarding inadvertantly omitted pages from NRC 801222 request for add info re control of heavy loads.

  EIBENHUT.D 0 Division of Licensing. 81/02/03 6pp
- 8103050632 Act receipt of 810122 ltr providing add1 info requested in MRC 801120 ltr FIDRELLI.0 Region 3. Chicago: Reactor Construction & Engineering Support Branch: 81/02/09. 1p 07829 173
- --BI0305063B Forwards add1 info re testing of facility steam generator snubbers reported in B01015 ltr. TRANM.T.R. Commoπwealth Edison Co. 81/01/22 3pp. 07829 174.
- 8103300160 Ltr to all operating PMR licenses requesting info on autiliary feeduater sys seismic design Forwards request for add1 info. List of actions requested of licenses w/o seismically qualified sys & results of NRC welldowns. EIBENNUT. D. O. Division of Licensing. 81/02/10. 13pp.

- BIO3030540 Requests changes to Licenses DPR-39 & DPR-48 & Tech Spec App A to incorporate requirements for continued implementation of IMI-2 Lessons Learned Category A items Application is fee every TRAMM.T R Commonwealth Edison Co 81/02/17 4pp 07803 174
- --8103030545 lech Spec Change 81-1 to energency power supply requirements valve position indication instrumentation for inadequate core cooling & containment isolation • Componealth Elison Co 81/02/17 20pp 07803 178
- B103160567 Ltr to all operating plants & CP holders forwarding clarification of [M] Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 49 days that implementation dates will be net EISEMMUT.D 9 Division of Cicensing 81/02/18 12pp
- 8103200781 Forwards notice of Director's decision per 2.206 in response to 800417 petition requesting that Director of Ofcof Nuclear Reactor Regulation suspend OL Amende 52 & 49 to Licenses DPR-39 & DPR-48, respectively DENTON.H R Dffice of Nuclear Reactor Regulation. Director 81/02/18 2pe
- --8103290786 Notice of issuance of Director's decision under 10CFR2 205 DENTON.H R Office of Nuclear Reactor Regulation, Director 81/02/18 2pp
- --Bi03200795 Director's Decision Bi-2 denying Pollution & Environ Problems, Inc. B00417 request for immediate suspension of license to permit relacking & compaction of spent fuel pool DENION.H R. Office of Nuclear Reactor Regulation, Director, B1/02/18 1000
- --Biog200803 Initial Decision authorizing Director of Ofc of Nuclear Rector Regulation to make appropriate findings in accordance U/NRC regulations & to issue appropriate CL amond authorizing requested spent fuel sturage rack replacement LITTLE.L W. REMICK.F J. WILE.J F. Atomic Safety and Licensing Board Panel. BO/02/14 102pp.
- B103100214 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810214

  MEPPLER. J. C. Region 3. Chicago, Office of the Director 01/02/20

  Zon
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREG-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISE(HWJ.D.O Olvision of Licensing. 81/02/20 Bpp.
- 8103130073 Forwards revised Tech Spec Page 35 which contained error in original 810114 submittal u/OL Amends 60 & 57.
  VARGA-8. A Operating Reactors Branch 1. 81/02/24 2pp. 07912 017
- --8103130078 Revised Tech Spec Page 35. # Operating Reactors Branch 1. 81/02/24 ip 07912.019
- 8103230030 Ltr to all licensees of operating nuclear power plents & applicants for OLs (escept Bt Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT. D. O. Division of Licensing 81/02/25. Spp
- 8103230813 Generic Ltr B1-06 to all CP holders & DL applicants re 10CFR90.71(a). "Periodic Updaking of FBARs." effective B0D722.1nfo re FSAR legal status.format & content encl. EISENHUT.D O Division of Licensing. BI/O2/26.
- 8103030860 Forwards status summary for NUREO-0737 items to which util committed to respond by 810301 Long-term program under intensive internal review Program util be submitted by 810316 ABEL, J S Commonwealth Edison Co. 81/02/27. 3pp.
- B103040701 Provides written statement supporting continued safe operation re environ qualification of electrical equipment Continued operation justified ABEL, J.B. Commonwealth Edison Co. 81/02/27, 2pp. 07810 045
- 8103090593 "Evaluation of Operation of Zion Station Units 1 & 2 W/One Loop Itolated."

  LYON.R. E. E000 Idaho. Inc. FIN A-6267. 8103090593. 81/02/28. 1599. 07845-334.

0241 Submits supplemental info to 810204 transmittal re use of 1024) Submits supplemental into to Bluzue transmittal re use eithange technique for rod worth measurements Discusses ective actions for tests hot meeting design criteria renned in BiO211 t O306 itra H.T.R. Commonwealth Edison Co. Bi/O3/O5. 3pp. 07907-087

0509 Forwards Procedure TSS 13. "Tendon Burveillence Test edures." In response to NRC B01125 generic request M.T.R. Corronwealth Edison Co. B1/03/06 1p. 07930 099

170512 Procedure 168 13. "Tendon Surveillance Test Procedures "
Commonwealth Edison Co. 80/07/29 1600 07930 096

OBO4 Lir to all licensees of operating plants, applicants for Dis lders of CPs forwarding SECY-BI-119 re info necessary to biish environ qualification of safety-related electrical prent NHUT.D G Division of Licensing B1/03/10 Ann

0517 Informs NRC that util will continue to require full obj informs that that util will continue to require ation training for NRC personnel entering radiations at facilities, pending further NRC communications M.T.R. Commonwealth Edison Co. 81/03/11. 1p.

CB52 Discusses review of util B10204 request for approval of rod ange technique for rod worth measurements & B10304 add1 re remedial actions Rod exchange technique acceptable. Ided util yubmits data from first use of technique A.B A. Operating Reactors Branch 1 B1/03/12 3pp 07974 350 3pp 07974 350

0886 Forwards info & drawing re bypass & reset of engineered ty features, in response to NRC 801015 ltr Aperture card lable in PDR

Cormonwealth Edison Co 81/03/13 App 07974 071

0351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of -A.Revision 16 to 0A propram Revisions reflect ADME er addenda code changes changes made per ASME survey & lifications & corrections M. T R Communicatth Edison Co 81/03/14 10

200369 Revised abstract & Pages 2-2,4-2,4-5,7-2 & 18-2 of Revision to GA program

Commonwealth Edison Co CE-1-A RI6 81/03/16 6pp

0095 POTENTIAL GEISMIC STRUCTURAL FAILURE MODES ABSOCIATED WITH ZION NUCLEAR PLANT BELL-R D., MESLEY-D A. Laurence Livermore Laboratory, FIN 26 NUREO CR-1704. B1/03/31. 60pp Available at NTIG 26 ° 8.014

pection reparts. IE Bulletins & correspondence

0711 Responds to Buppi 3 of 1E Bulletin 79-01B. "Environ ification of Class 1E Equipment." Suppliers have been acted to pravide qualification of acoustic monitors on of B safety valves J.S. Commonwealth Edison Co. B1/02/02. 3pp.

0115 Forwards IE Circular 81-02, "Performance of NRC-Licensed viduals While on Duty." No written response required. LER.J. D. Region 3. Chicago, Office of the Director. 81/02/09.

0566 Forwards 1E Insp Repts 50-295/B0-24 \$ 50-304/B0-26 on 10-11 \$ B10122 & notice of vialation. BLLI-0. Region 3 Chicago, Reactor Construction & Engineering ort Branch B1/02/09. 2pp. 07967.036.

20056B Notice of violation from insp on B01210-11 & B10122 Repion 3. Chicago, Reactor Construction & Engineering Aport Branch G1/02/07 1p. 07967 038

200972 IE Inep Repts 50-295/80-24 & 50-304/80-26 on 801210-11 & 2009/& IE Insp Repts 50-299/80-24 & 50-304/80-26 on 901216
blt22.Noncompliance noted audit of SNEC inadequate because
failure to identify SNEC mpt exempting personnel from
quired training w/o written justification
vI.T. Region 3. Chicago. Office of the Director.
VIELBON.D.H. Region 3. Chicago. Reactor Construction &
pineering Support Branch 81/01/30. 8pp. 07967:039.

0251 Forwards IE Info Notice 81-03, "Chacklist for Licensessing Notifications of Significant Events in Accordance PRSO.72 " No written response required LER.J. 9. Region 3, Chicago. Office of the Director. 81/02/12.

- BIO3160373 Forwards monthly status rept re evaluations performed in response to IE Bulletin 79-14. "Beisric Analysis for As-Built Safety-Related Piping Bys " Tables listing excessive pipe stresses enti JANECEK, R. F. Commonwealth Edison Co. 81/02/25 1p
- 8103160695 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines "No response required MIAUA, "Cracking in Main Steam Lines "No response required AEPPLER, J. G. Region J. Chicago, Défice of the Director 81/02/27 App. 07914 052
- 8103160494 Forwards IE Circular 81-03. 'Properable Beismic Monitoring Instrumentation' No response required KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/03/02 20.0
- 810317037: Responds to IE Builetin 81-01. "Gurveillance of Mechanical Snubbers." No Nuclear Safeguards Corp snubbers have been installed or util be installed on safety-related sys JANCER.R F. Commonwealth Edison Co. 81703/02 2pp.
- Bi03160894 Forwards revised IE Bulletin Bi-Oi. "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  KEPPLER, J Q Region 3, Chicago, Défice of the Director. 81/03/04.
- 8103160630 Forwards suppremental info re IE Bulletin 80-06. "Engineered Safety Feature Reset Controls " All mods completed Testing performed U/all equipment in actuated position TRAISELT R Commonwealth Edison Co. 81/03/10
- B103200394 Forwards IE Info Notice 81-06. Failure of ITE Model K-600 Circuit Breeker. No response required KEPPLER J O Region 3. Chicago. Office of the Director 81/03/11.
- 8103200699 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades "No action required.

  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/03/13.
- 8103200269 Forwards IE Info Notice 81-07. "Potential Problem H/Mater-Soluble Purge Dam Matts Used During Inert Gas Helding " No response required KEPPLER. J. G. Region 3. Chicago. Office of the Director. 81/03/16.
- R Periodic operating reports & related correspondence
- 8103020397 Forwards rept of radioactive effluents, 1980 GRAESBER, K. L. Commonwealth Edison Co. 81/02/04 tp. 07783: 073.
- --8103020404 Rept of radioactive effluents, 1980
  \* Commonwealth Edison Co 81/02/04 37pp, 07783,074.
- 8103030792 Forwards occupational radiation exposures rept for 1980. BITELLUB Commonwealth Edison Co. 81/02/25. Ip
- --8103030807 Occupational radiation exposures mept for 1980. Commonwealth Edison Co 81/02/25 3pp.
- 8103100349 Forwards monthly operating repts for Feb 1981. CRAEBBER.K.L. Commonwealth Edison Co. 81/03/09. 1p 07864: 349
- --8103100351 Monthly operating repts for Feb 1981. CODK, J. M. Commonwealth Edison Co. 81/03/05. 11pp 07864: 350
- S. Reportable occurrences. LERs & related correspondence
- 8103031014 PND-III-80-208.on 801106.main generator output breakers tripped, resulting in plant shutdown over two days. Cause not determined. Unit will be maintained in hot standby until BOILIO, pending determination of cause.

  KOHLER, J., SPEBSARD, R. L., REIMANN, F. W. Region 3, Chicago, Office of the Director. 80/11/07. 1p. 07795:266.
- 8103031073 PND-III-80-208A on 801107.Unit 2 commenced cooldown to cold shutdown resulting in plant shutdown over two days.Caused by maint on pressuring spray lines due to 801106 trip.Dutage to last at least three days.

  KDHLER, J., SPESSARD, R. L., REIMANN, P. Region 3: Chicago, Dffice of
  the Director. 80/11/07. 1p. 07795:331.

- 8103030997 PhD-111-80-235 on B31227, unit shutdown initiated resulting in outage of greater than two days Caused by maint an main condenser twise least Repairs to be completed & unit returned to svc by 801231 RETHANVLE W. MARNICKLE H. Region J. Chicago. Cffice of the Director. 80/12/29 1p 07793 265
- Biogn40445 Phg-III-B0-237 on B01225, unplanned gaseous release occurred during transfer of waste gas to holdup tank Caused by leaking valve investigation continuing LOYENDALE.P. FISHER.W. L. DAVIG.A.B. Region 3. Chicago. Office of the Oirector B0/12/29 ip 07811 353
- 8103020496 PNO-til-81-021 on 810223 received notification that OAO will begin conducting comprehensive analysis of comparative costs re upgrading sefety at utils to reduce danger to nearby gapulation cits Study will be completed in FV81 MENCZER, H B., MIND, J A. Region 3. Chicago. Office of the Director 81/02/24 20s. 07785 100
- 8103020597 PNS-III-81-004 on 810224, two equipment operators were arrested & charged w/possession &/or use of controlled substances individuals were awapeneded & access authorization to site was revoked Shift monitoring in progress MORELIUS.CE . MARABITO.R Region 3. Chicago. Office of the Director BI/02/24 1p. 07782-098

#### V Operator Elaminations

- 8103030769 Forwards supplemental into re-shift technical advisor training per NUREO-0737, item [ A 1 : (3) Into includes response to training requirements for shift control room engineers t projected exhaults for training completion.

  ABEL-J S Commonwealth Edison Co. 81/02/24. 4pp.
- B103050140 Forwards list of shift control room engineers meeting training & education requirements by dates indicated Many engineers completed training by B10101. Target date for completion of training is mid-1981 ABEL-J.S. Commonwealth Edison Co. 81/02/24. 4pp
- 8103200574 Forwards supplemental info re long-term shift technical advisor program, including candidate qualification, selection criteria, training plans & bases for phase-out of shift technical advisor program mandated by NUREO-0737.

  ABELI-J.S. Componwealth Edition Co. 81/03/17 1900

DOCKET 50-305 KEMAUNEE NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

- 8103040878 Forwards suppl fire protection safety evaluation in response to 790215, 1019 & 800416 submittals Review of remoining open items complete. Adaquately staffed & trained Pire brigade will be maintained. Sprinkler sys mode have been completed. VARQAL 8. Operating Reactors Branch 1. 81/02/13 7pp. 07812:238
- 8103180264 Ltr to all gower reactor licenses w/plants licensed prior to 790101. Forwards NRC position & request for addlineore safe shoutdown capability for compliance w/80119 fire protection rule.

  EIGENHUT.D 0 Division of Licensing. 81/02/20. 13pp
- 8103310338 Ltt to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. W/o encl. EISEMMUT.D 9. Division of Licensing. 81/03/05 App.
- 8103240370 Forwards Industrial security manual. Revision 2 Plan withheld (ref 100FR2 790) MATREMS, E. R. Misconsin Public Service Corp. 81/03/13 (p. 07986:355.
- 8103230693 Forwards revised security force training & qualification manual & responses to request for additinfo. Encl withheld (1005FR2. 790).
  MATHEMB. E. R. Misconsin Public Service Corp. 81/03/16. ip. 07973: 357.
- B103260593 Advises that dedicated shutdown capability will be tompleted within 30 months of NRC approval. Design description will be submitted by B10409 Emergency lighting w/8-h battery for all thutdown operations areas & routes will be provided. MATHEMS E. R. Misconsin Public Service Corp. 81/03/19. 2pp. 08040:331.

- P Operating license stage documents & correspondence
- BIO3193732 Ltrs to all licensees of operating plants, applicants for DLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREG-0612 Forwards NRC position re interim actions & request for add1 info EISENHUT. D. O Bivision of Licensing BO/12/22 30pp.
- BiDii50319 Discusses followed study re degradation of internal appurtenances in LWR piping during normal plant operation & potential effects when degraded appurtenances are subj to accident loads. Recommends broad review of recurrent problems BROWNE J Director's Office BO/12/24 4pp.
- BiO3190387 Ltr to all licensues of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-releted electrical aquipment Items addressed involve cold shutdown-roplacement parts & NUMEO-0737 ESENHUT.D O. Division of Licensing BI/01/19. 6pp
- BiO3120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.7ion 1 & 2 & YMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads EISENMUT.D Q Division of Licensing 81/02/03 6pp
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for addl info. list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISENHUT.D 0 Division of Licensing 81/02/10 13pp.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A.1.2 re upgrade of amergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.D 0 Division of Licensing. 81/02/18 12pp.
- 8103090137 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 KEPPLER.J. O. Region 3. Chicago. Office of the Director 81/02/20 200 07850.081
- B103250024 Ltr to all power reactor licensees & license applicants re MREO-0619 criteria Footnote 2 in Table 2 contains arror due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENHUT.D O Division of Licensing. B1/02/20. Upp.
- B103030690 Requests expedited review of Proposed Amend 40s for License OPR-43-submitted 800416.rs removal of requirement for fosm suppression sys.

  MATHEMS E. 8. Wisconsin Public Bervice Corp. B1/02/25. 2pp. 07789 127.
- Bio3230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except Bt Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blactout event & promptly implement energency procedures EISERHUT.D.O. Division of Licensing 81/02/25. Spp.
- 8103230391 Forwards Amend 31 to License DPR-43 safety evaluation & notice of issuance & availability VAROA, 8.A Operating Reactors Branch 1. 81/03/09. 2pp. 07980-341
- --8103230361 Amend 31 to License DPR-43, revising one-time extension of test frequency interval for turbine stap & governor valves from monthly to period of four months. VARQA.B.A. Operating Reactors Branch 1. B1/03/09. App. 07980-343
- --8103230365 Safety evaluation supporting Amend 31 to License DPR-43.

  \* Operating Reactors Branch 1. B1/03/09. 4pp. 07980 347
- --B103230372 Notice of issuante & eveilability of Amend 31 to License DPR-63. VARGA: 8 A. Operating Reactors Branch 1. B1/03/09. 2pp. 07980:331
- 8103170496 Notifies of change in schedule for probabilistic risk assessment study completion Datailed documentation & technical reviews will essure lesting rept significance.

  Rept availability expected in June 1981
  TRAMM.T.R. Commonwealth Edison Co. 81/03/10. 1p. 07922:065
- 8103310804 Ltr to all licensees of operating plants, applicants for ULA & holders of CPs forwarding SECV-81-117 re info paressary to

#### JOCKETED HEIMS

- 8103170525 Comments on NUREO-0737 Item 11 D 1 requirements re-relief & safety valve testing Block valve testing was not included in generic testing program EPRI relief & safety valve testing may provide valuable info re capability of valves to close MATHEMS.E R Wisconsin Public Service Corp 81/03/11 2pp 07930 118
- 8103231077 Forwards request for addl info re outstanding questions on degraded grid & adequacy of electric distribution sys voltages. Draft request for addl info re adequacy of electric distribution sys voltages also encl
- distribution sys voltages also encl vARQA.B A Operating Reactors Branch 1 81/03/13 8pp
- B103310b92 Forwards add1 info re rating valve operator at various openings Analysis indicates that valve & operator are qualified to accept LOCA induced loads four oversize drawings encl Aperture cards are available in PDR MATHEMS.E R Wisconsin Public Bervice Core B1/03/23 2700.
- 8103270726 Forwards "Reload Safety Evaluation Rewaunee Cycle 7 " MATHEMB.E R. Wisconsin Public Service Corp. 81/03/24 1p. 08035 083
- --B10327072B "Reload Safety Evaluation Kawaunes Cycle 7"

  Wisconsin Public Service Corp \* Wisconsin Power & Light Co

  Madison Cas & Flectric Co -- B1/03/18 -- 64p. 08035-084
- G inspection reports. IE Bulletins & correspondence
- B103090737 Bubmits notarization for 800923 & 1208 ltrs responding to IE Bulletin 80-11 rs masonry wall design MATHEMS.E. B. Wisconein Public Barvice Corp. 80/12/23 ip
- 8103050768 Forwards IE Insp Rept 50-305/80-28 on 801101-30 & 1201-05. No noncompliance noted HEIBHMAN.R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch BI/OI/IA 2pp 07828-096
- --Bi03030778 IE Insp Rept 50-305/80-28 on B01101-30 & 1201-05 No noncompliance noted Major areas inspected operational safety verification, monthly naint observation & LER, IE bulletin & ctrcular Patlaway NELSO's R L , FITZPATRICK, B., WARNICK, R F. Region 3, Chicago, Office of the Director B1/01/15 Spp. 07828.078.
- 8103130016 Forwards IE Insp Rept 50-305/80-29 on 801208-31 No noncompliance noted
- noncompliance noted

  HEIGHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support

  Brench. 81/01/19 2pp. 07913.016.
- --8103130021 IE Insp Rept 80-305/80-29 on 801208-31. No noncompliance noted Hajor areas inspected operational safety verification, monthly maint & surveillance observation & plant operations procedures.

  NELSON.R L , FITZPATRICK, B., WARNICK, R F Region 3, Chicago, Office of the Director. 81/01/16 Spp. 07913.019.
- 8103240556 Responds to IE Builetin 79-018. Buppi 3. "Environ Gualification of Class IE Equipment." Radiation monitoring equipment installed in auxiliary bldg to provide increased monitoring capability.
  MATHEMS.E.R. Wisconsin Public Service Corp. 81/02/02 3pp
- 8103020098 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. KEPPLER.J. 9. Region 3. Chicago. Défice of the Director. 81/02/09. 2pp. 07787:347.
- B103040264 Forwards IE Info Notice B1-03, "Checklist for Licensees Making Notifications of Bignificant Events in Accordance W/10CFR50, 72 " No written response required. KEPPLER, J. Q. Ragion 3, Chicago, Office of the Director B1/02/12, 2pp. 07813 299.
- 8103190100 Ack receipt of 810206 ltr informing N9C of steps taken to correct findings in Health Physics Appraisal Rept 50-305/80-26 KEPPLER.J.G. Region 3, Chicago, Office of the Director. 81/02/25
- --8103190110 Responds to significant appreisal findings noted in Health Physics Rept 30-305/80-26. Corrective actions: added personnel to station health physics staff & program being developed to implement svc air monitoring by 810225.

  MATHEMS.E.R. Wisconsin Public Bervice Corp. 81/02/06. Spp. 07960-228

- 8103090678 Act receipt of 810205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-25.
  NORELIUS.C E Region 3. Chicago. Diffice of the Director. \$1/02/26.
  Ip 07846 COI
- --8103090694 Respands to N9C 810121 itr re-violations noted in [E Insp. Rept 50-305/60-25 Corrective actions withheld (ref 10CFR2 790)
  MATHEMS E R Wisconsin Public Service Carp. 81/02/05. 1p. 07/46 302
- 8103160628 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines." No response required MEPPLER.J. 9 Replon 3. Chicago, Office of the Director 81/02/27. 2pp. 07917-079.
- Bio3170076 Forwards IE Circular 81-03, "Inoperable Beismic Monitoring Instrumentation" No response required KEPPLER J G Region 3. Chicago. Office of the Director. 81/03/02 2pp 07939 210
- BiO3i40BB5 Forwards revised IE Bulletin B1-01. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements MEPPLER. J 0 Region 3. Chicago. Office of the Director. B1/03/04. ip. 07915.029.
- B103170336 Responds w/proper affirmation to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys W/Loss of Offsite Power" Info submitted in 800911 ltr is correct MATHEMS.E.R. Wisconsin Public Service Corp 81/03/04 1p 67925-292.
- 8103200360 Forwards 1E Info Notice 81-06, "Failure of IYE Model K-600 Circuit Breaker" No response required KEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/03/11, 200
- 8103190185 Ack receipt of 801204,810107 to 0109 lits informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-23 All items reviewed still considered items of noncompliance KEPPLER J O. Region 3. Chicago, Office of the Director. 81/03/12 2pp. 07965-033
- --8103190191 Resubmits attachment to 810107 ltr.unitten in response to 1E lnep Rept 50-305/80-23 Typographical arrors identified in Items 1, 2 & 6 MATHEKE E. R. Wisconsin Public Service Corp. 81/01/09. App. 07985-035
- --B103190197 Responds to NRC B01113 ltr re violations noted in IE Inap Rept 50-305/B0-23 Corrective actions instrument & control personnel refreshed in cellbr methods & In performance of surveillance procedures. MATHEMS C R Misconsin Public Service Corp. B1/01/07. App. 07945-041
- --Bi03190201 Informs NRC that response to IE Insp Rept 50-305/80-23 will be submitted by Bi0107.per 801203 telcon w/B Warnick No proprietary info MATHEWS.E R Wisconsin Public Bervice Corp. B0/12/04 1p. 07965.047
- B103200776 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No action required. KEPPLER.J. O. Region 3, Chicago, Office of the Director. B1/03/13 2pp. 07966:138
- 8103231064 Responds to IE Bulletin Bi-Oj. "Burveillance of Mechanical Bnubbers." No snubbers installed in safety-related sys. MATHEMBLE R. Wisconsin Public Service Corp. 81/03/13 ip. 07976:331.
- B103200345 Forwards IE Info Notice B1-07, "Potential Problem W/Water-Soluble Purge Dam Matle Used During Inert Gas Helding." No response required.

  KEPPLER.J. 0 Region 3. Chicago, Office of the Director. B1/03/16.
  2pp. 07966:304
- R. Pariodic operating reports & related correspondence
- 8103030833 Forwards "Semiannual Effluent Release Rept. Jul-Dec 1980." MATHEMB.E.R. Wisconsin Public Service Corp. 81/02/27. ip. 07788.249
- --8103030837 "Bemtannual Effluent Release Rept. Jul-Dec 1980."

a want the contract of the con

8103180537 Forwards LERS 81-004/03L-0 & 81-005/03L-0
MATRIES E R Washington Public Power Supply System 81/03/04 IP

--BI03100340 LER BI-004/05..-O on BI0202.6HR guar IB talen out of svc for routine maint before demanstrating ocerability of RHR pump IA Caused by personnel inadvertent oversight Applicabilities of Tech Specs to be reviewed by personnel BMOXER.C 5 Washington Public Power Supply System BI/03/04 Ip 07862 312

--B103100543 LER B1-005/03--0 on B10202.1977 & 1980 containment integrated leaf rate tests not performed per Tech Specs Caused by inconsistency between Tech Specs & plant surveillance procedure. SP-56-BB. Updated LER to be submitted SCHRDCK. C. A. Mashington Public Power Supply System. B1/03/04 in 07862-313.

8103310637 Forwards LER 81-005/03L-0
MATHEMB E R Wisconsin Public Service Corp 81/03/26 1p

--Bi03310647 LER Bi-C06/OSL-O on Bi0224, transfer pump rotor 18 DA tripped on overload while attempting to recirculate boric acid storage tent B prior to sampling Caused by toric acid crystallization in pump volute during periods of non use SHOMER-C S Hisconsin Public Bervice Corp Bi/03/26 is

#### V Operator Examinations

8103130457 Updates actions in response to NUREO-0737 requirements
Reactor operators & other plant personnel are learning use
of installed equipment & sys to control or mitigate
accidents causing severe damage.
MATHEMS-E R Misconsin Public Gervice Corp 81/03/09 App
07911-340

DOCKET 50-304 PRAIRIE ISLAND NUCLEAR STATICH. UNIT 2

F. Security, medical, emergency & fire protection plans

Bi01070348 Releases public version of util upgraded emergency plan FELTON.J.M. Division of Rules and Records 80/12/01 lp. 07404 001

--BID1220991 Forwards public version of util dreft upgraded emergency plan MAYER.L. D. Northern States Power Co. BO/08/15 [p. 06372.029

--Bi01070952 Public version of upgraded emergency plan.

\* Northern States Power Co 80/08/15 105pp. 07404.002.

B101080276 Releases public version of util draft emergency plan FELTON J. M. Division of Rules and Records. B0/12/03 lp.

--BIO317000B Forwards public version of draft emergency plan. MAYER, L O Northern States Power Co. 79/12/31 ip 01693.292.

--8101080203 Public vertion of Graft emergency plan • Northern States Power Co. 79/12/31 64pp

BI03030246 Approves BI0209 request for extension of installation date of fire pump encil & related day tank curbing to BI0601.FR notice encil.

DENTON.H R. Office of Nuclear Reactor Regulation, Director.

BI020713 3pp. 07832 BI26

--8103050297 Notice of extension of installation date of fire pump encl & related day tank curbing to 810601.
CABC.E.O. Office of Nuclear Reactor Regulation, Director.
81/02/13 | p 07832.115.

8103050301 Releases public version of revised emergency plan. FELTON.J.B Division of Rules and Records 81/02/17. jp. 07806.003

---Bi03050307 Forwards public version of revised emergency response plan in response to NRC 801114 ltr. Alert & notification status rept enc! MAYER-L.O. Northern States Power Co. Bi/02/06. 3pp.

--Bi03050313 Public version of revised emergency response plan.

Northern States Power Co. 81/02/28 300pp. 07806:001.

to 790101 forwards NAC position a request for add into the safe shuttown capability for compliance u/801119 fire protection rule FISCHUT. D O Division of Licensing 81/02/20 I3pp

B103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria Josephiae acceptable method for meeting NRC requirements N/o encl EISENNUT.D O Division of Licensing 81/03/09 App

Bio3130228 Forwards Revision 3 replacement page to "Emergency Proparedness-Evacuation Time Estimates." ctd Apr 1900.per 801209 request RAYR.I. O. Morthern States Power Co. 81/03/11 1p 07907 084.

--8103130234 Revision 3 to "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant" • Northarn States Power Co - 81/03/11 2pp 07907.085

8103261052 Forwards emergency planning info for placement in LPDR W/o 8103950301 SCUDER: J.L. Division of Rules and Records 81/03/:[ ip 08940-271

8103180525 Requests extension of schedule requirements of IOCFR90. Sections 50 48 (c)(2), (c)(3), & (c)(9) re completion of App R fire protection mods MAYER.L O Northern States Power Co 81/03/13 app 07943 355

8103240354 Advises re implementation of fire protection mods not previously accepted by NRC Evaluation of energency lighting sys will be completed by Bill17 Oil collection sys mods for reactor coolant purp are scheduled after 810816 MAYER.L.O. Northern States Power Co. 81/03/19 3pp. 07990 142

#### l Financial information

B103200219 Forwards Annual Financial Ropt 1980 BRUSVEN,A D Northern States Power Co 81/03/17 40pp 07968 221

--8103200222 Annual Financial Rept 1980. MCCARTHY.D LARSON.C Northern States Power Co. 01/03/17 ip 07968:222

### J. Insurance & incomnity information

B103030730 Forwards Endorsement 4 to MAELU Binder XD-36 W/o Endorsement 4 to MAELU Binder XB-37 JOH/4060R 0 Northern States Power Ca 81/02/24 3pp 07796 057

8103170380 Forwards Endorsoment 5 to NGLIA Sinders E8-36 & E0-37 & MAELU Binders X8-37 & X8-36 MAELU Binders X8-37 & X8-37

P Operating license stage documents & correspondence

8103190732 Ltrs to all licenses of operating plants, applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re interin actions & request for addl info.
EISEINUT.D.O Division of Licensing BO/12/22 30pp

Si03190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREG-0737 EISENHUT.D Q Division of Licensing 81/01/19. 6pp

8103120014 Ltr to all licensess of operating plants CP holders & OL applicants escapt Indian Point 2 & 3. Zion 1 & 2 & TMI-1. forwarding inadvertantly omitted pages from NRC 801222 request for add info re control of heavy loads. EISENHUT, B. Q. Division of Licensing. 81/02/03 6pp.

8103300160 Ltr to all operating PRR licensees requesting info on auxiliary feedwater sys seismic design. Forwards request for add1 info.list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns. EIBENHUT, D 0 Division of Licensing. 81/02/10. 13pp.

8103160667 Ltr to all operating plants & CP holders forwarding clarification of THI Action Plan Item III.A 1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met.

EISENHUT, D. 0. Division of Licensing. 81/02/18. 12pp.

- 8103090174 Forwards organizational charts depicting NRC Region 3 heorganization.effective 810216 KEPPLER. J G Region 3. Chicago, Office of the Director 81/02/20 2pp 07892 106
- B100250024 Ltr to all power reactor licensees & license applicants ro NERCO-0619 criteria Fuotnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of oristing low flow controller EISERWAUTO O Division of Licensian B1002/20 Ann
- 8103050519 Forwards Amends 45 & 39 to Licenses DPR-42 & DPR-60.
  respectively & notice of issuance & availability.
  CLARK.R A Operating Resolves Branch 3 81/02/25 3pp 07825 052.
- --810305052? Amends 45 & 37 to Licenses DPR-42 & DPR-60 respectively, adding requirement to maintain safeguards contingency plan to be implemented within 30 days & guard training & qualification plan within 60 days
  CLARK.R A Operating Reactors Branch 3 81/02/25 4pp
  02/25 095
- --8103050932 Notice of Issuance & availability of Amends 45 & 39 to Licenses DPR-42 & DPR-60 respectively CLARK.R A Operating Reactors Branch 3. B1/02/29. 2pp 07825 059
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except Bt Lucie, Units I & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISE(IMJT, D. O Division of Licensing B1/02/25 Spp.
- 8103130140 Forwards Amends 46 & 40 to Licenses DPR-42 & DPR-60, respectively & notice of issuance & availability CLARK.A Licensing Branch 3 81/03/02 3pp 07907 298
- --UIO3130146 Amends 46 to 40 to Literaes OPR-42 to DPR-60, respectively, incorporating new requirements for instruments & equipment & shift manning, resulting from NRC assessment of IMI-2 accident CLARK-R A Operating floactors Branch 3 81/03/02 32pp 07907 301
- --8193130190 Notice of issuance & availability of Amends 46 & 40 to Licenses DPR-42 & DPR-60, respectively CLARK R A Deperating Reactors Branch 3. 81/03/02 2pp 07997 333
- 0103170158 Forwards responses to MRC BD1105 questions no fuel storage fatility mod Earlier responses were forwarded 801121.810114 \$ 0203 MAYER, L.O. Noithern States Power Co. 81/03/10 20pp 07925,274.
- B103310004 Ltr to all licensees of operating plants applicants for OLs 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.
  ETSERHUT, 0-9. Division of Licensing. B1/03/10 6pp.
- BIO3310616 Forwards RML review of util analysis of alternate safe shutdown rapability for facility, originally submitted 791022 Concurs w/BML conclusion that proposed mods do not meet /IRC criteria CLARK.R.A. Operating Reactors Branch 3 81/03/23. 2pp. 08059 165.
- B103310178 Informs that implementation of NUREO-0737 post-TMI item I.C. 5 requirement.uiil be delayed until 810701 due to mpt procedures being written in series rather than in parallel. Procedures build on requirements per higher level directive. MAYER.L. Q. Northern States Power Co. 81/03/27. ip. 08062.318
- O Inspection reports. IE Bulletins & correspondence
- B103090794 Forwards IE Insp Repts 90-282/80-20 & 50-306/80-20 on 801201-31. No noncompliance noted. HEIGHMAN.R F. Region 3. Chicago. Reactor Operations Nuclear Busport Branch. 81/01/20. 2pp 07849.230.
- --Bi03090799 IE Insp Repts 50-292/80-20 & 50-306/80-20 on B01201-31 No noncompliance noted Major areas inspected plant operation, maint surveillance security & IE bulletin followup. FEIERABEND. C. D. BURDESS B. L. LITTLE, N. S. Region 3, Chicago, Diffice of the Director. B1/01/20. 1p. 07849, 232
- B103130677 Forwards IE Mgt Meeting Repts 50-263/80-21,50-282/80-21 & 50-306/80-21 on 801121 KEPPLER.J. O Region 3, Chicago, Office of the Director. B1/01/20 2pp. 07913.267.

- --8103130679 IE Mgt Meeting Ropts 50-263/80-21.50-282/80-21 & 50-308/80-21 on B01121 Areas discussed regulatory performance of activities at facilities per systematic assessment of licensee performance program HEIS-MAN.R F. Region J. Chicago, Reactor Operations Nucléar Support Branch 81/01/13 16pp 07913 269
- 8103020083 Responds to IE Bulletin 81-01 No snubbers of type describe and in wise or planned for use in safety-related sys GLIDERIS. D E Northern States Power Co. 81/02/06 2pp 07785 0a
- 8103020067 Forwards IE Circular Bi-02. 'Performance of NRC-Licensed Individuals While on Duty " No written response required MEPPLER.J O Region 3. Chicago. Office of the Director. 01/02/09 200 07787 299
- 8103040272 Forwards JE Info Notice 81-03. "Checklist for Licensees Maxing Notifications of Bignificant Events In Accordance W/10CFR50 72." No written response required. KEPPLER. J. C. Region 3. Chicago. Office of the Director. 81/02/12. 2pp. 07813-307
- B103190049 Forwards IE Insp Repts 50-202/81-02 & 50-306/81-02 on B10101-31 No noncompliance noted HEISHMAN R F Region 3. Chicago. Reactor Operations Nuclear Suppor Branch B1/02/12 2cp 07964 102
- --BiO3190038 IE Inap Repts 50-282/81-92 & 50-306/81-02 on Bi0101-31 N noncompliance noted Major areas inspected plant operation. maints surveillance, security, rediction protection & followup on 1E bulletins FEIERABEND.C D. BURGEGB.D.L. LITTLE.H S Region 3, Chicago. Office of the Director 01/02/11 App 07964 104
- B103160706 Forwards IE Info Notice B1-04. "Cracking in Main Steam Lines" No response required KEPPLER.J O Region 3. Chicago Office of the Director. B1/02/27. 2pp. 07914-075
- 8103160921 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER,J G Region 3. Chicago. Office of the Director 81/03/02 2pp 07916-318
- 8103160978 Forwards revised IE Dulletin D1-01, "Surveillance of Mechanical Snubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  KEPPLER.J. 0. Region 3. Chicago. Office of the Director. 81/03/04 ip 07915-001
- B103200381 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required KEPPLER.J O Region J. Chicago. Office of the Director. 81/03/11. 2pp 07972 133
- 8103200693 Forwards IE Info Notice 81-05. "Degraded DC Bys at Palisades" No action required. KEPPLER.J O Region 3. Chicago. Office of the Director 81/03/13. 2pp. 07966 128
- 8103200333 Forwards [E Info Notice 81-07, "Potential Problem W/Water-80luble Purge Dam Matls Used During Inert Gas Welding " No response required KEPPLER, J. V. Region 3, Chicago, Office of the Director. 81/03/16. 2pp. 07766 280.
- R Periodic operating reports & related correspondence
- 8103030565 Forwards "Annual Operating Rept.1980" Covers occupational exposure. Changes. tests & experiments & safety valve & relief valve failures & challenges MAYER.L.O. Northern States Power Co. 81/02/27. [p. 07793-215.
- --8103030575 "Annual Operating Rept.1980." Covers occupational exposu changes: tests & experiments & safety valve & relief valve failures & challenges.
  \* Northern States Power Co. 81/02/27, 12pp 07793:216.
- 8103030828 Forwards "Effluent & Waste Disposal Semiannual Rept for Ju Dec 1980." MAYER:L O Northern States Power Co. 81/02/27. 1p. 07795-177.
- --8103030835 "Effluent & Weste Disposal Semiennual Rept for Jul-Dec 1980." 
  \* Northern States Power Co 81/02/27. 9pp 07795:178.
- 8103100355 Forwards monthly operating repts for feb 1981.
  MAYER. L. D. Northern States Power Co. 81/03/09. 1p. 07864: 361.

- --BIO3100361 Monthly operating repts for Feb 1981 MUNSTAD. A Northern States Power Co 81/03/01 Bpp. 0784 CO1
- 8103270477 Forwards "Annual Radiation Environ Monitoring Program, 1980."
  WARD, E.C. Northern States Power Co. 81/03/25 ip 08043.091
- --BI03270482 "Annual Radiation Environ Monitoring Program, 1980 " HUEBNER, L. G. Maielton Environmental Sciences Corp. BI/02/26 1459 98043 992
- BiO3310209 Forwards revised Page 1 of "Effluent & Haste Disposal Semiannual Rept." reflecting correct reporting period of Jul-Dec 1980. MAYER, U. O. Northern States Power Co. 81/03/27 ip. C8062 319.
- --8:03310337 Revised Page 1 of "Effluent & Waste Disposal Semiannual Appt. Jul-Dec 1980" a Northern States Power Co 81/03/27 ip 08262 320
- S. Reportable occurrences. LERs & related correspondence
- 8103200731 Forwards LER 81-002/01T-0 MAYER, L Q Rorthern States Power Co 81/03/13 to 07967 326
- --Bi03200734 LER Bi-032/017-0 on Bi0301 during eddy current eram of steam generator tubes, tubes found legraded & defective Coursed by correction b/or fretting Defective tubes plugged HNRSTAD. A A Northern States Power Co. Bi/03/13 3pp 07967 327
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT
  F. Becurity, medical, emergency & fire protection plans
- 8103180264 Ltr to all power reactor licensess u/plants licensed prior to 790101. Forwards NRC position & request for add1 info resate shutdom capability for compliance u/801119 fire protection rule.

  EISEMHUT.D.O. Division of Licensing 81/02/20 13pp.
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements W/o encl. EISEMBUT. D. Q. Division of Licensing. 81/03/05 6pp.
- 8103100609 Requests exemption from Section III L.Paragraphs 3 & 4. of IOCFR50. 48 & IOCFR50. App R refire protection New fire protection sys has been installed Existing sys have been improved Unsite power loss due to fire is very unlitely RANDAZA, J 8 Mains Yantee Atomic Power Co. 81/03/06. 3pp 078A3.083
- 8103200120 Bubmits info re util compliance u/revised Section 10CFR50 48 to asw App R to 10CFR50 on fire protection Shift supervisor removed from fire brigade Addi emergency lights will be installed prior to 811119.

  RANDAZZAJ B. Maine Yantee Atomic Power Co. 81/03/12. 2pp. 07970.095
- 9 Adjudicatory correspondence
- BIOJOSOSTO Forwards State of ME patition to intervene in spent fuel competion proceeding SROWN.R.E. Maine. State of 81/02/26. to 07829 067
- -- 6103050577 Petition to intervene in spent fuel compaction proceeding. State of ME apposed to util application to increase spent fuel pool storage capacity. JE Tierney & RE Brown notices of appearance & Cartificate of Svc encl TIERNEY, J. E., BROWN, R. E. Maine, State of. 81/02/26, 7pp. 07899-048
- 8103030514 Notice of intent to file &/or resubmit addl specific contentions. Applicant emended proposal validates marlier unaccepted intervenor contentions & establishes basis for new contentions. Svc list included.

  MILLER, D. 8 Sentable Maine Power. 81/02/27. 2pp. 07795:332.
- 8103190527 Response in support of State of ME patition to intervene in spent fuel pool capacity expension proceeding. Interest requirements sesisfied Cartificate of Bvc encl. MCGURREN.H.J. Hearing Branch L. 81/03/18. 3pp. 07955:125.

- intent to file add1 specific contentions Interest & aspects requirements het in original 791123 petition to intervane Certificate of Svc enci MCOURER. H J Hearing Branch I 81/03/19 Spp. 07967 357
- H Congrel correspondence
- Bi03180906 Forwards itr to editor re-spent fuel rod storage at facility Supports nuclear power Opposes further granting of funds to HE Energy Committee W/o entl MARCOUXL C Affiliation Unknown 81/03/01 pp. 07994 186
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for DLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREG-0612. Forwards NNC position re interim actions & request for addl info ETSECHUT.D.9. Division of Licensing 80/12/22. 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown replacement parts & NUHEG-0737 EISENHUT.D.9 Division of Licensing 81/01/19. App.
- B103120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3.71on 1 & 2 & TMI-1. forwarding inadvertently oritted pages from NRC B01222 request for add1 info re control of heavy loads. E18ENHUT, D. Q. Division of Licensing. 81/02/03 6pp.
- 8103300160 Ltr to ail operating PWR licensees requesting info on auxiliary feedwater sys seismic design. Forwards request for addl info-list of actions requested of licensees w/o seismically qualified sys & results of MC welkdowns.
  EISENHUT.D.O. Division of Licensing. 81/02/10 IJpp
- 810316044B Application for Proposed Change 29. Suppl 2 to amend Licens DPR-36. adding Tech Specs 3.22 % 4.11 re ventilation & filter sys limiting conditions for operation & surveillance requirements, respectively RANDATA, J. B. Maine Yankee Atomic Power Co. 81/02/13 2pp 07918-204
- --Bio3i60494 Proposed Tech Specs 3 22 & 4 ii ne ventilation & filter limiting conditions for operation & surveillance requirements, respectively \* Maine Yankee Atomic Power Co. Bi/02/13 12pp. 07916:206
- Bio3160667 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Itsn III.A. 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates uill be met. EIGENMUT.0 0. Division of Licensing. Bi/O2/IB. 12pp.
- 8103290024 Ltr to all power reactor licensees & license applicants re NUREG-0419 criteria. Footnote 2 in Table 2 contains error due to lestage testing deletions. Licensee may submit analysis to justify use of existing low flow controller. EISENHULD 0 Division of Licensing. 81/02/20. 8pp.
- 8103110449 Forwards "Portial Review Equipment Evaluation Rept by Ofc Nuclear Reactor Regulation for ME Yankee Atomic Power Co." Hittsh response required NOVAK-T.M. Assistant Director for Operating Reactors. 81/02/23. 3pp
- --8103110454 "Pertial Review.Equipment Evaluation Rept by Ofc of Nucl Reactor Regulation for ME Yankee Atomic Power Co." \* Office of Nuclear Reactor Regulation, Director. 81/02/23. 25pp. 07883:329.
- 8103041013 Notification of 810303 meeting w/util in Bethesda. MD to discuss GA program & spent fuel pool capacity expansion. REGUA, 9. Operating Reactors Branch 3. 81/02/23. 2pp. 07812:020
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucia,Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. ETBENHUT.D.Q. Division of Licensing. 81/02/25. 5pp.
- B103030839 Forwards "ME Yankee Nuclear Plant Reactor Pressure Vessel Surveillance Program: Capsule 263." Rept documents results of reactor vessel wall surveillance capsule removed during refueling outage. Rept eveilable in Central Files only.
  RANDAZZA-U.B. Maine Yankee Atomic Power Co. B1/02/27. 4pp. 07830.003.

7900-253

ORDCE, R. H. Majne Yankee Atomic Power Co. 81/03/11. in 07917: 144

3120109 Notice of issuance & availability of Amend 53 to License DP-74 CLARKIR A. Operating Reactors Branch 3 81/02/27, 20g 7900 259

- 10534 Informs that deficiencies re environ qualification of ctricel equipment have been evaluated Continued safe lifty operation is assured. WISDN. U.P. Maine Yankee Atomic Power Co. 81/03/02 2pp H7: 105
- .10820 Responds to TAC 06580 request for safety evaluation of iceptibility of safety-related equipment/sys to flooding im failure of non-Category 1 selamic sys Accepts util slysis Requests util analysis re turbine bidg flooding. A9099 IA3
- 3110826 Safety evaluation supporting util analysis re susceptibility f safety-related sys to flooding from failure of nonor savely related bys to flogoling from failure of non-lategory I sys - Assistant Director for Safety Assessment. 81/03/02. 2nn

541 PPAP

- 3110840 "Technical Evaluation of Busceptibility of Safety-Related isticate Technical Caused by Failure of Non-Category 1 Sys for NE Yankee Atomic Power Station " PPS.R.C. Lewrence Livermore Laboratory. BI/02/28 16pp. 1909.167.
- 90323 Forwards "Best Estimate Post-Test Prediction for LOFT lear Experiment L3-6 " Prediction cerried out by RELAP47 3 based licensed code. Util will submit another post-test diction of LOFT L3-6 as calculated RELAPS/Modi J.J. Yankas Atomic Electric Co. B1/03/03 1p מפכ חפמכה
- 3090330 "Best Estimate Post-Test Prediction for LOFT Nuclear speriment L3-6."
  CHOR-L.: LODNIS-J.: HUSAIN-A. Yankee Atomic Electric Co.
  11/03/03 - 70pp. 07990: 230
- 60388 Discusses util position to Tech Spacs requirements & load dding reinstatement under certain conditions. Mode to be formed to reinstate emergency bus automatic load shedding ture per BIO121 schedule Burveillance tests to be done. RITY.J H. Maine Vankee Atomic Power Co. B1/03/05. 2pp. 17:345
- 80285 Forwards Amend 34 to License DPR-36 & notice of issuance & [lab[lity] RB.R.A. Operating Reactors Branch 3 B1/03/03. 3mg 07944:211
- 3180294 Amend 54 to License DPR-36, providing additions to Tech Bpec o assure that redundancy in decay heat removal capability ill be maintained in all operation modes. LARK-R. A. Operating Reactors Branch 3. 81/03/05. 9pp. 7944:214.
- 3180309 Notice of issuance & availability of Amend 54 to License PR-36 LARK.R A. Operating Reactors Branch 3. 81/03/05. 2pp. 7944:223.
- 30351 Forwards YDGAP-I-A.operational GA program.Revision 9.ra iss & responsibilities of personnel involved in ablishing & executing operational GA program.
  NSON: W P. Yankee Atomic Electric Co. 81/03/09. ip. 07907-104.
- 3130359 Operational GA program-Revision 9, re duties & esponsibilities of personnel involved in establishing & xecuting operational GA program. ARTIN.R. L., PIKE, D. B., MODOY, D. E. Yankee Atomic Electric Co. 1/03/09.
- 00400 Discusses LWR primary coalant sys pressure isolation valves. nt 5 interfacing sys LOCA caused by innseries check valve lure LOCA unitiely w/mator-operated valve in closed ition. Requests relief from certain monthly testing. DAZZA-J. B. Haine Yankee Atomic Power Co. 81/03/09. 2pp. 71:273

- 8103250302 Corrects paragraph designation 2.8(6)(e) in Amend 53 to License DPR-36 issued 810227 New paragraph designation should read 2.8 (6)(g). CLARK, R.A. Doerating Reactors Branch 3. 81/03/12 200 07999.288
- BiD3240958 Forwards applicable PWR and to NRC 201222 ltr re control of heavy loads BHR encl inadvertently transmitted.

  CLARK.R A Decreting Reactors Branch 3 81/03/13 2500
- 8103240382 Forwards errata to BCL-585-21. "M5 Yankee Nuclear Plant Reactor Pressure Vesset Surveillance Program Capsule 263 " RANDAZZA, J. B. Haine Yankee Atomic Power Co. 81/03/17. 1p. 07987: 737
- --B103240399 Errata to "ME Yankee Nuclear Plant Reactor Pressure Vescal Surveillance Program Capsule 263 PERRINJ. B Battelle Hemorial Institute, Columbus Laboratories BCL-985-21 ERR B1/03/17 7pp. 07987.336.
- 8103260025 Notifies that 770918 & 29 submittals re-modified spent fuel pin storage reviewed. Requests addl Info within 30 days CLARK.R.A. Operating Reactors Branch 3. 81/03/17. 10pp. 08042.110.
- 8103261189 Forwards corrected Pages 4.1-11,4.1-12 & 3 3-2 to Tech Apecs, reflecting changes made by Amends 82,93 & 94 to License DPR-36. CLARK.R.A. Operating Reactors Branch 3 81/03/19, 2pg 08035:294.
- --8103261176 Corrected Pages 4 1-11.4 1-12 & 3.3-2, reflecting changes made by Amends 52.53 & 34 to License DPR-36.

  \*\*Operating Reactors Branch 3. D1/03/179. 3pp. 08035:276
- 8103310226 Forwards "Best Estimate Post-Test Prediction for LOFT Nuclear Experiment L3-6 (RELAPS/Mod1 Predictions)." MAY, J.A. Yankee Atomic Electric Co. 81/03/20. 1o. 08040:143.
- --8103310231 "Dest Estimate Post-Test Prediction for LOFT Nuclear Esperiment L3-6 (RELAPS/Mod1 Predictions)." HUBAIN.A., LUDMIB.J. 8CHOR.L. Yenise Atomic Electric Co. 81/03/20 88pp. 08060:144
- 8103310246 Responds to NRC 810123 ltr re inability to verify appropriateness of atmospheric dispersion factor used to assess fuel handling accident inside containment.BKIRON code application & factor celculation documentation enci.
  OARRITY.J. H. Maine Yankes Atomic Power Co. 81/03/24. 2pp.
- --Bi03010257 "SkiRON: Computer Code for Determining Atmospheric Dispersion Conditions for DBA Evaluations." One-hour extusion area boundary X/O at 0.5% exceedance probability developed from site meteorological data for Jan-Dec 1977 encl.
  HAMAUI.J.N., LAZNOW.J., LITTLEFIELD.P. Yankee Atomic Electric Co. YAEC-1138 77/10/31. 200pp
- BI03310407 Advises that investigation of three specimens of federally endangered shortnose sturgeon taken from intake trash racks during 1980 has been completed. Add1 monitoring requirements not necessary. Requests not
- Q. Inspection reports: IE Bulletins & correspondence
- 8103040220 Forwards IE Info Notice 81-03, "Chacklist for Licensees Haking Notifications of Bignificant Events In Accordance W/100FR80.72. "Na written response required. ORIER.B.H Region I. Philadelphia. Office of the Director. 81/02/12. ip. 07813:183
- 8103200176 Forwards IE Info Notice 81-04, "Cracking in Main Steam Clines." No response required.

  QRIER.B.H. Region 1 Philadelphia, Office of the Director.
  B1/02/27. tp. 07972:020.
- 8103200135 Forwards IE Circular 81-03, "Inoperable Belamic Monitoring Instrumentation," No written response required. ORIER.B.H. Region 1. Philadelphia, Office of the Director. 81/03/02. 1p. 07971-343.

- BIOLEGOIOS Furmands revised If Biolistin Ol-Cir "Borveillance of Mechanical Goodses" o/corrected Pages 5 & 6 Change in identification of Parillites w/CP to which buildfin is applicable dose not affect util requirements CREER, D H. Region 5 Philadelphia. Office of the Director III/03/04 ip 0/969.C60
- #HOMA60505 Clarifies response to 11 Bulletin 80.06. "Engineeral Mafety Feature (ESF) Reset Controls." per INC request Auxillary relays will be installed to modify control circuitry for specified valves.

  GRUCCER 14 Maine Variee Atomic Four Co. 111703/09 4pp (1771) 151
- HI03200207 Forwards It. Info Notice B1-06: 'Failure of IIE Model B-800 Circuit Breater' ' No response required G1ENEB H Hegion 1. Philadelphia, Office of the Director 61703711 | 19 07969-069
- HID/310194 Forwards ME Vankes inservice thap program Revision 1 re complex ting per 100709 lequest.

  OARRITY.J H. Mains Annes Atomic Phose Co. B1709725 Ip
  - U10 PRIO200 ME Vanker inservice insp program. Revision I. re pump & valve testing GPEED.L. J. WOUD.E. JANDULPH.J.D. Mains Yanker Atomic Power Co U1702/24 77pp
- R Periodic operating reports & related correspondence
- RIGHTORIF Forwards discharge monitoring rept for Jan 1981 its in Hi.
  Dapt of Environ Protection encl
  QARRITY of H. Haine Yankse Atheric Power Co. 01/00/04 Jpp
  0/861-027
- HEODIODED Discharge constanting rept for Jan 1981 Haine Yenkee Atomic Power Co. 01/02/12 Sno. 0/883 229
- DIGGEROSSY Forwards discharge continuing maps for heb 1701 Lie forwarding maps to Giate of MC encl GAMERTY J M Maine Vanies Atomic Pawer Co - 01/03/16 - 2pp.
- -- MIO3100590 Discharge monitoring mept for Feb 1981 FLANDERS, R. Maine Vankee Atomic Power Co. U1/03/16 Spp.
- 6 Reportable occurrences, IRRs & related correspondence
- Dio3100248 RP 01-001/017-0 following Cycle 4/5 refueling outage, analysis of reactor vessel wall surveillance cepsule indicated vessel wall fluence approx 2 3 times greater than predicted Cause int stated Tach Bosc Change being prepared MOMONE C. Mains Varies Atomic Power Co. 41/702/13 2pp 0750/, 001
- --Elio2040619 LER III-001/017-0 on 400007-discrepancy found in comparison of results of RCS less test Caused by difference in calculation programs Afor errors in uniginal methodology. Tech Gpec rod being prepared.

  ANDCROWN II. Maine Vanise Atomic Power Co. 81/02/24. App. 07017-081
- #103050624 PND-1-U1-0RY. on U10227, security guards went on strike, because of inability to negotiate acceptable contract w/ explorer Liceruses has implemented strike contingency plans. Blate of HE has been notified.
  LAUUN.R H , KEINIO.R R., CEVLIN.J. N. Region 1, Philadelphia, Office of the Director 31/02/27, 2pp. 07926-240
- U103100412 PRO-1-81-031 on 810303, switchboard operator received talephone message to threat of sabotage. Search of factifity the re-identification of onesite personnel was performed FBI has been informed. Info assessment team & State of MC notified MADDEN.M.J. KIDIEN.H.B.B. DEVLIN.J. Region 1, Philadelphia, Office of the Utentin (11/03/03 2pp. 97865-209.
- E103230684 PNS-1-81-007 on 810316, senior reactor operator proceeded to controlled area w/o showing proper identification Operator had left identification in control room earlier that day. SHETLAND. P., VALLO, R. M., PROUNTER, E. J. Region 1, Philadelphia, Office of the Director 81703717 ip 07973 353

- V. Operator traminations
- DECKET 50-311 BALLY AUCLIAN GEGERATING STATION, UNIT 2
- I NAC Safety Evaluation Separt (SER), supple & correspondence
- 0103030575 MARCIY LVALUATIES REPORT RELATED TO THE OPERATION OF DALF MARCEAR GREATING BIATION USITY DESCRIPTION OF DALF Hervice Electric and Oas Company, et al.) \* Office of Nuclear Ewactor Reguletion, Director NUMBER 0517 HOS RESOLUTE 17036 AVAILABLE ARTIU \$5.00 02793,305
- F. Becurity, modical, emorgency & fire protection plane
- #1010/0330 Releases public version of util emergency plan FELTON J H. Division of Relea and Records 100/12/01 ip 0200-1200
  - 0101.22062) forwards public version of energency plan CEURIZZES P. Hobbic Bervice Lieutric & Gas Go. of Now Jersey 109/07/17. Ip. 06/17/2005
- HED1970377 Public votation of emergency plan

  R Public Dervice Liertric & Quarto of New Jersey HOZDZZI2
  300pp 02401 229
- IND 3030ETh Reteases public version of emergency plan for facility III TDN-J.R. Division of Rules and Records. Hi2027[7] ip
- BIOTOSD344 Forwards public version of nevised energency plan, in response to NIC request for add fine.
   BITTLE L. Public Gervice Liettric & dee Co. of New Jersey BITOTOS. App. 07(BIO 00)
  - 810:1083/151 Public version of revised emergency plan # Public Bervice Flectric 6 Oas Co. of New Jersey | HIZDIZTO Supp. 07002-001.
- HIGHHORM Lit to all power reactor licensees w/plants licensed peto to 2000% browneds RMC position is request for addition resease shutdown capability for compliance w/HULITY fire protection rule. EIGENUULD 2 Division of Licensing HI/02/20 Lipp
- Ut03100000 Requests that encl emergency planning info be made public available U/o 0100100022 UK00000: It. Division of Rules and Records (HI/OD/27) to 07000 169
- DIGTIO0095 Requests that encl emergency planning tith be made public available the Higgiround GOUDER, J. E. Division of Rules and Records HIGG/2/27 to
- 07053-171
- 810316330 it to all licenses of operating plants & holders of CPs forwarding NUBEG-0696. "Functional Criteria for Imergency Hesponse Facilities." Criteria describe acceptable method for masting NRC requirements M/o sucl Electrol. D O Division of Licensing. U1/03/05. App.
- B103261057 Forwards emergency planning into for placement in LPDN 97-B103050344 BBUDDRAJI. Division of Rules and Records B1703711 ip 08040-270
- 0103170271 Porwards Bubmittal 2 of security training & qualification plan. Plan withheld tref 100882 790; UNERITS.R A Public Service Electric & Gas Co of New Jersey 01/03/43 ip 07939 213
- G103240604 Discusses evaluation of B01031 fire test rept. "Cable Tra Fire Test - 3M Fire Barrier Gys " Bys exhibits equivalent or better characteristics than Kapupol & can provide acceptable fire barrier for cable trays & cables TEDEBCO.R L. Assistant Director for Licenting G1/03/10 2pp 07789 190
- 8103230713 Bubmits info to fire protection program backfit item compliance w/10CFR50.App R
  HITTLER L. Public Bervice Electric & Oae Co. of New Jersey
  81/03/19 ipp. 07977.344

B103310351 Forwards revised pages for security training & qualification plan Encl withheld (ref 10CFR2 790)
UDERITZER A Public Service Electric & Gas Co of New Jersey
B1/03/24 1p 08079 150

#### H General correspondence

- BIO3110353 Responds to BI0202 request for info re efforts to expedituationsing of constructed nuclear plants Significant portion of NRC efforts contributed to lessons learned from TMI-2 Facility license delayed by emergency plan status. DIRCK6.W J. Office of the Executive Director for Operations BI/03/03 2pp 07885 190
- --BIO3110364 Forwards JV Heimark BIO104 ltr urging expeditious licensing of constructed nuclear plants & further efforts toward solving waste disposal problem BRADLEY. B Senate BI/02/02 2pp 07683 192.
- B103310419 Forwards NUREO-0517.0578.0694.0737.1005R50 App E.NRC B10114 meeting transcript.FEMS B10205 itr & NRC B10205 memo.ppr recent telcon request W/o encl MIRAGOLIA.F J Liconsing Branch 3 81/03/24 to 08059 301
- f Financial information
- 8103170984 Forwards Annual Financial Rept 1980. BRADLEV.E.J. Philadelphia Electric Co. 81/03/13. 700.
- --8103170606 Annual Financial Rept 1980.

  \* Philadelphia Electric Co. 81/03/13 46pp
- --8103170616 Annual Financial Rept 1980 \* Atlantic Electric of New Jersey 81/03/13 4000
- --8103170426 Annual Financial Rept 1980.

  \* Delmarva Power & Light Co. 81703706 40pp
- J Insurance & indomnity information
- 8103060362 Forwards Endorsement 3 to MAELU Binder XB-60 & Endorsement 3 to MAELU Binder XB-72 CORREAM A Marsh & McLennan.inc. H & M Nuclear Consultants.inc. Div. 91/01/27 Spp 07840.233
- 8103060513 Forwards Endorsement 43 to NELIA Policy NF-230 CORREAM A Marsh & McLennan Inc., M & H Muclear Consultants, Inc Div 81/02/23 2pp. 07806 228
- Bi03090607 Forwards Endorsements 6 & 4 to NELIA Binders EB-60 & EB-72, respectively

  CORREA-M A Public Service Electric & Oas Co. of New Jersey.

  Bi/02/27. 3pp 07844:151.
- B103110712 Forwards Endorsement 6 to MAELU Binder XB-60 & Endorsement 4 to MAELU Binder XB-72 CORREAM A Marsh & McLennan, Inc., M & M Nuclear Consultants, Enc. Div. 81/03/06 3pp 07885.126.
- P. Operating license stage documents & correspondence
- 8103110373 Informs that 8-3 mercative currently used in OL issuances may have to be modified, based on forwarded memo W/o encl.
  MIRAOLIA.F. J. Licensing Branch 3 80/12/19. Ip. 07884-143.
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREQ-Obl2, Forwards NRC position re-interim actions & request for addl info EISENHUT. D. Q. Division of Licensing 80/12/22. 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safeky-related electrical equipment Items addressed involve cold shutdown, replacement parts & NUREO-0737. EISEMHUTD Q. Division of Licensing. 81/01/19 App.
- B103120014 Ltr to all licensees of operating plants CP holders & OL applicants except Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding (nadvertently untited pages from NRC 801222 request for addl info re control of heavy loads.

  EISENHUT D. O Division of Licensing. 81/02/03. 6pp.

- B103300160 Ltr to all operating PWR licensees requesting info on auxiliary feeduater sys skismic design Forwards request for add info. list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns.

  EISENWO7-0-9 Division of Licensing 81/02/10 13pp.
- BIO3160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of smergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENMUT-D 9 Division of Licensing 81/02/18 12pp
- B103290024 Ltr to all power reactor licensees & license applicants of NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  E15ENMUT.D.O Division of Licensing. 81/02/20. 8pp.
- B103060439 Requests add1 payment re B01120 application for organizational changes to Tech Spece. Class III fee required for Unit I HILLER.W O. License Fee Management Branch. 81/02/23 1p 07839 249
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs lexcept 6t Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures ETSENHUT.D 9 Division of Licensing. 81/02/25. 5pp.
- 8)03120845 Advises that no public ltrs or requests have been received requesting hearing on Amend 5 to License DPR-75
  KERRIDAN-J D Licensing Brench 3 8)/02/26 ip 07904.023
- --BIO3120849 Forwards Amend 5 to License DPR-75. safety evaluation & notice of issuance & availability. MIRACIAF J. Licensing Branch 3. 81/02/26. 2pp. 07904:024.
- --8103120854 Amend 5 to License DPR-75, extending license for fuel lac & low power testing. MRRAQLIA.F J. Licensing Branch 3 81/02/26 2pp 07904:026
- --8103120856 Safety evaluation supporting Amend 8 to License DPR-75.

  \* Licensing Branch 3 81/02/26 2pp 07904:028.
- --8103120858 Notice of issuance & availability of Amend 5 to License DPR-75 MIRROLIA.F J Licensing Branch 3 81/02/26. 4pp. 07904 030.
- Bi03130056 Forwards request for add1 info re QA program & NUREO-0737 requirements for Q-list update. Response should be submitted within 45 days TEDESCO. R L. Assistant Director for Licensing. B1/02/27. Spp. 07912-070
- 8103[60273 Forwards preliminary evaluation rept re environ qualification of safety-related electrical equipment, indicating potential deficiencies. TEDESCO.R L. Assistant Director for Licensing. 81/03/06. 33pp. 07921-283
- 8103[60468 Forwards add1 emend fee to cover fee discrepancy caused by reclassification of arends, per NRC 810220 ltr.

  8CHNEIDER, F. W. Public Bervice Electric & Gas Co. of New Jersey.

  81703706 1p 07917-339.
- ~-Bi0316047) Describes procedures for processing litre w/checks receiving directly by License Fee Mgt Branch D1098.8 License Fee Management Branch. 81/03/13 Ip. 07917:360.
- 8103310B04 Ltr to all licensees of operating plants applicants for Ol b holders of CPs forwarding SECY-B1-119 re info nacessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT.D Q. Division of Licensing. 81/03/10. App.
- Bio3230539 Ack receipt of Bio306 ltr re liet of identified deficience concerning environ qualification of safety-related electrical equipment Environ qualification of equipment reviewed per IE Bulletin 79-018 & NUREO-0588.

  HITTL-RL Public Service Electric & Qas Co. of New Jersey.

  Bi/03/19. 3pp. 07977:276.

301/E ( ED ) | E | 110

# Q Inspection reports. EE Bulletins & correspondence

- B103020139 Forwards |E Info Notice Bi-Oi, "Possible Failures of GE Type HFA Relays " No response required GRIER. B M Region I. Philadelphia. Office of the Director. B1/01/16 ip 07783 239
- 8100490085 Forwards IE Irap Repts 30-272/80-32 & 50-311/80-22 on 601116-1231 Ng nancompliance noted BRUNNER.E J Region I. Philadelphia, Reactor Operations Nuclear Support Branch B1/01/21, 20p. 07960 324
- --BI03190098 IE insp Repts 50-272/80-32 & 50-311/80-22 on 801116-123) No noncompliance noted Major areas inspected followup of licenses events & previous insp items.conformance w/Tech 8pecs & operating parameters & log & record reviews NCRRHQLK.L.J. HILL.W M. Region I. Philadelphia. Office of the Director KgIMIQ.R R. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 81/01/20 19pp 07980-326.
- 8103060464 Supple 790706.0924 & 1005 responses to 1E Bulletin 79-02.
  "Pipe Support Base Plate Designs Using Concrete Espansion
  Anchor Bolts "Tension & Shear loads on Hilti bolts are less
  than specified mas:
  SCHKEIDER, F. M. Public Service Electric & Qae Co. of New Jersey
  81701723 2pp 07636-030
- 8103060471 Supple 791205 response to IE Bulletin 79-02. Revision 2"Pipe Support Base Plate Designs Using Concrete Espansion
  Anchor Bolts " Further investigation revealed one support on
  Unit 1 & three safety-related supports on Unit 2
  SCHNEIDER, FM Public Service Electric 5 Das Co. of New Jersey
  81/01/23 2pp 07836 032
- Bi03100636 Immediate Action Ltr Bi-03 forwarding corrections discussed in Bi0129 telcon re violation of physical protection program Corrections withheld (ref 102FR2.790).

  ORIER.B.H Region 1. Philadelphia. Office of the Director Bi/01/30 ip 07863 028
- 8103240736 Requests extension until 810209 to respond to Suppl 3 of 1E Bulletin 79-018. "Environ Qualification of Class 1E Equipment." re equipment required to achieve 2 maintain cold shutdown UDERITZ.R A Public Service Electric & Oas Co of New Jorsey 81701/30. 2pp 07990:022
- BiO3190892 Act receipt of B01201 & 19 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-272/80-27 & 50-311/80-20
  CARLBON-R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B1/02/04. 1p
- --Bi03190903 Responds to NRC B01105 ltr re violations noted in IE Insp. Repts 50-272/80-27 & 50-311/80-20 Corrective actions: fire brigsets members trained to individual designated to perform surveillence for fire barriers to identify deficiencies. BCHMS/DERIF.M. Public Bervice Electric & Oas Co. of New Jersey. B0/12/01. 3ps.
- BIGG040183 Forwards IE Info Notice B1-03, "Checklist for Licensess Making Notifications of Significant Events In Accordance W/IOCFR50. 72. No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director. B1/02/12 ip. 07813-031
- 8103200199 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required. GRIER.8 H. Region I. Philadelphia. Office of the Director. 81/02/27. 1p 07972:040.
- 8103200208 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No written response required. ORIER.B.M. Region 1. Philadelphia. Office of the Director. 81703702 ip. 07906:197.
- 8103200095 Forwards revised IE Bulletin BI-O1, "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of factilities w/CF to which bulletin is applicable does not affect util requirements. CRIER.8. H. Region I. Philadelphia, Office of the Director. BI/O3/04. ip 07969-047.
- B103200154 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Dreater." No response required. ORIER.B.H. Region I. Philadelphia. Office of the Director. B1/03/11. ip. 07968.292.

- R Periodic operating reports & related correspondence
- 8103060547 Forwards interin 'Semiannual Radioactive Effluent Release Rept." Jul-Dec 1980 summariting liquid & gaseous releases & solid waste shipments from facility MITTL, R.L. Public Bervice Electric & Cas Co. of New Jersey B1703702. 1p. 07839:186
- --Bi03060552 "Gemiannual Radioactive Effluent Release Rept." Interim re for Jul-Dec 1980 - Public Service Electric & Cas Co of New Jersey. RERR-91 Bi/03/31 47p 07839:187

# U Congressional/Executive Correspondence

- 810324009) Forwards fourth monthly status rept to Congress for Bi0[15-02]5. Rept discusses actions taken on licensing reviews of new facilities. Rept will be amended to include add1 info requested on BI0217 XMMKRRR.C. Office of Congressional Affairs. B1/02/27 3no.
- BIO3270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce calsy in licensing process.

  HEMORIE, J M Commissioners 81/03/12 5pp

## V Operator Examinations

- BJ03230401 Forwards names of personnel for reactor operator license rensual 8 Conner.A Foshner & F Kaminski have completed all aspects of requalification program.

  SCHNEIDER.F W Public Service Electric & Oas Co. of New Jersey BJ/01/13. 4pp 07980:358
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATION OF THE BECUTITY TESTING THE PROTECTION Plans
- B103040129 Responds to B01002 ltr re IRC response team role at emergency facilities during energency situations as cited in NUREG-0679 Roles very from entitoring & advisement to response direction & regt control.

  REID-R W Upersting Reactors Branch 4. B1/02/19. 3pp. 07809.309
- 8103060366 Responds to util 801117 ltr requesting comments on proposed use of City Hall & Community Ctr in Oalt-CA as emergency operation facility Location is acceptable. No special protection factors are required REID.R W Operating Reactors Branch 4. BI/02/20. 4pp. 07840 296
- 8103180264 Ltr to all power reactor licenses w/plants licensed prior to 79010} Forwards NRC position & request for add1 info reseafe shutdown capability for compliance w/801117 fire protection rule.
  EISENHUT.D 0 Division of Licensing 81/02/20 13pp.
- 8103090102 Informs that facility has been identified by IAEA under Article 37 (b) of US/IAEA Safeguards Agreement for application of IAEA safeguards. Requests inventory rept & subsequent accounting repts 008 telegram encl. EISENHUT.D.O. Division of Licensing. 81/02/23 7pp. 07852:124.
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. H/o encl.

  816ENHUT. D. Q. Division of Licensing. B1/03/05 App.
- 8103240417 Discusses util plans for implementing App R requirements to 10CFR30 re fire protection program for nuclear power facilities operating prior to 790101 in response to NRC 810220 request Reassessment of each fire era encl. MATTIMELJ.J. Bacramento Municipal Utility District. 81/03/17. 9pp. 07970:170.
- --BI03240419 "Cerenic Fiber Blanket Wrap for Fire Protection of Cable Trays & Condusts."
  CHATILLE-C.E. Betrock & Wilcox Co. REIMAN.R.J. Cincinnati Ges & Electric Co. B1/03/17. 10pp.
- 8103270519 Submits info re physical security plan. Details withheld (ref 10crR2 790).

  WALBRIDGE. W.C. Sacramento Municipal Utility District. 81/03/20.
  19 08034:134.

# DOCKETED ITEMS

07802.337

- 1 Financial information
- 8103120391 Forwards util CYBL cash flow projections, net revenue budget statement, net revenue statement & BOI231 balance sheet
  Financial statement for CYBO will be mailed moon completion rinancial statement for CY80 will be mailed upon completion MATTINDE. J D. Sacramento Municipal Utility District. 81/03/05 app. 07905 004
- J Insurance & indomnity information
- 8103110362 Forwards Endorsement 37 to MAELU Policy MF-75 & Endorsement
  - 44 to ANI Policy NF-212
    MATTIMOE, J J Bacramento Municipal Utility District. 81/02/28 3pg. 07872 314
- 8103110580 Forwards Endorsement 4 to MAELU Binder X8-49 MATTIMDE, J. J. Sacramento Municipal Utility District 81/02/29 2pp. 07078 222.
- P Operating license stage documents & correspondence
- 8103090028 Forwards corrected evaluation of 800828 response to Lessons Learned Task Force Requirement 2.1 3.b re instrumentation tearned lask rotte requirement &: 1 3.0 Te instrumentation for detection of inadequate core cooling. Insufficient effort provided for advance warning for inadequate care cooling EISENHUT, D 9 Division of Licensing. 80/09/24 Upp. 07849 274
- B0102309B9 Surmary of 800B21 meeting w/B&W reactor owners group re abnormal transient operating guidelines program. vIBBINO.Q Operating Roactors Branch 4 B0/09/30 29pp.
- 8103190732 Ltrs in all licensees of operating plants applicants for OLS & holders of CPs re-control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re-interim actions & request for addl EIGENHUT, D. G. Otvisian of Licensing. 80/12/22 30pp
- Bio31903B7 Ltr to all licensees of operating plants & applicants for Ous & holders of CPs to program for environ qualification of safety-related electrical equipment litems addressed tinvolve told shutdown replacement parts & MUREO-0737. EISENHUT O O. Division of Licensing. BI/OI/19 App
- 8103120014 Ltr to all licensess of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.7 ton 1 & 2 & TMI-1, forwarding inadvortently onitted pages from NRC 801222 request for add1 info re control of heavy loads. EISENHUT, D. G. Division of Licensing. 81/02/03 App
- 8103300160 Ltr to all operating PWR licensess requesting info on auxiliary feeduater sys setsmic design. Formards requesting into auxiliary feeduater sys setsmic design. Formards request for addi info.list of actions requested of licensees w/o setsmically qualified sys & results of NRC walkdowns.
  EISENHUT.D Q. Division of Licensing. 81/02/10. 13pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A.1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be mat. EISENHUT-D.9. Division of Licensing. Bi/O2/18 12pp.
- BIO3250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENHUT. B.O. Division of Licensing 81/02/20. Spp.
- 8103030502 Forwards nonproprietary & proprietary versions of computer printouts re-updated low pressure turbine disc calculations. Change in calculating tengential stress changed critical crack site.Proprietary version withheld (ref 10CFR2 790) MATTIMOE.J.J. Barramento Municipal Utility District. 81/02/23.
- BIO3090699 Generic 1tr to all B&W licensees re capability of small break LDCA model to predict small break behavior Post-test evaluations of L-4-1 t 8-07-10D predictions requested for submittel by 810401. REID, R. W. Operating Reactors Branch 4. 81/02/24. 3pp.
- BIO3120332 Requests that util submit results of visual insp during refueling outage & rept any fuel assembly holddown epring failures REID.R.W. Operating Reactors Branch 4. B1/02/24. 3pp. 07903:339.

- 8103230030 Ltv to all licensees of operating nuclear power plants & applicants for OLs (except St Lucis, Units | & 2) Requests applicants for DLs (except Mt Lucis-Units | & 2) mequest util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT.D.O. Division of Licensing 81/02/25. Spp
- 8103040748 Discusses 801215 ltr re commitments for implementation of teems in TMf action plan Util promises to provide NRC w/detailed scope & schedule requested in NUREO-0737, by 810331 Refs Items II K 2 10 & II. K 3 30 MATTIMOE, J.J. Bacramento Municipal Utility District. 81/02/26 1p 07912 270
- 8103110644 Remits check for balance due for proposed Amend 72 to OL.in response to NRC 810211 [tr MATTINGE, J. Secramento Municipal Utility District 81/02/27 tp
- Bi03120229 Ack receipt of 800211 response to 790821 info request to B& reactor owners group Requirements of TMI Action Plan Item
  [] X 2 19. "Benchmark Analysis of Sequential Autiliary
- Feedwater Flow, "fulfills request Sefety evaluation enci.
  REID.R W Operating Reactors Branch 3 91/02/27 2pp --Biogico245 Safety evaluation re Item II.K 2.19 "Benchmark Analysis of Requential Auxiliary Feedwater Flow" for B&W reactor plants.
- provided by CRAFT-2 similar to TRAP-2 program a Office of Nuclear Reactor Regulation, Director. 91/02/27 2pp 8103120296 Ack receipt of 800209 response to 790921 info request to B& reactor owners, Requirements of TMI Action Plan Item II.K 2 19. "Benchmark Analysis of Sequential Auxiliary

Intent of Action Item II. K. 2 19 accomplished & results

Feedwater Flow, "fulfills request Safety evaluation encl REID.R W. Operating Reactors Branch 3 81/02/27. 2pp. --8103120308 Sefety ovaluation re TMI Action Plan Item II K.21.19, 'Benchmark Analysis of Bequential Auxiliary Feedwater Flow'' for B&W plants, Intent of Action Item II.K. 2 19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program.

- Office of Nuclear Reactor Regulation, Director 81/02/27

B1/02/27 200

BiO3120789 Discusses compliance w/THI Action Pien Item II K. 2 19. "Benchmerk Analysis of Sequential Auxiliary Feedwater Flow "More rigorous assessment is being performed under Item II.K. 3.30. Item is resolved. Bafety systuation ent.

REID, R W Operating Reactors Dranch 4 81/02/27. 2pp

- 0103120838 Discusses compliance w/TH1 Action Plan Item II.K.2 19.
  "Benchmark Analysis of Bequential Auriliary Feedwater Flow "
  Hore rigorous assessment is being performed under Item
  II.K.2.30. Item is resolved. Befoty evaluation encl.
- REID.R W. Operating Reactors Branch 4. 81/02/27. 3pp. 07904-036
- G103040328 Forwards Vols I & II of "Review of Recent Geologic & Seismologic Info Portinent to Beismic Bafety," in response to NRC 800414 info request Repts available in Central Filos BOBSENMAIER.W. Sacramento Municipal Utility District. 81/03/02 1p. 07830.007.
- B103090193 Notlification of B10402-03 meeting w/B&W owners group in Bethesda.MD to discuss responses to NRC 810109 ltr re asymmetric LOCA loadings VIBSING. G. Operating Reactors Branch 4. 81/03/02. 2pp.
- 8:03:20261 Ack receipt of 800630 response to 770821 info request to B& reactor owners group Requirements of TMI Action Plan Item
  II.K. 2 19. "Genchmark Analysis of Bequential Auxiliary
- Feedwater Flow, " fulfills request. Befety evaluation encl. RELD.R.W. Operating Reactors Branch 4. 81/03/02. 4pp. --8103120270 Bafety evaluation re TMI Action Plan Item II.K. 2.19, "Benchmark Analysis of Bequential Auriliary Feedwater Flow." Intent of Action Item II.K. 2.19 accomplished & results provided by CRAFT-2 similar to TRAF-2 program.

  « Office of Nuclear Reactor Regulation, Director. 81/03/02 2pp
- 8103170390 Forwards safety evaluation re TMI Action Plan Item II.K. 2 19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow" for BBN reactor plants. Util found in compliance w/item REID.R.W. Operating Reactors Branch 4. 81/03/04. 2pp.
- ~-B103170671 Bafety evaluation re TMI Action Plan Item II.K. 2.19. "Benchmark Analysis of Sequential Feeduater Flow" for DAW reactor plants.

\* Office of Nuclear Reactor Regulation, Director. 81/03/04. 2pp

- 8103110304 Responds to NRC 810122 | this requesting submittal of plan for upgrade of auxiliary feedwater sys Equipment deliver; is scheduled for Aug 1982 Final design will be submitted by Jan 1982 Juliant 1982 Juliant 1982 | Julian
- 8103310604 Ltr to all licensees of operating plents applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EIEENHUT. 0 Q Division of Licensing 81/03/10 6pp
- 8103260090 Forwards preliminary results of NRC review of environ qualification of safety-related electrical equipment at facility identified deficiencies & ranifications should be reviewed & overell findings submitted NDVAK-T H Assistant Director for Operating Reactors B1/03/17 220b 08040-038
- 8103270684 Informs that Btw owners group submitted BAM-151P.

  "Irradiation-Induced Reduction in Charpy Upper Shelf Energy of Reactor Vessel Welds" to fulfull submittal requirements of 10CFR50. App 0

  PARKER. W O Dute Power Co 81/03/23 1p.
- --8103270693 Forwards BAM-1511P. Irradiation-Induced Reduction in Charpy Upper Shelf Energy of Reactor Vessel Helds "
  Describes implementation predictive methodology to determine svc life of reactor vessels M/o enci.
  TAYLOR.J H Babcock & Wilcos CO 81/03/12 2pp.
- Q Inspection reports, IE Bulletins & correspondence
- B103030130 Forwards IE Insp Rept 50-312/60-38 on 801201-31 No noncompilance noted CREWS, J. L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch B1/01/15 2pp 07790 267
- --Bi03030134 IE Insp Rept 50-312/B0-38 on B01201-31 No nancompliance noted Major areas inspected operational safety verification, monthly eaint observation & SALP inspectivities CANTER.H L. G'ERIEN.J Region 5. San Francisco. Office of the Director FAULKENBERRY.B Region 5. San Francisco Reactor Operations Nuclear Bupport Branch 81/01/15 1095. 07790 269
- 8103050026 Forwards IE losp Rept 50-312/80-37 on 801201-05 Ma noncompliance noted SPENCER.0 B Region 5. Ben Francisco. Reactor Construction & Engineering Support Branch 81/01/16 299 07827:356
- --8103050035 IE Inep Rept 30-312/80-37 on 801201-05 No noncompliance noted. Major areas inspected: activities performed in response to IE Builletin 79-018
  ELIM-J O. Region 5. San Francisco. Défice of the Director DDDS-R.T. Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 81/01/15 3pp. 07827:358
- 8103020066 Forwards IE Circular B1-02. "Parformance of NRC-Licensed Individuals While on Duty " No written response required ENGELMEN.R H. Ragion 5. Ban Francisco, Office of the Director. 81702709 1p. 07787-255
- 8103160330 Forwards IE Info Notice 81-03 "Checklist for Licensees Making Notifications of Significant Events in Accordance W/10CFR50 72 "No response requires ENGELKEN.R H Region 5. Sen Francisco, Office of the Director. 81/02/12 | p 07922.038
- 8103040007 Act receipt of 810126 ltr informing NRC of steps taken to correct violations noted in iE Ineg Rept 50-312/80-35 Revised response acceptance limits for empty snubber reservoirs required.
  CREMB. J. L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 81/02/13. 2pp. 07815.334
- --8103040016 Responds to NRC 810108 ltr re violations noted in IE Insp. Rept 50-312/80-39 Corrective actions: bhree audits re insp. special processes & document control added & surveillance procedure re refueling outages written MATTIMOE, J. Bacramento Municipal Utility District. 81/01/26. 4pp 07815-336
- --8103040021 Forwards IE Insp Rept 50-312/80-35 on 801208-12, notice of violation to potice of deviation CREMS, J.L. Region 5, 8an Francisco, Reactor Operations Nuclear Support Branch. 81/01/08 2p. 07815:340.
- --BIO3040027 Notice of violation from insp on B01208-12 FAULKEMBERRY. B. Region 5. Gen Francisco. Office of the Director. B1/01/07. 2pp. 07815-342.

- -BIOGOGOGS Notice of the Director FAULKENBERRY, B Region 5. San Francisco. Defice of the Director BI/OI/O7 ip 07815 344
- --3103040041 IE lnsp Rept 50-312/80-33 on 801208-12 Noncompliance noted failure to audit control of processes, inservice insperocedures not properly reviewed & approved & inadequate acceptance criteria for snutter operability ZMETZIO. 3 B. Region 5, San Francisco. Office of the Director FAULKHASERRY. D. Region 5, San Francisco. Roactor Operations Nuclear Support Branch. 81/01/07 9pp. 07815.343
- R100240700 Forwards 1E loso Rept 80-312/B1-02 on B10119-23 No noncompliance noted BDOK.H E. Region 3. San Francisco. Fuel Facility & Materiale Safety Stanch B1/02/24 220 07983 234
- --8103240708 IE Insp Rept 50-312/81-02 on 810119-23 No noncompilance noted Hajor areas inspected outstanding insp followup items. esposure control, training & respiratory protection KORTH.H S. CILLIS.H. NENSLAMSKI, F.A. Region 5, Gan Francisco, Office of the Director 81/02/24 13pp 07983: 236
- 8103050540 Ack receipt of 810126 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-312/80-36. Request for withdrawal of notice of violation, item B. denied. CREUS. J. L. Region 3. San Francisco. Reactor Operations Nuclear Support Branch. 81/02/26 ip 07828.317
- ~-BI0305050 Responds to NRC Bi0109 ltr re-violations noted in IE insp Rept 30-312/E0-36 Corrective actions program developed to identify old monconformance repts for prompt closure MATTHOE.J J Secremento Municipal Utility District. Bi/01/26 2pp. 07828-318
- --Bi03050559 Forwards IE Insp Rept 50-312/80-36 on 801103-28 & natice of violation CREMB.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 81/01/07 2pp. 07828.320
- --8103050566 Natice of violation from insp on 801103-28 CREWB.J L. Region 3. San Francisco. Reactor Operations Nuclear Support Branch 81/01/08 2pp. 07828.322
- --8103050575 IE insp Rept 30-312/80-35 on 801103-28 Noncompliance noted nonconformance repts not promptly corrected & content of nonthly rept did not fulfill requirements CANIER.H.L. O'BRIEN.J P. NORTH.H.S. Region 5. Ban Francisco. Office of the Director. 81/01/08 13pp. 07028-324.
- 8103160694 Forwards IE Info Notice 81-04. 'Cracking in Main Steam Lines' No response required ENOBLKEN.R H. Region 5. San Francisco. Office of the Director B1/02/27. Ip 07914-178
- 8103170001 Faruards IE Circular 81-03, "Inoperable Saismic Monitoring Instrumentation." No response required. ENGELKEN.R. H. Region 5. San Francisco. Défice of the Director 81703702. 1p. 07939-098
- BiO3160828 Forwards revised [E Dulletin 81-01, "Surveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6 Change in identification of Parilities w/CPs to which bulletin is applicable does not affect util requirements.

  ENGELKEN,R. H. Region 5, San Francisco, Office of the Director 81/03/04. 1p. 07916:185.
- 8103180655 Ack receipt of B10212 ltr informing NRC of staps taken to correct violations noted in IE Health Physics Appraisal Rept 80-012/80-02.
  ENGELMEN.R.H Region 5. Gan Francisco, Office of the Director.
  81/03/03-0 1p. 07949:228.
- --Bi031B0662 Responds to NRC Bi0116 ltr re violations noted in IE Health Physics Appreisal Rept 50-312/B0-32 Corrective actions: check-in/check-out sys added to instrument inventory control/assigning equipment damage responsibility to user. WALBRIDGE-M.C. Bearemento Municipal Vtility District. 81/02/12 19pp. 07949-229.
- 8103260108 Responds to IE Bulletin 91-01. "Surveillance of Mechanical Snubbers." No mechanical snubbers installed on safetyrelated sys. MATTIMOE.J.J. Bacramento Municipal Utility District. 81/03/06. 1p 08042:128
- 8103180930 Ack receipt of 810227 ltr informing NRC of steps taken to correct violation noted in IE insp rept. CREWS.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. Bi/03/09. 1p. 07953:160.

- --8103180954 Add1 response to NRC B10108 ltr re 810108 notice of deviation Corrective actions Surveillance Procedure 20; 10A for safety sys hydraulic snubbers surveillance insp will be revised to clarify testing requirements MATTIMOS. J. Sacramento Hunicipal Utility District. 81/02/27 229 07953 164.
- 8103170442 Responds to 810224 request for visual inep of fuel assembly holddown springs inen procedure completes on 810332 Mines on holddown springs danage observed Fuel assemblies containing control rods precluded visual exam of springs mattliffe.j J Barramento Municipal Utility District. 81/03/11. 1p
- 8103200249 Forwards IC Info Notice 01:06. 'Failure of IYE Model x-600 Circuit Breazer' No response required ENGELKEN, R H Region 3, San Francisco, Office of the Director 81/03/11 jp 07468 337
- 0100200037 Forwards IE Info Notice 81-09. "Pegraded DC Bys at Palisades " to response required ENOELKEN.R H Region 9. 53+ Francisco. Office of the Director 81/03/13 ip 07970 073
- R Periodic operating roports & related correspondence
- B103190567 Forwards radiation exposure environ protection & effluent & waste disposal rept for 1980 MATIMOE J J Sacramento Municipal Utility District 81/02/27 ip 07955 008
- --8103190568 Rediction exposure environ protection & effluent & waste disposal rept for 1980

   Sacramento Municipal Utility District 81/02/27, 150pp 07959 009
- 8103170647 Forwards munthly operating rept for Feb 1981 ADDRIOUEZ, N J Sacramento Municipal Utility District 81/03/10 In 07939-003
- --8103170649 Monthly operating rept for Feb 1981 COLOMBD. R W Sacramento Municipal Utility District 81/03/10 6pp. 07937 004
- S Reportable occurrences. LER's % related correspondence
- 8103100960 RO on 810206 automatic initiation logic for motor-driven fire pump P-440 was defeated Caused by draining of circulating water sys & absociated intake structures to facilitate repairs Pump should be fully operable 81033i WALBRIDGE N C Sacramanto Municipal Utility District. 81/02/20 1p. 07893-153
- B103030735 Forwards LER 81-007/917-0 MATTIME.J J Gacramento Municipal Utility District B1/02/24. 2pp 07791:305
- --B103030740 LER B1-007/01T-0 on B10210 info received that certain safety-veloted instrument errors extend those assumed in FBAR analysis Possibly caused by string error discrepancies. Applicability of mothodology used in rept being reviewed CDLOMBO. R.W. Satramento Municipal Utility District 01/02/24 ip. 07791.307.
- 8103030761 Forwards LER BI-004/D3L-0 MATTIMBE J J Sacramento Municipal Utility District. 81/03/25 2pp -07791,320.
- --BIO3030766 LER BI-004/03L-O an BIO202 component cooling water isolation valve failed to close during surveillance pracedure 205.07C, isolation valve surveillance test. BFV-46204 Caused by water in air line of valve actuator Water drained.

  COLOMBO.R W. Sacramento Municipal Utility District. BI/02/25
  19. 07791-322
- 8103030815 Forwards LER 81-003/03L+0. MATTIMOE. J. Bacramento Municipal Utility District. 81/02/25. 2pp 07798-001.
- --8193030820 LER 81-003/03L-0. on 810203 during reactor bldg spray sysloop 8 BFAS tast-reactor bldg spray pump 8 started late. Caused by incorrect setting on model 628 Agastat timer Timer reset. COLDMOD.R.W. Bacramento Municipal Utility District. 81/02/25 lp. 07798-003.

- 8103040637 RO 81-010 decay neat sys A cooler bypass connection fitting noted not conforming to pipe stress requirements.per IE Bullettin 79-14 revieu Caused by analysis technique used New technique indicates connection not overstressed ROBRIQUEZ.R J Sacramenta Municipal Utility District. 81/02/26 2pp 07817 075
- BiO3130561 RO R1-012 on B10303, while performing reactor protection syscalibr. setpoints for high reactor bidg pressure were higher than allowed by Tech Specs Cause not stated Complete rept forthcoming CUSRE, R P Bacramento Municipal Utility District 81/03/04 2pp 07908 289
- 0103130584 Forwards LER 81-009/017-0 MATTIMOE. J. Sacramento Municipal Utility District. 81/03/04 2np 07913-032
- --9103130595 LER 81-008/01T-0 on 810218, breaker did not trip during preventative maint on breaker 3A09, RBS Funp P-291A Caused by loose wire on pigtail of trip coil due to use of 14-16 aug lug on 20 aug wire All lugs on pigtail leads to be replaced. COLONBO, R. W. Batramento Municipal Utility District 81/03/04 12 07913 034
- BiO3:30600 Forwards LER 81-006/03L-0 MATTINGE, J. Sarromento Municipal Utility District. B1/03/05 2ab 07912 032
- --8103130608 LER 81-006/03L-0 on 810205 one of two pressurizer code safety valves.P8V-21306.lifted above setpoint level per Tech Specs during bench test Possibly caused by seat leakage during test to limited capacity of bench tester CCLOMBD.R W Sacramenta Municipal Utility District 81/03/05. 1p 07912 054
- 0103170664 Forwards LER 91-010/017-0 MATTIMOE.J J. Sacramento Municipal Utility District 81/03/10 2pp. 07925-138
- --B103170667 LER B1-010/01T-0 on B10225.A/E.performing analysis for IE Bulletin 79-14.informed of potential piping stress problem on decay heat removal sys A.line 26120-10 Gaused not stated Sys use restricted to temps & prossures below design limits. COLONGO.8 W. Sacramento Municipal Utility District. 81/03/10. in 07925.140
- 8103170657 Forwards LER 81-009/03L-0 MATTIMOE, J J Sorramento Municipal Utility District. 81/03/11. 2pp 07929 144
- --BI03170661 LER BI-009/03L-0 on BI0217 during testing of mod to diesel generator room vent fans, breaker 52-3817 tripped free Cause undstermined Breaker replaced u/Class 1 breaker & returned to svc.
  CGLOHBO.R W Sacramento Municipal Utility Dietrict, BI/03/11.
  10 07925 146
- BIO323072B Forwards LER B1-015/04T-0 Event analysis submitted.

  DUBBER R P. Sacramento Municipal Utility District 81/03/16 2pp.
- --Bi03230732 LER Bi-015/047-0 on Bi02j4-review of Feb 1981 effluent charts showed Tech Spec for plant effluent pH was exceeded Caused by effluent diversion setpoint being slightly out-of-tolerance Setpoints lowered COL0780.R.H. Sacramento Municipal Utility District. 81/03/16. 1p. 07974-196
- B103240460 Forwards LER B1-012/01T-0 Detailed event analysis submitted MATTIMDE, J. J. Sacramento Municipal Utility District. 81/03/16 2pp. 07984.322.
- --8103240463 LER 81-012/017-0 on 810303.as-found setpoints for high reactor bidg pressure trip were nated exceeding Tech Spec. Caused by instrument drift Switches reset & setpoints revised.

  CDL0/180.R W Sacramento Municipal Utility District. 81/03/16

07984.324.

- Bi03200409 Corrected PNO-V-Bi-011 on Bi0316, alarm on reactor bidg low level gas monitor channel sounded. Caused by presence of Kr-85 & Xe-133.6 lignificance of release & possible personnel exposures are being evaluated NGRTICH . UENSLANDKI.F Region S. San Francisco, Office of the Director. 81/03/17 ip 07971:272
- 8103240453 Forwards LER 81-011/03L-0 Datailed event analysis submitted.

- --dio3240457 LER 81-011/031-0 on 810217. reactor bldg sump/decay heat removal sys flow path obstructed Caused by installation of blant test flanges on suction lines Flanges removed & test proceedure revised CPLOMED. Fig. 8 Sacraments Municipal Utility Gistrict 81/03/17 in 07984 318
- 8100310603 RD 81-016 on 810312 coils found plugged on component cooling water side of lube oil occier to high pressure injection pump 8 Gaised by from oilde buildup investigation continuing Complete rept within 14 days REDRIEUEZ R J Secremento Municipal Utility District 81/03/18 299 08062 220
- B103310961 Forwards LER B1-012/03L-0 MATTINGE, J. J. Sacramento Municipal Utility District B1/03/23 2pp 08081 226
- --BIO3310567 LER BI-013/031-0 on BIO223, inner door of reactor bidg personnel hatch failed to close completely Caused by misinterpretation of Tech Spets Hritten interpretation to be distributed COLOMBO.R W Sacramento Municipal Utility District B1/03/23 ip. CB081 228

# T Hearing transcripts on non-antitrust matters

- 8103199634 Hemorandum of law that St Lucie decision.ALAB-603, should not be applied to require quantitative assessment of probability of failure of fMI-1 decay heat removal sys since no special circumstances esist.

  BAXTER.T.A. Metropolitan Edison Co. BAXTER.T.A. Shaw. Pittman. Potts 8 Tro-bridge 8/03/09 13pp. 07963 347
- --BIODI90646 Testimony re acceptability of feedwater transients referenced in NUREO-0560. Friends of the Earth Contention Illa Feedwater transients not discussed in NUREO were those where my response was not unusual Certificate of Gvc encl. RUBIN. M. P. Procedures & Test Review Branch NOVAK, T. M. Assistant Director for Operating Reactors BI/OD/11 722 07964 017
- ECCKET 50-313 ARXANSAS NUCLEAR ONE. CHIT I
- 8103180264 Ltr to all power reactor licensess u/plants licensed prior to 790101 Forwards NRC position & request for addlinfore safe shutdown capability for compliants u/801119 fire protection rule EIESKNUT. D. Division of Licensing. 81/02/20 13pp. 07944 105
- B103230214 Notifies that licensee plans to participate in emargency preparations exercise u/state & local authorities on B10324-25 Narrative summary of emergency exercise scenario encl. Requests info re-extent of RRC involvement in exercise. TRIMBLE.D C Arianses Power & Light Co. B1/02/23. 4pp. 07975 014.
- 8103100113 Requests that encl emergency planning info be made publicly available H/G encl.
  SBUDER, J L Division of Rules and Records 81/02/27 to 0.78431179
- BID331033B Ltr to all licenses of operating plants & holders of CPs forwarding NUREG-0695. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl. EISENHUT. D Ø Division of Licensing. 81/03/05. 6pp. 08079:077.
- Bio3110126 Releases public version of implementing procedures for emergency plen FELTON.J M. Division of Rules and Records. 81/03/06 1p 07806-001.
- --Bi03110138 Forwards public version of implementing procedures for emergency plan includes Series 1202. "Emergency Operating." Series 1903. "Energency Plan Procedures" & Series 1904, "Hagnitude of Release Procedures"
  TRIMBLE-D C Artanses Power & Light Co 81/02/27. 1p. 07806:001
- --B103110148 Public version of implementing procedures for emergency plan includes Series 1202, "Emergency Operating." Beries 1903, "Emergency Plan Procedures" & Beries 1904, "Magnitude of Release Procedures"

   Arkenses Power & Light Co. 81/02/27 750pp. 07806.001

- B103240050 Requests esemption from fire protection made required by 10CFR90. App R. Sections III 0 & L Util compliance w/fire protection sefety evaluation provides adequate protection Reactor coolent pump designs were sent B00416 & 0512 IRINBLE. D C Arlanses Fower & Light Ca B1/03/19 4pp 07990 1
- B103260965 Forwards energency planning info for placement in LPCR W/o 8103110138 SOUBER J L Division of Rules and Records. 81/03/19 ip 08040-283
- P Operating license stage documents & correspondence
- B010230589 Summary of B00B21 reating w/BBB reactor owners group re abnormal transient operating guidelines program VIBSING.Q Operating Reactors Branch 4 80/09/30 29pp
- --8103230355 Draft Abnormal Transient Operating Ouidelines.Part I --Adequate Core Cooling Reactor Trip/Forced Shutdown HALLMIN A. TWILLEY.R C. WALTERB.J F Babcock & Hilcox Co 80/07/30 54pp
- --8103230375 Draft Abnormal Transient Operating Guidelines.Part 2.Vo Fundamentals of Reactor Control for Abnormal Transients NAPIN.D A. SHANSCN.E. CARTER.L.R. Bahcock & Wilcox Co 80/07/30 150pp
- --BIO32303B6 Draft Abnormal Transient Operating Guidelines,Part 2.Vo Discussion of Selected Translents MAPIN,D A., BWANSOWLE, CARTER.L R Babcock & Hilcox Co BO/07/30 12560
- BiO3190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NOREO-Obil2 Forwards NRC position re-interim attions & request for additinfo ETERMINUT.D O Division of Licensing 80/12/22 30pp.
- BiOliSO319 Discusses followup study re dagradation of internal apportendences in LHR pipting during normal plant operation & potential effects when degraded apportenences are subjituaccident loads Recommends broad review of recurrent problems BRGHN.E.J. Director's Office 80/12/24 App
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUMEG-0707 EIBENHYF.D.O Division of Licensing BI/OI/19 App. 07764-090
- BiO3120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info ro control of heavy loads EISENHYI.D O Division of Licensing 81/02/03 6pp.
- 8103040032 Requests rept on failed fuel assembly holddown spring per util 800827 itr Probable cause & corrective actions should be detailed. Also requests util commitment to perform 100% insp of springs during next refueling outage.

  REIO.R W. Operating Reactors Branch 4 81/02/09. 2pp 07816 34
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for addition of actions requested of licensees w/o seismically qualified sys & results of NCC walkdowns EISERHUT.D.O Division of Licensing. 81/02/10 13pp 08093.145
- B103030112 Forwards revised NRC Region 4 organization chart, effectiv 810227. SEYFRIT,K.V. Region 4, Dallas, Office of the Director. 81/02/17
- 8103160669 Ltr to all operating plants & CP halders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergancy support facilities. Requests confirmation within 45 days that implementation dates will be ret.

  EISENHUT, D O. Division of Licensing 81/02/18 12pp. 07915:247
- B10306042B Notifies of payment due for Unit 1 application re definit of "operable." Unit 2 800813 application requires Class II fee only Balance due will be applied to sum used NRC. MILLER.H.O. License Fee Management Branch. B1/02/20. 2pp. 07835:276.

- BIORIBORRO Act receipt of util BOORIR & link applications for Tech Specs changes Discusses differences in fee classes for Units 1 & 2 Add1 fee required to complete total fee due for BOI128 ancliration MILLER, W.O. I trensp Fee Management Branch B1/02/20 200
- 810325024 ttr to all power reactor licensees & license applicants re NUREQ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller E15ENHUT, P.O. Division of Licensing 81/02/20 Bop
- 8103090699 Ceneric lts to all BAW licensees re canability of small break LOCA model to predict small break behavior Post-test evaluations of L-4-1 & S-07-100 predictions requested for submittel by 810401 REID.R W Operating Reacture Branch 4 81/02/24 3pp 0/844 233
- B103239030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (ercept Bt Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promotly implement emergency procedures EISENHUT D Q Division of Licensing 81/02/29 900 07980 269
- 8103030790 Forwards marked-up updated text of Cucle 5 reload rept. reflecting changes resulting from reshuffle of fuel assemblies to minimize use of failed fuel TRIMBLE.D.C. Artanses Power & Light Co. 81/02/26 16pp 02795.059
- 8103040471 Bobrits add) info re Cycle 9 startup w/five failed fuel assemblies Util is continuing work w/0%W to determine cause of failed fuel during Cycle 4 operation Util will submit progress rept within 6 months.
  TRIMBLE.D C. Arkenses Power & Light Co. 81/02/26 2pp. 07812 337
- B103230B13 Generic Ltr B1-06 to all CP holders & DL applicants re 10CFR50 71(e). "Periodic Updating of FSAR." effective B00722 Info re F9AR legal status.format & content encl E15E4HJT.D O Division of Licensing 81/02/26 10pp
- 8103030824 Forwards resconse to Item II K 3 17 NUREQ-0737 re ECCS TRIMBLE.D C Arkanses Power & Light Co 81/02/27 9pp
- 8103090535 Cormits to provide necessary info for extension of 810101 coadline for response to NUREO-0737 items info for items in A i 3.11 E 4 2.11 F i % (II 0 3.4 will be provided by 810331 item II D i info will not be provided before 810701 TRIMBLE.D C Arkanses Power & Light Co. 81/02/27. 2pp 07845 12 07845 123
- 8103090847 Advises that approx 60 days will be required to develop acceptable scope & schedule w/R&W for response to Item II x 3.30 of NUREG-0737 Revisions to scope of proposals are TRIMBLE D C Arkansas Power & Light Co 81/02/27. 1p 07846 113
- 8103120227 Act secesat of BOO211 response to 770821 info request to B&W toglever mer receipt ar advert response to Audie three reactor owners group Regulrements of IMI Action Plan Item II K. 2 19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow," fulfills request Safety evaluation encl. REID.R W. Operating Reactors Branch 3. 81/02/27 2pp
- --8103120245 Gafety evaluation re Item II.K. 2 19 "Benchmark Analysis of Sequential Autiliary Feedwater Flow" for B&W reactor plants Intent of Action Item II K 2 19 accomplished & regults provided by CRAFT-2 similer to TRAP-2 program.

  \*\*Office of Nuclear Reactor Regulation, Director 81/02/27 2pp
- 8103120276 Ack receipt of 800205 response to 790821 info request to B&W reactor owners. Requirements of TMI Action Plan Item II.K. 2.19. "Genchmark Analysis of Bequential Auxiliary Fredwater Flow." Pulfills request Safety evaluation encl. REID.R W. Operating Reactors Granch 3. 81/02/27. 2pp
- --BI0312030B Bafety evaluation re TMI Action Plan Item II K. 21. 19. "Benchmark Analysis of Sequential Ausiliary Feeduater Flou" for B&W plants, Intent of Action Item II. K 2.19 accomplished & results provided by CRAFT-2 similar to TRAP-2 program. • Dffice of Nuclear Reactor Regulation, Director. 81/02/27 01/02/27 2pp
- 8103120789 Discusses compliance w/TMI Action Plan Item II K 2 19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow " More rigorous assessment is being performed under item II.K. 3.50. Item is resolved Bafety evaluation ent. REID.R.W. Operating Reactors Branch 4 81/02/27. 200

- B103090193 Natification of B10402-03 meeting w/B&N owners group in Rethesda. MD to discuss responses to NRC 810109 Itr re asurmetric LDCA loadings VISSING O Operating Reactors Branch 4 81/03/02 2pg.
- 8103120261 Ack receipt of 800630 response to 790821 info request to breactor owners group Requirements of TMI Action Plan Item 11 k 2.19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow," fulfills request Safety evaluation encl REID.R W Operating Reactors Branch 4 81/03/02
- --B103120270 Safety evaluation re TMI Action Plan Item II K 2 19. "Genchmark Analysis of Sequential Auxiliary Foedwater Flow." Intent of Action Item II K 2 19 accomplished & results provided by CRAFT-2 striler to TRAP-2 program . Office of Nuclear Reactor Regulation, Director 81/03/02. 20
- 8103170390 Forwards safety evaluation re TMI Action Plan Item II K 2 19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow' for Bad reactor plants Util found in compliance w/item REID B W Operating Reactors Branch 4 81/03/04. 2pp
- --BIO3170671 Bafety evaluation to TMI Action Plan Item II R. 2. 19. Benthmark Analysts of Sequential Feedwater Flow" for 884 reactor glants Office of Nuclear Reactor Regulation, Director 81/03/04 20
- B1031B0246 Forwards request for addl info re "Qualification of Reacto Physic Methods for Application to PHR of Middle South Utils Sys "Requests schedule of response & identification of application of rept to units. CLARKIR A Operating Reactors Branch 3 81/03/04 9pp. 07944 04
- 8103180138 Forwards Amend 52 to License BPR-51, safety evaluation &
- natice of issuance & availability
  REID, R. W. Operating Reactors Branch 4 81/03/09 200 07943.202
- --B103180152 Amend 52 to License DPR-51 modifying Tech Specs to support of the special of the sp 07943 204
- --BiO3180171 Bafety evaluation supporting Arend 52 to License DPR-51. Office of Nuclear Reactor Regulation. Director 81703709
- -- BIG3:80:80 Notice of Issuance & availability of Amend 52 to License DPR-51 BTOLZ.J F. Operating Reactors Branch 4. 81/03/09 2pp. 07943 250
- 8103200093 Informs that staff functions of Region 4 reassigned, offective Blo227 QL Madsen-Chief of Reactor Projects Branch, designated as principal cantect & recipient of correspondence re reactor constat & recipient of correspondence re reactor const & operation activities SEYFRIT.K V Region 4. Dallas. Office of the Director B1703709 1p. 07969 046
- 8103160493 Responds to NRC 810109 request for add1 info re asymmetric LOCA loads. Requests technical review meeting on 810402 & 03 to clarify ambiguities & answer reraining questions. Hritten response will be provided by 810630 TRIMBLE-D C. Ariansas Power & Light Co. 81/03/10. 2pp. 07915.01
- BIO3180B37 Forwards Arends 53 & 21 to Licenses DPR-51 & NPF-6. respectively, safety evaluation & notice of issuance &
  - availability
    CLARK.R.A Operating Reactors Branch 3 REID.
    Reactors Branch 4 81/03/10. 3pp 07953-197. REID.R W Moerating
- --8103180893 Amends 93 & 21 to Licenses DPR-51 & NPF-6.respectively. ingligues amone 33 of to Licenses by Prist a mirror respectively modifying Tech Specs dealing w/administrative controls for personnel entry into high radiation areas REID.R W. Operating Reactors Branch 4 CLARK-R A. Operating Reactors Branch 3 B1/03/10 10pp 0793:200.
- --8103180859 Safety evaluation supporting Amends 93 & 21 to Licenses DPR-91 & NPF-6, respectively \* Office of Nuclear Reactor Regulation, Director 81/03/10 2p 07953 210
- --8103180948 Notice of issuance & availability of Amends 93 & 21 to Licenses DPR-51 & NPF-6, respectively CLARK R A Operating Reactors Branch 3 81/03/10. 2pp. 07953-212

- 810331680# Ltr to a!) licensees of operating plants applicants for Ols & holders of CPs forwarding SECY-Bi-119 re info necessary to ostablist environ qualification of safety-related electrical oppipment EIBENSUT. D.O. Division of Licensing 81/03/10 6pp 68077-270
- B103160499 Provides add1 into to two confirmation of existing commitments reliters in NuREG-0737, "Clarification of TNI Action Plan Requirements " Encludes into re-shift manning & shorthterm accident & procedures review TRIMBLE.D C Arkansas Power & Light Co 81/03/11 300 07913-018
- B103190121 Forwards response to B10112 request for info to energency fuedwater sys design Tech Specs modified Nov 1977 to conform wistd wording for valve testing for ECCS Energency Procedure 1202 26 identifies supply requirements TRIMBLE, D. C. Arkansas Power & Light Co. 81/03/12 18pp
- 9103190913 Pessonds to NUREO-0737. Item 111 D. 3 4-re control room.
  Pabitability Marked-up plot plan & one oversize carked-up drawing end! Aparture card its available in PDR
  TRIMBUE.D C Arkansas Power & Light Co B1/03/13 9pp 07965-336.
- B100230245 informs that environ qualification review results of safety-related riectrical equipment identified potential equipment deficiencies Requests review of identified deficiencies b remifications within 10 days of receipt of its r.0VAK.I.M. Assistant Director for Operating Rouctors 81/03/16 293p 07979 061
- A103270641 Submits failed fuel evaluation scope Analyses will be performed to dotyrmine unusual trends & fuel will be visually inspected Feasibility study of post-irradiation oramination methods will be conducted TRIMSLE. B C. Arkansas Power & Linkt Cc. 81/03/20. 266. CR043 008
- 9103270694 Informs that BSN curiers group submitted BAN-1911P.
  "Irradiation-induced Reduction in Charpy Upper Shelf Energy of Reactor Vessel Welcs" to fulfull submittal requirements of 1007890 App 0
  PARKER, W O Duke Power Co GI/03/23 1p
- --D103270693 Forwards DAW-1911P. Itradiation-Induced Reduction to Charpy Upper Shelf Energy of Reactor Vessel Holds." Describes implementation predictive methodology to determine svc life of reactor vessels. W/o encl TAYLOR. J M. Babcock & Wilcox Co. B1/03/12 2pp
- 8103300391 Responds to NRC lists of deficiencies re preliminary review of environ qualification of sefety-relabed alectrical equipment Concludes that slant can continue to operate in sufe mennur. License should not be modified or suspended. TRIMBLE D.C. Arkshies Pouer & Light Co. 81/03/28 3cs. 08057 246
- ) Inspection reports: IE Bulletins & correspondence
- G103950602 Forwards IE Insp. Repts 50-313/00-25 & 50-368/80-25 on 601215-18. No noncompliance noted MADBEN.9 L. Regium 4. Dallas. Reactor Operations Nuclear Support Branch. G1/01/19 2pp 07829-107.
- --8103050636 IE loop Repts 50-313/80-25 & 50-368/80-25 on 601215-18 No noncompliance noted Major areas inspected; 6A program, procedures & control rod worth measurement. ANES-ANSLEY,M. CONSTRALE. & L., DRAN. & Region 4, Delias, Office of the Director 81/01/16 4pp. 07829, 107.
- 8:03050017 Ack receipt of util 8:0107 ltr re violations noted in IE Insp Repte 90-313/20-19 & 50-368/80-19 Util is in compliance windowstriel socurity plan. Records will be changed to reflect agreement #EULY-JA Region 4- Dallas- Office of the Director. 8:/01/29. ip 07027-030.
- --8103050030 Forwards response to NRC 801219 lit re violations noted in IE Insp Repts 30-313/80-19 & 50-368/80-19 Response withheld tref 10CR2 790).
  TRIMBLE D. C. Arransas Power & Light Co. 81/01/07. 1p. 07827-031
- 8103030062 Ack receipt of 810113 ltr expressing contern re short turn around time for response to IE insps. Policy changed to require response within 25 days of rept receipt. RELLY-J A. Region 4. Dalles. Office of the Director. 81/01/29, ip. 07827:035

- ---8103090079 Expresses contern re short turn around time for respons IE Insp Repts 50-313/80-19 & 50-369/80-19 Advises that the repts require responses within 20 days from date of receipt TRIMBLE D.C. Arianses Power & Light Co. 81/01/13 2pp 07827 034
- 8103231014 Forwards IC Insp Repts 90-313/81-71 & 50-368/81-0; on 801222-810121 No noncompliance mated MADSEN 9 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 81/01/30 2pt 07778 CO7
- --8103231026 IE Insp Repts 50-313/81-01 % 50-368/81-01 on 601222-810 No noncompliance noted Major areas inspected following on previousity identified items. IE Bulletin 79-050 & THI action plan requirements JOHKSDN. N.D. CALLAN. L.J. HUNNICUTT. D.H. Region 4. Usilias. Off of the Director. Bi/01/27 9pp 07978 007
- 810320341 Forwards tE Circular Gl-O2. "Parformance of NRC-Licensed Individuals While on Duty." No written response required SEYFRIT.A V. Region 4. Dallas. Office of the Director. 61/02/09 tp. 07965-294.
- 8103041029 Act receipt of 801209 ltm re violations noted in 1E lnsp Repts 50-313/80-21 & 90-362/80-21 Corrective actions will be reviewed during future insp MADSEN 9 L Region 4, Dellas, Reactor Operations Nuclear Suspent Branch 81/02/11 ip 07820 072.
- --8103041034 Responds to violations nated in IE Insp Repts 50-313/80 50-388/80-21 Corrective actions power distribution & burn-up log changed to flag dampling operations requirements & access panel installed on 2VVC 113 TRIMBLE D. C. Arkansas Power & Light Co. 80/12/09 4PP 07620 073.
- 8103160354 Forwards IE Info Notice 81-03 'Checkitet for Liconsees Haking Notifications of Significant Events in Accordance W/10CFR30 72 'Ne response required SEYFRIT.K V. Region 4. Dallas. Office of the Director 81/02/12 ip 07922.050
- 9103390470 Updates 800930 mend re need for militifrequency eddy curre insplusing rotating pancald coil at facility Supplemental insplusion not required NOONAN.V.5 Assistant Director for Haterials & Qualifications Engineering 81/02/18 2pp 63084 246.
- 8103160649 Forwards IE Info Notice 81-04. "Cracking in Moin Steam Lines." No response required SEYFRIT.K v Region 4. Dallas. Office of the Director 81/02/27 ip 07917 116
- 8103170048 Forwards IE Circular 81-03, 'Inogerable Selamic Monitorin Instrumentation." No response required SEYFRIT.K V Region 4, Dollas, Office of the Director 81/03/02 ip. 07939-171.
- 8103270308 Updates info re admittance of NRC personnel to facility Forwards lists of regional inspectors W/o encl SEYFRIT.K V. Region 4. Dallas. Office of the Director 81/03/03 2pp 08044 I78
- 8103160986 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Bnubbers." w/corrected Pages 5 & 6 Change in identification of factlifice w/CFS to which bulletin is applicable does not affect util requirements SEYRRIT.K V Region 4. Dallas. Office of the Director 81/03/04 pp. 07915-007
- 8103240093 Updates NRC 819303 ltr re admittance of NRC personnel to facility Personnel should be issued permanent nonemployee. no escort required, picture badges. Forwards lists of personnel M/o encl
  SEYRIT, W Region 4, Dallas, Office of the Director 81/03/13
  2pp. 07987:291.
- 8103230172 Forwards 1E Info Notice 81-07. 'Potential Problem W/Water-Soluble Purge Dam Matle Veed During Inert Gas Helding.' No response required.

  BEYFRIT.K.V Region 4, Delias, Office of the Director 81/03/16 to 07977-208
- R. Pariodic operating reports & related correspondence
- 8103030795 Forwards screen monitoring rept for Jan 1981 TRIMBLE.D.C. Arkansas Power & Light Co. 81/02/25, 1p

- --BI03030802 Screen monttoring rept for Jan 1981 • Artaceas Power & Light Co B1/02/24 14pp
- 8:03120316 Forwards "Rept on Radioactive Liquid Effluents.App A.Jul-Dec 1980 " IRIMBLE D C Arkansas Power & Light Co 81/03/03 in
- --8103120321 "Rept on Radioactive Liquid Effluents App A. Jul-Dec 1980 "
  \* Artaniai Power & Light Co 81/03/03 Bpp 07585.001
- 8103230559 Forwards monthly operating rept for Feb 1981 TRIMPLE, D.C. Arkansas Power & Light Co. 81/03/12 1p. 07974 107
- --8103230569 Monthly operating rept for Feb 1981 BRAMLETT.L. S. Artenses Power & Light Co. 81/03/13 Sep 07974.108
- BiO3240239 Forwards corrected draft rept of 'Effluent & Waste Disposal Semiannual Rept for CY79" per BiO226 request TRIMBLE D.C. Arkonsas Power & Light Co. Bi/O3/19. 18pp
- 5 Reportable occurrences, LERs & related correspondence
- B103110629 Forwards add1 Cycle 5 info re failed fuel evaluations to document 810303-04 telcon agreements on future evaluations Evaluation to determine cause of failed fuel during Cycle 4 operation will continue TRIMBLE.D C. Arkansas Power & Light Co. 81/03/04 2pp 07887-107.
- 8103170373 PND-IV-81-007 on GIO310, three contract maint workers found working in high radiation area w/o health physics tochnician supervision or knowledge of existing radiation hazards. Caused by las administrative controls for area door keys. HUNNICUTT, D.M. JUHNSON, W.D. MADBELLO L. Region 4. Dallas, Office of the Director 61/03/11 2pp 07924-084.
- --8103240437 LER 81-002/99X-0 on 810303, during steam generator tubing surveillance insp. first sample results on E24A found three tubes exceeded plugging limit Cause not stated SHIVELY.C N Arkenses Power & Light Co. 81/03/18 2pp. 07984 304
- 8103310649 Forwards revised LER 80-028/01X-1 TRIMBLE.D.C Arkansas Power & Light Co 81/03/24. ip 08061-042
- --BIO3310656 Revised LER 80-028/01X-1: an BOO731, intake structure concrete access plugs removed. Later review identified access barriers to be missile shields & no protection provided at personnel access doors Plugs replaced SHIVELY. C. II Arsansas Power & Light Co BI/03/24. 4pp 08061:043
- B103310589 Forwards LER 81-004/03L-0.
  TRIMBLE.D.C Arkansas Power & Light Co 81/03/25. Ip 08062-208.
- --BIO3310590 LER BI-004/03L-0 on BIO227, diesel fire pump battery bank surveillance test found not completed within grace partod. Caused by failure to hotify supervisor that procedure could not be completed during shift BRAMLETT.L B Arkensas Power & Light Co 81/03/25 1p.

## V. Operator Examinations

- 8103100656 Submits status rept of significant milestones accomplished to improve operator training program.
  CAVANAUGH. M. Arkentss Power & Light Co. 81/02/17. 5pp. 07863.006
- 8103160497 Provides add1 info to b/or confirmation of existing commitments relitems in NUREG-0737. "Clarification of TMI Action Plan Requirements" Includes info re-shift manning & short-term accident & procedures review IRIMBLE D.C. Arkansas Power & Light Co. 81/03/11. 3pp 07915-018.
- DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

  F Security, medical, energency & fire protection plans
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info retaff shutdown capability for compliance w/801119 Pire protection rule.

  EISENHUT.D. 9. Division of Licensing. 81/02/20. 13pp.

- 8103100675 Requests that encl emergency planning info be made publicavailable N/o encl
  SQUEER J C Otylicion of Rules and Records 81/02/27 ip.
  07868-312
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NURED-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable rethod for meeting NRC requirements U/o encl FISENHUT.D Q Division of Licensing. G1/03/05 dpp
- O Adjudicatory correspondence
- 8103240025 Responds to 810210 memo requesting legal opinion as to whether Supremy Court refusal to hear case re price squeeze requires Section 103a proceeding Commission may want to await decision in Fort Pierce Utils Authority vs NRC. RUTBERO, J. Antitrust Division 81/03/16. 3pp. 07990 344
- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants.applicants for OLs & holders of CPs re control of heavy loads Requestd review per guidalines in NUREG-Obliz Forwards NRC position reinterin actions & request for addl info.

  EISENHUI.D O Division of Licensing 80/12/22 30pp
- BID3190387 Litrig all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment litens addressed involve cold shutdown replacement parts & NUREO-0737 EISENRUT.D O Division of Licensing BI/01/19 App
- B10302079B Forwards Amends 44 & 26 to License DPR-98 & DPR-74-respectively. & notice of issuance & availability.
  VAROA.6 A Operating Reactors Branch 1 81/01/30. 3pp. 07781.5
- --B103020762 Arends 44 & 26 to Licenses DPR-50 & DPR-74, respectively revising fire protection Tack Specs to reflect mode to facility & revising Tech Bpec index to add environ qualification.

  VARQA, B. A. Operating Reactors Branch 1. B1/01/30. 1Bpp. 07781: 255
- --BI03020767 Notice of issuance & availability of Amonds 44 & 26 to Licenses DPR-98 & DPR-74 respectively. VARQA, B A. Operating Reactors Branch 1. 01/01/30. 2pp. 0781:273
- BiO3120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3,2ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC B01222 request for addlinfore control of heavy loads.
  EISENMUT.D.O Division of Licensing. 81/02/03. App.
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater mys seismic design. Forwards request for addl info. List of actions requested of licensees w/o seismically qualified mys & results of NGC walkdowns. EIBERHUT.D.O. Division of Licensing. 81/02/10. 13pp.
- B103031083 Notification of 810225 meeting w/utils & Westinghouse in Bethesda.MD to discuss power distribution limits following reload for Unit 2 MINER.8 Depreting Reactors Branch 1. 81/02/17. 2pp. 07797; 03
- 8103160667 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A. I 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be net. EISENHUT.D O. Division of Licensing. 81/02/18. 12pp.
- 8103020626 Updates 810112 info re util R&D program re hydrogen contingesures for ice contenser containments Interim distributed ignition sys will be manually actuated from auxiliary bldg. Agrees to 810312 technical meeting. HWNTER.R. 8. Indiana & Michigan Electric Co. 81/02/20. 2pp. 07782-099.
- B)03090123 Forwards organizational charts depicting NRC Region 3 reorganization effective 8102/6. KEPPLER.J.G. Region 3. Chicago, Office of the Director. B1/02/2020.057.
- 8103290924 Ltr to all power reactor licensees & license applicants of NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D. O Division of Licensing. 81/02/20. App.

- Bio3110103 Forwards 'Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for IN & MI Electric Co.DC Cook.Units 1 & 2." pactial review Written response required MOVAK.T. Assistant Director for Operating Reactors B1/02/24 3pp 07884 268
- --Bi03110189 "Equipment Evaluation Rept by Dfc of Nuclear Reactor Regulation for IN & MI Electric Co.DC Cook Units | 6-2."
  partial review Diffice of Nuclear Reactor Regulation, Director 81/02/24
  2599 07834-271
- B103230030 Lir to all licensees of operating nuclear power plants & applicants for CLs (errept St Lucie Units 1 & 2) Requests util review to determine capability to nitigate station plackbout event & promptly implement energency procedures FISS/MULTID 2 Division of Licensing B1/02/25. Spp
- 0103230813 Generic Ltr 81-05 to all CP holders & OL applicants re IOCFR50 7:1et. "Periodic Updating of FSARs." effective B00722 Info re F9AR legal status format & content encl EISENHUT.D 0 Division of Licensing B1/02/26 10pp
- BIO3180909 Forwards summary of 810114 meeting w/util & EXXON Nuclear in Betheeda-MD to provide util opportunity to explain EXXON plans for reload ECC9 analysis for facility Meeting summary & list of attendees erci MINKER D Deserting Reactors Branch 1 81/03/02 3pp 07953-114.
- --BIO2230759 Summary of BiO114 meeting w/vendor in Betheeds.MD.re plan for reload ECCS analysis Implementation of ICECGN code to compute tCCA containment pressure during refload & REFLEX code to computer refload transient approved AUDETIE.8 F. Reactor Surtens Branch BIO/1/27. 200. 65024 189
- BiOJ120740 Notification of 810318 meeting soutils in Bethesda, MD to discuss hydrogen control measures for facility containments benefit servivability of equipment within containments Agenda enci MINER, 8 Description Reactors Branch i 81/02/03 Jop 07904 333.
- 8103310804 Ltr to all licenses of operating plants, applicants for OLs & holders of CPs forwarding SECV-81-119 re info necessary to establish environ qualification of safety-related electrical equipment FISCNMINIT. O O Division of Licensins. 81/03/10 6pp.
- O Inspection reports, IE Bulletins & correspondence
- 8103130104 Forwards IE Insp Repts 50-315/80-20 & 50-316/80-16 on 801117-21 & 8[0113 & motice of violation HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 81/01/23 2pp 07907-276
- --BI03133112 Notice of violation from insp on B01117-21 & B10113 HEISHMAY.R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. B1/01/23 1p. 07907-278
- --BIO3130119 IE Insp Repts 50-315/80-20 & 50-316/80-16 on 801117-21 & BIO133 Honcompliance noted inadequate pump run time during surveillance & failure to establish ref valve for pump inlet pressures for inservice imap program.
  PESCHEL-J M . CONNAUGHTON.K Region 3. Chicago. Office of the Director. BAKER,K.R. Region 3. Chicago. Reactor Operations Nuclear Support Branch. BI/O1/22 | Tipp 07907-279
- BiOJ230354 Forwards second set of responses to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment " Also forwards summary table of equipment qualification status of IMI-related equipment & info re cold shutdown equipment, MALONEY.O.P Indiana & Michigan Electric Co. Bi/02/03 21pg 07079-32A
- 8103120480 Forwards IE Insp Repts 50-315/80-21 & 50-316/80-17 on 801201-31 & notice of violation. HEIBHMAN, R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 81/02/04. 2pp 07905:182
- --8103120484 Notice of vialetion from insp on 801201-31 HEIBHMAN,R F Region 3. (Dicago: Reactor Operations Nuclear Support Branch: 81/02/04 1p. 07905 184
- --B1031204B7 IE Insp Repts 50-315/B0-21 & 50-316/B0-17 on B01201-31. Noncompliance noted two containment spray sys inoperable during mode changes & automatic feedwater pump trip on low suction pressure not installed BMANBON, E.R. DUBRY, N.E. BOYD, D.C. Region 3. Chicago, Office of the Director 81/02/02 App. 07905.183

- 8103020109 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required MEPPLER. J 9 Region 3. Chicago. Office of the Director 81/02/09 225 07788 013
- 8103160988 Forwards IE Enforcement Conference Repts 30-315/81-02 & 50-316/81-02 on 810113 KEPPLER.J. J. Region 3. Chicago. Office of the Director 81/02/09 2pp. 07915 009
- --Bi03160994 IE Enforcement Conference Repts 50-315/B1-02 & 50-316/B1-02 on Bi0113 No moncompliance noted Areas discussed recent occurrences at plant resulting in reduced margins of safety BOYD.D C. NEISHMAN R F. Region 3. Chicago. Office of the Director B1702/09 App. 07915-011
- 8103040335 Forwards IF Info Notice 81-03. 'Checklist for Licensees Making Notifications of Significant Events in Accordance W/105FR50 72' No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 81/02/12 2pp 07815 273
- 8103060286 Ack receipt of 810128 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-319780-19 & 50-316780-15 HEIBHAMIR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 81702717 ip 07839-301
- --BIDDDE0297 Responds to MRC Biolofi it reviolations noted in IE Insp. Repts 50-315/80-19 % 50-316/80-15 Currective actions repaired penetration fire seals Medo issued re-fire seals requirements

  ODLANULE Indiana & Michigan Pawer Co. 81/01/28. 3pp. 07839-302
- 8103130157 Forwards IE Inst Repts 50-315/80-24 to 50-316/80-20 from 801229 mgt meeting re systematic assessment of licenses performance KEPPLER.J O Region 3. Chicago. Office of the Director 81/02/24 2ps. 07708 078
- --8103130165 tE Insp Repts 50-315/80-24 & 50-316/80-20 from 801229 mit meeting re systematic assessment of licensee performance Performance is adequate HEISHMAV.R.F. Region 3. Chicago, Reactor Uparations Nuclear Support Branch 81/02/05 8pp 07908 078
- 8103160700 Forwards IE Info Notice 81-04. "Cracking in Main Albam Lines" No response required KEPPLER. J Q Region 3. Chicago. Office of the Director 81/02/27 2pp. 07914-062
- 8103160481 Forwards IE Circular 81-03, "Inoperable Boismic Monitoring Instrumentation." No response required MEPPLER, J. O. Region 3, Chicago, Office of the Director 81/03/02. pp. 07915:296
- BiO3160BAB Forwards revised IE Sulletin Bi-O1. "Burveillance of Mechanical Enubters." w/corrected Pages 5 & 6 Change in identification of facilities L/CPs to which bulletin is epplicable does not affect util requirements

  KEPPLER. J G Region 3. Chicago. Office of the Director 81/03/04
  2pp 07914 223
- 8103170261 Responds to NRC 810224 ltr providing partial review of util responses to IE Bulletin 79-018 re environ qualification of Class IE safety-related oquipment Continued safe operation of facilities adequately assured Equipment list complete HUNTER.R.S. Indiana & Michigan Electric Co. 81/03/09 3pp. 07934-237.
- 8103200870 Forwards 1E Info Notice 81-06 "Failure of ITE Model K-600 Circuit Breaker" No written response required. KEPPLER J G Region 3. Chicago, Office of the Director. 81/03/11. 200. 07967:199
- 8103240006 Forwards IE Info Notice 81-00. "Failure of ITE Model K-600 Circuit Breaker." No response required.

  KEPPLER J O. Region 3. Chicago, Office of the Director. 81/03/11
  2pp. 07990.348
- 8103180111 Ack receipt of 810223 Itr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-315/80-20 k 30-316/80-16
  HE IBMMAN R F. Region 3. Chicaga, Office of the Director 81/03/12 ip. 079/3.174

- --8107189123 Responds to NRC 810123 ltr re violations noted in IE Insp. Repts 50-315/80-20 % 50-316/80-16 Corrective actions reviewing procedures to ensure inclusion of 15-minute criterion on safety-related pump operation. HINTER: R 5 Indiana % Michigan Electric Co. 81/02/23 Spp. 67943 175
- B103231076 Responds to IE Bulletin B1-01, "Surveillance of Mechanical Snubbers ' No mechanical snubbers installed on safety-related equipment HUNIERLR S Indiana & Michigan Electric Co B1/03/12 2pp 07976-327
- 6103200681 Forwards IE Info Notice 81-05. 'Degraded DC Sys at Palisades' No action required KEPPLER, J G Region 3. Chicago. Office of the Director 81/03/13 250 07966 178
- B103200266 Forwards IE Info Notice BI-07. 'Potential Problem M:Water-Soluble Purgo Dam Matls Used During Inert Gas Welding " No response required MEPPLER. J G Region 3. Chicago. Office of the Director 81/03/16. 200 07970 393
- 8103250168 Ack receipt of 810302 itr informing ARC of steps taken to correct violations noted in IE Insp Repts 50-315/80-21 ½ 50-316/80-17 IEISHMAN.R F Region 3. Chicago. Office of the Director 81/03/17 to 07976 040
- ---G103250175 Responds to NRC G10204 ltr re violations noted in IE Insp. Repts 50-315/B0-21 % 50-316/80-17 Corrective actions mpt directive issued emphasizing need to most commitment deadlines & to notify NRC of missed deadlines HUNTER. B Indiana & Michigan Electric Co. B1/03/02 2pp. 07996.041
- R Periodic operating reports & related correspondence
- 3103100342 Forwards monthly operating tept for Jan 1981 SIGNLER, D. V. Indiana & Michigan Electric Co. 81/02/10 1p 07864-321
- --8103160346 Monthly operating tept for Jan 1981 TETZLAFF.A L. . GVENSSON.B A . CAMPBELL.D R Indiana & Michigan Electric Co 81/02/12 10pp 07864 322
- 8:03050477 Forwards "Annual Operating Rept. 1980 '
  SHALLER, D. Y. Indiana & Michigan Electric Co. 81/02/27 2pp
- --Bi03050485 "Annual Operating Rept.1980 " BHALLER, D.V., SVENSBON, 8 A., TBURLEY, E.L. Indiana & Michigan Electric Co. B1/02/27 2lpp 07825-003
- 5 Reportable occurrences. LERs & related correspondence
- BIO3040054 PxO-III-80-187 on BO1011 reactor scrammed Caused by control valve fluctuations resulting in greater than 100 lb differential pressure between main steam lines Bafety injection initiated SHANSON.E. BOYD. D.C. HEISHMAN.R.F. Region 3. Chicago, Office of the Director BO/10/14 2pp. 07819-292
- B103100562 Forwards LER 80-039/03L-0.updated LER 80-034/03x-2 & 810123 Itr SHALLER.D V. Indiana & Michigan Electric Co 81/03/03 ip 07862:318.
- --Bi03100577 Responds to IE Insp Repts 50-315/80-15 & 50-316/80-14 Corrective actions alorm bistable recalibr to proper satpoint & design change initiated to correct indicator & alorm problems.

  HUNTER-R. 9 Indiana & Michigan Electric Co. 81/01/23 4pp. 07862-322
- 8103;80532 Forwards LER 81-002/03L-0. SHALLER D V. Indiana & Michigan Power Co 81/03/12 lp. 07950.103
- --B10318D540 LER B1-002/03L-0 on B10215.west notor driven auxiliary feed pump was removed from svc to repair emergency leakoff line check valve.FM-160 Caused by dirt causing valve to stick Valve cleaned.
  WINNER.D G Indiana & Michigan Power Co 81/03/12. lp. 07950:104

- 8103230755 Forwards LER 81-003/03L-0 SMALLER.D V Indiana 3 Michigan Electric Co 81/03/13 1p. 07974-031
- --Gi)3230760 LER 81-003/03L-0 on 810212, during normal operations, coroom cable vault left unattended w/no fire watch posted while access door was sealed for testing Caused by misunderstanding of Tech Spec 3.7 10 Personnel reinstructed PIEHL-R H Inglana & Michigan Electric Co. 01/03/13 lp 07974,042
- 8103270689 Forwards updated LER 80-019/03X-1 544LLER, D V Inciana & Michigan Electric Co 81/03/23 1p 02001 275
- --B103270694 Updated LER 80-019/03x-1 on 800811 surveillance requir Tech Spot 4 8 1 te not performed Caused by operator error Operator reprinanded Procedures revised to include breaker alignment & to require signoff on completion KETTH. B Indiana & Michigan Electric Co 81/03/23 2pp 08043 276
- COCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT. UNIT 2

  F Security, medical, emergency & fire protection plans
- 8103180264 Ltr to all power reactor licensees w/plants licensed pri to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 fire protection rule EISENHUT.D @ Division of Licensing 81/02/20 (3pp
- Bio3i00675 Requests that enci emergency planning info be made publicavallable W/o enci SOUDER, J. Division of Rules and Records 81/02/27 ip. 07865-312
- 8103310338 Ltr to all licensees of operating plants & holders of CP forwarding NURED-0676. Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements N/o encl EIGENAUT.D O Division of Licensing 81/03/05 App.
- P Operating license stage documents & correspondence
- DI03190732 Ltrs to all licensess of operating plants-applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position reinterim actions & request for add info. EISERHUT.D.O Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licenses of operating plants & applicants fo OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown, replacement parts & NUREO-0737 EISENHUT.D.O. Division of Licensing 81/01/19 App
- 8103029758 Forwards Amends 44 & 26 to License DPR-58 & DPR-74.
  respectively, 5 notice of issuance & availability
  VARDA.S.A Operating Reactors Branch 1. 81/01/30 3pp. 07781:
- --BIO3020762 Amends 44 & 26 to Licenses DPR-58 & DPR-74, respectivel revising fire protection Tech Specs to reflect mode to facility & revising Tech Spec index to add environ qualification. VARCA-8 A Operating Reactors Branch 1. BI/OI/30 18pp. 07781-255
- ---8103020767 Notice of issuance & availability of Amends 44 & 26 to Licenses DPR-58 & DPR-74, respectively VARGA. S A Operating Reactors Branch 1. 81/01/30. 2pp. 07781:273
- B103120014 Lir to all licensess of operating plants CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & IMI-1, forwarding inadvertently omitted pages from NRC B01222 request for add1 info re control of beavy loads.
  EIEENHUT.D. 0 Division of Licensing. B1/02/03. App.
- 8103040231 Forwards Amend 27 to License DPR-74, safety evaluation & notice of issuance & evaluability VANGA 8 A Derating Reactors Branch 1. 81/02/10. 2pp. 07813:
- --Bi03040245 Amend 27 to License DPR-74-revising moderator temp coefficient Tech Spec VAROA.S.A. Operating Reactors Branch 1. 81/02/10. Spp. 07813:233

07813 242

- 8103300160 Ltr to all operating PWR licenses requesting info on ausiliary feedwaler sys sessmic design Forwards request for addition for all info. list of actions requested of licensees w/o satisfically qualified sys & results of MC walldowns.
  EISENHUT. D 0 Division of Licensing 81/02/10 13pp
- 8103040280 Forwards Amend 28 to License CPR-74, safety evaluation & notice of Issuance & availability VARDA, B. A. Operating Reactors Branch | 81/02/12 2pp 07815-226
- --B103040288 Amend 28 to License DPR-74 revising trip setpoints & allowed making to tricing or and tryonizing the sector allowed to reactor protection sys & engineering safety features actuation VARGA,8 A Operating Reactors Branch 1. 81/02/12 App. 07814-228
- --Bi03040294 Safety evaluation supporting Amend 28 to License DPR-74 Office of Nuclear Reactor Regulation, Director 81/02/12 3co
- --8103040304 Notice of issuance & availability of Amend 28 to License VARQA, S. A. Licensing Branch 1 81/02/12 20g. 07815 239
- 8103031083 Notification of 810225 meeting w/utile & Mestinghouse in Bathesda. MD to discuss power distribution limits following reload for Unit 2 MINER & Coerating Reactors Branch E 81/02/17 2pp. 07797 037.
- 8103160669 Ltr to all operating plants & CP holders forwarding iudicuoux Lit to all operating plants & th holders forwarding clarification of TMI Action Plan Itom III A 1.2 re upgrade of amergoncy support facilities Requests confirmation within 43 days that implementation dates will be not EISENMUT.D.O. Division of Licansing 81/02/18 12pp.
- Bi03020626 Updates Bi0il2 info re util RBD program re hydrogen control measures for ice condenser containments. Interim distributed ignition sys will be manually actuated from auxiliary bidg. Agrees to 810312 technical resting HUNTER, R. B. Indiane & Michigan Electric Co. B1/02/20 2pp. 07782: 099
  - 03090123 Forwards organizational charts depicting NRC Region 3 reorganization.effective B10216.
    KEPPLERJ Q Region 3: Chicago: Office of the Director. B1/02/20 2pp. 07850 057
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low file controller.
  EIGENHUT.D.O. Division of Licensing 81/02/20 8pp
- 0103110103 Forwards "Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for IN & MI Electric Co.DC Cook,Units 1 & 2," partial review Hritten response required. MOVAW, T.M. Assistant Director for Operating Reactors. 81/02/2 Assistant Director for Operating Reactors. 81/02/24. 3pp. 07884; 268.
- ---8103110187 "Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation for IN & MI Electric Co.DC Cook, Units 1 & 2, " partial review

  • Office of Nuclear Reactor Regulation, Director - 81/02/24. 2500. 07884:271.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie-Units I & R). Requests util review to determine capability to mitigate station blackout event & promptly implement energency procedures. EISENHUT. D. Q. Division of Licensing. 81/02/23. Spp.
- 8103120740 Notification of 810318 meeting w/utils in Bethesda, MD to discuss hydrogen control measures for facility containments & survivability of equipment within containments. Agenda encl. MINER, E. Operating Reactors Branch 1 81/03/03. 3pp. 07904:333.

8103130104 Forwards 1E Insp Repts 30-315/80-20 & 90-316/80-16 on 801[17-2] & 810[1] & notice of violation IETBM\*AN.R F Region 3. Chicago, Reactor Operations Nuclear Suppo Grand 81/01/23. 2pp 0/707-276

- --BIO3130112 Notice of violation from insp on BO1117-21 & BIO113 HEISHMAN, R. F. Region 3. Chicago. Reactor Operations Nuclear Support Granch B1/01/23 1p. 07907 278
- ---BI03130119 IE toen Repts 50-315/80-20 & 50-316/80-16 on 801117-21 RIGITALLY IE THEN REPTS 30-313/40 20 & 30 316/40-16 bit doining auriellance & Patture to establish ref valve for sump inlet pressures for Injervice instantion for Valve for pump into pressures for Injervice inst propram
  PESCHEL.J M. CCNNAUGHTGN.K Region 3. Chicago. Office of the Otrector Gamer. R Region 3. Chicago. Reactor Gamericons Nuclear Support Branch 81/01/22. 11pp 07907-279
- B103230354 Forwards second set of responses to LE Bulletin 79-018. "Environ Qualification of Class LE Equipment." Also forwards surpary table of equipment qualification status of FMI-related equipment & info re cold shutdown equipment MALONEY.O.P. Indiana & Michigan Electric Co. 91/02/03 21pp 07070 224
- 8103120480 Forwards IE Insp Repts 50-315/80-21 & 30-316/80-17 on 801201-31 & notice of violation MEISHMAV.R.F. Region 3. Chicago. Reactor Operations Nuclear Suppo Brench 81/02/04 2pp 07905 182
- --Bi03120484 Notice of violation from insp on B01201-31. HEI\$HKAN,R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch, B1/02/04 ip 07905 184
- --6103120487 IE Insp Repts 30-315/80-21 & 50-316/80-17 on 801201-31 Noncompliance noted two containment spray sys inoperable during mode changes & automatic feedwater pump trip on low Suction pressure not installed SMANSON.ER. DUDRY.NE - BOYD.D.C. Region 3. Chicago. Office othe Director Bi/02/02 Bp 07905 185
- 8103020609 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required.

  KEPPLER J 0 Region 3, Chicago, Office of the Director. 81/02/09 07788 013. 200
- 8103160988 Forwards IE Enforcement Conference Repts 50-315/81-02 & 103107700 FOTUAROS IR ENFORCEMENT CONFERENCE MEPTS 30-313701-02 & S-313701-02 A KEPPLER.J Q. Region 3. Chicago. Office of the Director. 81/02/09 2pp 07915-009
- --B103160994 IE Enforcement Conference Repts 50-315/81-02 & 50-316/8 On BiOli3 No honcompliance noted Areas discussed recent occurrences at plant resulting in reduced margins of safety DOYO.D.C. HEISHMAN.R.F. Region 3. Chicago, Diffice of the Director. B1/02/09 4pp. 07913.011
- 8103040309 Forwards IE Info Notice 81-03. 'Checklist for Licenses Making Notifications of Significant Events in Accordance M/10CFR50. 72 "No written response required MEPPLER-J. G. Region 3. Chicago. Office of the Director. BI/02/12 2pp 07815:273
- 8103060286 Ack receipt of 810128 itr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-315/80-19 &
- COTTECT VIOLENTIAL CONTROL OF CON
- --8103060297 Responds to NRC 810106 ltr re violations noted in IE In Repts 50-315/80-19 & 50-316/80-13. Corrective actions: repaired genetration fire seals. Nemo issued re fire seals requirements DOLAN, J. E. Indiana & Michigan Power Co 81/01/28 3pp. 07839:302.
- 8103130157 Forwards IE Insp Repts 50-315/80-24 & 50-316/80-20 from BO1229 mgt meeting re systematic assassment of licenses performance KEPPLER.J. O. Region 3. Chicago, Office of the Director. 81/02/24 2pp. 07908:096

# DOCKETED ITEMS

- --8103130165 IE Insp Repts 50-315/80-24 & 50-316/80-20 from 801229 mgt meeting he systematic assessment of licensee performance Performance HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 81/02/05 8pp 07908 098
- 8103350700 Forwards IE Info Notice B1-04. 'Cracking in Main Stean Lines' 'No response required MEMPLER.JO Region 3. Chicago. Office of the Director 81/02/27. 2pp 07914-062
- 0103160481 Forwards IE Circular 81-03. "Inoperable Setemic Monitoring Instrumentation" No response required KEPPLER. J Q Region 3, Chicago. Office of the Director. 81/03/02 ip. 07915-296
- 8103160B6B forwards revised IE Rulletin Ri-Ot. 'Burveillance of Mechanical Shubbers.' w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements KEPPLER. J 0 Region 3. Chicago. Office of the Director 81/03/04 2pp 07914 223
- B103170261 Responds to NRC B10224 ltr providing partial review of util responses to IE Bulletin 79-018 re environ qualification of Class IE safety-related equipment Continued pafe operation of facilities adequately assured Equipment 31st complete HUNIER.R.S Indiana & Michigan Electric Co 81/03/09 3pp. 07934 237
- B103200870 Forwards IE Info Notice B1-06 'Failure of ITE Model K-600 Circuit Breaker.' No written response required.

  KEPPLER.J. O Region 3. Chicago. Office of the Director B1/03/11
  2pp 07967 199
- 8103240006 Forwards IE Info Notice 81-06. 'Failure of ITE Model K-600 Circuit Breaker 'No response required. KEPPLER. J Region J. Chicago. Office of the Director 81/03/11 2pp 07990 340
- B103180111 Ack receipt of B10223 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-315/80-20 t 50-315/80-20 t 90-315/80-20 t REJBMMAN.R F Region 3. Chicago. Office of the Director. 81/03/12 ip 07743 174
- --8103180123 Responds to NRC 810123 ltr re violations noted in 1E Insp. Repts 50-315/80-20 & 50-316/80-16 Corrective actions: reviewing procedures to ensure inclusion of 19-minute criterion on safety-related gump operation. HUNIER.R.B. Indiana & Michigan Electric Co. 81/02/23 Spp. 02743 175
- B103231076 Retponds to IE Bulletin 81-01, "Burveillance of Mechanical Shubbers" No mechanical shubbers installed on safety-related equipment tRNTER.R 8 Indiana & Michigen Electric Co 81/03/12 2pp 07976-327
- 8103200681 Forwards IE Info Notice 81-05. "Degraded 00 Sign at Palisades." No action required. KEPPLER.J.O. Region 3. Chicago. Office of the Director 81/03/13 2pp 07766:178
- 8103200266 Forwards IE Info Notice 81-07. "Potential Problem W/Water-Soluble Purge Dam Matla Used During Inert Gas Walding." No response required KEPPLER, J O. Region 3. Chicago, Office of the Director 81/03/16 2pp. 07970: 353.
- 8103250168 Ack receipt of 810302 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/60-21 & 50-316/60-17 HEIBHMAN.R.F. Region 3. Chicago, Office of the Director. 81/03/17. lp. 07996.040.
- --8103250175 Responds to NRC 810204 itr re violations noted in IE Insp. Repts 50-315/80-21 & 30-316/80-17. Corrective actions mpt directive issued emphasizing need to meet commitment deadlines & to notify NRC of missed deadlines. HUNTER-R. 8. Indiana & Michigan Electric Co. 81/03/02 2pp. 07996:041.
- R. Periodic operating reports & related correspondence
- 8:03050477 Forwards "Annual Operating Rept. 1980."

- --8103050485 'Annual Operating Rept. 1980 "

  EMALLER.D.V. SVENSSON.B A. TOMM.EV.E I. Indiana & Michigan Electric Co. 81/02/27 21pp 07825.003
- S Reportable occurrences. LERs & related correspondence
- Bio2030B31 Final deficiency rept re possible svc water leak in ventilation unit of lower vol combainment initially reported Bio220 Drip pan pipe had become plugged Drip pan overflowed No leak prists Requests notification of withdrawal.

  BirALLER.D V Indiana & Michigan Power Co Bi/02/27. Ip
- 8103050626 Forwards updated LER 80-024/03x-1 SHALLER.D V Indiana & Michigan Electric Co. 81/02/27 Lp 07827-159
- --8103050628 Updated LER 80-024/03x-; on 800520.alern indicated availated feedwater pump tripped in nonrunning auto standby position Caused by turbine control linkage unlatching from trip & throttle valve.possibly due to lumber on trip linkage MEITH-R 8 Indiana & Michigan Electric Co 81/02/26. 2pp 07829 160
- 8103100360 Forwards updated LER 81-001/04X-1.
  SHALLER.D.V Indians & Michigan Electric Co 81/03/03 1p.
  07845 042
- --8193109369 Updated LER 81-001/04X-1 on B10112-nd apparent flow obserthrough rediation monitor R-19 from steam generator 21.

  Caused by bad diaphragm in roto-meter flow regulator Flow meters to radiation monitor to be nedified.

  R18CHLIN9-J L. Indiana & Michigan Electric Co. B1/03/04. Jpp. 07865-043
- B103100562 Forwards LER 80-039/03L-0.updated LER 80-034/03X-2 & 810123 1tr SHALLER-D. V Indiana & Michigan Electric Co B1/03/03. 1p. 07862-318
- --8103100566 Updated LER 80-034/03X-2 on 801204, containment isolation valve NCR-252 found not fully seated w/shut indication in control room during Mode 5 Cause undetermined. Valve stroke adjusted
  RISCHLING. J. Indians & Michigan Electric Co. 81/03/04 2pp 07862 319
- --D103100572 LER 00-039/03L-0: on 80072B, low pressure claim failed to clear ω/increased nitrogen pressure Cause not stated. Reference response to 1E Insp Repts 80-315/80-15 % 30-316/80-14. HURPHY.C E. Indiana & Michigan Electric Co. 81/03/04. 5pp. 07862-321
- --8103100577 Responds to iE Insp Repts 90-315/80-15 & 30-316/80-14. Corrective actions alarm bistable recalibr to proper setpoint 5 design change initiated to correct indicator 5 alarm problems.
  HUNTER.R S. Indiana & Michigan Electric Co. 81/01/23. 4pp 07862-322
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- BIO1080201 Releases public version of util draft sits emergency plan. FELTON J M Division of Rules and Records. BO/11/28. ip.
- --Bi03170091 Forwards public version of Revision 10 to draft site smargency plan. MCEMEM.J E. Stafco, Inc. 79/12/31. ip. 016B2:002.
- --8101080207 Public version of Revision 10 to draft site emergency plants Baltimore Gas & Electric Co. 80/01/01. 300pp.
- Bi01070447 Releases public version of util emergency plan. FELTCN.J.H. Division of Rules and Records. 80/12/02. 1p. 07408: 099.
- --B101220599 Forwards public version of draft Revision 10 to util smergency plan REMERIE.T. Baltimore Que & Electric Co 80/02/19. 1g. 04141.115.
- --8101070449 Public version of draft Revision 10 to emergency plan.

- Bi0304D917 Approves requested extension of completion dates for fire protection node re-emergency lighting & reactor coolant pump oil collection Attachment to Bi0130 ltr & FR notice entl. DENION.H R. Dffice of Nuclear Reactor Regulation, Director Bi/02/13 4pp
- --B103040929 Notice of extension until B1060; for completion date of fire protection made CASE.E.G. Office of Nuclear Reactor Regulation. Director 81/02/13. 2pp
- 8103180264 Ltr to all power reactor licenses w/plants licensed prior to 750101 Forwards NRC gosition & request for addlinfo re safe shutdown capability for compliance u/801119 fire protection twile FISFEMBE, D 0 Division of Licensing 81/02/20 137p
- B103090189 Releases public version of energency response plan for facility
  FELTON J M Division of Rules and Records B1/03/02 1p
- --8103050197 Forwards public version of emergency response plan for facility consisting of States of MD, VA.DE & Washington.DC radiological emergency response plans Cross-ref against NUREO-0534 criteria enc! PRITCHETT.T N Baltimore Oas & Electric Co 80/12/31 7pp 07806:001
- --Bi03050211 Public version of energency response plan for facility.
  consisting of States of MD.VA.DE & Mashington.DC
  radiological emergency response plans
  e Raltimora 244 & Electric Co. 80/12/31 800no 07806:001
- Bj03310338 Ltr to ail licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl EIBENHUT.D 0 Division of Licensing. 81/03/05 6pp
- 8100270597 Forwards emergency planning into for placement in LPDR W/o B103050197 BOUDER, J. L. Division of Rules and Records. 81/03/11 lp. 08044-244
- BiO3270B07 Discusses plans for achieving compliance w/App R requirements re fire protection regulations Requests exemption from certain hose test & lube oil collection requirements Response to SER Item 3 2 1 revised BiO217 encl LUNDVALL. A E Baltimore Gas & Electric Co. 81/03/19 63pp. 08044.249.
- 8103270596 Requests 30-day extension to study evacuation time estimate. Study will be available after 810401 LUNDVALL, A E Baltimore Gas & Electric Co 81/03/20 ip 08043 151
- H. General correspondence
- 8103120180 Forwards amend package, including safety evaluation, for NRC authorization of increase in spent fuel pool storage repactity, per 790830 request. Original commitment to forward package inadvertently overlooked. W/o encis.

  CLARK, R. A. Operating Reactors Branch 3 81/03/03 12 07901 359
- 8103230505 Requests that add1 addresser be added to distribution list for correspondence to dockets. LUNDVALLA E. Baltimore Cas & Electric Co. 81/03/17, lp. 07979-337
- J. Insurance & indemnity information
- BiO3190417 Forwards Endorsement 5 to NELIA Binders E8-52 & 53 & Endorsement 5 to MAELU Binders X8-52 & 53 OAMMIE.Q.B. Beltimore Gas & Electric Co. B1/03/16 Spp. 07965:079.
- P. Operating license stage documents & correspondence
- 8103190732 Lits to all licensess of operating plants, applicants for OLs & holders of CPs recontrol of heavy loads. Requests raview per guidelines in NUREO-O612 Forwards NRC position reinterim actions & request for addi

- B103190397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737 FISELMITED & Division of Licensing B100119 & Spp
- 810312-3314 Limits all licensees of operating plants. CP holders & QL applicants, except Indian Point 2 & 3.21on 1 & 2 & TMI-1, forwarding inadvertently emitted pages from JRC 801222 request for addlinfore control of heavy loads EJSENHUT, D 9 Division of Licensing 81/02/03 App
- 8103300160 Ltr to all operating PMR licensess requesting info on auxiliary feedwator sys seismic design Forwards request for addl info. Hist of actions requested of licensees w/o spismically qualified sys & results of NRC walkdowns EISENMUT, D. O. Division of Licenseing 81/02/10 13pp
- B103160669 Ltr to all operating plants & CP holders forwarding clarification of TM1 Action Plan Item III A 1 2 re upgrade of erergency support facilities Requests confirmation within 45 days that implementation dates will be net. ESERNUT. D O Division of Licensing 81/02/18 12pp
- B103100097 Forwards "Partial Review of Equipment Evaluation by Off of Nuclear Reactor Regulation for BOSE, Calvert Cliffs Units ( & 2 " Written response required MOVAK.TM Assistant Director for Operating Reactors. B1/02/19 3pp 07866 017
- --8103100069 "Partial Review of Equipment Evaluation by Ofc of Nuclear Reactor Regulation for BOSE.Calvert Cliffs Units 1 & 2 " « Assistant Director for Operating Reactors 01/02/19. 29pp 07864-020
- 8102030539 Forwards Amends 50 % 32 to License DPR-53 % DPR-69respectively & notice of lescance & availability CLARKAR A Operating Reactors Branch G 81/02/20 3pp 07828.308
- --8103050547 Amends 50 & 32 to Licenses DPR-53 & DPR-69, respectively, adding requirement to maintain guard training to qualification plan for implementation within 60 days of Commission approval CLARK.R.A. Operating Reactors Branch 3 81/02/20. App 07828 311
- --3103050596 Notice of issuance & availability of Amenda 50 & 32 to Licenses DPR-53 & DPR-69, respectively TRAMMELL,C M Operating Reactors Branch 3 81/02/20 2pp 07828 315
- B103110509 Notification of B10226 meeting w/util in Dethesda/MD to discuss welling codes & resulting const adequacy of spot welds used in spent fuel pool racks for facility.
  CONKER.E. L. Operating Reactors Branch 3 B1/02/20. 2pp 02872 006
- B103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 critoria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  ETBENHUT.O Q. Division of Licensing 81/02/20 8pp.
- B103110217 Forwards request for add1 info on C-E owner's group submittel on "RCS Asymmetric Loads Evaluation Program," final rept Includes generic & plant-specific requests. CRUICHFIELD.D. Operating Reactors Branch 5. 81/02/23 27pp.07889.159
- B103030695 Postpones until B10701 response to NUREO-0737 action plan Item II 3.1 re reactor coolant vent sys LVNOVALLA E Baltimore Gas & Electric Co B1/02/25. Ip
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for DLs (except 8t Lucie. Units 1 & 2) Requests util review to determine capability to mitigate exation blackout event & promptly implement emergency procedures. EISENHUT.D O. Division of Licensing 81/02/25 3pp.
- 8103030764 Requests extension until 810701 to submit schadule for response to NUREO-0737 Item II.K 3.30 re small break LOCA codel.
  LUNDVALL-A E Baltimore Gas & Electric Co 81/02/26. 1p 07794-084
- B103230813 Generic Ltr 81-06 to all CP holders & OL applicants re IOCf850.71(e). "Periodic Updating of FSARs." effective B00722.1nfo re FSAR legal status.format & content anci. EIBENHUT.D G Division of Licensing B1/02/26.

- evaluation regt re environ qualification of safety-related electrical equipment will not jeopardize continued safe operation of facilities LUNDVALL, A E Baltimore Cas & Electric Co 81/03/03 200 0.7097 11A
- 8]03]0057] Forwards proprietary & nonproprietary versions of "Responses to First Round Questions on Statistical Combination of Uncertainties Program-Part 2 (CEM-124 (B)-MP) " LUNDVALLA E Baltimore Gas & Electric Co BI/03/07 600 07853 039
- --BIO3160573 Nangraprietary version of 'Responses to First Round Questions on Statistical Combination of Uncortainties Program Part, 2 (CEVI-124 (BI-NP) \* Combustion Engineering, Inc. BI/02/28, 22pp 07853 045
- 3103120173 Forwards amend package, including safety evaluation, for HRC authorization of increase in spent fuel puol storage capacity.per 791106 request Original commitment to forward package inadvertently overloused W/o encla CLARK, R A Operating Reactors Branch 3 81/03/03 1t 07901.35B
- 8103130476 Forwards responses to NRC 801104 ltr requesting info re containment sumps & insulation for operating reactors OLSON.R C Baltimore Gas & Electric Co 81/03/03 4pp 07907 023
- -- 8103130479 'Boer for Plant Insulation Except Reactor Cavity Insulation. \* Bechtel Payer Corp (subs of Bechtel Corp ) 75/01/23 12ao 07907 027
- --BIO3130483 "Spec for Plant Insulation Unit 2. Except Reactor Cavity Insulation. RCS & Steam Generators Insulation " ARNDLD.A J Bechtel Corp 79/04/18 19pp. 07907 039
- 8103100445 Forwards proprietary & nonproprietary versions of C-E responses to NRC first round questions re CEN-119(B)-P & CEN-119(B)-PP. "Detter Asial Bhape Belection " Proprietary responses withhely (ref 10CFR2 790). Affidayit ent. LUKDVALLA E Baltitore Gas & Electric Co. 81/03/04. 24pp.
- 8103120454 Forwards Class I & IV fees for BOLLIO application for OL Objection for the control of the con
- --BIO3120549 Act receipt of application fee re util Bio227 request. DI698.R. Liceuse Fee Management Branch. Bi/03/10. ip. 07901.233.
- B103;30432 Requests NRC review of proposed auxiliary feedwater systeming mode in light of info re costs & reliability installation of bypass valves around 1-AFH-161 & 2-AFH-161 does not significantly improve systeming bility. LUHDVALL, AE Baltimore Gas & Electric Co. 81/03/05. 3pp 07908 227
- 8103200244 Responds to NRC 810304 request for info re draft safety evaluation on implementation of recommendations for evalueuron on implementation or recommendations for autiliary feedwater sys Changes have been reviewed to ensure required flow capability to steam generator.

  LUNOVALL, A.E. Baltimore Oas & Electric Co. 81/03/09. 4pp.
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-(19 re info necessary to establish environ qualification of safety-related electrical FISHBUT.D C Division of Licensian 61/03/10 Ann
- 8103240470 Forwards evaluation of GEN-133(8). "FIESTA One-Dimensional Two Group Space-Time Kinetic Code for Calculating PMR Boram Reactivities." Rept acceptable for ref in licensing actions CLARK, R. A Decrating Reactors Branch 3. 81/03/13. Ip. 07981:335.
- --B103240475 Topical rept evaluation of CEN-133(B), "FIESTA One Dimensional Two Oroup Space-Time Kinetic Code for Calculating PMR Scram Reactivities "Rept acceptable 4 Operating Reactors Granch 3. B1/02/26 5p. 07981:337.
- BIO327042B Application to amend Olsschanging Tech Spec 3.4.1[ to reduce tare barrel movement nonitoring & reporting requirements
  LUNDVALL.A.E. Baltimore Oas & Electric Co. 81/03/23. 2pp 08045:035

- monitoring & reporting requirements \* Daitimore Gas & Electric Co. 81/03/23 3ng 08046-037
- 8103270487 Forwards proprietary & nonproprietary versions of "Environ Impact of Extended Burnup Fuel Cycles in Calvert Cliffs Units 1 & 2 \* Proprietary version available Central Files SHIP 05047 050
- --BIO3270494 Nonproprietary version of "Environ Tract of Extended Burn Fuel Cutles in Calvert Cliffs Units 1 & 2 Combustion Engineering. Inc. CEN-122(D)NP 81/03/31 35oo 08947 056
- 8103270570 Application for amend of CLs.Tech Specs Pages 3/4 1-3. 3/4 3-3.3/4 3-4.3/4 3-5.3/4 3-8.3/4 3-9 & 3/4 9-2 re alarm to alert operators of dilution event LU-DVALL.A E Baitimore Cas & Electric Co 81/03/23 4pp 08046 239
- --B103270602 Proposed changes to Tech Specs Pages 3/4 1-3,3/4 3-3, 3/4 3-4,3/4 3-5,3/4 3-8,3/4 3-9 & 3/4 9-2 re alarn to alert operators of dilution event \* Baltimore Das & Electric Co 81/03/23 1000 08046.243
- 8103260347 Forwards elementary wirring diagrams for auxiliary feedwater initiation circuit Facility annunciator mad table & drawing change notices encl Apareture cards are available in PDR. EVANS. MH Baltimore das & Electric Co BI/03/24 10pp.
- O Inspection reports. IE Bulletine & correspondence
- 8103129540 Forwards 1E loso Repts 90-317/80-22 & 30-318/80-18 on BRUNNER.E. J. Region I. Philadelphia. Reactor Operations Nuclear Bupport Branch - 01/01/15 | 2pp. 07904.272
- --8103120461 IE Imag Repts 30-317/81-22 % 50-318/80-18 on 811101-30 No noncompliance noted Major areas inspected: control room & accessible portions of auxiliary & radiation protection. ARCHITZELR E., CALLAHAN.C. J., BLAND, J.S. Region 1. Philadelphia. Office of the Director. 81/01/07 16pp 07904 274
- 8103020127 Forwards IE Info Notice 81-01, "Possible Failures of GE Type IFA Relays " No response required. GRIER.B M Region 1. Philadelphia, Office of the Director 81/01/16. Ip 07703 265
- 8103190673 Forwards IE losp Repts 50-317/80-25 & 50-318/80-21 on 801215-19 No nancompliance noted. BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch BI/01/21 2pp. 07964 072.
- --8103190676 IE inap Repts 90-317/80-25 & 50-318/80-21 on 801215-19 No noncompliance noted Major areas inspected general training. technician training, reactor operator requalification technician training, reactor operator requalification training & startup test program for Unit 1. Cycle 9.
  BETTENHAUSEN.L., TROBROSKI, W. Region I, Philadelphia, Office of the Director. CAPHION.D L. Region I, Philadelphia, Reactor Operations Nuclear Support Granch. BI/OI/19. 7pp. 07964 074.
- BIO3180603 Forwards update responses to IE Bulletin 79-018. Buppl 3, "Environ Gualification of Class IE Equipment" Test program for ITT Barton transmitters is scheduled for completion by Sept 1981 (I/o entls LUNDVALL, A.E. Baltimore Gas & Electric Co GI/02/03 2pp. 07933 350
- 8103040179 Forwards IE Info Notice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/IOCRRDO, 72 " No written response required.
  GRIER.B H Region 1. Philadelphia, Office of the Director.
  B1/02/12 Ip 07813-019
- 8103190679 Responds to 810127 IE Bulletin 81-01. "Burveillance of Mechanical Snubbers." Mechanical snubbers not used in safety-related applications LUNDVALL.A E. Battimore Gas & Electric Co. 81/02/19. 2pp. 07964: 055
- 8103300384 Ack receipt of 810209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-317/80-16 & 50-318/80-19. Notes understanding re liquid raduasts sys per BIO211 conversation BRUNKER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 81/02/20 Ip. 08057-339.

- ~-8103300398 Responds to ARC 810115 ltr re violations nated in 16 Insp Repts 50-317/80-16 & 50-318/80-15 Corrective actions oxygen analyses partian of gas analysing sys returned to syc in Dec 1980 LUNDVALL.A E Saltimore Gas & Electric Co 81/02/09 4pp 08057 340
- --8103300361 Forwards IE Insp. Repts 50-317/80-16 & 50-318/80-15 on 801001-31 & notice of violation EMPLYMENT J. Region J. Philadelphia. Reactor Operations Nuclear Support Branch 81/01/15 2pp 08:57-344
- --8103300362 Notice of violation from inep on 691001-31

   Region 1. Philadelphia. Office of the Director 81/01/12 4pp 08057 346
- --BI03300367 IS Insp Repts 50-317/80-16 % 50-318/80-15 on B01001-31 Noncompliance noted gas analyting sys oxygen analyter out of syc for past several yrs w/no 10CFR50 59 review or rept of change having been nase ARCHITIEL, R E . CALLAHAN, C J . BLANG. J S Region 1. Philadelphia. Oppine of she Director B1/01/12 24pp C8057-350
- BiO3200193 Forwards IE info Notice Bi-O4. "Cracking in Main Steam Lines " No response required GRIER.B H Region 1. Philadelphia. Office of the Director 81/02/27 1p 07972 034
- Bi03200182 Forwards IE Circular 81-03. "Inoperable Baismic Monitoring Instrumentation" No written response required GRIER.8 H. Region 1. Philadelphia. Office of the Director 81/03/02 ip 07966 187
- 8103200074 Forwards revised IE Bulletin Bi-Oi. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 % & Change in identification of facilities o/CP to which bulletin is applicable does not affect util requirements GRIER. B H. Region i. Philadelphia. Office of the Director 81/03/04. 1p. 07988 203.
- 8103200209 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Braater" No response required GRIER. B H. Region I. Philadelphia, Office of the Director B1/03/11. 1p. 0796B 322.
- , Reportable occurrences. LERs & related correspondence
- 8103040654 Forwards updated LER 80-043/03X-1.
  RUSSELL-L B Baltimore Oas & Electric Co B1/02/23 1p 07811-339
- ~-Bi03040857 Updated LER 80-043/03X-1. on 800Bi9 melfunction of disconnect device 89-32B occurred during maint Caused by failure of horseshoe clip retaining pin that connects sections of lintage. Clip replaced MENDERLICH.R. L. Baltimore Cas & Electric Co. Bi/02/23. 2pp 07811-339
- 8103110480 Forwards LER 81-009/03L-0 RUSBELL.L B. Beltimore Oas & Electric Co 81/03/05 1p 07859, 356
- --8103110487 LER 81-009/03L-0 on 810205 reactor protector sys channel 0 trip units bypassed. Caused by increase in temp detactor resistance, protably due to increased connection resistance in containment input removed from channel D LAGIEMSKI.J.S. RIZZD.P.Q. Baltimore Cas & Electric Co. 81/03/05. 1p. 07869-357.
- 8103260603 Forwards LER 81-012/03L-0. RWSSELL-L B. Seltimore Oas & Electric Co. 81/03/13. 1p 08039-314
- --Bi03260612 LER 81-012/03L-0.on 810213.while shifting from 1 to 2 running charging pumps.letdown relief valve CVC-345-RV lifted & failed to reseat.Possibly caused by pressure surge in line. Valve matls review being conducted.

  DAVIS-8. M., HUSEBY. D. E. Beltimore Oas & Electric Co. Bi/03/13. 2pp. 08035:315.
- 8100260882 Forwards LER 81-011/03L-0. RUBSELL-L.B. Baltimore Oas & Electric Co 81/03/13. 1p. 08036.291.
- --Bi03260B93 LER 81-0i1/03L-0: on 010212, thermal margin/low pressure & steam generator low pressure trip units bypased while investigating intermittent failures of reactor protective sys channel D steam generator pressure.

  LAGIEMBK1\_J\_8. R1ZZ0.P. 0 Baltimore Gas & Electric Co. 81/03/13.
  1p. 08036:29.

- Bi03260924 Forwards LER Bi-013/03L-0 AUSSELL-L B Baltimore Gas 5 Electric Co 91/03/17 1p 08036 307
- --B103260934 LER B1-013/03L-O on B10217 inboard turbine bearing journal in autiliary feeduater pump 11 cas found heavily host scored to abbit rations suspended in oil Probably coused by inproper oil level or contaminated oil Procedures Changed DAVIB.S N . PERCE. B Daltimore (as & Electric Co 01/03/17 200 08036 338
- DOCKET 50-318 CALVERT CLIFFS MUSLEAR POWER PLANT. UNIT 2 F. Becurity, medical, emergency & fire protection plans
- BioloBo2D1 Releases public version of util draft site emergency plan FELTON.J M. Division of Rules and Records 80/11/28 [p
- --8103170091 Forwards public version of Revision 10 to draft site emergency plan
  MCGUSULU E Staffor Inc. 79/12/31 1p. 01682-002
- ~-8101080207 Public version of Revision 10 to draft site emergency clan \* Baltimore Gas & Electric Co 80/01/01 300pp
- 8101070647 Releases public version of util energency plan FELTON J M Division of Rutes and Records. 80/12/02 1p 07408 099
- --Biol220599 Forwards public version of draft Revision 10 to util emergency plan REIMER.E T Baltimore Oas & Electric Co. 80/02/19 ip 0444 it5
- B103040917 Approves requested estension of completion dates for fire protection made re emergency lighting & reactor coolant pump oil collection Attachment to 810130 ltr & FR notice encl DENTON; HR Diffice of Nuclear Reactor Regulation, Director B1/02/13 4pp
- --8103040929 Notice of extension until 010601 for completion date of fire protection mods
  CASE.E 0 Office of Nuclear Reactor Regulation, Director 81/02/13. 2pp
- 8103180264 Ltr to all power reactor licenses w/plants licensed prior to 790101 Forwards NRC position & request for addl Info re safe shutdown capability for compliance w/801119 fire protection rule.

  EISENHUT-D O Division of Licensing. 81/02/20 13pp
- 8103050189 Releases public version of emergency response plan for facility.
  FELTON J M Division of Rules and Records 81/03/02. 1p. 07806:001.
- --8103050197 Forwards public version of smergency response plan for facility-consisting of States of HD, VA, DE & Washington, DC radiological smergency response plans, Cross-ref against NUREO-0654 criteria and PRIICHETT, I. N. Baltimore Gas & Electric Co. 80/12/31. 7pp 07804, 001.
- --Bi03050211 Public version of emergency response plan for facility.
  consisting of States of MD.VA.DE & Weshington.DC
  radiological emergency response plans
   Baltimore Gas & Electric Co. 80/12/31. 800pp. 07806:001
- G10331033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl. EISENHUT.D.G. Division of Licensing. 81/03/05. App.
- 8103270597 Forwards emergency planning info for placement in LPDR W/o 8103050197.
  SOUDER, J. L. Division of Rules and Records 81/03/11. Ip. 08044-944
- 8103270807 Discusses plans for achieving compliance w/App R requirements re fire protection regulations. Requests exemption from certain hose test & lube oil collection requirements. Response to SER ltem 3.2 irrevised B10219, and LUNDVALL. A.E. Baltimore Gas & Electric Co. 81/03/19. 63pp 08044:249.

- 8163270596 Requests 30-day extension to study evacuation time estimate Study until be available after 810401 LUNDVALL.A E Baltimore Gas t Electric Co 81/03/20 ip appear 191
- H General correspondence
- 8103120183 Forwards arend package, including safety evaluation, for NSC authorization of increase in spent fuel pool storage capacity, per 790830 request Original commitment to forward package inadvertently overlooked W/o encis
  CLARK, R.A. Operating Reactors Branch 3 81/03/03 1p 07901 359
- B103230505 Requests that addl addressee be added to distribution list for correspondence re Jockets LUNDVALL.A E. Baltimore Gas & Electric Co. B1/03/17 1p 07977-337
- J Insurance & indennity information
- 8103190417 Forwards Endorserent 5 to KGLIA Binders EB-52 & 53 & Endorsement 5 to MAELU Binders XB-52 & 53 GAMMIE: 0 B Dallimore Oas & Electric Co B1/03/16 Spp 07985 099
- P Operating license stage ducuments & correspondence
- 6103190732 Ltrs to all licensess of operating plants applicants for Dts & holders of CPs recontrol of heavy leads Requests review per guidelines in NAMEO-O612 Forwards NATO position reinterim actions & request for addlines info FIREINHITO O Division of Licensies 80/12/22 30cm
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs to program for onviron qualification of safety-related electrical equipment litems addressed involve cold shutdown, replacement parts & NUREO-0/27. EISENHUT.D Q Division of Licensing 81/01/19 App
- BIO3120014 Ltr to all licenses of operating plants, CP holders & OL applicants, except Indian Point 2 & 3.7 cm 1 & 2 & Inti-1, forwarding inadvertently unitted pages from NRC BO1222 request for addl info re control of heavy loads EISENHUT, D O Division of Licensing 81/02/03. Opp
- 8105020728 Forwards Arend 31 to License DPR-69, safety evaluation & notice of issuance & availability CLARK A Decreting Reactors Branch 3 81/02/10 3pp 07781:275
- --8103020732 Amend 31 to License DPR-69, authorizing cycle 4 operation of increase in fuel enrichment modified guide tubes for control element assembles 6 use of new reactor protection systrip CLARX-R A. Operating Reactors Branch 3. 81/02/10. 83pp 07781-278
- --BI03020735 Safety evaluation supporting Amend 31 to License DPR-69 \* Office of Nuclear Reactor Regulation, Director. 81/02/10 24pp. 07781 359
- --8103020739 Notice of issuance & availability of Amend 31 to License DPR-69 CLARA, R.A. Deprating Reactors Branch 3 81/02/10 2pp. 07/82 021
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design. Forwards request for addl info. list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISRNMUT.D.O Division of Licensing B1/02/10 13pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A 1.2 re upgrade of emergency support facilities Hequests confirmation within 45 days that implementation dates will be met. EISENHUT.D.O. Division of Licensing. 81/02/18 12pp.
- 8103100097 Forwards "Partial Review of Equipment Evaluation by Ofc of Nucleor Reactor Regulation for BOSE. Calvert Cliffs Units 1 & 2" Written response required.

  MOVAX.T.M. Assistant Director for Operating Reactors. 81/02/19
  3pp. 07864.017
- --8103100069 "Partial Review of Equipment Evaluation by Ofc of Nuclear Reactor Regulation for BG&E, Calvert Cliffs Units 1 & 2 " \* Assistant Director for Operating Reactors: 81/02/19, 25pp. 07866:020

- B103050537 Forwards Amends 50 & 32 to License DPR-53 & DPR-69, respectively & notice of issuance & availability CLARK, B A Derating Reactory Branch 3 81/02/20 3pp 07828 30
  - --Biogopo547 Amends 90 & 32 to Licenses DPR-53 & DPR-69, respectively, adding requirement to maintain guard training & qualification plan for implementation within 60 days of Commission approval CLARK-R A Operating Heactors Branch 3 Bi/02/20 4pp. 07894 311
- --8103050556 Notice of issuance 5 availability of Amends 50 & 32 to Licenses DPR-53 & DPR-69, respectively TRAMMELL C M Operating Reactors Branch 3 81/02/20 2pp 02808 315
- BIODIIO50<sup>©</sup> Notification of BIO226 meeting w/util in Bethesda.MD to discuss welding codes 3 resulting conts adequacy of spot welds used in spent fuel pool racks for facility CDNNER.E.L. Operating Reactors Brench 3 BI/02/20. 2pp D7072 DDA
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Excensee may submit analysis to justify use of existing low flow controller EISENHUT. D 0 Division of Licensing 81/02/20 Opp
- 8103110217 Forwards request for add1 info on C-E owner's group submittal on "RCS Asymmetric Loads Evaluation Program," final rept Includes generic & plant-specific requests. GRUTCHFIELD.D. Operating Reactors Branch 5 81/02/23 27pc
- 8103030695 Postpones until 810701 response to NUREO-0737 action plan Item II 8 I re reactor coolant vent sys LUNDVALLA E Baltimore Gos 8 Electric Co. 81/02/25 Ip
- G103230930 Ltr to all licensess of operating nuclear power plants & applicants for OLs (except 9t Lucie-Units 1 & 2) Requests util review to determine capability to mitigate station blactout event & prorptly implement emergency procedures ETSENHUT. D G Division of Licensing 81/02/25 9pp
- 8103030764 Requests extension until 810701 to submit schedule for response to NUREG-0737 Item II.K. 3 30 re small break LOCA codol.

  LUNDVALLAR E Baltimore Gas & Electric Co B1/02/26. 1p 07776-094
- 8103230813 Generic Ltr 81-06 to 411 CP holders & D. applicants re ICCFRSO 71(e), "Poriodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl. EISEMHULD 2. Division of Licensing 81/02/26.
- B103090385 Advises that deficiencies identified in NRC 010219 evaluation rept re environ qualification of safety-related electrical equipment will not jeopardize continued safe operation of facilities
  LUNDVALLAR E Saltimore Gas & Electric Co. 01/03/03. 2pp 02892 LIA
- 8103120173 Forwards amend package including eafety evaluation for NRC authorization of increase in spent fuel gool storage capacity per 791106 request Original commitment to forward package inadvertently overlooked W/o encis
  CLARK.R.A. Operating Reactors Brench 3 81/03/03. Ip 07901 358.
- Bio3130476 Forwards responses to NRC 801104 ltr requesting info recontainment surps & insulation for operating reactors
  OCSDN.R.C. Baltimore Gas & Electric Co. 81/03/03 4pp 07907:023
- --Bi03130479 "Spec for Plant Insulation Except Roactor Cavity Insulati RCS & Steam Generators Insulation." \* Bechtel Power Corp (aubs. of βechtel Corp.) 79/01/23. 12pp. 07907 027
- --B103130483 "Spec for Plant Insulation Unit 2. Except Reactor Cavity Insulation.RCB & Steam Generators Insulation " ARMOLD.A J Bechtel Corp. 75/04/18 15pp. 07907:039
- 8103120484 Forwards Class I & IV fees for 801110 application for OL amends in response to NRC B10219 request Application proposed changes to six areas of facility Tech Specs re TMI-2 Lessons Learned Category A Items. OLSON.R.C. Baltimore Oas & Electric Co. 81703/04. Ip. 07901.232
- --8103120949 Ack receipt of application fee re util 810227 request. 01698 R. Licanse Fee Management Branch 81/03/10. ip 07901-233

- G103130432 Requests NRC review of process ausiliary feedbater systemsign mode in tight of inforce costs L reliability [nestallation of bipass valves around 1-AFH-161 to 2-AFH-161 does not significantly improve systematicallity LUNDVALLIA E Battimore Oas L Electric Co. 81/03/05 3;F named DO27
- B103200244 Responds to NRC 810304 request for info re-draft safety evaluation on implementation of recommendations for auxiliary feeduater sys Changes have been reviewed to ensure required ficuly capability to steam generator LUNDVALL.A E. Jailinone Gas & Electric Co. 81/03/09 4pp
- 8103310804 Ltr to all licensees of operating plants applicants for CLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment
  FISENHUT.D 9 Division of Licensing 81/03/10 App
- BIO3240470 Forwards evaluation of CEN-133(B). "FIESTA Cha-Dimensional Iwo Group Space-Tire Kinetic Code for Calculating PMR Scren Reactivities." Rept acceptable for ref in licensing actions for vertous ORE which require reactor trip CLARK A Cocreating Reactors Branch 3 81/03/13 ip 07781 335
- --BI03240475 Topical rept evaluation of CER-123(B). 'FIESTA.One Dimensional Two Oroup Space-Time Kinetic Code for Calculating PMR Scram Reactivities "Rept acceptable • Operating Reactors Branch 3 BI702726 Spp 07981 337.
- 8103270428 Application to amen: OLs changing Tech Spec 3 4 11 to reduce core barrel novement monitoring & reporting requirements LUNDVALL. A E Saitimore Cas & Electric Co 81/03/23 2pp 08046 035
- --BIO3270433 Proposed Tech Spec 3 4 11 reducing core barrel movement monitoring & reporting requirements 9 Baltimore Gas & Electric Co 81/03/23 3pg 08046 037
- 81032704B7 Forwards proprietary & nonproprietary versions of "Environ Impact of Extended Burnup Fuel Cycles in Calvert Cliffs Units 1 & 2 " Proprietary version available Central Files only UNIVALL, A & Baltinore Gas & Electric Co. 81/03/23 opp. 08047-050
- --8103270494 Nanproprietery version of 'Environ Impact of Extended Burnup Fuel Cycles in Calvert Cliffs Units 1 & 2 " • Combustion Engineering, Inc. CEH-122(B)NP 81/03/31 35pp 08047, 056
- B103270570 Application for amend of OLs. Tech Specs Pages 3/4 1-3. J/4 3-3. J/4 3-4. J/4 3-5. J/4 3-8. 3/4 3-9 & J/4 9-2 re alarm to alert operators of dilution event LUNDYALL. A E Baltimore Cas & Electric Co B1/03/23 App
- --8103270602 Proposed changes to Tech Specs Pages 3/4 1-3.3/4 3/3.
  3/4 3-4.3/4 3-5.3/4 3-8.3/4 3-9 & 3/4 9-2 re alarm to alent operators of dilution event # Baleimore Das & Electric Co. 81/03/23 | 1000 | 08046 243
- 8103260547 Forwards elementary wiring diagrams for auxiliary feedwater initiation circuit Facility annunciator mod table & drawing change notices entl Aperature cards are available in PDR EVANG.K H Baltimore Oas & Electric Co 81/03/24 1035
- 8103270706 Forwards corrected tech Bpec Figure 2.2-3 re util 801204 fourth cycle license application EIPPOLD.W J Baltimore Qas & Electric Co. 81/03/24 lp. 08045 102
- --Bi03270708 Proposed Tech Spec Figure 2 2-3 re thermal margin/low pressure trip setpoint. • 8altimore 9as & Electric Co. 81/03/24. ip. 08045:103
- G Inspection reports: IE Bulletine & correspondence
- BIO3120640 Forwards IE Insp Regts 50-317/80-22 & 50-318/80-18 on 801101-30. No noncompliance noted BRUNNER.E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch 81/01/15 2pp. 07904-272.
- --8103120561 IE Insp Repts 50-317/81-22 & 50-318/80-18 on 811101-30. No noncompliance noted Major areas inspected control roun & accessible portions of auxiliary & radiation protection. ARCHITZEL-R E., CALLAHAN.C J. BLAND.J B Region 1, Philadelphia. Office of the Director 81/01/07. 16pp 07904:274.

- BI03020127 Forwards IE Info Notice 81-01. "Possible Failures of GE Type
  MFA Releys" No response required
  SRIER.B H Region 1. Philadelphia. Office of the Director
  81/01/16 p 07785 265
- 8103190573 Forwards IE insp Repts 90-317/80-25 \$ 90-318/80-21 on B01215-19. No noncompliance noted BRUNKER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Grants 81/01/21 2pp 07964 072
- --Bi03199576 IE Insp Repts 50-317/80-25 % 50-318/80-21 on 801215-19 No noncompliance noted Major areas inspected general training, technician training, reactor operator requalification training & startup test program for Unit I.Cycle 5 BETTERHAUSEN.L. TROSKOSKI.W Region I. Philadelphia, Office of the Director CAPHION.D L Region 1, Philadelphia, Roactor Operations Nuclear Support Branch 81/01/19 7pp 07964 074
- 8103180603 Forwards update responses to IE Bulletin 77-018.8uppl 3. "Environ Qualification of Class IE Equipment " Test program for ITT Barton transmitters is scheduled for completion by Sept 1981. I/O encis
  LUNDVALL.A E Baltimore Gas & Electric Co. 81/02/03 2Fp. 07993 350
- 8103040179 Forwards IE Info Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CFR99 72 " No written response required GRIER.B H. Region I. Philadelphia. Office of the Director 81/02/12 ip 07813 019
- 8103190679 Responds to 810127 IE Bulletin BI-O1, "Surveillance of Mechanical Snubbers | Mechanical snubbers not used in safety-related applications.
  LUKDVALLA E Baltimore Gas & Electric Co 81/02/19 2pp.
  07944 095
- B103300354 Ack receipt of B10209 itr informing NRC of steps taken to correct violations noted in It Insp Repts 50-317/80-16 & 50-318/60-15 Notes understanding re liquid radwaste eys per B10211 conversation BRUINER.E J Region 1. Philosolphia. Reactor Operations Nuclear Eurport Branch B1/02/20 is 08057 339
- --Bi0330035B Responds to NRC Bi0115 lir re-violations noted in IE Insp Repts 50-317/B0-16 & 90-318/E0-15 Corrective actions orygen analyzer portion of gas analyzing sys returned to svc in Duc 1980 LUNDVALL.A E Baltimore Oas & Electric Co 81/02/09 App 08057-340
- --Bi03300361 Forwards lE linep Repts 50-317/80-16 % 50-318/80-15 on 801001-31 & notice of violation BRUNNER,E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 81/01/15 2pp 08057-344
- --81033C0362 Notice of violation from insp on 801001-31.

   Region i. Philadelphia. Office of the Director 81/01/12 App 80597 346
- --8103300367 IE Insp Repts 50-317/80-16 & 50-318/80-15 on 801001-31 toncompliance noted gas analyting sys oragen analytes out of set for past several yes wine 10CFR30 37 review or rept of change having been made ARCHITZEL.R E. CALLAHAN, C.J. BLAND, J. B. Region 1, Philadelphia. Office of the Director. 81/01/12. 24pp 08097-390
- B103200193 Forwards IE Info Notice B1-04. "Cracking in Main Steam Lines." No response required. GRIER.B.H. Region i. Philadelphia. Office of the Director. B1/02/27 ip. 07972 034
- 8103200192 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No written response required CRIER.8.H. Region 1, Philadelphia, Office of the Director. Bi/03/02. 1p 07966 197
- 8103200074 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements.

  ORIER, B. M. Region I. Philadelphia. Office of the Director 81/03/04. 1p. 07968 205
- 8103200209 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required GRIER.8 H. Region 1. Philadelphia. Diffice of the Director. 81/03/11 1p. 07968 322

- g Resortable occurrentes, LFRs & related correspondence
- 8103060938 Forwards updated LER 81-002/03L-1 RU38ELL.L B Raltimore Gas \* Electric Co B1/03/01 [p 07837 167
- --BIGGO60545 Updated LER 81-002/03.-1 on Bi010B & 0227 diesel generator 12 started automatically Generator was stopped & start failure alarm received Cauped by insufficient contact mipe by local break glass start switch Actuator fitting removed LAGIEMSXI.J S. RIZZO.F O. Baltirore Cas & Electric Co. Bi/03/01 2pc. 07837 188
- 8103263635 Forwards CER 81-010/03C-0 RUSSECLUL 8 Saltimore Gas & Electric Co. 81/03/17 1p 08035-325
- --BIOJ260645 LER BI-Cl0/OJL-O on G10J01.pocer-operated relief valve ERV-402 failed to seat resulting in valve isolation. Caused by insufficient pressure in sys while filling RCS Pressure raised & valve seated #ENDERLICH.R L. RAYBURN.C L. Baltiture Qas & Electric Co BI/OJ/17 2pp 0E035 J26
- COCKET 90-320 THREE MILE IGLAND MUCLEAR STATION, UNIT 2
- 8102270852 Partial response to FOIA request for documents written by BC Rusche during tenure w/MCC Forwards documents listed in App A FELTOM J. H. Division of Rules and Records 81/02/04 2pp 07/77 075
- F. Security, medical, emergency & fire protection plans
- 9103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info re safe shutdown capability for compliance w/E01119 fire protection rule
  EISENEVIT.D D Division of Licensing 81/02/20 13pp.
- B1031000BB Requests that enci emergency planning into be made publicly available W/a enci SOUDER-JL Division of Rules and Records 81/02/27 ip 07493-172
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for neeting NRC requirements U/o encl EISENIUT.D G. Division of Licensing. 81/03/09. 6pp.
- 8103170518 Advises that emergency preparedness exercise & drill will be conducted in Dec 1701. in response to NRC 801224 request Util complement to quarterly NRC-evaluated exercises should be deleted.

  HCVEY.G K. Metropolitan Edison Co. 81/03/12 2pp 07930 112
- 8103300387 Requests exemption from completion time requirements of new fire protection requirements Facility remains in cold shutdown which requires no active support for active core cooling MOVEY: 0 K Metropolitan Edison Co 81/03/24 3pp 08055.313
- G Adjudicatory correspondence
- 8103020664 Ack receipt of \$5,000 in payment of proposed civil penalties per 800807 notice of violation Forwards order imposing civil penalties per 800807 notice of violation.

  STELLO.V Director's Office. Office of Inspection and Enforcement 81/02/10. 2pp 07782 048
- --8103020672 Order imposing civil monetary penalty in amount of \$2.000 for noncompliance re transportation of radwaste. Evaluations & conclusions encl.

  5TELLO.V. Director's Office. Office of Inspection and Enforcement 81/02/10. App. 07782-050
- 8103180693 Requests to make limited appearance statement at restart hearing Expresses concern ne Unit 2 cleanup & opposition to Unit 1 being reopened Response requested MINNICH M Affiliation Unknown 81/02/24 p. 07945-092.

- 8103:09772 Discusses scheduling meeting between NRC. Het Ed & Environ Coalition on Nuclear Power during up of 810316 Meeting to determine if total or partial settlement of intervenor contentions is possible
  LEVIE.5 H Hearing Branch 2 81/03/92 ip 07862 242.
- 8103110339 Forwards J Levendusky affidavit in support of confidentiality request per 1005FR2 790 Affidavit prepared in accordance w/tRC 810122 ltm to Met Ed Affidavit withheld (ref 1005FR2 790)
  BAIL J N Carella, Rain, Gilfilan & Rhodes 81/03/05 ip 076FR2 103
- B103120297 informs that NRC will file testimony on remaining right capability issues on or before which filed Testimony on testign mod will be during which of B10316 & 23 Mgt capability issues will begin around B10331 SHAYSON-0 T. Hearing Branch 1 B1/03/09 2pp. 07900.198
- --B103120272 Responds to B10130 ltr re info flow during 1M1-2 accident Failure of important info to reach NRC was inequestle Util entires are questionable New legislation not required. Regulations modified to impose clear reporting duties. BRADFORD.P.A. Commissioners 81/02/24 3pp 07900-212
- --Bi03120285 Responds to request for personal views re info flow Juri TMI-2 accident Persons in charge were unaward of or did not understand indications of core damage & gross degradation Recommended enforcement actions inconsistent u/facts. MICHELSON.C Director's Office Bi/02/20. 3pp 07900 215
- H General correspondence
- 8103261031 FOIA request for documents & info re consideration.plannin esecution or utilization of two studies by P Slovic & EJ Walsh concerning IMI CDMEN.R L Affiliation Unknown 81/02/12 2pp. 08035-326
- BIO3099073 Responds to BIO121 ltr recurrent status of afforts to regolve cornerns wistorage of EPICDR-11 resime Provisions include substantial containment of liners & contents & sampling of liquids collected in sump of storage modules SYNDER.B J INT Program Office. BI/02/18 2pp 07892 152
- 8103180383 Opposes restart of TMI-1 until TMI-2 has been cleaned up. ENSINGER.S. Affiliation Unknown 81/02/22 1p.
- B103180597 Urges closer supervision of nuclear energy production MADDOX: H Affiliation Unknown. 81/02/22 1p. 07944-271
- 8103080692 Responds to B10114 ltr re amount of accident water release into Busquehanna River Approx 2.776.000 gallons were released from 790328-0420 Releases did not approach Tech Spec action limits SNYDER.B. J. TMI Program Office 81/02/24. ip 07836:109
- B103170357 Opposes reopening of TMI-1 & -2 Implementation of evacuation plan inadequate

  Affiliation Unknown B1/02/24. 1p.
- 8103130724 Ack receipt of 810107 comments re TMI programmatic EIS. 549DER.B J. TMI Program Office 81/02/25 ip.
- --B103130732 Forwards comments re TMI programmatic EIS B0088.P A Affiliation Unknown 81/01/07. le
- --8193120736 Comments on programmatic DES for fatility redecontamination NTC has not properly informed public norgiven clear picture of radwarts decontamination & disposal, 80046.9 A Affiliation Unanoun 80/11/18 Spp.
- 8103170497 Urges permanent shutdown of facilities.
  DAVIB.B Affiliation Unknown 81/02/25 1p. 07935-276
- B103190310 Supports early restart of Unit 1 & continuation of cleanup of Unit 2 WACK03-H M Affiliation Unknown 81/02/25, 3pp. 07586:001.
- 8103170394 Recommends that NRC turn more attention to safety issues arising from facility accident. ALLBAUGH.C Affiliation Unknown. 81/02/27 2pp.
- B103190007 Advises that rescheduling of 810306 luncheon/meeting for Lancaster & Lebanon Chambers of Commerce to 810617 is acceptable Requests viewgraph projector for use during talk HENDRIE.J. M. Commissioners 81/02/27 ip. 07960-106.

- of Commerce has been rescheduled for B10517 Requests attendance WALMER R S House of Rep B1/02/23 ip 07960 107
- 8103170650 Daposes facility restart 67-89058.0 Affiliation Websen 81/02/28 to 07585-001
- B103190468 Forwards resolution on TH1~2 & revised resolution or TH1~1, on behalf of Charbor of Commerce Supports facility restart W/o revised TH1~1 resolution ORIGHLAF Berks County, Lesscort, PA 81/03/02 2nc 07965 2A7
- 8103170352 Urges RRC to keep TMI-2 in operation 5 TMI-1 respond 56RY56UR12.1 A Affiliation Unknown 81/03/04 to
- 8103180648 Responds to itr requesting federal aid to expedite cleanup of Busquehanna River following TMI accident Delays are due to development of cleanup methodology rather than insufficiant funding FCCOE.W H HMS. Dept of US Public Health Service 81/03/04 Ip 07994 183
- B103190467 Urges restart of Unit 1 & Cleanup of Unit 2 Middletoun.PA area bally needs electricity produced by facilities OVERDER.E G Affiliation Unknown B1/03/05 200 07956 065
- B103200620 Comments by Pennfield Corp re facility restart Util has learned lessons from accident Supports restart BRECKERRIDGE.P Pennfield Corp 81/03/05 2pp. 07971 253
- 8103180692 Cornents that federal aid should be granted to expedite cleanup & haiard randval for people dounstream along Susquehanna River.
  BURSSR 0 Affiliation Voltnoum RIVORAD 16 07970 179
- 8103160977 Submits info re constrengineering & design of TMI (n response 810224 request SNYOER 8 J TMI Program Office 81/03/10 ip 07921.160
- --BIO3160983 Requests info re const. engineering & design of TMI HEIMBUECHER. J. Affiliation Unknown BI/02/24 lp 07921 161
- 8103180445 Forwards AUREO-OLB9, "Potential Impact of Licensee Default on Cleanup of TMI-2" Final programmatic EIB re disposal & decontaination of raduasties prepared TMI-1 restart to be decided after ASLB hearing termination
  DENTON-H R Defice of Nuclear Reactor Regulation, Director 81/03/10 to 07953 099
- n-Bi03180453 Forwards Business. Industrial & Prof Association Bi0211 resolution.re TM1-2 recovery cost sharing, funding mechanism for gout & industry supported nuclear insurance program. cleanup costs & TM1-1 restart FREMSTAD.8 & Business. Industrial. & Professional Association. Bi/02/20 3pp 07953 101
- G1031G109B Responds to G10206 litr expressing contern re health effects of nuclear power NRC & state & local govts have improved response mechanisms around nuclear power plants info re health effects from rediation encl
  DENICN.H R Office of Nuclear Reactor Regulation, Director B1/03/11 S4pp
- B103170403 Questions safety & feasibility of INI-1 restart beside TMI-2 cleanup operation Cites atmosphere of intense public scrutiny & carns of catestrophic consequences of any significant accident EDDLEMAN.W Affiliation Unknown 81/03/16 ip
- B103190900 Submits proposed resolution on cleanup of TML Cleanup process should proceed as quickly as possible.

  \* Lebenon County, PA 81/03/16. 2pp 07965:258.
- B103270014 Act receipt of B10209 itr re effect of advisury panel operation on non-voting members NRC requested Governor of PA to designate one state representative as voting member of IMI Citizens Advisory Panel.
  HENDRIE.J M Commissioners B1/03/17 Ip. 08047.092
- --B103270016 Submits mod to proposal of substituting non-voting observers for Commonwealth representatives on THI Citizens Advisory Panel. Requests that at least one observer be designated as active voting masher of panel.

  HENDRIE.J M. Commissioners. 81/03/17. 1p. 08047.093

- Advisory Panel Governor has been requested to consider at least one voting state representative MIMMICH JE Boyphin County PA 61/02/09 ip 08047 074
- ---BIO3270021 Discusses reasons for replacing three state representatives on TMI Citizens Advisory Panel re decontamination whom-voting observers THORNBURGH, D. Pennsylvania. State of 81/02/02 2pp 08047 095
- 8103270702 Responds to 1tr submitted on behalf of CP Smith re restart of Unit 1 t cleanup of Unit 2 final EIB on Unit 2 concludes that existing methods are adequate to perform cleanup AGLB decision on restart uill be made in late 1981 KANMERER. C Office of Congressional Affairs 81/03/19 ip AGNAT 049
- B103261024 Responds to FDIA request for Jocuments re consideration, planning, statution or utilitation of two studies by P Blovic & EJ Walsh concerning TMI Forwards NUREO/CH-1093, MUREO/CH-1213 & RJ Budnit; R30229 mean 470 encis FELTON.J M Division of Rules and Records 81/03/23. Ip

## 1 Financial information

- 8103170387 Submits rept for Jan 1981 of progress made toward curtailing util expenditures to remain within credit available through Spring 1981 Consination of factors reduced need to borrow & credit available progressing the progressing of t
- B103120222 Motifies that primary contact for cleanup cost estimates cill be GE Myers
  MUXILL-H D Metropolitan Edison Co B1/03/09. 1p 07904 355.
- P Operating license stage documents & correspondence
- 8103180864 Cornents on NURED-0683 re draft programmatic E19 for decontamination it disposal of radwaytes from TM1-2 accident Suggests radwaytes be entumbed in TM1-2 containment Propagers encl BR053-1D Roswell Park Herorial Institute BD/09/03. 29pp 07944-272
- --8103180873 "A 1980 Reassessment of Health Hazards of Low Level Johning Radiation " BROSS, I D. Adswell Park Memorial (Institute 80/03/15 31pp 07944.301
- --8103180880 Comments on "Graft EIG Hest Valley Liquid High Level Waste Innobilitation Project (WVLH, NIP) | BROSS: I D | Roswell Park Menorial Institute | 60/02/02 | 20pp 07933-256
- 8103180889 Comments on NUREO-0683. 'Oraft Programmatic EIR re Decontamination & Disposal of Radvastes Resulting from 790328 Accident Tril-2 " Alternate means of disposing of radwastes should be thoroughly investigated MDRRFS-A E Lancaster, PA 60/11/19, 4pp. 08165-043
- 8103190732 Lirs to all licenses of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position reinterim actions b request for addition of EISENMUT.D.O Division of Licensing 80/12/22 30pp.
- BiO31903B7 Ltr to all licensess of operating plants & applicants for Oss & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREQ-0737 EISENHUT. D O. Division of Licensing. BI/OI/19 & Opp.
- B103170134 FQIA request for documents providing retourological data for areas surrounding TMI site magnetic tapes u/hourly data summaries for 790328-0501 & repts describing methodologies MANNER.A Berger, D 81/02/02 ip 07939-058.
- 8103120014 Ltr to all licensess of operating plants CP holders & OL applicants, except Indian Point 2 & 3.2ion 1 & 2 & TMI-I, forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads. EISENMUT, D O. Division of Licensing. 81/02/03 6pp.
- 8103060786 Summary of neeting B10108 u/General Public Utils & Mat Ed at TMI site re-baron dilution & recriticality, PDINDEXTER, T C . NEWBERRY, B. TMI Program Office B1/02/06. 9pp. 07837:289

of the to all operating PWR licensess requesting info on O Ltr to all operating PMK licensees requesting into ing feedwater sys seismic dasign Forwards request for fo.list of actions requested of licensees w/o ally qualified sys & results of NRC walkdowns r.O. 9 Division of Licensing Bl/OZ/10 lapp

9 Ltr to all operating plants & CP holders forwarding cation of TMI Action Plan Item III A 1 2 re upgrade gency support facilities Requests confirmation within that implementation dates will be not 1.0 0 Division of Licensing 81/02/18 12cp

6 Ack receipt of NRC 810106 ltr re util 801104 description of ency plan for transfer & storage of reactor ment bidg sump water Response forthcoming ... Metropolitan Edison Co. 81/02/20 1p. 07815 208

4 Ltr to all power reactor licensees & license applicants re 4 Ltr to all power reactor licensees & license applice 619 criteria Footnote 2 in Table 2 contains error due age testing deletions Licensee may submit analysis to use of existing low flow controller T.D.9 Division of Licensing 81/02/20. Opp

7 Forwards application for arend to License DPR-73 submitted Spac Change Request 26 Certificate of Svc enc] K. Metropolitan Edison Co. 91/02/23 2pp. 97785 162

413 Application for amend to License DPR-73 submitted as Tech Change Aequest 26 for Apps A & 3 .9 K Metropolitan Edison Co. 81/02/23 13pp. 07785 164

420 Proposed Tech Spacs 2 1.2.3a-b.3/4 6 1.5.7/4.6 4.3 6 1.3-5. .3 6 2 4 1.3 3 7 7 1.3 7 10 1-2.3 9.12-13.4 6 1. 1.3-5.5 1 1-2.5 2 1-2.6 3.1.6 4 1-2.6 5 1 1-2.Tables -11.2 7-1.2 3-2.4 3-6.10 8 Pages 2-13.14.2 1-3a et al tropolitan Edison Co 81/02/23 29pp 07785-177

9 Forwards pretiminary assessment of potential source of clides found in ground of TM1, in response to NAC request New data confirms that borated water storage dominant source of contamination K Metropolitan Edison Co 81/02/23 66pp

7 Requests that NRC utilize special panel to independently upgraded util radiological control program during Apratus of mgt plan committed actions to resolve NRC panel finalings encl
R.C. Metropolitan Edison Co. 81/02/24 48pp 07789-063.

9 Respands to NRC BIO112 request for contingency plan for It liners in extended storage Plan will not be ed until 810313 B. Metropolitan Edison Co. 81/02/24 ip. 07795:175

Metropolitan Edison Co. 81/02/24 1p. 07799:179

2 Requests add1 info re util 810119 cork seel contamination -137 & 3r-93 ratio in cort seal samples; sources of n cort seal cavity & plans for monitoring areas tage from containment bild sump are needed. .L. H. FMI Program Office. 81/02/24 Spp. 07839 054

O Requests estimate of gallons of water released to anna River during whof 790328 & info re ration of radioactive matls A Affiliation Unknown. 81/01/14 to 03904:259.

O Requests addl infore util 800626 request for permission to A-R & GMR-1 canisters for protection against late radionuclides Util must submit acceptable program & tost data prior to use of canisters. L.H. This program Office. 81/02/25 5pp. 07839.042

O Ltr to all licensees of operating nuclear power plants & nts for OLs (except 6t Lucie,Units 1 & 2) Requests view to determine capability to mitigate station tevent & promptly implement emergency procedures. T.D.O Division of Licensing 81/02/23. Spp.

3 Advises that programmatic 618 is scheduled for issuence in 1 & will include update on time & cost estimates, in e to 810208 itr.
B.J. TMI Program Office. 81/02/25 ip. 07974:359.

290 Requests info re update on programmatic E18 (NUREO-0583). LS:A O. Affiliation Unknown. 81/02/08. Ip 07974:360.

8103230973 Notifies of issuance of NURED-0757, 'Radon Releases From U Mining & Milling & Calculated Health Effects," which contains new info potentially relevant & matl to ASLAS proceedings
TERRY, O A Division of Fuol Cycle & Material Bafety. 81/02/26
2pp 08022 227

BIO305047B Submits results of offsite analyses re identification of contamination source of cort mat) used for expansion joints tetween reactor & advacent bloos Probable cause is transport of RCS leakage to seeks during Jecontemination HDVEY. G K Metropolitan Edison Co B1/02/27 Spp 07836 230

8103100431 Responds to Chairman Ahearne 810112 request for positive action re containment bldg entries Planned entries are currently limited to approx one per conthidue to financial restrictions. HOVEY, O.K. Metropolitan Edison Co. 81/02/27. 200 07855 213

8103119143 Advises that proposed design re-processed water storage tanks is not adequate to provide control over release of radioactive matis in accordance w/Criterion 60.General Design Criteria. App A. IOSERSO Requests solution by BIO315 BARRETY, L H TML Program Office B1/02/27 App 07884 07884: 301

H103124039 Forwards 801222 & 810203 generic lins he control of heavy loads Biandby pressure control sys.EPICDR-11 sys.tank farm in Spent Fuel Pool A & submerged demineralizer sys require protection from heavy loads SNYDER, B J TMI Program Office 81/02/27 2pp 07900 305

~-B103120047 Ltr to all licenspee of operating plants applicants for DLs 5 holders of CPs re-control of heavy loads. Util must review controls of heavy loads to determine compliance U/NUREG-0612
E18EN:U1.0 0 Division of Licensing 80/12/22 3pp 07700:307

--8103120056 Ltr to all licensees of operating plants, applicants for QLe & holders of CPs re control of heavy loads. Forwards missing pages to Encl 3 of 801222 generic ltr W/related info EIBCNNUT.D G Division of Licensing 81/02/03 24pp 07900 310

8103160089 Forwards paper re effects of tritium Paper discusses potential environ impacts & health effects of tritium in general w/specific examples of analyses around TMI. DIRCKEN J Office of the Executive Director for Operations 81/03/03 4pp 07918 181

B103100522 Informs that response to NRC B10224 request for add1 infore cark seal contemination was supplied in util B10227 Itr Info balance to be submitted by B10327 HDVEV.O K Metropolitan Edison Co. B1/03/05 lp. 07853:105

8103120821 Submits comments & resolutions by review of 800725 aubmittal of 800616 radiation protection plan. Revision 2. Radiation protection plan acceptable w/incorporation of resolutions. Evaluation enci BARREIT, L H TMI Program Office. 81/03/05. 2pp. 07905: TKL Program Office. 81/03/05, 20p. 07905:032.

~-8103120823 "Evaluation of Radiation Protection Plan " TMI Program Office 81/03/05. 5pp. 07905:034.

8103170128 Responds to FOIA request for documents providing meteorological data for areas surrounding TM1 site.magnetic tages u/hourly data surmaries for 790328-0501 & repts describing methodologies. Forubards App A documents.
FELTON.J.M. Division of Rules and Records 81/03/05. 3pp 07939 035

--8103170139 Twek Specs Pages 2-7 through 2-15 re limiting conditions for operation & monitoring requirements for gaseous effluents a Matropolitan Edison Co. 81/03/05. 9pp

8103180060 Transcript of 810309 meeting in Washington DC re briefing on programmatic EIS for TM1 Pp 1-69 e Commissioners 81/03/09 66pp

--BiO3180071 Provides Commission w/programmatic EIB. "Decontamination & Disposal of Radwastes Resulting From Mar 20,1979 Accident at TMI-2." & proposed statement of policy by Commission on DIRCK9.W.J. Office of the Executive Director for Operations. 9£CY-81-133. 81/02/27. 5pp. 07942:310.

- --BiO3180075 hetice of availability of "Programmatic EIS for Decontamination of IMI-2" SHYDER/B J IMI Program Office Bi/02/27 2pp 07942 316
- --8103180079 FINAL PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO DECONTAMINATION AND DISPOSAL OF RADIDACTIVE HASTES RESULTING FROM THE MARCH 28. 1979. ACCIDENT AT THREE MILE ISLAND MUCLEAR STATION. UNIT 2

   THI Program Diffice NUMBS-0683 VOI 81/03/31 300pp
  Available at NTIS \$10.00 08028 129
- --BIO318C085 FINAL PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO EECONTAMINATION AND DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM THE MARCH 28, 1979, ACCIDENT AT THREE MILE ISLAND NUCLEAR STATION, UNIT 2

   TMI Program Office NURSO-0683 VOZ 81/03/31 330pp
  Available 4t NTIS \$10.00 08033 163
- B103199126 Responds to B10113 ltr re suitching from organic to inorganic ion exchange media in future EPICOR-II prefilters Requests evaluation of use of core corrosion resistant matl for first stage ion exchange vessels

  BNYDER.B J Thi Program Office 81/03/10 3pp 07965-110
- B103250102 Staff requirements more re B10309 briefing on final programmatic EIS concerning facility decontamination Commission requested proposed language to delegate closuup authority to Director of Dir of Nutlear Reactor Regulation CHILK, S.J. Office of the Secretary of the Commission B1/03/10 to 07977-317
- BIO3260973 Forwards final programmatic EIS re decontamination & disposal of radwastes at facility & FR notice W/o final rapt
  BNYER, B J TMI Program Office 81/03/10 Ip 08040 225
- --8103260978 Notice of availability of final programatic EI5 for decontamination & disposal of raduastes at facility SNYDER, B J. THI Program Office. 81/03/09 2pp 08040 226.
- Bio3310804 Ltr to all licenses of operating plants applicants for Ots & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment
  EISENNUT.D 9 Division of Licensing 81/03/10 App
- B103170475 Forwards suppliemental into to 810219 ltm requesting rod of order to solidify EPICOR-II spent resins Concrete intrusion barriers for liners w/high levels of Sr-90 are bying discussed w/state govt HQVEY. O K Metropalitan Edison Co 81/03/11 7pp 07935 247
- 8)03180466 Forwards revised "Technical Evaluation Rept. Submerged Demineralization Sys." Mar 1981 Requests approval to operate sys HOVEY. 0 K Motropolitan Edison Co 81/03/11 1p 07951.123
- --0103160475 "Technical Evaluation Rept-Submerged Demineralization Sys."

   Metropolitan Edison Co B1/03/31 76pp. 07951,124
- 8103180685 Forwards license amend Request 2-deleting Section 2 E (4) of License DRR-73 MOVEY. 0 K Metropoliten Edison Co 81/03/11. App 07954-091
- --DID31B0697 License amend Request 2 to permit shipment of low lovel EPICER-11 liners to commercial shallow land burial sites b investigation of alternate forms of waste processing & liner disposal HOVEY, O.K. Metropolitan Edison Co. 81/03/11. 3pp 07994.095
- 8103170534 Submits addl info in response to ARC 810824 request re contresal contamination includes info re Cs-137 to Br-90 retion in cort-seal sergles & sources of water in cort-seal cavity. HOVEY, 0 M. Metropolitan Edison Co. 81/03/12. 6pp. 07930-121
- 8103230554 Comments on NRC. "Finel Programmatic EI8 (IMI Accident)," dtd Mar 1981 Clarification of statements re investigation of socioecohomic impacts of release of processed accident water to Susquehanna River provided MASSICOT.P. Maryland, State of. 81/03/13. 2pp. 07977:083
- BiOJi90595 Bubmits contingency plan for EPICOR-II liners while in extended storage in response to NRC BiOli2 request. Util will install pans under eight liners proven loss likely to retain integrity for over 10-yrs.

  HDVEY-O.K. Metropolitan Edison Co. Bi/OJ/16 4pp. 07956-061.
- B103250105 Forwards TM1 weekly status report for wk of B10308-14. BARRETT, L. H. TM1 Program Office. 81/03/16. 5pp. 07997. 304.

- --8103250111 Submits first rept of Advisory Panel for Decontamination of TMI-2 Radioactive contaminated water located in reactor bldg should be decontaminated as quickly as possible MINVICH. J. E. Dauphin County. PA 81/02/20 2pp 07997 309
- --BI03250116 Comments that NRC should valve requirement for solidification of low level waste whom util has met all requirements re leakage avoidance, safe transportation, shialding 8 other shipping precaultions Lit to DOZ entl MIMICH.JE Dauptin County. PA. BI/02/23 3pp 07997 311
- BIO3190383 Forwards requests for extension of content period re draft programmatic EIS Litrs should be docketed, but not distributed Extension has been granted LEECH.P THI Program Office 81/03/17 Ip
- --Bi03193391 Requests 120-day extension of corrent period for draft program-atic E15 Extension will allow individuals % citizen groups to provide NRC w/constructive % substantive comments POLLCOX.R P. Critical Mass Energy Project 80/08/29 1p
- --Bi03190376 Requests extension of comment period for draft programmatic EIB KROEMER.C J. Affiliation Unknown 80/09/04 1p.
- --BIO319037B Requests vicension of comment poriod for draft programmatic E18 ALPERT, S. Affiliation Unknown BO/09/02 1p
- --8103190407 Requests extension of corrent period for draft programmatic EIS SCHIEFF, O Affiliation Unknown 80/09/04 Ip
- --8103190914 Requests extension of comment period for draft programmatic E19 EPSTEIN B Application Unknown 80/08/31 1p
- 8103230694 Forwards corrected table. 'EPICCR-II Low Level Liner Ci Deposition." to util 610311 ltr. HOVEY.O K. Metropolitan Edison Co. 81/03/17 2pp. 07977:339
- 8103230703 Forwards corrected table. EPICOR-II Low Level Liner Ci-Deposition. to 810311 Amend Request 2 to License DPR-73 MOVEY-0 K Metropolitam Edison Co. 81/03/17 2pp. 07977 341
- B103260468 Staff requirements memo to B10316 meeting w/Advisory Panel for Decontamination of TM1-2 in Washington DC No action taken. Commonwealth of PA observers present CHILKS J. Offlice of the Secretary of the Commission. 81/03/17 1p. 08037 172
- 810J270457 Notification of contract execution Mod 1 to "Provision of Technical Assistance to Assess Psychological Giress repecontarination & Disposal of Radwastes at TMI Unit 2 "Contractor: Human Design Group LITILEM Administrative Contracts Branch FIN 8-6890 81703/17 ip 08043-216
- --Bi03270463 Mod 1, reducing total amount of contract to "Provision of Technical Assistance to Assess Psychological Stress re Decontamination t Disposal of Radwastes at TMI Unit 2 " \* Human Design Group PERLMAN.J Administrative Contracts Branch. FIN 8-6890 BI/03/17 ip. 08043.217.
- 81D3230573 Confirms filing of NRC E18 "TM1-2 Decontamination & Disposal of Radwasto Resulting from 790328 Accident Landonderry Township, Dauphin County, PA 'FR natice of availability scheduled for 810320 Public review to terminate 810420 WILSON.K Environmental Protection Agency. 81/03/18 ip. 07977:087.
- 8103240243 Forwards Tech Specs Change Request 26. requesting amend to App 8 of OL HOVEY. O. K. Metropolitan Edison Co. 01/03/18. jp 07986:292.
- --8103240250 Tech Spect Change Request 26. Addendum A. amending OL to suspend aerial remote monitoring program requirements H3VEV-9 K Metropolitan Edison Ca. 81/03/18 App. 07986:293
- --Bi03240286 Revised Toch Specs Pages 3-21 & 22 re environ monitoring requirement.

  \* Metropolitan Edison Co. 01/03/18 2pp. 07986.297.
- 81032503B7 Notifies that util response to NRC B10227 ltr re processed water storage tenks will be submitted by 810327 per discussion U/R Dellamy.

  HDVEY. 9. 8. Metropolitan Edison Co 91/03/19 1p. 08022:181

31 Acvises that recovery OA plan & organisational chang ted in 80,0000 lit are acceptable N-list of structures, apponents & safety items should be included in plan ide ( 50, Revision I. should be followed B J TMI Program Dffice B1/03/20 3pp 08000 247

Bi Advises that recovery QA plan & organizational changes

34 Informs that B&W owners group submitted AAM-1911P, Lation-Induced Reduction in Charpy Upper Shelf Energy Lor Vessel Welds' to fulfull submittal requirements -RSO. App 0 -RSO. Duke Power Co. 01/03/23 1p

2693 Forwards BAN-1511P. Itradiation-Induced Reduction in by Upper Shelf Energy of Reactor Vesse) Welds." Tibes implementation predictive nethodology to determine infe of reactor vessels Who encl DR.J H. Babcock & Hilcox Co. 81/03/12 2pp

P2 Responds to NRC 801107 ltr & suppls util 801204 ltr re ped demineraliser sys Also provides response to NRC is for addl info re sys drawings Requests approval to to for dust into the says exceedings necessary approved to a containment surep water & RCS water 2 R Ketropolitan Edison Co. 81/03/23. 14pp. 08055 106

tion reparts. IE Bulletius & correspondence

25 Forwards IE Info Notice 80-44. "Actuation of ECCS in Plation Mode While in Hot Shutdown" No written He required Six Region t. Philadelphia, Office of the Birector 16 1p 07905 332

9 Forwards IE Insp Rept 90-320/80-15 on 800901-1018 No. oliance noted I.H. Region I. Philadelphia. Office of the Director 17 2pp 07789 139

0955 IE luen Rent 50-320/80-15 on 800901-1018 No mancamaliance Major areas inspected plant operation, health physics &

on inst & review L.K., BAKLEY, M., MOSLAK, T., Region 1, Philadolphia, Office of Jirector, BO/11/24 Spp., 07787 137

2 Forwards IE Insp Rept 50-320/80-20 on 801209-11 No liance noted

OH Region I, Philadelphia, Fuel Facility & Materials Bafety BI/OI/O? 2pp 07824.253

DB2 1E lise Rept 90-323/80-20 on 801209-11 Na noncompliance | Major areas inspected licensee actions in response to |iste Action ttr 80-31 including revise & revision of oncy plan inclementing procedures.
DBON.D., GALLINA.C. Region I, Philadelphia, Office of the tor BORES, R.J. Region I, Philadelphia, Fuel Facility & tale Bafety Branch 81/01/06 Spp. 07024 255

5 Faruards IE Insp Rept 50-320/80-16 on 800915-1027 No. liance noted but due dates for completion of ive actions for radiological controls program not

H Region 1. Philadelphia. Office of the Director 9 2pp 07846 076

723 IE Insp Rept 50-320/80-16 on 800915-1027 No noncompliance Major areas inspected status of radiation protection am implementation Five commitment dates overdue. MKY, M. BARLEY, M. CONTER. Region 1. Philadelphia. Office of Mrector B0/12/05 23pp 07846:078

4 Forwards IE Info Notice 81-01. "Possible Failures of GE Type eys" No response required. .H Region I- Philadelphia. Office of the Director 6. tp. 07783-250

4 Ack receipt of \$5.000 in payment of proposed civil panalties 807 notice of violation Forwards order imposing civil es per 800807 notice of violation V Director's Office. Office of inspection and Enforcement O 2pp. 07782

672 Order imposing civil monetary penalty in amount of 62,000 oncompliance re transportation of radwaste Evaluations

Clusions encl

C.V. Director's Office Office of Inspection and Enforcement

2/10. 6pp. 07782-050

4 Forwards IE Info Notice 81-03, "Checklist for Licensees Notifications of Bignificant Events In Accordance 50.72." No written response required. H. Region 1. Philadelphia, Office of the Director. 2. 10. 07813 242.

- HIDDOIGNOS Forwards Hostinghouse ropt "TMI-2 Low Pressure Disc Ultrasonic lasp Rept " Also forwards proprietary version of mati properties rept for Low Pressure | & 2 turbines Mat1 properties rept withheld (ref 10CFR2 790) SYLVANOR Virginia Electric & Power Co 81/02/27 2pp 07809 273
- --8103040274 TMI-2 Low Pressure Disc Ultrasonic Insp Rept "
   Westinghouse Electric Corp. 81/02/02 2pp 07809 276
- 8103200180 Forwards JE Info Notice 81-04. "Cracking in Main Steam Lines "No response required
  GRIER.B.H. Region I. Philadelphia. Office of the Director
  GI/02/27 tp 0.7972 024
- 8103200138 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No written response required GRIER, B H. Rugion 1. Priladelphia, Office of the Director 81/03/02 10 07971 345
- 8103203048 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Snubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CP to which bulletin (s applicable does not affect util requirements GRICR.8 H. Region I. Philadelphia. Office of the Director 81/03/03 1; 07968-194
- 8103200148 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Brealer" No response required.
  GRIER.IN M. Region 1. Philadelphia, Office of the Director.
  81/03/11 1p 07760.283
- B103230092 Ack receipt of 810306 ltm transmitting full payment of \$2,003 civil penalty imposed by MRC B10210 order THOMPSON D. Enforcement & Investigation Staff. B1/03/16 Ip 07980: 327
- R Periodic operating reports & related correspondence
- B103100042 Forwards quarterly rept for fourth quarter of 1980 HDVEY.O.K. Metropolitan Edison Co. B1/01/13 ip. 07866 045.
- --8103100051 Guarterly rept for fourth quarter of 1980.

  \* Netropolitan Edison Co. 81/01/14. 22pp 07866:046.
- 8103170134 FOIA request for documents providing meteorological data for areas surrounding TMI site magnetic tapes withoutly data survarias for 790328-0501 & repts describing methodologies KANNER.A. Berger. D. 81/02/02 ip 07939-038
- 8103050768 Forwards THI weekly status rept for 810208-14 BARRETTLUM THE Program Office. 81/02/13 5pp. 07836 [12.
- 8103060513 Forwards TMS Program Ofc weekly status rept for 810215-21.

  BARRETT, L. H. IMS Program Office 81/02/23 App. 07836:093
- 8)03030863 Forwards 'Effluent & Waste Disposal Bemiannual Ropt. Jul-Dec 1980: Supplemental Info. Unit 2" & "Effluent & Waste Disposal Bemiannual Rept. Jul-Dec 1980: Supplemental Info. EPICOR-11. " KOVEY. O M. Metropoliten Edison Co. 01/02/26. 1p. 07796: 169.
- ---B103030B&7 "Eff)vent & Waste Disposal Bemiannual Rept.Jul-Dec 1980. Bupplemental Info.Unit 2" \* Metropolitan Edison Co 81/02/26 10pp. 07796-170
- --B103030874 "Effluent & Waste Disposal Semiannual Rept.Jul-Det 1980. Supplemental Info.EPICOR-II." Metropolitan Edison Co 81/02/26 32pp. 07796:180
- BiO3040297 Forwards "Effluent & Haste Disposal Bemiannual Rept. Jun-Dec 1980: "for util & EPICOR-II. HOVEY.O.K. Metropolitan Edison Co. 81/02/26. 1p. 07809-321.
- ---B103040309 "Effluent & Waste Disposal Semiannual Rept.June-Ooc 1980."
   Matropolitan Edison Co 81/02/26. 43pp 07809:322
- 8103100345 Forwards "Annual Operating Rept 1981." HUKILLIH.D. Metropolitan Edison Co. 01/02/28. ip. 07869.046.
- ---8103100370 "Annual Operating Rept. 1980 "

  \* Metropolitan Edison Co. 81/02/28. 3pp. 07865:047.
- B103110070 TMI ofc weekly status rept for wk of B10222-28.

  BARRETT-L H. TMI Program Office. B1/03/02. Spp. 07884:353.

- 8103100552 Forwards Thi Aquatic Study Monthly Rept for Jan 1981." prepared by Ichth-plogical Associates, Inc for Met Ed TEITT, 7 A General Public Utilities - GPU Service Corp 81/03/05 le 07667 279
- --810310354 "IMI Aquatic Study, Monthly Rept for Jan 1981"
  NARDACCI.G A linthypiogical Associates, Inc. 81/03/05 (4pp 03947 281
- 8103170128 Responds to FDIA request for documents providing meteorological data for areas surrounding TMI site.magnetic taces w/hourly data sunmaries for 790328-0301 & rents describing methodologies Forwards App A documents
  FELTGN.J M. Division of Rules and Records 81/03/05 3cp A7039 A35
- --8103170150 Forwards TMI meterological data tape for Jul 1978-June 1979. in response to ARC request ABRAMS N Pickard Lowe & Garrick 80/05/16 3on
- --8103170153 Local climatelogical data, monthly surparies for 1979 MITCHELL, D.B. Commerce, Dept. of 79/12/31 12:pp
- --8103170159 "Local Climatological Data Annual Surmary W/Comparative ♥ Commerce.Dect of 78/12/31 3pp
- --8103170[63 'Local Climatological Data Annual Surmary H/Comparative # Commerce. Dest of 77/12/31 Ass
- --8103170167 "Local Climetological Data Annual Summary H/Comparative · Comferce. Dept of 74/12/31 3pp
- 8103190936 Weeking statue rept for at of 810301-07 BARRETT, L H INT Program Office. 81/03/09 Spp. 07965 231
- B103250105 Forwards TM1 weekly status report for wt of 810308-14 BARRETT-L H TM1 Program Office 81/03/16 3pp 07997-304.
- --8103250111 Submits first rept of Advisory Panel for Decontamination of TMI-2 Radioactive contaminated water located in reactor bldg should be decontaminated as quickly as possible
  MINNICH. J E Dauphin County. PA 81/02/20 2ps. 07997-309.
- --BI03280116 Comments that NRC should unive requirement for solidification of low level waste when util has met all requirements re leakage avoidance safe transportation. shielding & other shipping precautions Ltr to DDE enc!
  MINNICH. J. E. Dauphin County, PA 81/02/23 3pp. 07997:311.
- 8103300257 Forwards groundwater monitoring data for 800125-810225 Tritium concentrations Continue to trend down in monitoring well MH-2 & up in MW-3. HDVEY.O.K. Metropolitan Edison Co. 81/03/20 2pp. 08057.194
- --B103300264 Groundwater monitoring data for B00125-B10225 One oversize drawing enci Aperture card is available in PDR.

  # Hetropolitan Edison Co 81/03/20, 23pp. 08057:196
- S Reportable occurrences. LERs & related correspondence

- 8103030662 Forwards LER 81-002/01L-0. HOVEY, Q. K. Metropolitan Edison Co. 81/02/25, Io. 07798-091.
- --8103030667 LER 81-002/01L-0 on 810126 emergency diesel generator 8 determined inoperable on 810119 Caused by auxiliary operator not completing switching order No corrective action Operator CHAPLIN.S D. Metropolitan Edison Co. 81/02/25. 3pp. 07798-092.
- 8103040691 PND-THI-81-006 on B10227, contaminated rodent faces found in control & svc bldg. Affected areas roped off. Exterminator contacted to capture posts Contaminated rodents do not pose radiological rist to public or environ.

  SHANBAKY.H. FASAND.A. BARRETT.L. THI Program Office. B1/02/27.
  29p. 07919 243
- 8103100549 Forwards updated LER 80-051/03L-1 HDVEY: 0. K Metropolitan Edison Co. 81/03/03 1p. 07862: 314.
- --8103100556 Updated LER 80-051/03L-1:on 801110,18-inch long crack observed which penetrated fire barrier seal 3-484-51 Cause not stated Hourly fire watch implemented until seal repaired & returned to svc. CHAPLIN. 8 D. Metropolitan Edison Co. 81/03/03. 3pp. 07862.315.

- 8103120631 Forwards LER 81-003/03L-0 HOVEY O K Metropoliten Edison Co 81/03/05 ip 07904-264
- -8103120639 LER 81-003/03L-0 on 810202. while performing surveilla 4333-R2. deluge valve FS-V-426A failed to operate properly 4333\*Maideluge valve rosviscon railed to operate properly Apparently caused by malfunction of solenoid operator, arresting automatic release of hydraulic lock. CHAPLIN.S D. Matropolitan Edison Co. 81/03/05. 3pp. 07904
- 8103170558 For Jards LER 91-004/03L-0 HDVEY. 0 K Metropolitan Edison Co 81/03/06 Lp 07933 094
- --8103170965 LER 81-004/03L-0 on 810204 energency diesel generator Temp maintained by periodic starting until pump motor repair on 810302 CHAPLIN, S.D. Metropolitan Edison Co. 81/03/06 3nn 07974
- 8103170595 Forwards LER 81-005/016-0
  HOUFY, G. K. Hetronalitan Edison Co. 81/03/09 1p 07933 346
- --BIO3170563 LER 81-005/OIL-0 on BIO207, incore thermocouple H-9 ex erratic tehavior. Cause unknown Thermocouple being monitored CHAPLIN S D Metropolitan Edison Co. B1/03/09. 2pp 07933
- 8103170353 LER 81-007/01P on 810312 discovered that suitable offile grab samples were not obtained before removal of EPICOR II bldg effluent radiation Monitor M-18 from svc Datails will the included in following rept
  HOVEY, Q. h. Metropolitan Edison Co. Bi/03/12 2pp
- 8103200541 PN3-TM1-81-007 on B10317, ion exchange media column test IO32(004) P(G-16]-9[-UV on BIO317, ion exchange Media Column test supporting submerged deminerallier systectinical evaluation data.not performed during seventh entry into IMI-2 reactor Caused by lodged submersible pump above sump uater CONTE.R FASANJA . BARRETTL C. Region i. Philadelphia. Uffice the Director 81/03/18 2pp. 07972:166
- 8103250423 PNO-TMI-81-007A on Bi0317 during attempt to re-enter re tldg.technicians unable to lower submersible pump into sump to proceed w/roolite experiment. Five gallons of sump water for experiment obtained on 010320.

  AALMAN 9 - CONTE.R - FASAND A Region 1. Philadelphia, Office of Director 81/03/23 2pp 07976 194
- T Hearing transcripts on non-antitrust matters
- B103040Be9 Transcript of Advisory Panel for Decontamination of THI-2 B10211 meeting in Herrisburg.PA.Pp I-53 

   Advisory Councit for Decontamination of TMI Unit 2. B1/02/11
- 8103090349 Transcript of Advisory Panel for Decontamination of TMI BIO219 meeting in Harrisburg, PA Pp 1-90 \* Corrissioners 81/02/19, 92pp 07847,004
- 8103190250 Commission determination releasing portions of transcri B10128 closed meeting in Washington DC re GPU federal tort claim.pg [-19. Commissioners. CHILK.B.J. Office of the Secretary of the Commission B1/03/02. 21pg
- U. Congressional/Executive Correspondence
- 8103050764 Responds to 810130 itr reliac investigation into report of info during accident IE issued encl natics of violation after completion of investigation forwards Commissioners Ahearne & Gilinsky views to matter.
  AHEARNE J F. Commissioners 81/02/13 ip. 07831:325.
- --8103050775 Submits views re util reporting of info during invest of accident Licensee must be responsible for evaluating & responding to accident Endorses conclusions of NRC staff AHEARNE.J.F. Cormissioners 81/02/13. 1p. 07831 326
- --8103050788 Responds to 810130 ltr re NRC conclusion from investig of info reporting during accident Util probably withheld info which would have made accident appear more serious & reactor situation more precarious OILINSKY, V. Commissioners. 81/02/13 2pp. 07831:327
- --8103050813 Requests individual Commissioner views re util report: info from 790328 accident.

  UDALLH K. House of Rep. - Interior & Insular Affairs. 81/01/:
  1p. 07831.333.

- 8103]70731 Responds to BI0130 request for Commissioner views rewithholding of info during accident at facility Failure of certain info to reach MRC & PA authorities justified revocation of licenses New legislation is not required BRADFCRO.P A Commissioners 81/02/24 3pc 07930 155
- ---8103170737 Burmary of Commissioner Bradford 810213 meeting w/V Stello.

  N Moseley & IE Investigation Team re info flow during facility accident Discussion focused on Oradford 810123 & 28 questions to Elecutive Director for Operations

  CLEMENTS. W L NRC No Detailed Affiliation Given 81/02/24 200 07930 158
- --B103170746 Requests info re investigator conclusion that contradictions in testimony re facility info flow during accident were in no case result of lying BRADFORD.P A Commissioners B1/01/28 1p 07730 160
- --BiO3170753 Discusses two examples of apprehension re IE conclusion that no facility into flow testinony contradictions were result of lying BRADFORD.P A. Commissioners. 81/01/23 ip 07930:161
- B103250003 Forwards marked-up colleguy between R Mattson of NRC & two members of President's Commission on Accident at IMI, during Mattson 790601 deposition NRC failed to analyze older plants re interpretation of new NRC regulations BRADFORD.P A Commissioners 81/03/02 11pp 07996.330
- B103120299 Informs that NRC will file testimony on remaining agt capability issues on or before wk of 810316 Testimony on design mod will be during uts of 810316 t 23 Mgt capability issues will begin around 810331
  SWANSOW
- --B103120263 Responds to 810130 ltr re info flow during TMI-2 accident Agrees w/investigation conclusion that conflicts of info did not result from lying. Withholding of info was not intential HEURRIE. J M Cormissioners B1/02/20 3pp. 07900:209
- --BIO3120272 Responds to BIO130 ltr re info flow during TMI-2 accident. Failure of important info to reach NRC was inexcusable Util metives are questionable New legislation not required Regulations modified to impose clear reporting duties BRADFORD.P A Commissioners 81/02/24 3pp. 07900.212
- --8103120205 Responds to request for personal views re info flow during TMI-2 accident Persons in charge were unawers of or did not understand indications of core damage & gross degradation Recommended enforcement actions inconsistent wifacts.
  MICHGLEON.C. Director's Office 81/02/20 3pp. 07900.219
- EDCKET 90-321 EDWIN : HATCH NUCLEAR PLANT, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101. Forwards NRC position & request for addl info resafe shutdown capability for compliance w/801119 fire protection rule EISENHUT.D Q. Division of Licensing 81/02/20 IDpp.
- 8tO33tO33G Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0.696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/a encl. EISEMWNT.D. 2 Division of Licensing. 81/03/05. 6pp.
- H Osneral correspondence
- 8103230430 Responds to 810127 itr questioning NRC re independent chemical analysis of TMI wastes NRC onsite personnel are manitoring activities & info on continuing basis re all aspects of cleanup.

  RNYDER.B.J. TMI Program Office. 81/03/13 2pp. 07975-018.
- J Insurance & indemnity information
- 8103060450 Forwards Endorsement 4 to MAELU Binders XB-51 & XB-67.W/o Binder XB-51. FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. DIV. 81/01/28 3pp. 07837: 323.
- 8103100437 Forwards Endorsement 46 to MAELU Policy MF-78. FIELDER: J. Mersh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 81/03/02. 2pp. 07865:215.

- $\boldsymbol{P}$  . Operating license stage documents & correspondence
- B103190732 Ltrs to all licensers of operating plants.applicants for OLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NOREG-0612 Forwards NRC position reinterin actions & request for addlinfo ETSEINFUT.D O Division of Licensing B0/12/22 30pp
- B10319037 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREQ-0737 EISENHUT.O.O Division of Licensing 81/01/19. App.
- 8103240290 Ltr to all MWR licensees forwarding Suppl I to generic safety evaluation on MWR scram discharge sys Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation.
  ETSERNUT.D 0 Division of Licensing 81/01/23 2pp.
- 8103120014 Ltr to all licensess of operating plants CP holders & QL applicants except Indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads EISENHUT D.9 Division of Licensing 81/02/03 App.
- 810316069 Ltr to all operating plants & CP holders forwarding clarification of TML Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be mot EISECHUT. D. O. Division of Licensing 81/02/18 12pp
- 8103050497 Advises that Classes IV & I fees are required for Tech Spireview of 800915 application.
  HOLLOWAY.C J License Fee Management Branch 81/02/20. 1p 07835-242
- 810329024 Ltr to all power reactor licensess & license applicants re MUREC-0619 criteria Factnote 2 in Table 2 contains ceron due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

  EISENHUT, D. O. Division of Licensing. 81/02/20 Spp.
- 8103020514 Requests mod of schedules for completion of Mark I program per NRC 810113 orders Completion is tied u/1982 refueling outage for each unit Requests hearing in event NRC does not approve or act upon request WIDNER, W.A. Georgia Power Co. 81/02/24 3pp. 07782.094.
- BIO3230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except Bt Lucie Units I & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENMUT.D.O Division of Licensing Bi/02/25. 3pp.
- Q103100425 Application for amend to Licenses NPF-5 & DPR-57, submitted as proposed changes to Tech Specs re BUR scream sup design. MID\*LER.N. A. Georgia Power Co. B1/02/26 3pp. 07857:233
- ---8103100429 Tech Spec Tables 3 6.3-1.3 7-1 & Page 3.7-20 for primary containment isolation valves.
  4 Ocorgis Power Co. 81/02/26 Spp. 07867:236
- B103170225 Lir to all BWR licensess (except Numboldt Bay & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting nat1 per guidelines of encl Revision 1 to NUREG-0313 Model Tech Specs only encl. EISENHUT, D.G. Division of Licensing B1/02/26. 3pp.
- --8103170256 Model Tath Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-5 surveillance requirements for ABISE Code Class 1/2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements.

   General Electric Co. 81/02/26. 4pp.
- B103230B13 Generic Ltr 81-05 to all CP holders & DL applicants re 10CFR90.71(e), "Periodic Updating of FBARs," effective B00722 Info re FBAR legal status format & content encl. EISERHUT-D.O. Division of Licensing. B1/02/26. 10pp.
- B103120302 Forwards Amends B1 & 22 to Licenses DPR-97 & NPF-5, respectively & notice of lasuance & availability, REID.R.H. Operating Reactors Branch 4. 81/02/27. 3pp. 07905:22
- --BiO3120505 Amends BI & 22 to License DPR-97 & NPF-5, respectively, revising administrative control Tech Specs re requirements for facility safety review board insp & audits.

  REIDR W. Dereting Reactors Branch 4. Bi/02/27. 9pp. 07905:229.

- --BIG312050B hotice of issuance & availability of Amends B1 & 22 to License GPR-97 & hPF-9, respectively REID.R M. Operating Reactors Branch 4 81/02/27 3pp G7905 238
- 8103100489 Submits additinfo to BMR scram discharge sys mbds.per 801001 request mods usli be implemented as needed to result in conformance to couners group criteria by end of 1982 provided qualified equipment is confercially available MIDNER, M.A. Georgia Power Co. 81703704 2pp. 07857-221
- B103130570 Submits addl info re status of compliance J/NUREO-0737. Item II x 3 27 No changes required re tero ref point for reactor pressure vessel water level if NRC disagrees, implementation of hardwere mode may be later than B10701 UNDVERSUA Separate Power Co. B1/03/06. 19. 07911 288
- 8103160461 Application for amend to License DPR-57, incorporating revised Tech Specs for Cycle 5 operation J/Reload 4 fuel inserted HR-DER, W.A. Georgia Power Cc. 81/03/06 3pp 07918 224
- --Bi23160465 Proposed changes to Tech Specs 3 11 B & 4 1% C for Cycle 5 operation w/Reload 4 fuel inserted Quargia Power Co Bi/03/05 7gp 0791B 227
- 8103160589 Notifies that util B01010 commitments to BE4 screen discharge sys long-term mots do not satisfy NRC criteria Revised Tech Specs must be proposed at least 3 rooths in advance of mod completion dates
  REIO.R M Dereting Reactors Branch 4 81/03/06 2pp 07915 2CO
- B103310804 Ltr to all licensees of operating plants applicants for CLs tholders of CPs forwarding SSCY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT. D G Division of Licensing 81/03/10 6pp.
- B103270095 Surmary of 810204 meeting w/Mark I owners group & OE in Betheeda. MD re-supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUPEQ-0061 Slide presentation & list of attendees encl. ORIMES.C I Licensing Branch 3 81/03/16 Spp
- 8103240222 Forwards Y1003J01A13. \*Bupplemental Reload Licensing Submittal for Edwin I Natch Nuclear Plant Unit 1.Reload 4. \* Rept was inadverdantly critted from 810306 submittal. GUCKA.L T. Georgia Power Co. B1/03/17 1p 08026.236
- --Bio3240230 "Supplemental Reload Licensing Submittal for Eduin I Hatch Nuclear Plant Unit 1.Reload 4." KAMIMSKI, Q. T. ENGEL, R. E. General Electric Co. y1003J01A13 80/07/31. 25pp. 08026-257
- 8100240909 Bubmits comments & requests for cartain exemptions from final version of 100FR30 48.App Riper 810220 request, MIDNER.M A. Georgia Power Co. 81/03/19 14pp. 07986:148
- 8103300268 Requests extension of two uts for subnittal of snubber surveillance Tech Specs requested in NRC 801120 ltr. Additing will allow sufficient review of mechanical snubber listing & time to obtain necessary info from vendon.

  HIDNER.M.A. Georgia Power Co. 81/03/23. ip 08055 282.
- Q. Inspection reports, 1E Bulletine & correspondence
- B102280574 Forwards IE Info Notice B1-01. "Possible Failures of GE Type HFA Relays " No response required.

  D'REILLY, J.P. Region 2: Atlanta, Office of the Director. 81/01/16.
  10.
- 8103050358 Forwards 1E Mgt Meeting Repts 50-321/80-41.50-366/80-41. 50-424/80-16 & 50-425/80-16 on 801020 No noncompliance noted D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/01/29. 2pp. 07824-227.
- --BI0305036B IE Mgt Heeting Repts 50-321/BD-41,50-366/BD-41,50-424/BD-16 & 50-425/BD-16 on B01020. Major areas discussed: NRC evaluation of util regulatory performance per systematic assessment of licensee performance program. LEWIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 81/01/28. 16pp. 07824.229
- B103090784 Forwards 1E Mgt Meeting Repts 50-321/80-51 & 50-366/80-51 on B01223 No noncompliance noted MURPHY.C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/01/30. 2pp. 07849, 225.

- --8103090789 [E Mgt Meeting Repts 90-321/80-51 & 50-366/80-51 on B: \_ej Major areas discussed recairs to back#ill supporting Rh-R & sec Later piping at Intake structure LENAMA'. J Region 2. Atlanta. Office of the Director CONLC'. T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/29 3pp 07849 227
- 8103020263 Forwards IE Circular 81-02. 'Performance of NRC-Licensed Individuals While on Duty ' No written response required D'REILLY. J.P. Ragion 2. Atlanta, Office of the Director 81/02/09 ip 07785 333
- 8103160094 Forwards IE Inst Repts 90-321/80-45 & 50-366/80-45 on B01014-1114 No nanco-pliance noted LEWIS-R C Region 2. Atlanta. Reactor Operations Nuclear Support Sranch B1/02/09 2pp 07921 165
- --BIO3160107 IE Insp Repts 90-321/80-45 & 90-366/80-45 on 801014-1114 No noncompliance noted Major areas inspected. Tech Spec compliance noted Major areas inspected. Tech Spec by preventative maint activities RGGERS.R F Region 2. Atlanta. Office of the Director DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/079 3pp 07921 167
- 8103020709 Supplements previous response to 1E Sulistin 60-24.1ter 3 re prevention of damage due to water leakage inside containment Spill occurred in closed sys while in cold shutdown on 791218 Caused by personnel error WIDNER W A Georgia Power Co 81/02/10 ip 07/84 091
- 8103040138 Forwards IE Info Notice 81-03. "Checklist for Licensess Making Notifications of Bignificant Events In Accordance W/10CFR50 72" No critten response required DrREILLY, J.P. Region 2. Atlanta, Office of the Director 81/02/12 is. 07819-341
- BIO3100723 Forwards Suppl 3 to IE Bulletin GO-17. "Failure of Control Rods to Insert During Scram at SWR" No written response required
- O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/17. Ip 07866.319
- 8103160694 Forwards IE Info Notice B1-04. "Cracking in Main Steam Lines" No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director - 811/02/27 Ip 07714-047
- 8103160560 Forwards IE Circular Bir03, "Inoperable Seismic Monitoring Instrumentation" No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Birector BI/03/02 ip. 07916 340
- Bio3i70079 Forwards revised IE Bulletin Bi-Gi, "Gurveillance of Mechanical Snubbers." W/corrected Pages 5 & 6 Change in identification of facilities w/Cfs to which bulletin is applicable does not affect util requirements O'REILLY, J.P. Region 2, Atlanta, Office of the Director Bi/O3/C4 ip. 07935:204
- 8103260503 Forwards update to 810217 response to IE Bulletin 79-018-"Environ Qualification of Claes 1E Equipment" Update provides justification for continued operation considering MSIV limit installations as inadequate.
- 8103240834 Forwards IE Insp Repts 50-321/81-04 & 50-366/81-04 on B10110-0220 & notice of violation LEWIS.R.C. Region 2. Atlanta, Office of the Director B1/03/10. 2pp. 07984:234.
- --8103240839 Notice of violation from insp on 810110-0220 > Region 2. Atlenta. Office of the Director 81/03/10 lp. 07984-236
- --8103240B48 IE Insp Repts 50-321/01-04 & 90-366/01-04 on 810110-0220 Noncompliance noted inoperability of core spray sys ROGENS R F. KELLCOO, P. Region 2. Atlanta. Office of the Director 81/03/09. 10pp. 07984:237.
- 8103200263 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required. C'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03/11 1p. 07968.358.

- 6103240800 Forwards IE Insp Repts 50-321/81-03 & 50-366/81-03 on B10217-20 & notice of violation LEMIS.R.C. Region 2. Atlanta. Office of the Director B1/03/11 202
- --8103240897 Notice of violation from insp on 810217-20 \* Region 2. Atlanta. Office of the Director 81/03/11 2pg
- --BIO3240819 IE Ineg Repts 90-321/81-03 & 50-366/81-03 on BIO217-20 Moncompliance noted failure to implement procedure to retrieve documents & to accomplish error analysis PEEBLES. T A. BRYANT. J C. Region 2. Atlanta, Office of the Director BI/03/10 Spp
- 8103200036 Forwards IE Info Notice 81-05, 'Degraded CC Sys at Palisades "No response required.
  O'RRILLY.J.P. Region 2. Atlanta. Office of the Director. 81/03/13
  1p 97969 103
- 8103240291 Ack receipt of 810306 ltr inforcing NRC of steps taken to correct violations noted in IE Insp Repts 50-366/81-01 & 50-32/81-01 LEMIS.R C Region 2. Atlanta, Office of the Director. 81/03/13 to 0.7886 322
- --8103240295 Responds to NRC 810209 ltr re violations noted in IE Insp. Repts 50-366/81-01 & 50-321/81-01 Corrective actions rearranged dryuell control point requiring workers to sign radiation work permit prior to return of security badge WIDNER.W A Georgia Power Co. 81/03/06 2pp 07986 323.
- --Bl03240299 Forwards IE Insp Repts 30-366/BI-01 & 50-321/BI-01 on B01126-Bl0107 & notice of violation LEHIB.R C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch Bl/02/09 2pp 079B6 325
- --8103240306 Notice of violation from inep on 801126-810107

   Region 2, Atlanta, Office of the Director 81/02/07 ip
- --8103240312 IE Insp Repts 50-366/81-01 & 50-321/81-01 on 801126-810109 Noncompliance noted failure to record drywell exit radiation doses for sit workers.

  ROGERS.R F Region 2. Atlanta, Office of the Director DANCE.H C Region 2. Atlanta, University Region 2. Atlanta, But Carlon Succession Succes
- 8103240100 Responds to IE Bulletin 81-01. "Burveillance of Mechanical Boubbers " Unit 1 has two accessible soubbers mfg by Intl Nuclear Gazeguards Corp installed on sazety-related sys Unit 2 soubbers replaced w/Pacific 8cientific soubbers on 810322 WIGNER.W A Georgia Power Co 81/03/13 5pp 08042 123
- 8103250133 Ack receipt of 810223 & 0313 itrs informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/80-46 & 50-366/80-46 LEMIS.R C. Region 2. Atlanta, Office of the Director. 81/03/19 pp. 07996.001
- --9103250139 Bubmits revised response to 810223 ltr re-violation noted in IE Insp Regts 90-321/80-46 & 30-366/80-46 Uses WRC-desired format Corrective actions Unit 1 IBI project plan review & approved WIBHERW A. Deorgia Power Co. 81/03/13. 2pp 07996.002
- --8103250142 Responds to NRC 810129 itr re violation noted in IE Insp. Repts 90-321/80-46 & 50-366/80-46. Corrective actions: procedure revised so that inservice insp project plans will be reviewed & approved by plant review board prior to insp. HIDIKER.W A. Georgia Power Co. 81/02/23. 2pp 07996 004
- --8103250145 Forwards IE insp Repts 50-321/80-46 & 50-366/80-46 on 801203-05 & notice of violation.
  MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/01/29. 2pp. 07996-006
- --BI03250149 Notice of violation from insp on 801203-05

  \* Region 2, Atlanta, Office of the Director 81/01/27 ip.
  07998:008
- ""B103280134 IE Insp Repts 50-321/80-46 & 50-366/80-46 on 801203-05.
  Noncompliance noted failure to approve inservice insp plan.
  CROMLEY. B.R. Region 2. Atlanta. Office of the Director.
  HERDIA. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 01/01/19. 7pp. 07996:009.

- BiO32a1174 Responds to IE Bulletin 80-25. 'Operating Problems W/Tanget Rock Bafety Relief Valves at 3MRs " Review indicates no instances where two-stage safety relief valve failed to perform Procedurys for operation \$ maint have been reviewed MIDNER.WA Georgie Power Co. 81793/19 2pp. 08040.264
- 8103270051 Ack receipt of B10302 ltr informing ARC of steps taken to correct violations noted in IE Insp Rept 30-321/80-44 LEWIS-R C Region 2- Atlanta, Office of the Director 81/03/19.
- --8103270062 Responds to NRC 810209 ltr re violations noted in IE Imsp Repts 30-321/80-44 % 80-366/80-44 Corrective actions soubber insp procedure revised & personnel cautioned to recognize potential effects of inoperable equipment. XELLY-R J. Georgia Power Co. 81/03/02 2pp. 08049.170
- --Bi03270071 Forwards IE Insp Repts 59-321/80-44 & 50-366/80-44 on B01118-21 & notice of violation LEMIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/05 200 08045 172
- --Bio3270082 Notice of violation from ins; on 801118-21

   Region 2. Atjanta. Office of the Director Bi/02/05 ip
- --BI03270096 IE Insp Repts 50-321/80-44 & 30-366/80-44 on B0111B-21 Moncompliance noted timeliness of maint activities not adequately controlled by mgt controls. MrITENER.H L. Region 2. Atlanta, Office of the Director GUICK.D R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. B1/21/20 3pp. 08043:175
- R Periodic operating reports & related correspondence
- B103040193 Forwards "Bemiennuel Rept.Plant Radioactive Effluent Releases Jul-Dec 1965" MAKRY,M. Ceorgia Power Co. 81/02/26 ip 07808 257
- --9103040199 'Bemjannual Rept.Plant Radioactive Effluent Releases, Jul-Do 1980 ' eergja Pauer Co 81/02/26 +3pp. 07808 259
- 8103090305 Forwards "Annual Operating Repts for 1980" MANRY: M. Georgia Power Co. 81/92/28 lp. 07848:096
- --0103090508 Annual Operating Repts for 1980 "
  \* Georgia Power Co 81/02/28 51pp 07848 097
- 8103310459 Forwards monthly operating rept for Feb 1981.
  MARRY.M. Georgia Power Co. 81/03/10 1p. 08081 189
- --8103310464 Monthly operating rept for Feb 1981. KAM18H-18H-J.M. Georgia Fouer Co. 81/03/10 7pp 08081:190
- 8 Reportable occurrences. LERs & related correspondence
- B103020539 Forwards LER B1-007/03L-0.
  MARRY.M Georgia Power Co. B1/02/19 1p. 07782.354.
- --8103020545 LER 81-007/03L-0 on 810203 & 19 unit 1 cable spread room sprintler sys was inoperable for period greater than 14 days & special repts were not issued Caused by personnel error Personnel reinstructed.

  CCG01N.C L. Georgia Power Co. 81/02/19. 2pp. 07782 359
- 8103030790 Forwards LER 81-009/03L-0 MARRY.M. Georgia Power Co 81/02/24 1p 07791:314.
- --Bi03030795 LER 81-009/03L-0 on 810205, nitrogen storage tank inventory went below 2000 gailon Tech Spec requirement. Caused by supplier delaying shipment. Shipment received Supplier instructed not to delay shipments.

  BAKLEY, B. X. Georgia Power Co. 81/02/24 2pp. 07791: 319.
- 8163030869 Forwards LER 81-010/017-0.
  MANRY-M Georgia Power Co. 81/02/24 1p. 07798-013.
- --B103030B77 LER 81-010/01T-0 on B10211.AE reported that diesel generate 1A.1C.2A.2D & 1B outlet set water piping & associated seismic supports exceeded Tech Spec. Caused by design polision. Design mods made.

  COOGIN.C L. Georgia Power Co. B1/02/24 2pp 0779B:014

- --8103130464 LER 81-011/03U-0 on 810214. Liquid raduasts sample tant. W3181. distharped prior to ensights, contrary to E19 Caused by technician error in collecting Unit 2 raduasts sample in prelabeled Unit 1 W318-1 bottle 800678.W H Gentals Power Co. 81/03/05 29p 07913-100
- 8103160730 Forcards LER 81-008/031-0 MAURY, M. Georgia Pouer Co. 81/03/10 1p 07914 120
- --BIO3160734 LER BI-009/03L-0 on BiO216 in normal operations at 309 MMT. IE51-NOIRA, B. C. & D actuated at 10 2.11 3.11 2 5 10 7 psig. respectively Caused by suitch setpoint Crift Parksdale suitches recalibr NIX.R I. Georgia Power Co. 81/03/10 2pp 07914 121
- EDCKET 50-322 SHOREHAM NUCLEAR POWER STATICH

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licenses of operating plants applicants for Ota & holders of CPs re control of heavy loads Requests review per guidelines in NNREO-Dola Forwards NRC position reinterim actions & request for addl info
- B103190387 Ltr to all licenses of operating plants & applicants for QLs & holders of CPs re program for environ qualification of safety-related electrical aguipment liters addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT.D Q Division of Licensing B1/01/19 6pp
- 8103120014 Ltr to all licensees of operating plants.CP holders & CL applicants, except Indian Point 2 & 3. Zion i & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENAUT.D 0 Division of Licensing 81/02/03 6pp
- 8103050951 Notification of 810311 & 12 meeting w/Mark II owners group & QE in Betheade. MD to discuss Mark II generic long-term program ANDERSON. C. J. Generic Issues Branch 81/02/12 12pp 07828. 195
- 8103230024 Ltr to all power reactor licensees & license applicants re MARQ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee ray submit analysis to justify use of existing low flow controller EISENMIT. D 0 Juvision of Licensing. 81/02/20 8ps.
- 8103030756 Forwards add1 info re containment isolation leakage testing, in response to NRC 780922 & 1214 requests. Fricary containment isolation valves unll be added to Type C local leakage program NDVARROL P Long Island Lighting Co. 81/02/24. 3pp. 07808 246
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for GLs (ercept 8t Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blactout event & promptly impleased emergency procedures. EIBENHUT.D O. Division of Licensing. 81/02/25. Spp.
- 8103170225 Ltr to all BHR licensess (errept Humboldt Bay & LaCrosse) requesting review of ABME Code Cless 1 & 2 pressure boundary pipting-safe ends & fitting mati per guidelines of encl Revision 1 to Nucc-0-0313. Hodel Tech Bpers only encl.
  EISENHUT. D Q Division of Licensing. 81/02/26 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 % 3/4 4-8 re surveillance requirements for ABME Code Class 1,2 % 3 components & RCB operational lesiage limiting conditions for operation & surveillance requirements. • Ownerel Electric Co. B1/02/26. 4pp.
- 8103170655 Ltr to holders of CPs & applicants for OLs (BWRs) requesting review of ABHE Class 1.2 & 3 pressure boundary piping, safe ands & fitting mati per guidelines of enci Revision I to NURED-O313. Model Tech Bpset only enci.
  EIBENMUT. D. O. Division of Licensing 81/02/26. 3pp.
- 8103230813 Ceneric Ltr 81-06 to all CP holders & DL applicants re 10CFR30 71(e). "Periodic Updating of FSRRs." affactive 800722 Info re FSRR legal status, format & content encl EISENHUT. D. O. Division of Licansing. 81702/26 10pp.
- 8103120473 Notification of 810305 meeting w/util in Bethesda. MD to discuss facility Mart II closure program & testing of

- 8103130601 Notification of 810313 meeting w/Mark II owners group in Bethasca. MD to discuss Mark II safety relief valve loads & poal teep limits
  SULT M Ceneric Issues Branch 81/03/03. 2pp 07912 136
- 8103390431 Forwards addl info re-seismic qualification review.per 1.70 B10228 request info supple 810130 info MOVARRD. J. Long Island Lighting Co. 81/03/05 20pp 07846 151
- 8103110303 Forwards for review & approval SWECO 8101. "Models Used in LCCTVS Computer Code to Determine Pressure & Temp Response of Vapor Suppression Containments Following LCCA " 87ABBURY.R B Stone & Rebster Engineering Corp. 81/03/06 2pp 07883-031
- --8103110312 'Models Used In LCCTVS Computer Code to Determine Pressure & Temp Response of Vapor Suppression Containments Following LOCA "
  ODCOWIN.E F , BRADBURY.R D . HENNESSY, W P Stone & Webster Engineering Corp SWECO-8101 81/02/28 257pp 07083 003
- 8103310804 Ltr to all licensees of operating plants.applicants for OLs bholders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment FIREMHUT.D Q Division of Licensing 81/03/10 App
- 8103160587 Forwards facility main control room preliminary assessment rept.provides for ARC 810330 review of main control room.per NUREQ-0737. Item 1 D 1 W/o encl NOVARRO.J.P. Long Island Lighting Co. 81/03/12 2pp 07918 096
- BIO3170170 Forwards 'Shorehem SORT Force for Equipment Qualification Review at Site," in response to NRC 810128 request NAVARRO, J.P. Long Island Lighting Co. 81/03/12. 1p.
- --BI03170173 "Bhorehan SQRT Forms for Equipment Qualification Review at Site."
   Stone & Webster, Inc. 01/03/13 175pp
- B103200444 Forwards Suppl 2 to NUREO-0407. "Mark 11 Containment Lead Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper, Suggests Mar 1901 meeting w/Mark 11 owners to discuss review program W/o enc1 KNIEL,K. Generic Issues Branch. B1/03/16. 1p. 65134-218
- 810319092: Forwards info reflecting understanding between NRC & util renormal ventilation sys.intake structure. M8IV loop control sys. jet pump holddown bean cracking & safety relief valve startup Info to be incorporated into FSAR.

  MOVARRO. J. P. Long Island Lighting Co. 81/03/17 \$1pp. 07965 159
- B103240235 Forwards UP Noverro affidavit supporting B10312 request for withholding from public disclosure suppl to "Plant Design Assessment for Befety Relief Valve & LOCA Loads, Shoreham Nuclear Pouer Station Unit 1." dtd Feb 1981.

  NDVARROUP P Long Island Lighting Co. B1/03/12. App. 07990 332
- 8103310914 Burmary of B10313 neeting w/Mark II owners group re supression pool temp limit & T-quencher load spec. W/o encl list of attendees & resting handout. BU.T.M. Generic Issues Branch. 81/03/24. 3pp. 08061.115.
- 8100310932 Requests estimate of monthly cost to maintain impacted unit in inactive status, including separate costs of replacement energy & capital expense during delay period. Estimate to be provided verbally by 810327 & confirmed by 810403.
  TEDESCO.R L. Assistant Director for Licensing. 81/03/25 9pp 08082 094
- 8103310389 Forwards Suppl 2 to NUREO-0487, "Mark II Containment Lead Plant Program Evaluation & Acceptance Criteria." Deviations from criteria are to be documented in design assessment rept during FSAR roview. W/o encl.
  YOUNGBLOOD. B J. Licensing Branch 1. 81/03/26 3pp. 08059 311.
- 8100310299 Forwards "Bhoreham Requalification Plan & Equipment Lists at Oualification Level" & "Amplified Response Spectra for Equipment Oualification." Revision 1, in response to NRC B10128 request.

  NAVARRO, J. P. Long Island Lighting Co. 81/03/27. 2pp. 08077:278
- --8103310306 "Shoreham Requalification Plan & Equipment Lists at Obalification Level."

  9 Stone & Webster, Inc. 81/03/25, 58pp. 08077; 280

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8103230538 Discusses NRC slippage of date of issuance for Shorehan SER.in response to 810127 itr issuance date dependent on review status for LaSalle 1 KAMMEPER.C Office of Congressional Affairs 81/03/03. 2pp. 07977 RBO
- BiO3160539 Forwards info addressing MRC concerns re EER review info will be incorporated into F8se. NDVARRO.JP Long Island Lighting Co. 81/03/12 20pp
- --8103160547 Preliminary "Flood Insurance Study Village of Belle Terre.Suffolk County.NY " Related Info encl. • Harris - Toups, Associates 80/01/31 27pp
- 8103230860 Discusses On hearing scheduling process BER technical input schedule for CYBL & CYB2 encl DENTON-H R Office of Nuclear Reactor Regulation, Director B1/03/13 5pp 0/977 099.
- BIO3180502 Forwards info for SER review info will be incorporated into FSAR NOVARRO J P. Long Island Lighting Co. 81/03/1A 12ng 07952-289
- BIO3200642 Forwards info for SER review re angineered safety features, reactor core isolation cooling setpoint.humidity control, diesel generator reliability & purge sys duct Info will be formally incorporated into FSAR.

  NOVARROJ P Long Island Lighting Co BI/03/18 93pp
- F Security, medical, emergency & fire protection plans
- Bi03310338 Ltr to all licensues of operating plants & holders of CPs forwarding NUREO-0656. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting JRRV requirements II/o encl EISERHVI.D. Q. Division of Licensing. Bi/03/05 &pp.
- 81031603B3 Forwards 810311 amended physical security plan.Revision 3. Plan withhold (ref 10CFR2 709). MOVARROJ P Long Island Lighting Co. 81/03/12 3pp. 07917:342.

#### G Adjudicatory correspondence

- 8103030870 Forwards permittee apposition to Shoreham Opponents Coalition 810123 request for facility CP suspension, revocation or mod Certificate of Svc encl. EARLEY.A F. Hunton & Williams. 81/02/27. 2pp 07775:160
- --B103030B76 Permittee opposition to Shoreham Opponents Coalition 810123 request for facility CP suspension revocation or mod EARLEY.A.F Long Island Lighting Co EARLEY.A.F Hunton & Hilliams 81/02/27. 8pp 07795:162
- B103050706 Opposition to Shoreham Opponents Coalition 810123 request that CP be suspended, revoked or modified No basis for requested action No substantial health or safety issues raised to sustain show cause order. EARLEY, A F. Long Island Lighting Co. EARLEY, A F. Hunton & Williams. 81/02/27. 8pp. 07821:328.
- Q. Inspection reports. IE Bulletins & correspondence
- Bi03060304 Forwards IE thep Rept 50-322/80-19 on B01215-18 No noncompliance noted CARLBON.R T. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. B1/01/09. 2pp 07837:054.
- --0103060311 IE insp Rept 50-322/80-19 on B01215-18. No noncompliance noted Hejor areas inspected status of outstanding items work in progress & status of const.

  NARROW-L. Region i, Philadelphia, Office of the Director.

  MATIA-J. Region i, Philadelphia, Reactor Construction & Engineering Bupport Branch. 81/01/08 6pp 07837:056.
- B1031B0173 Forwards 1E Insp Rept 80-322780-18 on 801023-1231.No noncompliance noted. BRUNNER,E.J. Region 1: Philadelphis. Reactor Operations Nuclear Support Branch. B1/01/21. 2pp. 07943-303.
- --Bi03iB0i90 IE Insp Rept 80-322/80-18 on B0i023-123i No noncompliance noted. He yor areas inspected: work activities, preoperational testing & plant staff activities HI00iNS-J.C. Region 1. Philadelphia. Office of the Director. KIBTER-H.B. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 81/01/20 4pp. 07943:305.

- 8103030256 Forwards Suppl 5 to IE Bulletin 80-17. "Feilure of Contr Rods to Insert During Stram at BMR "No written response required ORIER.B H Region 1. Philadelphia, Office of the Director. 81/02/13 ip 07790 302
- BI03200143 Forwards IE Circular Bi-03, "Inoperable Besemic Monitors Instrumentation " No written response required GRIER.8 H. Region 1. Philadelphia, Office of the Director. 81/03/02 jp 07971 349
- B103230196 Forwards revised 1E Bulletin B1-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. GRIER.8 H Region 1. Philadelphia. Office of the Director. B1/03/04 1p 07977:244
- 8103200134 Forwards IC Info Notice 81-06. "Failure of ITE Model K-6 Circuit Breaker " No response required CRIER.B H Region I. Philadelphia. Office of the Director. B1/03/11 1p 0.7968 271
- BIO3180526 Responds to NRC Info Request 121 27 me preservice insp program plan Discusses program status me piping & vessel welds.components & supports on reactor coolent pressure boundary NOVARROL P. Long Island Lighting Co 81/03/16 2pp. 07954:08
- U Congressional/Executive Correspondence
- 8103240572 Responds to Bi0119 ltr expressing concern re slippage of issuance date for facility EER Commission will meet w/staff to discuss hearing process on 810223 & licensing schedules on 810226 AHCARIE. J F Commissioners 81/02/23 2pp 07987.176
- B103240091 Forwards fourth monthly status rept to Congress for B10115-0215 Rept discusses actions taken on licensing reviews of new facilities Rept will be anended to include addl info requested on B10217.

  KAMMERER.C Office of Congressional Affairs 81/02/27 Spp
- 8103240124 Responds to 810127 itr expressing concern re slippage of issuance date for facility BER Commission will meet w/ staff to discuss hearing process on 810225 & licensing schedules on 810224 AMEARNE, J. F. Commissioners 81/03/03. 2pp. 63138:218.
- 8103270110 Responds to request for rept on possible add1 improvemen to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
  HENDRIE. J M. Cormissioners 81/03/12. Spg.
- --Bi03270931 Submits recommendations to expedite impacted DL hearing Code should include set of TMI-related DL requirements ASLAB decisions on fuel loading & low power testing should be immediately effective
  BICKMIT. L. Office of the General Counsel. 81/02/23. 1Opp. 08043.344
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- BIO3190732 Ltrs to all licensees of operating plants.applicants for OLs & holders of CPs re control of heavy loads.Requests review per guidelines in NURBO-0612 Forwards NRC position reinterim actions & request for addl info EIBENHUT.D Q. Division of Licensing. 80/12/22. 30pp.
- 8103170387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737. EIBENHUT.D.O Division of Licensing. 81/01/19. 6pp.
- BiO3120014 Ltr to all licenses of operating plants, CP holders & OL applicants, except Indian Point 2 & 3,21on 1 & 2 & THI-1, forwarding inadvertently onlited pages from NRC B01222 request for add info re control of heavy loads.

  EISENHUT, D G. Division of Licensing. BI/02/03. 6pp.
- G103050818 Responds to NRC 791005 request for add1 info re potential errors in steam generator water level measurements due to environ teep effocts on level ref logs. Calculations showing required error setpoint for low-low trip function encl. CRANC.P.A. Pacific Gas t Electric Co. 81/02/19. 3pp. 07828:13

- B103280024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISEAMUT.D 0 Division of Licensing. 81/02/20 8pp
- Sichagoogo Litrito all litensees of operating nuclear power plants & applicants for CLs (except St Lucie/Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures.

  EISENHUT. O O Division of Licensing. 81/02/25 Spp
- 8103060279 Butmits supplemental responses to specific action plan requirements includes info re RCS vents, post-accident sempling capability, training for nitigating care Jarage, NGSS vendor review of test procedures & shift technical advisor CRANE.P A Pacific Oas & Electric Co 01/02/26 32pp 07839 323
- 8103230813 Generic Ltr 81-06 to all CP holders & GL applicants re 10CFRSO 71(e). "Periodic Updating of FBARs," effective 800722 Info re FSAR legal status.for-at & content encl. ETSERHUT-D O Division of Licensing. 81/02/26
- 8103050273 Forwards info re-potential net positive suction head problems wifeld pump when taking suction on containment sump CRANE.P A Pacific Gas & Electric Co 81/03/02. Spp. 07831 309
- B103260852 Forwards 147 meilgrams & ltrs addressed to setretary Edwards W/o ltrs Authors & addresses listed. BETANCOURT.8 Energy Dept of. 81/03/03. app. 08036.285
- B103120B17 Forwards request for add1 info re items 260-11 through 260-16 delineated in B10122 GA program Review of Table 3.2-4. "Classification of Btructure.Gys & Components for Dieblo Canyon." identified deficiencies in Item 260-17. TEDESCO.R t. Assistant Director for Licensing 81/03/06 5pp 07905.021
- 8103280923 Forwards request for add1 info re Jan 1981 wave damage to breatwaters protecting plant intake structure Response needed for completion of review.

  TEDESCO.R L. Assistant Director for Licensing 81/03/09 8pp. 08036-310.
- B103120456 Forwards Westinghouse burst & blockage calculations in response to NRC 791109 itm ne fuel rod models used in LUCA ECCB evaluation models Current Mestinghouse models are conservative & comply w/10CFRSO.app K CRANE.P.A Pacific Oas & Electric Co. 81/03/10. Upp. 07906-278
- 8103170542 Notifies of rapt to be prepared by 810715 re adequacy of safety-related mesonry walls Rept will address identification.design review. Structural Engineering Branch design criteria.deficiencies & implementation schedule. CRANE.P.A Parific Cas & Electric Co 81/03/12. 2pp. 07930.129.
- 8103170145 Notification of 810316 meeting w/mear-term DL applicants in Bathesda.ND no info required to be submitted on environ qualification of electrical equipment prior to sits visit & NRC review.

  BURNECLL B Licensing Branch 2. 81/03/12 15pp. 07965-004
- B1033000B7 Forwards add1 info requested by NRC 800B27 ltr re application for DL. Submittal addresses. main feedwater & steam piping feedwater isolation valves FCV-441.FCV-44, penetration sleeves & flued head & equipment hatch. CRANE, P. A. Pacific Gas & Electric Co. B1/03/12. 53pp.
- Bi03i70403 Submits responses to Questions 3 & 4 in NRC 800827 ltr restress corresson cracking & turbine missiles.

  CRANE, P. A. Pacific Oos & Electric Co. 81/03/13. 3pp. 07934:334.
- 8103170615 Requests acknowledgment of receipt of Westinghouse coments re-emergency procedures which were discussed at 810311 meeting w/NRC Procedures will be consistent w/Hestinghouse ref emergency operating instructions.

  CRANE, P. A. Pacific Gas & Electric Co. 81/03/13. 2pp. 07925:170.
- BIO3170665 Provides requested info re NUREO-0737 Items II B. 3.postaccident sampling capability, II. D. 1. testing of reactor relief & safety valves. II. K. 2. orders on BSN plants, II. K. 3., final B&O task force suggestions & III. D. 1.1. sys integrity. CRANE, P. A. Pacific Gas & Electric Go. BI/03/13. 17pp. 07925-121.
- B103200529 Responds to B10306 request for add1 info re GA/GC program requirements.

  CRANE, P. A. Pacific Gas & Electric Co. B1/03/18. Spp. 07972:160.

- 8103240396 Forwards response to MRC request for addit clarification of 1810206 submittal relation 11.F 2 of NUREG-0737 concerning inadequate core cooling CRANE, P.A. Pacific Gas & Electric Co. 81/03/19 3pp 07987
- B103300311 Forwards status of Mestinghouse review of util low portest grognary power ascension procedures & energency procedures re Task Action Plan Item 1 C 7 Reviews will be completed prior to operation above 5% full power CRAMER PA Pacific Oas & Electric Co B103/26 2pp 08055
- E NAC Safety Evaluation Report (SER), supple & correspondence
- 810320308 Forwards Suppl 12 to SER NUREG-0679, "SER Re Operatio Diablo Canyon Nuclear Power Plant.Units 1 to 2 " Suppl delineates evaluation of all TMI-2 catters for operation at power levels not to exceed 5% of rated full power. MIRAOLIA: F. J. Licensing Branch 3 81/03/04 6pp. 07971 028
- 8103230112 Forwards list of open issues for which util submitted but no BER input has been received. Encl 2 identifies issues for which util must provide info & expected submittal dates BUCKLEY.R Licensing Branch 3. 81/03/16 3pp 07983.001
- 8103180664 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CANYON AUCLEAR POWER PLANT, VUITS 1 & 2 Docket Nos 50-275 and 50-223 (Pactfic Gas and Electric Corpany) 

  Office of Nuclear Reactor Regulation. Director NURGO-0675 81/03/31 54pp. Available at NITS 43 75 08024 291
- F Security, medical, emergency & fire protection plans
- 8103310336 Ltr to all licensees of operating plants & holders of forwarding RUREG-0596. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISERWUT.D Q. Division of Licensing 81/03/03 App
- 8103160130 Forwards responses to NRC Bi0101 comments on Revision security plan Responses withheld (ref 10CFR2 790) Written response required CRANE, P.A. Pacific Gas & Electric Co. 81/03/12. Ip 07921
- BiO3170463 Advises that previously submitted state radiological do not meet regulatory requirements, per NUREO-0737 Plans are still in full force & effect Revision 2 of emergency plan has been submitted & is supplemented by 810113 ltr CRANE, P.A. Pacific Gas & Electric Co. 81/03/12. pp. 07925.
- B103170533 Responds to NRC B01216 request re evaluation of potent earthquake effects in emergency response plans. Evaluation results will be incorporated in emergency plan prior to operation above 5% power CRANK: P.A. Pacific Gas & Electric Co. 81703/13 ip. 07930:1
- BiO3240426 Forwards info re fire protection program at facility. Bections [[[.6.1]] J & []] D of App R to 10CFR90.Util will increase capacity of reactor coolant pump oil collection sys & porform setsmic evaluation. CRANE.P A Pacific Gas & Electric Co 81/03/20 3pp. 07987
- BiO3310645 Forwards discussion of site specific meteorological for submitted in response to NRC request for info re upgraded meteorological program for emergency preparedness per criterial in NuRGe-0654.app 2 Actionaledgement requested CRANE, P.A. Pacific Gas & Electric Co. 81/03/27 app. 08075.
- 9 Adjudicatory correspondence
- 8103110674 Order granting extension until 810213 for Commission decide whether to review ASLAB 801230 order.
  CHILK 8 J. Office of the Secretary of the Commission 81/02/0
- 8103110371 Order granting extension until 810220 for Commission of decide whether to review ASLAB 801230 order. CHILK-8 J. Office of the Secretary of the Commission. 81/02/1 jp. 07886:129
- 8103120633 Order affirming ASLAB 801230 decision chastising Gover Brown counsel. HH Brown & LC Langher. For conduct in proceeding Conduct was (II)-considered & constituted extremely poor judgment. Banitized order encl. CHILK. B. J. Diffice of the Secretary of the Commission. 81/02/6 3pp.

- plan released vipleted No sanctions imposed BIBHOP.C J Office of the Secretary of the Curmission BO/12/31
- 8:03090554 Joint Intervenors' Interrogatories directed to util requesting info re Contentions 4.5.11.13 % 24 Certificate of Svc encl Related correspondence REYNCLDS.J R San Luis Obisso Mothers for Peace REYNCLDS.J R Center for Leu in the Public Interest 81/02/23 15pp 07629 036
- B103050564 Joint Intervenors' interrogatories directed to NRC requesting info re Contentions 4.5.11.13 & 24 Centificate of Sv. enc. Related correspondence REYNOLOS.J R Gan Luis Obispo Mothers for Peace. REYNOLDS.J R Center for Law in the Public Interest. B1/02/23 15pp. 07029 050
- 8103050674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties (CHRISTENBURY, E. Hearings Division B1/03/04 2pp
- 8103050842 Objections to ABLO 810213 prehearing conference order admitting Joint Intervenors' Contentions 4.5.11.13 & 24. Mero cantion in NURECO-0737 insufficient to make issue ASLB used crong std for reogening records W/Certificate of Svc CRANE.P A Pacific Oas & Electric Co. OEHR.A C Snell & Wilmer NORTON.B Sruce Norton 81/02/25. 7pp 07828.161
- \$103020400 Responds to Commission B10220 order criticizing CA Governor Brown counsel Order was misleading grossly generalized & conveys false inpressions about counsel conduct Transcripts should be publicly available & Itr should be sent w/order BROWN.H H. LAYPHER.L C. California. State of B1/02/26 Spp. 07702 178
- BIO3130484 Responds to DB Fleischaker BIO219 ltr re util refusal to permit 8 Bilver to tour facility. As party to proceeding. Bilver rights to tour facility are governed by NRC discovery regulations Related correspondence. CRANE.P.A Patific Gas & Electric Co BI/02/26 Ip 07913-088
- 8103030597 Response supporting NRC 810223 request for directed certification to clarify CLI-80-42 Briefs should be filed. 21 days after certification & reply briefs 10 days later. Certificate of 8vc enci.
  REYMOLOS J. R. Center for Law in the Public Interest FLEISCHAKER, D. Fleischaker, D. S. 81/02/27 Spp. 07793:210.
- 8103030883 Forwards objections to ASLB 810213 order NUREO-0737 does not apply to licenses to load fuel & conduct low power tests Requests relief from Items III A 1 1 & III A 2 requiring compliance w/App E to 10CFR90 prior to fuel load FURBUSH.M.H. Pacific Oas & Electric Co. 81/02/27. 2pp. 07796 219.
- --BIOGOGOBBB Objects to ABLB BIO213 order admitting Joint Intervenors' Contentions 4, 5, 11, 13 & 24 Good cause was not demonstrated Record should puly be reopened for significant new evidence that affects decision CRANE.P A Pacific Gas & Electric Co. GENR.A.C. Snell & Wilmer. NORTON.B. Bruce Norton B1/02/25 Spp. 077/6-221.
- --Bi03030894 Forwards FEMA/NRC interim agreement on criteria for luw power testing at new commercial nuclear facilities Public health & safety is adequately protected if facility is located in state receiving previous concurrence. ORIMES.B. M. Energency Preparedness Task Force RYAN.R. Federal Emergency Management Agency 81/02/27 2pp. 07796-226.
- 8103130494 First set of interragetories & requests for production of documents directed to Governor Brown requesting info re-Contentions 4.5,11,13 & 24 & uitnesses to be called. Certificate of Bvc encl Related correspondence. GEHR.A.C. Pacific Qas & Electric Co. GEHR.A.C. Bnell & Wilmer. 81/02/27. 16pp. 07913.096.
- 8103130500 First set of interrogatories & requests for production of documents directed to Joint Intervenors requesting info re Contentions 4.5, 11,13 & 24 & ultresses to be called. Certifficate of Svc encl Related correspondence. GEHR.A.C. Pacific Qas & Electric Co. GEHR.A.C. Bnell & Wilmer 81/02/27. 18pp. 07713 038
- 8103120560 Response opposing util 810226 request for directed certification.review of ASLB 810213 order & review of entire OL proceeding. Request overbroad.ill-defined & w/o legal basis. Certificate of Svc encl.

  REYNOLDB.J.R. San Luis Obispo Mothers for Peace REYNOLDB.J.R.

  Scenic Shoreline Preservation Conference, Inc. REYNOLDB.J.R. Center for Law in the Public Interest. BI/03/09. 11pp. 07904:233.

8103130559 Opposes util 810227 request for relief from certain emergency response planning requirements contained in NUREQ-0737. "Clarification of IMI Action Plan Requirement." Emergency planning is subj. of edmitted contention. REYNOLDB. J. R. Center for Law in the Public Interest. 81/03/09. Spp. 07908.322

91 /03/09

admitted contention to be decided in proceeding REYNOLDS, J.R. Center for Law in the Public Interest

07904 244

- B103:80356 Response on behalf of Oovernor Brown supporting NRC B1022 request for directed certification of certain issues. Opposes util 810226 similar request issue re need for EIA should be directly certified M/Certificate of Svc GEORGIOU. B. 8. LAMPHER. L. C. California, State of. LAMPHER. L. C. Jiill. Christopher & Phillips 81/03/09 13pp 07953:038
- 8103120353 Forwards responses to State of CA Governor Brown 810220 interrogatories & document production requests directed to tAC JCNES.B W. Hearing Branch 2 81/03/10. Ip 07901 190.
- --Bi03120373 Response to CA Governor Brown Bi0220 interrogatories & request to produce re-emergency planning. Objects to Ducurent Request 2 as being overly broad if document request is more specific, NRC will comply Certificate of Svc encl DRES.B W. Hearing Branch 2 TAM.P 5 Emergency Preparedness Licensing Br. (after B01119 see IKE). 81/03/10 Spp. 07901 191
- 8103130406 Order directing NRC to provide status rept on issuance dat of Suppl 12 to BER BOMERBLES Atomic Safety and Licensing Board Panel. 81/03/10. 1 07911-202
- BIO3200678 Answers to CA Governor Brown BIO220 interrogatories & document production requests re util state & local amergency response plans Objects to document production request Centificate of Svc encl Related correspondence.

  NGITCH: B GEHRAG. C FORBUSH: M H Pacific Oas & Electric Co BI/03/11 7pp 07969-260
- 8103180848 Response to ABLS 810310 request for status rept on issuance of SER.Suppl 12 Document (seved on 810304 Suppl 13 or 14 to be issued by 620331 One suppl to deal winon-THI Issues better will deal w/TMI Issues Certificate of Svc enci.

  JONES 8 W. Hearing Branch 2. 81/03/16 3pp 07903.214.
- 8103190637 Notice of ASLB reconstitution. JF Wolf cheirman. GD Bright & JR Kline. members COTTER. B. P. Atomic Bafety and Licensing Board Panel. 81/03/16. 2pp 07964-081
- 8103230715 Answers to Joint Intervenors' 810223 interrogetaries re Contention 4,FBAR,6ER, emergency planning regulations & public evacuations Certificate of Svc encl Related correspondence NORTON.B., GEHR.A C., FURBUSH.M.H. Pacific Ges & Electric Co. 81/03716. 103pp. 07973.224.
- 8103260626 Clarifies util position as represented in Joint Intervenor response to util request for directed certification. No further hearing necessary re util notion to load fuel & conduct low power tests

  CRANE, P.A. Pacific Oas & Electric Co. 81/03/16. 1p. 08041:108
- B103260720 Responds to NRC B10224 request for admissions by joint intervenors re facility low power test proceeding. Certificate of Svc encl Related correspondence. REYNOLDS, J.R. Ban Luis Obispo Mothers for Peace. REYNOLDS, J.R. Center for Law in the Public Interest. B1/03/16. 6pp. 08041:073
- 8103260750 Joint Intervenors response to NRC 810224 interrogatories of core exit thermocouples & saturation maters, reactor vassal water levels, inadequate core cooling & energency planning issues. Certificate of Syc encl. Related correspondence.
  REYNCLOB.J.R. FLEISCHAARR.D. Affiliation Unknown. REYNQLDB.J.R. Center for Law in the Public Interest. 81/03/16. 22pp. 08036:025
- 8105260788 Response to NRC requests for admissions & Interrogatories reactor pressure vessel water level.core exit thermocouples & emergency procedures for inadequate core cooling. H/affidavits & Certificate of Svc Related correspondence, BROWN.H.H. GEORGIQU.B.8 california, State of. BROWN.H.H. Hill:Christopher & Phillips. 81/03/16. 55pp. 08036:098.

- 8103190616 Request for corrections of nisinterpretation of revised policy statement by accepting cartification or clarifying statement ASLB illogally constricted intervenors: rights to challenge sufficiently of TMI-related safety requirements WEIBSLER Union of Concerned Scientists WEISSLER. Parmon & Weist 81/03/17 9pp 07963-276
- --Bi03190622 Request to address Cormission as amicus curiae in support of requests for certification filed by Joint Intervenors & CA Governor Brown to urge Commission to correct ASLB error Certificate of Syc encl
  HEISSE R Union of Concerned Scientists HEISS. E. R Harmon & Heiss. 81/03/17 Spp. 07963:285
- B103Ta0945 Request to compel util to answer interrogatories under oath NRC regulations require such action. Failure to comply creates problems w/answers at trial. W/prof qualifications & Certificate of Svc Related correspondence.
  GECROIDU. B. B., LANPHER. L. C. California. State of. LANPHER. L. C. Hill. Christopher & Phillips 61/03/17 17pp 08036:239.
- B103190052 Correction to B10316 rept in response to ASLB B10310 order re issuance of Buppls 13 & 14. Issuance date should be G10331 not B20331. Certificate of Eye and 1. Cert
- Bi03200030 Response to util 819226 motion for directed certification of ASLB BI0213 ruling re litigation of Joint Intervenore' contentions. Commission should direct certification & reverse ASLB rulings admitting contentions L/Certificate of Bvc. CLHSTEAD.H.J. Hearing Branch 4. JCNES.B W. Hearing Granch 2. 81/03/18. 30pp. 07970.023
- B103260966 Informs of Joint Intervenor desire & intention to be heard on merits of issues raised by NRC & PO&E B10223 & 26 requests for directed contilication Review of B10401 substantive response expected prior to decision PLEIBCHAKER.D., REVNELDS.J.R. Center for Law in the Public Interest. B1/03/20 2pp 08041-056
- 8103260807 Notification that Covernor Brown will submit brief discussing merits of util & IRC B10226 & 0318 submittals, respectively. Brief will be filed to assure opportunity to be heard on safety-related issues M/Certificate of Svc BROWN.H.H. California, State of, BROWN.H.H. Hill.Christopher & Phillips B1/03/23. 5pp 08036:202.
- BiO32701B1 Buppl to NRC 810316 response to Joint Intervenors interrogatories. BNNL ongoing research may been on listed interrogatories Certificate of Svc encl.

  JOKES B M. Hearing Stanch 2 81/03/25. 3pp. 08045 318.
- 8103270460 Errata to NRC response to Joint Intervenors' interrogatories.Certificate of Byc encl. JONES-B.W. Hearing Branch 2 81/03/25. 4pp. 08034:140.
- H General correspondence
- 8103200383 Urges startup of fatilities. HIQQINS.C. Affiliation Unknown. 81/02/10. 1p. 07585:001.
- BIO3200585 Urges startup of facilities.
  PRINCE C Affiliation Unknown 81/02/12. 1p. 07585:001.
- 8103200699 Urges administration to adopt policy to expedite licensing of nuclear power plants & to appoint strong chairman to enforce policy.

  ALQUIST-R. E. AYALA-R. S. BRATHRIGHT, D. E. Celifornia, State of. B1/02/12. 3pp. 07970:001.
- B103270465 Supports Pacility DL application. ALDRICH-R. L. Affiliation Unknown. 81/02/12: 1p. 08043.090.
- 8103160295 Urges startup of facilities. NOMEROLL V. Affiliation Unknown. B1/02/13. ip. 07918:362.
- BI03300321 Ten ltrs urging startup of fecilities. NELSON, B. O. Affiliation Unknown, B1/02/13, 11pp.
- 8103260814 Comments on NRC performance re French nuclear industry plan. WALKER: 9. J. Affiliation Unknown, 81/02/18. ip. 08041:072.
- 8103270444 Package of 121 mailgrams from citizens supporting facility startup. MURPHY.N. Affiliation Unknown. 81/02/18. 121pp.

- 8103200486 Urges that NRC grant CLs u/o delay Applicant has met all safety-related & sets-sic requirements Plants are needed for electrical power generation STEFAHETTI.H J Affiliation Unknown 81/02/19 1p 07985 001
- 8103200600 Supports licensing of plants BRADSHAW J. Affiliation Unknown B1/02/19 ip 07971 260
- BIO3170492 Urgss startup of facilities
  REHBOCK C R Affiliation Uninown BI/02/20. ip. 07985.001
- 8103200463 Supports plant operation. BRAGHETTA.L H APFILIAtion Unknown 81/02/20 ip 07587 001
- Bi03200902 Urges that NRC grant OLs u/o delay Applicant has not safety-related & seismic requirements Plants are needed for electrical power generation VOLLE, H Affiliation Unknown 81/02/20. Ip 07585 001
- BIO3170617 Supports license issuance (FEON.R Affiliation Unknown B1/02/23 1p
- 8103200424 Urges NRC to grant license for facilities. TORRICE, R A. TORRICE, E. Affiliation Untrown 81/02/29 | Ip 07885-031
- 8103200544 Urges startup of facilities a Affiliation Unknown 81/02/23 in 97585 001
- B103040230 Responds to FOIA request for H Denton 771010 memo 5 supporting documents Forwards documents listed in App A Rept entitled "Hurbolds Bay Power Plant Site Dealogy Investigation" is available in PDR. FELICIAL JM Division of Rules and Records. 81/02/24. 2pp
- 8103170384 Urges startup of facilities WHEATLEY.A.D Affiliation Unknown. 81/02/24 [p. 07589.001.
- 8103170500 Corments that facility should be started up Safety & seismit requirements have been most SCHROSOR.M.E. Affiliation Uninown 81/02/24 Ip
- B103200467 Bupperts plant operation BHITH, B. Affiliation Unknown B1/02/24 Ip 075B7.001.
- 8103200471 Supports facility operation. FINER, L. Affiliation Unknown 81/02/24 ip. 07971 263
- B103230711 Opposes granting of OL. Planned site within 2.5 miles of Hosgri fault.
  BARCLAY, H. Affiliation Uninoun. 81/02/24. 1p. 07977:343
- B103200474 Supports plant operation ROGERS.D. H Affiliation Unknown. B1/02/26. Ip. 07971: 262.
- Bi03200337 Urges startup of facilities HILLARD.C.L Affiliation Unknown 81/02/26. Ip. 07585:001.
- 8103110470 Forwards Orange County Chamber of Commerce 810227 resolution favoring irrediate licensing of facilities TRUHILL, L. D. Orange County, CA. 81/02/27, 2pp. 07882:159
- 8103120899 Forwards FOIA request for documents to Abalone Alliance. 770806 demonstration at San Onofre nuclear plant & 780806 demonstration at Diablo Canyon nuclear plant. KOEHLER, W.R. Justice, Dept. of. 81702/27. 2pp.
- B103200493 Urges that NRC grant OLs w/o delay.Licensee has met safety-related & seismic requirements.Plants are needed for electrical power generation.
  CUMHINDS-F.E. CLAUGH.R.H. PHILLIPS.T.J. Affiliation Unknown.
  81/02/27 1p. 07585.COI.
- BI03200498 Urges that NRC grant OLe w/o delay. Applicant has met safety-related & seismic requirements. Plants are needed for electrical power generation.

  OULLICITY. COOLEY.F. H., MARTIN.F. J. Affiliation Unknown. BI/02/27

  Ip. 07885:001.
- 8103200548 Urges startup of facilities. MURRAY.H.: MORBE,A.E. Affiliation Unknown. 81/02/27, 1p. 07585.001.
- B103200552 Urges startup of facilities. MEBS.A.J Affiliation Unithown B1/02/27. 1p. 07585:001.

- 6103209933 Urges that NRC grant OLs for Parsities w/o delay.due to need for electrical energy BLOWERS.L Affiliation Unknown 81/02/20 ip 07985 001
- 8103170588 Opposes delayed restart of facility BROWN,F Affiliation Unknown 81/03/02 to
- 8103170456 Urges that NPC grant facility OL Facility has met all safety & seismic requirements & is needed to provide electrical energy in critical yrs ahead BEJARAND.J R AFFILIATION UNKNOWN 81/03/03 is
- 8103;70490 Urges startup of facilities TYLER.W J. PHILLIPS.R C Affiliation Unknown 81/03/03 1p 02583 001
- B103170501 Expresses admiration for Ahearne Requests autograph
  CZIKGUSKY, L Affillation Unknown. 81/03/03 ip 07585 001
- 8103170329 Expresses concern re delay in licensing facility High energy prices & underscratic licensing delay are due to antinuclear activists
  LAMB.P.R. Affiliation Unknown 81/03/03 lp
- BIO3200514 Urges that NRC grant OLs w/o delay. Applicant has met safety-related & seismic requirements. Plants are needed for electrical power generation CORDRAY.D A Affiliation Unknown. B1/03/03 1p 07989.001
- B103200586 Urges startup of facilities
  PDA.L.A Affiliation Unknown 81/03/03. ip 07585 001.
- BIO3110348 Bupports IMI-1 restart & licensing of other facilities SKERNOOD, G. L. Affiliation Unknown BI/03/04 19 07883 283
- B103180519 Expresses shock re delays in licensing new nuclear plants Cormissioners responsible for delays. ALLEN.C.R. Affiliation Uningum. 61/03/09 ip. 07944-261
- 8103120852 Responds to FOIA request for Jacuments of Abalone Alliance.
  770806 demonstration at San Onofre nuclear plant & 780806
  demonstration at Slabin Conyon nuclear plant Forwards E0
  Case 770203 Ito to Bouthern CA Edison Co
  FELTORIJ M Division of Rules and Records 81/03/10 lp
- 8103260529 Urges expeditious licensing of util to load fuel & assume full power operation Util has accomplished all retrofitting ceasures. State of CA needs 20% power increase that facilities could supply CURP.M. California, State of 81/03/11 Ip 08037-362
- B103200532 Urges grenting of OL to facility
  ALBRECHT, R. O. . ALLEN-D. C. Application Unknown 81/03/16 lp
- BJ0326080B Urges restart of facilities Environ.political.ecohomical & sociological damage caused by needless shutdowns are immeasurable.

  OUNNEATR. 8. Affiliation Uninoum 81/03/19 ip
- B103260819 Urges NRC to expedite full power licensing of facilities & restart of TMI-I Concern for safety & careful review of licensing process has gone beyond reasonable caution TACHAOL.3 W Affiliation Uninown. B1/03/21
- P Operating license stage documents & correspondence
- B103310BDA Lir to all licensees of operating plants applicants for DLs & holders of CPs forwarding BECY-81-117 re info necessary to establish environ qualification of safety-related electrical equipment EIBENAUT. D 9 Division of Licensing. B1/03/10 6pp.
- Q Inspection reports: IE Bulletine & correspondence
- 8103030489 Forwards IE Insp Repts 90-275/80-23 & 90-323/80-12 on 801201-31 No noncompliance noted CREWB.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 81/01/13 2pp
- --BI0303049B IE Insp Repts 30-275/80-23 & 30-323/80-12 on B01201-31
  No noncompliance noted Major areas inspected preoperational
  testing plant tour operating staff training fuel storage &
  operator training
  YOUNG, T. BAOAQLIO. M. Region 5. Ban Francisco, Office of the
  Director. STERNBERG. D. M. Region 5. Ban Francisco, Reactor
  Operations Nuclear Support Branch 81/01/08. 4pp.

- 8103180515 Foruards IE Insp Repts 90-275/81-01 & 50-323/81-01 on 810101-31 No noncompliance noted. CREWS.J.L. Region 5. San Francisco. Reactor Operations Nuclear Byoport Oranch 81/02/06 2pp 07949-318
- --Bin3180523 IE Insp Repts 50-275/Bi-01 % 50-323/Bi-01 on Bi0101-31. Nanocompliance noted Major areas inspected preoperational testing, plant tour fire prevention protection & IE builetin/ circular followup
  YOUNG T , BAGAGLIO M Region 5, San Francisco Office of the Director. STERNBERO M Region 5, San Francisco Reactor Operations Nuclear Support Branch 81/02/06 5pp 07949-320
- 8103020076 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty" No written response required ENGELMEN.R.H. Region 5. San Francisco. Office of the Director 81702709 1p 07787 342
- 8103160636 Forwards 1E Info Notice 81-03 "Checklist for Licensees Making Notification of Bignificant Events in Accordance W/10CFR30 72." No response required EMBELMEN.R H. Region 5. Ban Francisco. Diffice of the Director.
- 8103160661 Forwards IE Info Natice 81-04. "Cracking in Main Bleam Lines" No response required. EMJELKEN.R H. Region S. Ban Francisco. Office of the Director 81/02/27 1p 07914-250
- B103170023 Forwards IE Circular B1-03. "Inoperable Seismic Monitoring Instrumentation" No response required ENGELKEN/R H Region S. San Francisco. Office of the Director B1/03/02 1p. 07939-149
- 8103140845 Forwards revised [5 Bulletin 81-01, "Surveillance of Mechanical Boutbers," w/corrected Pages 5 & 6 Util is added to CP facilities to which bulletin is applicable Response should include estimate of manpower expended ENGELMEN.R H Region 5, San Francisco. Diffice of the Director. 81/03/04 ip 07914.205
- 0103200252 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required ENGELKEN R. H. Region 5. San Francisco. Office of the Director. 81/03/11 ip 07968-340
- B103200047 Forwards IE Info Notice B1-05, "Degraded DC Sys at Palisades " No response required ENGELKEN.R H Region 5, San Francisco, Office of the Director. B1/03/13 Ip. 07970 019.
- S Reportable occurrences. LERs & related correspondence
- 810G020514 Interim deficiency rept re 6-s delay in containment spray pump start after high-high pressure signal during LOCA, initially reported 801204 Starting sequence will be changed. Final rept due after design of modified starting scheme. CRANE, P.A. Pacific Gas & Electric Co. 91/01/19. 2pp.
- 8103180489 Final deficiency rept re Hagan Model IIB low level amplifiers indicating improper output voltages, initially reported on 810206 Transistors 2N699 in Location GI4 will be replaced Technical analysis encl.

  CRANS. P.A. Pacific Oas & Electric Co. 81703/09 16pp
- 8103300480 Board notification re facility breakwater demage on B10129 Damage to be further inspected by NRC Bafety implications to be determined following discussions w/applicant & consultant TEDESGO.R L. Assistant Director for Licensing 81/03/18. 3pp. 08057: 173
- U Congressional/Executive Correspondence
- B103200455 Requests info re Commission position on licensing procedures
  BAILET, D. House of Rep. B1/02/18 ip. 07971:264.
- B103240091 Forwards fourth monthly status rept to Congress for B10115-0215 Rept discusses actions taken on licensing reviews of new facilities Rept will be amonded to include addl info requested on 810217.

  KAMMERER.C. Office of Congressional Affairs. 81/02/27. 3pp. 07990: 119
- Bio3270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
  HENDRIE: J M Commissioners. 81/03/12. Spp

- --BID327093: Bubmits recommendations to expedite impacted OL hearings Code should include set of TMI-related OL requirements ASLAB decisions on fuel loading & low power testing should be immediately effective BICMMIT. L. Office of the General Counsel B1/02/23 10pp
- V Operator Examinations
- 8103020579 Submits info re shift technical advisor operator training & qualification & 880 Task Force recommendations in response to NRC request Supportive documentation enci. Related correspondence CRANE.P A Pacific Gas & Electric Co 81/02/13 23pp
- DOCKET 90-324 BRUNSHICK STEAM ELECTRIC PLANT. UNIT 2 F Security, medical, emergency & fire protection plans
- BIO3180264 Ltr to all power reactor licensees u/plants licensed prior to 790101 Forwards NRC position & request for addlinfore safe shutdown capability for compliance u/BO3119 fire protection rule EISEN-MUT.0 Q. Division of Licensing 81/02/20 13pp.
- Bi03310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements M/o enci
- 9103120669 Requests elemption from certain requirements of 10CFR90 48 & 10CFR90, App. R refire protection Current fire protection measures suffice to protect public health & safety Supporting info encl.

  VTLEY.E.E. Carolina Power & Light Co. 81/03/06 36pp. 07906.242
- 8103190163 Releases public version of emergency procedures FELTOR. J. N. Division of Rules and Records. Bi/03/13 ip 07806.001
- --8103190169 Forwards public version of operating ranual Vol 13. Book 2.
  exergency procedures
  UTLEY.E E Carolina Power & Light Co 81/02/25 ip. 07806 001
- --8103190177 Public version of operating manual.Vpl 13.8001 2.emergoncy procedures includes emergency classifications & control, onergency action procedures energency facilities & equipment & training exercises & drills.

  \* Carolina Power & Light Co 81/02/25 375pp. 07806 001.
- Bi03240349 Informs that exemption request was filed Gi0311 seeking stansion until Gi0911 for providing plans & schedules for compliance w/fire protection safe shutdown capability item Emergency lighting w/G-h capability will be installed UTLEV-E E Carolina Power & Light Co. 81/03/19. 2pp 07981 395.
- B103251194 Requests that encl emergency planning into to placed in LPDR M/o 8103190169 SOUDER/JL Division of Rules and Records 81/03/24 ip. 08040-243
- G Adjudicatory correspondence
- 8103030552 Forwards B10227 petition for hearing re-order for license and & grant of exemption extension per NRC B10128 orders FLYNN-5 F Carolina Power & Light Co 81/02/27 1p. 07775.208
- --Bi03030561 Petition for hearing re Bi0113 order for license mod & grant of exemption extension Request directed to order establishing completion dates of 820228 & B11130.Cortificate of filing encl
  JONES.R. E., FLYIN.S.F. Campline Power & Light Co. 81/02/27, 3pp 07795:209
- J. Insurance & indemnity information
- B103100393 Forwards Endorsement 5 to MAELU Binders XB-54 & XB-55 BARHAM.C D. Carolina Power & Light Co. 81/03/05 3pp. 07867:244
- B103230645 Forwards Endorsement 3 to MAELU Binders XB-34 & XB-55 Informs of error in 810305 transmittel ltr which referred to MELIA Binders EB-54 & EB-55 as XB-54 & XB-55.
  BARHAM.C.D. Carolina Power & Light Co. 81/03/17.

- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NAREO-0612 Forwards NRC position re interim actions & request for add info [ISECHUJI.D G Division of Licensing 80/12/22 30pp
- giO3190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of sefety-related electrical equipment items addressed involve cold shutdown replacement parts & NUREO-0737 EISECHUTU.D Q Division of Licensing 81/01/19 App
- 8103240290 Lin to all BHR licensers forwarding Suppl L to generic safety evaluation on BHR scram discharge sys Summerlies re-evaluation of interim measures recommended per 801201 safety evaluation EISENHUT.D 0 Div(sion of Licensing 81/01/23 Zpp
- 8103120014 Ltr to all licensees of operating plants.CP holders & CL applicants.except Indian Point 2 & 3.7ion ( & 2 & IMI-1, forwarding inacvertently contitted pages from NRC 801222 request for add1 info re control of heavy loads
- B103150869 Ltr to all operating plants t CP holders forwarding clarification of IMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be net EISCR##IT.D Q Division of Licensing B1/02/18 12pp

EIGENHUT, D.O. Division of Licensing 81/02/03

- 8103250024 Ltr to all power reactor licensees & license applicants re INREG-0619 criteria Foutnoto 2 in Table 2 contains error due to leakage testing Seletions Licensee may submit analysis to justify use of existing lou flow controller EIBENNUT.D O Division of Licensing 81/02/20 Spp
- Bi03030BB7 RQ on 810223, analysis indicated that ten supports on control rod driveline yent line would fail in as-built condition during designed setsmic event on 810220 RCIC tripped w/o receiving permission DIETZ.CR Carolina Power & Light Co. 81/02/24. 10 07795 199
- 8103230030 Ltr to all licensees of operating nucleur power plants & applicants for Ois feacest St Lucie. Units 1 & 2) Requasts whil review to determine capability to nitigate station blackable event & pramptly implement energency procedures EISE(HVI-D) O Division of Licensing 81/02/25 Spp
- 8103030752 Clerifies util 801215 position re NUREO-0737 Item [ A | 3 re limitations on overtime required of licensed operators Util maintains that normal facility manning policies neet NRC

guidance Addl limits will create administrative burden
UTLEY.E E Carolina Power & Light Co 81/02/26 5pp 07796-079

BIO3116061 Bummary of BIO219 neeting w/util in Bethosda, MD to discuss App R procedural & technical questions Util plans to file elemption requests for relief from 10UFR50 4B & from certain and requirements Agenda & list of attendess encl HA:NDM.JN Operating Reactors Branch 2 BI/02/26. App.

07884-359

- B103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting mail per guidelines of encl Revision I to NUREO-0313. Model Tech Specs only encl. EISERHUT.D.O. Division of Licensing. 81/02/26 3pp.
- --8193170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 | surveillance requirements for ABME Code Class 1.2 & 3 | components & RCS operational leakage limiting conditions for operation & surveillance requirements | General Electric Co | GI/O2/26. App
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR80 71(e), "Periodic Updating of FBARs." effective 800722, Info re FBAR legal status, format & content encl. EIEENHUT. D.O. Division of Licensing. 81/02/26 10pp.
- B103110592 Forwards "Component Insp Program & Hydrostatic Test Program & "Pump & Valve Test Program."
  UTLEY.E.E. Carolina Power & Light Co. 81/03/02. 2pp. 07869 205.
- --8103110575 "Component Insp Program & Hydrostatic Test Program." \* Carolina Power & Light Co 81/03/02 78pp. 07869:207.
- ~-8103110597 "Pump & Valve Test Program." Twenty-four oversite drawings

- B103090529 Clarifies commitments made in util 801215 ltr re NUREO-0737. Clarification of TML Action Plan Requirements "Lists responses to issues raised by NRC re shift manning operating activities & emergency preparedness. UTLEY.E E Carolina Power & Light Co. 81/03/03. 2pp. 07848 158
- aio3090633 Submits list of deviations from NRC requirements for NUREO-0737 Item 11 F 1, "Addl Accident Monitoring instrumentation" No plans to sample reactor bldg vents since vents are isolated in any high radiation situation UTEY.E E Carolina Power & Light Co. 81/03/03 2pp 07844 292
- 8103:10424 Forwards suppl to 800916 request for revisions to Tech Specs repost-accident monitoring instrumentation & administrative controls cer Category A Lessons Learned requirements info provides add clarifications u/o changing technical content III FY.E E Ceroline Power & Light Co. 81/03/09 App. 07873-348
- BiO3130384 Requests that NRC issue mods to BiO113 orders re compliance with UREO-0661 criteria for Hart I containment program Major safety mods on Unit I requested during refueling outage. Cominor rods during subsequent refueling outages. UTLEV.E E Carolina Power & Light Co. Bi/03/09 Spp. 07908 194
- Bioggio804 Ltr to all licensees of operating plants applicants for O.s. 5 holders of CPs forwardin; SECY-Bi-119 re info necessary to establish environ qualification of safety-rolated electrical equipment gisEthuyU.D.O. Division of Licensing 81/03/10. App
- 8103160437 Requests amend to License DPR-62 re York Specs revision to establish new vessel level setholints por new common instrument zero level instrument setholint tables excl UTLEY.E E Carolina Power & Light Co. 81/03/11 2pp. 6918 001
- --9193160442 Proposed Tech Specs revisions to Tables 2 2 1-1 through 3 3.6 1-2 re instrumentation setpoint \* Carolina Power & Light Co. 81/03/11 7pp
- 8103160459 Application for amend to Licenses OPR-71 & DPR-72 revising Tech Spec 3 7 1.2 re-sec water operability requirements Approval by 810403 requested UTLEY.E.E. Caroline Power & Light Co. 81/03/13 3pp 07917 380
- 8103260264 Forwards Amends 34 & 99 to Licenses DPR-71 & DPR-62, respectively, cafety evaluation & notice of issuance & availability IPPDLITO 1 A Operating Reactors Branch 2 81/03/16 2pp 08042.014.
- --Bi0326027B Amends 34 & 55 to Licenses DPR-71 & DPR-62 respectively, incorporating certain TMI-2 lessons Joanned Category A requirements no valve position indication shift technical advisor augmentation & indication indication property of the property o
- ~-8193260289 Safety evaluation supporting Amends 34 & 99 to Licenses DPR-71 & DPR-62.respectively \* Office of Nuclear Reactor Regulation, Director 81/03/16 4pp 08042 034
- --8103260298 Notice of issuance & availability of Amends 34 & 35 to Licentes DPR-71 & DPR-62 respectively IPPOLITO, T A. Operating Reactors Granch 2 81/03/16. 2pp. 08042 038
- B103270095 Surrary of B10304 meeting w/Mark I caners group & QE in Bethesda.MD ro supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MUREG-0661.Silde presentation & list of attendees encl. GRIMES.C I Licenting Branch 3. 01/03/16. 5pp.
- 8103230591 Forwards QA program reflecting organizational changes, including creation of corporate OA dept & const of records storage facility at Brunswick QA program available in Central Files only.

  UNLEY.E.E. Carolina Power & Light Co. 81/03/18 2pp. 07972 184
- 8103260054 Forwards Amend 96 to License DPR-62, safety evaluation & notice of issuance & availability IPPOLITO. A. Operating Reactors Branch 2 81/03/20 2pp 08041,220

- --Bi03260052 Amend 56 to License DPR-62 establishing new vessel level setpoints that are consistent w/installation of common ref level required by I/I Action liten II K 3 27 in NUREG-0737 IPPOLITO.I A Operating Reactors Branch 2 81/03/20. 15pp 08041 200
- --Bi03260066 Safety evaluation supporting Amend 56 to License DPR-62

  \* Dffice of Nuclear Reactor Regulation, Director 81/03/20. 2pp
- --6103260070 Notice of issuance & availability of Amend 56 to License DPR-62 IPPCLITO.T.A. Operating Reactors Branch 2 81/03/20 2pp.
- 8103260098 Notification of 810324 meeting w/util to discuss licensee proposed Ferh Spec changes which allow taking nuclear svc water sys out of svc for maint HANNCN.J II Certaing Reactors Branch 2 81/03/20 2pp 08041 241
- 8103270649 Informs of delay in submittal of application for Toch Spuc amend re stubber surveillance.per NRC 801120 request Delay caused by problems whydraulic shubbers Application currently scheduled for submittal by 810301 UTLEY.E E Carolina Power & Light Co 81/03/20 2pp 08043:006
- 8103270609 Descrites background, scope of revised plans & schedule for completing mods re installation of charcoal adsorber #ys Augmented offgas sys to be operable by 811231. Continued operation will not result in adverse impact on environ. UTLEY.E.E. Carolina Power & Light Co. 81/03/23 6pp. 08043 152
- O Inspection reports, IE Bulletins & correspondence
- 8103180410 Forwards Revision 2 to 90-day response to Suppl 3 of IE Sulletin 79-010. "Environ Qualification of Class IE Equipment " Safety relief valve position indication is only TMI action plan equipment installed at Brunswick.
  FURR.O J. Carolina Power & Light Co. 81/01/30. 2pp. 07944 118.
- ---8103180425 Forwards response to add1 data requests of Bupp1 3 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment 'Util does not plan to test or roplace nonsefety-grade equipment grade equipment EURR, B.J. Cerolina Power & Light Co. 81/01/30 IBpp 07944-120
- B103120775 Forwards IE Insp Repts 50-324/00-41 & 50-325/80-44 on B01/01-23 No nencompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B1/02/05 2pp 07905.310
- --9103120783 IE Insp Ropts 50/324/80-41 & 50-325/80-44 on 801101-25 No noncompliance noted Major areas inspected control room observations, ravisus of plant logs, tours of vital areas & radiation protection.

  OUZTS J.E., SXINVER.P.H. Region 2. Atlanta, Office of the Nuclear Support Branch 81/02/06 opp. 07905.312
- Bi03020186 Forwards IE Circular 81-02, 'Performance of NRC-Licensed Individuals White on Duty." No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/02/09 ip.
- 8103090286 Forwards Paragraph 4. inedvertently omitted from details of IE Insp Repts 30-324/80-37 & 50-325/80-42 LEWIS.R.C. Region 2: Atlanta. Reactor Operations Nuclear Support Branch Bi/02/11 ip 07646-351
- --Bi03390297 Paragraph 4.inadvertently omitted from details of IE Insp Repts 50-324/80-39 & 50-325/80-42 • Region 2, Atlanta, Office of the Director. Bi/02/11. ip.
- B103040174 Forwards IE Info Notice 81-03, "Checklist for Licenses Making Notifications of Significant Events In Accordance W/10Er800, 72, " No written response required. D'REILLY, J.P. Region 2, Atlanta, Diffice of the Director. 81/02/12. 1p 07813-013
- 8103100739 Forwards Suppl 9 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/02/17. 1p. 07866-325.
- 8103060240 Responds to IE Bulletin 81-01, "Surveillance of Machanical Snubbers "No mechanical snubbers in use at facility. FURR.B J. Carolina Power & Light Co. 81/02/18 1p 07839-308.

- 8103090413 Att receipt of IE Insp Repts 50-402/81-01.30-401/81-01. 50-402/81-3; & 50-403/81-01 on 810105-09 Na proprieter, info HOMER P.W. Carolina Power & Light Co. 81/02/18 19 07849 180
- --8103090422 Forwards IE Insp Repts 50-261/81-01.50-324/81-01. 52-325/81-01.50-400/81-01.50-401/81-01.50-402/81-01 & 50-403/81-01 on 810105-09 No noncompliance noted KURPHY, C. E. Region 2. Atlanta Reactor Construction & Engineering Support Branch 81/02/09 290 07849 IB1
- --8103090430 IE Insp Repts 50-261/81-01.50-324/81-01.50-325/81-01.
  30-400/81-01.50-401/81-01.50-402/81-01 t 50-403/81-01 on
  810106-09 No nancempliance noted flagor areas inspected closeout of previously identified enforcement matters
  8ROHNLEE.V. Region 2. Atlanta. Office of the Director CONLOW.TE Region 2. Atlanta. Reactor Construction & Engineering Europeot Branch 81/32/09 6pp 07849 183
- B103240076 Submits summary & schedule for followp response to infractions of NRC requirements, per IE Bulletins 79-02.07 & 16 Generic analysis has been completed showing that typical branch connections contain acceptable stresses DIETZ.C.R. Carolina Power & Light Co. 81/02/25 63p 07989. R93
- 8103160708 Forwards 18 Info Notice 81-04. "Cracking in Hain Steam Lines." No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. B1/02/27 tp. 07914-083
- 8103110592 Forwards "Component Insp Program & Hydrostatic Test Program" & "Pump & Valve Test Program" UTLEY, E. Carolina Power & Light Co. 81/03/02 2pp. 07869-205
- --8103110395 "Component Insp Program & Hydrostatic Test Program '
  Carolina Power & Light Co 81/03/02 78pp 07869 207
- 8)03|60659 Forwards IE Circular 8)-03. "Inoperable Seismic Monitoring Instrumentation." No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/02
- B103170062 Forwards 1E Circular 81-03, "Inoperable Seismic Monitoring Instrumentation". No response required 0'REILLY-J.P. Region 2, Atlanta, Office of the Director 81/03/02 1p. 07939.185
- B103170083 Forwards revised IE Bulletin Si-Oi, "Surveillance of Mechanical Snubbers," w/corrected Pages 5 & 6 Change in identification of facilisties w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/04.

  1p. 07933 285
- B103120815 Forwards request for add1 info re 800130 submittal of revised inservice inst program for tiping & welds Response required within 50 days following receipt of itr. [PP00.ITD.T A Operating Resectors Branch 2 81/03/05 3pp 07905-017
- B103200301 Forwards IE Info Notice 81-06. "Failure of ITE Nodel K-600 Circuit Breaker." No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/03/11. jp. 07969:034
- 8103190871 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades" No response required. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 81/03/13 1p. 07965-282
- B103310904 Responds to 1E Bulletin B0-25. "Operating Problems W/Target Rock Safety Relief Valves at SWRs." During valve assembly, at Hyle Labicheths will be made to ensure that solenoid actuators are free of Loc-Tite pior to operation. FURR.B. J. Carolina Power & Light Co. 81/03/20 2pp. 08098:150
- R. Periodic operating reports & related correspondence
- 8103030177 Forwards, "Semiannual Environ & Effluent Rept.Jul-Dec 1980." DIETZ.C.R. Carolina Power & Light Co 81/02/25. ip.
- --8103050191 "Semiannual Environ & Effluent Rept. Jul-Dec 1980."
   Carolina Power & Light Co. 81/01/23. 12500.
- 8103230286 Forwards "Annual Operating Rept for 1980." DIETLC.R Carolina Power & Light Co. 81/02/26. 1p. 07992-083

BiO3100605 Forwards amends to "Semiannual Environ & Effluent Release Rept," Jan-June 1979 re description of max theoretical results of potential auriliary boiler releases subsequent to BO0222 release & inclusion of stabilisation pand discharges DIETZ.CR Carolina Pauer & Light Co. B1/03/03 2pp.

Carolina Power & Light Co 81/02/26 80pp 07992 084

- --B103100612 Amends to "Sectionnual Environ & Efficient Rolease Rept." Jan-June 1979 • Carolina Power & Light Co 81/03/03 24pp
- 8103190506 Monthly operating repts for Feb 1981 WILLIS-E Carolina Power & Light Co 81/03/11 20pp.

- B103190502 Forwards monthly operating repts for Feb 1981 DIETE.C R Carolina Power & Light Co 81/03/II 1p
- S Reportable occurrences. LERs & related correspondence
- 5103050523 Forwards LER 81-C01/03L-0 DIETZ, C.R. Carolina Power & Light Co. 81/02/27 ip. 07828-302
- --Bi03050536 LER Bi-001/03L-O on Bi0129, during surveillance testing. HPCI sys initiation reactor level switch actuated at simulated level above Tech Spec. Caused by components slipping due to loose set screws on actuator pointers PABIVA.M J Carolina Power & Light Co Bi/02/27. 2pp 07828.303
- B103110579 Forwards LER 81-025/017-0 DIETZ, C.R. Carolina Power & Light Co. 81/03/03. Lp 07897 094
- --8103110686 LER 81-025/01T-0 on B10223, per IE Bulletin 79-07 analysis.
  10 pipe supports on control rod driveline vent line piping
  found susceptible to failure in seismic event. Caused by
  as-built condition Beens & plates added to supports
  PASTYAN J Carolina Power & Light Co B1/03/03 2pp
  07887-095
- 810310040B PNO-11-81-020 on 819304, furing surveillance functional testing of accessible hydraulic anubers, failure rate of 20% occurred Functional testing of 107 snubbers revealed 20 which failed to meet criteria ULIAM, C., KELLOOO, P. J. Region 2. Atlanta, Office of the Director 81/03/05 1p 07867-243
- B103160762 Forwards LER 81-015/03L-0 DIETZ.C R Carolina Power & Light Co B1/03/05 ip 07914 150
- --Bi03160765 LER Bj-015/03L-0 on Bi0207, law level switch 2-B21-LIB-NO3ID-3 actuated at -49.6 inches simulated reactor level Caused by switch rubbing on instrument magnet preventing accurate indication & switch actuation PABTVA-M.J. Carolina Power & Light Co. Bj/03/05 2pp. 07914-151
- 8103130510 RO 2-81-41 on 810306 while performing function test of accessible snubbers featlure rate of approx 20% identified. Cause not stated investigation continues. DIETZ-C R Carolina Power & Light Co. 81/03/06. Ip. 07908.291.
- B103160771 Forwards LER B1-017/03L-0. DIETZ-C R Carolina Power & Light Co. B1/03/09. ip. 07921 333.
- --8103160774 LER 81-017/03L-0: on 810207, operator noticed that reactor level instrument 821-LIS-N0170 pegged high & on 810212, noticed H017D (netrument reading higher than other level instruments. Caused by low level in instrument ref leg POULK, R H Caroline Power & Light Co. 81/03/09 2pp 07921 334.
- 8103180635 Forwards LER 81-018/03L-0, DIETZ-C R. Caroline Power & Light Co. 81/03/09, ip. 07947-318
- --8103180643 LER 81-018/03L-0: on 810210, primary containment atmospheric monitor hydrogen analyser, 2-CAC-AT-1283-1, model 7C, showed varying indications. Cause unknown. Indication was found steady upon investigation. PASIVA: M.J. Carolina Power & Light Co. 81/03/09. 2pp 07947-319.
- 8103170263 PNS-II-81-003 on 810312, telephone bomb threat was received Search of Unit 2 produced negative results. Area declared clear TILLMAN.A., MCGUIRE, D.R. Region 2, Atlanta, Office of the Director 81/03/13. 1p. 07939:214

- 9103230689 Parwards LER DL 017703L-0 DIFTE ON CALUITHA Power & Light Co. 01703716 1.0 0.792.1.398
- --BIOR230705 IER BI NIVOR G on BIO214 RBB whatdook conding supply inboard isolation valve. Fill-COV, sould not upon from RTQD Caused by burned valve rights which the Motor andel BMD3. rewound & reinstalled PASIVA II J. Cornilina Power & Light Co. fil/On/la Con 37773 399
- 8103240467 Corwards LER DI 0277030 O DIFTE C R Carolina Power & Light Co History ip 07903 060
- --8109240472 LER B1 077768 O on B10225 for Ing normal startup reactor coolant conductivity from greater than 2 mobazem2 Caused by breakfour of argentes to reactor vessel originating in breakious or alganics in reactor vissel originating condensate storage tank page to English Pager & Light Co. 41703717 07903 361
- 0100270666 Forwards LER UL OCGZOUL -0 DICTZ-C R Cavelina Proof & Light to 01703720 In 00043 270
- --8100270674 TER DI 6267030 O on BIOSSE primary containment atmospheric containment atmospheric containment are sugger analyses of CAL-AIH 1757 C Falsely indicated monitor stygen analytes a contraction canned by defective photohetic gauge Cange regions?
  PASTVA.M.J. Carelina Power & Light Co. HIVOJEO Spp. 00043-271
- 3103300326 Fercards LER DI 000ZUOL 0 DIETZ.C R. Carolina Power & Fight to | 01703720 in | 00047 in
- achieved when rad 26 17 was fully withdraum during normal operation Cause not determined Operational where of rud with pagiva. a J carolina Power & light Co 11170 1727 To 00047 175
- 0100310044 Enrogras LER 01 (@3200C-0) DICTAIC R. Carulina Posser & Light Co. ULZONAN 200 00001 217
- --- 0103310360 IER 01 0237638 O no 010224-prinary containment atmospheric TO SHOULD BE THE TO SHOULD BE TO THE SERVE THE CONTROL OF THE SERVE THE SERV 000001 219
- 0103310673 Forwards LER 04 00270 % 0 0 01203726 1p 00062 167
- -- 9103310703 ffR Bl-04270 4 0 an 810.24 unit 2 torus avyen concentration termination of the state of the 00062 160
- 8103310682 Forwards (ER B) 07470 H 0 DIETEC R Carolina Power & Light Co 401/0.1/27 ip 00021 074
- -- 0100010868 LER By 03470.0 O on 010025 discovered reactor core isolation cooling mys computent test had not been performed as required Caused by failure of uperating instructions to provide for rescheduling tests and perference on due data PASTMAN J. Carolina Fourt & Light to BIASMAN App 00061 075

# V Operator Caminations

- RIGGOPO929 Clarifies commitments made in util HO1215 ltr re-NUREO-0737. "Clarification of TMI Action Plan Requirements" Lists responses to issues raised by NRC is shift mainting operating activities & energonicy preparedness. UTLEY. E.E. Garolina Power & Light Co. #11/03/03 2pp. 07H4B 15H
- 8103240491 Confirms commitment that all licensed operators within operations unit will receive formal training in reactor vessel ref level changes prior to completion of mod UTLEY/E E Carolina Power & Light Co 81/03/18 ip 07/86 145

- DOCKET 50-005 BRUNDOLOK 93EAM LLECTRIC PLANT, UNIT 1
- a discurity, medical, emergency & fire protection plans
  - HIGHINGER Its to all power reactor licensus explaints licensus to 79300 forwards MEC position to request for additions as safe shutdown capability for compliance w/HO1119 firm orntection into FIGURE OF DIVISION OF LICENSING OF CONTROL CON
- minimized the to all licensees of operating plants & holders : Purwarding thilly 0698. Functional Criteria for Impropercy Response Facilities " Criteria describe acceptable method Response Facilities "Citoria describe Acceptable nu for meeting this reguliements live encl [15] [Fill], D. G. Division of Litensing U1/0.4/05 App
- Fig. 120667 Requests prooption from curtain sequirements of 1001  $1000\,R99.\,\mathrm{App}\,R$  to fire protection Correct fire protection measures suffice to protect public health 4 safety bupper ting then uncl Carnina Power & Light Co - 01/00/05 unce del 1 36.00 075
- UIO 1190163 Reteases public version of electronic procedures

  Fill DBC J N Division of Roles and Records UI/03/13 0.0006 001
- \$100190169 Forwards public version of uperating manual Vol 1. emergency procedures
  Only, the Carolina Power & Light Co. 01/02/25 tp. 076
- HICHPOIST Public version of operating manual Vol 1.1. Hook 2. a procedures includes everyone, classifications & control emergency action procedures emergency facilities & equipment A training process & drills # Carolina Power & Light Co | 01/02/23 | 3/3pp | 0/005 001
- miorpanias informs that exemption request was filed missil seed artenation mutil Big911 for providing plans & schedules for compliance office protection eafe emition capability the Compgency Lighting w/O b capability will be installed IMLEY.E. Caralina Proof & Light Co., 1070.0719, App. 03 0296
- BIGGEOGRAPH Requests that our personal planning info be placed rene ave arealisates Division of Roles and Records - 01/03/24 LOOPER, J. C. 00040 243
- is Adjudiratory correspondence
- nto REDUNE For wards 010227 petition for bearing to order for li mad & grant of eramytion extension per ISEC BIOLDI miders. 67791 IL MIN. D. F. Carolina Power & Light Co. Bishards ip
  - HIDDONOSAL Petation for hearing to BIO113 order for license of ne premptine extension Request directed to order establishing completion dates of NACONE 6 HISTO Centificat of filing erel Sputtbar L. Flynd D. Carolina Power & Light Co. 8170272 07795 209
- J. Insurance & Indomnity information
- HIGHOORS Forwards Indoesement 9 to HAFLU Hinders XD-54 & XD-5 BARHAS. C.D. Carolina Power & Light Co. 01/07/05 See 070
- 8103236645 Forwards Endorsement 5 to MALLU Binders X8-54 & XII-1 Informs of error to RIG109 transmittal lite which referred to MrIA Binders EU-94 & FU-99 as XB-94 & 48-59 TARRAMED D. Carolina Power & Light Co. BF709717 Spp. 074
- () Advisory Committee on Reactor Refeguerie reports & correspon
- DI03270095 (Hummary of HI0304 meeting w/Mark I owners group & 08 Hethesde.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MAREO 0661 Blide presentation & list of attendees enti-CRIMEG.C I Licensing Branch J HI/03/16 Spp.
- P. Operating license stage documents & correspondence
- H103190732 Ltrs to all licensees of operating plants applicants (K.s. & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position reinterin actions t request for addl info EIBENHUT.D.O. Division of Licensing 80/12/22 30pp 079

- Old3(90307 Ltr to all licenses of operating plants & applicants for Ols & holders of CPs re program for environ qualification of safety-related electrical equipment ltems addressed involve cold shutdown replacement parts & NAGEO-0737 EISEM-NUT.D O Division of Licensing 81/01/19 App
- 8103240290 Ltr to all BHR licensess forwarding Suppl I to generic safety evaluation on BHR scran discharge sys Summarizes re-evaluation of interam measures recommended per 831201 safety evaluation [EISENHUT.D 9 Division of Licensing 81/01/23 2pp 07986-312
- B103120014 Ltr to all licensees of operating plants.CP holders & O\_applicants.ercept Indian Point 2 & 3.2ion 1 & 2 & IMI-1, forwarding inadvertently onitted pages from MPC 001222 request for addlinfore control of neav, loads EIEENHUT.D 9 Division of Licensing B1/02/03 dpp
- BiO316069 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation dates will be net EISENHUT. D G Division of Licensin; 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re NARC-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISE/HVI.D 0 Physion of Licensiang 81/02/20 Epp
- B103030897 RD on B10223 analysis indicated that ten supports on control rod driveline vent line could fail in ex-oull condition during designed seismic event Cn B10220 RCIC tripped u/o receiving permission

  DEFT.C. C. Caroline Power & Light So. B1/02/24 ip 07795 159
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for OLs lescept St Lucie. Units ( & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENPUT.D 2 Division of Licensing 81/02/25 Spp.
- B103030752 Clarifies util B01215 position re NU9E9-0737 Item I A 1 3 re limitations on overtime required of licensed operators Util maintains that normal facility manning policies meet NRC guidence AddI limits will create administrative burden UTLEY.E E. Carolina Power & Light Co. B1/02/26 Spp. 07796-079
- 8103110061 Surnary of B10219 meeting w/util in Bethesda.MD to discuss App R procedural & technical questions Util plans to file exemption requests for relief from 10frR90 48 & from certain mod requirements Agenda & list of attendess encl HANNON.J.N Operating Reactors Branch 2 81/02/26 4pp 07884-359
- 8103170225 Ltr to all BHR licensess (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class i & 2 pressure boundary piping, safe ends & fitting mail per guidelines of encl Revision 1 to MUREQ-0313 Model Tech Specs only encl EISENHUT.D 0 Division of Licensing 81/02/26 3pp. 07934 315
- --Bi03170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 resurveillance requirements for ABME Code Class 1,2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements # General Electric Co. B1/02/26 4pp 07934,318.
- 8103230813 Generic Ltr Bi=06 to all CP holders & DL applicants re IGCFR50 71(e), "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content enci EISENNUT.D. G Division of Licensing. B1/02/26.
- 8803110592 Forwards "Corponent Insp Program & Hydrostatic Test Program" & "Pump & Valve Test Program" UTLEY, E. Carolina Power & Light Co. 81/03/02 2pp. 07869 205.
- --8103110595 "Component Insp Program & Hydrostatic Test Program "
   Caroline Power & Light Co 81/03/02 78pp 07869 207
- --B103110597 "Pump & Valve Test Program " Twenty-four oversize drawlings enci Aperture cards are available in PDR Carolina Pour & Light Co. B1/03/02. 63pp. 07869-285
- 8103090529 Clarifies commitments made in util 801215 itr re NUREG-0737. "Clarification of IMI Action Plan Requirements " Lists responses to issues raised by NRC re-shift manning, operating activities 5 emergency preparedness UTLEY.E.E. Carolina Power & Light Co. 81/03/03 2pp. 07848 158

- 8103090633 Submits list of deviations from NRC requirements for NURECO-0737 Item II f 1. Add Accident Monitoring Instrumentation 'No plans to sample reactor bidg vents since vents are isolated in any high radiation situation UTIEY.E E Carolina Power & Light Co. 81/03/03. 2pp. 07844-292
- BiO3i10687 Application for about to License DPR-71 revising Tech Specs to allow operation up to 50% of rated thermal power w/one recirculation loop out of svc until 810315 UTLEY.E E. Carolina Power & Light Co. 81/03/05 ip
- --BIO3|1069| Tech Spec 3/4 2 for power distribution limits • Carolina Power & Light Co B1/03/05 4pp
- 8103230158 Confirms 810305 telcon authoritating OL amend & Tech Specs change MOVAR.T H Assistant Director for Operating Reactors 81/03/06
- --8103250161 Revise: Tech Specs 3/4 2 re power distribution limits
  Handwritten draft safety evaluation encl
   Assistant Director for Operating Reactors 81/03/06 App
- 8103110424 Forwards suppl to 803916 request for revisions to Tech Space rappost-accident monitoring instrumentation & administrative controls per Category A Lessons Learned requirements Info provides add) clarifications u/o changing technical content UTLETEE Carolina Power & Light Co 81/03/09 App 07873 348
- B1031303B4 Requests that NRC issue mods to B10113 orders re compliance w/kUREG-0661 criteria for Mark 1 containment program Major safety mods on Unit 1 requested during refuelling outage, w/minor mods during subsequent refuelling outages UTLEY.E E Carolina Power & Light Co B1/03/07 5pp 0790B 194
- Bio3310804 Ltr to all licensees of operating plants applicants for OLs 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISECHUT. D Q Division of Licensing 81/03/10 App
- BIO3190145 Notification of BIO315 meeting w/near-term OL applicants in Bethesda. MD re info required to be submitted on shviron qualification of electrical equipment prior to site visit & NRC review
  BURNELLS Licensing Branch 2 81/03/12 15pp 07965 004
- 8103160459 Application for arend to Licenses DPR-71 & DPR-72 revising Tech Spec 3 7 1 2 re svc water operability requirements Approval by 810403 requested UTLEY, E.E. Carclina Power & Light Co. 81/03/13 3pp. 07917 350
- --B103160464 Tech Bpec 3 7 1 2 for svc water sys. \* Carolina Power & Light Co 81/03/13 6pp. 07917 393
- 8103180846 Application for amend to License DPR-71 revising Tech Specs to allow operation up to 30% rated thermal power w/one recirculation loop out of sec until 810315 UTLEV.E.E. Carolina Power & Light Co. 81/03/13. 2pp. 07954 058
- --8103160892 Revised Tech Specs 3/4 2 re power distribution limits Util justification encl. 4 Carolina Power & Light Co. 81/03/13. 26pp. 07994-061
- 8103269264 Forwards Amends 34 & 55 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability IPPOLITO. A Operating Reactors Granch 2 81/03/16 2pp 08042:014
- --8103260278 Amends 34 & 99 to Licenses DPR-71 & DPR-62, respectively, incorporating certain TMI-2 lessons learned Category A requirements re valve position indication, shift technical advisor augmentation & lodine monitoring IPPOLITO. TA Uperating Reactors Branch 2 81/03/16 18pp 08042-014
- --BI03260289 Gafety evaluation supporting Amends 34 & 55 to Licenses CPR-71 & DPR-62, respectively • Office of Nuclear Reactor Regulation, Director 81/03/16 499 08042 034
- --B103260298 Notice of issuance & availability of Amends 34 & 55 to Licenses DPR-71 & DPR-62 respectively IPPDLITO.T.A. Operating Reactors Branch 2. B1/03/16. 2pp. 08042 038

- B103230591 Forwards GA program reflecting organizational changes, including creation of corporate GA dept & const of records storage facility at Brunswick GA program available in Central Files only UTLEF,E E Carolina Power & Light Co 81/03/18 2pp 07972 184
- B:0326005B Notification of B10324 meeting w/util to discuss licensee proposed Tech Spec changes which allow taking nuclear syclater sys out of syc for maint HATHOW JN Operating Reactors Branch 2 B1/03/20 3pp month 241
- B103270649 Informs of delay in submittal of application for Tech Spec amend to shubber surveillance.per INIC B01120 request Delay caused by problems w/hydraulic shubbers Application currently scheduled for submittal by B10501 UTLEY.E.E. Carolina Power & Light Co. B1/03/20 2pp. 08043 006
- B103270609 Describes background scope of revised plans & schedule for completing mods re installation of charcoal adsorber sys Augmented uffges sys to be operable by B11231 Continued operation will not result in adverse impact on environ UTLEY.E E Carolina Power & Light Co 81/03/23 6pp 08043 152
- Q Inspection reports. IE Bulletins & correspondence
- B)03180410 Forwards Revision 2 to 90-day response to Suppl 3 of IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" Safety relief velve position indication is only TMI action plan equipment installed at Brunswick FURR.B J. Carolina Power & Light Co. 81/01/30 Zpp. 07944 118
- 8103120775 Forwards IE Insp Repts 50-324/80-41 & 50-325/80-44 on 801101-25 No noncompliance noted LEMIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/05 2pp 07905 310
- --Bi03120783 IE insp Repts 50/324/80-41 & 50-325/80-44 on 801101-25 No nancompliance noted Major areas inspected control foom observations, review of plant logs, tours of vital areas & radiation protection
  CVZTS. J E , BKINKER.P M Region 2, Atlanta, Diffice of the Director KELLUGO.P J Pegion 2, Atlanta, Reactor Operations Nuclear Support Branch B1/02/06 6pp 07905 312
- 8103020185 Forwards 1F Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty "No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 81/02/09 to 07705 294
- 8103090286 Foruards Paragraph 4. Inadvertently omitted from details of IE Insp Repts 50-324/80-39 & 50-325/80-42 LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 81/02/11 ip 07846 351
- --8103090297 Paragraph 4. inadvortently omitted from details of IE Insp. Repts 59-324/80-39 & 90-325/80-42 \* Region 2. Atlanta. Office of the Director 81/02/11 ip 07846 352
- 8103040174 Forwards IE Info Notice 81-03. "Checklist for Licensess Making Notifications of Righlficant Events In Accordance W/10CFR90 72" No written response required G'REILLY. J.P. Region 2. Atlanta. Office of the Director 81/02/12 ip. 97813 913
- 9103100735 Forwards Suppl 5 to 1E Builetin 80-17, "failure of Control Rods to Insert During Scram at BWR." No written response required D'REILLY. J P Region 2. Atlanta. Office of the Director 81/02/17 ip 07846 329
- 8103069240 Responds to IE fluitetin 81-01. "Surveillance of Mechanical Snubbers" No mechanical snubbers in use at facility FURR.8 J Carolina Power & Light Co. 81/02/18 1p. 07839.308.
- 8103090413 Ack receipt of IE Insp Repts 50-400/81-01.90-401/81-01. 50-402/81-01 & 50-403/81-01 on 810195-09 No proprietary info. MOMS.P W Carolina Power & Light Co 81/02/18 ip 07849.180
- --9103090422 Forwards IE Insp Repts 50-261/81-01.50-324/81-01. 50-325/81-01.50-400/81-01.50-401/81-01.50-402/81-01 & 50-403/91-01 on B10106-09 No moncompliance noted MURPHY. C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branck 81/02/09. 2pp 07849 181.

- --BIOJC90430 [E Insp Repts 50-261/BI-01.50-324/BI-01.50-325/BI-01.50-400/BI-01.50-400/BI-01.50-402/BI-01 on BIO106-09 No noncompliance noted Major areas inspected. closeout of previously identified enforcement matters BROWNLEE.V.L. Region 2. Atlanta. Office of the Director. CONLOV.T.E. Region 2. Atlanta. Reactor Construction & Engineerin Support.Branch BI/02/09 opp. 07849 183
- B103240776 Suprits surrery % schedule for followup response to infractions of ARC requirements.per IE Bulletins 79-02-07 & 16 Generic analysis has been campleted showing that typical branch connections contain acceptable stresses.

  DEFIC.C R. Carolina Power & Linkt Co. B1/02/25 dog. 07989 293
- B103160708 Forwards (E. Info Notice 81-04, "Cracking in Main Steam Lines" No response required O-REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/27 Ip 07914 083
- B103110592 Forwards 'Component Insp Program & Hydrostatic Test Progra & Pump & Valve Test Program ' UTLEY E Carolina Pour & Light Co 61/03/02 2pp
- --8103110595 "Component Insp Program & Hydrostatic Test Program "
   Carolina Power & Light Co 81/03/02 78pp
- BiO3160659 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation" No response required D'REILLY.J P Region 2. Atlanta. Office of the Director 81/03/02 19
- B103170062 Forwards IE Circular B1-03. "Inoperable Balanic Monitoring Instrumentation " No response required O'REILLLY JP Region 2. Atlanta. Office of the Director B1/03/02 1p 07939 183
- 8103170083 Forwards revised IE Bulletin B1-01. "Burveillance of Mackanical Bnubbors." w/correctod Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. OTREILLY.J P. Region 2. Atlanta. Office of the Director B1/03/04 ip 07933 236
- 8103120Bin Forwards request for addl info re 800130 submittal of revised inservice inep program for piping & welds Response required within 40 days following receipt of itr IPPOLITO.T A Operating Reactors Branch 2 81/03/03. 3pp 07905-017
- B103200301 Forwards IE Info Notice B1-06. "Feilure of ITE Model K-600 Circuit Breater" No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director. B1/03/11 1p 07969-034
- B103170871 Furuards IE Info Notice 81-05, "Degraded DC Sys at Palisades" No response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 81/03/13 1p 07965-282
- 8100310904 Responds to 1E Bulletin 80-25. "Operating Problems W/Tange Rock Safety Rollef Valves at SWRs." During valve assembly, at Myle Lab. checks will be need to ensure that solenoid actuators are free of Loc-Tite pior to operation.
  FURR. B. J. Carolina Power & Light Co. 81/03/20. 2pp. 08058-150
- R Periodic operating reports & related correspondence
- 8103050177 Forwards. "Semiannual Environ & Effluent Rept. Jul-Dec 1980 DIETZ. C.R. Carplina Power & Light Co. 81702/24 1p.
- --8103030191 'Semiannual Environ & Effluent Rept. Jul-Dec 1980."
  4 Carolina Pouer & Light Co 81/01/23 125pp
- B103250286 Forwards "Annual Operating Rept for 1980" DIETZ, C. R. Carolina Power & Light Co. 81/02/26. Ip. 07992:083.
- --8103250289 "Annual Operating Rept for 1980 "
   Carolina Power & Light Co 81/02/26 80pp. 07992:084.
- 8103100605 Forwards amends to 'Semiannual Environ's Effluent Release Rept." Jan-June 1979 re description of max theoretical results of potential auxiliary boiler releases subsequent to 800222 release & inclusion of stabilization pond discharges. DIETZ.C R Carolina Power & Light Co 81/03/03 2pp.
- --BIO3100512 Amends to "Semiannual Environ & Effluent Release Rept," Jan-June 1979.
  - \* Carolina Power & Light Co 81/03/03 24pp

```
B103190506 Monthly operating rapts for Fet 1981
WILLIB.E Carolina Power & Light Ca 81/09/11 20pp
```

B103190502 Forwards monthly operating roots for Feb. 1781 DIETZ, C.R. Carolina Puber & Light Co. 81/03/11 lp

9 Reportable accurrences, LERs & related correspondence

--0103100620 LER 81-023/DJL-0 on U10128 control tod eciam accomulators 46-19 & 30-07 found inoporable due to inoperable internal teatoge detectors Caused by sticking lovel switch floats Buitches replaced & letectors chocked PASTVA.N J. Carolina Power & Light Co. B1/02/19 ip 07862 341

8103030743 Forwards LER 81-015/03L-0 BIETZ, C.R. Carotina Power & Light Co. 81/02/24 ip. 07771 300

--Br0303074B LER 81-019/03L-() on 810127, red older minitor B failed to initiate RTOB downscale alarm 5 rod out block at downscale alarm setpoint Caused by mechanically stock contacts in control relay K-2 in cabinet circuitry 801a; replaced PABTVA.M J. Carolina Power & Light Co. 81/02/24 12 07/91 JG9

G103040687 Forwards LERs 81-021/03...0 & B1-023/03...0 LER B1-021/07L-0 was incorrectly identified as LER B1-023/03...0 in B10219 cover for LER B1-023/03L-0 stands correct as proviously submitted Encis are correct copies for both LERs D1E72.C R Carolina Power & Light Co. B1/02/24 Ip 07ili1 143

--B103040693 LER B1-021/03L-0 on B10126 control rad scrac accumulators
46-15 t 30-07 Jetermined inoperable due to imperable
internal leakage detectors Caused by Sticking level suitch
floats in detectors Roth Level suitches implaced
PASTVA-M J. Carolina Power & Light Cn B1/02/19 by 07011 344

--8103090009 LER BI-020/03L-O on Bi0205 reacter pressure indicator, 1-032-PI-3332, input signal span found out of spec Caused by shifted diaghragm in indicator transmitter. Model 11920996227028098 Transmitter replaced PASIVA. N. J. Carolina Power & Light Co. 81/02/26 ip 07848 149

8103040644 Forwards LER 81-026/04T-0 DIFTZ.C.R. Caralina Power & Light Co. 01/02/27 1p. 07811 334

--BIO3040647 LER BI-026/04T-O on BIO214.liquid offluent discharge high range indicator/recorder indicated flow rate less than actual.Caused by mechanical linkage between flow paddle & transmitter becoming loose causing felse flow indication PASTVA.M J Carolina Power & Light Co. BI/02/24 2pp 07811 335

--G103090994 LER 81-017/03L-O on B10130 reactor core isolation cooling turbine tripped due to high steam eshaust pressure upon auto-initiation signal Pollowing reactor scram Caused by fine debris blockage in drain put steam trap
PASTVA.M J. Carolina Power & Light Co. 81/02/27 1p. 07829 080

--Bi03110592 LER Bi-019703L-O on Bi0204 isolation valves to primary containment post-accident radiation monitor. I-CAC-AI-1262. found open w/conitor photohelic unit removed Caused by Inadequate raint procedures Bupplemental rept to be issued. PASTVA.H J Carolina Power & Light Co 81703/06 ip 07887 098

Bio3130510 RD 2-Bi-41 on Bio304, while performing function test of accessible shubbers. Failure rate of approx 20% identified Cause not stated investigation continues DIETZ C R Carolina Power & Light Co 01/03/06 ip 07908 291

B1D3160683 Forwards LCR 81-024/03L-0
D1ET2.C.R. Carolina Power & Light Co 81/03/06 1p 07914 331

HIGH ZOARS Lection for the Officer of College College

- OMO ALPHASE (FO DE DEALTH) to the ULDATE Sorth a country instrucental two latters walves from Legal to got long Coat P1 2 2 La 4 H salve KADC would not upon tanged by defective certical extent automobility and land to the latter built and the replace to walve tracted proportion of the country layers. The Latter 2 to CANADA CONTRACT CANADA PC. CONTRACT LAYERS (1994) 10 2 CONTRACT CONTRA

#HO.H.70446 Focuse do 11月 HL の25.0円 0 - BIETZ.C R - Corolina Power ち Fight co - ロジロコロト コテー のフォト・25

BIGHT/0447 IER DI 0.970 s. G on 040.41 desting normal operation in interdisting particle tight association received indicating IPCL to blue steam intal death part steam intal 124 Decimals to the received indicating on the total control of the received indicated by Hypass calculations and the PAGIVA II J. Cacalina Process College Co. (1920-14) Free 1979-99 205

BIOSEZ/OARE LANGERON CONTRACTOR OF CARACTER C

HIBBITORAL PARTIE OF Our on HIGHER totageness have the soft and reserved beauth of Unit 2 gradued inspitive results Area doctored clear

CIBER THEIMAGA , PERMINCO R. Region 2, Atlanta Office of the line MEXOSKE - Ip. 07/17 244

#103230720 Entraids updated LEG OF OFFICE | Land the Power & Light Co. | HEROEXEL | Ip | 07974-1.

-BIODEROAD Optated the state of the property of selections by a red blocks were received obvious asymmetric control to pattern observed facing by reddensate procedure Procedure overselve verify all rods PASIVALE A Carolina Procedure to 10100014 to 10 1027

--B103240465 tFR ht (inbrus to in though dissel generator of start pressure has alark annough to distinct of parel Career to 400 volt breakers for both an compressors for generator in off position breakers placed to no position of the providence of the carefront breakers to the position.

9103240579 Forwards [18 II] 6277078 O DIETZ-C R. Carolina Power & Eight Co. Divolvio. ip. 67907 4

--BIO3240204 tER BI 077/0.0 O on BIO21/.dissel generator limbout on dissel generator to bile clustic duri to PI respect test on 4160-volt sufficepair for energying too F I laughed by door hitting seal hard-causing lock-out relay to pirt on POULK-R M. Carulina Power & Light Co. 011/01/2011 bp. 07/0.5

- 8103270762 Forwards tEH 81-031/011-0 pleT2.C R Carolina Power 5 Light Co 81/03/18 :p 08043 292
- --8:03279767 LER 8:-031/017-0 on 8:0220.control room received ennunciator that reactor core isolation cooling sys turbine tripped Cause: ty operator tripping turbine who consent while making description furbine reset & personnel counseled PASTVA.M. U. Carolina Power & Light Cu. H1/03/18. 2pp. 08343-293
- 8103270749 Forwards LER 81-030/03L-0 DIETZ. C. R. Carolina Power & Light Co. 81/03/20 tp. 08043 289
- --8103270757 LER 81-030/02-0 on 810219 £ 0317. switch 1 of reactor pressure switch 1-B21-P5-NN21D model 288 would not actuate Causer by switch actuation screw out of adjustment Screw adjusted after first event Linkage adjusted after second PASTVA.M J. Carolina Power & Light Co. 81/03/20 2pp 6803-270

## v Operator Examinations

- 8103090527 Clarifies commitments made in util 801219 ltr re NUREC-0737, "Clarification of THI Action Plan Requirements" Lists responses to issues raised by NRC re shift manning, operating activities & emergency preparedness utilfy E Cerolina Power & Light Co. 81/03/03 2no
- O Inspection reports. IE Bulletins & correspondence
- 8103030449 Ack receipt of 801224 ltr informing NRC of stops taken to correct violations noted in IE insp Rept 50-326/80-02 BCDK.H E Region 5. San Francisco. Evel Facility & Materials Safety Granch 01/01/14 ip 0/779 267
- --8103030480 Responds to NRC B01208 lit ro violations noted in IE Insp. Rept 30~326/80-02 Corrective actions escurt provided to any person required to perform work in facility which is not directly associated with radiation producing device.

  MC0AVOH. J. L. California. Univ. of. Irvins. B0/12/24 Spp. 07709-2AR
- --Bi03030488 Forwards IE Insp Nept 59-326/80-02 on B01027-30 & notice of violation BOSK N E. Region 9. San Francisco. Fuel Facility & Materials Safety Branch B0/12/10 2pp 07795 276
- --8103030495 Notice of violation from insp on B01029-30 BOCK-H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch B0/12/08 ip 07795 278
- 8103020011 Forwards [E Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. ENGELKEN R H Region 5. San Francisco, Office of the Director 81/02/09 ip 07787:179.
- B103230053 Forwards IE Insp Rept 50-326/B1-02 on B10226 No noncompliance noted Rept withheld (ref 10CFR2 790) NGRDERHAUJ, L. R. Region 5. San Francisco, Safeguards Branch B1/03/II 2pp 07978 095
- 8103230060 Forwards IE Physical Security Insp Rept 50-326/81-01 on 810286-27. No noncompliance noted Rept withheld (ref 1005R2 790) NURDERHAUG.L.R. Region 5. San Francisco: Safaguards Branch. 81/03/13. 1p. 07978:243.
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT I
- A Application/construction stage documents & correspondence
- Bi0323005B Forwards 810210 memo w/rough draft. "Analysis of Hydrogen Mitigation for Degraded Core Accident in Bequoyah Nuclear Power Plant" & B10122 memo w/rept entitled "Evaluation of Igniter Concept for Use in Bequoyah Nuclear Plant. "
  TEDESCO.R L. Assistant Director for Licensing. 81/02/19. 2pp. 07978-097.

- --8102280325 Recommends position re-upper plenum igniters of ice condenser plants per review of "Analysis of Hydrogen Hitigation for Dugraded Cure Accidents in Sequench Nuclear Power Plant : MYPLEY T E Division of Reactor Safety Research 81/02/10 2pp 65042-076
- --B1022B0404 Informs that further analysis necessary re location of ignitors in ice consensor plants Possibility of detonation in upper planum should be considered Recommends ignitors be removed

  MURLEY. T. E. Division of Reactor Bafety Rusearch B1/02/09 2pp
- --BiO3233973 Rough draft. 'Analysis of Hydrogen Mitigation for Degrad Core Addidats in Sequoyah Nuclear Power Plant." prepared for Ofc of Nuclear Regulatory Research SERMAN.M., SHERMAN.M.P., CUMMINOS.J.C. Sandia Laboratories. B0/12/01 130pp 07970 to3
- --BI03230079 Comments on upper plenum igniters of ice condenser plant per review of Evaluation of Glow Plug Ignitor Concept for Use in Sequengah, Nuclear Plant : Evaluation enci HAURAHAY.E J Office of Policy Evaluations 81/01/22 2pp 07978 232
- --BIO3230084 "Evaluation of Glow Plug Igniter Concept for Use in Sequoyah Nuclear Poser Plant " STPEHLCD.R A Affiliation Unknown BI/OI/O9 9pp. 07978 234
- 8103020401 Forwards data from Starting Test 8 5 i re vater temp of upper head taken at various power levels during power ascension testing MILLS.L.M. Tennessee Valley Authority 81/02/23 2pg 07784 231
- 8103091007 Notification of 810303 meeting w/util in Bethesda. MD to discuss R&D program on equipment survivability during hydrogen burn STANLE-C Licensing Branch 2 81/02/26 3pp 07028-243
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8103030836 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEGUDYAH NUCLEAR PLANT.UNITS 1 AND 2 Docket Nos 90-327 and 50-328 (Tennessee Valley Authority) Office of Nuclear Reactor Regulation, Director NUREG-0011 804 81/01/31 31pp. Available at NTIB \$2 00 07789 176
- Bio3040927 Forwards Suppl 4 to SER (NUREC-0011) re application for licenses (I/o encl SCHWENCER, A Licensing Branch 2 Bi/02/18 2pp 07813, 336
- F Security, medical, emergency & fire protection plans
- B1010B0119 Releases public version of util radiological emergency plane FELTON-J II Division of Rules and Records. 80712701 1p. 07416-194
- --8101220517 Forwards public version of util radiological emergency pl MILLE-L M. Tennessee Valley Authority. 80/06/19. 1p. 05496-224
- --BioloBol23 Public version of radiological emergency plan.
   Tennessee Valley Authority B0/06/19 120pp 07416,195
- 8012040091 Releases public version of util emergency plan. State of TN radiological emergency response plan for site. FELTON. J N. Division of Rules and Records B0/12/03 lp. 07196.039
- --8101220526 Forwards public version of TN multi-jurisdictional radiological emergency preparedness plan for site (Part of util plan)
  MILLS.L. N. Tennessee Valley Authority, 80/06/19. [p. 05496.226
- --8012040399 Public version of State of IN multi-jurisdictional radialogical energency response plan for Sequoyah Nuclear Power Facility (Part of util plan).

  \* Tennessee, State of 80/06/02 686pp 07156:040
- 8(03060336 Forwards add) info re guard training & qualification plans Encl withheld (ref 100FR2 790) MILLS-L M Tennessee Valley Authority 81/02/26 Ip.
- BIO3310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for neeting NRC requirements N/o encl EISENMUT, D.9. Division of Licensing. 81/03/05. 6pp.

- sives assurance of meeting license condition PENTON HR Diffice of Nuclear Reactor Regulation, Director 81/02/26 4pc 07893 154
- --BIO3103040 Forwards petition for review of Director's decision under OSCOUGH Forwards Section for review or official sections 100FR2 206 denging revocation of OL License conditions imposed on facility are inadequate Supporting info encl BATES, A. The Nuclear Regulatory Commission 80/10/16 666 07833 160
- ---BiO3100046 Submits to exceptions to 801008 Director's decision under 10CFR2, 226 denying request for revocation of facility UL Containment mati strengths are not sufficient to assure safe margin in event of hydrogen formation. BATES A The Nuclear Regulatory Commission 80/10/16 3pp 97833 166

## H Semeral correspondence

- Bi03020790 Forwards um Hendrie corments on UA Post B0illi article re facility licensing. In response to MO1218 request for reply to M Banson 801⊋09 ltr DIRCKS.W J Office of the Esecutive Director for Operations 81/01/27 ip 07/82 008
- --B103020B01 Requests resconse to encl M Banson 801209 its profession DOWNEY T House of Rep. 80/12/18 3pp 07/82 090.

#### J. Insurance & indemnity information

- 8103060454 Forwards Endorsement 2 to MAELU Binder AB-66 FIELDER, J. Marsi. & McLennan, Inc., M & M Nuclear Consultants. Inc Div. 81/01/27. 3pp. 07837-321
- B103110690 Forwards Endorsement 3 to MACLU Bindar XR-66 FIELDER J. Marsh & Micteman. Inc., H & M Nuclear Consultants.inc Div B1/03/06 app. 07083-030
- 310317064B Advises that B10223 | Itr requires corrections Ltr should have forwarded Endorsement 3 to ANI BEP Excess Binder CB-66 & is effective as of 800229 FIELDER.J Harsh & McLeonan, Inc., H & M Nuclear Consultants. Inc Div 81/03/10, 1p 07925 147
- P Operating license stage documents & correspondence
- 9103120014 Ltr to all licensess of operating plants.CP holders & UL 103120014 Ltr to all licenses of operating plants Gr no applicants except Indian Point 2 & 3.7ino 1 & 2 & Hn-1. forwarding inadvertently emitted pages from NRC 801222 request for add info re control of heavy loads EISE/Bull. 0 0 Division of Licensing 81/02/03 cpp
- 8103050098 Forwards Amend 2 to License DPH-77, safety evaluation & notice of issuance & availability SCHWENGER. A. Licensing Dranch 2. 01/02/09. 200 07027 275
- --8103050109 Amend 2 to License DPR-77, revising license condition for 103030107 Amend 2 to Literase unrecovering proposed changes to hydrogen control measures & approving proposed changes to App A Tech Specs for interim distribution ignition sys. SCHHENCER, A Licensing Branch 2 81/02/09 App 07827.272
- --8103650113 Notice of issuance & availability of Amend 2 to License SCHEENCER, A Licensing Branch 2 81/02/09. 2pp 07827:203
- --8103030121 Bafety evaluation supporting Amend 2 to License DPR-77 Office of Nuclear Reactor Regulation, Director, 81/02/07 Upp 07027: 285
- B103300160 Ltr to all operating PHR licensees requesting info on autiliary feedwater sys seismic design Forwards request for addi Info list of actions requested of licensees w/o seismically qualified sys & results of NRC welkdowns. EISERRUT, D.O. Division of Licensing 81/02/10 13pp.
- B103030356 Forwards Amend 3 to License DPR-77, safety evaluation & notice of issuance & availability.

  SCHMENCER. A Licensing Branch 2 81/02/13 2pp 07803.256

460710303720 Notice of tecomic & availability of Amend I to License

Office of Nortes Resites Regulation, Director HI/D-/11 200

- BLOSOSSEZ Cafety evaluation supporting Amend I to License DPR 77

- OCHRENOTREA Licensing Branch 2 (ULZUZZI) 200 (CZOUT 222)
- HIGH 60667 Ltr to all operating plants f CP holders forwarding clarification of IMI Action Plan How HI Act 2 to updrade izaritzbasian or imi niczoni czan itom ili A t & to upgrado uf ocergoni, support faistittos Requosts roufiloation within 49 days that replementation dates will be not Fluckled. In a Stockled of Lacouston elizabeth
- 8103296024 Lie to all popul reactor licenses a license applicants re noneconversion and proventions of temporary for the second and sec to lookage testing adjections intensed has a second small justify ase of existing low flow continuing [15:FABJI.D. O. Division of Liversing 101702200 Upp
- B103020475 Forum de revised companse to hable 0.747. Item 11 1 4 2 5 reconstainment present a setpoint laborities (3. 001217 & BIOID/ contained prince of the PILLBAL H. Johnston Valley Authority | DIZONYAL | Spp. 07765 119
- HID 1030707 Integrity data from Starting lest 0.5 1 to water temp of none testing per tiertion 6 3 % of timpels to far thity Sen We. enc 1
- MILLO.L B. Tannasson Vallay Authority (11702721 In 0770R F47
- 8103099190 forwards engineering rept. Insp Device in Lieu of Joseph furts ' Includes description results & conclusion of proliminary tosts performed using desica EROSE J.L. Tennessee Valley Authority (19702727) to 197050 jim
- --- BIO3090201 "losp Device to firm of Insp Posts " Photographs enel \* Tennessee Valley Authority Dizuzzaz lapp Dznan Lik
- 8103110046 Entuards notice of consideration of asond to facility in . to response to United application to authorize outite tow-level waste storage for 5 yes. SCHERRIGHA - Licensing Deanth 2 - 01702727 - 1pp - 02077 - 06.
- 3 8103410851 Notice of consideration of among to facility is calcilit HOTIES application to authorize mostle inc level wante storage for 5 are bELLEOD ticonsing branch 2 BIVO2223 her
- BIO3110721 informs that util will submit rapt to purge/vent valve operating experience before startup following first outage Rept demonstrates valve reliability & operability. & justifies additioning time
  MILLSoft H. Tennessee Valley Authority (8120320) ip 02095 122
- 8103110648 Informs that Info will be provided by HIDA ID on mathtageing ice mass as high as possible propertion of the mass as time function, similated heat balances to illustrate margin b methods to minimize heat loss rate, per fill' renuest MILLER. H. Tennessee Valley Authority 111/11/14 to 11/4112 146
- BIO3180104 Forwards Amend 4 to 1 (cense DPR 22, safety evaluation E notice of issuance & availability
  ECHNICHCER A Licensing Branch 2 BIZOTZOS 200 02745 325
- -8103100110 Amend 4 to License DPR-77.changing App A fech Upers where total min ice weight in the condenser not less than 2-223-100 lbs 5 min ice weight in sample baskets not less than 1200 lbs/bastet SCHUENCER, A. Licensing Branch 2 HIZDION 11pg 07945 127
- 07945 300
- -- 8103180120 Notice of Issuance & availability of Amend 4 to Illense DPR-77 BCHMENCER, A. Licensing Branch 2 Hizo3706 Hpp. 07945 H44
- 8103310804 Lir to all licensess of operating plants applicants for fils & holders of CPs forwarding GLCY-DI-119 re info necessary to establish environ qualification of safety related electrical equipment EIBENRUT, DO Division of Licensing Highlin App

- log into will be processed on monthly basis & included in annual operating rept efficient of the first processes and success with the first processes and first processes will St. If Tennesses Valloy Authority 81/03/12 ip 07934 361
- 8103240042 Revises 810130 nemo re costs of processing OL No add) CL for required for review since cost exceeds max fee. HOLLOKAY.C J Cicense Fee Management Branch 81/03/13 ip 07889 216
- --B103240050 Discusses costs for DL review Addit funds willbe expended by Div of Bys Integration on ice condensor problem before facility granted unconditional license Approves billing of license DERAON. H ii Office of Nanagement and Program Analysis 81/01/22 200 07989 220
- 8103190176 Forwards proprietary & nonproprietary version of "Westinghouse Reactor Protection Bys/Engineered Safety Features Actuation Bys Setpoint Methodology," Oversize drawing encl Proprietary version withheld (ref 10CFR2, 790) MILLS.L II Tennessee Valley Authority 81/03/16 2pp 99231 054
- --Bi031901B3 Nonproprietary version of "Westinghouse Reactor Protection Sys/Engineered Safety Features Actuation Sys Betpoint Methodology 'Table 3-4 will be available in PDR on aperture card TULEY.C R, SHARP.D R, MILLER.R B Westinghouse Electric Corp 81/03/16 23pp 95231 056
- 8103190212 Forwards "Research Program on Hydrogen Combustion & Control. Quarterly Progress Rept 2 ' HILLS.L M Tennossee Valley Authority 81/03/16 1p. 07963 001
- --8103190217 "Research Program on Hydrogen Combustion & Control, Quarterly Progress Rept 2 ' • Tennessee Valley Authority 81/03/16 54pp 07963 002
- BIO3300173 Submits addl info re Item 2 1 ba of NUREQ-0978 re surveillance frequency change Test results from 1980 quarterly insp frequency determined favorable & Insp frequency will be changed to annual rate MILLS.L M Tennessee Valley Authority 81/03/24 ip 08053 017.
- 8103310500 Application for amend to License DPR-77, requesting mods to Tech Specs Table 3 2-1.0MD parameters Figure 6.2-2.facility organization & Bection 6 5 1 2.plant review committee composition MILLS.L M Tennesser Valley Authority 81/03/25 1p 08062 332
- --8103319906 Tech Space 3 2.6 2 & 6 4 node to DNB parameters, facility organization & plant operations review committee
- composition
   Tennessee Valley Authority 81/03/25 3oo 08062.353
- G Inspection reports. IE Bulletins & correspondence
- 8102280484 Forwards IE Info Notice 81-01, "Possible Failures of OE Type HFA Relays." No response required O'REILLY. J.P. Region 2. Atlanta, Office of the Director. 81/01/16
- 910310011[ Forwards | E. Insp. Rept. 50-327/80-47 on 801104-30 No noncompliance noted. LEMIS.R.C. Region 2, Atlanta. Reactor Operations Nuclear Support Branch 81/01/29 2pp. 07857 062
- ~-6103100121 IE Insp Rept 30~327/80~47 on 801104~30. No noncompliance noted Major areas inspected operational safety verification, power ascension test witnessing & LER review.

  BUTLER, 5. D. Region 2. Atlanta, Office of the Director DANCE. H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch.
  81/01/28 7pp 07857.064.
- 8103130147 Forwards IE Insp Repts 50-327/80-49 & 50-328/80-27 on 801201-05. No noncompliance noted.

  LEWIS.R.C Region 2- Atlanta, Reactor Operations Nuclear Support Branch. 81/02/05 2pp. 07913.008
- --8103130155 IE lnsp Repts 50-327/80-49 % 50-328/80-27 on 801201-05.No noncompliance noted Major areas inspected preoperational testing preoperational sys well-down of Unit 2 % plant tour. JULIAN.C. FORD.E.. DANCE.H C. Region 2. Atlanta, Office of the Director 81/02/05. Spp. 07913.010.
- 8103130159 Forwards IE Insp Repts 50-327/80-51 & 50-328/80-29 on 801229-31. No noncompliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/05 2pp 07912:208

- verification power ascension testing ROs & events & independent inspectors of the Director DANCE.H C Region 2. Atlanta. Defice of the Director DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch BI/O2/
- B103040570 Act receipt of B01030 ltr informing of corrective actions re IE Insp Rept 90-327/80-36 Withholding application approved. M/o IE Insp Rept 50-327/80-36 to notices of violation. Apps A b 3 encl Page B & App B withheld (ref 10CFR2 790) LEWIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/06 1p 07811 001
- --8103040578 Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/80-36 Informs that NRC is evaluating request that info be withheld (ref 10CFR2 790) LEMIG.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/21 ip 07811 002
- --8193040583 Responds to NRC 801007 ltr re-violations noted in IE Insp. Rept 50-327780-38 Requests portions to withheld Corrective actions withheld (ref 10CFR2 790) MILLE-L M Fennessee Valley Authority 80/10/30 tp 07811 003
- --Bi03040505 Forwards IC Insp Rept 50-327/80-36 on B00801-31 & notice of violation LEHIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/10/07 Rep. 07811.004
- ---8103040587 Notice of violation from insp on 600801-31.

  Region 2. Atlanta. Office of the Director 80/09/30. 1p.
- --Bi03040593 IE Insp Rept 50-327/B0-34 on G00801-31 Noncompliance noted failure to control designated vehicles to follow procedure & to comply w/Tech Specs Page B withheld (ref 100FR2 790) COTTLG.N T. BUTLER.B D. Region 2. Atlanta. Office of the Director DANCE.N C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/30 3pp 0/811 007.
- 8103130189 Forwards IE Insp Repts 90-327/80-45 & 90-328/80-24 on 801125-1202 No noiscompliance noted LENIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Granch 81/02/06 2pp 07908-325.
- --8103130201 IE Insp Repts 50-327/80-45 & 50-328/80-24 on 801125-1202 No noncompliance noted Major areas inspected power ascension. Itemsee special rept review & monitoring of operations. CONAT.T J Region 2. Atlanta, Office of the Director. DANCE.H.C Region P. Atlanta. Reactor Operations Nuclear Bupport Branch 81/02/06 Spp. 07/08 327
- Bi03020277 Forwards IE Circular Bi-D2, "Performance of NRC-Licensed Individuals While on Duty." No written response required.

  D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/02/09.
- R1031B0417 Forwards IE Insp Repts 50-327/R0-48 & 50-328/B0-26 on B01216-17 No noncompliance noted. MARNIYC E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B1/02/09 2pp 07943 036.
- --B103180426 IE Insp Repts 50-327/80-48 & 50-328/80-26 on 801216-19. No noncompliance noted Major areas inspected installed equipment review per NUREG-0398 response. of BBDNS-T D Region 2. Atlante. Office of the Director CONLON-T E Region 2. Atlante. Reactor Construction & Engineering Bupport Branch 81/02/09 App. 07943 038
- 8103180449 Forwards IE Insp Repts 90-327/81-01 & 50-328/81-01 on 810106-09 No noncompliance noted. MVRPHY,C E Region 2- Atlanta. Reactor Construction & Engineering Support Branch 81/02/10. 2pp. 07939. 276
- --BIO3180485 IE Insp Repts 50-327/81-01 & 50-328/81-01 on BiO106-09.No noncompliance noted Major areas inspected electrical & instrumentation, licenses identified items & followup on IE Circular 80-23.
  OIBBONS, T.D., MERRIWEATHER, N. Region 2, Atlanta, Office of the Director CONCOLT E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/02/06. 4pp. 07939:278.
- 8100040195 Forwards IE Info Notice 81-03. "Checklist for Licensess Making Notifications of Bignificant Events In Accordance U/100FRS0 72" No unitten response required.
  O'REILLY-J P Region 2. Atlanta. Office of the Director. 81/02/12. Ip.

- 0103240140 Forwards IE Insp Repts 30-327/80-50 & 30-320/80-20 on 901201-24 No noncompliance noted. LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/13 2pp 07980 221
- --Bi0324014& IE Insp Repts 50-327/B0-30 & 50-328/B0-2B on 801201-24 No noncompliance opted Hajor areas inspected licensee action on previous insp findings, operational safety verification to power accomption test witnessing BUTLER-8 D Region 2. Atlanta. Office of the Director DAMCE.H C Region 2. Atlanta Bactor Operations Nuclear Support Dranch B1/02/13 7pp 07980 220
- 8103160682 Forwards IE Info Notice 81-04. 'Cracking in Main Bloam Lines." No response tequired O'REILLY, J.P. Region 2, Atlanta, Office of the Director B1/02/2/ in.
- B103160316 Forwards IE Circular Bi=03. 'Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER. J O Region 3. Chicago, Défice of the Director 81/03/02 lb.
- 8103170085 Provides addl info re IE Bulletin UD-13. "Possible Loss of Emergency Notification Sys (ENB) w/Loss of Offsite Power" Util expects to complete required made at Browns Ferry by 810427 & at Sequoyah by 810421 MILLS, LM Tennasse Valley Authority 81/03/03 ip
- 8103170011 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director 01/03/04
- 8103260019 Forwards update to 800809 response to EE Bulletin 79-03A "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Stgel Piping." 8A-312. Type 300 series fusion walded pipe not used at facilities Addl info will be sent by 810630 MILLS.L.M. Tennesses Valley Authority. 81/03/04. 2pp 08042 108
- 8103160844 Provides supplemental response to 16 Bulletin 80~06.
  "Engineered Safety Foature(ESF) Reset Controls "NUREO-0508 review determined that certain containment joulation valves could open on reset Suitches will be replaced after 810601 MILLE.L M Tennessee Valley Authority 81/03/05 4pp 07715 226
- B103200197 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breaker." No response required O'REILLY, J.P. Ragion 2. Atlanta, Office of the Director. Bi/03/11 1s.
- B103200003 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No response required.
  O'REILLY-J P. Region 2. Atlanta, Defice of the Director B1/03/13 in.
- 8103240607 Responds to IE Builetin Bi-Oi, "Burveillance of Mechanical Boubbers," No snubbers installed on sefety-related sys. MILLS, I. M. Tennesser Valley Authority 81/03/13 ip. 07702-311
- 8103240466 Forwards response to violation noted in 1E Insp Rept 50-327/81-02 on 810218 Corrective action.util has clarified requirements for determination that item does not constitute unreviewed safety question.

  MELLB.C.M Fennessee Valley Authority. 81/03/14 2pp. 87987-356
- 8103240535 Responds to NRC 810213 itr re-violations noted in IE Insp. Rept. 50-327/80-46 Corrective actions Keithly 602 electrometer use re-evaluated personnel qualification records updated procedures revised & insp. procedure updated. HILLG-L. M. Tennessee Valley Authority. 81/03/16 19pp. 07986:167.
- 8103261117 Ack receipt of 810316 itr informing NRC of steps taken to correct violations noted in 1E inep Rept 50-327781-04. LEWIS.R.C. Region 2. Atlanta. Office of the Director 81/03/18 to. 08035:249.
- --BI03261122 Responds to NRC 810217 ltr re violations noted in IE Insp. Rept 50-327/Bi-04 Corrective actions withheld (ref. 10CFR2, 790).
  MILLS.L. H. Tennessee Vallay Authority. 81/03/16. Ip 08035-250

- HIGG261137 IE Insp Rest 56 J27781 G4 on BIGG26 36 Non-compilance noted failure to meintain positive access control to vital mass petalls ujthbud tref 166182 790)
  TOPINU J. RILLA D. NEGUIRE D.R. Region 1. Philadelphia. Diffice of the Director. HIGG2713 ip. 600 P. 470
- R Pariable operating termits 5 related correspondence
- DIOTHIO-MA Forwards RPDL's distributer continuing copts, Hullion (1922) STEIRR-O R feminesses Valley Authority (1920)2014 ip (1980)
- BIO31104BL REDEB 319Charge contineing repts. HOLLOT BIO201 EL-ASHRY.M.T. Tempesse Valley Actionates - BLV03/04 - Vapp
- 8103200542 Forwards monthly operating rept for Feb (20) BALLEGIBLE J B. Isonesses Valley Authority B1203212 Ip 07271 TA
- BIGB200343 Honthly operating cept for Leb 1981 EDBINGS M - femceased Valley Authority 01704704 - 11pp 67271-017
- 8103310427 Forwards Openial Rept NO ILBN NO Z. 381. "Nadiological legact Assessment Gagobyah Nucleur Flant Jan Jone 1700" & RH-81-2 G31. "Radiological Impact Assessment Gagobyah Nucleur Plant Jul Her 1900" . MILLG.L B. Tarnessee Valley Authority | NIZO1724 | Jpp | D8057 214
- -HIODDIOHR6 "Radiological Impact Assessment Dequayab Ructum: Plant Jan-Jone 1980" # Tennesse Valley Authority | RESP 6-501 | BIZOIZ24 | Plant 08059-217
- --HIO331049D (Radiological Impact Assessment Sequoyab Northean Plant, Jul-Dec 1980) "

   Tennesses Valley Authority WHIO 2 011 0170 M24 2 1pp onney Dec
- C. Reportable occurrences, LIAs & related correspondence
- #103069790 RO MAD 127780176 on #01211 to Mode 5 during IC Bulletin 79-14 review discovered that Thermon heat Changer Coment could result in pipe or hanger failure Cassed by Astione Co consider effect of cement on supports Coment removed DALENTING J Tennessee Valley Authority | Bulletin | Ip 07806 001
- 8103020502 Forwards LER DISONY/ORLS 0 GREEN-H U Tennessee Malley Authority H1702724 Ip 07702 050
- --BI03020936 IER BI-009703C-O on BI0127, containment complevel loop L=63-177 declared inoperable Caused by calibi drift due to problem wileyel transmitter Transmitter replaced MCGRIFF-J H. HILBEY/A H. Tennessee Valley Authority (BI202744) pp. 07702-383
- 8103090409 Bubmits hPDEB Buncompliance notification Newage treatment plant effluent samples cullected on BIDIA/ 6217 revealed less than min 1 Gwg/I dismived osygen Cause is unknown Treatment efficiency was reduced by ambient temp decreases CL-ABREY.R T Tennessee Valley Authority 81763703 Jpp 07092-120
- 0103100490 Forwards the 01-0137036-0 080EN-H J Tennessee Valley Authority 01703703 1p 07062 206
- --BIO3100476 LLB DI-013/Oll-O un BIO203.11quid radwaste monitor.
  O-RE-70-122, declared inoperable Caused by high bacignound count reading due to less in Brooks rotemeter Rotemeter smals replaced, sample chamber cleaned b monitor flushed out MCORIFF. J M., WILKEY, A. H. Tennessee Valley Authority HI/O-HO.1 ip 07862-287.
- 0103100480 Forwards LER 80-206/03x-1 GREEN-H J. Tennessee Valley Aubbority 81/03/04 1p 07862 284

- 8103110477 Forwards LER 91-017/03L-0 GREENH J. Tennessee Valley Authority 81/03/04 Ip. 07869 353
- --6103110485 LER B1-017/03L-0 on B10212.welder accidentally blow pin hole in pipe sleeve-releasing low level activity Xe-133 Caused by thin wall pipe 2 restricted access Pin hole repaired MCGRIFF. J H. KIRK. G B. Tennessee Valley Authority 81/03/04 to 07869 354
- 8103110531 Forwards LER 81-018/93L-0 CREEN.H J. Tannossee Valley Authority 81/03/04 1p 07872 278
- --8103110535 LER B1-018/032-0 on 810205.discovered that 81-137 2.RCB cater inventory, not performed within 72-h per surveillance requirements Caused by steady state conditions not being established long enough for performance before reactor trip MCGRIFF.U M. KIRK.0 B. Tennessee Valley Authority 81/03/04 in 07872-279
- 8103100500 Forwards LER 81-016/03L-0 GREEN.H J. Tennessee Valley Authority 81/03/05 Ip 07862 298
- -.8103100504 LER 91-016/032-D. on 810206 diesel generator 28-8 breaker tripped tuice while attempting to synchronize w/TVA power grid for surveillance test 51-7 Caused by avercurrent during paralleling operation Target reset & parallel repeated MADDOX.S. G. MCGRIFF. J. M. Tennessee Valley Authority 81/03/05 3pp 07862 299
- 8103100468 Forwards LER 81-020/03L-0 GREEN.H J. Tennessee Valley Authority 81/03/06 1p 07862 282
- --8103100477 LER 81-020/03L-0 on 810207, radiation monitor for exhaust path 2-R-90-100 found inoperable w/unit in mode 5 & A8078 train 3 fan discharging through shield blog enhaust vent. Caused by mod to 480-volt shutdown board on 810206 MCGRIFF.J H. WILKEY.A H. Tennessee Valley Authority 81/03/06 ip 07862 233
- 8103170614 RO 80-008 exceeded Tech Spec 3 11 1 2 during third & faurth querters of 1900. Failing to notify Commission when dose requirements limit was braken Apparently caused by breatdown in inter/intradivisional communications sys OPEEN. J Tennessee Valley Authority 81703709 23pp 07938 342
- B10323063B PNS-[I-BI-GO2 on B10309, handwritten bomb threat discovered adjacent to personnel alricok to Unit 1 reactor containment Area searched w/negative results HILL.A. TOBIN.W. Region 2. Atlanta, Office of the Director B1/03/09 Ip 07974 it5
- 6103170530 Forwards LER 81-019/03L-0 GREEN.H.J. Tennessee Valley Authority B1/03/10. 1p. 07929 337.
- --9193170536 LER 81-019/03L-0 on 810211.inside containment (solation valve 1-33-704 on sxc air header discovered omitted from drawing Valve added MKGRIFF. J M , KIRK.O B Tennessee Valley Authority 81/03/10 2pp. 07929 338
- 8103170408 Forwards LER 81-021/00±-0 CREEN.H J. Tennessee Valley Authority 81/03/11. 1p. 07923:199
- --8103170413 LER 81-021/03L-0 on 810211, reactor coolant pumps 1 & 2 were stopped. Caused by RCB pressure going to zero after Riff containment spray isolation valve inadventently opened. Pumps returned to operable status in approx I-h. MCGRIFF.J. M. KIRK.O. B. Tennessee Valley Authority. 81/03/11. Ip. 07923 200.
- 8103170590 Forwards LER 81-022/03L-0. OREEN.H J. Tennessee Valley Authority. 81/03/13. tp. 07939:242.
- --8103170595 LER BI-022/03L-0 on BI0219, w/unit in Mode 5, chloring detector O-CLAN-43-205A declared inoperable. Caused by electrolyte used to drip onto sensor becoming stopped up in felt filter Filter replaced & detector returned to svc HILKEY.A M., MCORIFF.J.M. Tennessee Valley Authority. 81/03/13. 1p. 07939, 243.
- 8103170624 Submits NPDES notification of noncompliance w/effluent limitations Discharge exceeded limits on 810224,26 & 0304. Caused by partial plugging of discharge flowmeter & effluent accumulation in sand filter Design mod requested. EL-ASHRY.M T Tennessee Valley Authority. 81/03/13. 2pp.

- --BIO3290306 LER B1-026/01f-O on B10310 analysis of primary containment atriots electrical penetrations revealed probable leak paths under accident conditions Caused by design Pallure to evaluate scaling mail New cables conduits 5 scale ordered (MADDOX-5 0 . MCGRIFF. J M Tennessee Valley Authority 81/03/18 2pp 07996 332
- 8103240402 PRC-f1-81-023 on B10314.low steam generator water level reactor trip experienced due to main feedwater regulating valve failing closed Auriliary feedwater pumps realigned & pumped river water into steam generators CRLEBLYMAR R. OUICK.D. Region 2. Atlanta, Office of the Director 81/03/19 2pp 07986 340
- 8103250497 Forwards LER 81-023/03L-0 GREEN.H J. Tennessee Valley Authority 81/03/20 Ip 07996 233.
- --8103250507 LER 81-023/03L-0 on 810303, design review per IE Bulletin 79-14 discovered sleeves 925, 329, 533 & 537 on TVA 474470-5 are not 4-inch as-built size Caused by incorrect installation during const Sleeves modified MCGRIFF, J M. KJRK, O.D. Tennessey Valley Authority 81/03/20 16 07996 234
- B103310477 Forwards Special Rept 80-B.RH-80-6-801. "Radiological Impact Assessment. Seguoyah Nuclear Plant. Jan-June 1980" & RH-81-2-801. "Radiological Impact Assessment. Seguoyah Nuclear Plant. Jul-806 1980 "
  MILLS. L. M. Tennessee Valley Authority 81/03/24 2pp 08059 214.
- --8103310483 Special Rept 80-8 during third & fourth quarters of 1980, Tech Spec 3 11 1 2 found exceeded Caused by effluent releases of P-32 from facility. Investigation of P-32 in secondary cycle util continue following plant startup. e Tennessee Valley Authority 81/03/24 21pp. 08099-216
- DUCKET 50-320 SECUCYAH NUCLEAR PLANT. UNIT 2

  A Application/construction stage documents & correspondence
- B103190732 Line to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREG-Od12 Forwards NRC position re-interim actions & request for add1 info E16EHHUT. D Q Division of Licensing 80/12/22. 30pp.
- 8:03:20014 Ltr to all licensess of operating plants CP holders & OL applicants, except Indian Point 2 & 3, Zion i & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 80:222 request for add1 info re control of heavy loads. EISECHNUT. D O Division of Licensing. Bi/OZ/O3 App.
- B103230098 Forwards B10210 memo w/rough dreft, "Analysis of Hydrogen Mitigation for Degraded Core Accident in Sequoyah Nuclear Power Plant" & B10122 memo w/rept entitled "Evaluation of Ignitor Concept for Use in Sequoyah Nuclear Plant." TEDESCO.R L. Assistant Director for Licensing. B1/02/19. 2pp 07978.097
- ~-Bi02280325 Recommends position to upper planum ignitors of ice condenser plants per review of "Analysis of Hydrogen Hitigation for Degraded Core Accidents in Sequoyah Nuclear Hower Plant " MURLEY.T.E. Division of Reactor Bafety Research. 81/02/10 2pp. 65042-076
- --Bi022B0404 Informs that further enalysis necessary re location of igniters in ice condenser plants Possibility of detonation in upper planum should be considered. Recommends ignitors be removed HURLEY, T. E. Division of Reactor Bafety Research. B1/02/09, 2pp. 65042,089
- --B103230073 Rough draft, "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequoyeh Nuclear Power Plant," prepared for Ofc of Nuclear Regulatory Research.

  BERMAN, M. SHERMAN, M.P. CUMMINOS, J. C. Bandia Laboratories

  G0/12/01 130pp. 07978:103
- ---8103230079 Comments on upper planum igniters of ics condensar plants: per review of "Evaluation of Olow Plug Igniter Concept for Use in Sequoyah Nuclear Plant." Evaluation encl. HANRAHAN-E J. Office of Policy Evaluations. 81/01/22. 2pp. 07978:232
- --8103230084 "Evaluation of Clow Plug Igniter Concept for Use in

, . . . . . . . . .

- B103250024 Ltr to all power reactor licensees & license applicants re PAREG-0619 criteria Footnote 2 in Table 2 contains error due to leatage testing deletions Licensee may subnit analysis to justify use of eristing low flow controller FISTEMBULE 0 Division of Licensing 81/02/20 Bpp
- B103020475 Forwards revised response to NUREC-0737. Item II E 4 2 5 re containment pressure setpoint Submittals did 801219 & 810107 contained erroneous info MILLS-L N Tenesses Valley Authority 81/02/23 200 07785. 119
- BIO323030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie-Units 1 & 2) Requests util review to determine capebility to mitigate station blackout event & promptly implement emergency procedures EISENHUT.D 0 Division of Licensing 81/02/25 Spp
- Biogoficor notification of Biogog meeting usual in Bethesda.MD to discuss R&D program on equipment survivability during hydrogen turn graphs.C Licensing Branch 2 Biso2/26 3pp 07828-243
- 8103230813 Generic Ltr 81-C6 to all CP holders & C. applicants re IOCFR50 71(e). "Periodic Updating of F58Rs." effective 800722 Info re F58R legal status.format & content end EISEMUNT.O G Division of Licensing 81/02/26 10pp
- 8103110846 Forwards notice of consideration of amend to facility CL. in response to 801124 application to authorize ensite iou lavel waste storage for 8 yrs
  SCHMENCER.A Licensing Branch 2. 81/02/27 3pp 07877 335
- --Bi0311085| Notice of consideration of amend to facility OL resutil B01124 application to authorize onsite low level waste storage for 5 yrs BELLS-D Licensing Branch 2 81/02/27 5pp 07877 339.
- B103100453 Discusses results of auxiliary feeduater pump endurance test for Unit 1 submitted B01104 Since test results were acceptable util does not intend repeating tests on Unit 2. MILLS.L M. Tennessee Valle, Authority B1/03/03 1p 07867.228
- B103160378 Advises that 43 igniters for Unit 2 containment at locations similar for Unit 1 will be installed before B10415 fuel loading date, for implementation of interim distributed ignition sys Final resolution of hydrogen control is B20131.
  MILLB.L.M. Tennessee Valley Authority 81/03/10 ip. 07917 199
- BiO3:70141 Informs that compliance w/NUREG-0737. Item II.F.I will be meti-requiring operating reactors to have design details for containment high radiation monitor evailable for review by 810701

  MILLS.L. H. Tennessee Valley Authority. 81/03/10 ip 07925-313
- BiO3310804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT, D O Division of Licensing. 81/03/10. 6pp
- 8103170459 Natifies of util plan for ECCS outage data collection, in response to NUREG-0737. Item II X.3 17 Configuration control log info will be processed on monthly basis & included in annual operating rept MICLES.L.M. Tennessee Valley Authority 81/03/12 1p. 07934:361
- B103230451 Informs that currently scheduled date for facility fuel loading is B10501 MILLS-LM Tennessee Valley Authority. B1/03/13 1p. 07977.046.
- 8103190212 Forwards "Research Program on Hydrogen Combustion & Control. Owarterly Progress Rept 2 MILLER.LM Tennessee Valley Authority. 81/03/14 1p. 07763-001
- --B103190217 "Research Program on Mydrogen Combustion & Control.Quarterly Progress Rept 2 " \* Tennessee Valley Authority. B1/03/16 54pp 07963.002.
- 8103270777 Forwards "Assessment of Ultrasonic Reflectors in Sequoyah Unit 2 Reactor Vessel Nozzle Bores" & "Assessment of Ultrasonic Reflectors in Watts Bar I Reactor Vessel Nozzle Bores: "Repts available in Central Files only.
  MICLE-LM Tennesses Valley Authority. 81/03/20 ip.
- Bi03300173 Submits add1 info re item 2.1.6a of NUREO-0578 re surveillance frequency change. Test results from 1980 quarterly insp frequency determined favorable & insp frequency will be changed to annual rate. MILLS.L.M. Tennessee Valley Authority. Bi/03/24. lp. 08053-017.

- E ARC Safet; Evaluation Report (SER), supply & correspondence
- BIOJOJOBBO BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEQUEVAN NUCLEAR PLANT. UNITS 1 AND 2 Docket Nos 50-327 and 50-328 (Tennessee Valley Authority) a Office of Nuclear Reactor Regulation, Director NUREO-CO11 504 BIOJOJOJ 319 Available at NTIS \$2.00 07789 176
- 8103040927 Forwards Suppl 4 to SER (NJREO-0011) re application for licenses W/o encl SCHWENCER.A Licensing Branch 2 81/02/18 2pp 07813 336
- F Security, medical, emergency & fire protection plans
- 8101080119 Releases public version of util radiological energency plan FELTON. Jr. Division of Rules and Records 80/12/01 ip 07415-194
- --Biol 220517 Forwards public version of util radiological emergency plan MICLS.L M. Tennessee Valley Authority (80/06/19 lp. 09496-226
- --8101080123 Public version of radiological owergency plan
   Tennesse Valley Authority 89/06/19 120pp 07416 193
- 8012040391 Releases public version of util emergency plan. State of Tr radiological emergency response plan for situ FELTGH. J ft Division of Rules and Records 80/12/03 lp 07156 039
- --8101220526 Forwards public version of TN multi-jurisdictional radiological emergency preparedness plan for site (Part of util plan) MILLS.L.K. Tennesses Valley Authority 80/06/19. ip. 05496-226
- --B012040398 Public version of State of TN multi-jurisdictional radiological energency response plan for Boquoyah Nuclear Power Facility (Part of util plan) 1790-1890 07156-040.
- 8103060336 Forwards add1 info re guard training & qualification plans Enc1 withheld fref ICCFR2 7901 MILLS-L H Tennessee Valley Authority 81/02/26. Ip.
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding hUREG-0896. 'Functional Criteria for Emergency Response Factities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT.D. 9 Division of Licensing 81/03/05. 6pp
- B103160572 Provides justification for interim operation of facility during initial criticality until fire protection mod for essential raw cooling water say completed on G10630. Continuous & rowing fire watches will be established. MILLBLUM Tennessee Valley Authority E1/03/09. 1p. 07917-200
- J. Insurance & indemnity information
- 8103360454 Forwards Endorsement 2 to MAELU Bindar XB-66 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 81/01/27 3pp. 07837 321.
- BiO3170648 Advises that BiO223 ltr requires corrections. Ltr should have forwarded Endorsement 3 to ANI BFP Escass Binder EB-66 & is effective as of 500229. FIELDERJ Marsh & McLennen, Inc., 11 & M Nuclear Consultants, Inc. Div. Bi/O3/10 tp. 07925.147
- **G** Inspection reports. IE Bulletine & correspondence
- B1022B04B4 Forwards IE Info Notice B1-01. "Possible Failures of GE Type IFA Relays "No response required. O'REILLY.J P. Region 2. Atlanta, Office of the Director. B1/01/16
- 8103130147 Forwards IE Insp Repts 50-327/80-49 & 50-328/80-27 on 801201-05 No noncompliance noted. LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/05. 2pp. 07913:008
- --BI03130155 IE Insp Repts 50-327/80-49 & 50-328/80-27 on 801201-05. No noncompliance noted Major areas inspected preoperational testing preoperational system of Unit 2 & plant tour. JULIAN.C., FORD.E., DANCE, H.C. Region 2, Atlanta, Office of the Director. 61/02/05. 5pp 07913:010.

- B103130159 Forwards IE Insp Repts 50-327/80-51 & 50-328/80-29 on 801229-31 No noncompliance noted CFWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Bupport Branck 81/02/05 2pp 07912 208
- --0103130167 IE insp Repts 50-327/80-51 % 50-328/80-29 on 801229-31 No noncompliance noted Major areas inspected upprational safety verification power ascension testing ROs & events & inspendent insp effort FORD. E Region 2. Atlanta. Office of the Director DANCE. H C Region 2. Atlanta Reactor Operations Nuclear Support Branch 81/02/95 4pp 07912 210
- 8103130188 Forwards IE Ensp Repts 50-327/80-45 t 50-328/80-24 on 801125-1202 No noncompliance noted LEMS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Stanch. 81/02/06 2pp 07908 325
- --8103130201 IE Insp Repts 50-327/80-45 & 90-328/80-24 on B01125-1202 No nancompliance noted Major areas inspected power ascension. Incensee special rept review & monitoring of operations. DD:AT.T J. Region 2. Atlanta. Office of the Director DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/06 5pp 07908 327
- B103020277 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required D'RE(LLY. J.P. Region 2. Atlanta. Office of the Director B1/02/09
- BI03180417 Forwards IE Insp Repts 90-327/80-48 & 50-328/80-26 on 801216-19 No noncompliance noted.
  MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/09 2pp 07943 036
- --BI03180426 IE Insp Repts 90-327/80-48 & 50-328/80-26 on 801216-19 No noncompliance noted Major areas inspected: installed equipment review per NuREO-0388 response.

  91886/85.T.D. Region 2. Atlanta. Office of the Director COMCO.T.E. Region 2. Atlanta. Reactor Construction & Engineering Support Granth 81/02/09 4pp 07943.038.
- B1031B0449 Forwards IE Insp. Repts 50-327/B1-01 & 50-328/B1-01 on B10106-09 No moncorpliance noted. MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch B1/02/10 2pp. 07939 276
- --8103180455 IE Insp Repts 90-327/81-01 & 50-328/81-01 on 810106-09 No nancompliance noted Major areas inspected electrical & instrumentation, licensee identified items & followup on to Circular 80-23 OIBRONS.T D . HERRIHEATHER. N. Region 2. Atlanta. Office of the Director. CONLCN.T E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/06 4pp. 07939.278.
- 8103240140 Forwards IE Insp Repts 50-327/80-50 & 50-328/80-28 on B01201-24 No noncompliance noted. LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/13 2pp. 07980:221
- --8103240146 IE Insp Repts 30-327/80-30 & 50-328/80-28 on 801201-24 No noncompliance noted Major areas inspected licensee action on previous insp findings operational safety verification & power ascension test witnessing.

  BUTLER.S D Region 2. Atlanta. Office of the Director DANCE.H. C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/13 7pp. 07980:223
- 81031606B2 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines" No response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/02/27. Is
- 8103160516 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No response required.

  KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/03/02 lp
- 8103173011 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Snubbers." w/corrected Pages 3 & 6 Changa in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 81/03/04.
  19.
- 8103260019 Forwards update to 800805 response to IE Bulletin 79-03A "Longitudinal Held Defects in ASME 8A-312. Type 304 Steinless Steol Piping." SA-312. Type 300 series fusion welded pips not used at facilities Addl info will be sent by 810630.

  MILLS, L.H Tennessee Valley Authority. 81/03/04. 2pp. 08042:108

- 8103200197 Forwards IE Info Notice 81-06. "Failure of ITE Model K-6 Circuit Breaker." No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/03/
- 8103200003 Forwards IE Info Notice 81-05. "Degraded DC Bys at Palisades" No response required D'REILLY, J.P. Region 2. Atlants, Office of the Director. 81/03/ 10
- R Periodic operating reports & related correspondence
- B103110476 Forwards N°DES discharge monitoring repts 801101-810201 BTEINER-0 R. Tennessee Valley Authority B1/03/04 1p. 07801.3
- --BIO31104Bi NPDES discharge monitoring repts.801101-810201 EL-ABHRY,M F Tennessee Valley Authority 81/03/04 92pp
- S Reportable occurrences. LERs & related correspondence
- 8103040794 First interim deficiency rept re inconservative loads on pipe support design mods.initially reported 801217. Caused by failure to reflect load increases not requiring design mods on support drawings Addl info espected by 810302 MILLS. L.M. Tennessee Valley Authority 81/01/19 2pp 07810:14
- 8103030893 Final deficiency rept re defective guide tube support pin initially reported 800324. Cause not stated Upper internals guide tube support pins will be replaced whose gine supplied by Westinghouse MILLS.L If Tennessee Valley Authority 81/01/23 2pp 07795 2;
- 8:03030778 Third interim deficiency rapt re possible imadvertent bordilution initially reported on 800710 Westinghouse investigation is engaing w/completion of evaluation in Mar 1782. Next rept will be forwarded by 820608 MILLS. L M. Tennessee Valley Authority. 81/02/06. 1p. 07796. 12:
- 8103050707 Part 2: first interim rept re limit switch actuator for Masoneilan air operated valves supplied by Hestinghouse, initially reported on 810120 TVA acaiting Hestinghouse reply to notification Next rept by 810401 MILLS, L.M. Tennessee Valley Authority, 81/02/19, 3pp. 07825, 16
- 8103040797 Fifth interim deficiency rept.originally reported on 8002 re environ qualification of class IE components w/o documentation confirming operability in ambient conditions. Cause not stated Next rept will be submitted by 810402 MILLS.L.M. Tennessee Valley Authority. 81/02/29. 6pp. 07813 04
- 8103040775 Fourth interim deficiency reptroriginally reported on 800424 re incorrect insulation weight used in piping analysis Review of as-constructed insulation drawings against completed analyses to be submitted by 810408.
  MILLS.L II Tennossee Valley Authority. 81702/26. 1p. 07813 059
- 8103090693 Second interim deficiency rept re offsite power voltage fluctuation, initially reported on 801020 Setpoints have been calculated for future degraded voltage relaying to assure adequate starting voltage for 460 valt motors.

  MILLEL M Tennessee Valley Authority. 81/02/27 2pp. 07848:28
- Bi03i20i82 Interim Part 21 rept.originally reported on Bi0128.re excessive pressure drops across essential raw cooling water sys strainers. Evaluating test data to determine corrective action Next rept to be submitted Bi
- 8103110545 Second interim deficiency rept.originally reported 801215 retrievable info from valve tag numbers. Manufacturers catalogs being used to obtain valve data. Discrepancies being analysed. Next rept to be submitted by 810401.

  MILLS.L M. Tennessee Valley Authority. 81/03/02. Ip. 07878:225
- B103110614 Second Interim Deficiency Repts 80RD-90-328/81-08, WBRD-50-390/81-07 & WBRD-50-391/81-06 re unconservative loads on pipe support design mode.initially reported 801217. Approx 2000 support drawings found Rept expected by B10401. MILLS.L M. Tennessee Valley Authority. 81/03/02. 1p. 07887-109
- Bi03090409 Submits NPDEB noncomplience notification Bewage treatment plant effluent samples collected on Bi0127-0217 revealed less than min 1.0mg/l dissolved oxygen. Cause is unknown. Treatment efficiency was reduced by ambient temp decreases. EL-ABHRY.M.T. Tennessee Valley Authority. Bi/03/03. 2pp. 07892 120.

- BIO3310A59 Second interim deficiency rept.originally reported on S01210 re-fillet weld misspecification Gaused by etceeded 60 degree nin angle for intersecting members of fillet-welded stands tee joints Fills. M. Fernessee valley Authority 81/03/03 3pp 07872 325
- 8103:10433 Final deficiency meptine failure of containment isolation valve limit switches to meet environ qualification in event of accident initially reported on 810202 Unqualified limit switches will be replaced MILLS.L.M. Tennessee Valley Authority 81/03/04 2pc 07873 354
- 8103110627 Final deficiency rept.originally reported on 800325, refailure of upper head injection hydraulic isolation valve accumulator weighing sys Caused by stiffening of connecting hydraulic lines under pressure Administrative change made MILLS.L N Termassee Valley Authority 81/03/04 2pp 07872 321
- 8103130465 Final deficiency rept re thermon heat transfer cement.
  Initially reported 801125 Cenert will be recoved from all
  areas which restrict specified capabilistics for pige
  roughent
  MILLES. N. Tennessee Velley Aushority 81/03/05 2pp 0791: 352
- Bi03180362 Revised final deficiency rept.originally reported 800325 reupper head imjection hydraulic isolation valve accumulator weighing say Coused by stiffening of connecting hydraulic lines under pressure Repairs to be rade prior to fuel load MILLS.L.M. Tennessee Valley Authority 81/03/12 2pp 07944.266
- 8103170624 Submits NPEES notification of noncompliance w/effivent limitations. Discharge exceeded limits on 810224.26 & 0304 Caused by partial plugging of discharge flowmeter & effluent accumulation in sand filter Design mod requested EL-ASH3Y.H T Tennessee Valley Authority 81/03/13 2pp 07925:164
- 8103240404 Fourth interim rept re failure to consider loads from 3-inch check valve in seismic analysis of chemical & vol control sys.initially reported on 801002 Loads at Sequoyah not significant Results of reanalysis in final rept by 810915 MILLS.L.M. Tennessee Valley Authority 81/03/17 ip 07987 181
- 8103240420 Third interim deficiency rept re ASCO Model HTX8320A22V solemaids in radiation monitoring systimitially reported on 801208 Investigation continuing to determine need for repair-relocation or replacement Nest rept by 810403.

  MILLS-L H Tennessee Valley Authority 81/03/17. Ip 07987 186
- B103270672 Revised final interim deficiency rept.originally reported on B10202.re environ qualification of valve limit switches. Unqualified limit switches will be replaced by B20630 w/ switches that are environmentally qualified per NUREG-0588 MILLS-L M Tennessee Valley Authority. 81/03/18 3pp 08047.116
- 8103310555 Fourth interim deficiency rept re environ quelification of electrical equipment. Util still gathering environ qualification documentation on components. Next rept will be submitted by 810414

  MILLS.L.M. Tennessee Valley Authority 81/03/25 ip 08075 231.
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants, applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NUREO-0612. Forwards NRC position reinterim actions & request for add info EISENMUT. D O Division of Licensing. 80/12/22. 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs to program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NURREQ-0737.

  EISENHUT.D Q. Division of Licensing. 81/01/19. App.
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info recontrol of heavy loads.

  EISENHUT.D.Q. Division of Licensing 81/02/03. 6pp.
- 8103090131 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216
  KEPPLERIJ 9. Region 3. Chicago, Office of the Director. 81/02/20

- fil02250024 Lin to all power reactor licensees % litense applicants re MAREG-0619 criteria Fontnote 2 in Table 7 contains error due to leakage testing deletions Licensee may subsit analysis to justify use of eristing low flow controller (1921-07.0 ) pivision of Licensing 61/02/20 8pp
- BiO3020210 Forwards PLO-0147. "Midland Plant Auxiliary Feedwater Gys Reliabitity Analysis: Study, along w/previously submitted info. demonstrates sys design adequacy Responses to NRC info requests entl COCK. J N. Consumers Power Co. 81/02/23 12pp 07783 194.
- --BI03020220 "Midland Plant Aurillary Feedwater Sys Reliability
  Analysis"
  SLEY.D C . CATE.C L . STILLWELL.D W. Pickard Lowe & Garrick. Inc.
  PLG-0147 80/10/21 225pp 07783 206
- B103040692 Forwards response to questions to teartor pressure vessel support moss Requests approved by 810301 COCK. J M. Consuers Power Co. 81702/24 7pp 0/812 255
- 8103130440 Forwards responses to NRC 810212 questions re reactor vessel support mods for design approval Requests responses on design concept by 810301 to meet const schedule M/a encl Related correspondence COOK, J H. Consumers Power Co. 81/02/24 3pp. 07908-230
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except 8t Lucie Units 1 & 2) Requests util review to determine capability to miligate station blackout event & promptly implement emergency procedures £ISETHUI.D 0 Division of Licensing BI/02/29 Spp
- 8103230813 Jeneric Ltr 81-06 to all CP holders & OL applicants re IOCFR\$0 71(e), "Periodic Updating of FSARs," effective 803722 info re FSAR legal status, format & content encl E188(NUT.D 0 Division of Licensing 01/02/26 10pp
- BIO3040620 Forwards 'Site Specific Response Spectra Part I.Response Spectra. SEE.Original Ground Surface." & "Site Specific Response Spectra Part III. Beisnic Hazard Analysis." per NRC 801205 request Review requested. KEELEV.0 S Consurors Power Co. 81/03/02 Bpp 07808 302.
- --8103040020 "Site Specific Response Spectra: Part 1. Response Spectra, SSS. Original Oround Surface '
  - \* Weston Geophysical Corp. 81/02/28 89pp 07008.310
- --BIO3040034 "Site Specific Response Spectra.Fart 111.Spismic Hazard Analysis "
  • Weston Geophysical Corp. B1/02/2B 79pp 07809 038
- 8103060643 Act receipt of NRC 810210 ltr re licensing schedules for facilities. Final design review meeting scheduled 810326.
  Responses to NUREG-0694 being reformatted to correspond to
- NUMECO-0737.

  SELBY- J. D Consumers Power Co. 81/03/02. 2pp 07837. 278
- BiO3100855 Forwards written presentation. "Dusign to Achieve & Maintain Cold Shutdown." Graf presentation will be made before Util Design Review Board on BiO326.

  COCK.J.W. Consumers Payer Co. Bi/O3/05. ip. 07863:i03.
- --8103100558 "Design to Athleve & Meintein Cold Shutdoun," unfitten presentation at 810326 meeting of Util Design Review Board Consumers Power Co. 81/03/03, 47pp. 07863-106.
- 8103160296 Approves BO1210 design concept for reactor pressure vessel support cods. Revised concept consistent w/devolopment of research re effects of bloudoum forces on vessel internals. TEDESCO.R.L. Assistant Director for Licensing. 81/03/06 lp 07921:336.
- B103190663 Confirms B10313 meeting w/util In Olen Eilyn, IL to discuss GA program improvements, REPPLER, J. G. Region 3, Chicago, Office of the Director. B1/03/10 ip. 07934:337
- B103310B04 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EIBENHULD. 0. Division of Licensing. 81/03/10. 6pp.
- 8103269883 Discussor 810337 tologo

Ann Artor, MI to audit seismic & structural design Ann Artor.MI to audit seismic t structural design calculations for major safety-related structures (COD.D S Licensing Dianch 3 81/03/16 4pc 07942 357

- 3103190111 Confirms telcon re 810320 meeting w/Ofc of Nuclear Reactor Regulation to discuss items re upgrading licensee QA topical Teps HOFFMAN, D.P. Consumers Power Co. 81/03/16 200 07964 190
- 9103200639 Forwards Americ OB to application for CP t OL.consisting of Revision 15 to responses to 114C requests re plant fill COJK.J k. Consumers Power Ca. B1/03/16 1p. 07971 169
- -8103200644 Amend BB to application for CP & CL, revising responses to HRC requests re-plant fill CCDA. J W. Consumers Power Co. 81/03/16 ip 07971 170
- --BIO3200650 "Revision II to Responses to NRC Requests Re Plant Fill."
  submitted as Amend 88 to application for CP t OL
  Consumers Power Co BI/03/16 64pp 07971 172
- 3103230307 Notification of 810416 meeting w/util.Weston Geophusical corp & Bechtel in Bethesda.MB to review site specific tesponse spectra for SSE at original ground surface & seismic hazard analysis
  HOOD, D. Licensing Branch 3 81/03/16 4pp 07975 053
- aic3240496 Advises of intentions to implement modified reactor pressure vessel support concept for Unit 2.00 proviously proposed for CODAL J.W. Consumers Power Co. 81/03/17 In 07987 360
- 3103260079 Notification of 810428 meeting w/Sechtel in Ann Arbor.MI to aiuszouurz mottrication or viluazi meeting w/Dechtel (n Ann discuss independent deeligh roview of deeligh to achieve & maintain cold shutdown at facilities HEDD:D Licensing Branch 3 81/03/18. 2pp 08040-121
- 9:03260120 Forwards list of generic ltrs & bulletins issued to power reactor licensees & applicants in 1980 FEDESCA.L Assistant Director for Licensing 81/03/18 27pp 08039 260
- 3103260133 Confirms agreement to participate in 810428 meeting w/util Jesign review board in Ann Arbor-Mi to review facility
  Jesign to achieve & maintain cold shuddown Transcript will
  be necessary for incorporation into util OL application
  JECCSCO.R I Assistant Director for Licensing 81/03/10. 2pp 08039-287
- 9103240445 Forwards affidavit re distribution of Amend 80 to CP & DL applications SUDZIN.D N Consumers Power Co B1/03/20 1p 07981 342
- --8103240454 Affidavit re distribution of Amend 88 to CP & OL applications
  BUDZIK. D.M. Consumers Power Co. 81/03/20 3pp 07981-343
- 8103260180 Forward: BAU-1628. "Reactor Vessel Brittle Fracture Analyses During Small Break LCCA Events W/Extended Loss of Feedwater, " submitted in response to NUREG-0737, Item II K 2.13 Thermal shock not concerned w/startup.
  COOK, J W Consumers Power Co 81/03/20 2pp. 08041:124
- BIG32607IB Notifies that emergency operations facility dosson info will be provided as part of normal OL process in response to NRC BIO21B Generic Ltr Bi-10 re post-TMI requirements. Requested info will be submitted by Jul 1983 OL issuance COJX.J W. Consumers Power Co. Bi/O3/20. ip. OB041:079.
- 9103260700 Bubmits info per 810227 telcon re resolution of facility soils hearings issues Borings syc water blog & electrical panetration areas percanent plant dewatering & site specific seismic criteria discussed COOK. J W Consumers Power Co. 81/03/23 6pp 08041.081.
- Security, medical, emergency & fire protection plans
- 9103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements U/o encl EISE(#UT.D.9. Division of Licensing. 81/03/09. 6pp.

- 8103039776 Notice of withdrawel of appearance in proceeding Certificate of Svc uncl WARREN,S & Affiliation Unknown, 81/02/11 300 07791.266
- 8102270630 Discusses 810210 telcon C Carson will be expert geologist witness Reducate names of individuals responsible for greliminary site choice
  MARSHALL.W H Mapleton Intervenors 81/02/21 2pp.
- 8103040568 Memorandum summarizing 810128-29 prehearing conference w/wtil.8 Stamiris.6 Warren.Mapleton Intervenors & M Binclair re applicant notion to corpel depositions of NRC witnesses & further discovery Further discovery BECHMEEFER.C Atomic Safety and Licensing Board Panel. Bi/02/27. App 07816-337
- 8103130491 Response to Intervenor B Stamiris Bi0126 interrogatories & LOSIONATE RESPONSE to intervenor b examinis alora in raply to CPC BIOLIT response to intervenor request Certificate of Svc encl Related correspondence a Consumers Power Co BI/02/27 16pp 07913 072
- 8103120336 Objects to Findings in ASL8 B10227 memo EPA.not NRC or Arr; Corps of Engineers.has jurisdiction on soils in flood riverfront plain MARBIACLL.W H Mapleton Intervenors 81/03/04 Ip 07901-250
- 8103100337 Notice that 810324-25 prehearing conference rescheduled for BIOAD2-03 restree that usuar-20 presenting converence restricted to BIOAD2-03 Parties; proposed agendas to be submitted by BIO327 rather than BIO220 as proviously stated BICHIDEFER.C Atomic Safety and Licensing Board Panel BI/03/06 pp. 07844-320
- B103200761 Forwards responses to NRC B01126 interrogatories Responses to third set of NRC interrogatories will be filed prior to B10402 probering conference W/o encl.
  BRYUNER.E J. Consumers Power CO. B1/03/09 1p. 07767-068
- D103203563 Forwards intervenor 810126 response to util 810119 discovery STAMIRIE. 3 Affiliation Unknown B1/03/11 1p.
- --8103200567 Objects to util 810119 discovery reply Util did not adequately respond to requests for documents re soil soitlement costs.addl borings & administration bldg settlement Related correspondence BTAMIRIS.3 Affiliation Unknown 81/01/26 Spp.
- STAMIRIS. 3 Affiliation Unknown 81/03/11 1p
- 8103260737 Anguers to NRC 801126 interrogatories re fill areas & remedial actions Contificate of Bvc & affidavits and

  \* Consumers Power Co DHAR.B., SWANBERG.H Bechtel Corp

  D1/03/11. 22pp 08035 332
- 0103200524 Forwards cover ltr.which was sent out w/applicant responses to NRC 801126 interrogatories 8 was Inadvertently omitted from copies to persons on svc list W/o encl.Related correspondence.

  ORUNNER, E. J. Consumers Power Co. B1/03/12 1p. 07971:302.
- 8103230632 Request for order compelling NRC answers to util 801112 Interrogatories 13-16. NRC should have tabulated acceptance criteria & has obligation to do so now Certificate of Bvc enci Related correspondence.
  FARNELLA 9 Consumers Power Co.
  Dwale. 81/03/12 Spp 07977 245 FARNELLIA B. Ishami Lincoln &
- 8103260796 Notice of J Kane 810326 deposition in Bethesda.MD rematters set forth in ASLB 810128-29 prehearing conference ruling on issues in 791206 order modifying CP. Certificate of Svc encl. Related correspondence. FARNELL.A S Consumers Power Co. FARNELL.A S Isham, Lincoln & Beals. GI/O3/17. 4pp 08035:197
- 8103190619 Proposed transcript corrections to D Hood 810219 deposition in Bethasda.MD. Contificate of Bvc encl. HG/DD: D Licensing Branch J. 81/03/18 4pp. 07963:290
- 8103260764 Natice of appearance in proceeding Certificate of Svc encl BROWN, E M Office of the Executive Legal Director. 81/03/25 3pp. 08036:070

failed to respond to interrogatories within scope of discovery Certificate of But ercl. PATON.M.D. Hearing Branch 4 81/03/26 10pp 08034 040

## H General correspondence

- 9100180679 Forwards constituent JB Lanies Bi0135 request for Benator Warner Intervention re 801219 request to DDE for info on plant restart. DDE sent 801219 request to RRC for response Requests rest on stated concerns WARNER, J W Benate. 81/02/18 2pp. 07954 089
- 8100230581 Requests that correspondence be addressed to UH Cook, Vice President. CPC Related correspondence.
  818HDP, B L Consumers Power Co. 81/03/02 10 07977, 279

## I. Financial information

- 8103160328 Forwards Annual Financial Rept 1980. PERRY.P A Consumers Power Co 81/03/11 1p 07917 132
- --8103160538 Annual Financial Rept 1980
  \* Consumers Power Co 81/02/13 28pp 07585.001
- G Inspection reports: IE Bulletins & correspondence
- 8103040900 Forwards IE Mgt Meeting Repts 50-329/80-36 & 50-330/80-37 on 801124.1202 & 17

  KEPPLER.J. 9 Region 3. Chicago. Office of the Director 81/01/08.
  In 07812 138.
- --8103040909 IE Mgt Meeting Repts 50-329/80-36 & 50-330/80-37 on 801124, 1202 & 17 Areas discussed recently reorganized GA organization FIGRELLI.9. Region 3. Chicago. Reactor Construction & Engineering Support Branch 81/01/07. 3pp. 07812.139
- 8103040142 Forwards 1E Investigation Repts 50-329/80-10 & 50-330/80-11 on 800306-0731 Items of noncompliance forwarded in separate ltr KEPPLER. J O. Ragion 3, Chicago, Office of the Director 81/01/12 2pp 07819: 348
- --BI03040159 fE Investigation Repts 50-327/80-10 & 50-330/80-11 on 800306-0731. Najor eroes investigated allegations re-eatl traceability-falsification of records & training of GC inspectors Exhibits encl WEIL.C.H. COMER.J. JUNES.C.E. Region 3. Chicago. Office of the Director. 81/01/09 38pp. 07819.330.
- 8103120247 Forwards IE Insp Repts 50-329/81-02 & 50-330/81-02 on B10109 & 20-21. No noncompliance moted. FIGRELIA. Region 3. Chicago, Reactor Construction & Engineering Support Branch. B1/92/02. 2pp. 07900 286.
- --8103120252 IE Insp Repts 50-329/81-02 & 50-330/81-02 on 810109 & 20-21 No honcompliance noted Major areas inspected preservice inepprocedures, work activities & nonsestructive exam personnel certifications & data

  KARD, K D. Region 3. Chicago, Office of the Director.

  DANIELSON, D.H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. B1/01/30. 3pp 07900-288
- 8103180198 Forwards IE Insp Repts 80-329/81-01 & 50-330/81-01 on 810107-09, notice of violation & notice of deviation. KEPPLER, J. 0. Region 3. Chicago: Office of the Director. 81/02/02. 2pp. 07745, 271.
- --BI03180203 Natice of violetion from insp on Bi0107-09. KEPFLER, J. G. Region 3, Chicago, Office of the Director. 81/02/02. 2pp. 07945:273.
- --8103180208 Notice of deviation from insp on 810107-09.

   Region 3. Chicago: Office of the Director. 81/01/28. 19 07943, 275.
- r-Dio3180213 IE imap Repts 50-329/81-01 & 50-330/81-01 on 810107-09. Noncompliance noted inadequate procedures document control & Garacords & deviation from consistent to provide geotechnical engineer.

  GALLAOMERIE J., LANDSTANIR B., BUTPHINIR N. Region 3. Chicago-Office of the Director. 81/01/28. 13pp 07945:276.
- 8103030114 FDIA request for CPC 810202 response to NRC proposed fine on facility const activities.

  BATTLE, L. C. Affiliation Unknown. 81/02/03 1p. 07791:188

8103030105 Responds to FOIA request for CPC response to NAC proposed fine on facility const activities Document was provided on 81021[
FELTON: J M Division of Rules and Records B1/02/19 lp 07791 157

Individuals While on Duty 'No written response required MERPLER. J. G. Region 3. Chicago. Office of the Director - BI/02/09 2pp - 07787-273

- G103040655 Responds to IE. Bulletin 79-02 Pipe Support Design Agency ha requested relaxation of prohibition on expansion anchor bult use upstream 8 downstream of pumps Request denied. Existing criteria will be retained Final response expected by G11215 CD04.47 Consumers Power Co. 81/02/26 Spp. 07815 111
- 8103160704 Forwards JE Info Notice 81-04. "Cracking in Main Stean Lines." No response required REPPLER. J O. Region 3. Chicago. Office of the Director 81/02/27 2pp 07914-069
- 8:03:60504 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation." No response required REPPLER. J. G. Region 3. Chicago. Office of the Director. 81/03/02 2pp. 97914,003
- 810316CB92 Foruards revised IE Bulletin 81-01. "Surveillance of Mochanical Shubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. MEPPLER. J O Region 3. Chicago. Office of the Director 81/03/04 in 97913-056.
- 8103190358 Responds to 1E Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No subj valves used in safety-related say. COGK.J W. Consumers Power Co. 81/03/09 Ip 07998-001
- 8103240016 Forcards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater" No response required XEPPLER.J. 0. Region 3. Chicago. Office of the Director 81/03/13 200 07990 315
- 8103200665 Forwards |E Info Notice 81-05, "Degraded DC Sys at Falisades." No action required KEPPLER.J O Region 3. Chicago. Office of the Director. 81/03/13 2pp 07766.188
- BiO3200312 Forwards IE Info Notice 81-07. "Potential Problem L/Water-Solvole Purpe Dam Matis Used During Inort Castelling." No response required XEPPLER, J O Region 3. Chicago, Office of the Director 81/03/16-2pp 07966.294
- R Periodic operating reports & related correspondence
- 8103050479 Forwards ALAB-106 monthly rept for Jan 1981 Includes Bethtel.B&H & util monconformance repts CODM.J.W. Consumers Power Co. 81/02/25. 300pp
- 8 Reportable occurrences. LERs & related correspondence
- 8103090079 Trip rept of JP Matra & J Kane 810127 site visit re cracks in concrete foundation of borated water storage tanks. Plastic sheeting erected adjacent to Unit 2 tank Excavation to inspect cracks not yet started. IKOOD.O S. Licensing Branch 3. 81/02/20. 8pp 07852:144.
- 8103040649 Interim deficiency rept re containment internal structures roating, initially reported 791213. Applied Sys 9 coating samples are being tested at ORNL. Interim or final rept expected by 810529 COUN.J.W. Consumers Power Co. 81/02/23. 7pp. 07815:114.
- 0103060479 Forwards ALAB-106 monthly rept for Jan 1981 Includes Bechtel B&W & util nonconformance repts. CODA, J. W. Consumers Power Co. 81/02/25 300pp.
- 8103040649 Interim deficiency rept re sway strut rod ends initially reported 801031. Bechtel is reviewing specer size & bearing rovement for acceptance as resolution to loose bushing problem Interim or final rept expected by 810410. COOK. J.W. Consumers Power Co. 81/02/27. 3pp. 07815.121.

- FINADADA77 Interim deficiency rept to ECCAS cabinet wiring Caused by wireing changes made at Dalley Controls Co during sus charkout Hardware will be corrected in accordance w/drawings by B10930
  - CONK.J W Consumers Power Co 81/02/27 4nd 07810 169
- 8103170611 Interim deficiency rept re anomalies in NSBS seismic & LOCA analysis, initially reported 801218 Bechtel will replace obsciete ref in engineering dept procedure Corrective actions scheduled for 810331 completion COOM, J W Consumers Power Co 81/03/12 3pp 07925 172
- Bi03300352 PNS-III-Bi-05 on Bi0323 Midland County Bheriff Dept received telephonic bomb threat from male caller Borb threat procedure & search of facility (nitiated No fuel on site ticensee made press release State of MI will be notified CRECD.JR. FISHER.W. Region 3. Chicago. Office of the Director 81/03/23 1p 08055 277
- I Wearing transcripts on non-antitrust matters
- 8103090349 Deposition of J Branner on 810122 in Bethesda. MD re acceptable plastic analysis methods applicable to buried ateing sys TOAMMER. J Rockwall International Corc. 81/01/22 A2nn 65037 317
- B10311928: Proposed transcript corrections to AJ Cappuci 810122 COSTINAUT Proposed transcript corrections to AJ Cappuct B10122 deposition Certificate of Svc encl PATON-W D Hearing Branch 4 CAPPUCLA J Mechanical Engineering Branch 81/03/09 3pp 07885 288
- 8103110292 Proposed transcript corrections to RE Sheumaker 810119 deposition Certificate of Svc encl PATON: WD Hearing Branch 4. SHELMMAKER.R E. Division of Reactor Construction Inspection 81/03/09 Spp 07880.174
- U Congressional/Executive Correspondence
- 9103270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
  HENDRIE J M Commissioners 81/03/12 5pp
- --BiO3270947 Submits recommendations re-scheduling personnel resources & hearing ngt for GL proceedings. Panel must obtain exemption from biring freeze for two recently appointed chairmen. COTTER. B P Atomic Safaty and Licensing Board Panel 81/02/25 3360
- DICKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants applicants for DLs & holders of CPs re control of heavy loads flequests review for guidelines in NUREG-0612 Forwards NRC position reinterim actions & request for addl info EIBENNIT. D 9 Division of Licensing. 80/12/22 30pp.
- 8103[90387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed invalve cold shutdown, replacement parts & NUREG-0737 EISENHULD O Division of Licensing, 81/01/19 6pp.
- Bio3;20014 Ltr to all licensees of operating plants CP holders & OL applicents except Indian Point 2 & 3.7ion i & 2 & TMI-1 forwarding inadvertently emitted pages from NRC Boi222 request for add inforce control of heavy loads EISSNMUT. D Q Division of Licensing. Bi/02/03 dpp.
- 8103090131 Forwards organizational charts depicting NRC Region 3 reorganization.effective B10216. KEPPLER J O. Region 3. Chicago, Office of the Director B1/02/20 2pp. 07450.075
- 8103250024 Ltr to all power reactor licensees & license applicants re MPEG-G619 criteria Footnate 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT, D-9. Division of Licensing. B1/02/20 8pp
- 8103020210 Forwards PLO-0147. "Midland Plant Auxiliary Feedwater Bys Reliability Analysis" Study along u/previously submitted info demonstrates sys design adequacy Responses to NRC info requests encl. Consumers Pawer Co. 81/02/23 12pp. 07783 194

- --8103020220 "Midland Plant Auxiliaru Feedwater Bus Reliabilitu Analysis ' BLEY.D C . CATE.C L . STILLWELL.D W Pickard Lowe & Carrick. II PLO-0147 BO/10/31 225pp 07783 206
- 8103040692 Forwards response to questions re reactor pressure vesse support node Requests approval by 810301 CCDK.J W. Consumers Power Co. 81702/24 7pp. 07812 255.
- 8103130440 Forwards responses to NRC B10212 questions re reactor versupport nods for design approval. Requests responses on design concept by 810301 to meet const schedule. W/o encl Related correspondence
  COOK. J.W. Consumers Power Co. 81/02/24 Jan. 07908 230
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except 5t Lucie, Units 1 & 2) Requests applicants of the releast of the second of the second of the station blackout event & promptly implement emergency procedures EISE(HAVID G Division of Licensing 81/02/23 5pp
- B103230B13 Generic Ltr B1-06 to all CP holders & CL applicants re 10CFR80 71(e), 'Periodic Updating of FSARs,' effective B00722 Info re FSAR legal status, format & content encl E1BENHyT.D 2 Division of Licensing B1/02/26
- 8103040020 Forwards "Site Specific Response Spectra Part 1.Response Spectra: SSE, Original Ground Surface, " & "Site Specific Response Spectra Part III. Selsnic Hazard Analysis." per NAC 801205 request Review requested. KEELEY. G B. Consumers Pawer Co 81/03/02 8pp 07908.302
- ~-8103040028 "Site Specific Response Spectra Part I.Response Spectra Original Ground Surface " # Weston Ceophysical Corp. 81/02/28 89pp 07808 310
- --B103040034 "Site Specific Response Egectra, Part III, Seismic Hazard Analysis "
  - Westen Geophysical Corp. 81/02/28 79pp. 07809.038
- B103050643 Ack receipt of NRC 810210 ltr re licensing schedules for facilities Final design review meeting scheduled 810026 Responses to NUREG-0674 being reformatted to correspond to NUREG-0737 SELBY, J.D. Consumers Power Co. 81/03/02. 200 07837 278.
- 8103100595 Forwards written presentation. "Design to Achieve & Maint Cold Shutdoun" Oral presentation will be made before Util Design Review Board on B10326 COCK.J W Consents Power CO 81/09/05 ip 07863 105
- -- 8103100558 "Design to Achieve & Maintain Cold Shutdown." written presentation at 810326 meeting of Util Design Review Board 4 Consumers Power Co. 81/03/05. 47pp. 07863:106
- 8103160296 Approves 801210 design concept for reactor pressure vassa support mods Revised concept consistent w/development of research re effects of blowdown forces on vessel internals. TEDESCO-R L Assistant Director for Licensing. 81/03/06 07921.336
- 8103190663 Confirms Bi0313 meeting w/util in Olen Ellyn. IL to discus QA program improvements.
  KEPPLER-J. C. Region 3. Chicago: Office of the Director 81/03/10 1p 07954-397
- 8103310804 Ltr to all licensees of operating plants applicants for 0 & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment EIBENAUT.D G Division of Licensing. 81/03/10. 620.
- 8103260893 Discusses 810227 telcon w/licenses re changes in remedial actions for plant soil settlement. Borings, exploration & testing authorized, per NRC 800630 request Proposal for svc water bldg has been changed HDOD.D Licensing Branch 3 81/03/13. 2pp. 08040:211.
- 8103190035 Notification of 810420-24 meeting w/util & consultants in Ann Arbor.MI to audit seismic & structural design calculations for major safety-related structures.
  HODD.D.S. Licensing Branch 3 81/03/16. 4pp. 07962:357
- B103;901;1 Confirms telcon re 810320 meeting w/Ofc of Nuclear Reactor Regulation to discuss items re upgrading licenses QA topical HOFFMAN, D.P. Consumers Power Co. 81/03/16 2pp.

Revision 11 to responses to MRC requests re-plant fill COSK, J W. Consumers Power Co. 81/03/16 ip 0797; 169

- --BIO3200644 Amend 8B to application for CP b Oursevising responses to MAC requests replant fill COPA. AM. Consumers Proce Co. B1/03/16 5p 07971 170
- --Bi032006t0 "Revision Li to Responses to NAC Requests Re Plant Fill."
  submitted as emend 88 to application for CP & OL
   Consumers Power Co 81/03/16 64pp 07971 172
- 8103240495 Advises of intentions to implement modified reactor pressure vessel support concept for Unit 2.as previously proposed for Unit 1 CDCA. J N Consumers Power Co. 81/03/17 1p 07487-360
- BIOJ260079 Notification of BIO428 meeting a/Bechtel in Ann Arbor.MI to discuss independent Jesign review of design to achieve & maintain cold shutdown at facilities #1020.D Licensing Branch 3 BI/03/18 2pp 08040 [2]
- 8163260120 Forwards list of generic litts & bulletins issued to gover reactor licensees & applicants in 1980 TEDES/O.R. L. Assistant Director for Licensing 81/03/18 27pp 08039 260
- 8103260133 Confirms agreement to participate in 810420 meeting u/util sestign review board in Ann Arbor. Hi to review facility design to achieve & maintain cold shutdown Transcript will be necessary for incorporation into util CL application.
  TEDESCO.R C. Assistant Director for Licensing 81/03/18 2pp 08039-287
- 8103240445 Forwards affidavit re distribution of Amend 88 to CP & C. applications BUD21N-D M Consumers Power Co 81/03/20 ip 07981-342
- ~-8103240454 Affidavit re distribution of Amend 88 to CP & DL applications.
- B103260180 Forwards BAH-1620. "Reactor Vessel Brittle Fracture Analyses During Small Break LOCA Events W/Estonded Loss of Feedwator." Submitted in response to NUREO-0737. Item II K 2 I3 Thermal shock not concerned w/stertup CCOA. J W. Consumers Power Co. B1/03/20 2pp 08041-124
- B10326971B Notifies that emergency operations fectlify design info will be provided as part of normal OL process in response to MRC 81021B Generic Ltr Bi-10 re post-fill requirements Requested info will be submitted by Jul 1983 CL issuance COCK.J D Consumers Power Co. 81703720 1p. 08041-079.
- 8103260700 Submits info per 810227 telcon re resolution of facility soils hearings issues Borings svc water bldg & electrical penetration areas.permanent plant dewatering & site specific saismit criteria discussed COGN.J.W. Consumers Power Co. 81/03/23 app. 08041 081
- F. Security, modical, emergency & fire protection plane
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl. EISENHUT. 0.0 Division of Licensing Bi/03/05 6pp.
- **G.** Adjudicatory correspondence
- 8103030776 Notice of withdrawal of appearance in proceeding. Certificate of Svc enti MARREN.8 K. Affiliation Unknown. 81/02/11 3pp. 07791.266
- 8103040569 Memorandum summarizing 810128-29 preheating conference woutile 8 Stabiris. 8 Warren. Hapleton intervenors & M. Sinclair rolepilcant motion to compel depositions of NRC witnesses & further discovery.

  BECHHOEFER.C. Atomic Sefety and Licensing Board Panel. 81/02/27 pp. 07816.337.

- Certificate of Svc encl Related correspondence
  Cortificate of Svc encl Related correspondence
  Consumers Pewer Co 81/02/27 16:p 07913 072
- A103120336 Objects to findings in ABLB 810227 memo EPA, not IRC or Are; Corps of Engineers, has jurisdiction on suils in fload riverfront plain MARSHALL, H Mapleton Intervenors 81/03/04 ip 07401 250
- 8103100337 Notice that 810324-25 prehenring conference reschuduled for 810402-03 Parties' proposed agendas to be submitted by 810327 rather than 8102-0 as previously stated 8ECHEMEFER. C. Atomic Safety and Licensing Board Panyl. 81/03/06 to 07864-320.
- 8103200963 Forwards intervenur 810126 response to util 810119 discovery response STAMESS APPLICATION Unknown 81/03/11 [p
- --BIO3293567 Objects to util Biolif discovery repty Util did not adequately respond to requests for documents re-smil settlement costs.aid burings & administration alog settlement Related correspondence
  BIOSERS Affiliation Unknown BI/OI/26 Spp
- --Bio3200570 Requests 4-day extension to file motion to compel discover from applicant Related correspondence STANIRIB.3 Affiliation Uninown B1/03/11 ip
- B103260737 Answers to NRC B91126 interrugatories to fill Areas & tomedial actions Certificate of Svc & Affidavits encl . Consumers Power Co. DHAD.O., SUAMBERO, N. Dechtel Corp. B1703711 22pp 08033 332
- B103200524 Forwards cover ltr. which was sent out w/applicant responses to NRC B0122 interrogatories 8 was indivertently omitted from topics to persons on sec list W/a and Rolated correspondence BRUNNER 5 / Consumers Power Co B1/03/12 ip 07971 302
- B103230632 Request for order compelling LRC answers to util B01112 Interrogatories 13-16 RRC should have tabulated acceptance criteria & has obligation to do so now Certificate of five encl. Related correspondence FANELLIA S Consumers Power Co. FARRELLIA S Isham. Lincoln & Beale 81/03/12 Bpp 07977 246
- B103260796 Notice of J Kane B10326 deposition in Bethesda-MD reratters set forth in AELB B10128-27 prehearing conference ruling on issues in 791206 order modifying CP Cartificate of Svc encl Related correspondence FARNELL-A S Cansumers Power Co FARNELL-A G. Juham. Lincoln & Beals B1/03/17 App 08036 197
- Bio3190619 Proposed transcript corrections to Dillood 810219 deposition in Jothesda-MD Cortificate of Sec enc. I HCOD.D Licensing Branch 3. 81/03/18 4pp 0/963 290.
- B103260764 Notice of apparance in proceeding Certificate of Svc encl BNOWN, E.M. Diffice of the Espective Logal Director B1/03/25 320 08036-070
- 8103270979 Request to compet ensuers to interrogatories Applicant has failed to respond to interrogatories within scope of discovery Certificate of Byc encl. PATON, M.D. Hearing Branch 4 01/03/26 10pp 08034-040
- H General correspondence
- 8103230581 Requests that correspondence be addressed to UH Cook, Vice President, CPC. Related correspondence BISHOP, B.L. Consumers Power Co. BI/VOJ/02. 1p. 07977: 279.
- 1 Financial information
- B10316092B Forwards Annual Financial Rept 1980. PERRY, P. A. Consumers Power Co. 81/03/(i ip
- --8103160538 Annual Financial Rept 1980 \* Consumers Power Co. 81/02/13. 28pp.

- 3 Inspection reports. IE Bulletins & carrespondence
- 8103040900 Forwards IE Myt Meeting Repts 50-329/80-36 & 50-330/80-37 on 801124.1202 & 17
  WEPPLER.J G Region 3. Chicago, Office of the Director 81/01/08 on 09812 138
- --8103046909 IE Mgt Meeting Repts 50-329/80-36 & 50-330/80-37 on fi01124. 1202 & 17 Areas discussed recently reorganized GA crganization F[ORELLI.G Region 3, Chicago Reactor Construction & Engineering Support Branco 81/01/07 3pp 07812 139
- 8103040142 Forwards 1E Investigation Repts 50-329/80-10 & 50-330/80-11 on 800308-0731 Items of noncompliance forwarded in separate itm REPPLER. J O Region 3. Chicago. Office of the Director 81/01/12 220 27819 340
- G103090:82 Discusses resident inspector findings re installation of care support vent valves for facility installation procedure is being revised? personnel training will be reviewed CODK. J & Consumers Power Co 81/01/22 Ip 07848 197
- 8(03)20247 Forwards IE Insp Repts 50-329/BI-02 \$ 50-330/BI-02 on Biolog & 20-21 No noncompliance noted FICRELLIA Region 3. Chicago. Reactor Construction & Engineering Support Branch BI/02/02 2pp 07900 286
- --BIO3120252 IE Insp Repts 50-329/81-02 & 50-330/81-02 on Bi0109 & 20-21
  No noncompliance noted Major areas inspected preservice insp
  procedures, work activities & nondestructive exam personnel
  certifications & data
  WARD, X D Region 3. Chicago Office of the Director.
  DANIELSON, D H Region 3, Chicago. Reactor Construction &
  Engineering Support Branch B1/01/30 Spp 07900 208
- 8103(80)98 Forwards 1E Insp Repts 50-329/81-01 & 50-330/81-01 on Biolo7-09.notice of violation & notice of deviation XEPPLER. J O Region 3. Chicago. Office of the Director 81/02/02 20s 0/945 2/1
- --8103180203 Notice of violation from insp on Biolo7-09 KEPPLER, J. O. Region 3. Chicago. Office of the Director: B1/02/02 200 07949 273
- --BIO3180208 Notice of deviation from imag on Bi0107-09

   Region 3, Chicago, Office of the Director 01/01/28. Ip
- --BIO3160215 IE Insp Repts 50-329/01-01 & 50-330/01-01 on BI0107-09 Noncompilance noted inadequate procedures, document control & OA records & deviation from commitment to provide geotechnical engineer PALLAGHER.E J. LANDSMAN.R D. SUIPHIN.R N. Region 3. Chicago-Dffice of the Director BI/01/20 IJp 07945:276
- 8103030114 FOIA request for CPC 810202 response to NRC proposed fine an facility const activities.
  84TLEC. C. Affiliation Uningen. 81/02/03 1p 07791:158.
- 8103020059 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. KEPPLER. J G. Region 3. Chicago: Office of the Director. 81/02/09 20p 07787-273
- 8103030106 Responds to FOIA request for CPC response to NRC proposed fine on facility const activities Document was provided on 810211 FELTON, J B. Division of Rules and Records 81/02/19, 1p. 07791 157
- 8103040655 Responds to IE Bulletin 79-02 Pipe Support Design Agency has requested relaxation of prohibition on expansion enchor bolt use opstream & downstream of pumps Request denied Existing criteria will be retained Final response expected by 811215 CODK-J.W. Consumers Power Co. 81/02/26 3pp. 07815:111.
- 8103160704 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines:" No response required KEPPLER, J. G. Region J. Chicago, Office of the Director. 81/02/27 2pp. 97914:069
- 8103160504 Forwards [E Circular Bi=03, "Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER, J. O. Region 3, Chicago, Office of the Director. 81/03/02. 2ps. 07916:003

- 8103160892 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Shubbers," w/corrected Pages 3 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements KEPPLER, J 0 Region 3, Chicago, Office of the Director 81/03/04
- 8103170358 Responds to IE Sulletin 80-21. 'Valve Yokes Supplied by Malcolm Foundry Co.Inc.' No subj valves used in safety-related sys. COUK.J H. Consumers Power Co. 81/03/09 1s. 07955-001
- 8103240016 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater ' No response required MEFPLER J O Region 3. Chicago. Office of the Director 81/03/11 20n 07990 315
- 8103200663 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades" No action required MEPPLER, J.O. Region 3. Chicago. Office of the Director 81/03/13 200 07966 158
- 8103200312 Forwards IE Info Notice 81-07. "Potential Problem W/Water-Soluble Purge Dan Matio Used During Inset Gas Holding: No response required KEPPLER. J. 9 Region 3. Chicago. Office of the Director 81/03/16. 20p. 0796
- R Periodic operating reports & related correspondence
- 8102060479 Forwards ALAB-106 monthly rept for Jan 1981 includes Bechtel, B&W & util nonconformance repts CCEM, J W Consumers Pueer Co 81/02/25 300pp
- 9 Reportable occurrences. LERs & related correspondence
- B103040029 PNO-111-81-010 on 810116, stop work order re installation of core support assembly vent valves (squed to BSM after discrepancies noted included failure to maintain adequate inventory control 8 to identify valve parts NNOP.R. 8 gutphin.R. 8 egion 3. Chicago. Office of the Director. B1/01/19 2pp 07816 347
- B103090079 Trip rept of uP Matra & J Kane B10127 site visit re cracks in concrete foundation of borated water storage tanks. Plastic sheeting erected adjacent to Unit 2 tank. Excavation to inspect cracks not yet started. HOOD. D. Licensing Branch 3 B1/02/20. Bpp 07852:144
- 8103040649 Interim deficiency rept re containment internal structures coating initially reported 771213 Applied Bye 9 coating samples are being tested at GRNL Interim or final rept espected by 810529 CODK. J.W. Consumers Power Co. 81/02/23 7pp 07815:114
- 8103040645 Interim deficiency rept re away strut rod ends initially reparted 801031 Bechtel is reviewing spacer size & bearing movement for acceptance as resolution to loose bushing problem Interim or final rept expected by 810410 COOK, J W. Consumers Power Co. 81/02/27 3pp. 07615.121
- B103040677 Interim deficiency rept re ECCAB cabinet wiring. Caused by wiring changes made at Bailey Controls Co during syscheckout Hardware will be corrected in accordance w/drawings by B10930 CODK. J W Consumers Power Co B1/02/27 App. 07810:169
- BiO3170611 Interim deficiency rept to anomalies in NB98 seismic & LOCA analysis, initially reported B01218 Bechtel will replace obsolete ref in engineering dept procedure Corrective actions scheduled for B10331 completion.

  COOA.J W. Consumers Power Co. 81/03/12. 3pp 07925.172.
- 8103300352 PNS-III-81-05 on 810323 Midland County Sheriff Dapt received talephonic bomb threat from male caller Bomb threat procedure & search of facility initiated No fuel on site. Licensee made press release. State of MI will be notified. CREED. J. R. FISHER. W. L. Region 3. Chicago, Office of the Director 81/03/23. 1p G8055-227
- T. Hearing transcripts on non-antitrust matters
- B103090349 Deposition of J Brammer on B10122 in Bethesda, MD reacceptable plastic analysis methods applicable to buried piping sys

  BRAMMER, J Rockwell International Corp. B1/01/22 62pp.
  65089-317.

- DOCKET 30-331 BUANE ARNOLD ENERGY CEMTER

  F Security, regital, emergency & fire protection plans
- 8101070962 Releases public version of util energency plan
- B10(070462 Releases public version of util energency plan FELTON, J. M. Division of Rules and Records 89/12/03 Ip 07402-232
- --BIDI230527 Forwards facility radiological emergency response plan ROBIL D IDWA Electric Light & Power Co. 79/12/31. 2pp O1699-279.
- --Bi0107046? Public version of State of IA.Linn County radiological emergency response plan (Part of util plan)
   Linn County.(A B0/01/31 240pp 07402 233
- --9101070472 Public version of emergency plan
   fous Electric Light & Power Co 79/12/31 250pp 07403 0[6
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101. Forwards NRC position to request for addition resaft shutdown capability for compliance w/801119 fire protection rule FERRINARIL D. D. Division of Licensina 81/02/20 13aa
- 8103050280 Advises that implementing procedures for emergency plan are being forwarded under separate cover.per App E to 10CFR90 Addl procedures to be submitted by 810320 R90T.L D 10ua Electric Light & Power Co. 81/03/02 1p 07826 356
- 8103181125 Forwards comments on 790817.1030 & 800825 guard training & qualification plan Requests revisions & addl info within 60 days. Encl withintel (ref 100FR2 7901.

  IPPOLITO.T A. Operating Reactors Branch 2 81/03/03.
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding hUREG-0694. "Functional Griteria for Energency Response Facilities." Criteria describe acceptable method for meeting NRC requirements II/o encl EISERHUI.D. O Division of Liconsing 81/03/05 app
- 8103240216 Responds to requirements of 10CFR50 48 re fire protection & 10CFR50 to provide design descriptions of needed mpts. Commitment to complete fire protection features accepted by NRC in 780601 fire protection SER & 810210 Suppl 1 encl 8007+0. D Towa Electric Light & Power Co 81/03/19. 4pp. 07990.338
- J insurance & indemnity information
- 8103090533 Forwards Endorsements 2.3 & 4 to NELIA Binder £8-50 & MAELU Tinder X8-50. MENSIEIN.R. Lowenstein.Newman.Re(s.Azelrad & Toll. 81/03/04. ip. 07846:125

B10312C014 Ltr to all licensees of operating plants.CP holders & CL applicants, except Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding imadvertently omitted pages from IRC 801222 request for addlines to control of heavy loads exercises.CP Joynston of Licensing 81/02/03 App

B1701723

FISHBUT, D.O. Division of Licensing

- 8103030086 Forwards Abend 63 to License DPR-49, safety evaluation to notice of issuance to availability IPPQLITG.7 A Operating Reactors Branch 2 81/02/10 2pp 020A8 187
- --B103030097 Amend 63 to Litense DPR-49 revising litense condition re completion of made for fire protoction. IPPOLITO. TA Operating Reactors Granch 2 81/02/10 App 02898 189
- --8103030107 Safety evaluation supporting Amend 60 to License DPR-49

   Operating Reactors Branch 2 01/02/10 7pp 07808 191.
- --8103030115 Notice of Issuance & Availability of Amend 63 to License DeR-49 | PPDLITO.T A Operating Reactors Branch 2. 81/02/10 2pp 07608 198
- B103050310 Forwards Amend 64 to License DPR-49, safety evaluation & notice of issuance & availability IPPDLIFO.T.A. Operating Reactors Branch 2 B1/02/17 2pp 07826-025
- --B103050314 Arend &4 to Litense DPR-49, incorporating some TMI-2 lessons learned Category A requirements re emergency power supply/inadequate core coalling-valve position indication & containment isolation iPPOLITO-TA Operating Reactors Branch 2 B1/02/17, 18pp 07824-027
- --BI03050317 Bafety evaluation supporting Amend 64 to License DPR-49

   Dffice of Nuclear Reactor Regulation. Director B1/02/17 4FP
- --8103059322 Notice of issuance & evaluability of Amend 64 to License DPR-49 IPPOLITO, T A Operating Reactors Branch 2 B1/02/17. 2pp 07824-049
- Biolicocky Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1.2 rw upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.D.O Division of Licensing BIO2/18. 12pp
- 8103030845 Application for amond to App A Tech Specs re containment & isolation valves for License DPR-49.

  ROITLL D Towa Electric Light & Power Co 81/02/20. Ip. 07797 340
- --8103030850 Proposed Tech Spec Pages 3.7-22 % 3.7-25 re containment isolation valves.

   lowa Electric Light & Power Co 81/02/20, 4pp. 07797 341

- BIO3390244 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216 WEPPLER. J. G. Region 3. Chicago. Office of the Director 81/02/20 22p 07850 357
- B103290024 Litr to all power reactor licensees & license applicants re MSEG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee ray submit analysis to justify use of existing low flow controller error MIT.D.G. Division of Licensing 81/02/20 8pp
- B103040197 Revises B01231 response to NUREO-0737 re plant shielding. training for mitigating core damage & common ref level Mods will be completed by B20101 RCOT.L.O. Ioua Electric Light & Power Co. B1/02/23 2pp. 07820-039
- 8103230330 Ltr to all licensees of operating nuclear power plants & applicants for Ols (accept 9t Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISSNHUT.D O Division of Licensing GI/OZ/25 Spp.
- 6103170225 Ltr to all BWR licensees (except Humboldt Gay & LaCrosse) requesting review of ASME Code Class 1 % 2 pressure boundary piping-safe ends & fitting mat1 per guidelines of encl Revision 1 to NUMEO-0313 Model Tech Specs only encl stephHMID D D Buysion of Licenseing 01/02/26 3pp
- --8103170266 Model Tach Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 ry surveillance requirements for ASMC Code Class 1.2 & 3 consinents & RCS operational leakage limiting conditions for operation & surveillance requirements & operal Electric Co. 61/02/26 4pp
- B103180137 Forwards Amend 65 to License DPR-49 & notice of issuance & availability [PPDLITO.T A. Operating Reactors Branch 2 91/03/03. 3pp 07943-195.
- -8103180142 Amend 65 to License DPR-49, including requirement to maintain a fully implement safeguards contingency plan within 30 days of agroval by Commission [PPOLITO. TA Operating Reactors Branch 2 81/03/03 200
- --8103160147 Notice of issuance & availability of Amend 69 to License DPR-49 IPPOLITO,T A Operating Heactors Branch 2 01/03/03 2pp 07933 200
- 8103310994 Ltr to all licensees of operating plants, applicants for GLs bholders of CPs forwarding GECV-B1-II9 re info necessary to establish environ qualification of safety-related electrical equipment EISE(NMT-D 0 Division of Licensing 01/03/10 App
- 8103230232 Informs that environ qualification relivew results of safetyrelated electrical equipment identified potential equipment deficiencies Requests review of Identified deficiencies & ramifications within 10 days of receipt of 1tr MOVAK.T M. Assistant Director for Operating Reactors 01/03/14 70pp. 07979 001
- 8103270095 Surmary of 810304 meeting w/Mark 1 numers group & GE in Esthesda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per MAREO-0366 Slide prosentation & list of attendees encl. CRIMES.C I Licensing Stanch 3 B1/03/16 Spp.
- 8103260563 Forwards updated list of natis needed for assessment of impacts of facility operation (Requests that util provide contractor, Environ Science & Engineering, w/available items on list.

  1PPOLITOLTA Operating Reactors Branch 2. 81/03/18 3pp. 08037-259
- 8109300552 Forwards Amend 66 to License DPR-49, safety evaluation & notice of issuance & availability IPPOLITO T A Operating Reactors Branch 2 81/03/23. 2pp. 08058 072
- ~-Bi03300566 Amend 66 to Licenso DPR-49, reflecting replacement of power operated inboard Containment Isolation Valve CU-4371-B U/manual stop check valve IPPOLITO. TA Operating Reactors Brench 2. 81/03/23. 3pp 08059.074.
- \*\*BIO33009bB Bafety evaluation supporting Amend 66 to License DPR-49
  \* Office of Nuclear Reactor Regulation, Director 81/03/23. 2pp
  08058 079

- --BIO3390559 Notice of issuance % availability of Amend 46 to License DPR-49 HAMMON.J N. Operating Reactors Branch 2 81/03/23 2pp OBC58 CB1
- G Inspection reports. IE Bulletine & correspondence
- 8103050397 Forwards tE Insp Rept 50-331/60-24 on 601201-31 No nuncompliance noted HEISHMAN,9 F Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/16 2pp 07824 291
- -- G103050402 IE Insp Rept 50-331/80-24 on 801201-31 No noncompliance noted Major areas inspected plant operations & naint, procedures, docucentation & work performed CHRISTIANSON.W. CLARBY.L. & LITTLE.W. & Region 3. Chicago. Office of the Director 81/01/16 4pp 07824 293
- BIO3120395 Forwards 1E Health Physics Appraisal Rept 50-331/80-21, notice of violation & significant appraisal findings WEPPLER, J.G. Region 3. Chicago, Office of the Director 81/02/02 3pp. 97705 091
- --8103120400 Notice of violation from health physics appraisal on 801110-21 KEPPLER, J.Q. Region 3. Chicago, Office of the Director 81/02/02 2pp 07905 096
- --BIO312040B IE Health Physics Apprecial Rept 50-331/80-21 Noncompliand noted weaknosses in radiation protection dest staffing lovels.interim emergency response capabilities & availability of operable purtable survey instruments HILLER, D.E., PAUL, R.A., GRANT, N.B. Region 3. Chicago, Office of the Director 01/01/28 29pp 07905 098
- 8103020073 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty" No written response required MEPPLER, J. Q. Region 3, Chicago, Office of the Director 81/02/09, 2pp 07787-307
- B103190114 Forwards IE Insp Rept 90-331/81-01 on B10101-31 No noncompliance noted 地区18HMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch B1/02/11 2pp 07960 236
- --B103190122 IE Insp Rept 90-331/81-01 on 810101-31. No noncompliance noted Major areas inspected review & observations of plant operations, maint, procedures, documentation & work performed CHRIBTIANSON.W. CLARDY.1, 8. 1.11TLE.W.B. Region J. Chicago. Office of the Director 81/02/06 9pp 07960 238.
- 8103040292 Forwards IC Info Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events in Accordance 4/100767857 72. No written response required KEPPLER. J G. Region 3. Chicago. Office of the Director 81/02/12 2ac 07015 249.
- B103030270 Forwards Suppl 5 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BLR' No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 81/02/13 2pp 07790 315
- B103160478 Forwards IE Circular 81-03, "Inoperable Beismic Monitoring Instrumentation" No response required KEPPLER, J O Region 3, Chicago, Dffice of the Director B1/03/02 2pp. 07915-293
- BIO3160975 Forwards revised IE Bulletin D1-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. KEPPLER. J 0 Region 3. Chicago. Office of the Director 81/03/04 ip 07915 142
- B103200392 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breaker' No response required KEPPLER, J. G. Region 3. Chicago. Office of the Director B1/03/11 2pp. 07972 149.
- B103200651 Forwards IE Info Notice B1-05. "Degraded DC Sys at Palisades No action required KEPPLER. J O Region 3. Chicago Office of the Director 81/03/13 2pp. 07967.253

supervisor assigned to provide supervisory oversight of technical & routine health physics activities RD37.4. D. love Electric Light & Power Co. 81/02/27 12pp 08034-095

B103310402 Responds to IE Bulletin 80-25. "Operating Problems w/Target Rock Safety Relief Valves at 8MRs "No two-stage safety relief valves in use Procedures will be revised to include requirements re valve malfunctions RDDT.LD Jour Electric Light & Power Co. Bi/03/20 4pp 08058:179

# R Periodic operating reports & related correspondence

- B103040487 Forwards "Semiannual ReptrRadioactive Effluent Releases. Jul-Dec 1980." MINECK D. L. Icua Electric Light & Power Co. 81/02/25 ip 07810.062
- --B103040497 "Semiannual Rept.Radioective Effluent Releases, Jul-Dec 1980 " • lowe Electric Light & Power Co 81/02/25 7pp 07810 063
- 8103090524 Forwards "Annual Operating Rapt of Facility Changes.Tests & Experiments.1980 "
  MINECK.D L. Idua Electric Light & Power Co. 81/02/26 | Ip. 07845-207
- --B103090525 "Annual Operating Rept of Facility Changes Tests & Experiments 1980."

  a low Electric Light & Power Co. 81/02/26 45pp. 07845-208
- BiO3180499 Forwards monthly operating rept for Feb 1981 MINECK.D L lows Electric Light & Power Co 81/03/12 ip 07948 287
- --BIO31BO499 Monthly operating rept for Feb 1981. VANSICKEL J. Towa Electric Light & Power Co 81/03/12 7pp.
- 8 Reportable occurrences. LERs & related correspondence
- B103020695 PNO-III-80-206 on 801105, planned shutdown begun to replace pump seals on recirculation pump A Seals have been in use for five years withoreasing leakage Plant will start up on 801109.
  CHRISTIANSON.W. LITTLE.W.S. HEIGHMAN.R.F. Region 3. Chicago. Office of the Director 80/11/06 1p. 07782 042.
- 8103040128 PNO-III-80-210 on B01110, leating relief valve was cycled in attempt to reseat & resultant blowdown caused reactor scram. During recovery, discovered that A MSIVs did not close Caused by improperly connected wire in circuit BMITH, J. CHRISTIANSON, N. LITYLE, 48 Region 3, Chicago, Dffice of the Director 80/11/12 1p. 07819 333
- 8103050567 Forwards (ER 81-006/03L-0) MINECK: D. L. Jowa Electric Light & Power Co. 81/02/26 1p. 07829.065.
- ---B103050578 LER B1-006/03L-O on B10127 during normal operation, containment pressure recorder PR 43844 failed upscale Caused by bad connection due to bent pins on amplifier card for pen 1. Pins reoriented.

  RAOER.M. B. I lows Electric Light & Power Co. B1/02/24 1p 07827-066.

8103170566 Forwards LER 81-009/03%-0 MINECK.D L fowa Electric Light & Power Co 81/03/11. ip 07933-360

07935 278

- --8103170575 LER 81-009/03L-0 on Bi0212.isolation valve V-18-19 to ser discharge vol high level switch LS-1861D found closed during hardware testing Caused by personnel error Valve opened & personnel reinstructed on compliance w/procedures TODAER.D H Towa Electric Light & Power Co. 81/03/11 1p 0793-741
- B103240409 PNO-III-BI-033 on B10316, at 38% power, small was blown on offgas sys resulting in unplanned airborne activity release to reactor blog Airborne activity level returned to normal within approximation. HEISHMAN.R F. Region 3. Chicago, Office of the Director B1/03/17 2pp 07987 179
- B103310717 P:0-III-B1-034 on B10321, recirculation loop discharge valve B failed to close Valve inoperability from LOCA 100p selection logic circuitry to be tested during outage Contactor at breaker manually closed.closing valve CHRISTIANGON.F. LITTLE.W. SCHWEIBINZ.E. Region 3. Chicago. Office of the Director. 81/03/23 1p 08062 224
- MIRECK.D L Toya Electric Light & Power Co 81/03/25 1p 08061 083

  --8103310679 LER 81-010/03u-0 on 810224.fan for standby filter unit 8
- --8103310679 LER B1-010/03L-0 on B10224-fan for standby filter unit found not running during operational test Caused by personnel error in opening broaker for control bldg emergency air supply fan. Personnel reinstructed.

  RAGER-M S | Jowa Electric Light & Power Co | B1/03/25. | 2pp 08061 064
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

  F Security, medical, erergency & fire protection plans

8103310673 Forwards LER 81-010/03L-0

- B103040092 Forwards info re status of fire protection safety evaluats supplementary items. Three items remain incomplete IPPOLITO: TA Operating Reactors Branch 2 01/02/13 Spp 07612, 232.
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101. Forwards NRC position & request for addl info reseafe shutdown capability for compliance w/801119 fire protection rule
- protection rule EISENHUT.D.G. Division of Licensing 81/02/20. I3pp.
- B103[10854 Forwards notice of extension of completion dates for fire protection mods in response to B102[1 ½ 18 requests.
  Discussion of schedular relief encl.
  DENTO\*\*LH R. Office of Nuclear Reactor Regulation, Director.
  B1/02/24 7pp. 07877 344.
- --8103110856 Notice of extension of completion dates for fire protect nods in response to 810211 % 18 requests CASE.E.G. Office of Nuclear Reactor Regulation. Director 80/12/24 1p. 07877-351.
- 8109310938 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for ceeting NRC requirements U/o encl. E18ENHUT.D.O. Division of Licensing. 81/03/05. 6pp.

- 6103270733 Releases public version of draft implementing procedures for everyency plan
  FELTOH.J.H. Division of Riles and Records 81/03/19 lp
  07836 JOI
- --E103270736 Forwards public version of draft implementing procedures for energency plantin response to NRC B01113 ltm BAYHELJP Power Authority of the State of New York 81/02/27 22p 07836 301
- --8163270739 Public version of draft implementing procedures for energency flan + Power Authority of the State of New York 81/02/27 200pp 07896 601
- p. Operating license stage documents & correspondence
- 8103199732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interim actions & request for add1 info EISECHUT. D O Division of Licensing 80/12/22 30pp
- BiO3193387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREC-0737 EISENAUT.D G Division of Licensing 81/01/19 App
- 8103240290 Ltr to all BWR licensees forwarding Buppl 1 to generic safety evaluation on BWR scrar discharge sys Summarizes re-evaluation of interim measures recommended per 801201 safety evaluation FISCHWUT.D G. Division of Licensing 81/01/23 2pm
- 8103120014 Ltr to all licensees of operating plants.CP holders & O. applicants.except Indian Point 2 & 3.71on 1 & 2 & TMI-1. forwarding inadvertently omitted pages from IRC 801222 request for add1 info re control of heavy loads FIECHWILO 9 Olivision of Licensing 81/02/03 App
- BIO3160269 Ltr to all operating plants & CP holders forwarding clarification of TMT Action Plan Item III A I 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be net EISEINUT.D O Division of Licensing. 81/02/10 12pp
- 810226036B Forwards application for amend to License DPR-39. Proposed thange designed to meet intent of model Tech Specs Definition of model Tech Spec 1 2 & clarification of 3 0 9 co-bined into single definition of aperable BAYKE. J P Power Authority of the State of New York B1/02/20 32c 97770 116
- --8102260970 Application for amend to License DPR-59 Proposed changes to facility Tech Specs Include Table of Contents & Sections
  1 0 & 3 9 New Sections 3 0 & 4 0 proposed
  BAYNE.J P Power Authority of the State of New York. 81/02/20
  1p 07770 119
- --9102260572 Replacement pages to proposed Tech Specs 1. O through 1.2 for sefety limits % 3.0 through 3.5e limiting conditions for operation e. Power Authority of the State of New York 81/02/20 13pp 07773 120
- --8102260575 "Bafety Evaluation of Definition of Term Operable" • Power Authority of the State of New York. B1/02/20 2pp 07770 135
- --8102260551 "GE BWR Reactor Load Line Analysis for James A Fitzpatrick Nuclear Power Plant " 9 General Electric Co. NEDO-24243 80/02/28 45pp. 07972:186
- --BI02260555 "GE BWR Load time Limit Analyss for James A Fitzpetrick Nuclear Power Plant Cycle 4, ' Suppl 1 \* General Electric Co NEDO-24243 81 80/07/31 14pp. 07972 240
- 9103020376 Forwards application to amend License DPR-59.correcting typographical error in Tech Specs Table 4.6-1.ltem 1.6 re inservice insp of pressure containing welds in vessel panetrations. Amend fee enci BAYNE. J P Fower Authority of the State of New York. 81/02/20.2pp. 07783 065.

- --BI03020383 Application to amend License DPR-59 correcting typographic error in Tech Spec Table 4 6-1. Item i 6 re inservice iner of pressure containing welds in vessel penetrations 34YNE. J P Power Authority of the State of New York 81/02/20 16 07/83.047
- --gi03020391 Proposed Tech Spec Table 4 6-1. Item 1 6, correcting typographical error in insevice Insp of pressure containing welds in vessel penetrations Bafety evaluation senci.

  \* Power Authority of the State of New York 81/02/20 Spp
- BIO3250024 Ltr to all power reactor liconsees & license applicants Fe MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing iow flow controller EISE/HUT.O Q Division of Licensing BI/02/20 Opp
- BIO3230030 Ltr to all licensess of operating nuclear power plants & applicants for OLs (except St Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blockout event & promptly implement emergency procedures. EISENHUT.D O Division of Licensing BI/02/23 3pp
- Bio3170225 Ltr to all DWR licenses (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class I & 2 pressure boundary piping, safe ends & fitting mati per guidelines of encl Revision 1 to HUREO-0313 Model Tech Specs only encl EISERHUT.D.O Division of Licensing 81/02/26 3pp.
- --Bi03170266 Model Tech Specs Pages 3/4 0-2-3/4 0-3-3/4 4-7 & 3/4 4-B r surveillance requirements for ASME Code Class 1.2 & 3 components & RCB operational lestage limiting conditions for operation & surveillance requirements # General Electric Co B1/02/26 4pp
- 8103030696 Requests Commission 810113 order be notified to allow extension of deadline to complete Mark [ long-term program nods by B20630 t permit deviation from App A to NNREG-0661.

  Extension necessary due to delays in procurement & analysis 8AYUE. J P Power Authority of the State of New York 81/02/27 300
- 8103180003 Forwards Amend 51 to License DPR-59 & notice of issuance & availability.

  IPPOLITO, T.A. Operating Reactors Branch 2 81/03/02. 3pp.
  07943-311
- --DIO3180004 Arend 51 to License DPR-59, adding requirement to raintain & implement safeguards contingency plan within 30 days of Commission approval IPPOLITO, T.A. Operating Reactors Branch 2 B1/03/02. 2pp 07943-314
- --5103180006 Notice of issuance & availability of Amend 51 to Licenso PPR-59 IPPOLITO, T A Operating Reactors Branch 2 B1/03/02. 2pp 07943.316
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ quelification of safety-related electrical equipment.

  EJSENHUT, D 9 Division of Licensing. 81/03/10. App.
- 8103130536 Forwards application to emand CL & Tech Spec changes or corresposure.

  BAYNEY P Power Authority of the State of New York. 81/03/11.
  - DAYNE, J.P. Power Authority of the State of New York. B1/03/11. 2pp. 07911:277.
- --B103130548 Application for amend to OL to extend max average planar linear heat generation rate limits for use during current operating cycle, per IE Info Notice 80-04. BAYNE, J. P. Power Authority of the State of New York. B1/03/11. ip. 07911-279
- --8103130560 Proposed Tech Spec changes no core exposure, affecting Figures 3 5-1 & 3.5-2 Bafety evaluation of changes encl. e. Power Authority of the State of New York B1/03/09. 9pp. 07911:280
- 8103270095 Summary of 810304 meeting u/Mark I owners group & GE in Bathesda. MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NAREO-0661 Slide presentation & list of attendess and! ORIMES. C. I. Licensing Branch 3 81/03/16 5pp.
- 8103310011 Forwards Amend 52 to License DPR-59, safety evaluation & notice of issuance & availability IPPOLITO, T.A. Operating Reactors Branch 2. 81/03/18. 2pp. 08079, 139.

- Q Inspection reports. IE Sulletins & correspondence
- B103050284 Forwards IE Inst Rept 50-333/80-22 on 801201-05 No noncompliance noted MARTIN-M O. Region 1. Philadelphia, Safeguards Branch B1/01/05 200 07825 351
- --BIO3050291 IE Insp Rept 50-333/80-22 on 801201-05 No noncompliance noted Major areas inspected security plans security program audit & security organization Details uithheld (ref 100FR2 790)

  BAILEY, R J , SMITH C. Region 1, Philadelphia, Office of the Director DEVLIN.J M Region 1, Philadelphia, Safeguards Branch. 84/01/01. Lp 07825 353
- Bi03050792 Forwards IE Insp Rept 50-333/80-19 on 801020.21 & 24 No noncompliance noted BRUFINER. E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch Bi/01/08 2pp 07828 i3i
- --8103050797 IE insp Rept 50-333/80-19 on 801020.21 & 24 No noncompliance noted Major areas inspected GA program changes audits & litensee action on previous insp findings NAPUDA.Q Region 1. Philadelphia, Office of the Director. GREENMAN.E. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 81/01/06 3pp 07928 133
- 8103050746 Act receipt of 810119 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30°333/80-03 SMITH-0 H. Region i. Philadelphia. Fuel Facility & Materials Bafety Brench. B1/01/300 18 078/89 058
- --8103050752 Responds to NRC 801222 ltr re violations noted in IE Insp. Rept 50-333/80-03 Corrective actions policy statement on respiratory usage issued Accoptability of supplied breathing air verified per Reg Guide 8 15.
  PASTERNAK.R. J. Power Authority of the State of New York 81/01/19. 2pp. 07828 059
- --8103050755 Forwards IE Insp Rept 50-333/80-03 on 800311-14 & notice of violation SMITH-0 N Region 1. Philadelphia, Fuel Facility & Haterials Safety Branch 80/12/22 2pp 07828.061
- --8103050798 Notice of violation from insp on 800311-14
   Region 1. Philadelphia. Office of the Director 80/12/16. 19
  07828 063.
- --B103050762 IE Insp Rept 50-333/80-03 on B0031j-14.Noncompliance noted. failure to ensure breathing air of acceptable quality & quentity & failure to have written respiratory usage policy statement
  NIMITA.R.L. Region i. Philadelphia. Office of the Director KKAPP.P. J. Region i. Philadelphia. Fuel Facility & Materials
  Sefety Brench B0/12/16 9pp. 07828:064.
- 8103100203 Responds to IE Bulletin B0-17-Suppl 4. "Failure of Control Rads to Insert During Screm at BHR" Portions of continuous monitoring sys described in OE documentation were removed from sys & replaced by components from different vendor PASTERNAM, R. J. Power Authority of the State of New York. 81/02/02.3pp. 07865-330
- 8103040228 Forwards IF Info Natice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events in Accordance W/10CFR30, 72, " No written response required.

  ORIER. B H. Region 1, Philadelphia, Diffice of the Director B1/02/12. 1p. 07813:195
- 8103230250 Ack receipt of 810122 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-15.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. BI/02/12 ip. 07975.083

- --8103230295 Notice of violation App B.from insg on 800830-1024 Par withheld (ref 10CFR2 790) • Region 1. Philadelphia. Office of the Director 80/12/10
- --8103230310 IE Insp Rept 50-333/80-15 on 800830-1024 Noncompliance noted failure to rept event correctly to follow health physics procedures 5 to control access to vital area SAUMACA.W., LINVILLE.J. CHUNO.J. Region 1, Philadelphia, []99: of the Director 80/12/10 15pp 07975 094
- B103030278 Forwards Suppl 5 to IE Hulletin B0-17. "Failure of Contra Rods to Insert During Scram at BMR." No written response required GRIER:B H. Region 1. Philadelphia, Office of the Director B102/13 1a 07790-322
- B103270793 Forwards IE Mgt Meeting Rept 50-333/81-03 on 810129 No noncompliance noted Facility performance evaluation also encl GRIER.B H Region I. Philadelphia. Office of the Director B1002/20 2cp 08034 107
- --Bi03270793 IE Mgt Meeting Rept 50-33781-03 on Bi0129 Areas discurresults of NRC board convened to evaluate licensee performance from Dsc 1979-Nov 1980 per systematic assessment program
  BAUMACK. H H , LINVILLE, J C , DDEMFLEIN, L T , Region 1, Philadelphia, Office of the Director B1/02/13 7pg. 08034 10
- B103270809 Ack receipt of B10213 itr informing NRC of steps taken to correct violations noted in IE Waste Packaging Insp Rept 50-33780-24 (1500003480-21). Item of noncompliance cited in B10115 ltr will be withdrawn BMITH.O H Region i. Philadelphia. Fuel Facility & Materials Baft Branch B1/02/20 ip 08034 119
- --Bi03270Bi5 Responds to NRC Bi0115 ltr re violations noted in IE Ha Packaging Insp Rept 30-333/80-24 (13000034/80-21) Corrective actions obtaining photographic records of each waste shipment showing vehicle tractor & trailer numbers. PABIERIAKR R J Power Authority of the State of New York 81/02/13 3pp. 08034 120
- --8103270021 Forwards 1E Waste Packaging Insp Rept 50-333/80-24 (13000039/80-21) on 801106 % notice of violation SMITH.O.H Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. 81/01/15 2pp. 08034 123
- --8103270826 Notice of violation from inep on B01106.

   Region 1. Philadelphia, Office of the Director. B0/12/02. I
  08034 123.
- --B103270832 IE Waste Pactaging Insp Rept 50-333/80-24 (15000034/80-on B01106 Noncompliance noted: one stipment of radioactive matl arrived at burisl site u/o prescribed placard on front of tractor or front of trajler.

  HACARTHUR. TC Region 1, Philadelphia, Office of the Director POTIER. J. P. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/12/02 4pp. 08034:126
- 8103200178 Forwards IE Info Notice B1-04, "Cracking in Main Steam Lines." No response required. ORIER.8.H. Region 1. Philadelphia, Office of the Director. B1/02/27. 1p 07972.022
- 8103200231 Forwards IE Circular 81-03, "Inoperable Seismic Monitorin Instrumentation." No written response required GRIER B.H. Region I. Philadelphia. Office of the Director. 81/03/02. 1p. 07972:069.

- 8103230069 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Shubbers.' w/corrected Pages 3 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements GRIER B H. Region 1. Philadelphia. Office of the Director B1/03/04 1p
- BIO32002B3 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breater" No response required SRIER.B H Region 1. Philadelphia. Office of the Director B1/03/11 12 07969 022
- 8:03230552 Forwards evaluation. "Inservice Insp.5-Yr Review." per Tech 5:ec requirement BAYNE.J P Power Authority of the State of New York 81/03/18 1a
- 07979 303
- --810323055B Rept 1. "Insprvice Insp.5-Yr Review"
  LDIER.G . SANCIC.D . GURRENTING.A V Pauer Authority of the State
  of New York 81/02/11 16pp 07979 306
- p periodic operating reports & related correspondence
- 8103350311 Forwards "Effluent Release & Waste Disposal Gemiannual Rept. J.1-Dec 1989 " PASTERNAX.R J Power Authority of the State of New York 81/02/18 in 97827 142
- --8103050315 'Effluent Release & Waste Disposal Semiannus! Rept.
  Jul-Dec 1980 '
   Power Authority of the State of New York 81/02/18 84pp
- B103130383 Forwards monthly operating rept for Feb 1981. PASTERNAK.R J. Power Authority of the State of New York - 81/03/06 is 07911-156
- --8103130397 Honthly operating rept for Feb 1901 ZUFELT.E. Power Authority of the Blate of New York B1/03/06 Bop 0.7911 157
- 3 Reportable occurrences. LERs & related correspondence
- 8103110555 Forwards LER 81-018/03L-0 PASTERNAK, R J Power Authority of the State of New York. 81/03/06 In 07875 329
- --8103110557 LER B1-018/03L-0 on B10209, steam line high flow switches 02-0915-116A & 1163 were found outside Tech Spec Probably caused by instrument drift Buitches calibr CHLOS.W V Power Authority of the State of New York B1/03/06 ip. 07879 330
- BIO3160726 Forwards LER BO-0B3/01x-1 PASTERNAK.R J Power Authority of the State of New York. 81/03/09 10 07914 115
- --8103160729 LER 80-083/01x-1 on 801118 average power range monitor channel D was inoperable & channels B or F bypassed against Tech Spec Caused by crosswiring low power range monitor datectors 44-37B & 44-37C Wiring corrected.

  CHILDS.W V Power Authority of the State of New York B1/03/09. 4pp 0.7914 116
- 8103160739 Forwards LER 81-010/03X-1 PASTERNAN.R J. Power Authority of the State of New York 81/03/09. 19 07914 135
- --8103150742 LER Bi-010/03x-1.on 910117.HPCI sys did not automatically operate at rated speed upon receipt of auto start signal following reactor scram & isolation. Caused by reactor water level shrink Speed & discharge pressure increased.

  CHLOS.U. Power Authority of the State of New York. 81/03/09. 1p 07914 134
- 0103160743 Forwards LER 81-019/03L-0
  PASTERMAK.R J Power Authority of the State of New York B1/03/09
  19 07914 137
- --Bi03160744 LER 81-019/03L-0: on Bi0210. during normal operation, reactor water conductivity exceeded Tech Bpec 3 6 C 4 limits. Caused by addition of caustic to condensate storage tanks due to gersonnel error Two condensate storage tanks cleaned. CHILDS.M.V. Power Authority of the State of New York. B1/03/09. 1p 07914-138

PASTERNAK, R. J. Power Authority of the State of New York 81/03/09
1p. 07925 148

--B103170651 LER 81-020/031-0 pp. B10213, during goreal operation, PPCI

8103170646 Forwards (ER 81-020/03L-0

- --Bi03170651 LER 81-020/03L=0 on Bi0213, during normal operation. FPCI controller indicated possible controller failure Sys declared inoperable Caused by failure of two transistors in amplifier Controller replaced & returned to svc CHILDS. W. Power Authority of the State of New York B1/03/09 to 0.7925 to
- 8103240441 Forwards LER 81-022/034-0 PASTERHAR, J. Power Authority of the State of New York 81/03/19 (p. 07984 310)
- --8103240447 LER 81-022/03.-0 on 810220.review revealed torus water lev recorders had not been included in callbr program per 800123 Tech Specs change Caused by personnel error Recorders checked & callbr with 2e performed once each six months CMLDS.W V Power Authority of the State of New York 81/03/19 10 07784 311
- 8103240596 Forwards LER 81-021/03u-0 PASTERNAX.R J Power Authority of the State of New York 81/03/19 16 07982 361
- --8103240603 LER 81-021/03:-0 on 810219, core spray pipe break switch 14-DPIS-43A found set above Tech Spec limit Caused by instrument drift Eurovillance increased to daily, guide valve changed to more conservative set point & training conducted CHILDS.W V Power Authority of the State of New York 81/03/19 Ip 07982 362
- 8103310664 Forwards LER 81-023/03L-0 PASTERNAK.R J Power Authority of the State of New York 81/03/27. 1a 08061 049
- --8i03310669 LER 8i-023/03L-0 on 8i0229, reactor water level instrument 02-3-LIS-10IC found set below allowable limits & on 8i0302 instrument found above allowable limits Cause for both failures believed to be broken switch lock Lock repaired CHILDS.W V. Power Authority of the State of New York. 8i/03/27 in 08061 090

#### V Operator Examinations

- BIO3190496 Forwards revised BIO10B response to NUREO-0737, Items 1 A 1 I 3 & II B.4, re-shift technical advisor & training for mitigating core damage, respectively
  BAYIE.J P Power Authority of the State of New York BI/03/13
  Ann 07963 180
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT I

  F. Security, medical, emergency & fire protection plane
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addition or safe shutdown capability for compliance w/B03119 firs protection rule ETSENHUT.D 0 Division of Licensing 81/02/20 13pp.
- 8103310338 Ltr to all licenses of operating plants & holders of CPs forwarding NUREO-0696, "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements M/o encl EISEEMULD. O. Division of Licensing. 81/03/05 App.
- 8103170066 Releases public version of emergency plan. FELTON.J M Division of Rules and Records 81/03/10. ip. 07928.033.
- --Bi03170071 Forwards public version of emergency plan. Consists of State of OH emergency response plan. Columbiana County. OH & Hancock County. W draft emergency response plans.

  DUN44.C. N Duquesne Light Co Bi/01/30 2pp 07928.034
- --Bi0317007B Public version of emergency plan. Consists of State of OH emergency response plan. Columbiana County, OH & Hancock County, WV draft amorgency response plans.

  « Ouqueine Light Co. B1/01/30. 600pp. 0792B-036.
- Bio3i60049 Releases public version of revised implementing procedures for emergency plan FELTON-J M. Division of Rules and Records. Bi/O3/11. Ip. O7BO& 001.

- of PA disaster operations plan. State of WV radiological
- B103240408 Requests, per 10CFR50 12, extension of specified schedule 103440404 requests, per 100FRD0 12-extension of specified sci dates of ne21, enacted fire protection regulations in 100FR50 4B Extension not detricental to health & safety No urgent considerations condate use of Asp R requirements DUINN-C N Duquesne Light Co 81/03/18 5pp 07990 179
- BiO3240448 Informs of inability to provide available redundant source of meteorological data accessible during calibr periods by BiO401 Other NUREG-C654 milestones will be met Necessary dundant sensors & recorders ready in third quarter 1981 DUNN.C N Puqueene Light Co 81/03/18 2co 07982 259
- 8103240520 Submits plans & schedules for Bections III-9.III-J & III-D of App R to fire protection requirements
  DUING N Duqueme Light Co 81/03/18 2pp 07981-328
- 1103260365 Forwards 810318 request for exemption from App R&IOCFR50 48 schedule requirements re fire protection per 10CFR90 12(a)
  DUNN-C.N Ducuesne Linkt Co. 81/03/18 is 08037 262
- AINTENDED BECAUSE that encl emergency planning info be claced in LPDR W/> 8103160037 SGUDER. J L Division of Rules and Records 81/03/24 1s 08040 234
- Signocited Requests that encl emergency planning into be placed in LPDR. H/o 8103190455 SOUDER, J. L. Division of Rules and Records. 81/03/24 1p 08040 236
- Giordaillo Requests that encl ecerospic planning into be placed in LPDR W/a 8103160053 SOUDER. J L Division of Rules and Records 81/03/24. 1p 08040 244
- RIGGD70009 Requests that encl emergency planning info be placed in LPDR W/o 8103170071 SOUDER, J. L. Division of Rules and Records B1/03/24. 1g. 08047:090

#### P Operating license stage documents & correspondence

- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREQ-0612 Forwards NRC position re interim actions & request for addl info FISENHULD O Division of Licensina 80/12/22 30cm
- 8101150319 Discusses follows study re degradation of internal appurtenances in LMR piping during normal plant operation & potential effects when degraded appurtenances are subj to accident loads. Recommends broad review of recurrent problems BROWN, E. J Director's Office 80/12/24 400.
- 8102270565 Notification of contract execution, Mod 2 to "Environ Manitoring Program W/Commonwealth of PA. " Contractor. Commonwealth of PA MAISDEN, L. Research Contracts Branch FIN B-5111. B1/01/07. 10.
- --8102270590 Mod 2. adding TLD monitoring around facilities & increasing amount of contract to "Environ Monitoring Program W/ Cormonwealth of PA." GERUSKY-T.M Pennsylvania, State of. FIN 8-5111. 81/01/07. 4pp

A103300160 Ltr to all operating PWR licensees requesting info on IUUJUOIGU Ltr to all operating PHR licensees requesting info auxiliary feeduater sys setsoic design Forwards request for addl info list of actions requested of licensees w/o setsmically qualified sys & results of NRC aalkdowns. EISENHUT, D.O. Division of Licensina B1/00/10 120-

\* Operating Reactors Branch 1 B1/02/07 1900

asticfu NEC requirements. W/exception

8103040252 Forwards Amend 38 to License DPR-66 & notice of issuance & 

07585 (0)

- --BI03040260 Amend 38 to License DPR-66 including requirement that guard training & qualification plan be fully implemented within 60 days & all security personnel qualified within 2 VARGA.S A Operating Reactors Branch | 81/02/11 2pp 07813 294
- --BI03040270 Notice of issuance & availability of Amend 38 to License 000-14 Operating Reactors Branch L. 01/02/11. 3pp DIN DO 07813 296
- minananana Formards Arend 39 to License DPR-66, safety evaluation & notice of issuance & availability
  VAROA.S.A Operating Reactors Branch 1 81/02/11 2pp 07815 190
- -- R103040291 Amend 39 to License DPR-66, adding License Conditions 2 C (7), 2 C (8) & 2 C (9) & revising Tech Specs to incorporate TMI-2 lessons learned category A items VARGA, 8 A 91/02/11 20nn Operating Reacture Branch 1 07815 192
- --8103040303 Safety evaluation supporting Amond 39 to License Office of Nuclear Reactor Regulation, Director. 81/02/11 4pp 07819 212
- --Bi03040311 Notice of issuance & availability of Amend 39 to License VARGA,R A. Operating Reactors Branch 1 81/02/11 07815 216
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A L 2 re upgrade of general support facilities Requests confirmation within 45 days that implementation dates will be met. EISENHUT, D.O. Division of Licensing, 81/02/18 12pp.
- Bi03250024 Ltr to all power reactor licensees & license applicants re MUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licenses may submit analysis to justify use of existing low flow controller. EISENHUT. D.Q. Division of Licensing. 81/02/20 Spp.
- B103030841 Informs that licensee agreed to actions re resetting of main feedwater & bypass valves after feedwater isolation eignal. Control circuitry revised to prevent valves from returning to pretrip position on resetting EBF signal. DUNN. C. Duquesne Light Co. B1/02/23. 1p 07795: 172.
- 8103090095 Requests composition & qualifications of new onests safety & offsite review committees within 30 days. B1/02/23. 2pp. 07852.129 VARGA, S. A. Operating Reactors Branch 1

# DOCKETED ITEMS

- 6103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie-Units 1 & 2) Requests util review to determine capability to mitigate station blackout event 3 promptly implement emergency procedures EISEIRMULD 0 Division of Licensing 81/02/29 Spp
- 8103230813 Oenerit Etr 81-06 to all CP holders & OL applicants re ICCFR:0 71(e). 'Periodic Updating of FSARs.' effective 800722 Info re FSAR logal status.fornat & content encl EISE(HAJI.D. 2 Division of Licensing 81/02/26 10pp
- BIO3C10abl "Evaluation of Operation of Beaver Valley Power Station. Unit i J/One Loop Isolated." technical evaluation rept LYDLR E BOBO Idaho. Inc FIN A-6267 BIO3040661 BI/02/28 Ibsp 97816 001
- 8103120447 Forwards corrected fech Bpecs Page D 3/4 0-1 to Amend 36 to Litense DPR-66 VARSALS A Deciating Reactors Branch 1 81/03/02 lp D7905 142
- --3103120450 Corrected Tech Specs Page B 3/4 0-1 to Amend 36 to License DPR-66 • Operating Reactors Branch 1 B1/03/02. 2pp 07905:143
- 3103120061 Forwards Amend 40 to License DMR-65, safety evaluation & ratice of issuance % availability VARQALS A Operating Reactors Branch I B1/03/03. 3pp 07900 224
- --810312006B Amend 40 to License DPR-66, revising Tech Books to reflect installation of undervoltage relays as protection against systalined undervoltage condition VAR3A.S A Operating Reactors Branch 1 81/03/03 11pp 07900
- --8103120072 Safety evaluation supporting Amend 40 to License DPR-66

   Office of Nuclear Reactor Regulation. Director 81/03/03 Spp
  0790/238
- --8103120076 Notice of Issuance & availability of Amend AO to License PR-66 VAR9A.B A Operating Reactors Branch | BI/03/03 2pp 07900 246
- 810331CB04 Ltr to all licensees of operating plants, applicants for CLs tholders of CPs forwarding SECY-B1-119 re info horossary to establish environ qualification of safety-related slectrical equipment EISENHUI.D G Division of Licensing B1/03/10. App
- 8103170147 Application to amend App A Tech Specs to provide redundancy in decay heat removal capability in all modes of operation Proposed change includes mod for water level in refueling cavity Requests change be handled as emergency DMALC N Duquesne Light Co. 81703/13 3pp 07928:294.
- ~-8103170151 Proposed App A Tech Specs re decay heat removal capability \* Duquesne Light Co 81/03/13 17pp 07925 297
- 8103170196 Revision 1 to application for Amend 45 to License DPR-66.
  Perising App A Tech Spec 6 5 2 2 re Offsite Review
  Consittee membership
  DUANIC N Dequesne Light Co 81/03/13 3pp 07739:087
- -8103170162 Proposed revisions to App A Tech Bpec 6 5.2.2 re Offsite Review Committee membership. Prof qualifications enci. 4 Duquesne Light Co. 01703713. 3pp. 07939.092
- B103170577 Application for Amend 5B to License DPR-66 Proposed Tach Specs change would permit deviation of 16 eteps between rod demand 4 rod position indicators Info withheld (ref 10CFR2.790). Results available in Central Files only. DURN.C.N Duquesno Light Co B1/03/13 3pp 07930.232
- --8103170592 Proposed changes to Tech Specs 3 1 3 & 4 1 3 for moveble control assemblies

  \* Duquesne Light Co 81/03/13 4pp 07930.235
- --8103170589 Forwards Westinghouse application for withholding proprietary info (ref 10CFR2.790) re analytical results of impact of increased rod misalignment on peaking factors. DUNN.C N Duquesne Light Co. 81/03/13. ip. 07930.239.
- -- 8103170593 Forwards affidavit requesting that analytical results of

- 8103230491 Forwards supplemental test data re performance of RHR p at facility Proposed Tech Specs Change 60 adequately reflects intent of ASME Code re pump performance SIEBER-J D Duquesne Light to 81/03/14 2pp 07979 333
- 81032470622 Canfirms 810314 authoritation to amend License DPR-66. changing Teck Specs to provide redundancy in decay heat removal capability & revising surveillance requirement for RHR pumps
  NOVAN.T M Assistant Director for Operating Reactors 81/03/16
- 8103240194 Application for Arend 39 to License DPR-66, changing App Tech Specs to ensure redundancy of auxiliary feedcator flow during normal & accident conditions Class III fee enci EUNIL (\*\*) Duryusane Light Co 81/03/20 2pp 07990:130
- --B103240200 Proposed changes to Tech Spec 3 7 1 2 to ensure redund of auxiliary feedwater flow during normal & accident conditions

   Dequese Light Co. 81/03/20, 2pp. 07990 132
- 8103240694 Forwards 1980 rept of facility changes, tests & experiment per 100FR50 59 requirement DUNA, C N Duquesne Light Co 81/03/20. 21pp 08041 087
- 8103300286 Forwards proposed Tech Spec 4 4 1 3 1 re 010313 applicat for Amend 60 to License DPR-66 CUNN.C N Drugsene Light Co 81/03/24 1p 08095 104
- --B103300289 Proposed Tech Spec 4 4 1 3 1 re RC5 surveillance requirements • Duguesne Light Co 81/03/24 1p. 08095.109
- 8103300302 Forwards response to NRC 810129 ltr re N-1 loop operation for facility Actions re reactor protection sys will be completed w/reactor subcritical in Mode 3.prior to operation u/one loop out of svc DUNN-C N Duquesne Light Co 81/03/24 Spp. 08055 121
- G Inspection reports. IE Bulletins & correspondence
- 8103090060 Forwards supplemental response to IE Bulletin BO-24. Item 2e & 2c.re prevention of damage due to water lealage inside containment Lists measures taken to ensure that all abnormal water accumulation would be detected DURN. C. N. Duquesne Light Co. 81/01/19 App. 07852.160
- U103050337 Ack receipt of 810107 ltr informing NRC of steps taken torrect violations noted in IE Insp Rept 50-334/80-28
  BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 81/01/22 ip 07826-062
- --8103050343 Responds to NRC 801212 itr re violations noted in 16 I Rept 50-334/80-28 Corrective actions emphasized that requirements of station administrative procedures & maint manual must be fallowed.
  DURNIC N. Buqueane Light Co. 81/01/07 2pp. 07826:063
- --8103050350 Forwards IE Insp Rept 50-334/80-28 on 801014-17 & notiviolation
  BRUNKR. E. J. Region i, Philadalphia, Reactor Operations Nuclea
  Bupport Branch 80/12/12 2pp. 07825-065
- --8103090355 Notice of violation from insp on 801014-17.

   Region 1. Philadelphia. Office of the Director 80/12/09.
  07826-047
- --8103050365 IE insç Rept 50-334/80-28 on 801014-17.Noncompliance r failure to note procedure revisions per administrative procedures in area of startup testing of new/redified sys BETTENHAUBEN.L. Region 1. Philadelphia. Office of the Director CAPHTON.O L. Region 1. Philadelphia. Reactor Operations Nuclea Support Branch. 80/12/09 7pp 07826:068
- 8103250170 Responds to util 801231 & 810112 ltrs re stetus of IE Bullstin 79-018 Confirms util commitment to seal limit suitches in May-June nonrefueling outage Requests advice by 810301 re schedule change & design development. GRIER.8 H Region 1. Philadelphia. Office of the Director. 81/01/26. 2pp 07996 076.
- B103030376 Forwards IE Mgt Meeting Rept 50-334/80-31 on B01219.No nancompliance noted

- DUNN.C N Diquesne Light Co 81/01/12 2pp 07846 019
- 8103050277 Act receipt of 910120 ltr informing NRC of steps taken to correct violetions noted in IE Imap Rept 50-334/80-20 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 81/02/02 1; 07596 001
- --8103050282 Responds to NAC 801208 ltr re violations noted in IE Insp Rept 50-334/80-20 Corrective actions withheld (ref 10CFR2 7901
- DUNIT, C N Duquesne Light Co 81/01/20 2pp 07825 337
  8103100178 Responds to IE Builetin 80-11. "Mesonry Wall Design " Walls
- identified as unable to meet acceptance criteria will be re-evaluated to determine effect of failure on safety-related sys Rept on results will be prepared by 810223.

  DUNNIC N Duquesne Light Co 81/02/02 2pp. 07893 187.
- 3103230228 Forwards response to Suppl 3 of IE Bulletin 79-018. "Environ Ovalification of Class IE Equipment" & updates 801231 response to bulletin includes qualification info for NUREG-0737 equipment & equipment re coid shutdown. DUNN.C N Buquesne Light Co 81/02/02 30pp. 07978 320.
- 8103040202 Forwards IE Info Notice 81-03. "Checklist for Licenseed Making Notifications of Significant Events In Accordance W/10CF800 22." No written response required ORIER.8 H. Region 1. Philadelphia, Office of the Director. 81/02/12. 10. 07813 129.
- B103200171 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines " No response required CRIER.8 H Region 1. Philadelphia. Office of the Director B1/02/27 ip. 07972 014
- 8103200167 Forwards IE Circuler 81-03, "Inoperable Selemic Monitoring Instrumentation" No written response required ORIER.B.H. Region I. Philadelphia, Office of the Director. 81/03/02 1p. 07972-012
- 8103200102 Forwards revised IE Bulletin Bi-Ol. "Surveillance of Mechanical Snubters." w/corrected Pages 5 & 6 Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements.

  GRIER.B H. Region 1. Philadelphia. Office of the Director.

  B1/03/04. 1p. 07969 084.
- 8103200141 Forwards 1E Info Notice 81-05. "Failure of ITE Model X-500 Circuit Breater." No response required. Office of the Director 81/09/11. 1p. 07968:277
- 8103260876 Requests change to inservice insp program for spray heat suchanger sys integrity to meet ABME Code criteria re freon tests conducted at facility VARQALS A Operating Reactors Branch 1. 81/03/12 20p. 08040:209
- B103310211 Requests authorization to use Code Case N-210 W/conditions specified in Reg Guide 1, 147 in inservice insp program. Also requests exemption from requirement to maintain test pressure for 4-h prior to examinations.

  DUNN C.N. Duquesne Light Co. 81/03/26. 3op. 08061:021.
- R Pariodic operating reports & related correspondence
- B103050599 Forwards "NPDES Discharge Monitoring Rept. Jan 1981." MODRE, 9. W. Duquesne Light Co. 81/02/29. 2pp. 07826: 241.

--BIO3030722 "Personnel Whole Body Ergosures for CY78 " CAREY, J. J. Duquesne Light Co. 81/02/25 ip 07826 233

CAPEY. J J Duquesne Light Co 81/02/25 in 07826:232

- --BIO3050730 "Personnel Whole Body Exposures for CY79 "
  CAREY. J. Duguesna Light Co. 81/02/20 ip 07826 234
- --B103050736 "Personnel Whole Body Esposures for CY80 "
  CAREY. J. Puguesne Light Co. B1/02/25 1p. 07826 235
- BIO3100978 Forwards "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1980 " DUNN.C N Duquesne Light Co 81/03/04 ip 07868 046
- --Bi03100581 Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1980 .

   Duqueine Light Co 81/03/04 70pp 07888.047
- 8103310235 Forwards "1980 Annual Environ Rept.Nonradiological " DUNN.C N Duquesne Light Co 81/03/27 ip 08059 330
- --8103310239 1980 Annual Environ Rept Normadiological." \* Puguesne Light Co 81/03/27 167pp 08039 331.
- S Reportable occurrences. LERs & related correspondence
- 8103050669 PNO-1-81-026. on 810219. 2-inch RCS valve inside containment found leaking Cause not stated. Plant was shut down to repetr test. Velve isolated & packing leakings reduced Repair will be attempted after partial cooldown
  BECKMANN.D. KEIMIG.R. GREENMAN.E. Region 1. Philadelphia. Office of the Director. 81/02/20 2pp 070279 237
- 8103020395 RO Bi-014/01P on 810221.during startup preparations.weld there RC-11 nipple penetrated RCS boundary found leaking Action plan being determined Plant is in Mode 5 & is being detained to midspan in RCS loops to allow for repair WERLING, J A Duquesne Light Co. 81/02/23 3pp. 07585.001
- B103100584 Forwards LER 81-013/03L-0. MERLING J. A Duquesne Light Co 81/03/02 2pp 07862: 332
- --8103100585 LER 81-015/02L-0 on 810204.RC8 loop 1 low flow annunciator alarmed intermittantly Flow channel 414 declared inoperable & bistable tripped Caused by leaking diaphragm Diaphragm replaced LACEY.W 8 Ducuesne Light Co. 81/03/02 2pp 07862:334
- 8103100987 Forwards LER 81-016/03L-0 MERLING J. A. Duquesne Light Co. 81/03/02 2pp. 07862:336.
- ~~8103100589 LER 81-016/03L-O on 810207 packing leak found in steam trap isolation valve. Caused by valve stam packing failure. Packing rings added.
  LACEV. H 9 Duquesne Light Co 81/03/02. 2pp. 07862:338.
- 8103170598 Forwards updated LER 80-094/99x-1.
  MERLING J A Duguesne Light Co. 81/03/02 2nn 07930:091.
- --BI03170517 Updated LER 80-094/99X-1 on 801117 during normal startup operations steam line low pressure bistable began to intermittently trip & reset. Caused by supervisor error. Responsible personnel repriranded & reinstructed. LACEY.W. S. Duquesne Light Co. 81/03/02 2pp 07930:093.

- 8103120476 RD 81-017/01P on 810305.RH4 low flow alarm actuated w/low running current on pump 1 B during reactor shutdown at 160 F & atmospheric pressure Cause not stated Sys vented & reactor coolant piping refulled to approx 65% MERLING.J A Doquesne Light Co 81/03/06 2pp
- 8103130599 Forwards LER's 81-017/03L-0 & 81-018/03L-0
  LERLING J A Duguesne Light Co 81/03/06 2pp 07913 189
- --E103130606 LER Bi-017/03.-0 on Bi0207, analog rod position indicator channels H2 & 88 & associated rods were declared inoperable when indications exceeded Tech Spec Caused by non-linearity in Indicator callibr curves Tech Spec mod proposed LACEY. W. S. Dogwesne Light Co. Bi/03/06 2pp. 07913 187
- --B103150611 LER BI-018/03u-0 on 910208, analog red position indicator channels H2.PB.F10 % K10 exceeded Tech Specs Caused by loss of indicator accuracy in calibr curves region Tech Spec mod proposed LACEY.W S Duayesne Light Co. B1/03/06 200 07913 187
- B103170405 Forwards LER 81-014/017-0 WERLTNO.J A Duguesne Light Co 81/03/09 2pp 07930, 134
- --B193170599 LER 81-014/017-0 on 810221.uhile preparing for plant startup.celd leak occurred in RCS Cause of weld failure is unknown New procedure was implemented & instrument line relocated.Followup rept will be provided LACEY.W S Duquesne Light Co 81/03/09 2pp 07930 136
- 8:03260474 Forwards LERs 81-021/031.-0 & 81-022/031.-0 WERLING. J. A. Puquesne Light Co. B1/03/12 ... 2pp
- --8103260486 LER 81-021/09L-0.on 810210, safety injection accumulator 18. (SI-TK-18) low level alarm tounded Caused by chemist leaving valve open following sampling 8 tank draining down Velve shut tacev. U 5 Duzuesne Light Co. 81/03/12 2pp
- --8193260691 LER 81-022/03L-0 on 810211.control room chloring detector 1018 was tripped upon discovering that electrolyte was not dripping Cause not stated Flow orifice cleaned & wick replaced Investigation underway LACEY.U. 8 Duquesne Light Co 81/03/12 2pp
- 8103260697 Forwards LER 81-020/03L-0 WERLING, J. A. Duquesne Light Co. 81/03/12 2pp. 08035-328
- --B103260707 LER B1-020/03L-0 on B10209, renote control room multipoint recorder temp channels declared inoperable Caused by accidental repositioning of local test switch midway through gassous waste discharge Switch returned to normal position. LACEY.W 5 Duquesne Light Co 81/03/12 2pp 08035-330
- DOCKET 50-935 ST LUCIE PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- BiO3i80264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position 5 request for add1 info re safe shutdown capability for compliance w/B01117 fire protection rule
  EISEN-MUT-D.Q Division of Licensing 81/02/20. 13pp.
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0596. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements (I/o encl. EISRIHUT, D.O. Division of Licensing. 81/03/05. App
- 9103160963 Forwards review of util 810102 greegency plan for fecility. Emergency response exercise must be conducted w/state & local govt agencies to test integrated capability of emergency preparedness plans CLARM.R.A. Deerating Reactors Branch 3 81/03/09. 23pp 07915-163
- B103260602 Requests exemption from 10CFR50 48 & App R to 10CFR50 schedule dates for compliance w/fire protection requirements per 10CFR50, 12(a) & 10CFR50 48(c)(6) 48 and 48 and
- H. General correspondence
- BitO0030900 Requests reviews of guard training & qualification plan be sent to Assistant Secretary. Nept of Veteran & Community Affairs. Tallahassee. FL.
  EUMRE, J. G. Florida, State of 81/02/20 lp. 07795. 217.

- 8103180649 Requests corrents & views on encl util itr re licensin schedule CHILES.L Berete 81/03/10 in 07983 170
- J. Insurance & findemnity information
- 8103060424 Forwards Endorsement 4 to MAELU Binder X8-59 FIELDER, J. Marsh & McLennan. Inc., M & M Nuclear Consultants, In Div. 81/01/27, 2no. 07837-327
- 0103110651 Forwards Endorsement 5 to MAELU Dinder XB-59 FIELDER. J. Harsh & McLennan. Inc. . It & M Nuclear Consultants. In Div 01/03/04 2pp 0/872 200
- P Operating dicense stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants of OLs & holders of CPs recontral of heavy loads Requests review per guidelines in NUMEO-0612 Forwards NRC position reinterim actions & request for add1 (nfa EISECHUT.D 9 Division of Licensing 80/12/22 30np
- B101190319 Discussos followup study re degradation of internal appurtenances in LkR piping during normal plant operation & potential effects when degraded appurtenances are subj to accident loads Recommends broad review of recurrent problems BROWN.E J Director's Office B0/12/24 4pp
- 8103190387 Ltr to all licenses of operating plants & applicants CLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737 EISENRUT.D 0 Division of Licensing 81/01/19. App
- 8103120014 Ltr to all licenses of operating plants.CP holders & applicants.except Indian Point 2 & 3.2ion 1 & 2 & TMI-1. forwarding inadvertently unitted pages from NRC 801222 request for additing or control of heavy loads EISENHUT.D 0 Division of Licensing 81/02/03 6pp
- Bio3030091 Informs that util commitments to 791023 interim positicontainment purging 8 venting acceptable & should remain in affect pending completion of long-term review CLARK-R A Operating Reactors Branch 3. 01/02/09. 2pp. 0779
- B103300160 Ltr to all operating PWR licenses requesting info on auxiliary feedwater sys selsmic design Forwards request for addlined, list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns.

  EIBERNUT, D 9 Division of Licensing B1/02/10 13pp.
- BiO3160569 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 12 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met EISENHUT. D O Division of Licensing 81/02/18 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicant NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENNUT. D.Q. Division of Licensing. 81/02/20. 8pp.
- 8103109021 Requests add1 info re differences between 791207 propo inservice testing program & program described in 770916 submittal Spec of changes made re check valve cycling test requested. Program applicable for 10 yrs.commencing 761221 CLARK.R.A Operating Reactors Branch 3. 81/02/23. 2pp. 0786
- 8103120648 Forwards Amend 38 to License DPR-67.safety evaluation of notice of issuence & availability (LARN-R A Operating Reactors Branch 3 81/02/25, 2pp 0790
- --8193120652 Amend 38 to License DPR-67 modifying Tech Specs to in limits on secondary containment bypass leakage & control room outside air intake CLARK.R A. Operating Reactors Branch 3. 81/02/23. 9pp. 02904-300
- --8103120657 Bafety evaluation supporting Amend 38 to License DPR

   Office of Nuclear Reactor Regulation, Director. 81/02/25, 07904 309
- --B103120663 Notice of issuance & evailability of Amend 38 to Lic PPR-67. CLARK,R.A. Operating Reactors Branch 3 81/02/25. 2pp. 07904-311

- 8103250328 Forwards Amend 39 to License DPR=67.ETA.negative declaration & notice of issuance & availability CLARK.R A Decrating Reactors Branch 3 81/03/10 2pp 07995 326
- --BIO3250334 Amend 39 to License DPR-67. deleting monradiological water quality requirements & pertinent license conditions. & adding reporting requirements CLARK.R A Deprating Reactors Branch 3 81/03/10 13pp 07993 328
- --BIG3250339 ElA supporting Amend 39 to License DPR-67.

   Dffice of Nuclear Reactor Regulation, Director 81/03/10 8pp 0.7995 341
- --BIO3250349 Notice of issuance & availability of Amend 39 to License FPR-67 Negative declaration encl CLARK: A Operating Reactors Branch 3 81/03/10 2pp
  - CLARK.R A Operating Reactors Branch 3 81/03/10 2pp 07995 349
- B103310894 Ltr to all licensees of operating plants applicants for 0%s & holders of CPs faruarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISCIMUT. B Q Division of Licensing 81/03/10 dop
- B103240202 Application to amend App B of License BPR-67, changing delay sample location & adding Fresh, leady vegetable location. UHR10.R E Florida Power & Light Co BI/03/12 4pp. 07982.251
- 8103240368 Forwards info re containment sumps & insulation in response to NRC 801107 ltr URRIZER E Florida Power & Light Co 81/03/16 12pg 07990.101
- G. Inspection reports. IE Sulletins & correspondence
- 8103120829 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required. 0'REILLY-J.P. Region 2. Atlanta, Office of the Director. 80/12/16 ip 07906-015
- 8103050417 Forwards IE Insp Rept 50-335/80-36 on 801110-28 No noncompliance noted. LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 81701/29 2pp 07824.316
- --8103050428 IE Insp Rept 50-335/80-36 on 801110-28 No noncompliance noted Major areas inspected followup of previous insp findings & followup of IE bullatins.circulars & info notices

  ELROD.S A Region 2. Atlanta. Office of the Director JULIAN.C A Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/29 106p 07824-318
- B103090732 Forwards 1E Mpt Meeting Repts 50-250/80-31,50-251/80-29, 50-335/80-33 & 30-389/80-14 on 801029 No noncompliance noted D'REILLY, J. P. Region 2: Atlanta, Office of the Director. 81/02/03 200 07848 262
- --8103090766 IE Mgt Meeting Repts 50-230/80-31.50-291/80-29.50-335/80-33 \$ 50-387/80-14 on B01079 to discuss results of evaluation of util regulatory performance. LEWIS.R C. Region 2- Atlanta, Reactor Operations Nuclear Support Branch B1/02/02 21pp. 07848-264.

- 8103040164 Forwards 1E Info Notice 81-03, "Checklist for Licensees Maiing Notifications of Significant Events In Accordance W/100F859 72" No written response required 0°REILLY. J.P. Region 2. Atlanta. Office of the Director 81/02/12
- 8103040773 Advises that util litrs L-79-192 & L-79-153 re IE Bulletin 79-04 were did incorrectly as 790905 Litrs should be did 790805.

  WHATO, RE Florida Power & Light Co B1/02/13 ip 07810 118
- SIGNISOLS Forwards Performance Appraisal Section Insp Rept
- 30-335/80-00 on E01117-21-1201-05 & 08-12 App A summerizing two program weaknesses & soven areas rated average also entl
  STELLO.V Director's Diffice Office of Inspection and Enforcement 11/02/23 600 07907 335
- ---BI03130172 Performance Appraisal Section Insp Rept 50-339/80-04 on B01117-21,1201-05 & 08-12 Major areas inspected licensee mgt control over selected activities Attachment A withhold (ref 10CFR2 790) MARRAY, B. A.VO.W.P. BELANDER, J.L. Performance Appraisal Section B1/01/30 99pp 07907 341
- 8103160\*18 Forwards IE Info Notice 81-04, "Cracking in Main Bleam Lines 'No response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/02/27 19 97914 100
- 8103160663 Forwards 1E Circular 81-03, "Inoperable Beismic Monitoring Instrumentation" No response required 0:REILLY, J P Region 2, Atlanta, Office of the Director. 81/03/02 ip 37914 262
- Biodiff0028 Forwards revised IE Bulletin Bi-Oi. "Burveillance of Mechanical Shubbers." w/corrected Pages 5 & 6 Change in identification of facilities u/CPs to which bulletin is applicable does not affect util requirements. O'REILLY, J.P. Region 2. Atlanta, Office of the Director Bi/O3/04 pp. 07939 153
- 8103160B78 Forwards request for add1 info re util 800B04 updated response to EE Bulletin 80-06. "Engineered Bafety Feature (EBF) Reset Controls "Util must provide description re mode planned for charging purps; installation date & test.

  CLARK, R. A. Operating Reactors Branch 3 81/03/04 3pp. 07915:239
- 8103200271 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required. O'REILLY, J.P. Region 2. Atlanta, Dfrice of the Director. 81/03/11 p. 07969.007
- B103240730 Forwards IE Insp Rept 50-335/81-02 on 810102-30 & notice of violation LEWIS.R.C. Region 2, Atlanta, Office of the Director. 81/03/12. 2ap 07983.326
- --BI03240738 Natice of violation from inep of Bi0102-30

  \* Region 2. Atlante, Office of the Director. Bi/03/12 2pp.
  07983-328

- BIDDIDIO PECTUARDS IE Info Notice BI-05. 'Degraded DC Sys at Palisades No response required DieELLY.' P. Region 2 Atlanta. Uffice of the Director BI/03/13 In 07969 033
- SICRESCOP Ack receipt of 810305 ltv informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/81-01 [EMS-R C Region 2 Atlanta, Office of the Director B1/03/17 to 7/98-017
- -3103250036 Responds to NRC 819213 ltr re violations noted in IE Insp Rept 50-335/81-01 Corrective actions withhold ref 10CFR2 790) HeRIJ R E Fiorida Paper & Light Co 81/03/06 ip 07998 018
- --B100253010 Forwards IE Insp Rept 50-335/B1-01 on B1011B-23 5 notice of violation Notice of violation withheld (ref 10CFR2 790) HELIA. H B Region 2. Atlanta. Bafeguards Branch B1/02/13 2pp 2758 019
- --BI03250016 IE insp Rept 50:339/81-01 on 810118-23 Noncompliance noted failure to conduct performance tosts of intrusion alone sys at 7-day intervals Betails withheld cref 102FR2 7601
  TILLMAILA, HALL, B. Region 2, Atlanta, Office of the Director MCCUPE, D.R. Region 2, Atlanta, Safeguards Branch 81/02/13 259 07998 021
- 9 Periodic operating reports & related correspondence
- 8:03253273 Forwards 'Annual Operating Rept for 1980."

  18-013.6 E Florida Power & Light Co 81/02/27 ip 07992 001
- --e:03250276 'Annual Operating Rept for 1980 " + Fictida Power & Light Co - 01/02/27 - 01pp. 07992:002
- 8103130350 Forwards monthly operating repts for Feb 1981 SCHRIDT A D Florida Power & Light Co 81/03/07 ip 07911:107
- --8103130354 Monthly operating repts for Feb 1981 (MILSON V T florida Power & Light Ca 81/03/07 9pp 07911 108
- $\boldsymbol{\xi}$  Reportable occurrences. LERs  $\boldsymbol{\delta}$  related correspondence
- 8103090530 RD 00-003 on 801202 steam intake area recording thermograph sys reported lost Probably caused by storm surge wave action or corrected fishing Sys replaced on 801210 U-RIO.R E Florida Power & Light Co 80/12/19 3pp. 07849-253
- 810313)351 Forwards LER 81-004/03L-0 SCHMIDT A D Florida Power & Light Co 81/02/25 ip 07911 139
- --8103130366 LER BI--004/03L-O on BIOI26, switch yard oil circuit broaker 038 46 tripped on differential current Probably caused by differential current relay 3reaker closed PACE,P L Florida Power & Light Co BI/02/25 [p. 07911 140
- 8103130585 Forwards LER 81-007/03L-0 SCHHIDT.A D Florida Power & Light Co 81/02/26. Ip 07913 030
- --8103130572 LER 81-007/03C-Q on 810131.80P8 computer drapped off line causing loss of Cambridge electron accelerator pulse counting backup position indication cause software related Corputer placed on line & indication restored PACE.P L Florida Power & Light Co. 81/02/26. 1p. 07913-031
- 8103160753 Forwards LER 81-008/03L-0 SCHMIDT, A D Florida Power & Light Co 81/02/26 ip 07914 133
- --810316075B LER B1-00B/03L-0: on B10202. digital data processing systemped off line resulting in loss of control element assembly pulse counting backup position indication. Caused by software-related problems investigation continuing PACE.P. L. Florida Power & Light Co. B1/02/26. p. 07914-134.
- 8103160712 Forwards LER 81-006/03L-0. SCMMDT.A D Florida Power & Light Co 81/03/02. 1p. 07914:093
- \*\*BIO3160720 LER 81-006/03L-0 on 810129.00 insp showed that visual insp of debris not documented during containment surveillance entries in standing radiation work permits. Caused by lack of signoff space. Attachment will be added 81M\*\*ONS.K. Florida Power & Light Co. 81/03/02. 1p. 07914-094.

- COCKET 50-336 MILLSTONE NUCLEAR POWER STATION. UNIT 2 F Security, medical, energency & fire protection plans
- 8103040192 Requests response to encl comments re Aug 1979 guard training & qualification plan
  CRUTCHFIELD.D Derating Reactors Branch 5 81/01/27 3pp
  07812 287
- BIO3180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for add1 info resafe shutdown capability for compliance w/G01119 fire protection rule
  EISENHUT,D 3 Division of Licensina BI/02/20 13on
- 8103100092 Requests that encl emergency planning info be made public available IV/2 encl SOUBER J L Division of Rules and Records 81/02/27. Ip 07853 173
- B103310338 Ltr to all licensess of operating plants & holders of CPs forwarding hUREG-0696. Functional Criteria for Evergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT.O.G Division of Licensing 81/03/09 6pp
- B103290391 Requests elemptions to App R. fire protection requirements Disputes NRC conclusion that no add1 costs will be incurred through compliance Submits dedicated shutdown systematican costs description & analysis of implementation costs CCOMSIL-U O Northeast Nuclear Energy Co (subs of Northeast Utilities) B1/03/19 29pp 08022-182
- 8103300360 Requests exemption from certain requirements of IOCFR50 AR & IGCFR50.48 re-fire protection program Justification discusses SER open items.omergency lighting & evaluation of alternate & deficated shutdown systems. COURSIL.H. G. Connecticut Yarkee Atomic Pawer Co. COUNSIL.H. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/03/19 29pp. 08059 155
- J Insurance & indomnity information
- B10310043/ Forwards Endorsement 46 to MAELU Policy MF-78.
  FIELDER: J. Marsh & McLennan.inc . M & M Nuclear Consultants, Inc.
  Div 81/03/02 2pp 07869 219.
- 0103100411 Forwards Endorsement 5 to NELIA Binders E8-15 & EB-16. COMMELL, Y. J. Northeast Utilities 81/03/04. 2pp 07865-207
- 8103310493 Forwards Endorsements & to NELIA Binders EB-15 & EB-16 & Endorsement 67 to NELIA Policy NF-173
  SINTSI, J M. Marsh & McLennan, Inc., II & M. Nuclear Consultants, Inc. Div. 81/03/26 App. 08078 355
- 8103310424 Forwards Endorsement 60 to MABLU Policy MF-52. SINISILU H. Marsh & McLennan.Inc.. H & H Nuclear Consultants.Inc Biv. 81/03/27 3pp 08070 293
- P Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensoes of operating plants applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position re-interim actions & request for add! info.

  EISENRUT-D O Division of Licensing. 80/12/22 30pp.
- BIO0390387 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREG-0737.

  EISENHUT.D.O Division of Licensing. 81/01/19. Opp.
- BIO3093063 Responds to 791019 itr re inadvertent safety injection during surveillance testing Response adequately addresses concerns. NRC considers matter resolved.

  CRUICHFIELD D Operating Reactors Branch 5. 81/01/29. 3pp. 07882.197.
- 8103120014 Ltr to all licensees of operating plants.CP holders & DL applicants.except Indian Point 2 & 3.Zion I & 2 & TMI-1, forwarding inadvertently unlitted pages from NRC 801222 request for add1 info re control of heavy loads.

  EISENHUT,D.C Division of Licensing. 81/02/03. App.

```
07808 152
```

8103160669 Ltr to all operating plants & CP holders forwarding tlarification of TRL Action Plan Ite- III A | 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be not FISENHUT.D 0 Division of Licensing 81/02/18 12pp

. , r. ii

- 8103020399 Responds to NRC 810114 ltr requesting auxiliary feedwater pump endurance test & compliance w/requirement to automate steam driven auxiliary feedwater pump Test confirmed pump vibrations did not exceed allowable limits COWESTLAW O Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/02/19 11pp 07785 206
- 8103290024 Ltr to all power reactor licensees & license applicants re NURCO-O&19 criteria Footnote 2 in Table 2 contains error due to lessage testing celetions Licensee may submit analysis to justify use of existing low flow controller EIEEFHUI.D O Division of Licensing 81/02/20 Bpp
- BIO3110217 Forwards request for add1 info on C-E cuner's group submittel on "RCB Asymmetric Loads Evaluation Program." final rept Includes generic & plant-specific requests (RUJCHFIELD. D. Operating Reactors Branch 5 81/02/23 27pp
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie Units | & 2) Requests util review to determine capability to mitigate station blackout event & prototly implement emergency procedures EISENAUT.D 0 Division of Licensing 81/02/25 Spp
- 8:03090211 Provides justification for nin containment pressure used to initiate containment isolation for facility.por NRC 801231 request ro NNRC-0-0737 Present containment isolation setpoint is adequate & no reduction in setpoint is warranted. COUNSIL-N C. FEE.W.F. Northeast Nuclear Energy Co. Isubs of Northeast Utilities) 8:02/227 2pp 07850-347
- 8103260557 Discusses costs for implementation of TMI action plan requirements NRC estimates of required industry resources have been consistently low Corperison of NRC estimate w/ actual costs encl COUNSIL-W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL-W O Connecticut Yankee Atomic Power Co BI/03/02 App 08040 172
- 8103120335 Forwards ECC8 outage rept for facilities for 1980.in response to NUMEO-0737.Item II K 3 17.No sys or Tech Spec rods are required. COUNSIL.H 0. Connecticut Yantee Atomic Power Co. COUNSIL.H 0. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/03/04 IBpp 07901 200
- Bio3i60359 Forwards nonproprietary & proprietary versions of test rept. "Hydraulic Flow Tast of Model C Prototype Fuel Assembly."
  Application & affidavit for withholding enci Proprietary rept withhold (ref. 10CFR2 790)
  CQUNBIL, H. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, H. O. Northeast Utilities B1/03/06 (3pp. 07916-197.
- --B103160264 Nonpreprietary version of "Hydraulic Flow Test of Model C Prototype Fuel Assembly." \* Westinghouse Electric Corp. 81/03/31. 16pp. 07916.170
- 8103310804 Ltr to all licensees of operating plants applicants for CLs 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISE/HUVI.0.9 Division of Licensing. 81/03/10 ópp.

- a Inspection reports. IE Bulletins & correspondence
- 8103020148 Forwards 1E Info Notice BI-Ol. "Possible Failures of GE Type HFA Relays" No response required GRIER.8 H Region 1. Philadelphia. Office of the Director 81/01/16 1p 07785 253
- 8103180304 Forwards IE Insp Repts 50-245/80-24 & 50-336/80-23 on B01109-1231 No noncompliance noted BRUINER, E. J. Region I. Philadelphia. Reactor Operations Nuclear Support, Branch 61/01/28 2pp 07944 225
- --BIO31BJ315 IE Insp Repts SO-245/BO-24 & 50-336/BO-23 on 801109-1231 & noncompliance noted Major areas inspected control rooms & accessible portions of Unit 1 reactor, turbine, radwasts & gas turbine generator SHEDLOSKY, J T Region 1. Philadelphia, Uffice of the Director KEIMIO, R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 81/01/27 Upp 07944 227
- 8103040196 Forwards [E Info Notice 81-03. "Checilist for Licensees Making Notifications of Bignificant Events In Accordance U/10CFR50 72 " No written response required ORIER.8. H. Region 1. Philadelphia. Office of the Oirector 81/02/12 1p 07813 117
- 8103200181 Forwards IE Info Notice 81-04, 'Cracking in Main Stean Lines "No response required CRIER. 8.H. Region 1. Philadelphia. Office of the Director 81/02/27 19 07972 026
- B103200237 Forwards IE Circular B1-03. "Inoperable Beismic Manitoring Instrumentation" No written response required GRIER.B.H. Region 1. Philadelphia. Office of the Director. B1/03/02 1p 07972 073
- 8103200039 Forwards revised IE Dulletin 81-01, 'Surveillance of Mechanical Snubbers,' w/cornected Pages 5 & 6. Change in identification or facilities w/CP to which bulletin is applicable does not affect util requirements GRIER.B H. Region 1. Philadelphia. Office of the Director 81/03/04 ip 07968 IGB
- 8103200184 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required ORIER.B.H. Region 1. Philadelphia. Office of the Director 81/93/11 1p 07968 310
- R Pariodic operating reports & related correspondence
- B103030904 Forwards "Semi-Annual Radioactive Effluents Release Rept. Jul-Dec 1980" per format of Reg Oulde 1.21 & requirements of Reg Oulde 10 1.

  COUNBILL N 9 Northeast Nuclear Energy Ca (sub= of Northeast Utilities) B1/02/27. 1p. 07794.206.
- --8103030909 "Scmi-Annual Radioactive Effluents Release Rept.Jul-Dec 1980 "
  • Northeast Nuclear Energy Co (subs. of Northeast Utilities). 81/02/27 112pp 07794 207.
- 8103050673 Forwards "Millstone Nuclear Power Station Units 1 & 2, Annua Rest. 1990 "
- --Bi03050676 "Millstone Nuclear Power Station Units 1 & 2. Annual Rept. 1980 "

   Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
  Bi/02/27 3Bpp 07829-302

MRDCZKA-E. J. Northeast Utilities, 81/02/27, 1p. 07829:301

- --8103170594 Kenthly operating rept for Feb 1981 FIM.ETT. 9 H. Northeast Utilities 81/03/03 6pp 07935 343
- 8:03310476 Forwards corrected Reg Quide 1 16 repts for "Annual Coerating Rept. 1980." originally submitted on 810227 PROCEMALE J Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/03/26 Ip. 08CB1 208
- --B103310462 Corrected Reg Guide I I6 repts for "Annual Operating Rept. 1980." originally submitted on B10227 - Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/03/06 2pp 08081.209
- s Reportable occurrences. LERs & related correspondence
- 8103050512 Forwards LER 81-007/03L-0 MRCZKA-E J Northeast Nuclear Energy Co (subs of Nurtheast Utilities) 81/02/24. 1p 07829 125
- --8103050616 LER 81-007/03L-0 on 810127 diesel generator 12U oil cooler found leaking svc water Caused by corroded sacrificial finc ancde Zinc inspected & replaced & maint insp of fince increased from monthly to weekly.

   Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/32/24 % p. 07827 126
- 810305060B Forwards LER 81-009/03L-0 MRCZMA-E J Northeast Nuclear Energy Co (subs. of Northeast Mailtires B1/02/27 1p 07829 118
- --8103050610 LER 81-009/03.-0 on B10204 plant computer malfunctioned resulting in inoperability of pulse counting position indication sys Caused by circuit card Pailure in 1801 process controller Card replaced & computer restarted s Northeast Nuclear Energy Co (subs of Northeast Utilities) B1/02/27. 1a 070829.119
- 8103100505 Forwards LER 81-008/91T-0 PROCEMALE J. Northeast Nuclear Energy Co. (aubs. of Northeast Utilities) 81/02/27 Ip. 07862 332.
- --8163100510 LER 81-008/01T-0 on B10213, determined spring can type hanger installed inproperly, resulting in overstressed sucket welded joint Coused by incorrect design Hanger removed & pipe isoletes & depressurized Design to be corrected REBETAR, J. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) B1/02/27, ip 07862 303.
- COLKET 50-338 MORTH ANNA POHER STATION. UNIT 1

  F Security. medical, emergency & fire protection plans
- 8101070168 Releases public varsion of util emergency plan.including Cortonwealth of VA. Drange County. Caroline County & Henover County ratiological emergency response plans FELTOW. J M Division of Rules and Records 80/12/03 ip 07405-071
- --8101220198 Forwards public version of util revised emergency planincluding Commousalth of VA. Grange County. Caroline County E Hanover County radiological emergency response plans BACH.E.A. Virginie Electric & Power Co. 800/04/29. Opp. 04784 Op.
- --Bi01070185 Public version of Commonwealth of VA.Caroline County smergency operations plan. Anner H. "Radialogical Defense." Caroline County. VA. 80/04/29, 70pp. 94503:001
- ~8101070204 Public version of Commonwealth of VA.Orange County reficiological emergency response plan.
   Orange County, VA 78/12/31. 61pp 07405:074
- \*\*-8101070210 Public version of Commonwealth of VA.Hanover County radiological emergency response plan. \* Hanover County-VA. 77/05/31. 60pp. 07405:134.
- --Biolo70220 Public version of util radiological emergency response plan 45 amended through Revision 3 5 Virginia Electric & Power Co. 80/06/25 200pp 07405:192

- Bi03040366 Suppls 80(215 response to NUREO-0737 re-emergency greparedness Rept uill not be completed until 810415 Barkup meteorological tower signals at facilities & strip chart recorders at Surry uill not be installed until 810801 SYLVIA.B 9 Virginia Electric & Power Ca 81/02/27. 2pp
- 8103040389 States that emergency plan implementing procedures were submitted on 803722.per NURED-0737.item [II A 2 Procedures are in use 5 support current station emergency plan.
  3AUM-E A. Virginia Electric & Power Co 81/08/27 ip 07820-151

Division of Licensing 81/02/20 13pp.

- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0896. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements. H/o encl ETSENHUT.D O Division of Licensing 81/03/05 App
- O Adjudicatory correspondence

EISENHUT D O

- 8102260162 Memorandum & under approving Unit 1 restart when NRC is satisfied that replacement rotor is properly installed. Ultimate disposition of turbina insplissure awaits results of further studies. BISHOP.C J. Atomic Safety and Licensing Appeal Panel 81/02/23. App. 07770 027
- BiO3110294 Forwards M Hazelton affidavits discussing mode to previous reported IRC analytical rodel of turbine crack growth.
  Recommends that Unjt 1 turbine discs be reinspected at next refueling outage
  TREBY-8 A Hearing Branch 1 81/03/09. 3pp 07889:236.
- --8103110263 Recommendation that Unit 1 turbine discs be reinspected onest refueling outage Effect of actual yield strength should be included in more quantitative way & separate crack growth rates should be used Affidavit enci.

  HAZELTON U.S. Materials Engineering Branch 81/03/09 Spp. 02/08 230
- ~-8103110270 Response to NASLAP 800303 memorandum & order justifying crack growth rate curves in NRC analysts Discusses assurance that Unit I can operate until 801201 W/lou probability of turbine disc rupture. W/tables & charts HAZELTON.U S Materials Engineering Branch. 80/03/24. 14pp. 07803-244
- BIO3110492 Ack receipt of BIO309 ltm ABLAB does not directly respond to questions posed by nonparty re-order term blade failure on Page A of BIO223 memorandum Order should have stated, disk failure.

  BIBHUP.C. J. Atomic Bafety and Licensing Appeal Panel. 81/03/09.
  10. 07871-359.
- --8103119457 Requests explanation of sentence on blade failure in ABL/ 810223 memorandum & order. POLLARD, R.D. Union of Concerned Scientists. 81/03/05 2pp. 07871-340
- H General correspondence
- 8103250181 Informs that 116 spent fuel assemblies are stored in facility spent fuel pool in response to 810211 ltm. Spent fuel pool is located in spent fuel bldg which serves both facilities DENTONIH R. Office of Nuclear Reactor Regulation. Director 81/03/19 6pp 07997.279.
- J Insurance & indemnity information
- 8103060312 Forwards Endorsement 49 to MAELU Policy MF-57.

  MAIRFIELD.K J. Marsh & McLeonan Inc. M & M Nuclear Consultants Inc.

  DIV. 81/01/27 2pp. 07836-332
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs 8 holders of CPe to control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position reinterin actions & request for addl

```
EISENHUT. D.O. Division of Licensino 81/02/10
RIGGLAGASS Lin en all oceratino plants & CP holders forwarding
 clarification of TMI Action Plan Item III A 1 2 re upgrade
```

seismically qualified sys & results of NRC walkdowns

- of emergency support facilities Requests confirmation within 45 days that implementation dates will be net EISENHUT. D.O. Division of Licensing 81/02/18 12pp
- 8[03]60115 Surrary of B10218 meeting w/Anchor/Darling Industries in Bethesda MD re dyna A/Damp mechanical snubber & in place active vorint to dyna Mydamp mechanical shipper & in plac surveillance testing Design of shubber neets inservice insp program requirements Add1 info may be requested. ENGLE.L.B. Operating Reactors Branch 3 81/02/20 16 07921 170
- --8103160127 Paper "Component Support Shubbers-Design. Application & Testing." presented at 600812-15 Pressure Vessels & Piping ence in San Francisco.CA REIFF.D D Division of Reactor Safety Research 80/08/12 11on 07921 186
- RIC3250024 Ltr to all power reactor licensees & license applicants re NUREG-0619 criteria Footnote 2 in Table 2 contains error due to leatage testing deletions Licensee reg submit analysis to justify use of eristing low flow controller. ETSENUT.D 0 Division of Licensing. 81/02/20 Bpp
- 3103230030 Ltr to all licensees of operating nuclear sower plants & applicants for DLs (except St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENIUT. D. G. Division of Licensing BI/02/25. 5pp.
- 8103120159 Surmary of 810219 site visit conducted by ASLAB re replacement of Low Pressure Turbine Rotor 2 w/TMI-2 Low Pressure Turbine Rotor 2 ENGLE.L B Operating Reactors Branch 3 81/02/26, 5pp 07901:352
- 8103040293 Forwards info re auxiliary feedwater automatic initiation & flow indication system 810202 request.

  SYLVIA.B.R. Virginia Electric & Power Co... 81702/27. 10pp.
- B103120023 Notifies of fee required for review of VEP-FRD-36. "Control Rod Reactivity Worth Determination by Rod Swap Technique MILLER, W.O. License Fee Management Branch. 81/03/02 | jp.
- 8103090327 Responds to NRC 810227 request re surveillance of RCS flow
- aplitter plates Ultrasonic testing revealed indications in Loop A splitter plate Addl tests will be performed during maint outage scheduled for Nov 1981.

  SYLVIA.B.R. Virginia Electric & Power Co. B1/03/04. 1p. 07832-064
- 8103160227 Reiterates request for info re turbine missile issue. ALAB-589: In-depth description of turbine disc failureprobability model.disc-fragment exit-energy model & damage probabilities are required NOVAK, T. H Assistant Director for Operating Reactors 81/03/04. 07918 346
- 8103100420 Responds to NUREO-0737. North Anna meets dedicated hydrogen control penetration requirements. Requirements do not apply to Surry Design changes are being developed to add remote operated isolation valves. SYLVIA, B. R. Virginia Electric & Power Co. 81/03/05. 19. 07843 195
- B103110529 Application for amend of Licenses NPF-4 & NPF-7, submitted as proposed Tech Spec changes increasing fuel enrichment limits to 4.1 weight percent of U-235 Approval requested by B10501. FERQUEON, J. H Virginia Electric & Power Co 81/03/06 07878: 145

ENGLE.L B. Operating Reactors Branch 3 81/03/09. 2pp 07912 134 8103230328 Notification of 810320 meeting w/utils.EPR! & Westinghouse in Bethesda.MD to discuss & review block valve testing.

8103130616 Notification of 810312 meeting w/util in Bethesda.MD for licenses atable rent on rultistructure amplified response

spectra analysis & required mods

- Anenda encl FNOLE, 3 Operating Reactors Branch 3 81/03/10 300 07973 021
- 8103310804 Ltr to all licensees of operating plants, applicants for Ols & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical ecus enant
- 8103160602 Application to amend License NPF-4, changing App A Tech Spec Table 3 7-4 to reflect rulti-structure amplified response spertrum reanalusis Changes delete four southers & add one Class [1] fee encl

EISENBUT, D.O. Division of Licensing. 81/03/10 App.

- FERGUSGN. J. H. Virginia Electric & Power Co. 81/03/12. 3pp. 07915 202
- --Bi03i60506 Proposed Tech Spec Table 3 7-4.adding Snubber UFPD-H-600 deleting Snubbers WFPD-H98-232-233 & 234 & WFPD-H-223 9 Virginia Electric & Power Co. 81/03/12 4pp 077919-209
- 8103290392 Forwards safety evaluation supporting use of low pressure rotors until next refueling outage & turbine disc reinspection Evaluation includes 810212 turbing rotor inso data & Westinghouse calculations CLARK, R. A. Operating Reactors Branch 3 81/03/13 200 08022 161
- --8103250357 Bafety evaluation supporting use of low pressure rotors until next refueling outage & reinspection of turbine discs
   Office of Nuclear Reactor Regulation. Director 81/03/13 Ip
- 08022 143 8103240240 Forwards proposed Tech Specs changes to suppl 810313 application to amend License NP4-4 re replacement of
- snubbers WFPB-HSS-219, 220 & 221 & BI-HSS-100A-B w/rigid SUPPORTS FERQUEON, J. H. Virginia Electric & Power Co. 81/03/16 2pp. 07990.328
- --8103240247 Proposed Tech Specs changes to Table 3 7-4 rs safety-rela hudraulic southers Virginia Electric & Power Co. 81/03/16. 200. 07990:330
- 8103300549 Forwards Amends 24 & 5 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & availability.

Operating Reactors Branch 3 - 81/03/18, - 2pp. - 08058.097

CLARK, R. A

- --8103300554 Amends 24 & 5 to Licenses NPF-4 & NPF-7, respectively. revising Tech Specs to require at least one charging pump be operable when one unit is in Modes 5 & 6 & other unit is in
- Modes 1, 2, 3 & 4 CLARK, R. A. Operating Reactors Branch J. 81/03/18, 14pp. 0805B-099
- ~~8103300557 Safety evaluation supporting Amends 24 & 5 to Licenses NPF-4 & NPF-7, respectively. Office of Nuclear Reactor Regulation, Director. 81/03/18. 2pp 08058, 113
- --B103300560 Notice of issuance & availability of Amends 24 & 5 to Litebase NPF-4 & NPF-7, respectively. CLARK, R. A. Operating Reactors Branch 3 81/03/18. 2pp 08058.115.

- to incorporate STS re inservice surveillance requirements for snubbers, per NAC BOILPO request Delay due to updating snubber listing Application will be submitted by B10420 SYLVIA.B R Virginia Electric & Pauer Co. 81/03/19 Lp. 07976: 353
- 8103270526 Provides status re-multi-structuro ARB reanalysis in response to 801107 request Preliminary reanalysis & design of support hods for reneining piping outside containment will be completed by 810931 SYLVIA, 8 R Virginia Electric & Power Co 81/03/20 App. 19946 207
- BIC3330805 Forwards Amends 23 & 6 to Licenses NPF-4 & NPF-7, respectively & matice of issuance & availability CLARK, R A Operating Meactors Branch 3 B1/03/20 3pp 08058 058
- --8103360509 Amends 29 % 6 to Licenses NPF-4 & NPF-7, respectively, including requirement to maintain guard training & qualification plan to be fully implemented within 60 days of Commission approval CLARA.R A Cperating Reactors Branch 3 81/03/20 4pp. 08058 061
- --B103305914 Notice of issuance & availability of Amends 25 & 6 to Licenses RPF-4 & NPF-7, respectively CLARX R A Operating Reactors Branch 3 81/03/20 2pp DR058 0A5
- 8103330546 Forwards Amend 26 to License NPF-4, safety evaluation & natice of issuance & availability CLARK, R.A. Operating Reactors & Franch 3 81/03/24 2cc 08058-083
- --0193300552 Arend 26 to License NPF-4, changing Tech Spec Table 3 7-4 by removing, adding & relocating certain plant snubbers CLARK.R A Operating Reactors Branch 3 81/03/24 11pp 08058 085
- --8103360559 Bafety evaluation supporting Amend 26 to License NPF-4

   Office of Nuclear Reactor Regulation. Director 81/03/24 3pp
  08038 072
- --BIOCHOOSSY Notice of issuance & availability of Amend 25 to License (RF-4, CLAPK.R A. Operating Reactors Branch 4 RI/03/24 Zpp OROSB 095
- 0103310565 Forwards info re effects of extended fuel burnups on actional source terms & locking in response to NRC serbal request supplementing 800315 & 810306 litra reproposed Tach Spec changes to increase contichment level SYLVIA. 3. R. Virginia Electric & Power Co. 81/03/26 (3pp c8075-217.
- G Inspection reports, IE Bulletins & correspondence
- 8:00290656 Forwards Revision 2 to response to 1E Bulletin 79-010. 'Environ Qualification of Class 1E Equipment" & MRC 000029 ofder for nod of license SYLVIA. 3 R Virginia Electric & Power Go 80/12/01. Sipp 07997 026
- 8102050264 Forwards IE Insp Repts 90-338/80-39 & 80-339/80-37 on 831023-24 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. Bi/01/19 28p. 07625-267
- --8103050272 IE Inso Repts 90-339/80-37 & 50-339/80-37 on 801023-24 No noncompliance noted Major areas inspected containment integrated leak rate testing & surveillance activity on pipe supports & restraint sys UCH/80U.A.H. Region 2. Atlanta. Office of the Director. KELL.0GO.P.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/18 Spp. 07628:271
- 8103040795 Forwards IE Insp Rept 50-339/80-40 on 801203-05. No roncompliance noted MARPHY.C.E. Region 2: Atlanta: Reactor Construction & Engineering Bupport Branch. 81/01/30. 2pp 07812 159
- --B103040B01 IE insp Rept 50-338/80-40 on 801203-05. No noncompliance noted. Major areas inspected inservice insp program revieu. 3A plans & procedure revieu eCONOMOS. N. Region 2. Atlanta. Office of the Director HERDT. A. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 8E/01/20 4pp 07812-161

- Repts 80-338/80-39 & 80-339/80-33 Corrective actions fire watch poster at affected doors & necessary repairs made No proprietary info 8YLVIA, U.A. Virginia Electric & Power Co 81/02/02. 4pp 07801-99
- --8103120961 Forwards IE Insp Repts 90-338/80-35 & 90-339/80-33 on B31001-21 & notice of violation LEMB.R C Region 2. Atlanta. Reactor Operations Nuclear Suppor Branch B1/01/08 200 07901 299
- --6103120965 Natice of violation from insp on 801001-31.

   Region 2, Atlanta, Diffice of the Director 81/01/08 ip
- ---8103120971 IE Imap Repts 90-338/80-35 & 50-339/80-33 on 801001-31.

  Woncompliance noted failure to complete action statement requirements of Tech Spec 3 7.15

  KERSTER.E H. TATIERSALL.A P. KELLBOO.P J. Region 2. Atlanta, Office of the Director 81/01/98. 17pp 07901 302.
- B103020177 Forwards IE Circular B1-02. "Performance of NRC-Licensed Individuals While on Outy." No written response required O'REILLY-J P. Region 2. Atlanta, Office of the Director B1/02/01 p. 07789 291
- 8103040149 Forwards IE Info Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events in Accordance W/10CFR30-72" No written response required D'REILLY. J. P. Region 2. Atlanta. Office of the Director. B1/02/1; p. 37820-033
- 0103050770 Ack receipt of 010112 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/80-26 & 50-339/80-31 LEGIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 01/02/19 is 07828 153
- --Bi03090776 Supple Bi0112 response to NRC B01212 ltr re violations of in IE insp Repts 90-336/80-26 & 50-339/80-31 Corrective actions identifying technical manuals to be used for specific & poneric safety-related procedures SYLVIA: 3 R Virginia Electric & Power Co 81/02/12 3pp. 07828 114
- 8103310778 Forwards IE Insp Rept 50-308/81-01 on 810119-22 No noncompilance noted MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/23 2pp. 08062 280
- --B103310707 IE Insp Rept 50-338/81-01 on 810117-23. No noncompliance noted Major areas inspected inservice insplactivities & steam turbine rotor low pressure disc cracking ECCHOM98.N Region 2. Atlanta. Office of the Director HERDI.A Region 1. Philadelphia. Reactor Construction & Engineering Buppt Branch 81/02/23 6pp 08062.282.
- 8103040265 Forwards Westinghouse rept "TMI-2 Low Pressure Disc Ultrasonic Insp Rept." Also forwards proprietary version of metl properties rept for Low Pressure L& 2 turbines. Matl properties rept withheld (ref LOCFR2, 790). SYLVIA.8 R Virginia Electric & Power Co. 81/02/27, 2pp. 07809-273
- --8103040274 "TMI-2 Low Pressure Disc Ultresonic Insp Rent "
  \* Westinghouse Electric Corp 01/02/02 2pp 07809:276.
- 8103160713 Forwards IE Info Notice B1-04. "Cracking in Main Bleam Lines." No response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director. 81/02/2' 1p. 07914-089.
- 8103160564 Forwards 16 Circular BI-03. "Inoperable Seismic Monitoring instrumentation" No response required.
  D'REILLY, J. P. Region 2. Atlanta. Office of the Director 81/03/03
- BiOD170067 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Shubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/03/04 ip
- 8103240726 Forward, IE Insp Repts 80-338/81-03 & 80-339/81-02 on 810203-06. No noncompliance noted. LEWIS, R.C. Region 2. Atlanta, Office of the Director. 81/03/10. 2pp 07983.271

- 8103200314 Forwards IE Info Notice 81:06. "Failure of ITE Model N-600 Circuit Breater." No response required O'REILLY.J.P. Region 2. Atlanta. Office of the Diractor. 81/03/11 19 07969 040
- B103231CB3 Forwards add1 info, re response to IE Bulletin 79-02. "Pipe Support Base Plete Designs Using Concrete Espansion Anchor Bolts," per MRC request Base plate anchor bolt load ratio vs stiffness ratio were developed from finite element studies SYLVIA-8 R Virginia Electric & Power Co. B1/03/12 2pp 07976-321
- B103200030 Forwards IE info Notice Bi-05. "Degraded OC Bys at Palisades." No response required. O'REILLY.J P. Region 2. Atlanta. Office of the Director B1/03/13. pp. 07967 074
- B103310278 Forwards stear generator inservice insp preliminary rept.
  Includes results of second inservice eddy current
  elemination of steam generator during current Cycle II-fili
  refueling outage
  gy\_VIA.B R Virginia Electric & Power Co B1/03/26 3pp
- R Periodic operating reports & related correspondence
- BIO3030795 Forwards "Radioactive Effluent Release Rept for North Anna Power Station." 801701-1231 5 amend to 800101-0630 release rept SYLVIA, B. R. Virginia Electric & Power Co. 81/02/27 1p
- --8103030801 "Redioactive Effluent Release Rept for North Anna Power Btation." 800701-1231 Arend to 800101-0630 release rept enci GILBERT. J D . STAFFORD. A H . CARTHRIGHT. W R. Virginia Electric & Power Co 81/01/23 6000p.
- 8103170581 Forwards monthly operating repts for Feb 1981. 8YLVIA-8 R Virginia Electric & Power Co. 81/03/13 1p 07935-333
- --BIO3170586 Monthly operating repts for Fab 1981. ROBERS.L.L. Virginia Electric & Power Co. 81/03/05. 7pp 07933 3734
- S Reportable occurrences. LERs & related correspondence
- B103170445 Notifies of exception to facility NPDES for Feb 1981 Caused by defective flow meter. Flow meter to be repaired. BREHMERM L. Virginia, State of. B1/03/03. 1p
- 8103170439 Forwards LER 81-010/03L-0. CARTWRIGHT.W R Virginia Electric & Power Co 81/03/11. 1p 07939:237.
- --BIO3170444 LER BI-010/O3L-O. on BIO211.w/unit in Mode &.contairment purge & exhaust (solation sys was rendered inoperable when power to MOV-MV-1008.D was lost Caused by fault on high resistance connection Defective perts replaced. CARTHRIGHT.W R. Virginia Electric & Power Co. BI/O3/11 2pp. 07939:258.
- Biod240489 Forwards updated LER 80-087/03X-1.
  CARTMRIGHT W R Virginia Electric & Power Co. 81/03/18, 1p. 07981: 331.

- --Bi0324056i Updated LER 81-007/99x-1: on 810115.plug found missing from tube at row 1. column 12 On 810202.tub more plugs found missing. Caused by box seals One tube was replugged on 810124 Other two tubes replugged on 810303.

  CARTMRIGHT.W R Virginia Electric & Power Co. 81/03/18. 2pp 22202 315.
- 8103260842 Forcards LER B1-013/03L-0 CARTMRIGHT.W R Virginia Electric & Power Co 81/03/18 1p
- --B103260852 LER B1-013/031-0 on B10223.auxiliary bldg statrwell fire door A74-5 at elevation 274 could not close & letch Caused by misellyment between door & frame due to loose door hinges Hinges tack welded to door jamb CARTMRIOHT.W R Virginia Electric & Power Co. 81/03/18 2pp 00074-237
- 8103310952 Forcards LER B1-016/03L-0 CARTICHICHT, W.R. Virginia Electric & Power Co. B1/03/27 1P. OROBL 222
- --8103310597 LER Bi-016/03L-O on 810220 in mode 5.18-month surveillant of dc distribution sec sys found to have exceeded surveillance interval Caused by combination of problems including battery analyser equipment problems CARTHRIGHT.M.R. Virtinia Electric & Power Co. 81/03/27 3pp 08081 223.
- U Congressional/Executive Correspondence
- B103270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process HELORIE. J H Cornissioners. B1/03/12 Spp
- --B103270938 Discusses issue of licensing delays in anticipation of hearing before Bevill Committee In circumstances where no appeal has been taken from ASLAB initial decision. ASLAB will complete review within 40 days ROSENTHAL.A.B. Atomic Bafety and Licensing Appeal Panel. B1/02/18 Spp 0R043.354.
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- Bi01070168 Releases public version of util emergency plan.including Commonwealth of VA. Drange County, Caroline County & Hanover County radiological emergency response plans. FELTON-J M. Division of Rules and Records 80/12/03. ip 07/405 071.
- --BIO122019B Forwards public version of util revised emergency planincluding Commonwealth of VA.Orange County.Caroline County & Namover County radiological emergency response plans BAUM.E.A. Virginia Electric & Power Co. 80/04/29. 2pp 04734:006.
- --Biolo70185 Public version of Commonwealth of VA.Caroline County emergency operations plan.Annex H. "Radiological Defense " \* Caroline County.VA BO/04/29, 70pp. 94903.001
- --Bi01070R04 Public version of Commonwealth of VA.Orange County radiological emergency response plan. • Oftenge County, VA. 78/12/31. 61on. 07405.074.

#### ひひひんし にひ ひ にいり

- --810:070210 Public version of Commonwealth of VA.Hanover County radiological energency response plan \* Hanover County, VA 77/05/31 60pp 07405.134
- --610:070220 Public version of util radiological emergency response plan as amendad through Revision 3 \* Virolnia Electric & Power Co 80/06/29 200pp 07405 192
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NPC position & request for addl info re \*\*afe \*\*shutdown capability for compliance w/801119 fire protection rule EISEL\*\*4/T.D.9 Division of Licensing. 81/02/20 13gp
- B103C40366 Supple B01219 response to NUREG-0737 re emergency preparedness Rept will not be completed until B10419 Backup meteorological tower signals at facilities & strip chart recorders at Surry will not be installed until B10801 SYLVIA.3 R Virginia Electric & Pawer Co B1/02/27 2pp
- O103040385 Btates that emergency plan implementing procedures were submitted on 800722-per AUREO-0737. Item III A 2 Procedures are in use & support current station emergency plan PAUM-E A Virginia Electric & Power Co 81/02/27 1p. 07820 151.
- 810931033B Ltr to all licenses of operating plants & holders of CPs forwarding NUREG-0676. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISEMPUT.0 9 Division of Licensing 81/03/05. 6pp
- Q Adjudicatory correspondence
- B10R260162 Memorandum t order approving Unit 1 restart when NRC is satisfied that replacement rotor is properly installed. Ultimate disposition of turbine insplicate awaits results of further studies. B15H3PRC J. Atomic Safety and Licensing Appeal Panel. B1/02/23 doc. 07770-077
- 8103110254 Forwards W Hazelton affidavits discussing node to previously reported NRC analytical model of turbine crack growth Accommends that Unit 1 turbine discs be reinspected at noxt refueling outage TREBY.8 A Pearing Branch 1 81/03/09 3pp 07888,236
- ---9103110263 Recommendation that Unit 1 turbine discs be reinspected at next refuelling outage Effect of actual yield strength should be included in more quantitative way & separate crack growth rates should be used Affidavit encl HAZELTON, B Materials Engineering Oranch. 81/03/07. 5pp 07883-239
- --8193110270 Response to NASLAP 800303 memorandum & order justifying crack growth rate curves in NRC analysis Discusses assurance that Unit 1 can operate until 801201 m/low probability of turbine disc rupture M/tables & charts. MAZELTOV, M. S. Materials Engineering Branch 80/03/24 tapp 07985 244
- B) 0311 0452 Ack receipt of 810303 ltr. ASLAD does not directly respond to questions posed by numberty re order term blade failure on Page 4 of 810223 menorandum Order should have stated, 'disk failure'' BISHOP, C. J. Atomic Bafety and Licensing Appeal Penel. BI/03/09. IP 07871 359
- --8103410457 Requests explanation of sentence on blade failure in ABLAB R10223 memorandum & order POLLARD, R D. Union of Concerned Ecientists. 81/03/05 2pp 07671:350
- 14 Semeral correspondence
- 8402250181 Informs that 116 spent fuel assemblies are stored in facility spent fuel pool in response to 810211 ltr. Spent fuel pool is located in spent fuel bldg which serves both facilities. DENTOTH, H.R. Office of Nuclear Reactor Regulation, Director. 86703/19. 6pp. 07997-279.
- J. Insurance & indemnity information
- B103360312 Forwards Endorsement 45 to MAELU Policy MF-57.
  HAIRFIELD.N.J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc.
  DIV. 81/01/27 2pp 07836 352

- P Operating license stage documents & correspondence
- Bio3190732 Lins to all licensees of operating plants, applicants for DLs & holders of CPs re-control of heavy loads Requests review per guidelines in INREG-0612 forwards NRC position relintering actions & request for addl info EISECHUT, D. G. Division of Licensing 80/12/22 30pp.
- B103190387 Ltr to all licensees of operating plants & applicants for the & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737 EISENHUT, D.O. Division of Licensing, 81/01/19 600
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.ercept Indian Point 2 & 3.7ion 1 & 2 & THI-1. forwarding inadvertently omitted pages from NRC 801222 raquest for add info re control of heavy loads EISECHUJT.D 9 Division of Licensing 81/02/03 bpp
- B103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys setsmic design Forwards request for additinfo list of actions requested of licensees w/o setsmicelly qualified sys & results of NRC walldowns EISEISHUT D 0. Division of Licensing 81/02/10. 13pp
- 8103140669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 43 days that implementation dates will be met EISERHOT. D O Division of Licensing 81/02/18. 12pp
- 8103160115 Summary of 810218 meeting w/Anchor/Darling Industries in Bethesda-MD re dyna A/Damp mechanical snubber & in place surveillance testing Dasign of snubber meets inservice insp program requirements Add1 info may be requested ENOLE-L. B. Operating Reactors Branch 3 81/02/20 16pp. 07921-170
- --BIO3160127 Paper "Component Support Snubbers-Design Application t Testing." presented at BCO812-15 Pressure Vessels & Piping Conference in San Francisco.CA PEIFF.D D. Division of Reactor Safety Research 80/08/12 11 07921
- 8103290024 Ltr to all power reactor licensees & license applicants PNREO-0619 criteria Footnate 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISEMHUT. D O Division of Licensing 81/02/20 Opp
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUI.D. O. Division of Licensing 81/02/23 3pp.
- 8103120157 Burmary of B10219 eite visit conducted by ASLAB rereplacement of Low Pressure Turbine Rotor 2 w/TM1-2 Low Pressure Turbine Rotor 2 ENGLE:L B. Operating Reactors Branch 3 81/02/26 Spp. 07901:
- B103110214 Forwards request for add1 info re App 8 QA program items Items should be added to 9-list or written justification for not adding items should be submitted within 60 days CLARN-R.A Operating Resctors Branch 4. B1/02/27. Spp. 07884.
- 8103120151 Confirms BiO213 teleon notifying that request for info r structural integrity of pump notiles for low head safety injection sys resolved Pump notiles will not experience loads exceeding worst case loads CLARK.R A Operating Reactors Branch 3 BI/02/27. 2pp 07901:
- B103120023 Notifies of fee required for review of VEP-FRD-36. "Control Rod Reactivity Worth Determination by Rod Swap Technique" MILLER.W.D. License Fee Management Branch B1/03/02. Ip
- BiO3180014 Forwards "Partial Review Equipment Evaluation Rept," by Ofc of Nuclear Reactor Regulation.per B01107 order for mod of OL. Requests affirmation supporting safe operation of plantitaking noted deficiencies into account NDVAN.T.M. Assistant Director for Operating Reactors. B1/03/03. 3pp 07944 003
- --8103180018 "Partial Review, Equipment Evaluation Rept." • Dffice of Nuclear Reactor Regulation, Director, 81/03/03, 33pp. 07944-006.

- 8103160227 Resterates request for info re turbine missile issue. ALAB-597 In-tepth sescription of turbine dist failure-probabilists, model distr-fragment exit-energy model distance probabilisties are required AD/AM.TH Assistant Director for Operating Reactors 81/03/04 3pg 07918 346
- 8103100420 Response to NUREC-0737 North Anna neets dedicated hydrogen control penetration requirements Requirements count apply to Surry. Design changes are being developed to add remote operated itsolation values
  SYLVIA.3 R. Virginia Electric & Power Co. 81/03/05. 1p
- BiODIIO529 Application for arend of Licenses HPF-4 b NPF-7, submitted as proposed Tech Spec changes increasing fuel enrichment limits to 4 1 Leight percent of U-235 Approval requested by 80501 FERGUSZMLUN Unique Electric & Power Co. 81/03/C6. 49F 07078 bis
- --8103110533 Proposed Tech Spec change for Tech Specs 5 3.5 4.5 5 % 5 6 re reactor core.reactor collect sys % fuel storage e Viratria Flectric & Power Co. 81/03/C6 6pp 07878 149
- --8103110538 "Nuclear Design Analysis Rept for New Evel Storage Racks for Surry Nuclear Power Station." prepared under Project 3157 for VEPCO EUC4-P Nuclear Energy Service. Inc. 814C648 80/03/26 28Fp 07878 155
- --GIG3110540 "Criticality Analysis of Spent Fuel Storage Racks for Verto North Anna Unit 1 % 2 " SO2NO, P v NUS Corp NUS-1761 ADD 1 E0/08/31 25pp 07878-183
- 0103130742 Act receipt of 810219 info required for staff audit of util steam & feedvater break analysis Submittel adequate in meeting requirements

  EISENHUT.D 0 Division of Licensing 81/03/06 in 07912 099
- 8103190173 Forwards "North Anna Unit 2 Startup Rept." SYLVIA: 8 R Virginia Electric & Power Co 81/03/10 Ip 08032-271
- --8103190179 "North Anna Unit 2 Startup Rept "
  WHITE, A K. ROTELLA-T & . KUNSITIS T J Virginia Electric & Power
  Co 81/03/06 250pp 08082 272
- B103310894 Ltr to all licensees of operating plants applicants for GLs tholders of CPs forwarding SECY-B1-119 rs info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT D 0 Division of Licensing. B1/03/10 App.
- BIOG200043 Forwards safety evaluation of info re low head safety injection & outside recirculation agray pump operability submitted B011250 Response is acceptable & issue is resolved.

  CLARKAR A Operating Reactors Branch 3 81/03/11 3pp. 07972 180
- --8103200051 Bafety evaluation supporting low read safety injection & autiside recirculation spray pump operability
   Office of Nuclear Reactor Regulation, Director 81/03/il 2pp
  07972 102
- 8103200274 Requests clarification of technical bases of NRC partial review rept identifying potential deficiencies in environ qualification of Class IE equipment.psr 810303 ltr.

  Qualification program appropriate Meeting requested.

  SYLVIA.B.R. Vérginia Electric & Power Co. 81/03/13 3pp.
- B103300549 Forwards Amends 24 & 5 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & evailability CLARK-R A Operating Reactors Branch 3 81/03/18 2pp 08058 097.
- --Bi03300554 Amends 24 & 5 to Licenses NPF-4 & NPF-7, respectively, revising Tech Speck to require at least one charging pump be operable when one unit is in Modes 5 & 6 & other unit is in Modes 1-2-3 & 4.

  CLARK-R A Operating Reacture Branch 3 Bi/03/18. 14pp 080980 099
- --BIO3300557 Safety evaluation supporting Amends 24 & 3 to Licenses NPF-4 & NPF-7, respectively # Office of Nuclear Reactor Regulation, Director. 81/03/18 2pp. 08058:113.

- --9103300540 Notice of issuance & availability of Amenda 24 LS : Licerses r.PF-4 & NPF-7: respectivel, CLAR.R A Operating Reactors Branch 3 81/03/18 2pp cm388 15
- B103230787 Informs of Jelay in submitted of license amend application incorporate SIS re inservice surveillance requirements for snubbers, ser SIC 801120 request Delay due to updating snubber listing Application will be submitted by B10420 SKLVIA-3 R Virginia Electric & Power Co B1/03/19 ip north 253
- BIO3260467 Surmarizes program for compliance w/Heg Quide 1 97.
  Revision 2-in response to Item 2 C 16 of Own conditions Modor replacement of Instrumentation will be completed by June 1933 on first refueling outage SYLVIA.B.R. Virginia Electric & Power Co. 11/03/20 2pc 06037 356
- BIO3300505 Forwards Arends 25 & 6 to Licenses MPF-4 & NPF-7, respectively 5 notice of issuance 5 availability CLARKIR A Operating Reactors Branch 3 BIY33/20 3pp GEGS re-
- --8103350509 Amends 25 & 6 to Licenson NPF-4 & RPF-7, respectivel, including requirement to maintain guard training & qualification gian to be fully implemented within 60 days of Commission approval CLARK.R. A. Operating Reactors Branch 3 811/03/20 4pp 00:35 06:1
- --B103300514 Notice of issuance & availability of Amenda 25 % & t; Licenses NPF-4 & NPF-7, respectively CLARK-R A Operating Reactors Branch 3 81/03/20 2pp CB058 065
- 8103310365 Forwards info to effects of extended fuel burnups th accident source terms & radine epiting, in response to NRC verbal request supplementing 800510 % 810306 Itrs reproposed Tech Spot changes to increase empiriment level SYLVIAB R. Virginia Floctric & Power Co. 81703726 13pp
- Q Inspection reports. IE Bulletins & correspondence
- 8103050264 Forwards 1E linep Repts 90-338/80-39 & 80-339/80-39 on 891023-24-Hb noncompliance noted. (EMIB.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/19 2pp 07825 269
- --BIO3050272 IE then Ropts 50-338/00-39 & 50-339/00-37 on B31023-28 %; noncompliance noted Major areas inspected containment integrated leak rate tooting & surveillance activity on pipa supports & restraint sys JCRNSON, A H. Rogion 2. Atlanta. Office of the Director KELLOGO, P. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. BI/OI/IB Spp. 07883.271
- B103120596 Responds to NRC B10108 ltr re-violations noted in 1E losp Repts 90-338/80-35 % 50-337/80-33 Corrective actions: Fire with posted at affected doors & necessary repairs made Naproprietary info.

  BNLVIA.B.R. Virginia Electric & Power Co. 81/02/02 4pp 07901-2795
- --8103120561 Forwards IE liner Repts 50-336/80-33 & 50-339/80-33 on 801001-21 & notice of violation LEMBS R.C. Region 2. Atlanta. Reactor Operations Nuclear Supplement 81/01/08 2pp 07901 299
- --8103120965 Notice of violation from imap on 801001-31.

  \* Region 2. Atlanta. Office of the Director 81/01/08 IP 07901.301
- ~-8103120571 1E Insp Repts 30-338/80-33 & 50-339/80-33 on 801001-31 Nencompliance noted Pailure to complete action statement requirements of Tech Spec 3.7.15 MEBSTERS H. TATTERSALLA P., KELLOGG, P. J. Region 2. Atlanta. Office of the Director Bi/Oi/OB 17pp. 07701:302.
- 8103020177 Forwards IE Circular B1-02, "Performance of NGC-Licensed Individuals While on Duty " No written response required O'REILLY. J. P. Region 2, Atlanta, Defice of the Director B1/02/09 ip.
- 0103040149 Forwards IE Info Notice 01-03, "Checklist for Licensees Making Notifications of Significant Events In Accordance W/10CFR50, 72, " No written response required 0'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/02/12

- 8103050770 Ack receipt of 810112 ltm informing NRC of steps taken to correct violations noted in IE insp Repts 50-338/80-24 t
- --B103650776 Supple B10112 response to ARC B01212 ltr re violations noted in IE losp Repts 50-339/80-26 & 50-339/80-31 Corrective actions identifying technical manuals to be used for actions lumberlying sections and the section of the 81/02/12 300 37820 114
- 8103160713 Forwards 18 Info Notice 81-04, "Chacking in Main Steam (03160713 Forwards It live motice aloue, "cracking in Main Lines "No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director
- 8103160354 Forwards 16 Circular 81-03. "Inuperable Beismic Monitoring Instrumentation" No response required O'REILLY, J.P. Region 2. Atlanta, Diffice of the Director 81/03/02 10 07916 343
- 8103170057 Forwards revised IE Bulletin Bi-Oi, "Burveillance of 103170057 Forwards reviews in univers the province the mechanical Southers.' witcorrected Pages 5 & 6 Change in sentification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  G-REILLY-J.P. Region 2. Atlanta, Office of the Director. 81/03/04
  17 07937 189
- 9103240726 Forwards IE Trisp Repts 90-338/81-03 & 90-339/81-02 on EBISEN C Region 2. Atlanta. Office of the Director 81/03/10
- --8103240733 |E Insp Ropts 50-338/81-03 & 50-339/81-02 on 810203-06 No noncompliance noted Major areas inspected core performance noncompliance notes instance inspectes the performance by power distribution monitoring
  BURNETI.P I , muRPHY.C E Region 2, Atlanta, Office of the
  Director 81/03/09 8pp 07983 273
- 8103240789 Forwards IE linsp Repts 50-338/80-41 & 50-339/80-38 on 801201-810110 & notice of violation D'REILLY, J P Region 2. Atlanta, Office of the Director. 81/03/10. 2pp 07984 205
- --8103240793 Notice of violation from insp on 801201-810110 \* Region 2. Atlanta, Office of the Director 07984-207
- --8003240803 [E Iner Repts 50-338/80-41 & 50-339/80-38 on 801201-810110 Noncompliance noted failure to trip inoperable instrument within time frame required by Tech Specs WEBSTER, E. H. INTIERGALL, A. P. Region 2. Atlanta, Office of the Nuclear Support Dranch 91/03/06 lipp. 07994:209.
- 8103200314 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required. D'RETLLY, J P Region 2. Atlanta, Office of the Director. 81/03/11
- 8103203030 Forwards IE info Notice 81-05, "Degraded DC Sys at Palisades. No response required O'RELLLY, J. P. Region 2. Atlanta, Office of the Director 81/03/13 1s 07969-094
- R Periodic operating reports & related correspondence
- 8103030795 Forwards "Radioective Effluent Release Rept for North Anna Power Station." 801701-123; & amend to 800101-0630 release SYLVIA, B.R. Virginia Electric & Power Co. 81/02/27. ip
- --Bi0303080i "Redicactive Effluent Release Rept for North Anna Power Station, " 80070j-1231 Amend to 800101-0630 release rapt GILBERT, J. D., STAFFORD, A. H., CARTHRIGHT, W. R. Virginia Electric & Power Co 81/01/23 600pp
- 81031708B1 Forwards monthly operating repts for Feb 1981. SYLVIA.8 R. Virginia Electric & Power Co. 81/03/13 lp 07935: 333.
- --8103170586 Monthly operating repts for Feb 1981. RD0ERB.L.L. Virginia Electric & Power Co. 81/03/05. 7pp.

- S. Reportable occurrences, LERs & related correspondence
- 8163020518 Forwards LER 81-013/03L-0 CARTWRIGHT, W. # Virginia Electric & Power Co 81/02/25 07782 346
- -- 8103020922 LER 81-013/05L-0 on 810126 containment hi & hi-hi pressu channel III annunctator energized Caused by instrument drift traines til amunitator energijes Lauses by Instrument drif-in nomisolated power supply card S/N 5080. Increasing output voltage Card replaced & channel callbr CARTURIONI, W. R. Virginia Electric & Power Co. 81/02/25 200
- 8103170445 Notifies of esteption to facility MPDES for Feb 1981 Caused by defective flow meter flow meter to be repaired BREHMER.M.L. Virginia. State of 81/03/03 1p
- B103100629 Forwards LER 81-017/03L-0 CARTHRIGHT IN R Virginia Electric & Power Co 81/03/05 1p
- --B103103632 LER 21-017/02L-0 on 810205 reaction chamber gas temp indicating controller TIC-5 failed high offscale resulting instructing concrosser, (it->, ratied high offscale resulting in automatic shutdown of recombiner unit, 2-HC-HC-I, on high temp interlock Caused by loose plug connection CARTURIONY, W R Virginia Electric & Power Co 81/03/05 2cp 07862 348
- 8103110461 Forwards LER 81-018/03L-0. CARTURIGHT, W.R. Virginia Electric & Power Co. Bi/03/05 07872 017
- --8103110468 LER 81-018/03L-0. on 810208, train flow path 8 isolated fro refueling chemical addition tent to refueling water storage tank Caused by maint on drain valve leakage due to red CARTUREOHI, M. R. Virginia Electric & Power Co 81/03/05 2pp 07872 018
- 8103170370 Forwards LER 81-023/03L-0 CARTERIGHT. W. R. Virginia Electric & Power Co. Bi/03/11 07935 323.
- --Bi03170574 LER 81-023/03L-0 on 810220 during surveillance test revise data from two previous tests on diesel 2J batteries was found not usable Caused by failure to verify that initial conditions were consistent w/previous tests CARIMRIOHY. H R Virginia Electric & Power Co 81/03/11 2pp 07935 324
- 8103170434 Forwards LER 81-019/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co. 81/03/13 1p 02939 260
- --B103170437 LER 81-019/03L-0 on 810214-at 100% power, auxiliary 1031/043/ LEN BITUFF/OUTTO ON BIOZIA-AT 100X power, AUTILIA feedwater overspeed trip valve tripped twice-rendering feedwater pump inoperable Caused by improper alignment of linkage parts Parts machined & pump returned to svc CARTWRIGHT, W.R. Virginia Electric & Power Co. B1/03/13. B1/03/13 3pp 07939 261
- 8103250481 Forwards LER 81-020/03L-0 CARTHRIGHT W. R. Virginia Electric & Power Co. 81/03/18 07004 217
- --B103250489 (.ER 81-020/03L-0: on B10218, emergency diesel generators 2H 2J were declared inoperable Caused by batteries failing surveillance test Cells replaced. CARTWAIGHT, W.R. Virginia Electric & Power Co. 81/03/18 3pp 07774 218
- B103260755 Forwards LER 81-021/03L-0
  CARTWR10HT, W R Virginia Electric & Power Co B1/03/18 1p. 08036:091.
- --8103260760 LER 81-021/03L-0: on 810217, boron injection tank found to contain boron concentration below Tech Spec limit Caused by leak in check valve in boric acid supply line to blender 2-CH-15%-allowing primary grade water to backflow. CARTWRIGHT, N. R. Virginia Electric & Power Co. 81/03/18 81/03/IB 3eg. 08034 052
- 8103260832 Forwards LER 81-024/03L-0.
  CARTWRIGHT.W.R. Virginia Electric & Power Co. 81/03/18. ip. 08034.233

- --8103260835 LER BI-024/03L-0 on BI0224 quench spray pump & associated values removed from svc Caused by repair of pump leafs Leaks repaired & subsys returned to svc CARIARIGITHER Virginia Electric & Power Co. BI/03/18 20p pages 274.
- 8103310340 Forwards LER 81-026/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 81/03/26 1p
- --9103310578 LER 81-026/03L-0 on B10226 tentainment quench spray subsystrate A taten out of sec to repair leas on filled indicator On following day, train B removed from sec to perform maint & repair leas in fittings & hoses CARTMRIGHT MR Virginia Electric & Power Co. 81/03/26 2pp. 00001 215
- B1033[0570 Forwards LER B1-030/03L-0 CARTURIGHT.W R Virginia Electric & Power Co B1/03/26 1p CB052 272
- --8103310573 LER 81-030/03L-0 on 810316 casing cooling subsys 8 was removed from svc during mode 1-contrary to Tech Spec 3 6 2 2 Caused by need to prevent pressurfication of sys while performing caint on valve 103/48-2010 CARTARIOHIU R Virginia Electric & Power Co. 81/03/26 2cp 08062 273
- 8103310576 Forwards LER 81-027/03L-0 CARTHRIGHT.M R VITGINIA Electric & Power Co 81/03/26 1a 080A2 275
- --BIO3310579 LER BI-027/03...O on BIO228 requirement to determine core asial paper distribution within limits every 8-h was missed when conitaring sys feiled w/o operator incubedge Caused by processor overheating due to inadequate ventilation CARTARIGHT W.R. Virginia Electric 3 Power CO. BI/03/26 2pp. 08042-274
- B103310630 Forwards LER 81-022/03L-0 CARTHRIGHT.W R Virginia Electric & Power Co 81/03/26 Ip ORCA1 039
- --0103310633 LER 01-022/03L-0 on 010310.31-day surveillance interval re updating assal power distribution confitoring sys was surveided by 25% Caused by personnel not upgrading surveillance log CATIMIOHT.W R Virginia Electric & Power Co 81/03/26 2pp 08041 040
- U Congressional/Executive Correspondence
- 8103270110 Response to request for rept on possible add1 improvements to MRC licensing process. Legislation allouing interin operations in advance of hearing completion would reduce dalay in licensing process.

  #EXDRIE.J H Commissioners 81/03/12 5pp.
- --Bl0327093B Discusses issue of licensing delays in anticipation of hearing before Bevill Committee In circumstances where no appeal has been taken from ASLB initial decision. ASLAB will complete review within 60 days.

  RDBENTHALLA B Abomic Sefety and Licensing Appeal Panel B1/02/18 5pp. 08044 354
- DOCKET 50-341 ENRICE FERMI ATOMIC POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- B103199732 Ltrs to all licensess of operating plants applicants for OLs & holders of CPs to control of heavy loads. Requests review per guidelines in NOREO-O612 Forwards NRC position reinterim actions & request for addl info ETEENHUT. O. Division of Licensing 80/12/22. 30pp
- 8103190387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve told shukdown.replacemont parts & NURED-0737.
  EISENHUT.D.O Division of Licensing. 81/01/19. App.
- 8103120014 Ltr to all licensees of operating plants, CP holders & CL applicants except Indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertently onitted pages from NRC B01222 request for add info re control of heavy ladds.

  EISENMUT, D. Q Division of Licensing. B1/02/03 dpp.

- 9103110211 Forwards requests for add; Intelleting the souther swing clearance at specified heatup & cooldown intervals
  TEDESCO.R L Assistant Director for Licensing G1/02/18 Gpt 07885 147
- 8103290024 Ltr to all power reactor licenses & license applicants re MRRG-0617 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENMUT. B G Division of Licensing B1/02/20 Spp.
- B103110225 Ack receipt of B10127 ltr refission product release t surmarites NRC actions on problem NRC rept on state of technology of Iodine release is due in Mar 1901 DIRCKS.W J. Office of the Executive Director for Operations B1/02/25 2pp 07895 183
- --BIO3110240 Expresses support for encl Nuclear Bafety Oversight Condittee BO1221 Ith to President Carter, re research suggesting that judine products may not be released as freely as had been assured in reactor safety studies MCCARTHY, W.J. Detroit Edison Co. 81/01/29 3pp. 07885 185
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 % 2) Requests util review to determine capability to mitigate station blactout evant & promptly implement emergency procedures EISECHUT.D G Division of Licensing 01/02/25 3pp.
- B1030504B3 Updates status of Mort I containment long-term program for facility, re-schedule for submittal of plant-unique analysis Util via alternate NUREO-0661 criteria for assessment of safety relief loads
  TAU3EN.H Detroit Edison Co. 81/02/26 4pp. 07826 103
- B103170225 Ltr to all BkR licensees (except Humboldt Day & LaGrosse)
  requesting review of ASME Code Class 1 & 2 pressure boundary
  ciping-safe ends & fitting rati per guidelines of encl
  Revision 1 to NUREG-0313 Model Tech Specs only encl
  EISENNUT.0 9 Division of Licensing 81/02/26 Jpp
- --8103170266 Model Yech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 6 3/4 4-8 resurveillance requirements for ASME Code Class 1.2 6 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements # General Electric Co. 81/02/26. 4pp.
- B103170655 Ltr to holders of CPs & applicants for QLs (BWRs) requesting review of ASME Class 1.2 & 3 pressure boundary piping, safe and & fitting mail per guidelines of encl Revision 1 to MURGO-0313 fisel Tech Specs only encl.
  EISENHUT.D.O Division of Licensing 01/02/26 3pp
- 8j03230813 Generic Ltr 81-06 to all CP holders & OL applicants re jOCERBO 71(e). "Periodic Updating of FGARs." effective 800722 Info re FSAR legal status fornat & content encl. EISENHVI.D O. Division of Licensing 81/02/26.
- B103230298 Forwards requests for add1 info re environ safety & financial issues for continuing review of OL application. TEDEECO.R L. Assistant Director for Licensing. B1/03/07 26pp 07975-053
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs Libers of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment EIBERHUT, D. D. Division of Licensing 81/03/10 App.
- B103190145 Notification of 810316 meeting w/near-term OL applicants in Setheada-MD re info required to be submitted on environ qualification of electrical equipment prior to site visit & NRC review. BURNELLYS. Licensing Branch 2. 81/03/12. 15pp
- 8103270095 Summary of B10304 meeting w/Mark I owners group & GE in Bethesde.MD re-supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NJREO-0661. Blide presentation & list of attendees onci. GRIMES.C.I. Licensing Branch 3. 81/03/16. Spp.
- B103240434 Concludes that OL issuance will have no effect on cultural resources eligible for or listed in Netl Register of Historic Places
  B108LDM-M M Michigan, State of. B1/03/1B 1p. 07986.310

81/03/13 bps 07966 112

- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREC-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements (No encl EISENHUI, D O Division of Licensing 81/03/05 App
- P. Operating license stage documents & correspondence
- B1D3090108 Forwards organizational charts depicting NRC Region 3 reorganization.effective B10216 MEPPLER. J G. Region 3. Chicago. Office of the Director B1/02/20 2pp 07850 045
- 9 Inspection reports: IE Bulletine & correspondence
- 8103170698 Forwards 1E Investigation Rept 50-341/80-22 on B01015-17, 21-23.1103-07 & notice of violation MEPPLER, J G. Region 3. Chicago. Office of the Director B1/02/05 2pp 07926-309
- -8103170704 Notice of violation from investigation on 801015-17.21-23 & 1103-07 KEPPLER.J G. Region 3. Chicago. Office of the Director 81/02/05 200 07926-311
- --BIO3170710 IE Investigation Rept 50-341/80-22 on BO1019-17.21-23 % i103-07 Manconpliance noted fatture to include part number when documenting welds % fatture to have documented finitallation procedure FOSIGR.UE. SHAPKER.J. NDRELIUB.C.E. Region 3, Chicago Office of the Director BI/08/02 21pp 07926-313
- --Bi03170724 Discusses allegations to const of facility Allegations to be investigated include actions in response to NRC citation, unqualified personnel, set screen in water pump, deviation disposition repts & improper pressures exerted on alleger. FOSTER.JE Pegion 3, Chicago, Office of the Director 80/10/14 35pp 07926 334
- 8103020077 Forwards IE Circular 81-02. "Performance of NRC-Licensed individuals While on Duty " No written response required. KEPPLER, J G Region 3. Chicago, Office of the Director 81/02/09 2pp 07787:313
- 8103120128 Submits revised response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Revises Tables 1-4 re-penetrations containment nozzle to cap weld, process line celd, flued head weld & nozzle ntpple weld HINES.E. Petroit Edison Co. 81/02/12 app. 07900:181.
- B1030302B9 Forwards Suppl 5 to IE Bulletin 80-17, "Failure of Control Rojs to Insert During Scram at BUR." No written response required.

  KEPPLER.J. O Region 3, Chicago, Office of the Director. 81/02/13.
  229 98073 319
- 8103050407 Forwards IE Insp Rept 80-341/80-19 on 801101-30 No noncompilance noted. HEIBHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 81/03/02 2pp 07824:307.
- --BI03050412 IE Insp Rept 50-341/80-19 on 801101-30. No noncompliance noted Major areas inspected licensee action on previous insp findings & IE bulletin & circular followup LITTLE.R.H. & BYRON.P.M. LITTLE.W.S. Region 3. Chicago. Office of the Director 81/01/09 3pp. 07824.309.
- 0103140530 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required KEPPLER.J. O Region 3, Chicago, Office of the Director. 81/03/02 2pp. 07916:327.
- BIO3190364 Responds to IE Builetin 80-23. "Failures of Solemoid Valves Mfg by Valcor Engineering Corp." Unlikely that Valcor solemoid valves are used if one is found valve will be reviewed for mod or replacement HINES.E. Detroit Edison Co. 81/03/03 2pp. 07954:361

- B103200389 Forwards IE Info Notice 81-05. "Failure of TTE Model K-c Circuit Breaker ' No response required KEPPLER.J O Region 3. Chicago, Office of the Director. 81/03/1 200 07972 145
- B103200655 Forwards IE Info Notice B1-05. 'Degraded DC Sys at Palisades' 'No action required PEPPLER.J O Region 3. Chicago. Office of the Director B1/03/1200 07966 143
- 8103200297 Forwards IE Info Notice 81-07, "Potential Problem W/Water-Boluble Purge Dam Matls Used During Inort Gas Welding "No response required. 
  KEPPLER. J G Region 3, Chicago. Office of the Director 81/03/1
- S Reportable occurrences. LERs & related correspondence
- B1030906/2 Interim deficiency rept re-pipe support beam struts.
  Initially reported 801113 Power Piping noted problems in
  overstressing where struts were installed off vertical
  position & subjected to bending morent Final rept by 810627
  HINES.E. Detroit Edison Co 81/03/03 2pp 07844 149
- B103160431 Final deficiency rept re core spray pump motor handling damage.initially reported 790223 GE completed rept on repairs to notor Motor is onsite awaiting installation. HINES.E. Detroit Edison Co. 81/03/05 Ip 07916
- B103160422 Interim deficiency rept me Type CMC micro-switches in control room initially reported on 801203 Testing of switches is continuing Bis defective switches have been replaced Finel rept util be forwarded by B10707.

  HINCS.C. Dotroit Edison Co. 81/03/06 ip 07916:173.
- 8103160482 Interim deficiency rept recut reinforcing bar original reported on 791227 Sargent & Lundy Engineering completed analysis of five most critical slabs One slab appears overstressed Final rept will be forwarded by 810710.

  WELLE D A Detroit Edison Co. 81703710. ip. 07915:015.
- 8103160752 Interim deficiency rept re nonseismic pieces of heating, ventilation & air conditioning duct erected over \$\darkor\ in close proximity to safety-related equipment, initially reported in BO0118 telcon Final rept by 810714.

  WELLB.D A Detroit Edison Co. 81/03/10 2pp. 07914: 145.
- U Congressional/Executive Correspondence
- 8103240091 Forwards fourth monthly status rept to Congress for B10115-0215 Rept discusses actions taken on licensing reviews of new facilities Rept will be amended to include add1 info requested on 810217 KAMMERER, C. Office of Congressional Affairs 81/02/27. 3pp
- B103270110 Responds to request for rept on possible addl improvements NRC licensing process tegislation allowing interimoperations in advance of hearing completion would reduce delay in licensing process
  HENDRIE: J M Commissioners. B1/03/12 Spp. 08043.329.
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergency & fire protection plans
- 8103180264 Ltr to all power reactor licensees u/plants licensed pri to 790101. Forwards NRC position & request for addl info re safe shutdown capability for compliance w/801119 fire protection rule. EISENHATA D 0 Division of Licensing. 81/02/20. 13pp.
- 8103170474 Forwards update to 801204 ltr re-nonfunctional fire barriers. Three-h fire penetrations on encl list were repaired & returned to svc by 810219 YU:01.C.P. Portland General Electric Co. 81/03/04. 3pp. 07939: 244
- 810331033B Ltr to all licensees of operating plants & holders of Cl forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements II/o encl EISCHHUT, D.O. Division of Licensing. 81/03/05. App.

- --8103160042 Public version of implementing procedures for radiclogical emergency plan includes unusual event emergency alert & notification, site > general emergency & command classification.
- + Partland General Electric Co. 81/01/02 390pp 07806 001
- 8103240349 Requests add1 time to revise guard training & qualification plan per NRC 810123 ltr.Revised training & qualification plan & changes resulting from Revisions 4 & 5 of security plan will be submitted by 810591 MITHERS B D Portland General Electric Co 81/03/j8 2pc 02990.325
- B103240514 Advises that fire protection review for plant complete & add1 mods will not significantly enhance safety BRCEML.D U. Portland General Electric Co. 81/03/19 3pp 07984-162.
- H General correspondence
- B103120409 FOIA request for documents re amount of radiation involved in recent water leak at facility TRUMBETTA.R Affiliation Unknown 81/02/19 2pp 07586 001
- 8103090197 Forwards FR notice re relocation of LPDR from Columbia County Courthouse. St Helens to Multmomah County Library, Partiand. GR FELTON, J M Division of Rules and Records. 81/02/18 1p. 07848 342
- -- 8103090202 Notice of relocation of LPER Prom Columbia County Courthduse. St Helens to Multnomeh County Library, Portland, DR. FELTON. J. H. Division of Rules and Records 81/02/18 2pp. 07848-343
- BIG3190492 Requests that all correspondence re-facility be directed to BD Withbrs. KARGELR Portland General Electric Co. 81/03/04 io. 07955-065.
- 8100120405 Responds to FDIA request for documents re amount of radiation involved in recent water leak at facility NRC has no record re reported water leak Shutdown was considered routine maint procedure. No inspleas initiated. FELTON, J.M. Division of Rules and Records. 81/03/10. 1p 07901.218
- 8103250172 Forwards FR correction notice correcting LPDR telephone number in 810225 FR notice FELTON, J.B. Division of Rules and Records. 81/03/16 ip. 07996-060
- --8103250176 Correction notice correcting LPDR telephone number given in 810225 FR notice FELTON-J M Division of Rules and Records B1/03/12 1p. 0796-062
- J. Insurance & Indemnity information
- B103:10376 Forwards Endorsement 38 to HAELU Policy HF-86 WILBON,F R. Portland General Electric Co. 81/03/04 2pp. 07889:194.
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensmes of operating plants, applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NOREO-0412 Forwards NRC position re interim actions & request for add
- 8:03190397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment, Items addressed involve cold shutdown-regiscement parts & NUREQ-0737. EISENHUT, D.O. Division of Licensing 8:/01/19 6pg.

- 8103030417 Forwards Physicians for Social Responsibility r "Evaluation of Design Harards of Airborne Ash & Pyroclas Flow for Trojan Power Plant Site." Requests review to determine if info alters NPC site suitability conclusion F19ErABUT, D.9 Division of Licensing 81/02/09 ip
- 8103300160 Ltr to all operating PWR licensees requesting i auxiliary feedwater sys seismic design Forwards request add1 info. List of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns EISENHUT.D O Division of Licensing 81/02/10 13pp
- 8103050201 Forwards SER suppline implementation of improve auxiliary feedwater sys Proliminary implementation approfor Item 11 E | 1 of TMI task action plan is complete Twingraining open items exist (CAMA, R.A. Operation Reactors Branch 3 81/02/18 6pp
- B103050568 Advises of decision to withdraw License Change 15 to License NPF-1 Tendon degradation has not appeared curing first three surveillance tests, therefore change n warranted UITHERE B D. Portland General Electric Co. B1/02/20 03782-274
- 8103060486 Requests add1 fee remittance to 801024 Tech Spe application D1039.RM License Fee Management Branch 81/02/20 1
- 8103250324 Lir to all power reactor licensees & license ap MUREO-0619 criteria Footnote 2 in Table 2 contains error to leakage testing deletions Licensee may submit analysi justify use of eristing low flow controller EISENH-JT.D O Division of Licensing 81/02/20 8pp
- 8103090702 Advises of fee determinations to preliminary to BD0722 application for license amend Class II & III fees required Remittance requested MILLER.W 0 License Fee Management Branch B1/02/24. 07844:231
- 8103120724 Forwards safety evaluation of E00-EA-5232. "Ade Bitation Electric Distribution Bys Voltages Trojan Nuclea Power Station" CLASK, R. A. Doerating Reactors Branch 3 81/02/24. 200
- --Bi03120731 Safety evaluation of E00-EA-5252, "Adequary of Electric Distribution Gys Voltages, Trojan Nuclear Powe Station"
  # Operating Reactors Branch 3 81/02/24, 3pp. 0790
- 8103240675 Advises of applicability of IAEA safeguards und 39(b) of US/IAEA safeguards agreement Installation infoinitial inventory rept & subsequent accounting repts required US Dept of State telegram encl EISENHUT, D. G. Division of Licensing 81/02/24. 4pp.
- Bio3050790 Forwards Bechtel safety evaluation re acceptable severing tendons in precast panels of control bldg floor slab during mods Certificate of Svc encl. Related correspondence

  BROCH. D. J. Portland General Electric Co. Bi/02/25. 5
  07628.126.
- Bio3230030 Ltr to all licensees of operating nuclear power applicants for OLs (except Bt Lucie-Units 1 & 2) Request util review to determine capability to mitigate station blackout event & promptly implement emergency procedurar EISENHUT, D 0 Division of Licensing 81/02/25. Spp.
- Biogo90594 Informs of completion of survey re rail transpicatis per NUREO-0237. Action Item 3.D. 3.4. "Control Room Habitability Requirements." Redundant amounts detector a sergency procedures to be completed by 830101.

- 8103310604 Ltr to all licensees of operating plants applicants for OLs includes of CPs forwarding SECY-BI-119 to info necessary to establish environ qualification of safety-related electrical equipment arechively 0.0 Division of Licensing 81/03/10 Ann
- 9103170440 Responds to B10127 & 0310 requests for Nostinghouse schematic diagrams for review of engineered safety features for IRC II/a encl LENISCH-J W Portland General Electric Co B1/03/11 lp. 07923-209
- 8163179608 Responds to MRC 791119 ltr re containment purging issue Valves will be qualified.per MRC 790927 guidelines to justify complete permanent agening for containment venting Completion of any resulting mode expected by June 1982 WITHERS B D Portland General Electric Co. 81/03/12 ip
- 8103200248 Forwards License Change Application 71 requesting amend of License HPF-1 WITHERS.B D. Portland General Electric Co. 81/03/16 ip 07988-017
- --8103230254 Application to amend License NPF-1 to incorporate change in Mode 5 shutdown margin requirement HITHERS, B D. Portland General Electric Co. 01/03/16 App. 07948 018
- --8103260264 Tech Spec 3/4 1 for reactivity control sys • Portland General Electric Co 81/03/16 5pp 07968 022
- 8103200551 Forwards License Change Application 72 requesting amend to License NPF-1 WITHERS B D Portland General Electric Co. 81/03/16 lp 07972 076
- --G103200555 Liceuse Change Application 72 requesting amend to Liceuse APF-1, to incorporate containment air lock testing requirements change MITHERS. B D. Portland General Electric Co. 81/03/16. 3pp 07972-077
- --8103200560 Tech Specs 3 6 1 3 5 4 6 1 3 for containment air locks testing requirements change \* Portlen5 General Ejectric Co. 81/03/16 1p. 07972:080.
- 8103270635 Forwards addl fees in support of License Change Applications 63 t 6B in response to NRC 810224 ltr WITHERS. B D Portland General Electric Co 81/03/19. 3ee.
- 8103260572 Responds to NRC 810310 telcon requesting add1 info re License Change Application 70 Updated Table 2 reflecting final Cycle 4 design encl. Prompt approval requested to avoid impacting spring refueling outage 8RCEM..D J Portland General Electric Co 81/03/20. 3pp 08041 115
- 8103270768 Forwards License Change Application 57. Revision 2 requesting amend to License NPF-1 to change Tech Specs re-borated water source. W/o Certificate of Svc WITHERB, 80 Portland General Electric Co 81/03/23 7pp. 08043 195
- --8103270770 Application for amend submitted as License Change 57.
  Revision 2 to License NPF-1 to change Tech Specs re borated outer sources
  MITHERS 8.D. Portland General Electric Co. 81/03/23. Spp.
  08043,196
- ~~8103270773 Revised Tech Specs 3/4 1-15 & 3/4 1-3 re borated water sources.
  - \* Portland Ceneral Electric Co. BI/03/23 App. 08043:201.
- 9 Inspection reports. IE Builetins & correspondence
- 8103100016 Forwards 1E Insp Rept 50-344/80-31 on 801201-31 No noncompliance noted. CREMB.J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 81/01/19. 2pp. 07862.105.

- 8103180893 Forwards IE Insp Rept 50-344/B1-D1 on 010105-00 No noncompliance noted CREWS.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Breach 01/01/29 Zoo
- "-BIO3160913 IE Impp Rept 50-344/BI-OI on 810105-08 No noncompliance noted Major areas inspected maint surveillance, design, design changes & mods.response to IE bulletins & circulars & followup on previous inspliteme.

  CARLEDIA J D. AD-MGUNA D. Region 5. San Francisco. Office of the Director STEANBERG DM Region 5. San Francisco. Reactor Operations Nuclear Support Branch. BI/O1/29. Spp.
- B103230204 Submits response to Suppl 3 of IE Bulletin 77-018. "Environ Qualification of Class IE Equipment" includes info re nin equipment needed for cold shutdown & qualification info for NURE3-0737 HITHERS.B D Portland General Electric Co 81/01/30 3pp 07980.285
- 8103020090 Forwards IE. Circular Bi-O2. "Performance of NRC-Licensed Individuals While on Duty " No written response required ENSELWEN.R H Region 5. San Francisco. Office of the Director. 81/02/09 ip 07787 331
- B1032311CB Bubmits add1 info re IE Bulletin 79-03A. "Longitudinal Weld Defects in ABME SA-312. Type 304 Bitainless Steel Pipe." per 80080B ltr Piping sys are adequate BROEHL, D.J. Purtland General Electric Co. B1/02/11. 1p. 07977:054
- 8103160340 Forwards IE Info Notice 81-03 "Checklist for Licensees Making Notifications of Significant Events in Accordance W/10CF899 72" No response required ENGELKEN, R H. Region 5. Ban Francisco. Office of the Director
- B10325000B Forwards IE Insp Rept 90-344/81-03 on 810209-11 No noncompliance noted CREMB.J L Region 9. San Francisco. Reactor Operations Nuclear Support Branch B1/02/23 2pp. 07998 023
- --Bi03250015 IE Insp Rept 50-344/8)-03 on Bi0209-11.No noncompliance noted Major areas inspected training, requalification training & organization/administration.

  CARLSON.J D. Region 5. San Francisco Office of the Director.

  BIERNBERG.D H Region 5. San Francisco. Reactor Operations Nuclea Support Branch B1/02/22 3pp 07998 025
- B103240737 Forwards IE Insp Rept 50-344/81-04 on 810102-30 No noncompliance noted CREMS.J L Region 3. San Francisco, Office of the Director. 81/02/28 2p 07983 341
- --BIOJ240744 iE insp Rept 50-344/81-04 on BiO102-30. No noncompliance noted. Major areas inspected follows on LERs, item of noncompliance plant operations & surveillance testing. MALKROS. M. M. JOHNSTON. O. W. Region 5. San Francisco. Dêfite of th Director. BERNBERG. D. M. Region 5. Ban Francisco. Reactor Operations Nuclear Support Granch. 81/02/24. App. 07983-343.
- 8103160652 Forwards IE. Info Notice 81-04. "Cracking in Main Steam Lines " No response required ENGELKEN.R.H. Region 5. San Francisco. Office of the Director, 81/02/27. 1p. 07914-173
- 8103170026 Forwards IE Circular 81-03, "Inoperable Saismic Monitoring Instrumentation." No response required ENGELKEN.R. H. Region 5. Ban Francisco. Office of the Director, 81/03/02. 1p. 07939: 151.
- 8103160843 Forwards revised IE Builetin 81-01, "Surveillance of Nechanical Enubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. ENGELMEN.R. H. Region 5. San Francisco. Diffice of the Director. 81/03/04 1p. 07914.203.
- 8103200262 Forwards IE Info Notice 81-06, "Failure of ITE Model K-600 Circuit Breaker." No response required. ENGELKEN.R.H. Region 3, San Francisco, Office of the Director. 81/03/11. ip. 07968.355.

81/03/13 to 07970:052

- R. Pariodic operating reports & related correspondence
- 8103030841 Forwards 'Annual Rept of Trojan Nuclear Power Plant Portland General Electric Co. For 1980 " HITHERS.B. D. Portland General Electric Co. 81/02/27. 1p 07/97-047
- --8103030848 "Annual Rept of Trojan Nuclear Power Plant.Portland General Electric Co. for 1960 " • Portland General Electric Co. POE-1013-80 81/03/01 185pp 07797:048
- 8103160673 Forwards menthly operating rept for Feb 1981 YUNDT.C.P. Portland General Electric Co. 81/03/02 ip 07914-291
- --8103160678 Monthly operating rept for Feb 1981 BAIR-0 0, Portland General Electric Co. 81/03/02. App.
- 5. Reportable occurrences. LERs & related correspondence
- 8103020562 Forwards LER 81-004/03L-0 YUNDT, C.P. Portland General Electric Co. BI/02/18 2pp. 07782, 144
- --Bi03020569 LER 81-004/03; O on Bi0122, fan cooling unit for pump did not automatically start during periodic operating test of containment spray pump B Caused by thermal overload trip on fan unit supply breaker B-2419 Overloads raset BAIR:0 0 Portland General Electric Co. Bi/02/18. Ip 07782-144
- 8103030646 Forwards LER 81-603/03L-0 VUNDT.C P Portland General Electric Co 81/02/25 2pp 07793.137
- --Bi03030661 LER 81-003/03L-0. on 810130, oin required number of source range channels not net when both channels of nuclear source range indications falied to energize automatically Caused by improper actuation of instrument crowber circuit.

  BAIR. 0 0 Portland General Electric Co 81/02/25 ip 07793 139
- 8103170317 RD on 810214, during normal blowdown to river of circulating water sys, thermal discharge exceeded ET8 limit for 68 minutes. Operators reminded to monitor indications & alarms closely, Procedure written
  YUNDT, C.P. Portland Ceneral Electric Co. 81/03/10 ip 07939 274.
- ODCKET 50-346 DAVIS-8ESSE NUCLEAR POWER STATICH, UNIT 1 F. Security, medical, emergency & fire protection plans
- BiO3180264 Ltr to all power reactor licenses u/plants licensed prior to 790101 Forwards NRC position is request for additinform safe shutdown capability for compliance u/801119 firs protection rule.
  EISENHAUT.D.D. Division of Licensing. 81/02/20. 13pp.
- 8103190748 Ack receipt of 810219 itr re improvement of security program.per 810129 meeting. KEPPLER.J. 0 Region 3. Chicago, Office of the Director. 81/03/04, 2pp. 07963.226.
- --B103190755 Forwards plane to improve security program. Plans withheld (ref 10CFR2,770)
  CROUSE, R.P. Teledo Edison Co. B1/02/19, ia 07953 228
- 8103310339 Ltr to all licensees of operating plants & holders of CPs forwarding NURSO-0596. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. W/o anct.

  EJSENHULD O. Q. Division of Licensing 81/03/05. 6pp.
- 8103200626 Advises that certain portions of emergency plan implementing & supporting procedures contained proprietary info Pages 9, 4, 3-10.11 & Administrative Memo 37 are starped proprietary & should be removed.

  CRDUSE.R.P. Toledo Edison Go 81/03/17. ip. 07971:250.

- water capability CRCUSE, R.P. Toledo Edison Co. 81/03/19 6pp 08043:304
- 8103310655 Advises that submittal of upgraded study addressing MAC coments transmitted by 810102 summary rating sheet for evacuation time estimate study planned for 810502 CROUSE, R P. Toledo Edison Co. 81/03/27 1p. 08075-201
- J. Insurance & indemnity information
- B103130410 Forwards Endorsement 35 to ANI Policy NF-236 & Endorsement 27 to MAELU Policy MF-92 CCREA.C Marsh & McLennan.Inc., 8 & M Nuclear Consultants,Inc. 9 81/03/03 3pp 07907 065
- 8103110372 Forwards Endorsement 5 to AMI Binder ED-61 CORREALM A. Marsh & Milleman.inc . If & N Nuclear Consultants.inc DIV. 81/03/06 2pp. 0/872-311
- P Operating license stage documents & correspondence
- 8010230599 Summary of B00821 meeting U/RtW reactor owners group reabnormal transient operating guidelines program VISSING O Operating Reactors Branch 4 80/09/30. 29pp
- B103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREG-0612 Forwards NRC position reinterin actions & request for add1 info E19EPHUT.D Q Division of Licensing 60/12/22 30pp.
- 8103199387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment, items addressed involve cold shutdown-replacement parts & NUREG-0737.
  ETSENHUT.D Q Division of Licensing 81/01/19 6pp
- 8103120014 itr to all licenses of operating plants CP holders & CL applicants, except indian Point 2 & 3,25 on 1 & 2 & TMI-1, forwarding inadvertently emitted pages from NRC 801222 request for addition of control of heavy loads EISENHUT. D G Division of Licensing 81/02/03 6pp
- 8103020001 Forwards list of applications & fees due for various chat to Tech Specs MILLER. N. O. License Fee Management Branch 81/02/05 2pp 07/85 353
- 8103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for addl info.list of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns.

  EISEN:UT.D O. Division of Licensing 81/02/10 13pp
- 8103041015 Advises of resolution of TMI action plan requirement. Item II.K 2 15. "Effect of Blug Flow on Steam Generator Tubes". Blug flow induced by natural circulation will not result in adverse steam generator tube loading REID.R W. Operating Reactors Branch 4. 81/02/17 2pp 07812.30
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Iten III.A, 1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be mot. EISENHUT.D O Division of Licensing. 81/02/18. 12pp
- 8103020507 Forwards payment for Tech Spec changes re 800822.0916-11 & 18 submittals.

  GROUSE.R.P. Toledo Edison Co. 81/02/20 2pp. 07784:097.
- BiOOOO634 Notification of 810005 meeting w/util & EDB Nuclear Inc Bethesda. MD re resolution of 9 taff position reparding third auxiliary feedwater pump to be installed at facility. GARMER. D. J. Operating Reactors Branch 4 81/02/20 2pp. 07793-026
- B103090254 Forwards organizational charts depicting NRC Region 3 reorganization.effective B10216. KEPPLER, J.O. Region 3. Chicago, Office of the Director 81/02/2 20p. 07892:056.
- 8103250024 Ltr to all power reactor licensees & license applicants NUREO-D619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EIGENHUT. D O. Division of Licensing. 81/02/20. 8pp.

```
evaluations of L-4-1 5 S-07-10D predictions requested for submittal 3, 010401
REID.R W. Operating Reactors Oranch 4 81/02/24 3pp
```

- 8:03230030 Ltr to all licensees of operating nuclear power plants & applicants for GLs lescept Bt Lucie. Units 1 % 2) Requests util review to determine capability to ritigate station blacious event & promptly implement emergency procedures ETEE(HHUT.D G Division of Citensing 81/02/25 Spp
- BIO3100559 Identifies revision in method of flow indication for pressurizer 5 hot leg vents Solonoid operated valves J/stem operated limit switches provide open or closed position suitches for indicating lights in control room CROWELR P Toledo Edison Co 81/02/27 4pp 07867.294
- BIO3120229 Act receipt of BO9211 response to 790821 info request to BtW reactor owners group Requirements of TMI Action Plan Item 11 N 2 19. "Jenchmark Analysis of Gequential Auxiliary Feedwater Flow." fulfills request Safety evaluation encl REID.R W Operating Reactors Branch 3 81/02/27 2pp
- --8103120245 Bafety evaluation reliter II K 2 19 "Benchmark Analysis of Sequential Auriliary Feedwater Flou" for 86W reactor plants.
  Intent of Action Item II K 2 19 accomplished & results provided by CRAFI-2 similar to TRAP-2 program
   Office of Nuclear Reactor Regulation, Director. 81/02/27 2pp
- E103120296 Ack receipt of 800205 response to 790821 info request to 8&W reactor curers Requirements of TMI Action Plan Item II K 2 19. "Benchmark Analysis of Sequential Auxiliary Feedwater Flow." Fulfills request Safety evaluation enci REID.R W Operating Reactors Branch 3 81/02/27 2pp
- --8103120308 Safety evaluation re TMI Action Alan Item II K 21 19.
  "Banchmark Analysis of Sequential Auxiliary Feedwater Flow"
  for 880 plants Intent of Action Item II K 2 19 accomplished
  & results provided by CRAFT-2 similar to TRAP-2 program
  # Office of Muclear Reactor Regulation, Director 81/02/27 2pp
- B103120789 Discusses compliance w/TMI Action Plan Item II K. 2.19.
  Benchmark Analysis of Bequential Auxiliary Feedwater Flow "
  More rigorous assessment is being performed under Item
  II. X. 3.30 Item is rusolved Safety evaluation encl
  REID.R W. Operating Reactors Branch 4. 81/02/27. 2pp
- 8103090193 Natification of 810402-03 meeting w/R&W owners group in Bethesda.MD to discuss responses to NRC 810109 ltr re asymmetric LOCA loadings

VISSING. O. Operating Reactors Branch 4 81/03/02 2pp

- 8103120261 Act receipt of 800630 response to 790821 info request to 88W reactor numers group Requirements of TMI Action Plan Item
- reactor owners group. Requirements of TMI Action Plan Item II. K. 2 19. "Benchmatk Analysis of Sequential Auxiliary Feedweter Flow." fulfills request Safety evaluation enct. REID.R.W. Operating Reactors Branch 4 81/03/02 4pp
- --BIO3120270 Safety evaluation to TMI Action Plan Item II K 2 19, "Benchmark Analysis of Sequential Auriliany Feedwater Flow." Intent of Action Item II K 2, 19 accomplished & results provided by CRAFT-2 similar to IRAP-2 program Office of Nuclear Reactor Regulation, Director 81/03/02. 2pp.
- Bio3170390 Forwards safety evaluation to TMI Action Plan Item II.K 2.19, "Benchmark Analysis of Sequential Auxiliary Feedwater Flow" for B&W reactor plants. Util found in compliance wittem REID.R.W Operating Reactors Branch 4 81/03/04. 2pp
- --BID317067) Bekety evaluation re TM1 Action Plan Item II % 2 19.
  "Benchmark Analysis of Sequential Feedwater Flow" for 8&W
  reactor plants.
  \* Office of Nuclear Reactor Regulation, Director. 81/03/04
- BIO3160152 Forwards Cycle 2 startup rept for facility CRCUSE, R P Toleco Edison Co. B1/03/05 ip 07919 333.
- --8103140159 Cycle 2 startup rept for facility.
  4 Taledo Edison Co. 81/03/05. 12pp. 07919.334.

- G103180500 Forwards Revision 1 to Suppl 2 of "Seismic Re-evaluation" Rept reflects revisions to analysis to enargency diesel generator & cooling water heat exchanger CROUSE/R P Toledo Edison Co G1/03/13 1p 07944 191
- --BIOJ100903 Revision 1 to Suppl 2 of "Seismic Re-evaluation " Rept reflects revisions to analysis re energency diesel generator & cooling water heat exchanger • Toleco Edison Co BI/03/13 Bpp 07944 192
- B103240051 Forwards 'Environ Quolification of Bafety-Related Electrica Equipment,' partial review Several deficiences identified relack of proper documentation. NGVARK,T M Assistant Director for Operating Reactors 81/03/16 Opp 07987-297
- --810324005R 'Environ Qualification of Bafety-Related Electrical Equipment," partial review \* Office of hucker Reactor Regulation. Director 81/03/16 38pp 07487-302
- B103240501 Forwards info re accident induced neutron flus error issueper RRC B10114 request. CROUSE:R.P. Toleds Edison Co. B1/03/18 14pp 07981-314
- 8103300481 Forwards Amend 37 to Licenso MPF-3, safety evaluation & notice of issuance & availability.

  SIGLZ.J F Derating Reactors Brench 4 81/03/24 3pp 08058 020
- --8103300-185 Amend 37 to License NPF-3, adding Tech Specs incorporating certain 7HI lessons learned Category A requirements STOLZ.J F Operating Reactors Branch 4 81/03/24. 21pp
- --B100000488 Befety evaluation supporting Amend 37 to License NPF-3

   Office of Nuclear Reactor Regulation, Director. 81/03/24 3pp
  08036.044.
- --8103300490 Notice of issuance & availability of Amend 37 to License NPF-3 STOLZ.J.F Gerating Reactors Dranch 4. 81/03/24 2pp 00038:047
- B103300226 Forwards 10 oversize drawings re bypass & reset capabilitie of engineered safety features.per NRC B10203 request Drawings available in Central Files CROUSE.R P Toledo Edison Co 81/03/26 ip 08053:016.
- Q Inspection reports. IE Bulletins & correspondence

08050 023

- B103170127 Forwards Revision 3 to response to 1E Bulletin 79-01B Buppl 3. "Environ Qualification of Class IE Equipment " Revision 3 encompasses boron precipitation control sys. IE pressurtion heaters sys & post-TKI nods W/o enci. CROUBE.R P Toledo Edison Co. 81/01/30. 3pp. 07938:097.
- 8103020107 Forwards IE Circular BI-Q2, "Performance of NRC-Licensed Individuals While on Duty." No written response required. KEPPLER: J O Region 3. Chicago. Office of the Director. Bi/02/09 2pp. 07788.007
- 8103160948 Forwards IE Insp Rept 50-345/80-34 on 801205-23 No noncompliance noted. FEISHMAN: R F Region 3. Chicago, Reactor Operations Nuclear Support Brench 81/02/09 2pp. 07915:116
- --B103160753 IE Insp Rept 90-346/80-34 on 801205-23 No noncompliance noted. Major areas inspected operational safety verification, monthly surveillance observation & follower on inadvertant safety features actuation RODERS. M. 9. BMITH. J.D. WARNICK, R.F. Region 3. Chicago. Office of the Director B1/02/06 App. 07915.118
- 8103040287 Forwards IE Info Notice 81-03. "Checklist for Licensess Making Notifications of Bignificant Events In Accordance W/10CFR50 72." No written response required. KEPPLER, J O. Region 3. Chicago, Office of the Director. 81/02/12. 2pp. 07815-241.

Lines ' 'lo response required

KEPPLER. J D. Region 3. Chicago. Office of the Director 81/02/27

Zon 97914-277

- BIOD160527 Forwards IE Circular B1-03. Inoperable Sessmic Monitoring Instrumentation "No response required KEPPLER. J G Region 3. Chicago. Office of the Director B1/03/02 2pg 07916 324
- G103160875 Forwards revised IE Bulletin B1-01. "Surveillance of Mechanical Southers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. MEPPLER. J 0. Region 3. Chicago. Géfice of the Director 81/03/04 20n 07914 202
- 8103190327 Responds to IE Bulletin Bi-O1. "Surveillance of Mechanical Boubbers." Required insp program will be completed prior to completion of neit refueling outage, scheduled for Mar 1982 Results will be submitted within 60 days after insp. CROUSE.R P. Toledo Edison Co. 81/03/06 ip 07955 005
- B103200384 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circust Breater" No response required KEPPLER.J Q Region J. Chicago. Diffice of the Director 81/03/11 20p. 07972 137
- 8103230385 Confirms schedule for 810317 meeting w/util in Olen Ellyn. IL to discuss regulatory enforcement actions reliters of nancompliance KEPPLER. J Q Region 3. Chicago. Office of the Director 81/03/11 tp 07980 357
- B103200648 Forwards IE Info Notice B1-93. "Degraded DC 84% at Paissades " No action required KEPPLER.J O Region 3. Chicago. Office of the Director G1/03/13 2pp. 07967 298
- B103200235 Forwards IE Info Notice 81-07. "Potential Problem W/Water-Soluble Purge Dam Matis Veed During Inert Gas Welding " No response required KEPPLER.J G Region 3. Chicago. Office of the Director 81/03/16 Zop 07970 345
- R Periodic operating reports & related correspondence
- 8103050287 Forwards "Effluent & Haste Disposal Gemiannual Rept. Jul-Dac 1980." which (neorporated revised dose calculation & meteorological modeling methodology MURRAY.T D Toledo Edison Co. 81/02/19. 1p 07826.291.
- --8103050293 "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1980 "

   Toleda Edison Co 81/02/19. 6669 07826:292
- 8103130393 Forwards monthly operating rept for Feb 1981. MURRAY, T.D. Toledo Edison Co. 81/03/06 fp. 07911 171.
- --8103130397 Monthly operating rept for Feb 1981. SARBOUR: B Toledo Edison Co. 81/03/06 12pp 07911.172
- S Reportable occurrences. LERs & related correspondence
- 8103030967 PNO-III-80-238 on 801229, gaseous release of 0.1 C1 occurred when makeup tank vented through instrument line. Venting occurred during improperly authorized maint work. Bldg ventilation secured & bldg evacuated.

  ORCOER.L.R., FISHER.H.L. Region 3, Chicago, Office of the Director 80/12/30 Rpp 07795:232
- 8103040015 PND-III-B1-011 water found in 12 containment electrical penetrations in east penetration room Source of water undetarmined HEIBHMAN.R.F. , REYEB, L. A., WARNICK, R. F. Region 3. Chicago, Office of the Director 81/01/20. 3pp. 07815:354.
- BiO3020509 Forwards revised supplemental info sheets for LER 79-050 reunplanned reactivity insertion. Caused by mechanical, personnel & procedural error. Valve Mu 39 disassembled & gaskets installed MURRAY.T.D. Toledo Edison Co. Bi/02/18. 3pp. 07784:094

- 8103030826 Forwards LER 81-008/03L-0 M.984v.T D Toledo Edison Co 81/02/26 1p 07798 004
- --0103030034 LER 01-000/05L-0 on 010127.345 to suitchyard bus k tripped ; locked out.de-energizing startup transformer O2 Caused by action from directional ground current relay & charred phase lightning arrester C on startup transformer MATHERY.D Toledo Edison Co 01/02/26 3pp 0/798 005
- --Biggoggar LER 8(-099/031-0 on Biggoggar) generator 1-2 could not be started w/left side set of air start motors during diesel generator surveillance test 5081 01 Caused by failure of one air start motor due to broken solenoid drive shaft SYBLO. J. Toledo Edison Co. 81/02/2/ 2pp. 07798 009
- 8103130573 Forwards LER 80-083/03L-1 MR9AY, I D. Toledo Edison Co. 81/02/27 lp. 07908 263
- --Bigg130579 LER Bo-083/93L-1 on B01116. station experienced feeduater suing which caused stean generator I-1 lovel to exceed Tech Specs Caused by faulty relay in integrated control sys Relay was replaced LMITEFIL. 3 Toledo Edison Co. 80/12/15 2pp. 07708 284
- 8103090557 Forwards LER 80-091/011-1 MURRAY, T D Toledo Edison Co 81/03/02 ip 07845 318
- --8103090561 LER 80-091/017-1 on 801223, determined that floor beam above block wall between control room t stairway AD-1 & at top of wall 3307 would be overstressed during seismic event Caused by methodology change Struts will be added.
  MEKGEL-C Toledo Edison Co 81/01/06 3pp 07845 319
- 8103090963 Forwards LER 81-010/03L-0 MMRRAV, T D Tologo Edison Co 81/03/04 1p 07845 323
- --8103090568 LER 81-010/03L-0 on 810202.MSIV bypass valve MS 100 A failed to close. Probably caused by component failure Actuator pring adjusted to increase tension until valve would close TRAUTHAN. D. Toledo Edison Co. 01/03/04 2pp 07845-324
- 8103130986 Forwards LER 81-011/03L-0 MWRRAY.T D Toledo Edison Co 81/03/06 1p 07908 286
- --8103130594 LER 81-011/03L-0 on 810205 post-accident monitoring instrument HP1 Flow I-2 was declared inoperable Caused by bad current buffer Current buffer was repaired recalibr & reinstalled HPI Flow 1-2 was returned to operable status MAKATURA. L. Toledo Edison Co. 81/03/06. 2pp. 07908.287
- 8103160736 Forwards LER 79-062/03L-1 MURANY, I. D. Toledo Edison Co. 81/03/06 Ip. 07914.129
- --BIO316074B LER 79-062/03L-1.on 79052L auxiliary feedwater suction pressure switches PBL107C.PBL4928B % PBL4930A found inoperable & pressure setpoints of PBL4929.PBL4929B % PBL493IA found outside limits Caused by Instrument drift. BTBL2.J.F Toledo Edison Co. 79/06/15. 4pp. 07914:126
- 8103170612 Forwards LER 78-064/03L-1 MURRAY.T.D. Toledo Edison Co. 81/03/06. 1p 07935:392.
- --Bi03170618 LER 78-064/03L-1: on 780608, personnel discovered large flow oscillations in flow rate of containment post-accident radiation monitor RE 3030. Caused by component failure of motor on pump Pump repaired & operable.

  8CHMENNINGL Toledo Edison Co. 78/07/05. 2pp. 07935-333
- 8103170362 PMQ-lil-gi-027 on 810307.controlled power reduction initiated due to combostible gases found in oil from main transformer. Gause not stated. Repeir or replacement of transformer expected to take 1 wk. REYES.L.A., MARNICK.R.F., HEISHMAN.R.F. Region 3. Chicago, Office of the Director. 81703709 1p. 07924 080.

- BIO3190517 PNU-SI1-BE-030 on BIO3II. plant manually scrammed due to low steam generator level Caused by closure of startup feedwater control valve investigation underway REYES.L. MCGRIGGR.L. MARNICK.R.F. Region 3. Chicago
- 8103170458 Forwards LER 81-012/03L-0 MARRAY, T. D. Toledo Esison Co. 81/03/13 1p. 07922-061
- --8193170493 LER 51-012/03C-O on B10212.control rod 1-3 atsolute position indication declared inoperable due to fluctuating signals causing asymmetric rod alares Exact cause undetermined but absolute position indication leads picting up noise ERIGER. J Toledo Edison Co. 81/03/13 3pp 07922 062
- 8103269426 Forwards corrected Page 3 to supplemental info for LER-80-090 MURRAY.T D. Toledo Edison Co. 81/03/17 2pp. G8037-352
- 8103310627 Corrected Page 3 to supplemental info for LER 80-690 MURRAY. T D Toledo Edison Co 81/03/17 3pp 08061-036
- B103260902 Forwards LER 81-013/03L-0
  PMRRAY, T D Taledo Edison Co 81/03/20 in 08036-304
- --8103260913 LER 81-013/03L-0 on 810218 control room normal ventilation dampers tripped shut resulting in no power available to chlorine detector I above control room or in block house Caused by failure of 10 amp fuse of circuit YIII FROMME.R Toledo Edison Co. 81/03/20 2pp. 08036-305
- 8103310592 Forwards LER 81-015/03L-0 PURRAY, T. D. Toledo Edison Co. 81/03/24 1p. 08062-213
- --BI03310593 LER BI-015/03L-0 on BI0227.eccess door 107 found propped open from ECCS 2 pump room 115 to miscellaneous waste monitor tank t pump room 114 Caused by Pailure to follow posted signs while clearing odor from room POWERS. I Toledo Edison Co. BI/03/24 2pp 08062:214
- --8103310623 LER 80-025/05x-1 on 800330 control rod group 5 rod 11 absolute position indication declared inoperable Caused by fluctuating signals resulting in numerous asymmetric rod alarms due to defective reed switch assemblies LERNER B J Tolodo Edison Co 81/03/24 3pp 00061-025
- COCKET 99-348 JOSEPH M FARLEY HUCLEAR PLANT, UNIT 1
- Bi03230Bi3 Generic Ltr Bi=06 to all CP holders t OL applicants re 10CFRBD 71(e), "Portiodic Updating of FGARs," effective 800722 Info re FSAR legal status, format & content encl EISENHUT, D 0 Division of Liconsing Bi702/26 lOpp.
- E ARC Bafety Evaluation Report (SER), supply & correspondence
- 8103250642 Forwards Suppl 8 to SER (NUREG-0117) W/o encl SCHWEUCER.A Licensing Branch 2 81/03/19 2pp 08000:344
- f Security, medical, emergency & fire protection plans
- 8103060475 Requests NRC assistance in developing Class A dose projection model for use in ordering offsite protective actions.per FERA recommendation Written statement of rodifying factors requested re App 2 of NURGO-0634 MCNSES, J. L. Alabama, State of. 81/02/18, 2pp. 07838-344.
- 8103180264 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards NRC position & request for addl info resafe shutdown capability for compliance w/B01119 fire protection rule EISENHUT.D.O Division of Licensing. 81/02/20 13pp. 07944-105.
- 9103100184 Submits info re physical security plan. Details withheld (ref 10CFR2.790) CLAYTON,F. L. Alabama Power Co. 81/03/04. 1p 07867:164
- 8103100381 Discusses results of confirmatory sound survey to verify control room noise level. Control noise & elarm levels are acceptable No further action is required. CLAYTON.F. L. Alabama Power Co. B1/03/04 1p. 07865:199.

- 8103310338 Ltr to all licensees of operating plants & holde forwarding NUREG-0896. 'Functional Criteria for Emergency Response Facilities' 'Critoria describe acceptable method for meeting NRC requirements N/O encl EISENMUT.D G Division of Licensing 81/03/05 app 0
- B103250429 Submits fire protection upgrade response to 10CF 10CFR50 App R requirements info re implementation schedul plant areas inaccessible while unit is operating & design description for alternate shutdown encl CLAYTON.F L Alabama Power Co B1/03/19 7pp 07996 i
- J Insurance & indomnity information
- 8103060351 Forwards Endorsonent 2 to HAELU Binder X8-73 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consulta Div 81/01/27 3pg 07840 231
- B103060416 Forwards Endorsement 1 to MAELU Dinder XB-73 FIELDER, J. March & McLennan, Inc., 11 & M Nuclear Consulta Div. B1/01/27 2nc 0/837.329
- BIO3060442 Forwards Endorsement 4 to MAELU Binder XB-62. FIELDER J. Marsh & McLennan Inc., H & M Nuclear Consulta Div 81/01/27 3pp 07837 329
- 8103110637 Forwards Endorsement 5 to MAELU Binder X8-62 FIELDER, J. Marst & McLennen, Inc., M & M Nuclear Consulta Div. 81/03/06 2pp 07877 398
- K Utility Final Safety Analysis Report (FSAR) & amends
- BiO3270401 Forwards Amend 77 to FBAR for Unit 1 & CL applic Unit 2 Certificate of Svc encl CLAYTON-F L Albama Power to 81/03/25 3pp 08046.0
- --8103270411 Application for Amend 77 to FBAR for Unit 1 & for Unit 2 CLAYTO: FL Alabama Power Co 81/03/25 3pp 08046
- --8103270417 Amend 77 to FSAR CLAYTON F L Alabams Power Co 81/03/25 3pp 08046
- M Antitrust correspondence
- B1031B9606 Discusses Municipal Electric Util Authority peti pitraordinary relief to hasten ABLB decision on antitrust review ABLB should not be pressured to reach early decision BALCH S E Jalch, Bingham, Baker, Hawthorne, Utiliams & B1/03/11 13pp 07933-075
- P Operating license stage documents & correspondence
- 8103199732 Ltrs to all licensees of operating plants applic. OLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position interim actions & request for addl info. EIBE
- 8103190387 Ltr to all licensess of operating plants & appli OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdoun-replacement parts & NUREO-0737. EISERMUT, D O Division of Licensing. BI/01/19. App. 0
- B103120014 Ltr to all licensees of operating plants.CP hold applicants.except Indian Point 2 & 3.2ion 1 & 2 & THI-1. forwarding inadvertently omitted pages from NRC B01222 request for add; info re control of heavy loads EISENHUT.D.O. Division of Licensing. 81/02/03 App.
- 8103300160 Ltr to all operating PWR licensees requesting in auxiliary feedwater sys seismic design Forwards request f addl info. List of actions requested of licensees w/o seismically qualified sys & results of NRC walkdowns. EISENEUT, D. O. Division of Licensing 81/02/10. 13pp
- 8103040060 Forwards Amend 18 to License NPF-2, safety evaluation notice of issuance & availability.

  VAROASS A Operating Roactors Branch 1. 81/02/13. 2pp.
- --8193040067 Amend 19 to License NPF-2 changing new rod bow & bases Also revises heatup & cooldown curves & bases VARQA.5 A Operating Reactors Branch 1. 81/02/13. 21

- --810304C077 Safety evaluation supporting Arend 18 to License NPF-2

   Office of Nuclear Reactor Regulation, Director 81/02/13 3pp
- --8103040084 Notice of insurance 5 evailability of Amend 18 to License MPF-2 VARGA.5 A. Operating Resctore Branch 1 81/02/13 2PP
- 8103200324 Forwards partial review. "Equipment Evaluation Rept by Ofc of Nuclear Peactor Regulation Equipment Qualification Branch for AL Power Co JM Farley Unit 1." Hritten response required within ten days of receipt of itr NOVAK. T.M. Assistant Director for Operating Reactors. 81/02/13 350
- --BI03200335 'Equipment Evaluation Rept by Ofc of Nuclear Reactor Regulation Equipment Qualification Branch for AL Power Co JM Farley Unit 1." partial review • Equipment Qualification Branch B1/02/13 4bcp
- 8303160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be ret EIBENHIT.D 0 Division of Licensing 81/02/18 12pp 07915 247
- 8103050652 Forwards Revision 2 to FXP-O-M-007. "Emergency Dose Calculational Manual "Revision intent is to Jeprove backup/ interim dose calculational method by providing better pluce haundary definition.

  CLAYTON.F. L. Alabama Power Co. 81/02/19 1p. 07832-026
- --8103050654 Revision 2 to "Emergency Dose Calculational Manual" MCCRACKEN.R W. Alabama Power Co. 81/02/16 71pp 07832 027.
- 8103297024 Ltr to all power reactor licensees & license applicants re NUREG-0619 resteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D 0 Division of Licensing 81/02/20 8pp.
- BIO3020388 Forwards add1 info per NRC BI0220 telcon, clarifying TMI action plan requirements. Shift menning & guidance on procedures for verifying correct performance of operating activities discussed CLAYTON, F.L. Alabama Power Co. B1/02/23 Spp. 07785 217.
- BIO3230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie. Units 1 & 2) Requests util review to determine capability to attigate station blackout event & promptly implement emergency procedures.

  EISENHUT. D. 0 Division of Licensing B1/02/25. Spp. 07980 269.
- 8103100498 Forwards revised Tech Specs confirming basis for loss of flow trip to prevent ONB in event of loss of one or more reactor coolant pump Revised Tech Specs reflect new DNBR limit of 1 34 CLAYTON.F.L. Alabama Power Co. 81/03/04. 1p. 07867-215
- --8103100502 Revised Tech Specs re limiting safety sys settings. + Alabama Power Co 81/03/04. tp. 07867-216
- --BIO3100393 Revised Tech Specs re limiting safety sys settings s Alabama Power Co B1/03/04 2pp 07867:217
- B103160369 Submits evaluation to degraded grid voltage & adequacy of station electric distribution sys for facility Design Is acceptable based on mods analysis & tosts conducted. increased surveillance & compliance Utriterion VARQA:S.A. Operating Reactors Branch 1 81/03/09. 3pp. 07915-186
- 8103310804 Ltr to all licensees of operating plants applicants for OLs 4 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT. D. 0 Division of Licensing 81/03/10 App. 08077.270
- BiO3240483 Requests extension for submittal of license amend application for Tech Specs revisions to snubber surveillance in response to NRC 801120 ltr Extension is needed for updating Table 3 7-4 re 1E Bullettin 79-14 CLAYTON.F.L. Alabama Power Co 81/03/20. 1p. 07987:338
- 8103310288 Application for temporary amend to Licenses NPF-2 & NPF-8, changing Tech Spec 3 7.4 to allow facilities to be in Hodes 1-4 during mod requiring voluntary limiting conditions for operation of svc water sys. Class 11/ fee encl.

  CLAVION.F. L. Alabama Power CO 81/03/24 5pp. 08079 068

- --B103310294 Proposed temporary revision to Tech Bpec 3 7 4 re in conditions for operation of svc water sys Bases for changes encl A Alabama Power Co B1/03/24 App 08079 073
- g inspection reports, IE Bulbetins & correspondence
- 8103050068 Forwards IE Insp Repts 50-348/80-38 & 50-364/80-49 on 801202-05 No honcompliance noted MARPHY.CE Region 2. Atlanta. Reactor Construction & Engineer Support Branch 81/01/19 2pp 07827 254
- --8103050078 IE Insp Repts 50-348/80-38 % 50-364/80-49 on 801202-No noncompliance noted Major areas inspected installed equipment review per IE Bulletin 79-018 & NOREG-0580 GIBBOMS. T D. CCNLCN. T E. Region 2. Atlanta, Uffice of the Director 81/01/14 5pp 07827 256.
- B103050390 Forwards IE Insp Repts 50-348/80-37 & 50-364/80-51 on B01215-18 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineer Support Branch B1/01/29 2pp 07824 279
- ---BI03050410 IE Insp Repts 90-348/80-37 % 50-364/80-51 on B01215noncephilance noted Major areas inspected inservice insp.
  low pressure turtine disc creating, previous insp findings
  & IE Bulletin B0-0B
  CROWLEY, B R Region 2. Atlanta. Office of the Director
  HEROT. A R Region 2. Atlanta. Reactor Construction & Enginee
  Support Branch 81/01/28 7pp 07824-201
- 8102240569 Forwards Revision 3 to util response to 1E Bulletin 79 'Environ Qualification of Class IE Equipment ' Equipment that util be utilized to achieve one path to cold shutdown listed W/o ancis.

  CLAYTON,F.L. Alabama Power Co. 81/02/02 4pp. 07989, 170
- 8103090747 Forwards IE Insp Repts 50-348/80-36 & 90-364/80-48 on 801117-21 No noncompliance noted 810HR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Brench 81/02/03 2pp 07849 189
- --B103090755 IE insp. Repts 50-348/80-36 & 50-364/80-48 on 801117noncompliance noted Major areas inspected coordinated licensee.state & local govt radiological emergency exercise ANDREKS. D L. Region 2. Atlanta. Defice of the Director JENKIN3. 9 R. Region 2. Atlanta. Fuel Facility & Materials Sa Branch 81/02/02 7pp 07899.191
- 8103020299 Forwards IE Circular B1-02. "Performance of NRC-Licens Individuals While on Duty " No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 81/0 Ip. 07789-328
- 8103160954 Forwards IE Insp Repts 50-348/80-40 & 50-364/80-90 on 801103-28 No noncompliance noted. IEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Suppo Branch 81/02/10 2pp. 07918-122
- --8103160950 IE insp Repts 50-368/80-40 \$ 90-364/80-30 on 801103noncompliance noted Major areas inspected plant status, cross connection of sec water purp lube & cooling water & plant cleanliness.

  BRADFORD.W H. MULKEY J. P. Region 2. Atlanta. Office of the Director Julian. C. A. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/10 Opp 07919:124.
- BIOGN40126 Forwards IE Info Notice Bi-O3. "Checklist for Licensed Mating Notifications of Bignificant Events in Accordance W/IOCFR99 72." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/C Ip 07819-027
- 8103240773 Requests withdrawal of util 800404,0730,1030,1112 & 81 responses to IE Bulletin 79-018 from PDR pending detailed review of catl by Westinghouse for proprietary determination.
  - CLAYTON, F. L. Alabama Power Co. 81/02/12 2pp. 07990.024.
- 8103230251 Forwards Revision 4 to response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." Revision includes list of cold shutdown equipment outside harsh environs & exposed to post-accident radiation. We encl. CLAYION.F L. Alabama Power Co. 81/02/13 2pp. 07980.288.
- 8103030879 Responds to preliminary results of MRC 810213 evaluate of util response to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment." Util review indicates that facility can continue to operate safely CLAYTON.F. L. Alabama Power Co. 81/02/26. 2pp. 07788.079

- B:03160716 Forwards IE Info Notice 81-04. "Cracking in Main Steam CUSION/ID FURWARDS IN INTO NOTICE OF U.S. "Cracking in Main Sceam Lines" No response required O'REILLY.J P. Region 2. Atlanta, Office of the Director - 81/02/27 07714 075 10
- Indication regulars IE Circular GI-03 "Inoperable Science Monitoring Instrumentation" No response required Oracitly, J.P. Region 2, Atlanta, Office of the Director 81/03/02 Jp. 07914-276 8103160674 Forwards IE Circular 81-03 "Inoperable Seismic Monitoring
- 8103170356 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Snutbers, w/corrected Pages 5 to Change in applicable does not affect util requirements
  Oraclety. J P. Region 2. Atlanta, Office of the Director 81/03/04
  15 07939 179
- NUMERONE POPURED IN THE MODEL OF THE MODEL K-600 Circuit Dreaker." No response required Dragilly. JP Region ≥ Atlanta. Office of the Director. 81/03/11 is p. 07968-334 8103200238 Forwards IE Info Notice B1-06. 'Fatture of ITE Model K-600
- B103240775 Forwards IE Safety Insp Repts 50-348/81-04 & 50-364/81-05 on B10224-27 No noncompliance noted LERGE R C Region 2. Atlanta, Office of the Director 81/03/12 200 07983 281
- --8103240786 IE Safety Insp Repts 50-348/81-04 & 50-364/81-09 on B10224-27 No noncompliance noted Major areas inspected fallowup of IF Rulletin 80-11. Dicensee action on previous
- 6|03|90864 Forwards IE Info Notice 81-05. "Degraded DC 8ys at Palisades 'No response required O'REILLY.J P. Region 2. Atlanta. Office of the Director 81/03/13. 1p. 07969-275
- 8103260399 Forwards IE Health Physics Appraisal Repts 50-348/80-41 & 50-364/80-52 notice of violation & significant appraisal 21 od 1 n a 5 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/13. 400
- --- Big3260360 Notice of violation from health physics appraisal on 801201-12
  - a Region 2. Atlanta, Office of the Director 81/03/13 2pp
- --9103260370 IE Health Physics Appraisal Repts 90-348/80-41 & 30-264/80-52 Noncompliance noted failure to follow procedures for release of sys for maint HISEY.C M. PERRY.W., GIBSON, A.F. Region 2. Atlanta, Diffice of the Director 81/03/10 26pp
- R Periodic operating reports & related correspondence
- 8103060518 Forwards 'Semiannual Radioactive Effluent Release Rept Jul - Dec 1980. CLAYTON F L Alahana Power Co 81/03/02 1p 07836:145.
- --8103050525 "Bemiannual Radioactive Effluent Release Rept Jul-Dec 1960." + Alabama Power Co 81/03/02 83pp 07834 146
- 8103180504 Forwards monthly operating rept for Feb 1981 MCDDNALD.R.P. Alabama Power Co 81/03/12 Ip. 07949.302.
- --8103180507 Monthly operating rept for Feb 1981. HAIRBION.W Q Alabama Power Co 81/03/01 4pp. 07949 303.
- 8109310434 Forwards "Annual Operating Rept. 1980" (LAYYON, F. L. Alabama Power Co. 81/03/23 1p. 08081: 178
- --8103310439 "Annual Operating Rept. 1980." \* Alabama Power Co 81/03/23 10pp 08081 179
- 8103310422 Forwards "Annual Nonradiological Environ Operating Rept for Period Ending 801231." per ETS Section 5 & 1 a.Part A. CLAYTEN.F L. Alabama Power Co. 81/03/26 1p.
- --BI03310427 "Annual Nonradiological Environ Operating Rept for Pariod Ending 801231
  - Alabama Power Co 81/03/26 107pp

- 8 Reportable occurrences. LERs & related correspondence
- 8103020598 Forwards LER 81-003/03L-0 CLAYTON F L Alabama Power Co 81/02/23 1p 07782 058
- --8103020606 LER 81-003/03L-0 on 810202, fuel storage pool area gaseou activity-ventilation sys isolation radiation monitor R250 declared inoperable Caused by drive belt breaking Belt HAIRSTO'L N G Alabama Power Co. 81/02/23 10
- 8103170607 Forwards LER 81-004/03L-0. CLAYTON F L Alabama Power Co 81/03/09 Ip 07935.349
- --8103170610 LER 81-004/03L-0 on 810205.fire barrier wall in control is ventilation equipment room declared inoperable due to unsealed penetration Caused by failure to provide followup to action work request issued but not accomplished HAIRSTON. W G Alabama Power Co. 81/03/09 2pp 07935 350
- V Operator Examinations
- BIO3D2338B Forwards addl info per NRC 810220 telcon, clarifying TM1 action plan requirements Shift manning & guidance on activities discussed activities of the decision of operating activities discussed CLAYTON.F L. Alabara Power Co. 81/02/23 5pp 07785 217
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT I A Application/construction stage documents & correspondence
- BiO3190732 Ltrs to all licensees of operating plants applicants for OSTANDAZ LETS to all illustrates of operating plants upper the CPs re control of heavy loads Requesta review per guidelines in NUREO-OSI2 Forwards NRC position reinterin actions 8 request for add 1 info ELEENHUT, D.O. Division of Licensing, 80/12/22 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutcown, replacement parts & NUREO-0737. EIEENRUT, D.O. Division of Licensing Bi/01/19 App
- 8103120014 Ltr to all licensees of operating plants, CP holders & CL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvortently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT, D O Division of Licensing, 81/02/03, App.
- 8103050951 Notification of 810311 & 12 meeting w/Mark II owners group & GE in Bethesda.MD to discuss Mark II generic long-term ANDERSON, C. J. Generic Issues Branch. 81/02/12 12pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TML Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met.
  EISENRUT. D. O. Division of Licensing 81/02/18 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow Controller ESERMUT.D O Division of Licensing. 81/02/20 Spp
- 8103170225 Ltr to all DWR licensees (except Humboldt Bay & LaGrosse) requesting review of ASME Code Class | & 2 pressure boundary piping safe ends & fitting matl per guidelines of enci Revision 1 to NUREG-0313 Model Tech Specs only encl. EISEKHUT, D. G. Division of Licensing. 81/02/26 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-E surveillance requirements for ASME Code Class 1,2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements.

  # General Electric Co 81/02/26. 46
- B103170658 Ltr to holders of CPs & applicants for QLs (BMRs) requests review of ABME Class 1.2 & 3 pressure boundary piping safe ends & fitting mail per guidelines of encl Revision 1 to NUREQ-0313 Model Tech Specs only encl EIBENHUT.D O Division of Licensing 81/02/26 3pp

ſ

```
DIG3230B13 Ceneric Ltr B1-06 to all CP holders & GL applicants for IOSFR30 7Lies. Periodic Updating of FSAGs." effective BG03722 laks re FSAG legal status format & content entil EISEIMUT. D G. Livision of Licensing B1/02/28 10pt
```

- 8103120093 Forwards request for add1 info re Americ 24 to PSAR Util must provide survay, of various efforts to identify causes of low strengths at 28 days.

  TEDES/O.R L. Assistant Director for Licensing. 81/02/27 3pp. 07900, 33R.
- 0103130601 Notification of 010313 meeting J/Mert II comers group in Betheeda.MD to discuss Mark II safety relief valve loads & pool tery limits SULT M. Ormeric Issues Branch 81/03/03 2pp
- 81/3120404 Furtards surmary of B10119 nesting WACORN re-const & licensing of facility Public meeting should be considered in developing rulemaking process for siting criteria DENTCH-HR Office of Nuclear Reactor Regulation. Director B1/03/09 16 07905 182
- --BIO312041) Surmary of BIO119 meeting WACORN in Philadelphia-PA reconst 5 licensing of facility SELLS-D Licensing Sanch 2 BI/02-03 2pp 07906 193
- BID3130509 Responds to NUREG-0737. Item 1 0 fine low power test program BMR owners group is developing generic grogate muith uill be adhered to Bignificant plant transients uill be performed once w/licensed personnel MEMPER. J B Philadelpfio Electric Co. 81/03/06. 2pp. 07911 289
- B103310834 Ltr to ati licensees of operating plants, applicants for CLs & holders of CPs forwarding SECY-81-115 re info necessary to establish environ qualification of safety-related electrical equipment EIGENWIT.D O Division of Licensing 81/03/10 6pp
- 8103200444 Forwards Suppl 2 to NUREO-0487. "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper Suggests Mar 1981 meeting w/Mark II cuners to discuss review program. W/o encl PMIEL. M. Generic Issues Branch 81/03/16 Ip 65:34 2:8
- 8103190363 Forwards acceptance revisu copy of Amend 23 to license application consisting of FSAR, emergency plan-fire protection evaluation rept & probabilistic risk assessment BRADLEY, E. J. Philadelphia Electric Co. 81/03/17. 2pp. 65128-334
- ~-8103190566 Acceptance review copy of Amend 25 to CL application.
  consisting of FSAR amergency plan.environ rept.fire
  protection rept & probabilistic risk assessment.
  BDYER.V S Philadelphia Electric Co 81/03/16 lipp 65128 33a
- 8103190969 Forwards acceptance review copies of "Fire Protection Evaluation Rept" & "Probabilistic Risk Assessment." Vols 1 & 2 ERADLEY.E J. Philadelphia Electric Co. 81/03/17. 2pp
- --BIO3190570 "Fire Protection Evaluation Rept "
  Philadelphia Electric Co. 81/03/17. 365pp
- --Bi03190571 "Probabilistic Risk Assessment." Vol 1.

   Philadelphia Electric Co. Bi/03/17 261oo
- --B103190574 "Probabilistic Risk Assessment," Vol 2.

  # Philadelphia Electric Co B1/03/17 491pp
- 8103230652 Bubmits info on four items not contained in 810317 final rept of facility probabilistic risk assessment including sits specific liquid transport, population data for yr 2000, sits specific meteorology & preliminary supporting info.

  BRADLEY, E. J. Philadelphia Electric Co. 81/03/18. 2pp. 07979-330
- 8103260604 Advises that requested design info will be provided, per MUREO-0737 Item III A | 2.in connection w/fac;!ity QL application review process MEMPER.J S Philadelphia Electric Co. 81/03/20, is
- 8103310914 Burnary of 810313 rooting u/Mark II owners group re suppression pool temp limit & Trquencher load spec. M/o encl list of attendess & meeting handout. SU.T.M. Generic Issues Branch. 81/03/24 3pp 08061 115.

- C Utility Environmental Report (ER), amends & corres
- 8103190650 Forwards acceptance review copy of environ Limerics Units 1 % 2 BRADLEY.E.J. Philadelphia Electric Co. 81/03/17
- --B103190652 Acceptance review copy of environ rept. V Units 1 % 2 • Philadelphia Electric Co B1/03/17 400pm
- --8193190653 Acceptance review copy of noviron rept.V Units 1 & 2 • Philadelphia Electric Co 81/03/17 300pp
- --BIO3170656 Acceptance review copy of environ rept.V Onite 1 t 2 • Philadelotta Electric Co B1/03/17 400pp
- --BIO3190659 Acceptance reviso copy of environ ropt. V Units 5 2 • Philadelphia Electric Co 81/03/17 185pp
- D ARC Draft/Final Environmental Statements, supply &
- 8103170599 Requests notices of Intent & of any scupin & FES for facility on behalf of RE Nater Energency Bucks County Audubon Society, Bucks County Land Use Force-Limerici Ecology Action et al (CCMEDD) HA Lockwood, Reif & Bolger Bi/03/11
- --8103170602 Responds to 801219 ltr re preparation of IRC will specifically consider into & data development to issued of IES for CP DES & FES witssued after campletion of review IEDESCO. R L. Assistant Director for Licensing 07925-177.
- F Security, medical, emergency & fire protection pla
- 8103310338 Ltr to all licensess of operating plants to forwarding NUREO-0696. "Functional Criteria for Eme Response Facilities" Criteria describe acceptable for meeting NRC requirements N/o encl. EISENHUT.D G Division of Licensing 81/03/05 6
- 8103190553 Forwards acceptance review copy of Amend 2 application.consisting of FSAM.emergency plan.fire protection evaluation rept to proteblistic risk ass BRADLEY.E J. Philadelphia Electric Co. 81/03/17.
- --Bi03190565 Acceptance reviou copy of Amend 25 to Ol consisting of FBAR, emergency plan, environ rept. fi protection lept & probabilistic risk assessment BOYER, V 5. Philadelphia Electric Co 61/03/16
- BIO3190569 Forwards acceptance review copies of "Fire Evaluation Rept" & "Probabilistic Risk Assessment." Vols 1 % 2 874ADEV.E J Philadelphia Electric Co 81/03/17
- --8103190570 "Fire Protection Evaluation Rept "
  Philadelphia Electric Co B1/03/17 365pp.
- O Adjudicatory correspondence
- B103170599 Requests notices of intent & of any scupin & FES for facility, on behalf of DE Water Emergency Bucks County Audubon Society, Bucks County Land Use Force-Limerick Ecology Action, et al LGCKMOOD. H A Lockwood, Reid & Bolger 81/03/11
- --BI03170602 Responds to B01215 ltr re preparation of NRC will specifically consider info & data development to issuance of FES for CP DES & FES with issued after completion of review TEDESCO.R L. Assistant Director for Licensing. 07925 177.
- H General correspondence
- 8103160777 F01A request for 11 categories of document KANNER.A Berger, D. 81/02/13, 3pp 07915-220.

Thilandiania Fibririr in

1130409 Forwards constituent 3 Johnson 810227 Itr.re lack of icility evacuation plan for response Related erespendence

1 4 CO O S House of Ren. 81/02/24 200 07911 203

11 21 4

3200356 Responds to 801215 ltr to editor Util has not yet applied or OL Licensing process will take at least two yes Public parings will be held (for to editor encl DESCO.R L. Assistant Director for Licensing 81/02/25 3pp

1170100 Responds to 810116 ltr re OL proceedings for facilities As icensing review proceeds apportunities for add; meetings iil be presented DEECO.R L Assistant Director for Licensing 81/03/03 2pc 1935-357

3163773 Partial response to FOIA request for 11 categories of Bouments re facility Forwards documents listed in App A reuments re facility Forwards documents listed in App A arch is currently underway for addl documents N/o encl .REC-0825. 'Rept of Siting Policy Task Force " LTON.JM Division of Rules and Records 81/03/09 2pp 1915 218

ig90023 Responds to B01223 ltr re facility Public meetings will be heduled after OL application is submitted & accepted sues noted in ltr will be addressed in future safety & viron reviews DESCO.R L Division of Licensing 81/03/09 in 07960 ioB

1230287 Advises that util is espected to submit OL application risk assessment rept in Mar or Apr 1981, in response to 0211 ttr

OFSCO.8 L. Assistant Director for Licensian 81/03/09 In

93230263 Requests info to submittal of risk assessment ropt & offocts of blasting at nearby Quarry LENIS, M. Affiliation Unknown. 81/02/11 Ip

190132 Ack receipt of B01215 ltr re concrete pours & blasting near cilities When FR notice for OL application is published. tition to become party to proceeding may be requested SEL-WIT.D 9 Assistant Director for Licensing 81/03/10 3pp 1965 10-6

1230457 Responds to 810205 ltr opposing const of power plants No OL 11 be issued until emergency plans approved Util requested - perform risk assessment study to be submitted application for On. DESCO.R L Assistant Director for Licensing 81/03/16. 2pp 977 265

03230464 Notifies that members of Citizen Action in Northeast apposed to const of power plants Requests emergency planning hearing be held in Philadelphia.PA Recommends alternative sources of aperau

ROBENBERG, A. Citizen Action in the Northeast. 81/02/05 3pp. 07977 268

270703 Expresses concern re startup of facilities EBBITT.M M - Affiliation Unknown - 81/03/20 ip.

inancial information

170584 Forwards Annual Financial Rept 1980 ADLEY E J. Philadelphia Electric Co. 81/03/13 7pp

03170596 Annual Financial Rept 1980

\* Public Service Electric 5 Gas Co of New Jersey 81/02/16 52pp

03170606 Annual Financial Rept 1980 Philadelphia Electric Co. 81/03/13 46pp

03170616 Annual Financial Rept 1980 Atlantic Electric of New Jersey. 81/03/13. 40pp

G3170626 Annual Financial Rept 1980 \* Delmatva Power & Light Co 81/03/06. 40pp

- A103190934 Acceptance review copy of Chapter I to Limerick Units I & 2 \* Philadelphia Electric Co. 81/03/17 225op

21 117 11

- B103190539 Acceptance review copy of Chapter 2 to Limerick Units 1 & 2 FSAR, "Site Characteristics"

  # Philadelphia Electric Co. 81/03/17 37500
- B103190542 Acceptance review copy of Chapter 3 to Limerick Units 1 & 2 FSAR. "Design of Structures, Components, Equipment & Bys " Philadelphia Electric Co 81/03/17 B90pp
- 8103190949 Acceptance review copy of Chapter 4 to Limerick Units 1 & 2 FSAR, "Reactor"

  \* Philadelphia Flattic Co. 81/03/17 125an

- B103190947 Acceptance review copy of Chapter 5 to Limerick Units 1 & 2 FEAR, "RCB & Connected Sys" # Philadelphia Electric Co 81/03/17 175pp
- 8103190547 Acceptance review copy of Chapter 6 to Limerica Units 1 & 2 FEAR. "Engineered Safety Features "
  \* Philadelphia Electric Co 81/03/17 350pp
- 8103190552 Acceptance review copy of App 6A to Limerick Units 1 & 2 FBAR. "Subcompartment Differential Pressure Considerations" + Philadelphia Electric Co = 81/03/17 = 35pp
- BiO3190555 Acceptance review copy of Chapter 7 to Limerick Units | & 2 PSAR, "Instrumentation & Controls" ## Philadelphia Electric Co | Bi/O3/17 | ElOOpp
- 8103190556 Acceptance review copy of Chapter 8 to Limerick Units 1 & 2 FBAR. "Electric Power" 6 Philadelphia Flectric Co 81/03/17 (35pp
- 8103190558 Acceptance review copy of Chapter 7 to Limerick Units 1 & 2 FEAR. "Auxiliary Bys."

   Philadelphia Electric Co. 81/03/17 700pp

- 8103190560 Acceptance review copy of Chapter 10 to Limerick Units 1 & 2 FBAR. "Steam & Power Conversion Sys."

   Philadelphia Electric Co. 81/03/17 90pp
- 8103190563 Forwards acceptance review copy of Amend 25 to license application.consisting of FBAR.emergency plan.fire protection evaluation ropt & probabilistic risk assessment. BRADLEY.E J. Philadelphia Ejectric Co. 81/03/17 2pp. 65128 334
- --Bi03190366 Acceptance review copy of Amend 25 to OL application, consisting of FSAR emergency plan environ reptifire protection rept & probabilistic risk assessment BOYER.V S. Philadelphia Electric Co BI/03716 lipp. 65128:336.
- 8103190577 Acceptance review copy of Chapter 11 to Limerick Units 1 & 2 FBAR. "Radwaste figt"

  \* Philadelphia Electric Co 81/03/17 200pp.
- 8103190382 Acceptance review copy of Chapter 12 to Limerick Units 1 & 2 FBAR. "Radiation Protection." \* Philadelphia Electric Co 81/03/17 300pp.
- 8103190586 Acceptance review copy of Chapter 13 to Limerick Units | & 2 FSAR. "Conduct of Operations" a Philodelphia Electric Co. 81/03/17. 120pp
- 8103190588 Acceptance review copy of Chapter 14 to Limerick Units 1 & 2 FSAR, "Initial lest Program" # Philadelphia Electric Co. 81/03/17. 100pp.
- 8103190591 Acceptance review copy of Chapter 15 to Limerick Units 1 & 2 FEAR. "Accident Analysis."

   Philadelphia Electric Co 81/03/17, 450pp.

ŧ

```
8103190594 Acceptance review copy of Crapter 16 to Linerick Units 1 & 2
   FHAR, "Tech Scece
      Philadelphia Electric Co. 81/63/17 2pp
8103190598 Acceptance review copy of Chapter 17 to Limerica Units 1 & 2
    * Philadelphia flettric Co - 81/03/17 125pp
8103190602 Acceptance review copy of App A to Limerick Units 1 & 2
   FSAR, Interfaces for Std Designs

• Philadelphia Electric Co BI/03/17 1p
BIO3190605 Acceptance review copy of supplied timeric) Units i 5/2
FBAR. "Responses to NRC Questions" Folders only encl

Philadelphia Electric Co. 81/03/17 28pp
M Antitrust correspondence
8103310413 Requests info identified in Reg Guide 9 3 re significant
   changes occurring subsequent to previous CP antitrust
   G Inspection reports. IE Bulletins & correspondence
8103090080 Forwards agenda for 1E mgt 810127 meeting in Philadelphia.PA to discuss assessment of regulatory performance te facility
   const
   CRIER. B H Re;
81/01/22 200
                     Region I. Philadelphia. Office of the Director
Zon 07852 142
8103100252 Responds to IE Bulletin 80-16. 'Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters WEIther A or D Output Codes ' QE has ordered surveys of transmitters Status rept espected by 810430 AEMPER. J. 9 Philadelphia Electric Co. 81/01/30 2pp. 07853 208
8103200056 Act receipt of 810120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-20 &
   50-35780-18
CARLSON.R T Region 1. Philedelphia. Reactor Construction & Engineering Support Branch 81/02/03 19 07970 056
-- 9103200065 Responds to NRC B01217 Itr re violations noted in IE Insa
      Repts 50-352/80-20 & 50-353/80-18 Corrective actions
      obtained disposition & authorization to rework weld
      preparation Training session held to suplain requirements
      KEMPER, J. S. Philadelphia Electric Co. 81/01/20 3pp.
                                                                                           07970 057
--8103200071 Forwards IE Insp Repts 50-352/80-20 & 50-353/80-18 on
      801104-28 & notice of violation
CARLBON.RT Aegion I. Philadelphia. Reactor Construction &
Engineering Support Branch 80/12/17 2pp 07970-060.
--B103200075 Notice of violation from insp on 801104-28
       Region 1, Philadelphia, Office of the Birector. 80/12/16. 2pg
07970-062
--8103200084 IE Inap Repts 50-352/80-20 & 50-353/80-18 on 801104-28.
      Noncompliance noted pipe weld preparation ground into base
      metal w/o GE authorization & undercut exceeded Tech Specs on
      Psedwater pipe restraint
DURR.J P Region 1. Philadelphia. Office of the Director
MATTIA.J C. Region 1. Philadelphia. Reactor Construction &
Engineering Support Branch B0/12/16. 9pp. 07970:064
8103030398 Forwards Suppl 5 to 1E Bulletin 80-17. "Failure of Control Rods to Insert During Scram et BMR " No written response
   ORIER B H Region 1, Philadelphia, Office of the Director.
81/02/13 Ip. 07795.008
8103300186 Forwards IE Mgt Meeting Repts 50-352/81-03 & 50-353/81-03
    on 810127. No noncompliance noted
   ORIGR. B. H. Region 1. Philadelphia. Office of the Director.
81/02/19. 1p. 08057.123
--Bi03300193 IE Mgt Meeting Repts 50-352/B1-03 & 50-353/B1-03 on B10127. No honcompliance noted Areas discussed results of systematic assessment of licensee performance from Oct 1979-Sept 1980. DURR.J.P. Region I. Philadelphia. Office of the Director. CARLSON.R.T. Region I. Philadelphia. Reactor Construction & Engineering Support Branch. B1/02/II. 9pp 08097:124.
```

8103200213 Forwards 1E Circular 81-03. "Inoperable Seismic Monitoring

```
8103230230 Forwards revised [E Bulletin 81-01, "Surveillance
    rechanical Brobbers, w/corrected Pages 5 & 6 Change in
     recommission of facilities u/CPs to which bulletin is
    applicable coes not affect util requirements GRIER. BK Region 1. Philadelphia. Office of the Directo B1/03/04 p 07977 262.
Bi03270015 Bubhits addl response to IE Bulletin 80-16 re po
misapplication of Rosemount transmitters GE currently
     issuing field disposition instructions for 1150 Rosemount
     insp Insp results to determine corrective action.
    KEMPER. J 5 Philadelphia Electric Co 81/03/05
8103200175 Forwards 1E Info Notice 81-06. 'Failure of ITE M
    Circuit Breaker." No response required
ORIER.B H Region 1. Philadelphia, Office of the Directo
81/03/11 12 07969 307
proposals Researche to NRC 810227 ltm re violations nated i
    Rests 50-352/81-01 & 90-353/81-01 Corrective actions
     nondestructive testing indications documented & open rewo
     notices reviewed
    MEMPER. J 5 Philadelphia Electric Co Bi/03/23 App
S Reportable accurrences, LERs & related correspondence
8103100165 Ack receipt of 801230 final Significant Deficien re ASME bolts, nots 2 stude obtained from unapproved source
                                  Region 1. Philadelphia, Reactor Constructio
     Engineering Support Branch 81/02/02 ip 07865.339.
B103100265 Ack receipt of B10113 final Significant Deficien
     re grounding of flexible conduit.
CARLSCN.R T Region L. Philadelphia, Reactor Construction
     Engintering Support Branch 81/02/06 ip 07863 202.
 8103190704 Ack receipt of 801217 final Significant Deficien
      re violations of separation criteria in power generation control complex Rept not acceptable Requests date when fi
      control complex Rept not acceptable. Requests uses when re-
rept will be filed if sufficient info is not available no
CARLSSY.R T Region 1. Philadelphia, Reactor Constructio
Engineering Support Branch 81/02/13 2pp 07965 226.
 BiO3300316 Interim Significant Deficiency Rept 35 re heatin
ventilation & air conditioning fabrication & installation
Si; months required for evaluation Final rept will be
      Sis months required in the state of the stat
      KEMPER. J B
 DOCKET 50-353 LIMERICK GENERATING STATION. UNIT 2
  A Application/construction stage documents & correspondence
 8103190732 Ltrs to all licensees of operating plants, applic
     OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612. Forwards NRC position interim actions & request for add info
      EISEKHUT, D.G. Division of Licensing 80/12/22. 30pp.
  0103190387 Ltr to all licensees of operating plants & appl:
      CLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed
       involve cold shutdown, replacement parts & NUREG-0737.
      EISENHUT, D. G. Division of Licensing, 81/01/19. App
 8103120014 Ltr to all licenses of operating plants CP hole applicants except indian Point 2 & 3,2ton 1 & 2 & TMI-1.
       forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads
      EISENHUT. D.O. Division of Licensing. 81/02/03
  8103050951 Notification of 810311 & 12 meeting w/Mark II or
```

& GE in Bethesda.MD to discuss Mark II generic long-term

ANDERSON.C.J. Generic leaves Branch B1/02/12 12pp.

8103160669 Ltr to all operating plants % CP holders forward clarification of TMI Action Plan Item III A 1.2 re upgraud emergency support facilities Requests confirmation will be matched that implementation dates will be mat.

EISENHUT.D 9. Division of Licensing 81/02/18. 12pp.

8103250024 Ltr to all power reactor licensees & license ap MURGO-0619 criteria. Protnote 2 in Table 2 contains error to leakage testing deletions. Licensee may submit analysi justify use of existing low flow controller. EISENMUT. D D. Division of Licensing. 81/02/20 Bpp.

M&T3070

- BiG3170229 Ltr to all BWR licensees (except Numboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends % fitting nath per guidelines of encl Revision 1 to NUREG-M313 Model Tech Specs only encl EXSEM-M37.D G Division of Licensing 81/02/26 3pp
- --Bi031702cc Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ASME Code Class 1.2 & 3 components & RGS operational leakage limiting conditions for operation & surveillance requirements • General Electric Co. 81/02/26 App.
- 8103170655 Ltr to holders of CPs & applicants for OLs (BWRs) requesting review of ASME Class 1.2 & 3 pressure boundary piping, safe ends & fitting math per guidelines of encl Revision 1 to NUREC-0313 Model Tech Specs only encl ESESHAUT. D 9 Division of Licensing 81/02/26 3pp
- Bio3230813 Generic Ltr 81-06 to all CP holders & OL applicants re IOCFR90 71(e). 'Poriodic Updating of FBARs." effective BOO722 Info re FBAR legal status format & content encl ETSE:MUT.D 0 Division of Licensing Bi/02/26 10pp
- B103120093 Forwards request for add1 info re Amend 24 to PSAR Util must provide surmary of various efforts to identify causes of low strengths at 29 days
  TEDESCO.R L Assistant Director for Licensing 81/02/27 3pp
- Dio3120601 Notification of Bio313 weeting w/Mark II numers group in Bethesia. MD to discuss Mark II safety relief valve loads & post terp limits
  SM.T.K. Generic Issues Branch 81/03/03 2nd
- B103120404 Forwards summary of B10119 deeting W/ACDRN re const & licensing of facility Public reeting should be considered in developing rulemaking process for siting critoria DENICH.H R Office of Nuclear Reactor Regulation. Director 91/03/05 16 07906 1/2
- --8103120411 Summary of 810119 meeting w/ACORN in Philadelphis.PA reconst & licensing of facility SCLUS-D Licensing Franch 2 81/02/03 2pp 07906 193
- 0103130503 Responds to NUREO-0737. Item 1 0 1.re law power test program BAR owners group is developing generic program which will be adhered to Bignificant plant transients will be performed once w/licensed personnel REMER. J 5 Philadelphia Clectric Co 01/03/06 2pp. 07911:209.
- 8103310804 Ltr to all licensees of operating plants applicants for Ois 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISSEMUT. D. 9. Division of Licensing 81/03/10 App
- 8103200444 Forwards Suppl 2 to NUREO-0487. "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria" & policy, issue paper Suggests Mar 1981 desting u/Mark II owners to discuss review program W/o encl KNIEL K Jeneric Issues Branch 81/03/16. 1p. 63134:218
- Bro3190863 Forwards acceptance review copy of Amend 25 to license application, consisting of FBAR, emergency plan, fire protection evaluation rept & probabilistic risk assessment BRADLEY, E. J. Philadelphia Electric Co. BI/O3/17 2pp. 65128 334
- --8:03:90366 Acceptance review copy of Amend 25 to OL application, consisting of FSAR.emergency plan, environ rept fire protection rept & probabilistic risk assessment.

  BOYER: V B Philadelphia Electric Co BI/03/16. 11pp 65:28:336
- G103190569 Forwards acceptance review copies of "Fire Protection Evaluation Rept" & "Probabilistic Risk Assessment." Vols 1 & 2. BRADLEY.E J. Philoselphia Electric Co. 81/03/17. 2pp.
- --8103190570 "Fire Protection Evaluation Rept."

   Philadelphia Electric Co 81/03/17 365pp.
- --8103190571 "Probabilistic Risk Assessment," Vol 1.
  Philadelphia Electric Co. 81/03/17 261pp
- --8103190574 "Probabilistic Risk Assassment." Vol 2 \* Philadelphia Electric Co 81/03/17 491pp.

- B103230652 Submits info on four items not contained in 810317 fina rept of facility probabilistic risk assessment including site specific liquid transport population data for yr 2000, site specific meteorology & preliminary supporting info. BRADLEY.E J. Philadolphia Electric Co. 81703718 2pp. 07979
- 8103260604 Advises that requested design info will be provided, per NUREG-0737 litem [][ A [ 2. in connection u/facility IIL application review process KEMPER. J 8 Philagelphia Electric Co 61/03/20 lp.
- 8103316914 Summary of 810313 meeting a/Mark II owners group re suppression pool temp limit & 1-quencher load spec H/o encl list of attendees & reeting handout SU.T M Generic Issues Branch 81/03/24 3pp 08061 115
- C Utility Environmental Report (ER), amends & correspondence
- 8103190650 Forwards acceptance review copy of environ rept.Vols 1-Licerick Units 1 & 2 BRADLEY.E J. Philadelphia Electric Co. 81/03/17 2pp
- --BIG3190652 Acceptance review copy of environ rept.Vol |.for Limet Units | 1 2 • Philadelphia Electric Co | 81/03/17 | 400pp
- ---8103190693 Acceptance review copy of environ rept.Vol 2.for Line Units 1 & 2 • Philadelphia Electric Co. 81/03/17 300pp
- --8103190656 Acceptance review copy of environ rept.Vol 3.for Line Units 1 & 2 • Philadelphia Electric Co 81/03/17 400pp
- --8103190659 Acceptance review copy of environ rept.Vol 4. for Limet Units 1 & 2 > Philadelphia Electric Co 81/03/17 (85op
- D. NRC Draft/Fine) Environmental Btatoments, supple & correspondent
- 8103170599 Requests notices of intent & of any scoping meetings re & FEB for Pecility, on behalf of DE Hater Emergency Group, Bucks County Audubon Boclety, Bucks County Land Use Task Force, Linerick Ecology Action, et al LOCKHOOD, H. A. Lockwood, Reid & Bolger, 81/03/11 lp.
- --BiO3170602 Responds to B01215 littine preparation of EIS for fact:
  NRC will specifically consider info & data developed subsequent to issuence of FES for CP DES & FES will be issued after completion of review.
  TEDESCO.R L Assistant Director for Licensing. B0/12/16. 1p
- F Security, medical, energency & fire protection plane
- B10331053B Ltr to all licensues of operating plants & holders of Cf forwarding NUREO-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements.11/o encl EISEKHUT.D.O Division of Licensing. 81/03/05 6pp.
- 8103190563 Forwards acceptance review copy of Amend 25 to license application.comsisting of FBAR.emergency plan.fire protection evaluation rept & probabilistic risk assessment. BRADLEY.E. J. Philadelphia Electric Co. 81/03/17. 2pp
- --G103190566 Acceptance review copy of Amend 25 to OL application. consisting of FSAR.emergency plan, environ rept.fire protection rept & probabilistic risk assessment. BOYER.V. S Philadelphia Electric Co 81/03/16. hipp.
- 8103190569 Forwards acceptance review copies of "Fire Protection Evaluation Rept" & "Probabilistic Risk Assessment." Vols 1 & 2. BRADLEY & J. Philadelphia Electric Co. 81/03/17. 2pp
- --9103190970 "Fire Protection Evaluation Rept."
   Philadelphia Electric Co. 81/03/17. 365pp
- O Adjudicatory correspondence
- 8103170999 Requests notices of intent & of any scoping meetings re & REB for facility, on behalf of DR Water Emergency Group, Bucks County Auduban Society, Bucks County Land Use Task Force-Limerick Ecology Action.et al LOCKWOOD, H.A. Lockwood, Reid & Bolger. 81/03/11 1p. 07925:17

- --B103170402 Resconds to 801215 ltm re preparation of EIS for facility 103170602 Responds to 801215 ltr re preparation of EIS for facilit NRC will specifically consider info & data developed subsequent to issuance of FES for CP DES & FES will be jysued after completion of review TEDESCO.R.L. Assistant Director for Licensing 80/12/16 ip. 07925 177
- M. Congral correspondence
- BIOBLA0777 FDIA request for it categories of documents refacility KANNER, A Berger, D. 81/02/13 320 07915 220
- B103050989 Responds to B10108 ltr forwariing City Council of Philadelphia B00529 Resolution 169 Jacanding halt of facility constitts & resolution will be retained in files for consideration in DL application review. DENTON.H R. Office of Auclean Reactor Regulation, Director BI/O2/19. 229 07831 346.
- 8103130409 Forwards constituent 8 Johnson 810227 ltm,re lack of facility evacuation plan. For response Related correspondence HALKER, R S. Hause of Rep. 61/02/24. 2pp 07911; 203
- B103200354 Responds to B01215 ltr to editor Util has not yet applied for DL.Licensing process will take at least two yes Public hearings will be held Ltr to editor encl.

  TEDESCORR L. Assistant Olirector for Licensing. B1/02/25. 3pp 07771 035.
- 8103170100 Responds to 810116 ltm re 0\_ proceedings for facilities As ticeneing review proceeds, opportunities for add meetings will be presented TEDESCO.A.L Assistant Director For Licensing 81/03/03 2pp 07935 359
- 8103160773 Partial response to FOIA request for \$1 categories of IUSISU//S Partial response to FDIA request for II categories documents re facility Forwards documents listed in App A Search is currently underway for addI documents W/o encl NURCO-0625. "Rept of Sitting Policy Task Force." FELTON.J.M. Division of Rules and Records. 81/03/05 2pp. 07915-218
- 8103190023 Responds to 801223 ltr re facility. Public meetings will be scheduled after CL application is submitted & accepted issues nated in itr will be addressed in future safety & environ reviews
  TEDESCO,R L. Division of Licensina B1/03/09 is 07960.108
- Bio3230257 Advises that util is espected to submit OL application which assessment rept in Mar or Apr 1981, in response to 810211 ltr TEDESCO.R | Assistant Director for Licensing 81/03/09 in
- --8103230263 Requests info re submittal of risk assessment rept & effects of blasting at nearby quarry.
  LEMISH Affiliation Unknown. 81/02/11. 1p.
- 6103190132 Ack receipt of 801215 ltr re concrete pours & blasting near Actilities When FR notice for DL application is published, patition to become party to proceeding may be requested.

  EIBENHUT. D @ Assistant Director for Licensing 81/03/10 3pp 07965 106
- 8103230497 Responds to 810208 ltr opposing const of power plants No DL will be issued until emergency plans approvad. Util requested to perform risk assessment study to be submitted w/application for OL TEDESCO.R. L. Assistant Director for Licensing. B1/03/16 2pp. 07977-266
- --8103230464 Notifies that members of Citizen Action in Northeast opposed to comet of power plants Requests swergency planning hearing be held in Philadelphia. PA. Recommends alternative sources of energy ROBENBERG, A. Citizen Action in the Northeast 81/02/05. 3pp.
- 8103270703 Expresses concern re startup of facilities. TREBBITT-N.H. Appillation Unknown. 81/03/20. Ip
- f. Financial information
- 8103170584 Forwards Annual Financial Rept 1980. BRADLEY, E. J. Philadelphia Electric Co. 81/03/13. 7pp.
- --8103170596 Annual Financial Rept 1980. Public Service Electric & Gas Co. of New Jersey. 81/02/16.
   52pp.

- --- 8103170606 Annual Financial Rept 1980 Philadelphia Electric Co 81/03/13
- --8103170616 Annual Financial Rept 1980

   Atlantic Flortric of New Jersey 81/03/13 40cp
- --8103170626 Annual Financial Rept 1980 \* Delmarva Power & Light Co 81/03/06 40pp
- A Utility Final Safety Analysis Report (FSAR) & amenda
- 8103190326 Forwards acceptance review copy of Limerick Units 1 & 2 3840LEY.E J. Philadelphia Electric Co. 81/03/17 2pp
- --8103190539 Acceptance review copy of Limerick Units 1 & 2 FBAR
   Philadelphia Electric Co 81/03/17 5700pp
- 8103190534 Acceptance review copy of Chapter 1 to Limerick Units i FSAR. "Introduction & General Description of Plant " Philadelphia Electric Co 81/03/17 225pp.
- 8103190939 Acceptance review copy of Chapter 2 to Limerick Units 1 FSAR, "Site Characteristics + Philadelphia Electric Co. 81/03/17 375pp
- 8:03:90942 Acceptance review copy of Chapter 3 to Limerick Units & FSAR. "Design of Structures Components Equipment & Sys " . Philadelphia Electric Co. 81/03/17. 800pp
- 8103190345 Acceptance review copy of Chapter 4 to Limerick Units 1 FBAR, "Reactor Philadelphia Electric Co 81/03/17 125pp
- B103190547 Acceptance review copy of Chapter 5 to Limerick Units 1 FBAR, 'RCB & Connected Sus " FSAR, 'RCB & Connected Sys "

  Philadelphia Electric Co 81/03/17 175pp.
- 8103190549 Acceptance review copy of Chapter & to Limerick Units I FBAR. "Engineered Bafety Features" \* Philadelphia Electric Co 81/03/17 350pp.
- 8103190552 Acceptance review copy of App 6A to Limerick Units 1 & FSAR. "Subcompartment Differential Pressure Considerations."
   Philadelphia Electric Co. 81/03/17 35pp
- B103190955 Acceptance review copy of Chapter 7 to Limerick Units PSAR, "Instrumentation & Controls." \* Philadatphia Electric Co 91/03/17 800pp.
- 8103190536 Acceptance review copy of Chapter 8 to Limerick Units : FSAR, 'Electric Power'"

  Philadelphia Electric Co 81/03/17, 135pp.
- 8103190598 Acceptance review copy of Chapter 9 to Limerick Units | | FSAR: "Au:llieny Bys " | e Philadelphia Electric Co | Bt/03/17 | 700pp
- 8103190560 Acceptance review copy of Chapter 10 to Limerick Units
- FSAR, Steam & Power Conversion Sys. # Philadelphia Electric Co. 81/03/17 90pp.
- 8103190563 Forwards acceptance review copy of Amend 25 to license application.consisting of FBAR emergency plan.fire protection evaluation rept & probabilistic risk assessment. BRADLEY.E J. Philadelphia Electric Co. 81/03/17. 2pp.
- --8103190366 Acceptance review copy of Amend 25 to OL application consisting of FSAR emergency plan.environ rept.fire protection rept.\$ probabilistic risk assessment 80YER-V S Philadelphia Electric Co 81/03/16. https://doi.org/10.1007/16.
- B103190577 Acceptance review copy of Chapter 11 to Limerick Units FBAR. "Redwaste Mgt." Philadelphia Electric Co. B1/03/17. 200pp
- 8103190592 Acceptance review copy of Chapter 12 to Limerick Units FSAR. "Radiation Protection." \* Philadelphia Electric Co. 81/03/17. 300pp
- 8103190585 Acceptance review copy of Chapter 13 to Limerick Units FBAR. "Conduct of Operations" » Philadelphia Electric Co. B1/03/17 120pp.

## DOCKETED ITEMS

- 8103150588 Acceptance review copy of Chapter 14 to Limerick Units 1 & 2 FSAR, Initial Test Program • Philadelphia Flettric Co. 81/03/17 100oo
- 8103190591 Acceptance review copy of Chapter 15 to Limerick Units 1 % 2 ECAR 'Accident Analysis Philadelphia Electric Co 81/03/17 450pg
- 8103190594 Acceptance review copy of Chapter 14 to Limerick Units | & 2 FEAR, "Tech Specs
- Philadelphia Electric Co 81/03/17 2no 8103190598 Acceptance review copy of Chapter 17 to Limerick Units 1 & 2
- Philadelphia Electric Co. 81/03/17 125nm
- 8103190602 Acceptance review copy of App A to Limerick Units 1 & 2 FBAR. "Interfaces for Std Designs".
   Philadelphia Electric Co. 81/03/17 ip
- B103190605 Acceptance review copy of suppl to Limerics Units 1 % 2 F5AR. "Responses to NRC Questions" Folders anly encl # Philadelphia Electric Co = 81/03/17. 28pp
- 'A Antitrust correspondence
- 8103310413 Requests info identified in Reg Guide 9 3 re significant changes occurring subsequent to previous CP antitrust FB 1 V B J
  - TOALSTON A Utility Finance 81/03/26 3pp 08059 302 Utility Finance Branch (formerly Antitrust & Indemnito)
- 9 Inspection reports. IE Bulletins & correspondence
- 8103090080 Forwards agenda for IE mgt 810127 meeting in Philadelphia, PA to discuss assessment of regulatory performance re facility corst GRIER, B. H
  - Region 1, Philadelphia. Office of the Director BI/01/22 200 07852 142
- 8103100252 Responds to IE Dulletin 80-16. "Potential Misapplication of Rosembunt, Inc. Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " OE has ordered surveys of transmitters Status rept expected by 810430. KEMPER, J.S. Philadelphia Electric Co. 81/01/30. 2pp. 07863 208
- 8103200356 Ack receipt of 810120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-20 &
  - CARLSCN.R F Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 01/02/03 1p. 07970-056
- --8103200065 Responds to NRC 801217 ltr re violations noted in IE Insp Repts 50-352/80-20 % 50-353/80-18. Corrective actions: obtained disposition & authorization to rework weld preparation Training session held to explain requirements KEMPER, J B Philadelphia Electric Co 81/01/20 3pp. 07970 057
- --8103200071 Forwards IE Insp Repts 50-352/80-20 & 50-353/80-18 on 801104-28 % notice of violation CARLSCN R. T Region 1. Philade CARLSCY, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/12/17 2pp 07970:060.
- --8103200084 IE Insp Repts 50-352/80-20 & 90-353/80-18 on 801104-28 Noncompliance noted pipe weld preparation ground into base metal w/o GE authorization & undercut exceeded Tech Specs on featuater pipe restraint.

  DURR, J.P. Region I. Philadelphia. Office of the Director.

  MATIA.J.C. Region I. Philadelphia. Reactor Construction &

  Engineering Support Branch. 60/12/16. 9pp. 07970:064.
- 8:03030398 Forwards Suppl 5 to 1E Sulletin 80-17, "Failure of Control Rods to Insert During Scram at BNR. " No written response GRIER B.H Region 1. Philadelphia, Office of the Director. 81/02/13 1p. 07795-008.
- 8103390186 Forwards IE Mgt Meeting Repts 50-352/81-03 & 50-353/81-03 on 810127. No noncompliance noted. GRIER, B. H. Region 1. Philadelphia, Office of the Director. 81/02/19 ip 08037 123.
- --B103300193 IE Mgt Meeting Repts 90-352/81-03 & 50-353/81-03 on 810127 No noncompliance noted Areas discussed results of systematic

- 81032D0213 Forwards IE Circular Bi-03, 'Inoperable Seismic Monitorin Instrumentation' No written response required. GRIER.B H. Region I. Philadelphia, Office of the Director Bi/03/02 ip 07966-200
- 8103230230 Forwards revised IE Bulletin Bi-Oi, 'Burveillance of Mechanical Snubbers. W/corrected Pages 5 % 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements GRIER.B H Region 1. Philadelphia. Office of the Director 81/03/04 ip 07977 262
- B103270015 Submits add1 response to IE Bulletin 80-16 re potential misapplication of Rosemount transmitters GE currently issuing field disposition instructions for 1150 Resembnt MEMPER. J S Philadelphia Electric Co 81/03/05 3pp. 08047:097
- 8103200175 Forwards IE Info Notice 81-06. "Failure of ITE Model K-60 Circuit Breeker" No response required GRIER.B II Region 1. Philadelphia. Office of the Director 81/03/11 1p 07968 307
- 8103300309 Responds to NRC 810227 Itr re violations noted in IE Insp. Repts 50-352/81-01 & 50-353/81-01 Corrective actions. nandestructive testing indications documented & open rework MEMPER, J. B. Philadelphia Electric Co. 81/03/23 600 08057-149
- S Reportable occurrences. LERs & related correspondence
- 8103100165 Ack receipt of 801230 final Significant Deficiency Rept 18 PASSE belts nuts & study obtained from unapproved sources.

  CARLEDON: R T Region I. Philedelphia. Reactor Construction & Engineering Support Dranch. B1/02/02 ip 07863-339
- 8103100269 Ack receipt of 810113 final Significant Deficiency Rept 29 CARLSDN.R. T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 81/02/06 ip 07863-202
- 8103190704 Ack receipt of 801217 final Bignificant Deficiency Rept 15 tographic Ack receipt or SULETY final Bignificant Deficiently in eviolations of separation criteria in power generation control complex Rept not acceptable Requests date when final rept will be filed, if sufficient info is not available now. CARLSDIAR T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 81/02/13 2pp. 07968: 226
- 9103300316 Interim Bignificant Deficiency Rept 35 re heating, ventilation & air conditioning fabrication & installation. Bix months required for evaluation Final rept will be forwarded by Blo930 REPRESENTED BY BOST 151 BENEFIT OF BIYOS SPP. 08057:151
- DGCKET 30-354 HOPE CREEK NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for Ots & holders of CPs to control of heavy loads. Requests review per guidelines in NURE9-0612. Forwards NRC position re interim actions & request for addl info.
  EISENMUT.D. Q. Division of Licensing 80/12/22. 30pp.
- Bi031903B7 Lin to all licensess of operating plants & applicants for Dis & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown, replacement parts & NUREG-0737. EIBENHUT, D. G. Division of Licensing. 81/01/19. Opp.
- B103120014 Ltr to all licensees of operating plants CP holders & OL applicants except Indian Point 2 & 3.Zion 1 & 2 & TMI-1. forwarding inadverbently unitted pages from NRC B01222 request for addl info re control of heavy loads. EIBENHUT.D.O. Division of Licensing. B1/02/03. 6pp.
- B103140669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met. EISENHUT.D.O. Division of Licensing. B1/02/18. 12pp.
- 0103250024 Ltr to all power reactor licenses & license applicants re NUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licenses may submit analysis to

- BiO3170229 Ltr to all BER licensees (except Humbolst Bay & LaCrosse) 103170229 Ltr to all MAR licensees (ercept Humbolist Mey & Lati requesting review of ASMC Cost Class 1 & 2 pressure bouncary piping, safe ends & fitting catl per guidelines of end! Revision 1 to NOREG-0313 Model Tech Specs only end! EISEMANI, D G Division of Licensing 81/02/2b. 3pp.
- --8103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re surveillance requirements for ASME Code Class 1.2 & 3 components & ACS operational leakage limiting conditions for operation & surveillance requirements

  # General Electric Co 81/02/26 4pp
- BIO3170655 Ltr to holders of CPs & applicants for Obs (BWRs) requesting review of ASME Class 1.2 & 3 pressure boundary piping, safe ands & fitting mather guidelines of encl Revision 1 to NAREO-0313 Model Tech Space only and EISENHUT, D. G. Division of Licensing. BI/02/26 3pp
- 8103230813 Owneric Ltr 81\*06 to all CP holders & OL applicants re 10CFR50 78(e). "Periodic Updating of FBARs." effective 800722 info re FSAR legal status format & content encl EISENHUY.D Q Division of Licensing 81/02/26 10pp
- 8103230973 Notifies of issuance of NUREG-0757, "Radon Releases From U Bining & Milling & Calculated Health Effects." which contains new info potentially relevant & matl to ASLAB proceedings
  TERRY 4 A Division of Fuel Cucle & Material Safety. 81/02/26 200
- 8103310804 Ltr to all licensees of operating plants applicants for 0.s & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical \*auipmant EIBENHUT, D. Q. Division of Licensing 81/03/10 App
- 8103270095 Surmary of 810304 ceeting w/Mark I owners group & OE in Bethesda-MD re supplementary tests conducted in Full-scale test facility & resolution of outstanding Mark I issues per NURES-0661 Blide presentation & list of attendees encl GRIMES,C | Licensing Branch 3 81/03/16 5pp
- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method meeting NRC requirements. H/o encl. EISEKHUT, D. G. Division of Licensing. 81/03/05. App.
- I Financial information
- 8103170584 Forwards Annual Financial Rept 1980 BRADLEY, E. J. Philadelphia Electric Co 81/03/13 700
- --8103170596 Annual Financial Rept 1980

  \* Public Service Electric & Oas Co. of New Jersey. 81/02/16.
- --B103170606 Annual Financial Rept 1980. Philadelphia Electric Co 81/03/13. 45pp
- --8103170616 Annual Financial Rept 1980. \* Atlantic Electric of New Jersey 81/03/13. 40pp.
- --8103170626 Annual Financial Rept 1980.

   Delmarva Power & Light Co. 81/03/06 40pp.
- G Inspection reports. IE Bulletins & correspondence
- 8103180674 Forwards IE Insp Rept 50-354/80-22 on 801204, 13, 22 & 31. No carLSON.R.T. Region i Philadelphia Reactor Construction & Engineering Support Branch. 81/01/21. 2pp. 07949:267
- --8103180678 IE Insp Rept 50-354/80-22 on 801204.13.22 & 31.No noncompliance noted Major areas inspected quality-related procedures, specs & equipment w/observations made of transporting lifting & setting of reactor pressure vessel.

  BANDERS-W F . MCBREARTY.R.A Region I. Philadelphie. Office of the
  Director. TRIPP.L.E. Region i. Philadelphie. Reactor Construction
  & Engineering Support Branch. 81/01/20. 4pp. 07949:269.

- 8103240736 Requests extension until 810207 to respond to Suppl 3 of IE Bulletin 79-018. "Environ Qualification of Class IE Equipment," to equipment required to achieve & maintain cold shutdown UDERTY.R A Public Service Electric & Gas Co. of New Jersey 81/21/30 2pp 07990 022
- 8:03030290 Forwards Suppl 9 to 1E Builetin 80-17. "Failure of Contro Rods to Insert During Scram at BUR." No written response GRIERLB M Region L. Philadelphia. Office of the Director 91702/13 ip 07790 337
- 8103300520 Forwards IE Mgt Meeting Repts 50-354/81-03 & 90-355/81 C CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 81/02/26. 2pp 08058 067
- --B103300520 IE Mat Meeting Repts 50-354/81-03 & 50-355/81-03 on UIC Areas discussed performance of piping subcontractor & recent licensee responses to items of noncompliance ALLEAGUE RESPONSES to Items or noncompliance
  BATEMAN, W.H., REYNULDS-S.D., Region 1, Philadelphia, Wefice of t
  Director TRIPP.L. E. Region 1, Philadelphia, Reactor Construct
  & Engineering Support Branch. 81/08/25. 3pp. 08058 0649
- 8103209203 Forwards IE Circular B1-03. "Inoperable Resemic Hunstarts Instrumentation" No written response required GRICR.B H Region 1. Philadelphia. Office of the Director B1/03/02 ip 07966 195
- 8103230237 Forwards revised IE Bulletin Gi-O1. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities c/CPs to which builtetin is applicable does not affect util requirements GRIER.B H Region I, Philadelphia, Office of the Director B1/03/04. Ip. 07977 204
- 8103200137 Forwards IE Info Notice 81-06. "Failure of ITE Mudel x 60 Circuit Breaker " No response required. CRIER.B H. Region I. Philadelphia, Office of the Director. 81/03/11. 1p 07968 274
- 8 Reportable occurrences, LERs & related correspondence
- 8103190113 Finel potential significant deficiency rept to Pipe CA 19 MC 70. initially reported on 801007 Pipe acceptable as delivered & not reportable per 10CFR50. 89e. Pipe seam parosity repaired.
  MARTIN. T J Publi Public Service Electric & Qas Co. of New Jersey 81/01/27. 2pp 07960 234
- 8103100145 Ack receipt of 801229 final rept re-potential significant deficiency of subsembly of biological shield.
  CARLSON,R T. Region 1. Philadelphia, Reactor Construction &
  Engineering Support Branch. 91/02/02 ip. 07869:350.
- --8103100151 Final rept re-potential significant deficiency of subassembly of biological shield, initially reported 800701 Item found not reportable
  MARTIN.T J Public Bervice Electric & Qas Co. of New Jersey
  80/12/29 2pp 07865 359.
- 8103160222 Act receipt of Bi0127 ltr forwarding Final defirtency re-re SA-135 KC 70 pipe Matter will be reviewed during subsequent insp CAREBON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 81/02/13. 1p. 07718:345
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8103190732 Litra to all licensees of operating plants, applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re

interim actions & request for addl info.

- EISENHUT, D. G. Division of Licensing. 80/12/22. 3000.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPS re-program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown replacement parts & NUREO-0737. EISENHUT, D. O. Division of Licensing. 81/01/19. 6pp

8103120014 Ltr to all licensess of operating plants, CP holders & OL applicants, except indian Point 2 & 3.2 ion 1 & 2 & TMI-1, forwarding inserversettly undiffer each series and MAC R01232

- BiO3160669 Ltr to all operating plants & CP holders forwarding clarification of THI Action Plan Item III A 1 2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be ret EISEUHUT.0 0 Division of Licensing Bi/O2/18 12pp
- G100250024 Lit to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leekage testing deletions Licensee may submit analysis to justify use of eristing low flow controller EISEN-VI-0 Q Division of Licensing 81/02/20 Bns
- B103170229 Ltr to all BMR licensess (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping: safe ends & fitting matl per guidelines of encl Revision 1 to NUREO-0313 Model Tech Specs only encl EISEN-MULT.D Q. Division of Licensing B1/02/26 3ps
- --8103170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4-8 Te surveillance requirements for ABHE Code Class 1.2 % 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements • Otheral Electris Co. 81/02/26 4nn
- B103170655 Ltr to holders of CPs & applicants for Ols (BHRs) requesting review of ASME Class 1-2 & 3 pressure boundary piping, safe ends & fitting mat1 per guidelines of enci Revision 1 to NUREC-0313 Model Tech Specs only enci EISENHUT D & Division of Licensing B1/02/26 3pp.
- 8103230813 Generic Ltr 81-06 to all CP holders & DL applicants re 10CFRSO 71(e). "Periodic Updating of FSARs." effective 800722 info re FSAR legal status format & content encl. E1SENHUT: D O Division of Licensing. 81/02/26 10pp
- 8103230973 Notifies of issuance of NUREG-0757, "Radon Releases From U Mining & Milling & Calculated Health Effects." which contains new info potentially relevant & mail to ABLAD proceedings
  TERRY. O A Division of Fuel Cycle & Material Safety 81/02/26.
- 8100010804 Ltr to all licensees of operating plants applicants for CLs & holders of CPs forwarding SECY-81-119 re info necessary to establish snorron qualification of safety-related electrical equipment EISCH-UT.0 Q Division of Licensing. 81/03/10 600
- B103270095 Bummary of B10304 meeting w/Mark I coners group & GE in Bethasda.MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREC-0061 B1ide presentation & list of attendees encl GRIMES-C.I. Licensing Branch 3 B1/03/16 Spp
- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements. (My encl EISENHUT.D G. Division of Licensing. 81/03/05 6pp

#### I. Financial information

- 8103170584 Forwards Annual Financial Rept 1980 BRADLEY/E J Philadelphia Electric Co 81/03/13. 7pp.
- --8103170596 Annual Financial Rept 1980

   Public Service Electric & Que Co. of New Jersey. 81/02/16.
  92aa
- --8103170606 Annual Financial Rept 1980

  \* Philadelphia Electric Co. 81/93/13. 46pp.
- --8103170616 Annual Financial Rept 1980.

  \* Atlentic Electric of New Jersey. 81/03/13. 40pp.
- --8103170626 Annual Financial Rept 1980. \* Deimerva Power & Light Co. 81/03/06 40pp.
- G. Inspection reports. IE Bulletins & correspondence
- 9103240736 Requests extension until B10209 to respond to Suppl 3 of IE Bulletin 79-018. "Environ Gualification of Class IE Equipment." re equipment required to achieve & maintain cold shutdown.
  UDERITZIR.A. Public Service Electric & Gas Co. of New Jersey.
  81/01/30 2pp.

- 8103030290 Forwards Suppl 5 to IE Builetin 80-17. 'Failure of Con Rods to Insert During Scram at BWR " No written response required. GRIER.B H Region 1. Philadelphia. Office of the Director 61/02/13 ic 07790.337.
- 8103300520 Forwards IE Mgt Meeting Repts 50-354/81-03 & 50-355/81-810209 CARLEON R. T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 81/02/26 2pp 08058 067
- --9103300528 IE Mgt Meeting Repts 50-394/81-03 & 50-355/81-03 on Areas discussed performance of piping subcontractor & recent licensee responses to items of noncompliance.

  BATEMAN. W. H. REYNDLDS. S. D. Region 1. Philadelphia. Office of Director TRIPP. L. E. Region 1. Philadelphia. Reactor Construct Engineering Support Branch 81/02/25 3pp 08058 069
- B103200203 Forwards IE Circular B1-03, "Inoperable Saismic Monitor Instrumentation " No written response required GRIER: B H Region I. Philadelphia, Office of the Director B1/03/02 ip 07966:195.
- 8103230237 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Shubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements GRIER.B II. Region 1. Philadelphia, Office of the Director 81/03/04. Ip. 07977: 264.
- B103200137 Forwards IE Info Notice 81-05, 'Failure of ITE Model K-Circuit Breaker " No response required. ORIER:B H. Region 1, Philadelphia, Office of the Director B1/03/11. 1p 07958: 274.
- 8. Reportable occurrences. LERs & related correspondence
- 8103190113 Final potential significant deficiency rept re Pipe BA-KC 70 initially reported on 801009 Pipe acceptable as delivered & not reportable per 10CfRSO 55e. Pipe seam porosity repaired MARTIN.T. J. Public Bervice Electric & Gas Co. of New Jersey. 81701/27. 2pp 07950 234.
- 8103160222 Act receipt of 810127 ltr forwarding finel deficiency r re BA-155 KC 70 pipe, Matter will be reviewed during subsequent insp. CARLSON,R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch Bi/02/13. 1p. 07918:345.
- 8103160243 Ack receipt of 810127 ltr forwarding final deficiency resurface indication RPV 2 Matter will be reviewed during next insp CARLSON,R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 81/02/13 1p 07918.358
- 8103200497 Ack receipt of 810127 final deficiency rept re surface indication on Reactor Pressure Vessel 2 CARLSON.R T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 81/02/15. 1p 07967.024.
- --Bi03200505 Final deficiency rept relared noted on Reactor Pressurvesel 2 which included pocosity & linear indications approx one-inch in diameter, initially reported 791213 Investigation revealed that item is not significant deficiency.

  MARTIN-T.J. Public Service Electric & Oas Co. of New Jersey.
  Bi/01/27. 2pg. 07967-025.
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR
  P Operating license stage documents & correspondence
- B103060501 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/02/2pp. 07836:081.
- O Inspection reports, IE Bulletins & correspondence
- B103020054 Forwards IE Circular B1-02, "Performance of NRC-License Individuals While on Duty." No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director. 81/02/2pp. 07787:205

- DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- Bip3190732 Ltre to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position resisterim actions & request for add1 info EISENHUT, D O Division of Licensing 80/12/22 30pp
- BiO31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical aculpment liters addressed involve cold shotdown replacement parts & NUREG-0737 EISERHUT. D. O Division of Licensing. BI/OI/19 5pp.
- Biodicould Lite to all licensees of operating plants.CP holders & OL applicants.e.cept Indian Point 2 & 3. Zion 1 & 2 & THI-1. forwarding inadvertently omitted pages from NRC BOIZZZ request for add1 info re control of heavy loads EISEFHWIT.D Q Division of Licensing BI/OZ/D3 App.
- BIO3050850 Lists allaged deficiencies which could peopardize health & safety of public as reported by Govt Accountability Project Expresses concern over reanner in which second NRC investigation will be performed MEYER.C R Physicians for Social Responsibility. BI/02/11. 2pp 07828 [71.
- 8103050751 Notification of 810311 & 12 neeting w/Mark II cwners group & GE in Bethesda.MD to discuss Mark II generic long-term program ANDERBON.C J. Generic Issues Branch. 81/02/12 12pp. 07828 199.
- 8103:105ii Notification of 810223-27 meeting v/util at site to enable staff to propose preliminary evaluation of facility control room w/regard to human factors
  PELTIER, I.A. Licenstan Branch 2 81/02/12 3on 07869 358.
- 8103040465 Natification of B10316-20 meeting w/util corporate ofc remot structure & technical resources review Proposed agenda and.
  PETTIER 1. Licensing Branch 2 81/02/13. 5pp 07820 195
- 8103060104 Forwards request for add1 info re lestage from RHR suction valve nearest to suggression pool during post-LOCA long-term coaling TEOESCO-R L. Assistant Director for Licensing 81/02/13 3pp

07839 031

- B103030640 Notification of 810224-25 meetings u/util at site to reviec const status. Proposed agenda encl. PELTIER I.A. Licassing Branch 2. 81/02/18 6ss 07795.028.
- 8103050111 Requests that maint records for snubbers be documented represervice axam & preoperational testing. Util must verify that enubber location-orientation position setting & configuration are according to design drawings TEDESCO.R L. Assistant Director for Licensing 81/02/19 3pp. 078-39-034.
- B103100529 Forwards organizational charts depicting NRC Region 3 reorganization.efffective 810216. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/02/20 2pg. 07865:246.
- Bi03250024 Ltr to all power reactor licenses & license applicants re NAREG-0619 criteria Footnots 2 in Table 2 contains error due to leakage testing delations Licenses may submit analysis to justify use of existing low flow controller.

  EISENHUT D 0. Division of Licensing. 81/02/20 8pp.
- BiO3230030 Ltr to all licensees of operating nuclear power plants & applicants for QLs (except 8t Lucie,Units 1 & 2). Requests util review to determine capability to mitigate station blackout event 1, promptly implement emergency procedures EIBENHUT, D. Q. Division of Licensing. 81/02/23. Spp.
- 8:03:70225 Ltr to all BWR licensees lescept Humboldt Bay & LaCrosse) requesting review of ABME Code Class I & 2 pressure boundary piping, sefe ends & fitting matl per guidelines of encl Revision I to NUMEGO-03:3 Model Tech Specs only encl EISENHUT, D. O. Division of Licensing. 81/02/26. 3pp.
- --B103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re surveillance requirements for ABME Code Class 1,2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements. e Deneral Electric Co. B1/02/26. 4pp.

- B103170855 Ltr to holders of CPs & applicants for OLs IBMRs) re review of ASME Class 1.2 & 3 pressure boundary piping safe ends & fitting rati per guidelines of encl Revision I to NAMEG-0313 Model Tech Specs only encl EISE(HNJT. 0 0 Division of Licensing. 81/02/26 3pp
- B100239813 Opneric Lin 81-06 to all CP holders & DL applicants 10CFR90.71(e), "Periodic Updating of FSARs," effective B00722.1he'r re FSAR legal status.format & content encl EjsEK:WJT.0 0 Division of Licansing 81/02/26 10pp
- 8103;30601 Notification of 810313 meeting u/Mark II owners grow Bethesda.MD to discuss Mark II safety relief valve loads & goal temp limits SULF M Generic Issues Branch 81/03/03 2op 07912 136
- BJ03160245 Act receipt of 801201 ltr submitting info on low past turbline disc [nfo will be withheld (ref [00FR2 790] IF06860:R L. Agistant Director for Licensing BJ/03/03
- 8103230185 Confirms that add1 work on internals could proceed butil review & acceptance of OA documentation & procedures submitted by Reactor Controls for work applicable to vessel internals spec & other applicable design requirements 80A0MANNIE A Cintinnati Oas & Electric Co 81/03/04 2op 07997-277.
- B103100436 Submits law power testing & augmented operator train co-mitments to Thi task action item ( G ), in response to R Tedesco B10114 ltr BDRGMANN.E A Cincinnati Oas & Electric Co B1/03/03 2pp. 07867: 230
- 8103110763 Ack receipt of 810202 itr providing supplemental industrial schedule for review & mod of OA procedures, per 810107 request.

  NORELIUS. C. E. Region 3. Chicago, Office of the Director 10. 0.7873 399
- --B10311075B Supple B01204 ltr re schedule for review & mod of procedures.per B10107 request Consultant engaged for projects Mode to be compilated by B10415 BGROMANN.E A Cincinnati Oas & Electric Co B1/02/02. Ip 02073-360
- 8103110495 Forwards supplemental info re leak chase channel attachments, in response to NRC 801120 request BORGMANN, E.A. Cincinneti Ges & Electric Co. 81/03/06. 11pp 07882:147.
- B103120753 Notification of B10324-26 maetings w/util \$ BNW. In fL & Moscow.OH to review emergency operating procedures of Dresden simulator & Zimmer control room. PELTIER. I Licensing Branch 2. 81/03/06. 3pp 07905 300
- 8103310804 Ltr to all licensees of operating plants applicants to holders of CPs forwarding SECY-Bi-117 re info necessary to establish environ qualification of safety-related electrical equipment.

  218ENHUT. D 0. Division of Licensing. 81/03/10. 6pp
- 8103190145 Notification of 810314 meeting u/near-term GL applic Bathesda.MD re info required to be submitted on environ qualification of ejectrical equipment prior to site visit & NRC review. BURHELLS Licensing Branch 2. 81/03/12. 15pp.
- 8103200365 Summary of 810224-26 caseload forecast panel meeting at site re assessment of const status to determine licensing priority, manpower & resources allocation. Attendance lists & agenda encl. PELTIER. J. A. Licensing Branch 2. 81/03/12 8pp. 07966 324
- B103200405 Application to amend CPPR-8B to authorize extension completion date to B21231 BDROMANN.E.A. Cincinnati Gas & Electric Co. B1/03/16 3pp 07968-940
- 8103200444 Forwards Suppl 2 to NUREO-0487, "Mark II Conteinment Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper Suggests Har 1981 meeting w/Mark II owners to discuss review program W/o encl. KNIEL.K. Generic (sques Branch, 81/03/16, 1p. 65134:218
- 9103230195 Requests resolution of hydrogen control matter for d core accidents in plants w/srell containments. TEDESCOR L. Assistant Director for Licensing. 81/03/16

- 8103300281 Forwards 76 oversize P\$10s revised in FSAR.Revision 71. submitted 810327 List of P\$10 changes encl Aperture cards will be available in PDR AACKSOWAM Sargent & Lundy. Int 81/03/24 3pp 08057 191
- 8103310914 Summary of 810313 meeting w/Mark II owners group re suppression pool temp limit & T-quencher load spec. W/o encl list of attendees & neeting handout 5U.T ff Generic Issues Branch BI/03/24 3pp.
- SID310274 Responds to NRC 810316 request for add1 info to hydrogen control at facility Provisions have been made to inert containment w/nitrogen Bys will be in place & functional by commercial operation of station BCROMARK.E A Cincinnati Gas & Electric Co 81/03/26 1; 08078 391
- 8)03310383 Anend II5 to application for CL containing response to Round 2 questions in NRC 810114 ltr & Revision 71 to FSAR CCROMMEN.E A Cincinnett Gas & Electric Co 81/03/27 2pp
- E NAC Bafety Evaluation Report (SER), supple & correspondence
- B103200674 Requests info for SER & supplemental SER two was prior to SER date indicated on encl schedule Requests, four months prior to SER issuance, equipment qualification info per IE Bulletin 79-018, for SERs scheduled after June 1981.

  DENION, HR Office of Nuclear Reactor Regulation. Director 81/03/13 6pp. 07966 094
- F. Security, medical, energency & fire protection plans
- 8102040395 Forwards public version of emergency glan Includes State of CRI emergency plan. Clermont County, DH. State of KY. Campbell. Pandleton & Bracken Counties. KY. draft emergency plans (Plans submitted under separate cover ltr)
  BDRQMANN.E A Cincinnati Gas & Electric Co 81/01/30 2pp 07616 234
- --Bi02040399 Forwards facility emergency plan & State of CH nuclear power plant emergency response plan W/o encis.

  WETTERHARM J. Conner, Moore & Corber Bi/01/30 2pp

  O7546 236
- 81033i0330 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0676. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o enc! EISENHUT.0.0. Division of Licensing. 81/03/05 6pp.
- 8103170097 Releases public version of emergency plan for fecility FELTON.J M Division of Rules and Records 81/03/11 [p 07806 001
- --8103170186 Public version of emergency plan includes State of OH energency plan & Clermont County, DH. State of KY & Campbell, Pendleton & Bracken Counties, KY draft emergency plane.

  \* Cincinnati Gas & Electric Co. 81/01/30 1300pp. 07806:001.
- 8303261210 Requests that encl emergency planning info be placed in LPDR. W/o 8102040395 SOUDER. J L. Division of Rules and Records 81/03/24 lp. 63040:246
- BIO0310213 Forwards Revision 11 to industrial security plan Encl withheld (ref 100FR2 790). BOROMAN.E A Cincinnati Cas & Electric Co 81/03/25. 2pp. 08077:117
- Q Adjudicatory correspondence
- Bi02260292 Herorandum requesting applicants. NRC & intervenors to address listed questions in Bi0302 hearing liftnesses should be able to address questions on generic safety problems requiring shutdown & qualifying for inclusion in rate base. BECHHOEFER.C. Atomic Safety and Licensing Board Panel. Bi/02/23 3pp. 07770:050
- 8103050674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties. CHRISTERMURY.E. Hearings Division. 81/03/04. 2pp.
- 8103200510 Notice that GE Pattison is new county prosecuting atty & should be substituted for prior representative.R Jones.on all pleadings Certificate of Svc and pattibods. GE: FISSE, LR Clermont County, DH: 81/03/02. 3pp. 07971:011.

- 8103209511 Notice of withdrawal of appearance in OL proceeding due of conflict of interest Certificate of Svc encl FISSE.L R Zimmer Area Citizens - Zimmer Area Citizens of KV 81/03/02 2pp 07971 014
- 8103200343 Notice of appearance in OL proceeding Certificate of Svc encl PATTISON. 0 E. FISSEL R Clermont County. OH 81/03/02 4pp 07931 204
- B103249546 Schedule for filing proposed findings & conclusions.
  Applicants must file by B10424 Intervenors by B10605, NRC by
  B10702 & applicants' repty by B10903 Filings will not
  prejudice parties' right to seek reopening of record.
  BECHHOEFER.C Atomic Sefety and Licensing Board Panel 81/03/20
  2pp 07984 354

### H General correspondence

- 8103230835 Forwards 810305 ltm to emphasize importance of matter of irregularities at facility, per 801223 ltm 8hareholders resolution encl Response requested 10550.¢ Affiliation Unitnoum 81/03/10 5pp 07977 094.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8103310383 Amend 115 to application for CL containing response to Round 2 questions in NRC 810114 ltr & Revision 71 to FBAR BOROMANN.E A Cincinnati Gas & Electric Co 81/03/27. 2pp
- --B103310386 Amend 115 to FSAR.Revision 71.

  \* Cincinnati Gas & Electric Co. B1/03/31. 225pg.
- Q Inspection reports. IE Bulletins & correspondence
- B1030504B1 Forwards (E Insp. Rept. 50-358/80-26 on 801201-05,15-19, 22, 26 & 29-31 & notice of violation | EISHMAN.R.F. Region 3, Chicago. Reactor Operations Nuclear Suppo Branch B1/01/27 2p 07825-024
- --B1030504B9 Notice of violation from insp on B01201-05.19-19.22.26 29-31 HEISHMAN.R.F Region 3. Chicago. Reactor Operations Nuclear Support Brench B1/01/27. 1p. 07825.026
- --Bi03050499 IE Insp Rept 50-358/80-26 on 801201-05/15-19/22/26 & 29 Noncompliance noted failure to obtain & verify corrective action taken on procedure implementation deficiency. DANIELS.F.T., WARNICW.R.F., GHYNN.T.P. Region 3, Chicago, Offic of the Director. 81/01/23. App. 07825-027
- B103020133 Forwards IE Circular B1-02. 'Performance of NRC-Licensed Individuals While on Duty.' No written response required. KEPPLER.J G. Region 3. Chicago. Office of the Director. 81/02/09 2pp. 07788.038
- B103040308 Forwards IE Info Notice 81-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance W/10CFR50 72" No written response required.

  KEPPLER, J O. Region 3. Chicago. Office of the Director B1/02/12 2pp. 07815 280.
- 8103030283 Forwards Suppl 5 to 1E Sulletin 80-17, "Failure of Contro Rods to Insert During Scram at BMR." No written response required KEPPLER.J.O. Region 3- Chicago, Office of the Director. 81/02/13 2pp 07790 329.
- 8103190071 Forwards JE Inep Rept 50-358/81-01 on 810105-30 & notice violation. HEISHMAN R. F. Region 3. Chicago: Reactor Operations Nuclear Suppo Brench. 81/02/13. 2pp. 07964:141.
- --BI03190076 Notice of violation from insp on 810105-30. HEIBHHAN.R.F. Region 3. Ghicago. Reactor Operations Nuclear Support Branch 81/02/13. 1p. 07964:143.
- ---8103190082 IE insp Regt 50-358/81-01 an 810109-30.Noncompliance no fellure to follow procedure during control rod drive hydraulic preoperational test.

  DANIELS,F.T., GWYNN,T.P., WARNICK,R.F. Region 3, Chicago, Offic of the Director. 81/02/12. 6pp. 07964:144.
- 8103160488 Forwards IE Circular 81-03, "Inoperable Seismic Monitorin Instrumentation " No response required. KEPPLER, J. G. Region J. Chicago, Office of the Director. 81/03/02 2pp. 07915:305

- BiO3160038 Forwards revised IE Bulletin Bi-Oi, Surveillance of Mechanical Snubbers. W/corrected Pages 5 % 6 Change in identification of facilities J/CPs to which tulletin is applicable does not affect util requirements KEPPLER. J Q Region 3. Chicago. Office of the Director Bi/O3/04 20% 07914 214
- B103230115 Ack receipt of B10202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-16
  NGRELIUS.C E. Region 3. Chicago. Office of the Director B1/03/05
  ip 07976 247
- --8103230120 Supple response to NRC 810107 ltr re violations noted in 1E Insp Rept 50-358/80-16 Corrective actions outside consultant engaged to conduct thorough review of util E HJ Ketser Co QA procedures by 810227 Hods implemented by 810415
  BDRGMANNIE A Cincinnati Gas & Electric Co 81/02/02 1p
- 8103160976 Ack receipt of 810217 ltr informing NRC of steps taken to correct violations notes in IE Insp. Rept 50-358/80-26
  HEISHMAN.R F. Aegion 3. Chicago, Office of the Director B1/03/06 ip 07914 358
- --B1031609BA Responds to NRC B10127 ltr re violations noted in 16 insp Rept 30-358/B0-26 Corrective actions 0A procedure 18-0A9-01 revised providing add1 requirements for closing out util 0A audit findings EDROMAINALE A Cintinnati Gas & Electric Co B1/01/17 20p 07914 339
- 8103250138 Follows up 801230 Interim response to 16 Builetin 80-23. "Failure of Sciencid Valves Hfg by Valcor Engineering Corp."

  GE review concludes that no subj valves used in MSSS portion of equipment
  BDROMANN.6 A Cincinnati Oas & Electric Co 81/03/09 lp.
  0799-071
- 8103200352 Forwards |E Info Notice 81-06. "Failure of LTE Mode) R-600 Circuit Breater = No response required REPPLER.J. © Region 3. Chicago, Office of the Director. 81/03/11 2pp 07972 109
- BiO3200657 Forwards IE Info Notice Bi-03, "Degraded DC Sys at Palisades " No action required MEPPLER.J Q Region 3, Chicago, Office of the Director Bi/03/13 Zpp 07766 153
- B103200306 Forwards IE Info Notice 81-07. "Potential Problem W/Mater-Soluble Purge Dam Matis Used During Inert Gas Walding " No response required.
  KEPPLER.J. G. Region 3. Chicago, Office of the Director. 81/03/16
  Zpp. 07966-250.
- T Hearing transcripts on non-entitrust matters
- BiO3110374 Transcript of BiO302 hearing in Cincinnati.OH. Pp. 3.609-4.145.

  \* Atomic Bafety and Licensing Board Panel. Bi/03/02. 350pp.
  07886-192.
- 8103110290 Transcript of 810303 hearing in Cincinneti. DH Pp 4.146-4.389. • Atomic Safety and Licensing Board Panel. 81/03/03 240pp 07878: 226
- 8103110399 Transcript of 810304 hearing in Cincinnati, DH. Pp. 4, 386-4, 642 • Atomic Bafety and Licensing Board Panel. 81/03/04, 257pp. 07875, 035
- U Congressionel/Executive Correspondence
- 8103240091 Forwards fourth monthly status rept to Congress for 810115-0215. Rept discusses actions taken on licensing reviews of new facilities. Rept will be amended to include addl info requested on 810217.
  KAMMERER-C. Office of Congressional Affairs. 81/02/27. 3pp.
- 8103180529 Urgas acceleration of hearing schedules for facility.NRC should compress time used for NRC analysis & review of hearing racord.OL procedure should be completed before Jul 1982 deadline.
  LUKEN.T.A. House of Rep. 81/03/06. 1p. 07950:102.
- 8103270110 Responds to request for rept on possible add1 improvements to NRC licensing process. Legislation ellowing interim operations in advance of hearing completion would reduce delay in licensing process.

  HENDRIE, J. M. Commissioners 81/03/12 Spp.

- --8103270931 Submits recommendations to expect to impacted (N. hearings Code should include set of TMI-related OL requirements ASLAB decisions on fuel loading & low power testing should be irrediately effective BICAWITL Office of the General Counsel 81/02/23 10pp
- --Bi03270947 Submits recommendations re scheduling personnel rescorces bearing that for OL proceedings Panel must obtain exemption from hiring freeze for two recently appointed chairmen COTTER. B P. Atomic Safety and Licensing Board Panel B1/02/25

# v Operator Examinations

- 8103100436 Submits low power testing t augmented operator training commitments re TM1 task action from t G l.in response to R Tedesco 810114 ltr BORGMANN.E A Cincinnati Gas & Electric Co 81/03/05 2pp 07867\_230
- DOCKET 50-369 BATTELLE MEMORIAL INST CRITICAL FACILITY

  Q Inspection reports. IE Bulletins & correspondence
- Bi03020023 Forwards IE Circular Bi-02, 'Performance of NRC-Licensed Individuals While on Duty " No written response required ENGELKEN R H Region 5. San Francisco, Office of the Director Bi/02/09 ip 07707 209.
- DOCKET 90-361 BAN DIOFRE NUCLEAR STATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-DATA Forwards NRC position re interin actions & request for addl info STESHWINT DO Division of Licensing 80/12/22 30pp
- 8103031067 'Environ Statements Project:" monthly progress rept for Dec 1980. INTEL.N E. Oak Ridge National Laboratory. FIN D-0760-1 8103031067 80712731 4pp 07794-341
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical aquipment liters addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT.D O. Division of Licensing 81/01/19 App
- BiO3120014 Ltr to all licensees of operating plants CP holders & U-applicants, except Indian Point 2 & 3.7ion 1 & 2 & THI-1, forwarding inadvertently omitted pages from NRC B01222 request for add info re control of heavy loads EIEENHUT.D O. Division of Licensing B1/02/03 6pp
- 8103060541 Forwards responses to Equipment Qualification Granch questions & comments re seismic qualification of equipment List of encis attached.

  BASKIN.K.P. Southern California Edison Co. 81/02/13 3pp. 07841,001
- --8103060551 Revision of "Seismic Testing of Befety Channel Fission Detectors & Holder Type ELE 304-5000-1 & PA-501 Preamplifier ELE 304-5000-1." \* Hyle Laboratories. E-115-556. 76/02/29 100pp 07841 C04
- --Bi03060597 Revision 1 to "Beismic Analysis of Shutdown Heat Eichanger-Type CEU for San Onofre, Units 2 % 3 " CULLEY, J. M., WEILER, R. A., BALAMOTIB, P. T. NUB Corp. TR-79-74 RI 76/02/10. 200pp.
- --B103060561 "Beismic Simulation Test Program on Auxiliary Protective Cabinet." KUYKENDALL, A. DAVIES, L. M. Wyle Laboratories. 43482-1, 77/04/30 400pp. 07841-126
- --B103060565 Revision A to "Seismic Binulation Test Program on Engineer & Befety Features Actuation Bys Auxillary Relay Cabinet "
  JORDAN.H., BREMER.B Wyle Laboratories, 42913-1 RA, 75/11/83
  125pc 07642-165.
- --Bi03060571 Revision to "Seismic Analysis of Control Panels for Circle AN Products Co. Pomona. CA."
  ANDERSON, J., VICKERS. T. Hyle Laboratories. 54498-2. 77/02/03 200ps. 07842:278.

- -8193360979 Revision A to "Seismic Testing on Control Panel-Shipping Section Number 3." ANDERSON, J. J. Wyle Laboratorius 34498-1 RA 76/09/30 60pp 07843-074
- ~-9103060615 Revision to 'Seismic Vibration Testing on SPEC 200 Control Equipment HERE'Y.L.W. DEMERS E.A. Folhoro Corp. PERS 75-113 R1 26/05/04 25pp 97843 142
- --9103060619 'Getsmic Vibration Test of 265-N 696C 200 Rack "
  FEREY, L. W. SEARS. J Forboro Corp T4-1025 76/06/25 70pp
- --9193060623 Revision B to "Seismic Analysis of Auriliary Feedcater Pumps. Ban Onofre Generating Station, Units 2 & 3 " Borg-Marner Corp. Byron Jackson Pump Div DC-1102 RB 78/06/02. 45pp. 07843 234
- --9103060529 Revision 1 to "GS-2N Seismic Qualification Rept for Byron Jackson, F. 40101."

  SIR018. H. J. LICHTSTEINER, E. Terry Corp. TM-64 R1 78/07/05 30040 07843 278
- 8103180593 Forwards addit clarification of util 810202 response to NRC requirements in NURCO-0737 & MUREO-0660 Provides info reliter I.C B. Eliot monitoring of selected energency procedures for near-term OL applicants

  BASKIN.K.P. Southern California Edison Co 81/02/16 8pp
- BIO3180260 Forwards addi clarification to response to TNI Action Plan Item II-E-I I re auxiliary feedwater sys reliability evaluation DASKIN.K P. Bouthern California Edison Co. 81/02/18 20pp.
- 8103050992 Notification of contract execution. Mod 1 to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"

  LITILE.M Administrative Contracts Branch FIN 8-6898-0 81/02/20 to. 07828 241
- --8103051001 Mod 1.changing period of performance & obligating add1 funds to "Followon Simulation of Earthquaks Ground Motions for San Gnofre Nuclear Generating Station"

  ANI.K Hassachusetts Institute of Technology. PERLMAN.J Administrative Contracts Branch. FIN B-6898-0 G1/02/20 1p. 07888 242
- G103290024 Ltr to a)1 power reactor licensees & license applicants re MUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

  EISEMUT.D 9 Division of Licensing. 81/02/20 Bpp.
- 8103050268 Notification of 810303-05 meeting w/util in Sen Clemente, CA to conduct site audit of sys Interaction program Proposed agenda encl.

  80303-8 Licensing Branch 3. 81/02/23. 6pp. 07825-276
- B103050644 Notification of B10224-26 meeting w/util in Ben Clemente, CA to conduct audit of applicant mgt & organization R000.14 Licensing Brench 3. B1/02/23 5pp. 07827 184.
- BIO3230030 f.fr to all licensees of operating nuclear power plants & applicants for QLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUT.D Q Division of Licensing. B1/02/25. Spp.
- BID3190033 Notification of contract execution. Hod 5 to "Bimulation of Earthquake Ground Hotions for Ban Onofre Nuclear Generating Btation: Final Rept " Contractor: RB Herrmann.

  LITTLE: M Administrative Contracts Branch FIN 8-6531. 81/02/26 to 07964: 163.
- --Bi00190042 Mod 5, deobligating balance & closing out contract, to "Bimulation of Earthquake Oround Motions for Ban Onofre Nociear Generating Station.Final Rept."
  HERRIANN.R.B. Herrmann.R.C. PERLMAN.J Administrative Contracts Branch. Fin 8-6531. 81/02/26. 1p. 07764:164.
- B103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR50 71(e), "Periodic Updating of FBARs." effective 800722 Info re FBAR legal status format & content encl. EtSENHUT.D.O. Division of Licensing. 81/02/26. 10pp.

- 8103100774 Natification of 810305 meeting w/util & C-E in Bethesda.MD to discuss Item II F 2 of NUREG-0737 requirements for facilities

  HUAND. L T Core Performance Branch 81/02/27 3pp 07862 243
- 8103120790 Notification of 810304 meeting w/util in Bethesde.MD to discuss equipment qualification program RODD-H Litensing Branch 3 BJ/03/02 4pp. 07905:297
- 8103110548 Forwards "Open Item 7 Reactor Internals Analysis." in response to Question 312 46 & revision to FSAR Section 3 9 A 3. Responses distributed as part of Arend 24 distribution BASKIN. R P Southern California Edison Co 81/03/05 19pp 07882 247
- 8103120553 Forwards application for amend to licenses submitted as Amend 23 to FSAR. Amend 5 to fire hazards analysis, drawings & piping verification program FSAR amend includes emergency plan u/o privacy data. Aparture cards will be in PDR DIETCH.R Southern California Edison Co 81/03/05. Ip 07894-001
- --B103120557 Application for amend to Licenses CPPR-97 & CPPR-98 submitted as Amend 23 to FSAR Amend consists of responses to NUPEC-0737 dtd Nov 1980. emergency plan revisions, response to NRC B01107 questions & miscellaneous corrections DIETCH.R Bouthorn Celifornia Edison Co. CUITON.G.D San Diego Gas & Electric Co. 81/03/05 3pp
- --B10312049B "Watertight Reliability of Condensate Storage Tank & Concrete Enc. Walls Under UBE & Tornedo Events "
   Southern California Edison Co. 80/12/15, 47pp. 07894 030
- --BIOJI20704 "Investigation of Leminar Flow In Fractured Porous Rocks WILSON.C R , WITHERSPOON.P California, Univ of Berkeley. 70/1/130. 24pp 07894 082.
- --8103120709 "Validaty of Cubic Law for Fluid Flow in Deformable Roct Fracture " HITHERPOOK.P. California. Univ. of Berteley. HANG.J.S. IMAL.K Lawrence Livermore Laboratory. 79/10/31 33pp 07894:100
- --8103120722 "Program Plan for Piping Verification Program (Thermal Expansion-Steady State Vibration & Dynamic Effects)." Revision 6. • Southern California Edison Co. 81/02/20 250pp. 07894 194.
- B103100390 Forwards "Primary Reactor Containment Integrated Leakage Rata Test" & "Primary Reactor Containment Structural Integrity Test "

  BASAIN, K P Southern California Edison Co. 81/03/06. 1p

  07866-079
- --B103100396 "Primary Reactor Containment Structural Integrity Test."

  # Bechtel Power Corp (subs. of Bechtel Corp.). B1/02/28 200pp
  07866.080
- 8103170766 Notification of 810310 meeting woutil in Bethesda.HD to discuss explosion hazards at facilities ROOD.H Licensing Brench 3. 81703706. 4pp. 07928:017.
- 8103[[0725] Forwards revised response to NRC Bys Interaction Brench Question 510 i re seismic & nonseismic Category i sys interaction Response to be distributed w/Amend 24 per 791029 syc list. Affidavit to be forwarded within 10 days.

  BASKIN.K.P. Southern California Edison Co. B1/03/09. Bpp. 07885 130.
- B103176760 Notification of B10310 meeting w/util in Bethesda.MD to discuss facility fuel analysis.
  RODD-N. Literaing Branch 3. B1/03/09. 4pp. 07927:361.
- 8103310804 Ltr to all licenses of operating plants, applicants for OLs & holders of CPs forwarding BECY-Bi-119 re info necessary to establish soviron qualification of safety-related electrical equipment.

  EISENHUT, D. O. Division of Licensing. 81/03/10. 6pp.
- 8103170635 Forwards application to amend CPPR-97 & CPPR-98.extending completion dates to Bil015 & 821115.respectively.

  DIETCH.R. Southern California Edison Co. Bi/03/16. 1p.
- --8103170639 Application to amend CPPR-97 & CPPR-98, extending completing dates to 811015 & 821115, respectively.

  DIETCH, R. Southern California Edison Co. COTTON, G. D. Ban Diego Oas & Electric Co. 81/03/16 App.

- 8103310384 Forwards ACRS 810317 let re GL application review NIRAGLIA.F J Licensing Branch 3 B1/03/23 422 08058 183
- D. ARC Draft/Final Environmental Statements, supple & correspondence
- 8103230609 Porwards NUREG-0490, suppl to facility DES & FR notice MIRAQLIA, F. J. Licensing Branch 3. 81/01/16 3pp 68022:229
- 8103060320 Advises that DES suppl has been reviewed No comments HDFFMAN, C.S. Interior, Dept of 81/03/02 ip 07836 348
- 8103060468 Confirms 810302 telcon extending until 810316 comment period for dreft suppl to DES.

  SAKAKI. 8 Environmental Protection Agency 81/03/02 ip

  07840.238
- 8103130447 Submits comments on fluxEQ-0490 suppl to DES is operation of facilities Suppl does not fulfill intent of Commission statement of interim policy NRC should consult CEO rept. "NRC Environ Analysis of Nuclear Accidents is It Adequate "THEMPSON Q Union of Concerned Scientists. B1/03/09 4pp 07908 279
- Bi03i30526 Joint intervenors' comments on DES suppl (NUREQ-0490). Concludes that unique features including earthquake hazard, warrent addl engineered safety features Requests analysis of postulated cooling sys failure Certificate of Svc encl. BARTON, R. J. Ban Diego. Univ of, INHARTON, R. J. Wharton & Pogalies B1/03/09 15pp. 0790B 297
- B103230423 Forwards general & specific cornents on DES Assessment of anviron impacts for severe accidents uses methodologies developed in MASM-1460 & NUREG-0440 Original Section 7 should be revised to agree w/supplemental data.
  MACKENIIE. J. Environmental Protection Agency 81/03/16 app 07977 124
- 8103260507 Recommends that FEB include emergency evacuation plan for residents in areas where accident risk is highest APUERDIC. Housing & Urban Development Dept of 81703/18 Ip 08040-330
- 8103300332 Comments on NUREO-0490, "Suppl to DES re Departion of San Onoffe Nuclear Concreting Station Units 2 & 3" Statement in Section 7.1 4.3 re whole body dose counts requires clarification.

  BASKIN.X P. Southern California Edison Co. 81/03/24 2pp 08095-324.
- E. NRC Befety Evaluation Report (SER), supply & correspondence
- 8103040173 Forwards SER ne DL application & FR notice. H/o BER. MIRAGLIA-F. J. Licensing Branch 3. 81/02/06 4gp. 07812 322.
- --B103040180 Notice of Issuance & availability of BER re OL application. MIRAQLIA.F. J. Literaing Branch 3 81/02/06 200 07812.326
- B103050423 Forwards BER re OL epplication for review. Open issues identified in rept will be resolved prior to Mar 1981 ACRS meeting TMI-related issues will be addressed in BER suppl to be issued prior to meeting. W/o BER.
  TEDEBEOD.R.L. Assistant Director for Licensing 81/02/06 ip. 07826:090
- 8103180780 Forwards Suppl 1 to SER. HIRAGUIA.F. J. Licensing Branch 3. 81/02/25. 5pg 08026:012.
- --8103180987 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BAN CHOPER NUCLEAR GENERATING STATION UNITS 2 AND 3 Office of Nuclear Reactor Regulation, Director Nureg-0712 801. 81/02/28. 200pp. Available at NIB 46.50. 08026.017.
- 8100030679 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SAY ONOFRE NUCLEAR GENERATING STATION.UNITS 2 AND 3. Bouthern Californie Edican Company.st el. (This document interporates NAREQ-0712.issued 1980).

  9. Office of Nuclear Reactor Regulation. Director NUREQ-0712. 81/02/28. 450pp. Available at NTIS. 812 DO. 07791:336
- 8103100023 Forwards Suppl 1 to SER (MUREO-0712).W/o encl CHANBLER.L.J. Hearing Branch 1. 81/03/06. 1p. 07862.115.
- BiO3170772 Notification of ACRS Subcommittee on San Onofre 2 & 3 810311 meeting & Gull Committee 810312 meeting in Washington,DC to discuse SER & Suppl 1 to SER. Agendas encl.
  TEDESCO.R.L. Assistant Director for Licensing. B1/03/09 7pp. 07928:026.

- 8103230891 Discusses O. hearing scheduling process SER technical schedules for CMB1 & CMB2 encl DENTON H R Office of Nuclear Reactor Regulation. Director 81/03/13. 7pp 07977 Oct
- F Becurity, medical, emergency & fire protection plans
- B101090097 Releases public version of util energency plan. FELTÖY, J. M. Division of Rules and Records B0/12/01 ip 07409 003
- --Bi01220201 For Jards public version of emergency plan
  BASKIN K P Southern California Edison Co 80/08/(8 2pc
- --8101090104 Public version of emergency plan + Southern California Edison Co + San Diego Cas & Elect 80/07/31 240pp 07429 002
- B103020429 Forwards radiological emergency response plan, arrier of Ban Clemente Mar 1981 emergency operations plan Related correspondence
  BEDLETTO. J. A. Gouthern California Edison Co. B1/02/23 1:07792:222
- ~-B193020434 Radiological emergency response plan anner to City Clemente emergency operations plan Related correspondence \* San Clemente.CA 81/03/31. 105pp 07782 223
- B103120553 Forwards application for amend to licenses subnitted Amend 23 to FBAR. Arend 3 to fire hazards analysis drawings to piging verification program FBAR amend includes emergency plan w/o privacy data. Aperture cards will be in PDR DIETCH.R Southern California Edison Co. 81/03/05 [p
- --8103120557 Application for amend to Licenses CPPR-97 % CPPR-7 submitted as Amend 23 to FSAR Amend consists of responses to AUREO-0737 dtd Nov 1980, emergency plan revisions, response to NRC 801107 questions & miscellaneous corrections
  DIETCH.R. Southern California Edison Co. 81/03/05. 3pp
- --8103120717 "Fire Hatards Analysis." Amend 5.

  # Bouthern California Edison Co \* San Diego Gas & Flect
  81/03/05 59pp. 07894:133
- 8103310338 Ltr to all licenses of operating plants & holders or Porwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl EISER-MUT. D. 9 Division of Licensing. 81/03/05 6pp
- B103130276 Forwards Certificate of Svc confirming direct distri of Amend 23 to FSAR & Amend 5 to Fire Hezerd Analysis per encl svc list 268XIN.K P. Southern California Edjson Co 81/03/06 3pp 07907:081.
- 810317073B Notification of 81030P meeting u/util in Bethesda-MD discuss facility emergency plan. RDDD-M. Licensing Branch 3. 81/03/06. 4pp. 07927 172
- 8103110336 Forwards 'Physical Security Plan, Ban Onofre Nuclear Openerating Station, Units 1,2 & 3, Mar. 1981. "Plan withheld (ref 100FR2, 790) DASKIN, K.P. Southern California Edison Co. 81/03/10 3pp 07872, 317
- Q. Adjudicatory correspondence
- 810305054t Forwards notices of J Brune.G Greene.CP Buckley.H Le MP Kennedy depositions & motion for order setting final prehearing conference.Related correspondence. FONO.H. Chickering & Gregory. 81/02/24. 1p. 07828:337
- --8103050548 Hotice of J Brune 810320 deposition in La Julia CA Cartificate of Svc encl PloDTT.D.R. Bouthern California Edison Co. PloDTT.D.R. B. Ges & Electric Co. PloDTT.D.R. Chickering & Gregory 8170 4pp. 07828:338.
- ~~B103050555 Notice of 0 Greens B10327 deposition in Menlo Fark Certificate of Bvc encl. P100TT, D.R. Bouthern California Edison Co. P100TT, D.R. B Gas & Electric Co. P100TT, D.R. Chickering & Gregory B17 4pp. 07828; 342.

4pp 07828 346

--B103050565 Notice of M Legg 810330 deposition in Santa Barbara.CA

Chickerina & Greater

-BIO3050565 Notice of A L799 910330 deposition in Santa Barbara.CA
Certifficate of Svc encl
PIG377.D R Southern California Edison Co PIO071.D R San Diego
Oas & Fisturic Co PIG077.D R Chickering & Gregory B1/02/23
4pp 07828 350

. .

- --BIOJO50571 Notice of MP Kennedy BiOJ23 deposition in La Jolla.CA Centificate of Svc encl PiCDTT.D R Bouthern California Edison Co PIGDIT.D R San Diego Oas & Electric Co PIGDIT.D R Chickering & Gregory 81/02/23
- --810305057& Request for order directing final prehearing conference be convened on 810407 in too Angeles.CA PIODTI.D R Southern California Edison Co PIGUTT.D R San Diego Gas & Electric Co PIGUTT.D R Chickering & Gregory 81/02/23 2pp. 07828-358
- --BID3050581 Request for BIO407 proheering conference in order to clarify issues, set hearing schoole & identify uitnesses Conference appropriate in that all discovery will be completed by BIO403 Proposed order & proof of sec by mail encl PIOGIT. D.R. Southern Celifornia Edison Co. PIOGIT. D.R. San Diego Gas & Electric Co. PIOGIT. D.R. Chickering & Gregory. BI/02/23
- 8103130395 Fifth set of interrogatories & first request for production of documents directed to Friends of the Earth.A Carstens, L von Haden.D Ray & D Davey requesting info re 8an Clemente Plan. Certificate of Svc encl Related correspondence.
  CASEY.8 B Bouthern California Edison Co. CASEY.8 B San Diego Gas & Electric Co. CASEY.8 B Chickering & Oregory 81/03/02 10pp
- 8103330448 Third set of interrogatories & first request for production of documents directed to Orougs United Against Radiation Darger requesting info re Ban Clemente Plan. Certificate of Swc encel Related correspondence CASEY. 8.0 Southern California Edison Co. CASEY. 8.0 San Otego Gas & Electric Co. CASEY. 8.0. Chickering & Oregory. 81/03/02 10pp 07911: 248
- B103090674 Bubarts list of cases going to hearing during 1981 in LNICh emergency preparedness contentions have been raised by one or more parties.

  CHRISTENBURY, E. Hearings Division. 81/03/04 2pp
- BiO3120500 Forwards stipulation for signature Stipulation confirms oral agreement extending time for NRC responses to GUARD interrogatories.

  CHANDLERAL J. Hearing Branch 1 81/03/06 10 07901 279
- --BiO3t20576 Stipulation confirming BiO304 ora) agreement that MRC has until BiO401 to respond to OUARD BiO220 interropatories. CHAMDLER.L. J. Hearing Branch 1 Bi/O3/06 2pp 07901 280.
- 8103120583 Forwards stipulation for signature Stipulation confirms oral agreement estending time for NRC responses to Friends of the Earth interrogatories CMANDLER. L. J. Haaring Branch 1. 81/03/06 ip 07904-249
- --8103120590 Stipulation confirming 810304 oral agreement that ARC has until 810401 to respond to Friends of the Earth 810218,19 & 20 interrogatories CHANDLER.L J Hearing Branch 1 81/03/06. 2pp 07904 250
- 8)03)10328 Answer supporting applicants' 8)0217 motion to competitute answers to interrogatories. Intervenor Erlands of the Earth Patled to respond or responded evasively & incompletely to interrogatories Certificate of Svc encl CHANDLER.L. J. Office of the Executive Legal Director 81/03/09. 4pp 07882 03:
- B103130525 Joint Intervenors' comments on DEB suppl (NUREO-0490) Concludes that unique features including earthquake hazard, warrant addl engineered safety features Requests analysis of postulated cooling sys failure Certificate of Svc encl. B40ARTON.R. J. Ban Diego. Univ. of. (MARTON.R. J. Wharton & Pogalies. 81/03/09 15pp. 07908:297.
- 8103130526 Joint intervenors' comments on DEB suppl (NUREO-0490).
  Concludes that unique features, including earthquake hazard,
  uarrant addi anginsered safety features. Requests analysis of
  postulated cooling sys failure Cartificate of 8vc encl.
  MHARTON, R. J. Affiliation Unknown. B1/03/09. 15pp

- Related correspondence PIGDIT, D.R., MOCHER, C.R., Southern California Edison Co. 6 Gan Diego Gas & Electric Co. 81/03/10 50pp 07969:210
- Bio3200696 Response to Intervenor Friends of the Earth et al of interrogatories re energency plans & earthquakes verification & Certificate of Soc enci PIGOTT.D.R., MOCHER.C.R. Southern California Edison Co. San Bieco Cas & Electric Co. 81/03/10. 91nn. 07969-270.
- 8103200722 Response to intervenor B10220 first set of interror re rediation release-evacuations & emergency plans.
  CASEY.8 B. KOCHER.C.R. Southern California Edison Co.
  San Diego Gas & Electric Co. B1/03/10 3Bpp 07967.275
- 8103230540 Memorandum opposing final preheating conference as early Apr Conference is premature since State of CA & Count of Sen Diego issuence of emergency plans are subj to add1 discovery Certificate of Svc encl WHARTON.R J. Friends of the Earth. WHARTON.R J. Wharton Progalies. 81/03/11 5pp 07974 11o
- BIOJI80077 Notice of appearance in proceeding Certificate of HOEFCING.R K. Hearing Branch 4. 81/03/13 3ap 07942 34
- 8103260756 Motion for order compelling Groups United Against Danger to answer applicants' second set of interrogatories Intervenors failed to serve answers & objections on parties within 14 days after interrogatories served. P10077.D R , MDCMER.C Southern California Edison Co. P10 Chickering & Gregory 81/03/16 2pp 08036-035
- --B103260761 Memorandum in support of applicants' B10316 rotionswers to applicants second set of interropatories Order compelling answers will prevent unwarranted delays & additional Proposed orders & Proof of Svc encl P100TT, D.R., KOCHER, C.R. Southern California Edison CoptionTT, D.R. Chickering & Oregory, B1/03716 10pp. 08
- 8103310915 Forwards listing of personnel responsible for prepresentations to each intervenor interrogatory. Responses are scheduled for submittal by 810326 RDGD-H Licensing Branch 3. 81703/20 5pp. 08058:142.
- Bio3250449 Natice of ASLB reconstitution JL Kelly, chairmen & &CH Hand, members.
  COTTER, B.P. Atomic Bafety and Licensing Board Penal. Bi/Capp. 07996 214.
- H General correspondence
- 8103200599 Urges administration to adopt policy to expedite to find nuclear power plants % to appoint strong chairman to enforce policy ALQUIBT.A E. AYALA.R S., BOATWRIGHT, D.E. California. State 81/02/12 3pp 07970.001
- 8103110470 Forwards Orange County Chamber of Commerce 810227 favoring immediate licensing of facilities. TRUHILL.L.D. Orange County, CA 81/02/27. 2pp 07882-15
- 8]03270692 Requests decommissioning of facilities, due to service to service times a risks of radiation pipes, D. L. Affiliation Unknown. 8:/03/08 ip 08046:32:
- Bi03300392 Forwards on behalf of San Diego Association of Goresolution supporting operation of facilities Requests NRC grant OL, per federal regulations re safety of nuclear power operations to sergency planning for plant accidents. INFF.R.J. SanDiego.CA. 81/03/19 Spp 08058:117.
- I Financial information
- 8)03)10573 Forwards responses to Util Finance Branch Bi0114 ( 1. b-12. Index & info re decommissioning costs & unit prices ent! BABKIN.K.P. Southern California Edison Co. B1/03/10 7p; 07887 115.
- --BIO3110678 "Decommissioning Costs." \* NUS Corp 3382, 79/10/31, 22pp. 07897:122.
- --8103110684 Participation agreement among utils & Cities of Anaheim: CA Forms 10-K: [0-0 & S-16 & prospectus encl. • Southern California Edison Co. \* San Diego Cas & El \* Riverside: CA 80/11/12 340pp. 07887:144.

- --9103110690 Annual Financial Rept 1980 Info re regulatory environ.unit prices.rate development & cost of rancy & required return pric!

   Sen Diego Gas & Electric Co B1/03/10 76pp 07889 071
- --8103110698 Prepared testimony of JA Horton.HF Christis.AP Haut.AC Smith.MO Whyte.ME Ferguson.RV Knapp.et al.re util request for rate increase Prospectus encl HORTON.J.K., CHRIBTIE.H F., HAUB.A P. Southern California Edison Co. 79/12/31. 244pp 07888 #20
- --9103110704 Prepared testimon, & exhibits of RJ Cadenasso on behalf of CA Association of Util Shareholders regeneral rate case CADENASBO R J. Affiliation Unitno-m. 80/04/16 49pp 07889 160
- --BIO3110710 Prepared testimony of D1 Gardner re-study of cost of capital & rate of return for Southern CA Edison Co-GARDNER.D T California. State of 80/03/18. 44pp 07889 209.
- --BIO3110713 Prepared testimony of HF Christie re request for general rate increase proceeding Current financial data enti CHRISTIE, H F Southern California Edison Co 80/11/30 14pp 0/2889-257
- --8103110718 Ajdl prepared testimony of DT Gardner re general rate increase proceeding. garDNER, D T Gouthern California Edison Co. 80/11/58 7pp. 07809-271
- --Bi03110724 Prepared testimony of MO Lyons re general rate increase proceeding. Estimated operational & financial attrition infoent LYONS M 9. California. State of. 80/11/20 10PP 07889:278
- --8103110730 Decision 92549, granting util 791226 application for authority to increase rates for electric svc. Decision commits util to increased developmental & fuel cost-efficient implementation of conservation measures.

   California, State of, 80/12/30, 253pp 07889:288
- --B103110736 Prepared testimony of R Korpen re cost of capital & rate of return for 1982 test yr KORPAN-R. San Diego 9es & Electric Co 80/12/31 9ipp 07490 194.
- --9103110744 Prepared testimon, of FH Ault re 1982 test yr.including comparative financial data for 1978 & 79 & surmary of earnings 1980-83
  AULT.F. H. Ban Diego Gas & Electric Co. 80/12/31 98pp. 07890-283.
- --BiO3110748 Prepared testimony of PA Williams re cost of capital & rate of return for 1981 test yr WILLIAMS.P.A. San Diego Gas & Electric Co. 80/07/31. 27PP
- --8103150791 Prepared testimony of FH Ault re 1981 test unincluding comparative financial data for 1978 & 1979 & summary of earnings 1975-81.

  AULT.F.H. San Diego Pas & Electric Co 80/07/31 63pp.
  07891:006
- --B103110754 Testimony of E Guan re study of cost of capital & rate of return for Ban Diego Gas & Electric Co GUAN(E. California: State of. B0/09/08. 41pp 07891.069
- --BiO3110760 "Rept on Results of Operation of San Diego Oas & Ejectric Co. Electric Dept, Test Yr 1981." # California. Btate of 80/09/08 100pp. 07891.110.
- --BiO3:10762 "Rept on Results of Operation of San Diego Cas & Electric Co.Electric Dept, Test Yr 1981." 6 California, State of. 80/09/08 54pp. 07891:201.
- --Bi03i10766 Decision 92557 conditionally granting util 800701 & 02 applications for increased rates & charges for electric & gas even & revised electric dept tariffs. Related info encl. s California, State of. 80/12/31 535pp. 07891:259.
- --8103110773 Annual Finencial Rept for FY80.Related info encl.

  a Ansheim CA, 80/08/30, 175pp 07892:130.
- --B103110775 Annual Financial Rept for FY80 BREWER.H.E. Riverside CA. 81/03/10. 11pp. 07892:310.

- g Utility Final Bafety Analysis Report (FSAR) & a
- B103120553 Forwards application for amend to lice Amend 23 to FSAR Amend 5 to fire hazards analyst pipting verification program FBAR amend includes tian w/o privacy data Aperture cards will be in DIETCH.R Southern California Edison Co. 81/03
- --BIO3120557 Application for amend to Licenses CPI submitted as Amend 23 to FSAR Amend consists (NUREG-0737 dtc Nov 1980, amergency plan revisit NRC BOI107 questions & miscellaneous correctio DIETCH.R Southern California Edison Co CO Gas & Electric Co 81/03/09 3pp
- ---9103120559 Amend 23 to FSAR.Vols 1 & 2 • Southern California Edison Co • San Diet 61/03/05 2000pp 07895 121.
- --8103120698 "Watertight Reliability of Condensati Concrete Encl Walls Under DBE & Tornado Eventu • Bouthern California Edison Co 80/12/15
- --B103120704 'Investigation of Leminar Flow In Fr MILSON, C. R., WITHERSPOON, P. California, Univ 70/11/30 24pp 07894-082
- --8103129709 "Validity of Cubic Law for Fluid Flor Fracture" MITHERSPOON.P California, Univ of Berkele Lawrence Livernore Laboratory 79/10/31 3:
- --9103120717 "Fire Halards Analysis." Amend 5 • Southern California Edison Co. • Gan Die B1/03/05 59pp 07874 133
- --8103120722 "Program Plan for Piping Verificatio Expansion Steady State Vibration & Dynamic Ef Revision & • Southern California Edison Co 81/02/20
- B103130276 Forwards Certificate of Svc confirming of Amend 23 to FSAR b Amend 5 to Fire Heisard An encl svc list. BABKIN.K P. Southern California Edison Co. 81 07907-081.
- Bio3260545 Forwards revised Section 2 2 3 of San FBAR. Revision provides offsite hazards re-evalumethods & results. & complies w/NRC criteria BABAIM. P Southern California Edison Co. Bi OADAT 322
- --8103260351 Revised Section 2 2 3 to 8an Onofre discussing methods & results of offsite haiar evaluation Section complies w/NRC criteria e Gouthern California Edison Co 81/03/24
- O. Advisory Committee on Reactor Bafaguards repor
- Bio3050299 Notification of ACRB Bi0311-12 meeting support necessary to avoid delay in issuing safavaluation List of items on agenda & status of enci. IEBESCO, R. L. Assistant Director for Licensing.
- B103050420 Forwards ACRS B10210 1tr re review of matters re OL applications for facilities MIRAQLIA.F. J. Licensing Branch 3. 81/02/13
- 8103050239 Notification of ACRS 810311-12 meeting support necessary to avoid dalay in issuing safevaluation.List of items on agenda & status of encl.

  TEDESCO.R.L. Assistant Director for Licensing. 07825:231.
- BiQ3170772 Notification of ACRS Subcommittee on S meeting & full Committee BiQ312 meeting in Wash discuss BER & Buppl 1 to BER Agendas encl TEDESCO.R.L. Assistant Director for Licensing. 07928.026.
- B103230442 Recommends that facility employ seisming supplied at Diablo Cenyon set to actuate at of BEE acceleration.

  MARK.J.C. ACRE Advisory Committee on Reactor B1/03/17. 3pp. 07977:047.

- g Inspection reports. IE Builetins & correspondence
- 8103030512 Forwards IE Insp Repts 50-351/80-24 & 50-362/80-13 on E01216-19 No noncompliance noted SPENCER.9 & Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 81/01/09 2pp 07795.321
- --8103030521 IE Insp Repts 50-361/80-24 & 50-362/80-13 on 801216-19 No noncompliance noted Major areas inspected const activities involving licenses action on previous insp findings & IOCFR50 59s repts ECMMARDFLUH, ELINUJO Region 5. San Francisco, Office of the Director DODDS.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch 81/01/08 App 02793-223
- 8103090053 Forwards IE Insp Rept 50-361/80-23 on 801115-1218 No noncompliance noted CREMS.J L Region 5. San Francisco. Reactor Operations Nuclear Eupport Branch 81/01/14 2pp. 07827 249
- --S103050061 IE Insp Rect 50-361/80-23 on 801115-1218 No noncompliance noted Major areas inspected preoperational test program & procedures & independent insp effort PATE.R. J. Region 5. San Francisco. Office of the Director FAULKEI:BERRY, U. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 81/01/14 3pp 07827 251
- BIO3020091 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required EMDELMEN.R H Region 5. San Francisco. Office of the Director. BI/02/09. 1p 07787.291
- B103160322 Forwards IE Info Notice 81-03 'Checklist for Licensee Making Notifications of Significant Events in Accordance W/1005F850 72 " No response required EXOELKELLR M. Region 3. San Francisco, Office of the Director 81/02/12. | 1p | 0/922 032
- 9103250027 Forwards IE Insp Rept 50-361/81-02 on 810126-30 No noncompliance nated BDCK.H E. Region 5- San Francisco, Office of the Director B1/02/18. 2pp. 07998-265
- --Bi03250031 IE insp Rept 50-361/61-02 on Bi0126-30 No noncompliance noted Major areas inspected previous insp findings. preoperational testing procedures, process & effluent radialogical monitoring sus 3 emergency radiation monitors. FiBM.R F : HAMADA.O : MENGLAMBKI.F A Region 5. Sen Francisco. Office of the Director. Bi/02/17. 7pp 07998 267
- BIO316065B Forwards IE Info Notice BI-04, "Cracking in Main Steam Lines." No response required. ENGELKEN.R H Region 5. San Francisco. Office of the Director. BI/02/27 Ip 07914 237
- BIO3170002 Forwards IE Circular BI-03. "Inoperable Beismic Monitoring Instrumentation." No response required. ENGELKEN.R H. Region 5. Ban Francisco. Office of the Director BI/03/02 ip. 07739:100
- 8103160816 Forwards revised IE Bulletin BI-OI, "Burveillance of Mechanical Snubbers," w/corrected Pages 5 & 6 Util 1s deleted from CP facilities to which bulletin is applicable ENGELKEN.R H. Region 5. San Francisco, Office of the Director B1/03/04 1p. 07914 169.
- 8103200243 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required. ENGELKEN.R H. Region 5. Ben Francisco. Office of the Director. DI/03/11. |p. 07968:331.
- 8103200072 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades." No response required. ENGELKEN.R.H. Region 5. Sen Francisco. Office of the Director. 81/03/13. | 1p. 07970-254.
- 9 Reportable occurrences, LERs & related correspondence
- 8103020423 Final deficiency rept re-potential release of contaminated water initially reported 810107. Caused by inadequate motor control ctr assignments for Train A. Assignments will be changed prior to fuel loading.

  PAPAY. L. T. Southern California Edison Co. 81/02/03. 2pp. 07784: 119.

- no bomb onsite info assessment team has been notified SCHWAN.C. MERTENSEN.W Region 5. San Francisco. Diffice of the Director Bi/03/04 ip 0/2665 206.
- 8103180599 Interim deficiency rept re compliance of bolting matls WABME Boiler & Pressure Vessel Code. Section III.
  NCA-3867 4(e) Final rept is delayed until 810918 due to difficulty in obtaining info from suppliers.
  NUMBLE Southern California Edison Co. 81/03/13 in 07993 235
- T Hearing transcripts on non-antitrust matters
- 8103180645 Transcript of ACRS Subcommittee on San Onofre 810311 meeting in Mashington DC Pp 1-224 Viewgraphs encl \* ACRB Advisory Committee on Reactor Safeguards: 81/03/11. 227pp. 07947 323
- U Congressional/Executive Correspondence
- 8103240091 Forwards fourth monthly status rept to Congress for BIOI15-0215 Rept discusses actions taken on licensing reviews of new facilities Rept will be arrended to include add1 info requested on BIO217 MAMMERGR.C Office of Congressional Affairs BI/02/27. 3pg
- B103273110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process HENDRIE. J fl Commissioners B1/03/12 Spp
- --B103270931 Submits recommendations to expedite impacted OL hearings Code should include set of TMI-related OL requirements ASLAB decisions on fuel loading & low power testing should be immediately effective.
  BICKMIT.L Defice of the General Counsel 81/02/23. 10ap
- --BI03270947 Bubmits recommendations re-scheduling personnel resources thearing mpt for OL proceedings Panel must obtain exemption from hiring freeze for two recently appointed chairmen.

  COTYER. B.P. Atomic Bafety and Licensing Board Panel. B1/02/25.

  33pp.
- DOCKET 50-362 SAN GYOFRE NUCLEAR STATION. UNIT 3
- A. Application/construction stage documents & correspondence
- BIO3190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0512. Forwards NRC position re interim actions & request for addl info.

  EISENHUT. D. O. Division of Licensing. B0/12/22. 30pp.
- BIO3031047 "Environ Statements Project," monthly progress rept for Dec 1980 ZITTEL.H E Oak Ridge National Laboratory. FIN D-0760-1. BIO3031067. 80/12/31 4pp 07794.341
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown.replacement parts & NUMEG-0737. ETERNHUT.D.O Division of Licensing. 81/01/19. dpp.
- BiO3120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding inadvertently emitted pages from NRC 801222 request for addl info re control of heavy loads EIBENHUT, D. Q. Division of Licensing. Bi/02/03. 6pp.
- B103060541 Forwards responses to Equipment Qualification Branch questions & comments re-seismic qualification of equipment List of snc1s attached.

  BABKIN: X P. Southern California Edison Co. 81/02/13 3pp. 07841:001.
- --B103060551 Revision of "Beisnic Testing of Safety Channel Fission Detectors & Holder Type ELE 304-3000-1 & PA-501 Preamplifier ELE 304-6000-1."

  \*\*Wille Laboratories.\*\* E-115-556.\*\* 76/02/29.\*\* 100pp. 07841:004.
- --B103050557 Revision i to "Beismic Analysis of Shutdown Heat Exchanger: Type CEU for Ben Dnofre:Units 2 & 3."
  CULLEY, J. H., WEILER, R. A., BALAMOTIB, P. T. NUB Corp. TR-75-74 Ri. 76/02/10 200pp.

Catinet." KUYKEADALL, A. . DAVIES, L. M. Wule Laboratories 43482-1. 77/04/18. 07841 126. 40000

\_ [] [] []

- --8103060365 Revision A to "Beismic Bimulation Test Program on Engineered Bafety Features Actuation Sys Auriliary Relay Cabinet " JORDAN. H., BREMER. 5. Hyle Laboratories 42913-1 RA 75/11/13 1255p 07842:163
- --BIOJOAD57; Revision to "Seismic Analysis of Control Panels for Carcle AM Products Co.Pomona.CA" ANDERSON.J., VICKERS.T Hyle Laboratories 54498-2, 77/02/08 200pp. 07842 298
- --B103060575 Revision A to "Seismic Testing on Control Penel Shipping Section Number 3 ANDERSDN: J J Myle Laboratories. 54498-1 RA 76/09/30 60pp
- --8:03050615 Revision to "Seismic Vibration Testing on SPEC 200 Control Equipment "
  HEMEY, L W., BEMERS, E A. Folboro Corp. PERB 75-113 R1 76/09/04 25pp 07843:142
- --8103066619 "Seismic Vibration Test of 2E5-N SPEC 200 Rack '
  HENEY-L W. . SEARS-J. Forbora Corp. 14-1025 76/06/25 70pp
- --B103060623 Revision B to "Seismic Analysis of Autiliary Feedwater Pumps.Ban Onofre Generating Station-Units 2 & 3." # Borg-Warner Corp Byron Jacteon Pump Div DC-1102 RB 78/06/02 45pp. 07843:234.
- -- 9103040629 Revision | to "95-2N Seismic Qualification Rept for Buron pouvouver nevietor i to vanem betenic Gyalification Rept for Bi Jacteon.F. 40101 " BIRDIB.H. J., LICHIBTEINER.E Terry Corp. TM-64 R1 78/07/05 300pp 07843 278
- 8103180593 Forwards add! clarification of util 810202 response to NRC requirements in NUREO-0737 & NUREO-0860. Provides info re tem I.C. B. pilot monitoring of selected emergency procedures for near-term DL applicants.

  BASAIN. R. Bouthern Celifornia Edison Co. Bi/02/16. Bpp.
- 8103180268 Forwards add1 clarification to response to TMI Action Plan Itan II-E-1, I re auxiliary feedwater sys reliability evaluation BASKIN, K. P. Southern California Edison Co. 81/02/18. 20pp. 07954: 187
- BIO0050992 Notification of contract execution Mod I to "Follown Simulation of Earthquake Organd Motions for San Onofre Nuclear Openerating Station " LITTLE-M Administrative Contracts Branch FIN 8-6898-0. 81/02/20.
- --BI03051001 Mod 1.chenging period of performence & obligating add1 funds to "Followen Simulation of Earthquake Oround Motions for Ban Onofre Nuclear Generating Station." AMLK. Massachusatts Institute of Technology FIN 8-6898-0. 81/02/20. 19.
- 8103250024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee way submit analysis to justify use of existing low flow controller. EISENAUT. D. O. Division of Licensing. 81/02/20 Spp
- 8103030269 Notification of 810303-05 meeting w/util in San Clements.CA to conduct site audit of sys interaction program Proposed agends encl. ROOD, H. Licensing Branch 3. 81/02/23 6pp. 07825:276.
- 8103050644 Notification of 810224-26 meeting w/util in San Clemente, CA to conduct audit of applicant mgt & organization, ROOD, H. Licensing Branch S. 81/02/23, Spp. 07829:184,
- S103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie, Units ) & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement erergency procedures. EISENHUT, D. G. Division of Licensing. 01/02/25. Spp.
- B103190033 Notification of contract execution Mod 3 to "Simulation of Earthquake Ordund Motions for Ban Onofre Nuclear Generating Station: Final Rept." Contractor: RB Herrmann, LITTLE.M. Administrative Contracts Branch. FIN 8-6531. 81/02/26.

6103230B13 Caneric Ltr B1-06 to all CP holders & Ol [CCFRSD.71(e), "Periodic Updating of FSARs," eff-803722 Info re FSAR legal status format & conten-EISERMUT.D-0 Division of Licensing 81/02/26

"Simulation of Earthquake Cround Motions for Se Nuclear Generating Station Final Rept \*\*
HERRMA'N, R B Herrmann, R E FIN B-6531 81/6

- B103100774 Natification of B10305 meeting w/util & to discuss Item II.F 2 of NURES-0737 requirements facilities
- HUAND, L. T. Core Performance Branch 01/02/27 B103120750 Notification of 810304 meeting w/util it discuss equipment qualification program

  RBBO.H. Licensing Branch 3 81/03/02 4cp 0
- 8103110548 Forwards "Open Item 7 Reactor Internals 3. 9. A 3. Responses distributed as part of Amend 20
- 07882 247 B103120553 Forwards application for amend to licen-
- 10312/0551 Forwards application for amend to litera-Amend 23 to FSAR, Amend 5 to fire hazards analysi-piping verification program FSAR amend includes in plan M/o privacy data Aperture cards will be in DIETCH. R. Southern California Edison Co. 81/03. --8103120557 Application for arend to Licenses CPP/ submitted as Amend 23 to FBAR Amend consists or NUREG-0737 dtd Nov 1980, emergency plan revision NRC 801107 questions & miscellaneous correction DIETCH-R. Southern California Edison Co. 81/0
- --Bi03120698 "Watertight Reliability of Condensate Concrete Encl Walls Under DBE & Tornado Events Southern California Edison Co B0/12/15
- --B103120704 "Investigation of Laminar Flow In Fra W1650N.C.R., WITHERSPODN.P California, Univ. 70/11/30. 24pp 07894:082
- --B103120709 "Validity of Cubic Law for Fluid Flow Fracture." PTACEUTE HITHER®POON,P. California, Univ. of, Berkeley Lawrence Livermore Laboratory. 79/10/31 33
- ~-8103120722 "Program Plan for Piping Verification Expansion, Bleady State Vibration & Dynamic Eff Revision 6. \* Southern California Edison Co. 81/02/20.
- 8103170766 Notification of 810310 meeting w/util i discuss explosion hazards at facilities RDBD:H Licensing Branch 3 81/03/06. 4pp 0
- 8103110725 Forwards revised response to NRC Bus In Question 510 1 ra seismic & nonseismic Category interaction Response to be distributed w/Amend 2 svc list Affidavit to be forwarded within 10 day BASKIN. K. P. Southern California Edison Co 817 07885, 130.
- Bio3170760 Notification of Bio310 meeting w/util i discuss facility fuel analysis RDDD:H. Licensing Brench J. 81/03/09 4pp 0
- 8103310804 Ltr to all licensess of operating plant to holders of CPs forwarding SECY-81--119 re info establish environ qualification of sefety-relate equipment.
  EEBENHUT, D. O. Division of Licensing. 81/03/10
- 8103170638 Forwards application to amend CPPR-97 & completion dates to 811015 & 821115, respectively DIETCH.R. Southern California Edison Co. 81/03
- --B103170639 Application to amend CPPR-97 & CPPR-9 dates to B11015 & B21115, respectively. DIETCH.R. Bouthern California Edison Co. COT Gas & Electric Co. B1/03/16 6pp.
- 8103310384 Forwards ACR8 810317 ltr re DL applicat MIRAGLIA, F. J. Licensing Branch 3. 81/03/23. 4

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8103230609 Forwards NUREO-0490, suppl to facility DES & FR notice MIRAQLIA, F J Licensing Branch 3 81/01/16 3pp 08022 229
- 8:03060320 Advises that DES suppl has been reviewed No comments
  MEFFMAN.C S. Interior, Dept of 8:/03/02 to 07836:348
- 8103360468 Confirms 810302 telcon extending until 810316 comment period for draft suppl to DES SAKAKI,8 Environmental Protection Agency 81/03/02 ip 07840 238
- 8103130447 Submits comments on NUREO-0490, suppl to DEB re operation of factilities Suppl does not fulfill intent of Commission statement of interim policy NRC should consult CEO rept.

  "NRC Environ Analysis of Nuclear Accidents is it Adequate "THOMPSON O Union of Concerned Scientists B1/03/09 4pp 07908 279
- 8103:30526 Joint intervenors' comments on DEB suppl (NUREO-0490) Concludes that unique features including earthquake hazard, warrant add engineered safety features Requests analysis of postulated cooling sys failure Certificate of Svc encl WHATON R. J. Affiliation Unknown 81/03/09 15pp
- B103230423 Forwards general & specific comments on DER Assessment of environ impacts for severe accidents uses rethodologies disveloped in MASH-1460 & NUREO-0440 Original Section 7 should be revised to agree w/supplemental data.

  MACKENZIE. J Environmental Protection Agency. 81/03/16 App
- B103260607 Recommends that FES include energency evacuation plan for residents in areas where accident risk is highest AUUERO.C Housing & Urban Development.Dept. of B1/03/18 ip 06040:330
- 8103300332 Comments on NUREO-0490. "Suppl to DES re Operation of San Onofre Nuclear Generating Station Units 2 & 3 " Statement in Section 7: 4 3 re whole body dose counts requires clarification BASKIN.K P. Southern California Edison Co 81/03/24 2pp
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8103040173 Forwards BER re OL application & FR notice, W/o SER MIRAGLIA.F J. Literaing Branch 3 81/02/06 4pp 07812 322.
- --8103040180 Notice of issuance & availability of BER re GL application MIRAGLIA.F. J. Licensing Branch 3 81/02/06 2pp 07812 326
- 8103050423 Forwards SER re OL application for review Open issues identified in rept will be resolved prior to Mar 1991 ACR8 meeting. TMI-related issues will be addressed in SER suppl to be issued prior to meeting. W/o BER TEDESCO.R.L. Assistant Director for Licensing 81/02/04 lp. D2824.090
- 0103180980 Forwards Suppl 1 to SER. HIRAQLIA.F J. Licensing Branch 3. 81/02/25 5pp 08026:012.
- --BIO3160907 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SAN DMDFRE NUCLEAR GENERATING STATION, UNITS 2 AND 3.

   Office of Nuclear Reactor Regulation, Director, NUREO-0712 BO1.
  81/02/28. 200pp. Available at NTIS 46 50 08026:017
- 8103030679 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BAN DNORRE NUCLEAR GENERATING STATION.UNITS 2 AND 3 Southern California Edison Company at al. (This document incorporates NUREO-0782.issued 1980).

   Office of Nuclear Reactor Regulation, Director, NUREO-0712 81/02/28 450pp Available at NTIS 612 00, 07791:336
- 8103100023 Forwards Suppl 1 to SER (NUREO-0712) 4/o enc1 CHANCLER, L. J. Hearing Branch 1. 81/03/06 1p. 07862:115.
- 8103170772 Notification of ACRS Subcommittee on San Onofre 2 & 3 810311 nesting & full Committee 810312 meeting in Washington. DC to discuss SER & Suppl I to SER. Agendas encl TEDESCO.R. L. Assistant Director for Licensing. 81/03/09 7pg
- B103230891 Discusses OL hearing scheduling process SER technical input schedules for CYBL & CYB2 encl DENTON, H R. Office of Nuclear Reactor Regulation, Director. 81/03/13. 7pp. 07977.062.

- F Becurity, medical, emergency & fire protection plans
- 8101090097 Releases public version of util energency plan FELTON, J M Division of Rules and Records. 80/12/01. 19 07429 001
- --Bi01220201 Forwards public version of energency plan BABKIN, K.P. Southern California Edison Co. 80/08/18 2pp 04-17 759
- --Bi01090104 Public version of energency plan

  \* Bouthern California Edison Co \* San Diego Gas & Electri
  B0/07/31. 240pp 07429 002
- 8103020428 Forwards radiological emergency response plan, anner to of San Clemente Mar 1781 emergency operations plan. Related correspondence.
  3EQLETTO. J. A. Bouthern California Edison Co. 81/02/23 ip. 07782-222.
- --8103020434 Radiological energency response plan, enner to City or Clemente emergency Operations plan Related correspondence. # Ban Clemente, CA 81/03/31 105:0 07782:223.
- 8103120553 Forwards application for amend to licenses submitted a Amend 23 to FSAR. Amend 3 to fire hazards analysis, drawings & piping verification program FSAR amend includes amergency plan w/o privacy data Aperature cards to be in PDR. DIETCH-R. Southern California Edison Co. 81/03/09. 1p.
- --8103120557 Application for amend to Licenses CPPR-97 & CPPR-98 submitted as Amend 23 to FSAR. Amend consists of responses to NUREQ-0737 dtd Nov 1980, emergency plan revisions, response to NRC 801107 questions & miscellaneous corrections.

  DIETCH, R. Southern California Edison Co. 81/03/05 3pp
- --Bi03120717 "Fire Hazards Analysis." Amend 5

  Bouthern California Edison Co. \* San Diego Gas & Electri Bi/03/05 5-7pp 07094-133
- B10331033B Ltr to all licensees of operating plants & holders of forwarding NUREO-0496. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements U/O encl
  EISENNUT.D 9. Division of Licensing B1/03/05. 6pp.
- B103130276 Forwards Cortificate of Svc confirming direct distributed Annual 23 to FBAR & Amend 5 to Fire Hazard Analysis per encl svc list.

  BABKIN-K P Southern California Edison Co. 81/03/04. 3pp.
- 8103170738 Notification of 810309 meeting u/util in Bethesda.MD to discuss facility emergency plan RDQD>H Licensing Branch 3 81/03/06 4pp. 07927-172
- 8103110335 Forwards 'Physical Security Plan, San Onofre Nuclear Generating Station, Units 1.2 & 3. Mar. 1981 " Plan withheld tref 100FH2.790). BASKIN, K.P. Southern California Edison Co. 81/03/10 3pp. 07872:317
- O Adjudicatory correspondence
- 8103090541 Forwards notices of J Brune G Greene CP Buckley, M Legg MP Kennedy depositions & motion for order setting final prefearing conference. Related correspondence. FONJ-M. Chickering & Gregory 81702724. 1p. 07828-337
- --810305054B Natice of J Brune 810320 deposition in La Jolla, CA. Cartificate of Svc enci. PIODTI.D.R. Bouthern California Edison Co. PIGDTT.D.R. Ban Oas & Electric Co. PIGOTT.D.R. Chickering & Gregory, 81/02, 4pp. 07628
- --9103050555 Notice of Q Greene 810327 deposition in Menio Park, C/ Certificate of Svt encl. FJOOTY, D.R. Bouthern California Edison Co. P100TT, D.R. Ban Ges & Electric Co. P100TT, D.R. Chickering & Gregory, 81/02, 4pp. 07828:342.
- --Bi03090560 Natice of CP Buckley 810325 deposition in Fullerton. Certificate of 8vc encl. Pi00TT, D. R. Bouthern California Edison Co. Pi00TT, D. R. Ben Qes & Electric Co. Pi00TT, D. R. Chickering & Oregory. 81/02 4pp 07828: 346.

- -- 9103320255 Notice of H Legg B10330 deposition in Santa Bartara.CA Centificate of Svc enci P10017.D R Southern California Edison Co P10017.D R San Diego Gas & Electric Co PIGOTT. D. R. Chickering & Gregory 81/02/23 444 01828 340
- --- B103050571 Notice of MP Kennedy B10323 deposition in La Joila.CA (C)330371 Notice of Ar Kernely Bioses deposition in La Solitation Certificate of Evc and P(COTT. D R Boythern California Edison Co PIGDTT. D R San Di Pas & Electric Co PIGDTT. D R Chickering & Gregory B1/02/23 San Diebo 07828 354
- -- 8103050576 Request for order directing final prehearing conference be Conversal on 810407 in Los Angeles, CA
  PIGOTT, D.R. Scuthern California Edison Co. PIGOTT, D.R. Ban Diego
  Gas & Electric Co. PIGOTT, D.R. Chickering & Gregory 81/02/23
- --8i03023381 Request for 810407 prehearing conference in order to clarify issues set hearing schedule kidentify uitnesses Conference appropriate in that all discovery util be completed by 810403 Proposed order & proof of svc by neil ent? PIOOTT. D.R. Southern California Edison Co. PIOOTT. D.R. San Diego 248 & Electric Co. PIOOTT. D.R. Chickering & Gregory. 81/02/23
- 8103130396 Fifth set of interrogatories & first request for production of documents directed to Friends of the Earth. A Carstens. of documents directed to Frience or the Letter in Certifiers.

  L von Haden D May & D Davey requesting info re San Clemente
  Plan Certificate of Svc encl Related correspondence
  CASEY. B Bouthern Celifornia Edison Co CASEY. S B San Diego G
  & Electric Co CASEY. B B Chickering & Gregory B1/02/02 TOpp San Diego Gas

900 07828 360

07911 184

- 810313044B Third set of interrogatories & first request for production of documents directed to Groups United Against Radiation Danger requesting info re San Clemente Plan Certificate of Byc enc! Re enc! Related correspondence int anci nelated correspondence (ASEY.8 B Southern Celifernie Edison Co CASEY.8 B San Diego Q L'Elattric Cc CASEY.8 B Chicharing & Oregory B1/03/02 10pp. San Diego Gas 07911 248
- 8103050674 Submits list of cases going to hearing during 1981 in which seargency preparedness contentions have been raised by one or more parties CHRISTENBURY, E Hearings Division 81/03/04. 200
- B103120503 Forwards stipulation for signature Stipulation confirms oral agreement extending time for MRC responses to GUARD interrogatories CHANDLER, L. J. Hearing Branch 1 81/03/05 19 07901 279.
- --8103120376 Stapulation confirming 810304 oral agreement that NRC has until 810401 to respond to OUARD 810220 Interrogatories CHANDLER, L. J. Hearing Branch 1. 81/03/05 2pp. 07901 280
- 8103120583 Forwards stipulation for signature Stipulation confirms oral agreement estanding time for MRC responses to Friends of the Earth Interrogatories CHANDLER.L J Hearing Branch 1. 81/03/06 1p. 07904.249.
- --B103120590 Stipulation confirming S10304 oral agreement that NRC bas until 810401 to respond to Friends of the Earth 810218, 19 &
- CHANDLER-L J Hearing Branch 1 81/03/06 2pp. 07904 250
- BIODIIO328 Answer supporting applicants' BIO217 mation to compel further enswers to interrogatories Intervenor Friends of the Earth failed to respond or responded evasively & incompletely to interrogatories Certificate of Svc encl. CHANDLER, L. J. Diffice of the Elecutive Legal Director BI/03/C 81/03/09
- B103130526 Joint intervenors' comments on DES suppl (NUREO-0490) Oncludes that unique features including earthquake hazard, marrant addl engineered safety features Requests analysis of postulated cooling sys failure Certificate of Svc enci.

  BUAGATONIR J San Diago-Univ of: WHARTONIR J Wharton & Pozalies.

  B1/03/09 15pp 07908.297
- BIOG200664 Response to Intervenor Friends of the Earth, et al fifth set of interrogetories, defining terms to discussing Cristianitos fault & earthquates Verification & proof of svc encl. Related correspondence.
  PLOOTI, D.R., KOCHER, C.R. Southern California Edison Co. P. Ban Diego Cas & Electric Co. 81/03/10 50pp. 07969.210. PIODIT D R
- 8103200696 Response to Intervenor Friends of the Earth et al sixth set 103200070 Response to invervenor Friends or the Earth et al of interrogatories re smergency plans & earthquates.

  Verification & Certificate of Buc enc!

  PIQOTI-D R , KOCHER:C.R. Southern California Edison Co. P

  Ban Disgo Get & Electric Co. Bi/03/10. 9ipp. 07969:270. PIGOTT, D R

- 4103200722 Response to intervenor 810220 first set 103200722 Response to intervenor bload first set re radiation release evacuations & emergency pla CASEY.S.B., KOCHER.C.R. Bouthern California Edi San Diego Ges & Electric Co. 81/03/19. (189p)
- B103230440 Memorandum Opposing finel prehearing co-early Apr. Conference is premature since Stata of of San Diego issuence of emergency plans are sub-discovery Certificate of Sec encl IMARTON R J. Friends of the Earth UMARTON R J
- Pegalies 81/03/11 5pp 07974 116 8103180077 Motice of appearance in proceeding Cent HDEFLING.R.K. Hearing Branch 4 (HT/ODV19 App

8103260756 Motion for order compelling Groups Unite Danger to answer applicants' second set of inter-intervenors failed to serve enswers & objections

- Intervenors ratted to serve ensuers on jections within 14 days after interrogetories served p100Tt.D R . KCCHER.C Bouthern California Edis. Chickering & Gregory 81/03/14 2pp 08036:09: --BIO3260761 Memorandum in support of applicants' 8
- 8103310915 Forwards listing of personnel responsible responses to each intervenor interrogatory Responsible scheduled for submittel by 810326 ROOD-H Licensing Branch 3 81703770 Spp. OE
- BIO3250449 Notice of ABLB reconstitution Jl. Kelly, c & CH Hand, members COTTER.B.P. Atomic Bafety and Licensing Hoard Pa 2pp. 07996.214

### H Ceneral correspondence

- 8103200699 Urges administration to adopt policy to of nuclear power plants & to appoint strong chair enforce policy.
  ALGUIST, A E , FCRAN, J F , MONTUYA, J B Californi 81/02/12 30p
- BIO3110470 Forwards Draige County Chamber of Commer favoring immediate licensing of facilities TRUHICL-L. D. Orange County, CA 01/02/27, 2pp
- B103270692 Requests decommissioning of Pacifities, d violations & risks of radiation.
  PIPER.D.L. APPLILATION Unknown. 81/03/08 1P
- 8103300392 Forwards on behalf of San Diego Associat resolution supporting operation of facilities Registrated OL per federal regulations re safety of nuc operations & emergency planning for plant accident MMFF.R. J. BanDiego.CA 81/03/19. 3pp 08039.1

# I. Financial information

- 8103110673 Forwards responses to Util Finance Brance 1.b-12. Index & info re decommissioning costs & un prices encl.
  BASKIN, K. P. Bouthern California Edison Co. 81/0
- --8103110678 "Decommissioning Costs." \* NUS Corp 3382. 79/10/31. 22pp 07887 123 --Bl03i10684 Participation agreement among utils & C Anahelm. CA Forms 10-K. 10-Q & B-16 & prospectus of Bouthern California Edison Co # San Diego Riverside. CA BO/II/12. 340pp 07887: 144.
- ---B103110690 Annual Financial Rapt 1980 Info re regu prices rate development & cost of money & requir encl.
  - \* San Diego Gas & Electric Co. 81/03/10. 76pp
- m-8103110698 Prepared testimony of JK Horton HF Chri Smith MD Whyte ME Ferguson RV Knapp et al. re uti for rate increase Prospectus enci. HORTON J. K. CHRISTIE M. F. HAUS A. P. Gouthern Co. 79/12/21 2440 07000-220 Co. 79/12/31. 244pp. 07868:220.

## DOCKETED ITEMS

- --B103110704 Prepared testimony & exhibits of RJ Cadenasso, on behalf or CA Association of Util Shareholders re general rate case
  CARFMASSOR J Affiliation Unknown 80/04/16 49nc 0/889 160
- --8103110710 Prepared testimony of DT Dardner re study of cost of capital & rate of return for Southern CA Edison Co GA9D1ER.D T California, State of 80/03/18, 44pp. 07889 209
- --8i03110713 Pregared testimony of HF Christie re request for general rate increase proceeding Current financial data encl CHRISTIE.H F Bouthern California Edison Co GO/11/30 14pp 07889 257
- -- 8103110718 Add1 prepared testimony of DT Cardner re general rate increase proceeding PARDHER, D.T. Southern California Edison Co. 80/11/18 7pp 07889 271
- --8:03110724 Prepared testimony of MC Lyons re general rate increase proceeding Estimated operational & financial attrition info LYCNS.M 9 California, State of 80/11/20 10PP 07807.278
- --8103110730 Decision 92949, granting util 791226 application for authority to increase rates for electric svc Decision commits util to increased developmental & fuel cost-efficient implementation of conservation measures California, State of 80/12/30 253pp 07859 288
- --8103110736 Prepared testimony of R Korpan re cost of capital & rate of return for 1982 test yr. KORPAN. R San Diego Gas & Electric Co BO/12/31. 91pp. 07890 194
- --9103110744 Prepared testimony of FH Ault re 1982 test yr.including comperative financial data for 1978 & 79 % summary of earnings 1980-03 AULT.F.R. San Diego Gas & Electric Co 80/12/31. 98pp. 07890-283
- --0103110740 Prepared testimony of PA Williams re cost of capital & rate of return for 1981 test yr MILLIAMS.P A San Diego Gas & Electric Co 80/07/31 27PP
- --0103110751 Prepared testimony of FR Ault re 1901 test yr.including comparative financial data for 1978 & 1979 & summary of earnings 1979-81. AULT.F H Ban Diego Pas & Electric Co BD/07/31 63pp 07891:006

07890 341

- --B103:10794 Testimony of E Quan re study of cost of capital & rate of return for San Diego Gas & Electric Co. QUAN.E California. State of B0/09/08 41pp. 07091 069
- --8103610760 "Rept on Results of Operation of Ban Diego Ons & Electric Co.Electric Dept.Test Yr 1981" California, State of 80/09/08, 100pp. 07891.110.
- --8103110762 "Rept on Results of Operation of San Diego Gas & Electric Co-Electric Dept. Test Yr 1981 " \* California, State of B0/09/08. 94pp. 07891.201.
- --8103110766 Decision 92597.conditionally granting util 800701 & 02 applications for increased rates & charges for electric & gas svcs & revised electric dept tariffs. Related info encl California, State of 89/12/31 535cp. 07891:259
- --8103110773 Annual Financial Rept for FY80 Related info encl. \* Anabeim, CA 80/06/30, 175pp 07892 130.
- ---8103110775 Annual Financial Rept for FYBO. BREWERLH.E. Riverside: CA. 81/03/10. 11pp. 07892:310
- M. Utility Final Bafety Analysis Report (FSAR) & amends
- 8103120553 Forwards application for amend to licenses submitted as Amend 23 to FSAR Amend 3 to fire hazards analysis drawlings & piping verification program FSAR amend includes emergency plan w/o privacy data Aperture cards will be in PDR DIETCH:R Bouthern California Edison Co. B1/03/05. Lp 07894 001
- --8103120357 Application for amend to Licenses CPPR-97 & CPPR-98 submitted as Amend 23 to FSAR Amend consists of responses to NVRS-0-0737 Std Nov 1980, emergency plan revisions, response to

- ~\*B103123559 Amend 23 to ERAR, Unit 1 & 2 Southern California Edison Co . \* San Diego Das & Electric Co 81/03/05, 2000nc 07895 121
- B103130276 Forwards Certificate of Bvc confirming direct distribution of Amend 23 to FBAR & Amend 3 to Fire Hazard Analysis per encl svc list. BARKIN K P Bouthern California Edison Co. 81/03/06 300 07907 001
- B103260545 Forwards revised Section 2 2 3 of San Onofre Units 2 & 3 FSAR Revision provides offsite hazards re-evaluation methods & results, & complies w/NRC criteria BASKIN.K.P. Southern California Edison Co 81/03/24. ip 09037 222
- --8103260991 Revised Section 2 2 3 to Ban Dnofre Units 1 & 2 FBAR. discussing methods & results of offsite herards re-Southern California Edison Co. 81/03/24 3600. 08037-223
- O Advisory Committee on Reactor Bafaquards reports & correspondence
- 9103050420 Forwards ACRB B10210 1tr re review of seismic & geologic matters re DL applications for facilities
  MIRAGLIA.F J Licensing Branch 3 81/02/13 4pp. 07826.091
- 8103050259 Notification of ACRS 810311-12 meeting Discusses Staff support necessary to avoid delay in issuing safety evaluation List of items on agenda & status of open items TEDESCO. R. L. Assistant Director for Licensing 81/02/23. 4pp. 07975 751
- B103170772 Notification of ACRS Subcommittee on San Onofre 2 & 3 8103 meeting & full Committee 910312 meeting in Washington. BC to discuss SER & Buppl 1 to SER Agendes encl TEDESCO.R. L. Assistant Director for Licensing. B1/03/09 7pp
- BiO0230442 Recommends that facility employ seismic scram sys similar sys employed at Diablo Canyon, set to actuate at 50% to 60% of BSE acceleration. MARK.J.C. ACRS Advisory Committee on Reactor Safeguards Bi/O3/17 3pp. 07977:047
- 8103310384 Forwards ACRB 810317 ltm re OL application review. MIRAQLIA, F. J. Licensing Branch 3. 81/03/23 4pp
- Q. Inspection reports, iE Bulletins & correspondence

07928 026

- 8103030512 Forwards IE Insp Repts 50-361/80-24 & 50-362/80-13 on B01216-19. No noncompliance noted. SPENCER, G S Region 5, Ben Franc Region 5. Ben Francisco. Reactor Construction & Engineering Support Branch 81/01/09. 2pp 07795 321.
- --B103030521 IE Insp Repts 50-361/80-24 & 50-362/80-13 on 801214-19 No noncompliance noted Major areas inspected const activities involving licensee action on previous insp findings & Constant Research Res Director DDDDG,R T Region 5. Ben Francisco, Reactor Construction & Engineering Support Branch 81/01/08. App. 07795 323
- 8103020051 Forwards IE Circular 81-02, "Performance or NRC-Licensed Individuals While on Duty." No written response required. ENGELKEN.R.H Region 5. San Francisco. Office of the Director. 81/02/09. 19 07787:251.
- 8103160322 Forwards IE Info Notice 81-03 "Checklist for Licensee Makin Notifications of Bignificant Events in Accordance W/100FR80.72 " No response required. ENGELKEN.R.H. Region 5. Ben Francisco. Office of the Director. 81/02/12. Ip 07922:032
- 8103160658 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines." No response required. ENOCLKEN.R.H. Region 3: San Francisco: Office of the Director. 81/02/27: [p. 07914:20]
- 8103170002 Forwards IE Circular 81-03. "Inoperable Baismic Monitoring Instrumentation." No response required EMBELKEN.R.H. Region 9. San Francisco. Office of the Director. 81/03/02. 1p. 07939.100.

- 8103160882 Forwards revised (E. Bulletin 81-01. "Survey Hance of Hechanical Shubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ENGELMENR H. Region 3. San Francisco. Office of the Director 81/03/04 1p. 07915 021
- 8103200243 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater " No response required ENGELKEN R. H. Region 5. Ban Francisco. Office of the Director B1/03/11 12 07968.331
- 8103200072 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades" No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director. 81/03/13 1g 07970 254
- 8 Reportable occurrences. LERs & related correspondence
- 8103020423 Final deficiency rept re-potential release of contaminated uster initially reported 810107. Caused by inadequate cotor control ctr assignments for Train A Assignments will te changed prior to fuel loading FAPAV.L T. Bouthern California Edison Co. 81/02/03 2pp 07/784 119
- BIO3100406 Ph8-V-Bi-003 on Bi0303 switchboard operator received bomb threat from unidentified caller Search of facility revealed no bomb ensite info assessment team has been notified SCHMAN.C. Region 5. Ben Francisco, Office of the Director Bi/03/04 1p
- 8103180959 Interim deficiency rept no compliance of bolting matts butASME Boiler & Pressure Vessel Code Section III.

  NCA-3887. 4(e) Final rept is delayed until 810918 due to difficulty in obtaining info from suppliers

  MUHN. D.E. Southern California Edison Co. 81/03/13. ip 07993-235
- T. Hearing transcripts on non-antitrust matters
- 8103180645 Francript of ACRS Subcommittee on Sen Onofre 810311 Freting in Washington, DC Pp 1-224 Vieugraphs encl.

  \* ACRS ~ Advisory Cormittee on Reactor Safeguards 81/03/\$1, 227pp. 07947: 329
- U. Congressional/Executive Correspondence
- Bi03240091 Forwards fourth monthly status rept to Congress for Bi0115-0215 Rept discusses actions talen on licensing reviews of new facilities. Rept will be ahended to include add1 info requested on Bi0217
  KAMMERER, C. Office of Congressional Affairs. Bi/02/27. 3pp
- DDCKET 50-353 FORKED RIVER NUCLEAR STATION, UNIT I

  A. Application/construction stage documents & correspondence
- Bio3i90732 Ltrs to all licensees of operating plants applicants for CLs & holders of CPs rs control of heavy loads Requests review per guidelines in NUREQ-Obiz Forwards NRC position reinterim actions & request for addition.

  EISENHUT, D. Q. Division of Licensing 80/12/22. 30pp.
- 6103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for anviron qualification of safety-related electrical equipment. Items addressed involve cold shutdown-replacement parts & NUREO-0737. EISENMUT.D.O. Division of Licensing. 81/01/19. Spp.
- 8103120014 Ltr to all licensees of operating plants, CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & FMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads. EISENHUT, D. O. Division of Licensing. 81/02/03. 6pp.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A.1.2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met. EISENHUT.D. 9. Division of Licensing. 81/02/18. 12pp.
- Bi03250024 Ltr to all power reactor licensees & license applicants re MMRC-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to

- 8103230813 Generic Ltr B1-06 to all CP holders & 10CFRSO 71(e). "Periodic Updating of FSARs." ef 803722 Info re FSAR legal status.fornat & contesting E15EUMUT.D.C Division of Licensing 81702/26
- 8103310804 Ltr to all licensees of operating plan & holders of CPs forwarding SECY-81-119 re info establish environ qualification of safety-relat equipment. EISENHUT. D.O. Division of Licensing 81/03/10
- F Security, medical, emergency & fire protection
- 8103310330 Ltr to all licensees of operating plan forwarding huREO-0596. "Functional Criteria for Response Facilities" Criteria describe accepta for nesting NRC requirements M/o encl EISEKHUT. D O. Division of Licensing 81/03/05
- a Inspection reports, IE Bulletins & corresponds
- 8103200190 Forwards IE Circular 81-03, "Inoperabl Instrumentation" No written response required. GRIER. B H Region 1, Philadelphia, Office of t 81/03/02. Ip 07966 191.
- 8103200085 Forwards revised [E Gulletin 81-0]. "8
  Mechanical Snubbers." w/corrected Pages 5 & 6 C
  identification of facilities w/CP to which bull
  applicable does not affect util requirements.
  GRIER. B. M. Region 1. Philadelphia. Office of t
  81/03/04. ip 07968 214
- 8103200130 Forwards IE Info Notice 81-06, "Failur Circuit Breater " No response required ORIER.8 H Region 1. Philadelphia, Office of t 81/03/11. 1p 07469-286.
- DOCKET 30-364 J35EPH M FARLEY NUCLEAR PLANT, UNI E. NRC Safety Evaluation Report (BER), supple & c.
- B103250642 Forwards Suppl 5 to SER (NUREO-0117) W SCHWENCER, A Licensing Branch 2, 81/03/19 2
- 8103270079 BAFETY EVALUATION REPORT RELATED TO THE M. FARLEY NUCLEAR PLANT.UNIT 2 Docket No. 50-36 Power Company) \* Office of Nuclear Reactor Regulation, Direct B1/03/31. 153pp Available at NTIS \$5.50
- F. Becurity, medical, emergency & fire protection
- 8103060475 Requests NRC assistance in developing of projection model for use in ordering offsite preactions:per FEMA recommendation. Written statement and iffying factors requested re App 2 of LVREGO-OMCNEES.J.L. Alabama. State of 81702/18 2pp
- 8103100184 Submits info re-physical security plan (ref 10CFR2 790). CLAYTON.F. L. Alabama Power Co. 81/03/04. Ip.
- 8103100381 Discusses results of confirmatory sound control room noise level Control noise b elemmacceptable. No further action is required. CLAYTON.F. L. Alabama Power Co. 81/03/04. 1p
- BIO3310338 Ltr to all licensees of operating planforwarding NUREO-0595. "Functional Criteria for Response Facilities." Criteria describe acceptat for meeting NRC requirements W/o encl. EISENMUT.D 9. Division of Licensing. 81/03/05.
- B109250429 Bubmits fire protection upgrade respon-10CFR50 App R requirements. Info re implementation plant areas inaccessible while unit is operating description for alternate shutdown encl. CLAYTON-F. L. Alabama Power Co. 81/03/19 7pp
- O. Adjudicatory correspondence

- J Incurance & Indemnity information
- 8103060351 Forwards Endorsement 2 to MAELU Binder XB-73 FIELDER, J. Marsh & McLennan. Inc., IS & M. Muclear Consultants. Inc. Div. 81/01/27, 2co. 07840, 231
- 8103060416 Forjands Endorsement i to MAELV Binder X8-73 FIELDER, J. Harsh & McLennah. Inc . M & M Nuclear Consultants, Inc Div. Bi/O1/27 3pp 07837 329
- 8103060442 Forwards Endorsement 4 to MAELU Binder XB-62 FIELDER J. Marsh & McLennan Inc , M & M Nuclear Consultants Inc Div 81/01/27 3pp 07837 325
- 8103:10637 Forwards Endorsement 5 to HAELV Binder X8-62 FIELDER, J. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc. Div. 81/03/06 Zpp. 07877 398

### M Antitrust correspondence

- BIO3:80606 Discusses Municipal Electric Util Authority petition for extraordinary relief. to hasten ASLB decision on antitrust review ASLB should not be pressured to reach sarly decision BALCH, S E Balch, Bingham, Bater, Hauthorne, Williams & Ward B1/03/\$1 13cs. 07953.075
- P Operating license stage documents & correspondence
- B103120014 Ltr to all licensues of operating plants CP holders & OL applicants, except Indian Point 2 & 3.2 ion 1 & 2 & TMT-1, forwarding inadvertently omitted pages from NRC B01222 request for add1 info re control of heavy loads. EISENHUT D. 9 Division of Licensing, 81/02/03. App
- B103300160 Ltr to all operating PWR licensees requesting info on auxiliary feedwater sys seismic design Forwards request for aid; info, list of actions inquested of licensees o/o seismically qualified sys & results of NGC walkdowns.

  EISENHUT.0 0 Division of Licensing. 81/02/10 13pp.
- BIO3160669 Ltr to all operating plants & CP holders forwarding colarification of TMS Action Plan Item III A.1 2 re upgrade of emergency support facilities. Requests confirmation within 49 days that implementation dates will be met. EIEENHUT.D 0 Division of Licensing. 81/02/18 12pp.
- 8103050652 Forwards Revision 2 to FNP-O-M-007, "Emergency Dose Calculational Manual " Revision intent is to improve backup/ interim dose calculational method by providing better plume boundary definition. CLAYTON F L Alabama Power Co. 81/02/19 1p 07832-026
- --8103050654 Revision 2 to "Emergency Dose Calculational Manual"
  HCCRACKEN,K W. Alabama Power Co. 81/02/16, 71pp, 07832:027.
- 8103020451 Forwards addl info.per NRC 810213 ltr.re facility @-list. Measuring & test equipment used for safety-related structures.sys & components & mesonry walls per IE Dulletin BO-II discussed. CLAYTON F L. Alabama Power Co. 81/02/20, 10pp. 07785.121.
- 8103020304 Forwards add! Class IE electrical equipment environ qualification info, in response to Bi0109 NUREG-058B audit exit meeting Mester list of equipment required to function under postulated accident conditions encl.
  CLAYTON.F L. Alabama Power Co. 81/02/20 33pp. 07785:066
- 8100250024 Ltr to all power reactor licensees & license applicants re NUREG-0619 criteria Footnote 2 in Table 2 contains error due to leatage testing deletions. Licensee may submit analysis to justify use of existing low flow controller. EISENHUT-D Q. Division of Licensing. 01/02/20. Spp.
- 8103020388 Forwards add1 info per NRC 810220 telcon-clarifying TMI action plan requirements. Shift manning & guidance on procedures for verifying correct performance of operating artivities discussed. CLAYTON, F. L. Alabama Power Co. 81/02/23. 5pp. 07785: 217.
- 8:03030606 Forwards addl Q-list info in clarification of 8:0220 ltr. per MRC B10224 telcon Justification provided for Items not appearing on list. CLAYTON-F.L. Alabama Power Co. 81/02/25. 10pp 07774:196.
- 8103040703 Confirms that seismic qualification review teem mods discussed in 810209 ltm & 810228 telcon have been completed. CLAYTON F. L. Alabama Power Co. 81/02/26 ip. 07810:044.

- A103100530 Application to amend License NPF-B authorizing temporar railef from App A Tech Bpecs to perform augmented Low Power Tast 501-7-007 "Natural Circulation Cooldown & Boron Mixing." Class III amend fee and 81/02/27, 4pp. 07865.252 CLAYTEN F L Alabama Power Co
- --8103100531 Revision 3 to 'Special Low Power Tests Bafety Evaluat

  + Alatama Power Co Bi/01/31 Sipp 07865 257.
- 810310049B Forwards revised Tech Specs confirming basis for loss of flow trip to prevent QNB in event of loss of one or more reactor coolant pump Revised Tech Specs reflect new DNBR CLAYTCN, F L Alabama Power Co 8(/03/04 1p 07867, 215.
- --8103100503 Revised Tech Specs re limiting safety sys settings.
  4 Alabama Power Co 81/03/04. 2pp 07867:217
- 8103120207 Requests add1 info supporting safe operation of plant & compliance o/GDC4 me deficiencies found in environ qualifications of safety-related electrical equipment by 810309 Equipment evaluation mept per NyRGO-0588 encl.

  TEDESCORR L Assistant Director for Licensing. 81/03/04 2pp A7904 187
- --8103120216 "Equipment Evaluation Rapt by Oft of Nuclear Reactor Regulation Equipment Qualification Branch for AL Power Co. Farley Unit 2 "
  - # Equipment Gualification Branch 81/03/04 43pp. 07906:19
- B103130399 Notifies that util review of N4C 810304 evaluation of facility response to NUREG-0568 indicates that plant meets General Design Criteria 4 & can operate safely, Iten-by-item re-evaluation per 810304 itr will be provided later. CLAYTON, F. L. Alabama Power Co. 81/03/06 2pp 07907.077.
- Bi03310B0A Ltr to all licensees of operating plants applicants for & holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical EIBENHUT. D 9 Division of Licensing 81/03/10 6pp
- 8(03)90078 Unofficial transcript of 8(03)1 meeting in Hashington.Do discussion & possible vote on full pawer license for Farley Pp 1-36
  - Commissioners. 81/03/11. 37pp 07961 001
- -- 8103170693 Forwards drafts of transmittal itr to util. License NPI FR notice; to be used in 810311 meeting w/Commission DIRCKB.W.J. Office of the Executive Director for Operations. 81/03/06 22pp. 65121:038.
- -- 8103190103 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF OSTYOLOG SAFELY EVALUATION REPORT INCLUDED IN THE GENERAL OF UNGERING ME. FARLEY NUCLEAR PLANT, UNIT 2 Docket No 50-034 (Alabama Power Company). Supplement 5 to NUREG-75/034 • Office of Nuclear Reactor Regulation Director. NUREG-0117 DRFT: 81/03/11. 110pp. 07762-181
- --B10319010B ETS (nonradiological) for facility.

  \* Alabama Power Co. B1/03/11. 15pp. 07962-325
- B10327069B Informs of delay in completion schedule for subcooling a mods, originally scheduled for 810501 Delay caused by problems in equipment receipt & design change review. Completion currently scheduled for 810531. CLAYTON, F. L. Alabama Power Co. 81/03/20. 2pp. 08042-344.
- 8103310288 Application for temporary amend to Licenses NPF-2 & NPF changing Tech Spec 3.7.4 to allow facilities to be in Modes 1-2 during mod requiring voluntary limiting conditions for operation of svc water sys. Class III fee encl.

  CLAYTON, F. L. Alabama Power Co. 81/03/24. 5pp. 08079.068.
- --Bi03310294 Proposed temporary revision to Tech Spec 3.7.4 re lim conditions for operation of svc water sys. Bases for changes encl. \* Alabama Power Co B1/03/24. 4pp. 08079:073.
- BIO0270401 Forwards Amend 77 to FBAR for Unit 1 & QL application f Unit 2.Certificate of Svc encl. CLAYION F. L. Alabama Power Co. B1/03/25. 3pp. 08046:024.
- --B103270411 Application for Amené 77 to FSAR for Unit 1 & OL appl for Unit 2 CLAYTON, F. L. Alabama Power Co. 01/03/25. 3pp. 08046:032.

- Q. Inspection reports. JE Bulletins & correspondence
- 81030800AB Forwards IE Inso Repts 50-348/80-38 & 50-364/80-49 on BOI202-05 No noncompliance noted MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. B/001/15 20p 07827 254
- --8103050078 IE Insc Rests 50-348/80-38 % 50-364/80-49 on 801202-05. 1030500/8 IE They hepth Surjandou-30 % 30-304/90-49 on Golave No nancompliants noted Hajor areas inspected installed equipment review per IE Bulletin 79-018 & hJREO-0380. GIBBONS, T. D., CONLON, T. E. Region 2. Atlanta, Office of the Director 81/01/14. Spp. 07827.236
- 8103050390 Forwards IE Into Repts 50-348/80-37 & 50-364/80-51 on Bugsts-18 No noncompliante noted
  MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering
  Bupport Branch. Bi/01/29 2pp 07824 279
- --8103030410 [E Insp Repts 50-348/60-37 & 3C-344/80-91 on 801215-18 No noncompliance noted. Hejor areas inspected: inservice insp. noncompliance holds. Major ereas inspected inservice insp.

  low pressure turbine disc tracking previous insp findings

  § IE Bulletin 80-08.

  CROMLEV.B R. Region 2. Atlanta, Office of the Director
  MEROT.A R. Region 2. Atlanta, Reactor Construction & Engineering
  Support Brench. Bi/01/28 7pp 07824 281.
- 8103090747 Forwards IE Insp Repts 50-348/80-36 & 50-364/80-48 on BIOHR.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch, 81/02/03. 2pp. 07849 189
- --0103090755 IE Insp Repts 50-349/80-36 & 50-364/80-48 on 801117-21 No noncompliance noted Major areas inspected coordinated number places represented the season of the State of the Street of Jenish Street of the Street of Jenish Street of Jenish Street of the Street of Jenish J
- 8103020289 Forwards 1E Circular 81-02, "Performance of NRC-Licensec Individuals While on Duty." No written response required D'REILLY.J.P. Region 2, Atlanta, Office of the Director 81/02/09 19. 07785 328
- 8103160954 Forwards IE Insp Repts 50-349/80-40 & 50-364/80-50 on 601103-28 No noncompliants noted. LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Syanch. 81/02/10 2pp 07915 122.
- --9103160960 IE Inso Repts 90-348/80-40 & 50-364/80-50 on 801103-28 No noncompliance noted. Major areas inspected plant status, cross connection of syc water pump tube & cooling Later & plant Director, JULIAN.C.A Region 2, Atlanta, Office of the Director, JULIAN.C.A Region 2, Atlanta, Reactor Operations Nuclear Support Brench. 81/02/10 8pp 07915:124
- 8103190030 Forwards 15 Insp Rept 50-364/81-02 on 810126-28. No Noncompliance noted

  BTOHR, J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 81/02/11, 2pp. 07964.110
- --B103190057 IE Insp Rept 50-364/81-02 on B10126-28 No noncompliance noted Major areas inspected radiation protection redusets moves, rejor areas imspected.radiation protection, radobate mgt. effluent control procedures & waste sus mod TROUP.O.L. Region 2. Atlanta, Office of the Director OIBSON,A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. B1/02/10 Spp. 07964:112.
- 8103040126 Forwards IE Info Notice 81-03. "Checklist for Licensess Making Notifications of Bignificant Events in Accordance M/IOCFRSO. 72. " No written response required.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/02/12.

  1p. 07819:327.
- 8103020451 Forwards add1 info.ger NRC 810213 ltr.re facility 8-list deasuring & test equipment used for safety-related structures, sys & components & masonry walls per IE Bulletin CLAYTON F L. Alabama Power Co. 81/02/20 10pp. 07785-121.
- 8103160716 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines. No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/02/27. ip. 07914 095
- 8103160674 Forwards 16 Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required.
  0'RETILLY. J.P. Region 2. Atlanta, Office of the Director. 81/03/02
  1p. 07914:296.

- Bl03170056 Forwards revised IE Bulletin 81-01. \* IQGI70056 Forwards nevised IE Bulletin 81-C1. \*
  Mechenical Shubbers," w/corrected Pages 5 & 6
  identification of facilities w/CPs to which bu
  applicable does not affect util requirements
  O'REILLY-J P Region 2- Atlanta, Office of th
  12 07939 179
- BL03130729 Forwards IE Insa Rept 80-354/81-06 on noncompliance noted LEUIS.R.C. Region 2. Atlanta. Reactor Operati Branch 81/03/06 2pp 07912 065
- --8103130733 IE Insc Rest 50-364/81-06 on 810223 103130733 IE Insp Rept 30-364/81/06 on B10223 noted Major areas inspected security organizinglementing procedures Details withheld (remgORE.O E Region 2. Atlanta. Office of the MCGUIRE.O R Region 2. Atlanta. Free Facili
- 6103200238 Forwards IE Info Notice 81-06. "Failu Circuit Breater' No response required O'REILLY, J.P. Region 2. Atlanta. Office of th Ip 0768 334
- B103240775 Forwards IE Safety Imap Repts 50-348/ LEWIS.R C. Region 2. Atlanta. Office of the D 2pp 07983 281
- ~-8103240786 IE Safety Insp Repts 50-348/81-04 & 810224-27 No noncompliance nuted Major areas follows of IF Bulletin BC-11. licenses actio to the principle of the state o
- B103190864 Forwards 1E Info Notice B1-05. "Degra Palisades " No response required O'REILLY, J. P. Region 2. Atlanta. Office of th 1p 07965 275
- 8103260355 Forwards IE Health Physics Appraisal 30-364/80-52 notice of violation & significant findings. D'REILLY, J.P. Region 2. Atlanta, Office of th
- --B103260360 Notice of violation from health phy 801501-15 \* Region 2, Atlanta, Office of the Director
- --8103260370 IE Health Physics Appraisal Repts 5 30-364/80-32 Noncompliance noted failure to procedures for release of sys for maint HOSEY.C.M. PERRY.W. QIBBON.A.F. Region 2. Director 81/03/10 2600
- A Periodic operating reports & related correspo
- 8103060518 Forwards "Semiannual Radioactive Effl Jul-Dec 1980 ' CLAYTON, F. L. Alabama Power Co. 81/03/02 1p
- --8103060529 "Semiannual Radioactive Efficent Re \* Alabama Power Co 81/03/02 83pp 0783
- 8103170653 Forwards monthly operating rept for F
- CLAYTOM F L Alabama Power Co 81/03/09 Ip
- --8103170656 Monthly operating rept for Feb 1981. MAIRSTON, W. G. Alabama Power Co. 81/03/01.
- 8103250072 Bubmits 1980 annual rept of changes t 100FR50. 59. GL received on B01023. No changes to experiments were implemented in 1980. CLAYTON F. L. Alabama Power Co. 81/03/17. 2p.
- U. Congressional/Executive Correspondence
- 8103240091 Forwards fourth monthly status rept to 910115-0215 Rept discusses actions taken on its reviews of new facilities. Rept will be amended additinfo requested on 910217. KAMMERER, C. Office of Congressional Affairs

### v Operator Examinations

- 8103020388 Forwards add1 info per NRC 810220 telcon.clarifying TMI action plan requirements Shift manning & guidance on procedures for verifying correct performance of operating activities discussed CLAYTON.F.L. Alabama Power Co. 81/02/23 Son
- DOCKET 50-366 EDWIN 1. HATCH NUCLEAR PLANT, UNIT 2

  F. Security, reducal, emergency & fire protection plans
- 8103180264 Lir to all power reactor licensees w/plants licensed prior to 770101 Forwards NRC position & request for addl info results about down capability for compliance w/801119 fire protection rule.
  EISENHAUTO 0 Division of Licensino 81/02/20 13on
- 8103310330 Ltr to all licensess of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities 'Criteria describe acceptable method for meeting NRC requirements. H/o encl EIGENHUT, D O Division of Licensing 81/03/05. App.
- J. Insurance & indemnity information
- 8103050450 Forwards Endorsement 4 to MAELU Dinders X8-51 & X8-67 W/o Binder X8-51. FIELDERJ Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div 81/01/28, 3pp. 07837.323.
- P. Operating license stage documents & correspondence
- 6:03:90732 Ltrs to all licensess of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0512 Forwards NRC position re interior actions & request for addl info EISE/NHV.D O Division of Licensina 80/12/22 30op.
- BIO3190387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment liens addressed involve cold shutdown replacement parts & NUREO-0737.
  EISENHUT. 0 0 Division of Licensing 81/01/19. 6pp.
- Bio3240290 Ltr to all BWR licensees forwarding Suppl 1 to generic safety evaluation on BWR scram discharge sys Summarizes researchation of interim measures recommended per Bol201 safety evaluation.
  EISENWINT.D. 0 Division of Licensing. 81/01/23. 200
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC B01222 request for add1 info re control of heavy loads. EIBENHUT.D Q. Division of Licensing 81/02/03 App.
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of IMI Action Plan Item III. A 1 2 re upgrade of exergency support facilities. Requests confirmation within 45 days that implementation dates will be not EIBENHUT, D. 9. Division of Licensing. 81/02/18. 12pp.
- 8103060497 Advises that Classes IV & I fees are required for Tech Spec review of 800919 application. HOLLOHAY. C.J. License Fee Management Branch 81/02/20. ip. 07836: 242.
- B103290324 Ltr to all power reactor licensees & license applicants re MUSEO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller.
  EISENHUT.D G Division of Licensing. 81/02/20. 8pp.
- B103020514 Requests mod of schedules for completion of Merk I program per NRC B10113 orders. Completion is tied w/1982 refueling outage for each unit Requests hearing in event NRC does not approve or act upon request.
  WIDNER, W.A. Osorgia Power Co. B1/02/24 3pp. 07782:094.
- 8103230030 Ltr to all licensess of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUT.D.O. Division of Licensing. 81/02/25 Spp.

- 8103100425 Application for amond to Licenses NPF-5 & DPR-57 submitte as proposed changes to Tech Specs re 8MR scram sus designs MICNCR-M A Georgia Power Co 81/02/26 30a 07867 233
- --8103100429 Tech Spec Tables 3 6 3-1.3 7-1 & Page 3 7-20 for primary containment isolation valves. • Georgia Power Co. Bit/02/26 Spec. 07867 236
- BiO3170228 Ltr to all BHR licensees (except Humboldt Bey & LeCrosse) requesting review of ASME Code Class 1 % 2 pressure boundary piping, safe ends & fitting mati per guidelines of enci Revision 1 to NUREG-0313 Model Tech Specs only enci EISEIBHJT. D 9 Division of Licensing B1/02/26. Jpp.
- --Bi03170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4
- B103230813 Generic Lir B1-06 to all CP holders & DL applicants re 10CFR50. 71(e). "Periodic Updating of FBARs." effective B00722 Info re FBAR legal status format & content encl. EISENHUT.D G Division of Licensing D1/02/26 10pp
- 8103120502 Forwards Amends 81 & 22 to Licenses DPR-57 & NPF-5, respectively & notice of issuance & availability REID/R W Operating Reactors Branch 4. 81/02/27 3pp 07905.227
- --Bi03120505 Amends BI & 22 to License DPR-57 & NPF-5, respectively, revising administrative control Tech Specs re requirements for Pacility safety review board insp & audits.
  REID,R W. Operating Reactors Branch 4. BI/02/27 9pp. 07905:229.
- --Bi03120508 Notice of issuance & evallability of Amends Bi & 22 to License DPR-57 & NPP-5, respectively. REID.R W. Operating Reactors Branch 4, Bi/02/27, 3pp 07905:238
- BIO3100485 Submits add1 info re SWR scram discharge sys mods.per BO10 request Mods will be implemented as needed to result in conformance to owners group criteria by end of 1982 provided qualified equipment is commercially available.

  WIDKER. M. A. Georgia Power Co. 81/03/04, 2pp. 07867.221
- 8103130570 Submits add1 info restatus of compliance w/NUREG-0737. Ite [I K.3 27 No changes required rezero ref point for reactor presture vessel water level If NRC disagrees, implementation of hardware mods may be later than 810701 WIDMER. W. A. Georgia Power Co. 81/03/06, ip. 07911:288.
- 81031605B9 Notifies that util 801010 commitments to BHR scree dischar sys long-term mods for not actisfy NRC criteria Revised Tech Specs must be proposed at least 3 months in advance of mod completion dates. REID.R W Operating Reactors Branch 4. 81/03/06. 2pp 07915:200
- 8103190218 Forwards Amend 23 to License NPF-5, safety evaluation & notice of issuance & availability REID.R W. Operating Reactors Branch 4 81/03/06. 3pp. 07965-070
- --Bi03190231 Arend 23 to License NPF-5, adding limiting conditions for operation & surveillance requirements for sys monitoring output of power supply for reactor protection sys. REID-R W Operating Reactors Branch 4, 81/03/06 9pp. 07965:073
- --Bi03190235 Befety evaluation supporting Amend 23 to License NPF-5

   Office of Nuclear Reactor Regulation, Director. 81/03/06. 3p
- --B103190242 Notice of issuance & availability of Amend 23 to License NFF-3. REID-R.U. Operating Reactors Branch 4, B1/03/06 2pp. 07965:089.
- 8103310B04 Ltr to all licensees of operating plants, applicants for OL & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT.D.O. Division of Licensino. 81/03/10. 600.
- B103270093 Bummary of B10304 meeting w/Mark I owners group & QE in Betheede,MD re supplementary tests conducted in full-scale test facility & resolution of outstanding Mark I issues per NUREO-0661. Blide presentation & list of attendees entl. GRIMES.C. I. Licensing Branch 3 81/03/16 5pp

- B100240509 Bubmits commants & requests for certain exemptions from final version of 10CFR50 48-App R.per B10220 request MIDNER. H A Georgia Power Co 81/03/19 14pp 07986 14B
- 8103300268 Requests extension of two USs for submittal of snubber surveillance Tech Spece requested in fiRC 801120 ltr Addition will allow sufficient review of mechanical snubber listing & time to obtain necessary info from vendor MIDNER. M A Georgia Power Co 81/03/23 lp C8055 282
- O. Inspection reports, IE Builetins & correspondence
- 8103050358 Forwards 1E Myt Maeting Repts 50-321/80-41, 50-366/80-41, 50-424/80-16 & 50-425/80-16 on 801020 No noncompliance noted D'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/01/29 2pp 07824: 227
- --9103030368 IE Mgt Meeting Repts 30-321/80-41.50-366/80-41.50-424/80-16 & 50-423/80-16 on 801020 Mejor areas discussed: MRC evaluation of util regulatory performance per systematic assessment of licenses performance program LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/01/28 lopp 07824-229
- BIO3090784 Forwards IE Mgt Heeting Repts 50-321/80-51 \$ 50-366/80-51 on BO1223 No noncompliance noted MURPHY.C.E. Region 2- Atlanta. Reactor Construction & Engineering Support Branch. Bi/O1/30 2pp. 07849 225.
- --BI0J090789 [E Mgt Heeting Repts 80-321/80-31 & 50-366/80-51 on B01223 Major areas discussed:repairs to backfill supporting RHR & sec water piping at intate structure.

  LENAMAN, J. J. Region 2. Atlanta. Office of the Director.

  CONCON, T. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/01/29 3pp. 07849-227
- B103020263 Forwards IE Circulan B1-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/02/09, 1p. 07785: 333
- B103160094 Forwards IE Imp Repts 50-321/80-45 & 50-366/80-45 on 801014-1114. No noncompliance hoted. LEWIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B1/02/09. 2pp. 07921-165.
- --Bio3160107 IE Insp Repts 50-321/80-45 & 30-366/80-43 on B01014-1114 No noncompliance noted Major areas inspected: fach Base compliance. Ros operator performance. GA practices, corrective & preventative maint activities.

  ROSERB.R.F. Region 2. Atlanta, Defice of the Director. DANCE.H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 81/02/09. 3pp. 07921:167.
- 8109020709 Bupplements previous response to IE Bulletin 80-24, Item 3 reprevention of demage due to water leakage inside containment. Bpill accurred in closed sys white in cold shutdown on 791218, Caused by personnel error.

  HIBNER, M. A. Georgia Power Co. 81/02/10 Ip. 07784:091.
- 8103040138 Forwards 1E info Notice 81-03, "Checklist for Licensees Making Notifications of Bignificant Events In Accordance M/10CFR30, 72. " No written response required, O'REILLY, J. P. Region 2- Atlanta, Office of the Director, 81/02/12, ip. 07819:341,
- 8103100723 Forwards Suppl 5 to IE Sulletin S0-17. "Failure of Control Rods to Insert During Screm at SWR." No written response required O'REILLY, J.P. Region 2. Atlanta, Defice of the Director. 81/02/17. 1p. 07866:319.
- 8103170093 Confirms commitment to install qualified limit switches & solenoids by 820630. Commitment will be reflected in package updating util response to IE Bulletin 79-018, "Environ Qualification of Class iE Equipment."

  WIDNER, W. A. Georgie Power Co. 81/02/17. 2pp. 07935:355.
- 8103160694 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines: "No response required. O'REILLY.J.P. Region 2. Atlanta, Office of the Sirector. 81/02/27. 1p. 07914:047.
- 8103160560 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation." No response required.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/02.
  19. 07916:340.

- Bioli70079 Forwards revised IE Bulletin Bi-Oi. "Surveillandechanical Gnutbers." w/corrected Pages 3 & 6 Change in identification of factilities w/CPs to which hulletin is applicable does not affect util requirements O'REILLY. J P. Region 2. Atlanta. Office of the Director.
- 8103160862 Responds to IE Bulletin 79-018. "Environ Qualificate IE Equipment" Plans for "exact-kind" & "like-kind replacements outlined UIDMER, WA Ocargia Power Co 01/03/05 2pp 07915 2
- 8103260903 Forwards update to 810217 response to 1E Bullet Environ Qualification of Class 1E Equipment "Update provides justification for continued operation considerty MSIV limit installations as inadequate W/o encl MIDMER.W.A. Georgia Power Co. 81/03/09 p. 08007-20.
- B103240B34 Forwards IE Insp Repts 50-321/B1-04 & 50-366/B1 810110-0220 & notice of violation LEMIS.R C. Region 2. Atlanta, Office of the Director

2pp 07984.234

- --8103240039 Notice of violation from insp on 810110-0220 s Region 2. Atlanta. Office of the Director 81/03/16
- 07984-236.

  --8103240B48 IE Insp Repts 50-321/01-04 & 50-366/81-04 on the Noncompliance noted imperability of core spray system ROCES.R F. KELLOGO.P. Region 2. Atlanta, Diffice of 81/03/09 10pp 07934-237
- B103200263 Forwards IE Info Notice B1-06. "Failure of ITE I Circuit Breaker" Mo tesponse required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director Ip 07968-358
- 8103240800 Forwards IE linsp Repts 30-321/81-03 % 50-366/N3-810217-20 % notice of violation. LEMIS.R.C. Region 2- Atlanta- Office of the Director.
- --8103240807 Notice of violation from Insp on B10217-20
  \* Region 2. Atlanta. Office of the Director B1/03/8
- --BI03240819 IE Insp. Repts 90-321/BI-03 \$ 50-366/BI-03 on i Noncompliance noted failure to implement procedure to retrieve documents & to accomplish error analysis PEEBLES T.A., BRYANT, J.C. Region 2, Atlanta, Office of Director, 81/03/10, 5pp.
- 6103200036 Forwards IE Info Notice B1-D5. 'Degraded DC 8ys Patitades.'' No response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Directur ip. 07967:103.
- B103240291 Ack receipt of B10306 itr informing NRC of step correct violations noted in IE Insp Repts 50~366/01~01 & 50-321/81-01 LEWIS.R.C. Region 2. Atlanta, Office of the Director.
- ip 07986:322.

  --8103240295 Responds to NRC 810209 itr re violations note: Repts 50-366/81-01 & 80-321/81-01 Corrective actions. rearranged drywell control point requiring workers to rediction work permit prior to return of security badg MIDNER, M. A. Georgia Power Co. 81/03/06 2pp. 07986
- LEWIS.R.C. Region 2. Atlanta: Reactor Operations Nucli Branch. 81/02/09. 2pp. 07986:325.

  --8103240396 Notice of violation from insp on 801126-81010° \* Region 2. Atlanta: Office of the Director. 81/02/0° 07986:327
- --8103240312 IE Insp Repts 50-366/81-01 & 50-321/81-01 on E Noncompliance noted: failure to record drywell exit radiation doses for six workers.
  - Noncompliance noted: Failure to record drywell exit radiation doss for six workers. RODERBURF. Region 2. Atlanta, Office of the Director Region 2. Atlanta, Reactor Operations Nuclear Support 81/02/09. 4pp. 07986:328.
- 8103260100 Responds to 18 Sulletin Bi-Oi. "Burveillance of Snubbers." Unit i has two accessible snubbers mfg by Int. Nuclear Safeguards Corp installed on safety-related syst. 2 snubbers replaced w/Pacific Scientific snubbers on BiOS MIONER.W.A. Georgia Power Co. 81/03/13. 3pp. 08042:13

- 8103290133 Ack receipt of 810223 & 0313 ltrs informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/80-46 & 50-366/80-46 LEWIS.R.C. Region 2. Atlanta. Office of the Director 81/03/19 pp. 07976.001
- --B103250137 Submits revised response to 810223 ltr re violation noted in 1E Imap Repts 50-321/80-46 & 50-365/80-46 Uses NRC-desired format Corrective actions Unit 1 IBI project plan review & approved WIDMER.W A Georgie Power Co. 81/03/13 2pp. 07996 002.
- --0103250142 Responds to NRC Biol29 ltr re violation noted in IE Imap Repts 50-321/80-46 th 50-366/80-46 Corrective actions: procedure revised so that inservice inap project plans cill be reviewed & approved by plant review board prior to inap. HIDNER-H A Georgia Power Co. 81/09/23 2nn 07994 NNA
- --8103250145 Forwards IE Insp Repts 50-321/80-46 & 50-366/80-46 on 801203-05 & notice of violation. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/29. 2pp 07996 006.
- --B103250154 IE Inep Repts 90-321/80-46 & 50-366/80-46 on 801203-05.
  Noncompliance noted failure to approve inservice inspiplan CRONLEY, B.R. Region 2. Atlanta, Diffice of the Director, HERDY, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch B1/01/19 7pp 07996 009.
- 8103261174 Responds to IE Bulletin BO-25. "Operating Problems W/Target Rock Safety Relief Valves at BKRs." Review indicates no instances where two-stage safety relief valve failed to perform Procedures for operation & maint have been reviewed WIDNER. W.A. Operate Power Co. 81703/17 2pp. 00040,264
- 8103270351 Ack receipt of 810302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/80-44.
  LEWIS.R.C. Region 2. Atlanta. Office of the Director. 81/03/19.
- --Bi03270062 Responds to NRC Bi0205 itr re violations noted in IE Imsp. Repts 50-321/80-44 & 50-366/80-44 Corrective actions: snubber insp procedure revised & personnel cautioned to recapilize potential effects of inoperable equipment KELLY-R J. Georgia Power Co. 81/03/02 2pp. 08045.170
- --8103270071 Forwards IC Insp Repts 30-321/80-44 & 80-366/80-44 on BOILLB-21 & notice of violation LEMIG.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch BI/02/05 2pp. 08045-172
- --G103270082 Notice of violation from insp on H01118-21 \*\* Region 2, Atlanta, Office of the Director 81/02/05. 1p
- --8103270096 IE Insp Repts 50-321/80-44 & 30-366/80-44 on 801118-21. Noncompliance noted timeliness of maint activities not adequately controlled by mgt controls GHITENER, H. Region 2. Atlanta. Office of the Director. QUICN. Dr. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/01/30 5pp 08045:175.
- R Periodic operating reports & related correspondence
- 8103040193 Forwards "Gemtannual Rept.Plant Radioactive Effluent Releases.Jul-Dec (980." MANRY.M Osorgia Power Co. 81/02/26 Ip. 07808:257
- --BI03040199 "Bemiannual Rept.Plant Radioactive Effluent Releases, Jul-Dec 1989 " 4 Georgia Power Co. 81/02/26. 43pp. 07808:259.
- B103290505 Forwards "Annual Operating Repts for 1980."

  MANRY-M. Georgia Power Co. 81/02/29. ip. 07848:096.
- --8103090508 "Annual Operating Repts for 1980." \* Georgia Power Co. 81/02/28. 51pp. 07848:097.
- 8103310447 Forwards monthly operating rept for Feb 1981. MANRY.M Georgia Power Co. 81/03/10 Ip. 08081:199.
- --BI03310453 Monthly operating rept for Feb 1981. KAMISHLIAN, J. M. Georgia Power Co. 81/03/10 Spp. 08081: 200.

- S Reportable occurrences, LERs & related correspondence
- 8103020576 Forwards LER Bi-006/03L-0.
  MANRY.M Georgia Power Ca 81/02/19 10 07782.060
- --8103029582 LER 81-006/03L-0 on 810123, standby gas treatment sys f train, 2146-D001A, removed less halogenated hydrocarbon refrigerant gas than required by Tech Specs during testing by vendor Caused by defective tharcoal in filter bed CD901N.C.L. Georgia Power Co. 81/02/19 20p. 07782:061.
- B103020569 Forwards LER 81-004/03L-0
  MANRY-M Georgia Power Co B1/02/20 1; 07782:163
- --B103020575 LER B1-004/03L-0. on B10122, notable loads found exceeding vendor allowables for reactor core isolation cooling steam turbine during reanalysis of piping & hangers per IE Bulletin 79-14 Caused by AE error in sys design C090IN.C L. Georgia Power Co. B1/02/20 2pp. 07782 164.
- 8103030759 Forwards LER 81-011/03L-0. MANRY, M. Openaia Power Co. 81/02/24 to. 07791:317
- --Bi03030765 LER 81-011/03L-0 on 810204, nonrated window discovered in rated fire wall Caused by design, mfg & constrinstablation error. Direct conversion reactor study 81-48 submitted & fire watch established CO001N.C L Georgia Power Co. 81/02/24 2pp 07791:318
- B103090390 Special rept on B10221. following reactor scram on low reactor water level due to loss of condensate broster pump. HPC1 was manually initiated & injected into reactor vessel HPC1 was secured after water level was restored to normal. MANRY. M. Georgia Power Co. B1/02/26 2pp. 07832: 118
- 8103130458 Forwards LER 81-009/03L-0. MARRY, N. Georgia Power Co. 81/03/05 1s. 07913:109
- --8103130460 LER 81-009/03L-0. on 8102(2. reactor coolant not analyzed per 24-h as required by Tech Spec Caused by reactor vessal hydro during time period when next conductivity measurement was to be taken.
  RDOERS-W H Georgia Power Co. 81/03/05. 2pp 07913.110.
- B103130467 Forwards LER 81-010703L-0 MANRY-M Georgia Power Co. 81703705 1g. 07913:112.
- --Bi03130469 LER Bi-010/03..-0. on Bi0222, reactor core isolation coals auto flow controller did not control turbine properly while in auto position during quictatant test. Caused by loose ribbon connector on flow control M-4 station COOSIN.C L. Georgie Power Co. Bi/03/05. 2pp. 07913:113.
- 8103160737 Forwards LER 81-012/02L-0. MANRY.M Georgia Power Co 81/03/12 ip. 07914:130.
- --Bi03i60740 LER Bi-012/02L-0. on Bi0224, during surveillance testing, standby liquid control pump B failed to start, losing squibb valve B continuity. Caused by failure of control fuse in circuit breaker. Fuse replaced.

  NIX.R.T. Georgie Power Co. Bi/03/12 2pp. 07914:131.
- 8103230707 Forwards updated LER 80-139/01X-1. MARRY, M Georgia Power Co. 81/03/17 1p. 07973:398.
- --8103230716 Updated LER 80-139/01x-1: on 801008.AE advised that drywequipment drain sump discharge to redwaste piping not seismic beyond imboard isolation valve. Caused by installation error on enchor 2011-RAD-A90 Restraint added. CO001N.C.L. Georgie Power Co. 81/03/17. 2pp. 07973:359.
- 8103230712 Forwards updated LER 80-149/03X-1. MANRY.M. Georgia Power Co. 81/03/17. 1p. 07974:00b.
- --B103230721 Updated LER 80-149/03X-1: on B01031,RHR pump suction isolation valve 2E11-F4B was found leaking. Caused by scratches on valve seat, probably due to valve closing on debris. Valve seat polished.
  C0901N.C.L. Georgia Power Co. B1/03/17. 2pp. 07974:007.
- B103230746 Forwards LER B1-003/03L-0. MANRY, M. Georgia Power Co. B1/03/17. 1p. 07977:237.

- 8103230812 Forwards updated LER 80-151/03x-1.
  MANRYLM Georgia Power Co. 81/03/17. to. 07974 193
- --Bi03230820 Updated LER 80-151/03X-1 on 801120.primary feedwater isolation valve 2821-F010B leakage rate found to exceed bypass path penetration Tech Spec Caused by scratches on seat of valve due to valve closing on debris. CG031N.C.L. Georgia Power Co. B1/03/17 2pp 07974 196
- --Bi03230833 LER 81-015/03L-D on 810304, intermediate range monitor H (2051-K601H) would not come on scale for overlap check between intermediate & source range monitors during ecram recovery procedure HkP-2-1010. Caused by pushed back pins. NIX-R. T Georgia Power Co B1/03/17 2pp 07974.199
- 8103300363 PND-11-81-24: on 810323 during investigation of drywell low pressure alarms seven of eight panel valves were found closed. Cause not stated Valve lineups performed w/no discrepancies identified RELLOGO, P. J., LEHIS, R. C., Region 2, Atlanta, Office of the Director 81/03/24. Ip 08093:154

## DOCKET BO-367 BAILLY GENERATING STATION

- A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants.applicants for OLs & holders of CPs re control of heavy loads Requests revises per guidelines in NUREQ-0612 Forwards NRC position re interim actions & request for add | Info. EISENWINT.D Q. Division of Licensina 80/12/22. 30ao.
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment items addressed involve cold shutdown replacement parts & NUREO-0737.

  EISENHUT.D.O. Division of Licensing 81/01/19. Spp
- BiO3120014 Ltr to all licensees of operating plants.CP holders & GL applicants.except Indian Point 2 & 3, Zion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC B01222 request for add info re control of heavy loads.

  EISENHUT.O.O. Division of Licensing. 81/02/03. 6pp.
- B103050931 Notification of B10311 & 12 meeting w/Mark II owners group & QE in Bethesda.MD to discuss Mark II generic long-term program.
  ANDERBON.C.J Generic Issues Branch. 81/02/12. 12pp.
- B103160622 Forwards water well record for observation well 23B. Installed B10206.Well constructed entirely of stainless steel components for water-quality sampling.

  LAPHAM.W.W. Interior.Dept. of. Geological Survey. B1/02/12 3pp. 07917-131.
- BiOG110520 Forwards response to util 80120B ltr re site groundwater analysis. D'Appolonie Consulting Engineers rept criticizing USOS contains only repetition of shown & ack methodology limitations. Internal DOI memos encl. FREDERICK. D. O. Interior, Dapt. of, Geological Survey. B1/02/18, 36pp. 07872:232.
- 8103140669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A.1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be mat. EISENHUT.D.9. Division of Licensing. 81/02/18 12pp.
- 8103100526 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216. KEPPLER.J. O. Region 3. Chicago. Office of the Director. 81/02/20. 2pp. 07865: 236.
- 8103230024 Ltr to all power reactor licensees & license applicants re NJREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller. EISENHUT. D. Q. Division of Licensing. 81/02/20. Bpp.

- --Bi03170266 Model Teth Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 surveillance requirements for ABMS Code Class 1.2 & 3 components & RCS operational leakage limiting conditions operation & surveillance requirements & General Electric Co. Bi/02/26 4pp
- BIO3170695 Ltr to holders of CPs & applicants for DLs (BWRs) review of ASME Class 1.2 & 3 pressure boundary piping, eafeends & fitting mati per guidelines of encl Revision I to MWRCO-0313 Hodel Tech Specs only encl EISENHUT, D O Division of Licensing B1/02/26 3pp
- 8103230813 Generic Ltr Bi-O6 to all CP holders & UL applican IOCFR50 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status, format & content oncl CISENHUT, D. G Division of Licensing 81/02/26 10pp.
- 8103130601 Notification of 810313 meeting w/Mark II owners of Bethesda.MD to discuss Mark II safety relief valve loads & pool temp limits. SU,T.M. Generic Issues Branch 81/03/03 2op
- B10309042B Advises that eddl detailed pile placement require be incorporated into 780714 pile installation procedures prior to installation of safety-related piles SHORB.E M. Northern Indiana Public Bervice Co. B1/03/04.
- BiO3170191 Forwards safety evaluation re-pile foundation des installation for facility Licensee may drive safety-relate piles for main power block per 780308 proposal EISENHUT.D D Division of Licensing Bi/03/05 2pp 07
- --Bi03170196 Bafety evaluation repile foundation design & 1 for facility License may drive safety-related piles for main power block per 78030B proposal for foundation mat CLI-79-11 encl # Division of Licensing 81/03/31 48pp 07934 251.
- --8011060713 Forwards Hydrologic & Geotechnical Engineering description of method for pipe installation of facility Specific details of procedure slightly different from AC approved plan
  KNIOHT.J P Assistant Director for Components & Structu Engineering 80/10/17 4pp 03711 018
- B103100026 Forwards safety evaluation re facility pile found encl. QOLOBERO, 8 C Hearing Branch 2. 81/03/96 1p 07862-11
- Bio33i0804 Ltr to all licensess of operating plants applican & holders of CPs forwarding SECY-BI-119 rs info necessary establish environ qualification of safety-related electric equipment.

  EIBENRUT, D. Q. Division of Licensing 81/03/10 6pp
- B103200444 Forwards Buppl 2 to NUREO-0487, "Mark II Contains Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper. Buggests Mar 1981 meeting W/Mark II owners to discuss review program W/o enci KNIEL
- B103310914 Bummary of B10313 meeting u/Mark II owners group suppression pool temp limit & T-quencher load spec. U/o encilist of attendees & meeting handout SU.T.M. Generic Issues Branch 81/03/24. 3pp
- F Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licenses of operating plants & holder forwarding NUREO-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl EIBENHUT. D.O. Division of Licensing 81/03/05 ápp.
- Q. Adjudicatory correspondence
- S103:30490 Urges NRC to immediately establish firm nat1 poli prohibiting siting of nuclear power plants near densely populated areas Opposes ASLAB ruling that location will no be considered in facility CP extention request. BUSHEMI-J. Indiena-State of. 80/11/25 lp. 07913.091.



- 8103050685 Limited reply per ASLB 810212 memorandum & order ASLB should order production of documents because contract provisions between util & 08 are relevant & essential to issues.

  Certificate of Svc encl VOLLENR J Porter Gounty Chapter Intervenors VOLLENR J VallenR J & Micher J M , 81/02/24 7pp 07829 267
- 8103130630 Response to 801125 ltr re-scope of ASLB hearing on util request for CP extension ASLB did not hold that site suitability could never be re-examined once approved but that other review procedures were available 81CMHIT-L. Office of the General Counsel 81/02/25 2pp 07913-214
- Bio3090631 Response to ASUB 810212 order adopting Porter County Chapter Intervebars Contention 13 & supporting contention for reasons stated in intervenors' response Unsigned Certificate of Svc encl BAPKINA Illinois, State of Bi/02/26 3mp 07829 170
- B103050707 Response supporting admissibility of Contention 13 per ASLB 810212 order Filing of contention within two months of receipt of info should not be deemed late Certificate of Bvc encl VOLLEN.R J Parter County Chepter Intervenors VOLLEN.R J Vollen.R J & Whicher, J H. 81/02/26 100p 07821 333
- 8103190532 Request for admission of Contention 14. Bubmittal was within reasonable time & will not prejudice any party Contention identifies matters to be litigated & is within scope of proceeding Certificate of Svc encl VOLLEN.R. J. Porter County Chapter Intervenors VOLLEN.R. J. Vollen.R. J. & Whicher, J. N. 81/03/06 6pp. 07963:229.
- 810327064B Response in opposition to Porter County Chapter Intervenors 810306 motion for admission of new Contention 14 Disparate safety concerns unrelated to grounds for CP extension request outside scope of proceeding Certificate of Bvc enc1 OOLDBER9.8 C. Hearing Branch 2. 81/03/26 7pp 08043 248.
- 8103310222 Advises that date of Div of Licensing 810116 itr to AGL8 was ristyped as 810126 on Page 2 of NRC response to motion to admit proposed Contention 14.

  QULDBERGS C. Hearing Branch 2 81/03/27 ip 08079 088
- 8103310237 Responds to 810313 inquiry into status of NRC review of CP application NRC hopes to complete evaluation of application, including EIA Issuence by June 1781. Consultant retained to assist in EIA preparation.

  O

# H General correspondence

- 8103120352 Requests delay in granting CP to licenses until public hearing is held to address evacuation of population during emergency.

  OMERSY-9. Affiliation Unknown 81/02/23 lp
- B103110342 Opposes facility licensing. BCHRADER.D. Affiliation Unknown. B1/02/27. ip.
- 8103110356 Opposes facility licensing. GREEN-L Affiliation Unknown 81/02/27, ip.
- B103110363 Opposes facility licensing. DEEB-R.L. Affiliation Unknown. B1/02/28. ip. 07886.128.
- 8103120414 Expresses concern re Bailly siting near Gary-IN Opposes const close to heavily populated Chicago.IL area. HINTZEN.H Affiliation Unknown. B1/03/10. ip. 07905-001.
- 0 Inspection reports: IE Bulletins & correspondence
- 8103020069 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals White on Duty." No written response required. KEPPLER. J. G. Region 3. Chicago. Office of the Director. 81/02/09. 2pp. 07787:296
- 810303031: Forwards Buppi 3 to IE Bulletin BO-17, "Failure of Control Rods to Insert During Scram at BMR." No written response required.

  KEPPLER.J. 0 Region 3, Chicago, Office of the Director 81/02/13.
  2pp. 07790.224
- 8103250692 Forwards IE Insp Rept 50-367/81-01 on 810127-28.No noncompliance noted FISHER.No. Region 3. Chicago: Fuel Facility & Materials Bafety Brench. 81/02/20. 2pp. 07998:254.

- --8103230658 IE Insp Rept 30-367/81-01 on 810127-28.No noncompliant noted Major areas inspected administrative controls, ecological monitoring program & well monitoring results.

  CESTMANN.M. J. PAPERIELLO.C. J. Region 3. Chicago, Defice of th Director 81/02/18 App. 07998.286
- B103160479 Forwards IE Circular B1-03, "Inoperable Beismic Monitori Instrumentation." No response required, XEPPLER, J. G. Region 3, Chicago, Office of the Director. B1/03/0 20p. 07915.290.
- BiO3160874 Forwards revised IE Bulletin Bi-Oi. "Burveillance of Mechanical Shubbers," w/corrected Pages 5 & 6.Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  XEPPLER. J 0 Region 3. Chicago, Office of the Director, 81/03/0 2no 07914.229
- 8103200396 Forwards IE Info Notice 81-06, "Failure of ITE Hodel K-6 Circuit Breaker." No response required. KEPPLER, J O Region 3, Chicago, Office of the Director 81/03/1 2pp 07972.141
- 8103200550 Forwards IE Info Natice 81-05, "Degraded DC 89s at Palisades." No action required. KEPPLER.J. Q. Region 3, Chicago, Office of the Director 81/03/1 20p. 07955 148.
- B103200328 Forwards IE info Notice B1-07, "Potential Problem W/Water-Soluble Purge Dam Matis Used During Inert Gas Helding " No response required KEPPLER, J. O. Region 3, Chicago, Office of the Director B1/03/1. 2op. 07966:270.
- R Periodic operating reports & related correspondence
- Bi03030B23 Forwards 1980 quarterly rept on scological monitoring program Rept contains analyses & interpretation of data for Oct-Dec 1980 W/o encl. PURCELL, J.F. Northern Indiana Public Service Co. 81/02/19. 1p 07795:187.
- 8103030685 Forwards well charts for 810211-18.Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water mater readings & UBOB wells for 810218. Cable froze on well 518. Clock stopped on well 528.BBN-R.J. Northern Indiana Public Service Co. 81/02/25. 32pp. 07794: 071.
- B10310047B Forwards well charts for B10218-25, & Bailly Wells w/o recorders, pand levels-pneumatic pressure transducers, water meter readings & UBOS wells for B10225.
  BOHN.R.J. Northern Indiana Public Bervice Co. 81/03/06. 33pp. 07853:071.
- 8103240391 Forwards well charts for 810225-0304. Bailly wells w/o recorders, pand levels, pneumatic pressure transducers, water reter readings & U898 wells for 810304. Clock etopped on Hell 14 Cable hung up on Hell 518.

  BDHN.R.J. Northern Indiana Public Service Co. 81/03/13. 35pp. 07990:218
- 8103250247 Forwards well charts for 810304-11.8ailly wells u/o recorders, pond levels, pneumatic pressure transducers, water meter readings, USOS wells & graphs for 810311.

  BAHIR J. Northern Indiana Public Bervice Co. 81/03/20. 32pp. 07998:084
- U. Congressional/Executive Correspondence
- 8103270110 Responds to request for rept on possible addl improvement o NRC licensing process. Legislation allowing interimoparations in advance of hearing completion would reduce deleg in licensing process.

  #ENDRIE: J M Commissioners. 81/03/12. Spp.
- --BIO3270947 Submits recommendations re scheduling personnel resourhearing mpt for OL proceedings Penel must obtain esemption from hiring freese for two recently appointed chairmen COTTER B.P. Atomic Bafety and Licensing Board Penel. BI/02/25 33pp. 08043:359

- DOCKET 50-368 ARMANBAB NUCLEAR OVE. UNIT 2

  F. Security, medical. emergency & fire protection plans
- 8103180264 Ltr to all comer reactor licensees w/plants licensed prior to 770|01 Forwards NRC position & request for add) info re safe shutdown capability for compliance u/801119 fire protection rule.
  EIBERNHYT, D. O. Division of Licensing 81/02/20 13pp
- Bio3230214 Natifies that licensee plans to participate in emergency preparedness exercise w/state & local authorities on Bio324-25 Natrative summary of emergency exercise ecenaria encl Requests info relected of NRC invalvement in exercise.

  TRIMBLE.D C Artenses Power & Light Cd Bi/02/23 4pp 07975 014
- 8103100113 Requests that encl emergency planning info be made publicly available M/o encl SOUDER, J.L. Division of Rules and Records 81/02/27. 1p 07853:179
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. W/o encl EISENHUT. D O Division of Licensing 81/03/09 App
- Bio3ii0126 Releases public version of implementing procedures for emergency plan
  FELTON.J M. Division of Rules and Records. Bi/03/06 ip
  07806-001
- --B103110138 Forwards public version of implementing procedures for emergency plan. Includes Series 1202, "Emergency Operating," Series 1703, "Emergency Plan Procedures" & Series 1704, "Magnitude of Release Procedures "
  TRIMBLE.D.C. Arkenses Power & Light Co. 81/02/27 1p 07806-001
- --Bi0311014B Public version of implementing procedures for emergency plan. Includes Series 1202, "Emergency Operating," Series 1903, "Emergency Plan Procedures" & Series 1904, "Magnitude of Release Procedures." & B1/02/27, 750pp 07806-001
- 8103240360 Requests exemption from fire protection mode required by 10CFR50.App R.Sections III 0 & L. Util compliance w/fire protection safety evaluation provides adequate protection. Reactor coolant pump designs were sent 800416 & 0312 TRIMBLE.D.C. Arkanses Power & Light Co. 81/03/19 4pp. 07990.145
- B103260945 Forwards emergency planning info for placement in LPDR. H/G 8103110138.

  SOUDER.J.L. Division of Rules and Records. B1/03/19 1p 08040.283.
- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NVREO-0612. Forwards NRC position re-interim actions & request for add
- 8103190387 Ltr to all literases of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment (tems addressed involve cold shutdown replacement parts & NUREO-0737. EIBENHUT.D.Q. Division of Licensing, 81701/19, 6pp.
- 8103120014 Ltr to all licensess of operating plants CP holders & DL applicants, except Indian Point 2 & 3, Zion 1 & 2 & THI-1, forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads.

  EISENHUT, D. O. Division of Licensing. 81702/03. App.
- 8103300160 Ltr to all operating PMR licensess requesting info on auxiliary feedwater sys seismic design. Forwards request for add info, list of actions requested of licensess w/o seismically qualified sys & results of NRC walkdowns. EISENHUT. D. O. Division of Licensing. 81702/10. 13pp.
- S103030112 Forwards revised NRC Region 4 organization chart, effective B10227.

- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Itan III A I 2 rs upgrade of emergency support facilities Requests confirmation within 43 days trat implementation dates will be mot EISENHUT.D Q Division of Licensing 81/02/18. 12po
- 8103060428 Notifies of payment due for Unit 1 application rede of operable." Unit 2 800813 application requires Class II fee only Belance due will be applied to sum owed NRC HILLER.N.D. License Fee Management Branch 81/02/20 2pp 07835 276
- B103180390 Ack receipt of util 800813 & 1128 applications for T Specs changes Discusses differences in fee classes for Units 1 & 2 Addi fee required to complete total fee due for 801128 application.

  MILLER. H 0 License Fee Management Branch 81/02/20 2pp.
- B103250024 Ltr to all power reactor licensees & license applica IMREO-0619 criteria.Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee way submit analysis to justify use of existing low flow controller EISENHUT, D O Division of Licensing. 81/02/20 8pp
- B103110436 Forwards "Partial Review Equipment Evaluation Rept b Nuclear Reactor Regulation for AR Power & Light Co. AR Nuclear One. Unit 2 " Written response required. NOVAK.T H Assistant Director for Operating Reactors.
- --8103110443 "Partial Review Equipment Evaluation Rept by Ofc a Reactor Regulation for AR Power & Light Co.AR One,Unit 2 " # Office of Nuclear Reactor Regulation, Director 81/02/2 25ps 07884 004
- B103230030 Ltr to all licensees of operating nuclear power plan applicants for DLs (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT, D G Division of Licensing B1/02/25. Spp
- B103230813 Opheric Ltr B1-06 to all CP holders & OL applicants 10CFR90.71(e), "Periodic Updating of FBARs," effective 800722 Info re FBAR legal status, format & content encl. EISENHUI.D 9 Division of Licensing. 81/02/26 10pp
- B103030824 Forwards response to Item II.K.3.17.NURE9-0737 re EC outages. TRIMBLE.D.C. Arkenses Power & Light Co. 81/02/27 9pp 07
- 8103090535 Commits to provide necessary info for extension of 8 deadline for response to NUREO-0737 items Info for Items 1 A. 1.3. II. E. 4.2. II. F. 1. & III. D. 3. 4 uill be provided by 810331. Item II. D. 1. info uill not be provided before 810701 TRIMBLE.D. C. Arkansas Power & Light Co. 81/02/27. 2pp. 07
- 8103090379 Reiterates util 800905 request for NRC concurrence of permanent operation of core performance calculators/control element assembly calculators for facility computer datalink. TRIMBLE.D.G. Arkansas Power & Light Co. 81/02/28. 4pp. 07
- Bi03:20472 Forwards Amend 20 to License NPF-6 & notice of issua evailability. CLARK,R A. Operating Reactors Branch 3 Bi/03/03. 3pp. 07
- --Bi03120474 Amend 20 to License NPF-6, adding two license condichanging Tech Specs to incorporate addit requirements perreviews & mods to satisfy Category A-TMI-2 Lessons Learned recommendations. CLARKIR A. Operating Reactors Branch 3. B1/03/03. 17pp. 07905:161.
- --8103120477 Notice of issuance & availability of Amend 20 to L HPF-6. CLARK, R. A. Operating Reactors Branch 3. 81/03/03. 2pp. 07908:178
- B103200452 Forwards Amend 19 to License HPF-6, safety evaluation notice of issuance & availability.
  CLARK R. A. Operating Reactors Branch 3. 81/03/03. 2pp. 07
- --8103200435 Amend 19 to License NPF-6, providing clarification "operable" re single failure criterion for safety sys. CLANUR A. Departing Reactors Brack 3. BL/03/03. 9ee

- --B103200476 Notice of insuance & availability of Amend 19 to License RPF-6 CLARK.R A Operating Reactors Branch 3 B1/03/03 2pp 07967.004
- BiO3180246 Forwards request for add1 info re "Qualification of Reactor Physic Methods for Application to PLR of Mid51e South Utils Sys " Requests schedule of response & identification of application of rept to units (LARK.R.A. Operating Reactors Brench 3 81/03/04 9pp 07944 042
- BI03090439 Forwards remaining sections of 'Cycle 2 Reload Analysis Rept.' Containing necessary transfert analyses & marked-up Tech Specs Affidavit encl.
  CAVANAVEH. H. Arkansas Power & Light Co. 81/03/05 200 07892 196
- --9103090440 "Cycle 2 Reload Analysis Rept." remaining sections Harked-up Tech Specs encl • Arkhaes Power & Light Co 81/03/05 179pp 07892-198
- Bio3110445 Responds to NRC 810225 request for review of deficiencies listed in NRC environ qualification of safety-related electrical equipment preliminary review Deficiencies listed are addressed in 801031 response to IE Bulletin 79-018 TRIMBLE D.C. Arkansas Power & Light Co. 81/03/06. 3op 07873 356
- 8103200093 Informs that staff functions of Region 4 reassigned, effective 810227 GL Madsen.Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondance re reactor contact & operation activities.

  SEYRRIT-K V Region 4- Dallas, Office of the Director 81/03/09 in 07989-048
- 1103180837 Forwards Amends 93 % 21 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 REID.R.W Operating Reactors Branch 4 81/03/10 3pp 07993 197
- -8103180883 Amends 33 & 21 to Licenses DPR-51 & MPF-6 respectively, modifying Yech Specs dealing u/administrative controls for personnel entry into high radiation areas REID.R.H. Operating Reactors Branch 3 CLARK.R.A. Operating Reactors Branch 3 81/03/10 10pp 07953 200
- -9103180899 Safety evaluation supporting Amends 53 & 21 to Licenses DPR-51 & NPF-6, respectively
   Office of Nuclear Reactor Regulation, Director 81/03/10 2pp. 07953 210
- -8103183868 Notice of issuance & availability of Amends 53 & 21 to Licenses DPR-51 & NPF-6, respectively CLARA,R A Operating Reactors Branch 3 81/03/10. 2pp 07953-215
- 103310604 Ltr to all licensees of operating plants, applicants for OLs trolders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EIBENHUT, D. G. Division of Licensing. 81/03/10. App.
- 103180513 Responds to NUREO-0737. Item III D 3.4, re control room habitability. Marked-up plot plan & one oversize marked-up frauling anci. Aperture card is available in PDR.
  IRIMBLE D C Artansas Power & Light Co 81/03/13 3pp 07965.334
- 1103240127 Responds to NRC 801124 ltr re short-term recommendations for facility emergency feedwater sys. Response to new questions & long-term recommendations will be provided by 810501 & 0701, respectively.

  TRIMBLE-D. C. Arkansas Power & Light Co. 81/03/16, 17pp. 07990.273
- 3100240363 Requests delay until next refueling outage for required installation of one addl main feedwater isolation valve in each main feedwater line. Existing valves are reliable. NRC should review need in light of costs.

  TRIMBLE.D. C. Artansas Power & Light Co BI/03/17. 2pp. 07990:149
- 8103310377 Forwards request for add1 info on util 810220 submittal re-Cycle 2 reload. CLARM.R.A. Operating Reactors Branch 3 81/03/23. 4pp. 08059:318
- G Inspection reports. IE Bulletins & correspondence
- 9103050602 Forwards (E. Ineg Repts 50-313/80-25 t 50-368/80-25 on 901215-18 No noncompliance noted. MADBEN, 9.L. Region 4. Dallas, Reactor Operations Nuclear Support Franch 81/01/19 2pp. 07827:107.

- --B103030636 IE Insp Repts 50-313/80-25 & 50-369/80-25 on 801215-18 No noncompliance noted Major areas inspected 8A program, procedures & control rad worth measurement. ANESHANSLEY, M., CONSTABLE, O. L., DEAN, B. Region 4, Dallas, Office of the Director B1/01/16 App 07829, 109
- B103050017 Ack receipt of util 810107 ltr re violations noted in IE Insp Repts 50-313780-19 & 50-358780-19. Util is in compliance w/industrial security plan Records will be changed to reflect agreement KELLY. J A Region 4. Dallas. Office of the Director 81/01/29. ip 07827.030
- --B103050030 Forwards response to NRC 601219 ltr re violations noted in IE Insp. Repts 50-313/80-19 & 50-369/80-19 Response withheld (ref 10CFR2 790)
  TRIMBLE D C Arkansas Pawer & Light Co 81/01/07 Ip 07937 031
- 8103050062 Act receipt of Bi0113 itr expressing concern re short turn around time for response to IE ineps Policy changed to require response within 25 days of rept receipt.
  KELLYJ A Region 4. Dallas. Diffice of the Director Bi/01/29. ip 07827-035
- --Bi03050079 Expresses concern re short turn around time for response to IE imag Repts 30-313/80-19 & 50-369/80-19 Advises that imag repts require responses within 20 days from date of receipt TRIMBLE.D.C. Arkansas Power & Light Co. 81/01/13 2pp. 07827 074.
- B103231014 Forwards IE Insp Repts 50-313/81-01 & 50-368/81-01 on 801222-810121 No noncompliance noted MADBEN-9 L Region 4. Dellas Reactor Operations Nuclear Support Branch 81/01/30 2p 07978:007
- --Bi03231026 IE imsp Repts 50-313/Bi-01 & 50-368/Bi-01 on B01222-Bi0121 No noncompliance noted Major areas inspected followup on previously identified items IE Bulletin 79-030 & TMI action plan requirements
  JOHLSON, W D. CALLAN, L J., HUNNICUTY, D.M. Region 4, Dallas, Office of the Director. Bi/01/29. 9pp. 079/B.009
- 8103200341 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required. SEYRRIT.K V Region 4. Dallas, Office of the Director 81/02/09 pp. 07966:294
- 8103041029 Ack receipt of 801209 itr re-violations noted in IE Insp. Repts 30-313/80-21 & 30-368/80-21. Corrective actions will be reviewed during future insp. MADSEN. O. L. Region 4. Dallass Reactor Operations Nuclear Support Branch. 81/02/11 1p. 07820:072.
- --Bi03041034 Responds to violations noted in IE Insp Repts 50-313/80-21 50-388/80-21 Corrective actions: power distribution & burn-up log changed to flag sampling operations requirements & access panel installed on 2VUC 118.
  TRIMBLE D C. Arkensas Power & Light Co. 80/12/09. 4PP. 07920-073.
- BiOGISOS94 Forwards IE Info Notice Bi-OS "Checklist for Licensees Making Notifications of Bignificant Events in Accordance W/iOCFR59, 72 " No response required.
  BEYFRITA V. Region 4: Delles: Office of the Director. Bi/O2/12. ip. 07922-050
- 8103160649 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required. BEYFRIT.K.V. Region 4, Dallas, Office of the Director. 81/02/27. 1p. 07917-116
- 8103170048 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation " No response required. SEYFRIT.K V. Region 4, Dalles, Office of the Director. 81/03/02. 1p. 07939:171.
- B10327030B Updates info re admittance of NRC personnel to facility. Forwards lists of regional inspectors U/o encl. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. 81/03/03 2pp 08044:178.
- 8103160986 Forwards revised IE Bulletin B1-01. "Surveillance of Mechanical Snubbars." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. SEYFRIT.K.V. Region 4. Dallas. Office of the Director. B1/03/04. jp. 07915:007

DOOKE (ED 11 pinto

```
B103230191 Forwards NAC comments on proposed IE bulletin. "Flow
Blockage of Cooling Water to Safety Gys Components by
Combicula Sp (Asiatic Cham) & Mytilus Sp (Mussel) " Draft IE
bulletin more appropriate as IE info notice
NOVAK.T.M. Assistant Director for Operating Reactors. B1/03/10
```

- 8103240644 Forwards comments & marked-up draft IE bulletin on flow blockage of cooling water sys by clars & silt Draft document is more appropriate for issuance as IE info natice MOVAN.T.M. Assistant Director for Operating Reactors. 81/03/10
- NGVAK.T.M Assistant Director for Operating Reactors 81/03/1 App 07585 001.
- Bio3240093 Updates NRC Bio303 ltm re admittance of NRC personnel to facility Personnel should be issued permanent nonemployee, no escort required picture badges. Forwards lists of personnel U/a encl
  SEYPRIT.K V Region 4. Dallas, Office of the Director Bi/03/i3
- BiO3230172 Forwards [E Info Notice Bi-07. "Potential Problem W/Mater-Soluble Purge Dam Hatls Used During Inert Gas Welding " No response required SEYFRIT.K V. Region 4. Dallas, Office of the Director. 81/03/16 ip 07977:208
- R. Periodic operating reports & related correspondence

200 07989.291

- 8103120316 Forwards "Rept on Radioactive Liquid Efficients App A.Jul-Dec 1980 " TRIMBLE D. C. Arkenses Power & Light Co. 81/03/03. 1p
- --8103120321 "Rept on Radioactive Liquid Effluents.App A. Jul-Dec 1980 "
  4 Artaneas Power & Light Co 81/03/03 8pp 07585 001.
- 8103180546 Forwards monthly operating rapt for Feb 1981 TRIMBLE.D.C. Artanias Power & Light Co. 81/03/13 ip. 07950:106
- --8103180549 Monthly operating rept for Feb 1981. PEMPERORAFTIR Arkansas Power & Light Co. 81/03/13. Spp. 07950:107
- 8103240239 Forwards corrected draft rept of "Effluent & Haste Disposal Semiannual Rept for CY79" per 810226 request. TRIMBLE.D. C. Arkanses Power & Light Co. 81/03/19. 18pp.
- S Reportable occurrences. LERs & related correspondence
- 8103100507 Forwards LER B1-006/03L-0, TRIMBLE-D.C. Artanses Power & Light Co. 81/03/03. 1p. 07862:304.
- --8103100519 LER 81-006/03L-0. on 810204, containment surp leval indicator 2LI-5645-1 was declared inogerable. Caused by defective converter. Converter replaced, PENDERORAFT, R. Arkansas Power & Light Co. 81/03/03. ip 07862:305.
- 8103100511 Forwards LER 81-005/03L-0. FRIMBLE-D.C. Artansas Power & Light Co. 80/03/03 Ip 07862 309.
- --BIO3100513 LER BI-005/03L-0: on 810204, core operating limit supervisory sys rendered inoperable. Caused by computer failure. Boftware reloaded & computer restarted. Backup computer will be installed
  PENDERORAFT.R. Arkenses Power & Light Co BI/03/03 ip 0282-2310
- 8103120599 Forwards LER 81-007/03L-0 TRIMBLE D.C. Arkanss Power & Light Co. 81/03/04. 1p. 07904:254.
- --Bi03120610 LER Bi-007/03L-0. on Bi0206, control room emergency chiller. 2VE-19, tripped Caused by low suction pressure due to leaking expansion valve. Valve repaired & sys refilled w/freon. • Arkansas Power & Light Co. Bi/03/04. ip 07904:253
- 8103120517 Forwards LER 81-010/03L-0. TRINBLE.D.C. Arkansas Power & Light Co. 81/03/05. ip 07904:261
- --B103120626 LER B1-010/03L-0: on B10212, during Mode 1 operation, control element assembly calculator (CEAC) 2 found inoperable. Cause unknown CEAC 2 returned to operable status by reinitializing sys. All feature indications returned to normal BHIVELY, C.N. Arkansas Power & Light Co. B1/03/03. 1p. 07904:262.

--8103170495 LER 81-009/03\_-0 on 810211.during Mode I operation performing refueling uster tank level indication channel: checks.Channel A indicated greater then 100% followed by Channel B 3-h later Caused by frozen transmitter lines S-IVELY.C N. Ariansas Power & Light Co. 81/03/10 ip 07937 249

079

- 8103;70490 Forwards LER 81-008/03L-0
  TRIMBLE, D.C. Arkaceas Power & Light Co. 81/03/12 to
- --B103170452 LER B1-00B/O3L-0 on B10217, during Made 3 operation reactor trip from 1002 power. I-131 dosp aquivalent of 1 59 uG labserved Caused by expected spike in coolant activity Liquid processed through pricery decineralizers FISER.9. R03ERS.P. SHIVELY.C. Arkansas Power & Light Co B1/03/12. 2pp 07937 251
- 8103240415 Forwards LER 81-013/03L-0
- --B103240425 LER BI-013/03L-0 on B10304. reactor coolant sys col temp indicator 2TI-4715A found reading 10 F high Caused by bad servo motor Servo cotor replaced & indicator talibr Scheduled replacement of sigma indicator PCRTON.K Arkansas Power & Light Co B1/03/19 ip 0798

TRIMBLE D C Arkansas Power & Light Co 81/03/19 15 079

B103310595 Forwards LER B1-012/03L-0
TRIMBLE.D C Arkansas Power & Light Co B1/03/26 Ip 080

--B103310597 LER B1-012/03L-0 on B10303.lnop two svc water head
engineered safety feature isolation valve 2CV-1406-2 would
not open from control room Caused by valve operator torquin

out due to valve stem binding SHIVELY. C.N. Arkansas Power & Light Co. B1/03/26 Ip

V Descator Examinations

08065: 519

- 8103100694 Submits status rept of significant milestones accomp to improve operator training program CAVANAUOH. W. Artansas Power & Light Co. 81/02/17 Spp. 07
- DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- B102190636 Requests EIS be issued prior to opening of licensing hearings. PRINGLE-W W. Affiliation Unknown. 80/01/20 1p. 07726.073
- 8103041030 Forwards request for add1 info re Q-list review for facility. Util must provide justification for amitting following (tens-rediation monitoring instrument storage calibr & maintifuel assemblies & containment control. MOQNAN. V B. Assistant Director for Materials & Qualification Engineering. 81/02/20 7pp
- F Security, medical, emergency & fire protection plans
- 8103030974 Notification of reschaduled 810212 meeting w/util in Bethasds.ND to discuss fire protection matters. Meeting originally set for 810210. BTRKEL-R A. Licensing Branch 1, 81/01/30. 3pp. 07799: 237
- B103100110 Advises of acceptance of safeguards contingency plan must be implemented within 30 days Encls to 790323 & 801217 ltrs withheld (ref 10CFR2 790). YOUNGBLOTO: 8 J. Licensing Branch 1. 81/02/24. 2pp. 07866.
- YDUNGBLODD, 8 J. Licensing Branch 1. 81/02/24. 2pp. 07866.6
  8103090517 Forwards Revision 10 to modified amended security pla
- 8103310338 Ltr to all licensess of operating plants & holders or forwarding NUREO-0676. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements. U/o encl. EISENHUT. D. O. Division of Licensing. 81/03/05. 6pp.
- 8103160270 Informs that provided items identified in encl emergy preparadness evaluation are resolved facility emergency plan will meet 100FR50 requirements. Completion schedule requested by 810313 TEDESCO.R.L. Assistant Director for Licensing. 81/03/06 1007921:314.

8103310138 Ack receipt of 810302 ltr transmitting change to security plan Change consistent w/10CFR50 54(p) Encl withhold (ref 10CFR 2.79)
YOUNDELDOD. 8 J Operating Reactors Branch 1. 81/03/25 2pp.
6862-2.099

## O Adjudicatory correspondence

- Bi03050611 Response in objection to AELB Bi0217 memorandum & order cenging admission of Contentions 9 & 6 Supplementary EIB on Class 9 accident is necessary predicate in proceeding Denial should be certified to Commission W/Certificate of Svc (CM: D B Carolina Environmental Study Group. Bi/03/02 Spp 07829 120
- B103099674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties.

  CHRISTERBURY: 8 Hearings Division. 81/03/04 2pp
- 8103170292 Informs that name & address has been placed on NRC Certificate of Svc as representative of Carolina Environ Study Oroup RETCHEN.E Q Hearing Branch 4 81/03/11 to 07923.218
- 8:032306:0 Forwards Carolina Environ Study Group application for subposes re reopened facility OL proceeding Related correspondence
  B.UH. S. Carolina Environmental Study Group BLUM. B. Blun & Sheely
  8:703711 | p. 07977 281.
- --Bi03230622 Carolina Environ Study Oroug application for subpoens re reopened McQuire Units 1 & 2 OL proceeding List of proposed witnesses & questions enci Related correspondence. BLUM.S Carolina Environmental Study Oroug DLUM.S Blum & Sheely BI/02/26 10pp. 97977.282
- --8103230628 "Nuclear Reactor Accidents.Value of Improved Containment '
  Related correspondence
  PEYEA, J., VON HIPPEL,F. Princeton Univ 80/01/20 1tpp
  07977-272
- B103270590 Request for license authorizing operation up to & including 35% rated power Fuel loading initial criticality & zero power physics testing to be completed by B10515 Certificate of 8vc encl MCGARRY. J M Duke Power Co MCGARRY, J M Debevoise & Liberman 81/03/24 6pp 08034 053
- 8103310122 Informs that NRC completed review of info in record Generally info is sufficiently detailed Encl affidavits, reactual const of air handler ducts should be included in tecord SCINTO, J. F. Hearings Division 81/03/27, 2pp 08077 121
- --Bi0331014B Joint affidavit re const details of air handling unit ducts Vendor confirmed existence of insulation barrier on drawings & installation in facility ducts IMC has no further concerns about pyrolysis of foam MODNAN.V S. Assistant Director for Materials & Qualifications Engineering PCLK.H E. Structural Engineering Branch. PARCIEMBKI.K J. Chemical Engineering Branch. BI/03/27 7pp. 08029 123

### H General correspondence

- 9103120330 Forwards, for review, 910213 ltr from JW Cox re facility licensing. Response requested MOULINGS. F. Senate 91/02/27 2pp. 07901:251
- 8103180607 Urges OL for Unit 1 be issued promptly Delay in licensing is costly to rete payers.
  MITCHEELL.R. Bouth Carolina, State of. 81/03/09 2pp 07753 088.
- 6103260568 Opposes facility licensing SIMPSON.C. Affiliation Unknown. 81/03/19. ip.

### I Finencial information

BIO3310549 Forwards Annual Financial Rept 1980, annual certified financial statements, 1981-83 financial forecast & util statement re available funds to satisfy liability Info quarantees retrospective premiums per 10CFR140.26 THIES.A C. Duke Power Co. 81/03/24 1p

- P. Operating license stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants.applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position relinterin actions & request for addl
- B103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shotdown, replacement parts & NUREC-0737 EISENHUT. D. 9 Division of Licensing 81/01/19. dop.
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3.2ion 1 & 2 & TMI-1. Forwarding inadvertently omitted pages from NRC 801222 request for add! info to control of heavy loads EISEPHUT.D. O. Division of Licensing 81/02/03 6pp.
- 8103300160 Ltr to all operating PWR licenses requesting into on auxiliary feedwater systemic design Forwards request for addition. Ilst of actions requested of licensees w/o satismically qualified systemics of NRC walkdowns EISECHUIU. D. O. Division of Licensing 81/02/10 13pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Iton III. A 1 2 re upgrade of eregency support facilities Requests confirmation within 45 days that implementation dates will be not. EIBENHUT, D. 2. Division of Licensing 81/02/18 12pp
- 8103230058 Forwards 810210 reno w/rough draft. "Analysis of Hydrogen Mitigation for Degraded Core Accident in Sequepah Nuclear Power Plant" & B10122 meno w/rept entitled "Evaluation of Igniter Concept for Use in Sequepah Nuclear Plant "
  TEDESCO.R.L. Assistant Director for Licensing. 81/02/19. 2pp.
- --BI022B0325 Recommends position re-upper planum ignitors of ice condensor plants per revieu of "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequoyah Nuclear Power Plant"

  MURLEY, T. E. Division of Reactor Bafety Research. Bi/02/10. 2pp 65092-076
- --BI02280404 informs that further analysis necessary relocation of igniters in ice condenser plants Possibility of detonation in upper planum should be considered. Recommends ignitors be removed.

  MCRLEY, T. E. Division of Reactor Safety Research. 81/02/09 2pt 65042-089
- --B103230073 Rough draft: "Analysis of Hydrogen Hitigation for Degrad Core Accidents in Bequoyah Nuclear Power Plant," prepared for Ofc of Nuclear Regulatory Research BERHANN. H. P. CUMNINGS. J. C. Bandia Laboratories B0/12/01. 130pp. 07978:103.
- --BIO3230079 Comments on upper planum igniters of ice condenser plant per review of "Evaluation of Olow Plug Igniter Concept for Use in Bequoyah Nuclear Plant " Evaluation encl HAMRAHAN.E.J. Office of Policy Evaluations. BI/01/22 2pp 07978-232
- --BIO3230084 "Evaluation of Olow Plug Igniter Concept for Use in Bequough Nuclear Power Plant" STREHLOW, R. A. Affiliation Unknown. 81/01/09. 9pp. 07978: 234.
- 8103041030 Forwards request for add1 info re 0-list review for facility. Util must provide justification for omitting following items rediction monitoring, instrument storage calibr & maint.fuel assemblies & containment control. NDCNAKI.V. 8. Assistant Director for Materiels & Qualifications Engineering. 81/02/20 7pp 07819:271.
- B103090304 Application for amend to license submitted as proposed revision to Tech 8jecs PARKER.W C. Duke Power Co. 81/02/23. 2pp 07830:300.

\_---

- ---8103090310 Tech Specs 3 4 7 2.3/4 5 1.3 5 1 1.4 5.1 1.3/4 5.3.3 5 5 3.4 5 3.1.4 5 3 2.3 8 1 2.3 11.2.3.4 51 2 5 & Tables 3 4-1. 3 7-6 & 3 3-13 re oxygen concentration in waste gas holdup systhydrogen monitor requirements et al. 90% Power Co. 81/02/23 11:p 07850 302
- B10309057B Forwards PMR const milestones & activities for McGuire 1 & 2. Catauba | & 2. C. Catauba | &
- 8103:10272 Forwards safety evaluation no environ qualification review for safety-related equipment fiesponse to items requiring action should be submitted by 810527 IEDESCO.R L. Assistant Director for Licensing 81/02/24 2pp 07884 218
- --Bi03110275 Safety evaluation supporting environ qualification review of safety-related electrical equipment
  -- Office of Nuclear Reactor Regulation. Director 81/02/24
  22ss 07884 220.
- 8103090049 Forwards request for additinfo relidentification of safetymelated structures, sys & components evolute operational GA program Response required by 610302 TEDESCO.R L. Assistant Director for Licensing. 81/02/25. 8pp 07832-169
- 8103030791 Advises that mods identified in util 801014 itr have been completed re-reset of equipment upon reset of engineered safety features actuation signal PARKER. W. O. Dute Power Co. 81/02/26 ip 07796 078
- Sio3039714 Forwards certified matl test repts for selected containment pressure boundary components, including containment vessel shell plate, equipment hatch barrel haif & brecing assembly & steam piping.

  PARKER, H. O. Duke Power Co. BI/02/27 54pp 65068, 144
- 8103030731 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Buppl 1 1" PARKER W. D. Dute Power Co. B1/02/27 1p. 07789 110
- --8103030734 "Reactor Containment Bldg Integrated Leak Rate Test Suppl 1."

   Duke Power Co. 81/02/27, 16pp. 07769.111.
- 8103050528 Forwards "Review of Piping Setsmic Analysis Methods," in response to NRC 810126 request for technical justification of response spectra.

  PARKER, M. C. Duke Power Co. 81/03/02 ip 07826-210
- --8103030503 "Review of Piping Seismic Analysis Methods"

  \* Dute Power Co. 01/03/02. 16pp 07826 211
- 8103110321 Advises that analyses of liquid & gaseous radwastes are performed by Teledyne Isotopes, per schedule requirements of Tech Space 3 9.8 & 3.10 9, satisfying Tech Spec 6.4 L. Detailed review of vendor analysis procedures unnecessery. PARKER. M.O. Dute Power Co. 81/03/03. 2pp.
- 8103130151 Forwards DF Ross 810302 memo transmitting BNL rept. "Some Very Preliminary Results of Short-Term Analysis (3-4k 8tudy) of Hydrogen Combustion During Degraded Core Accidents in Bequoyah Nuclear Power Plant in Presence of Olaw Plugs " TEDESCD.R.L. Assistant Director for Licensing 81/03/04. 1p. 07919-214
- --B103130160 Forwards for Board Notification.BNL rept. "Some Very Preliminary Results of Short-Term Analysis (3-Mk Study) of Hydrogen Combustion During Deparaded Core Accidents in Bequoyah Nuclear Fower Plant in Presence of Olow Plugs "ROSS-D.F. Division of Systems Integration. 81/03/02. 1p. 07912:216.
- --8103130169 Forwards "Bome Very Preliminary Results of Short-Term Analysis (3-Wk Study) of Hydrogen Combustion During Degraded Core Accidents in Bequoyah Nuclear Power Plant in Presence of Olow Plugs " BARI.R.A. Broothaven National Laboratory, 81/01/23, lp. 07912:217
- --Bi03i30177 "Bome Very Preliminary Results of Short-Term Analysis (3-Wk Btudy) of Hydrogen Combustion During Degraded Core Accidents in Sequeueh Nuclear Power Plant in Presence of Glow Plugs."

  PRATT-W.T. Brookheven National Laboratory. 81/01/15. 150pp. 07912:218

- B103|305|5 Confirms completion of structural reanalysis of 17 Category 5 resoury walls identified as requiring mode to meet specified design criteria PARKER.W O Dute Power Co B1/03/09 Ip 07911 276
- 0103130545 Responds to NUREG-0737. Item II F 2. 'Instrumentation for Detection of Inadequate Core Cooling " Conformance of reactor vessel level sys to Reg Ouide 1 97 will be addressed when overall compliance submitted on 810423 PARKER.N D Duke Power Co 81/03/09 4pp 07908 315
- 8103230479 Forwards updated responses to NRC 800323 ltr re TMI concerns Zero power physics testing is scheduled for completion by May 1981 PARKER-W O. Duke Power Co. 81/03/07 62pp 07976 239
- Bio3310804 Ltr to all licenses of operating plants, applicants for (N.s. 5, holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  FISPNUT. D. O. Division of Licensing BI/03/10 600
- B103240495 Notifies that description of conformance of subtooling monitor to Reg Guide 1 97 will include assessment of core exit thermocouples using Attachment 1 to Item II F 2 in NAREO-0737
  PARKER, M. O. Duke Power Co. 81/03/18 200 07982 261
- 8103300318 Forwards response to NRC 810229 ltm re identification of safety-related structures, sys % components PARKER, NO. Duke Power Co. 81/03/25 10pp 08055 138.
- B103300336 Confirms B10324 telcon w/NRC reliten II.F 2 of NUREG-0737. Existing analog mater on core exit thermocouple monitoring panel will be replaced w/Installed display capable of reading to at least 2.300 F by B10601 PARKER.W D. Dute Power Co. B1/03/25 2pp 08095 322
- 810330335 Forwards proposed revision to Tech Spec Tables 3 6-2. 3.7-4a.3.7-44 & 3.8-1 re containment isolation valves, safety-related hydraulic & mechanical snubbers & containment penetration conductor overcurrent protective devices. PARKER.H.O. Duke Power Co. 81/03/27 2pp 08055 184
- --8103300359 Proposed Tech Spec revision re Tables 3 6-2.3 7-4a. 3 7-4b & 3 8-1 concerning containment isolation valves, safety-related hydraulic & rechanical shubbers & containment penetration conductor overcurrent protective devices Dute Power Co 81/03/27. 90pp 08055:186.
- G. Inspection reports: IE Bulletins & correspondence
- 8103050217 Forwards Preoperational Safeguards Insp. Rept. 50-369/81-05 v. 810111-15 No. noncompliance noted. XENIA, N. B. Region 2. Atlanta, Safeguards Branch, 81/01/27, 2pp. 07829-219
- --8103050229 Preoperational Safeguards Insp Rept 50-369/81-05 on 810111-15 No noncompliance noted Major areas inspected security organization & implementing procedures. Details withheld (ref 10CFR2. 790) MODRE.D.E. HOWELL.J.C. MCOURE.D.R. Region 2, Atlanta. Office of the Director. 81/01/27 1p. 07825:221
- 8103120793 Forwards IE Insp Rept 50-369/80-39 on 801101-30 No noncompliance noted. LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 81/02/03. 2pp
- --Bi03120B02 iE Insp Rept 30-369/80-39 on 801101-30 No nancompliance noted. Major areas inspectas, preoperational & startup toest procedure review titnessing & test results review GRAHAM, M. J. DONAT. T. J. Region 2. Atlanta. Defice of the Director JULIAN. C. A. Region 2. Atlanta, Reactor Operations Nuclear Suppor Brench. Bi/02/05. Spp.
- 8103020203 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty." No written response required. Of REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/02/09 ip. 07785.306
- BIO31804B3 Forwards IE Insp Repts 30-369/81-04 & 50-370/81-01 on BIO120-23. No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 81/02/10, 2pp. 07945:220

- on IE Bulletin BO'23 21BSONS, T.D., YERRIMEATMER, R. Region 2. Atlanta, Office of the Director CON,ONT E. Region 2. Atlanta, Resitor Construction 5 Engineering Support Branch 81/02/10 Spp. 07941 222
- 6)03040167 Forwards IE Info Notice 81-03. Checilist for Liconsees Hairing Notifications of Significant Events in Accordance W/100FR50 72 " No Critten response required O'REILLY. J.P. Region 2. Atlanta. Office of the Director 81/02/12 to
- 8:03050161 Approves itcensee 801215 request for relief from ASME Code requirements for preservice inso at facility Technical issues described in 801215 ltr were previously addressed by URC VICTOR AND ADDRESSED BROOK 1 81/02/17. 200 07659 052
- 8103050290 Forwards IE Insc Rept 50-359/81-06 on 810127-29 No noncompliance noted FERNAL N B Region 2. Atlanta. Safeguards Branch 81/02/19 2pp 07823 394
- ---BID3050296 IE Insp Hept 50-369/81-06 on BIO127-29 No noncompliance note; Major areas inspected local Lawenforcement capability to respond to contingencies & screening program Details withheld (ref 100FR2 790) MCDRED E Region 2. Atlanta. Office of the Director MCDRED E Region 2. Atlanta. Safeguards Branch B1/02/19 ip 07033 354

- --8103050422 Forwards IE Inst Ropt 50-369/80-41 on 801204-07 No noncompliance noted STCHR. J.P. Region 2. Atlanta. Fuel Fecility & Materials Safety 3ranch 81/01/30 by 07824-329
- --8103050427 IE Insp Rept 50-369/80-41 on 801204-07 No noncompliance noted Najor areas inspected coordinated radiological energency seecise
  AVURENS-D L. Region 2. Atlanta. Office of the Director
  JEMAINS-S R. Region 2. Atlanta. Fuel Facility & Materials Gafety
  Branch. 81/01/30 7pp 07824-333
- 8103120806 Act receipt of 1E insp Rept 20-369/80-39. No proprietary Info PARKER N. O Date Power Co. 81/02/27 to 07905-326
- 8103130133 Ack receipt of IE Insp Rept 50-359/80-40 on D01201-31 No proprietary info Paper No. 0 Oute Power Co. 81/02/27 to 07907 290
- --0103130136 Forwards IE Insp Rept 50-369/80-40 on BD1201-31 No noncompliance noted LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/04 2pp 07907 291
- --8103130143 IE Insp Rept 50-369/80-40 on B01201-31 No noncompliance noted Major areas inspected startup procedure review. screppency planning-review of Tech Boecs & training program review.

  DDNAT, T J . GRAMAMM J Region 2. Atlanta. Office of the Director JULIALL C A Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/06 Spp 07907 273
- #103160725 Forwards 1E Info Notice B1-04, "Cracking in Main Bleam Lines." No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director B1/02/27 ip.
- 810316065; Forwards IE Circular 81-03. "Inoperable Belsmic Monitoring Instrumentation" No response required 0.9821LLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/02 ip 0.7917-121
- 8103160961 Ack receipt of 1E Inep Rept 50-369/81-02 on 810112-16 No proprietary info PARKER, N O Duke Power Co 81/03/04, Ip. 07915 132.
- --Bi03160965 Forwards IE Insp Rept 30-369/81-02 on 810112-16 No moncompliance noted BTCHR-J P Region 2. Atlanta. Fual Facility & Materials Safety Branch. 81/02/10 2pp 0/7915:133

- TROUP-O L Region 2. Atlanta, Diffice of the Director Gibbon A Region 2. Atlanta, Fuel Facility & Materials Safety Branch 81/02/07 7pp 07915 135
- BiO3176041 Forwards revised IE Bulletin B1-01. "Surveillance of Pechanical Snubbers." w/corrected Pages 5 % 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements O'REILLY. J P. Region 2. Atlanta. Office of the Director B1/03/04 ip 97939 167
- B103170079 Ack receipt of 810206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-369/80-32 LEWIS-R C Region 2. Atlanta. Office of the Director 81/03/04 lp 07939 194
- --Bl03(700B) Responds to NRC B10115 ltr re violations noted in 1E Insp. Rept 30-369/60-32 Corrective actions test coordinator counseled on injointance of documenting variance from procedures
  PAPER V O Duke Power Co 81/02/06. 2ap 07939 195.
- --8103170094 Forwards IE Insp Rept 50-369/80-32 on 801031-30 & notice violation LEMIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/01/15 2pg 07939,197
- --8103170086 Notice of violation from thep on 801001-30

   Region 2. Atjanta. Office of the Director. 81/01/14 (p.
- --G103170089 IE Insp Rept 50-369/80-32 on G01001-30 Noncompliance note failure to follou procedures & to evaluate test results DDNAT.T J. GRAHAM.M J. MEYERS.D C. Region 2. Atlanta. Office of the Director. G1/01/14 10pp 07939 200
- D103]80478 Ack receipt of IE Insp Rept 50-369/81-01 on B10105-07. No proprietary info PARKER, NO Dute Power Co 81/03/04 1p 07941 063
- --Bi03180468 Forwards IE Insp Repts 59-369/81-91 on Bi0105-07 No noncompliance noted STCHM.J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch Bi/02/10 2no 07941 064
- --B103180491 IE Insp. Rept 50-369/B1-01 on B10105-07 No nancompliance noted Major areas inspected GC & capability tests for measurement of radioactivity in liquid b gaseous effluents HCNTGCMERY, D.M. Region 2. Atlanta, Diffice of the Director OIDSON A.F. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 81/02/09 5pp 07941-066
- B103240602 Ack receipt of IE Insp Repts 50-369/81-04 & 50-370/81-01 No proprietery info PARKER, N.O. Duke Power Co. 81/03/04 | 1p. 07982 312
- 8103180194 Ack receipt of 810219 ltr informing ARC of steps taken to correct violations noted in IE Insp Repts 50-369/80-38 & 50-370/80-20 LEWIG.R.C Region 2. Atlanta. Office of the Director. 81/03/06 tp 07945 248
- --8103180207 Responds to ARC 810127 ltr re violations noted in IE Insp Repts 50-369/80-38 & 50-370/80-20. No proprietary info Corrective actions completed technical audit of EDB-Ban Francisco piping analysis & audit no design input tracking PARKER. N O Duke Power Co. 81/02/19 6pp 07945: 249.
- --Bi03180217 Forwards IE Insp Repts 59-369/80-38 & 50-370/80-20 on B01203-09 & 17-18 & notice of violation.
  MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Eupport Branch B1/01/29 2pp. 07945 259
- --BiO31BO222 Notice of violation from Insp on 801203-09 % 17-18 # Region 2. Atlanta. Office of the Director. 01/01/29. 1p. 07945 257
- --BIO3180239 IE Insp Repts 50-269/80-38 & 50-370/80-20 on 801203-05 & 17-18 Noncompliance noted failure to establish adequate measures for control of design interfaces & coordination among participating design organizations.
  HERDT.A.R. FOBTER.L. E. WDNO, H. Region 2. Atlanta, Office of the Director. Bi/01/29 13pp 07945 258.

#### DOCKETED LIFING

- BiD3200281 Forwards IE Info Notice Bi-On "Failure of ITE Model K-600 Circuit Breaker" No response required D'REILLY, J.P. Region 2. Atlanta. Diffice of the Director 81/03/11
- BIO3200013 Forwards IE Info Notice 81-05. Degraded CC Sys at Palisades "No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03/13
- 8103310773 Act receipt of IE Insp Rept 90-369/B1-06 Rept combains proprietary info passeR.H O Guie Power Co B1/03/16 ip 08062 279
- B:03240747 Act receipt of B:0310 itr informing NRC of steps taken to correct violations notes in IE Inap Rept 50-369780-32 LEMIS.R C Region 2. Atlanta. Office of the Director B://03/18 ip 07983 349
- --8103240797 Forwards revised response to violations noted in IE Insp Rept 50-359/80-32 Corrective actions test coordinators counseled on inportance of documenting any variance from test procedure no proprietary info PARKER. N. D. Cute Power Co. 81/03/10 3pp. 07983-350
- 8 Reportable occurrences. LERs & related correspondence
- BIO3060770 Advises that corrective actions specified in 801126 % 810109 deficiency repts have been completed for Fode & sys Remaining actions will be completed by 810301 page.R. N. O. Dute Power Ca. 81/01/28 ip. 07885 001
- 8103040629 Forwards LER 81-004/03L-0 PAGKER:N 0 Cute Power Co 81/02/26 lp. 07817 070
- --BI03040632 LER 01-004/03:-0 on 810129-0212, various firestops & fire doors found inoperable for periods exceeding 1-h Caused by const in & through areas normally closed off Fire watches & patrols established

  OVELLETTER W. Duke Power Co 81/02/28 1p 07817:071
- --gij3040706 LER Bi-001/03L-0 on BiD129-0212 several fire detection instruments were inoperable for periods exceeding 1-h caused by const in area Fire watches & patrols established GUELLETTE, R W Dute Power Co Bi/02/28 ip 07811:348
- B103940713 Forwards LER 81-003/93L-0 PARKER/N 0 Duke Pouer Co 81/02/26. Ip 07811 349.
- --9/03040720 LER 81-003/03L-0 on 910129, conventional waste plant discharge flow monitor found inoperable Caused by inaccurate flow readings due to inability of instrument to measure continuous discharge flow New equipment ordered DUELLETTER W Dute Power Co 81/02/28 3pp 07811 350
- 8103100457 Forwards LER 81-005/03L-0 PARKER, W D DUSS ROWET CC 81/03/02 1p. 07862 276
- --8103100494 LER 81-005/03L-0 on 810202, power supply to toth excore range monitors was interrupted Caused by maint personnel cutting off power to investigate steam genorator status lights & lo-lo level alarcs Personnel instructed OWELLETIER. W. Duke Pauer Co. 81/03/04 2pp. 07862 277.
- B103100467 Forwards LER 81-006/03L-0.
  PARKER.N D Duke Power Co 81/03/03 ip 07862.279
- --B103100494 LER B1-006/03u-0 on 810202, leaking scal discovered on RHR pump. Caused by improperly loaded spring which holds seal faces together Seal replaced.

  DUELLETIE.R W Duke Pauer Co. 81/03/04 2pp 07862 280.
- B103100426 Forwards LER B1-011/03T-0.
  PARKER-H O. Buke Power Co. 81/03/04 Spp. 07862-246
- --8603100435 LER 81-011/03T-0 on 810210 both pressure seals on inner door of lower personnel air lock feiled Caused by hole in one seal & bubble in other seal Soals replaced & returned to manufacturer.

  OUELLETIC.R.W. Duke Power Co. 81/03/04. 1p. 07862:249.

- --B103100449 LER B1-010/03L-0 on B10207, total RMR flow exceeded Tech Spors Caused by air line supplying actuator on RMR valve breaking, allowing valve to fail open RMR flow reset Rigid air supply lines to be replaced willerible lines CLELLETTE. R W Duke Power Co. 01/03/09 Ip 07862 256
- 8103130481 For Lands LER 81-007/03L-0 PARKER:W 0 Dute Pawer Co 81/03/04 ip 0/913 089
- --Bi031334B7 LER Bi-007/03L-0 on Bi0203.Ri-R sys train A was declared inoperable Caused by draining essential header to repair lealing valves in nuclear syc water sys Valves repaired train A returned to syc OLELETTE.R W Duke Power Co. Bi/03/09 ip 07913 090
- 0103100428 Forwards LER 81-012/037-0 PARKER.W 0 Dute Power Co 01/03/05 2pp 07862 290
- --8103100439 LER 81-012/03T-0 on 801211, legistion valve NV-250 found needfied closed under administrative control per Tech Spec Caused by lack of signoff step in Jaily surveillance items Procedure change incorporated OUELLETTE.R W Duke Power Co 81/02/25 ip 07862 352
- 8103130454 Forwards LER 81-000/03L-0 PARKER: N O Date Power Co 81/03/05 1p 07911 274
- --B103130456 LER B1-00B/03L-0 on B10203.control area ventilation systrain A declared inoperable Caused by draining essential heater to repair leaking valves in nuclear syc water sys valves repaired 8 train A returned to syc UJELLCTTE, R & Duke Power Co. B1/03/09 ip 07911 275
- 8103240396 Bignificant Deficiency Rept 369-370/80-02 re steam generate narrou-range level transmitter cable failure to meet environ qualification requirements Cable in Unit 1 for steam generator level transmitters replaced in Aug 1980.
  PARKER-W O Duto Power Co 81/03/17 2pp. 07986-358
- T Hearing transcripts on non-antitrust matters

07909.230

- B103130291 Transcript of B10224 OL hearing in Charlotte.NC Pp 2.674-2.891

  Atomic Safety and Licensing Board Panel 81/02/24 219pp 07910 087
- 8103130370 Transcript of B10225 hearing in Charlette.NC Pp 2.892-3.10
   Atomic Safety and Escensing Board Panel 81/02/25 220pp
- 8103133246 Transcript of Bi0227 DL hearing in Charlotte NC Pp 3.331-3.440 \* Atomic Safety and Licensing Board Panel B1/02/27 141pp 07910.320
- 8103:10437 Transcript of 810303 DL hearing in Charlotte, NC Pp 3.441-3.618 \* Atomic Safety and Licensing Board Panel 81/03/03 179pp 07870-032
- B103:10323 Transcript of B10304 Di. hearing in Charlotte-NC
- Pp 3.519-3.511 \* Atonic Safety and Licensing Board Panel 81/03/04 194pp 07880 179
- 8103110418 Transcript of 810305 GL hearing in Charlotte.NC Pp 3.812-3.972 \* Atomic Safety and Licensing Board Panel 81/03/05 162pp 07877 001
- 8103110430 Transcript of 810306 OL hearing in Charlotte.NC Pp 3.973-3.997.

  \* Atomic Eafety and Licensing Board Penel B1/03/06 26pp 07870 001
- 8103180554 Transcript of 810310 CL hearing in Charlotte.NC Pp 3,996-4,182 \* Atomic Safety and Licensing Board Panel. B1/03/10 186pp 07930 295

B103100441 Forwards LER 81-010/03L-0.

## DOCKETED ITEMS

8103180439 Transtript of 810311 Of hearing in Charlotte.hC Pp 4, 183-4, 372, Staff analysis of higroren control measures encl Atomic Sefety and Licensing Board Panel 81/03/11 67938, 100 8103180548 Franscript of 810312 OL hearing in Charlotte.NC Pb 4,373-4,541 Reactor & containment sys performance Access Safety and Licensing Board Panel 81/03/12 170pp
07950 112 8103180488 Transcript of 810313 OL hearing in Charlotte, NC Pg 4, 542-4.664 Atomic Safety and Licensina Board Panel 81/03/13 125mg 8103240265 Transcript of 810317 OL hearing in Charlotte.NC Pg 4,665-4.869 Atomic Safety and Licensing Board Panel 81/03/17 207nc 07991 005 8103240277 Transcript of 810318 On hearing in Charlotte, NC Pp 4,870-5,025 Atomic Bafety and Licensing Board Panel 81/03/18 160pp 07963 031 8103240273 Transcript of 810319 OL hearing in Charlotte. NC Pp 5. 026-5. 257 Atomic Safety and Liconsing Board Panel 81/03/19 234pp 07982 001 ∪ Congressional/Executive Correspondence 8103240091 Forwards fourth monthly status rept to Congress for B10119-0219 Rept discusses actions taken on licensing reviews of new facilities Rept will be amended to include addl info requested on 810217 KATHERER.C. Office of Congressional Affairs 81/02/27. 3pp 8103120515 Expresses concern re licensing procedure & effects of licensing delays Immediate effectiveness rute should be reinstated to allow authorized plant operations to begin Delays in literating process will increase capital costs ANDREMS-I . HEFREN.W G . MENDON.B House of Rep. 81/03 81/03/02 400 07906 294 9103270810 Responds to request for rept on possible additingrovements to NRC licensing process Legislation allowing interist operations in advance of hearing completion would reduce delay in licensing process
HENDRIE, J. M. Commissioners 81/03/12 Spp --Bi03270931 Submits recommendations to expedite impacted OL hearings Code should include set of IMI-related CL requirements ASLAB decisions on fuel loading & low power testing should be laneliately offective BICWHT.L. Offelce of the General Counsel BI/02/23 10pp DOCKET 30-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence 8102190636 Requests EIS be issued prior to opening of licensing PRINGLE. W. W. Affiliation Unknown 80/01/20 1p 07726 073

8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interin actions & request for addlines

6103190387 Ltr to all licensees of operating plants & applicants for

8103120014 Ltr to all licensees of operating plants.CP holders & OL

ULs & holders of CPs re program for environ qualification of safety-related electrical equipment items addressed involve cold shutdown replacement parts & NUREO-0737 EISENMUT.D 0 Division of Licensing BI/01/19 &pp.

applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 001222 request for addl info re control of heavy loads.

80/12/22 30pp

EIBENHUT, D.Q. Division of Licensing

8103041030 Forwards request for addl info to 8-list review for facility Util must provide justification for phitting following items radiation monitoring, instrument storage rusiowang items radication monitoring, instrument storage callby b maint fuel assemblies b containment control RCOMAN.V S Assistant Director for Haterials & Qualifications Engineering 81/02/20 7pp. 07B19 27 8103230024 Ltr to all power reactor licensees & license applicants NOREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee May submit analysis to justify use of existing low flow controller EIBENHUT.DG Division of Licensing 81/02/20 8pp 8103090578 Forwards PMR const filestones & activities for McOulre 2. Catawba 1 & 2 & Charakes 1 Key event dates provided GROGANU F Pute Power Ca 81/02/24 & 5pp 07890 186 8103090049 Forwards request for addl info re identification of saf related structures, sys & components subj to operational QA program Response required by 810302 TEDESCO R L Assistant Director for Licensing 81/02/25 Bon 07852 169 B10323030 Ltr to all licensees of operating nucleor power plants applicants for OLs forcept St Lucie. Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly inplement energency procedures EIBENHUT.D 2 Division of Licensing B1/02/25 Spp 8103230813 Generic Ltr 81-04 to all CP holders & OL applicants re OCCRSO 71(e), 'Periodic Updating of FSARs.' effective BOD722 info re FSAR legal status format & content encl EIECHAULD 9 Division of Licensing 81/02/26 10pp B103030714 Forwards certified matl test repts for selected contain pressure boundary components including containment vessel shell plate equipment hatch barrel half & brating assembly \$ eteam piping PARKER.W O. Duke Power Co 81/92/27 54pp 68068 144 8103050528 Forwards 'Review of Piping Sciente Analysis Methods." L response to NRC 810126 request for technical justification of response spectra
PANKER,W O Dute Power Co 81/03/02 ip 07826 210 --8103090533 "Review of Piping Seismit Analysis Methods"

\* Duke Power Co 81/03/02 ibno 07826 811. 6103:10321 Advises that analyses of liquid & gaseous raduastes are performed by Toledyne isotopes, per achedule requirements of Tech Spec o 9 8 % 3 10 9, satisfying Tech Spec 6 4 1 Detailed review of vendor analysis procedures unnecessary PARKER W 0 Dute Power Co 81/03/03 2pp BIGGIGGES Confirms completion of structural regulation of 17 Cate I masonry wolls identified as requiring mode to neet specified design criteria PARKER, NO Duke Power Co. 81/03/09 ip 07911.276 BIO3130545 Responds to NUREG-0737. Item II F 2. "Instrumentation fo Detection of Inadequate Core Cooling " Conformance of reactor vessel level sys to Reg Oulde I 97 will be addressed when overall compliance submitted on BIO423 PARKER. W 0 Duke Power Co BI/03/09. 4pp 07908.315 8103230479 Forwards updated responses to NRC 800923 ltr re TMI Concerns Zero power physics testing is scheduled for completion by May 1981 PARKER. W.D. Dute Power Co. 81/03/09 62pp 07976.239

8103300318 Forwards response to NRC 810225 ltr re identification o

8103310804 Ltr to all licensees of operating plants, applicants for & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical

8103240455 Notifies that description of conformance of subcooling monitor to Reg Ouide 1 97 will include assessment of core exit thermacouples using Attachment 1 to Item II.F.2 in

EISENHUT D O Division of Licensing 81/03/10 App

PARKER, W. O. Duke Power Co. 81/03/18. 2pp. 07982 261

englement

NURFO-0737

## F. Security, medical, emergency & fire protection plans

- 8[03030974 Natification of rescheduled 810212 meeting w/util in Bethesda.MD to discuse fire protection matters Meeting originally set for 810210 3[KAEL.R.A Litensing Branch 1 81/01/30 3pp 07795 237
- 8103109110 Advises of acceptance of safeguards contingency plan Plan rust be implemented within 30 days. Encis to 790323 & 801217 its withheld (ref 10CFR2 790) VOUNCORD. ON 1 Licensing Branch 1 81/02/24 2cc 07866 003
- 8103090517 Forwards Revision 10 to codified amended security plan Plan withheld (ref 10CFR2 790) PARAGRAW Q Duta Power Co 81/03/02 1: 07844 355
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl EISENHUT.D O. Division of Licensing. 81/03/05. App.
- 8103160270 Informs that provided items identified in encl energency preparedness evaluation are resolved facility energency plan will meet 100FR50 requirements Completion schedule requested by 810313 TEDESCO.R L. Assistant Director for Licensing 81/03/06 14pp 07921:314
- G103240527 Notifies that response to six open items in emergency preparedness evaluation rept will be provided w/response to Ceneric Ltr Bi-10 by G10403.per B10306 request PARKER, U D Dube Power Co G1/03/16 1p 0786 166
- B103310139 Act receipt of B10302 ltr transmitting change to security plan Change consistent w/100FR30 \$4(p) Encl withheld (ref 100FR 2 790).
  YOUNOBLOOD,B J Operating Reactors Branch 1 B1/03/25 2pp 08062-099

### G. Adjudicatory correspondence

- 8102030à11 Response in objection to ASLB 810217 memorandum & order denying admission of Contentions 5 & 6. Supplementary E15 on Class 9 accident is necessary predicate in proceeding Denial should be certified to Commission IV/Certificate of Bvc COHI2-D B Carolina Environmental Study Group 81/03/02 Spp 07829-120
- 8103030674 Bubmits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties.

  CHRISTENSURY. E. Hearings Division 81/03/04 2pp
- 8103170292 Informs that name & address has been placed on NRC Centificate of Svc as representative of Carolina Environ Brudy Oroup KETCHEN.E. 9. Hearing Branch 4. 81/03/11. 1p. 07923.218
- \$103230610 Forwards Carolina Environ Study Oroup application for subposees re respected Pacifity OL proceeding Related correspondence.

  BLUM: S. Carolina Environmental Brudy Group BLUM: S. Blum & Sheely 81/03/11. 1p. 07977:281
- ~-BiO3230622 Cerolina Environ Study Group application for subposens re reopened McOuire Units 1 & 2 CL proceeding List of proposed witnesses & questions encl. Related correspondence. BLUM.S. Cerolina Environmental Study Group BLUM.S. Blum & Sheely Bi/O2/26. 10pp 07977.282
- 8103270590 Request for license euthorizing operation up to & including 35% rated power. Fuel loading initial criticality & zero power physics testing to be completed by 810519 Certificate of 8vc encl.

  MCGARRY, J. M. Duke Power Co. MCGARRY, J. M. Debevoise & Liberman. 81/03/24. App. 08034.053
- 8103310122 Informs that NRC completed review of info in record. Openerally info is sufficiently detailed Encl affidevits.ra actual const of air handler ducts.should be included in record BCINTO.U.F. Hearings Division. 81/03/27. 2pp 08079.121

- --B103310148 Joint affidavit re const details of air handling unit ducts vendor confirmed existence of insulation harrier on drawings 5 installation in facility ducts NAC has no further concerns about pyrolysis of foam NODNAW, V S. Assistant Director for Materials 5 Qualifications Engineering POLK. HE. Structural Engineering Branch PARCZEMSALIK I. Chemical Engineering Branch 81/03/27 7pp 08079 103
- H General correspondence
- B103120330 Forwards, for review. B10213 ltr from JN Cox re facility itcensing Response requested MCLLINGS. E.F. Bonate 81/02/27 2pp 0/701 251
- S103180607 Urges Ct. for Unit 1 be issued promptly Belay in licensing is costly to rate payors MITCHELLAR South Carolina, State of 81/03/09 2pp 07953-093
- B100260968 Opposes facility licensing SIMPBON C Affiliation Uning 81/03/19 Ip

### I Financial information

- B103310549 Forwards Annual Financial Rept 1980, annual certified financial statements, 1981-83 financial forecast & util statement re available founds to satisfy liability Info guarantees retrospective premiums per IOCFR140 26 THIES.A C Dute Power Co B1/03/24 1p
- ---8103310638 Annual Financial Rept 1980, including financial statements. 1981-83 Financial forecast & statement re sources of available funds to satisfy liability HORN.C Dute Power Co. 81/02/13 Sipp
- Q Inspection reports. 1E Bulletins & correspondence
- B103020203 Forwards IE Circular B1-02. "Performance of NRC-Licenses Individuals While on Duty." No written response required D'REILLY, J. P. Region 2. Atlanta. Office of the Director 81/02/09 to
- B103180483 Forwards IE Insp Repts 50-359/81-04 & 50-370/81-04 on B10120-23 No noncompliance noted MURPHY.C E Region 2- Atlanta, Reactor Construction & Engineering Support Branch B1/02/10 2pp. 07741 220
- --Bi03180492 IE Insp Repts 50-359/81-04 & 50-370/81-01 on Bi0120-21 No noncompliance noted Major areas Inspected electrical cables & terminations, instrumentation components & sys & followp on IE Bulletin 80-23 GIBBONS, T.D., MERRIWEATHER, N. Region 2. Atlanta, Office of the Director CONLON T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/02/10 3pp 07945 222
- 8103160457 Ack receipt of 801009, 1208 & 810130 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370780-12
  RMRPHYC. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/26 ip 07915 269
- --8103160480 Forwards add1 response to NRC 800917 ltr re violations note in IE Insp Ropt 50-370/80-12 Corrective actions qualification of procedures revised by 810301 to require min number of checkpoints & documentation of test objects PARXER, W.O. Duke Power Co. 81/01/30 2pp 07915 270
- --8193160498 Forwards add1 response to NRC 800917 1tr re violations note
  in IR Insp Rept 50-370/80-12. Corrective actions established
  procedures for training nondestructive eram personnel to
  meet guidelines & intent of SNT-TC-1A
  PARKER, M. O. Duke Power co 80/12/08 3pp 07915:272
- --B103160510 Responds to NRC 800917 ltr re violations noted in IE Insc Rept 50-370/B0-12 Corrective actions examiner candidates required to demonstrate proficiency by use of process control from M-4A during practical exam PARKER.W.O Dute Power Co 80/10/09. 3pp. 07915-275
- --B103160522 Forwards IE Insp Rept 50-370/B0-12 on B00812-15 & notice of violation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. B0/09/17 2pp. 07915:278.
- --B103160829 Notice of violation from insp on B00812-15.

  \* Region 2. Atlanta, Office of the Director. B0/09/09. ip.
  07918:280.

- ~-BIO3160537 (E Insp Rept 50-379/80-12 on BOOB12-15 Noncompliance noted failure of visual eram training & qualification program to meet ASHE requirements

  ZAJACLE D Region 2. Atlanta. Diffice of the Director HERDT. A Region 2. Atlanta. Reactor Construction & Engineering Support Branch BO/07/09 App 07915 281
- Bio316685: Forwards IE Circular Bi~03, "Inoperable Beismic Monitoring Instrumentation" No response required GREILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/02 pp. 07917-121
- 8)03170041 Forwards revised IE Bulletin 81-01. "Surveillance of Machanical Shubbers." U/torrected Pages 5 % 6 Change in identification of facilities U/CPs to which bulletin is applicable does not affect util requirements

  O'REILLY, P. Region 2. Atlanta. Office of the Director 81/03/04

  1p. 07937 167
- 8103240602 Ack receipt of IE Inst Repts 50-369/81-04 & 50-370/81-01 No proprietary info PARKER, W O Dute Power Co 81/03/04 ip 07982 312
- 8103180194 Ack receipt of 810219 ltr informing NRC of steps taken to correct violations noted in IE inap Repts 50-369/80-38 & 50-370/80-20
  LEWIS.R C. Region 2- Atlanta, Office of the Director 81/03/06
- --Bi03180297 Responds to NRC 810129 ltr re violations noted in IE Insp Repts 99-359/80-38 & 90-370/80-20 No proprietary info Corrective actions. Completed technical audit of EDS-Ban Francisco piping analysis & audit re design input tracking PARKER, U O Duke Power Co 81/02/19 6pp 07945-249
- --8103160217 Forwards IE Insp Repts 50-369/80-38 % 50-370/80-20 on 801203-09 & 17-18 % notice of violation MURPHY.C E Region 2. Alianta, Reactor Construction & Engineering Support Brauch 81/01/29, 200 0/949 200
- --8193180222 Notice of violation from insp on 801203-05 & 17-18 \* Region 2: Atlanta: Office of the Director 81/01/29. ip 07945.257
- --Bi03180237 IE Insp Repts 50-369/80-37 & 50-370/80-20 on 801203-05 & f7-18 froncompliance noted failure to establish adequate measures for control of design interfaces & coordination among participating design organizations. JERDIA R : F05TERLE E : WOW9.H. Region 2: Atlanta. Office of the
- Director Bi/Oi/29 13pp. 07945-258

  B10320028: Forwards IE Info Notice Bi-O6. "Failure of ITE Model K-600 Circuit Broaker" No response required Office of the Director Bi/O3/11
- 8103200013 Forwards IE Info Notice 81-05. "Degraded DC Bys at fallsados " No response required. O'REILLY, J P. Region 2. Atlanta, Office of the Director 81/03/13. tp. 07969.072
- S Reportable occurrences. LERs & related correspondence
- 8103240396 Bignificant Deficiency Rept 369-370/80-02 re steam generator rerrow-range level transmitter cable failure to meet environ qualification requirements Cable in Unit 1 for steam generator level transmitters replaced in Aug 1780 PARKER. H. O. Dute Pouer Co. B1/03/17 2pg. 07986/398.
- T Hearing transcripts on non-antitrust matters

1 n

- 8103130251 Transcript of 810224 OL hoaring in Charlotte.NC.Pp 2.674-2.891 4. Atomic Gafety and Licensing Board Panel. 81/02/24. 219pp
- 8103133370 Transcript of 810225 hearing in Charlotte-NC Pp 2.892-3.107.
   Atomic Safety and Licensing Board Panel 81/02/25. 320pp. 37709: 001.
- 9103130261 Transcript of 810226 OL hearing in Charlotte,NC.Pp 3.108-3.300. \* Atomic Sefety and Licensing Board Penel. 81/02/26. 194pp 07907 230
- 8103130246 Transcript of 810227 OL hearing in Charlotte.NC Pp 3:301-3:440.

  Atomic Safety and Licensing Board Panel 81/02/27 141pp.
  07910 320.

8103110437 Transcript of 810303 OL hearing in Charlotte.NC Pp 3.441-3.618 • Atomic Safetu and Licensing Board Panel 81/03/03 179pp

07870 032

07950 295

4. 664

07981.006

07906.299

- 8103110323 Transcript of 810304 CL hearing in Charlotte.NC Pp. 3.619-3.811
- Pp 3.619-3.811
  Atomic Safety and Licensing Board Panel 81/03/04 194pp
  07880 179
- 8(03)104(8 Transcript of 810305 GL hearing in Charlotte, NC Pp 3.8): 3.972 \* Atomic Bafety and Licensing Board Panel 81/03/05 162pp 07877-001
- 8103110430 Transcript of 810306 OL hearing in Charlotte.NC Pp 3.975 3.997 • Atomic Safety and Licensing Board Panel 81/03/06 26pp
- 07870 001

  B103180594 Transcript of 810310 OL hearing in Charlotte.NC Pp 3.998-4.182

  \* Atomic Safety and Licensing Board Panel 01/03/10 186pp.
- 8103180437 Transcript of 810311 OL hearing in Charlotte.NC Pp 4.183
  4.372 Staff analysis of hydrogen control measures encl.

  A tomic Safety and Licensing Board Panel B1/03/11 192pp
- 07938 100

  BIO3180549 Transcript of 810312 OL hearing in Charlotte.NC Pp 4.373-4.541 Reactor & containment sys performance assessment encl # Atomic Safety and Licensing Board Panel 81/03/12. 170pp. 07950. 112

8103180488 Transcript of 810313 OL hearing in Charlotte, NC Pp 4, 942

Atomic Safety and Licensing Board Panel 81/03/13 (25pp.

- 07941: 227

  B103240266 Transcript of 810317 OL hearing in Charlotte.NC.
  Pp 4.665-4.859

  A Atomic Safety and Licensing Board Panel. 81/03/17. 207pp.
- 8103240277 Transcript of 810318 OL hearing in Charlotte NC. Pp 4,870-5,025 \* Atomic Safety and Licensing Board Panel. 81/03/18 160pp. 07983.001
- 8103240273 Transcript of B10319 OL hearing in Charlotte.NC. Pp 5.026-5.237 • Atomic Safety and Licensing Board Panel. 81/03/19. 234pp. 07982 001.
- U Congressional/Elecutive Correspondence
- 8103120615 Expresses concern re licensing procedure & effects of licensing delays. Irmediate effectiveness rule should be reinstacted to allow authoritized plant operations to begin Delays in licensing process will increase capital costs ANDREWS. 1. HEFNER, W. G. . HENDON, 8. House of Rep. 81/03/02 4pp
- DOCKET 50-373 LABALLE COUNTY STATION. UNIT 1

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OC.s & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREG-0612 Forwards NRC position re-interim actions & request for addl info.
  E18ENHUT.D.O. Division of Licensing 80/12/22. 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for the state of the control of the state of the control of safety-related slectrical equipment. Items addressed involve cold shutdown.replacement parts & NUREO-0737. EIBERHYT.0 O Division of Licensing. 81/01/19 App.
- 8103120014 Ltr to all licensees of operating plants.CP holders & Ol applicants.except indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertantly omitted pages from NRC B01222 request for addl info re control of heavy loads. EISENHUT.D.Q. Division of Licensing. B1/02/03 6pp.

- 8103050951 Notification of 810311 & 12 meeting byMark II owners group & GE in Bethesde.MD to discuss Mark II generic long-term program AMDERSON.C J. Generic Issues Branch. 81/02/12 18pp.
- B103060375 Requests snubber maint records to documented due to history of inoperable & incorrectly installed snubbers Preservice inspinust be prerequisite for preoperational testing of snubber thermal motion TEDESCO.R.L. Assistant Director for Licensing B1/02/19 3pp 07836-292.
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization effective 810216 MSPPLER, J. O. Region 3. Chicago. Office of the Director 81/02/20 200
- 8103250024 Ltr to all power reactor licensees & license applicants re NUMEG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISERNIUF D Q Division of Licensing 81/02/20 App.
- 8103020619 Responds to NAC 810220 questions re NUREQ-0737 Provides info re reporting ECCS outages & common water level ref Changes will be incorporated in FSAR DELOCORDE. C. O. Commonwealth Edison Co. 81/02/23 200 07782 097
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for OLs (except St Lucie. Units 1 & 2) Requests util review to determine capability to nitigate station blactout event & promptly implement energency procedures. EISENMUT. D.O. Division of Licensing 81/02/25 5pp
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Cote Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of enci Revision 1 to NUREO-0313 Model for B
- --BIO3170266 Model Teth Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ASNE Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements • General Electric Co. BI/O2/26 4pp
- 8103170655 Ltr to holders of CPs & applicants for GLs (BWRs) requesting review of ASME Class 1.2 & 3 pressure boundary piping safe ends & Pitting matl per guidelines of encl Revision I to NUREG-0313 Model Tach Specs only encl.
  EISENHUT, D. 0 Division of Licensing B1/02/26 3pp.
- B103230B13 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR50, 71[e], "Pariodic Updating of FSARs," effective B00722 Info re FBAR legal status format & content encl. EISEKHUT, D. O. Division of Licensing. 81/02/26 10pp
- 8103150102 Requests assessment of differences between util criteria & MRC interim cirteria on impact of facility mesonry well evaluation. Difference must be resolved prior to startup following first refueling TEDESCO. R L. Assistant Director for Licensing 81/03/02 10pp. 07917:332
- 8103130601 Notification of 810313 meeting w/Merk II owners group in Bethesda, MD to discuss Mark II safety relief valve loads & pool temp limits. SU.T.M. Generic Issues Branch 81/03/03 2pp
- 8103110154 Forwards "Bummary of Conformance to NRC Regulations of 10CFR20, 50 & 160." Rept available in Central Files only. DELOEGREE, L. D. Commonwealth Edison Co. 81/03/06 1p. 07857: 076.
- 9103120647 Forwards supplemental rept re environ qualification of safety-related electrical equipment in harsh environs in cases where compliance w/NUREO-0588 criteria is not documented re-evaluation will be completed by 810631.
  DELOGORGE-L.O. Commonwealth Edison Co. 81/03/09 lipp 07906 286.
- 8103310804 Ltr to all licenses of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to astablish environ qualification of safety-related electrical equipment.

- BIOJ200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of CE-1-A.Revision lò re GA program Revisions reflect ASME winter addenda code changes changes made per ASME survey & clarifications & corrections program Revisions & CE-1008 program Rev
- ---8103200359 Revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of Revision 16 to 0A program Commonwealth Edison Co CE-1-A RIG 81/03/16 6pp
- BI03200444 Forwards Suppl 2 to NUREO-0487. "Mark II Containment Lead plant Program Load Evaluation & Acceptance Criteria" & policy issue paper Suggests Mar 1981 meeting w/Mark II owners to discuss review program W/o encl. NWIEL.K Owners (Issues Branch 81/03/16 ip 69134 218
- B103240371 Forwards Vol 5 of "Equipment Bualification Belsmic Gualification Review Team Post-Audit Documentation." to suppl response to ARC 810220 & 24 questions Rept is available in Central Files only FELBERGEL O Communication to 81/03/19 in 08022 009
- BIO3310914 Summary of B10313 neeting w/Mark II owners group resuppression pool temp limit & T-quancher load spec. U/a encl list of attendees & meeting handout BU.T.K. Generic issues Branch B1/03/24 3pp
- 8103310397 Forwards Suppl 2 to NoREO-D487. 'Mark II Containment Lead Plant Program Evaluation 5 Acceptance Criteria " Deviations from criteria are to be documented in design assessment rept curing FBAR review 4/o encl YCUMOBLCOD.3.J Licensing Branch 1 81/03/26 3pp 08059:308
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8103020017 Informs that 801103 EER supplies applicable until receipt of responses to NRC 801120 & 810210 requests for addlinforce 0-list 200NAN.V.S. Assistant Director for Materials & Qualifications Engineering 81/02/18 1p 65030.143
- B1030901B2 Forwards branch SER input in response to ALAB-444, re status of unresolved safety Issues KNIEL K Generic Issues Branch B1/02/18 3/pp 07846 285.
- B103170215 Forwards SER for review Eightoen Issues remain outstanding Resolution of all open items required before OL issuence W/o encl.

  16D65CO.R L. Assistant Director for Licensing 81/03/05 2pp 07925:282
- B103230641 Forwards NUREO-0319 facility BER & notice of availability YOUN08L00D.3 J Licensing Branch I B1/O3/13 3pp 08030:001
- --B103230648 Notice of availability of NUREQ-0519, facility BER YOUNDBLOOD B.J. Licensing Branch 1 B1/03/13. Ip. 08030 004
- --8103230659 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE LA BALLE COUNTY STATION.UNITS 1 AND 2 Docket No. 50-373 and 50-374 (Commonwealth Edison Company)

   Office of Nuclear Resettor Regulation, Director, NuREO-0519 81/03/31, 300pp. 08930 005.
- BI03230869 Discusses OL hearing scheduling process BER technical input schedule for CYBL & CYBL enci DENTON: H R. Office of Nuclear Reactor Regulation, Director BI/03/13. 9p. 07977:075
- F Security, medical, emergency & fire protection plans
- B101080051 Releases public version of util draft emergency plan. NNREO-0634 info encl. FELTON.J.M Division of Rules and Records 80/12/02 18pp
- --Bi01230543 Forwards public version of draft emergency plan for generating stations. PEOPLEB.D.L. Commonwealth Edison Co. BO/04/24, Jpp. 04837 169
- --BIG10BQG6B Public version of draft emergency plan for generating stations.

- n-gj01220299 Forwards public version of util revised draft emergency plan Wystation annexes PECPLES.D L. Commonwealth Edison Co 80/06/04 2pp 05370 005
- --BEG1090019 Public version of Revision 1 to draft emergency plan
- --8101080029 Public version of draft energency plan annex \* Commission Edison Co 80/07/31 Sopp 07417-191
- B103050583 Forwards security plan revision Revision withheld tref ICCFR2 7901
  ABEL J B Commonwealth Edison Co 1 81/03/02 ip 07826 273
- 8103310338 Ltr to all licensoes of operating plants & holders of CPs forwarding NuREO-0656. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for resting NRC requirements W/o encl ETSER-UT.D O Division of Licensing 81/03/05 App
- 8103290685 Releases public version of implementing procedures for emergency plan Friffic. In Division of Rules and Records 81/03/19 lo.
- --B100250852 Forwards public version of emergency plan implementing procedures for corporate command ctr.environ director & plant-specific procedures
  DELGEORGE.L. O Cormonwealth Edison Co 81/02/27 2pp
- --Bitd290702 Public version of emergency plan implementing procedures for corporate command ctr. Paviron director & plant-specific procedures

   Corronwealth Edison Co. Bi/OZ/27. 1400pp
- M. Utility Final Bafaty Analysis Report (FBAR) & amends
- B103250397 Forwards Amend 99 to FBAR

  DELGECROE:L 0 Commonwealth Edison Co 81/03/19 Lp 07997.870
- O Inspection reports, IE Bulletins & correspondence
- B103090623 Forwards IE Insp Rept 30-373/80-56 on 801021-1231 Nu noncompliance noted. HEIBHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch B1/01/20 2pp 07845-349
- ~-Bi03090627 IE Insp Rept 90-373/80-56 on 801021-1231 No noncompliance noted Major areas inspected licensee action on previous insp findings & clarification of licensee position re onsite review corrittee requirements WALKERIR D , BREPLEY, B E , SPEBBARD, R L Region 3, Chicago, Office of the Director Bi/01/19 9pp 3/845 391
- B103040275 Forwards 1E Insp Rept 50-373/80-53 on 801203-04 No noncompliance noted. FIGHER.M.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch 81/01/22 2pp 07815.140
- --8103040278 lE Insp Rept 50-373/80-33 on 801203-04 No noncompliance noted Major areas inspected emergency planning including conduct of emergency planning exercise involving site & general emergency Exercise scenario encl
  DESTMANN.J., JANUSKA.A O. PAPERIELLO.C.J. Region 3. Chicago, Office of the Director 81/01/21 48pp. 07815-142.
- GioGo20115 Forwards IE Circular 91-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 81/02/09. 2pp.
- 8103040249 Forwards IE Info Notice 81-03, "Checklist for Litensees Kaking Notifications of Bignificant Events in Accordance W/10CFR50 72" No written response required KEPPLER. J O Region 3. Chicago, Office of the Director 81/02/12 2pp. 07813-275.
- 8103030292 Forwards Suppl 5 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram et 84R " No written response required.

  XEPPLER J 9. Regjon 3. Chicago. Defice of the Director 81/02/13 2pp. 07790.340.

- 8103260072 Forwards 1E Insp. Repts 90-373/81-02 & 30-374/81-02 on B10112-14 at Reactor Controls. Inc. on B10115 at Earthquake Engineering Bys. on B10119 at site & 810122-23 at Bargent & Lundy No noncompliance noted F1082LLL.G Region 3. Chicago. Reactor Construction & Engineering Support Branch B1/02/13 2pp 08041 243
- ---BIO3260084 IE Insp Repts 50-373/BI-02 & 50-374/BI-02 on BIO112-14.19, 19 & 22-23 No noncompliance noted Hejor areas inspected RCI control drive sys suspension sys design control & GA program
  YIN.I T. Region 3. Chicago. Office of the Director DAMIELSON.D H. Region 3. Chicago. Reactor Construction & Engineering Support Branch BI/02/I2 7pp OB041:245
- BiO3250020 Forwards IE Insp Repts 50-373/81-01 & 50-374/81-01 on BiO107-08 No noncompliance noted FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch Bi/02/17. App 07978 &60
- --Bi03290023 IE Insp Repts 50-373/Bi-01 & 50-374/Bi-01 on Bi0107-08 No noncompliance noted Major areas inspected hip rap on spitically follower of unresolved items suppression pool mods & safety relief valves nod & installation RijkER, JH , MILLIAMS.C C Region J. Chicago. Office of the Director 81/02/17 3pp 07998 262
- 81030a0375 Requests enubber maint records be documented due to history of inoperable & incorrectly installed southers Preservice insp must be prorequisite for preoperational testing of enubber thermal motion.

  TEDESCOR L Assistant Director for Licensing 81/02/19 3pp 07835 292
- 8103300150 Forwards IE Insp. Rept 50-373/80-49 on 800924-25.1028. 1119-20.29-26 & 810120 No noncompliance noted HEIBHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Granch 81/02/23 2pp 08033-054
- --B103300155 [E Insp Rept 50-373/80-49 on 800924-28.1028.1119-20.25-26 B10120 No nencompilance noted Major areas inspected. preoperational test procedures & previous open Ltens MAURA.F.A. HQFKINS.J.B. ROJINBON.D.L. Region 3. Chicago, Office of the Director 81/02/18 7pp 08053 056
- B103160494 Forwards IE Circular B1-03. "Inoperable Betamic Monitoring Instrumentation " No response required KEPPLER. J. O Region 3. Chicago. Office of the Director. B1/03/02 200
- 8103110375 Ack receipt of B10203 ltr informing MRC of steps taken to correct violations noted in IE Insp Repts 30-373/B0-48 % 50-374/B0-30. Classification of B10129 meeting as enforcement conference & level of noncompliance unchanged KEPPLER. J. 0. Region 3. Chicago. Office of the Director B1/03/03. 2pp 07873-313.
- --8103110370 Responds to NRC 810109 ltr re violations noted in IE Insp. Repts 50-373/80-48 & 50-374/80-30. Corrective actions stop work order issued on 80111 covering installation & insp. of safety-related control rod driveline piping supports REED.C. Companies of the companies
- BiO3170092 Forwards revised IE Bulletin 81-01, "Butveillance of Mechanical Snubbers," w/corrected Pages 5 & 6.0til is added to CP facilities to which bulletin is epplicable. Response should include estimate of manpower expended KEPPLERIJ O Region 3. Chicago. Office of the Director. 81/03/04 ip. 07935:280
- 8103200394 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required. KEPPLER. J. Q. Region 3. Chicago, Office of the Director. 81/03/11 200
- G103200695 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades." No action required.

  KEPPLER.J C Region 3. Chicago. Office of the Director. 81/03/13.
  20n
- BID3200269 Forwards IE Info Notice BI-07, "Potential Problem M/Water-Boluble Purge Dam Matls Used During Inert Gas Welding "No response required KEPPLER, J. Q. Region 3, Chicago. Office of the Director. BI/03/16.
- BIO3261193 Responds to IE Bulletin 80-29. "Operating Problems W/Target Rock Safety Relief Valves at BWRs " Engineering review of LaBalls safety relief valve pneumatic supply sys still in progress. Mode will be completed prior to fuel loading. RAUSCH.T.J Commonwealth Edison Co. 81/03/19. 7pp.

- A Periodic operating reports & related correspondence
- 8103170465 Forwards "Fog & Rise ice Monitoring Program Sunnary, 1980 " Data collected during operational phase cill be Analyted. Interpreted & compared w/B10123 draft ETS DELOEDREEL D Campanesith Edison Co 81/03/11 ip 07925 233
- --8103170468 'Fog & Rime Ice Honitoring Program Busmary, 1980, "
   Commonwealth Edison Co 81/03/11 ICpp 07925-234

### V. Operator Examinations

- 8103030769 Forwards supplemental info re shift technical advisor training per NUPEG-0737. Item I A i | (3) info includes response to training requirements for shift control room engineers & projected schedule for training corpletion ABEL J 3 Commorwealth Edison Co | 91/02/24 | 497
- B103050140 Forwards list of shift control room engineers meeting training & advection requirements by dates indicated Many engineers completed training by B10101 Target date for completion of training is m(d-1981 ABEL J S Commonwealth Edison Co 81/02/24 4pp
- B103200574 Forwards supplemental info re long-term shift technical advisor program, including candidate qualification, selection criteria, training plans & bates for phase-out of shift technical advisor program mandated by NCRC-0737 ABEL. J S Commonwealth Edison Co B1/03/17 19pp
- DOCKET 90-374 LASALLE COUNTY BTATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position reinterim actions & request for addlinfor. EISE(HUT.D.O. Division of Licensing 80/12/22 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREG-0737.
  EISENHUT-D.Q. Division of Licensing. 81/01/19 dop
- 8103120014 Ltr to 411 licensees of operating plants.CP holders & GL applicants.except Indian Point 2 & 3.2ion 1 & 2 & THI-1, forwarding inadvertently onitted pages from NRC 801222 request for add1 info re control of heavy loads EIBENHUT.D Q. Division of Licensing 81/02/03 app.
- 8103050991 Notification of 810311 & 12 marting w/Mark II owners group & QE in Bethesda, MD to discuss Mark II generic long-term program. ANDERSON-C. J. Generic Issues Branch. 81/02/12. 12pp
- BIO3060375 Requests snubber maint records be documented due to history of inoperable & incorrectly installed snubbers. Preservice inspirus to presquisite for preoperational testing of snubber thermal motion. TEDESCO.R.L. Assistant Director for Litensing. B1/02/19. 3pp. 07836:292.
- 8103100214 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216 MEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/02/20 2pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re FAREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

  EISENHUT, D. 0 Division of Licensing. 81/02/20 8pp.
- 8103020619 Responds to NRC 810220 questions to NUREQ-0737. Provides info re reporting ECCB outages & common water level ref. Changes will be incorporated in FBAR. DELOEDRGE, L. D. Commonwealth Edison Co. 81/02/20, 2pp. 07782-097.
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs fercept Bt Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement erergency procedures. EISENHUT. D. 9. Division of Licensing. 81/02/25. Spp.

- BiD3170225 Ltr to all RMR licensees (except Humboldt Day & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary ciping-safe ends & fitting mail per guidelines of encl evision t to NUREO-0313 Model Tech Specs only encl eistmut.D 0 Division of Licensing 81/02/26 3pp
- --8103170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 rd surveillance requirements for ASME Code Class 1.3 & 3 companents & RCS operational leakage limiting conditions for operation & surveillance requirements & General Electric Co. 81/02/26 App.
- 8103170655 Ltr to holders of CPs % applicants for CLs (BCRs) requesting review of ASCE Class 1.2 % 3 pressure boundary piping, safe ends & fitting rati per guidelines of encl Revision 1 to NURGE-0313 Model Tech Spacs only encl FISENBULT D & Division of Licensing 81/02/26 3pp
- B103230813 Denetit Ltr 81-06 to all CP holders & GL applicants re 1005R50 71(e). "Periodic Updating of FBARs." effective 800722 Info re FSA9 legal status format & content encl EISENHUT.D @ Division of Licensing 81/02/26 10pp
- 8103160102 Requests assessment of differences between util criteria & NRC interim cirteria on impact of facility masonry wall evaluation Difference must be resolved prior to startup following first refueling TEDESCO.R L Assistant Director for Licensing 81/03/02 10pp 07917 332
- 810313060) Notification of 810313 meeting J/Mark II puners group in Bethesda.MD to discuss Mark II safety relief valve loads & pool temp limits SULT M Generic Issues Branch 81/03/03. 2pp
- B103120647 Forwards supplemental rept re environ qualification of safety-related electrical equipment in harsh environs. In cases where compliance w/NUREO-0588 criteria is not documented, re-evaluation will be completed by 810631 DELOEDROE, L. D. Commonwealth Edison Co. 01/03/09. 11pp. 07906-206
- B103310B04 Ltr to all licensees of operating plants, applicants for C.s. Libolders of CPs forwarding SECY-B1-117 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISERHUT.D 0 Division of Licensing 81/03/10. App
- BIO3190145 Notification of BIO316 meeting w/near-term DL applicants in Bethesda. HD re info required to be submitted on environ qualification of electrical equipment prior to site visit & NRC review.

  BURRELL-5 Licensing Branch 2 BI/O3/12. 15pp.
- 8103200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of CE-1-A.Revision ib to GA program Revisions reflect ABME winter addends code changes changes made per ABME survey & clarifications & corrections. TRANM.T.R. Commonwealth Edison Co. 81/03/16 Ip.
- --8103200369 Revised abstract % Pages 2-2,4-2,4-5,7-2 % 18-2 of Revises 16 to 04 program # Commonwealth Edison Co CE-1-A R14 B1/03/16. dpp.
- 8103200444 Forwards Suppl 2 to NuREO-0487. 'Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria' & policy issue paper Buggests Mar 1981 meeting w/Mark II owners to discuss review program. W/o ancl NIEL.K Generic Issues Branch 81/03/16 ip. 69134 218
- 8103240371 Forwards Vol 5 of "Equipment Qualification: Baismic Qualification Review Toam Post-Audit Documentation." to suppl response to NRC 810220 & 24 questions. Rept is available in Central Files only.

  DELOBOROE, L. O. Commonwealth Edison Co. 81/03/19. ip. 08022 005
- 8103310914 Bummary of 810313 maeting w/Hart II owners group re suppression pool tamp limit & T-quencher load spec. W/o enci list of attendees & neeting handout. SU:T.M. Generic Issues Branch. 81/03/24. 3pp.
- Bi03310397 Forwards Buppl 2 to NUREO-0487, "Herk II Containment Lead Plant Program Evaluation & Acceptance Criteria." Deviations from criteria are to be documented in design assessment rept during F8AR review, W/o sncl. YOUNGBLOOD, B. J. Licensing Branch 1. Bi/03/26. 3an. 08099:308

PC Bafety Evaluation Report (SER), supply & correspondence

1320017 Informs that 801103 SER suppl is applicable until receipt of isponses to 1190 801170 & 810210 requests for addition or illist. The common of the com

DMANN S Assistant Director for Haterials & Qualifications of the strong 11/02/18 to 65050 143

2270182 Farwards branch SER input in resconse to ALAR-444, re status f unresolved safety issues affil. K. Generic (saves Branch, 81/02/18, 37op. 07846-285

3170215 Forwards SER for review Eighteen issues remain outstanding paolution of all open items required before OL issuance H/o acl. CESCO,R L. Assistant Director for Licensing. 81/03/09 2pp

2025 262

1230641 Forwards NUREG-0519.facility SER & notice of availability 1:NOD1.COD.8 J Licensing Branch | 81/03/13. 3pp 08030 CO1

03230648 Nutice of availability of NUREG-0519. facility 6ER

03230559 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE LA BALLE COUNTY BIATION UNITS 1 AND 2 Docket Nos. 50-373 and 50-374 (Commonwealth Edison Company) . Office of Nuclear Reactor Regulation. Director NUREO-0519 B1/03/31 300pp 08030:005

9230869 Discusses Ol hearing scheduling process BER technical input hedule for CYB1 & CYB2 anci NTON-H R Office of Nuclear Reactor Regulation, Director 1703/13 Spp. 07977-075

Becority, modical, emergency & fire protoction plans

DSOCSI Releases public version of util draft emergency plan PREG-0654 info encl CITON, J.M. Division of Rules and Records 80/12/02 18pp

01230943 Forwards public version of draft emergency plan for generating stations PEDPLES, D. L. Commonwealth Edison Co. 80/04/24 3pp. 04837:169

01000068 Public version of draft energency plan for generating stations.
• Cormonwealth Edison Co 80/07/31, 190ss

GB0003 Releases public version of util draft emergancy plants. 10N.J M. Division of Rules and Records. 80/12/03 ip

01220258 Forwards public version of util revised draft emergency plan #/station annexes
PEOPLES.D L. Commonwealth Edison Co 80/06/04. 2pp 05370:005

191989919 Public version of Revision 1 to draft emorgancy plan. • Commonwealth Edison Co 80/07/31 139pp

| OlCHO229 Public version of draft emergency plan annex • Commonwealth Edison Co. 80/07/31 SOpp. 07417:191.

3050583 Forwards security plan revision Revision withheld ef 100FR2 790) SEL,J.B. Commonwealth Edison Co. 1. 81/03/02 1p. 07826 273

3310338 Ltr to all licensees of operating plants & holders of CPs orwarding NUREO-0696. "Functional Criteria for Emergency seponse Facilities." Criteria describe acceptable method or meeting NRC requirements. U/o encl (SENHUT.D 0 Division of Licensing. B1/03/05. App.

32506B9 Releases public version of implementing procedures for nergency plan. ELTON-J M. Division of Rules and Records. 81/03/19. ip.

03250692 Forwards public version of emergency plan implementing procedures for corporate command ctr.environ director & plant-specific procedures.
DEL-9EORGE, L. D. Commonwealth Edison Co. 81/02/27. 2pp.

103250702 Public version of emergency plan implementing procedures for corporate command ctr.environ director & plant-specific procedures. Commonwealth Edison Co. 81/02/27. 1400pp.

K Utility Final Safety Analysis Report (FBAR) & amends

8103250397 Forwards Amend 55 to FSAR
DELGECROF, L. D. Componealth Edison Co. 81/03/19 1c 07997 170

-- 8103250400 Agend 55 to EBAR Commonwealth Edison Co 81/03/31 78:p 07997 171

G Inspection reports, IE Bulletins & correspondence

8103020115 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No unition response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 81/02/09 200

8103040249 Forwards IE Info Notice 81-03. "Checklist for Licensees Making Notifications of Bignificant Events In Accordance M/10CFR50 72." No written response required. MEPPLER, J. G. Region 3. Chicago, Office of the Director. 81/02/12 2pp. 97813.275.

8103030292 Forwards Suppl 5 to 1E Sulletin 80-17. "Failure of Control Rods to Insert During Scram at BHR " No written response REPPLER, J. O. Region 3. Chicago, Office of the Director 81/02/13 2an 07790 340

8103260072 Forwards IE Insp Repts 50-373/81-02 & 50-374/81-02 on 910112-14 at Reactor Controls, Inc. on 810113 at Earthquake Bioliz-14 at Reactor Controls inc. on Bioliz at Larthquake
Engineering Bus on Biolid at site & 8f0122-23 at Bargent &
Lundy No noncompliance noted
FIORELLI.9. Region 3. Chicago: Reactor Construction & Engineering
Bupport Branch. 81/02/13 2pp. 08041 243.

--8103260084 IE Insp Repts 50-373/81-02 & 50-374/81-02 on 810112-14,15, 17 & 22-23 No moncompilance noted Major areas inspected:RCI control drive sys suspension sys design control & QA program YIN. L. T VIN.I.T. Region 3. Chicago, Office of the Director.
DANIELBON.D.H. Region 3. Chicago, Reactor Construction &
Engineering Support Dranch. 81/02/12 7pp 08041:245.

8103250020 Forwards 1E Insp Repts 50-373/81-01 & 50-374/81-01 on 103290020 Forwards 12 Inap Repts 50-3/3/81-01 & 50-3/4/81-01 on B10107-08 No noncompliance noted. FIORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch. 81/02/17 2pp. 07998.260

--8103250023 IE Into Repts 50-373/81-01 & 50-374/81-01 on B10107-08 No loggoods it into kept 50-37-20-0. Solds and of the control length of the control length

Bi03060375 Requests snubber maint records be documented due to history of inoperable & incorrectly installed snubbers Preservice insp must be prerequisite for preoperational testing of snubber thermal motion TEDEBCO.R. L. Assistant Director for Licensing. 81/02/19. 3pp.

B103160494 Forwards IE Circular B1-03. "Inoperable Beismic Monitoring Instrumentation," No response required.
KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 81/03/02.

8103110375 Ack receipt of 810203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/80-48 & 50-374/80-30. Classification of 810129 meeting as enforcement conference & level of noncompliance unchanged KEPPLER, J O Region 3, Chicago, Office of the Director. 81/03/03. 2pp. 07873.313.

--Bi03i10390 Responds to NRC Bi0109 ltr re violations noted in IE Insp. Repts 50-373/80-48 & 50-374/80-30. Corrective actions: stop work order issued on B01III covering installation & insp. of safety-related control rad driveline piping supports. REED. C. Commonwealth Edison Co. B1/02/03 11pp. 07873:315.

BiO3160B94 Forwards revised IE Bulletin Bi-OI. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

KEPPLER. J. Q. Region 3, Chicago, Office of the Director. Bi/O3/04

8103200394 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required. KEPPLER, J. O. Region 3. Chicago. Office of the Director. 81/03/11.

03200695 Forwards IE Info Notice 81-05. "Degraced CC 84s at Paliades. "No action required KEPPLER, J. O. Region 3. Chicego. Office of the Director B1/03/13 2pp

03200269 Forwards IE Info Notice 81-07. "Potential Problem M/Mater-Boluble Purge Dam Hatls Used During Inert Gas Helding " No response required KEPPLER. J. G. Region 3. Chicago, Office of the Director 81/03/16 2n.

03261193 Responds to JE Bulletin BO-25. "Operating Problems W/Target Rock Safety Relief Vajves at BHRs: Engineering review of LeSalle safety relief valve pnewmatic supply sys still in grogress Mods will be completed prior to fuel loading RAUSCH-T J Commonwealth Edison Co B1/03/19 7pp

Periodic operating reports & related correspondence

03170463 Forwards "Fog & Rice Ice Monitoring Program Summary, 1980 " Data collected during operational phase unil be analyzed, interpreted & compared w/810123 draft ETS DELGEORGE, L D Commonwealth Edison Co 81/03/11 tp 07925 233

8103179468 "Fog & Rime Tce Monitoring Program Surmary-1780 " • Coemorwaalth Edison Co. 81/03/11 10pp. 07925-234

Reportable occurrences. LERs & related correspondence

03120562 Interim deficiency rept re insulator cracks on eposy module portion of Amphenol Bams electrical penetrations. initially reported on B01020 Tests on pre- & cost-crimped modules in progress Next rept by 810601
DELOCORDEL O Componwealth Edison Co 81/03/06 2pc 07901 348

Operator Examinations

OCIDIOTOR Forwards supplemental info re shift technical advisor training per NURSO-0737-litem 1 A.1 1.(3) info includes response to training requirements for shift control room engineers & projected accedule for training completion. ABEL.J.S. Commonosalth Edison Co. 81/02/24. 4pp

03030140 Forwards list of shift control room angineers meeting training & education requirements by dates indicated. Many engineers completed training by 810101. Target date for completion of training is sid-1981

ABEL.J.S. Commonwealth Edison Co. 81/02/24 4pp

O3200574 Forwards supplemental info re long-term shift technical advisor program, including candidate qualification, selection criteria, training plans & bases for phase-out of shift bechnical advisor program mendated by NUREO-0737
ASEL. J. B. Commonwealth Edison Co. 81/03/17 19pp.

CKET 50-375 NUCLEAR EXAMINATION REACTOR

Operating license stage documents & correspondence

O3160202 Forwards guidance re radiation levels for release of reactor facility to unrestricted access NRC agrees willcanses plans to dorse surveillance testing. In view of 800910 application to dismantia reactor REID.R.W. Operating Reactors Branch 4 81/02/27 3pp. 07918, 324

Inspection reports. IE Bulletins & correspondence

OGDROO27 Forwards IE Circular Bi-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required ENGELKEN, R.H. Region 5, Sen Francisco, Office of the Director. Bi/02/09. ip. 07/87:214.

OCKET 50-376 NORTH COAST NUCLEAR PLANT
Adjudicatory correspondence

O3110506 Request for reconsideration of ABLB B10218 order granting application withdrawal w/o prejudice. Applicant actions & clear lack of necessity for plant demand that dismissal be w/orejudice. Certificate of Bvc encl
FERNOS.O. Affiliation Unknown. B1/03/03 5pp. 07872:001

- 8103200743 Answer opposing O Fernos 810303 request for reconsideration of ASLB 810218 order granting withdrawal w/o prejudice of util application Also opposes request to stay decision No new info presented Certificate of Svc enci AXELRAD.M Puerta Rico Mater Resources Authority AXELRAD.M Lowenstein.Newman.Reis.Azelrad & Toll 81/03/12 4pp 07967 353
- 8103240387 Response apposing intervenots' 810303 petition for reconsideration of ASLB 810218 memorandum & order Requested relief is untirely & motion fails to set forth new grounds or errors not previously addressed Certificate of Suc enci

DOCKET 90-382 WATERFORD GENERATING BTATION, UNIT 3

A Application/construction stage documents & correspondence

- BIO3190732 Litrs to all licensoes of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NAREG-O612 Forwards NPC position re-interim actions & request for addl
- BIO31903B7 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown. replacement parts & NUREO-0737 EISENHUT.D. G. Division of Licensing 81/01/19 600
- 8103120014 Ltr to all licensees of operating plants.CP holders & CL applicants, except Indian Point 2 & 3,2 ton 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC B01222 request for addl infore control of heavy loads EISENHUT.D.O Division of Licensing. B1/02/03 6pp
- 8103190019 Notification of cancellation of B10224-27 meetings u/utit in Taft. LA to discuss drawings. power sys & instrumentation & control review questions
  KEBLUSEK-8. Licensing Branch 2 81/02/06 ip 07960 354
- B103040761 Advises that IE has requested that proservice inep & test requirements for snubbers be included in licensing process forwards requirements to ensure snubber operability. Fost program should be specified in amend to FSAR.

  TEDESCO.R L. Assistant Director for Licensing 81/02/11 App. 07810 119
- 8103050009 Summary of Bi0122 meeting w/util.Ebasco & Middle Bouth Byce for LOCA asymmetric load analysis NRC review will be based on C-E generic rept Attender list encl KBBLUBEK.S Licensing Branch 2 BI/02/11 5pp. 07828-004.
- 8103050968 Summary of Caseload Foretast Panel 810(13-19 meeting w/util in Taft.LA re status of const of facility. Agenda & list of attendees encl KEBUSEN.S Licensing Branch 2 81/02/13 lipp. 07828 181
- 8103050880 Forwards revised NRC Region 4 organization chart effective 810227. SEYFRIT-K.V. Region 4. Dallas, Office of the Director. 81/02/18 2pp. 07831.355.
- BIO3050128 Notification of BIO224 meeting w/util in Dethesda.MD to discuss questions re structural engineering.
  KEBLUSEX-S. Operating Reactors Branch 2. 81/02/20. Rpp 07897-001
- 8103090730 Requests addl info re OL application review. TEDESCO.R.L. Assistant Director for Licensing. 81/02/20 12pp 07844-104.
- 8103280024 Ltr to all power reactor licensees & license applicants re MUREO-0619 criteria. Footnote 2 in Table 2 centains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EIBENMUT.D. O Division of Licensing. 81/02/20. Bpp
- 8103120470 Notification of 810306 meeting w/util.EBASCO & Law Engineering in Bethesda MD to discuss seismology & geology of site. KEBLUSEX+B. Licensing Branch 2. 81/02/23 3pp. 07905.196.
- BIO3120726 Summary of BIO108 meeting w/util in Bethesde.MD reultimate heat sink for facility.List of attendes encl. KEBLUSEK.B. Licensing Branch 2 81/02/25. 4pp. 07904:330.

- 810323000 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISEL+UT. D 0 Division of Licensing 81/02/25 Spp.
- BLO3040498 Advises that util will furnish environ qualification data for safety-related electrical equipment by 820108.in response to IRC 801125 ltr MAURINL V. Louisiana Power & Light Co 81/02/26 lp 07815-289
- 8(03)10208 Forwards Round 2 requests for add1 info re OL application review repaired. 8 1 Assistant Director for Licensian BI/02/24 110
- 8103230813 Deneric Ltr 81-06 to all CP holders & O\_ applicants re 10CFR90 71(a), "Periodic Updating of FGAKs," effective 80D722 Info re FBAR legal status format % content encl EISEMHUT, D. O. Division of Licensing 81/02/26 10pp
- 9103030908 Forwards package of 18 diesel generator control wiring diagrams Also forwards 37 oversize control wiring diagrams Drawings withheld (ref 10CFR2 790)

  NOFER.9 0 Leuisiana Power & Light Co. 81/02/27 ip 07833 002
- 8103110235 Forwards Round 2 Requests 281 1-6 for addl info re OL application review Response should be submitted by 810403 TECESCO.R L. Assistant Director for Licensing 81/02/27 4pp 07684 195
- 8103110239 Forwards Round 2 requests for add1 info re OL application review Requests are numbered 030 9-43
  TEPESCR L. Assistant Director for Licensine 81/02/28 14cc
- BIOG160447 Requests cooperation in accelerated review of Pacility. w/ plan for BER publication in May NRC rust receive necessary info by Bio417
  TEDESCO.R.L. Assistant Director for Licensing B1/02/28 2pp 07914-202
- 8103110742 Forwards second round questions re add1 info for CL review. TEDESCOR L. Assistant Director for Licensing 81/03/03. 2pp 07872-328
- --8103110746 Second Round Questions 0040, 126 through 0040, 147 redisel generator automatic start signal # Power Systems Branch, 81703703 ijpp. 07872 330
- B103t60176 Forwards Geosciences Branch Round 2 request for addigeologic info-to-complete review of CL application TEDESCOR L Assistant Director for Licensing. 81/03/05 9pp 07919-354
- B103170311 Forwards Amend 16 to application for OL-containing Amend 16 to FSAR ASUALL.S L Louisiana Power & Light Co 81/03/05. 1p. 07922 066
- --BIO3170914 Amend 16 to application for OL.containing Amend 16 to FBAR # Louitians Power & Light Co. 81/03/05. 2pp. 07922:067
- Bi03200087 Informs that staff functions of Region 4 reassigned, effective Bi0227. GL Madsen. Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondence re reactor const & operation activities.

  SEYPRIT. K. V. Region 4. Dallas, Office of the Director. BI/03/09, ip. 07968-217.
- 8103170538 Notifies that emergency operating procedures re LOCA. Inadequate core cooling, steam generator tube rupture & loss of feeduater until be submitted by 810731. Addl time is needed to address issues being discussed by CE owners group MAJRIN:L.V. Louisiane Power & Light Co. 81/03/10. 2pp. 07930: 127.
- B103310804 Ltr to all licensees of operating plants, applicants for OLS 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.
  E1SELHOUT, D. Q. Division of Licensing 81/03/10 6pp.
- SIGMI70619 Forwards Amend 1 to OL application Amend includes supporting financial documentation ABMELL.D.L. Louisians Power & Light Co B1/03/12 2pp 07925.314.
- --B103170623 Application for Amend 1 to OL application ASHELL-D. L. joulsian+ Power & Light Co. B1/03/12 App. 07925-316

- --8103170627 Annual Financial Rest 1979

   Louisiana Power & Light Co 80/02/15 29pp 07928 319
- 8103190145 Notification of 810316 meeting u/near-term CL applicants Bethesda MD reinfo required to be submitted on environ qualification of electrical equipment prior to site visit & NRC review BURNELLS Licensing Branch 2 81/03/12 13pp
- BIO3190310 Notification of BIO326 meeting u/util in Taft.LA to visit auxiliary feedwater reliability study site KEALUBEK.S Licensing Branch 2 81/03/12 300. 07954 304
- 8103240046 Egruards flow diagrams & instrument drawings in support of MRC containment isolation sys review. Aperture cards available in PRR HART. J. WITTICH. W. Louisiana Power & Light Co. 81/03/17 ip. 65142.062
- B103250405 Forwards FSAR Chapter 11, per B10305 request for add1 info Remaining Info for containment sys review will be forwarded by B10331. N/o enc1 KEBLUSEK-S Licensing Branch 2 B1/03/17 1p 07997 269.
- 8]03230401 Advises of corrections to numbering of questions forwards in NRC 810305 ltr. Questions 362.1 2 362.2 should be numbered 362 6 & 362 7 REBUSEK: S. Licensing Branch 2 61/03/18 1p 07997 272.
- 8103300183 Notification of 810414-16 meeting w/util re instrumentation of trustral drawing review & discussion of Round 2 questions.

  KEBLUSEK.B. Licensing Branch 2 81/03/18 3pp. 08053 133
- 8103240357 Forwards info re facility FBAR relative to CEDMs FOFER © 0 Louisiana Power & Light Co. 81/03/19. 18pp
- 8103260373 Forwards 'Response to FEAR Question 110 1/Asymmetric Loads in answer to question & requests discussed during B10122 meeting w/KRC Major items identified in subsequent 810211 minutes addressed Rept available in CF only.
  MAURIN.L V Louisiana Power & Light Co. B1/03/23 6pp 08022-046.
- 8103260373 Forwards "Response to FBAR Guestion 110 1/Asymmetric Load in answer to question & requeste discussed during 810122 meeting w/NRC. Hajor items identified in subsequent 810211 minutes addressed Rept available in CF only HAMRIN.L V Louisiana Power & Light Co. 81/03/23. 3pp
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 8103200689 Requests info for SER & supplemental SER two wks prior to SER date indicated on encl schedule Requests four months prior to SER issuance equipment qualification info per IE Bulletin 79-018 for SERs scheduled after June 1981.
  DENTON, HR Office of Nuclear Reactor Regulation, Director 81/03/13 app. 07966:106
- 8103200451 Notification of 810331 meeting w/util Battelle Columbus Le ORNL.C-E & EDBASCO in Bethesda-MD to discuss remaining open items in Mechanical Engineering Branch draft safety evaluation.

  MEBLUSEN,S. Licensing Branch 2 81/03/16. 3pp 07966.351.
- F Security, medical, emergency & fire protection plans
- BIO3160105 Forwards request for add1 info re fire protection review. TEDESCO.R L. Assistant Director for Licensing. 81/02/25 8pp.
- B103130065 Forwards request for add1 info re fire protection.
  TEDEBCO.R.L. Assistant Director for Licensing 81/02/26. 8pp.
- B103120748 Summary of 810107 meeting w/util in Bethesda,MD to discus physical security plan. Attendance list encl. KEBLUSEK/8. Licensing Branch 2. B1/02/27. 4pp. 07909:307
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements. W/o encl. EISENNUT. D. Q. Division of Licensing. 81/03/05. App.
- B103230270 Forwards revised request for add1 info re fire protection (Question 040, 148).
  TEDESCO.R L. Assistant Director for Licensing B1/03/10. Upp. 07975:004

- B103230642 Forwards 12 gversije drawings for fire protection review.per R Prados request Aperture cards are available in PDR HART, J. HITTICH.W. Louisjana Power & Light Co. B1/03/17 2pp. 07994 049
- G Adjudicatory correspondence
- 8103030635 Forwards annual repts for 1979 & addl financial info per biRC 810205 request Testinony of JM Erwin-PM Loviselle-RJ Lurito & LA Public Svc Commission Order Uni4078 Formal responses to be submitted via Amend 16 by 810309

  ASMELLO L Lovisians Power & Light Co 81/02/27 303pp 02833 012
- --Bloggoda'9 LA Public Sec Commission Order U-14078 permiting increase in electric rates
  POWELL T.E. KENNOW.E. SCHWEGMARW.T. Louisiana. State of 79/12/18 | Lopp. 07830-027
- I Financial information
- B103030635 Forwards annual repts for 1979 & add1 financial info per NRC B10205 request Testimony of JH Erwin. 8M Loviselle. RJ Lurito & LA Public Buc Commission Order U-14078 Formal responses to be submitted via Amend 16 by 810309.

  ASMELL. D. & Louisiane Power & Light Co. 81/02/27 305pp 02830 012
- --8103030839 LA Public Svc Commission Order U=14078 permiting increase in electric rates. POHELL, T.E., KENNON, E., BCHWEGMANN, T. Louisiana, State of 79/12/18 16pp. 07830:327
- --B103030645 Direct testimony & exhibits of JH Erwin. ERHIN.J H. Louisiana Power & Light Co. 80/05/26 104pp ORBJ 442
- --B103030690 Testinony & exhibits of BH Louiselle ng fair rate of return before Public Svc Commission of Statz of LA. LOUISELLE, B H Kosh, Louiselle, Lurito & Associates, Inc 79/10/31. Epp. 07831.083
- --BI03030695 Testimony & exhibits of RJ Lurito pe fair rate of return before Public Svc Commission of State of LA LURITO.R. J. Kosh. Louisello. Lurito & Associates.inc. 79/10/31. 134pp 97831:169.
- 8103170619 Forwards Amend 1 to OL application. Amend includes supporting financial documentation.

  ABNELLO L Louisiana Power & Light Co 81/03/12 2pp. 07729.314
- --B103170627 Annual Financial Rept 1979.

  \* Louisiane Power & Light Co. 80/02/15. 29pp. 07925.319
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8103170511 Forwards Amend #6 to application for DL, containing Amend 16 to FSAR.
  ASNELL-0 L Louisiana Power & Light Co. 81/03/05 ip. 07922.066.
- --8103170914 Amend 16 to application for OL, containing Amend 16 to FSAR \* Louisiana Power & Light Co. 81703/05 20p 07922 067.
- --8103170516 Amend 16 to FBAR.
   Louisiane Power & Light Co. 81/03/05. 200pp. 07922:070
- 8103200747 Certificate of Bvc for FBAR Amend 16 on 810316 BANDINI:E. Louisiana Power & Light Co. B1/03/16 1p. 07967-362
- G Inspection reports. IE Bulletins & correspondence
- 8103230201 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No Malcolm valve parts in use.

  MAURIN.L.V. Louisiana Power & Light Co. 81/01/02. 19 07977.039.
- 8103090090 Forwards IE Inop Rept 50-382/80-36 on 801216-19. No noncompliance noted. SEIOLE-W C. Region 4. Dallas. Reactor Construction & Engineering Support Branch. 81/01/09. 2pp. 07827: 268.
- --BI03050096 IE Imag Rept 50-382/80-36 on 801216-19, No noncompliance noted Hajor areas inspected const activities re followup review of proviously identified unresolved items & GA/GC

- Bi03050592 Forwards IE Insp Rept 50-382/80-34 on B01116-1215 N noncompliance noted rADSEN.9 L Region 4. Dallas. Reactor Operations Nuclear Su Branch B1/01/12 2pp 07829-095
- --Bi03030598 IE Insp Rept 90-382/80-34 on B01116-1215 No nonco noted Major areas inspected operational staffing overall preoperational test program 5 plant rours CONSTABLE O. C., DUGOLS D. C., WESTERMAN T. F. Region 4. Del Office of the Director 81/01/09 3p. 07829 097
- Q103230221 Responds to IE Bulletin BO-23. 'Failures of Bolenoi Mfg by Valcor Engineering Corp " No Valcor valves w/cited part numbers are used to perform safety-related functions MAURIN.L V Louisiana Power & Light Co 81/01/23 1p 07
- BiO3230175 Forwards |E Insp Rept 50-382/80-35 on 801216-810115 noncompliance noted HADSEN O L Region 4 Dallas, Reactur Operations Nuclear Su Branch 81/01/28 2pp. 07980 281
- ~-B103230187 IE Insp Rept 50-382/80-35 on 801216-810115 No non noted Major areas (inspected overall preoperational test program & plant tour. CONSTABLE,O L., WESTERMAN.T F Region 4, Dallas. Office o Director 81/01/27 2pp 07980 203
- B103190008 Discusses caseload forecast panel meeting at const B10112-19 & forwards IE Mgt Meeting Rept 50-302/B1-01 BEIDLE:N C. Region 4: Dalias: Reactor Construction & Engine Support Branch. 81/01/30 1p 07962-350
- --B103190012 IE Mgt Heeting 30-382/Bi-Oi on B10112-15 Major ar discussed const schedule design & engineering procurerent activities craft work force & test procedures STEMARIAR C. CROSSMAN.H A. Region 4. Dallas. Office of t Director 81/01/27 App. 07462 351
- B103040761 Advises that IE has requested that preservice insprequences for shubbers be included in licensing process Forwards requirements to ensure shubber operability. Test program should be specified in amend to FSAR TEDESCO.R L. Assistant Director for Licensing 81/02/11
- 8103160634 Forwards IE Info Notice 81-04. "Cracking in Main St Lines" No response required. BEYFRITAY V. Region 4. Dallas. Office of the Director 81/ 10. J7917 089
- BIO0170007 Forwards 1E Circular BI-03, "Inoperable Beismic Mor Instrumentation." No response required. BEYFRIT.K V. Region 4. Dallas, Office of the Director Bio Ip. 07929-105
- 8103160832 Forwards revised IE Bulletin B1-01. "Burveillance of Mechanical Enubbers." w/corrected Pages 5 & 6 Change in identification of Patilities w/CPs to which bulletin is applicable does not affect util requirements BEYFRITAK. Region 4. Dallas. Office of the Director. 81/10. 07914-189
- 8103160295 forwards preservice examination sycs bid peckage Prinsp will be performed for 4 months beginning Nov 1981 Response to Question 121 2 will be forwarded in near future. Encl in Central Files only COBTELLO. J NRC No Detailed Affiliation Given 81/03/12 07914:001.
- BIO3230186 Forwards IE Info Notice 81-07. "Potential Problem M/Water-Soluble Purge Dam Matls Used During Inert Gas Welding." No response required.

  SEYFRIT.K V. Region 4. Dellas. Office of the Director. 81/10. 07977:231
- 8 Reportable occurrences, LERs & rolated correspondence
- 8103040707 Interim Deficiency Rept 17 originally reported on 0 base metal defects in main a stoam & residuate containment penetration anchors. Eristing cracks being repaired. Lug & stiffener joint welding procedures to be modified. ASHELLD. L. MILHISER. R. J., WILLS. J. Louisiana Power & Light 102/27. 4pp. 07812:255.
- B103130417 Interim Deficiency Rept 22 originally reported on a inadequate electrical inequation on encore neutron flux detectors. Corrective action mode to be provided after reworld category that the submitted by B10731.

## DOCKETED ITEMS

```
A107310870 Interio Stanificant Const Deficiency Rept 22 re inacequate
   electrical insulation on ex-core neutron flux detectors Mode provised by C-E via Field Action Request 105W Final rept bu
   010731
   ASLELL.D.L. Louisiana Power & Light Co. 81/03/06 4pp
8103240378 Interim deficiency rept (Significant Const Deficiency 25) re
OF Circuit Breakers ARR-30 % ARR-50 failure to close OE will
   supply parts & technical supervision to replace bearing assemblies Final rept will be submitted on 811130 ASHELL.D.L. Louisiana Power & Light Co. 81/03/16 4pg
                                                                                     406 07990 191
8:m9240433 PRO-IV-81-009 on 810317, eight const workers arrested for
   cessession & sale of cartijuana No OA/OC personnel involved
GTELNAT.R C. (FDDSTALN A Region 4. Dallas. Diffice of the
Birector 81/03/18 tp 07981-347
T Haaring transcripts on non-antitrust matters
8103030b35 Forwards annual repts for 1979 & addl financial info per NRC glo205 request Testicony of JH Erwin.DM Louiselle-RJ Lurito L LA Public Svc Commission Order V-14078 Formal responses to
   be submitted via Amend 16 by 810309
ASHELL D L. Louisiana Power & Light Co 81/02/27 305pg
   27870 DID
--8103030645 Direct testimony & exhibits of JH Erwin
ERNIN-J H. Louisiana Power & Light Co 80/05/26
                                                                                                                               910320
                                                                                      10400
      07930 342.
                                                                                                                               07835 230
~~BI03030650 Testimonu & eshibits of BM Louiselle re fair rate of return
      Sefere Public Svc Commission of State of LA
LOUISELLE. B M Kosh. Louiselle. Lurito & Associates. Inc.
79/10/31 Bdpp 07831 003
--8103020655 Testimony & exhibits of RJ Lurito re fair rate of return
before Public Svc Commission of State of LA
LURITO.R J Kosh, Louiselle, Lurito & Associates, Inc. 79/10/31
134pp 07831 169
                                                                                                                               CURTIS, N W
                                                                                                                              07030 011
U Congressional/Executive Correspondence
8103240991 Forwards fourth monthly status rept to Congress for
   810115-0218 Rept discusses actions taken on licensing
   revious of new facilities Rept will be amended to include addl info requested on 810217

KAMMERER.C. Office of Congressional Affairs 81/02/27 3pp
8163270110 Responds to request for rept on possible add1 improvements
   to NRC licensing process Legislation allowing interim
operations in advance of hearing completion would reduce
  Seley in licensing process
(ENDRIE.J. M. Commissioners 81/03/12 Spp.
--B103270931 Submits recommendations to expedite impacted DL hearings
      Code should include set of TMI-related CL requirements ABLAB
      decisions on fuel loading & low power testing should be immediately effective.

BICANITAL Office of the General Counsel 81/02/23. 10pp.
V Operator Examinations
B103190318 Summary of $10107 meeting u/util in Dethesda.MD re operator training program.Plan judged acceptable Applicant advised to submit educational proposals as app Plan to be submitted by
   mid-Har [98].
   KEBLUSEK, S Licensing Branch 2 81/03/10 4pp. 07954:313
DOCKET 99-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1
A Application/construction stage documents & correspondence
8103190732 Ltrs to all licensees of operating plants, applicants for
  OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interim actions & request for addlines.
   EISENMUTED 0 Division of Licensing. 80/12/22. 30pp.
```

8103190387 Ltr to all licensees of operating plants & applicants for

CLs & holders of CPs re program for environ qualification of sefety-related electrical equipment ltems addressed involve cold shutdown replacement parts & NUREQ-0737.
EISENHUT. D G Division of Licensing 8/01/19. dep.

- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3.7ion | & 2 & THI-1, forwarding inadvertently unitted pages from NRC 801222 request for additation of control of heavy loads
  EISENHULD O Division of Licensia B1/02/03 600 BIODO30985 Notification of BIO225 meeting w/util in Bethesda.HD to discuss presentation & review of 1980 archeological survey STARK-R M Licensing Branch 1 81/02/12 3pp 07795 234 8103050951 Notification of 810311 & 12 meeting w/Mark II owners grou & GE in Bethesda, MD to discuss Mark II generic long-term ANDERSON-C J Generic Issues Branch 81/02/12 | 1200 07828 195 8103030093 Notification of 810227 meeting w/vtil in Bethesda.MD to discuss util responses to staff questions STARK.R M. Licensing Branch 1 81/02/17 3pp. 07791 203. 8103050234 Notification of 810227 meeting w/util in Bethesda.MD to discuss responses to NRC questions STARK-R M Licensing Branch 1 81/02/17 300 07832 205 BIO3060507 Forwards request for addl info re core performance mails ( QA for QL application review Response should be submitted by TEDESCO.R.L. Assistant Director for Licensing. 81/02/20 13pp Bio3290024 Ltr to all power reactor licensees & license applicants re NURCO-0619 criteria. Footnote 2 in Table 2 contains applied to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller. EISENNIT.D 0 Division of Licensing 81/02/20 Bpp 8103040273 Forwards "Balance of Plant & NSSS SORT Forms for NRC Selected Equipment," which completes presite visit package. Pennsylvania Power & Light Co 81/02/25. Ip. B103110439 Notification of 810306 meeting w/util in Bethesda.MD to discuss compliance w/General Design Criteria-91 STARK.R.M Licensing Branch 1 B1/02/23 3pp 07070:221 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement energency procedures. EISENNUI.D O Division of Licensing 01/02/23 Spp BIO3:70225 Lir to all BHR licensees (escept Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping safe ends & fitting met! per quidelines of encl Revision i to NUREO-0313 Model Tech Specs only encl EISENHUT, D O. Division of Litensing 81/02/28. 3pp --BIO3170266 Model Tech Space Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-6 surveillance requirements for ABME Code Class 1.2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements.

  # Jeneral Electric Co. Bi/02/26 4pp 8103170655 Ltr to holders of CPs & applicants for GLs (BMRs) requesting of ASME Class 1.2 % 3 pressure boundary piping, safe ands & fitting math per guidelines of encl Revision 1 to NUREC-0313 Model Tech Spece only encl. EISENHUT-D C. Division of Licensing 81/02/26. 3pp. B103230813 Generic Ltr 81-06 to all CP holders & OL applicants re IGGFR80.71(a), "Periodic Updating of FBARs," effective B00722 Info re FBAR legal status, fornat & content encl. EIBERHUT.D O. Division of Licensing. 81/02/26. 10pp. BIO3020410 Forwards Amend 30 to application for OLs.containing Revision 21 to FBAR CURTIS N. H. Pennsylvania Power & Light Co. 81/02/27. 1p. --- 8103020425 Amend 30 to application for OLs. containing Revision 21
- 8103030769 Forwards util responses re performance of human factors review Annunciators.controls & displays described

CURTIS, N. W. Pennsylvania Power & Light Co. 81/02/23. 1p.

FBAR

07783 112.

331 for Units 1 & 2. respectively, in response to util 123 request. ENHUT.D 0. Division of Licensing 81/02/28 3pp 07915-211

3160763 Deder extending const completion dates to 821231 & 840331 or Units 1 & 2. respectively 1868-07.D.O. Division of Licensing 81/02/28 2pp 07915 214

G160770 Evaluation of util 810123 request for extension of ompletion dates for CPPR-101 & CPPR-102 Extension granted until 821231 & 830331 for Units 1 & 2, respectively Division of Licensing 81702/28 2pp 07915:216.

990619 Forwards info re Category I masonry walls employed by plants ler CP & DL review in response to NRC BC0420 request ginel reply was enci in B00908 ltr. TIB.N.4 Pennsylvania Power & Light Co B1/03/03. 18pp

144 329.

00424 Notification of 810309-10 resting w/util in Bethesda.MD to New App 9 compliance & containment isolation for Hilties

RK.R.M Licensing Branch 1 81/03/03 3nn 07864-215

3060) Notification of BiO313 maeting w/Mark II owners group in heads MD to discuss Mark II safety relief valve loads & 11 temp limits.

General Issues Branch 81/03/03 2pp 07912 136

09368 Forwards B Went B10220 ltr re review of archaejogical-tion of facility regt. in response to NRC request NTIS.N.W. Ponnsylvania Power & Light Co. 81/03/04 2pp 65: 194

00523 Forwards draft symptom based procedures per NURE9-0737.Item .B requirement. ITIS.N W. Pennsylvania Power & Light Co. 81/03/04 44pp

53:105

30421 Forwards documents re facility seismic-hydrodynamic program qualification of safety-related equipment.per NRC qualification of safety-related equipment.per NRC qualification Review maste audit scheduled for 810316-20 qualification Review maste audit scheduled for 810316-20 qualification 49pp

70794 Notification of 810318 meeting w/otil in Washington DC to icuss facility licensing schedule. RK.R M. Licensing Branch 1 81/03/09. 3pp 07927.358

90143 Notification of 810316 meeting w/near-term OL applicants in heads. ND re-info required to be submitted on environ lification of electrical equipment prior to site visit &

Treview WELL, B. Licensing Branch 2 81/03/12 15pp.

230013 Notification of time change for 810318 meeting w/util in thington, DC to discuss licensing schedula RK.R.H. Licensing Brench 1. 81/03/13. 3pp 07980, 302

80894 Forwards final response to TMI-related requirements. pressing all requirements of NUREO-0737 & answering NRC 9220 request for info Die oversized drawing encl. 1718.N.M. Pennsylvania Power & Light Co. 61/03/16. 150pp. 91,213

00444 Forwards Buppl 2 to NUREQ-0487. "Mart 1% Containment Lead NOTE Program Load Evaluation & Acceptance Criteria & icontainment in Program Load Evaluation & Acceptance Criteria & icq issue paper. Buggests Mar 1981 meeting w/Mark II lers to discuss review program. W/o encl EL.K. Generic Issues Branch. 81/03/16. 1p 65134:218

30347 Forwards request for addl info re structural engineering let responses to be submitted by 810320 liberal Birector for Licensing. 81/03/16. 3pp. 173:007.

BOII4 Forwards responses to questions 123.1 - 123.9 per 810202 | pest for add1 info. Info will be incorporated into next | ision of facility FBAR. | ITIS.N.W. Pennsylvania Power & Light Co. 81/03/17. 25pp.

45:053.

MOD25 Notification of B10326 meeting w/util in Bethesda.MD to cust until wish to appeal six staff positions restainment Bys Branch review

RK.R.M Licensing Branch L. 81/03/18 3pp. 07983:357.

review osit interview items re personnel training matrix, support operations procedures & schedules & mgt presentation handouts Encl available in Central Files only CURTIS.N W Pennsylvania Power & Light Co 81/03/20 3pp 08022 002

- 810326116D Forwards request for add1 info to radiological assessment.
  Requests final responses by 810327
  TEDESCO.R.L. Assistant Director for Licensing 81/03/23 4pp CB040 230
- 8103270711 Forwards technical basis for facility compliance to General IUJZ/V/II Forwards tecnnical basis for facility compliance to Design Criterion 51 re containment pressure boundary includes info re lowest sec netal temp.ferritic matis & suppression chamber access hatch & dry well head flange CURTIS.N M. Pennsylvania Power & Light Co. 81/03/24 50pp
- 8103300314 Advises of Status of Phase II environ qualification rept loggious and the services of the services of the class of the class of the control of the contro CURTIS N W Pennsylvania Power & Light Co 81/03/24. 2pp 08055 136
- 8103310833 Surnary of 810313 meeting ofotil in Bethasda MD re FSAR Chapter 14 BTARK.R M Licensing Granch 1 81/03/24 3pp 08062 164
- B103270341 Forwards proprietery version of LNC Nuclear Industries, Inc topical rept. Vol. II re solid radwaste solidification Rept uithheld (ref 10CFR2 790) CURTIS N. Pennsylvania Power & Light Co. 81/03/29. Ip 08043 043
- 8103270538 Advises that environs associated w/high energy line breaks & impact on Class IE equipment will be addressed in rept to be submitted 810410 CURTIBIN W Pennsylvania Power & Light Co. 81/03/29, 1p 08043:042
- 0103270621 Confirms position that ATMS recirculation purp trip fix is being installed u/redundant safety grade trips prior to fuel load Design details will be available for review during third quarter 1991 CURTIEN.K Pennsylvania Power & Light Co 81/03/25. Ip 08043 15B
- 8:03270669 Advises that sufficient interlocks are available to COSTIGNATION HOUSES that survicient interlocif are available trastrict RPA & core spray pump starting per NRC instrumentation & control Concern 2.8HR & core spray interlocks bypassed by jumpers when Unit 2 is under const. CURTIS.M.W. Pennsylvania Power & Light Co. 81/03/23 1p.
- B103270686 Forwards util response to FSAR Questions 230 5,230.6 & 1032/0000 remarks will response to rain questions 200 3.000.0
  230 7.Units will not be operated in natural circulation mode or wionly one recirculation pump in aperation Stability analysis will be performed for second cycle
  CURTIS.N.M. Pennsylvania Power & Light Co. 81/03/25 4pp 08046: 321
- 8103270731 Requests that Footnote 31 to Table 3 2 1 be revised to read-"sys & components so designated conform to Quality Group D (augmented) including selemic requirements as defined in NRC Branch Technical Position ETBS 11-1 Parts 8 4 & 8.5." CURTIS-N H Pennsylvania Power & Light Co 81/03/25. 1p 08043: 313.
- 8103270737 Confirms that loose parts monitoring sys will be installed to operational at time of fuel load.

  CURTIS:N W. Pennsylvania Power & Light Co 81/03/25. 1p. 08043: 314
- B103270742 Confirms that HPCI sys automatically restarts on low water lavel after manual shutdown CURTIB.N. 4. Pennsylvania Power & Light Co. 81/03/25. ip
- 8103270799 Forwards draft Revision A to "Process Control Program for Radwaste Bolidification Bys." Requests review & comments. CURTIS.N W. Pennsylvania Power & Light Co. 81/03/25. 1p. 08045:079.
- --8103270802 Draft Revision A to "Process Control Program for Radwaste Solidification Sus. Pennsylvania Power & Light Co. 81/02/27 14pp. 06045:080

- 81Q3310566 Forwards revised responses to Questions 32.7 & 32.24 of FSAR CLOTIS,N.W. Pennsylvania Power & Light Co. 81/03/25 3pp 08043 601
- 810330382 Forwards repts. 'Archaelogical Investigations at Susquehanna Steam Electric Station. Pond Hill Resevoir Site' & "Archaeclogical Investigations" re flood plains Repts available in Central Files only CURTIS.N W Pennsylvania Power & Light Co 81/03/26 lp
- 81033(0462 informs of corrections to RCPB matls FSAR Table 9 2-4 re ferritic matls 3 austenetic stainless steel. CLRTIS.N W Pennsylvania Power & Light Co 81/03/26 2pp GSAR 233
- 81-03316496 Responds to NRC concerns re-undervaltage protection when grid is between 19% & 95% of rated voltage Renoving LOCA permissive from 278 9 & 4 relays will result in trip regardless of LOCA signal condition CURTIES.N W Pennsylvania Power & Light Co 81/03/26 Ip 08059, 204
- 9109310501 Confirms verbal commitment to air test feedwater peretration CURTIS-N W Pennsylvania Power & Light Co 81/03/26 ip CRASS 203
- 8103310532 Forwards Tech Spec Section 3 8 3 3 re thermal overload protection during accident conditions Also forwards two overtile Crawings.per ARC request U/o Tech Spec Aperture cards are available in PDR CURTIS N # Pennsylvania Power & Light Co 81/03/26 ip O8662 105
- 8103310431 Advises that response to THI requirements provided In Ltr PLA-659 Util position meets requirements of HUREG-0737. CURTIS-N W Pennsylvania Power & Light Co 01/03/27 ip 08062 323
- B103310437 Clerifies response to 0211 295 Any leak into ECCB pump room from suppression pool will be contained by pump room walls. Pump room water level at max will level out w/suppression pool water level. CURTIS-NS Pennsylvania Power & Light Co. B1/03/27. Ip 08042 324
- 8103310454 Forwards RHR Drawings BB96-E-153 Sheets 2.4.6.8.47.49.91 \$ 53 re RRR LPCI pump interlocks Alter forwards GE Drawings 79164494J. Sheets 3 & 4 re CS interlocks 11/0 drawings CVR18.N H Pennsylvania Power & Light Co. 81/03/27 1p 58039 271
- BiO3310480 Forwards response to NRC BiO323 request for addl info re Questions 331 16.17.18 % 19 concerning FBAR CURTIS.N W Pennsylvania Power & Light Co. Bi/O3/27. 40pp O6379 001
- BIO33:0528 Forwards comparison of LaBalle & Susquehanna of mar-Class IE from Class IE control & instrument circuits LaBalle compliance based on SER. Busquehanna compliance taken from FSAR Page B 1-16 CWRIBS.N. Pennsylvania Power & Light Co. 81/03/27 2pp 08063 008
- D PRC Draft/Final Environmental Statements, supply & correspondence
- B103693671 Forwards draft suppl to DES (NUREG-0564) as requested W/a encl STARA.R M. Licensing Branch 1. 81/02/25. 19 07844.280
- E NRC Bafaty Evaluation Report (SER), supple & correspondence
- 8103060534 Requests add1 SER info re outstanding questions, incomplete responses & final fire protoction rept Info should be submitted by 810320 for inclusion in SER TEDESCO.R L. Assistant Director for Licensing 81/02/20 3pp. 07832:209
- ©103230009 Notification of B10317 meeting w/util in Bethosda.MD to discuss all Mechanical Engineering Branch issues before issuence of BER input to licensing STANK.R M Licensing Branch 1 B1/03/12 3pp. 07980.294.

- B103290571 Responds to B1022D request Vertification of operability of security sys not required prior to issuance of SER Design of sys evaluated in SER & verification of operability & completion is audited prior to fuel load CURTIES.N W Pennsylvania Power & Light Co B1/03/13 ip
- 8103230866 Discusses D. hearing scheduling process SER technical in schedule for CYB1 & CYB2 encl DENION-H R Office of Nuclear Reactor Regulation. Director 81/03/13 5pp 07977 104
- Bi03270657 Notifies that reanalysis of pressure transients described SER for ODYN will be submitted by June 1981 CURTIB.N W Pennsylvania Power & Light Co 81/03/25 ip CR047-101
- F Security, medical, emergency & fire protection plans
- 8103130218 Notification of 810311 & 12 meetings u/util in Beruick, P. review fire protection made & followup to previous fire protection review STARKER M Licensing Branch 1. 81/02/23 3pp 07908 345
- 8103310338 Ltr to all licensees of operating plants & holders of CP forwarding NuREG-0696, "Functional Criteria for Emergency Response Facilities 'Criteria describe acceptable method for meeting fRC requirements U/o encl EISENHUT. D O Division of Licensing. 81/03/05 6pp
- Bi03230315 Notification of Bi0329-R6 reeting w/util in Bethesda,MD of discuss Facility emergency plan & proparedness.
  BIARK.R M Licensing Branch I. 81/03/13 3pp 07973-015
- 8103310511 Forwards marked-up copy of proposed revision to emergency plans, reflecting util response to NRC commonts. Revision util be submitted as amend to application as soon as possible. Who encl CURTIB.N U Pennsylvania Power & Light Co 81/03/26 lp 08059-201

## G. Adjudicatory correspondence

- 8103040574 Memorandum & order granting NRC Bi0130 rotion Citizens Against Nuclear Dangers & Environ Coalition on Nuclear Power directed to respond to NRC & applicants' outstanding interrogatories by Bi0327.

  BECHMORECR.C. Atomic Sefety and Licensing Board Panel. Bi/02/27. App. 07016.345
- 8103110463 Petition to intervene in proceeding re spent fuel pools 8 request for hearing ECHULTZ.O A Susquehanna Environmental Advocates 81/03/02 2pp 07872-020
- 81031303B5 Request to compal discovery from intervenors Susquehanna Environ Advocates. Environ Coalition on Nuclear Pour & Citizans Against Nuclear Danger on Contention 6 re emergency plan Certificate of Svc encl SILBERO. J Pennsylvania Pourr & Light Co. BILBERO. J Allegheny Electric Cooperative. Inc. BILBERO. J Bhau. Pittman. Potts & Trowbridge 81/03/03 Asp. 07911-165.
- B103090674 Bubmits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties

  CHRIGHENBURY. E. Hearings Division. 81/03/04. 2pp.
- 8103200751 Motion for summary disposition of Contention 12 No genuin issue of matl fact to be heard & applicants entitled to favorable decision as a matter of law.

  SILBERO, J. E. Pennsylvania Power & Light Co. SILBERO, J. E. Bhaw. Pittman, Potte & Troubridge. 81703/09. 2pp. 07968:001.
- --8103200737 Statement of not1 facts that there is no genuino issue heard re Contention 12 SILBERG J.E. Pennsylvania Power & Light Co. BILBERG J.E. Shau Pittman, Potts & Troubridge. 81/03/09. 4pp 07968.003
- --Bi03200763 Affidavit that facility design does not violeta NRC std creats unreatanable risk to public Alleged problem of flow induced vibrations in core-creating in-vessel sparger failurs, does not exist Certificate of Byc encl WATANABE.H I General Electric Co. WATANABE.H.T. Pennsylvania Power & Light Co. 81/02/24. 8pp. 07968:007.
- 8103260735 Answers of Busquehanne Environ Advocates to interrogetor: on emergency plan & new contentions.Related correspondence. SCHULT2-Q R. Busquehanna Environmental Advocates. B1/03/13 [1]

- individed Memorandum & order granting applicants' motion for summary disposition of Contention 16 Partial disposition granted to extent Contention 2 involves chlorination to counteract upstreem releases BECHMOEFER.C. PARIS.D M., SRIGHT.C D. At Board Panel 81/03/16 21pp. 07963 326. Atomic Bafety and Litensing
- B103R607B6 Response in apposition to NAC 810130 mation to compet Intervenue & tu ASLS 610302 merorandum on sare sub; Intervenues are relating on as yet unpublished documents for info.FEB.SER & FSAR must be published W/Certificate of 8vc HALLIQAN, T. J. Citizens Against Nuclear Danzers 81/03/16 42c 190 45000
- 8103230635 Notice of ASLB reconstitution up Gleason, chairman & 60 Bright & PW Purdom members. COTTER, B. P. Atomic Safety and Licensing Board Panel 81/03/19 07974 113

## 1 Financial information

- B103110389 Forwards request for addi info re util finance Response requested by Bio327
  TEDESCO.R L. Assistant Director for Licensino B1/03/04 Fco 07884: 129
- 8103270734 Responds to NRC 800304 request for financial info. Info. Info. Including Allegheny Electric Cooperative data forwarded to J Peterson Addi copy will be forwarded by 810403 CURTIB, N. W. Pennsylvania Power & Light Co. 81/03/25 to. 08047 209
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8103020410 Forwards Arend 30 to application for DLs.containing Revision 21 to FSAR.
  CURTIS.N N Pennsulvania Power & Light Co. 81/02/27 10
- -8103020425 Amend 30 to application for Ols. containing Revision 21 to CURTIS N. H. Pennsylvania Power & Light Co. 81/02/23 1p. 07783 112
- --B103020429 Revision 21 to FBAR

   Pennsylvania Power & Light Co 81/02/28 80pp 02783 [13
- 8103230429 Forwards Revision 22 to FSAR CURTIS, N. W. Pennsylvenia Power & Light Co. 81/03/20 Ip 07975:111
- --8103230437 Revision 22 to FSAR \* Pennsylvania Pouer & Light Co. 81/03/20 169pp. 07975:112
- P Operating license stage documents & correspondence
- B100310804 Etr to all licensees of operating plants applicants for Olis & holders of CPs forwarding SECY-B1-119 re info necessary to astablish environ qualification of safety-related electrical EISENHUT. D. Q Division of Licensing. 81/03/10 App.
- G Inspection reports. IE Bulletins & correspondence
- 8103050803 Forwards [E Insp Repts 50-387/80-33 & 50-388/80-20 on B01201-11 No noncompliance noted CARLSOV, R. T. Region I. Philadelphia. Reactor Construction & Engineering Bupport Branch. B1/01/06 2pp. 07828: 138
- --8103050812 1E Inep Rept 50-387/80-33 & 50-388/80-20 on 801201-11. No noncompliance noted. Major areas inspected. OC activities reinstallation of instrumentation sys & performance of preservice.

adelohia.

7. No

Nuclear

ROILIZ-14 & 17 No nencompliance noted.

SMITH.O H Region 1. Philadelphia. Fuel Facility & Materials

Granch 81/02/04 2pp 07875 342

- --8103110546 [E Insp Repts 90-987/80-30 t 50-338/80-18 on B01112 No noncompliance noted Major areas Inspected environ protection programs including mot controls & verification of inclementation of CP requirements
  JACKSON, T. SAKENAS, C.A. Region 1. Philadelphia. Office of
  Director BORES, R.J. Region I. Philadelphia. Fuel Facility Materials Safety Branch 81/02/03 600 07876 344
- 9303230631 Responds further to 1E Bulletin 90-21. "Melve Yoles 6 by Halcolm Foundry Co. Inc." Confirmation that no subjustive parts in use other than those previously identified expected. bu 810314 CURTIBIL Pennsylvania Power & Light Co B1/02/11 2pp 07975 028
- 8103230842 Responds to IE Bulletin 79-26. "Boron Loss From BWR C Blades " Exposure history will be recorded to determine Blo depletion in each control blade Shutdown margin tosts will be conducted per Tech Spec requirements CURTIBIN H Pennsylvania Pozer & Light Co. 81/02/11 2pr 07979 030
- 8103100097 Confirms 810226 mgt meeting at facility to discuss Ni assessment of regulatory performance re const No response required. Agenda enc l ORIER. 6 H Region I. Philadelphia. Office of the Director. 81/02/12 2pp 07866 005
- 8103030386 Forwards Suppl 5 to IE Bulletin 80-17. "Failure of Co Rods to Insert During Scram at BWR" No written response recuired GRIER, B.H. Region 1. Philadelphia, Diffice of the Director 81/02/13 ip 07808 230
- 8)03200201 Forwards IE Circular 81-03. "Inoperable Beismic Monit Instrumentation" No written response required. CRIER.B H. Region 1. Philadelphia. Office of the Director 81/03/02. 19 07966 193
- B103200023 Forwards revised IE Sulletin B1-01. "Surveillance of Hechanical Bnubbers." w/corrected Pages 5 % 6 Util is added to CP facilities to which bulletin is applicable Response should include estimate of manpower espended ORIGE. O. H. Region L. Philadelphia, Office of the Director 81/03/04 pp. 07968 183
- 8103200170 Forwards IE Info Notice 81-06. "Failure of ITE Model Circuit Breaker " No response required ORIER.8 H. Region 1. Philadelphia, Office of the Director. 81/03/11 1p 07968-304
- 8103230819 Forwards inservice insp program for pumps & valves & piping & instrument diagrams which show Class 1,2,3 & nancode safety sumps & valves Aperture cards will be available in PDR CURTIS, N. H. Pennsylvania Power & Light Co. 81/03/20 33pp 07991:005
- --8103230834 Inservice insp program for pumps & valves.
  \* Pennsylvania Power & Light Co. 81/03/20. 96pp. 07991 0
- 8103310914 Swmmary of 810313 meeting w/Mark II buners group re suppression pool temp limit & I-quencher load spec W/o enci-list of ettendees & meeting handout. SULT M. Generic Issues Branch. 81/03/24 3pp
- B103270713 Responds to IE Builetin 80-07. "BWR Jet Pump Assemble Failure" & 0112-10 BWR/4 beams, as presently designed & installed, are predicted to have longer life. Beams will be inspected periodically as part of inservice insp program. CURTIS.N W. Pennsylvania Power & Light Co. 81/03/25 2pp. 00045-109. 08045:105
- S Reportable occurrences, LERs & related correspondence
- 8103100181 Ack receipt of 810116 interim deficiency rept re Sta silding links.
  CARLBON.R.T. Region to Philadelphia. Reactor Construction & Engineering Bupport Branch. 81/02/03 tp. 07865:333.
- --BiO3100192 Interim rept re potentially significant deficiency Co sliding limitially reported 800623. Bechtel has concluded initial sampling insp. Sampling results will be evaluated Final rept expected by May 1981. CURTIB.N.W Pennsylvania Power & Light Co. 81/01/16. 2pp 07865: 334

- grounded flexible conduit
  CARLSCHAR T Region 1. Philadelphia. Reactor Construction &
  Engineering Sucport Grant 81/02/05 10 07963 200
- BIO310G2RB Ack receipt of B10122 final deficiency rept re unauthorized welding of attachment to reactor pressure vessel CARLSGN.R. I Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B1/02/06 ip 07863 198
- 8103270331 Act receipt of 810210 final deficiency rapt re excessive cvality of small clareter pipe CARLEGONR T Region 1. Philadelphia. Reactor Construction & Fortneering Support Branch 81/02/23 lp 08034-067
- 830333C050 Ack receipt of 810211 final deficiency rept re GE timing relack Final rept on Agastat relays due May 1981 CAMEDONR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch G1/02/23 1p 08053 040
- 8:0303C812 Final deficiency rept re Anchor-Darling valve yoke crackinginitially reported on 800707 Anchor-Darling replacing affected parts wyrlority given to Unit 1 Replacement scheduled for completion by May 1981 CURTIS-N W Pennsylvania Power & Light Co 81/02/26 3pp. 03794-163
- BIO30904C8 Status update of deficiency releasaive voltage drops in power & control circuits initially reported 801020 Partial stop Lork on Unit 2 cable installation for affected circuits implemented Final rept will be submitted in May 1981 CARTISIN N Pennsylvania Power & Light Co. 81/03/02. 4pp. 07836 209
- 8)03)0643 Interim deficiency rept re pipe supports welded to containment liner plate Resolution of deficiency is more complex than originally anticipated Final rept in May 1981 CLATIS:N.W. Pennsylvania Power & Light Co. 81/03/06 2pp. 67855-217
- BiO3:10702 Btatus update of deficiency rept.originally reported on BiO529.re gipe supports welded to containment liner plate Bethtel advised util that resolution more complex than craginally thought Final rept will be evailable by May 1981. CARTIS.N.4 Pennsylvania Power & Light Co. B1/03/06 2pp. crass nest
- 81C3231091 Part 2: rept re déficiency of Pacific swing check valves. Initially reported 810119 Hold tags placed on valves. Investigation initiated final rept scheduled for May 1981 CMRIB.N M. Pennsylvania Power & Light Co. 81/03/11 Spp.
- U Congressional/Executive Correspondence
- 8163270110 Responds to request for rept on possible add1 improvements to ARC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process 1608REC 4 Commissioners 81/03/12 5pp
- --8:03270931 Submits recommendations to expedite impacted OL hearings.
  Code should include set of TMI-related OL requirements ABLAS decisions on fuel loading & low power testing should be immediately effective
  BICKMIT.L. Office of the General Counsel 81/02/23 10pp
- --8103270947 Submits recommendations re scheduling, personnel resources & hearing npt for OL proceedings. Panel must obtain exemption from hiring freeze for two recently appointed chairmen COTIER. B P Atomic Safety and Licensing Board Panel. 81/02/25. 33cp.
- COCKET 90-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

  A. Application/construction stage documents 8 correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs recontrol of heavy loads. Requests review per guidelines in NUREO-Ob12 Forwards NRC position reinterim actions & request for addl info EISENHUT, D. O. Division of Licensing. 80/12/22. 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737.
  EISENHUT.D 9. Division of Licensing. 81/01/19 6pp.

- applicants.ercept indian Point 2 t 3,710n 1 t 2 t Mi-1, forwarding inadvertently unitted pages from NRC 801222 request for add info re control of heavy loads EISE/HVUT.D 0 Division of Licensing 81/02/03 App
- BIO3030985 Notification of 810225 meeting w/util in Bethesda.MD to discuss presentation 6 feview of 1980 archeological survey of site STARK.R M. Licensing Branch I. 81/02/12 3pc 07793-234
- B103050991 Notification of 810311 & 12 meeting c/Mark II comers gro & GE in Bethesda.MD to discuss Mark II generic long-term program ANDERSON.C J. Generic Issues Branch. 81/02/12 1200
- B103030003 Notification of 810227 meeting w/util in Dethesda.MD to discuss util responses to staff questions STARK.R M Licensing Branch 1 B1/02/17 3pp 07791.203
- 8103090234 Notification of 810227 meeting w/wtil in Bethesda.MD to discuss responses to NRC questions. 8TARK.R.M. Licensing Branch i 81/02/17 3pp 07832 205
- 8103060507 Forwards request for add1 info re core performance.matls QA for QL application review Response should be submitted by 310320
  TEDESCO.R L Assistant Director for Licensing 81/02/20 13pp 07835 230
- 8103250024 Ltr to all power reactor licensees & license applicants of MUREO-0619 triteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENNUT.D.D. Division of Licensing. 81/02/20 9pp
- 8103040273 Forwards 'Baiance of Plant & NGSS SORT Forms for NRC Selected Equipment," chich completes presite visit package. CURTIS:N W Pennsylvania Power & Light Co. 81/02/25. 1p. 03202-011
- Biogito439 Notification of Biogo6 meeting w/util in Bethesda.MO to discuss compliance w/General Design Criteria-Si. STARK.R M. Licensing Branch I. 81/02/25 3pp. 07070.221
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for O., (except 8t Lucie, Units 1 t 2). Requests util review to determine capability to nitigate station blackout event & promptly implement energency procedures EISENHUT. D 9 Division of Licensing. 81/02/25 Spp
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of AEME Code Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision 1 to NUREG-0313 Model Tech Specs only encl EISEGHUF D 9. Division of Licensing, 81/02/26 3pp.
- --BiO3170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4surveillance requirements for ABME Code Class I.2 % 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements a General Electric Co Bi/02/26 4pp.
- 8103170655 Ltr to holders of CPs & applicants for DLs (BWRs) request review of AGME Class 1.2 % 3 pressure boundary piping, safe ends & fitting mail per guidelines of encl Revision 1 to NUREO-0313 Model Tech Epecs only encl.

  EISENHUT.D.O Division of Licensing. 81/02/26. 3pp.
- 8303230813 Generic Ltr B1-06 to all CP holders & OL applicants re 10CFRS0 71(e), "Periodic Updating of FBARs." effective 800722 Info re FBAR legal status, format & content encl EISEPHUT.D O. Division of Licensing. B1/02/26.
- 8103020410 Forwards Amend 30 to application for Cis.containing Revision 21 to FSAR CURTISN W Pennsylvania Power & Light Co 81/02/27. 1p.
- 8103030769 Forwards util responses re performance of human factors review Annunciators, controls & displays described.
  CURTIS-N W. Pennsylvania Power & Light Co. 81/02/27. 26pp.
  07788-347.
- 8103160760 Forwards order extending const completion dates to 821231 840331 for Units 1 & 2, respectively, in response to util 810123 request. EISENNUT.D 0 Division of Licensing 81/02/28 3pp. 07915.211.

- --8103160763 Order extending const completion dates to 821231 & 840231 for Units 1 & 2. respectively EISE/MUT, D 0 Division of Licensing 91/02/28 2pp 07913 214
- --8103160770 Evaluation of util 810123 request for extension of completion dates for CPPR-101 & CPPR-102 Extension granted until 821231 & 830331 for Units 1 & 2-respectively blivision of Licensing. 81/02/28 2pp. 07715 216
- 8103090615 Forwards info to Category I hasbory dails employed by plants under CP & CL review in mesponse to NRC 800420 request Original reply was entl in 800908 ltm CURTIS.N N. Pennsylvania Power & Light Co 81/03/03 1892
- Bj03100424 Natification of B10309-10 meeting w/util in Bethesda. HD to review App O compliance & containment isolation for facilities. BTARM.R M Licensing Branch 1 B1/03/03 3pp 07864 219
- Bi03:30601 Notification of Bi03:3 meeting w/Mart II cuners group in Bethesda. MD to discuss Mark II eafety relief valve loads & pool terp limits
  SULT. M. Generic issues Branch 8:1/03/03 2pp
- 8103100368 Forwards 8 .ent 810220 ltr re review of archaelogical section of facility rept. in response to NRC request CURTIS.N W Pennsylvania Poter & Light Co 81/03/04 2pp 07844-194
- BIO3100523 Forwards dreft symptom based procedures per NUREC-0737. Item 1 C. 8 requirement CURTIS.N W. Pennsylvania Power & Light Co. 81/03/04 44pp 07833 10A
- B103130421 Forwards documents to Pacifity seismic-hydrodynamic program for qualification of safety-related equipment.per NRC request Documents will support Seismic Qualification Review Team site audit scheduled for B10316-20 CMSTSN W Pennsulvania Power & Liaht Co 81/03/09 49pp
- 8103170754 Notification of 810318 meeting w/util in Washington DC to discuss facility licensing schedule STARKER M Licensing Branch 1 81/03/09 3pp 07927.358
- 8103190145 Notification of B10316 meeting w/near-term OL applicants in Bethesda. MD re info required to be submitted on anviron qualification of electrical equipment prior to site visit & NRC review
  BURWELL. 8 Licensing Branch 2 81/03/12 15pp
- 8103230013 Notification of time change for 910318 meeting w/utll in Washington, DC to discuss licensing schedule STARK.R. H. Licensing Brench 1 81/03/13 3pp 07980 302
- B103180394 Forwards final response to TMI-related requirements, addressing all requirements of NUREO-0737 & answering NRC 810220 request for info.One oversized drawing encl. CURTIB:N W Pennsylvania Power & Light Co. 81/03/16 190pp 07951:213
- B103200444 Forwards Suppl 2 to NUREQ-0487. "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper, Suggests Har 1981 meeting u/Mark II comers to discuss review program W/o encl. KNIEL/K. Generic Issues Branch 81/03/16 1p 65134-216
- @103230347 Forwards request for add1 info re structural engineering Final responses to be submitted by 810320 TEDESCO.R.L. Assistant Director for Licensing 81/03/16. 3pp. 07973:007
- 8103180114 Forwards responses to questions 123 1 123 9 per 810202 request for add1 info info will be incorporated into next revision of facility FBAR.

  CURTIS.N.M. Pennsylvania Power & Light Co. 81/03/17 29;p. 07948-053.
- B103240825 Notification of B10326 meeting w/util in Bethesda. MD to discuse until wish to appeal six staff positions re-Containment Sys Branch review. BTARK, R. M. Licensing Branch I. 81/03/18 3pp. 07983:357.
- Bi03240436 Forwards responses to NRC request for documentation of mgt review exit interview items re personnel training matrix, support operations procedures & schedules & mgt presentation handouts. Enci available in Central Files only CURTIS.N W. Pennsylvania Pawer & Light Co. B1/03/20 3pp 08022.002

- BIO3241160 Forwards request for add1 info re radiological assessment Requests final responses by BIO327 TEDESCO.R E. Assistant Director for Licensing BI/O3/23 App ADDAD 270
- B103270711 Forwards technical basis for facility compliance to Deneral Design Chiterion 51 ne containment pressure boundary Includes into re lowest svc metal temp. Ferritic matis & suppression charber access hatch & dry well head flange CVRTIS.ALM Pennsylvania Pouer & Light Co. B1/03/24 50pp
- B103300314 Advises of status of Phase II environ qualification rept for Class IE equipment Items requiring resolution include qualification status of NSSS components & support program Re-evaluation will be forwarded CURTIS.N N Pennsylvania Power & Light Co 81/03/24 2pp 08055 136
- 8103310893 Summary of B10213 recting u/util in Sethesda.MD re F3A9 Chapter 14 STARKA M Licensing Smanch 1 81/03/24 3pp 08062 164
- 8103310914 Summary of 810313 meeting u/Mark II owners group re suppression pool temp 1(nit & T-quencher load spec W/o encl list of attendees & meeting handout SU,T M Generic Issues Branch 81/03/24 3pp
- 8103270341 Forwards proprietary version of UNC Nuclear Industries. Inc topical rept. Vol II re solid radwaste solidification Rept withheld iref 10CFR2 7901 CURTIS.N W. Pennsylvania Power & Light Co. 81/03/25 ip opens 043
- B100270538 Advises that environs associated w/high energy line breaks & impact on Class IE equipment will be addressed in rept to be submitted B10410 CURTIG.N W Pennsylvania Power & Light Co 81/03/25 (p 08043 042
- 8103270621 Confirms position that ATMS rectrculation pump trip fix is being installed wiredundant safety grade trips, prior to fuel load Design details will be available for review during third quarter 1981 CURTIS.N M. Pennsylvania Power 5 Light Co. 81/03/25 ip cand 3 158
- B103270668 Advises that sufficient interlocks are available to restrict RHR & core spray pump starting per NRC instrumentation & control Concern 2 RHR & core spray interlocks bypassed by jumpers when Unit 2 is under const CURTIB-N H Pennsylvania Power & Light Co 81/03/25 ip 08043 164
- 8103270686 Forwards util response to FBAR Questions 230 9,230 6 \$ 230 7. Units will not be operated in natural circulation mode or w/only one recirculation purp in operation Stability analysis will be performed for second cycle. CURTIB.N W Pennsylvanja Power & Light Co. 81/03/25 4pp 08046-321.
- B103270731 Requests that Footnote 31 to Table 3 2 1 be revised to read "sys & components so designated conform to Quality Group D (augmented) including seismic requirements as defined in MRC Branch Technical Position ETSB 11-1 Parts B 4 & B 5 " CUQTIB-N W Pennsylvania Power & Light Co 81/03/25 1p. ppo43-313
- B103270737 Confirms that loose parts routtoring sys will be installed toperational at time of Puel load CURTIS-N-W. Pennsylvania Power & Light Co. 81/03/29 lp 08043-314
- B103270742 Confirms that HPCI sys automatically restarts on low water lavel after manual shutdown CURTIS N.W Pennsylvania Power & Light Co. B1/03/25 lp. 08043.165
- \$103270799 Forwards draft Revision A to "Process Control Program for Radwaste Solidification Sys " Requests review & comments CURTIS:N W Pennsylvania Power & Light Co. 81/03/25 ip 08045:079.
- --BIO3270802 Draft Revision A to "Process Control Program for Radwaste Bolidification Sys." \* Pennsylvania Power & Light Co 81/02/27, 14pp 08045-080.
- 8103310566 Forwards revised responses to Questions 32.7 & 32 24 of FBAR.
  CURTIS.N.W Pennsylvania Power & Light Co. 81/03/25 3pp.
  CB0A3.001.

etration TITE:N W Pennsylvania Power & Light Co. 81/03/26 ip 559-203

310502 Forwards Tech Spec Section 3 8 3 3 re thermal overload station during accident conditions Also forwards two presise drawings, per NRC request, II/o Tech Spec Aperture distance available in PDR.
TIGN W. Pennsylvania Power & Light Co. 81/03/26 ip. 262-106

- 310431 Advises that response to TMI requirements provided in • PLA-699 Util position meets requirements of NUREO-0737 3719.N U Pennsylvenia Power & Light Co 81/03/27 ip 362-383
- 010437 Clerifies response to G211 295 Any leak into ECC9 pump room
  in suppression pool will be contained by pump room walls
  by room vater level at has will level out u/suppression
  it uater level
  itid.N.W. Pennsylvania Power & Light Co. 81/03/27 ip
  MS2 324

810434 Forwards RHR Drawings 0856-E-153 Sheets 2,4.6,8,47,49,51 & re RHR LPCT pump interlocks Also forwards 0E Drawings E419MJ Sheets 3.4 i re 05 interlocks M/a drawings IE165N.W Pennsylvania Power & Light Co. 81/03/27 1p 359 291.

010460 Forwards response to NRC B10323 request for addl info resistions 331. 16.17.18 & 19 concerning FBAR HIJGN W. Pennsylvania Power & Light Co. 81/03/27 40pp 179.001

- 010&E0 Forwards comparison of LaBalle & Susquehanna of --Class IE from Class IE control & instrument circuits Balle compliance based on SER Susquehanna compliance taken in FBAR Page 6:1-16 IFIG.N.U. Pennsylvania Power & Light Co. 81/03/27 2pp. ASS 008.
- C Draft/Final Environmental Statements, supple & correspondence
- 990871 Forwards draft suppl to DES (NUREG-0964), as requested tencl. GRK-R H Licensing Branch 1. 81/02/25 ip 07844 280
- C Bafety Evaluation Report (SER), suppls & correspondence
- 4053) Requests addl SER info re outstanding questions incomplete panses & final fire protection rept Info should be mitted by 810320 for inclusion in SER (ESCO.R.L. Assistant Director for Licensing. 81/02/20 Jpp. 132-209
- 30009 Notification of 810319 meeting w/util in Bethesda.HD to cuss all Mechanical Engineering Branch issues before wance of BER input to licensing. RK.R.M. Licensing Branch 1 81/03/12. 3pp 07980:294
- OC571 Responds to BIO220 request. Verification of operability of unity sys not required prior to issuance of BER Design eys well-united by the BER & verification of operability & pletion is audited prior to fuel load.

  fiB.N.H. Pennsylvania Power & Light Co. B1/03/13. [p. 72.083]

- forwarding NUREG-08/6. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT, D. O Division of Licensing. BI/03/05 App
- 8103230315 Notification of 810325-26 meeting w/util in Bethesde.MD to discuss facility energency plan & preparedness STARK.R M Licensing Branch 1 81/03/13 3pp 07973 015
- 8103310511 Forwards marked-up copy of proposed revision to emergency plan-reflecting util response to NRC comments Revision will be submitted as amend to application as soon as possible W/o enci CURTIB.N W Penissivania Power & Light Co 81/03/26 lp 08057 201.
- O Adjudicatory correspondence
- 8103040374 Memorandum & order granting NRC 810130 motion Citizens Against Nuclear Dangers & Environ Coalition on Nuclear Power directed to respond to NRC & applicants' outstanding interrogatories by 810327 BECHNOEFER.C. Atomic Sofety and Licensing Board Panel 81/02/27 4pp 07816 343
- BIO3130385 Request to compel discovery from intervenors Susquehanna Environ Advocates, Environ Coalition on Nuclear Power & Citizens Against Nuclear Danger on Contention & re-emergency plan Certificate of Svc encl
  SILBERO, J. Pennsylvania Power & Light Co. SILBERO, J. Allegheny Flectric Cooperative. Inc. SILBERO, J. Shaw. Pittman. Potts & Trowbridge 81/03/03 &pp. 07911.165
- 8103090674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or more parties.

  CHRISTENBURY.E. Hearings Division B1/03/04 2pp.
- 8103200751 Motion for surnery disposition of Contention 12.No genuine issue of matl fact to be heard & applicants entitled to favorable decision as a matter of lau SILBERG. J. E. Pennsylvania Power & Light Co. SILBERG. J E. Shaw. Pittman. Potts & Troubridge 81/03/09 2pp 07768.001.
- --Bi03200797 Statement of mat) facts that there is no genuine issue to be heard re Contention 12 BILBERG.JE Pennsylvania Power & Light Co. BILBERG.JE Shaw. Pittman. Potts & Trowbridge 81/03/09 4pp. 07968:003
- --Bi00200763 Affidavit that facility design does not violate NRC stds or create unreasonable risk to public Alleged problem of flouinduced vibrations in conscreating in-vessel sparger failure does not exist Certificate of Svc encl. HATANABE.H T. General Electric Co MATANABE.H T. Pennsylvania Power & Light Co 81/02/24 8pp 07968-007.
- 8103260735 Answers of Susquehanna Environ Advocates to interrogatories on emergency plan & new contentions Related correspondence.

  8CHULTS-2.R. Susquehanna Environmental Advocates 81/03/13 11pp.
- 8103;90632 Memorandum & order granting applicants' motion for summary disposition of Contention 16 Partial disposition granted to extent Contention 2 involves chlorination to counteract upstream releases BECHHOEFER.C. PARIS.O N. BRIGHT.O.O. Atomic Safety and Licensing Board Panel 81/03/16 21pp. 07963 326

- BiO3260786 Response in opposition to IRC BiO130 notion to compet discovery & to ASLB BiO302 menorandum on same subj. Intervenors are relying on as yet unpublished documents for info FES.SER & FBAR must be published W/Centificate of Syc HALLIOAN T. J. Citizens Against Nuclear Dangers. Bi/03/16. App. 08038-091
- Bi03230635 Notice of ASL9 reconstitution JP Gleason.chairman & GO Bright & PH Purdom.members COTTER.B.P Atomic Safety and Licensing Board Panel 81/03/19 2pp. 07974 113

#### I Financial information

- 8103110389 Forwards request for addl into relutil finance Response requested by 810327 TEDESCO.R.L. Assistant Director for Licensing 81/03/04 9pp 07884-129
- 8103270734 Responds to NRC 800304 request for financial info Info. Including Allegheny Electric Competative data forwarded to J Peterson Addi copy will be forwarded by 910403 CURTIS.N W Pennsylvania Power & Light Co 81/03/25 ip 00042 200
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8:03020410 Forwards Anend 30 to application for Ouscontaining Revision 21 to FBAR CURTIB-N W Pennsylvania Power & Light Co 8:/02/27 tp 07783 1:1
- --8103020425 Amend 30 to application for DLs.containing Revision 21 to FBAR CURTIS.N.W Pennsylvania Power & Light Co 81/02/23 ip 02783-112
- --8103020429 Revision 21 to F8A9 + Pennsylvania Power & Light Co. 81/02/2B. 80pp 07783 113
- 103230429 Forwards Revision 22 to FSA9 CURTIS:N W Pennsylvania Power & Light Co DI/03/20 ip 07975 111
- -8103230437 Revision 22 to FBAR

   Pennsylvania Power & Light Co 81/03/20 169pp 07975-112.
- P Operating license stage documents & correspondence
- B103310804 Ltr to all licensees of operating plants, applicants for DLs & holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical aquipment EIBENHUT-D G. Division of Licensing 81/03/10 6pp
- Q Inspection reports. IE Bulletins & correspondence
- B103050803 Forwards IE Insp Repts 30-387/80-33 & 50-388/80-20 on B01201-11. No nancompliance noted. CARLSDN-R T. Region I. Philadelphia. Reactor Construction & Engineering Support Branch B1/01/06 2pp 07928:138
- --8103050812 IE Insp Rept 50-387/80-33 & 50-398/80-20 on 601201-11 No noncompliance noted. Major areas inspected GC activities reinstallation of instrumentation sys & performance of preservice insp
  NARROWLL MCBREARTY.R.A. PADLING.R.J. Region 1. Philadelphia. Office of the Director. 81/01/05. 14pp 07828:140
- B103110544 Forwards IE Insp Repts 50-387/80-30 & 50-388/80-18 on 801112-14 & 17. No noncompliance noted. SMITH.Q.H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch B1/02/04 2pp 07876:342.
- --8103110546 IE lnsp Repts 50-387/80-30 & 50-388/80-18 on 801112-14 & 17 No moncorpilance noted Major areas inspected environ protection programs including regt controls & verification of implementation of CP requirements.

  JACKBON T., SAKENAS C. A. Region 1. Philadelphia, Diffice of the Director. BORES R J. Region 1. Philadelphia, Fuel Facility & Materials Sefety Brench. 81/02/03. 6pp. 07876-344
- 8103230831 Responds further to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co.Inc." Confirmation that no subjected parts in use other than those previously identified expected by 810316 CURTIS.N W. Pennsylvania Power & Light Co. 81/02/11. 2pp. 07975.028.

- 8103233042 Responds to 1E Bulletin 79-26. 'Doron Lass From BMR Control Biades 'Esposure history will be recorded to determine Bio depletion in each control blade Shutdoun margin tests will be conducted per Teth Spec requirements CURTIS.NM Pennsylvania Power & Light Co. 81/02/11 2pp 07975-039
- B103100097 Confirms B10226 mpt meeting at facility to discuss ARC assessment of regulatory performance re coust No response required Agenda enci ORIER.B H Region t. Philadelphia. Office of the Director B1/02/12 2p 07866 005
- Bi03030386 Forwards Suppl 5 to 1E Bulletin 80-17, "failure of Control Rads to Insert During Scram et SiR 'No written response required GRIER.G H Region 1. Philadelphia, Office of the Director 81/02/13 1p 07808 230
- B103200201 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation" No written response required ORIER,B H. Region 1. Philadetphia. Office of the Director B1/03/02 1p 07966 193
- Bi03200105 Farwards revised IE Builetin Bi-01. "Burveillance of Mechanical Shubbers." u/corrected Pages 5 & 6 Change in identification of facilities u/CP to which bulletin is applicable does not affect util requirements GRIER, B H Region I. Philadelphia. Office of the Director Bi/03/94 to 07969 058
- 8103200170 Forwards IE Info Notice 81-06. 'Faijure of ITE Model K-673 Circuit Breaker " No response required GRIER B H Region I. Philadelphia. Office of the Director 81/03/11 10 07968 304
- --8103230834 Inservice this program for pumps & valves
  \* Pennsulvania Power & Light Co B1/03/20 94pp 07991 006
- B103270713 Responds to IE Bulletin 80-07. TRUR Jet Pump Assembly Failure" & 3112 10 BWR/4 beams as presently designed & installed are predicted to have longer life. Beams will be inspected periodically as part of inservice Insp program CURTIS.N W Pennsylvania Power & Light Co 81/03/25 2pp CB045 109
- S Reportable occurrences. LERs & related correspondence
- B103100181 Ack receipt of 810116 interim deficiency rept re States Co slicing links CARLSDN-R T. Region 1- Philadelphia, Reactor Construction & Engineering Support Branch 81/02/03 ip 07865 333
- --BiG3100192 Interim rept re potentially significant deficiency of State Co sliding link-initially reported B90623 Bechtel has concluded initial sampling insp Bampling results will be evaluated. Final rept expected by May 1981.

  CURTIS.N W Pennsylvania Power & Light Co 81/01/16 2pp 0785-334
- Bi03100278 Act receipt of Bi0114 interim deficiency rept re improperly grounded flexible conduit. CARLSON.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 81/02/05 ip 07863.200
- 9103270331 Ack receipt of 910210 final deficiency rept re excessive ovality of small diameter pipe CARLSON R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch Bi/02/23 ip 08034 067.
- 8103300050 Ack receipt of 810211 final deficiency rept re GE timing relays. Final rept on Agastat relays due May 1981 CARLSGUR. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 81/02/23 1p. 08053 040.
- 8103030812 Final deficiency rept re Anchor-Darling valve yake cracking. initially reported on 800707 Anchor-Darling replacing affected parts w/priority given to Unit 1.Replacement scheduled for completion by Kay 1981.

  CURTIS-N.M. Pennsylvania Power & Light Co 81/02/26 Spp 07796.163.

- 8103090408 Status update of deficiency re-excessive voltage drops in paper & control circuits initially reported 801020 Partial stop work on Unit 2 catte installation for affected circuits irplemented Final rept will be submitted in May 1981 CUTTIBIN W Pennsylvania Power & Light Co 81/03/02 App 02853 209
- 9:03100443 Interim deficiency rept re pipe supports welded to containment liner plate Resolution of deficiency is more complex than originally anticipated final rept in May 1991 CURTISIN Pennsylvania Power & Light Co 81/03/06 2pp nyos 217
- 81031:0702 Status update of deficiency rept.originally reported on B1027-re pipe supports welded to containment liner plate Eachtel advised util that resolution more copplex than criginally thought final rept util be available by May 1981 CURTIS.N W. Pennsylvania Power & Light Co. 81/03/06. 2pp CR85 679
- 8103231091 Part 21 rept to deficiency of Pacific swing check valves, initially reported 810119 Hold tags placed on valves (overtigation initiated Final rept scheduled for May 1981 CURTIS-N W Pennsylvania Power & Light Co
- ♥ Congressional/Executive Currespondence
- 8103270110 Responds to request for rept on possible addl improvements to NRC litersing process Legislation allowing interim operations in advance of hearing completion would reduce delay in literating process (SUNRELUM Oramissioners 81/03/12 Soc.
- --5103270931 Submits recommendations to especite impacted OL hearings Code should include set of TMI-related OL requirements ASLAB decisions on feel loading & low power testing should be immediately effective.

  31CMINITY. Office of the General Counsel 01/02/23. 100p
- --8103270947 Submits recommendations re scheduling, personnel resources & hearing most for CL proceedings Panel must obtain exemption from Jiring freeze for two recently appointed chairmen COTTER B P Atomic Safety and Licensing Doard Panel 81/02/25
- SCCKET 53-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8:03:190732 Ltrs to all licensees of operating plants.applicants for OLs & holders of CPs to control of heavy loads. Requests review per guidelines in NUREG-O612. Forwards NRC position reliterin ectsons & request for addl info E15ENHUT-D O Division of Licensino 80/12/22 30pp.
- 830115D319 Discusses followup study re degradation of internal appurtenances in LHR piping during normal plant operation & potential effects when degraded appurtenances are subj to accident loads Recommends broad review of recurrent problems BROWN.E J Director's Office 80/12/24 4pp.
- BIO3190397 Ltr to all licensees of operating plants & applicants for DAs & holders of CPs re program for environ qualification of sefty-related electrical aquipment. Items addressed Invaive cold shutdown.replacement parts & NUREO-0737 EISENHUF, D Q Division of Licensing BIO/1/19 App
- BiO3120014 Etr to all licensees of operating plants, CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads EISENHUT, D Q. Division of Licensing. 81/02/03. App.
- 8103160669 Ltr to all operating plants & CP holders forwarding clanification of TMI Action Plan Item III A 12 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation dates upli be met EISENHUT.D O Division of Licensing. 81/02/18 12pp.
- 8103290024 Ltr to all power reactor licensees & license applicants re MREQ-0649 criteria Footnote 2 in Table 2 contains error due to leatage testing deletions. Licensee may submit analysis to justify use of existing jow flow controller.
  EISENHUT.D Q Division of Licensing 81/02/20. Bpp.
- 8103050023 Notification of 810302 meeting w/util & contractors in 8ethesds.MD to discuss facility schedule & third party/NRC review of application ME9888.V Licensing Branch 1. 81/02/24 3pp. 07839.237

- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs fercept 8t Lucis.Units 1 & 2? Requests util ravieu to determine capability to mitigate station blackout event & promotly implement emergency procedures EISENHUT. D 0 Division of Licensina BI/02/29 500.
  - 9103200081 Forwards application document.FSAR & environ rept reaccepted OL application to replace previously submitted documents 11/0 enc]

    50'JDER.J L Division of Rules and Records 81/02/26 Ip 07972 174
  - 8103230813 Generic Lir 81-05 to all CP holders & DL applicants re ICCFR90 Pite). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl EISENNUT.D O Division of Licensing 81/02/25 10pp
  - 8103090562 Forwards proposed preoperational & operational monitoring programs for Unit 2 Requests review & comments by 810430 ZELLER. II D. Environmental Protection Agency 81/02/27 32pp. 07850 093
  - BIO3110074 Forwards notice of receipt of application for Dinotice of availability of applicant environ reptinctice of consideration of issuance of OL % notice of opportunity of hearing YCUNOBLOOD, 3 J. Licensing Branch I B1/02/27 3pp 07884 344.
  - --8103110087 Notice of receipt of application for D., notice of availability of applicant environ reptinotice of consideration of issuance of D. 2 notice of opportunity of hearing youNGBLOOD, B. J. Licensing Branch 1 81/02/27 6pp 07884-347
  - BiO3130378 Burnary of BiO302 neeting u/util re independent design review (IDR) pilot program List of attendees encl NERBES-V Licensing Branch I. BI/03/06 4pp. 07912-156
  - 8103160536 Notification of 810311 reeting w/util in Silver Spring.MD to provide contractors participating in independent design review pilot program w/info on staff scape of FBAR review Agenda encl
    NERSEG.V Licensing Branch | 81/03/06 Spp 07915.287
  - 0103160554 Requests formal approval of util independent design review grage and to provide significant refuction in licensing time. UMRIO-RE Floride Power & Light Co 81/03/09 2pp 07915-161.
  - 8103170777 Notification of date & time change to 810311-12 meeting w/util in Dethesda-MD to provide contractors participating in independent design review pilot program w/info on staff scope of review of FBAR Agenda ent!.

    NERSEES V Licensing Branch 1. 81/03/09 4pp 07728-022
  - BIO3130429 Provides info re results of 800826-30 test conducted to demanstrate reactor coolant pump seal dusting adequacy during postulated station blactout conditions Major seal failure abnormal leakage did not occur UM410. R.E. Florida Power & Light Co. 81/03/10 3pp. 07908 224.
  - B103180649 Requests comments & views an encl util ltr re licensing schedule.

    CHILEB.L. Senete. B1/03/10 ip.
  - ---Bi03180653 Urges licensing schedule be revised to reflect Oct 1982 completion date not Dec 1983.
    MCDONALD.M Floride Power & Light Co 81/03/03 Spp.
  - B103310B04 Ltr to all licensess of operating plants, applicants for OLs & holders of CPs forwarding BECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D 0 Division of Licensing B1/03/10 opp.
  - BiO3j60599 Responds to NRC BOI253 ite no 800523 Commission memorandum order. Util will submit info supporting environ qualification of electrical equipment for facility four months before expected issuance of full power license.

    UHRIG.R E. Florida Power & Light Co. 81/03/12. 1p. 07917:197

- design changes since CP environ review & to discuss questions on demography, socioeconomic & environ impacts of plant operation Hyllst of attendees.
  MERGES.V. Licensing Branch 1 81/03/17 4pp 07980 298
- 8103240573 Advises that docket date for Dt application is 810217 FR notice and L. VERMISSELEDU. B. J. Licensing Branch L. 81/03/18 2pp 07982 330
- ~~8103240574 Notice of apportunity for public participation in proposed licensing action for issuance of CL.

   Office of Nuclear Reactor Regulation, Director 81/03/09 2pp
- 8103240749 Forwards request for add1 info re FSAR for review of Clapplication Response should be submitted by 810931 TEDESCO.R L. Assistant Director for Licensing 81/03/18 Spp
- 8103260659 Grants util 810306 request for extension to allow submittal of NPDES permit application by 810415. Util 810306 ltm encl ZELLER.H D Environmental Protection Agency 81/03/18 4pp CMO37 340
- G103260082 Notification of G10324-25 meeting w/util & consultants in Bethesda.MD to hear & discuss design info that should be submitted so staff can complete review per SRP sections MERSES.V Licensing Branch 1 B1/03/20 3pp C6041 252
- C Utility Environmental Report (ER), amenda & correspondence
- 8103240570 Forwards request for add1 info re environ rept evaluation Response should be submitted by 810501 TEDESCOR L. Assistant Director for Licensing 81/03/18. 10pp 07982:334
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8103050060 Extends invitation to attend 810218 site visit S/NRC repreparation of EIS for CL application review Map encl YUNVORLODOR J. Licensing Branch 1 91/02/12 200
- 103090352 Extends invitation to attend 810218 site visit w/NRC repreparation of E15 for OL application review Map encl YDUNGSLODD.8 J. Licensing Branch ( 81/02/12 2pp
- B103050366 Invites FL Dept of Regulation to attend B10218 site visit WARC re-preparation of EIS for DL application roview Mapencl YDUMBELODD, B J Licensing Branch ( B1/02/12, 2pp. 07806:001
- 8103050371 Invites FL Dept of Natural Resources to attend 810218 site vist w/KRC re-preparation of EIB for OL application review Map encl VCLV/00BLDGG.B. J. Licensing Branch 1. 81/02/12 200
- 8103050377 Extends invitation to attend 810218 site visit u/APC repreparation of EIS for OL application review Info re listed or proposed endangered species requested Map encl. YOUX08LD3D.8.J Licensing Branch 1 81/02/12 2pp
- B1030503B1 Extends invitation to attend 81021B site visit w/NRC repreparation of EIB for OL application review Map encl YOUNOBLOSO, B. J. Licensing Branch 1. 81/02/12: 3pp
- F. Becurity, medical, emergancy & fire protection plans
- BIO331033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. IVo enci
- H. General correspondence
- B103180649 Requests comments & views on enc1 util ltr re licensing sthedule.

  CHILES.L. Benate 81/03/10 ip.
- J. Insurance & indomnity information
- 8103060424 Forwards Endorsement 4 to MAELU Binder XB-59 FIELDER.J. Marsh & McLennen, Inc., M & M Nuclear Consultants, Inc. Div. B1/01/27, 3pp. 07837-327.

- DIV 81/03/06 2pp 07872 280
- G. Inspection reports: 1E Bulletins & carrespondence
- 8103120829 Forwards 18 Info Notice 80-44, "Actuation of ECCS in Recirculation Made While in Hot Shutdown" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/12/16
- 8103070752 Forwards IE Mgt Meeting Repts 50-290/80-31.50-251/80-29 50-335/80-33 & 50-389/80-14 on 801029 No nancompliance noted O'REILLY.J P Region 2. Atlanta. Office of the Director 81/02/03 200
- --9103090765 IE Mgt Meeting Repts 30-250/80-31.50-251/80-27.50-335/80-3 & 50-389/80-14 on 801029 to discuss results of evaluation of util regulatory performance. LEMIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/02 21pc.
- B103020251 Forwards IE Circular B1-02. 'Performance of NRC-Licensed Individuals While on Duty 'No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 81/02/69 ip 07785 321
- B103190040 Forwards TE Insp Rept 50-389/81-01 on 810120-23 No nontemptiance noted MARPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/11 2pp 07964 170
- --BIO3190045 IE Insp Rept 50-369/BI-01 on BI0120-23 No noncompliance noted Major areas inspected structural concrete earthfill & previously identified items HARRIB.J R Region 2. Atlanta. Office of the Director CONLON.Y E Region 2. Atlanta. Reactor Construction & Engineering Support Branch BI/02/11 3pp 07964 1/2
- 810304078% Responds to 1E Bulletin 80-21 re use of valve parts cast by Malcom Foundry Co.inc Two of seven equipment vendors have not yet provided info re safety-related valves Info anticipated by 810529

  URRIO.R E Florida Power & Light Co. 81/02/13 ip 07810:126
- 8103090160 Ack receipt of B10129 ltr informing NRC of staps taken to correct violations noted in 1E insp Rept 50-389/80-13 rVRPHY. E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/18 tp 0.7840
- --8103090168 Responds to NAC 810102 itr re violations noted in 1E Insp. Rept 90-389/80-15 No proprietary info Corrective actions 16 of 19 missing test coupons located & addl coupons being made to meet NAC requirements

  UHRIG.R E Florida Power & Light Co 81/01/29 App 07848 318
- 8103140663 Forwards 1E Circular BI-03. "Inoperable Setemic Monitoring Instrumentation 'No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BI/03/02 ip. 07914: 262
- 8103170028 Forwards revised IE Bulletin Bi=01. "Surveillance of Machanical Shubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements O'REILLY.J P. Region 2. Atlanta. Office of the Director. 81/03/04 1p 07939-193.
- Bi03200271 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required.
  D'REILLY, J. P. Region 2. Atlanta. Office of the Director. Bi/03/1i io.
- B103260200 Forwards IE Insp Rept 50-389/81-03 on B10224-27 No noncompliance noted LEWIB.R C. Region 2. Atlanta, Office of the Director B1/03/12 2pp 08941:305
- --8103260211 IE insp Rept 50-389/81-03 on 810224-27 No noncompliance noted Major areas inspected licensee action on previous insp findings, 100FR80 55e licensee identified items & safety-related welding structures.

  OIRARD, E. H. . HERDT, A. Region 2. Atlanta, Office of the Director 81/03/11. 6pp. 08041-307.

- BIDDZD2019 Forwards IF Info Notice B1-05. "Degraded DC Sys at Palisades" No response required D'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/03/13 to
- R Periodic operating reports & related correspondence
- 8103260455 Forwards status rept of const/startup progress for Feb 1981 UNRIGHR E. Florida Power & Light Co. 81703720. Rep. 08037-354
- S Reportable occurrences. LERs & related correspondence
- 8103030872 Notifies delay in final deficiency rept submittal re door frame Nelson stud failures Final rept scheduled for B00930 submittal human frame Lucion Filanda Power & Light Co. 80/07/20 10 07808 202
- 9303030B17 Advises that 801223 response to 801124 rept of potential IOCFR90 99e item determined issue re-missed ABME Section III final Endestructive stem in rig of control element drive retranseminator housings not reporteble per subj regulation UMSIO, RE Florida Power & Light Co. 81/01/08 in 07788 333
- U Congressional/Executive Correspondence
- BIC3180536 Requests consideration of costs involved if DL schedule completion date is not changed from Dec 1983 to Dct 1982 FASCELLD B House of Rep 81/03/06 ip 07950.105
- 810323C849 Supports encl util ltr requesting revision of licensing schedule for facility
  "CCCLUMB House of Rep. 81/03/06 ip 07979 022
- --B103230853 Urges revision of licensing schedule to reflect Oct 1982 as completion date for facility MCOCIA-D.M Florida Power & Light Co B1/02/27 Son 07975 023
- OCCKET 90-390 WATTS BAR NUCLEAR PLANT. UNIT 1

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads Requests eviluate per guidelines in NUREO-0612 Forwards NRC position re interir actions & request for addl info f156NHUT.D Q Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPS re program for environ qualification of safety-related electrical equipment Items addressed involve rold shutdown.replacement parts & NUREO-0737 EISEMBULD Q Division of Licensing 81/01/19 App
- 8103120014 Ltr to all licensees of operating plants, CP holders \$ Ot. applicants, except Indian Point 2 \$ 3.71on 1 \$ 2 \$ TMI+1. forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT. D @ Division of Licensing 81/02/03 6pp
- 8103120544 Forwards add1 info re containment vessel bidg analysis, per 801205 request. Fifteen oversize drawings encl Aperture cards in PDR.
  MILLS.L.d. Tennessee Valley Authority 81/02/19 8pp 07907 005
- 9103250924 Ltr to all power reactor licensees & license applicants re ARREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EIEEEMAUT. O g Division of Licensing. 81/02/20 App
- 9103020427 Forwards summary of audit re separation of electrical soutpment & sys. Audit revealed that cables of different divs crossed in control bidg cable spreading room & in auxiliary bidg on elevations 713 & 737, separation was not maintained MILLS-L II Tennessee Valley Authority 91/02/24, 4pp 07785 054
- 8103230033 Ltr to all licensees of operating nuclear power plants & applicants for DLs texcept 6t Lucle. Units 1 & 2). Requests util review to determine capability to nitigate station blackbut event & promptly implement emergency procedures EISENHUT. 0 Q. Division of Licensing 81/02/25 Spp.
- 9103030751 Advises that mods identified in util 801014 ltr have been completed re-reset of equipment upon reset of engineered safety features actuation signal. #ARREF.H O. Dute Power Co. 81/02/24 ip 07796 078

- 9103230813 Generic Ltr 81-05 to all CP holders & CL applicants re IGCFR\$0 71(e). "Periodic Updating of FSARs." effective B00722 Info re FSAR legal status format & content encl EISENHUT. D G Division of Licenting 81/02/2
- G103310804 Ltr to all licensees of operating clants applicants for Ol to holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment
  EISELF-WI.D.O. Division of Licensing 81/03/10 App.
- 8103270777 Forwards "Assessment of Ultrasonic Reflectors in Sequeyah Unit 2 Reactor Vessel Nozzle Bores" & "Assessment of Ultrasonic Reflectors in Matts Bar J Reactor Vessel Nozzle Bores " Repts available in Central Files only MILLS-L M Tennessee Valley Authority 81/03/20 ip
- E NRC Safety Evaluation Report (SER), supply & correspondence
- #103240002 Requests info for SER & supplemental SER 2 wks prior to date indicated on encl schedule Applicant should provide equipment qualification info,per IE Bulletin 79-01B.if SER scheduled after June 1981
  DENTON.H R Office of Nuclear Reactor Regulation, Director B1/03/13 7p 07990 113
- F. Security, redical, emergency & fire protection plans
- 8103060336 Forwards add1 info re guard training & qualification plans Encl withheld (ref ICCRR 790) MILLEL IN Tenessee Valley Authority. 81/02/26 ip
- G103310339 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISENRYI.D 9 Division of Licensing 81/03/05 App.
- J. Insurance & indemnity information
- 8103060737 Unesecuted Amend B to Indemnity Agreement B-88 substitutin Item 3 of agreement attackment cyllen 3 from License SMM-1861 from 790905 & License BMM-1873 from 810217 BALTZMAN, J D Utility Finance Branch (formerly Antitrust & Indemnity) 81702/17 ip 07835-340
- 8103230498 Forwards ejecuted Amend 1 to Indemnity Agreement 8-89, changing Item 3 re license numbers
  PARRIES H @ Tennesse Valley Authority 81/03/16 2pp. 07979 33
- K Utility Final Bafety Analysis Report (FSAR) & amends
- B103170322 Forwards Amend 42 to FBAR MILLS.L.M. Tennessee Valley Authority. 81/03/09 Ip 07930 278
- --8103170325 Amend 42 to FSAR \* Tennessee Valley Authority 81/03/09 500pp 07930 279
- @ Inspection reports. IE Bulletins & correspondence
- B103050444 Responds to NRC B00826 itr re-violation noted in IE Insp. Repts 50-390/B0-24 & 50-391/60-18 Corrective actions new gauges installed on B00804.
  MILLS, L.M. Tennessee Valley Authority. B0/09/17 2pp 07824:343
- --BIO3050463 Forwards IE Insp Repts 50-390/80-24 & 50-391/80-18 on BO0728-31 & notice of violation. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineerin Bupport Branch, B9/08/26 2pp 07824-345.
- --8103050462 Notice of violation from inep on 800728-31.

  \* Region 2, Atlanta, Office of the Director. 80/08/20 ip. 07824-347.
- --BiO3050472 IE Insp Repts 90-390/80-24 % 50-391/80-18 on B00728-31 Noncompliance noted foam generation gauge found out of calibr.
  O188GN.T.D. Region 2. Atlanta. Office of the Director CONLON, T.E. Region 2. Atlanta. Reactor Construction & Engineeric Support Branch 50/08/20 4pp 07824-348

```
D'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/01/16
10
```

- 8103020277 Forwards IE Circular B1-02. 'Performance of NRC-Licensed Individuals While on Duty 'No written response required D'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/09
- 8103040156 Forwards IE Info Notice 81-03, "Checklist for Licensees Making Natifications of Bignificant Events In Accordance W/10CFR80, 72, " No unitten response required, O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 81/02/12 1.
- 8100240493 Forwards IE Insp Repts 50-390/81-02 & 50-391/81-02 on | MURPHY.C E Region 2: Atlanta Reactor Construction & Engineering
  | Support Branch | 81/02/20 | 2pp | 08041 017.
- --8103260508 IE Insp Repts 50-340/81-02 & 50-391/81-02 on 810120-23 103260508 IE Insp. Repts 50-397/81-02 & 50-391/81-02 on 810120-23
  No fidencompliance noted Major areas inspected licensee attion
  on previous insp. findings & observation of removal & erens
  of reactor vessel inlet notife underclad cracting
  OIRARD.E M. Region 2. Atlanta. Office of the Director MERDT.A R
  Region 2. Atlanta Reactor Construction & Engineering Support
  Branch 61/02/20 7pp 08041:019
- 8103950563 Act receipt of 810129 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-30 & 50-391/80-23 LEWIS.R.C. Region 2. Atlanta. Reactor Operations Ruclear Support 50-391/80-23 LEHIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/24 ip 07829 018
- --8103050573 Supply 810114 response to NRC 801121 ltr re violations noted in IE Insp Repty 80-390/80-33 & 30-391/80-23 Corrective actions trend analysis programs to be implemented in design & const MILLS. L H Tennessee Valley Authorsty 81/01/29 2pg 07829 019
  - Bi03050582 Responds to NRC 801121 ltr re violations noted in IE insp. Repts 90-390/80-30 & 90-391/80-23 Corrective actions: instructed personnel that recurring nonconformances may be significant who being significant on individual basis. MILLS.L. H. Tennessee Valley Authority 81/01/14 Spp. 07829-021
- --B103050587 Notifies that required response to NRC 801121 ltr re-violations noted in IE Insp Repts 50-390/80-30 & 50-391/80-23 will be forwarded by 801224 MILLS: IM Tennesses Valley Authority 80/12/17 ip 07829 026
- --Bi03050990 Forwards IE Insp Repts 50-390/80-30 & 50-391/80-23 on Bi0901-1017 & notice of violation LEWIS.R C. Region 2. Atlants. Reactor Operations Nuclear Support Branch B0/11/21 2pp 07829.027.
- --8103050593 Notice of violation from insp on 810901-1017. \* Region 2. Atlanta. Office of the Director 80/11/20 19. 07829-029
- --BI03050600 IE Insp Repts 50-390//80-30 & 50-391/80-23 on 810901-1017.
  Noncomptiance noted: supervisor failed to rept nonconforming performance of spent fuel rack cells per drag tests
  MCDUNALD, J A. MEATHERLY, T. L. Region 2. Atlanta, Office of the Director. DANCE, M C. Region 2. Atlanta, Reactor Operations
  Nuclear Eupport Branch 80/11/20. 6pp. 07829:030
- 9103140682 Forwards IE Info Notice 81-94, "Crecking in Main Steam Lines." No response required.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director 81/02/27.
- 8103160316 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation." No response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/03/02
- Bi03i60B12 Forwards revised IE Bulletin B1-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 9 & 6. Util is deleted from CP facilities to which bulletin is applicable C'REILLY, J.P. Region 2. Atlanta, Office of the Director. B1/03/04 ip. 07914:171.
- BIO3260019 Faruards update to 800805 response to IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312.Type 304 Stainless Steel Piping: " SA-312.Type 300 series fusion welded pipe not used at facilities Add! info will be sent by 810630. HILLS.L.M Tennessee Valley Authority 81/03/04. 2pp. 08042:108.

-- Bio3180385 Responds to MPC 831125 ltr re violations moted in IE [+ Rests 53-390/80-32 4 50-391/80-25 Corrective actions all Schedule 160 welds will be reinspected Gelding procedures manual to be issued by 810223 MILLS-L M Tennessee Valley Authority 81/01/26 3;p 37943 009

Region 2. Atlanta, Office of the Director - 81/03/06

50-391/80-25 CENTS. 9 C

10 07943 008

07983 293

- --8103189392 Forwards interia response to 1E insp Repts 50-390/80-32 \$0-391/80-25 Final reply by 810123 Corrective actions celding procedures will be rade available to all welding crafts employees MILLS.L M Tennessee Valley Authority 80/12/18 300 95231 030
- --0103180396 Forwards IE Imap Repts 50-390/89-32 & 50-391/80-25 on 801021-24 & notice of violation MCRPHY.C E Region 2. Atlanta. Office of the Director 80/11/2 2pp 97943 015
- --8103180401 Notice of violation from thep on 801021-24 Region 2. Atlanta. Office of the Director BO/11/20 ip 07943 317
- --8103180412 IE Inso Repts 50-390/80-32 & 50-391/80-25 on 801021-24 Koncompliance noted undersized socket fillet welds accepted Noncompliance holed undersized societ fillet Weids accepted on reinsp & committeent to corrective action not fulfilled ECC::OMOS.N. Region 2. Atlanta. Office of the Director MEADI. Region 2. Atlanta. Office of the Director MEADI. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/11/20 ápp 37943 OLS PERDI. A
- (DJ24/BJ) ForLards (E. Inep Repts 30-340/BD-36 & 30-341/BD-28 on BD)201-31 & notice of violation O'REILLY-JP. Region 2. Atlanta. Office of the Director BI/03/I/ 2pp 07983 291. --8103240812 Notice of violation from insp on 801201-31 \* Region 2. Atlanta. Office of the Director 81/03/10 2pp

8103240809 Forwards IE Inso Repts 50-390/80-36 & 50-391/80-28 no.

- --8103240923 IE Insp Repts 50-390/60-25 % 50-391/80-28 on 801201-31
- 10344083 IE Insp. Repts 30-340/EU-35 No-341/80-215 on 801201-31 Noncompliance noted failure to take appropriate corrective action & failure to follow procedures MCDDNALD-J.A. HEATHERLY.T.E. Region 2. Atlanta. Diffice of the Director DANCE.H.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 81/02/20 Spp 07983 295.
- 8103200197 Forwards (E Info Notice Al-Ob. "Failure of ITE Model K-600 Circuit Breaker." No response required.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/03/1 8103200003 Forwards IE Info Notice 81-05, "Degraded DC Bus at

Palisades "No response required O'REBLLY, J.P. Region 2, Atlanta, Office of the Director 81/03/1:

- 8103310485 Responds to NRC 810213 itr re violations noted in IE Insp Rept 90-390/80-035 & 50-391/80-022 Revised corrective actions stop work action will be initiated when QA problem exists or work being performed w/o approved procedures.

  MILLS.L.M. Tennessee Valley Authority 81/03/26, 7pp 08075 23;
- S Reportable occurrences. LERs & related correspondence
- B103040754 First Interim deficiency rept re inconservative loads on pipe support design mods, initially reported B01217. Caused by failure to reflect load increases not requiring design mode on support drawings Addi Info
- 8103030809 First interim deficiency rept re high density spent fuel racks.per 100FR50 55(e) & Part 21.initially reported 801217. Tacks, per location of the feet of procedures & data acceptability in progress. Addl info expected by 810415
  MILLS.L M. Tennessee Valley Authority 81/01/21 2pp 07795 230
- 8103030853 Final deficiency rept re defective guide tube support pin-initially reported 800324 Cause not stated Upper internals guide tube support pins will be replaced w/new pins supplied by Westinghouse.
- MILLS, L M. Tennesses Valley Authority 81/01/23 2pp 07795 22

action under investigation
MILLB.L M Tennessee Valley Authority 81/02/24 2pp 07795 091

3103C40696 Final deficiency rept.originally reported on 801219.re
currant control problems w/diesel generators IA-A & 18-B
Clesel generator IA-A voilage regulator improper wiring
corrected & generator IB-B operational problems isolated
MILLS.E M Tennessee Valley Authority 81/02/24 20p 07812 262

9103373604 First interir deficiency rept re inadequate GA requirement for heating, ventilation & air conditioning sys.initially reported 800124 Addl info to be provided by 810430 Action plan responding to NRC 810210 ltr re sys audit enct.
HILLS.L.M. Tennessee Valley Authority 81/02/27 5pp 07050 166

3103110514 Second Interim Deficiency Repts SGRD=50-328/81-08, #BRD=50-390/81-07 & WBRD=50-391/81-06 re unconservative leads on gipe support design bods, initially reported B01217. Approx 2000 support drawings found Rept expected by 810401 MILLS.L.M. Tennessee Valley Authority 81/03/02 ip 07887 109

3193110464 First interim deficiency mept.originally meported on 810130, to high pressure fire protection piping merouting Field change requests for piping changes 3 additions approved w/a proper analyses re change effects on sys pressure MILLS.L M. Tennessee Valley Authority 81/03/02 2pp 07889 056.

BiO3120630 PNO-11-81-022 on BiO307, fire accurred in nonsafety-related digital computer sys in communications room of control bidg. Gause not slated Fire estinguished & investigation is in progress.

HILLER W. H. CCNDOW T. E. Region 2. Atlanta, Office of the Director 81/03/09. io 07906-298

3103170502 Second interim deficiency rept re inadequacy of selfdrifting escansion enthor design, initially reported on BO1204.Util is evaluating actual loads developed in anthor against drawing spec Next rept will be forwarded by B10327. MILLS.L.M Tennessee Valley Authority 81/03/09 2pp 07935 279.

8103180544 Final deficiency rept.initially reported 801216 re loose electrical terminations on diesel generator conftrol panels hire 312 found terminated w/o screu & held in place w/torque esel. Screu replaced & tightened KILLS.L M. Tennessee Valleu Authoritu. 81/03/12 4pp. 07950:295

8103240404 Fourth interim rept re failure to consider loads from 3-inch check valve in sejemic analysis of chemical & vol control sign initially reported on 801002 Loads at Sequoyah not significant. Results of reanalysis in final rept by 810915 MILLS.L.K. Tennessee Valley Authority 81/03/17 ip 07987.181

3:03270724 Final deficiency rept.originally reported on 810218 re Thermon Mfg Co heat transfer cement installed in pipe hanger area, restricting movement between pipe & hanger Caused by error in original piping analysis Cement will be removed. MILLS.L.M. Tennessee Valley Authority 81/03/18 2pp. 08047.207.

BICQ300158 Final Part 21 rept re inconsistent upper head injection hydraulic isolation valve accumulator weighing sys, initially reported 800329 Proposed design changes will not be implemented Procedure used for Sequoyah 1 will be used. httl.8.L M Tennessee valley Authority 81/03/18. 2pp 08055.332

3103310379 Final deficiency rept re damage to upper head injection piging hangers initially reported on 800815 Piping analysis initiated to determine loads generated by lifting incident becaused hanger & welds examined.

MILLS.L M. Tennessee Valley Authority. 81/03/25 2pg. 08062 216.

BiO3120014 Ltr to all licensess of operating plants, CP holders & QL applicants, except indian Point 2 & 3, 2ion 1 & 2 & 1Hi-t, forwarding inacvertently aritted pages from NRC 801222 request for addl info re control of heavy loads EISE(1HUT, D Ø Division of Licensing, 81/02/03 dpp

8103120544 Forwards addl info re containment vessel bldg analysis.per 801205 request Fifteen overslie drawings encl Aperture cards in FDR MILLS-L M. Tennessee Valley Authority 81/02/19 Boo 07907 005

8103290024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Foutnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D Q Division of Licensing 81/02/20 8pp.

B103020427 Forwards summary of audit re separation of electrical equipment & sys Audit revealed that cables of different divs crossed in control bidg cable spreading room & in ausiliary bidg on elevations 713 & 737-separation was not maintained MILLS-L. H Tennessee Valley Authority 81/02/24. 4pp 07785 054

8103230030 Ltt to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement amergency procedures EISENMOT, D 9 Division of Licensing 81/02/29 5pp

8103230813 Generic Ltr 81-06 to eil CP holders & DL applicants re SCCFRSQ 71(e). "Periodic Updating of FBARs:" effective B00722 Info re FBAR legal status format & content eht! EIBENHUI.D O Division of Licensing 81/02/26 10pp

8103310804 Ltr to all licenses of operating plants applicants for OLs b holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.

E NRC Safety Evaluation Report (BER), supply & correspondence

B103240002 Requests info for BER & supplemental SER 2 was prior to date indicated on encl schedule Applicant should provide equipment quelification info.per IE Bulletin 79-018.if SER scheduled after June 1981
DENTON.H.R Office of Nuclear Reactor Regulation. Director. B1/03/13. 7pp 07970 113

F Security, medical, emergency & fire protection plans

8103040717 Informs that licensee will conduct emergency preparedness exercises Sept 1981 for Browns Ferry & Mar 1982 for Watts Bar, per 810130 request Exercise scenarios will be provided four was before scheduled exercise MILLS.L ft Tennessee Valley Authorsty 81/02/25. Ip.

B103060336 Forwards add1 info re guard training & qualification plans. Encl withheld (ref 100FHz.790) MICLES.L.M Fannessee Valley Authority 81/02/26 ip.

8103310330 Ltr to all licenses of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl EISEMINUT.D.O. Division of Licensing. 81/03/03 App.

Res Control

- J. Insurance & indemnity information
- B103060739 Unexecuted Amend B to Indernity Agreement B-88.substituting Item 3 of agreement attachment w/lton 3 from License SWT-1801 from 790705 & License SWT-1873 from B10217 BALIZHANIJ D Utility Finance Branch (Formerly Antitrust & Indemnity) 81/02/17. 1p. 07835-340
- 8103230498 Forwards executed Amend 1 to Indemnity Agreement 8-88, changing Item 3 re license numbers
  PARRISH O Tennessee Valley Authority 81/03/16 2pp 07979 335.
- K Utility Fina) Bafety Analysis Report (FSAR) & arends
- 8103170322 Forwards Amend 42 to F8A9 HILLS.L M Tennesses Valley Authority 81/03/09 ip 07930 278
- --8103170325 Amenj 42 to FSAR \* Tempessee Valley Authority 81/03/07 500cp 07930 279
- O inspection reports. IE Bulletins & correspondence
- 8103090444 Responds to NRC 800826 ltm re viplation noted in IE Insp. Repts 50-390/80-24 & 50-391/80-18 Corrective actions.nec. gauges installed on 800804 MILLS.L.M. Termessee Valley Authority 80/09/17 2pp 07824 343
- --Bi03050453 Forwards IE Insp Repts 50-390/80-24 & 50-391/80-18 on 800728-31 & notice of violation HURPHY,C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/08/26 2pp. 07624 345
- ~~8103050462 Natice of violation from insp on 800728-31 • Region 2. Atlanta. Office of the Director 80/08/20. ip 07824-347.
- ~-Bi03050472 IE Imap Repts 50-390/80-24 & 50-391/80-18 on 800720-31 Noncompilance noted feel generation gauge found out of califir. O[BSON.T D. Region 2. Atlanta, Office of the Director CDN\_DN.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/20. 4pp. 07824-340.
- 8102280484 Forwards IE Info Notice 81-01. Possible Failures of GE Type 16FA Releys \* No response required. O'REILLY. J P Region 2. Atlanta, Office of the Birector 81/01/14
- 8103020277 Forwards IE Circular 81-02, 'Performance of NRC-Licensed Individuals While on Duty No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/09 in
- 8103260493 Forwards IE Insp Repts 50-390/81-02 & 50-391/81-02 on 810120-23 No noncompliants noted. MARPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 81/02/20 2pp 08041 017.
- n-Bio32A050B IE insp Repts 50-390/Bi-02 & 50-391/Bi-02 on Bi0120-23 No noncompliance noted Major areas inspected: licenses action on previous insp findings & observation of removal & econs of reactor vessel inlet notile undersiad cracking OIRARD,E H Region 2. Atlanta, Office of the Director HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch Bi/02/20. 9pp 08041-019.
- B103050563 Ack receipt of B10129 ltr informing NRC of steps taken to correct violations noted in IE Inst Repts 50-390/80-30 k 50-391/80-23.

  LEWIS-R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/24 lp. 07829:018
- --Bi03050873 Buppls 810114 response to NRC B01121 ltr re-violations noted in IE line Repts 50-390/B0-30 & 50-391/B0-23 Corrective actions: trend analysis programs to be implemented in design & const.

  HILLGLIM Tennessee Valley Authority. B1/01/29 2pp 07829:019.
- --8103050582 Responds to NRC 801121 itr re violations noted in IE Insp. Repts 50-390/80-30 & 50-391/80-23 Corrective actions:

- ~-8103050587 Notifies that required response to NRC 801121 ltm reviolations noted in IC Insp Repts 50-370/80-30 t 90-371/80-23 will be forwarded by 801224 MILLS.L M Tennessee Valley Authority 80/12/19 to 07827 c
- --8103050570 Forwards IE Insp Repts 50-390/80-30 & 50-391/80-20 on B10901-1017 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Sugges-
- --8109050593 Notice of violation from thep on 81090:-1017
   Region 2. Atlanta. Office of the Director 80/11/20 1p

Branch 80/11/21 2pp 07829 027

07829 029

- --8103050500 IE Insp Repts 50-390//80-20 t 50-391/80-23 on Bi0901-10 Noncompliance noted supervisor failed to rept nonconforming performance of spent fuel sact cells per drag tests MCD3/ALD, J.A., HEATHERLY, T.L. Region 2, Atlanta, Office of the Director DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/20 App. 07829 030
- B103160916 Forwards IE Circular B1.03. 'Inoperable Seismic Monitorin Instrumentation "No response required MEPPLER. J G. Region 3. Chicago. Office of the Director 81/03/02 Ip
- B103160912 Forwards revised 1E Bulletin B1-01. 'Burveillance of Meckanical Enubbers.' w/corrected Pages 5 & 6 Util is deleted from (P facilities to which bulletin is applicable O'REILLY, J P Region 2. Atlanta. Office of the Director B1/03/0-19 07914 171
- B103260017 Forwards update to B03805 response to IE Bulletin 79-03A "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Piping " SA-312. Type 300 series fusion welded pipe not used at facilities Addl info will be sent by B10630 MILLS.L.M Tennessee Valley Authority B1/03/04 2pp
- 8103180368 Ack receipt of B10126 ltr informing NRC of steps taken to correct violations noted in IE. Imp. Rept 50-390/00-32 & 50-39/20-29 LEWIS.R.C. Region 2. Atlanta. Office of the Director B1/03/05 in 07943-308
- --8103180385 Responds to NRC B01125 ltr re violations noted in IE In Repts 50-390/80-32 % 50-391/80-29 Corrective actions all Schedule 160 welds will be reinspected Helding procedures manual to be issued by 810223 MILLS.L M Tennesses Valley Authority. 81/01/26 3pp 07943-009
- --8103180392 Forwards interim response to IE Insp Repts 50-3990/80-32 50-391/80-25 Final reply by 810123 Corrective actions welding procedures will be made available to all welding crafts employees

  NILLS.L M Tennessee Valley Authority 80/12/18 3pp 9929 330
- --Bi03180376 Forwards IE Insp Repts 50-390/80-32 % 90-391/80-23 cm 831021-24 % notice of violation HURPHY-C E Region 2- Atlanta. Office of the Director BO/11/2 2pp 07943 015
- ~-8103180401 Notice of violation from insp on 801021-24.

   Region 2. Atlanta. Office of the Director 80/11/20. lp. 07943.017
- --BIO3180412 JE Insp Rapts 50-390/80-32 & 50-391/80-25 on 801021-24 Nancompliance noted undersired societ fillet welds accepted on reinsp & commitment to corrective action not fulfilled ECONOMOS, N. Region 2. Atlanta, Office of the Director. HERDI, A Region 2. Atlanta, Construction & Engineering Support Stanch. 80/11/20 & Spp. 97943 O18
- 8103240805 Forwards IE Insp Repts 50-390/80-36 & 50-391/80-28 on 801201-31 & notice of violation O'REILLY, J.P. Region 2: Atlanta, Office of the Director. 81/03/12pp. 07983.291.
- --B103240812 Notice of violation from insp on 801201-31 \* Region 2, Atlanta, Office of the Director. B1/03/10 2pc 0793:273.

plan support design mode, initially reported 801217 Caused by ploe support design mous, initially reported doles, caused by fatlure to reflect load increases not requiring design mods on support drawings Add info espected by \$10302 Add Add the Add the State of t

:19393C609 First interir deficiency rept re high density spent fuel racts per tockRSO, SStel & Past 21.initially reported 801217 Evaluations re affected procedures & data acceptability in progress Addi info expected by 810415 MILLS, L. M. Kennessee Valley Authority 81/01/21 2pp 07795 230

003030957 Final deficiency rept re defective guide tube support pins. Initially reported 800324 Cause not stated Upper Internals guide tube support pins will be replaced w/new pins supplied by Westinghouse MILLS.L.M. Ten Tennessee Valley Authority 81/01/23 2pp 07795 221

103030778 Third interio deficiency rept re possible inadvertent boron disution, sentially reported on 800710 Restinghouse investigation is outpoing. L/completion of svaluation in Mar 1992 Nest rept will be forwarded by 820608. MILLS.L. H. Tennessee Valley Authority (81/02/06) ip ()

10 07704 131

(03030780 Fourth interim deficiency rapt me excessive output 770829 Also reported under Part 21 Hostinghouse developed field mod tit Mods acceptable Tennessee Valley Authority 81/02/10 in 07/95-085

103030771 First interim deficiency rept re inadequate grid voltage necessary to ensure adequate offsite power to safety-related buses during IME Caused by design deficiency Corrective action under investigation
#[LLG.L. H Tennessee Valley Authority 81/02/24, 2pp 07795:091

103390804 First interim deficioncy rept re inadequate GA requirement for heating, ventilation & air conditioning sys, initially reported 890124 Addl Info to be provided by 810430 Action plan responding to NRC 810210 Its re sys audit encl.
MILLS.L.M. Tonnessee Velley Authority 81/02/27 Spp. . 5no. 07850.166

103110614 Becams Interin Reficiency Repts 50RD-30-328/81-08. MBRD-50-390/81-07 & MBRD-30-391/81-06 re unconservative loads on fipe support design mods initially reported 801217
Approx 2000 support drawings found Rept expected by 810401
M3LL8.L.M Tennessee Valley Authority. 81/03/02 1p 07 1p 07887 109

10311C564 First interim deficiency rept.originally reported on 810130. re high pressure fire protection piping rerouting Field thange requires for piping changes & additions approved w/o proper analyses re change effects on sys pressure fills. It Tennessee Valley Authority 81/03/02 2pp 07885

100120639 PhD-11-81-022 on B10307.fire occurred in nonsafety-related digital computer sys in communications room of control bldg Cause not stated fire estinguished & investigation is in progress
HILLER, M. H., CONDON, Y. E. Region 2. Atlanta, Office of the Director 07906.298 le.

03(70302 Second interim deficiency rept re inadequacy of welfdrilling expansion anchor design initially reported on BOI204. Util 14 evaluating actual loads developed in anchor against drawing apec. Next rept will be forwarded by BI0527 HILLS.L.M. Tennessee Valley Authority BI/03/09. 2pp. 07935 279

.03240404 Fourth interim rept re failure to consider loads from 3-inch chect valve in seismic analysis of chemical 2 vol control sys. Initially reported on 801002 toads at Sequoyah not segnificant Results of reanalysis in final rept by 810515 HILLG. If Tennessee Valley Authority. 81/03/17. 1p. 07987:181.

1100000 San Francisco. Office of the Director 81/02/09 to 07785 353

COCKET 50-393 VIRGIL C SUMMER MUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence

- 8103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests neview per guidelines in tureG-Odi2 Forwards NRC position ratio and interim actions & request for addition to EISENHUT, D 9 Division of Licensina B0/12/22 3000
- 8103031067 "Environ Statements Project." monthly progress rect for Dec 1000 ATTELL H E Oak Ridge National Laboratory FIN 8-0760-1 8103031047 80/12/31 4pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safetu-related electrical equipment (tems addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT. DO Division of Licensing 81/01/19.
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3.7ion 1 % 2 & YMI~1. forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT, D.O. Division of Licensing 81/02/03 App
- 8103041007 Natification of 810302 meeting w/util in Jenkinsville.5C to audit documentation re environ qualification of electrical drematups KANE, W.F. Licensing Branch 2 81/02/20 3pp. 07812 018
- B10309071B Advises that use of ASME Code Case N-282 in const of valves 4 inches & smaller is acceptable.per 810102 request Use should be documented in FBAR TEOLECO.R L Assistant Director for Licensing 81/02/20 2pp. 07844: 228
- B103250024 Lir to all power reactor licensees & license applicants re MUREC-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing delations Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D O Division of Licensing 81/02/20 8pp
- B103020362 Forwards response to FSAR Question 421 83 re Q-list Response will be incorporated into FSAR Amend 24.
  NICHOLS.T.C. South Cerolina Electric & Qas Co. B1/02/23. 19pp. 07284 250
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures
  FISHNUT, 0.0 0 (vision of Licensing 81/02/25 529)
- 8103230813 Generic Ltr 81-06 to ail CP holders & OL applicants re 10CFR50 71(a), "Periodic Updating of FSARs," effective 800722 Info re FSAR legal status, format & content encl. EISERHOUT.D.O. Division of Licensing 81/02/26. 10pp
- 8103120294 Corrects ref to Reg Guide 1.52 in 810225 ltr to NRC Ref was labeled as Reg Quide 1.5 2.
  NICHOLS, T.C. Bouth Carolina Electric & Gas Co. 81/03/03. 1p 07900-344

- B103110539 Documents telcon w/H Haass (ARC) responding to NRC Question 421 B3 re g-list Safety-related items nowwill be procured under OA program Response to question & appropriate tables will be revised to incorporate info MICHOLB.F C Eouth Carolina Electric & Gas Co 81/03/04 3pp 07/97/359
- 8103120307 Forwards Revision 1 to App %, "Effects of Near-Field Earthquake Oround Motion on Structure & Equipment Design." from rept entitled "Supplemental Setsmology Investigation". NICHOLS.T.C. South Carolina Electric & Oas Co. 81/03/04 | 1p.07900 348
- 8103160163 Bubmits list of items issued or clarified by NUREO-0737 MANE/N Licensing Branch 2 81/03/04 3pp 07919 347
- BiO3120416 Approves BO1219 request to use later code edibion & addenda in re-dnalysis program for ASNE Section 3.6(ass & chemical & vol control sys pump seal injection line & pressurizer relief lines

  TEDESCO.R L. Assistant Director for Licensing B1/03/05 2pp 07906-0754
- 8103100521 Forwards "Bupplemental Investigation. Evc Water Pond Heat Erbankment. Virgil C Bummer Nuclear Station." prepared by Moodward-Cityde Consultants & Bibert Associates. Inc. Rept submitted to assist NRC in evaluation of BER suppl NICHOLB. T. C. South Carolina Electric & Gas Co. 81/03/06 1p. 07866. 129.
- --B193100547 "Supplemental Investigation, Svt Water Pond West Embaniment. Virgil C Summer Nuclear Station." + Woodward-Clyde Consultants, Inc. + Gibbert/Commonwealth Cos 81/03/05 93pp. 07868 131.
- B103130340 Notification of 810310 meeting u/util in Bethesda.MD to discuss corporate mpt capabilities. KANG.MF Licensing Branch 2 81/03/06 3pp 07912 153
- 1103200622 Bubmits add1 info for Belamic Gualification Review Feam followup of 801014-17 seismic audit Equipment summary sheest & qualification summary encl.
  NECHOLET C. Bouth Ceroline Electric & Oas Co. 81/03/06. 66pp
- BIO318077B Amends previous response to TMI Item II X.3 i7 Change will be incorporated in FB4R Amend 25 NICHOLB T.C. Bouth Carolina Electric & Oae Co Bi/03/10 ip. 07954:107
- 8103310834 Ltr to all licensess of operating plants, applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.
  EISENHUT. D. O Division of Licensing 81/03/10 App.
- BIO3190145 Notification of BIO316 meeting u/near-term OL applicants in Bethesds.ND re info required to be submitted on environ qualification of electrical equipment prior to site visit & MRC review.

  DURNELL.B Licensing Branch 2 81/03/12 15pg
- B103200372 Summary of 810224 meeting w/util & Gilbert Associates in Bethesde MB re seismic response spectrum W/list of attendes.

  MANE M.F. Licensing Branch 2. B1/03/12. 4pp. 07966.331.
- 8103230653 Informs that final set of soils (creep) tests will result in final rept by end of Apr 1981. NICHOLS.T. C. Bouth Carolina Electric & Gas Co. 81/03/19. 1p. 07976.397.
- B103260275 Advises that encl Page 15 2-22b in FBAR Amend 24 was mistakenly renamed & new Page 15.2-22b was added. Renamed page will be added to FBAR in next amend to bridge info currently on Pages 15.2-22b & 15.2-23. NICHDLB-T C. Bouth Carolina Electric & Gas Co B1/03/20. 2pp. 08037:347.
- 8103270443 Forwards "Reactor Containment Bidg Structural Acceptance Test." NICHOLB, T. C. South Carolina Electric & Gas Go. 81/03/20. ip. 08046-040.

- --8103270452 "Reactor Containment Blog Structural Acceptance l FULTON. J F . HERR. J C . MUREADITH. F L Gilbert/Commonweal 2278 81/03/18 2009p 05348 041
- G103270436 Advises that responses from Hestinghouse numers graitens II x 3.5. [[ x 3 1 & [ ] x 3 2.per B10106 & 0219 ltrs have been sent NICKGLS.T & South Carolina Electric & Oas Co B1/03/23 open 3-087
- 8103300157 Submits add1 info re use of herbicides & rotary movemaint of transmission line rights-of-way associated w/ facility Info concerns cost 's effects of herbicides use relative to using notary movers.

  NICHCLS-7 C South Carolina Electric & Oas Co 81/03/24
  08053-142
- BiO3300161 Advises that facility const project is 98% complete load projected for Aug 1981 MICHOLB.T.C. South Carolina Electric % Gas Co. 81/03/24 09083:160
- 6103310414 Advises that util is gursuing use of results from h Steam Station test as fulfillient of Thi Item II D I requirements re qualification of PCRV block valves Util will test valves per NUREG-0737 if Marshall Test unsatisfactory NICHOLS-II C South Carolina Electric 1 Oas Co 81/03/25.
- 8103310461 Dutlines three-phase program re qualification of congt & plant training-per request at 810310 meeting MICHOLEST C South Carolina Electric & Oas Co. 81/03/25 08059-258
- 8103310494 Informs that military training route 45 over facilishaw Air Force Base terminated LE Hull 810303 ltr confirming termination of training route end NICHOLB.T.C. Bouth Carolina Electric & Oas Co B1/03/25 OB062:350
- 8103310339 Submits info on operability assurance of 6-inch pur isolation valves in response to Equipment Qualification Branch request Qualification programs described in FBAR Boctions 3 9.3 11 & 3A have been completed NICHQLB.T C. South Carolina Electric & Oas Co. 81/03/26 08079 083
- 8103310366 Forwards responses to FSAR Questions 121 30 & 121 3 response to NRC request Callibr blocks are clad in accordance w/ABME-Bection XI, Paragraph I-3122 No exams are plained for containment spray sys.

  NICKOLET. C. South Carolina Electric & Oas Co. 81/03/26 08079.084
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8103030648 Notification of 810224 meeting w/util & Oilbert Ass in Bethesda-MD to discusses seismic response spectrum.open Item 1.6.3 in BER KANE,W F. Licensing Branch 2 81/02/20 3pp 07799 034
- B103030760 Forwards draft Tech Specs in SER showing in-place & testing efficiencies per Reg Guide 1 5 2. Revision 2 NICHOLS T. C. Bouth Carolina Electric & Gas Co B1/02/25. 07789 011
- --8103030763 Draft Tech Specs 3/4 7 6 for control roum normal air handling sys & 3/4.9.11 for spent fuel pool ventilations sys & South Carolina Electric & Qas Co. 80/11/19 Spp. 077
- 8103060681 Submits schedule for environ qualification audit & supplemental SER input TEDESCO.R.L. Assistant Director for Licensing. 81/02/25 65070.315
- 8103030656 SAFETY EVALUATION REPORT RELATED TO DEFRATION OF VI SUMMER NUCLEAR STATION. UNIT NO. 1. (South Carolina Electric and Gas Company) • Office of Nuclear Reactor Regulation. Director NUREO-07 81/02/28 596pp Available at NTIS \$11 00. 07786:003
- B103200687 Requests info for SER & supplemental BER two wks pr BER data indicated on encl schedule. Requests, four months prior to BER issuance-equipment qualification info per IE Bulletin 79-01B. for SERs scheduled after June 1781. DENTON. H. R. Office of Nuclear Reactor Regulation. Director 81/03/13. opp. 07966:100.

14 Responds to BER Item 1 7 II of confirmatory issue to steam for level measurement errors Mod will limit increase-low steam generator water level subpoint due to refistup to 2%.
3. T.C. South Carolina Electric & Oas Co. 81/03/18 2pp. 889

ity, redical, emergency & fire protection plans

38 Ltr to all licensees of operating plants & holders of CPs ding NJREG-0496. Functional Criteria for Emergency se Facilities "Criteria describe acceptable method eting NHC requirements N/o encl JT. D.O. Division of Licensing 81/03/05 App.

icatory correspondence

51 Informs that util sent intervenor BA Bursey GER for ty.RJREG-0717 Receipt encl Related correspondence R R — Bouth Carolina Electric & Gas Co — B1/02/13 — 2pp 001.

57 Reply apposing intervenor 8 Bursey B10223 petition to be ed from ABLD B01230 order Dider sanction should be ed t Intervenor precluded from presenting uitnesses, ts or other direct evidence on six contentions of 3 Bouth Carolina Electric & Gas Co. KNOTTS, J. B. South ha Public Bervice Authority KNOTTS, J. B. Debevoise & an B1/02/26 Spp. 07782.147

09/3 Answers to intervenor DA Bursey interrogatories regency plans certificate of Bvc & Itr to Bursey enclouth Carolina Electric & 9as Co e Bouth Carolina Public Ice Authority BD/12/24 lipp 07782 152

74 Bubnits list of cases going to hearing during 1981 in emergency preparedness contentions have been raised by core parties Er.CURY. E. Hearings Division 61/03/04 2pp

27 Hemorandum & order denying intervenor B Dursey B10223 t to lift bar against affirmative case w/o prejudice ing later motions w/summaries of testimony

Atomic Bafety and Licensing Board Panel 81/03/09 07901 282

34 Order scheduling 810407 final prehearing conference in ia. Sc All matters specified in 10CFR2 752 will be ered Parties to file suggestions to ASLO actions by

Atomic Safety and Licensing Board Panel 81/03/10 1p. 47. H : 340

94 Errata correcting address of final prehearing conference led in ASLB B10310 order AN.H. Atomic Befoly and Licensing Board Panel B1/03/16 ip

37 Confirms tolcon to FEMA assistance necessary to show ts applicant preparations to implement state & local ncy plans U/o encl interrogatories R9.3 C. Hearing Branch 2. 81/03/19 2pp 07967-331.

27 Cornents on ASLS 610310 order scheduling prephearing er comments on AULS BIJUJIO order scheduling prepheering ence as requested ABLO should set final date for enor to file request to remove ber to presentation of active case Cartificate of Svc encl. RO.B.C Hearing Dranch 2 81/03/20 4pp. 07990 319.

79 Petition to intervene in OL proceeding & request for gs Contentions, supporting affidavits & affidavit of cl.

J.C. Affiliation Unknown 81/03/23 71pp 08053 063

al correspondence

9/ Comments on NRC projected schedule for licensing facility • 1982 Delays in tenget date for licensing will hinder Byc Commission efforts to regulate util rates & will se economic burden on consumers LL.R South Carolina, State of 81/03/09. 2pp. 07944 189

ty Final Bafety Analysis Report (FBAR) & amends

61 Forwards marked-up page in Chapter 3 5 of FBAR re valves as missiles outside reactor bldg Amend 24 to FBAR orating encl page.will be issued 810302. 8.7 C. Bouth Carolina Electric & Gas Co. 81/02/25 1p 099.

8103030698 Forwards Amend 24 to FSAR NICHDLB.T C South Carolina Electric & Gas Co Bi/03/02 2pp 07798 266

--8103930701 Amend 24 to FSAR \* South Carolina Electric & Gas Co 81/03/31 200pp 07798 270

6103130419 Forserds Amend 25 to FSAR changing precommercial major mod & maint, & OA organization charts NICHCLS.T C South Carolina Electric & Gas Co 81/03/11 2pp 07907 056

~-8103139473 Amend 25 to FSAR

\* South Carolina Flectric & Gas Co 81/63/11 4cm 07907 058

8103310458 Forwards marked-up revision to FSAR Section 15 3 1 2 1 to address SER Confirmatory Issue 1 7 20 re decrease in reactor coolant inventory event NICHULS. T.C. South Carolina Electric & Gas Co. 81/03/25 2on 08078 332

O Advisory Cormittee on Reactor Safeguards reports & correspondence

8103230308 Discusses ACRS 251st Meeting on 810312-14 re util QL 10323030B Discusses ACRS 291st Meeting on B10312-14 re util Diapplication Concludes that facility can be operated at power levels up to 2.775 KHz w/o undue risk.if items mentioned are given consideration pending completion of const & testing MARK.J C ACRS - Advisory Committee on Reactor Safeguards B1/03/18 3pp 07979 354

O inspection reports. IE Bulletins & correspondence

8103090366 Forwards IE Insp Rept 50-395/80-33 on 801104-06 & notice of STORR. J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/12/24 20p. 07847-297

--8103090370 Natice of violation from insp on 801104-06 \* Region 2, Atlanta, Office of the Director 80/12/23 lp. 07847-299

---B103090372 IE Insp Rept 50-395/80-33 on 801104-06 Noncompliance noted Pailure to post specified documents at const workers' entrance to restricted area or fuel handling bldg used for storage of unirradiated licensed fuel MRAY,J R. GIBBON-A F. Region 2. Atlanta, Office of the Director. 80/12/23. 800 07847:300

Bi03050210 Forwards IE Insp Rept 50-395/80-37 on 801201-04 No noncompliance noted.

MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Granch, 81/01/20 2pp 07823 212

--8103050219 IE Insp Rept 30-395/80-37 on 801201-04 No noncompliance 103050319 IE Insp Nept 30-393/80-37 on BUZUL-04 NG Indicopitation noted Major areas inspected action on previous inspection of undings review of quality records & observation of work & work activities for 10CFR30 55e items.

MCFARLAND.C R Region 2. Atlanta. Defice of the Director.

BRYANI.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch. BI701/20 3pp 07825.214.

B103050300 Forwards IE Insp Rept 50-395/80-39 on 801211 No moncompliance noted.
MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering
Bupport Branch 81/01/20 2pp. 07825 357.

--8103050304 IE insp Rept 90-395/80-38 on 801211 No noncompliance noted 103090304 (E Insp Rept 30-349780-38 on BU[2]) No noncompliance Note Major areas inspected steem generator feeduater line radiography per IE Bulletin 79-13 CROMLEY, B R. Region 2. Atlanta, Office of the Director HERDTA R Region 2. Atlanta, Reactor Construction & Engineering Support Branch. B1/01/19 3pp. 07825:359.

8103040821 Forwards 1E Insp Rept 50-395/80-39 on 801216-19 No noncompliance noted Purples of the Research Construction & Engineering Bupport Branch 81/01/30 2pp 07812:171

--BI03040825 IE insp Rept 50-395/80-39 on B01216-19 No noncompliance noted Major areas inspected.licensee action on previous insp findings & review of RCPB riping records.

OIRARD.E.H. Region 2. Atlanta. Office of the Director HERDT.A. Region 2. Atlanta. Resctor Construction & Engineering Support Branch B1/01/30. Spp. 07812:173

8103130674 Forwards 1E Insp Rept 50-395/80-41 on 801208-12.No noncompliance noted LEWIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 81/02/05. 2pg. 07913.226

- --Bi0313047B iE Insp Rept 50-395/B0-41 on B31208-12. No noncompliance noted Major areas inspected preoperational procedure & program raview.

  Wiltener. H. L. FALCONER. D. P. Region 2. Atlanta, Office of the Director GUICKL D. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch B1/02/05 3pp 07913 22B
- 8103020270 Forwards IE Circular B1-02. Performance of NRC-Licensed Individuals While on Duty 'No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/02/09 pp. 07785-343
- B103180824 Forwards |E Insp Rept 90-395/80-40 on B01117-B10102 No noncompliance noted. LEWIB-R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 81/02/11 2pp 07953-186
- --Bi031B0831 IE Insp Rept 50-395/80-40 on B01117-B10102. No noncompliance noted flajor areas inspected preservice valve program review, open item review & preopprational test procedure review BK0L05.J L. Region 2. Atlanta. Office of the Director KELL002.P J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B1/02/11. Spp. 07953-188
- 8103190313 Forwards JE Insp Rept 90-399/81-01 on 810110-13 No moncompliance noted LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/11 2pp 07994-307
- --B103190317 1E Inst Rept 50-395/B1-01 on B10110-13 No noncompliance noted Major areas inspected integrated leak rate test MHITENER,H L. Region 2. Atlanta, Office of the Director QUICK, D. R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch B1/02/10 4pp 07954-309
- 8103040144 Forwards 1E Info Notice 81-03. "Checklist for Licensees Making Notifications of Significant Events in Accordance Wilder805.72 "No written response required O'REILLY. J.P. Region 2. Atlanta. Diffice of the Director 81/02/12 19 07820:026
- 8103160591 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines" No response required. D'REILLY, J P Region 2, Atlanta, Office of the Director 81/02/27 ib. 07914, 333
- B103160597 Forwards IE Circular 81-03. 'Inoperable Beismic Monitoring Instrumentation' No response required O'REILLY J.P. Region 2: Atlanta, Office of the Director 81/03/02 to. 07917-048
- BiO3110653 Responds to coments received during exit interview of IE mgs audit conducted 810209-14 Appropriate action will be taken to insure that operations OA plan clearly understood & briefing sessions will be held MICHCLS.T.C. South Carolina Electric & Oas Co 81/03/04. App. 07882-181.
- 8103160821 Forwards revised IE Bulletin Bi-Ol. "Surveillance of Mechanical Bhubbers." w/corrected Pages 5 & 6.0til is added to CP facilities to which bulletin is applicable. Response should include estimate of manpower expended D'REILLY. J. P. Region 2. Atlanta. Defice of the Director Bi/O3/04 ip. 07914:167.
- 8103100374 Submits for documentation purposes, final rept on IE Dulletin 80-16 re potential substantial safety hazard on Rosemount Models (15) to 1152 transmitters, as 800829 response to subjuilletin not issued as final response NICHOLS-T.C. Southern California Edison Co. 81/03/03. 1p. 07867-249.
- B103160872 Sutmits final response to IE Bulletin 80-16. "Potential Misapplication of Rosemont Inc Models 1151 5 1182 Pressure Transmitter Widther A or D Output Codes." Work on nonsafety-related bransmitter is complete.

  NICHOLS: T C South Carolina Electric & Gas Co. B1/03/05 1p 07935: 238
- 8103200242 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 81/03/11. p. 07968:343
- 8103190889 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades" No response required.
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/03/13.
  1p. 07965:276

- 8103270747 Responds to Revision I of IE Bulletin 81-01. 'Surveille of Mechanical Snubbers 'Visual insps % push-pull testing unil be performed on snubbers installed on safety-related sys by 810701 Tests uill be completed by 810821 NICHOL8-T C. South Carolina Electric & Oas Co 81/03/17 29p 080.45 077
- 8103310905 Responds to Revision 1. Suppl 2 to IE Sulletin 79-14, "Sotsmic Analysis for At-Built Safety-Related Piping Sys " Two new procedures re preparation of field drawings & statches & field engineering have been added NICHDLS. T C South Carolina Electric & Oas Co 81/03/19 2pp 08088 148
- 8103270859 Responds to NRC ltr re violations noted in IE Insp Rept 50-395/81-03 Corrective actions procedures re records control have been revised fire retardant filing facilities have been obtained & sys for control of records is undercay NICHOLS T.C. South Carolina Electric & Oas Co 81/03/20 4pc 08046 205
- S Reportable occurrences. LERs & related correspondence
- 8103030832 Submits interim rept re-seismic qualification of Agasta relays supplied in relay panels rfg by GE.initially reported on 810106 Manufacturer being contacted to obtain necessary info to verify qualification of relays NICHOLB-T C. South Carolina Electric & Gas Co 81/02/05 1p 07796-168
- 8103100262 Interim deficiency rept re defective 480V switchgear trunits. Initially reported on 801126 Problem Jopower shields has been corrected investigation of IAN 504 & multi-amp tests is in progress final rept will be provided by 810330 NICHCLB. T C South Carolina Electric & Oas Co 81/03/06 4pp 07865, 192
- 8103170448 Interim deficiency rept.originally reported on 810204.r moisture in cooling pump motor 1A due to grounding Motor dried & megger readings acceptable Stator windings to be re-insulated to insure motor integrity Final rept to follow NICHOLS.T.C. South Carolina Electric & Oas Co. 81/03/10 2pp 07923 211
- B103170451 interim deficiency rept.originally reported on B10204.p potential substantial safety hexard per ICCFR21 re-pinched wires in safety-related square 0 motor control ctr Motor control ctr utring tie revisions being developed NICCIDLS.T C Bouth Carolina Electric & Oas Co B1/03/10 Jp 07923 213.
- 8103170526 Final deficiency rept.originally reported on 810217.per IOCFR21 re qualification of Agastat relays in vendor supplied equipment Relays moved to panel unlower response spectrum Reparted per 10CFR50 55(c) procedure NICHOUS.T.C. South Carolina Electric & Qes Co 81/03/10 2pp 07929 335
- B103170578 Interim deficiency rept.originally reported B10205, per 10CFR21 re missing air baffle in GE twergency feedwater pump motor 18 Motor shipped w/o air baffle Air baffle prodered NICHCLS.T.C. South Carolina Electric & Gas Co 81/03/10. 2pc 07929 342.
- 9103190643 Finel Part 21 rept re improper heat treatment of A-490 from Bouthern Bolt Co Caused by operator error at heat treatment plant Bolts replaced.
  NICHOLS, T. C. South Carolina Electric & Gas Co. 81/03/16. 4pp. 07964:084.
- 8103230690 Final potential significant deficiency rept re valve actuator not fully assembled initially reported on 810113. Condition not reportable per 10CFR90 95e. NICHOL8.T. C South Carolina Electric & Gas Co. 81/03/17. 1p. 07973:392
- 9103250440 Final deficiency rept re lack of full penetration welds attachments to Class 1 pipe, originally reported on 800730. All Class 1 welds reworked Class 2 & 3 welds re-examined. Approx ten hangers left to be corrected Procedure revised. NICHOLS T. C. South Carolina Electric & Oas Co. 81/03/17. 3pp. 07996:198

# DOCKETED ITEMS

- 6103270540 Final deficiency rept on substantial safety hazard re 480-xclt ITE breater failure to trip.initially reported 8102003 per Part 21 Procedure revisions initiated to include aid) insplof operating rechanism Retesting is 40% complete AICHO-5.T C South Carolina Electric & Gas Co 81/03/20 2pp 08046/233
- 8:33279620 Interim rept re potential significant deficiency or potential substantial safety hazard re circuit board failure in Westinghouse 7300 nuclear power plant control instrumentation, initially reported on 810219 MICHOLS, T.C. Bouth Carolina Electric & Oas Co. 81/03/20 ip
- 9103309070 RQ. recently, insufficient time noted for operators to take required actions in two boron dilution events Cause not stated Shutdown margin for Modes 4 & 5 will be changed. Source range setpoint will be changed to 2 times background MICHOLS. I C. South Carolina Electric & Cas Co. 81/03/23 ip 09355-320
- T. Hearing transcripts on non-antitrust matters
- 9103030492 Transcript of ACR8 Subcommittee on Electric Power 010226 deeting in Columbia.9C refacility OF review Pp 1-227 Elective surmary of findings encl e ACP8 Advisory Committee on Reactor Safeguards 81/02/26 23550 07801.293
- 6103030475 Transcript of ACRS Subcommittee on Electric Power 810227 neeting in Columbia-SC refacility CL review Pp 228-513 Slide presentation encl 

   ACPB Ajvijory Committee on Reactor Safeguards 81/02/27 36098 07802 166
- 6103180476 Transcript of ACRS Subcommittee on Surmer OL 810311 meeting in Washington. DC Pp 1-282 Viewgraphs encl e ACRE Advisory Committee on Reactor Safeguards 81/03/11 383pp. 37940 041
- J Congressional/Executive Correspondence
- BIOGRADON Forwards fourth munthly status rept to Congress for BIOLIN-CRID Rept discusses actions taken on licensing reviews of new facilities Rept will be amended to include add) info requested on BIORIT KAPHERRER.C. Office of Congressional Affairs 81/02/27. 3pc.
- 8103270110 Responds to request for rept on possible add1 improvements to NAC licensing process legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process

  MEMORIE.J M Commissioners 81/03/12 Spp
- --8103270931 Submits recommendations to expedite impacted OL hearings Code should include set of TMI-related CL requirements ASLAB decisions on fuel loading to low power testing should be indediately effective

  BICAMIT. L. Dffice of the General Counsel 81/02/23 10pp
- --8103270947 Submits recommendations to scheduling personnel resources & hearing mpt for OL proceedings Panel must obtain examption from Birling freeze for two recently appointed chairmen.

  COTIER 8 P. Atomic Safety and Licensing Board Panel 81/02/25 33pp.
- DOCKET 53-396 UNIV. OF VIRGINIA CAVALIER REACTOR
  O Inspection reports. IE Bulletins & correspondence
- 6103020368 Forwards IE Circular 81-02. "Performance of NRC-Licensed individuals While on Duty." No written response required 8'REILLY, J. P. Region 2. Atlanta. Office of the Director. 81/02/09 1p 07795: 273.
- A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidalines in NUREO-0612. Forwards NRC position re-interim actions & request for add info EISEM-NT, D. O. Division of Licensing 80/12/22. 30pp

- 8102020030 Forwards request for add1 info re HPP88-0A-004.Revision operational OA program description.Commitment required reducation & experience for director position HAASS.W P Quality Assurance Branch. 81/01/14. 5pp
- BiO3190387 Ltr to all licensees of operating plants & applicants OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdoun-replacement parts & NUREO-0737. ETSETHHUF.D O. Division of Licensing 81/01/19 app
- 8103120014 Ltr to all licensees of operating plants.CP holders & applicants.escept Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for addl snfo re control of heavy loads EISENHUT.D 9. Division of Licensing 81/02/03 6pp.
- B103250024 Ltr to all power reactor licensees & license applicant MAREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D. O Division of Licensing 81/02/20 App
- B103100169 Comments on NRC 801120 ltr re review of defects in sacrificial shield wall Licensee proposed corrective weld at 541-9t elevation const joint is acceptable, but other actions do not nest NRC criteria.

  TEDESCOR L Assistant Director for Licensing 81/02/25 3pp 07853:184
- 8103230030 Ltr to all licensees of operating nuclear power plants applicants for GLs (except 8t Lucie.Units 1 & 2). Requests util review to determine capability to mittgate station blackbout event & promptly implement emergency procedures EIEENHUT.D.O Division of Licensing 81/02/25. 3pp.
- 8103170225 Ltr to all 8WR licensess (except Humboldt Bay & LaCros requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision i to NUREO-0313. Model Tech B
- ---Bi03170266 Model Tech Boecs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 surveillance requirements for ABME Code Class 1,2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements a General Electric Co B1/02/26 4pp.
- 8103170653 Ltr to holders of CPs & applicants for ELs (BWRs) requireview of AGME Class 1,2 & 3 pressure boundary piping safe ands & fitting mail per guidelines of encl Revision 1 to NUREO-0313. Model Tech Specs only encl.

  EISEMBUT.D.O Division of Licensing 81/02/26 3pp.
- B103230B13 Generic Ltr B1-06 to all CP holders & D. applicants re 10CFR90 75(e), "Periodic Updating of FSARs:" effective B00722 Info re FSAR legal status format & content encl EJBENHUT.D.Q Division of Licensing. 81/02/26
- B103140191 Requests addl info re matl properties of primary containment, including modulus of elasticity. Poisson ratio yield, fracture & witimate stress of plates & reinforcing members.
- 8103110382 Forwards request for add1 info re Mark II containments TEDESCO.R.i.. Assistant Director for Licensing. 81/03/04. 3pp

07918: 319.

TEOESCO, R. L. Assistant Director for Licensing. 81/03/02 2pp

- 07684:130.

  8103160266 Requests 810331 followup meeting to 810127 meeting regeology & seismology of Hanford Reservation.
- B103310804 Ltr to all licensees of operating plants applicants for the holders of CPs forwarding BECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment.
  E18EP4HUT.D 0 Division of Licensing. 81/03/10. 6pp.

TEDESCO.R. L Assistant Director for Licensing 81/03/06. 2pp

- BIO3230322 Notification of BIO331 meeting w/util in Bethesda.MD to discuss site geology & seismology. LYNCH.M.D. Licensing Branch I. BI/O3/I3 3pp. 07973.018.
- 8103200444 Forwards Suppl 2 to NUREG-0487. "Mark II Containment L. Plant Program Load Evaluation & Acceptance Criteria" & Onlary issue apar Supplement No. 1981 meeting w/Mark II

09062 305

#### ノいしんとしとひ ししにいる

A7700 140

- 8103250379 Forwards request for additiontainment sus into for CL application review Required regulatory staff positions identified Items 022 OEB through 022 105 feel u/proposed hudrosen recombines TEDESCO.R.L. Assistant Director for Licensing 81/03/16 17pp 08022 144
- 8103250694 Requests submittal of revised GA program by 810410, including Bechtel GA program description for const manager activities TEDESCO.R L. Assistant Director for Licensing 81/03/IB 25p
- 8103310147 Requests add1 info re proposed reactor fuel jeston in order to complete review of Section 4.2 of FBAR Comments & info to assist in response encl. TEDESCO, R. L. Assistant Director for Licensing 81/03/24 600
- 8103310914 Surrary of 810313 meeting w/Mark 11 owners group resuppression good temp limit & T-quencher load spec H/o encl list of ettendees & meeting handout
- B103310166 Responds to 810220 request for exemptions from requirements of AMS DI.1 for 2) weld joints in sacrificial shield wall NPC accepts all but two weld joints u/o corrective action based on technical evaluation & util rationale TEDESCO.R. L. Assistant Director for Licensing 81/03/25 3pp

B1/03/24 356

F Security, medical, emergency & fire protection plans

Generic Leanes Branch

- 8:033:0338 Ltr to all licensees of operating plants & holders of CPs Porwarding NUREG-0096. "Functional Criteria for Emergency Response Fecilities." Criteria describe acceptable method for meeting MAC requirements W/o enci EISENHUT, D.G. Division of Licensing B1/03/05 And
- 8103310512 Forwards 801212 1tr requesting NRC concurrence w/location of offsite emergency operations facilities Facilities are technically adequate w/o add1 backup facilities at greater than 10 miles despite NUREO-0596 guidance. BBUCHEY, Q D. Washington Public Power Supply System 81/03/20 to. 08059 197
- --Bi03310520 Requests NRC concurrence re adequacy of location of offsite emergency operation facilities. Util should not be penalized a required to relocate facilities if current NRC ouidelines are modified BOUCHEY.0 D. Hashington Public Power Supply System B0/12/12. 3pp 09059:198
- K. Utility Final Bafety Analysis Report (FSAR) & erends
- BIO3300075 Forwards Amend 13 to FBAR.
  BOUCHEY, O. D. Heshington Public Power Supply System 81/03/17 2pp. 08054:001
- --8103300078 Amend 13 to FBAR.

   Hashington Public Power Buppig System. B1/02/28. 650pp. 08054:003
- 8103040207 Forwards 1E Insp Rept 50-397/80-20 on 801101-30 No

9 Inspection reports. IE Bulletins & correspondence

- noncompliance noted.

  SPENCER: 0 8 Region 5: San Francisco. Reactor Construction & Engineering Support Branch. 81/01/09. 2gc. 07813:141.
- --B103040219 IE Inep Rept 50-397/80-20 on B01101-30. No noncompliance noted Major areas inspected:licensee & contractor activities to re-eveluate & improve detailed work methods. TOTH.A. D. Region 5. Sen Francisco. Office of the Director. DODBs.R T. Region 5. Sen Francisco. Reactor Construction & Engineering Support Branch. 81/01/08 6pp. 07813:143.
- 8103100029 Forwards 1E Insp Rept 50-397/80-22 on 801201-31 No noncompliance noted. Region 5. San Francisco. Reactor Construction & SPENCER, O. S. Engineering Support Branch 81/01/27 2pp 07862:117
- ~-8103100036 IE Insp Rept 50-397/80-22 on 801201-31.No moncompliance noted. Major areas inspected: review of licenses preparations for installing sacrificial wall girth weld.

  TOTH,A D. HAUST.D.P. Region 5. San Francisco. Office of the Director. OGDOB.R.T. Region 5. San Francisco. Reactor.

  COnstruction & Engineering Support Branch. 81/01/26 7pp. 07862:119

- 8103050729 Forwards JE Inso Rept 50-397/80-19 on 801104-07 No. Engineering Support Branch 81/01/28 200 07829 036
- --9103090741 IE Inso Rept 50-397/80-19 on 801104-07 No noncompliance noted Major areas inspected licensee action on open enforcement items & preparation for repair of deficiencies in sacrificial shield wall in sacrificial shield wall HAIST, D. P., WAONER, H. J. D'ANGELO, A. J. Region S. San Francisco Office of the Director 81/01/27 10pp 07828 038
- 8103030434 Act receipt of 801126 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-397/80-16 SPENCER.0 S Region 5. San Francisco. Reactor Construction 6 Engineering Support Branch 81/02/02 ip 07789-142
- --8103030799 Forwards IE Insp Rept 50-397/80-16 on 800901-30 & notin
- Officering Segion 5. Ban Francisco. Reactor Construction & Engineering Support Branch BO/11/04 2pp 07769:147

--8103030805 Notice of violation from insp on 800901-30
\* Region 5. San Francisco, Office of the Director 80/11/03

- --BIO3030Bill IE losp Rept 50-397/80-16 on B00901-30 Honcompliance TOTAL AD THE STATE OF THE STATE
  - Engineering Suggert Branch 80/11/03 11gg 07789 150
- 8103020081 Forwards 1E Circular B1-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required ENGELKEN.R. H. Region 9. San Francisco. Office of the Director 81/02/09 1p. 07787-319 8103200901 Forwards Suppl 5 to LE Bulletin 80-17. 'Failure of Contro Rods to Insert During Scram at BLR " No written response
- required ENGELKEN R. H Region 3. San Francisco. Office of the Director 81/02/13 ip. 07967-232 8103240693 Forwards IE Insp Rept 50-397/81-01 on 810108-30 No
- noncompliance noted.

  SPENCER.G.S Region 5. Ban Francisco, Reactor Construction & Engineering Support Branch 81/02/18 2pp. 07983 217
- --8103240697 IE Insp Rept 50-397/81-01 on 810108-30 No noncompliance noted Major areas inspected licensee & contractor activities to re-evaluate & improve detailed work rethods. TOTH.A D. JOHNSON.A Region 5. San Francisco. Diffice of the Director. SPENCER.O B Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 81/02/12 07987 219
- 8103250001 Forwards JE Insp Rept 50-597/81-02 on 810127-30 No noncompliance noted. BPENCER: 9.8 Region 5. Ban Francisco, Reactor Construction & Engineering Support Branch. 81/02/20 2pp 07998.001
- --8103250004 IE Insp Rept 50-397/81-02 on 810127-30 No noncompliance noted. Major areas inspected const items including licenses action on open enforcement items & preparation for repair of deficiencies in sacrificial shield wall.
- HAIST D P., WACKER, W J., BURDDIN, J.F. Region 5, San Office of the Director, BI/02/19 14pp. 07998-003. Region 5. San Francisco.
- 8103170004 Forwards IE Circular 81-03, "Inoperable Seismic Monitoria Instrumentation " No response required ENOBLEEN.R H Region 3, San Francisco, Office of the Director 81703702. pp. 07930:268
- 8103160982 Forwards revised IE Bulletin 81-01, "Burveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. ENGELKEN.R.H. Region 5. Ban Francisco. Office of the Director Bi/O3/04. ip 07914:361
- 0103120186 Notifies that IE requested that enc) preservice insp & te requirements for snubbers be included in licensing process Requests that requirements to insure snubber operability be implemented. TEDESCUR L. Assistant Director for Licensing. 81/03/06. 6pp. 07903:013
- 8103200240 Forwards IE Info Notice 81-06. "Failure of ITE Model K-60 Circuit Breaker." No response required

786 Deficiency rept re overloads on supports for spray cond 786 Deficiency rept re overloads on supports for spray pund gifnitially reported on 801114 filssing alial restraint will be installed by contractor. CK.R Q Washington Public Power Supply System 81/02/23 2pp

- 416 Interior deficiency rept to leakage from vitimate heat sink pond A.fmittally reported 810207 Addl deta will be ned to verify leakage rate Spray pond A vill them be ed & inspected for leakage path K.R.O. Washington Public Power Supply System 81/03/05 2pp 7:241
- 497 interim deficiency rept re containment mod GA program Cown, initially reported on 801215 Final rept is cown.initially reported on UDI219 Final rept is oned until BID413.due to enjambed scope of entation review & need for addl welding insps CK.R G. Washington Public Power Supply System. U1/03/10. 2pp 5:274
- 534 Interim deficiency rept we design verification of Besemic Bry 1 Quality Class I heating ventilation % and it louing by hangers Revised contractor procedures
- Fen approved K.R.G. Uash D. 133 Washington Public Power Susply System 81/03/10 200
- 0-100 BREARON HARRIS NUCLEAR POWER PLANT, UNIT 1 Cation/construction stage documents & correspondence
- TIP Live to all licensees of operating plants, applicants for holders of CPs re control of heavy loads Requests y per guidelines in NUREO-OSI2 Forwards NRC position re m actions 5 request for addl info. Division of Licensing, 80/12/22 30pp Gr. n q
- 197 Ltr to all licensees of operating plants & applicants for holisers of CPs to program for environ qualification for provided electrical equipment items addressed to tald shutdown.replacement parts & NURCO-0737 UT.D 2 Division of Licensing. 81/01/19 6pp
- 14 Ctr to all licensees of operating plants, CP holders & DL Ants.ezcept Indian Point 2 & 3,Zion i & 2 & THI-1, ding Inadvertently omitted pages from NRC 801222 t for add info re control of heavy loads. UT.D Q. Division of Licensing. 81/02/03 App.
- 69 Ltr to all operating plants & CP holders forwarding ication of TMI Action Plan Item III A 1.2 re upgrade repency support facilities Requests confirmation within a that implementation dates will be mot ur p o Division of Licensing. 81/02/18. (2pp
- 24 Ltr to all power reactor licensees & license applicants re 0619 criteria-Footnote 2 in Table 2 contains error due kage testing deletions.Licensee may submit analysis to y use of smisting low flow controller UT.D.O Division of Licensing, 81/02/20. Bpp
- 00 Contents on review of info submitted in applicant 800919 % its re GA organizational changes & ANBI N45 2.2 1972 iton of info does not change acceptability of GA of Quality-related changes are acceptable. CDD: 8 J Licensing Branch 1 81/02/25 2pp. 07877.322

- BID33:0338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREC-06%. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT, D. G. Division of Licensing 81/03/05, 600
  - O Inspection reports. IE Sulletine & correspondence
- 8103020186 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required O'REIL(V.J.P. Region 2. Atlanta. Office are the Distress." 840000 O'REILLY, J P Region 2. Atlanta. Office of the Director 81/02/09
- 6103040064 Act receipt of IE Insp Repts 50~400/80-28.50~401/80-26. 30-402/80-26 t 30-403/80-26 on 801201-26 No proprietary 1000 HOXE, P H Carolina Power & Light Co 81/02/10 to 07819 294
- --8103040074 Forwards IE Insp Repts 50-400/80-28.50-401/80-26. 50-402/80-26 % 50-403/80-26 on 801201-26 No noncompliance notes. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/30 2pp 07819 295
- --8103040089 IE Insp Repts 90-400/80-28.50-401/80-26.50-402/80-26 & 30-403/80-26 on 801201-26 No nancompliance noted Major areas inspected; welding, matl control, concrete, soils, areas inspected weighting at a control control concrete.soils, cadualding & containment testing.

  MAXMELL 2 F Region 2. Atlanta. Office of the Director
  BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering
  Support Branch 81/01/30 4pp. 07819 297.
- 8103070413 Ack receipt of IE Insp Repts 50-400/81-01, 50-401/81-01, 50-402/81-01 & 50-403/81-01 on 810106-09 No proprietary HOWE.P W Carolina Pawer & Light Co 81/02/18 ip 07849 180
- --8103090422 Forwards IE Insp Repts 50-261/81-01.50-324/81-01. 50-325/81-01.50-400/81-01.50-401/81-01.50-402
- --8103090430 IE Insp Repts 50-261/81-01.50-324/81-01.50-325/81-01, 50-400/81-01.50-401/81-01.50-402/81-01 & 50-403/81-01 on 810106-09 No noncompliance noted Major areas inspected. Closeout of previously identified enforcement matters

  GRONALEE,V L Region 2. Atlanta. Office of the Director

  CONLON.T. E. Region 2. Atlanta. Reactor Construction & Engineering

  Support Branch 81/02/09 6pp 07849: 183.
- 8103160659 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No response required. Region 2. Atlanta. Office of the Director. 81/03/02. O'REILLY, J. P.
- 8103170062 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation " No response required D'RETLLY, J. P Region 2. Atlanta, Office of the Director 81/03/02 Lo
- 8103170083 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/03/04
- B103200301 Forwards IE Info Notice B1-06, "Failure of ITE Model K-600 Circuit Breaker." No response required O'REILLY, J P. Region 2, Atlanta, Diffice of the Director 81/03/11.

- 50-402/81-04 & 50-409/81-04 on 810202-20 No proprietary info. HC:E:P M. Carolina Power & Light Co. 81/03/12 1p. 08043-218
- --8103270518 Forwards 1E Insp Repts 50-400/81-04.50-401/81-04. 30-402/81-04 & 50-403/81-04 on 810202-20 No noncompliance nated LEMIS.R.C. Region 2. Atlanta. Dffice of the Director 91/03/04 2pp 08043.219.
- --8103270934 IE Insp Repts 50~400/81~04.50~401/81~04.50~402/81~04 & 50~403/81~04 on 810202~20 No noncompliance noted. Major areas inspected concrete.matl control.mechanical equipment & coating MAXHELL.0 F , JULIAN.C Region 2. Atlanta. Office of the Director 81/03/03 6pp 08043.221
- 8103190871 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades." No response required D'REILLY, J.P. Region 2. Atjanta. Office of the Director 81/03/13 to.
- 8]03260487 Ack receipt of 810305 ltr informing NGC of steps taken to correct violations noted in 1E Insp Rapts 50-400/81-02, 50-401/81-02, 50-402/81-02 & 50-403/81-02 LEHIS,R.C. Region 2, Atlanta, Office of the Director. 81/03/19 lp. 08041 003
- --B103260901 Responds to NRC B10212 1tr re violations noted in EE Insp. Repts 50-400/81-02.50-401/81-02.50-402/81-02 \$ 50-403/81-02 Corrective actions all seismically installed bores installed w/o instruction details removed.

  HCME.P. W. Carolina Power & Light Co. B1/03/05 329 CB041 C04.
- --8103260521 Ack receipt of IE Imap Repts 50-460/81-02, 50-401/81-02, 50-402/81-02 & 50-403/81-02 on 801229-810130 No proprietary info.

  HOUE, P. W. Carolina Fouer & Light Co. 81/02/18 ip 08041 007.
- --B103260536 Forwards 1E Insp Repts 30-400/81-02, 50-401/81-02, 50-402/81-02 & 50-403/81-02 on 801229-810130 & notice of violation MJRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 81/02/12 2pp 08041 008.
- --8103260542 Notice of violetion from inst on 801227-810130.

   Region 2, Atlenta, Office of the Director. 81/02/12 is
- --8:03260332 IE Insp Repts 30-400/81-02.30-401/81-02.30-402/81-02 & 30-403/81-02 on B01229-310130 Nancompliance noted Electrical Conduit Dus Bi482-88 installed w/o use of appropriate drawing, spec, procedure or instruction MAKMELL.O.F. Region 2. Atlanta. Office of the Director BRYANT.J.C. Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 81/02/10 6pp 08341.011.
- S. Reportable occurrences. LERs & related correspondence
- B103110600 Final Deficiency Repts 400/79-14-01,401/79-14-01,402/79-13-01 & 403/79-13-01 re procurement fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action taken CHIANGIN J Carolina Power & Light Co. B1/02/27, 5pp, 07887 110
- Bio3i10716 Interim deficiency rept re omission of protective coating & existence of damaged coating on Unit 1 containment liner, initially reported 801i14. Corrective actions scheduled for completion by 810315.

  CHIANGIN J. Carolina Power & Light Co. 81/02/27 2pp 07895:029
- 8103230745 Final deficiency rept re omission of protective coating & existence of damaged coating on Unit I containment liner due to concrete placement past required point inspectiteria. FCR-AS-287.written to allow coating u/o surface preparation. CHIANGLN. J. Carolina Power & Light Co. 81/03/16. 4pp. 07974.163
- DOCKET 50-401 SHEARCH HARRIS NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- BIO3190732 Ltrs to all licensess of operating plants, applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position relinterim actions & request for add

- OLs & holders of CPs we program for environ qualifit of safety-related electrical equiprent Items addres involve cold shutdown replacement parts & NuREO-073 EISERMUT, D O Division of Licensing 81/01/19 6
- BIO3120014 Ltr to all licensees of operating plants. Cl applicants, except Indian Point 2 & 3, Zion 1 % 2 & To forwarding inadvertently omitted pages from NAC 801; request for addl info re control of heavy loads EISENHUT, D 9 Division of Licensing BI/02/03 60
- 8(03)60669 Ltr to all operating plants & CP holders f clarification of TML Action Plan Item III A 1 2 re of emergency support facilities Requests confirmati 45 days that implementation dates will be net RISENHUT, D O Division of Licensing 81/02/18 1
- B103250024 Ltr to all power reactor licensees & licen MUREO-0619 criteria Footnote 2 in Table 2 contains to leakage testing deletions Licensee may subnit an justify use of existing low flow controller EISENHUT.D O Division of Licensing B1/02/20 B
- B103110260 Comments on review of info submitted in ap 1110 Itrs re GA organizational changes & ANSI N45 2 Evaluation of info does not change acceptability of program Quality-related changes are acceptable VQUNOBLOCO, D. J. Licensing Branch 1 81/02/25 2p
- B103230B13 Generic Ltr 81-06 to all CP holders & OL a 10CFR50 71(e). "Periodic Updating of FSARs." effect 800722 Info re FSAR legal status, format & content to EISENHUI.D O Division of Licensing. 81/02/26 1
- 8103310804 Ltr to all licensees of operating plants a tholders of CPs forwarding BECY-BI-II9 re info nec establish environ qualification of safety-related a equipment EIBENHUT.D O Division of Licensing. 81/03/10 &
- BiO3310518 Notifies that revised corporate OA program implemented by BiO423 to establish new corporate OA MCDUFFIE,M.A. Caroline Power & Light Co. 81/03/26/08078 342
- F Security, medical, emergency & fire protection pla
- Bi03310338 Ltr to all licensees of operating plants & forwarding NUREO-0696. 'Functional Criteria for Eme Rasponse Facilities " Criteria describe acceptable for meeting NRC requirements Myo encl EIBENHUT.D O Division of Licensing 81/03/05 6
- G Inspection reports. IE Bulletins & correspondence
- 0103020186 Forwards IE Circular 81-02. 'Performance of Individuals While on Duty 'No written response req D\*REILLY, J.P. Region 2. Atlanta, Office of the Dirty.
- 8103040064 Ack receipt of LE Insp Repts 50-400/80-20. 50-402/80-26 & 50-403/80-26 on 801201-26 No proprie info. HDWE:P.W. Carolina Power & Light Co. 81/02/10 1
- --Bi03040074 Forwards IE Insp Repts 50-400/80-28.50-4 50-402/80-26 & 50-403/80-26 on 801201-26 Na nonco noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construct Support Branch 81/01/30 2pp. 07819 295
- ~-8103040087 IE Insp Repts 50-400/80-28, 50-401/80-26, 50-403/80-26 on 801201-26 No noncompliance noted areas inspected welding reat; control concrete, soi cadwelding & containment testing.

  MAXHELL: 0 F Region 2, Atlanta, Office of the Di BRYANT, J C. Region 2, Atlanta, Reactor Construct Support Branch 81/01/30 4pp. 07819, 297
- 8103090413 Ack receipt of IE Insp Repta 50-400/81-01. 80-402/81-01 & 50-403/81-01 on 810106-09 No propriatinfo. HOWELP W. Carolina Power & Light Co. 81/02/18 I
- --8103090422 Forwards IE Insp Rapts 50-261/81-01.50-50-325/81-01.50-403/81-01.50-40

- --BEO3090430 IF Insp Repts 90-261/8E-01.50-324/8E-01.50-325/8E-01.50-400/8E-01.50-401/8E-01.50-402/8E-01.50-403/8E-01.50-402/8E-01.50-403/8E-01.on 393036-07 Nu mencompliance noted Kajur areas inspected closecut of previously identified enforcement matters BRD.FLEE.V L. Region 2. Atlanta. Office of the Director BIO2/CY Ans
- 8103160659 For Jards 16 Circular Bt-03. "Inoperable Seismic Monitoring Instrumentation." No response required O'REILLY J.P. Region 2. Atlanta. Diffice of the Director 81/03/02 Ip 07/14 242
- 9:0317CC62 rorwards IE Circular 81-03. Inoperable Seismic Monitoring instrumentation: No response required 0°4E3LLY.J P Region 2. Atlanta. Office of the Director 81/03/02
- 9103175083 Forwards revised IE Bulletin Bi-Ol. "Surveillance of Heckanical Brobbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  B'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/04
- d.C3200331 Forwards IE info Notice B1-Ob. "Failure of ITE Model K-600 Circuit Breaker" No response required CIRCULLY. J.P. Region 2. Atlanta. Office of the Director 81/03/11 ip
- 5103270506 ACK receipt of 12 Insp Repts 50-400/81-04.50-401/81-04. 50-402/81-04 & 90-403/81-04 an 810202-20 No proprietary Info. MOMELP M. Carolina Power & Light Co. 81/03/12 in 08043 218
- --3103270318 Forwards IE Insp Repts 90-400/81-04, 90-401/81-04, 90-402/61-04 % 90-403/81-04 on 810202-20 No noncompliance notes LEMIS R C Region 2. Atlanta, Office of the Director. 81/03/04 2pp 08043 219.
- --0303270534 IE Imap Repts 50-400/B1-04.50-401/B1-04.50-402/B1-04 & 50-403/B1-04 on B10202-20 No noncompliance noted Major areas imapected:concrete.matl control.methanical equipment & coating Makkello F. Utlinno Region 2. Atlanta. Office of the Director B1/03/03 4pp. 68043 221
- 6100150074 Forwards IE Info Notice 81-05. Degraded DC Sys at Pallsades "No response required.

  D'REILLY, J.P. Region 2. Atlanta, Uffice of the Director. 81703/13
  1p.
- 8103260497 Ack receipt of 810305 itm informing NRC of steps taken to correct violations noted in 16 Insp. Repts 50-400781-02.

  50-401791-02.50-402781-92 & 50-403781-02
  LEWIG.R C. Region 2. Atlanta. Office of the Director 81703719

  19 08341 003
- \*\*810326090) Responds to NRC 810212 ltr re violations noted in IE Insp. Repts 50-400/81-02.50-401/81-02.50-402/81-02 & 50-403/81-02 Corrective actions all seismically installed boxes installed U/3 Instruction details removed MCWE.P. U Caroline Power & Light Co. 81/03/05 3pp. 08041 C04
- \*\*\*BI03260521 Ack receipt of IE Insp Repts 50-400/81-02.50-401/81-02. 50-402/81-02 & 50-403/81-02 on 801227-810130 No proprietary info. MGHE.P. W. Cerolina Power & Light Co. 81/02/18. Lp. 08041-007
- --B103260536 Forwards 16 Insp Repts 59-400/B1-02, 50-401/B1-02, 50-402/B1-02 & 50-403/B1-02 on 801229-B10130 & notice of violation MURBIN, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/02/12 2pp 08041 008.
- ~-8103260952 IE lusp Repts 50-400/81-02.50-401/81-02.50-402/81-02 & 50-403/81-02 on 801227-810130 Noncompliance noted Electrical Conduit Box 81482-58 Installed w/o wse of appropriate drawing, spec.procedure or instruction MAXELLOF Region 2. Atlanta. Office of the Director BRYMILJ. C Region 2. Atlanta. Reactor Construction & Engineering Gupport Brench 81/02/10. 6pp. 08941.011.
- S Reportable occurrences. LERs & related correspondence
- 9103110600 Finel Deficiency Repts 400/79-14-01.401/79-14-01.402/79-13-01 & 403/79-13-01 re procurement fabrication & Linsp of engineered plates for concrete embedment & support of sefety-related loads Corrective action taken CHIAROIN J. Caroline Power & Light Co 81/02/27. 5pp 07807.110

- 9103110716 Interim deficiency rept re omission of protective coating & pristance of Jamaged coating an Unit 1 containment liner, initially reported 801114 Corrective actions scheduled for completion by 810315
  CHIANGI.N J Carolina Power & Light Co 81/02/27 2pp 07883 029
- DOCKET 50-402 EHEARON HARRIS NUCLEAR PEWER PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of neavy loads Requests review per guidelines in NUREC-0612 Forwards NRC position re interin actions & request for add info
  EISENHUT.D G Division of Licensing 80/12/22 33pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREO-0737 EISENHUT.D O Division of Licensing GI/OI/19 6pp
- Rio3120014 Lit to all licensees of operating plants.CP holders & Ocapplicants.except Indian Point 2 & 3.2ion 1 & 2 & TMT-1. forwarding inadvertently omitted pages from NRC 801722 request for addl info re control of heavy loads EISEMHUT.D Q Division of Licensing 81/02/03 &pp.
- G103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Iten III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation 3ates will be not EISENHUT. D G Division of Licensing 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria footnote 2 in Table 2 contains ecror due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller.

  EISERHUT, D. O. Division of Licensing 81/02/20. 8pp
- 0103110260 Connents on review of info submitted in applicant 800919 & 1110 ltrs re GA organizational changes & ANGI N45 2 2 1972 Evaluation of info does not change acceptability of GA program Quality-related changes are acceptable YOUNGBLOOD.B J Licensing Branch 1. 81/02/25. 2pp 07877 322
- 8103230813 Generic Ltr 81-06 to all CP holders & D. applicants re 10CFR50 71(e). "Periodic Updatting of FSARs." effective 800722 Info re FSAR legal status.format & content encl EISENHUT.0 0 Division of Licensing 81/02/26
- 8103310804 Ltr to all licensess of operating plants applicants for OLs 8 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT. D 0. Division of Licensing 81/03/10 App
- 610331:3518 Notifies that revised corporate GA program will be implemented by 810423 to establish new corporate GA dept MCDUFFIE.M A Carolina Power & Light Co 81/03/26 2pp. 00078 242
- F. Security, medical, emergency & fire protection plans
- Bi03310338 Ltr to all licensees of operating plants & holders of CPs forwarding NURSQ-0656. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements (Vo enc).
  EIBERHUT.D.O Division of Licensing 81/03/05 App
- Q Inspection reports. IE Bulletins & correspondence
- Bi03020186 Forwards IE Circular Bi-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. Bi/02/09, in
- 8103040064 Act receipt of IE lnsp Repts 50-400/80-28.50-401/80-26. 50-402/80-26 8 50-403/80-26 on 901201-26 No proprietary info MOME P. M. Carolina Power & Light Co. 81/02/10 ip. 07819 294.
- --B103040074 Forwards IE Insp Repts 50-400/80-28.50-401/80-26. 50-402/80-26 & 50-403/80-26 on 801201-26 No noncompliance noted. MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/30 2pp 07819 295

- 8103090413 Ack receipt of 1E insp Repts 50~403/81-01.50-401/81-01. 50~402/81-01 & 50~403/81-01 on 810106-09 to prophietary info MCME.P W. Carolina Power & Light Co. 81/02/18 | [p
- --B103090422 Foruards 1E Insp Repts 50-261/81-01.50-224/81-01. 50-323/81-01.50-402/81-01.50-401/81-01.50-402/81-01 b 50-403/81-01 on 810106-09 No noncopliance noted MURPHY.C E Region 2. Atlants. Reactor Construction & Engineering Support Branch 81/02/09 2pp
- --8103090430 IE Insp Repts 30-261/81-01.30-324/81-01.30-325/81-01. 50-460/81-01.50-401/81-01.30-402/81-01 & 50-402/81-01 on 810106-09. No noncompliance notes Major areas inspectes closeout of previously identified enforcement matters BROHNLEE, V L. Region 2. Atlanta. Office of the Director-81/02/09 Ass
- BiO3iAO659 Forwards IE Circular 81-03, "Inoperable Getect Monitoring Instrumentation" No response required D'REILLY, J. P. Region 2- Atlanta, Diffice of the Director 81/03/02, jp. 07914-242
- 0103170062 Forwards 1E Circular 81-03. Illoperable Seismic Monitoring Instrumentation." No response required Officially. J. P. Region 2: Atlanta, Office of the Director. 81/03/02
- 8103170083 Forwards revised IE Bulletin 81-01, "Surveillance of Machanical Soubters," w/corrected Pages 5 & Change in identification of facilities w/CPs to which bulletin is applicable does not affect will requirements.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/04 to.
- B1D3200301 Forwards IE inpo Notice B1-06. "Failure of ITE Model M=600 Circuit Breaker " No response required D'REILLY, J.P. Region 2: Atlanta, Diffice of the Director B1/03/11 19
- 8103270506 Ack receipt of IE Insp Repts 30-400/81-04, 50-401/81-04, 50-402/81-04 & 50-403/81-04 on 810202-20 No proprietary Info HOME-P-M Ceroline Power & Light Co 81/03/12 lp 68043 218
- --8103270518 Forwards IE losp Repts 50-400/81-04.50-401/81-04. 50-402/81-04 & 50-403/81-04 on 810202-28 No noncompliance noted. LEMIS.R.C. Region 2. Atlanta, Office of the Director 81/03/04 22p 08043 219
- --BI03270534 IE Insp Repts 50-400/BI-04.50-401/BI-04.50-402/BI-04 & 50-403/BI-04 on BI0202-20 No noncompliance noted Major areas inspected concrete. This control mechanical equipment & coating MAXMELL.G.F. JULIANC Region 2. Atlanta, Office of the Director. BI/03/03. App. 08049 221.
- 8103190871 Forwards IE Info Notice 81-05. Degraded DC Sys at Palisades. "No response required.
  D'ARILLY, J.P. Region 2. Atlanta, Direct of the Director 81/03/13
  19
- B103240487 Ack receipt of 810309 ftr informing FRC of steps taken to correct violations noted in IE Insp. Repts 50-400/81-02. 50-401/81-02.50-402/81-02 & 50-403/81-02 LEWIS.R.C Region 2: Atlanta. Office of the Director B1/03/19 Ip 08041:303
- --8103250891 Responds to NRC 810212 ltr re-violations noted in IE Insp Repts 30-400/81-02: 50-401/81-02: 50-402/81-02 & 50-403/81-02 Corrective actions all seismically installed bases installed w/o instruction details renoved. HOME.P. W. Carolina Power & Light Co. 81/03/05. 329 08041 004
- --8103260521 Act receipt of IE Insp Repts 50-400/81-02, 50-401/81-02, 50-402/81-02 & 50-403/81-02 on 601229-810130 No proprietary info. HONE-P.W. Carolina Power & Light Co. 81/02/18. ip 68041 007.

- --815.3260552 IE Insp Repts 50-400/81-02.50-401/81-02.50-402/61-02 50-400/81-02 on B01229-810130 Noncompliance noted Electrical Conduit Box 31482-53 installed w/o use of appropriate drawing speciprocedure or instruction MAXMELL OF Region 2. Atlanta. Office of the Director BRYANT OF Region 2. Atlanta. Reactor Construction & Engine Support Drawn 10/02/10 op 00/01 0:1
- S. Reportable occurrences. LERs & related correspondence
- 8103110600 Final Deficiency Repts 400/77-14-01.401/79-14-01. 402/79-13-01 \$ 403/79-13-01 re procurement fathication \$ inspired plates for cuncrete extendent \$ support of safety-related loads Corrective action taken CHIANGLOD U Carolina Power & Light Co. 81/02/27 Spc. 0268
- 8103110716 Interin deficiency reptire objection of protective coatestates of dahaged coating on Unit 1 containment liner.

  Initially reported 801114 Corrective actions scheduled for completion by 810315

  CHIANGLIN J Carolina Power & Light Co. 81/02/27 2pp. 0768
- DOCAET 90-403 BHEARCH HARRIS NUCLEAR POWER PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- BIO3190732 Ltrs to all licensees of operating plants applicants for the line of CPs recontrol of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position reinterim actions & request for addl info EISENUTED & Division of Licensing 80/12/22 30;p
- 8103190387 Ltr to all licensees of operating plants & applicants OLs & holders of CPs re program for environ qualification of safety-related electrical equipment liens addressed involve told shitdown replacement parts & NUREO-0737 EISENHUT.D 0 Division of Licensing 81/01/19 App
- 8103:20014 Ltr to all licensees of operating plants.CP helders & Capplicants.except Indian Point 2 & 3.2 ion 1 & 2 & TM1-1. forwarding inedvertently Calthed pages from NGC 801222 request for add) info re control of heavy loads EIBERHULD O Division of Licensing 81/02/03 dap
- BIO3160669 Ltr to all operating plants 3 CP Folders forwarding clarification of TMI Action Plan Item [[] A ] 2 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation Jates will be mot EISENMUT.D 0 Division of Licensing 81/02/18 12pc
- B103250024 Ltr to all power reactor licensees & license applicant MUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing seletions Licensee may subsit analysis to justify use of existing low flow controller EISEUHUI.D Q. Division of Licensing 81/02/20 8pp
- 8103110260 Co-ments on review of info submitted in applicant 8009 1110 ltrs re 04 organizational changes & ANSI N45 2 2 1972 Evaluation of info does not change acceptability of 8A program Quality-related changes are acceptable YOUNDBLOOD.6. J Licensing Branch 1 81/02/25 2pp
- B103230813 Generic Ltr B1-06 to all CP holders & OL applicants re 10CFR50 71(e). 'Periodic Updating of FSARs.' effective 530722 Info re FSAR legal status.format & content enci EISENIOT.0 g Division of Licensing 81/02/26 10pp
- B1GD310B04 Ltr to all licensees of operating plants applicants for & holders of CPs forwarding SECY-B1-117 re info necessary to establish environ qualification of safety-related electrical equipment. E1GENHUT-0 9 Division of Licensing B1/03/10 App
- 8103310618 Notifies that revised comparate QA program will be implemented by 810423 to establish new comparate QA dept MCDUFFIE.M.A Carolina Power & Light Co 81703726 2pp

- F Security, medical, emergency & fire protection plans
- 91033:0339 Ltr to all licensess of operating plants & holders of CPs forwarding NUNEO-0896 Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements U/o encl Electivity D 2 Division of Licensina 81/03/09 App.
- 4 Inspection reports. IE Bulletins & correspondence
- 9103020185 Forwards IE Circular 81-02. Performance of NRC-Licensed Individuals While on Duty 'No written response required DABILLY, J.P. Region 2. Atlanta. Office of the Director 81/02/09 ip
- \$103349364 Act receipt of IE lnsp Repts 50-400/80-28, 50-401/80-26. 50-402/83-26 & 50-402/83-26 on 801231-26 No proprietary info MDJE.P W Carolina Power & Light Co 81/02/10 1p
- --Bi03340074 Forwards IE Insp Repts 50-460/80-28.50-401/80-26. 50-402/80-26 & 50-403/80-26 on 801201-26 No nancompliance noted MJRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/30 200
- --Bi09040089 IE Insp Repts 50-490/80-28.50-401/80-26.50-402/80-26 & 50-403/80-26 on B01201-26 No noncompliance noted Major areas inspected welding-mail control concrete soils. cadwalding 6 containment testing MakMECL.9 F Region 2. Atlanta. Office of the Director B1/01/30
- 9:03390413 Ack receipt of TE Trisp Repts 50-400/81-01.50-401/81-01. 50-402/81-01 t 50-403/01-01 on 810105-09 No proprietary info NO-E-P N Carolina Power & Light Co 81/02/18 to
- --8103070422 Forwards IE Insp Repts 99-261/81-01, 50-324/81-01. 50-325/81-01, 50-400/81-01. 90-401/81-01. 90-402/81-01 & 50-403/81-01 on B10106-09 No moncompliance noted null first CE Region 2. Atlanta, Reactor Construction & Engineering Support Scanch 81/02/09 2pp
- --8103090439 IE Insp Repts 50-261/81-01.50-324/81-01.50-325/81-01. 50-400/81-01.50-401/81-01.50-402/81-01 5.50-403/81-01 on 810105-09 No noncompliance nobed Hajor areas inspected: closeout of previously identified enforcement matters 88CARLEE.V.L. Region 2. Atlanta. Office of the Director 81/02/99 505
- BiO3160659 Forwards IE Circular Bi-O3, "Inoperable Seismic Monitoring Instrumentation" No response required D'REILLY, J.P. Region 2: Atlanta, Office of the Director. 81/03/02. Ip
- BiO3170082 Forwards IE Circular 81-03. 'Inoperable Beismic Monitoring Instrumentation' No response required O'REILLY, J.P., Region 2. Atlanta, Office of the Director. 81/03/02.
- B103170083 Forwards revised [E Bulletin B1-01. "Burveillance of Mechanical Snubbers." J/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  D'REILLY. J. P. Region 2. Atlanta, Diffice of the Director. B1/03/04, 10
- 8103203301 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 81/03/11, 10
- 8103270506 Ack receipt of TE lnsp Repts 50-400/81-04, 50-401/81-04, 50-402/81-04 & 50-403/81-04 on 810202-20. No proprietary 11fc.

  HCME.P.M. Carolina Power & Light Co. 81/03/12. 1p.
- --8103270518 Forwards IE Insp Repts 50-400/81-04, 50-401/81-04, 50-402/81-04 & 50-403/81-04 on 810202-20 No noncompliance notes LEMIS.R C. Region 2. Atlanta, Office of the Director. 81/03/04. 299
- --8103270534 IE Insp Repts 50-430/81-04.50-401/81-04.50-402/81-04 & 59-403/81-04 on BIO202-20 No noncompliance noted Major areas inspected; concrete mati control mechanical equipment & coating PARMEUL, O. F. Region 2. Atlanta. Office of the Director. 81/03/03 & Spp.

- BIO3190871 Forwards IE Info Notice 81-05: "Degraded DC Bys at Palisades." No response required D'REILLY.J.P. Region 2. Atlanta. Office of the Director BI/03/13
- 8103260487 Act receipt of 810335 ltr informing ARC of steps telen to correct violations noted in IE Insp Repts 50-402/81-02. 50-401/81-02. 50-402/81-02 & 50-402/81-02 
  LEWIS.R C Region 2. Atlanta. Office of the Director 81/03/19
- --8103260901 Responds to NRC 810212 ltr re violations noted in IE Insp Repts 50-400/81-02.50-401/81-02.50-402/81-02 t 50-403/81-02 Corrective actions all seispically installed boxes installed w/o instruction details removed MOMELP.N Carolina Power & Light Co. 81/03/05 3no
- --8103260521 Ack receipt of IE losp Repts 50-400/81-02.50-401/81-02. 30-402/81-02 & 50-403/81-02 on 801229-810130 No proprietary info. HOWE.P.W. Carolina Power & Light Co. 81/02/18 ip
- --8103260536 Forwards IE Insp Repts 50-400/81-02, 50-401/81-02, 50-402/81-02 on 801229-810130 & notice of violation.
  MURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Subgort Dranch 81/02/12 200
- --8103260552 IE Insp Repts 50-400/81-02.50-401/81-02.50-402/81-02 & 50-403/81-02 on 801227-810130 Noncompliance noted Electrical Conduit Por B1482-58 installed w/o use of appropriate drawing, spec.procedure or instruction MAXWELL.9 F Region 2. Atlanta. Office of the Director 81/02/10 fee
- S Reportable occurrences, LERs & related correspondence
- B103110600 Final Deficiency Repts 400/79-14-01. 401/79-14-01. 402/79-13-01 & 403/79-13-01 re procurement. Pabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action taken CHIANGI.N J. Caroline Power & Light Co. B1/02/27. Spp.
- B103110716 Interim deficiency rept re omission of protective coating besistance of damaged coating on Unit 1 containment liner.
  Initially reported B01114 Corrective actions scheduled for completion by B10315.
  CHIANQIN J Caroline Power & Light Co. B1/02/27 2pp.
- DOCKET 80-404 NORTH ANNA POWER STATION. UNIT 3

  A. Application/construction stage documents & correspondence
- B103120023 Notifies of fee required for review of VEP-FRD-36. "Control Rad Reactivity Worth Determination by Rod Bwap Technique."

  HILLERIN D License Fee Management Dranch B1/03/02. 1e.
- G. Inepection reports: IE Bulletins & correspondence
- 8103020177 Forwards 1E Circular Bi-O2. "Performance of NRC-Licensed Individuals While on Duty " No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 81/02/09 ip 07785-271.
- 8103160713 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines," No response requires. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/02/27 1p.
- 8103160864 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation," No response required. O'REILLY-J-P. Region 2, Atlanta, Office of the Director. 81/03/02. 1p. 07916:343
- 8103170067 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Snubbers." w/corrected Pages 3 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 81/03/04. ip 07939-189.
- 8103200314 Forwards IE info Notice 81-05, "Failure of ITE Model K-600 Circuit Breaker." No response required.
  D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/11.
  1p

8103200030 Forwards 1E Info Notice 81-05. Degraded DC Sys at Palisades "No response required O'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/03/13

DECKET 50-405 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 8:03:20023 Notifies of fee required for review of VEP-FRD-36. "Control Rod Reactivity Worth Determination by Rod Bwap Technique."
  HILLERIN D License Fee Management Branch. 8:1/03/02 1p
- O. Inspection reports: IE Bulletins & correspondence
- 8103020177 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Duty." No written response required D'REILLY.J.P. Region 2, Atlanta. Office of the Director 81/02/09.
- 8103160364 Forwards IE Gircular 81-03. "Inoperable Setemic Monitoring Instrumentation" No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 81/03/02
- Bi0gi70067 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not effect util requirements

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/04
- BiO3200314 Forwards IE Info Natice Bi-Ob. 'Failure of ITE Model K-600 Circuit Breaker.' No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/11 10.
- 6103200030 Forwards IE Info Notice 61-05, "Degraded DC 8ys at Palisades." No response required.
  D'REILLY, J.P. Region 2. Atlante, Office of the Director. 81/03/13 in.

OCCKET 50-406 TUSARGEE INST. RESEARCH REACTOR

G Inspection reports: [E Bulletins & correspondence

B103020159 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals Shile on Duty " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/09 lp. 07788:074

DOCKET 30-407 UNIV OF UTAH RESEARCH REACTOR

- A Application/construction stage documents & correspondence
- 8303030138 Forwards revised NRC Region 4 organization chart, effective 810227. SEYFRIT, K. V. Region 4. Dailes. Office of the Director 81/02/17 200.
- F. Security, medical, emergency & fire protection plans
- 8101070341 Releases public version of univ emergency plan for research reactors.
  FELTON.J.M. Division of Rules and Records 80/12/02. 1p. 07414:300.
- ---8101220624 Forwards public version of univ reactor emergency plan, TURLEY, R.E. Utah, Univ of. 80/01/31. 1p 04025:115.
- --Biol070345 Public version of univ reactor emergency plan. BAND001BT.0.M , JENSEN.C M Utah. Univ of. UTEC ME 80-015. 80/01/01. 18pp. 07414-301.
- O. Inspection reports: IE Bulletins & correspondence
- 8103200214 Forwards IE Circular 81-02, "Performance of ARC-Licensed Individuals While on Duty " No written response required. SEYFRIT.H V. Region 4, Dellas, Dffice of the Director. 81/02/09, ip. 07972:049

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

- F Security, medical, emergency & Pire protection plans
- B103090326 Forwards Suppl 1 to 790727 fire protection safety eva supporting Amend 17 to License DRR-49 Unresolved fire protection items also enci CRUTCHFIELD. O Operating Reactors Branch 5 81/02/13 2pp 07847-211
- --B103090334 Suppl 1 to 790727 fire protection safety evaluation supporting Amend 17 to License DPR-45 a Office of Nuclear Reactor Regulation, Director 81/02/13 1400 07847 213
- BiO3200359 Forwards FR notice re-sitension of time for completion fire protection mods from 810225 to 811101 DENTON.H R Office of Nuclear Reactor Regulation. Director 81/02/13 3pp 07971 280
- ~-BiO32GO354 Notice of extension of completion date of fire prot mode from BiO225 to BillO1 CASE.E G Office of Nuclear Reactor Regulation. Director Bi/O2/13 to 07971 283
- 8103180264 Ltr to all power reactor incensees urplants licensed to 790101 Forwards NRC position & request for addition for safe shutdown capability for compliance w/801119 fire protection rule
  EISENHAT. D D Division of Licensing 81/02/20 13pp
- 8103090294 Advises that revision of "Radiological Energency Resp Plan" will require add1 time Delay due to contracting outside consultants to work w/util engineers to complete final draft. Revised submission date is 810331 LINDER.F. Dairqland Power Cooperative 81703702 2pp. 0765
- BiO3170207 Requests payment of Class II fee for request to posts installation of automatic water fire suppression sys DIGOS.R.M. License Fee Management Branch 81/03/05. Ip
- BIOG31033B Ltr to all licensees of operating plants & holders of forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT.D.G Division of Licensing 81/03/05 6pp.
- 8103130413 Forwards justification for extension of time to converge manual actuated deluge sys for main & auriliary power transformers to automatic actuation re fire protection. Total design of area is adequate & meets transformer requirements LINDER.F. Dairyland Power Cooperative. 81/03/09 5pp 0791
- 8103160551 Forwards revisions to modified amended security plan Revisions withheld (ref 10CFR 790). LINDER-F. Dairyland Power Cooperative 81/03/10. 2pp 0791
- 8103250182 Forwards comments on unresolved fire protection liters in Suppl 1 to 790727 SER transmitted by NRC 810213 ltr Items include Fixed suppression systheat detector circuit supervision 8 protection for electrical equipment.

  LINDER.F Dairyland Power Cooperative. 81/03/19. 25pp. 079

#### O. Adjudicatory correspondence

- 8103020422 Pertial initial decision extending 810225 operational for dewatering sys installation pending final ASLB determination of all remaining issues Exceptions to be filed within 10 days of evc.

  BECHHOEFER.C., ANDERSON.O.C., DECKER.R.S., Atomic Bafety and Licensing Board Panel. 81/02/24, 39pp. 07782:183.
- BiO3190627 Approved corrections to B01216 & 17 hearing transcrip BECHHOEFER.C. Atomic Befety and Licensing Board Panel. B1/03 17pp. 07963:294.
- J. Insurance & indomnity information
- B103050404 Forwards Endorsement 38 & 39 to ANI Policy NF-217. DEVINE H F. Deiryland Power Cooperative. 81/01/27. 4pp.

and the antition of Escanating Governor. 1066

9103190397 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs to program for environ qualification of safety-related electrical equipment litens addressed frodire cold shutdown replacement parts & NUMEG-0737 EISSIPSI.D & Division of Licensing 81/01/19 600

- 9103240270 Lin to all BMR licensees forwarding Buppl I to generic safety evaluation on BMR scram discharge sys Surmariles re-evaluation of Interin measures recommended per 801201 safety evaluation
  EISEIGNUT.D 0 Division of Licensing B1/01/23 Pag.
- E103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.ercept Indian Point 2 & 3.2ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC B01222 request for edd1 info re control of heavy loads E15EMBULD O Division of Licensing B1/02/03 App.
- 810304CCOL Forwards Amend 23 to License DPR-45, eafety evaluation & rotice of issuance & availability CRUICHFIELD. D. Operating Reactors Branch 5 81/02/04. 2pp 07815-293
- --Bl03040002 Amond 23 to items DPR-45 revising mgt structure & facility staff
  GRUTCHFIELD, 6) Operating Reactors Branch 5 Bi/02/04 30pp
  07815 292
- --Biggc40003 Sefety evaluation supporting Arend 23 to License DPR-45.

   Office of Nuclear Reactor Regulation, Director Bi/02/04.
  IGEN 07815-322
- --6103040634 Notice of issuance & availability of Amend 23 to License DPH-45 CRUTCHFIELD, D Operating Reactors Branch 5 61/02/04 2pp 07019-332
- 8103060419 Forwards 'Environ Qualification of Safety-Related Electrical Equipment.' partial review Written response required LAIMAB.O.C Assistant Director for Safety Assessment. 81/02/17 3pr. 07835 278
- 8103030830 Application to amend License DPR-45, changing Toch Specs re igs availability & performance. LthDER.F. Dejruland Power Cooperative 81/02/18. 2pp. 07795:224.
- ~-8503000840 Proposed Tech Specs re sys availability & performance • Dairyland Power Cooperative 81/02/18. 4pp. 07799.226.
- 9103090016 Forwards request for add1 info on BEP Topic VIII-1 A re adequacy of station electric distribution sys voltages Response required within 60 days CRUICHFIELD D. Operating Reactors Branch 5. 81/02/18. 5pp 03/82 188
- 8103160649 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be not EIGE:HUT.D.G. Division of Licensing 81/02/18. 12pp.

- B103290024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D 9 Division of Licensing 81/02/20 8pp
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for CLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackbut event & promptly implement emergency procedures EIBENHUT, D O Division of Licensing 81/02/25 5pp
- 8103170225 Ltr to all BMR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe and 5 & fitting rati per guidelines of ancl Revision I to NUREG-0313 Model Tech Specs only encl EISENHUT. D G Division of Licensing 81/02/26 3pp
- --8103170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ABNE Code Class 1.2 & 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements • General Electric Co. 81/02/26 4pp
- 8103230813 Oeneric Ltr 81-06 to all CP holders & OL applicants re IGCFR80 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl EIBENHUT.0 O Division of Licensing 81/02/26
- Bio3090425 Forwards schedule of SEP topics to be reviewed & submitted for NRC review, in response to NRC 810114 request Maint of encl schedule contingent upon timely receipt of acceptable SERs for other facilities.

  LINDER.F. Dairyland Power Cooperative 81/02/27. 2pp 07850:207.
- 8103160212 Confirms plans for performance of 810316-20 engineering analysis to identify vital equipment at site.NRC contractors should have access to facility info to areas CRUTCHFIELD, D. Operating Reactors Branch 5. 81/02/27 3pp. 07918 331
- 8103090432 Responds to NRC 810217 ltr requesting review of NRC identified deficiencies re environ qualification of electrical equipment. Conclusions reached in vtil 801031 ltr remain valid. Continued safe operation of facility assured. LINDER.F. Dairyland Power Cooperative 81/03/02 2pp 07850:204
- B103050271 Forwards DM Crutchfield B10225 ltr to F Linder.Amend 24 to License DPR-45, safety evaluation & notice of issuance & availability.
  BURNS, 8.0 Rulemaking & Enforcement Division 81/03/03. 1p. 07839: 248.
- --8103060277 Forwards Amend 24 to License DPR-45, safety evaluation & notice of issuance & availability CRUTCHFIELD, D. Operating Reactors Branch S. 81/02/25, 2pp 07839:269
- --8103060287 Amend 24 to License DPR-45, adding new requirements specifying limiting conditions for operation & surveillance requirements for emergency svc water supply sys & primary coolant sys pressure isolation valves.

  CRUTCHFIELD, D. Operating Reactors Branch 5. 81/02/25 9pp. 97839: 271.
- --8103060292 Sefety evaluation supporting Amend 24 to License DPR-45.

  # Office of Nuclear Reactor Regulation, Director 81/02/25.
  10pp. 07839.280.

A War

- --9103060313 'Primary Coolant S<sub>a</sub>s Pressure Isolation Valves " NCELL.P N . STILHELL.Y C. Franklin Institute/Franklin Research Genter PCLK.P J NRC No Detaile: Affiliation Olven IRC-03-79-118. 80/10/24. 10p. 0/839 289
- --B103060318 Notice of Issuance & availability of Amend 24 to License DMK-43 CRUTCHFIELD,D Operating Reactors Branch 5 81/02/29 2pp 07839 299
- 0103310255 Concurs u/NRC 601215 evaluation of SEP Topic [[1-8 C retrradiation damage, use of sensitized stainless steel 5 fatique resistance LINDER, F. Dairyland Power Cooperative 81/03/03 ip 08078 350
- 0103240998 Requests util propose Tech Specs changes re austenitic statifiless steel piping Forwards model Tech Specs draft sefety evaluation & NURGO-0313 Revision | NURGO-0313 not
- CRUTCHFIELD, D. Operating Reactors Branch 9 81/03/04 2pp --B103240065 Model Tech Specs 3/4 0 & 3/4 4 re RCS operational leakage.

  + Operating Reactors Branch 5 81/03/04 7ac
- 8103120310 Informs that SEP Topic 111-3 G re structural & other consequences of unjertrain sys failure has been deleted from facility ravie. Bite does not have sys to lower groundwater CRUTCHFIELD, D. Operating Reactors Branch S. 81/03/10 2pp
- 8103310894 Ltr to all licensees of operating plents applicants for DLs 4 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D. Q. Division of Licensing B1/03/10 6pp
- BI03200724 Advices that BEP Topics VI-7.C (ECCS single fablure critistion & requirements for locking out power to valves) & VI-7.C 2 (fablure node analysis) are correct except for integrated assessment Analysis at DPR-45 is duplicative. CRUTCHFIELD, D. Operating Reactors Branch 5 81/03/13 2pp.
- Bi03190649 Forwards LAC-TR-093. "Reactor Containment Bldg Integrated Leat Rate Test (ILRT) for La Crosss BHR (LACBR?). Det 1980. "
  LINDER Datryland Power Cooperative. B1/03/17. 1p
- --8103190648 "Reactor Containment Bldg Integrated Leak Rate Test (ILRT) for La Crosse Boiling Water Reactor (LACDMR). Dec 1980 " GODDMAN, L.S. Dairyland Power Cooperative. LAC-TR-093 80/12/31
- O Inspection reports: IE Sulletins & correspondence

07967 314.

- B103080754 Forwards IE Insp Rept \$0-409/80-17 on 801212-18.No ngncompliance noted HEISHMAN R F Regio Region 3. Chicago, Reactor Operations Suclear Support Branch. B[/01/20. 2pp 07828:087
- --8103050760 IE Insp Rept 50-409/80-17 on 801212-18 No moncompliance noted Major areas inspected containment integrated lesk rate MCPKING. J.B. Region 3. Chicago: Office of the Director. STREETER, J.F. Region 3. Chicago: Reactor Operations Nuclear Support Branch 81/01/16 4pp. 07828:089.
- 0103100704 Forwards IE Insp Rept 30-409/80-15 on 801208-11 % notice of violation. Written response re compensation for loss of health & safety supervisor required. FISHER, wt. Region 3. Chicago, Fuel Facility & Materials Safety Branch 81/01/21. 2pp 07866:273.
- --8103100715 IE Insp Rept 50-409/80-15 on 801208-11. Noncompliance noted. inadequate radiation survey & unmonitored release of radioactive matt OREGER, U. R. PAUL, R. A. Region 3. Chicago, Office of the Director FIBHER, U. Region 3. Chicago, Fuel Pacifity & Materials Bafety Branch 81/01/14 7pp. 07866 275
- --8103190720 Notice of violation from insp on 801208-11. FISHER-W.L. Region 3. Chicago, Fuel Facility & Materials Bafety Branch 91/01/21 1p. 07866:288.
- B103200296 Forwards supplemental response to IE Bulletin 80-13, "Cracking in Core Spray Spargers." No evidence of intergranular stress cornorion cracking in welds or piping was found for areas examined.

  LINDER.F. Dairyland Power Cooperative 81/01/30 4pp 07971:141

- Bio3020094 Forwards 1E Circular Bi-02. "Performance of NRC-Licensed Individuals While on Duty 'No written response required #EPPLER.J O Region 3. Chicago. Office of the Director Bi/02/0 200 07787 336
- 8103040300 Forwards IE Info Notice 81-03, 'Checklist for Licensees MAKING NOTIFICATIONS OF Significant Events In Accordance
  W/IOCFRS9 72 " No written response required
  WEPPLER. J O Region 3. Chicago. Office of the Director 81/02/1 07815 265
- 8103030290 Forward, Suppl 5 to IE Bulletin 80-17. 'Failure of Contr Rods to Insert During Scram at BLR. ' No written response
- REPPLER. J.G. Region 3. Chicago, Office of the Director 81/02/: ZDD 07790.29B
- 8103240385 Forwards IE Insp Rept 50-409/81-01 on 801201-810131 & no of violation

  HEIBMANAR F Region 3. Chicago, Reactor Operations Nuclear Supp

  Branch 81/02/17 2pp 07987-241
- --8193240388 Notice of violation from insp on 801201-810131 HEJSHYAN.R.F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 81/02/17 3pp 07987.243
- --8103240392 IE Insp Rept 50-409/81-01 on 801201-810131 Noncomplian noted fire barrier not maintained & failure of maint notes fire parrier not maintained & failure of maint personnel to notify control room operator prior to entering & eitting controlled area GENERY.W.L., BRANCH.M.W., BOYD, D.C. Region 3. Chicago, Office the Director 81/02/10 Gpp 07987 245.
- 8103050089 Ack receipt of 810121 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/80-14 HEIEBHMAN R F Region 3 Chicago, Reactor Operations Nuclear Supp. Branch 81/02/19 1p 07827-261
- --BIO3050100 Responds to NRC B01223 ltr re violations noted in 16 to Rept 50-409/80-14 Corrective actions bypass valve setting now recorded hourly Control room log book starp will be modified to include log for operating condition.

  LINDER.F Delryland Power Cooperative 81/01/21 App LINDER, F. Dairyland Power Cooperative 81/01/21 App. 07827 262. 8103120087 Responds to IE Bulletin 81-01. "Surveillance of Mechanic Shubbers." Mechanical snubbers, supplied by Intl Bafeguards Corp or Pacific Estentific Co. not used or planned for use
- Corp or recurred at the Corporative Corporative B1/02/27 ip 07900 180 LINDER F.
- 8103160311 Forwards IE Circular 81-03, "Inoperable Beisnic Monitorii Instrumentation," No response required KEPPLER J G Region 3, Chicago, Office of the Director 81/03/0 2pp. 07916 009
- 8103160865 Forwards revised IE Bulletin 81-01, "Burveillance of Machanical Bnubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  KEPPLER, J. O. Region 3. Chicago, Office of the Director 81/03/0:

  2pp. 07914:220
- B103230146 Forwards IE Insp Rept 50-409/81-03 on B10224-27 No noncompliance noted.

  NORELIUS.C.E. Region 3, Chicago. Office of the Director B1/03/0
- 20p. 07977 170 --8103230153 IE Insp Rept 50-409/81-03 on 810224-27 No noncompliance

noted Mejor areas inspected matl control & accountability including facility organization & operation measurement &

- controls Details withheld (ref LOCFR2. 790) FINLEY, A. O. FINLEY, A. O. Region 3, Chicago, Office of the Director CREED, Region 3, Chicago, Safeguards Branch. 81/03/06 1p. 07977:1
- 8103190678 Ack receipt of 810227 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409780-15 FIBMER.W.L. Region 3. Chicago, Office of the Director. 81/03/10 1p. 07964 269.
- --81031906B0 Responds to NRC B10121 ltr re violations noted in IE II Rept 50-409780-15. Corrective actions:manual shutoff valve installed in vacuum pump loop seal drain line & raduaste drums moved away from raduaste bidg.
  LINDER:F. Dairyland Power Cooperative. B1/02/27, 4pp 07964:270.
- 8103200366 Forwards IE Info Notice 81-06. "Feilure of ITE Model K-60 Circuit Breaker." No response required. KEPPLER J 9. Region 3. Chicago, Office of the Director 81/03/1. 2pp. 07972 113.

of Forwards 16 Info Notice Bi-OS. Degraded DC Sys at les : No action required. N.J. G. Rogion 3. Chicago. Office of the Director Bi/O3/13 17967-248

- dic operating reports & related correspondence
- 91 Forwards "Assoual Operating Rept.1980" F. Datryland Power Cooperative 81/02/27, 1p 07911 145
- 0392 "Annual Operating Rept.1930 " airyland Power Cooperative 81/02/27 (Opp 0791) 146
- table occurrences. LERs & related correspondence
- 66 Ph.(I-[[]-80-181.on 801004.unit tripped from 85% power Caused h water level trip due to 1B main feedwater pump ction Bus IR would not switch over to offsite power automaticall, Peactor restarted .N.L.. NGYD, D.C. HEISHMAN.R.F. Region 3. Chicago, Office of rector 80/10/06 2pp 07817 301
- 95 Forwards LER 81-003/03L-0.Detailed event analysis entl. iF. Dairyland Power Cooperative 81/02/25 5pp 07862 288
- 0501 LER 81-003/03L-0 on 810202 gross alpha activity of primary ant sample exceeded Tech Spec Caused by dograded fuel sling during previous fuel cyrles. Primary purification special cyrles. Primar
- 80 Forwards LER BH-001/02L-0. F. Dairyland Power Cooperative B1/02/25. 3pp 07877 233
- Occo LER Bi-001/02L-0 on Bi0201, independent circuit between ite transmission network & onsite power distribution system extend. Caused by disconnect switch opened due to ator error Two operators to operate switching order MANIL B. Delryland Power Cooperative Bi/02/25 ip 7 237.
- 03 PNO-LIT-B1-029 on B10309 & 10, reactor scrammed First Caused s of voltage on distribution train B due to misaligned ical distribution breakers Becond caused when operator to correct increasing water level ,M., MCGREGER.L. O. HARNICK.R.F. Region 3. Chicago. Office of rector B1/03/10 tp 07965-223
- 0-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
  cation/construction stage documents & correspondence
- 32 Ltre to all licensees of operating plants applicants for holders of CPs re-control of heavy loads Requests per guidalines in NUREO-O612 Forwards NRC position re-mattions & request for addl info.
  NUT.D Q Division of Licensing GO/12/22. 30pp
- B7 Ltr to all licensees of operating plants & applicants for holders of CPs re program for environ qualification etq-related electrical equipment litens addressed et cold shutdown.replacement parts & NUREO-0737.

  BUT.D Q Division of Licensing. B1/01/19. opp
- old Lite to all licensees of operating plents.CP holders & OL ants, except indian Point 2 & 3,2ion 1 & 2 & TMI-1, ding imadvertently omitted pages from NRC B01222 to for addl info re control of heavy loads.

  (UF.D.Q. Division of Licensing. 81/02/03 App
- 951 Notification of 810311 & 12 meeting w/Mark II owners group in Bethesda.MD to discuss Mark II generic long-term .m IDN.C J. Generic Issues Branch. 81/02/12. 12pp.
- 559 i.tr to all operating plants & CP holders forwarding Pication of TMI Action Plan Item III.A.1.2 re upgrade organicy support facilities. Requests confirmation within its that implementation dates will be met MT.D.G Division of Licensing 81/02/18. 12pp

- 8103250024 Ltr to all power reactor licensees & license applicants re NAREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing delations Licensee may submit analysis to justify use of existing low flow controller EIGENHUT. O 2 Division of Licensing 81/02/20 8pp
- Bi03120209 Notification of 810305 meeting w/util in Bethesda.HD to discuss testing requirements for unstaggered splices using OYWIDAU threadbar sys prior to use on facility. KIPER.K L Licensing Branch 1 81/02/25 3pp 07904 335
- B103170225 Ltr to all BLR licensess (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, eafe ends & fitting math per guidelines of encl Revision 1 to MUREG-0313 Model Tech Specs only encl EISEMHUT.O G Division of Licensing 81/02/26 3pp
- --8103170266 Model Yech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4-8 re surveillance requirements for ASI'E Code Class 1.2 & 3 components & RCS operational leatage limiting conditions for operation & surveillance requirements • General Ejectric Co 81/02/26 4pp
- B103170655 Ltr to holders of CPs & applicants for OLs (BWRs) requesting review of ASME Class 1.2 % 3 pressure boundary piping, safe ands & fitting mat1 per guidelines of enci Revision 1 to fAREO-0313 Model Tech Spets only enci.
  EISENHUT.D Q Division of Licensing 81/02/26 3pp
- 8103230813 Generic Ltr 81-05 to all CP holders & OL applicants re [OCFR50 7I(e), "Periodic Updating of FSARs." affective 8C0722 Info re FSAR legal status format & content encl EISEINHUT.D O Division of Licensing B1/02/26
- 8:03040430 Forwards environ qualification test info for balance of plant equipment, in response to 801001 jtr Info re environ qualification tests on equipment supplied by N388 will be submitted by 8:0301 DISC. D.P. Niegara Mohawk Power Corp. 8:1/02/27. 3pp. 07808:234.
- 8103130601 Notification of 810313 meeting w/Mark II owners group in Bethesda-MD to discuss Mark II safety relief valve loads & pool temp limits SU.T.M. Generit Issues Branth B1/03/03 2pp
- 8103130349 Summary of B10126 meeting w/util in Bethesda.AD re reorganization of ngt structure for OA functions Organization charts enc! KIPER.K.L Licensing Stanch | 81/03/04 7pp
- BIO3120642 Responds to 790809 request for review & approval of use of DYWIDAG threadbar sys for splicing reinforcing bar in Category [ structures Sys acceptable if conditions met & addl info submitted YDUNO8LODD.8.7 Licensing Branch 1. 81/03/05. 3pp 07906.129
- BIO3110303 Forwards for review & approval SHECO 8101, "Models Used in LOCTVB Computer Code to Determine Pressure & Temp Response of Vapor Suppression Containments Following LGCA." BRADBURY.R B Stone & Webster Engineering Corp 81/03/06 2pp. 07883:001.
- B103310804 Ltr to all licensees of operating glants, applicants for OLs & holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT, D. G. Division of Licensing 81/03/10 6pp
- 8103200444 Forwards Suppl 2 to NUREO-0487. "Mark II Containment Lead Plant Program Load Evaluation & Acceptance Criteria" & policy issue paper. Suggests Har 1981 meeting w/Hark fl owners to discuss review program W/o encl.
  KNIEL, K Oeneric Issues Branch 81/03/16 1p. 65134:218.
- B103240374 Forwards info provided at B10306 meeting w/NRC to discuss unstaggered splices re DYMIDAQ Threadbear Sys. Approvel by B10331 requested to use sys in unstaggered applications subj to described limitations & conditions.

  DIGE. D. P. Niegere Mohaut Power Corp. 81/03/18. 9pp. 07990:255.
- B103310781 Summary of B10306 meeting w/util in Bethesda.MD re use of Dywidag threadtar sys List of attendees encl.
  KIPER.K.L. Licensing Branch 1. 81/03/24 5pp. 08062:288
- B103310914 Bummary of B10313 meeting w/Mark II owners group re suppression pool temp limit & T-quencher load spec. W/o encl list of attendees & meeting handout. SU. T. M. Opneric Issues Branch. B1/03/24 3pp.

organization description encl
RHSDE.G.K. Niagara Mohawk Power Corp. 81/03/25 9pc 08097:133

B100300273 Advises that info to amend CP re-eitension of completion date will be provided by B10630 instead of B1033) as originally stated
RKDBE.0.x Niegara Mohaus Power Core B1/03/25 is C8055.281

- F. Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUMEO-0696. "Functional Criteria for Energynty Response Facilities" Criteria describe acceptable method for meeting tHC requirements. H/o encl.
  EISENHUT.D O Division of Licensing B1/03/05 6pp

### I Financial information

- B103160462 Forwards Annual Financial Rept 1980 LEMPGES T. E Niagara Mohawi Power Corp 81/03/12 1p 07916 277.
- ~-8103160467 Annual Financial Rept 1980 HAEHLIJ G - DONLON, W J - Niagara Mohawk Pouge Corp. 81/02/02 36pp - 07885.001.
- G. Inspection reports: IE Bulletins & correspondence
- 810303024B Forwards Suppl 5 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BMR" No critter response required GRIER.B.M. Region 1. Philadelphia. Office of the Director 81/02/13. 10. 07790 295.
- B103300003 Ack receipt of B10130 itr informing ARC of steps taken to correct violations noted in IE Insp Rept 50-410/80-11. CARLBON.R. T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 81/02/23 Ip 08053-022.
- -BIO330000B Responds to NRC 801217 ltr re violations noted in IE Insp. Rept 50-410780-\$1. Corrective actions Drawing EC-3BA. Revision 7. Issued on 801118 & Drawing EC-3BC. Revision 8. Issued on 801118 per Project Procedures 16 & 24. BISE, D.P. Niagara Mohawi Power Corp. 81701730 4pp 08053-023.
- --Bi03300011 Forwards JE Insp Rept 50-410/80-11 on 801021-23 & 1104-06 & notice of violation CARLBON,R. T. Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/12/17. 2pp. 08053.027.
- --8103300013 Natice of violation from insp on 801021-23 & 1104-06.

   Region 1, Philadelphia, Office of the Director. 80/12/09. 2pp 08053;029.
- --8103300016 IE inep Rept 50-410/80-11 on 801021-23 & 1104-06 Noncompliance noted five E&DCRs u/closing dates in excess of max time authorized by procedure not incorporated into Drawings 12177-EC-3806 & 12177-EC-380C-7 FEIL.R.A. Region 1. Philadelphia. Office of the Director. HATTIA.J. Region 1. Philadelphia. Office of the Director Engineering Support Branch 80/12/09. 7pp. 08033.031
- 8103200225 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation." No written response required. ORIER. B H. Region 1. Philadelphia. Office of the Director. 81/03/02 1p. 07972:063.
- B103230227 Forwards revised IE Bulletin B1-01, "Burveillance of Mechanical Bnubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ORIER, B H. Region I. Philadelphia. OPPice of the Director. 81/03/04. p. 07977:260.
- B103200144 Forwards IE Info Notice B1-06. "Failure of ITE Hodel K-600 Circuit Breaker." No response required.
  ORIER.B.H. Region 1, Philadelphia, Office of the Director B1/03/11. 1p. 07968-280.
- 8 Reportable occurrences. LERs & related correspondence
- 8103200647 Finel deficiency rept re eight rebar sections welded to shear bars on Reactor Pedestal Embedment Plate PB-37 in field initially reported on 800908 Condition not reportable per IOCFR30. 59e. RHODE-0-X. Niegara Mohawk Power Corp. 81/03/13 Spp. 07971: 245.

originally reported 610129 Design mod planned Next rept by 810901 REGOS O, K. Niagara Mohawk Power Corp. 81/03/13 App. 08001.30

- OCCKET 30-412 BEAVER VALLEY POWER BIATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NURGO-0612 Forwards NRC position re-interim actions & request for add1 info FISEIMFUT.D 9 Division of Licensing 80/12/22. 39pp
- B102270565 Notification of contract execution.Mod 2 to "Environ Monitoring Program H/Commonwealth of PA " Contractor Commonwealth of PA BA16DENL Reaerch Contracts Branch FIN 8-5111 81/01/07
- --8102270390 Mod 2.adding TLD monitoring around facilities \$ incre amount of contract to "Environ Monitoring Program W/ Commonwealth of PA" CERUSKY, T.M. Pennsulvania, State of FIN 8-5111 81/01/07.
- B103190387 Ltr to all licensees of operating plants & applicants of OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREO-0737 EIBENKUIT.O @ Division of Licensing B1/01/19. dop
- B)03120014 Ltr to all licensees of operating plants.CP holders & G applicants.ercept Indian Point 2 & 3.2ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EIBENHUT.D.O. Division of Licensing 81/02/03 App
- B103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUI,D.O. Division of Licensing. 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants NAREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of ecisting low flow controller EIBERHUT.D.O Division of Licensing 81/02/20. Bap
- B103230B13 Generic Ltr B1-06 to all CP holders & OL applicents re IOCFRSD.71(e), "Periodic Updating of FSARs." effective B00722. Info re FSAR legal status, format & content encl. ETEENNUT.D.O Division of Licensing. 81/02/26 10pp.
- B103310804 Ltr to all licensess of operating plants applicants for 5 holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D. 0. Division of Licensing 81/03/10 App.
- F. Security, medical, emergency & fire protection plans
- G10331033B Ltr to all licensees of operating plants & holders of (forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl. EISENHUT.D.O. Division of Licensing. 81/03/05. 6pp
- Q Inspection reports, IE Sulletins & correspondence
- B103060420 Responds to IE Bulletin 80-23, "Failures of Bolenoid V. Mfg by Velcor Enginering Corp " No Valcor valves being supplied to facility.
  MODLEVER.E.J. Duguesne Light Co. 81/01/29. 1p 07836:001.
- B103200173 Forwards IE Circular Bi-03, "Inoperable Beismic Monito Instrumentation " No written response required. ORIER.B.H. Region 1. Philadelphia. Office of the Director B1/03/02. 1p 07978.061.
- 8103230222 Forwards revised 1E Bulletin 81-01. "Burveillance of Hechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements ORIER, B H. Region 1. Philadelphia. Office of the Director 81/03/04. 1p. 07977.256.

#### DOCKELED LIFTAIS

- B103200317 Forwards IE Info Notice B1-06. 'Failure of ITE Model K-600 Citcuit Breaker " No response required GPICR.B M. Region 1. Philadelphia. Office of the Director B1/03/11 1p 07969 043
- S. Reportable occurrences, LERs & related correspondence
- 8103050315 Act receipt of 810102 Significant Deficiency Rept 80-07 to seisaic calculations for Category 1 structures Notification of design deficiencies should be submitted by 810622 CAPLSON RT Region 1. Palladelphia. Reactor Construction & Engineering Support Branch 81/02/04 1p 07836-349
- --810306033; Initial Bignificant Deficiency Rept 80-07 re seismic calculations for Category I structures Structures in auxiliary bldg found adequate. No structural deficiencies in design Calculation completion scheduled for Dec 1981 MCDLEVER.E. J. Duquesne Light Co. 81/91/02 2pp 07836
- 8:03200301 Ack receipt of 8:10129 Final Significant Deficiency Rept 80-03 reinferior welds on cable trop fittings CARLSCI-R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 8:1087/13 [p 07969:064
- BIO5240394 Final deficiency rept initially reported BIO218 re use of unauthorized document as basis for GC acceptance Review of snsp plans to be completed by BIO417 Evaluation determined deficiency not reportable per IO5FR50 55e 

  JOGLEVER.E. J Duquesne Light Co BI/O3/18 2pp 07990 ≥50
- DOCKET 90-413 CATAMBA MUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- S103199732 Lites to all licensees of operating plants applicants for OLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREO-O612 Forwards NRC position relaterim actions & request for add1 info Elsen-NUT.D O Division of Licensing 80/12/22 30pg
- BiO3190307 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737 EISENIUT.D & D(vision of Licensing BI/01/19 App
- SiO3120014 Ltr to all licensees of operating plants CP holders & GL applicants except Indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add I info re control of heavy loads.

  ELSENHUT, D O Division of Licensing 81/02/03 opp.
- 8103290024 Ltr to all power reactor licensees & license applicants re MAREQ-0619 criteria Footnote 2 in Table 2 contains error dus to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISEM-UT.0 Q Division of Licensing 81/02/20. 8pp
- 8103060384 Forwards final test plan for electrical connector tests Plan incorporates comments on earlier version Testing will begin by 810401; if connectors are delivered on schedule FEIT.8. Qualification Testing Evaluation Review Group 81/02/24 2155. 07840 273
- --Bio3020097 Forwards final version of "Connector Assembly Test Plan for Dute Power: Catawba Units 1 & 2. Connectors."

  BUCKALEH. W. H. Sandia Laboratories Bi/02/03 ip 07B40 275
- --Bi030605B9 "Connector Assembly Test Plan for Duke Power, Catauba Units 1 3 2. Connectors " 8 Sendia Laboratories B1/01/30, 17pp 07840:276.
- 8103090578 Forwards PAR const milestones & activities for McGuire 1 & 2.Catembe 1 & 2 & Cherokee 1 Key event dates provided.

  GROOAN.JF Dube Power Co. B1/02/24 opp 07850.186
- 8103160336 Requests approval of Caselood Forecast Panel visit to facility in Apr 1981 Panel estimates of fuel loading dates are needed to establish review schedulo for extended CPs. MIRAOLIA.F. J. Licensing Granch 3. 81/02/25 1p. 07916 084
- BiO2230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucie.Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures ETERNAUT. D. 0 Division of Licensing. BI/02/25 Spp.

- 8103230813 Generic Ltr 81-06 to all CP holders & CL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status.format & content encl EISENHUT.D O Division of Licensing. 81/02/26 10pp.
- 8103310804 Ltr to all licensees of operating plants, applicants for & holders of CPs forwarding SECV-81-119 rs info necessary to astablish environ qualification of safety-related electrical aquipment.

  EISELHHUT, D. 9. Division of Licensing 81/03/10 App.
- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licenses of operating plants & holders of CP forwarding NUREO-0596. Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements N/o encl fiseNHUT. D O Division of Licensing. 81/03/05 6pp
- O Adjudicatory correspondence
- B103020389 Informs that time for Commission to review Director's Decision DD-81-1 has expired Commission declined review & decision became final agency action on 810223 CHILM.8 J. Office of the Secretary of the Cormission 81/02/27 lp 07782 177
- 1 Financial information
- BiO33i0549 Forwards Annual Financial Rept 1980, annual certified financial statements, 1981-83 financial forecast & util statement to available funds to satisfy liability Info guarantees retrospective premiums per 10CFR140 26 THIEB.A C Duke Power Co. Bir/03/24 lp
- --8103310639 Annual Financial Rept 1980 including financial stateme 1981-83 financial forecast & statement re sources of available funds to satisfy liability HDRN.C. Duke Power Co. 81/02/13 51pp
- O Inspection reports. IE Bulletins & correspondence
- 8103040957 Supplemental response to NRC 801026 ltr re violations no in IE Insp Repts 50-413/80-23 & 50-414/80-23 Corrective actions battery racks 1008A-B & 2008A-B redesigned & seismically tested Results satisfactory PARKER-W O Dute Power Co 80/12/31 lp 07819.279
- Bi03040049 Ack receipt of B01126 & 1231 ltrs informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-413/B0-23 & 30-414/B0-23 MURPHY.C. C. Region 2. Atlanta: Reactor Construction & Engineerin Bupport Granch Bi/01/20 ip 07819 278.
  - MURPHY, C. E. Region 2. Atlanta: Reactor Construction & Engineerin Bupport Branch 81/01/28 ip 07819 278.
- --Bi03040078 Responds to NRC 801026 ltr re-violations noted in IE I Repts 80-413/80-23 & 50-414/80-23 Corrective actions varification of seismic design espected from vendor by 801215. Util will submit final response after review PARKER/W O. Duke Power Co. 80/11/26. 2pp 07819.280
- --8103040087 Informs that CE Murphy 800926 letter forwarding IE Ins Repts 50-413/80-23 & 50-414/80-23 not received until B01106 Response will be provided by 801126 PARKER.W.O. Dute Power Co. 80/11/10 1p 07819-292
- --BI03040097 Forwards IE Insp Repts 50-413/80-23 & 50-414/80-23 on B00825-29 & notice of violation. MURPHY.C & Region 2. Atlanta, Reactor Construction & Engineer Bupport Branch B0/09/26 2pp. 07819:283.
- --Bi03040103 Notice of violation from insp on 800825-29. \* Region 2. Atlanta, Office of the Director. 80/09/25. ip. 07819:285
- --Bi03040118 IE Insp Repts 30-413/80-23 & 50-414/80-23 on B00825-29 Nancompliance noted: supplier did not supply proper verification that item being furnished complied u/procurement requirements.
  WALTERS, D.K., CONLON. T.E., Region 2, Atlanta, Office of the Director 80/09/25 6pp. 07819:286.
- 8103050593 Forwards IE Insp Repts 50-413/80-38 & 50-414/80-38 on 801216-19, No nuncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineerin Bupport Branch. 81/01/30. Ip. 07829:013

- --Bi03050577 IE Insp Repts 50-413/80-39 & 50-414/80-38 on 801216-19 No noncompliance noted Major areas inspected RCPS pipings, observation of welding review of radiographs & observation of ASHE survey VANOSORN P K Region 2. Atlanta. Office of the Director Bryant. J C Region 2. Atlanta. Reactor Construction & Engineering Support Brench 81/01/30 4pp 07829 014.
- B103020203 Forwards IE Circular 81-02. Performance of NRC-Licensed Individuals While on Duty "No written response required G'REILLY-J P Region 2. Atlanta. Office of the Director 81/02/07 to
- 8103040044 Ack receipt of 1E insp Repts 50-413/80-36 & 50-414/80-36 on 801202-05 No proprietary info PARKER, N. O. Dute Power Co. 81/02/09 1c. 07816:354
- --8103040050 Forwards IE Insp Repte 50-413/80-36 & 50-414/80-36 on 801202-05 No honocorpliance noted.

  MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/01/21 2pp 07816 355.
- --8103040036 IE Insp Repts 50-413/80-36 & 20-414/80-36 on 801202-05 No noncompliance noted Major areas inspected observation of nondestructive earn activities & followup of licensee & MRC Identified items VAND30RN.P K Hegion 2. Atlanta. Office of the Director BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/20 5pp 07816 397
- 9103030073 Forwards response to IE Bulletin 80-23 Coils of all Valcor solenoid valves wypert numbers V70900-21-1 or V70900-21-3 will be replaced wycoils of improved const by 810213 Valcor is submitting proposed testing program PARKER, W 0 Oute Power Co. 81002/12 3pc 07808 203
- 8103090758 Ack receipt of 1E Insp Repts 50-413/80-37 & \$0-414/80-37 on 801209-11 No proprietary info. PARACRIM 0. Duke Power Co B1/02/23 lp 07846:101
- -8103090761 Forwards IE Insp Repts 50-413/80-37 & 50-414/80-37 on B01209-11. No noncompliance noted.

  8TORR.J P Region 2. Atlants. Fuel Facility & Materials Safety Branch. 81/02/04 2pp 07846:102
- --8103090767 IE insp Repts 50-413/80-37 & 59-414/80-37 on 801207-11.No noncompliance noted Major areas inspected environ protection including mgt controls, review of previous enforcement matters, waste mgt & controls.

  CUNNINGHAN, A. L. Region 2. Atlanta, Office of the Director JENKING, Q.R. Region 2. Atlanta, Fuel Facility & Materials Bafety Brench 81/02/04 Spp. 07846:104
- 8103090494 Ack receipt of IE Imap Repts 50-413/81-01 & 50-414/81-01 on 810112-16 No proprietary info. PARKER, N. O. Duke Pouse Co. 81/02/24 ip 07847:349.
- --Bi03090498 Forwards IE Inep Repts 30-413/Bi-01 & 50-414/Bi-01 on Bi0112-16 No noncompliance noted. HURPHY,C E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 81/02/06. 2pp. 07847.350.
- --BI03090903 IE Insp Repts 50-413/81-01 & 50-414/81-01 on Bi0112-16 No noncompliance noted Major areas inspected RCPB piping & safety-related piping observation of waiding.

  WANDOORN P. K. THOMAS M. Region 2. Atlanta, Office of the Director. BRYANTJ C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/02/06. App. 07847-352.
- 6103090818 Ack receipt of IE Insp Repts 50-413/80-38 & 50-414/80-38. No proprietary info.
  PARKER, N.O. Dute Power Co. 81/02/24. Ip. 07849;124
- 8103160651 Forwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation." No response required. Q'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/02. 1p.
- Biogi70041 Forwards revised IE Bulletin Bi-Oi. "Burveillance of Mechanical Bnubbers." w/corrected Pages 5 & 6.Change in identification of Pacilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. Bi/O3/O4.
  1p.
- 8100200281 Forwards IE info Notice 81-05, "Failure of ITE Model K-600 Circuit Breaker." No response required.

  D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/11, 18.

- 8103200013 Forwards IE info Notice 81-05, "Degraded DC Eys at Palisades' No response required C'REILLY.U P Region 2, Atlanta, Office of the Director 81
- S Reportable occurrences. LERs & related correspondence
- B103160746 Bignificant Deficiency Rept 413-414/81-02 re cracks contacts initially reported on 810202 Replacement parts for all broken by cracked arcing contacts to be provided by manufacturer PAMKER.W O. Dule Power Co. 81/03/09 3pp 07914.139
- DDCKET 50-414 CATAMBA NUCLEAR STATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants DLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-0512 Forwards NRC position reinteria actions & request for addl info EISEM-NUT.D Q Division of Licensing 80/12/22 30pp
- 8103190397 Ltr to all licensees of operating plants & applicant OLs & holders of CPs re program for environ qualification of sefety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT.D Q givision of Licensing Bi/O1/19 &pp
- 8103123014 Ltr to all licensees of operating plants. CP holders applicants except Indian Point 2 % 3.7ion 1 % 2 % TMI-1. forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EIBENNUT.D.O. Division of Licensing 81/02/03 6pp
- 8103250024 Ltp to a)) power reactor licensees & license applica /&REG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller E155MHUT.D Q. Division of Licensing 81/02/20 8pp.
- 8103060584 Forwards final test plan for electrical connector to incorporates coments on earlier version Testing will begin by 810401. If connectors are delivered on schedule FEIT.R Qualification Testing Evaluation Review Group 81/0 21pp. 07840-273
- --BIO3060387 Forwards final version of "Connector Assembly Test Duke Power, Catawba Units 1 & 2. Connectors" BUCKALEW. N. H. Bandia Laboratories 81/02/03. 10 07840
- --8103060589 "Connector Assembly Test Plan for Duke Power.Cataw & 2.Connectors" • Sandia Laboratories, 81/01/30 17pp. 07840,276
- 810309057B Forwards PWR const milestones & activities for McOut 2,Catawie 1 & 2 & Cherokee 1 Key event dates provided OROGAN,J.F Duke Power Co BL/02/24. App
- BiO3160336 Requests approval of Caseload Forecast Panel visit t facility in Apr 1981 Panel estimates of fuel loading dates are needed to establish review schedule for extended CPs. MIRAGLIA-F. J. Licensing Branch 3. Bi/02/29 jp. 07916:084
- BiO3230030 Ltt to all licensees of operating nuclear power plan applicants for OLs (except St Lucie.Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT.D. Q. Division of Licensing BI/02/25. Spp.
- Bio3230813 Peheric Ltr 81-06 to all CP holders & OL applicants 10CFR90.71(e), "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status, fornat & content enci ETBERHUT.D.Q. Division of Licensing. Bi/02/26 10pp.
- Bio3310B04 Ltr to all licensees of operating plants, applicants & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D Q Division of Licensing. Bi/03/10. 6pp.
- F. Becurity, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of prevending NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements NYA encl.
  EISENHUT.D.Q. Division of Licensing. 81/03/09. App

## 3 Adjusticatory correspondence

8105020389 Informs that time for Commission to review Director's Decision DD-Bj-1 has expired Commission poclined review & decision became final agency action on 810223 CHILL.B J. Office of the Secretary of the Commission. 81/02/27 is 97782 177

## I Finencial Information

- 8103310549 Forwards Annual Film-scial Rett 1980, annual certified financial statements 1981-83 financial forecast 5 util statement re available funds to satisfy liability Info guarantees retrospective premiums par 100FR140 26 HRES A C Duke Power Co B1703/2/1 In
- --0103310639 Annual Financial Hept 1500, including financial statements, 1981-83 financial forecast & statement re sources of available funds to satisfy 1jability HORN.C. Duke Pager Co. 61102/13 Sign
- 3 Inspection reports, 1E Bulletins & currespondence
- 8103040049 Act receipt of 801126 \$ 1231 ltrs informing NRC of steps taken to correct violations noted in 15 Insp Repts 50-413/80-23 \$ 50-414/80-23 MARPHY.C E. Region 2. Actianta. Reactor Construction & Engineering Support Branco 81/01/28 to 0/819-278
- --Bi03040957 Supplemental response to LRC 801026 ltr re violations noted in IE Insp Repts 90-413/80-23 & 50-414/80-23 Corrective actions baltery racis IDGIA-0 & IDGIA-0 redesigned & seismically bested Results satisfactory PARKER. 4 D. Duke Power Co. 80/12/31 1p. 07819-279
- --8199940078 Responds to NRC 801026 ltr re violations noted in IE Insp. Repts 50-413/00-23 & 90-414/80-23 Corrective actions, veriffication of selectic design expected from vendor by 891215 Util will submit final cesponse after review PARAER-RC Duke Power Co. 807/11/26 2pp. 07819-280
- ~-8103C400B7 Informs that CE Murphy 803926 letter forwarding IE Insp. Rapto 30-413780-23 & 50-414780-23 not received until B01105 Response will be provided by 801126 PARKER.W D. Duke Power Co. 83/11/10 tp. 07819:282
- --0103040077 Forwards IE Insp Repts 50-413/80-23 & 50-414/80-23 on ID06825-29 & notice of violation HURPING E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/26 2pp 0/019 283
- --8103340103 Notice of violation from insp on 800825-29

   Region 2. Atlanta. Office of the Director 80/09/25 ip. 0789-285
- --8103040110 IE insp Repts 50-413/80-20 3 50-414/80-23 on 800825-29 Mancerplience noted supplier did not supply proper verification that item being furnished complied w/ procurement regulrements WALTERS. D K., COMIONIT E. Region 2. Atlanta, Office of the Director 80/07/25 bpp 07819 286
- --BIO3650577 IE Insp Repts 30-413/80-38 & 50-414/80-39 on 801216-19 No noncompliance noted Major areas inspected RCPD piping, observation of welding review of radiographs & observation of ARMS survey VANDORN.P. K. Region 2. Atlanta, Office of the Director. BRYANT.J C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch B1/01/30 4pp 07829-014
- 6)03020203 Forwards IE Circular 8t-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. O'REILLY-U P Region 2. Atlanta. Office of the Director B1/02/09 to
- --BJ03040050 Forwards IE Insp Repts 50-413/60-36 & 50-414/80-36 on G01202-03 No moncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch G1/01/21 2pp 07816 355

- --Bi030A0056 IE Insp Rests 50-413/B0-36 & 50-414/B0-36 on B01202-05. No noncompliance noted Pajor areas inspected observation of nondestructive ends activities & following of licensee & NRC identified items
  VANDOORN.P K. Region 2. Atlanta. Office of the Director SRYANT.J C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. B1/01/20. Spp. 07816.337
- B103030073 Forwards response to IE Bulletin 80-23 Coils of all Valcor solenoid valves u/part numbers V70900-21-1 or V70900-21-3 uill be replaced u/coils of inproved const by 810213 Valcor is submitting proposed testing program.

  PARKER: N 0 Dute Power Co B1/02/12 3pp 07808 203
- B10309075B Ack receipt of IE Insp Repts 50-413/80-37 % 50-414/80-37 on E01209-11. No proprietary info PARKER, W.O. Dute Power Co. B1/02/23 tp. 07846 101
- --BI03090761 Forwards IE Insp Repts 50-413/80-37 & 50-414/80-37 on 801207-11 No honcompliance moted STOHR. J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch BI/02/04 2pp 07846 102
- --9103090767 IE Insp Repts 50-413/80-37 & 50-414/80-37 on 801209-11. No noncompliance noted Major areas inspected environ protection including mpt controls, review of previous enforcement matters, waste mpt & controls CUMMINGHAM. A.L. Region 2. Atlanta. Office of the Director JENAINS 9 R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 81/02/04 5pp 07846 104
- 8103090494 Ack receipt of IE Insp Repts 50-413/81-01 & 50-414/81-01 on 810112-16 No proprietary info PARXER.W O Duke Power Co 81/02/24 1p 07847 349
- --810309049B Forwards IE Ins. Repts 50-413/B1-01 & 50-414/81-01 on B10112-16 No noncompliance noted MURPHY C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/06 2pc 07847 350
- --Bi03090903 IE insp Repts 30-413/81-01 & 50-414/Bi-01 on Bi0112-16 No noncompliance noted Major areas inspected RCPB piping & safety-related piping observation of welding.

  VANDOGRN-P K. THOMAS-M. Region 2. Atlanta. Office of the Director BRYANT-J C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/06. 60p. 07847-392
- 9103090818 Ack receipt of IE Insp Repts 50-413/80-38 & 50-414/80-38. No proprietary info PARKER, WO Duke Power Co \$1/02/24 ip 07849 124
- 8103140651 Forwards (E Circular 81-03. 'Inoperable Seismic Monitoring Instrumentation " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/02 in
- 8103170041 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Shubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'RRILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/04. Ip
- 8103200281 Forwards 1E Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required.

  U'REILLY, J. P. Region 2. Atlanta. Office of the Director. 81/03/11.
- 8103200013 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades." No response required.
  DTREILLY, J. P. Region 2, Atlanta, Office of the Director 81/03/13 to.
- S Reportable occurrences, LERs & related correspondence
- 8103160746 Significant Deficiency Rept 413-414/81-02 re cracks found in contacts. Initially reported on B10202 Replacement parts for all broken or cracked arcing contacts to be provided by manufacturer PARKER. N. Duis Power Co. 81/03/09 3pp 07914:139

- DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1 A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interim actions & request for add info
  FISENHUT. D. O Division of Licensian B0/12/22 30m
- 8103190397 Lin to all licensees of operating plants & applicants for OLs & holders of CPs to program for environ qualification of safety-related electrical equipment Items addressed or serecy-related electrical equipment learns allowed involve cold shutdown replacement parts & AUREO-0737 EtSEKNIT, D. Q. Division of Licensing 81/01/19. Opp.
- 8103120014 Ltr to all licensees of operating plants.CP holders & CL applicants.except indian Point 2 & 3.7ion 1 & 2 & TMI-1. Forwarding inadvertently onitted pages from ARC 801222 request for add info re control of heavy loads EISENHUT, D. C. Division of Licensing, 81/02/03.
- S103090096 Notification of S10226-27 resting u/util & Bechtel in Bothwada.ND re revieu of applicant energency procedures MATORE.J.A Licensing Branch 3 51/02/09 3pp 07849 120

07832: 120

- B103030345 Requests addl info re FBAR FBAR should be arended to reflect FESCORES. TEDESCO.R L Assistant Director for Licensing. 81/02/20 7pp
- D103250024 Ltr to all power reactor licensees & license applicants re NJREQ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.
  EISENHUT.D Q. Division of Licensing 81/02/20 Gpp
- 8103120467 Notification of 810309-10 resting w/util & BNH. in Tulea. DK to review & walk through applicant energency operating MARTORE, J. Licensing Branch 3 81/02/25 3cc. 07905-154
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (except St Lucie,Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures £18ENHUT, D O Division of Licensing 81/02/25 Spp
- 8103030742 Forwards preliminary revision of FSAR Section 13.2 retraining in support of NRC review of NJREG-0737 THI-related requirements. Response to NRC 810126 itr re new requirements clarifications will be provided at later date.

  DALE-L F. Hississippi Power & Light Co. 81/02/26. 31pp. 07789-031
- 8103170225 Ltr to all BWR licensess (sreet Humtoldt Bau & LaCrosse) itys/2/23 (tr to a) but itselsess it arrept number by but acre-requesting review of ASME Code Cless 1 & 2 pressure boundary piping, safe ends & fitting mati per guidelines of enci Revision 1 to NUREO-0313 Model Tech Specs only enci EISENHUT.D.O Division of Licensing 81/02/26 3pp
- --BI03170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 resurveillance requirements for ASME Code Class 1.2 & 3 components & RCS operational leatage limiting conditions for operation & surveillance requirements # General Electric Co 81/02/26 4pp.
- BiO3170655 Ltr to holders of CPs & applicants for OLs (BHRs) requesting review of ABME Class 1.2 & 3 pressure boundary piping safe ends & fitting mati per guidelines of encl Revision 1 to NUREO-0313. Hodel Tech Specs only encl. EISENHUT, D. G. Division of Licensing 81/02/26. 3pp.
- 8103230813 Generic Ltr Bi-O6 to all CP holders & OL applicants re 10CFR5D 71(e). "Periodic Updating of FSARs," effective 800732. Info re FSAR legal status fornat & content encl EISEMBUIT.D. O. Division of Licensing. 81/02/26 10pp.
- 8103120327 Forwards proprietary GA program calculation sheets in response to NRC 800317-21 structural audit. Info withheld (ref 10CFR2 790).
  TRICKOVIC: R B Bechtel Power Corp (subs. of Bechtel Corp.), 81703703. 2pp 07906:337.
- 8103160147 Discusses interim actions needed for plant operation pending timel resolution of ATMS Emergency operating procedure should be developed describing actions to be taken in event of ATMS inculding manual ectarning tracedure to ATMS inculding manual ectarning actions to be taken in event of ATMS inculding manual ectarning tracedures. 07919: 330.

- B103160216 Approves 800606 request that info re NRC Mar 1980 stru-audit of facility be withheld from public disclosure (ref 1905FR2 770) TEDERCO.R I Assistant Director for Licensing 81/03/04 20/
- 8103100595 Forwards partial response to IRC 810127 request for it equipment qualification for select 2 hydrodynamic loads for non-NSSS equipment Response available in Central Files nn lu DALE, L.F. Hississippi Power & Light Co. 81/03/06 200 078
- 8103130400 Forwards clarification of previous changes in responsibilities Detailed organization chart encl STAMPLEY,N L Mississippi Power & Light Co 8103/09 3pp

07918 334

07907 069

- B103310B04 Ltr to all licenspes of uperating plants, applicants for the holders of CPs forwarding SFCY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment
- FISENHUT, DO Division of Licensing 81/93/10 App
- B103170523 Forwards proprietary info re autilitary bldg & contains bldg seismic time histories to assist in structural review of facility Lists seismic time histories provided Info withheld (ref 10CFR2 790) IRICKDVIC.R S Bechtel Power Corp (subs of Bechtel Corp ) 81/03/12 2pp 07930 il6
- 8103180228 Forwards preliminary response to NAC 810127 request for a engipment qualification for seismic & hydrodunamic loads re equipment qualification for seismic a righted for NSOS equipment Pertinent portions will be included in future FSAR amend Encl available in Central Files only DALE, L.F. Mississippi Pawer & Light Co. 81/03/16 2pp. 079
- 0103230828 Summary of 010926-27 meeting w/util 5 BNHL in Belbesd discuss emergency operating procedures per NUREG-0737 W/list of attendess
  MARTORE. J A Licensing Branch 3 81/03/16 Spp 07974 090
- 8103230898 Forwards Feb 1981. "Assessment of Impacts of Grand Gu: Nuclear Station on Threatened or Endangered Species " MIRAGLIA, F.J. Licensing Branch 3 81/03/17 (p. 07975-012
- 8103230541 Forwards 12 marked-up oversite drawings representing redundant safe shutdown raceway in auxiliary bldg corridors. Drawings are submitted per NRC 801203 & 04 request Aperture cards are available in PDR DALE.L.F. Mississippi Power & Light Co 81/03/18 4pp 079:
- 8103260997 Notification of 810326 meeting w/util in Bethesda-MD review facility OL schedule & projected fuel load date MARTORE. J.A. Licensing Branch 3 81/03/19. 3pp 00035-149
- E. NRC Safety Evaluation Report (SEA), supple & correspondence
- 8102 70606 Forwards graft input for SER. Chapter 2 3, prepared by 1021/0506 Parwards draft input for Sex.(hapter 2 3 prepared by Accident Evaluation Branch Open Libers in neteorology section review pertain to applicant program for measurement & utilization of parameters for emergency planning KREGER.HE Assistant Director for Radiation Protection 01/6 7pp 65013 184
- Bi03230887 Discusses OL hearing scheduling process. SER technical schedule for CYBL & CYB2 encl DENTON.H R Office of Nuclear Reactor Regulation. Director Bi/03/13 bp 07977:069
- F Security, medical, emergency & fire protection plans
- Bio3310338 Ltr to all licensees of operating plants & holders of 103310338 Ltr to all licensees or operacing placts o number forwarding NUREO-06%. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISENHUT.D 9. Division of Licensing 81/03/05 opp
- 8103160989 Forwards "Review Comments on Orand Oulf Nuclear Stati-Emergency Plan (Submitted S011RO)," containing addl info needed to complete review. Plan should be revised to comply w/NUREO-06594 Revision 1. Criteria for onsite preparedness TEDESCO.R.L. Assistant Director for Licensing. 81/03/06. 2p 07921: 147.
- 8103170199 Forwards revised security training & qualification pl. withheld (ref 100FR2.790).
  MCGAUGHY.J.P. Mississippi Power & Light Co B1/03/11. 2pp. 07933: 199.

- 8163231373 Forwards list of questions inappropriate for inclusion in recest for into refacility fire protection review #1RAG...IA.F Licensing Snanch 3 81/03/17 15pp
- 4 Jeneral correspondence
- 9:031207944 Advises that B10127 submittal re operational QA organilation changes does not neet requirements of Criterion I in App B to 10CFR20 Requests justification of reporting structure % identification of operation of specific job roles within 14 days HAA85. W.P. Quality Assurance branch 81/02/23 1p 07706 347
- K Littlity Final Safety Analysis Report (FSAR) & amends
- E103233529 for Jands affidavit of svc certifying distribution of whend 46 to FSAR.per NRC 780627 its CALE.L f Mississippi Power & Light Co 81/03/18 2pp 07979 346
- 0 Inspection reports. IE Bulletins & correspondence
- 303041022 Forwards IC Insp Rept 30-416/80-28 on 801103-26 No roncompliance nuted LFMLB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support 3-aach 80/01/19 2pp 07812-028
- --9103C41026 IE Insp Rept 50-416/80-28 on B0J103-26 No noncompliance noted Hajor areas inspected preoperational test procedure review case load forecast 5 preparations for fuel receipt HACIER.A 0 Region 2. Atlanta. Office of the Director RECLOGG.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch BIJOJ/18 5pp -07812-030
- E103020269 Forwards II Circular 81-02, 'Performance of NRC-Licensed Individuals While on Duty " No written response required D:REILLY, J. F Region 2: Atlanta, Office of the Director B1/02/09 If 0.7785 338
- 6103160331 Forwards (C Insp Repts 50-416/81-02 & 50-417/81-01 on BIOL21-23 No noncorpliance noted MAPPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Buppert Granca B1/02/10 2pp 07949 295
- "Us03180508 IE Insp Repts 90-412/81-92 & 20-417/81-01 on Bi0121-23 No noncempliance noted. Major areas inspected previous items concerning radiography & followup of licensee identified items

  GREF, J. L. VANBOURGE, P. K. Region 2. Atlanta. Defice of the Director. HERDI, A. R. Rugion 2. Atlanta. Reactor Construction & Engineering Support Brench. 81/02/10. Spp. 07749-297.
- 9103040141 Forwards IE Info Notice 81-03, "Checklist for Licensess Massrg Notifications of Bignificant Events in Accordance Wildoff890, 72 " No written response required O'AEILLY, J. P. Region 2: Atlanta, Office of the Director 81/02/12 pp. 97819 318
- 6169620331 flequests 40-day extension for IE Bulletin 90-23 response. Extension required to contact suppliers utilizing solenoid valves in safety-related sys to determine if Valcor Engineering was used as manufacturer
- DALE.L. F. Mississippi Power & Light Co. 81/02/13 1p 07784 269
- 0:03240619 Resounds to NRC 810119 ltr re violations noted in IE Insp. Papt 30-416/80-24 Corrective actions affected packages reviewed documents corrected 6 entered into package for completion.

  874\*PLEV.RL Mississippi Power & Light Co. 81/02/13 Spp. 07982 295
- --3103240520 Forwards IE Insp Rept 90-416/80-24 on 801001-31 & notice of violation LENIES C Region 7. Atlanta. Reactor Construction & Engineering Support Branch 01/01/19. 2pp. 07982 300
- --B193240626 Notice of violation from insp on 801001-31 • Region 2, Atlanta, Office of the Director B1/01/18 2pp 07402 332
- --8103240634 IE Insp Rept 50-416/80-24 on 801001-31 Nancompliance noted failure to follow walkdown protectors/failure to protect plant equipment & Failure to control sys altorations.

  MADRER.A G. Region 2: Atlanta: Refice of the Director KELUG2.P J. Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 81/01/18 //pp 07982 301

- --Bio3260186 IE Insp Rept 50-416/81-01 on Bio107-09 No noncompliance noted Major areas inspected preoperational testing GA program & testing records
  BELISLE.O A. FRECRICKSON.P. Region 2. Atlanta, Office of the Director. UpRIGHT.C H. Ragion 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/02/11. 9pp. 08041 296
- BIO3120579 Forwards Suppl 9 to 1E Bulletin 60-17. "Failure of Control Rods to Insert During Stree at BUR" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/02/17 p. 07905 240
- 8102050045 Ack receipt of 810117 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-416/80-27 & 90-417/80-17 RVRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/18 ip 07827 235
- --BI0305009B Responds to NRC 801224 itr re violations noted in IE Insp Repts 50-416/80-27 % 50-417/80-17 Corrective actions stop work order issued OA program revised to control temporary installations & nonconforming supports (dentified PCOA/PHY.J P Mississippi Power & Light Co 81/01/19 5pp 07827-236
- --Bl03050067 Forwards IE Insp Repts 50-416/80-27 % 50-417/80-17 on B01124-26 & notice of violation.
  MNRPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/12/24 2pp 07827.241
- --B103050073 Notice of violation from insp on B01124-26
  \* Region 2. Atlanta. Office of the Director B0/12/24 ip
  07827 243
- --B1030500B2 IE Insp Repts 50-416/B0-27 & 50-417/B0-17 on B01124-26
  Noncompliance nated control of temporary control rod
  drivatine sys pips supports & checkout & turnover
  organization activities
  BLAKE. J. Region 2. Atlanta. Defice of the Director HERDT, A R
  Region 2. Atlanta. Reactor Construction & Engineering Support
  Dranch B0/12/22 Spp 07027 244
- 8103030687 Responds to NRC 791018 ltr re violations noted in 16 Insp. Repts 50-416/79-15 & 50-417/79-15. Corrective actions QE completed tests in Jul 1980 to demonstrate qualification of power generation control complet cable connectors MCGAUGHY. J. P. Mississippi Power & Light Co. 81/02/20 15pp 07794 103
- 8103030725 Forwards interim responses to IE Bulletins 79-27 & 80-06 & patential design deficiencies in bypass override & reset circuits of engineered safety features. Response to IE Bulletin 79-27 scheduled for 810601 submittal DALE.L.F. Mississippi Power & Light Co. 81/02/20. \$4pp. 07795.093
- 8103160583 Forwards IE Cirtular 81-03. "Inoperable Seismic Monitoring Instrumentation" No response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/02 Jp. 07917:046
- BiO317009B Forwards revised IE Bulletin 81-01. "Surveillance of Machanical Bnubbers." w/corrected Pages 5 & 6 Util is added to CP facilities to which bulletin is applicable Response should include estimate of mangower expended. Bracility. P. Region 2. Atlanta. Office of the Olirector 81/03/04. ip. 07939-215.
- BiO3170095 Responds to IE Bulletin BO-21. "Valve Yotes Supplied by Malcolm Foundry Co.Inc." Partial review did not disclose use of specified valve parts Requests 60-day extension to complete review DALE, L.F. Mississippi Power & Light Co. 81/03/05. 2pp. 07935-357.
- 8103200258 Forwards | E Info Notice 81-06. "Failure of IYE Model K-600 Circuit Breaker." No response required O'REILLY, J. P. Region 2. Atlanta. Office of the Director 81/03/11 1p. 07968-349
- 8103190895 Forwards IE Info Notice 81-05. "Degraded DC Sys at Pallsades" No response required.

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03/13 ip 07965:300
- 8103310894 Responds to IE Bulletin 80-25. "Operating Problems W/Target Rock Safety Relief Valves at CURs." Appropriate GC procedures will assure insplot solenoid actuators for excess Loc-Title prior to operation. DALE.L F Mississippi Power & Light Co. 81/03/19. 4pp. 08058 152
- 8103260169 Forwards | E. Insp. Rept. 50-416/80-01 on 810107-09 No noncompitance noted Unresolved (tem disclosed LEMIS.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 81/02/13 2pp. 08041 294

- S Reportable occurrences. LERs & related correspondence
- 8103030785 Deficiency rept to failure of tack weld on safety-related automatic air damper supplied by Pacific Air Products Co. initially reported on 800912 Util working w/constructor rereportability per 100FR50.55a & 100FR21 MCGAUDHY.J. P. Mississippi Power & Light Co. 80/10/13 2pp
- G100040745 Status Rept 2 re Reactor Controls. Inc issuance of drawings prior to design adequacy verification, initially reported B00925 A/E is teviewing supplier evaluation Final rept expected by B10016
  MCGAUCHY, J. P. Mississippi Power & Light Co. 81/01/15 3pp 07810-164
- Bio3030774 Status Rept i for potential deficiency me Yarway motor operated valve chatter initially reported 810127. Final capt projected for submission by 811118 subject completion of svaluation of vendor & constructor final responses MCCAUGHY. J P Minnesota Power & Light Co 81/02/19 3pp. 07788 344
- B103050B91 Part 21 Status Rept 3 ra contact & indication malfunctions of Eletro Switches. Series 20. Type PR-20 & OE Switch S3A. initially reported on 800702 NSSS supplier has taken action to replace Switch 93A Final rept by B10717 MCGAUGHY, J.P. Mississippi Power & Light Co. 81/02/19 Spp. 07829 348
- 8103130048 Part 21 rept re design of mounting straps on Tuttle & Bailey heating ventilation & air conditioning sir diffusers, initially reparted 810129 investigation in progress to determine cause Final rept is due 810722 MCGAUJHY, J. P. Mississippi Power & Light Co 81/03/02 3pp 07912, 039
- B103240021 Final Part 21 rept re defective recirculation purp hanger components supplied by ITT Orinnell initially reported B01027. Equipment will be used in present condition Condition not reportable per 10CFR30 55(e) or Part 21 MCGAUGHY, J. P. Mississippi Power & Light Co. 81/03/02 3pp notable 234.
- 103240037 Part 21 rept re N9C Deviation Item 416,417/80-25-02 per 801028-31 IE Insp Repts 50-416/80-25 % 50-417/80-15.Full rept will be submitted by 810715. KCAUCHY, J. P Mississippi Power & Light Co 81/03/03 ip 07989-334
- B103170422 Interim deficiency rept.originally reported on B10804, re installation of expansion enthors for conduit hangers, instrument process tubing 5 air supply supports 2/0 proper approval Procedures revised Final rept to 56 sent by B10724 MCGAUGHY, J. P. Mississippi Power & Light Co. B1/03/10. 3pp. 07923, 203.
- B103170659 Final deficiency heptire reactor pressure vessel feedwater notals deficiency originally reported 800417 Evaluation determined deficiency not reportable per IOCFR50 55e MCQAUGHY, J. P. Mississippi Power & Light Co. B1/03/13 3pp 07925-141.
- 8103230726 Interim deficiency rept to installation of standby svc water pump. Initially reported on 810212 Pumps in Basins A & B inspected for deficiency & installation compared w/design drawings Final rept to be submitted by 810901. MCOAU0417 J. P. Mississippi Power & Light Co. 81/03/16 4pp 07974:190
- BiO3250441 Interim deficiency rept re-potential loss of solio metallic grounding of flexible conduit-originally reported 801210 Grounding requirement document will be issued to prevent recurrence of deficiency. Final rept by 810901 MCGAUGHY, J. P. Mississippi Power & Light Co. 81/03/19 4pp. 07996-203
- 8103270701 First Interim deficiency rept re-potential newspressurization of MSIV drain line piping. Initially reported on 810218 Caused by design errors Investigation is ongoing. Final rept will be submitted by 810916 MCGAUGHY. J. P. Mississippi Power & Light Co. 81/03/20. 4pp. 03047 045
- B103310663 Interim Deficiency Rept 9 re-discrepancies in design documentation for gower generation control complex penels & nardweep-priginally reported on B00223 Caused by as-shipped panels not matching as-shipped drawings MCGAU3HY. J.P. Mississippi Power & Light Co. B1/03/24 3pp 08064.047.

- #3100310411 Btatus Hept 2 re deficient nods to control noom heatsventilation 3 atronduitioning fire dampers initially reported 801216 Puring seliance event-safe operation could be affected As-built info being evaluated MCGAUNITU P Mississippi Power & Light Co 81/03/25 4pp 08062 102
- B103310400 Status Rupt 1 re ratis in ASCO valves not qualified fo accident conditions, initially reported B10224 Investigation in progress Final rept by B10801 mCoAUGHY.J P Mississippi Power & Light Co 81/03/26 3pp 08075 160
- DOCKET 50-417 GRAND GULF HUSLEAR STATION. UNIT 2

  A Application/construction stage documents & correspondence.
- 8103190397 Ltr to all licensees of operating plants & applicants OLs & holders of CPs re-program for ervison qualification of safety-related electrical equipment liters addressed involve cold shutdown-replacement parts & FUREC-0737 EJSENHUT.D O Division of Licensing 01/01/19 App
- B103120014 Ltr to all licensees of operating plants.CP holders 2 applicants.except Indian Point 2 & 3.Zion 1 & 2 & THI-1. forwarding inadvertently omitted pages from HRC B01222 request for add info re control of neavy loads EISENHJF.D O Division of Licensing B1/02/03 App
- B103090096 Notification of B10226-27 meeting u/util & Berhtel in Bethesds.MD re review of applicant energency procedures MATORE. J. A. Licensing Branch 3 81/02/07 Jpp 07849 (20
- B103050345 Requests add1 info re FSAR FSAR should be amended to responses
  TEDESCO.R L Assistant Director for Licensing B1/02/20 7;p
  07822 120
- 8103280024 Ltr to all power reactor licensees & license applicant NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D Q Division of Licensing 81/02/20 Upp
- Bio3120467 Notification of 810307-10 meeting w/wtil 5 BNNL in Tul to review 8 walk through applicant energency operating procedures MARTCRE.J Licensing Branch 3 B1/02/29 3pp 07905 194
- B103230030 Ltr to all licensees of operating nuclear power plants applicants for OLs (except St Lucie.Units 1 & 2) Requests util review to determine Capability to miligate station blackout event & promptly implement energency procedures EISENHUT.D 0 Division of Licensing 81/02/29 Spp
- 8103030742 Forwards preliminary revision of FSAR Bection i3 2 retraining, in support of NRC review of NARC-0737 TMI-related requirements Response to NRC Biol26 itr re new requirements clarifications will be provided at later date DALE.L.F. Mississippi Power & Light Co. Bi/O2/26. Bipp 07789-031
- B103170225 Ltr to all BWR licensees (except Humboldt Bay & LaCros requesting review of AGME Code Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of encl Revision 1 to NUREG-0313 Model Tech B
- --B103170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 surveillance requirements for ABME Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements + General Electric Co B1/02/26 4pp
- BIO3170655 Ltr to holders of CPs & applicants for OLs (BhRs) requirements of ABME Class 1.2 & 3 pressure boundary piping, safe ands & fitting math per guidelines of enci Revision 1 to NURGE-0313 Model Tech Specs only enci
- BiO3230Bi3 Generic Ltr Bi-Ob to all CP holders & CL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl. EISENHUT.D O Division of Licensing 81/02/26 10pp
- G103120327 Forwards proprietary GA program calculation sheets in response to NRC B00317-21 structural audit info withheld (ref 10CFR2 790) IRICKBUIC-R B Bechtel Power Corp (subs of Bechtel Corp ) B1/03/03 2pp 07906-337

- 8103:60147 Discusses interia actions needed for plant operation pending final resolution of ATLS Emergency operating procedure abould be developed describing actions to be taken in event
- of ATMS inculding manual scraming
  TEDESCOR L Assistant Director for Licensing 81/03/04 3pp A2019 333
- 8103140216 Approves 800606 request that info is fRC Mar 1780 structural audit of facility be withheld from public disclusive iref 10CER2 7931 TERRESCO. R L. Assistant Director for Licensing 81/03/04 Znd A2018 374
- 81031G0595 Forwards partial response to NRC 810127 request for info re equipment qualification for seismic & hydrodynamic loads for non-NSSS equipment Response available in Central Files CALE, L.F. Mississippi Power & Light Co. B1/03/06 2cn 07865 056
- 8103130400 Forwards clarification of previous changes in iogijausuu romands cianitication of previous changes in responsibilisties Detailed organization chart encl STARPLEY,N L. Hississippi Power & Light Co. BI/07/09. 3pp 07907 049
- 8:033:0804 Etr to all licensees of operating plants.applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical EISENHUT, D 9 Division of Licensing 81/03/10 600
- 810317-0523 Forwards proprietary info re auxiliary bldg & containment bldg sesemic time histories to assist in structural review of facility Lists seismic time histories provided info withheld (ref 10CFR2 790) TRICKOVIC.R S Bechtel Power Corp (subs of Bechtel Corp.)
  B1/03/12 2pp 07930 116
- 8103180220 Forwards preliminary response to NRC 810127 request for info re equipment qualification for setamic & hydrodynamic loads for NSSS equipment Pertinent partions will be included in future FBAR amend Encl available in Central Files only DALE.L F Mississippi Power & Light Co 81/03/16 2pp 97944 001
- 8103230828 Summary of 810226-27 meeting w/util & SNWL in Nethesda.MD to discuss emergency operating procedures per NUREO-0737 W/list MARTURE, J. A. Licensing Branch 3 81/03/16 Spp 07974 050
- 8103230098 Forwards Feb 1981. "Assessment of Impacts of Grand Oulf Nuclear Station on Threatened or Endangered Gpecies "
  MIRAGLIA.F J Licensing Branch 3 81/03/17 Ip 07975 012
- 8103030541 Forwards 12 marked-up eversize drawings representing rormans recommend to marked-up exerting cramings representing reduction take shutdown racesay in auxiliary bidg corridors. Orawings are subnitted per NRC 001203 & 04 request Aperture cards are available in PDR DALE, L. F. Mississippi Power & Light Co. 81/03/18 4pp 07974-067
- 8103260999 Notification of 010326 meeting w/util in Bethesde. MD to review facility OL schedule & projected fuel load date

3pp 08035 149

200

E MPC Bafety Evaluation Report (SER), supple & correspondence

MARTORE, J. A. Licensing Branch 3 81/03/19

- 8102176606 Forwards draft input for SER. Chapter 2. 3. prepared by Accident Evaluation Branch Open items in neteorology section ceview pertain to applicant program for measurement butilisation of parameters for energency planning KREGER, W. E. Assistant Director for Radiation Protection. 81/01/29 7cp. 65013 184
- 8103230887 Discusses OL hearing scheduling process SER technical input schedule for CV81 & CV82 encl DENTON-H R. Office of Nuclear Reactor Regulation, Director 81/03/13. App. 07977.069
- F. Security, medical, emergency  $\delta$  fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0896. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements W/o encl EEEEN-UT.D.O Division of Licensing 81/03/05. 6pp 8103160989 Forwards "Review Comments on Grand Oulf Nuclear Station Emergency Plan (Submitted 801120)." containing add1 info

needed to complete review Plan should be revised to comply WANDREG-0654. Revision furtheria for onsite preparedness

- 8103170199 Forwards revised security training & qualification oithheld (ref 100FH2 790)
  MCGAUGHY, J P Mississippi Power & Light Co 81/03/11 2p 07933 199
- 8103231073 Forwards list of questions inappropriate for inclu-request for info re-facility fire protection review M(RAQLIA:F Licensing Granch 3 81/03/17 15pp

8103120044 Advises that 810127 submittal re operational QA or

Mississippi Power & Light Co Bi/03/18 200

- H General correspondence
- changes does not meet requirements of Criterian I in App U to 10CFA50 Requests justification of reporting structure & identification of specific gob roles within 14 days Quality Assurance Branch 81/02/23 10 0790 K Utility Final Safety Analysis Report (FSAR) & amends
- B103230525 Forwards affidavit of svc certifying distribution Arend 46 to FSAR.per NRC 780627 ltr DALE.L F Mississippi Power & Light Co B1/03/18 2pp
- Q. Inspection reports, IE Hulletins & correspondence

- 8103020269 Forwards IE Circular Bi-O2. Performance of NRC-Li Individuals While on Duty "No written response required O'REILLY J. Region 2. Atlanta. Office of the Director Ip 07785-330
- 8103180501 Forwards 1E Insp Repts 50-416/81-02 & 90-417/81-01
- ROSIONANT FORWARDS IN 1915 Repts 30-4(8/81-02 & 30-4(7/81-01 BIO121-23 No noncompliance noted MURPHY, C E. Region 2, Atlanta. Reactor Construction & Engi: Support Branch BI/02/10 2pp 07949 295 --Bi03180508 IE losp Repts SD-416/81-02 % SD-417/Bi-01 on Bi0 naneompliance noted Hajor areas inspected previous items concerning radiography & followup of licensee identified itens.
- COLEY, J. L., VANDOORII, P. K. Region 2, Atlanta, Office of t Director HERDT, A. R. Region 2, Atlanta, Reactor Constru Engineering Support Branch 81/02/10. 5pp 07949.297 8103020381 Requests 60-day citension for IE Bulletin 80-23 re
  - Essension required to contact suppliers utilizing solenoid valves in safety-related sys to determine if Valcor Engineering was used as manufacturer DALE, L.F. Mississippi Pawer & Light Co. 81/02/13 ip 0
- 8103120579 Forwards Suppl 5 to IE Bulletin B0-17. "Failure of Rods to Insert During Scram at BWR" No written response repuired O'RETLLY J P. Region 2. Atlanta, Office of the Director
- 1p. 07905 240 B103090045 Ack receipt of B10119 ltr informing NRC of steps t correct violations noted in IE Insp Repts 50-416/80-27 &
- CONTROL VIDIALIAN AND 50-417/80-17 Sector Construction & Enginum Physics Region 2. Atlanta Reactor Construction & Enginum Physics Revolution Ph --8103050098 Responds to NRC 801224 ltm re violations noted i Repts 50-416/80-27 & 90-417/80-17 Corrective actions stop work order issued. GA program revised to control temporary
- installations & nonconforming supports identified MCGAUPHY, J. P. Mississippi Power & Light Co 81/01/19 07827 236
- --Bi03050067 Forwards IE Insp Repts 50-416/80-27 & 50-417/80-103020007 Forwards in into Region 30-416/60-27 & 30-417/80-801124-26 & notice of violation MURPHY.C.E Region 2. Atlanta. Reactor Construction & En Bupport Branch 80/12/24 2pp 07827 241
- --B103050082 IE Insp Repts 50-416/80-27 & 50-417/80-17 on 801 Noncompliance noted control of temporary control rod driveline sys pipe supports & checkout & turnover organization activities
  - BLAKE.J. Region 2. Atlanta. Dffice of the Director. HER Region 2. Atlanta. Reactor Construction & Engineering Sup Branch. 80/12/22. Spp. 07827 244
- B103030687 Responds to NRC 791018 ltr re violations noted in Repts 50-416/79-15 & 50-417/79-15 Corrective actions: GE completed tests in Jul 1980 to demonstrate qualification of power generation control complex cable connectors. MCDAUGHY, J.P. Mississippi Power & Light Co. B1/02/20 15 07774: 103.

- 8103030725 Forwards interim responses to IE Bulletins 79-27 & 60-06 & potential design deficiencies in typass.override & reset circuits of engineered safet, features Response to IE Bulletin 79-27 scheduled for 810601 submittal DALEL F. Nississippi Pawer & Light Co. 81/02/20 54pp 07795 093
- 8:03:60583 Forwards 1E Circular 8:-03, "Inoperable Seismic Monitoring Instrumentation" No response required O'REILLY, J.P. Region 2: Atlanta: Office of the Director 8:/03/02. pp. 07917-048
- 8103170063 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Shubbers.' w/corrected Pages 5 & 6 Change in Identification of factlities v/CPs to which bulletin is applicable does not affect util requirements. D'REILLY-J.P. Region 2. Atlanta. Office of the Director 81/03/04 ig 07939 187
- B103170095 Responds to TE Bulletin B0-21, 'Valve Yokes Supplied by Malcolm Foundry Co. Inc.' Partiel review did not disclose use of specified valve parts Requests 60-day extension to complete review DALE, L.F. Mississippi Power & Light Co. B1/03/09 2pp. 07935 357
- 8103200258 Forwards IE Info Notice 81-06, "Patjure of ITE Model K-800 Circuit Breaker" No response required.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/11 to 07988 349
- 8103190895 Forwards IE Info Notice 81-05, "Degraded DC Gye et Palisades" No response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director Bi/03/13 ip 07965 300
- 8103310894 Responds to IE Bulletin 80-25. 'Operating Problems W/Target Rock Bafety Relief Valves at BWRs " Appropriate GC procedures will assure imag of solenoid actuators for excess Loc-Tite prior to operation DALE, LF Mississkapp Rower & Light Co 81/03/19 4pp. 08058 152
- 8 Reportable occurrences. LERs & related correspondence
- B103030785 Deficiency mept me failure of tack weld on safety-melated automatic air damper supplied by Pacific Air Products Co. initially reported on B00912 Util working u/constructor me reportability per 10CFR50 55e % 10CFR21 MCQAUGHY. J.P. Mississippi Power & Light Co. B0/10/13 2pp 07796, 122
- 8103040745 Status Rept 2 re Reactor Controls. Inc. issuance of drawings prior to design adequacy verification, initially reported 800925. ArE is reviewing supplier evaluation Final rept expected by 810316.
  MCOAUGHY, J.P. Mississippi Power & Light Co. 81/01/15. 3pp. 07610-166
- B103030774 Status Rept 1 for potential deficiency re Yarway motor operated valve chatter initially reported B10127 Final rept projected for submission by B111B subj to completion of evaluation of vendor & constructor final responses MCCAUGHY. J P Minnesota Power & Light Co 81/02/19 3pp 0778B.344
- 8103050891 Part 2) Status Rept 3 re contect & indication malfunctions of Eletro Suitches, Beries 20. Type PR-20 & DE Switch S3A, initially reported on 600702 NSSS supplier has taken action to replace Switch 83A Final rept by 810717.

  MCGAUDHY. J P Mississippi Power & Light Co 81/02/19 5pp 07829 348
- 810313004B Part 21 rept re design of mounting straps on Tuttle & Bailey heating ventilation & air conditioning air diffusers, initially reported 810107 Investigation in progress to determine cause. Final rept is due 810722 MCGAUDHY, J.P. Mississippi Power & Light Co. 81/03/02 3pp. 07912 039.
- 8103240037 Part 21 rept re NRC Deviation Item 416.417/80-25-02 per 801028-31 IE Insp Repts 50-416/80-25 & 50-417/80-15 Full rept will be submitted by 810715.

  MC9AUGHY, J.P. Mississippi Power & Light Co. 81/03/03. 1p 07889, 334.
- Bi03170922 Interim deficiency rept. originally reported on Bi0504, re installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports w/o proper approval Procedures revised Final rept to be sent by Bi0924. MCONVDHY. J.P. Hissistippi Power & Light Co. Bi/03/10. 3pp 07923-203.

1

- 8103170699 Firal deficiency rept re reactor pressurnozile deficiency, originally reported 800417 Evaluate remined deficiency not reportable per 100FR50 MCOAUGHY. J P Mississippi Power & Light Co 81/107995 tal
- B103230726 Interin deficiency rept re installation of pump. Initially reported on B10212 Pumps in Basins inspected for deficiency & installation compared of autority First rept to be submitted by B10901 MCGAUOHY. J P Mississippi Power & Light Co 81/4 07974 150
- 8103250441 Interin deficiency rept re-patential loss graunding of flexible conduit originally reported graunding requirement document will be issued to precurrence of deficiency Final rept by 810901 MCGAUGHY. J P Mississippi Power & Light Co 8170 07996 203
- 8103270701 First interim deficiency rept he potentioverpressurization of MSIV drain line piping init reported on 810218 Caused by design errors Invest ongoing Final rept will be submitted by 810916 MC9AUGHY. J P Mississippi Power & Light Co 8170 08047 045
- B103310663 Interim Deficiency Rept 9 to discrepancial documentation for power generation control comple hardware originally reported on B00223 Caused by penels not matching as-shipped drawings MCQAUOHY. J.P. Mississippi Power & Light Co. 8176 B004: 047
- B103310411 Status Rept 2 re deficient nods to controventilation & airconditioning fire dampers initial reported B01216 During seismic event safe operation affected As-twilt info being evaluated MCGAUGHYJ P Mississippi Power & Light Co 8170 08062 102
- B103310400 Status Rept 1 re maths in ASCO valves not accident conditions.instially reported B10224 invoin propess Final rept by B10801 MCQAUQNY.JP Mississippi Power & Light Co B1/C 08075 to0
- DDCKE1 50-423 HILLSTONE NUCLEAR POWER STATION. UNIT
- B103190732 Ltrs to all licensees of operating plants
  DLs & holders of CPs recontrol of heavy loads Rec
  review per guidelines in MUREO-0612 Forwards NRC p
  interim actions & request for addition
  EISENHUT. D. G. Division of Licensing 80/12/22
- B1031903B7 Ltr to all licensoes of operating plants OLs & holders of CPs to program for environ quality of safety-related electrical aquipment Items addressivate cold shutdown replacement parts & NUREC-07 E18EKHUT.D O Division of Licensing B1/01/19
- B103120014 Ltr to all licenses of operating plants, applicants.except Indian Point 2 & 3.7ion 1 & 2 & forwarding inadvertently omitted pages from NRC BC request for addl info re control of heavy loads EISENHUT.D 3 Division of Licensing B1/02/03
- B103160669 Ltr to all operating plants 8 CP holders clarification of TMI Action Plan Item III A 3 2 re of amergency support facilities Requests confirmat 45 days that implementation dates will be net E166NMUT. D Q. Division of Licensing 81/02/18.
- 8103250024 Ltr to all power reactor licensees & lice RUREO-0619 criteria Footnote 2 in Table 2 contains to leakage testing Jeletions Licensee may submit a justify use of existing low flow controller. EISENHUT.D 9 Division of Licensing 81/02/20.
- 8103230813 Generic Ltr 81-06 to all CP holders & OL (OCFR50 71(e), "Periodic Updating of FBARs." effec 800722. Info re FBAR legal status.fornat & content EIBENHUT.D 9 Division of Licensing 81/02/26
- 8103310804 Ltr to all licensees of operating plants. & holders of CP4 forwarding SECY-81-119 re info ne establish environ qualification of safety-related equipment. EISENHUT.D.O Division of Licensing 81/03/10.

- F Security, medical, emergency & fire protection plans
- 8:033:0338 Lir to all littensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Energenty Response Facilities "Cliteria describe acceptable method for meeting NPC requirements N/o encl E186:NHJTO 2 Olvision of Litensina 81/03/05 6gg
- J. Insurance & indemnity information
- 8103100415 Forwards Endorsement 5 to MELIA Binders EB-15 & EB-16 CORRELL T J. Northeast Utilities 81/03/04 Rec. 07885:207
- BiO3310424 Forwards Endorsement 60 to MAELU Policy NF-52 SINISI.J M March & McLennan. Inc., M & M Nuclear Consultents, Inc. Div. Bi/03/27, 3pp 08078-293
- G. Inspection reports: IE Bulletins & correspondence
- B103020148 Forwards 1E Info Notice 81-01. "Possible Failures of GE Type HFA Relays." No response required GRIER.8 H Region 1. Philadelphia. Office of the Director B101/16 1p 07785 233
- 8103140145 Forwards 1E Mgt Meeting Rept 50-423/81-01 on B10106 No response required CARLSO'R T Region 1. Philadelphia. Reactor Construction & Engineering Support Oranch 81/01/28 2pp 07921 226
- --Bi03160155 IE Mgt Meeting Rept 50-423/81-01 on 810106 Areas discussed details re establishment of onsite ofc for placing full tire NRC inspector at facility M4TTIA.U C. CARLSON.R T. Region 1. Philadelphia, Reactor Construction & Engineering Support, Branch MCOSCAR, U. Region 1. Philadelphia, 0ffice of the Director 81/01/27 2pp 07921.228
- 8103200239 Forwards IE Circular 81-03. 'Inoperable Geismic Monitoring Instrumentation' No written response required GRIER.8 H Region I. Philadelphia. Office of the Director 81/03/02 ip 07972-073
- G10320C039 Forwards revised IE Bulletin 81-01. 'Burveillance of Machanical Shubbers." w/corrected Pages 5 % 6 Change in identification of facilities w/CP to which buildtin is applicable does not affect util requirements GRIER.8 H. Region 1. Philadelphia. Office of the Director G1/03/04 1p 07968 181
- 6303200184 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required GAIER.8 H Aegion 1. Philadelphia. Office of the Director 61/03/11 1p 07968 310
- 8. Reportable occurrences. LERs & related correspondence
- 8103100158 Responds to 800730 final Hept me deficiencies in rect anchor design & shear wall design Rept does not provide sufficient detail to enable NRC to determine sufficiency of corrective actions
  GARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 81/01/29 1p 07865 345
- G103100272 Ack receipt of B10119 interim deficiency rept re misalignment of shop welds CARLEOU.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B1/02/05 1p
- OCCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- RIO3190732 Ltrs to a)] licensees of operating plants applicants for CLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re-interim actions & request for add1 info.

  EISENHUT.0 0 Division of Licensing 80/12/22 30pp
- 8103020037 Requests draft inputs to safety evalution & EIB for CP amend re deletion of containment encl bldg. Info should be submitted by 810122 SCHWENCER.A. Licensing Branch 2. 81/01/13 2pp. 07785.052
- B103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs re program for environ qualification of sefety-related electrical equipment libens addressed involve cold shutdown, replacement parts & NUREO-0737 EISE:\*HUTO D Q Division of Licensino B101/19 Ann

- B103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3.7ion 1 & 2 & TMI-1. forwarding inadvartently omitted pages from NRC 801222 request for addlinforce control of heavy loads EISEN-WT.D G Division of Licensing B1/02/03 App
- 8103050720 Summary of 810129 meeting w/util in Bethesda.MD re-schedu for submitting OL application BURWELL.S B - Cicensing Branch 2 81/02/11 6pp 07821:353
- 8103090697 Forwards notice of proposed issuance of CP amends which have submitted for FR publication SCHEROCE.A Licensing Branch 2. 81/02/17 2pp 07844:246
- --B103090693 Notice of proposed issuance of amend to CPs SCHWENCER, A. Litensing Branch 2 81/02/17 dpp 07844, 248.
- 9:03160669 Ltr to all operating plants 6 CP holders forwarding clarification of TM1 Action Plan Item III A I 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be net EISENHUT D 9 Division of Licensing 81/02/18 12pp
- B103250924 Ltr to all power reactor kicensees & license applicants r NUREG-0619 criteria Footnote 2 in Table 2 contains error dus to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.D.O Division of Licensing. 81/02/20 Bpp
- BiO3230Bi3 Generic Ltr Bi-06 to all CP holders & OL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 600722 Info re FSAR legal status format & content encl EISENHUT.D. O Division of Licensing. 81/02/26
- 8103310894 Ltr to all licensees of operating plants applicants for Discharge of CPs forwarding SECY-BI-119 reinfo necessary to establish environ qualification of eafety-related electrical equipment EISENHUT, D. O. Division of Licensing 81/03/10. App.

  8103300325 Requests mod of PSAR Figures 2 5-15 & 2C-13 to allow backfill compacted to 95% in area north of turbine bldg
- backfill compacted to 98% in area north of turbine bldg Change will maximize use of remaining onsite Category I backfill mail HEAD.Q F Georgia Power Co 81/03/25 Spp 08035 148
- F Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding hUREO-0676. 'Functional Criterie for Emergency Response Facilities " Criterie describe acceptable method for meeting NRO requirements N/o enci
- Q Inspection reports. IE Bulletins & correspondence
- 8103050358 Forwards 1E Hgt Meeting Repts 50-321/80-41.50-366/80-41. 50-424/80-16 & 50-425/80-16 on 801020 Ng noncompliance noted O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 81/01/21 2pp 07824 227
- --8103030368 IE Mgt Meeting Repts 90-321/80-41,50-366/80-41,50-424/80 & 50-425/80-16 on 801020 Major areas discussed NRC evaluation of util regulatory performence per systematic assessment of licensee performence program.

  LEMIB.R C. Region 2. Atlanta, Reactor Operations Nuclear Supportended 81/01/28. 16pp 07824.229.
- 8103020263 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/0' ip. 07785: 333
- B103160560 Forwards IE Circular B1-03, "Inoperable Beismic Monitoring Instrumentation " No response required. Q'REILLY, J P Region 2. Atlanta. Office of the Director B1/03/06 1p. 07916-340
- 8103170079 Forwards revised JE Bulletin Bi-Oi. "Burveillance of Mechanical Snubbers." w/corrected Pages 5 t 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, J.P. Region 2. Atlanta. Office of the Director. Bi/O3/O-ip. 07939 284

- 8103200263 Forwards to Info Notice 81-06. "Failure of 116 Model K-600 Circuit Breaker" No response required O'REILLY, J.P. Region 2. Atlanta. Dirice of the Director. 91/03/11 p. 07768 358
- 8103200036 Forwards IE Info Notice 81-05. "Degraded DC Sis at Palisades." No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/13 tp. 07949 103
- B103240860 Ack receipt of B10303 ltr informing NRC of steps taken to correct violations noted in IE Imag Repts 50~424/81-01 & 50~425/81-01.

  LEWIB,R C Region 2: Atlanta. Diffice of the Director B1/03/13 to 07983:300
- --8103240668 Responds to ARC 810205 ltr re violations noted in IE lnsp Repts 30-424/81-01 & 50-425/81-01 Corrective actions procedure change made to incorporate correct testing procedure & rowise Concrete placement pour 10g KELLY.R J Georgia Power to 81/03/03 2pp 07983.301
- --8103240574 Forwards IE Insp Repts 30-424/81-0) & 50-425/81-0) on B10105-09 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Granch 81/02/05 2pp 07483 303
- --8103240678 Notice of violation from insp on 810106-09

   Region 2. Atlanta. Office of the Director 81/02/05 lp
  07983 305.
- ~-Bi03240&B6 1E insp Repts 30-424/8i-01 & 50-425/8i-01 on Bi0106-09 Noncompliance noted failure to tample concrete test cylinders every 100 cubic yards HARRIS.J R Region 2. Atlanta. Uffice of the Director CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branc. Bi/02/03 3pp 07983 306
- B103270132 Forwards IE Inst Repts 50-424/81-04 & 50-425/81-04 on B10218-20 & notice of violation LEWIS, R. C. Region 2. Atlanta, Office of the Director 81/03/13 230 08043 304
- --B103270145 Notice of violation from insp on B10218-20 \* Region 2. Atlanta. Office of the Director B1/03/13 ip 08043 306
- --8193270198 IE Insp Repts 50-424/81-04 \$ 50-425/81-04 on 810218-20 Noncompitance noted failure to follow procedure for controlling nonconformance items.
  CRCMILEY. 8. R. HERDY A R. Region 2. Atlanta, Office of the Director. 81/03/05 9pc 08045.307
- B103310921 Responds to IE Builetin 79-03A. 'Langitudinal Held Defects in ABME SA-312. Type 304 Stainless Steel Pipe ' Add1 info will be provided by B10403.pending B10323 tompletion of Hestinghouse investigation DUTCN.D Georgia Power Co. B1/03/20 2pp 08038.137.
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT. UNIT 2

  A Application/construction stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs to control of heavy loads Requests to twiew per guidelines in NNREG-0612 Forwards NRC position reinterin actions & request for addl info EISENHJT.D O Division of Licensing 80/12/22 30pp.
- 8103020037 Requests draft inputs to safety evalution & ETS for CP amend re delation of containment encl bldg Info should be submitted by 810122 BCHGENCER.A. Licensing Branch 2. 81/01/13 2pp 07785:052.
- 8103190397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed invalve cold shutdown-replacement parts & NUREO-0737.
  EIGENRUT.D.9 Division of Licensing. 81/01/19 opp.
- 8103120014 Ltr to all licensees of operating plants.CP holders & GL applicants.except Indian Point 2 & 3.2ion 1 & 2 & IMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads EIBENHUT.D.O Division of Licensing 81/02/03 6pp.
- BiO3050720 Summary of BiO329 meeting w/otil in Bethesda.AD re-schedule for submitting DL application BURWELL-B. B. Licensing Branch 2. 81/02/11. App. 07921:353.

- B103090687 Forwards notice of proposed issuance of CP amend been submitted for FR publication SCHWERGER A. Licensing Branch 2 51/02/17 2pp 07846
- --9103090693 Notice of proposed issuance of amend to CPs SCHKENCER, A Licensing Branch 2 81/02/17 6pp 078
- BIO316066\* Ltr to all operating plants & CP holders forward clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation with 45 days that implementation Jates will be mot EIBENHUT. D @ Division of Licensing 81/02/18 12pp.
- Bio3250024 Ltr to all power reactor licensees & license app MUREG-0519 criteria Footnote 2 in Table 2 contains error in to leakage testing deletions Licensee may submit analysis justify use of existing low flow controller EISE/NUT.D 0 pivision of Licensing GI/02/20 Bpr
- B103230B13 Generic Ltr 8[-06 to all CP holders & UL application (CCFRS) 71(e), "Periodic Updating of FSARs." effective B30722 Info re FSAR legal status format & content enci EIREMHUT.D. O Division of Licensing 81/02/26 10pp
- R103310804 Ltr to all licensees of operating plants.applical E holders of CPs forwarding BECV-81-119 re info necessary establish environ qualification of safety-related electric equipment
  ETEENHULD O Division of Licensing 81/03/10 App
- G103300329 Requests mod of PSAR Figures 2 9-15 & 2C-13 to a backfill compacted to 95% in area north of turbine bldg Change will manimize use of remaining unsite Category I backfill rati
  HEAD-0F Georgia Power Co 81/03/25 5pp 08055 148
- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensess of operating plants & holder forwarding NUREG-0696. "Functional Criteria for Energency Response Facilities " Criteria describe acceptable method for meeting NRC requirements N/O eacl EISEN-
- O Inspection reports: 1E Sulletine & correspondence
- B102280574 Forwards [6] Info Notice 81-01, 'Possible Failure's HFA Relays " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Directur. 1p.
- 8103080398 Forwards 1E Mgt Meeting Repts 50-321/80-41.50-35 50-424/80-16 & 50-429/80-16 on 801020 No noncompliance noted G'REILLY, J.P. Region 2. Atlanta, Office of the Director 2pp.
- --BIOJOSOJEB IE Mgt Meeting Repts 90-J21/80-41, 90-J66/80-41. & 50-423/80-16 on BO1O2O Major areas discussed NRC evaluation of util regulatory performance per systematic assessment of licenses performance program LENIES R. C. Region 2. Atlanta. Reactor Operations Nuclei Branch BI/O1/28. 16pp
- B103020263 Forwards IE Circular Bi-O2, "Performance of NRC-Individuals While on Duty." No written response required O'REILLY. J P Region 2, Atlanta. Office of the Director Ip
- B103160560 Forwards IE Circular 81-03. "Inoperable Seismic I Instrumentation " No response required O'REILLY-U P Region 2. Atlanta, Office of the Director Ip.
- 9)03170079 Forwards revised IE Bulletin Bi-OJ, "Burveillance Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements O'REILLY.J P. Region 2. Atlanta, Office of the Director ip. 07935:284
- B103200263 Forwards 1E info Notice B1-06. 'Failure of ITE M Circuit Breaker " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director Ip.

- 8103200036 Forwards IE Info Notice 81:05. Degraced DC 94s at Palisades "No response required D'AEILLY.J P. Region 2. Atlanta. Office of the Director 81/03/13 is.
- B103240560 Ack receipt of B10303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-424/B1-01 & 50-425/B1-01 LEWIS.R C Region 2. Atlanta. Office of the Director B1/03/13 lp. 07983 300.
- --0103240668 Response to NRC 010205 ltm re violations noted in IE Insp. Repts 50-424/01-01% 50-425/01-01 Corrective actions gracedure change rade to incorporate correct testing procedure & revise concrete placement pour log KECLLY.R J. Georgia Power Co. 81/03/03 2pp. 07903 301
- --8103240674 Forwards IE insp Repts 50-424/81-01 & 50-425/81-01 on 810106-09 & notice of violation MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/02/05 2pp 07983 303
- --8:03240696 IE Insp Repts 50-424/81-01 & 50-425/81-01 on 8:10:06-09 Noncompliance noted failure to sample concrete test cylinders every 100 cubic yards HARRIS-J R Region 2. Atlanta. Office of the Director CONJON.T.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 8:1/02/03 Jpp 07983 306
- G103270132 Forwards IE Insp Repts 50-424/81-04 & 50-425/81-04 on 810218-20 & notice of violation LEMIS.R C Region 2. Atlanta. Office of the Director 81/03/13 2pp 08045 304
- --8103270145 Notice of violation from insp on 810218-20
   Region 2. Atlanta, Office of the Director 81/03/13. is 08045 306
- --Bi0327019B IE Insp Repts 90-424/B1-04 & 30-425/B1-04 on Bi02;B-20 Noncompliance noted failure to follow procedure for controlling nonconformance items CRDM\_EY.B R. HERDI.A R. Region 2. Atlanta, Office of the Director Bir
- BiO3310721 Responds to 1E Bulletin 79-03A. "Longitudinal Weld Defects in ABME 9A-312. Type 304 Stainless Steel Pipe" Add1 info will be provided by BiO403 pending 810323 completion of Westinghouse investigation BUTTOM.D. Georgia Power Co. 81/03/20 2pp 08058 137

DOCKET 90-493 UC-SANTA DARDARA RESEARCH REACTER

F Security, medical, emergency & fire protection plans

- BiO3250203 Forwards Figure 2 to revised physical security plan Page withheld (ref 10CFR2 790)
  XAOGER A J California. Univ of Banta Barbara Bi/03/17 ip 07994 256
- O Inspection reports. IE Bulletins & correspondence
- 8103020021 Forwards 1E Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required EAGELKEN R H Region 5. San Francisco. Office of the Director. 81702/09 | p. 07787-204
- 8103260486 Forwards IE Insp Rept 50-433/81-01 on 810223-24 No roncompliance noted Rept withheld (raf 10CFR2 790). NCRDERHAU9.L R Region 5, San Francisco, Bafeguards Branch 81/03/16 Ip. 08041 Ool
- DOCKET BIN-90-437 FLOATING NUCLEAR PLANT. OFFSHORE POWER SYSTEMS
  A Application/construction stage documents & correspondence
- 8103170387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737 RISENHUT.D.O. Division of Licensing. 81/01/19. opp
- 9103120314 Ltr to all licensess of operating plants, CP holders & CL applicants, except Indian Point 2 & 3, 2 ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads FISENHUT, D & Division of Licensing. 81/02/03. 6pp

- 8102280289 Forwards projected target dates for pending CP applicat Schedule for CP issuance is heavily dependent on scope of TMI-related requirements DENTON.H R Office of Nuclear Reactor Regulation, Director 81/02/09 7 /pp
- 8103180037 Unofficial transcript of Commission 810212 meeting in Maskington. DC re SECY-81-20 policy on proceeding u/pending CP & ofg license applications Pp 1-115 • Cormissioners BI/O2/12 117pp 07949 326
- --8103030450 Recommends Cormission approve enti dreft final rule 1 re literating requirements for pending CPs & ofg literate applications & proposed statement of requirement re degraded core rulemaking DIRCKS-W J Office of the Esecutive Director for Operations SECV-91-020A 81/02/11 12pp & 55068 030
- B103160469 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A i 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be not EISEUHUT. D O Division of Licensing B1/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicents NUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use no existing low flow controller EISENKUT.0.9 Division of Licensing 81/02/20 8pp
- B103230B13 Generic Ltr B1-06 to all CP holders & OL applicants re 10CFR30 71(e), "Periodic Updating of FBARs." effective 800722 Info re FBAR legal status format & content end E18ENHUT.D 0 Division of Licensing B1/02/26 10pp
- B103310B04 Ltr to all licensees of operating plants.applicants for & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EIBERHUT.D 0 Division of Licensing 81/03/10 App.
- F Security, modical, emergency & fire protection plans
- 8100310338 Ltr to all incensees of operating plants & holders of Cf forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. N/o encl EISENHUT. DO Division of Licensing 81/03/05 6pp.
- Q Inspection reports. IE Bulletins & correspondence
- B103020170 Forwards 1E Circular 81-02. "Performance of NRC-Licensec Individuals While on Duty." No written response required. OfREILLY.J P. Region 2. Atlanta, Office of the Director. 81/02/1p. 07785 278
- Bi03160600 Forwards IE Circular Bi-03. "Inoperable Seismic Monitor: Instrumentation "No response required. O'REILLY, J.P., Region 2. Atlanta, Office of the Director Bi/03/ ip 07917.050
- 8103170052 Forwards revised IE Bulletin B1-01. "Burveillance of Mechanical Bhubbers." U/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable dues not affect util requirements O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 81/03/1p. 07939.175.
- 8103200246 Forwards IE Info Notice 81-06. "Failure of ITE Model K-d Circuit Breaker." No response required. O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 81/03/ 1p. 07968 346
- B103190884 Forwards IE Info Notice B1-05, "Degraded DC Bys at Palisades." No response required O'REILLY-J P. Region 2. Atlanta, Office of the Director. 81/03/1p. 07965:290
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- B103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREQ-O612. Forwards NRC position re-interim actions & request for addl info EISENHUT, D.G. Division of Licensing, 80/12/22, 30pp.

- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for anviron qualification of safety-related electrical equipment Items addressed Involve cold shutdown replacement parts & NUREG-0737 EISENHUT.D O. Division of Licensing 81/01/19 app
- 8103120014 Ltr to all kicensees of operating plants.CP holders & CL applicants, except Indian Point 2 & 3,7ion 1 & 2 & TMI-1. forwarding inadvertently omitted pages from NRC 801222 request for add; info recontrol of heavy loads EISENHUT.O O Division of Licensing 81/02/03, 6pp
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENMUT. D.O Division of Licensing 81/02/20 Gpp
- BIOJ230030 Ltr to all ifcensees of operating nuclear power plants & applicants for DLs (except St Lucie.Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement omergency procedures RIGENHUT.D Q Division of Licensing 81/02/25 Spp
- 8103230813 Generic Ltr 81-06 to all CP holders & CL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 900722 Info re FSAR legal status.format & content encl EISENHUT.D G Division of Licensing 81/02/26 10pp
- 8103310804 Ltr to all licensees of operating plants applicants for DLs b holders of CPs forwarding SECY-BI-117 re info necessary to establish environ qualification of safety-related electrical equipment
  EISENEMET.D G Division of Licensina 81/03/10 6ps
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8103250099 Informs that Action Item II K 2 15 of SER resolved Blug flow induced by natural circulation will not result in adverse loading on steam generator tubes IEDESCO.R L. Assistant Director for Licensing 81/03/17 2pp

Becurity, medical, emergency & fire protection plans

- 8103060336 Forwards add1 info re guard training & qualification plans Encl withheld (ref 10CFR2 7901 MILLS.L M Tennessee Valley Authority. 81/02/26 1p
- 8103310339 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0596. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl. EISENHUT, D. O. Division of Licensing. 81/03/05. 6pp

# J. Insurance & indemnity information

- B103020639 Forwards escerpt from Indomnity Agreement B-89, in response to NRC 900130 ltr Section 3. Article VIII conflicts w/TVA Act of 1933 which prohibits placement of liens against TVA property PARKIB.H G. Tennessee Valley Authority 81/02/24 3pp 07782 128
- g juspection regards. 1E Bulletins & correspondence
- B103100397 Forwards IE Insp Repts 50-438/80-27 & 50-439/80-26 on 801(18-2) & motice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/02. 2pp. 07864.173
- ---DIGB100401 Notice of violation from insp on 801118-21 • Region 2. Atlanta, Office of the Director. 81/01/02, ip 07864:175
- --BiO3100407 IE Imap Repts 50-438/80-27 & 50-439/80-26 on B01118-21 Noncomptience noted: failure to provide pressuriter surge line grinding procedures.

  KLEINSORGE, W.P. Region 2. Atlanta. Office of the Director.

  HERDI, R. Region 3. Atlanta. Reactor Construction & Engineering Support Branch 81/01/02. dep. 07864 176.
- 8103240593 Disputes violetions cited in IE Insp Repts 50-438/80-14 & 30-439/80-14 Visual exemination not required for NK-5000 welds. Util 801024 itr adequately expressed corrective actions. Heeting requested for 810122 to discuss concerns. MILLB.L M Tennessee Valley Authority. 81/01/13. 3pp. 07982-313.

- 8102280484 Forwards IE Info Natice 81-01. "Possible Failures of MFA Relays" No response required O'REILLY.U P. Region 2. Atlanta. Office of the Director 6 in 07775 298
- B103090333 Forwards IE Insp Repts 50-438/80-29 & 50-439/80-28
  B01201-05 No nencompliance noted
  MUPPHY.C & Region 2. Atlanta. Reactor Construction & Engis
  Support Branch B1/01/20 2pp 07826 057
- --Bi03050348 iE Insp Repts 50-439/80-29 & 50-439/80-28 on BD1:
  noncompliance noted Major areas inspected installation of
  globe valves in component cooling systreactor bldgs &
  autiliary bldg & intake pumping stations
  THOMAS M Region 2. Atlanta Office of the Director
  CANTRELL, F S Region 2. Atlanta Reactor Construction &
  Engineering Support Branch 81/01/20 3pp 07826 059
- BIO3(10517 Forwards IE Insp Repts 90-438/89-30 & 50-439/80-29 BO1215-19 No noncompliance noted MMRPHY.C E Region 2. Atlanta: Reactor Construction & Engin Support Branch BI/02/03 2pp 07872 227
- --8103110521 IE insp Repts 50-439/80-30 % 50-439/80-27 on 801 noncompliance noted Major areas inspected installation of hangers & supports % (installation & testing of anchor bot THOMAS.M. Region & Atlanta Office of the Director CANTRELL.F & Region & Atlanta Reactor Construction & Engineering Support Branch 81/02/03 3pp 07872 229
- B103120421 Forwards IE Insp Repts 50-438/81-01 % 50-439/81-01 B10104-07 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engin Support Branch 81/02/04 2pp 07704 270
- --8103120425 IE Insp Repts 50-438/81-01 & 50-439/81-01 on 8101 noncompliance noted Major areas inspected licenses action previous insp findings-licenses identified items & RCPO piping QIRARD, E. H. Region 2. Atlanta. Office of the Director E. Region 2. Atlanta. Reactor Construction & Engineering Suparch. 81/02/03 opp 07904-272
- B103020277 Forwards 1E Circular B1-02. "Performance of NRC-Lic Individuals While on Duty" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director ( ip 07785 348
- 8103050460 Ack receipt of 810130 itr informing NRC of steps to correct violations noted in IE Insp Repts 50-438/80-27 & 30-438/80-26 MVRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Buppart Branch 81/02/18 ip 07824 358
- --8103050469 Responds to NRC 810102 ltr re violations noted in Repts 50-438/80-27 & 50-439/80-26 Corrective actions, sequence control Charts will be invalidated & new ones issued to encompass requirements for weld grinding & insp CROS6.7 L. Tennessee Valley Authority 81/01/30 2pp 07824 359.
- BL03240710 Forwards IE Insp Repts 50-438/81-02 & 50-439/81-02 810125-30 No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engi Support Branch 81/02/18 2pp. 07983:250
- --Bi03240716 IE Insp Repts 50-439/81-02 & 50-439/81-02 on Bi0
  noncompliance noted Major areas inspected stressing of
  vertical tendons & button heading of horizontal tendons i
  Unit I reactor bidg.
  THOMAS.M. Region 2. Atlanta, Office of the Director
  CANIRELL, F. B. Region 2. Atlanta, Reactor Construction &
  Engineering Support Branch 81/02/18 3pp 07983 252
- 8103040777 Forwards response to infractions contained in IE In 50-438/80-14 & 50-439/80-14-01 Corrective actions on 810207. Helding Engineering Unit 8td Operating Procedure WEU-80P-715 issued to responsible individuels.

  MILLS-L.M Tennessee Valley Authority 81/02/20 3pp 05
- 8103140514 Forwards IR Circular 81-03, "Inoperable Selamic Mor Instrumentation " No response required MEPPLER, J. G., Region 3, Chicago, Office of the Director 81 1p. 07916, 308
- 8103170011 Forwards revised IE Bulletin 81-01, "Burveillance of Mechanical Enubbers," w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements O'REILLY, J. P. Region 2, Atlanta, Office of the Director.

- Bio32A0019 Forwards update to BCOROS resonnse to IE Bullatin 79-03A |DIRECTOR | Portured Supported to Bouldon response to 16 Bulletin 79
  "Longitudinal Heis Defects in ASME SA-312. Type 304 Stainless
  Steel Piping " SA-312. Type 300 series fusion welded pipe
  not used at facilities Addl info will be sent by 810630
  HILLS.L.M. Tennessee Valley Authority 81703704 2pp
- B103240264 Ack receipt of 801024.810113 % 0220 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts

  50-438/8)-14 & 50-437/80-14

  LEMIS.R.C. Region 2. Atlanta. Office of the Director 81/03/10 07991 002
- --8:03240274 Forwards revised response per 8:0204 telcon re violations noted in IE inso Repts 50-438/80-14 5-50-438/80-14. Corrective actions issued Welding Engineering Unit Procedure REU-SOP-715 & Instructed employees in procedural changes HILLS. In Tennessee Valley Authority 81/02/20 3pp

07981 000

1p 07996:044

- B1032C0897 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circust Breaker" No response required O'REILLY. J P. Region 2. Atlanta. Office of the Director G1/03/11
- B103240286 Ack receipt of B10209 ltr informing NRC of steps taken to correct violations noted in IE lisp Repts 50-438/80-28 &
- 50-439/83-27 LEMIB-R C Region 2. Atlanta, Office of the Director 81/03/12
- --8103240273 Resubmits 810123 response to violations noted in IE Insa Repts 30-438/80-28 & 50-439/80-27 Notary seal affixed HILLS.L M Tennessee Valley Authority 81/02/09 3 07983 002
- ~-9103240297 Responds to NRC 801230 ltm re violations noted in IE Insp. Rests 90-438/80-28 & 50-439/80-27 Corrective actions craft employees instructed to remove unauthorized rigging & craft mgt reinstructed on requirements.

  MILLS.L.M. Tennessee Valley Authority 81/01/23 3pp 07985 005
- --8103240302 Forwards IE Insp Repts 50-438/80-28 & 50-439/80-27 on HURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 89/12/30 2pp 0/785 008
- --8103240303 Notice of violation from insp on 801101-28
  + Region 2. Atlanta. Office of the Director 80/12/30 ip 07985 010
- --8103240308 IE Insp Repts 50-438/80-28 & 50-439/80-27 on 801101-28 Nancompliance noted pipe restraint rigged & supported w/o prior engineering approval
  WILCOX. J D Region 2. Atlanta. Office of the Director
  CAMIRELL.F. B Region 2. Atlanta, Reactor Construction &
  Engineering Support Branch 80/12/24 Spp 07985 011
- 8103230003 Forwards IE Info Notice 81-05. "Degraded DC Bys at Pailsades " No response required O'REILLT. P. Region 2. Atlants. Office of the Director 81/03/13 07969 068
- 8103250179 Ack receipt of 810306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-438/80-31 & 50-437/80-30 LEWIS R C Region 2. Atlanta. Office of the Director 81/03/18
- --8103250187 Responds to NRC 810209 ltr re violations moted in IE Insp. Rept. 50-438/80-31 & 50-439/80-30. Corrective actions FEAR section being revised to define method to be used in writing approving & controlling const test procedures MILLS, L M. Tennesses Valley Authority. 81/03/06 3pp 07996.045
- --8103250193 Forwards IE Insp Repts 50-438/80-31 & 50-439/80-30 on 801129-1226 & notice of violation MuRPHY.C.E. Region 2: Atlanta. Reactor Construction & Engineering Support Branch. 81/02/09. 2pp. 07996-048
- --9103250198 Notice of violation from insp on 801129-1226 Region 2. Atlanta, Office of the Director B1/02/09 ip. 07776:050
- --8103230206 IE Insp Repts 50-438/80-31 & 50-439/80-30 on 801129-1226 NOTIONAL IE Insp. Repts 50-434/80-31 & 50-434/80-30 on 801 Noncchpliance noted unapproved procedure used to perform const Plush of essential raw cooling water sys, Train A. WILCOX, J. D. Region 2. Atlanta, Diffice of the Director. CANTRELLE.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/02/09 Spp. 07996 051.

- 8103310624 Forwards revised response to NRC 810102 ltr re violations noted in 1E Insp Repts 50-438/80-27 & 50-439/80-26 Corrective actions new sequence control chart to be issued w/requirements for weld grinding & insp of grinding MILLE, L M Tennessee Valley Authority 81/03/26 2na 080A1 02
- S Reportable occurrences, LERs & related correspondence
- 8103030793 First interim deficiency rept re NAVCO spoul piece & radiographs. Ititially reported BO1114 Vendor radiographic technique under util review Considers 10CFR21 applicable to subj nonconformance Next rept to be submitted by 810225 MILLS.L M Tennessee Valley Authority 80/12/15 2pp 07788 33
- BIO3040768 First interim deficiency rept re IIT actuation springs in from incorrect math intitally reported B01217 Voltes.

  supplier of valve using ITT actuators requested to provide satisfactory resolution of deficiency
  MILLS-L. M. Tennessee Valley Authority B1/01/16 ip 07810,127
- B103040787 Second interim deficiency rept.originally reported on B00711.re incorrectly marked certified matl test rept for prestressing sys mall. Addl fabrication records & jetarls of
- planned corrective action requested MILLS.L M Tennessee Valley Authority 81/02/10 2pp 07813:07
- 8103040700 Responds to 800428 ltr re INRYCO tendon installation operations & related GA/GC activities Inspectors to be maintained on simultaneously stressed groups of dome & horizontal tendons INRYCO resumed tendon associated work
  MILLS.L.M Temnessee Vailey Authority B1/02/23 1p 07812-264.
- 8103090638 First Interim Deficiency Repts BLRD-50-438/81-15 & BLRD-50-439/81-15 re pipe hanger documentation error. initially reported 810128 Cable tray supports are being reviewed & evaluated Next rept expected by 810811 MILLS.L M Tennessee Valley Authority 81/02/27. 2pp 07844, 290
- 8103130027 Part 21 rept re undersized grease relief tubing in reactor vant cooling fans. Impairing required semiannual naint. initially reported BiOl28 Fans purchased from B&W. Investigation in progress MILLS.L.H Tennessee Valley Authority 81/02/27 3pp. 07912 049
- 8103110522 Final deficiency rept. Initially reported 810129 re storage temp limit exceeded During weekend of 810129 resistent limit exceeded During weekend of 810110-11. There was no heat in protective coating storage bldg Caused by blown fuse. Bldg heaters to warning lights rewired MKLLSL M. Tennessee Valley Authority 81/03/02 2nn 07 Tennessee Valley Authority 81/03/02 2pp 07878 208
- BIO3130466 Becond interim deficiency rept re const QA audit of sefety related non-ASME Held Insp BN-N-80-08 initially reported BO1020 Kelding design guide will be developed & issued Nert rept espected by BIO905 MILLS-L.M Tennessee Valley Authority. B1/03/06 2pp. 07911-291
- 8103170376 Final deficiency rept re-makeup pump control logic, initial reported 810206. Logic drawings w/design requirements that have not been implemented in makeup pump control logic listed Corrected designs will be issued by 810911
  MtLt8.L.M. Fannessee Valley Authority 81/03/09 Зрр. 07939-266
- BIO3300163 Part 21 rs ITT actuator for Valtes, initially reported BO1217. Util has received verbal confirmation from Valtek that no operational problems exist w/Valtek valves using ITT hydramotor actuators MILLS,L M Tennessee Valley Authority 81/03/17 2pp. 08055: 329
- 8103270909 Tenth interim deficiency reptrinitially reported 780710, re expansion anchors failure to pass qualification tests. Data concerning as-built strength of base plates w/installed expansion anchors is being evaluated. MILLS-L.M. Tennessee Valley Authority. 81/03/18 ip. 08043:145.
- 8103270522 Final deficincy rept re crane valves-welding concern first reported on 810220 Valves to be post-weld heat treated. Fourth lot of weld wire to be removed & seam rewelded before post-heat treatment MILLS.L M Tennessee Valley Authority. 81/03/20. 2pp. 08043:146
- 8103270462 Final deficienty rept.initially reported 800819 re power cables not qualified to IEEE 383-1974 flams test. Cables mistakenly installed in cable trays have been identified & will be removed from cable trays in safety-related areas.

  MILLS.L M Tennessee Valley Authority 81/03/23 2pp 08043: 086
- Bi03310603 Final deficiency rept re automatic closure of borated wate storage tank isolation valves initially reported on 801203. Revised design drawings implementing Design Criteria NA-ND-D740 to be completed by 810504.

- 8103310488 Fifth interim deficiency rept re AUMA Actuators noto: operated valve operators Actuators returned to factory for regain. AUMA has recommended actuators be reinstalled by factory trained svc employees Mext rept t. 810618 MILLS.t. M. Tennesse Valle, Authority 81703/25 2pp 08079-234
- 8103310357 First interin deficiency rept to welder qualification Melding personnel not properly qualified per AMS D1 1 as required by Process Specification 1 C 1.2 of G-29t for performing Class 1 seismic welding Next rept 810624 MILLS-L M Tennessee Valley Authority 81/03/25 2pp 08075 229
- 8103310551 Second interim deficiently re-certified math test repts on anchorheads. Util currently, abusting formal transmittals of certified math test repts for neats 9174, 97a33, 81775. 52214, 6065780 & 6067474 Nest rept to be submitted by 920119. HILLSELM Tennessee Valley Authority 81703/26. 2pp 08075 232
- DOCKET 50-439 DELLEFONTE NUCLEAR PLANT, UNIT &

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NCREO-OGIZ Forwards NRC position re interim actions & request for add | info EffectMUT.D Q Division of Licensing. 80/12/22 3020
- B1031903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREC-0737 EIBERHUT.D Q Division of Licensing. 81/01/19 6pp
- 8103120014 Ltr to all licensees of operating plants, CP holders & DL applicants, except Indian Point 2 & 3, Zion i % 2 & IMi-1, forwarding inadvertently omitted pages from NRC 801222 request for add inforce control of heavy loads.

  EISENHUT D 2. Division of Licensing 81/02/03 opp
- Bi03230024 Ltr to all power reactor licenses & license applicants re MUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licenses may submit analysis to justify use of existing low flow controller EISENHUT.D O Division of Licensing 81/02/20 8pp
- Bi03230030 Ltr to all licensees of operating nuclear power plants & applicants for OLe (except St Lucie, Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EIBENHUT.D 0 Division of Licensing 81/02/25 5pp
- 0103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR80 71(e). "Periodic Updating of FBARs." effective 000722 Info re FBAR legal status, formet & content encl EISENBUT.D.O. Division of Licensing 81/02/26
- 8)03360804 Ltr to all licensees of operating plants applicants for ULs & holders of CPs forwarding 5ECY-Bi-Lift re info necessary to establish anxiron qualification of safety-related electrical equipment EISECHUUT.D Q Division of Licensing 81/03/10 App
- E MRC Bafety Evaluation Report (SER), supple & correspondence
- B103250099 Informs that Action Itam II.K. 2 iS of SER resolved. Blug flow induced by natural circulation will not result in adverse loading on steam generator tubes. TEDESCO.R L. Assistant Director for Licensing 81/03/17 2pp 0.7997-318
- F. Security, medical, emargency & fire protection plans
- 8103060336 Forwards add1 info re guard training & qualification plans Enc1 withheld (ref 100FR2 790) HILLB.L.M. Tennessee Valley Authority 81/02/26. 1p.
- Bio33i0338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/A encl EIBENHKF.D.Q Division of Licensing 81/03/09. 6pp.

- Q Inspection reports: IE Bulletins & correspondence
- G103100397 Forwards 1E Insp Repts 50-438/80-27 % 50-439/80-26 on B01118-21 & notice of violation MyPHY/C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 61/01/02 2pp 07864 173
- --B103100401 Notice of violation from insp on B01118-21

   Region 2. Atlanta. Office of the Director B1/01/02 is 02854 175
- --B103160407 [E Insp Repts 50-438/80-27 % 90-439/80-26 on 801118-21 Noncompliance noted failure to provide pressurizer surge line grinding procedures KLEINSORGE.NP Region 2. Atlanta. Office of the Director. HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/01/02 App 07844-176
- B):03240593 Disputes violations cited in IE. Insp. Repts 50-438/80-14 & 50-439/80-14. Visual examination not required for NX-5000 welds. Util 601024 ltr adequately expressed corrective actions Meeting requested for B10122 to discuss concerns MILLS, L.M. Tennessee Valley Authority, B1/01/13 3cp. 07982 313
- B102280484 Forwards IE info Notice 81-01. Possible Failures of GE T<sub>e</sub>; HFA Relays " No response required O'REILLYJ P Region 2. Atlanta. Office of the Director B1/01/12 1p 07775 298
- 8100050333 Forwards IE linsp Repts 30-438/80-29 % 50-439/80-28 un 801201-05 No nencompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/01/20 22. 07826 057
- --8103050348 IE insp Repts 50-438/80-27 % 50-439/80-28 on 801201-09 % nppcompliance noted Major areas inspected installation of globe valves in component cooling systreactor bidgs & auxiliary bidg & intale purping stations.

  IHOMAS.M. Region 2. Atlanta. Office of the Director CANTRELL.F. S. Region 2. Atlanta, Reactor Construction & Fracinerins Support Branch 8/101/20 3pp 07826-059
- B103110317 Forwards 1E insp Repts 30-438/80-30 & 50-439/80-29 on B01219-19 No noncompilance noted MARPHY.C E Region 2. Atlanta: Reactor Construction & Engineering Support Branch B1/02/03 2pp 078/2 227
- --8103110521 [6] Insp. Repts 50-438/80-30 & 50-439/80-29 on 801215-19 N noncompliance noted. Major areas inspected installation of hangers & supports & installation & testing of anchor balts THOMAS.M. Region 2. Atlanta. Office of the Director CANTRELL.F. S. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/03 3pp 07872 229
- B103120421 Forwards 1E Insp.Repts 50-438/81-01 & 50-439/81-01 on 810106-09. No noncompliance noted MURPHY.C.E. Region 2. Atlanta: Reactor Construction & Engineering Eugport Branch 81/02/04 2pp 07904 290
- --8103120425 IE Insp Repts 50-438/81-01 % 50-439/81-01 on 810106-07 % noncompliance noted Major areas inspected licensee action on previous insp findings, licensee identified stems & RCPB piping.

  OTRARD, E. H. Region 2. Atlanta, Office of the Director HERDT. A. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/03. 4pp 07904.272.
- 8103020277 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/07 1p.
- B103050460 Ack receipt of B10130 ltr informing NRC of steps taken to correct violations noted in TE Insp Repts 50-438/80-27 t 50-439/80-26 MXRPHYC.E. Region 2. Atlanta: Reactor Construction & Engineering Support Branch B1/02/IB. 1p 07824.358.
- --Bi03050469 Responds to NRC 810102 itr re violations noted in IE Ins Repts 50-438/80-27 & 50-439/80-26 Corrective actions sequence control charts will be invalidated to new ones issued to encompass requirements for weld grinding & insp CRGGS-J.t. Tennessee Valley Authority. 8(/01/30. 2pp. 07824-359.
- B103240710 Forwards IE Insp Repts 50-438/81-02 & 50-439/81-02 on 810126-30. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/02/18. 2pp. 07983:250.

- --Bi032407(6 IE Insp Repts 50-438/81-02 % 50-437/81-02 on 810126-20 No nancecyllance noted Major areas Inspected stressing of vertical tendons & button heading of horizontal tendons in Unit I reactor blig THEMAS.M Region 2. Atlanta. Office of the Director CANIRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/18 3pc 07/83 252
- 8103040777 Forwards response to infractions contained in IE insp Repts 20-438/80-14 & 50-439/80-14-01 Corrective actions on 810207, helding Engineering Unit Std Operating Procedure WEV-50P-715 issued to responsible individuals MELLEL H Tennessee Valley Authority 81/02/20 3pp 07813-060
- 8103160516 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation" No response required rEFPLER.J O Region 3. Chicago. Office of the Director 81/03/02 (p. 07916-338)
- B103170011 Forwards revised IE Bulletin B1-01. "Surveillance of Mechanical Bnubbers." w/corrected Pages 3 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. DIREILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/04
- 8103260319 Forwards update to 800805 response to IE Builetin 79-03A "Longitudinal Held Defects in ABME 8A-312. Type 304 Stainless Steel Piping ' SA-312. Type 300 series fusion welded gipe not used at facilities Addl info will be sent by 810630 MILLS.L M Tennessee Valley Authority 81/03/04 2pp
- \$103240264 Ack receipt of 801024.810113 % 0220 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/E/-14 % 50-439/B0-14 LEHIB.R C. Region 2. Atlanta. Office of the Director 81/03/10 lp 07981 CO2
- --8100240274 Forwards revised response per 010204 tejcon re violations noted in IE losp Repts 90-438/80-14 & 50-439/80-14.
  Corrective actions issued Welding Engineering Unit Procedure WEU-SCP-715 & instructed employees in procedural changes MILUS.L M Tennessee Valley Authority 81/02/20 3pp 0798:003
- B10320D197 Forwards 1E Info Notice B1-06. "Failure of ITE Mode) M-600 Circuit Breater 'No response required D'RESLLY-J P Region 2. Atlanta. Office of the Director 81/03/11
- 8103240286 Ack receipt of 810209 ltr informing NRC of steps taken to correct violations noted in 1E Insp Hepts 50-439/80-28 & 50-439/80-27 LENIB.R.C Region 2. Atlanta, Office of the Director 81/03/12. is. 07905.001
- --6103240293 Resubcits B10123 response to violations noted in 16 Insp. Repts 50-438/80-28 & 30-439/80-27 Notary seal affixed.
  MILLS-L. M. Tennessee Valley Authority 81/02/09 3pp. 07985-002
- --8103240297 Responds to NRC 801230 ltr re violations noted in IE Insp. Repts 50-438/80-28 & 50-499/80-27 Corrective actions craft employees instructed to remove unauthorized rigging & craft mpt reinstructed on requirements #ILLB.L.M. Tennessee Valley Authority 81/01/23 3pp 07985-005
- --Bi03240302 Forwards IE Insp Repts 50-438/80-28 & 50-439/80-27 on 80f101-28 & notice of violation NURPHY.C.E. Region 2. Atlantar Reactor Construction & Engineering Bupport Granch 80/12/30 2pp 07985 008
- --BIG324030B IE Insp Repts 50-438/80-28 & 50-439/80-27 on 801101-28. Noncompliance noted pipe restraint rigged & supported w/o prior engineering approval. WILCOX-J D. Region 2. Atlanta, Office of the Director. CANTRELL, F. S. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/12/24. 3pp 07985 011
- 8103200003 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No response required.
  D'REILLY, J. P. Region 2, Atlanta. Diffice of the Director 81/03/13.
- 8103280179 Ack receipt of 810306 ltr informing NRC of steps teken to correct violations noted in 1E Insp Repts 50-438/80-31 & 50-439/80-30.

  LEMIS.R.C. Region 2. Atlanta. Office of the Director 81/03/18. 1p 079%:044

- --8103290187 Responds to NRC 810209 itr re violations noted in IE I Repts 50-438/80-31 & 50-439/80-30 Corrective actions FSAR spection being revised to define method to be used in writing, approving & controlling const test procedures HILLS.L.M. Tennessee Valley Authority 81/03/06 3pp 0799-045
- --8103250193 Forwards IE Insp Repts 50-408/80-31 & 50-409/80-30 on B01129-1826 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineer: Support Branch B1/02/09 2pp 07996 048.
- --R103250206 IE Insp Repts 50-438/80-31 & 50-439/80-30 pn 801129-126 Noncompliance noted unapproved procedure used to perform const Plush of essential new cooling water say. Train A WILCOK-J D Region 2. Atlanta Office of the Director CANTRELL, F B Region 2. Atlanta Reactor Construction & Engineering Support Branch 81/02/07 Spp 07996-051
- 8103310624 Forwards revised response to NRC BI0102 ltr re violations noted in IE lasp Repts 50-438/BD-27 t 50-439/80-26 Corrective actions new sequence control chart to be (asked w/requirements for weld grinding tinsp of grinding MILLS-L M Tennessee Valley Authority B1/03/26 2pp 08061:03
- 8 Reportable accurrences, LERs & related correspondence
- B103030793 First interim deficiency rept no NAVCO spool piece & radiographs, initially reported B01114 Vendor radiographic technique under util raview Considers 10CFR21 applicable to subj honconformance Nest rept to be submitted by B10223. MILLGILM Tennessee Valley Authority. B0/12/15. 2pp 07788-33
- 8103040768 First Interim deficiency rept re IIT actuation springs in from interrect math initially reported 801217 Valtes, aughlier of valve using ITT actuators requested to provide satisfactory resolution of deficiency, MILLB.L M Tennessee Valley Authority. 81/01/16 Ip. 07810 127
- 8103040789 Second interim deficiency reptracipinally reported on 800911 re incorrectly marked contified matirest rept for prestressing sys matirAddl fabrication records & details of planned corrective action requested MILLS L.M. Tennessee Valley Authority 81/02/10 2pp 07813:07
- B103090638 First Interim Deficiency Repts BLRD-30-438/81-15 & BLRD-30-439/81-15 re-pipe hanger documentation error, initially reported B10128 Cable tray supports are being reviewed & evaluated Next rept expected by 810811 MILLB-L H Tennessee Valley Authority 81/02/27, 2pp. 07844.25
- 8103130027 Part 21 rept re undersized grease relief tubing in reacto vent cooling fans.impairing required semiannual maint, initially repurted 810128 Fans purchased from 884. Investigation in progress MILLEGL.M. Tennessee Valley Authority 81/02/27. 3pp. 07912:04
- O103110522 Final deficiency rept-initially reported 810129, re-storag temp limit exceeded During weekend of 810110-11, there was no heat in protective coating storage bldg. Caused by blown duse. Bldg heaters to warning lights rewired MILLS.L.M. Tennessee Valley Authority. 81/03/02 2pp. 07878-20
- B103130465 Becond interim defliciency mepting const QA audit of safet related non-ASME Held finep BN-W-B0-0B, initially reported B01020. Wolding design guide will be developed & issued. Next mapt expected by B10305.

  HILLB-L.M. Tennessee Valley Authority B1/03/06. 2pp. 07911:29
- BiO3170376 Final deficiency rept to makeup pump control logic initie reported BiO206. Logic drawings w/design requirements that have not been implemented in makeup pump control logic listed. Corrected designs will be issued by BiO911 MKLLS.L M Tennessee Valley Authority BI/03/09. 3pp. 07937:26
- 8103300163 Part 21 re ITT actuetor for Valtes initially reported B01217.Util has received varbel confirmation from Valtes that no operational problems exist of Valtes valves using ITT hydramotor actuators. MILLBL M Tempasse Valley Authority 81/03/17. 2pp. 08095:3a
- 8:03270305 Tenth interim deficiency rept. initially reported 780710, respension anchors failure to pass qualification tasts. Data concerning as built strength of base plates w/installed expansion anchors is being evaluated.

  MILLB.L.M. Tennessee Valley Authority 81/03/18 1p. 08043:145

- 8103270522 Final deficincy rept re crane valves-welding concern first reported on 810220 Valves to be post-ueld feat treated Fourth lot of weld wire to be removed & seam rewelded before post-heat treatment MILLE.L H Tennessee Valle, Authority 81/03/20 200 08043 146 Bio3270462 Final deficiency rept.initially reported B00Bi9, re-power cables not qualified to IEEE 363-1974 flane test Cables mistatenly installed in cable trays have been identified & will be removed from cable trave in eafety-related areas MILLS.L M. Tennessee Valley Authority 81/03/23 200 08043 088 B103310609 Final deficiency rept re automatic closure of borated water Revised design drawings implementing Design Criteria
  N4-ND-D740 to be completed by 810504 MILLB.L.M. Tennessee Valley Authority. 81/03/24 2:p 08062 222. 8103310488 Fifth interim deficiency rept re AUMA Actuators notor operated valve operators Actuators returned to factor, for repair. AUMA has recommended actuators be reinstalled by factory trained syc employees Nest rept by BIQA18 Ternessee Valley Authority 81/03/25 2nd 08075 234 BIO0010539 First intorin deficiency rept re-telder qualification Wolding personnel not properly qualified per AUS DI 1 as required by Process Specification 1 C 1 2 of 0-29c for performing Class I seismic welding Next rept 810624 MILLE.L.M Ternesses Valley Authority 81/03/25 2pp 08075 229 9103310951 Becond interim deficiency re-certified catl test repts on anchorheads Util currently awaiting formal transmittals of certified mati test repts for heats 91974, 97693, 81775. 52214.6055780 & 6067474 Next rept to be submitted by 820119. HILLE, L. M. Tennessee Valley Authority 81/03/26 200 08075 232 DOCKET 50-440 REDRY MUCLEAR POWER PLANT, LINIT I A Application/construction stage documents & correspondence B1031903B7 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safetu-related electrical equipment Items addressed involve cold shutdown replacement parts & NURGO-0737 EISENBUT. D O. Division of Licensing 81/01/19 Op Bi03120014 Ltr to all licensees of operating plants CP holders & DL applicants except Indian Point 2 & 3. Zion 1 & 2 & TMI-1, forwarding shadwartently omitted pages from NRC 801222 request for addl info re control of heavy loads.

  EISENHUT D 0. Division of Licensing 81/02/03 6pp 8103090113 Forwards organizational charts depicting NRC Region 3 reorganisation, effective 810216.
  xEPPLER, J. Q. Region 3. Chicago, Office of the Director. 81/02/20 2pp. 07853:179 B103239024 Ltr to all power reactor licensess & license applicants re NAREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller ESENHUT, D. O. Division of Licensing 81/02/20. Box 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for Ols (except St Lucie-Units ) & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures. EISENHUT, D Q Division of Licensing, 81/02/25, 5pp.
- P103170655 Ltr to holders of CPs & applicants for OLs (OWRs) required of ASME Class 1.2 & 3 pressure boundary piping safe ends & fitting matiper purielines of encl Revision 1 to MUREO-0313 Model Tech Specs only encl EISELHUT, D & Division of Licensing B1/02/26 B103239B13 Generic Etr B1-06 to all CP holders & DL applicants re 10CFR80 71(e). 'Perlodic Updating of FSA9s.' effective BD0722 Info re FSA9 legal status format % content encl EISENHUT.D D Division of Licensing B1/02/26 10pp BIO3310B04 Ltr to all licensees of operating plants, applicants fo establish environ qualification of safety-related electrical anut comple EIEENAUT.D 0 Division of Licensing 81/03/10 App F Security, madical, emergency & fire protection plans roughouse Ltr to all licensees of operating plants & holder forwarding NJREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/O encl. EIGENHUT. D. G. Division of Licensing. 81/09/09 8103310338 Ltr to all licensees of operating plants & holders of ( G Adjudicatory correspondence 8103180629 Petition for leave to intervene Util may not be financ canable to operate Clant safely Requests FES & info re prehearing conference Ohio Citizens for Responsible Energy - 81/03/05 ALEXAUSER. .. 8103200733 Petition to intervene in proceeding by OH Citizens for Responsible Energy FES requested ALEXANDER. J. Affiliation Uninoun B1/03/06 ip 07967 330 B103180419 Forwards petition to intervene in licensing hearings WiLT.D.D. Wilt. D. D. B1/03/15 1p --B103180626 Petition to intervene in licensing proceeding & requi Hearing Proof of sec encl Wilt,D.D., LODGE,T. Appillation Unknown WILT,D.D. Wilt, D. 81/03/05 9pp 8103240594 Petition to intervene in licensing proceeding W/Certsf MARTIN.R E. . COFFEY, M D . PLATZ, J F Lake County, OH 81/03/10 3pp 07983:174 B103250226 Notice of filing petition to intervene by TJ Kenny MEANNY, T. J. Affiliation Unknown. B1/03/16 1p 08001 275 Affiliation Unknown. 81/03/16 1p --8103290229 Petition to intervene in proceeding #ENNY.T. J. Affiliation Unknown. 81/03/16 2pp 08001 296 8103270656 Notice of ASLB constitution PB Block, chairman & JR Klin FJ Shop members COTTER,B.P. Atomic Safety and Licensing Board Panel 81/03/24. 2pp 08043 259 B103310309 Answer opposing associations corporations & individuals BIO315 joint petition to intervene Associations have not shown interest standing or injury. Companies' economic interests (nsufficient Individuals' interests vague. 08079 090 BARTH C.A. Hearing Branch 3 81/03/27 9pp --8103310320 Answer apposing OH Citizens for Responsive Energy Bit petition to intervene No interest demonstrated by organization or member Organization was also not authorized to represent member.W/Certificate of Byc BARTH.C A - Hearing Branch 3 81/03/27. Bpp. 08079.099. H General correspondence
- --Bi03170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ABME Code Class 1,2 & 3 components & RCB operational leakage limiting conditions for

B103170225 Ltr to all BMR licensees (except Humboldt Bay & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting mat1 per guidelines of encl Revision 1 to NUREO-0313 Hodel Tech Specs only encl. EIBENHUT, D O. Division of Licensing. B1/02/26. 3pp.

8103110743 Advises that "accepted" application for OL will be forwarded under separate cover includes license application. Vol 1 & FBAR, Vols 1-18, All previously submitted info w/listed titles may be discarded.

SOUDER, J. L. Division of Rules and Records 81/02/26 Ip.

07885:012

- 8103170379 Submits info in order to participate in facility licenprocess. HEINRICH.T.J. Affiliation Unknown. 81/03/04 2pp.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8103160976 Forwards Amend 1 to FBAR consisting of responses to NRG

- --Big3160586 Ares.d 1 to FSAR

   Cleveland Electric Illuminating Co 81/03/13 300pp
  07919 605
- 8103230544 Forwards Certificate of Svc vv distribution of Amend 1 to FSAR DAVIDSDN.O R Cleveland Electric (!!uminating Co 81/03/13 3pp 07979 302
- 3 Inspection reports: IE Bulletins & correspondence
- E:03050198 Forwards IE insp Hepts 50-440/80-29 & 50-441/80-27 on E0:201-31 No noncompliance noted FIORELULG Region 3. Chicago. Reactor Construction & Engineering Support Branch 81/01/25 2pp 07825 200
- --8103050204 IE Insp Repts 50-440/80-27 & 50-441/80-27 on 801201-31 No noncompliance noted Major areas inspected welding of safetyrelated penetrations, water Intake structures & concrete placement & radiography techniques NuOHES. J. WILLIAMS. C.C. Region 3. Chicago. Office of the Director 8/00/17 10pp 07828 202
- 8103020058 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals Unite on Duty" No written response required MEPPLER.J Q Region 3. Chicago, Difice of the Director 81/02/07 Zpp 07787 267
- 8103230148 Forwards 1E lnsp Repts 90-440/81-02 & 50-441/81-02 on 610101-31 No nencompliance noted FEORELLI.G Region 3. Chicago. Reactor Construction & Engineering 5-pport Brack 81/02/11 2pp 07977 162
- --B103230151 IE Insp Repts 90-440/81-02 & 50-441/81-02 on B10101-31 No noncompliance noted Major areas inspected safety-related const activities, welding of electrical switchgear panels & control cabinets

  HWGHES. J. WILLIAMS. C. Region 3, Chicago. Office of the Director 81/02/11 app. 07977 164
- 8:03030244 Forwards Suppl 9 to 1E Bulletin 80-17, 'Failure of Control Rocs to Insert During Scram at BMR " No written response required HEPPLER. J. O. Region 3. Chicago, Office of the Director 81/02/13 2pp. 07790 291
- 8103120834 Ack receipt of 810209 ltr informing NRC of corrective actions in response to 810128 immediate action itr restafety-related coatings activities
  HEISHMAN R F Region 3. Chicago, Office of the Director 81/02/26
  1p. 07905:336
- B103160497 Forwards IE Circular B1-03. 'Inoperable Belsmic Monitoring Instrumentation' No response required KEPPLES, J.O. Region 3. Chicago, Office of the Director. B1/03/02 2pp. 07915-302
- 3103160836 Forwards revised IE Bulletin GirOi. "Burveillance of Pechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPP to which bulletin is applicable does not affect util requirements REPPLER. J G. Region 3. Chicago, Office of the Director Gi/O3/04 2pp. 07914 211
- 6103200368 Forwards 1E Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required. MEPPLER J. O. Region 3. Chicago. Office of the Director 81/03/11 2pp 07972 117
- 8103200660 Forwards [E Info Notice 81-05, "Degraded DC Sys at Palisades" No action required KEPPLER, J. 0. Region 3. Chicago, Office of the Director. 81/03/13 2pp 07966 [63]
- B10320029t Forwards 1E Info Notice B1-07. "Potential Problem M/Water-Ecluble Purge Dam Matls Used During Inert Gas Welsing "No response required MEPPLER. J. O Region 3. Chicago, Office of the Director. B1/03/16-25g 07966
- S Reportable occurrences. LERs & related correspondence
- 8103090364 Interim deficiency rept re suppression pool stainless steel cladding sensitization Further investigation on corrosion performance necessary final rept will be submitted by 810609 OAY1D80N-D.R. Cleveland Electric Illuminating Co. 81/02/26 1p. 07890:197

- B103090599 Update to B00929 final deficiency rept re Cutler-Hammotor control ctrs Requests extension of time to complete repairs from B10227 to B10601 Revised final rept expected by B10313

  DAVIDSON D.R. Cleveland Electric Illuminating Co. B1/02/26 07844:154
- 8103090693 Interim deficiency rept re fuel pool penetration pip: welds Full implementation of corrective action is incomplete Final rept uill be sent by 810391 DAVIDSOND R Componuealth Edison Co. 81702726 ip 07848:
- 810309053B Final deficiency rept re lamination identified in ASI guset plate hanger steel matt All matt has been conformed to new matt requirements All selected gussat plates have met specified acceptance criteria.

  DAVID503.0 R Cleveland Electric filuminating Co. 81/03/02 07848 161
- COCKET 50-441 PERRY NUCLEAR POWER PLANT. UNIT 2

  A Application/construction stage documents & correspondence
- 81031903B7 Ltr to all licensees of operating plants & applicants OLs & holders of CPs to program for environ qualification of safety-related electrical equipment items addressed involve cold shytdown.replacement parts & NUREO-0737 ELSENHUT.D Q Division of Licensing 81/01/19. App.
- BID3120014 Ltr to all licensees of operating plants, CP holders & applicants, except Indian Point 2 & 3, Zion 1 & 2 & Thi-1, forwarding inadvertently omitted pages from NRC B01222 request for addl info re control of heavy loads EISENBUT. D 0 Division of Licensing 81/02/03. App.
- 8103090113 Forwards organizational charts depicting NRC Region 3 reorganization.effective 910216 KEPPLER.J G. Region 3. Chicago. Office of the Director 81/0 2pp. 07853 179.
- BIORES-024 Ltr to all power reactor licenses & license applican NURES-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

  EISENBUT: D O. Division of Licensing 81/02/20 8pp
- BIO0230030 Ltr to all licensees of operating nuclear power plantapplicants for OLs (except Bt Lucie-Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EIBERHUT.D O Division of Licensing. Bi/02/25 Sep
- BIO3110743 Advises that "accepted" application for OL will be founder seperate cover includes license application.Vol 1 & FBAR.Vols 1-18, All previously submitted info w/listed titles may be discarded SDUDER-JL Division of Rules and Records 8t/02/26 ip 07835.012
- 8103170225 Ltr to all BWR licensees (except Humboldt Bay & LeCro requesting review of ASME Code Class I & 2 pressure boundary piping, safe ends & fitting mat1 per guidalines of enc! Revision I to NUREG-0313 Model Tech B
- --Bi03170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/ surveillance requirements for ASME Code Class 1.2 & 3 components & RCB operational leakage limiting conditions for operation & surveillance requirements # General Ejectric Co. Bi/02/26. 4pp.
- 8103170655 Ltr to holders of CPs & applicants for DLs (BWRs) requireview of ASME Class 1.2 & 3 pressure boundary piping safe ands & fitting mail per guidelines of encl Revision I to NUREO-0313 Model Tech Specs only encl.

  EISENHUT.D.O. Division of Licensing. 81/02/26. 3pp.
- 8103230813 Oeneric Ltr 81-06 to all CP holders & DL applicants re 10CFR50.71(\*), "Periodic Updating of FGARs," effective 800722. Info re FSAR legal status; fornat & content encl. ElBERNUT.D 0. Division of Licensing. 81/02/26. 10pp.
- BIOGG10804 Ltr to all licensess of operating plants applicants for bolders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENRUT.O.O Division of Licensing. 81/03/10. App.

```
F. Security, medical, emergency & fire protection plans
```

- Bioggiogga Litr to all licensees of operating plants & holders of CPs forwarding NUREG-0656. 'Functional Criteria for Emergency Response Facilities 'Criteria describe acceptable method for meeting NRC requirements N/O encl EISEMMIT.D Q Division of Centern Division of Licensins. Bi/03/05 Ass
- G Adjudicatory correspondence
- 8103180629 Patition for leave to intervene Util may not be exhaustable capable to operate plant safely Requests FES & info re prehearing conference ALEXANDER, J. Ohio Ci Ohio Citizens for Responsible Energy 81/03/06 to
- 8103200733 Petition to intervene in proceeding by ON Citizens for Responsible Energy FES requested. ALEXANDER, J. Affiliation Unknown 81/03/06 1; 07967, 330
- B103190519 Forwards petition to intervene in licensing hearings. WILT.D D. Wilt, D. D. B1703/15. ip
- --- 8103180626 Petition to intervene in licensing proceeding & request for Hadring Proof of svc encl Walt.D.D. LCDOE.T Affiliation Uniroun. WILT.D.D Halt.D.D. 81/03/03 93p
- 8103240594 Petition to intervene in licensing proceeding H/Certificate MARTINIR E . CCFFEYIM D . PLATZIJ.F Lake County, CH 81/03/16 07983 174 300
- 8103250226 Notice of filing petition to intervene by TJ Kenny KENNY.T J. Affiliation Unknown 81/03/16 1p 08001 295
- --8103250229 Petition to intervene in proceeding.

  KENNY.T. J. Affiliation Unknown. 81703/16 2pg 08001 296
- 100270556 Notice of ASLB constitution PB Block chairman & JR Kline & FJ Shon, Me-bars COTTER, B. P At Atomic Safety and Licensing Board Panel 81/03/24 2pp. 08043 259.
- d1033[0309 Answer apposing associations, corporations & individuals' BiO315 joint petition to intervene. Associations have not shoun interest, standing or injury. Companies' economic interests insufficient Individuals' interests vague BARTH.C A. Hearing Branch 3. 81/03/27. 9pp. 08079:090.
- --8103310320 Answer appasing OH Citizens for Responsive Energy 810311 patition to intervene. No interest demonstrated by organization or member Organization was also not authorized to represent member H/Certificate of Bvc BARTH-C A Hearing Branch D. 81/03/27 Bpp 08079 099.
- H General correspondence
- 8103170379 Submits info in order to participate in facility licensing HEINRICH, T. J. Affiliation Unknown. 81/03/04. 2pp.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8103160376 Forwards Amend 1 to FBAR consisting of responses to NRC 810122 acceptance review questions.51 Pk10s & revised App 1A to NUREO-0737 action plan requirements for OL applicants Aperture cards are available in PBR.

  DAVIDSON.D.R Cleveland Electric Illuminating Co. 81/03/13. ip.
- --8103160586 Amend 1 to FSAR Cleveland Electric Illuminating Co. 81/03/13. 300pp 07919 005
- B103230544 Forwards Certificate of Byc re distribution of Amend 1 to DAVIDSON, D. R. Cleveland Electric Illuminating Co. 81/03/13, 3gp.
- 9 Inspection reports: IE Bulletine & correspondence
- B103050198 Forwards IE Insp Repts 50-440/80-29 & 50-441/80-27 on 801201-31. No noncompliance noted
  FIORELLI.0 Region 3. Chicago. Reactor Construction & Engineering
  Bupport Branch 61/01/26 2pp. 07825-200.

- --8103090204 1E Insp Repts 50-446/80-29 5 50-441/80 27 on 901201-3 noncommittance nated Major areas inspected welding of safetyrelated genetrations, water intake structures & concrete platerant & radiugraphy techniques
  NUONES. J., MILLIAMS. C.C. Region 3. Chicago: Office of the
  Director 81/01/17 10pp 07825 202
- 8103020658 Forwards IE Circular 8t-02. 'Performance of NRC-Licens Individuals While on Outy' No written response required MEPPLER. J. G. Region D. Chicago. Office of the Director 81/02 2pp 07787 267
- 8103230148 Forwards 1E Insc Repts 50-440/81-02 & 50-441/81-02 on B10101-31 Na noncompliants noted
  #IDRELLI.0 Region 3. Chicago. Reactor Construction & Engineer
  Support Branch 8 1/02/11 2op 07977 162
- --BIO3230151 IE Insp Repts 50-440/81-02 & 50-441/81-02 pm 810101-1 noncompliance noted Major areas inspected safety-related const activities, welding of electrical switchcear page 4 & control cabinets
- NUOHES J., HILLIAMS, C.C. Region 3, Chicago, Office of the Director Office/11 App. 07977 164 B103030244 Forwards Suppl 5 to 1E Bulletin 80-17. "Failure of Con-Rods to Insert During Scram at BWR " No written reasonse

resulted.

07790 291

2pp 97972.117

8103120834 Ack receipt of 810209 ltr informing NRC of corrective

Region 3. Chicago. Office of the Director 81/02.

- Outdough Ack receipt or Blozoy for informing NRC of Correlactions in response to BloizB immediate action ltr research, related coatings activities
  HEIBHMAN.R F. Region 3. Chicago. Office of the Director 0170 1p 07905 336
- 8103140487 Forwards IE Circular 81-03. 'Inoperable Seismic Monitor Instrumentation " No response required KEPPLER.J O Region 3. Chicago. Office of the Director B1/03. 2pp 07915 302
- 8103160856 Forwards revised IE Culletin 81-01. 'Surveillance of Machanical Snubbers. " w/corrected Pages 5.7.6 Change in identification of facilities ../CPs to which builetin is applicable does not affect util requirements KEPPLER, J. O Region 3, Chicago, Office of the Director 81/03.
- 2pp. 07914; 211 BIO320036B Forwards IE Info Notice 81-06. 'Failure of ITE Model K-Circuit Breaker'' No response required KEPPLER. J. O. Region 3. Chicago. Office of the Director 81/03.
- 8103200668 Forwards 1E Info Notice 81-05. 'Degraded DC Sys at MAISAGES No action required MEPPLER. J C. Region 3. Chicago. Office of the Director - 81/03. 2pp. 07966:163
- 8103200271 Forwards IE Info Notice 81-07. "Potential Problem W.Water-Eclubie Purge Dam Matis Used During Inert Gas welding." No response required EPPLER, J.O. Region 3. Chicago, Office of the Director 81/03-29p. 07966-230.
- 5. Reportable occurrences. LERs & related correspondence
- 8103090564 Interim deficiency tept re suppression pool stainless steel cladding sensitization Further investigation on corrosion performance necessary. Final rept will be submitted by B10601 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 81/02/26 07850 197
- 8103090999 Update to 800929 final deficiency rept re Cutler-Hammel motor control ctrs. Requests extension of time to complete repairs from 810227 to 810601 Revised final rept expected by 810313 DAVIDBON, D. R. Cleveland Electric Illuminating Co. 81/02/26 07844: 154
- 8103090683 Interim deficiency rept re-fuel pool penetration piping welds. Full implementation of corrective action is incomplete final rept will be sent by 810301 DAVIDSON.D.R. Commonwealth Edison Co. 81/02/26 Ip. 07848; 24
- 8103090538 Final deficiency rept re lamination identified in ASTM gusset plate hanger steel rati All rati has been conformed to new matl requirements. All selected gusset plates have met specified acceptance criteria
  DAVIDSON.D.R. Claveland Electric Illuminating Co. 81/03/02 07849: 161

- COCKET 50-449 SEASHOOK NUCLEAR STATICAL UNIT 1
- A Application/construction stage documents & correspondence
- 8)03190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests review for quidelines in NUREO-Data Forwards NRC position re interim actions t request for addl info
  FigFr.HUT.G G Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants % applicants for OLs & holders of CPS te program for environ qualification of safety-related electrical equipment Ltems addressed involve cold shutdown replacement parts & NUREO-0737
  EISENUTED Division of Licensing 81/01/19 App
- Biodis20014 Ltr to all licensees of operating plants.CP holders & CL applicants.ercept Indian Point 2 % 3.71on 1 % 2 % TMI-1. forwarding inadvertently cmitted pages from NRC BDIS22 request for addline recontrol of heavy loads EISENHUT D G Division of Licensing 81/02/03
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A I 2 ne upgrade of energency support facilities Requests confirmation within 45 days that implementation dates will be net ETGER#-VI.B O Division of Licensing. 81/02/IB I2pp
- 8103253024 Ltr to all power reactor licensees & license applicants re fAJREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing law flow controller EISEMMUT.0 0 Division of Licensing 81/02/20 App
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFRSO 71(e), "Portodic Updating of FSARs," effective 800722 Info re FSAR legal status format & content enci. ETSECH-UT. D O Division of Licensing 81/02/26 10pp
- 8103236901 Notification of contract execution. Mad 1 to "Follow on Review of Seebrupt Nuclear Station. Units 1 & 2 " Contractor Fugro.Inc.
  MAIRSTO'H, C. A., EDGEHORTH, P. J. Technical Assistance Cuntracts Branch
  1/RC-03-80-119 81/03/10 1p 07974 226
- -- 8103233903 Mod 1. extending period of performance from 810125 to 810430 10323743 nod 1.ertensing periods or performance from Bibles to \$ limitsing jove Inability, to "Follow on Review of Seabrook Nyclear Station,Units | \$ 2 " 700409.9 T Furgo, Inc MATTIA.M J Administrative Contracts Branch N9C-03-80-119 BI/03/10 Ip 07974, 227
- 9103310834 Ctr to all licensees of operating plants.applicants for OLs & holders of CPs forwarding SECY-01-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHULD O Division of Licensing Bi/03/10 6pp.
- 8103230396 Discusses review of FBAR. Chapter 14, "Initial Test Program" Incorporating resolution of questions & NRC positions will reduce NRC review time TECEBOO.R L Assistant Director for Licensing 81/03/16 3pp. 07980 353
- F Security, medical, emergency & fire protection plans
- 8:033:0338 Ltr to all licenses of operating plants & holders of CPs forwarding NUREO-0676, "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements. W/o encl EISENHUT. D 0 Division of Licensing 81/03/05 6pp
- 8103170097 Advises that NRC evaluation of facility evacuation time estimates does not exist other than info provided in CP "Evaluation of Evacuation Time Estimates" by proceedings. Pikii encl. LESSY R.P. Antitrust Division 81/03/13 3pp. 07935-290.
- B103231079 Forwards request for addl fire protection info to complete facility program review Responses requested by 810919.
  TEDE8CO.R. L. Assistant Director for Licensing. 81/03/16. 8pp.
- G Adjudicatory correspondence
- B103040602 Answer opposing New England Coalition on Nuclear Pollution B10224 motion for directed certification Motion specifically disallowed by procedural rules & certification does not cover discovery rulings Certificate of Svc encl.
  DIGNAN.T.O Public Service Co of New Hampshirs DIGNAN.T.G Ropes & Gray. Bi/02/27. Spp 07817.065.

- Bi030204[4 Biatement re application of probabilistic method to astimation of seismic risk at facility Exhibits & Certificate of Svc enci
  - CHINNERY.M New England Coalition on Nuclear Pollution. 81/02/28 14500
- B103060349 Request for permission to reply to applicant B10227 reply
  New England Coalition on Nuclear Pollution B10224 motion for directed certification Alternatively requests referral of mation to ABLAB Certificate of Svc anci MEISB, E. R. JORDAN: H. B. New England Coalition on Nuclear Pollutio WEISE E R Harmon & Weiss 81/03/04 10pp. 07837-070
- BIO3060357 Submits M Trifunac questions re Chinnery earthquake formula. Trifunac requested extension for filing testimony No party objects Parties agreed that acceleration issue should be heard second LESSY. R. P. Antitrust Division 81/03/04 3pp 07837. CB2
- 8103090514 Forwards 810217 order scheduling 810406 evidentiary hearts on remanded setamic issues Also transmits 810305 order extending time to file testimony-euggesting questions posted to Chinnery & setting 810409 appearance M/o encis RUSENTHALIA. 8 Atomic Safety and Licensing Appeal Panel 81/03/0: RUSENTMALA. B. Atomic Safety and Licensing Appeal Panel B1/03/0: 2pp. 07844 349.
- 8103090516 Memorandum & order that earthquake intensity issue will be heard first opening w/further exposition of Chinnery methodology. Also grants seven-day extension for M Trifunac ## Fig. 1 Atomic Safety and Licensing Appeal Panel 81/03/03 App. 07844 351.
- 8103130425 Request for permission to contract & consult w/MD Trifunative NRC correlation of vibratory ground motion w/SSE Hitness will not be available for consultation or trial testimony. Certificate of Svc encl STROAM. W.B. New Englans Coalition on Nuclear Pollution JORDAN, W. Sheldon, Harmon & Weiss B1/03/11 700 07911 223. JORDAN, N. B.
- 8103200530 Notifies of 810318 ASLAB telephone conference w/parties to discuss New England Coalition on Nuclear Poliution B10311 request for permission to contact & consult w/Trifunat BISHOP, C J Atomic Bafety and Licensing Appeal Panel. 81/03/13 1p. 07971 311
- 8103200632 Forwards memorandum supporting 800630 request by Sea Coast Anti-Pollution League for order to show cause why CPPR-135 & 136 should not be suscended or revoked Promot decision requested BROTHELL, J. A. Massachusetts, State of. 81/03/13 1p. 07968 051
- --B103200637 Memorandum supporting Beaccast Anti-Pollution League SUJEUROS/ Memoranoum supporting Seaccast Anti-Pollution League 800630 request for order to show cause why CPPR-135 & 136 should not be suspended or revoked Energency plan is subj to post-licensing review per Et Pierce decision.

  8HQTHELL, J.A., 201.b.P. LEONARD, 8 M. Massachusetts, State of 81/03/13 19pp. 07969:052
- --8103200646 Affidavit re potential problems w/evecuation of resident of Newbury MA RIEL, Q.L. Affiliation Unknown BI/03/06. 3pp 07968 071
- --B103200652 Affidavit re-potential problems w/evacuation of resident Affiliation Unknown 81/03/06. 3pp 07968:074. PEARBON, M
- --B103200659 Affidavit re potential problems w/evecuation of resident Salisburg.MA. Certificate of Svc encl. OLIVERA.E. Salisburg.MA. 81/63/06 5pp. 07968:077.
- 8103170316 Forwards L Reiter rebuttal testimony to MA Chinnery direct testimony MA Chinnery 810310 ltr discussing 810310 telcon also enci. LESSY, R.P. Antitrust Division 81/03/16 2pp 07923:304.
- --8103170323 Rebuttal testimony to MA Chinnery direct testimony re-deterministic & probabilistic methodologies for estimation REITER, L. Geosciences Branch Bi/03/16, 4pp 07923:306.
- --8103170330 Discusses 810310 telcon u/Trifunac & Reiter All Trifunac questions were enswered in 1979 paper. Some results clarified during conversation CHINNERY, M. A. Massachusetts Institute of Technology. 81/03/10. 1p. 07923;310

- 8103190484 Response in apposition to New England Coalition on Nuclear Pallution Bi0004 request for permission to reply to applicant 810227 answer re directed certification if reply granted.certification must be denied A/Certificate of Svc LESBY.R.P. Antitrust Division 81/03/18 (1pp 07965-210
- 9103230477 Forwards A9LAB 810319 order reintervenor New England Coalition on Nuclear Pollution request for assistance & consultation at facility hearing. Board authorized consultation prior to hearing commencement 4/o encl ROSENTHALIA B Atomic Safety and Licensing Appeal Panel 81/03/19 205. 07979 275
- 8103240227 Forwards comments on selectic design criteria for plant site per ASLAB Order CLI-80-33 TRIFUNAC.tt D Southern California. Univ of 81/03/20 lp
- ~-8103240236 Comments on proposed characteristics of strong earthquake ground motion for seismic design criteria Discusses aspects of selecting seismic design criteria for sites 3 adequacy of proposed design levels Certificate of Svc encl
  TRIFUNAC.M D Bouthern California. Univ of 81/03/20 18pp
- 8103230439 Memorandum & order denying New England Coalition on Nuclear Power motion to direct ASLAB to certify Board 810212 memorandum & order Order is interligatory & cannot be appealed under rules of practice.

  CHILK, B. J. Office of the Secretary of the Commission 81/03/23 20n 07996.196

### H Comeral correspondence

- 8103060384 FOIA request for L Alsager 1tr requesting documents re const of nuclear plants in Sasbrook CH HEDELROS.M.F. Edwards & Angell. 81/02/12 2pp. 07835.357
- 8103060401 Confirms telcon w/Citizen Bafety Committee re NRC participation in 810319 meeting in Hampton NH re energency preparadoss 8TELLO.V. Birector's Office Office of Inspection and Enforcement 81/02/24 is 07835.361
- 8103130012 Ack receipt of 801124 ltr re evacuation planning FR excerpt & App E encl BTELLO.V Director's Office, Office of Inspection and Enforcement 81/02/24. 19pp
- G103060378 Responds to FOIA request for L Alsager 1th requesting documents re const of nuclear plants in Bestrook, NR & Commission response, NRC can locate no documents subj to request.

  FELTON, J M. Divesion of Rules and Records 81/02/23 1p. 07835:396
- 9 Inspection reports: IE Bulletins & correspondence
- 8103040436 Forwards IE Info Notice 81-01. 'Possible Failures of GE Type IFA Relays "No response required ORIER.B.H Region I. Philadelphia. Office of the Director. 81/01/16 1p 07820:059
- 0103270397 Ack receipt of 010123 Itr informing NRC of steps taken to correct violations noted in IE Inep Repts 30-443/80-12 & 50-444/00-12 CARLBON.R T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 01/02/20 pp 08034 135
- ~-B103270406 Responds to NRC 801230 ltr re violations noted in IE Insp. Repts 50-443/80-12 & 50-444/80-12 Corrective actions dual repeir process sheet says developed dicteting more controls during excavation & welding processes DEVINCENTIS.J. Public Bervice Co. of New Hampshire. 81/01/23 3pp. 08034.136
- 8103200228 Forwards IE Circular GL-03. "Inoperable Beismic Monitoring Instrumentation." No written response required GRIER-B.H. Region 1. Philadelphia. Office of the Director. BL/03/02. 1p. 07972:069
  - 8100200058 Forwards revised IE Bulletin 81-01, "Surveillance of Machanical Bubbers," w/corrected Pages 5 & Change in identification of facilities w/CP to which bulletin is applicable does not affect util requirements CRIER, B. H. Region 1, Philadelphia, Office of the Director. B1/03/04, 1p. 07968, 193.

- 6)03200188 Forwards IE Info Notice 81-06. 'Failure of ITE Model a Circuit Breaker' No response required GRIER.B H Region I. Philadelphia. Office of the Director 81/03/11 ip 07968 313
- S. Reportable occurrences. LERs & related correspondence
- 8103060234 Act receipt of 810115 ltm re pipe support design jeftc Matter will be reviewed during subsequent insp CARLSON.R T Region 1. Philadelphia. Reactur Construction & Engineering Support Branch 81/02/12 lp 07837 011.
- 8103180510 Interim deficiently rept re improper nondestructive era initially reported on 810126 Upon completion of investigation.util will determine reportability under 10067650 55e Nest rept will be forwarded by 810327 DEVINCENTIS.J. Putlic Service Co. of New Hampshire 81/02/23.
- T. Rearing transcripts on non-antitrust matters
- 8103230533 Rebuttal testimony on remand to ABLAB re deterministic methodologies on earthqueies Certificate of Bvc encl CHINNERY.M New England Coelition on Nuclear Pollution 91/03 22pp 07974-078
- OCCKET 50-444 SEAGROCK NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants f DLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NuREG-0612 Forwards NRC position re interim actions & request for addl info EISENHUT. 0 0 Division of Licensing 80/12/22 30pp
- BIO31903B7 Ltr to all licensees of operating plants & applicants OLs & holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown-replacement parts & NUREG-0737 EISENRUI, D. O Division of Licensing 81/01/19 App
- 8103120014 Ltr to all licensees of operating plants.CP holders \$ applicants.ercept Indian Point 2 & 3.2ion 1 & 2 & IMI-i, forwarding inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EISECHUY.D.O Division of Licensing. 81/02/03 6pp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III. A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT, D.O. Division of Licensing. 81/02/18 12pp.
- 8102330024 Ltr to all power reactor licensees & license applicant NAREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of eristing low flow controller EISENHUT. D O Division of Licensing 81/02/20 8pp
- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." gffective 800722 Info re FSAR legal status, format & content encl EISEMHUT, D O Division of Licensing. 81/02/26 10pp.
- B103230901 Notification of contract execution, Mod ( to "Follow on Review of Beabrook Nuclear Station, Units 1 & 2 " Contractor: Fugro, Inc. HAIRBION, C.A., EDOEKCRIH.P.J. Technical Assistance Contracts 3 NRC-03-80-115 81/03/10. 1p 07974 226
- --Bi03230903 Mod i.extending period of performance from 810125 to & limiting govt liability, to "Follow on Review of Beabrook Nuclear Station, Unite 1 & 2 YOUND, 0 T. Furgo. Inc. MATTLA.M. J. Administrative Contracts Branch NRC-03-80-115 81/03/10 lp 07974 227
- BiO3310B04 Ltr to all licensees of operating plants, applicants for bholders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT. D. G. Division of Licensing 81/03/10. App.
- B103230356 Discusses review of FSAR-Chapter 14, "Jnitial Test Pro Incorporating resolution of questions & NRC positions will reduce NRC review time TEDESCO.R.L. Assistant Director for Licensing 91/03/16 3pp 07980-353

EISENATED C Division of Licensing 81/03/05 App

8103170397 Advises that NRC evaluation of facility evacuation time estimates does not exist other than info provided in CP proceedings "Evaluation of Evacuation Time Estimates" by BNWL encl
LESSY.R P Antitrust Division 81703713 300 07935 390

G103231079 Forwards request for add1 fire protection info to complete facility program review Responses requested by 810515
TERESCO.R L. Assistant Director for Licensing 81/03/16 8pp

### G Adjudicatory correspondence

- 6103040602 Answer apposing New England Coalition on Nuclear Pollution 610224 and tion for directed certification Motion specifically disallowed by procedural rules & certification does not cover discovery rulings Certificate of Svc encl DIGNAN, I 9 Public Service Co. of New Hampshire. DIGNAN, I G. Ropes & Gray. 61702727 Spp. 07817-065
- 8103020414 Statement re application of probabilistic method to estimation of seismic risk at facility Exhibits & Certificate of Svc encil CHINNERY.M New England Coalition on Nuclear Pollution 81/02/28 145pp
- 6103080349 Request for permission to reply to applicant 810227 reply to New England Coalition on Nuclear Pollution 810224 motion for directed centrification Alternatively requests referred of mation to ASEAR Centificate of Byc enci HEIGS.E R. JURUAN, W.S. New England Cualition on Nuclear Pollution HEIGS.E R. Harmon & Weiss. 81703704 10pp 07837 070.
- #36304035/ Submits M Trifunac questions re Chinnery earthquake formula Trifunac requested extension for filing testimony N3 party ubjects Parties agreed that acceleration issue should be heard second LESSY.R P Antitrust Division 81/03/04 3pp 07837 082.
- 8103070514 Forwards 810217 order scheduling 810406 evidentiary hearing on remaided satemic torus Also transmits 810305 order extending time to file textimony, suggesting questions posted to Chirnery 1 setting 810407 appearance U/o encis PDESNIMAL A 8 Atomic Safety and Licensing Appear Panel 81/03/05 2pp 07844 347
- GLCC090516 Menorandum & under that earthquake intensity issue will be reard first opening w/further exposition of Chinnery rethodology Alag grants seven-day extension for M Trifunac to file testimony 315HCPF.C. J. Atomic Safety and Litensing Appeal Panel BI/03/05 app. 07044 351
- BIO3:30425 Request for permission to contract & consult w/MD Trifunacine NRC correlation of vitratory ground motion w/RSE Wilmess with not be available for consultation or trial testimony Certificate of Svc encl

  JORDAN.H B New England Coalition on Nuclear Pollution JORDAN.W S Sheldon. Harmon & Weiss 81/03/11 7pp 07911,223
- 8103200330 Notifies of 810318 ASLAB telephone conference U/parties to discuss New England Coalition on Nuclear Pollution 810311 request for permission to contact & consult U/Trifunac EISHOP.C J. Atomic Safety and Liconsing Appeal Panel 81/03/13 pp. 07974 311
- 8:03200632 Forwards memorandum supporting RO0630 request by Bea Coast Anti-Pollution League for order to show cause why CPPR-135 & 136 should not be suspended or revoked Prompt decision requested \$4014624.0 A Massachusette, State of. 81/03/13. 1p 07968 051.
- --Bi032C0637 Memorandum supporting Beecoast Anti-Pollution League 800533 request for order to show cause why CPPR-135 & 136 steuld not be suspended or revoked Energency plan is subj to post-licensing review per Ft Pierce decision 6:40TMELL.J A. GDUD.P. LECHARD-S M. Messachusetts. State of 81/03/13 [9pg 07968 052
- --Bi03200646 Affidavit re potential problems w/evacuation of residents of Newbury, MA RIEL, O. L. Affiliation Unknown. Bi/03/06 3pp 07968:07[

8103170316 Forwards L Reiter rebuttal testimony to MA Chinnery direct testicony MA Chinnery 810310 ltr distussing 810310 telcon also encl LESSY.R P Antitrust Division 81/03/16 2no 07923 304

Balisbury.MA 81/03/06 9ap 07968 077

- --BIO3170323 Rebuttal testimony to MA Chinnery direct testimony redeterministic & probabilistic methodologies for estimation of SSE REITER.L Geosciences Branch 81/03/16 4pp 07923 306
- --Bi03170330 Discusses Bi0310 telcon w/Trifunac & Reiter All Trifunac questions were answered in 1979 paper Some results clarified during conversation CHINMERY. M A Massachusetts Institute of Technology Bi/03/10 lp 07923
- 8103190484 Response in apposition to New England Coalition on Nuclear Pollution 810304 request for permission to reply to applicant 810227 answer re directed certification If reply granted certification nust be Jenied W/Certificate of Svc LESSY.R P Antitrust Division 81/03/18 11pp 07955 210
- 8103230477 For Jards ASLAB 810319 order re intervenor New England Coalition on Nuclear Pollution request for assistance & consultation at Pacifity hearing Board authorized consultation prior to hearing commencement H/o encl. RDSENTHAL.A. 5. Atomic Safety and Licensing Appeal Panel. 81/03/19 2co. 07979 225
- 8103240227 Forwards comments on seismic design criteria for plant site per ASLAO Order CLI-80-30 TRIFUNAC.M D Southern California. Univ of 81/03/20 ip. 07970 001
- --8103240236 Comments on proposed characteristics of strong earthquake ground motion for setsmic design criteria Discusses aspects of selecting seismic design criteria for sites & adequacy of proposed design levels Certificate of Svc encl
  TRIFURAC.M D. Southern California. Univ. of 81/03/20 18pp.
  07990 002
- 8103250439 Nemorandum & order denying New England Coalition on Nuclear Power rotion to direct ASLAB to certify Board 810212 nemorandum & order Order is interlocutory & cannot be appealed under rules of practice.

  CHILK. B.J. Office of the Secretary of the Commission. 81/03/23 2pp. 07996-196
- H General correspondence

OL TUEBALE

- 8103060384 FOIA request for L Aisager it requesting documents re const of nuclear plants in Seabrook, NH MEDEIROS M F. Edwards 8 Annell 81/02/12 2:0. 07835 357.
- 8103050401 Confirms telcon w/Citizen Safety Cornittee to NRC participation in 810319 meeting in Hampton, NH to emergency proparations.

  STELLO. V. Director's Office, Office of Inspection and Enforcement, 81702724 1p. 07835-351.
- BiO3130012 Ack receipt of B0i124 ltr re evacuation planning.FR excerpt & App E enci STELLO.V. Director's Office. Office of Inspection and Enforcement. 81/02/24 15pp.
- 8103060378 Responds to FDIA request for L Alsager itr requesting documents re const of nuclear plants in Seabroak.NM & Commission response NRC can locate no documents subj to request FELTOK.J M. Division of Rules and Records 81/02/23. Ip 07833-356
- Q Inspection reports. IE Bulletins & correspondence
- BIO3040435 Forwards 1E Info Notice Bi-Ol. "Possible Fallures of GE Type HFA Relays " No response required GRIER.B.H. Region I. Philadelphia. Office of the Director BI/Ol/16 Ip. 07820 059.

- BIO0270397 Ack receipt of Biole3 ltr informing NRC of steps taken to correct violations noted in IE lines Repts 39-443/80-12 & 30-444/80-12 CARLSON, RT Region I. Prilabelphia. Reactor Construction & Engineering Support Brench BI/02/20 ip 08034 133
- --Bi03270496 Responds to NRC B01230 ltr re-violations noted in IE Insp. Repts 50-443/80-12 & 50-444/80-12. Corrective actions dual repair process sheet sys developed dictating more controls during excavation & welding processes
  DEVINCENTIS, J. Public Service Co. of New Harpshire 81/01/23
  396. 08094 136
- 8103200220 Forwards IE Circular 81-03. Imperable Geishic Monitoring Instrumentation "No written response required GRIER, B.H. Region I. Philadelphia, Office of the Director BI/03/02 ip 07972 065.
- B10320005B Forwards revised TE Bulletin B1-01. "Burveillance of Mechanical Bnubbers." Wicorrected Pages 5 & 6. Change in identification of facilities W/CP to which bulletin is applicable does not affect util requirements ORIER. B. H. Region 1. Philadelphia. Office of the Director B1/03/04. | p. 0796B ISB.
- B103200188 Forward; IE Info Notice 81-06, "Failure of ITE Model K-600 Circuit Breaker." No response required GRIER.B.H. Region I. Philadelphia, DPPice of the Director 81/03/11 p 07968 313.
- 8. Reportable accurrences, LERs & related correspondence
- B103060234 Ack receipt of B10119 ltr re page support design deficiency Habter will be reviewed during subsequent insp. CARLSON R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B1/02/12 1; 07837:011
- 8103180910 Interim defittency rept re improper nondestructive exams, initially reported on 810126 Upon completion of investigation, util will determine reportability under 10CFR90.55e Next rept will be forwarded by 810327 DEVINCENTIS. J. Public Service Co. of New Hampshire 81/02/23 ip 07944.200.
- T. Hearing transcripts on non-antitrust matters
- 8103230833 Retuttel testimony on remend to ASLAB re deterministic methodologies on parthquakes Certificate of Syc encl CHIANERY M. New England Coalition on Nuclear Pollution. 81/03/16 22pp. 07979:078
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1
  A Application/construction stage documents & correspondence
- BioGi90732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-O612 Forwards NRC position re-interim actions & request for addl info, EIGENHUT, D. Q. Division of Licensing 80/12/22, 30pp.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of sefety-related electrical equipment. Items addressed involve cold chutdown replacement parts & NUREG-0737.
  EISENHUT.D.O Division of Licensing 81/01/19. 6pp.
- 8103120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add1 info re control of heavy loads. EISENMUT.D.Q. Division of Licensing 81/02/03. App.
- 8103060090 Forwards request for addl info re OL review Util must propose Tech Specs change to limit use of main containment purge sys to reactor operational modes of cold shutdown & refueling.

  TEMESCA: R.L. Assistant Director for Licensing. 81/02/11. Spp. 07839 OOI.
- 8103050122 Forwards revised NRC Region 4 organization chart, effective 810227. SEYFRIT-K.V. Region 4. Dalles. Office of the Director. 81/02/18. 2pp. 07827:003.
- BIO3050442 Notification of BIO310 meeting w/util in Betheeds.MD to discuss remayal of boron injection tank from ECCS & responses to Reactor Befety Board questions & positions. BURNELL's B. Licensing Branch 2 BI/02/20. 3pp 07824.340.

- 8103200342 Forwards request for add1 info needed for completion of review of CL application Requests that FSAR be amended to include info Info should to submitted within four wis TEDESCO.R L. Assistant Director for Licensing 81/02/20 12pp 07971-049
- B103290324 Ltr to all power reactor licensees & license applicants MREO-0619 criteria Foutnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subnit analysis to justify use of existing law flow controller E16ENHUT.D O Division of Licensing 81/02/20 Bpp
- 8:03270030 Let to all licenses of operating nuclear power plants : applicants for CLs (except 5t Lucie Units (& 2) Requests util review to determine capability to mitigate station blackout event 3 promptly implement emergency procedures EISE(HUPLD 0 Division of Licensing 8:1/02/25 Spp
- 8103230813 Oeneric Ltr Bi-06 to all CP holders & O. applicants to 10CFR90.71(e). 'Periodic Updating of FSARs.' effective 800722 Info re FSAR legal status format & content enci EIEEMHUT.D O Division of Licensing 81/02/26 10pp
- 8103090180 Notification of 810311 meeting woutfil in Bethesda.HD to discuss applicant responses to Site Analysis Branch questions. Series 311 0 control of mineral exploration activities within exclusion area 80RMELL.8 3 tipensing Branch 2 81/02/27 3pp 07847 289
- B1032000B3 Informs that staff functions of Region 4 reassigned, offective B10227 OL Madsen. Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondence to reactor const & operation activities BEYRII.K V Region 4. Dallas. Office of the Director BI/03/05 to 0796B:213
- 8103250320 Requests update on status of RRC 801212 unsite audit & subsequent safety evaluation JONES,R A. Teras Utilities Generating Co. 81/03/11 ip 07997 273
- 8103190145 Notification of 810316 meeting w/near-term OL applicants Bathesda.MD re info required to be submitted on environ qualification of electrical equipment prior to site visit & MRC review BURNELL.S Licensing Branch 2 81/03/12 15pp
- E NAC Safety Evaluation Report (SER), supple & correspondence
- B103120422 Forwards draft SER input. Util requested to review & prep corrects & arrange meeting w/MRC to discuss comments. Suggests meeting be held 810405 in State of NY TEDESCO.R L. Assistant Director for Licensing 81/02/27 app. 07906 141
- --Bi03120444 Draft SER input re determination of break locations to dynamic effects associated u/postulated rupture of pining, seismic subsystem analysis to mechanical sys & components # Assistant Director for Licensing 81/02/27 44pp 07905 !
- B103160261 Forwards Components Integrity Section BER input & request for add1 info re FSAR for facilities. Add1 info required refracture toughness of matle & qualifications of personnel performing fracture toughness tests.

  TEDBECO.R L Assistant Director for Licensing. 81/03/06. 25pp. 07917:194.
- BiO3200670 Requests info for SER & supplemental BER two wks prior I SER date indicated on encl schedule Requests four months prior to SER issuance equipment qualification info per IE Bulletin 79-01B, for SERs scheduled after June 1981 DENTON.H R Diffice of Nuclear Reactor Regulation, Director BI/03/13 6pp 07967-242
- F. Security, medical, emergency & fire protection plans
- B103130095 Forcerds request for add1 info re fire protection design Add1 info should be incorporated into FBAR Requests response within 6 uis. TEDESCO.R.L. Assistant Director for Licensing B1/02/20 Bpp 07912-001
- B103310338 Ltr to all licenses of operating plants & holders of Cf forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl

### G Adjudicatory correspondence

- 8103050769 First set of interrogatories & requests to produce directed to applicant Certificate of Svc encl Related correspondence MCCLL.A C. Citizens for Fair Utility Regulation MCCCLL.A C MCColl.A C 81/02/26 9pp 97828 104
- 8:03040405 Assuer apposing dittiens Association for Sound Energy B10209 notion for postponeent of responses to interrogatories recontention 22 All info available has been sent to intervenor Certificate of Svc encl POTMSCHILD. M. U. Operations & Administrative Division B1/03/02. 97: 07820 181
- B103050655 Second set of interrogatories & requests to produce directed to Citizens Por Fair Util Revolation re Contentions 1 & 6 Certificate of Sec enci Related correspondence REYNCLOS.N S. HORIN.W A Feas Utilities Generating Co REYNCLOS.N S. Debevoise & Liberman 61/03/02 16pc 07829 221
- 6103050568 Second set of interrogatories & requests to produce directed to TX Association of Community Organizations for Reform Nounce Contentions 10.12 & 14 Certificate of Sec encl Related correspondence REYNOLDS 8 HORIN H A Texas Utilities Opening Co REYNOLDS N 8 HORIN H A Texas Utilities Opening Co 07829 235
- 8:03060351 Request for order compelling intervenor Citizens Association for Sound Energy to provide full-direct & responsive answers to Interrogatories 0-4.6-5.0220-1-7.024-4(d) & (e). C24-5(a)-(j) & C24-5(e)-(r) Sertificate of Svc encl PDTHSCHILD.M U Operations & Administrative Division 81/03/04 37zp -07637:12
- 6103190365 Responds to intervenur Citizens Association for Sound Energy B10217 fourth set of intervogatories Answers include info re applicant filmential qualifications & emergency plan. Certificate of Svc encl Related correspondence REYNOLDS.N.S. HDRIN.W.A. Telas Utilities Operating Co-SEYNOLDS.N.S. Debevotes & Liberman G1/03/09 96p 07955 224
- 8103230631 Answer apposing applicants' 810223 notion to compel & require addl responses to applicants' second set of interrogatories to intervenor Bufficient grounds for order rot provided W/Cercificate of Svc Related correspondence ELLIB. U Citizens Association for Sound Energy 81/03/10 app 37972 051
- 8103230647 Answers to NRC first set of interrogatories & requests to produce to FBAR-accident sequence analyses, operator/maint error allocance & Class 9 accidents Certificate of Svc encl. Related correspondence FOWER C. Catisiens for Fair Utility Regulation 81/03/31 12pp 07973-325
- 8103160324 Informs that NRC will not respond to applicants' 810223 motion to compel & require supplementation of responses to applicants' second set of interrogatories directed to Citizens Association for Sound Energy 20146CHILD. H V Operations & Administrative Division. 81/03/12 pp. 07922 060
- 310J200552 Advises of original verification for intervenor Bi03l3 suppl to answers to utils' second set of interrogatories ELLIS. J. Citizens Association for Sound Energy 81/03/13 2pp 07970 252
- 6103230739 Supplement to Citizens Association for Sound Energy answers to applicants' second set of interrogetories re emergency planning & financial qualifications Certificate of Svc encl Related correspondence ELLIS. J. Citizens Association for Sound Energy 81/03/13 19pp. 07974 174
- B103189072 Request for order conpelling Association of Community Ergenizations for Reform Nou-TX to respond to NRC interrogatories & requests for production of documents, frienders has not filed answers Certificate of Svc encl ROTHSCHELD, M.U. Operations & Administrative Division. 81/03/16 2pp. 07942 342
- 8103270935 Response to Citizens Association for Sound Energy requests for production of documents Contained in 810217 fourth set of interropatories Certificate of Svc encl Related correspondence PEYMOLDS.N S. HORIN.M A. Tolas Utilities Generating Co. REYMOLDS.N S. Debevoise & Liberman. 81/03/24 Spp. 08034-009

8100270569 Second set of interrogatories & request for production documents directed to Citizens Association for Safe Energy Certificate of Sw. onci. ROTHSCHILD: M. U. Operations & Administrative Division B1/03/20 Bab. 08004-024

#### i Financial information

- 8103160379 Forwards request for add1 financial info to complete evaluation of application for OL Util should indicate estimated annual cost by yr to operate each unit for first 7 yrs of commercial operation.
  TEDESCO.R L. Assistant Director for Licensing 81/03/09 lips
- K Utility Final Safety Analysis Report (FSAR) & anends
- 8103090967 Forwards affidavit of svc for FSAR Abend 15 SCHMIDT:N C Teras Utilities Generating Co. 81/02/26 Spp 07850 192

#### M. Antitrust correspondence

- BiO3190629 Supplemental status rept re BiO223 settlement between f Utils Board of City of Brownsville.Tx.Central & Southwest Corp.Central Power & Light Co & West Tx Utils Characterijes settlement agreement W/Certi/licate of Svc BPIEOEL.O. PUIRIER.M R Brownsville.Tx SPIEOEL.O Spiegel & McDiarmid BI/O3/18 9p 07963 317
- 8103260817 Supplemental status rept of Kar 1781 Settlement complet W/Central & Southwest Corp & subsidiaries Reserves position that no administrative or judicial proceeding will prejudice Brownsville rights in future W/Certificate of Svc. SPIEOSELO POIRIER MR Brownsville.TX SPIEOSELO Spiegel & McDiarnid 91/03/19 7pp 09036 223
- P Operating license stage documents & correspondence
- BiO3310804 Ltr to all licensees of operating plants, applicants for the holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment EIBESHWT.0 9 Division of Licensing 81/03/10 App
- Q. Inspection reports. IE Bulletins & correspondence
- B1D3190284 Ack receipt of 1E Insp Repts 50-445/80-23.50-446/80-23.50-445/80-28 & 50-446/80-28 on B01119 No proprietary info GARY, R. J. Texas Utilities Generating Co. 80/12/17. lp. 07954
- BIO3230190 Responds to IE Bulletin BO-23. "Failures of Solenoid Va Mfg by Valcor Engineering Corp " No Valcor valve \(\omega\)/specified parts numbers in use GARY.R J. Texas Utilities Generating Co. 80/12/17 lp. 07977
- 8103230203 Responds to IE Builetin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No Malcolm valves parts in use QARY.R J. Taias Utilities Generating Co. 80/12/22 ip 07977
- 8103040437 Forwards IE Investigation Repts 50-445/80-22 & 50-446/8 on 800908-11 & 1106-07.

  SEYFRIT.K.V Region 4. Dallas. Office of the Director 81/01/2 ip 07813 323
- --BIJJ040455 IE Investigation Repts 50-445/80-22 % 30-446/80-22 on BIO9708-11 & 1106-07 No mencompliance noted Major areas investigated allegations that Broun & Root GA was not ensuring corrective action re documented nonconformances DRIBKILL, D. D., DIOACO:MA, T. L., SEYFRIT, K. V. Region 4, Dalles, Office of the Director BI/O1/21 12pp. 07813-324.
- BIO3190293 Ack receipt of IE Inap Repts 50-445/80-29 & 50-445/80-2 BIO102 No proprietary info. GARY.R.J Texas Utilities Generating Co. 81/01/21 1p. 07994
- 0103110774 Ack receipt of IE Insp Repts 50-445/80-27 & 50-446/80-2 proprietary info ORRY, R J Teras Utilities Generating Co 91/02/04 ip. 07875
- B103190277 Ack receipt of IE Insp Repts 90-449/80-22 % 90-446/80-2 B10121 No proprietary info QARY.R.J. Teras Utilities Generating Co 81/02/11. 1p. 07965

07839 001

07971 045

- 8103260483 Forwards IE Insp Repts 50-445/81-01 & 50-446/81-01 during Jan 1981 Ne noncompliance noted SEIDLE.W C Region 4. Dalias. Reactor Construction & Engineering Support Branch 81/02/13 200 08040 355
- --BID3260495 [E Inso Repts 50-445/BI-0] & 50-446/BI-0] during Jan 1981 No 103200475 [E ] map Repts 50-447/81-01 50-446/81-01 during Ja noncompliance noted Major areas inspected spins installation, piping sys supports & restraints & observation of protection of rajor installed equipment. TAYLOR, R 0 . CROSSMAN, M a Region 4, Dallas, Office of the Director 81/02/12 7pp 08040 357
- of protection TAYCOR.R 0 . CROSSIM Ant 81/02/12 B103160631 Forwards IE Info Notice 81-04. 'Cratting in Main Steam
- United "No response required SEVERITA V Region 4. Dallas. Office of the Director. 81/02/27 b 07917 084
- 8103170045 Forwards IE Circular 81-03. "Inoperable Seisbic Monitoring Instrumentation " No response required. BEYFRITIK V Region 4. Dallas. Office of the Director. 81/03/02 10 07939 169 8103160835 Forwards revised IE Bulletin 81-01. Surveillance of NUMBERGALS PROMOTED TO SERVICE OF THE BILLY SURVEY HATE OF MECHANICAL BRUDDERS. "W/Corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements SEYFRIT. K.V. Region 4. Dallas, Office of the Director. B1/03/04
- 8103230184 Forwards IE Info Notice 81-07. "Potential Problem M/Mater-Soluble Purge Dam Matls Used During Inert Gas Melding, "No response required SEYRITAK, V Region 4, Dallas, Office of the Director, 81/03/16 Jp. 07977-227
- S Reportable occurrences. LERs & related correspondence

07914 191

- 9103180555 Final deficiency rept re co-pressive atrength of pipe support baseplate grouting mati subjected to elevated temps.
  Initially recorted BIQ120 Condition found not reportable under 10CFR30 55(e) GARY. R. J Texas Utilities Generating Co. 81/02/18 1p. 07954.182
- 8:03260929 Notifies that evaluation re combustible dry state cable Jubricant deficiency will be completed by 810919 GARY.R J Yeras Utilities Conerating Co. 81/02/18. 1p. 08036.318
- B103240474 Interim deficiency rept.originally reported B10217.re Westinghouse valves that failed to close completely under gre-operational test conditions Westinghouse investigating Problem lies within Limitorque operators Mods scheduled Texas Utilities Generating Co B1/03/13 3pp. 07982: 253
- 8103240474 Interim deficiency rept.originally reported 810217.re Westinghouse valves that failed to close completely under gre-operational test conditions Westinghouse investigating Problem lies within Limitorque operators Mods echeduled QARY, R J Texas Utilities Generating Co B1/03/13. 3pp.
- U. Congressional/Executive Correspondence
- B103240091 Forwards fourth monthly status rept to Congress for 810115-0215 Rept discusses actions taken on licensing reviews of new facilities Rept will be arended to include add1 info requested on B10217. KAMMERER. C. Diffice of Congressional Affairs. 81/02/27 3pp
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2 A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0412 Forwards NRC position re interim ections & request for addl info EISENHUT. D. Q. Division of Licensing. E0/12/22. 30cc.
- 8:03:90387 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs reprogram for environ qualification of safety-related electrical equipment items addressed involve cold shutdown.replacement parts & NUREO-0737. EISENHUT.D.Q. Division of Licensing 81/01/19. opp.
- 103:20014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3,2ion 1 & 2 & TMI-1.

  Arrandating inadvertently united needs from NAC 80:222

- 81639A0090 Forwards request for add1 tofo to CL review Util ones propose Tech Specs change to limit use of main containment purge sys to reactor operational modes of cold shutdown & refueling.
  TEDESCO.R L Assistant Director for Licensing 81/02/11 9pp
- B103050122 Forwards revised NRC Region 4 organization chart.effec 810227
- SEYFRIT, K. V. Region 4. Dallas, Office of the Director 81/02/ 2cp 07827 063
- B103050442 Notification of B10310 meeting w/util in Bethesda. 43 t discuss reloval of boron injection tank from ECCS to responses to Reactor Safety Board questions typositions BURRELLS 9 ticensing Branch 2 81702720 3pp 07824 340
- 8103200342 Forwards request for addl info needed for completion o INJUSTIC FOR JAPOS REQUEST FOR ADDITION DIBBOOK FOR COMPLETION D review of OL application Requests that FBAR be amended to include info Info should be submitted within four wis TEDEBTOR L. Assistant Director for Licensing 81/02/20 12:
- 8103250024 Lir to all power reactor licensees & license applicant NUREO-0619 criteria Footnote 2 in Table 2 contains error due in leakage testing deletions Licensee may subrit analysis to justify use of existing low flow controller FIBENHUT, D O Division of Licensing 81/02/20 App
- 8103230030 Ltr to all licensees of operating nuclear power plants agolicants for Ols (except 9t Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackaut event & promptly implement energency procedures. EISENHUT, D.O. Division of Licensing 81/02/25 5pc
- 8103230813 Oeneric Ltr 81-06 to all CP holders & D\_ applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 930722 Info re FSAR legal status.format & content encl EISENHULD G Division of Licensing 81/02/26 10pp
- 8103090189 Notification of B10311 meeting w/util in Dethesda. HD t discuss applicant responses to Site Analysis Branch questions. Series 311 % control of mineral exploration
- activities within exclusion area BURWELL, B 3 Licensing Branch 2 81/02/27 3pp 07847 289
- 8103200093 Informs that staff functions of Region 4 reassigned, effective 810227 GL Madsen.Chief of Reactor Projects Branch, designated as principal contact 5 recipient of correspondence re-reactor const & operation activities SEYFRIT.X V Region 4. Dalles. Office of the Director (81/03/ 1s 07968 213
- 8103250320 Requests update on status of NRC 801212 onsite audit & subsequent safety evaluation JONES,R. A Terms Utilities Generating Co B1/03/11 ip 07997-273
- 8103190145 Notification of 810316 meeting w/near-term OL applican Bethesde, MD to info required to be submitted on environ qualification of electrical equipment prior to site visit &
- BURWELL B. Licensing Branch 2 81/03/12 15pp
- 8103120422 Forwards draft BER input Util requested to review & pr

E NRC Befety Evaluation Report (SER), supply & correspondence

- comments & arrange neeting w/HRC to discuss comments Suggests weeting be held 610405 in State of NY TEDESCO.R.L. Assistant Director for Licensing B1/02/R7. 699 07906:141
- -- BIO3120444 Draft BER input re determination of break locations dynamic effects associated w/postulated rupture of piping, seisnic subsystem analysis & mechanical sys & components Assistant Director for Licensing 81/02/7 449p 07 07706
- 8103140261 Forwards Components Integrity Section SER input & requ toglowed: rereards Components integrity section beh input a feat for add info re FBAR for facilities Add info required re fracture toughness of matis & qualifications of personnel performing fracture toughness tests TEDESCO.R L. Assistant Director for Licensing 81/03/06 25p 07917:154.
- 8103200670 Requests info for SER & supplemental SER two was prior SER date indicated on encl schedule Requests four months prior to SER issuance-equipment qualification info per IE Bulletin 79-018, for SERs scheduled after June 1981

## F. Security, medical, emergency $\ell$ fire protection plane

- 8103132595 Forwards request for add1 info re fire protection design add1 info should be incorporated into FSAR Requests response within 6 wis TERESTOR C. Assistant Director for Licensing 81/02/20 8pp 03912 031
- 8193310338 Ltr to all licensees of operating plants & holders of CPs forwarding huREG-Do96. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements 470 encl

### 3 Adjudicatory correspondence

- 8103340405 Answer opposing Citizens Association for Sound Energy 810209 notice for postponement of responses to Interrogatories recontention 22 All info available has been sent to intervenor Certificate of Svc encl SDTMSCHILD. M. U. Operations & Administrative Division. BI/03/02 app. 07820 181
- 8103350656 Second set of interrogatories & requests to produce directed to Cittiens for Fair Util Regulation re Contentions 1 & 6 Certificate of Sec encl Related correspondence REYKOLOBIN 9 HORINIM A Teras Utilities Cenerating Co-REYKOLOBIN 5 Delievoise & Liberman 81703702 16pp 07829-221
- BIO335964B Second set of Interrogatories & requests to produce directed to TX Association of Community Organizations for Reform Now to Contentions 10.12 & 14 Certificate of Svc encl Related correspondence
  REYNOLOS.N B . HORRING A Teras Utilities Openerating Co.
  REYNOLOS.N S Debevoise & Liberman BI/03/02 21pp 07829 239
- 8103060391 Request for order compelling intervenor Citizens Association for Sound Energy to provide full-direct & responsive assuers to Interrngatories 0-4.0-5.022-1-7.024-4(d) & (e), (24-5(a)-(j) & C24-5(a)-(r) Certificate of Svc encl ROTHSCHILD: HU Operations & Administrative Division 81/03/04 3766. 97837 121
- B103190565 Responds to intervenar Citizens Association for Sound Energy B10217 fourth set of interrogatories Answers include info reapplicant financial qualifications & emergency plan Certificate of Svc encl Related correspondence REYMOLOS.N S. HORING A. Tevas Utilities Generating Co. REYMOLOS.N S. Debevoise & Liberman. B1/03/09 9pp 07955 224
- 8103200631 Answer opposing applicants' 810223 mution to compet to equite add1 responses to applicants' second set of interrogatories to intervenor Bufficient grounds for order not provided W/Certificate of Svc Related currespondence ELLIS.3 Citizens Association for Sound Energy 81/03/10 6:p. 07972 091
- 9103230647 Answers to NRC first set of interrogatories & requests to produce re FBAR.accident sequence analyses operator/maint error allowance & Class 9 accidents Cortificate of 8vc encl Related correspondence FOUNE.R L Citiens for Fair Utility Regulation 81/03/11 12pp 07973 325
- 8103160384 Informs that NRC will not respond to applicants' B10223 cotion to compel & require supplementation of responses to applicants' second set of interrogatories directed to Sitizens Association for Bound Energy ROTHSCHILD.N U Operations & Administrative Division 81/03/12 to 07922 060
- 8103200562 Advises of original verification for intervenor 810313 suppl to ensuers to utils' second set of interragatories. ELLIS.J. Citizens Association for Sound Energy 61/03/13 2pp 07970, 232.
- 8103230735 Supplement to Citizens Association for Sound Energy answers to applicants' second set of interrogatories re emergency planning & financial qualifications Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Bound Energy. BJ/03/13 19pp. 07974 174.
- BIG3180072 Request for order corpelling Association of Community Organizations for Reform Now-TX to respond to NRC interrogatories & requests for production of documents intervenor has not filed answers. Certificate of Svc encl. ROTHSCHILD.RU. Operations & Administrative Division. 81/03/16 Jpp 07942.342

- 8103270536 Response to Citizens Association for Sound Energy F for production of documents contained in 810217 fourth set of interrogatories Centificate of Svc encl Related correspondence REMIQLOSN S . HORIN.W A Texas Utilities Generating Co. REMOLDS.N S . Debevoise & Libernam Ol/03/24 Spp 08034
- 8103279569 Second set of interrogatories & request for product documents directed to Citizens Association for Safe Energy Certificate of Suc encil ROTHSCHILD.M U. Operations & Administrative Division 81/0.800 026

### 1 Financial information

- BLO3i60579 Forwards request for addit financial info to complet evaluation of application for DL Util should indicate estimated annual cost by yr to operate each unit for first 7 yrs of commercial Operation TEDESCO.R L Assistant Director for Licensing 81/03/09 07915 189
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B103090567 Forwards affidavit of svc for FSAR Amend 15 SCHMIDT.H C Texas Utilities Generating Co 81/02/26 5pp 07890 192

#### M Antitrust carrespondence

- Bio3190529 Supplemental status noptine Bio223 settlement betwee Utils Board of City of Brounsville, TK, Central & Bouthwest Corp. Central Power & Light Co & West TX Utils Characterizes settlement agreement W/Certsficate of Bvc. SPIE08L, 0. PDIRIER M.R. Brownsville, TX SPIE08L, 0. Spiege RD161911 6 3103/18 9pt 07963, 317
- B103260Bi7 Supplemental status rept of Mar 1981 Settlement computerial & Southwest Corp & subsidiaries Reserves position that no administrative or judicial proceeding will projudice Grownsville rights in future G/Certificate of Svc SP1E0EL.0. POIRIER.M.R. Brownsville.TX BP1EGEL.0 Spiege McDiermid 81/03/18 9pp. 0E036:223
- P. Operating license stage documents & correspondence
- B103310B04 Ltr to all licensees of operating plants applicants & holders of CPs forwarding 5ECY-B1-119 ro info necessary to establish environ qualification of safety-related electrical equipment.
  EISEEHHUTLD O. Division of Licensing B1/93/10 App
- 9. Inspection reports: IE Bulletins & correspondence
- 8103190284 Act receipt of 1E Insp Repts 50-445/80~23.50-446/80-50-445/80-28 & 50-446/80-28 on 801119 No proprietary info OARY-R.J. Texas Utilities Generating Co. 80/12/17 1p. 03
- 8103230190 Responds to IE Bulletin 80~23. "Failures of Bolenoid Mfg by Valcor Engineering Corp " No Valcor valve w/specified parts numbers in use. GARY, R.J. Telas Utilities Generating Co. 80/12/17 ip 07
- 8103230203 Responds to IF Bulletin 80-21. "Valve Yokes Supplied Malcolm Foundry Co. Inc." No Malcolm valves parts in use GARY.R J. Teres Utilities Generating Co. 80/12/22 Ip. 07
- BIO3040437 Forwards IE Investigation Repts 50-445/80-22 & 50-44 on BGQ908-11 & 1106-07 SEYFRIT.K V. Region 4. Dallas. Office of the Director. 81/0 ip. 07813 323
- --8103040455 IE investigation Repts 90-445/80-22 & 50-446/80-22 800708-11 & 1104-07 No noncompliance noted Major areas investigated allegations that Brown & Root OA was not ensuring corrective action re documented nonconformances DRISKILL D D . DIOALDMA.T L . SEYFRIT.K. V Region 4, Dalis Office of the Director. 81/01/21 12pp. 07813 324.
- 8103190293 Ack receipt of 16 Inep Repts 50-445/80-27 & 50-446/6 B10102 No proprietary info. QARY/R J Texas Utilities Generating Co. B1/01/21. 1p 03
- 8103110774 Ack receipt of IE Insp Repts 50-449/80-27 & 50-446/8 proprietary info GAY-R-J. Texas Utilities Generating Co. 81/02/04 1p. 07

- B103190277 Ack receipt of IE losp Rapts 50-449/80-22 & 50-446/80-22 on B10121 No proprietary info.

  GARY.R J Teras Utilities Generating Co. B1/02/11 1p. 07965 183
- 9103260483 Forwards IE Insp Repts 90-445/81-91 & 93-446/81-01 during Jan 1981 No honcompliance noted SEIDLE, W.C. Rogino 4: Dallas, Reactor Construction & Engineering Support Branch 81/02/13 2pp 08/90 355
- --B103260475 lE Insp. Repts 90-445/B1-01 5 50-446/B1-01 during Jan 1981 No noncompliance noted Hajor areas inspected piping installation.piping sys supports & restraints & observation of protection of major installed equipment TAYLOR.R.O. CROSSMAN.W.A. Region 4. Dallas, Office of the Director. B1/02/12 7pp 08040 357
- 8303160631 Forwards IE Info Notice 81-04. "Cracking in Main Stead Lines." No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 81/02/27 12 0.7917:084
- B103170045 Forwards IE Circular B1-03, "Inoperable Seisnic Monitoring Instrumentation" No response required SEYFRIT. A V Region 4, Dallas, Office of the Director 81/03/02 ip 0.7939 169
- 0103160835 Forwards revised IE Bulletin 81-01. "Gurveillance of Mechanical Shubbers." w/corrected Pages 5 ½ 6 Change in identification of Pacifities w/CPs to which bulletin is applicable does not affect util requirements

  EEYFRIT.K V. Region 4. Dallas. Office of the Director. 81/03/04

  10 0.7914-191
- 8103230184 Forwards IE Info Notice 81-07. 'Potential Problem W/Water-Soluble Purge Dam Matis Used During Inert Gas Welding 'No response required EEYFRIT.K.V Region 4. Dallas, Office of the Director 81/03/16 to 07977 222
- 6. Reportable occurrences, LERs & related correspondence
- 8103180555 Final deficiency rept re compressive strength of pipe support baseplate grouting mail subjected to elevated temps. initially reported 810120 Condition found not reportable under 102FASO 55(e).

  GARYR. J. Texas Utilities Generating Co. 81/02/18 in 07954 182
- 8100260929 Notifies that evaluation re-combustable dry state cable lubricant deficiency will be completed by 810315.

  GARY.R J. Feas Wtilities Generating Co. 61/02/88 in 08036-318
- B103240474 Interim deficiency rept, originally reported B10217.re Mestinghouse valves that failed to close completely under pre-operational test conditions Mestinghouse investigating Problem lies within Limitorque Operators Mods scheduled. GARY.R J. Texas Utilities Generating Co. 81/03/13 3pp 07/982 263.
- DOCKET 50-448 DOUGLAS POINT NUCLEAR BEATIGH, UNIT L

  A Application/construction stage documents & correspondence
- 8103031067 "Environ Statements Project," nonthly progress cept for Dec 1980 ZITTEL,H E Oak Ridge National Laboratory FIN B-0760-1. 8103031067. 80/12/31 4pp.
- 8103170457 Responds to NRC 810223 request for add1 info re util plans for facilities. Completion of Cherokee 1 & 2 has been indefinitely delayed. Connercial operating dates for Cherokee 3 & Perkins 1,2 & 3 have not been determined. BAILL.L.C. Duke Power Co. 81703/12 2pp
- A. Application/construction stage documents & correspondence
  - 103031067 "Environ Statements Project." monthly progress rept for Dec 1980. ZITTEL.H E. Dak Ridge National Laboratory. FIN 8-0760-1 8103031067. 80/12/31. App

- DDCKET 50-450 SUMMIT NUCLEAR PEWER STATION. UNIT 1

  Q Adjudicatory carrespondence
- 8103250442 Supplemental response stating no objection to terminate proceeding & withdrawal of application w/o prejudice Enclings replindicates no noncompliance or adverse environ affects from onsite work noted XARMAN. Hearing Uranc' 2 81,03,24 in 07998-207
- --Bio3250443 Forwards (E insp Repts 50-450/Bi-Oi & 50-451/Bi-Oi on Bio127 No mencompliance noted CARLSCH:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch Bi/OZ/25 2pp 07996 208
- ---810325044B LE Insp Repts 50-459/B1-01 & 50-451/81-01 on B10127 M: noncompliancenoted Major areas inspected site conditions resulting for Lor Lork done per LMA Certificate of Svc encl MARROM-L. SAKEMAB-C. Region 1. Philadelphia. Office of the Director MATTIA-J. Region 1. Philadelphia. Reactor Construct & Engineering Support Branch. B1/02/17. 4pp. 07976-210.
- DOCKET 50-451 SUMMIT INCLEAR POWER STATION. UNIT 2

  G. Adjudicatory correspondence
- B103250442 Eupplemental response stating no objection to terminated proceeding & withdrawal of application w/o prejudice Enclinspropt indicates no noncompliance or adverge environ effects from onsite work noted MARMAN. Hearing Branch 2 B1/03/24 ip 07996-207
- --8103250443 Forwards IE Insp Repts 99-450/01-01 & 50-451/01-01 on B10127 No honcompliance noted CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 81/02/25 2pp 07776 200
- --8103250448 16 Insp Repts 50-450/81-01 3 50-451/81-01 on 810127 Ac moncompliancenoted Major areas inspected site conditions resulting from work done per Luk Certificate of Svc encl NATROWL . SAKENAS C Region 1, Philadelphia, Uffice of the Officer MATTAW Region 1, Philadelphia, Reactor Construct & Engineering Support Branch 81/02/17 Apc 07996 210
- DECKET 50-452 GREENWOOD EMERGY CENTER, USIT 2

  A Application/construction steps documents & correspondence
- B103110225 Ack receipt of B10129 ltr re fission product release & summarizes ARC actions on problem ARC rept on state of technology of iodine release is due in Mar 1981. DIRKMBN J Office of the Executive Director for Operations 81/02/25 2pp 07885.183
- --BIODITORIO Expresses support for enc) Nuclear Safety Oversight Committee BOIR21 Itr to President Carterine research suggesting that indine products may not be released as freely as had been assumed in reactor safety studies MCCARTHY.W J Detroit Edison Co 01/01/27 Jpp 07883 185
- DOCKET 30-453 GREFNWJOD EHEROY CENTER, UHIT 3

  A Application/construction stage documents & correspondence
- B103110225 Ack receipt of 810129 ltr re fission product release & summarites NRC actions on problem NRC rept on state of technology of iodine release is due in Mar 1981.

  DIRCKS.K J Office of the Esecutive Director for Operations 81/02/25. 2pp 07805 183
- --8103110240 Expresses support for entl Nuclear Bafety Oversight Committee G01221 Its to President Casterine research suggesting that indine products may not be released as freely as had been assumed in reactor safety studies MCCARTH/.W.J. Detrait Edison Co. 01/01/29 3pp. 07885:185
- DOCKET 50-454 BYRON BTATION, UNIT 1
- A Application/construction stage documents & correspondence
- B103190732 Ltrs to all licensess of operating plants, applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re interin actions & request for addl info EISENHUT. D O Division of Licensing 80/12/22 30pp

## DOCKETED ITEMS

- 8103190397 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREC-0737 EISEN-UT.D. O Division of Licensing 81/01/19 App
- BIO3120014 Ltr to all litensees of operating plants, CP holders & u. applicants, except Indian Point 2 & 3,710n i 5 2 & TMI-1, forwarding inadvertently omitted pages from MRC 801222 request for add info re control of heavy loads EISEMUI, D 2 Division of Licensing 61/02/03 6pp
- 8103020397 Forwards 14 oversize drawings referenced in responses to FSAR Questions 040 78 % 040 82 Drawings will be transmitted in Amend 29 Aperture cards in PDR TRANSMIT R Corronjealth Edison Co 01/02/06 2pp 07779-014
- 8:03100714 Forwards organizational charts departing NRC Region 3 rearganization.effective 810216 KEPPLER J O Region 3. Chicago. Défice of the Director 81/02/20
- 6:03290024 Ltr to all power reactor licensees 2 license applicants re MAREJ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISEMHUT.D O Division of Licensing BI/02/20 Upp
- 9105230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except 5t Lucie. Units 1 t 2) Requests util review to determine capability to mitigate station blashout swent & promptly implement emergency procedures EISEC-MID 2 Division of Licensing 9/02/25 5pc
- 8)03230813 Generic Ltr 81-06 to all CP holders & OL applicants re 1006850 71(e). "Periodic Updating of FSARs." effective 803722 Info re FSAR legal status format & content encl 81808401.0 Q Division of Licensing 81/02/26 10pp
- 9103110409 Forwards corrected version of summary slide JN/07-12 used in util 810218 presentation in Bethesda-MD in seismic reanalysis of facilities Requests appropriate distribution TRASM T R Communicative Edison Co. 81/03/04 3pp. 07073-346
- 8103130720 Authorizes use of ASME Code Case N-272 & Code Case V-275 for Ltil const.per review of B10203 request NOW1021 (300.3 ) Literating Branch 1 B1/03/05 1p 07912 096
- BIO3190819 Forwards Region 3 assessment of OA/GC program effectiveness & status. Program found generally effective Rockford League of When Voters 601121 allegations & subsequent temediate action ltr deal w/actions of single contractor DIRCKS.W J. Office of the Executive Director for Operations 03/03/69 5pp 65131 102
- 8103310804 Ltr to all licensees of operating plants, applicants for GLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment
  81561-001.D O Division of Licensing 81/03/10 App
- 810320031 Forwards revised abstract & Pages 2-2,4-2.4-5,7-2 & 18-2 of CE-1-A.Revision 16 re GA program Revisions reflect ABME winter addends code changes, changes made per ABME survey & clarifications & corrections: IRAMN, T R Commonwealth Edison Co 81/03/16 1p
- --BI03200369 Revised abstract \$ Pages 2-2, 4-2, 4-5, 7-2 \$ 18-2 of Revision 16 to 3A program Corronwealth Edison Co. CE-1-A RIA 81/03/16 6pp
- B103250171 Forwards second set of Round 2 questions re OL application review.covering areas of review performed by GA Stanch.

  TERESCO.R L. Assistant Director for Licensing 81/03/16 2pp 0799: 078
- --8103250177 Becond Round 2 quantions re QA areas.

  4 Division of Licensing. 81/03/16 3pp 07996.080
- EI03260097 Forwards request for add1 info for review of application for Ocs-consisting of tenth set of Round 1 questions. IEDE800.R L. Assistant Director for Licensing. 61/03/23. 2pp.
- --8103260109 Tenth set of first round numetions covering Power Sus

- 8103260445 Summary of 810318 meeting w/util in Jethesda. MD to disc methodology for seignic analysis at foundation levels & evaluation of acceptability of designs of structural components Attendance list & meeting handouts and AULUCK.R. MOON.C. Licensing Branch 1 81/03/23 49pp 08039
- 8103310382 Requests addl info to PRC human factors control room de neview site visit Requests confirmation of 810620 date for preliminarly assessment submittal Statement to status of Byron 1 for each encl criterion required within 14 days FEDESCO.R L. Assistant Director for Licensing 81/03/26 App 03039-314
- E NRC Safety Evaluation Report (SEA), supply & correspondence
- 8103230869 Discusses C. hearing scheduling process SSR technical in achedule for Cy81 & Cy82 encl DENTOW.H R. Office of Nuclear Reactor Regulation. Director 61/03/13 5ps 07977.075
- F. Security, medical, emergency & fire protection plans
- 0101080051 Releases public version of usil draft emergency plan NUREG-0654 info encl FELTUN.J M Division of Rules and Records 80/12/02. 18pp
- --8101230943 Forwards public version of draft energency plan for generating stations
  PECPLES. D. Componwealth Edison Co. 80/04/24 3pp. 04837 1
- 8101080003 Releases public version of util draft emergency plan FELTON-J M Division of Rules and Records 80/12/03 ip
- --9101220299 Forwards public version of util revised draft energence W/station abnorces
  PEOPLES D L. Curronuseith Edison Co. 80/06/04 2pp. 05370.0
- --Biologoois Public version of Revision 1 to draft emergency plan
  \* Cornonwealth Edison Co. 80/07/31 139pp
- B103310330 Ltr to all licensees of operating plants & holders of CP forwarding NUREG-0696. Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRG requirements (N/O encil EISENHULD O. Division of Licensing B1/03/05. 6pp

### Q Adjudicatory correspondence

- G103180973 Forwards JD Deress affidavit in response to M Cherry petitions to suspend const of facilities MILLER, of I sham, Lincoln & Deale @ 81/02/13. 2pp 07993; 242
- --G103160377 Affidavit in response to M Cherry petitions to suspend of facilities & RB Hubbard 3 GC filmor affidavit alleging deficiencies in facilities const
  DERESS.J D. Commonwealth Edison Co 80/12/19 13pp 07953.2
- B103030659 Requests extension until B10323 to respond to util petit for reconsideration due to other pressing matters Counsel for util has no objection.

  CHERRY, M.M. Cherry, M.M./Cherry, Flynn & Manter B1/02/21, 2p. 07793, 111.
- 8103050627 Response supporting applicant 810214 petition for reconsideration of ASLB 801219 memorandum & order Ruling on admissibility of contentsions re unresolved generic safety issues should be reconsidered Certificate of 8vc 8nct.

  KARMAN.M Hearing Branch 2 81/03/03 7pp 07829:162.
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8)03030902 Forwards affidavit certifying svc of FSAR Amené 29 on 810205 TRAMM.T.R. Commonwealth Edison Co. 81/02/25, 2pp. 07808,244.
- B103310448 Amend 30 to FSAR revising Chapters 4 & 15 & Sections 1 3.1 6 & 6 2.1 5
  TRANKIT R Composite 1th Edison Co. 81/03/20 10 08075 243

- Q Inspection reports. 1E Bulletins & correspondence
- B103090771 Forwards IE Insp. Repts 50-454/80-24 & 50-455/80-22 on B01209-12 & hotice of violation FtGRELIty Region 3. Chicago, Reactor Construction & Engineering Support Branch B1/01/24 2pp 07849 215
- ~~8103090774 Notice of violation from insp on 801269~12 FIDRELL1,Q. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/22, ip 07849 217
- B103020115 Forwards 1E Circular B1-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required MEPPLER. J G Region 3. Chicago. Office of the Director 81/02/09 200
- 8103020668 Responds to IE Bulletin 80-23. 'Failures of Solenoid Valves Mfg by Velcor Engineering Corp " Eight suspect valves have been supplied Replacement of coils will be completed by 810416 RAUSCH, T J. Commonwealth Edison Co. 81/02/11 2pp. 97782-127
- 8103261017 Forwards IE Insp Repts 50-454/81-01 & 50-455/81-01 on 810106-07 No noncompliance noted FIDRELL's Region 3. Chicago, Reactor Construction & Engineering Rupport Branch 81/02/12 2pp. 08035 150
- --B109261026 IE insp Repts 90-454/B1-01 5-55/B1-01 on B10105-07 No noncompliance noted Major areas inspected const site tour & const completion schedule JONES C.E., WILLIAMS C.C. Region 3. Chicago. Office of the Director.
- 0103130075 Ack receipt of 010126 itr informing NRC of steps taken to correct violations noted in IE insp. Repts 00-454/80-04 & 50-453/80-04. Disagrees w/qualifications of GA manager of Gys Control Corp.
  FIDRELLI-G Region 3. Chicago, Reactor Construction & Engineering Support Branch 61/02/17 ip 07907 265
- --8103130089 Responds to NRC 801230 ltr re violations noted in IE Insp. Repts 50-454/80-04 \$ 50-455/80-04 Corrective actions. Identified & documented deviations from specified technical requirements in Bys Control Corp components. REED.C Commonwealth Edison Co. 81/01/26 App. 07907:266
- B103160695 Forwards IE Info Notice 81-04. 'Cracking in Main Steam Lines.' No response required KEPPLER, J C. Region 3, Chicago, Office of the Director 81/02/27 2pp. 07914-092
- B103160494 Forwards IE Circular B1-03, "Inoperable Beismic Monitoring Instrumentation" No response required KEPPLER, J. G. Region 3. Chicago, Office of the Director B1/03/02
- 8103160894 Forwards revised [E Bulletin B1-01, "Surveillance of Michanical Bnubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect built requirements

  MEPPLER. J G. Region 3. Chicago. Office of the Director 81/03/04
- 0103200394 Forwards IE Info Notice 01-05. "Failure of ITE Model K-600 Circuit Breater." No response required.

  KEPPLER.J. G. Region 3. Chicago, Office of the Director 81/03/11
  200
- '03200695 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades " No action required.

  KEPPLER, J. G. Region 3. Chicago. Office of the Director. 81/03/13
- O3200269 Forwards 1E Info Notice 81-07, 'Potential Problem W/Water-Soluble Purge Dam Matis Used During Inert Oas Welding." No response required KEPPLER. J. G. Region 3. Chicago. Office of the Director. 81/03/16 206.

- S Reportable occurrences. LERs & related correspondence
- 8103310360 PND-111-81-035 on 810323 electrician removed plywfrom turbine bldg floor & fell through opening approx 25 f systaining fatal injuries Electrician died enroute to loca base fEISLER, J. HAYES, D. HANDR R. Region 3. Chicago, Office of Director 81/03/24 is 08662-322
- U Congressional/Esecutive Correspondence
- 8103270110 Responds to request for rept on possible add1 imp to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process HEXDELECT M Completioners 81/03/12 Map
- ---8103270947 Submits recommendations re-scheduling personnel hearing mot for OL proceedings Panel must obtain exempts from hiring freeze for two recently appointed chairmen COTTER.8 P Atomic Safety and Licensing Board Panel 8 33oo
- DECKET 50-455 SYRON STATION UNIT 2
- A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applica OLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NoREO-0612 Forwards NRC position interim actions & request for addl into EISECHIJT, D.9 Division of Licensing 80/12/22 30pp
- 8)03)90307 Ltr to all licensees of operating plants & opplic OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.ceptacerent parts & NURCG-0737 EISEN-UT.D Q Division of Licensing 81/01/19 App
- 810312C014 Ltr to all licensees of operating plants-CP holde applicants, escept Indian Point 7 & 3, 2 ton 1 & 2 & TMT-1. Forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D 3 Division of Licensing 81/02/03 App
- B103020357 Forwards 14 oversize drawings referenced in responses f8A9 Questions 040 78 \$ 040 82 Drawings will be transmitted in Amend 29 Aperture cards in PDR
  TRAINLY R Commonwealth Edison Co 81/02/06 2pp 0777
- B103j00214 Forwards organizational charts Sepiciting NRC Reginary and ration effective B10216 KEPPLER, J. Q. Region 3. Chicago, Office of the Director 200.
- 8103290024 Ltr to all power reactor licensees & license appl MUREG-0619 critoria Footnote 2 in Table 2 contains error of to leakage testing deletions Licensee may submit analysis justify use of existing low flow controller EISENHUT.D 9 Division of Licensing 81/02/20 Rpp
- 8103230030 Ltr to all licenses of operating nuclear power papelicants for Dis (except St Lucis, Units 1 & 2) Requests util review to determine capability to mitigate station blactout event & promptly implement emergency procedures EISENHUT, D 0 Division of Licensing 81/02/25 Spp
- 8103230813 Oeneric Ltr 81-06 to all CP holders & DL applican 10CFR5D.71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status fornat & content encl ETBEZHOT.D O. Division of Licensing 81/02/26 10pp
- 8103110409 Forwards corrected version of summary slide JW/07 util 810218 presentation in Bethesdak MD on seismic reanalysis of fecilities Requests appropriate distribution TRAMK. T. R. Commonwealth Edison Co 81/03/04 3pp 0/87
- B103130720 Authorizes use of ASME Code Case N-272 & Code Case util constiper review of B10203 request YQUN03LQQO.B.J Licensing Branch 1 81/03/05 ip 0791
- BiO3190B19 Forwards Region 3 assessment of GA/GC program eff & status.Program found generally effective.Rockford League of Homen Voters BO1121 allegations & subsequent immediate action lit deal w/actions of single contractor. DIRCKS.M.J. Office of the Executive Director for Operatio BI/O3/09 5pp. 65131:102

MILLER, M 1 Ishem, Lincoln & Beale 81/02/13 200 07953 242.

8103200351 Forwards revised abstract & Pages 2-2,4-3,4-3,7-2 & 18-2 of CE-1-A.Revision 16 re GA program Revisions reflect ASME winter addenda code changes changes made per ASME survey & classes at cont & corrections Commonwealth Edison Co 81/03/16 in TOAYM T H

- --8103200359 Revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of Revision 16 to GA Crossan Commonwealth Edison Co - CE-1-A RIA - 81/03/16
- RIDTS NITE Forwards second set of Round 2 questions re OL aselication review.covering areas of review performed by GA

TERRETOR Assistant Director for Licensing 81/03/16. 200 07996 078

- --8103250177 Second Round 2 questions re GA areas # Division of Licensing 81/03/16 3pp 07996 080
- 8103240097 Forwards request for addl info for review of application for OLs. consisting of lenth set of Round 1 questions.

  TENERGO, R. C. Assistant Director for Licensing 81/03/23. 2nd
- --8103250109 Tenth set of first round questions covering Power Sys Branch area of review \* Assistant Director for Licensing 81/03/23 6pp
- 8103263445 Summary of B10218 meeting u/util in Bethesda.MD to discuss rethodology for seismic analysis at foundation levels & evaluation of acceptability of designs of structural carparents Attendance list & meeting handouts encl M.U.C.A.R. MCC\*U.C. Licensing Branch 1 81/03/23 49pp 08039 337
- 6103310382 Requests addl info re NRC human factors control room design pussiusae nequests avoi into to MHC Duram factors control M review site visit Requests confirmation of 810620 date for prejiminary assessment submittal Statement me status of Buron I for each encl criterion required within 14 days TEDESID R L. Assistent Director for Licensing 81/03/26 4pp 08259 314
- E NGC Bafety Evaluation Report (SER), supple & correspondence
- 8103230857 Discusses GL hearing scheduling process BER technical input schedule for CYBI & CYB2 enci DENTON-II R Office of Nuclear Reactor Regulation. Directur BI/03/I3 Spp
- F Security, medical, emergency & fire protection plans
- Bi010B0051 Releases public version of util draft emergency plan MUREG-0694 info encl FELTON, J. M. Division of Rules and Records 80/12/02 18pp
- --Bij(230543 Forwards public version of draft emergency plan for generating stations
  - PECSIES, D. L. Commonwealth Edison Co. 80/04/24 3pp. 04837:169
- --BiDICS0068 Public version of draft prergency plan for generating stations
- Commonwealth Edison Co 80/07/31 150pp
- 6101060003 Releases public version of util draft emergency plan Division of Rules and Records 80/12/03. FELTON, J. M.
- --8101220258 Forwards public version of util revised draft emergency plan w/station anneres PECPLES, D.L. Componissaith Edison Co. 80/05/04 2pp. 05370 003
- --BioloBooi9 Public version of Revision 1 to draft emergency plan.

  # Commonwealth Edison Ca 80/07/31 13900
- BIO3310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o enc! EIGENHUT.D Q Division of Licensing 81/03/05 6pp

- --8103180577 Afficavit in response to M Cherry petitions to suspend com of facilities & AS Hobbard & QC Minor affidavit alleging
  - of fectivities is no nobbers of the street o DERESS. L D
  - H103030697 Requests extension until 810323 to respond to util petition for reconsideration due to other pressing matters Counsel CHERRY.K M. Cherry. M. M. /Cherry. Flynn & Kantor 81/02/21 2pp 07707 111
  - 810:3050627 Response supporting applicant 810214 petition for reconsideration of ASLB 801219 memorandum 5 order Ruling on admissibility of contentions re unresolved generic safety issues thould be reconsidered Certificate of Svc encl KARMAN, M. Hearing Branch 2 81/03/03 7:0 07829 162
  - K Utility Final Bafety Analysis Report (FSAR) & amends
  - 8103030702 Forwards affidavit contiduing syc of FBAR Amend 27 on 81.0204 TRANN. T.R. Composite Edison Co. 81/02/25 2nd 07808:244
  - 8103310448 Amend 30 to FSAR revising Chapters 4 5 to & Sections 1 3.1 4 6 6 2 1 5
    TRAMM. T R Commonwealth Edison Co. 81/03/20 1p. 08075 243
  - --8103310467 Atens 30 to FSAR Commonwealth Edison Co 81/03/31 761pp 08075:244
  - G. Inspection reports. IE Bulletins & correspondence
  - 8103090771 Forwards IE Insp Repts 50-454/80-24 & 50-455/80-22 on BO1209-12 & natice of violation FIGRELLIA Region 3. Chicago, Reactor Construction & Engineering Support Branch BI/01/26 2pp 07849-215.
  - --B103090774 Notice of violation from ines on B31209-12 FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Bupport Branch Bi/Ol/22 ip 07849-217
  - --BIOJOTO780 IE Insp Repts 30-459/BO-24 & 50-455/BO-22 on B31209-12 Moncompliance noted failure of BC to stop equipment installation ponding proper alignment of anchor boits & mounting holes in equipment stide
    JONES.C.E. WILLIAMS.C.C. Region J. Chicago. Office of the
    Director. 81/01/09 4pp 07849 218.
  - 8103020115 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. REPPLER. J. O Region 3. Chicago, Office of the Director 81/02/09. 200
  - 8103020868 Responds to IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp " Eight suspect valves have been supplied Replacement of coils will be completed by F10416 RAUSCH, T. J. Commonwealth Edison Co. 81/02/11 2pp 07782.129.
  - 8103261017 Forwards JE Insp Repts 50-454/81-01 & 50-455/81-01 on #10106-07 No nancompliance noted:
    #100ELLI.O. Region 3. Chicago: Reactor Construction & Engineering Support Branch, 81/02/12 2pp. 08039 153
  - --8103261026 IE Insp Repts 50-454/81-01 & 50-455/81-01 on 810106-07. No noncompliance noted Major areas inspected const site tour & const completion schedule.

    JONES C E - WILLIAMS C C Region 3, Chicago, Office of the Director. 81/02/10. 3pp. 08039 155
  - BIOD:130075 Ack receipt of BIO126 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-494/80-04 & 50-455/80-04 Disagrees w/qualifications of GA manager of Bys Control Corp FIGRELLI.O. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 81/02/17 1p. 07907.265
  - --B1031300B9 Responds to NRC 801230 ltr re violations noted in IE Insp Repts 30-454/80-04 & 50-455/80-04 Corrective actions. identified & documented deviations from specified technical requirements in Bys Control Corp components
    REED.C Componwealth Edison Co. B1/01/26 App. 07907.266.

- 8103160495 Forwards 1E Info Notice 81-04. Cracking in Main Steam Lines " No response required KEPPLER, J G Region 3. Chicago, Office of the Director 81/02/27 200
- 8103160494 Forwards 1E Circular 81-03. Inoperable Seismic Monitoring Instrumentation : No response required KEPPLER. J G Region 3. Chicago. Office of the Director 81/03/02
- 8103160894 Forwards revised 1E Bulletin 81-01, "Surveillance of Machanical Snubbers. "D/corrected Payes 9.5 6 Charge in identification of facilities D/CPs to which bulletin is applicable does not affect util requirements REPPLEA. J G Region 3. Chicago. Office of the Director 81/03/04 10.
- 8103200394 Forwards IE Info Notice 81-06. 'Failure of ITE Mudel K-600 Circuit Breaker.' No response required
  REPPLER, J Q Region 3, Chicago, Office of the Director - 81/03/11
- 8103200695 Forwards IE Info Notice 81-05, "Degraded DC Sys at OSKUDOTO FORMERS IN THIS HOLLE OF CO. OSG. CO. O Pos.
- 8103200269 Forwards IE Info Notice 81-07. 'Potential Problem MUMAter-Boluble Purge Dam Matls Used During Inert Gas
  Welding "No response required
  KEPPLER.J G. Region 3. Chicago. Diffice of the Director 81/03/16
- U Congressional/Executive Correspondence
- 8103270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
  HENDRIE, J.M. Commissioners 81/03/12. Spp
- --B103270947 Submits recommendations re-scheduling.personnel resources & hearing mgt for GL proceedings Panel must obtain elemption from hiring freeze for two recently appointed chairmen. COTTERNS P. Atomic Safety and Licensing Board Panel 81/02/25 3300.
- DOCKET 90-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensums of operating plants, applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-Obliz Forwards NRC position re interim actions & request for addl info 80/12/22 30pc
- 8103190387 Ltr to all licensess of operating plants & applicants for Cts & holders of Cts to grapma for sourien qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREC-0737 RISENHUT, D.O. Division of Licensing 81/01/19. App.
- 8103120014 Ltr to all licensees of operating plents.CP holders & GL applicants.except indian Point 2 & 3.Zion 1 & 2 & FMI-1. forwarding inequentently omitted pages from NRC 801222 request for add Info re control of heavy loads.

  EISENHUT.D.Q Division of Licensing 81/02/03. 6pp
- 8103020337 Forwards 14 oversize drawings referenced in responses to FBAR Questions 040.78 & 040.82. Drawings will be transmitted in Amend 29. Aperture cards in PDR.
  TRANKS.T.R. Commonwealth Edison Co. 81/02/06 2pp 07779:014.
- 103100214 Forwards organizational charts depicting NRC Region 3 reorganization effective B10216. KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 81/02/20. 200
- BIO3250024 Ltr to all power reactor licensees & license applicants re NURED-0619 criteria. Footnote 2 in Table 2 contains error due to laskage testing deletions. Licensee hay subsit analysis to justify use of existing low flow controller. EIEENHUT, D. O. Division of Licensing. 81/02/20. 8pp.

- 8103230030 Ltr to all licensees of operating nu applicants for OLs Kercept St Lucie. Units ( & blackout event & promptly implement emergency
  EISENHUT. D 0 Division of Licensing 81/02/
- 8103230813 Generic Ltr 81-05 to all CP holders 1QCFR50 71(e). "Periodic Updating of FSARs." 810722 Info re FSAR legal status format & com EISENHJT.D G Division of Licensing 81/02/
- 8103110409 Forwards corrected version of summar util 810218 presentation in Bethesda, MD on se reanalysis of facilities Requests appropriate TRAMM. T.R. Commonwealth Edison Co. 81/03/04
- 8103130720 Authorizes use of ASME Code Case N=2 util const.per review of 810203 request YOUN03LQDD.B J Licensing Branch 1 B1/03/0
- B103310B04 Lin to all licenses of operating pl & holders of CPs forwarding SECY-B1-119 re in establish environ qualification of safety-rel .igu[prent EISENHULD Q Division of Licensing 81/03/
- BIO3200351 Forwards revised abstract & Pages 2-CE-1-A.Revision 16 re DA program Revisions re winter addenda code changes thanges rade per clarifications & corrections TRAMS T R Commonwealth Edison Co 81/03/16
- --B103200369 Revised abstract & Pages 2-2-4-2-4 16 to GA program

  \* Corromealth Edison Co CE-1-A R16 81
- 8103250171 Forwards second set of Round 2 quest application review, covering areas of review p Beanch TEDEGCO.R. L. Assistant Director for Licensin 07996 078
- --8103250177 Second Round 2 questions re GA are:
  \* Division of Licensing 81/03/16 3pp
- 8100260997 Forwards request for addl info for ri DLs.consisting of tenth set of Round I questi TEDE800.R.L. Assistant Director for Licensin
- ---B103260109 Tenth set of first round questions
  Branch area of review
  - Assistant Director for Licensing 81/03
- BiO3250445 Summary of SiO318 meeting w/util in the methodology for seismic analysis at foundation evaluation of acceptability of designs of structure components Attendance list & meeting handouts AULUCK, R. MOON, C. Licensing Branch 1. 81/03
- 8103310382 Requests addl info to NRC human facts raview site visit Requests confirmation of Gi preliminary assessment submittal. Statement re Byron 1 for each encl criterion required with TEDESCO, R L Assistant Director for Licensin 08059 314
- E NRC Bafety Evaluation Report (BER), supple &
- 8)03230869 Discusses OL hearing scheduling proc schedule for CYB1 & CYB2 encl DENTON-H R. Office of Nuclear Reactor Regula 81703713. Spp.
- F. Security, medical, emergency & fire protection
- 8101080051 Releases public version of util draft NUREG-0654 info encl. FELTON: J M. Division of Rules and Records. I
- -- 8101230543 Forwards public version of draft en generating stations.
  PEOPLES D. L. Commonwealth Edison Co. 80/04
- --8101080068 Public version of draft emergency |
  - # Commonwealth Edison Co. 80/07/31. 150p

OCCOCCO Releases public version of util draft emergency plan

9101220258 Forwards public version of util revised draft emergency plan U/station annexes
PEOPLES D.C. Commonwealth Edison Co. 80/06/04 2pc 05370 005

3501080019 Public version of Revision I to draft emergency plan • Componwealth Edison Co = 80/07/31 = 139pp

03310333 Lir to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency leasonse Facilities " Criteria describe acceptable method for meeting NPC requirements W/o encl EISENHUT, D.O. Division of Licensing 81/03/05 App.

# General correspondence

031602234 Forwards results of radioactivity analyses of well water near facility on 800827.in response to concern voiced at unbic neeting re decontamination program (EPPLER, J. O. Region 3. Chicago, Office of the Director 81/03/10

3:0 07920 003

Utility Final Safety Analysis Report (FSAR) & amends

33030902 Forwards affidavit certifuing svc of FSAR Amend 29 on 310204 TRAYM.T 8 Cormonwealth Edison Co 81/02/25 250 07808 244

)3310448 Amend 30 to FSAR revising Chapters 4 & 15 & Sections | 3.1.6 % 6 2 | 5 | BAMM: 1 R | Componweelth Edison Co | 81/03/20 | 10 | 08075 243

3103310467 Amend 30 to FBAR • Commonwealth Edison Co 81/03/31 761np 08075 244

# Inspection reports: 1E Bulletins & currespondence

03180132 Forwards IE Insp Repts 50-456/81-01 & 50-457/81-01 an 310515-16 % 21 No noncompliance noted F16RELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Brench 81/02/05 2pp 07943 188

9103180140 IE Insp Repts 50-456/81-01 & 50-457/81-01 on 810115-16 & 21 No noncompliance noted Major areas inspected previous insp findings & movement of steam generator from outside to inside containment
SCHWEIBINZ, E., WILLIAMB, C. C. Region 3. Chicago, Office of the
Director 81/02/04 Spp. 07943 190

03020113 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Outy " No written response required KEPPLER J.O. Region 3. Chicago: Office of the Director 81/02/09

03230156 Forwards IE Insp Repts 50-456/81-02 & 50-457/81-02 on BIO127-28 No noncompliance noted. FIDRELLI.G Region 3. Chicago, Reactor Construction & Engineering Sypport Branch BI/02/10 2pp 07977 IBA

8103230162 IE Inep Repts 50-496/81-02 & 50-457/81-02 on 810127-28.No 103220102 IE Insp Repts 30-436/102 & 30-436/101-02 on BIO127-28 No noncompliance noted Major areas inspected dissel generator instellation & records raceway support celding & records & 5 tV switchgest installation & records.

NIESLER J H . LEER L . WILLIAMS C C Region 3, Chirago, Office of the Director. 81/02/09 4pp 07977 188.

03020668 Responds to 1E Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Eight suspect valves have been supplied Replacement of coils will be completed by

RAUSCH, T. J. Commonwealth Edison Co. 81/02/11, 2pp. 07782:129.

03160695 Forwards IE Info Notice 81-04. "Cracking in Main Steam

Lines." No response required MEPPLER, J. C. Region 3. Chicago, Office of the Director. 81/02/27.

03160494 Forwards IE Circular B1-03, "Inoperable Seismic Monitoring Instrumentation " No response required. REPPLER, J. G. Region 3, Chicago, Office of the Director 81/03/02

- 8103160894 Forwards revised IE Guiletin 91-01, "Surveillance of Mechanical Bhubbers," w/corrected Pages 3 & & Change in identification of facilities w/CPs to which bullotin is applicable does not affect util requirements MEPPLER, J G Region 3. Chicago, Dffice of the Director B1/03/04.
- 8103200394 Forwards IE. Info Notice Bi-Ob. "Failure of ITE Model K-600 Circuit Breaker" No response required KEPPLER.J G. Region 3. Chicago. Office of the Director. 81/03/11.
- 8103200695 Forwards [E Info Notice 81-03, 'Degraded DC Sys at Palisades 'No action required KEPPLEN.J & Region 3. Chicago, Office of the Director 81/03/13
- B103200269 Forwards [E Info Notice 81-07. "Potential Problem WiMater-Boluble Purge Dam Matts Used During Inert Gas Helding " No response required KEPPLER. J. G. Region 3. Chicago, Office of the Director 81/03/16 200

DOCKET SO-457 BRAIDWOOD STATION, UNIT 2 A Application/construction stage documents & correspondence

- 8103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-0612 Forwards NRC position re
  - interim actions & request for addl info
    EIBENHUI.D 9. Division of Licensino 80/12/22 3000
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown, replacement parts & NUREO-0737. EIBENHUT, D. O. Division of Licensing 81/01/19. Opp
- 8103120014 Ltr to all licensees of operating plants CP holders & OL applicants, except indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertently onitted pages from LRC B01222 request for addl info re control of heavy loads EIBENHUT.0 0. Division of Licensing. B1/02/03 6pp
- 8103020357 Forwards 14 oversize drawings referenced in responses to FBAR Questions 040 78 & 040 82. Brawings will be transmitted in Amend 29 Aperture cards in PDR TRAMM.TR. Commonwealth Edison Co. 81/02/06 2pp
- 8103100214 Forwards organisational charts depicting NRC Region 3 reorganisation, effective 010216 \*\*EPPLER.J Q Region 3. Chicago, Office of the Director 81/02/20 2pp
- 8103230024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISERHUI.D 9. Division of Licensing. 81/02/20 Spp
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 8t Lucie,Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EIGENHUT.D Q. Division of Licensing 81/02/25 5pp.
- 8103230Bi3 Generic Ltr 81-06 to all CP holders & UL applicants re 10GFR80 71(e), "Periodic Updating of FBARs," effective 800722 info re FBAR legal status.format & content encl. EISENHUT.D.O. Division of Licensing 81/02/26
- 8103110409 Forwards corrected version of summary slide UH/07-12 used in util 810218 presentation in Bethesda. HO on selenic reanalysis of facilities Requests appropriate distribution. TRAMM.T.R. Commonwealth Edison Co. 81/03/04. 3pp.
- B103130720 Authorites use of ASME Code Case N-272 & Code Case N-295 for util const.per review of 810203 request YOUNDELOOD, B. J. Licensing Branch L. 81/03/05 1p
- 8103310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical EIBENHIJT, D. Q. Division of Licensing. 81/03/10 6pp.

- Bi03200351 Forwards revised abstract & Pages 2-2.4-2.4-5.7-2 & 18-2 of CE-1-A.Revision 16 me GA program. Revisions reflect ASHE winter addends rode changes changes made per ASME survey & clarifications & corrections TRAHM, T.R. Commonwealth Edison Co. 81/03/16 1p
- 8103250171 Forwards second set of Round 2 questions re OL application review.covering areas of review performed by OA Branch TEDESCO.R L Assistant Director for Licensing 81/03/16 2pp
- --B103250177 Second Round 2 questions to GA areas.

  a Division of Licensing 81/03/16 3pp
- B103260097 Forwards request for add1 info for review of application for OLs. consisting of tenth set of Round 1 questions
  TEDESCO.R L Assistant Director for Licensing. B1/03/23 2pp
- --8103260109 Tenth set of first round questions covering Power Sys Branch area of review • Assistant Director for Licensing 81/03/23 6pp
- B103260445 Summary of B10218 meeting u/util in Bethesda.MD to discuss methodology for seismic analysis at foundation levels & evaluation of acceptability of designs of structural components Attendance list & meeting handouts encl AULUGK.R Licensing Branch 1. 81/03/23 49pp.
- 8103310382 Requests additinfoire NRC human factors control room design review sits visit Requests confirmation of 810620 date for preliginary assessment submittal bistement rejistatus of Byron i for each enclicriterion required uithin 14 days TEDESCO.R L. Assistant Director for Licensing 81/03/26 4pp
- E. NRC Bafety Evaluation Report (BER), supple & correspondence
- B103230869 Discusses OL hearing scheduling process SER technical input schedule for CVBI & CV82 encl DENTON.H.R. Office of Nuclear Reactor Regulation. Director. B1703/13 Spp
- F Security, medical, emergency & fire protection plans
- B1010B0051 Releases public version of util draft emergency plan NUREQ-0656 info encl FELTON.J.M. Division of Rules and Records B0/12/02 18pp.
- --BI01230543 Forwards public version of draft emergency plan for generating stations PROPLES D. Commonwealth Edison Co. 80/04/24 3pp. 04837-169
- -- 9101080068 Public version of draft energency plan for generating stations
   Componently Edison Co. 80/02/31 150cc
- 8101080003 Releases public version of util traft emergency plan FELTON.J M Division of Rules and Records. 80/12/03 ip
- --8101220258 Forwards public version of util revised draft emergency plan w/station annexes.

  PEOPLES.D.L. Commonwealth Edison Co. 80/06/04 ⊋2s. 05370:005
- --8101080019 Public version of Revision 1 to draft emergency plan
  Commonwealth Edison Co 80/07/31. 139pp.
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NURGO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for aseting NRC requirements. W/O enci EISENHUT.D. 9 Division of Licensing. 81/03/05. 6pp
- H General correspondence
- 8103160234 Forwards results of radioactivity analyses of well water near facility on 800827, in response to tontern voiced at public meeting re decontamination program KEPPLER.J.O. Region 3. Chicago. Office of the Director. 81/03/10. 3pp 07920-003.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- BIGG030902 Forwards affidavit certifying svc of FBAR Amend 29 on 810206.
  TRAHM.T.R. Gommonweelth Edison Co. Bi/02/25 2pp.

- B103310448 Amend 30 to FSAR revising Chapters 4 & 15 % Sections 1 3.1 6 & 6 2 1 5 re fuel asterolly design TRAMS.T R Corronvellth Edison Co. 81/03/20 lp
- O Inspection reports. IE Bulletins & correspondence
- B1031B3132 Forwards IE Insp. Repts 50-456/81-01 & 50-457/81-01 on 810115-16 & 21 No moncompliance noted filmELLI, G. Region 3. Chicago, Reactor Construction & Engines Support Branch 81/02/05 2pp 07943 189
- --Biggle0140 IE Insp Repts 50-456/Bi-01 % 50-457/Bi-01 on Biggle0115 No noncompliance noted Major areas inspected previous insp findings & movement of steam generator from outside to inside containment SCHWEIBINZE: WILLIAMS.C C Region 3. Chicago. Office of t Director Bigcotor 500/204
- 8103020115 Forwards IE. Circular 81-02, 'Performance of NRC-Licen Individuals While on Duty 'No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 81/0 20p
- 8103230156 Forwards IE Insp Repts 50-496/81-02 % 50-457/81-02 on 810127-28 No noncompliance noted FIDRELLI, O Region 3. Chicago. Reactor Construction & Engines Support Branch 81/02/10 2pp. 07977 186
- --8103230162 IE Insp Repts 50-456/81-02 & 50-457/81-02 on 810127 noncompliance noted Hajor areas inspected diesel generator installation & records apport welding & records & 5 VV suitchgear installation & records NIESLER.J H., LEER.L WILLIAMS.C C. Region 3, Chicago. Of the Director 81/02/09 App 07977 188
- 8103020668 Responds to IE Sulletin 80-23. "Failures of Bolenoid Mfg by Valcor Engineering Corp " Eight suspect valves have been supplied Replacement of coils will be completed by 810416.
  RAUSCH.T. J. Commonwealth Edison Co. 81/02/11 2pp
- 8103160695 Forwards 1E Info Notice 81-04. 'Cracking in Main Stea Lines.' No response required. KEPPLER.J G. Region 3. Chicago, Office of the Director 91/0 200
- 0103160494 Forwards 1E Circular 81-03. "Inoperable Beismic Monit Instrumentation" No response required KEPPLER. J. G. Region 3. Chicago. Office of the Director B1/0 202
- B103160894 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Snubbers:" w/corrected Pages 5 & & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  KEPPLER J Q Region 3. Chicago. Office of the Director 81/0
- 8103200394 Forwards IE Info Notice 81-06. "Failure of ITE Model Circuit Breaker" No response required KEPPLER. J. O. Region 3. Chicago, Office of the Director 81/0 266.
- B103200695 Forwards 1E Info Notice 81-05. 'Degraded DC Sys at Palisades' No action required KEPPLER.J. Q. Region 3. Chicago, Office of the Director 81/0 200.
- B103200269 Forwards 1E Info Notice 81-07, "Potential Problem W/Mater-Boluble Purge Dam Matis Used During Inert Cas Helding." No response required KEPPLER, J. O Region 3, Chicago, Diffice of the Director 81/0 Zap.
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREQ-Obiz Forwards NRC position reinterim actions & request for addi info

- gic31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Ltems addressed involve cold shutdown replacement parts & NUAEC-0737 stepHulJ.D Q Division of Licensing 81/01/19 Ann
- BiO3120014 Ltr to all licensees of operating plants.CP holders to applicants, except indian Point 2 to 3.7ion 1 to 2 to TMI-1, forwarding imadvectably unitted pages from NRC B01222 request for addlinfore control of keavy loads pisch-UTL,D 2 Division of Licensing B1/02/03 app
- 6103050103 Forwards revised NRC Region 4 organization chart effective 810227
  SEYRRITIN V Region 4. Dalles. Office of the Director 81/02/18
  2-6 707827 069
- GIO3160669 Ltr to all operating plants t CP holders forwarding clarification of IMI Action Plan Item III A I 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be net EISEIBMUT.D 0 Division of Licensing BI/02/10 1200
- 8103250024 Lir to all power reactor licensees 5 license applicants re MA60-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subnit analysis to justify use of eristing low flow controller erspentation D Q Division of Licenseing 81/02/20 8pp
- 6:00170225 Ltr to all SWR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 t 2 pressure boundary picing safe ends & fitting nati per guidelines of encl Revision i to NUREG-0313 Model Tech Boots only encl EISEMBUT.D G Division of Licensing 81/02/26 3pp
- --81031702&& Model fech Specs flages 3/4 0~2,3/4 0~3,3/4 4~7 % 3/4 4~8 re surveillance requirements for ABME Code Class 1.2 % 3 components % RCG operational leakage limiting conditions for operation & surveillance requirements • Omeral Electric Co 81/02/26 App
- 8103170655 Ltr to holders of CPs & applicants for QLs (BMRs) requesting review of ABME Class 1.2 & 3 pressure boundary piping safe ends & fitting mail per guidelines of encl Revision 1 to MARGO-0313 Hodel fach Specs only encl EISERBUT, D Q Division of Licensing 01/02/26 3pp.
- 8103233813 Opnorise Ltr 81-06 to all CP holders & CL applicants re 196835 71(e). "Periodic Updating of FRANts." effective 830722 Info ro FRANt legal status format & content encl EISENIUT.D O Division of Licensing 81/02/24 10pp
- 8103110303 Forwards for review & approval RMECO Biol. "Models Used in COCTVS Computer Code to Determine Pressure & Temp Response of Vapor Buppression Containments Following LOCA."

  6RADBURY, R B Stone & Webster Engineering Corp 81/03/06 2pp 07883 001
- 8103200089 Informs that staff functions of Region 4 reassigned, effective B10227 OL Hadsen. Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondence re reactor const & operation activities. SEFFRIT. W Region 4. Dallas. Office of the Director. B1/03/09 ip 07868 218
- 8103310804 Ltr to all licensees of operating plants, applicants for OLs 8 holders of CPs forwarding BECY-B1-119 vs info necessary to establish environ qualification of safety-related electrical equipment.
  ETBERRAUT. D. O. Division of Licensing 81/03/10 6pp
- 8103260043 Summary of Caseload Forecast Panel 810303-05 meeting & site visit w/utils & 95W in 8t Francisville.LA re-scheduling of const & observing const activities in progress Attendance list.meeting agenda.handouts & visual alds encl MO30.0. Licensing Branch 3. 81/03/12 50pp
- Bi03230135 Responds to Bi0223 itr Visit to facilities to review const progress & completion estimates cancelled because of budget cuts. DENTONIE.R. Diffice of Nuclear Reactor Regulation. Director Bi/03/i6. 4pp 07974 335
- --8103220142 Expresses disappointment that D Hood, project manager, unable to make expected inspivisit to plant due to budget cuts.

  Urges that decision be reversed.

  GUSTE, N. J. Louisiana, State of 81/02/23 1p. 07974.339

- 8103230881 Notifies that detailed analysis of preliminary const completion schedule estimates Unit 1 completion about Oct 1785 Analysis results to be forwarded within one wit IEDESCO.R L. Assistant Director for Licensing 81/03/17 200
- 8103260110 Forwards list of generic lins & bulletins issued to power reactor licensees & applicants in 1980
  TEDESCOR R L Assistant Director for Licensing 81/03/18 27pp
- F. Security, medical, emergency & fire protection plans
- BiO3310338 Ltr to all licensees of operating plants & holders of CPs forwarding hUREG-0696. Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. W/o encl EISKMHUT, D Q Division of Licensing Bi/03/05 opp
- 9 Inspection reports. IE Bulletins & correspondence
- B103230945 Forwards Suppl 4 to IE Bulletin 89-17. "Failure of Control Adds to Insert During Scran at BMR." No written response required SEYFRIT. K V Region 4. Dallas. Diffice of the Director. 80/12/18 16 07978 035
- B103230212 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No Malcom valve yokes in use Final rept will be subsitted by B10310 DRAPER.E. L. Oulf States Utilities Co. B1/01/06 by 07977-051
- 8103170226 Forwards IE Insp Rept 50-458/80-14 on 801215-17 & notice of violation BROWN, O D Region 4. Dallas. Fuel Facility & Materials Safety Branch 81/01/15 2pp 07925 245
- --8103170235 Notice of violation from insp on 801215-17 BROWN.9 D Region 4. Dallas. Fuel Facility & Materials Bafety Granch 81/01/14 ip 07925 267
- --BIO3170242 IE Insp Rept 50-458/BO-14 on BO1215-17 Noncompliance noted: concreté spoil deposit area selected such that weshwater w/pH of approx 12 was overflowing into Mest Creek WILBORN.L.. SPITZBERG.D B Region 4. Dallas, Office of the Director BRON.O D Region 4. Dallas, Fuel Facility & Materials Gafety Branch 81/01/14 &pp 07925 268
- 8103230223 Responds to 1E Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No Valcor valves w/cited part numbers are in use BRAPER, E. L. Gulf States Utilities Co. 81/01/23 lp. 07976-351
- 8103260516 Forwards JE Insp Rept 80-488/80-13 on 801101-1231 & natice of violation SEIDLE-M C Region 4, Dallas. Reactor Construction & Engineering Support Branch 81/02/06. 2pp 08041 036
- --BiO3260524 Notice of violation from insp on B01101-1231 GEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Bugport Branch 81/02/06 2pp. 08041 038
- --BI03260535 IE Insp Rept 50-458/80-13 on 801101-1231 Noncompliance noted failure to follow procedures to maintain uniform consistency of concrete at point of placement. BEACHA B . CROBSMAN M . Repion 4. Dallas, Office of the Director 81/02/06. 16pp 08041 040
- B103100728 Forwards Suppl 5 to 1E Sulletin 80-17. "Failure of Control Rods to Insert During Scram at BUR " No written response required SEYFRIT.K.V Region 4. Dailas. Office of the Director. B1/02/13 ip 07866-322
- 8103170015 Forwards IE Circular 81-03, "Inoperable Saismic Monitoring Instrumentation " No response required. 8EYFRIT.K.V Region 4. Dallas, Office of the Director. 81/03/02. 1p. 07939-110.
- BiO3250429 Ack receipt of BiO209 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-458/80-14. Response must be resubmitted under oath or affirmation. BROUNN & D. Region 4. Dallas. Office of the Director. Bi/O3/02. ip. 07996-352

- --BIO3250427 Responds to ARC BIO115 ltr re violations noted in IE linsurage 50-458,80-14 Corrective actions weste concrete spoil area resloyed b rebenned b, BIO107 to prevent untreated upter from overflouing into adjacent crees.

  PRAPER EL CUIF States Utilities CO BI/O2/09 4pp 07996 353
- B103160837 Forwards revised IE Bulletin B1-01. Surveillance of Mechanical Shubbers. O/corrected Pages 5 & 6 Change in identification of facilities O/CPs to build bulletin is applicable does not affect util requirements SEYRRIT.R V Region 4. Dailas. Office of the Director B1/03/04 ip 07914 195
- 8103230178 Forwards IE Info Notice 81-07. "Potential Problem W/Weter-Soluble Purge Dam Matle Used During Inert Gas Welding " No response required SEYFRIT.X V Region 4. Dallas. Office of the Director 81/03/16 12 07977 217
- 8103260223 Ack receipt of 810209 ltr 5 810396 affidavit informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/60-14 BRCWN-9 D Region 4. Dallas. Office of the Director 81/03/18 lp. 68041 350
- S. Reportable occurrences. LERs & related correspondence
- BIO3180369 Interim deficiency rept re overturning of primary containment shield wall initially reported on BIO126
  Nonconformence rept has been initiated to address damage to shield wall Nest rept will be forwarded uithin 60 days
  DRAPER.E.L. Ouif States Utilities Co. BI/02/24 Jpp. 07953 240
- Bi03109395 PN8-IV-Bi-003 on Bi0302-03 security guard for B&W received telephonic bomb threats from rale callers Area raped off & searched. No bomb found local investigation continues KELLY, J.A. Region 4, Dallas, Office of the Director. Bi/03/03 2pp. 07867 250
- U. Congressional/Executive Correspondence
- 8103300300 Requests reconsideration of decision to cancel NRC insp of const site due to budget restrictions fluctear power generation sefesty should not be jeopardized Wiencls LONG, R B . JOHNSTON, J B . Senate. 81/03/12.
- ODCKET 50-459 RIVER BEND STATION, UNIT 2

  A Application/construction stage documents & correspondence
- B103190732 Ltrs to all licenses of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NAC position re interim actions & request for addl info.

  EISENMUT.0 0. Division of Licensing 80/12/22 30pp
- B103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs represent for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREO-0737.
  EISENMUT.D.9 Division of Licensing 81/01/19. pp
- BIG3120014 Ltr to all licensees of operating plants CP holders & GL applicants, except Indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding imadvertently unitted pages from NRC B01222 request for add info re control of heavy loads EIBENHUT, D. O. Division of Licensing B1/02/03. 6pp.
- 810316Co69 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1.2 re upgrade of energency support facilities Requests confirmation within 45 days that implementation dates will be met.

  ETSENHUT. D 0 Division of Licensing 81/02/18 12pp.
- 8100250024 Ltr to all gover reactor licensees & license applicants re M/REQ-0619 criteria. Footnote & in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller.
  EISENBUT.D.Q. Division of Licensing. 81/02/20. Bpp
- 8103170225 Ltr to all BWR licensess (except Humboldt Day & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping safe ands & fitting mail per guidelines of encl

- --Bi00170266 Model Tech Specs Ruges 074 0 2 074 0-0.3 surveillance requirements for ASIN Code Class 1.2 components & RCS operational leakage limiting compensation & correlliance requirements a General Electric Co. Bi/02/2004 For
- B103170655 Ltr to rolders of CAS & applicants for OLS review of ABME Class I 2 % 3 pressure terminary ripid and & & fitting mail per guidelines of entl Revision MRR00-0313 Model Tech Specs and year.

  EISENHUT D 3 Division of Licensing 01/02/26 3
- 0103230813 Generic Ltd Bi-06 to all CO holders & UL at 1005890 71(e): "Periodic Undating of FSASs." effect 000722 Info ne FSAR legal status for out, content en EISERHUIT D G Division of Licensing 81/07/26 to
- B103110303 Forwards for review t approval EUECO B101. LOCIVS Computer Code to Determine Pressure t Teop Roof Vapor Suppression Containments Following LCCA t BRADBURY. R. 3 Stone & Webster Engineering Cost &
- B103200089 Informs that staff forctions of Region 4 is effective 810927 Gt. Madeen Chief of Mear or Project designated as principal contact & recipient of correspondence recreation contact & operation activity SEYFRIT. W. Region 4: Dallass Dirice of the Direct 12 07948 218
- 8103310804 Ltm to all licensees of operating plants as a holders of CPs forwarding SECV-BI-119 re info necessablish environ qualification of safety-related of equipment EISENMIN. D. G. Division of Licensing BI/23/10 6:
- 8103230135 Responds to 810227 itr Visit to recilities progress & completion estimates concelled because of cuts DENION.H R Office of Nuclear Reactor Regulation. [ 81/03/16 4pp 07974 335
- --8103233142 Expresses disappointment that D Hood proto make expected insplyish to plant due to budge Urges that decision be reversed QUSTE: W J Louislane. State of 81/02/23 lp
- 8103260110 Forwards list of generic ltrs & bulletins in reactor licensees & applicants in 1980 TEDESCO.R L. Assistant Director for licensing 81, 08039 230
- F Security, medical, emergency 3 fire protection plan
- 8103310338 Ltr to all licensees of operating plants & forwarding NUREG-0896. "Functional Criteria for Emer Response Facilities." Criteria describe accoptable of for meeting NRC requirements U/o encl EISENHUT. D. 9. Division of Licensing. 81/03/05. 68
- @ Inspection reports. IE Bulletins & correspondence
- 8103230049 Forwards Suppl 4 to 16 Bulletin AG-17. 'Fa: Rode to Insert During Scren at BMR' No written rear required SEYFRIT.K V Region 4. Dallas. Office of the Direct 1p. 07978 035
- B103230212 Responds to IE Bulletin B0-21. 'Valve Yoke Malcolm Foundry Co. Inc.' No Malcom valve yokes in us rept will be submitted by B10310 DRAPER.E L. Gulf States Utilities Co. B1/01/06
- 8103100728 Forwards Suppl 5 to 1E Builetin 80-17. 'Fai Rods to Insert During Scram at BWR' No written resp required SEYFRIT.K V. Region 4. Dallas, Office of the Direct tp. 07865.322

### DOCKETED ITEMS

- BiO3160837 Forwards revised 1E Bulletin 81-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 % 6 Change in identification of faculities w/CPs to which bulletin is applicable does not affect util requirements SEYFRIF.4. V. Region 4. Dallas. Office of the Director G1/03/G4 12. 27914 195
- B103230178 Forwards IE Info Notice B1-07. "Potential Problem W/Mater-Boluble Purge Dam Fatls Used During Inert Gashelding "No response required SEYFRITA V Region 4, Dailas, Office of the Director 81/03/16 to 0977 217
- S. Reportable occurrences. LERs & related currespondence
- 8103103355 PKS-1V-81-003 on 810302-03. security guard for 85W received telephonic book threats from male callers Area roped off & searched No book found Local investigation continues EELY.J A Region 4. Dallas. Office of the Director 81/03/03 2pp 07867 250
- U Congressional/Executive Correspondence
- 8103330300 Requests reconsideration of Sectision to cancel NAC inspluterations as site due to budget restrictions Nuclear power generation safety should not be Jeopardized Wiencis LONG, R.B. JOHNSTON, J.B. Benate 81/03/12
- CCCKET 50-460 MPP99 NUCLEAR PROJECT. U:111 1

  A Application/construction stage documents & correspondence
- 9103190732 Ltrs to all licensess of operating plants, applicants for OLS & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREO-Obiz Forwards NRC position reinterin actions & request for addlines info EISEN-WIT.D. 0 Division of Licensing 80/12/22 30cp
- B1C319C397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment items addressed involve cold shutdown.replacement.parts & NUREG-0737 EISENHUT.O Q Division of Licensing B1/01/19 App
- 8109120014 Lit to all licensees of operating plants, CP holders & EL applicants, except indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addition of control of heavy loads EISERMUT.D Q Division of Licensing. 81/02/03 &pp
- ELOGIO-0667 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met ELSEN-UT, 0 0. Division of Licensing 81/02/18 12pp
- 8103293024 Ltr to all power reactor licensees & license applicants re MLREG-0619 criteria Foutnoto 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISEWAUT.D G. Division of Licensing 81/02/20 8pp
- 8103230813 Generic Ltr B1-06 to all CP holders & OL applicants re 16CFR50 71(e). "Periodic Updating of FSARs." effective 903722 Info re FSAR legal status.format & content encl EISEAMUT.D O Division of Licensing B1/02/26
- 6103120186 Notifies that 1F requested that encl preservice insp & test requirements for snubbers be included in licensing process. Requests that requirements to insure snubbor operability be implemented.

  TEDESCO.R.L. Assistant Director for Licensing 01/03/06 App
- BIO3310804 Ltr to all licensees of operating plants applicants for OL6 & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical aquipment

  EISEMMUT.D.Q Division of Licensing 81/03/10 &pp
- F Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency

- 8103319512 Forwards 801212 itr requesting NRC concurrence w/location offsite emergent, operations facilities Facilities are technically adequate w/o additactup facilities at greater than 10 miles.cespite N/REG-0695 guidence 837/G-EY-9 B. Washington Public Power Supply System 81/03/20 108059 197
- --8103310920 Requests NRC concurrence re adequacy of incation of off emergency operation facilities Util should not be penalized a required to relocate facilities of current NRC guidelines are modified. BOUCHEY. 0 D. Washington Public Power Supply System 80/12/12 309 08099:198
- O Inspection reports. IE Bulletine & correspondence
- 8103190006 Forwards IE Insp. Repts 90-460/BI-01 t 50-513/BI-01 on 810113-16 No noncompliance moted SPENCER.O. 9 Region 5. San Francisco. Reactor Construction t Engineering Support Branch 81/01/26 2pp 07962 340
- --BIO3190011 IE Insp Repts 50-460/BI-01 % 50-513/BI-01 un BIO113-16 noncompliance nuted Major areas inspected constlactivities including licensee action an previous insp findings. 10FR50 55e tiens.IE bulletins & potential 10FR21 defects KIRSCH D F. MAGNER, M J Region 5. San Francisco. Office of the Director DODBS, R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch BI/01/23 Bpp 079A2 342
- B103620136 Responds to IR Bulletin 80-21. "Valve Yokes Supplied by Maftolm Foundry (c. Inc. Specifies valve parts were not used by vendors Response from B&W butstanding Results will be sent by B10322 MAZUR. O W. Washington Public Power Supply System. B1/02/03 2pp 07783. 054
- B103020072 Forwards 1E Circular B1-02. "Performance of NRC-Licensed Individuals While on Duty No written response required ENDELMEN.R H Region 3. San Francisco. Office of the Birector B1/02/09 1p 07787 302
- 8103040313 Ack receipt of 810127 ltr informing NRC of steps taken to currect violations noted in IE Insp Repts 90-460780-11 & 50-913780-11 BPENCER-9 8 Region 9. San Francisco, Reactor Construction & Engineering Support Branch 81/02/09 ip 07820:086
- --B103040325 Responds to NRC B01007 t B10105 ltrs re violations note IE Insp Repts 90-460/20-11 t 30-513/80-11 Corrective actions initiated B10114 field change notice for technical direction re renoval of support lugs from tipe spool and URLD W. Washington Public Power Supply System 81/01/27. 3 07820.067.
- --8103040332 Ack receipt of B11106 itr informing NRC of steps taken correct violations noted in IE insp Repts 50-460/80-11 & 50-513/80-11 Add info required re undersized pipe spool lugs & nondestructive exam SPENCER. 9 S. Region 3. San Francisco. Reactor Construction & Engineering Support Branch 81/01/05 2pp 07820 090
- --B103040341 Responds to NRC B01007 ltr re violations noted in IE In Repts 50-460780-11 & 50-513780-11. Corrective actions 0A surveillance performed on handom sample of spools & drawings identifying pipe spools w/shop-welfed lugs MAZUR.D N. Washington Public Power Bupply Bystem 80/11/06 3 07820 092
- --8103040330 Forwards 16 Insp Repts 50~460/80-i1 & 50-513/80-i1 on 800826-29 & 0909-i2 & notice of violation BPENCER. 0.9 Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 80/10/07. 2pp. 07820 095
- --8103D40353 Notice of violation from inst on 800826-29 & 0909-12 • Region 5. Ban Francisco, Office of the Director 80/10/03. 2pp. 07820-097
- --Bi03040374 (E Insp Repts 50-460/80-11 % 50-313/80-11 on 800026-29 0909-12 Noncompliance noted understized shop welds on pipe to pipe attachment fillet welds & unduthorized removal of arc strikes from stainless steel pipe spool.

  XIRSCH.D.F., TOTH.A.D., HERMANDEZ.O. Region 5. San Francisco. Office of the Director 89/10/03. 16pp 07820 099
- 8103170005 Forwards 18 Circular 81-03. "Inoperable Seismic Monitoring

- B103120186 Notifies that [E requested that enc] preservice insp & test requirements for shubbers be included in licensing pracess Requests that requirements to insure shubber operability be implemented.
  TEDESCO.R L. Assistant Director for Licensing. B1/03/06 6pp 07903.015
- 8103180828 Forwards IE Mgt Meeting Repts 50-460/81-03.50-508/81-03. 50-509/81-03 & 50-513/81-03 on 810225 ENGELKEN.R.H Region 5, San Francisco, Office of the Director 81/03/06. | jp 0/953 155
- --Bi03180951 IE Mgt Meeting Repts 50-460/81-03.50-508/81-03.50-509/81-03 & 50-513/81-03 on Bi0225 No nancompliance noted Areas discussed actions taken no concerns expressed by mgt at Oct 1980 systematic appraisal of licensee performance meeting FAULKENBERRY, B. CREWES, J. Englon S. San Francisco, Reactor Construction & Engineering Support Uranch 81/03/04, 4pp 0.3334 154
- 8103200233 Forwards IE Info Notice 81-96. "Failure of ITE Model K-600 Circuit Breater" No response required. ENGELKEN-R.H. Region 9. San Francisco. Office of the Director B1/03/11. 1p. 07968-325
- 8103200064 Forwards IE Info Notice 81-05. Degraded DC Sys at Palisades. No response required.
  ENORLKEN.R H Region 5. San Francisco. Office of the Director 81/03/13. 1p. 07968 264
- 9. Repartable occurrences, LERs & related correspondence
- B10302050B Interim deficiency rept for diesel generator combustion air intate design, originally reported B0120B Design revisions ensuring ectuation of generator under tornado conditions currently being evaluated Final rept to be issued B10501 MAZUR. D. M. Weshington Public Power Supply System. B1/01/05 3pp 07785:061.
- 8103020505 Interim deficiency rept re Bostrom Bergen Metal Products welded essemblies, initially reported on 801208 Hold has been established on assemblies prior to embedment to 411om GA review of aff records final rept will be sent by 810501 MAZUR. D. W. Hashington Public Power Bupply Bystem 81/01/07. Spg
- B103120406 Interim deficiency reptroriginally reported B10117, repotential defects in seem weld decay heat removal exchanger tubing. Generic implications under investigation Eddy current testing program will be used to supply visual data MAZUR. D. W. Heshington Public Power Bupply System B1/01/30. 3pp.02904-360
- 8103120423 Interim deficiency rept re inedequacy of load restrictions for spent fuel cask handling trans in General Burs Bldg. initially reported on 810107 Following selection of corrective action final rept will be forwarded MAZUR.D.W. Washington Public Power Supply System 81/02/02. 2pp 07901:220
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 9103190732 Lits to all licensess of operating plants, applicants for DLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREC-0612 Forwards NRC position re-interim actions & request for Add) info.

  EISENHUT, D. O. Division of Licensing. 80/12/22. 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment libes addressed involve cold shutdown-replacement perts & NUREO-0737. EIBENHUT.D.Q. Division of Licensing. 81/01/19. 60p.
- BIOGI20014 Ltr to all licenses of operating plants CP holders & DL applicants, except Indian Point R & 3, Jion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC B01222 request for add info re control of heavy loads. EIBENMUT.D.O. Division of Licensing. B1/02/03. opp.

- NUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subrit analysis to justify use of existing low flow controller EISECHUI.D 0 Division of Licensing 81/02/20 Bpp
- 8103110853 Surmary of 810107 & 08 meeting w/util.GE & Sargent at site re instrumentation & control sys design using solid state protection sys & complete Nuclenet sys Viewgraphs & handouts encl GRIMES.C I Standardization & Special Projects Branch 81/
- B103230030 Ltr to all licensees of operating nuclear power pla applicants for GLs (except St Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT, D. G Division of Licensing 81/02/25 Spp
- B103170225 Ltr to all BWR licensess (except Humboldt Bay & LaC requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting nati per guidelines of onci Revision 1 to NUREG-0313 Model Tech Specs only enci EIBENHUT, D. O Division of Licensing 81/02/26 3pp
- --BI03170266 Model Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & surveillance requirements for ASME Code Class 1.2 % 3 components % RCS operational leatage limiting conditions foperation & surveillance requirements General Electric Co. B1/02/26 4pp
- 8103170695 Ltr to holders of CPs & applicants for CLs (BWRs) review of ASME Class 1.2 & 3 pressure boundary piping, safe ends & fitting mat) per guidelines of ent; Revision 1 to NURCO-0313 Model Tech Specs only encl EISENHUT.D G Division of Licensing 81/02/26. 3pp
- B103230813 Generic Ltr B1-06 to all CP holders & DL applicants 10CFR90 71(e), "Periodic Updating of FSARs," effective B00722 Info re FSAR legal status, format & content encl E1SENHUT.D @ Division of Licensing 81/02/26 10pp. 079
- B103120711 Notification of 810324 8 29 meeting w/util & BNWL is Bethesda.HD to discuss organization & content of facility FSAR w/respect to mechanical design GRIMEB-C 1 Standardization & Special Projects Branch GI/( 201. 07904 321.
- 8103130333 Icrediate Action Ltr per Bi0220-27 discussion refurther exam of design fabrication installation & insp of seismic Category I supports & restraints Bupersedes 810218 ltr. updating corrective measures.

  KEPPLER, J O Region 3. Chicago, Office of the Director 8 3pp 07912 165
- 8103310804 Ltr to all licensees of operating plants, applicants & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D.O. Division of Licensing 81/03/10 App
- 8(0324038) Expresses concern about lack of progress re facilit review SER should be scheduled for completion by Dec 1981 as util expects OL application to be subj of public hearings Meeting requested to develop positive guidance KOCH.L.J. Illinois Power Co 81/03/17. 3pp 07990 252
- F. Security, madical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants 5 holders forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements U/o encl. EISENRUI, D. O. Division of Licensing. 81/03/05 dap.
- G. Adjudicatory correspondence
- B103040506 Discusses B10129 meeting u/Prairie Alliance re lega requirements of admissible contentions. Also notes B10225 meeting u/Alliance, util & Blate of IL in Champaign IL re legal requirements & substance of proposed contentions. GODDARD. R. J. Hearing Branch 2 B1/03/02 1p. 07816 336

- Bj03120344 Requests legal basis for InC assistance & funding to intervenor groups Assistance may be outside statutory scape of InC authority Util B10227 Ith re-preheating conference encl BEVILLT. House of Ref. Appropriations B1/03/03 7pp 079C0 353
- 810320587 Advises that Clinton School Board room in Clinton. IL. is suitable location for special prehearing conference. In response to Bio311 request Location satisfies neutral ground criterion Certificate of Svc anci

## H General Correspondence

- 0103170302 FQ1A request for LERs to Bilds, seven listed NUREOs, 1980 arrual rapt, current generic task action plan.insp & evaluation repts & IL Power responses
  MACLLER-C Prairie Allianco B1702/11 1p 07934 331
- 8)03:70297 Responds to FOIA request for LEAs re BWRs, seven listed NUREOS.1980 annual rept.current generic task action plan. insp & evaluation rests & IL Power responses Forwards seven listed NUREOS annual rept will be issued in Mar N/o encls FELTON.J M Division of Rules and Records 81/03/04 2pp 0323-1 239
- ${\mathfrak I}$  . Inspection reports, 18 Bulletins  ${\mathfrak L}$  correspondence
- BIO3120468 Forwards IE Insp Rept 50-441/81-02 on BIO126-27 & notice of visition FIGHER-H L. Region 3. Chicago. Fuel Facility & Materials Gafety Branch BI/02/06 2pp 07934 313
- --8103120575 Notice of violation from insp on 810126-27 FISHER.W L Region 3. Chicago. Fuel Facility & Materials Safety Branch 81/02/05 ip 07904-315
- --8103120600 IE Insp Rept 90-461/81-02 on 810126-27 Noncompliance nuted no periphyton sample collected at Location 7 during first quarter 1979 PHILLIPS.th P., PAPERIELLO.C. J. Region 3. Chicago, Oppice of the Director. 81/02/04 Spp. 07904 316
- 8:03020104 Forwards IE Circular 81-02. Performance of IRC-Licensed Individuals While on Duty "No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 8:/02/07 2pp. 07788 COI
- G103180371 Forwards IE Insp. Rept 90-461/81-01 on B10119-23 No roncompliance noted F10RELULO Region 3. Chicago, Reactor Construction & Engineering Support Branch. 81/02/09 2pp 07943-024
- --Bi031803B5 IE insp Rept 50-461/Bi-01 on Bj0119-23 No noncompliance noted Major areas inspected followep of unresolved Items, noncompliance. IE bulletine & circulars & review of electrical components to sys. OA implementing procedures %ESCOTT.H M. GARDENER.R. NAIOP.R. C. Region 3, Chicago, Office of the Birector Bi/02/09 10pp 07943-026
- Bi03230126 Forwards IE Insp. Rept. 50-461/81-03 on Bi0106-0202 & notice of violetion.
  FlGRELLI G. Region 3- Chicago. Reactor Construction & Engineering Support Branch. Bi/02/10 2pp. 07977 153
- --Bi0323012B Notice of violation from insp on Bi0106-0202 FIDRELLI.Q Region 3. Chicago. Reactor Construction & Engineering Support Branch Bi/02/10 2pp 07977 155.
- --BIO3233141 IE Insp Rept 90-461/B1-03 on B10106-0202 Noncompliance noted concrete poured in diesel generator Category I bldg floor w/o sandblast classing & removal of curing compound from const joint surface LIVERNORE. H H. KNDP. R. Region 3. Chicago, Office of the Director. B1/02/09. 3pp 07977 157
- 2102030318 Forwards Suppl 5 to IE Bulletin 80-17, "Failure of Control R34s to Insert During Scram at BWR" No written response required.

  KEPPLER J. O. Region 3. Chicago. Office of the Director. 81/02/13. 2ps 07790:228
- 8103051006 I-mediate action ltr re 810213 discussion between util & NRC concerning large bore hanger installation & insplativities at sits Safety-related hanger const installation has been stopped KEPPLER, J. O. Region 3. Chicago, Office of the Director. 81/02/18 2cp 07831 343

- 8103160486 Forwards IE Circular Bi-03, "Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER. J. G. Region 3. Chicago. Office of the Director 81/03/02 2pp 07915.297
- 8103160870 Forwards revised 1E Bulletin 81-01, 'Burveillance of Hachanical Shubbers,' w/corrected Pages 5 & 6.Change in identification of facilities u/CPs to which bulletin is applicable does not affect util requirements KEPPLER.J G. Region 3. Chicago, Office of the Director 81/03/04 2pp 0.7914-225
- 8103190079 Confirms 810312 meeting in Olen Ellyn. IL to discuss insp findings he thial team sinsp program conducted at facilities KEPPLER. J. O. Region 3. Chicago, Office of the Director 81/03/10 io. 07965 118
- 8103190089 Ack receipt of 810226 ltr informing NRC of steps taken to correct violation noted in 1E insp Rept 50-461/81-02 HIND, J. A. Region 3. Chicago. Offica of the Director 81/03/11 ip 07960 224
- --B103190076 Responds to NRC B10206 ltr re violation noted in IE Insp Rept 50-461/B1-02 Corrective actions checilist sys expanded to include all periphyton serples Unsuccessful attempts to collect samples will be documented OERBINER: W C Tillingis Power Co B1/02/26 200 07960 225
- B103200B73 Forwards iE. Info Notice B1-06. Failure of ITE Model R-600 Circuit Breaker " to written response required MEPPLER, J.O. Region 3. Chicago, Office of the Director B1/03/11 2pp. 07967-203
- 8103203672 Forwards IE Info Notice 81-05. "Degraded CC 84s at Palisades" No action required MEPPLER.J C Region 3. Chicago. Office of the Director 81/03/13 2pp 07966 168
- 8103200322 Forwards [E Info Notice 81-07. "Potential Problem W/Water-Soluble Purge Dar Matis Used During Inert Oas Welding 'No response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 81/03/16 200 07766
- S Reportable accurrences. LEAs & related correspondence
- 8103090865 Discusses status of corrective action re electrical hanger installation Progress in constructed hanger documentation & field const work controls has been made, but resolution of design & const terms prior to Apr 1981 is needed MOCH, J. 111inois Power Co. 81/02/25 ip 07848 238
- U Congressional/Executive Correspondence
- B103120344 Requests legal basis for NRC assistance & funding to intervener groups Assistance may be outside statutory ecope of NRC authority Util 810227 ltr re prehearing conference encl.

  BEVILL.T. House of Rep., Appropriations 81/03/03 7pp 07900, 395
- DOCKET 50-462 CLINTON POKER STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Let's to ail licensees of operating plants.applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-OS12 Forwards NRC position relinterin actions & request for addl info. EISENHUT.D Q. Division of Licensing 80/12/22 30pp.
- B103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREG-0737.
  EISENHUI, D.O. Division of Licensing. 81/01/19 6pp.
- 8103120014 Ltr to all licensees of operating plants.CP holders & DL applicants.except Indian Point 2 & 3.7ion 1 & 2 & TM[-1. forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads EISENHUT.D Q. Division of Licensing 81/02/03 6pp.
- Bio3090125 Forwards organizational charts depicting NRC Region 3 representation.effective 810216. KEPPLER.J. O. Region 3. Chicago: Office of the Director. 81/02/20 2pp. 07850:063

- 0103259024 Ltr to all gower reactor licensees & iscense applicants re MJREG-0619 criteria Footnote 2 in Table 2 contains error due to leatage testing deletions Licensee may submit analysis to justify use of existing low flow controller ETSERNHUT.D O Division of Licensing 81/02/20 Bpp
- 8103110853 Schmary of 810107 & 08 meeting w/util.CE & Sargent & Lundy at site re instrumentation & control sys design using solid state protection sys & complete Nuclenet sys Vieugraphs & handouts enci.

  GRIMES.C | Standardization & Special Projects Branch, 81/02/23 79nc
- Bi03230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie Units 1 & 2). Requests util review to determine capability to mitigate station blackaut event & promptly implement energenc, procedures EISENHUT. D 9 Division of Licensing 81/02/25. Spp.
- BiO3170225 Ltr to all BWR licensees (except Humboldt Bay & LaCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends & fitting matl per guidelines of enci Revision i to NUME@-0313 Model Tech Specs only enci EISENHUT, D. O. Division of Licensing B1/02/26 3pp.
- --8103170265 Madel Yerh Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 % 3/4 4-8 re surveillance requirements for ASME Code Class 1.2 % 3 components & RCB operational lessage limiting conditions for operation & surveillance requirements > Operat Electric Co 81/02/26. 4pp.
- 8103170658 Ltr to holders of CPs & applicants for OLs (BWRs) requesting review of ASME Class 1.2 & 3 pressure boundary piping safe ands & fitting mati per guidelines of enci Revision 1 to NUREO-0313. Nodel Tech Specs only encl
  EISENMUT.D. 0 Division of Licensing 81/02/26 3pp
- 8103230813 Oeneric Ltr 81-05 to all CP holders & OL applicants re 10GFR99 71(e). Periodic Updating of FSARs." effective 800722 Info re FSAR legal status, format & content encl EISENNUT.D.O Division of Licensing 81702/25 10pp 07975 332
- 8103120711 Notification of 810024 t 25 meeting w/util & DNWL in BetherdarMD to discuss organization & content of facility FBAR w/respect to mechanical design ORIMES.C I. Standardization & Special Projects Branch 81/03/02 2pp 07904.321
- 8103130333 Immediate Action Ltr per B10220-27 discussion refurther exam of design fabrication installation & insp of seismic Category E supports & restraints Supersedes B10218 Itr.updating corrective measures MEPPLER. J G Region 3. Chicago. Office of the Director. B1/03/05-30p. 07912-165
- 0103310804 Ltr to all licensees of operating plants applicants for D<sub>v</sub>s tholders of CPs forwarding SECV-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  ELECKHUT. D. C. Division of Licensing. 81/03/10. 6pp
- F Security, medical, emergency & fire protection plans
- BIO3310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for neeting NRC requirements H/o enci

## O Adjudicatory correspondence

- 8103040506 Discusses 810127 meeting o/Prairie Alliance re legal requirements of admissible contentions. Also notes 810225 meeting o/Alliance.util % State of IL in Champaign. IL re legal requirements & substance of proposed contentions. ODDDARD.R. J. Hearing Branch 2 81/03/02. 1p 07816: 336.
- 8103120344 Requests legal basis for NRC assistance & funding to intervenor groups, Assistance may be outside statutory scope of NRC authority Util 810227 ltr re prehearing conference encl.

  8EVILL, T. House of Rep., Appropriations 81/03/03 7pp.
- Bi03200587 Advises that Clinton Bobool Board room in Clinton [L.is suitable location for special prehearing conference in response to Bi03:1 request Location satisfies neutral ground criterion. Certificate of Svc encl FAZIO, P.V. Schiff. Hardin & Meite 81/03/11. 3pp 07968-102.

#### H Genaral correspondence

- 8103170302 FOIA request for LERs to SURs, seven listed NUR annual rapt.current genetic task action plan. 1955 & evaluation repts & IL Power responses MUELLERS Preirie Alliance 81/02/11 ip 07934 33
- 8103170297 Responds to FOIA request for LERs to BWRs. seve MMREOS.1980 annual rept.current generic task action platinsp & evaluation repts to IL Power responses Forwards s listed MMREOS Annual rept will be issued in Mar U/o enc FELTOW. J M Division of Rules and Records 81/03/04 07934 329

## g Inspection reports, 1E Bulletins & correspondence

- B103020104 Forwards 1E Circular B1-02. "Performance of NR Individuals While on Duty" No written response require KEPPLER. J.O. Region 3. Chicago. Office of the Director 239 07788 001
- B10303031B Forwards Suppl 9 to IE Bulletin 80-17. "Failur Rods to Insert During Scran at BWR" No written respons required KEPPLER. J. G. Region 3. Chicago. Office of the Director 2pp 07790 228
- 8103051006 Immediate action ltm re 810213 discussion betw concerning large bore hanger installation & insplactive at site Safety-related hanger constitutablation has be stopped KEPPLER. J O Region 3. Chicago. Office of the Director 200 07801 343
- 8103160486 Forwards IE Circular 81-03, "Inoperable Seismin Instrumentation," No response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 27p 07915-297
- 8103160870 Forwards revised IE Bulletin 81-01. "Surveilla Mechanical Enubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements KEPPLER. J C. Region 3. Chicago. Office of the Director 2pp. 07914 226
- 8103190079 Confirms 810312 meeting in Olem Ellyn, IL to di findings he trial team insp program conducted at facili KEPPLER, J. Q. Region 3. Chicago. Office of the Director ip 07965:118
- 8103200873 Forwards 1E Info Notice 81-06, "Failure of ITE Circuit Breater" No written response required MEPPLER, J. O. Region 3. Chicago. Office of the Director 2pp 07967-203
- B103200672 Forwards IE Info Notice 81-95. 'Degraded DC Sy Palisades' 'No action required KEPPLER, J.O. Region 3. Chicago. Office of the Director 2pp. 07966 168
- 8103200322 Forwards IE Info Notice 81-07. "Potential Prob W/Water-Bojuble Purge Dam Matls Used Nuring Inert Gas Welding: No response required. KEPPLER-J O Region 3. Chicago. Office of the Director Zpp. 07966-262

### U Congressional/Esecutive Correspondence

- 8103120344 Requests legal basis for NRC assistance & fund intervenor groups Assistance may be autiside statutory s of NRC authority Util 810227 Itr re prehearing conference.

  SEVILL.T. House of Rep. Appropriations 81/03/05 7 07900:355
- COCKET 50-463 FULTON GENERATING STATION, UNIT 1

# O. Adjudicatory correspondence

BID3040469 Decision & Order dismissing proceeding w/preju advising NRC that application should be terminated w/o conditions re-site restoration Applicant request for easite review was to prevent proceeding termination. CLARK-H & Atomic Befety and Licensing Board Panel. 8 07820, 200

- Bio3260336 Erreptions to ASLB Bio227 decision & order Applicant objects to portion of decision dismissing proceeding u/prejudice ASLB incorrectly & inconsistently required std of intent u/respect to use of site Certificate of Svc entl (RMIN, 0 F, BRADLEY, 6 J, Philodelpris Electric Co. (RMIN, 0 F, Fintens & Williams 91/03/17 19pp 08041 260
- 8103250407 Notice of reconstitution of ASLAB RS Saliman, chairman, MR Jannean & CR Mohl, members 815MOP.C J. Atomic Safety and Licensing Appeal Panel. 81/03/20 in 07997-257
- 8103260905 Notice of ASLA3 reconstitution RS Saliman.chairman & WR Jahnson & CN Kohlinenbors 816-0P.C J. Atomic Safety and Licensing Appeal Panel 81/03/20 12 08936 201
- DOCKET 50-464 FULTON GENERATING STATION. UNIT 2

  9 Adjudicatory correspondence
- 8103040469 Decision & Order dismissing proceeding u/prejudice & advising NRC that application should be terminated u/p conditions re site restoration Applicant request for early site review was to prevent proceeding termination CLARN.N & Atomic Safety and Licensing Doard Panel 81/02/27. 9pp 07820 200.
- 81032£0135 Exceptions to ASLB B10227 decision & order Applicant objects to portion of decision dismissing proceeding w/prejudice ASLB incorrectly & inconsistently required sid of intent w/respect to use of site Certificate of Bvc enci IRMIN.D P. BRADLEY-E J. Philadelphia Electric Co IRMIN.D P. Hanton & Milliams B1/003/17 199p. 09041.26D
- BIO3250407 Notice of reconstitution of ASLAB RS Baliman, chairman, WR Johnson & CN Rohl, members BISHOP, C J Atomic Bafety and Licensing Appeal Panel BI/03/20 ip 07997 257
- 8103240905 Notice of ASLAB reconstitution RS Baliman, chairman & WR Jahnson & CN Kohl, members 819802.C J Atomic Safety and Licensing Appeal Panel 01/03/20 to 08036 201
- COMET BIN-50-466 ALLENG CREEK NUCLEAR BIATION.UNIT!

  A Application/construction stage documents & correspondence
- 8103030450 Recommends Commission approve encl draft final rule 100FR80 re licensing requirements for pending CPs & mfg license applications & proposed statement of requirement re degraded core rulemaking.

  DIRCKS-W J Office of the Executive Director for Operations SECY-81-020A 81/02/11 12pp
- 8103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs to control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position to interim actions & request for addl info.

  RISENHULD. 0. Division of Licensing. 80/12/22 30pp.
- 8103031057 "Environ Statements Project." monthly progress rept for Dec 1983 21TTEL.H E Oak Ridge National Laboratory. FIN B-0760-1 8103031057 20/12/31 App
- B103190387 Ltr to all licensess of operating plants & applicants for CLs & holders of CPs re program for environ qualification of safety-related electrical equipment litens addressed linvalve cold shutdown-replacement parts & NUREO-0737. EISENH-UT.D. 9. Division of Licensing. B1/01/19 App.
- 8103180039 Unofficial transcript of Commission 810212 maeting in Washington, DC re SECY-81-20 policy on proceeding Depending CP & mfg license applications. Pp 1-115.

   Commissioners 81/02/12 117pp.
- 8103290024 Ltr to all power reactor licensees & license applicants re MREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT.O.G. Division of Licensing 81/02/20. Bpp
- GIO3120741 Notification of 810310 meeting w/util in BethesdarMD to fiscuss literating plans for facility. MODN-C-W. Literating Branch 1 81/03/03. 4pp. 07905.270

- 8103170744 Notification of time change for 810310 meeting w/util in Bethesds.MD to discuss literating plans for facility MCCN-C.W Literating Branch 1 81/03/09 4co 07727 NBA
- Bio3300307 Advises NRC that inservice dates of five planned generat units will be delayed due to financing constraints Allans Creek facility will be started up in Mar 1991 Urges NRC to continue timely licensing Support

  OPREALOR Houston Lighting & Power Co. 81/03/25 Ip 08055 i
- B Utility Preliminary Safety Analysis Report. amends
- B103100204 Forwards Amend 56 to PSAR OOLDBERGUUH Houston Lighting & Power Co 81/03/09 4pp 07853:193
- --B103100209 Amend 56 to PSAR

  \* Houston Lighting & Power Co. B1/03/31 475pp 07853 [97.
- D NRC Draft/Final Environmental Statements, supply & correspondent
- 8103250476 Forwards NUREO-0470, Euppl 2 to FES 8 notice of availabil YOUNGBLOOD, B J Licensing Branch L. 81703/19 3pp 08027:216,
- --B103250480 Notice of availability of NUREC-0470 Suppl 2 to FEB
  YOUNDROOD B. J. Licensing Granch 1 81/03/19 200 08027:21
- B103250737 Forwards Buppl 2 to NUREO-0470.FEB re facility const U/o encl. YOUNDELOOD.B J Licensing Branch 1 81/03/19 2pp
- B103260002 Forwards Buppl 2 to NUREO-0470. Pacifity FEB Includes discussion of problems & objections raised by federal, state & local agencies or officials & interested member of public M/o encl YOUNGELOOD.B J. Licensing Branch 1 81/03/19 3pp 08040.072.
- 8103270105 Forwards Suppl 2 to NUREO-0470 facility FES Also forwards notice of availability. M/o NUREO YOUNDS,0050. J Licensing Branch 1 81/03/19 ip 08044:123
- --8103270114 Notice of availability of Suppl 2 to NUREG-0470 facility FEB. YOUNGBLOOD, B. J. Litensing Granch 1 81/02/19 2on 08044.12
- B103300390 Informs that NUREQ-0470.final Eig.meets requirements for filing under Bection 1506 9 of CEO regulations.Notice of availability will be included in 810327 FR Public review period will end on 810511.

  MILEGNIK L. Environmental Protection Agency B1/03/25, 19 08055 310
- 9 Adjudicatory correspondence
- B103040386 Forwards contentions re NUREO-0470.8uppl 2: "Draft Suppl FEB re Const of Allens Creek Nuclear Generating Station, Unit 1:"
  DOHERTY, J. F. Doherty, J. F. B1/02/10. Ip
- BiO3020419 Informs that matl in util BiO128 & 0210 filings should no be included in decision on consideration of contentions. Applicant should have filed metl in original motion for summery disposition W/encls DOHERTY, J. F. Affiliation Unknown. 81/02/23 3pp.
- 8103060797 Submits Mar. 1981 court schedule allowing cross-examination of applicant, intervenor, NRC & TX expert witnesses HINDERSTEIN, C. Hinderstein, C. 81/02/24, 3pp. 07428:093.
- B103060B35 Forwards schedule for health & safety portion of facility licensing proceedings presented on B10223. Certificate of Bvc enci. COPELAND, J. G. Houston Lighting & Power Co. COPELAND, J. G. Bater Botts. B1/02/24. 6pp. 07837:158.

- B103050564 Response to intervenor Doherty third supplemental response to mobian for summary disposition inter-east has no right to file late responses; shows no good cause & infe has no relationship to affected contentions. M/Certificate of Bvc CCPELAND, J O., NEWAN, J R. Houston Lighting & Pozer Co COPELAND, J O. Daier & Botts B1/02/25 4pp 07827 201
- B103110512 Hemorandum & order senying Tx PIRO B10115 motion & request for interlocutory appeal & certification of question Delay between ruling & filing motion unreasonable No good cause shown for delay. Certificate of Bvc enci
  CHEATUM.E. L. LINEMBERGER.O. MOLFE. 8 J. Atomic Bafety and Licensing Board Panel. B1/03/02 9pp. 07872 008.
- B103190511 Response apposing Tx PIRO 610217 notions on procedural matters, referral of interlocutory appeal, certification of various issues & removal of AGLB Motion contains misrepresentations of ALAB rulings W/Certificate of Svc NEWHANL JR R . COPPLAND. J B Houston Lighting & Power Co NEGHAN. J R Lowenstein. Neghan, Reis, Artelrat & Toil 81/03/04 25pp 07963 237
- B103200769 Affidavit in response to 1DJ Bross affidavit re "19B)
  Reassessment of Health Herards of Low Level Ionizing
  Radiation.' Review of rept added no facts to modify earlieconclusions. Certificate of Gvc encl Related correspondence
  HAMILTON.L D Brookhaven National Laboratory 81/03/09. 20pp.
  07967 069
- B103120298 Request for extension until B10224 to file answer to interveror Doherty B10223 motion for reconsideration of amended Contention 21 Applicant does not appose motion Certificate of Svc enc!
  BLACK.R.L. Hearing Branch 1. B1/03/10 4pp 07901 001
- 8103120483 Order denying intervenor D Harrack B10305 petition for directed certification of ASLB interlocutory procedural ruling B18H0P.C. Atomic Safety and Licensing Appeal Panel B1/03/10 1p. 07901 278
- B103120530 Memorandum & order denying TX PIRO B10115 motion for directed certification of interlocutory ASLB ruling Filing motion four months after ruling negates claim that ruling upul have irreparable, inmediate & serious impact.
  B1SHOP.C.J Atomic Safety and Licensing Appeal Panel 81/03/10 3pp. 07901:287
- 8103160160 Forwards proposed revised schedules for testimony subnittal re-safety hearing sessions beginning 810911
  BLACKERL Diffice of the Elecutive Legal Director 81/03/12 4pp 07919-350.
- 8103170839 Forwards revised proposed schedule for first two safety hearings sessions to commence on 810511. Applicant agrees w/schedule.

  BLAGK-R L Hearing Branch 1. 81/03/12 4pp 07933 296
- B103170102 Response opposing Tx PIRO B10129 notions seeking reconsideration of AELB rulings on procedural matters, referral of interlocutory appeal & certification of various issues.

  BLACK.R.L. Hearing Branch 1. B1/03/13 16pp. 07735 293
- --B103170109 Affidavit re intervenors' answer opposing NRC motion for summary disposition of consolidated contention Reviews BJ Irwin paper. "1981 Reassessment of Health Heiards of Low Level Ionizing Radiation" Certificate of Bvc encl. GOTCHY.R.L. Radialogical Assessment Branch. 81/03/13 Tpp 07933-309.
- 8103260104 Response opposing intervenur Poherty 81022 motion for ABUB to reconsider & overturn ABUB 800310 ruling rejecting intervenor Contention 21 Motion untimely, no good cause shown for reconsideration & lecks besis W/Certificate of Evc. BLACK.R L. Hearing Branch i. 81/03/24, 7pp. 08037:037.

## H General correspondence

B)03170485 Supports use of solar coal, wind or water power over nuclear power. Opposes const of facility near Houston TX. Expresses concept ne four eyemetations.

HDFFMAN.1. Affiliation Unknown. 81/02/02. 1p. 07585:001.

- 8103180522 Urges ASLB to consider evacuation problems
- 8103230675 Forwards 810226 ltr from constituent re lo site. BENTSEN.L Senate 81/03/13 lp 07977 072
- --B103236693 Requests evaluation of NRC ruling & local facility proposed site KELLNER, D. KELLNER, L. Affiliation Unknown 81, 07977 093
- T. Hearing transcripts on non-antitrust matters
- B10305001B Transcript of B10223 hearing in Houston, TX \* Atomic Safety and Licensing Board Panel 81/02/ D7822 277
- 810303038 Transcript of 810224 hearing in Houston, The Atomic Safety and Licensing Board Panel 81/02/07821 089
- 8103090025 Transcript of 810225 hearing in Houston, TX • Atomic Safety and Licensing Board Panel 81/02/ 07823 244
- 8103050016 Transcript of 810226 hearing in Houston, IX • Atomic Safety and Licensing Board Panel 81/02/
- 8103050031 Transcript of 810227 hearing in Houston.TX • Atomic Safety and Licensing Board Panel 81/02/
- B103110406 Transcript of B10302 hearing in Houston.TX \* Atomic Bafety and Licensing Board Panel 81/03/ 02876 001
- 8103110389 Transcript of 810303 hearing in Houston, TX • Atomic Safety and Licensing Board Panel 81/03/ 07874 Oct.
- B103110425 Transcript of B10304 hearing in Houston.Tx • Atomic Eafety and Licensing Board Panel B1/03/ 07868 238
- 9103110378 Transcript of 810305 hearing in Houston, TX \* Atomic Safety and Licensing Board Panel 81/03/ 02873 801
- 8103110360 Transcript of 810306 hearing in Houston.TX • Atomic Safety and Licensing Board Panel 81/03/ 02083-204
- 8103290194 Transcript of 810316 hearing in Houston TX Charts showing population distribution around site \* Atomic Safety and Licensing Board Panel 81/03/ 07994.058
- 8103270219 Transcript of 810317 hearing in Houston TX Atomic Sefety and Licensing Board Panel 81/03/
- 8103250223 Transcript of 810316 hearing in Houston, Tx • Atomic Safety and Licensing Board Panel 81/03/ condition
- 8103250213 Transcript of 810319 hearing in Houston TX • Atomic Safety and Licensing Board Panel 81/03/ 07999-095
- Bi03310103 Forwards RB Codell testimony on potential dredging of Ban Bernard River to transport reactor vessel Testinony identical to WB Blvens testimony o Prof qualifications also encl.

- ODCKET STN-90-467 ALLEMS CREEK HUCLEAR STATION, UNIT2

  A Application/construction stage documents & correspondence
- 8103331067 "Environ Statements Project." monthly progress rest for Dec 1983 ZITTEC.H E. Oak Hidge National Laboratory FIN 0-0760-1 R103031067 HD/12/31 4nu
- 8103320307 Advises NRC that inservice dates of five planned generating units will be delayed due to financing constraints Allens Creek facility will be started up in Mar 1991 Urges NRC to continue timely licensing support CPREA.0 W Houston Lighting & Power Co 81/03/25 ip 08055 133
- H General correspondence
- 810317065B Opposes nuclear power WMES, k Affiliation Unknown 81/03/04 2pp 07585 001
- DGCAET BIN-50-470 CEBBAR SYSTEM BO. CCMBUSTION ENGINEERING
  A Application/construction stage documents & correspondence
- 8103120763 Notification of 810305 meeting w/util & C-E in Bethesda, MD to discuss agendas & schedules for independent design review board reetings
  FERRIGAN, J. D. Licensing Branch 3 ORIMES. C. I. Standardization & Special Projects Branch 81/03/02 3pp 07703-305
- 6103090621 Forwards info re RCG cold leg piping, for use in BNML confirmators, piping analysis of safety injection sys piping, per NRC B10220 request Reservations exist as to whether simplified analysis will yield accurate results SCHERER A E C-E Power Sustems 81/03/03 26cc 07844 302
- BIODITO+58 Requests that instrumentation & control independent design review be rescheduled at first available opportunity Delays will have significant inpact on BAR.FBAR & CEBBAR-F review SCHERER.A E CHE Power Bystems. BI/OB/II 1p 07925-245
- B. Utility Preliminary Balety Analysis Report, amends
- E10330330 Forwards non proprietery Amend 2 to CEBBAR FBAR providing App B re NOREG-0737. "Clarification of TMI Action Requirements." Revised App A page correcting statement in Amend 1. encl SCHERER.A E Combustion Engineering. Inc 81/03/25 2pp. 00057-217
- --8103300381 Amend 2 to CESSAR FBAR, revising one page to App A & providing App 8, addressing NUREO-0737. "Clarification of TMI Action Plan Requirements"

   Combustion Engineering. (nc. 81/03/12 23pp 08057 221
- K Utility Final Bafety Analysis Report (FSAR) & emends
- 8:03240537 Forwards add1 responses to be distributed w/Amend 1 to CEASAR FBAR \* Combustion Engineering, Inc. 81/03/23 65pp 07986 186.
- DOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8103190732 Let's to all licensoes of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests taview per guidelines in NUREO-Obi2 Forwards NRC position re interim actions & request for addl info EISE/NHUT.D. Q Division of Licensing 80/12/22 30pp
- B1031903B7 Ltr to all licensees of operating plants & applicants for OL4 % holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREO-0737 EISENBUT, D. O. Division of Licensing 81/01/19 App
- 9103180039 Unofficial transcript of Commission 910212 meeting in Washington.DC re SECY-81-20 policy on proceeding w/pending CP & Mg license applications.Pp 1-115
  + Commissioners 81/02/12 117pp.

- --Bi00000450 Recomends Commission approve encl draft final rule 10CFI re licensing requirements for pending CPs & infg license applications & proposed statement of requirement re degraded care rulemaking DIRCMS.W J Office of the Elecutive Director for Operations SECV-81-020A 81/02/11 12pp
- B103230024 Ltr to all power reactor licensees & license applicants re NUREO-0519 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flaw controller EISEN-WI.D Q. Division of Licensing 81/02/20 800
- 8103230458 Amend to 731221 license application, consisting of PSAR Amend 41 which provides responses to NRC questions on Amend 40 re emergancy planning PGWARD.JE 80ston Edison Co. 81/03/16 lp. 07976-026
- B. Utility Preliminary Safety Analysis Report, amends
- B103230458 Amend to 731221 license application, consisting of PSAR Amend 41 which provides responses to NRC questions on Amend 40 re emergency planning MOWARD.J. E Boston Edison Co. B1/03/16 [5 07976 026
- --8103230461 Amend 41 to PBAR \* Boston Edison Co | 81/03/16 | 100pm | 07976 027
- F. Security, medical, emergency & fire protection plans
- B103090753 Requests review of population data in App 13A of Amend 40 to PBAR sumitted B01010 Review should determine if data provides adequate basis on which evacuation time estimates can be developed MIRAGLIA.F.J. Licensing Branch 3 81/03/02 ip 07844 183
- Bi03iB0130 Forwards request for add1 info & commitments re onside emergency facilities needed prior to determining that Amend 40 meets requirements of 10CFR50 Responses to comments & questions to be amended in PSAR by 8103i8

  TEDESCO.R L Assistant Director for Licensing 81/03/03 8pp
- 8103300288 Requests confirmation of 810424 Amend 41 to PBAR Based on util 810227 memo.understands Emergency Preparedness Licensing Branch util complete review by 810422 High RAGE(AF J. Licensing Branch 3 81/03/22 Hp 08053 021.
- G Adjudicatory correspondence

07829 178

- 8103040488 Requests svc of documents upon util be made to TO Dignan instead of Gri Lewald Address unchanged DIGNANT Q Roops & Oray 81/02/23 | p 07816.335
- 8103030635 Forwards intervenors Cleeton exceptions to ASLB 810202 partial initial decision CLEETON A. R. CLEETGN. H. W. Affiliation Uninoum 81/02/25 ip
- --G103050637 Appeal & exceptions to ASL8 810202 partial initial decise ASL8 error in considering benefits vs costs before evidentiary hearing & in not determining effect of unsolved generic matters on CP issuance W/Certificate of Svc CLEETONIA R , CLEETONIM W. Affiliation Unknown 81/02/25 App
- 8103200757 Informs that Cormonwealth of MA needs time to evaluate supp to SER re emergency planning to prepare new interrogatories, to evaluate answers to interrogatories & to prepare written testimony Winotice of appearance & Certificate of Svc. SHOTHELLIJ A Massachusetts, State of 81/02/27. 4pp 07967.064
- 8103040481 Responds to ASLB 810219 order providing dates to assist in devising schedule NRC will complete review of applicant proposed emergency plan by 810430 SER suppl re TMI-2 related issues should be issued by Jul-1981 CODDARO, R. J. Hearing Branch 2. 81/03/02. 2pp. 07820 209
- BiO3130414 Response to ASLB BiO219 order notifying ABLB that applicant can be ready to proceed w/remaining emergency planning hearings after NRC files SER Certificate of Bvc encl. pIQNAN.TO Boston Edison Co DIQNAN.T.O Ropes & Gray 81/03/02 3pp. 07911-265
- B103050674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by one or note parties.

  CHRISIENSURY: E Hearings Division. B1/03/04. Zpp 07829:262

- B103190537 Request for order setting time period for filing brief in opposition to exceptions to partial initial decision Date should fun from filling of last brief in support of exceptions. Oranteed for ASLAB. 810309
  - DIGNAN, T. O Boston Edison Co Dignan, T.O. Ropes & Gray 81/03/09 07947 279 07947 279 204
- BIO3190614 Request for order that time frare for applicants to file brief opposing exceptions from partial initial decision will run from date last supporting brief was filed One brief will respond to all exceptions. U/Certificate of Svc.

  DIGNAN. T.O. Boston Edison Co. DIGNAN. F.O. Ropes & Gray. B1/03/05 400 07963 272
- 8103120292 Notice of appearance in proceeding Certificate of Svc enci-COLDBERG, J. R. Antitrust Division 61/03/10 3pp 07900-221
- 8103130042 Request for order directing that time for filing NRC brief in apposition to intervenors' exceptions shall run from date of filing of last brief in support of exceptions Cortificate ne Byr and 1 COLDBERG, J. R. Antitrust Division 81/03/12 308 07907 195
- 8100260160 Jaint motion for consolidation of date for filing briefs & extension until 810519 to file briefs Good cause for Commonwealth of MA is necessity for thorough review counse! Illness & litigation obligations Certificate of Box entil WRIGHT.F.B. Massachusetts. State of HERRMANN.H Massachusetts Wildlife Federation HERRMANN.H Herrmann.H B1/03/12 4pp 00041-290
- 8103190589 Order directing extension until 810330 for Commission to consider whether to review ALASP-632. CHILKS J. Office of the Secretary of the Commission. 81/03/13 07956:058
- 8103190043 Answer to intervenors-appellants' motion for extension of 60 days to file briefs in support of exceptions to partial initial decision NRC has no objection to 30-day extension Certificate of Svc enct. GOLDBERG, J R Antitrust Division 81/03/17 4pp 07964.098
- I. Financial information
- 8103170031 Annual Financial Rept 1783 Boston Edison Co. 81/03/18 44pp 07586:001
- J. Insurance & indemnity information
- 8103030630 Forwards Endorsement 43 to MAELU Policy MF-58. FOULSHAM, P. A. Boston Edison Co. 81/02/24 200. 07795.024
- DOCKET 30-472 PILORIM NUCLEAR POWER STATION, UNIT 3 Q Adjudicatory correspondence
- 8103050674 Submits list of cases going to hearing during 1981 in which emergency preparedness contentions have been raised by or more parties. CHRISTENBURY, E. Hearings Division. 81/03/04 2pp. 07829: 262
- I. Financial information
- B103170051 Annual Financial Rept 1980. Boston Edison Co. 81/03/19. 44pp. 07586 001.
- DOCKET BTN-50-482 WOLF CREEK GENERATING STATION, KANBAB GAS & ELECTRIC A. Application/construction stage documents & correspondence
- 8103200640 Forwards Work Hold Agreement 13 & revised corrective action program to enhance sipe cleanliness program. Immediate response requested. KOEBTER Q. L. Kansas Gas & Electric Co. 80/12/16, 6pp. 07971:239.
- 8:03:90732 Line to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads. Requests OLS & nolders or the returned or news towns and requirements and underlines in NUREO-0612 Forwards NRC position reinteria actions & request for add1 info.
  EISENHUT, D. O. Division of Licensing. 80/12/22 30pp.
- BiOJ90307 Ltr to all licensees of operating plants & applicants for CLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737. EIBENHUT, D. Q. Division of Licensing. 81/01/19. opp.

- 8:03:20014 Ltr to all licensees of operating plants.CP holders applicants, ercept inotan Point & 6 3.210n 1 6 2 6 Mi-1 forwarding inadvertently omitted pages from NRC 801222 request for addl info te control of heavy loads EISE(:HUT.D O Division of Licensing 81/02/03 4pp
- 8103040023 Forwards Radiological Assessment Branch request for add1 info to continue FSAR review Response required by TEDESCO,R L Assistant Director for Licensing 81/02/09 02015 357
- 8103050115 Forwards revised NRC Region 4 organization chart.ed 810227 BEYFRIT.K V Region 4. Dallas. Office of the Director. Bis 2pp 07827 006
- B103030270 Summary of B10212 meeting u/utils in Gaithersburg.P auxiliary feeduater sys for facilities Addl info ra short & long-term concerns w/sys to be provided per B00310 ltr List of attendess detailed description of sys & viewgraphs end! DRDMERICK.A Licensing Branch 1 B1/02/18 55pp 07825: 8100290024 Ltr to all power reactor licensees & license applic NUREO-0619 critaria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHULD O Division of Licensing 81/02/20 8pp.
- 8103030770 Forwards addl info re FEAR for facilities, in respon ARC 810107 request. Info provided to leak-tightness of control room toric gas protection control room emergency ventilation sys & habitability sys PETRICKN A Standardired Nuclear Unit Power Plant System

B1/02/24. 32cp 07796 089

- 8103110280 Forwards request for addl info re SNUPPB FBAR result Reactor Fuels Section of Core Performance Branch review. Responses requested by 810401 TEDESCO.R.L. Assistant Director for Licensing 81/02/23 07877:318
- 8103230030 Ltr to all licensess of operating nuclear power pla 103220030 Ltr to all licensees or operating nuclear power applicants for OLs (except 3t Lucis Units i & 2) Requests util review to determine canability to mitigate station blackout event & promptly implement emergency procedures EISENHULD 0 Division of Licensing BI/OZ/23. Spp
- 8103230813 Generic Ltr 81-05 to all CP holders & OL applicants 10CFRSO.71(e), "Periodic Updating of FSARs." effective 800722.info re FSAR legal status, format & content encl. £15ENBUT.D.O. Division of Licensing 81/02/26 iOpp. 8103030549 Forwards "Licensing Review Results for FSAR Chapte" (Electric Power) re Operation of SNUPPE Plants, " summary of
- special review conducted to assist NRC in CL evaluation PETRICK.N A Standardized Nuclear Unit Power Plant System BL/02/27. ip 07826-279.
- --8103090957 "Licensing Review Results for FBAR Chapter 8 (Ele Power) re Operation of SNUPPB Plants CAPONE D . CERMAK J . HEINLEIN D. Btandardized Nuclear Un Plant Bystem 81/02/27. 15pp 07826: 276
- 8103050642 Discusses OL review of facilities. Util is willing t togosove Discusses the review or racilities. Util is willing expedite review Requests that more meetings be held w/Auxiliary Eys Branch & that NRC attempt to neet commitments for issuence of requests for addl info. PETRICK.N A. Standardized Nuclear Unit Power Plant System 81/02/27. 2pp 07826-208.
- 8103120721 Notification of 810319 meeting w/utile & SNUPPS in Galthersburg. MD to discuss matters re svc water sys. component cooling water sys & ultimate heat sink. DRDMERICK, A. W. Licensing Branch 1. 81/02/27. Spp 07904.
- 8103130626 Notification of 810401 meeting w/utils & SNUPPS org to discuss control room ventilation sys, fuel pool area ventilation auxiliary radwaste area ventilation & turbine area ventilation. DROHERICK, A. W. Licensing Branch 1. 81/03/09 Spp.
- 8103200098 Informs that staff functions of Region 4 reassigned effective B10227 O. Madsen. Chief of Reactor Projects Branch designated as principal contact & recipient of correspondence re reactor const & operation activities. SEYFRIT K V Region 4: Dallas: Office of the Director. 81/ 1p. 07969: 050.

- 910331CB04 Ltr to all licensees of operating plants applicants for QLs b holders of CPs forwarding SECV-BI:-117 re info necessary to astablish environ qualification of safety-related electrical equipment EISPN-MIT.D.O Division of Licensing 81/03/10 6cg
- 3103230271 Notification of 810509 meeting a/utils & SNUPPS in Gaithersburg. MO to discuss structural design ORCHERICK. A H. Literating Branch 1. 81/03/12 Jun 07974 361
- 8103230023 Notification of rescheduled 810403 meeting w/utils & SNUPPS organization in Galthersburg.MD to discuss ventilation of control room & fuel pool.auxiliary racwaste & engineered safety feature areas Meeting originally set for 810401 DROMERICK.AW Licensing Branch 1 81/03/13 5pp 07978 018
- B103230420 Requests all info re GNUPPS GA program for design & const Response to be submitted by B10415 TEDESCO.R. L. Assistant Director for Licensing. B1/03/13 4pp 07980-328
- 9103230345 Forwards request for addl QA into to complete evaluation of FSAR.Responses to be submitted by 810515 TEDESCO.R L. Assistant Director for Licensing 81/03/16 9pp 07980.332
- Bi03230262 Notification of Bi0429 meeting w/utils in Gaithersburg, MD to discuss pressuriter relief valve-demineralized water sqs. portable sanitary water sqs. compressed air-main stream. condensate & feed water circulating vater sqs. BRCM-ERICK.A M. Licensing Branch 1 Bi/03/17 3pp 07975 001
- B103250103 Informs that Chapter 14 review process would have been shartened by 2 to 6 months if applicants had responded to NRC questions Appropriate info sent to other recent applicants should be submitted as amend to FBAR IEDESCO.R.L. Assistant Director for Licensing 81/03/17 3pp 07997-314
- 8103240831 Notification of 810513 meeting w/utile & SNUPPB in Oaithersburg. MD to discuss matters to new fuel storage, spent fuel coaling, fuel handling & functional design of reactivity control sys.

  RDPMERICH. A W. Litersing Branch 1 81/03/18 3pp 07984-231
- 8103260613 Responds to NRC 010207 request for add1 info ro FSAR [nfo will be incorporated into nest revision. PETRICK:N A Standardized Nuclear Unit Power Plant System. 81/03/20 13pp 08040:317
- 8103260996 Forwards summary of B10211-13 meeting re confirmatory piping analyses for plants
  DROFERICK. A W. Licensing Branch 1 81/03/20. 3pg. 08039: 222
- --8103261009 Summary of 810211-13 meetings w/utils.PNL.GNUPPB & Bechtel in Quithersburg.Md re confirmatory piping analysis to be performed by Mechanical Engineering Branch.
  TERAO.D. Mechanical Engineering Branch 81/03/18. 5pp. 08035-223
- B103270409 Forwards 703 oversize electrical instrumentation & control drawings.per NRC request Also forwards drawing list from Section 1.7 of FBAR Aperture cards will be available in PDR FETRICK.N. A. Standardized Nuclear Unit Power Plant System, 81/03/20. 21pp 08158-314.
- B1032707B1 Bummary of B10319 meeting w/utils & SNUPPB in Gaithersburg, MD re syc water sys ultimate heat sinks & component water sys for facilities. Add1 (nfo requested re protection of mechanical draft cooling towers against icing & debris.

  BRCMERICK, A W. Licensing Branch I. B1/03/23 6pp. 08034:072.
- B100310696 Notification of B10527 meeting w/utils & SNUPPS in Gaithersburg.MD to discuss protection against high & moderate energy breaks, internal & external missiles:flood protection & missiles generated by natural phenomena. DROMERICK: A W. Licensing Branch 1. 91/03/24 3pp. 08061:066.
- F. Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NVREO-0696. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for meeting NRC requirements. W/o encl. EIBENHUT, D. O. Division of Licensing. 81/03/05. 6pp.

### G Adjudicatory correspondence

- 8103120361 Advises trat contentions not available until contingency plan completed Requests info re requirements for Coffey County plan CHAPTY, N. Affiliation Unknown. 81/02/25 in
- 8103180608 Memorandum & order granting M Christy & ME Salava petition to intervene denying MO-MS Section ANS & MS for a Sensible Energy petitions to intervene & approving MO Public Svc Commission request to participate as gover representative CLEASCH J P Atomic Safety and Licensing Board Panel 81/03/13. 9pg 07947.281
- 8103180620 Order scheduling 810415 special prehearing conference in Emporial KB to identify issues, further actions on petitions to setablish future schedule for proceedings GLEASON, J.P. Atomic Safety and Licensing Board Panel. 81/03/13 ip. 07947-285
- Bi03iB06i3 Answer to ME Salava Bi02i6 supplemental potition to intervene Potitioner has sattsfied standing requirements Contentions may still be filed. Certificate of Bvc encl. KARNAR M. Hearing Branch 2 81/03/17 4pp 07947:276.
- B103260579 Requests notification of whether request to intervene has been granted Also requests that hearings be held in Burlington or at plant site. due to travel required for attendance at hearings in MD BLANFUSS: F. Affiliation Unknown. B1/03/17 1p.

#### H General correspondence

- 8103140620 Forwards FR notice re-relocation of LPDR from Coffey Count Counthouse in Burjington. KS to Emporia State Univ in Emporia. KB FELTON.J.M. Division of Rules and Records. 81/02/26 1p 07917-134
- --BiO3160626 Notice of relocation of LPDR from Coffey County Courthou in Burlington-KB to Emporia State Univ in Emporia KB. FELTON-J M Division of Rules and Records 81/02/26 2pp. 07917-139

#### M Antitrust correspondence

- BIO3050689 Forwards "Power Supply Planning Bludy" & BIO130 ltr to KB Oas & Electric & KB City Power & Light in response to NRC DIO209 ltr Bludy available in Central Files only. HANBON.O.E. Kansas Municipal Energy Agency. B1/02/23. 3pp. 03833-008
- G Inspection reports. (E Bulletins & correspondence
- 8103050394 Forwards IE Insp Rept 50-482/B0-23 during Dec 1980. No noncompliance noted. SEIDLE:H.C Region 4. Dallas. Reactor Construction & Engineering Support Branch 81/01/19 2pp. 07824:219
- --Bi03090361 IE Insp Rept 80-482/80-23 during Dec 1980. No noncomplian noted, He jor areas inspected, followsp action re-piping cleantiness, work hold agreement & immediate action its. VANDEL, T. E. CROSMAN, M. A. Region 4. Delias. Office of the Director. Bi/01/16 App. 07824; 221
- 8103050279 Forwards IE Inap Rept 50-482/80-24 on 801201-04.18 23 & 810106. No noncompliance noted. 6EIDLE.W C. Region 4. Dallas. Reactor Construction & Engineering Support Branch. B1/01/20. 2pp. 07825:339.
- --Bi03050295 IE Insp Rept 50-482/80-24 on 801201-04/18/23 & 810106 No noncompliance noted. Major areas inspected const activities including followup on previous insp findings & identified deficiencies.

  MARTIN-L. E. CROBSHAN-W. A. Region 4. Dallas Office of the Director. B1/01/20 6pp 07825:341
- 8103020686 Responds to IE Bulletin 80-23, "Failures of Bolenoid Valve Hig by Valcor Engineering Corp." Util does not use specified valves in safety-related functions PETRICK:N A. Standardized Nuclear Unit Power Plant Bystem. 81/02/05. 1p. 07782:134.
- 8103020694 Responds to IE Bulletin BO-21, "Valve Yoles Supplied by Malcolm Foundry Co.Inc." Util does not utilize specified valves.

  PETRICK.N.A. Standardized Nuclear Unit Power Plant System.
  81/02/05. 1p. 07792:135

- B103200207 Forwards IE Info Notice B1-04. 'Cracking in Hain Steem Lines' No response required GRIER. D. Region 4. Dallas. Office of the Director. 81/02/27 Ip 07972:047
- 8103170010 Parwards IE Circular 81-03, "Inoperable Seismic Monitoring Instrumentation" No response required SEYFRITIK V. Region 4. Dallas, Office of the Director 81/03/02 16. 07939 108
- 9103160825 Forwards revised IE Bulletin 81-01. Surveillance of Machanical Bnubbers." w/corrected Pages 5.8 & Change in identification of Pacifities w/CPs to which bulletin is applicable does not affect util requirements. SEYPRIT.K.W. Region 4. Dallas. Office of the Director 81/03/04 lp. 07914:183
- 8100230188 Forwards IE Info Notice 81-07, "Potential Problem W/Water-Soluble Purge Dan Matls Used During Inert Gas Welding." No response required.

  SEYFRIT.K V. Region 4, Dallas, Office of the Director. 81/03/16 pp. 07977:240
- 9 Reportable occurrences. LERs & related correspondence
- 8103180680 Interim deficiency rept re damaged motor control ctr.
  initially reported 801128. Ctr has been shipped back to
  manufacturer & reinspected. No extensive repair or redesign
  necessary. Damage is not reportable under 100FRSO 55(e).
  MOESTERIO L. Kansas Gas & Electric Co. 81/01/30. 1p. 07954.180
- 8103240132 Interim deficiency rept re 0E HFA relays initially reported B01223. IE Info Notice 8:-01 was issued to advise industry of problem Relays will be replaced as substitutes become available from CE, No insp planned.

  KDESTER.O. L. Kansas 9as & Electric Co B1/02/18 Ip 97969 259.
- BIO3180704 Interim deficiency rept re loose sway strut bushings, initially reported B00627. Investigations are being conducted to determine cause & develop plan for corrective action. KDESTERNO L. Kansas Oas & Electric Co. B1/02/26 2pp 07934 177.
- 9103310671 Interim deficiency rept re design interferences in Bergen Paterson pipe support/shock arrestor assembly used to support 8-20 inch pipe sections Caused by vendor failure to notify users of revisions.

  SEIKEN.S.J. Standardized Nuclear Unit Power Plant System 81/03/17 12pp. 08061 051.
- DOCKET BTN-30-483 CALLAHAY PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- B103190732 Ltre to all licensees of operating plants applicants for CLs & holders of CPs re control of heavy loads Requests review per guidelines in NNREO-Doi2. Forwards NRC position re interim actions & request for addi
- B1031903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed invalve cold shutdown replacement parts & NUREG-0737.

  EIBENHUT.D.O Division of Licensing. 81/01/19. App.
- SIC3120014 Ltr to all literasses of operating plants, CP holders & OL applicants, except indian Point 2 & 3.7ton 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads.

  EISENHUT, B. 0 Division of Literating. 81/02/03 6pp.
- 8103040023 Forwards Redicing ical Assessment Branch request for addition to continue FSAR review Response required by 810322.
  TEDEBEOR. L. Assistant Director for Licensing. 81/02/09. Spp. 07815:397.

- }

- 8103031087 Requests that enc1 preservice insp & test requirements to insure shubber operability be implemented at facility. TEDESCO.R. L. Assistant Director for Licensing. Bi/02/10. 4pp. 07795:334.
- 8103050270 Summary of 810212 meeting u/utils in Oaithersburg.MD reauxiliary feedwater sys for facilities.Addl info re short & lang-term concerns u/sys to be provided per 800310 ftr. List of attendess, detailed description of sys & viewpraphs encl. DROMERICK.A. Licensing Branch 1. 81/02/18 55pp. 07825:282

- 8103060493 Requests add1 info re FSAR addendum review by 810403 TEDESCO.R L. Assistant Director for Licensing 81/02/16 3 07835-243
- B103250024 Ltr to all power reactor licensees & license applica MREG-0519 criteria Footnota 2 in Table 2 contains arro. due to leakage testing deletions Licensee may submit analysis to justify use of elisting low flow controller EISENHUT.D.O Division of Licensing B1/02/20 Opp
- 8103030770 Forwards add1 info re FBAR for facilities in respons NRC 810107 request info provided re leak-tightness of control room-toxic gas protection control room energency ventilation sys & habitability sys PETRICK-II A Standardized Nuclear Unit Power Plant System. 81/00/24 320a 07794 089
- B103110250 Forwards request for add1 info re BNUPPB FBAR result Reactor Fuels Section of Core Performance Branch review Responses requested by B10401. TEDESCOR L Assistant Director for Licensing 81/02/25 4 07/877 318
- 8103230030 Ltr to all licensees of operating nuclear power plan applicants for CLs (except St Lucie-Units 1 % 2) Requests util review to determine capability to nitigate station blackout event & promptly implement emergency procedures. EISENHUT.D 9 Division of Licensing 81/02/25 Spp
- 8103230813 Ceneric Ltr 81-06 to all CP holders & OL applicants IOCFR90 71(e). 'Periodic Updating of FEARs.' effective BOD722 Info re FBAR legal status. Format & content encl. ETSENHOT.D O Division of Licensing 81/02/26 1
- Bi03050549 Forwards "Licensing Review Results for FBAR Chapter (Electric Power) re Operation of SNUPPB Flants," summary of special review conducted to assist NRC in OL evaluation PETRICK.N A Standardized Nuclear Unit Power Plant Bystem Bi702727. Ip 07826.275
- --BIO3050557 "Licensing Review Results for FBA9 Chapter B (Elec Power) re Operation of SWUPPS Plants " CAPQNE.D., CERNAK.J., HEINLEIN.D Standardised Nuclear Uni Plant System 81/02/27 13pp 07826-276
- 8103059642 Discusses CL review of facilities Util is willing to expedite review Requests that more meetings be held w/Ausiliary Sig Branch & that NRC attempt to meet commitments for issuence of requests for addl info. PETRICK.N A Standardised Nuclear Unit Power Plant System 81/02/27 2pp 07826 208
- B103120721 Notification of B10319 meeting w/utils & SNUPPS in Daithersburg. MD to discuss matters he ave water sys. component cooling water sys & utilinate heat sink DRQMERICK. A W. Licensing Branch 1 B1/02/27 Spp. 07904:3
- 8103130626 Notification of 810401 meeting w/utils & SRUPPR orgato discuss control room ventilation sys, fuel pool area ventilation auxiliary raduaste area ventilation & turbine area ventilation.

  DROMERICK. A. W. Licensing Branch 1. 81/03/09 5pp 07913 3
- 8)03310804 Ltr to all licensees of operating plants applicants & holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENHUT.D.O. Division of Licensing 81/03/10 http
- B103170436 Reiterates that both MO Historic Preservation Progra Advisory Council on Historic Preservation should be allowed to review final scope of work for cultural survey prior to Union Electric final agreements. GEICHMAN.M.S. Missouri, State of. 81/03/12 1p 07923 200
- 8103230271 Notification of 810505 meeting w/utils & ENUPPS in Oaithersburg MD to discuss structural design. DRDMERICK: A W. Licensing Brench 1. 81/03/12 3pp. 07974.3
- 8103180489 Responds to NRC 810130 request for add1 info re Call FSAR Discusses development & use of land. BYRAN J K. Union Electric Co. 81/03/13, 10pp. 07953:104
- Bi03230023 Notification of rescheduled Bi0403 meeting w/utils & organization in Gaithersburg.MD to discuss ventilation of control room & fuel pool auxiliary reduceste & engineered safety feature areas Meeting orlginally set for Bi0401. DRDMERICK.A W. Licensing Branch i. Bi/03/13. Spp. 07978 Q

## DOCKETED ITEMS

- 8193230423 Requests all info re SNUPPS QA program for design 5 const Paspanse to te submitted by 810415 TED5500.R L Assistant Director for Licensing 81/03/13 4ap
- TEDESCO.R L Assistant Director for Licensing 81/03/13 4pp 07980 328
- 8)01239262 Notification of 81042? meeting w/utils in Oaithersburg.MD to discuss pressurger relief valve.demineralized water sys. portable sanitary water sys.compressed air.main stream, condensate b feed water circulating water sys. pagmenfick.A W. Licensing Branch 1 B1/03/17 3pp 07975 001
- 8:03290108 Informs that Chapter 14 review process would have been shortened by 2 to 6 months if applicants had responded to MRC questions Appropriate info sent to other recent applicants should be submitted as amend to FBAR TECESCO.9 L Assistant Director for Licensing 81/03/17 3pp. 2009 2011
- 8103240831 Notification of 810513 meeting w/utils & SMUPPS in Gaithersburg. PD to discuse matters re new fuel storage, spent fuel cooling, fuel handling & functional design of reactivity control sys DROWERSKA N. Licensing Branch 1 01/03/18 3ap 07984 231
- G:03240259 Forwards response to questions per RL Tedesco Bi0209 request re FSAR.Addi info will be incorporated into FSAR in next revision & application
  BRYAN.J.k. Union Flectric Co. BI/03/20 | 11pp | 07986 299
- 8103z60513 Responds to NRC 810209 request for add1 info re FBAR Info will be incorporated into next revision PETRICK-N A Standardized Nuclear Unit Power Plant System 81703720 13pp 08040 317
- G103260596 Forwards summary of 810211-13 meeting re-confirmatory piping analyses for plants
  DROMERICK.A W. Licensing Branch 1 81/03/20 3pc 08035-202
- --BI03261609 Summary of BI0211-13 meetings w/utils.PNL.BNUPPB & Bechtel in Calthersburg.Md re confirmatory piping analysis to be performed by Mechanical Engineering Branch. TERAO.D Mechanical Engineering Branch B1/03/18 Spp 08035-225
- 8103270409 Forwards 703 oversize electrical instrumentation & control drawings.per NRC request Also forwards drawing list from Section 1.7 of FSAR Aperture cards will be available in PDR PETRICK-II A. Standardized Nuclear Unit Power Plant System 81/03/20 21pp 06158-314
- 8103270781 Summary of B10319 meeting w/utils & SNUPPS in Oaithersburg. HD relayed water sys ultimate heat sinks & component water sys for facilities Add infor requested re-protection of mechanical draft cooling towers against icing & deficis DRCMERICK. A Williams Branch 1 81/03/23 6pp 08034 072.
- 8103270658 Discusses 810319 meeting w/NRC Auxiliary Bys Branch to discuss svc water sys. Oltimate heat sinks & component cooling water sys. Oltimate heat sinks & component cooling water sys. Oltimatel provide add/discussion repotential for icling & debris to affect cooling tower STR10HT.R. L. Standardized Nuclear Unit Power Plant System. 81703/24 2pp 08043-004.
- 8103310696 Notification of B10327 meeting w/utils & BNUPP8 in Gaithersburg. MD to discuss protection against high & moderate energy breaks.internal & external missiles.flood protection & missiles generated by natural phenomena DRCMERICK. A W Licensing Branch 1. 81/03/24 3pp. 08061:066.
- 9103310372 Forwards request for add1 info re FBAR review info should be submitted by 810425
  TECESCOR L. Assistant Director for Licensing 81/03/26. 7pp. 68059-322
- 8103310217 Forwards add1 info re FBAR.per NRC 810212 request Info will be incorporated into FBAR w/heart revision ERVAN.J X Union Electric Co 81/03/27. 4pp. 08060:232
- C Utility Environmental Report (ER). amends & correspondence
- 8103180714 Forwards add1 info re environ rept.per NRC 810102 request. Resalting info espected by 810320. Info will be formally incorporated into Revision 2 pf environ rept.

- F Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding huREQ-0696 "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl
  EISERMUI.D Q Division of Licensing B1/03/05 App
- Q Adjudicatory correspondence
- 8103190613 Reply to NRC 801110 response opposing admittance of petitioner Contention i Plant deficiencies are significant interim actions to Compensate for deficiencies must be coordinated whocal govts Certificate of Svc encl REED.19 Affiliation Unknown 81/03/01 1000 07963 262
- B103130589 Notice of Appearance in proceeding Certificate of Svc encl CHACKES K M Missourians for Bafe Energy CHACKES K M Chackes & Hoare 81/03/03 4pp 07913-026
- 8103120386 Amended & supplemental joint petition to intervene, originally filed on 800923 Standing requirements for K Drey & contentions to be litigated set forth CHACKES.K M Coalition for the Environment, Bt Louis Region CHACKES.K M Missourians for Safe Energy CHACKES.K M Crawdad Aljience 81/03/06 15pp 0789 323
- --B103120403 Affidavit re ed background & research on nuclear power & specific facilities Certificate of Svc encl
  DREY. A Affiliation Unknown B1/03/06 20pp 07893.340.
- 8103120394 Responds to 810218 ltr & tolcon w/Loob re special preheari conference. NRC would support request to defer limited appearance statement Only one member of organization allowed to make statement LESGY.R P Antitrust Division. 81/03/11 2pp 07904 252
- 8103260579 Requests notification of whether request to intervene has been granted Also requests that hearings be held in Burlington or at plant site-due to travel required for attendance at hearings in MD.
  BLAUFURSEF Affiliation Unknown. 81/03/17 ip
- H General terrespondence
- 8103120239 Forwards K Dray 760108 ltr to Chairman Anders,in responsa 810209 request YOUNOSLOOO:8 J Licensing Branch 1 81/02/19 lp. 07901:325
- --BiO3120249 Forwards magazine article from Jan 1976 Progressive re inherent dangers of nuclear energy NRC should require util to disclose info on financial ability to construct facility DREY.K. Affiliation Unknown. 76/01/08 3pp 07901.326
- 8103260624 Requests hearing re issues of critical importance to ratepayers in State of MD. Certificate of Svc encl MEARNE. T. J. Nissouri, State of. 81/03/17 5pp 08040.309.
- M Antitrust correspondence
- B103030889 Responds to 801217 ltr re antitrust review for GL Any short-term sales or purchases it yr or less) transacted under existing interchange agreements on file w/FERC. No plans nade for new generating capacity beyond Unit 2 BRYANJ K Union Electric Co. 81/02/11 9pp 07795:145.
- Q Enspection reports. IE Bulletine & correspondence
- 8103050041 Forwards IE Insp Rept 50-483/80-31 on 801201-3) No noncompliance noted. FIORELLI-0 Region 3, Chicago: Office of the Director. 81/01/07 2pp. 07827:228.
- --Bi03050048 IE Insp Rept 90-483/80-31 on B01201-31. No noncompliance noted that or areas inspected safety-related const activities including protection of reactor vessel & other components of NSSS.

  HANSEN. W. A., KNOP. R. C. Region 3. Chicago, Office of the Director. B1/01/07 Spp. 07827. 230

- --BIO3020403 IE (msp Rept 50-483/80-30 on 801211-12 & 18-19 No noncompliance noted Major areas inspected discussions rediscovery & reporting concrete imperfections within Unit 1 reactor bidg dome.

  HAHMINS F C . PHILLIP.O A Region 3. Chicago. Office of the Director. HAYES, D W Region 3. Chicago. Reactor Construction & Engineering Support Branch 81/01/16. 55p. 07782-172
- 8103020686 Responds to IE Bulletin 80-23. "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp." Util does not use specified valves in safety-related functions PETRICK.N A Standardised Nuclear Unit Power Plant System 81/02/09. 1p 07782 134
- 8103020694 Responds to 1E Bulletin BO-21. 'Valve Yokes Supplied by Malcolm Foundry Co, Inc." Util does not utilize specified valves
  PETRICK.N A Standardized Nuclear Unit Power Plant System 61/02/09. 10 07782.139
- B103180150 Forwards [E Insp Rept 50-483/81-01 on 810113-16 No noncompilance noted FIGRELLS. Region 3. Chicago. Reactor Construction & Engineering Support Branch. B1/02/03 2pp. 07943-260
- --BI03180163 IE Insp Rept 50-483/B1-01 on BI0113-16 No noncompliance moted Major areas inspected quality records on structural installation to observation of pump & valve installation. ERB.C M. Region 3. Chicago. Office of the Director DANIELBON.D.H. Region 3. Chicago, Reactor Construction & Engineering Support Breach. BI/02/05. 40p. 07943-262
- 8103020128 Forwards IE Circular B1-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. MEPPLER, J O Region 3, Chicago, Office of the Director 81/02/09 289 07788 032
- 8103050179 Act receipt of 010202 ltr informing NRC of steps taken to correct violation noted in IE Imap Rept 30-483/80-27. FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch. 81/02/09. 19. 07825
- --8103050192 Responds to NRC 810106 ltr re-violations noted in IE Insp. Rept 50-483/80-27. Corrective actions, engineer uill address all questions in surveillance clase-out memo & not rely on info stated in surveillance procedures.

  BRYAN-J. K. Union Electric Co. 81/02/02 4pp. 07825 186
- B1030310B7 Requests that encl preservice insp & test requirements to insure shubber operability be implemented at facility. TEDESCO. R. L. Assistant Director for Licensing. B1/02/10. 4pp. 07793:334.
- B103160672 Forwards (E Info Notice B1-04, "Cracking in Main Steam Lines," No response required. KEPPLER.J.G. Region 3. Chicago, Office of the Director. 81/02/27. 2pp. 07914, 284.
- B103170072 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation " No response required KEPPLER.J. 0 Region 3. Chicago, Office of the Director. 81/03/02. 2pp. 07939.191.
- 8103160981 Forwards revised IR Bulletin 81-01, "Burveillance of Mechanical Bhubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable dose not affect util requirements.

  KEPPLER.J.O. Region 3, Chicago, Office of the Director. 81/03/04 ip. 07915:004.
- BIO3110750 Ack receipt of BIO218 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-27. Notes sample of documentation packages of electrical mechanical components to be reviewed per BIO226 telcon. HEISHMAN.R.F. Region 3, Chicago, Office of the Director, BI/03/05. Ip. 07877:838.
- --Bi03i10757 Responds to NRC Bi0106 ltr re violations noted in IE Insp. Rept 50-483/80-27. Corrective actions: surveillance rept respond until outstanding questions resolved. Fittings inspected & unacceptable mati segregated.
  BRYAN-J. X. Union Electric Co. Bi/02/18 10pp. 07877: 239.
- 8103200378 Forwards IE Info Notice 81-05, "Failure of ITE Model K-600 Circuit Breaker." No response required.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 81/03/11.
  2pp. 07972:129.

- G103200662 Furwards 1E Info Notice 81-05. 'Degraded DC Sys Palisades No action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 20p. 07966 089
- B10320033B Forwards IE Info Notice B1-07. 'Potential Proble W/Hater-Soluble Purge Dam Matls Used During Inert Gas Walding.' No response required KEPPLER. J. Q. Region 3. Chicago. Diffice of the Director 2pp. 07466-270
- S. Reportable occurrences. LERs & related correspondence
- 8103100128 Part 21 Rept U-28 re OE 810109 notification of e certain Leran coil spools supplied u/HFA relays All suppo spools will be replaced u/black or clear Leran coil spool implementation schedule dependent on availability of part BRYANJ K Union Electric Co 81/02/12 2pp
- BiO3130040 Part 21 Rept V-27 re loose bushings in Bergen-Pa struts, initially reported 010130 Generic rept will be subnitted by SNUPPB on behalf of util & Union Electric Co Final rept will be issued by 010601 BRYAN, J. K. Union Electric Co. 01/03/02 2pp. 07912 04
- 8103160749 Interim Deficiency Rept U-26 re containment dome imperfections, initially reported on B01205 Meeting conduction B10305 re inspit testing Addl details & analysis will presented in B10401 final rept BRYAN, J. K. Union Electric Co. 81/03/06. 3pp. 07914 14
- BiO3310671 Interim deficiency rept re design interferences Paterson pipe support/shock arrestor assembly used to support B-20 inch pipe sections Caused by vendor failure notify users of revisions SEIKEN.S.J. Standardised Nuclear Unit Power Plant System 12pp. 08061 051
- DOCKET BTN-50-484 TYRDNE ENERGY PARK, UNIT 1, NORTHERN STAT A Application/construction stage documents & correspondence
- BIO3090696 Forwards order revoling CP Draft of identical HR encl.: EISEMHUT.D.O Division of Licensing 81/02/03 4pp 0
- --8103090700 Order revoking CP EIBENHUT,D.Q. Division of Licensing 01/02/03 2pp
- O Adjudicatory correspondence
- 8103090696 Forwards order revoking CP. Draft of identical IIR entl. EIBENHUT.D. G. Division of Licensing. 81/02/03. 4pp 0
- --8103090700 Order revoking CP EISENHUT, D. G. Division of Licensing 81/02/03 2pp
- H General correspondence
- 8103270591 Confirms 810318 telcon re-termination of LPDR co Stout Library since NRC revoked facility CP, Matl-is being sent to Hinneapolis for info only FR excerpt re-order enc SOUDER: J. L. Division of Rules and Records. 81/03/19 4 08044:245
- DOCKET BIN-50-485 STERLING POWER NUCLEAR PROJECT. UNIT 1

  A. Application/construction stage documents & correspondence
- 8103190387 Ltr to all licensess of operating plants & appli CLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NOREO-0737. EISENHUT D. Q. Division of Licensing. 81/01/19. App.
- F. Security, medical, emergency & fire protection plans
- 8103040110 Forwards facility emergency planning info.W/o BI SOVDER.J.L. Division of Rules and Records. 81/02/12 i 07819-325

- Instrumentation: No written response required GRIER.B H Region I. Philadelphia. Office of the Director 81/03/02 ip 07971 353
- 8103230206 Forwards revised IE Bulletin 81-01. "Surveillance of Hechanical Snubbers." W/corrected Pages 5 & 6 Change in identification of facilities W/CPs to which bulletin is applicable does not affect util requirements. RRIER.8 H Region 1. Philadelphia. Office of the Director 810/3704 p 07977 254
- B103200157 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breaker" No response required ORIER, B H. Region 1. Philadelphia. Office of the Director B1/03/11 | Ig 07968 279

### DOCKET 50-486 CALLAMAY PLANT. UNIT 2

- A Application/construction stage documents & correspondence
- Bi03190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREU-Obi2 Forwards NRC position re interim actions & request for addl info EISSKHUT.D 0 Division of Licensing 80/12/22 30pp.
- 810319/2387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed snyblye cold shutdown replacement parts & hUREO-0737 EISEKHUT.D.O Division of Licensing. 81/01/19 Gpp.
- 8103120014 Ltr to all licensees of operating plants CP holders & DL applicants except Indian Point 2 % 3 Zion 1 & 2 % TMI-1. Forwarding inadvertently omitted pages from NRC 801222 request for add info re control of heavy loads EESENSUT.D 0 Division of Licensing 81/02/03 6pp
- 6103250024 Ltr to all power reactor licensees & license applicants re MRRO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subsit analysis to justify use of existing low flow controller EISERNOT. D G. Division of Licensing 61/02/20 8pp
- 6103030770 Forwards add1 info re FBAR for facilities, in response to NPC B10107 request info provided re leak-tightness of control room buile gas protection, control room emergency ventilation sys & habitability sys PETRICK.N A Standardized Nuclear Unit Power Plant System. 81702724 32pp 07746-087
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except St Lucis Units 1 & 2). Requests util review to determine capability to mitigate station blactout event & promptly implement emergency procedures. EISEN-IJT 0 0 Division of Licensing Bi/02/23. Spp.
- Bio3230Bi3 Generic Ltr Bi-06 to all CP holders & OL applicants re iccr850 7l(e). "Periodic Updating of FBARs." effective 903722 Info re FSAR legal status format & content encl EIBENHUT.D G Division of Licensing Bi/02/26 10pp
- 8100050949 Forwards "Licensing Review Results for FSAR Chapter B (Electric Power) re Operation of SNUPPS Plants," summary of special review conducted to assist NRC in OL evaluation. PERRICK, N A Stendardized Nuclear Unit Power Plant System 91/02/27. 19 07826-275
- --B103050557 "Licensing Review Results for FBAR Chapter 8 (Electric Power) re Operation of BNUPPS Plants "
  CAPONE.D. CERMAX.J. REINLEIN.D. Standardized Nuclear Unit Power Plant System 81/02/27. 15pp 07826:276.
- 9109050642 Discusses OL review of facilities. Util is willing to espedite review. Requests that nore neetings be held w/Aurfliang Bys Branch & that NRC attempt to meet commitments for issuance of requests for addl info. PETRICK.M.A. Standardized Nuclear Unit Power Plant System. 81/02/27. 2pp. 07826:208
- 8:033:10804 Ltr to all licensees of operating plants, applicants for DLa 5 holders of CPs forwarding SECY-81-119 re info necessary to attablish anviron qualification of safety-related electrical equipment.

  ELSENHUT.D.O. Division of Licensing 81/03/10. 6pp.

- 8103240259 Forwards response to questions per Rt. Tedesco B10209 req re FBAR. Add1 Info uill be incorporated into FBAR in next revision & application BRYAN-J K Union Electric Co B1/03/20 11pp 07986-299
- 8103260613 Responds to NRC 810209 request for add1 info re FSAR, Infi will be incorporated into next revision PETRICK.N A Standardized Nuclear Unit Power Plant System 81/03/20 13pp 08040-317
- 8103270409 Forwards 703 oversize electrical instrumentation & controdraulings per NRC request Also forwards drawing list from Section 1 7 of FSAR Aperture cards will be available in PDR PETRICKIN A Standardized Nuclear Unit Power Plant Bystem 81/03/20 21pp 08158 314
- BIO327065B Discusses BIO319 meeting w/NRC Auxiliary Bys Branch to discuss ave water sys.ultimate heat eints & component cooling water sys.Util will provide addl discussion repotential for icing & debris to affect cooling tower. STRIGHT.R L Blandardized Nuclear Unit Power Plant Bystem B1703724 2pp 080403.004
- 8103310217 Forwards add1 into se FBAR.per NRC 810212 request info wi be incorporated into FBAR w/nest revision BRYAN.J K. Union Electric Co. 81/03/27 4pp 08060:232
- F Security, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements M/o encl CISENNUT. D. O. Division of Licensing. 81/03/09 600
- O Adjudicatory correspondence
- 8103190613 Reply to NRC 801110 response opposing admittance of patitioner Contention 1. Plant deficiencies are significant. Interim actions to compensate for deficiencies must be coordinated w/local govts Certificate of Svc encl REED.J 0. Affiliation Unknown 91/03/01. 10pp 07963 262.
- 8103130589 Notice of appearance in proceeding Certificate of Svc enc CHACKES.K M Hissourians for Bafe Energy. CHACKES.K.M Chactes Hoare 81/03/03 4pp. 07913:026
- B103120594 Responds to B1021B 1tr & telcon w/Lopb re special prehear conference. NRC would support request to defer limited appearance statement. Only one member of organization allowed to rake statement LEBBY.R.P. Antitrust Division B1/03/11. 2pp. 07904-252.

### if General correspondence

- 8103120239 Forwards K Drey 760108 ltr to Chairman Anders in response 810209 request. YOUNGBLOOD: B J Licensing Branch 1. 81702/19. ip. 07901:325
- --8103120249 Forwards magazine enticle from Jan 1976 Progressive re inherent dangers of nuclear energy NRC should require util to disclose info on financial ability to construct facility. DREY.K. Affiliation Unknown 76/01/08. Spp. 07901:326

### M Antitrust correspondence

- Bi03030899 Responds to B01217 ltr re-antitrust review for DL Any short-term sales or purchases (I yr or less) transacted under existing interchange agreements on file U/FERC. No plans made for new generating capacity beyond Unit 2. BRYAN-J K. Union Electric Co. BI/02/11. 9pp. 07795:145.
- Q. Inspection reports: IE Bulletins & correspondence
- 8103020686 Responds to IE Bulletin B0-23, "Failures of Bolenoid Valv Mfg by Valcor Engineering Corp." Util does not use specified valves in safety-related functions PETRICK, N. A. Bhandardized Nuclear Unit Power Plant Bystem. 81/02/05. 1p. 07782:134.

- valves.
  PETRICK: N.A. Standardized Nuclear Unit Power Plant System.
  B1/02/05 in 07/82 135
- Bi03020128 Forwards IE Circular Bi-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required MEPPLER.J 9 Region 3. Chicago. Office of the Director 81/02/09 2pp. 07788-032.
- 8103160672 Forwards IE Info Notice 81-04. "Cracking in Hain Steam Lines." No response required WEPPLER. O Region 3. Chicago. Office of the Director 81/02/27 200 07914 284.
- 8103;70072 Forwards 15 Circular B1-03. "Inoperable Seismic Monitoring Instrumentation." No response required MEPPLER.J 0 Region 3. Chicago. Office of the Director 81/03/02 2pp 07939-191.
- 8103140981 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Shubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  KEPPLER. J. 0. Region 3. Chicago. Office of the Director 81/03/04.

  1p. 07915:004.
- 8103200378 Forwards 1E Info Natice 81-06. "Failure of ITE Model K-600 Circuit Breaker." No response required KEPPLER. J O. Region 3. Chicago. Office of the Director 81/03/11. 2pp 07972 129
- 8103200662 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades." No action required MEPPLER.J O. Region 3. Chicago. Office of the Director. 81/03/13. 2pp. 07766-089.
- 8103200338 Forwards IE info Notice 81-07. "Potential Problem M/Water-Boluble Purge Dam Matls Used During Inert Cas Helding." No response required. KEPPLER, J. G. Region 3. Chicago. Office of the Director 81/03/16. 2pp. 07966:290
- S Reportable occurrences. LERs & related correspondence
- 8103120175 Interim Part 21 rept re weld discrepancies in main control panels & auxiliary relay racks Generic program developed to assess impact of weld discrepancies Completion of program espected by 810701.

  BRYAN.J.K. Union Electric Co... 81/03/02 2pp.
- 8103160749 Interim Deficiency Rept U-26 re containment dome imperfections, initially reported on 801209 Meeting conducted on 810309 re insp & testing Addl details & analysis will be presented in 810401 final rept.

  BRYAN.J.K. Union Electric Co. 81/03/06. 3pp. 07914:142.
- 8103310671 Interim deficiency rept re design interferences in Berger Paterson gipe support/shock arrestor assembly used to support 8-20 inch pipe sections Caused by vendor failure to notify users of revisions.

  86IKEN-8.J. Btandardized Nuclear Unit Power Plant System. 81/03/17.
  129a. 08061:051.
- DOCKET BTN-50-400 PERKINS NUCLEAR STATION. UNIT | A Application/construction stage documents & correspondence
- BiO31903B7 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown replacement parts & NUREO-0737.

  EIBENHUT, D. O. Division of Licensing. 81/01/19 6pp.
- 8103180039 Unofficial transcript of Commission 810212 meeting in Washington.DC re 8ECY-81-20 policy on proceeding w/pending CP & mfg license applications. Pp 1-f13 a Commissioners. 81/02/12. 117pp.
- --8103030450 Recommends Commission approve enci draft final rule 10CFR50 re licensing requirements for pending CPs & ofg license applications & proposed statement of requirement re degraded core rulementing.

  DIRCKB-W.J. Diffice of the Executive Director for Operations, SECY-61-020A 81/02/11. 12pp.

- to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller FISEAMURING Division of Licensing 81/02/20 Gpp
- 8103090007 Requests info to schedule for licensing activities for facilities
  EISELBLID D. D. Division of Licensing 81/02/23 300 07849 2
- 8103170457 Responds to MAC 810223 request for add) info he util per facilities Completion of Cherokee 1 & 2 has been indefinitely dolayed Comercial operating dates for Cherokee 3 & Perkins 1.2 & 3 have not been determined AMLLLC Duke Power Co 81/03/12 2p 07934 339
- 9 Adjudicatory correspondence
- 8103200549 Presents reasons why ASLAS should proceed d/oral argume alternate site insues as previously scheduled PRREER & L. Duke Power Co. 81/03/10 4op. 07971-235
- BIO3260595 Discusses intervenor position relectif BIO310 response ASLB BIO225 inquiry relirdefinite suspension of constiplans at site Application should be suspended or dismissed until issues to schedule commitments have been resolved PFEFFERKORN. W. Preferiorn & Cooley. P.A. BI/O3/16 4pp cancelled.
- Bio3iB0610 Notice of appearance in proceeding Certificate of Svc TURK-S.E. Office of the Executive Legal Director Bi/03/17 07947-272
- 8103196059 Informs of MRC conclusions that pending appeal should heard new ASLAB & parties will have to expend further time by resources, but value of resources already expended will be preserved TURK-S.E. Office of the Executive Legal Director 81/03/17 07964, 120
- 8103230081 Informs that SE Turk will present argument on behalf of at 810401 or all argument Atty previously assigned to present or all argument will be unable to do so. TURK. B. E. Office of the Executive Legal Director 81/03/19 07978 303
- 8103290436 Memorandum discussing reasons to continue appeal from 800222 partial initial decision despite unclear util plans Recommends proceeding since adequate assessment can not be made of difference tine will make to water adequacy issue BISHOP.C J. Atomic Safety and Licensing Appeal Panet. 01/03/29pp 07997 344.
- I financial information
- B103310549 Forwards Annual Financial Rapt 1980, annual certified financial statements, 1981-83 financial forecast & util statement re available funds to satisfy liability Info guarantees retrospective premiums per 10CFR140 26 THIES.A C. Dute Power Co. B1/03/24 1p
- ~~BIO3310438 Annual Finencial Rept 1980. Including finencial state 1981-83 finencial forecast & statement re sources of available funds to satisfy liability. HORN,C. Dute Power Co. 81/02/13 Sipp
- O Inspection reports. IE Sulletins & correspondence
- 8103050238 Responds to IE Bulletin 80-21. "Valve Yokes Supplied b Malcolm Foundry Co.Inc " No valve yokes mêg by Malcolm Foundry Co.Inc are used at plants. DAIL.L.C. Duke Power Co. 81/01/27. 1p
- B103020242 Forwards IE Circular 81-02, "Performance of NRC-Licens Individuals While on Duty." No written response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director 61/0 1p. 07785.316.
- 8103160677 Forwards IE Circular 81-03, "Inoperable Seismic Monito Instrumentation," No response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/0 1p. 07914:31:
- 8103170033 Forwards revised IE Bulletin Bi-Oi, "Gurveillance of Mechanical Bnubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/0 ip 07939.160.

- BIGGGCO289 Forwards IE Info Notice Bi-O6. 'Failure of ITE Model K-609 Circuit Breaker' No response required DiREILLY. J. P. Region D. Atlanta. Dirice of the Director. 81/03/11 to 07949 Q28
- 8163200224 Forwards IE Info Notice 81-05. Degraded CC Sys at Fallsades "No response required CPEILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/13 | 07969 090
- DOCKET BIN-50-489 PERKINS NUCLEAR BIATION. UNIT 2

  A Application/construction stage docu-ents & correspondence
- 8:03190387 Ltr to all literisees of operating plants & applicants for OLS & holders of CPs re program for environ qualification of safety-related electrical equipment liters addressed involve cold shutdown replacement parts & NUREG-0737 EISEMHUT.D 0 Division of Licensing 0:1701/19 app
- 910318C039 Unofficial transcript of Conmission B10212 meeting in Wishington-DC to SECY-81-20 policy on proceeding Wypending CP & Ifg license applications Pp 1-115

  \*\*Cormissioners\*\* B1/02/12\*\* 11786

  \*\*Cormissioners\*\* B1/02/12\*\* 11786
- --BID3030450 Recommends Commission approve encl draft final rule 10CFR50 re licensing requirements for pending CPs & mfg license applications & proposed statement of requirement re degraded care rulemaking pECXXS.U J Defice of the Executive Director for Operations SECY-BI-020A BI/02/II 12pp
- B103290024 Lir to all power reactor licensees & license applicants re MAREO-0619 triteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow centroller EISELHUT. D 9 Division of Licensing B1/02/20 App
- 6103090007 Requests info to schodule for licensing activities for facilities EGSENVII.D 9 Division of Licensing 61/02/23 3pp 07849 242
- 9103170457 Responds to NRC B10223 request for add1 info re util plans for facilities Completion of Cherokee 1 & 2 has been indefinitely delayed Connercial Operating dates for Cherokee 3 & Perkins 1.2 & 3 here not been determined DAIL.E. C. Duke Power Co. B1/03/12 2pp 07734 039
- Q Adjudicatory correspondence
- 8103200549 Presents reasons why ASLAB should proceed w/ora) argument to alternate site issues as previously scheduled PERTEEN L Duke Power Co 81/03/10 4pp 07971 233
- 8103260995 Discusses intervenor position re util 810310 response to ASLB 810225 inquiry re indefinite suspension of const plans at site Application should be suspended or dismissed until issues re schudule commitments have been resolved rEFFFERKORN. Perferiorn & Cooley. P. A. 81/03/16 App. 881/03/16 195
- 8103189610 Notice of appearance in proceeding Certificate of 9vc encl TURK.8 E Office of the Erecutive Legal Director 81/03/17 3pp 07947 272
- 8103190059 Informs of N9C conclusions that pending appeal should be heard now ASLAB & parties will have to expend further time & resources, but value of resources already expended will be preserved TURALS E. Office of the Executive Legal Director. 81/03/17. 7pp 07964-120
- Gi00230081 Informs that SE Turk will present argument on behalf of NRC at 810401 oral argument. Atty previously assigned to present oral argument will be unable to do so TURK & E Office of the Riecutive Legal Director 81/03/19 [p 07978.303.
- B103250436 Memoranium discussing reasons to continue appeal from ABLB BY222 partial initial decision despite unclear util plans Recommends proceeding since adequate assessment can not be made of difference time will make to water adequacy issue BISHOP.C.J. Atomic Safety and Licensing Appeal Panel B1/03/20 9pp 07997, 344

### 1 Financial information

- 8103310549 Forwards Annual Financial Rept 1980, annual certified financial statements. 1981-83 Financial forecast & util statement re available funds to satisfy liability info guarantees retrospective premiums per 100FR140 26 HHIEB.A & Dute Power Co. 81/03/24 to
- ~-B103310638 Annual Financial Rept 1980 including financial statem 1981-83 financial forecast % statement re sources of available funds to satisfy liability HORN.C Duse Power Co. 01/02/13 Sipp

### G. Inspection reports: IE Bulletins & correspondence

- 8103020242 Forwards IE Circular 81-02. 'Performance of MRC-License Individuals While on Duty ' No written response required O'REILLY. J. P. Region 2. Atlanta, Office of the Director 81/02 to 1.
- 8103160677 Forwards TE Circular 81-03. 'Inoperable Belanic Monitor Instrumentation " No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03 1p 97914 311
- 9103170033 Forwards revised IE Sylletin 81-01, "Surveillance of Mechanical Snubbers," D/corrected Pages 5 5 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements O'REILLY. J. P. Region 2. Atlanta. Office of the Director 81/03, 1p. 07939-160
- G103200289 Forwards IE info Notice Bi-Ob. "Failure of ITE Model K-Circuit Breaker" No response required
  O'REILLY.J P. Region 2. Atlanta. Office of the Director B1/03.

  1p. 07849 028
- 8103200924 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades," No response required. U'REILLY, J.P. Region 2: Atlanta, Office of the Director 81/03, In
- DOCKET 97N-90-490 PERKING NUCLEAR BYATION. UNIT 3
- A. Application/construction stage documents & correspondence
- 8103190397 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment liters addressed involve cold shutdown replacement parts & NUREQ-0737. EISENIUT.D O. Division of Licensing 81/01/19 6pp.
- B103180039 Unofficial transcript of Commission 810212 meeting in Mashington. DC re BECY-B1-20 policy on proceeding U/pending CP & mfg license applications Pp 1-115 commissioners B1/02/12. 117pp
- --Bi03030450 Recommends Commission approve encl draft final rule 10 re literaing requirements for pending CPs & mfg literase applications & proposed statement of requirement re degraded core tuleraking DIRCKS.W J. Office of the Elecutive Director for Operations. SECV-BI-020A Bi/02/11 12pp
- Bio3290024 Ltr to all cower reactor licensess & license applicants NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licenses may submit analysis to justify use of assisting low flow controller.

  EISENHUT.D Q Division of Licensing Bi/02/20 Bpp
- B103090007 Requests info re schedule for licensing activities for Facilities. EISENHUT-D O. Division of Licensing. B1/02/23 3pp 07849:242
- B103170497 Responds to NRC B10223 request for add1 info re util pla for facilities Completion of Cherokee I & 2 has been indefinitely delayed. Commercial operating dates for Cherokee 3 & Perkins 1.2 & 3 have not been determined DAIL-L C Duke Power Co 81/03/12 2pp. 07934 339.

#### Q. Adjudicatory correspondence

B103200549 Presents reasons why ABLAB should proceed u/oral argument relaterate site issues as previously scheduled.

PORTER-N.L. Dute Power Co. 81/03/10 4pp. 07971:235.

- 8103260575 Discusses intervenor position re-util 810310 response to ABLB 810225 inquiry re-indefinite suspension of const plans at site Application should be suspended or dismissed until issues to schedule commitments have been resolved PPEFFERNORN, W. Prefferiorn & Cooley, P.A. 81/03/16 4pp.
- B103180410 Notice of appearance in proceeding Certificate of Swc encl TURK.8 E. Office of the Executive Legal Director B1/03/17 3pp 07947 272
- 8:03:90059 Informs of NRC conclusions that pending appeal should be heard now ASLAB & parties will have to expend further time & resources but value of resources already expended will be preserved
  TURK.8 E. Office of the Executive Legal Director 81/03/17 7F2
- 81032300B1 Informs that SE Turk will present argument on behalf of NRC at 910401 oral argument Atty previously assigned to present oral argument will be unable to do so.

  TURK-8 E. Office of the Executive Legal Director 81/03/19 1p 07978-303
- 8103280436 Hemorandum discussing reasons to continue appeal from ASLB 800222 partial initial decision despite unclear util plans. Recommends proceeding since adequate assessment can not be made of difference time will make to water adequacy issue 818HOP.C J. Atomic Safety and Licensing Appeal Panel. 81/03/20. 9pp. 07997:344
- I Financial information

07964 120

- B103310549 Forwards Annual Financial Rept 1980, annual certified Financial statements, 1981-83 financial forecast & util statement re available funds to satisfy isability, info guarantees retrospective preniums per 100FR140.26. THIES.A.C. Duke Power Co. 81703/24 10
- ~-B10331063B Annual Financial Rept 1980, including financial statements, 1981-83 financial forecast & statement re sources of available funds to satisfy liability.
  HORM.C. Duke Power Co. 81/02/13 51pp
- Q. Inspection reports. 1E Bulletins & correspondence
- B103020242 Forwards IE Circular 81-02. Performance of NRC-Licensed Individuals While on Duty "No written response required DYREILLY, J.P. Region 2. Atlanta, Office of the Director 81/02/09 ip.
- 8103160677 Forwards IE Circular 81-03, "Inoperable Beismic Monitoring Instrumentation " No response required.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 81/03/02.
  1p 07914:311.
- Bi03170033 Forwards revised IE Bulletin Bi-01, "Burveillance of Mechanical Snubbers," w/corrected Pages 5 & 6.Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. Bi/03/04. jp. 07939:160.
- 8103200289 Forwards IE Info Notice 81-06. "Feilure of ITE Model K-600 Circuit Breaker." No response required. O'REILLY.J.P. Region 2. Atlanta. Office of the Director 81/03/11 ip. 07967:028.
- 8103200024 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No response required.
  O'AEILLY, J. P. Region 2, Atlanta, Diffice of the Director. 81/03/13-16.
- DOCKET BTN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
  A. Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants, applicants for DLs & holders of CPs re-control of heavy loads. Requests review per guidelines in MNREO-Odia. Forwards NRC position re-interim actions & request for addl info. ETBENHUT. D. Q. Division of Licensing. 80/12/22. 30pp.
- 8103190387 Ltr to all licenses of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREO-0737. EIBENHUT.D.G. Division of Licensing. 81/01/19. App.

- BIO3120014 Ltr to all licensees of operating plants.CP hol applicants.escapt Indian Point 2 % 3.7ion 1 % 2 % TMI-1. forwarding inadvertently oritted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D 0 Division of Licensing 81/02/03 opp
- BiD3160667 Ltr to all operating plants & CP holders for an clarification of TMI Action Plan Item III A L 2 re upgrade mergency support facilities Requests confirmation us 45 days that implementation dates will be net EISEMHJI.D O Division of Licensing BI/02/IB 12pp
- B103250024 Ltr to all power reactor licensees & license as MUREO-0619 criteria Footnote 2 in Table 2 contains error to leakage testing elections Licensee may subnit analysi justify use of existing low flow controller EISENHUT.D Q Division of Licensing B1/02/20 Bpp
- 8103090007 Requests info re schedule for licensing activities facilities FISSEMULD 0 0 Division of Licensino 81/02/23 3pp.
- 8103090578 Forwards PHR const milestones & activities for 2.Catawba 1 & 2 & Cherokee 1 Mey event dates provided. GRODAN.J.F. Duke Power Co. 81/02/24. App
- B103230B13 Generic Ltr 81-06 to all CP holders & OL applic 10CFR5D 7f(e). "Periodic Updating of FSARs," effective B00722 Info re FSAR legal status format & content encl E16ENHULD 0. Division of Licensing. B1702726. 1Opp
- 810310D567 Forwards 810224 press release re delay of facility completion Financial situation has pushed facility completion into indefinite future DATLL C Dute Power to 817/3/04 2pp 07863.103.
- 8103310804 Ltr to all licenses of operating plants applic & holders of CPs forwarding SECY-81-119 re into necessar establish environ qualification of safety-related electr equipment EISECHUIV.D 9 Division of Licensing. 81/03/10 App
- B103170457 Responds to NRC B10223 request for add1 info re for facilities Completion of Cherokee 1 & 2 has been indefinitely delayed Commercial operating dates for Cher 3 & Perkins 1, 2 & 3 have not been determined DATL.L.C. Duke Power Co. B1/03/12 2pp
- F Becurity, medical, emergency & fire protection plans
- 810331033B Ltr to all licensees of operating plants & hole forwarding NUREC-0696. "Functional Criteria for Emergenc Response Facilities" Criteria describe acceptable metho for meeting NRC requirements. I/o encl. ETBENHUT. D. O Division of Licensing 81/03/05 6pp

## I Financial information

- 8103310549 Formands Annual Financial Rept 1980.annual cerfinancial statements.1981-83 financial forecast & util statement re available funds to satisfy liability Infoguarantees retrospective premiums per 100FR140.26. THIES.A C. Duke Power Co. 81/03/24. 1p
- --BIO331063B Annual Finencial Rept 1980, including financial 1981-83 financial forecast & statement re sources of available funds to satisfy liability.
  HORN.C. Duke Power Co. 81/02/13 Sipp.
- Q. Inspection reports, 1E Bulletine & correspondence
- B1030502B1 Forwards IE Insp Repts 50-491/80-10, 50-492/80-50-493/80-10 on 801202-05, No noncompliance noted. MWRPHY.C E. Region 2. Atlanta. Reactor Construction & E Support Branch. 81/01/20. 1p. 07825:347.
- --Bi03050288 IE Insp Repts 50-491/80-10.80-492/80-10 & 50-801202-05.No noncompliance noted Hajor areas inspected structural concrete nuclear set water dam.const status action on previous insp findings.

  HARRIB.J.R. Region 2. Atlanta. Office of the Director CONLONIT.E. Region 2. Atlanta. Reactor Construction & Support Branch. Bi/01/20. 3pp. 07825:348
- 910305023B Responds to IE Bulletin 80-21, "Valve Yokes Suj Malcolm Foundry Co.Inc." No valve yokes mfg by Malcolm Foundry Co.Inc are used at plants, DAIL-L.C. Duke Power Co. 81/01/27, Ip

- 8103029242 Forwards IE Circular 81-02. Performance of NRC-Licensed (-dividuals While on Duty " No written response required DMEILLY.J P. Region 2. Atlanta. Office of the Director B1/02/07 ip 07785.316
- 8103160677 Forwards IE Circular 81-03. 'Inoperable Geismic Monitoring Instrumentation' No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 81/03/02
- BIO3170033 Forwards revised IC Bulletin 81-01. "Surveillance of Mechanical Enubbers." w/corrected Pages 5 & 6 Change in identification of Pacifities w/CPs to which builetin is applicable does not affect util requirements

  O'REILLY, J. P. Region 2, Atlanta. Office of the Director 81/03/04 to
- BIO3200289 Forwards 1E Info Notice 81-96. "Failure of ITE Model K-600 Circuit Breater " No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director BI/03/11
- B103203024 Forwards IE Info Notice B1-09. "Degraded DC Gys at Palisades" No response required O'REILLY.J P Region 2. Atlanta. Office of the Director B1/03/13 in 07967 079
- S Reportable occurrences. LERs & related correspondence
- E103033854 PhD-11-81-018 on B10224 notification received re indefinite const delay on facilities Work on Unit I will be reduced & const on Unit 2 will be stopped Caused by Financial problems
  PEEBLES.T. BRYANT. J. C. Region 2. Atlanta. Office of the Director 81/02/25 1p 07797 339
- GCCMET STN-50-492 CHERCARE NUCLEAR STATION, UNIT 2 A Application/construction stage documents & currespondence
- E103190732 Ltre to all licensess of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in RUREG-0612 Forwards NRC position re interin actions & request for addl info CEENHUT. D.O. Division of Licensing 80/12/22 30pp
- et03190387 Ltr to all licensees of operating plants & applicants for OLS holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdoum-replacement parts & NUREO-0737 EISERNUT.D Q Division of Licensing 81/01/19 App.
- 8103120014 Ltr to all licensees of operating plants CP holders & OL applicants, except Indian Point 2 & 3, Zion 1 & 2 & THI-1, forwarding inadvertently omitted pages from NRC B01222 request for addl info re control of heavy loads EISEMMUT, D O Division of Licensing. 81/02/03 6pp
- BIO3160669 Ltr to all operating plants & CP holders forwarding clarification of TMT Action Plan Item III A 1 2 re upgrade of erespency support facilities Requests confirmation within 45 days that implementation dates will be met EISERHUT, B Q. Division of Licensing. 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re AMREO-0519 criteria Footnote 2 in Table 2 contains error due to leafage testing delations Licensee may submit analysis to justify use of existing low flow controller EIBENHUT.D 9. Division of Licensing 81/02/20 Bpp
- 8103C90607 Requests info re-schedule for licensing activities for facilities EISERHUI.O G Division of Licensing 81/02/23 3pp
- 8103090578 Forwards PMR const milestones & activities for McOuire & 2.Catauta & 8.2 & Cherokee I key event dates provided GROOMIN. J.F. Dute Power Co. 81/02/24 & pp.
- 8103230813 Oeneric Ltr 81~06 to all CP holders & OL applicants re 100f850 71(4). "Periodic Updating of FSARs." effective 800722. Info re FSAR legal status, forrat & content encl EISERHUT.D.O. Division of Licensing. 81/02/26 10pp
- BiO3100567 Forwards BiO224 press release re delay of facility completion Financial situation has pushed facility completion into indefinite future palt.L.C. Oute Power Co. Bi/O3/04 2pp 07863 103

- B103310804 Ltr to all literages of operating plants.applicants for OL: A holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENWID 2 0 (vision of Licensing 81/03/10 App
- 8103170457 Responds to NRC 810223 request for add1 info re util plans for facilities Completion of Cherokee 1 & 2 has been indefinitely delayed Commercial operating dates for Cherokee 3 & Pertins 1,2 & 3 have not been determined DAIL-L C Dute Power Co 81/03/12 2pp
- F Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding MyRCO-0695. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements W/o encl EISEMMUT.D Q Division of Licensine B1/03/05 doe

## I Financial information

- 8103310549 Forwards Athnual Financial Rept 1980, annual certified financial statements. 1981-83 financial forecast & util statement re available funds to satisfy liability info guarantees retrospective premiums per 10CFR140 26 THIEB.A G Dute Power Co 81/03/24. ip
- --BIO3310639 Annual Financial Rept 1980. including financial statements: 1981-93 financial forecast & statement re sources of available funds to satisfy liability HORN.C Duke Power Co 81/02/13 51pp
- Q Inspection reports. IE Bulletins & correspondence
- 8103050281 Forwards IE linsp Repts 50-491/80-10.50-492/80-10 & 50-493/80-10 an 801202-05 No noncompliance noted MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/01/20 1p 07825-347
- ---8103080288 IE Insp Repts 50-491/80-10-50-492/80-10 & 50-493/80-10 on B01202-05 No noncompliance noted Major areas inspected structural concrete nuclear ave water dam.const status & action on previous insp findings HARRIS-JR Region 2. Atlanta, Office of the Director CONLON-TE. Region 2. Atlanta, Reactor Construction & Engineering Support Branch B1/01/20 3pp. 07823 348.
- 8103050238 Responds to IE Bulletin 80-21. "Valve Yotes Bupplied by Malcolm Foundry Co. Inc." No valve yokes mfg by Melcolm Foundry Co. Inc. are used at plants
  DAIL-L C Dute Power Co. 81/01/27 Ip
- 8103020242 Porwards IE Circular 81-02, 'Performance of NRC-Licensed Individuals While on Duty "No written response required. O'REILLY, J.P., Region 2, Atlanta, Office of the Director. 81/02/09 to.
- ©103160677 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation." No response required D'REILLY J P Region 2. Atlanta. Diffice of the Director 91/03/02. 1p.
- 8103170033 Forwards revised IE Bulletin 81-01, "Surveillance of Machanical Enubbers," w/corrected Pages 3 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not effect util requirements

  O'REILLY, J P Region 2- Atlanta, Office of the Director 81/03/04 lp.
- B100200289 Forwards IE Info Notice Bi-Ob. "Failure of ITE Model K-600 Circuit Breater." No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B1/03/11. to
- 8103200024 Forwards IE Info Notice 81-05. 'Degraded DC 8ys at Palisades.' No response required.
  B'REILLY-J.P. Region 2. Atlanta, Office of the Director. 81/03/13.
  1p. 07969-090.
- S. Reportable accurrences: LERs & related correspondence
- B103030854 PNO-II-B1-018 on 810224 notification received re indefinite const delay on facilities Work on Unit 1 will be reduced & const on Unit 2 will be stopped Caused by financial groblems.

  PEEBLES.T., SRYANT, J.C. Region 2. Atlanta, Office of the Director.

  B1/02/25. 1p 07797: 339.

COCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3 A. Application/construction stage documents & correspondence

- B100190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re-control of heavy loads Requests review per quidelines in NUREO-0612 Forwards NRC position re interim actions & request for addl info
  EISENAUT.D G Division of Licensing 80/12/22 30pp FISENHUT, D. G.
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPs re-program for environ qualification of sefety-related electrical equipment. Items addressed involve cold shutdown replacement parts 5 NUREC-0737 EISENHUED O Division of Licensing 81/01/19 6p
- BIOGI20014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.2ion 1 & 2 & TMI-I. forwarding inadvertently orditted pages from NRC BD1222 request for addlinforce control of heavy loads EISENHUT.D O Division of Licensing B1/02/03 App
- 8103160669 Ltr to all operating plants & CP holders Forwarding clarification of TMI Action Plan Item III A 12 ne uggrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT. D. O Division of Licensing 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of eristing low flow controller EISENHUT.D.O. Division of Licensing 81/02/20 82p
- 8103090007 Requests info re schedule for licensing activities for EISENHUT, D. Q. Division of Licensing 81/02/23 3pp
- 8103090578 Forwards PHR const milestones & activities for McGuire 1 & 2. Catawha 1 & 2 & Cherokee 1 Key event dates provided. GROGAN-J F. Duke Power Co 81/02/24 dpp
- 8103230Bi3 Generic Ltr Bi-05 to all CP holders & GL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." affective 800722 Info re FSAR legal status.format & content encl EISENHUT, D. O. Division of Licensing 81/02/26 10pp
- BICCC310804 Ltr to all licensees of operating plants applicants for OLs B holders of CPs forwarding BECY-BIT-119 re snfo necessary to establish environ qualification of safety-rejated ejectrical equipment EISENHUT, D. Q. Division of Licensing 81/03/10 App
- 8103170457 Responds to NRC B10223 request for add) info re util plans for facilities Completion of Cherokee 1 & 2 has been indefinitely delayed Comercial operating dates for Cherokee 3 & Perkins 1.2 & 3 have not been determined DAIL, L.C Dute Power Co 81/03/12
- F Becurity, medical, emergency & fire protection plans
- 8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements W/o encl EIBENHUT D. C Division of Licensing. 81/03/05 6pp

## I Financial information

- 8100310549 Forwards Annual Financial Rept 1980, annual certified indicated a statements 1991-83 financial forecast & util statement re available funds to satisfy liability info guarantees retrospective premiums per 10CFR140.26. THIEB-A.C. Duke Power CO 81/03/24. 1p.
- --8103310639 Annual Financial Rept 1980, including financial statements. 1981-83 financial forecast % statement re sources of available funds to satisfy liability HORN.C. Duke Power Co. 81/02/13 51pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 8103050281 Forwards 15 Insp Repts 30-491/80-10, 50-492/80-10 & 50-493/80-10 on 801202-05. No noncompliance noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 81/01/20 1p 07825-347.

- --8103050288 IE Insp Repts 50~491/80~10.50~492/80~10 % 50~493/80~ AD1202-05 No noncompliance noted Major areas inspected structural concrete nuclear svc water dam const status & structural concrete.nuclear see Water variconst status & action on previous insp findings
  HARRIS.J.R. Region 2. Atlanta. Office of the Director
  CDN.DU.Y E. Region 2. Atlanta. Reactor Construction & Engine
  Support Branch 81/01/20 3pp 07825 348
- 8103090238 Responds to IE Sulletin 80-21. "Valve Yokes Supplies o Malcolm Foundry Co. Inc." No valve yokes m/g by Malcolm Foundry Co. Inc. are used at plants
  - DAIL.L C Dute Power Co 81/01/27 10
- B103020242 Forwards IE Circular B1-02, 'Performance of NRC-Licers Individuals While on Duty ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/0 Ip 07785 316
- B103160677 Forwards IE Circular B1-03, "Inoperable Sessmic Monsto Instrumentation" No response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 91/0 1 0
- 8103170033 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Snubbers," w/corrected Pages 9 & 6 Change in identification of facilities 1/CPs to which bulletin is applicable does not affect util requirements O'REILLY, J.P. Region 2. Atlanta (1861) Region 2. Atlanta, Office of the Director 81/0
- B103200289 Forwards IE Info Notice 81-06. "Failure of ITE Model & Circuit Breaker" No response required O'RELLUTJ P. Region 2. Atlanta. Office of the Director B1/0 10
- 8103200024 Forwards IE Info Notice 81-05, "Degraded CC Sus at Palisades "No response required
  D'REILLY-JP Region 2. Atlanta. Office of the Director 91/0 10
- DECKET 50-496 MONTAQUE NUCLEAR POWER STATION, UNIT 1 Q Adjudicatory correspondence
- 8103050662 Response supporting applicant 810210 motion to termina proceeding due to withdrawal of CP application Certificate KETCHEN, E 9 Hearing Branch 4 81/03/02 3nn 07829 254
- 8103300247 Order granting applicants' 810210 motion to terminate proceeding RECHHDEFER.C Atomic Bafety and Licensing Board Panel 81/03/ 2pp 08057 143
- J. Insurance & indemnity information
- 8103100411 Forwards Endorsement 5 to RELIA Binders EB-15 % EB-1A CONNELL T. J. Northeast Utilities 81/03/04 2pp
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2
- G. Adjudicatory correspondence
- 8103090/82 Response supporting applicant 810210 motion to termina proceeding due to withdrawal of CP application Certificate of 8vc enci KETCHEN.E O Hearing Branch 4 81/03/02 3pp 07829 264
- B103300247 Order granting applicants' Bi0210 notion to terminate proceeding. BECHHOEFER.C Atomic Bafety and Licensing Board Panel. 81/03/ 200 08057.143
- J. Insurance & indemnity information
- 8103100411 Forwards Enforsement 5 to MELIA Binders E8-15 & E8-16 CONNELL.T.J. Northeast Utilities 81/03/04 2pp

- EDCHET SIN-50-498 SOUTH TEXAS PROJECT. WILT 1
- A Application/construction stage documents & correspondence
- 9103041035 Requests authorization for limited restant of complex safety-related concrete & safety-related ANS & ASHE welding on 801006 Corrective actions for previously identified noncompliances are essentially completed GPREA.OR Houston Lighting & Power Co. 80/10/02 9pg 07813 346
- 8103350304 Updates 801002 request re re-examination, repair & restart of safety-related ASMS welding activities Util requests authorization to commence limited welding on 801124 Description of program & schedule encl OPERA Q W Houston Lighting & Power Co 60/11/19 11:pp app 270.2
- 8103041023 Modifies Attachment I.Line 1R of util 801119 | tr recomment cooling water sys in Unit I rechanical electrical auxiliar, bldg
  OPERA, OF Houston Lighting & Power Co. 80/12/02 400 07813 342
- 8103199732 Ltrs to all licensees of operating plants applicants for Its & holders of CPs re toutrol of heavy loads Requests review per guidelines in NUREG-C612 Forwards NRC position re interim actions & request for addl info £15£1M-JT.D O Division of Licensing 80/12/22 30pp
- 8:03031067 "Environ Statements Project." monthly progress mept for Dec 1980 21TTEL.H E. Uak Ridge National Laboratory. FIN 8-0766-1 810303:067 80/12/31 4pp
- 8103190387 Lit to all licensees of operating plants & applicants for (X.s. & holders of CPs to program for environ qualification of ladely-related electrical equipment liters addressed involve cold shutdown replacement parts & huREO-0737 EISEL-WI-D-0 Division of Licensing 8170[719 App
- BID3120014 Ltr to atl licensees of operating plants.CP holders & U\_applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently ontited pages from LRC 801222 request for addlinfore control of heavy loads EIBENHILD 0 Division of Licensing 81/02/03 App
- 8103059085 Forwards revised NRC Region 4 organization chart effective 810227 5EVFRIT.X V Region 4. Dailas. Office of the Director 81/02/18 292 07831 358
- 3103130714 Authorizes substitution of AEME safety-related welding SEYFRIT.R V Region 4. Dallas, Office of the Director. 81/02/19 1p. 07712-055
- 8103250024 Ltr to all power reactor licensues & license applicants re MUREQ-0519 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISEMHULD 0 Division of Licensing 81702/20 8pp
- 8103230030 Ltr to all licensees of operating nuclear power plants & applicants for OLs (except 8t Lucie.Units 1 & 2) Requests util review to determine capability to miligate station tlackout event & promptly implement emergency procedures. EISENHUT. 0 0 Division of Licensing 81/02/23 5pp
- B10323CB13 Oeneric Ltr B1-06 to all CP holders & CL applicants re 10CFR50 71(e). "Periodic Updating of FSA9s." effective 900722. Info re FSAR legal status format & content encl EISENMUT.O 0 Division of Licensing 81/02/26 10pp
- 8103050658 Forwards add1 info re application of cladding & swelling & rupture rodels for LOCA analysis, por NAC 801014 request Evaluation of petential impact of NUREG-0630 using fuel rod models and 1 OOLDEERS. J.H. Houston Lighting & Power Co. 81/02/27 App. 07832-018
- 8103090558 Forwards evaluation of cladding swelling & rupture models for LCCA analysis, per NYREC-0330, in response to NRC 801014 ltr.FSRA will be amended by 810501 to reflect ten grid fuel design.

  GOLDEERO, J. H. Houston Lighting & Power Co. 81/12/27. 6pp 07850, 198

- 8103200077 Informs that staff functions of Region 4 reassigned, effective 810227 OL Madson.Chief of Reactor Projects Branch, designated as principal contact & recipient of correspondence re-reactor const & operation activities SEYFRIT. A V Region 4. Dallas. Office of the Director 81/03/0 in 07071 339
- BIO3310804 Ltr to all licensees of operating plants applicants for & holders of CPs forwarding SECY-BI-119 re info necessary to establish environ qualification of safety-related electrical equipment EISENMUT.D 9 Division of Licensing 81/03/10 App
- B103200795 Presents info verifying adequaty of corrective actions committed to in response to NRC order to show cause ASME safety-related welding will be resured on regular basis on B10316 OPREA.9 W. Houston Lighting & Power Co. 81/03/13 3pc. 07967
- 8103200250 Forwards Amend 15 to FSAR Amend consists of changes to Chapter 13 & vorious technical & editorial changes to other chapters of FSAR Chapter 13 reflects current util organization re facility CCLOBERG, J H Houston Lighting & Power Co 81/03/18 4pp 07971 074
- --8103200304 Arend to DL application revising Chapter 13 to FSAR recurrent util organization relating to facility
  GDLDBERGOULH Houston Lighting & Power Co. 81/03/14 2pp
  07971:078
- B103270699 Submits corrections to NRC B10306 trip rept re B10217-1 meeting Organizational structure & operations QA program will be complete by end of 1981 Staffing for operations QA program will not be complete CCLLOBERG. J. H. Howston Lighting & Power Co. B1/03/24. 2pp psp.043-162
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8103180008 Trip rept of 810217-19 visit to util corporate headquer to project site to gather info for BER input concerning mgt capebility to organization
  SELLE.D.E Licensing Branch 2 81/03/06 7pp 07943-318
- F Becurity, medical, emergency % fire protection plans
- 8102310338 Litr to all licensees of operating plants & holders of Cl forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/O encl ELEENHUT.D O. Division of Licensing. 81/03/05. App
- BiO3270761 Requests that security guard training & qualification p be delayed pending receipt of specific guidance re security plan review schedule.per 800211 ltr ODLOBERQ.J.H Houston Lighting & Power Co. 91/03/25 2pp 08043.191
- 8103300168 Act receipt of Generic Ltr 81-01, "Post-THI Requirement: Emergency Operations Facility" & NUAEG-0476 "Functional Criteria for Emergency Response Facilities" Response will be submitted an schedule consistent u/NRC DL review GOLDBERG, J. H. Hauston Lighting & Power Co. 81/03/30 2pp. Oppns 327
- G. Adjudicatory correspondence
- B103040414 Identification of NRC uitnesses & substance of testimon B01202 prder Certificate of Svc enc! OUTLERREZ.J M Mearing Branch 3. 81/03/02 5pp. 07820 190
- 8103130416 Identification of witnesses & substance of testimony. Certificate of Svc encl \* Houston Lighting & Power Co. 81/03/02 12pp 07911:208.
- 81031B0633 Requests permission to speak at 810318 prehearing conference
  HUMPHREY O D. Affiliation Unknown 81/03/03. Ip. 07954:184
- 8[03]80527 Requests to make limited appearance statement at 810318 hearing in Austin. TX re facilities MEACHAM. M. Affiligation Unknown. 81/03/06 ip.
- B103180533 Requests to make limited appearance statement at ABLB B10317-18 hearing in Austin.TX re facilities BROWN.D W. Affiliation Unknown. 81/03/06 ip 07953 230

- 8103180782 Requests opportunity to express views re facility licensing to ASL8 on 810318 in Austin. TX KELLY.J.S. Affiliation Unknown 81/03/07 ip
- B103190644 Certificate of B10309 Svc for UR Newton B10309 ltr to ASLB. applicants' preliminary ensure to Citizens for Equitable Utils-Inc motion for order prohibiting distribution of tape by notice of encarance
  - OBITE OF appearance Restance NEWHAN. J. R. Houston Lighting & Power Co. NEWHAN. J. R. Lowenstein, Newman, Restance J. Arelrad & Toll BI/OJ/09 259 07964 088
- B103190647 Responds to ABLB B10213 notice of preheaving conference submits proposed agenda includes schedule for hearing.filling testimony sequence of presentation of testimony & applicant motion for extension of time

  NEWHAN.J R Lowenstein:Newman.Reis.Azelrad & Toll B1/03/09. Spp.
  07963-05B
- --Bi03190649 Preliminary answer to Citizens for Equitable Utilis. Inc motion for ASLB order prohibiting distribution of tape. If already received, ASLB should not hear tape until after oral arguments held Notice of appearance enc!

  NEMMAN.J.R. Houston Lighting & Pover Co. NEMMAN.J.R. San Antonio, TX. NEMMAN.J.R. Central Power & Light Co. 81/03/09. 4pp. 07963.063
- BiO3200792 Requests that ABLB revise hearing schedule outlined in BO1202 order due to extenuating circumstances Advises that legal counsel retained by Citizens Connerned About Nuclear Power-Inc has withdrawn from proceeding EABTMAN.K M Citizens Concerned About Nuclear Power-Inc. B1/03/09. ip. 07967-060.
- 8103120741 Responds to ABLB 810213 notice of prehearing conference, specifying issues to be considered Scheduling matters should be finalized to real arguments included on applicant motion & intervenor request
  OUTIERREZIUM Hearing Branch 3 81/03/11. 2pp
- 8103200988 Submits agenda for prehearing conference in response to 810213 notice of prehearing.

  SINKIN.L.A. Citizens Concerned About Nuclear Power, Inc.

  SINKIN.L.A. Citizens for Equitable Utilities 81/03/11 2pp
- B103180629 Requests permission to address ASLB 810318 public hearing Expresses concern re-safety & radwaste problems.

  HARRIBON-D. Affiliation Unknown. 81/03/12. 1p.
- B1031B03B3 Requests to make limited appearance statement at B1031B public hearing CARDINAL.G.V. Affiliation Unknown. 81/03/13 is.
- B103180063 Response apposing Citizens for Equitable Utils 810319 & Citizens Concerned About Nuclear Power 810312 motions for ASLB to postpone 810504 evidentiary hearing. Intervenors will suffer no irreparable harm Certificate of Bvc encl. OUTIERREZ. J. M. Hearing Branch 3. 81/03/16, 8pp. 07942:334.
- 8103270776 Order directing intervenors Citizens for Equitable Utils.Inc & Citizens Concerned About Nuclear Power to respond to interrogatories requesting identity of individuals supplying info re Contentions 1 & 2 Response due by 810330.

  BECHIOPTER.C. Atomic Safety and Licensing Board Panel. 81/03/18 6pp. 08043:275.

### H. Ownerel correspondence

- Bi01280010 Discusses reactor const GA program deficiencies in response to 800805 to 12 itrs Emphasis is placed on licensee mgt criteria in NRC licensing 8 insp program Preparation of rule change underway to monitor licensee GA program changes. DIRCRS.N.J. Office of the Executive Director for Operations. BO/12/08. 2pp. 94496.302
- BiO3300386 Package of 3 little from citizens & local govts supporting issuance of DL for facility.

   Affiliation Unknown. Bi/03/17. 5pp. 08035:316.
- K. Utility Finel Bafety Analysis Report (FBAR) & amends
- B103200290 Forwards Amend 15 to FBAR. Amend consists of changes to Chapter 13 & various tachnical & editorial changes to other chapters of FBAR. Chapter 13 reflects current util organization re-facility.
  GOLDBERG. J. H. Houston Lighting & Power Co. 81/03/18. 4pp. 07971:074.

- --Bi03200304 Amend to OL application revising Chapter 13 to current util organization relating to facility. GDLDBERO.J H Houston Lighting & Power Co 81/03/14
- --Bi03200310 Amend 15 to FSAR • Houston Lighting & Power Co 81/03/18 81pp 0797

## M Antitrust correspondence

- 8103190629 Supplemental status rept re 810223 settlement be Utils Board of City of Brownsville.TX.Central & Southwest Corp.Central Power & Light Co & West TX Utils Characterizes settlement agreement W/Centificate of Svc 8PIECEL.O. PDIRIERM R. Brownsville.TX SPIECEL.O. Sp McDiarnid 81/03/18 9pp 07963 317
- 8103260817 Supplemental status rept of Mar 1981 Settlement urCentral t Southwest Corp & subsidiaries Reserves positi that no administrative or judicial proceeding uill prejud Brownsville rights in future #/Certificate of Svc. SPIECEL.0 PORIERE\* MR Brownsville\*TX SPIECEL.0 Ba McDiarmid. 81/03/18 9pp 08036 223
- Q Inspection reports: IE Bulletins & correspondence
- 8103030344 Forwards IE Insp Repts 30-498/80-36 & 90-499/80-B01117-24 & 1201-04 No roncompliance noted BEIDLE-W C Region 4, Dallas, Reactor Construction & Eng Support Branch 80/12/31 2pp 07789 161
- --8103030358 IE Insp Repts 50-498/80-26 & 50-499/80-36 on B 1201-04 No noncompliance noted Major areas inspected: coactivities including items of noncompliance unresolved items & show cause order items HUBACEK, W G , GILBERT, D , CROESHAN, W A. Region 4. Dailiof the Director 80/12/30 13pp 07/89 163
- B103050106 Forwards 1E linsp Repts 50-499/80-33 & 50-499/80-Nov-Dec 1980 No nancompliance noted. SEIDLE-W C Region 4. Dallass Reactor Construction & Eng Support Branch. B1/01/14 2pp 07827 289
- --8103050112 IE Insp Repts 50-498/80-33 & 50-499/80-33 during 1980 No noncompliance noted Major areas inspected storage maint of components & equipment, structural steel, safety related welding & followup re show cause commitments PHILLIPS.H S., CROSSMAN.H A. Region 4, Dallas, Uffice of Director. 81/01/14. 4pp 07827.290
- 8103120384 Forwards IE Investigation Repts 50-498/80-31 & 50 on 801015-17,22-23 & 1113 No nencompliance noted SEYFRIF.K V Region 4. Dallas, Office of the Director 1p. 07905-243.
- --BI03120593 IE Investigation Repts 50-498/80-31 & 90-499/80 B01015-17.22-23 & 1113. No noncompliance noted. Major are investigated; allegations that individuals were rubired of were fired as result of NRC investigation DRIBKILL-D. D. HERR.R K. DIOALOMA.T L. Region 4. Dello of the Director BI/O1/21 10pp 07905:244.
- 8103130226 Forwards JE Investigation Repts 50-498/80-34 & 5 on 801027-31 & 1111-12 No noncompliance noted. SEIDLE.W.C. Region 4. Dallas. Reactor Construction & Eng Support Branch 81/01/26. 1p 07908.348
- ~-B103130R36 IE Investigation Repts 50-498/B0-34 & 50-499/B0 B01027-31 & 1111-12 No noncompliance noted Major areas investigated: allegations that unqualified personnel work in electrical dept affect record keeping DRIBMILL.D.D., JOHNSON.A.R. Region 4. Dallas, Defice on Director. BEIDLE-H C. Region 4. Dallas, Reactor Consti-Engineering Support Branch. B1/01/22 Bpp. 0790B 349
- 8103130337 Forwards IE Insp Repts 50-498/81-02 & 50-499/01-810105-09. No noncompliance noted.

  BEIDLE-W.C. Region 4, Delias. Reactor Construction & Eng Support Branch. 81/01/27. 2pp 07912-160
- --8103130348 IE insp Repts 50-498/81-02 % 50-499/81-02 on 8 nancompliance noted Major areas inspected const activit per resumption of ABME welding & re-eram of repair of existing welds.

  TOMLINSON.D.P., CROSSMAN.W.A. Region 4, Dallas, Office Director. HALL,R.E. Region 4, Dallas, Reactor Constructoring Support Branch. 81/01/27. 3pp. 07912.162

- 6:03190029 Forwards IE Insp Repts 50-498/80-38 % 50-499/80-38 on 801215-18. No nencompliance noted SEIDLE-W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 81/01/30 2pp 07964 152
- --Bi03190030 1E Insp Repts 50-498/80-38 % 50-499/80-38 on 801215-18 No noncompliance noted Major areas inspected AMB wolding, re-presentation & repair of existing welds & responses to previous insp findings (CROSSMAN.W A Region 4. Dallas, Office of the Director 81/01/29 9pp 0/764 154
- 8103230122 Responds to IE Sulletin 80-21. "Valve Yoles Supplied by Malcoln Foundry Co. Int." No Malcoln valve parts in use OFREA.G W. Mouston Lighting & Power Co. 81/02/10. 4pp. 07976-249
- 8:03261186 Forwards IE Insp Repts 50-498/81-03 & 50-499/81-03 on 810119-23, No noncompliance noted SEIDLE, H C Region 4. Dallas, Reactor Construction & Engineering Support Branch 81/02/11 2pp 08030 281
- --8109261198 IE Insp Repts 50-498/81-03 & 50-499/81-03 on 810119-23 No noncompliance noted Major areas inspected followup on items of noncompliance unresolved items to show cause order items TAPIA. J. I. OILDERTS. L. D. CROSSMAN. W. A. Ragion 4. Dallas. Office of the Director 81/02/11 ilpp 08035 283
- 8:03260497 Forwards IE ling Repts 50-498/81-05 & 50-499/81-05 on 810202-05 No noncompliance noted SEICLE.H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 81/02/13 2pp 02040 024
- --Bi03260471 IE insp Repts 50-498/Bi-05 & 50-499/Bi-05 on Bi0202-05 No nancompliance noted Major areas inspected corrective actions to show case order \$ previous insp findings HUBACEK.H.O. CROSSHAN.M.A. Region 4. Dallas. Office of the Director Bi/02/I3 opp 08340.026
- 8103160640 Forwards 1E Info Notice 81-04. 'Cracking in Main Steam Lines." No response required SEYFRIT.K V Region 4. Dallas, Office of the Director 81/02/27 to 37917 099
- 8103170019 Forwards IE Circular 81-03. "Imperable Beismic Monitoring Instrumentation" No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 81/03/02 bp 07937 147
- B103160B3h Forwards revised IE Bulletin B1-01. 'Surveillance of Michanical Shubbers.' 'D/corrected Pages 5 & 6 Change in Identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  SEYRRIT.K. V. Region 4. Dallas. Office of the Director B1/03/04
  13 07914 193
- BiO3230181 Forwards IE Info Notice Bi-O7. 'Potential Problem U/Aster-Colubie Purge Dam Hotts Used During Inert Gas Welding 'No response required SEYRRIT.M. V Region 4. Dallas. Office of the Director 81/03/16 to 07977 222
- 6 Reportable occurrences. LERs & related correspondence
- 8103050829 First interim deficiency rept re environ qualification of electrical equipment associated w/auxiliary feedwater pumps. Analysis will determine worst case accident conditions Next rept by 810109

  DP46A.0 W. Houston Lighting & Power Co 80/09/24 Spp 07029 100.
- \$103050837 Fourth interim rept re rejectable indications in girth welds in essential cooling water sus pipe, initially reported on 800312 Helds are included in limited restart program for ASHE pipe & pipe support welding. Next rept by 810326.

  OPREA 9 H. Houston Lighting & Power Co. 80/12/12 4pp. 07825 124.
- Bi00090862 Third Interim rept re lineal indications in greviously accepted piping welds initially reported on 800625 Limited re-examination & restart program for ABME pipe & pipe support welding is in progress Next rept by 810326 OPREA G W. Houston Lighting & Power Co. 80/12/12, 4pp. 07829 339.
- Biogobogge Final deficiency rept re-structural backfill math, initially reported on Boogs. Four isolated areas in Unit 2 power block found to have densities below specified GC criteria. Corrective action not required due to adequacy of backfill.

  OPREA. G W Houston Lighting & Power Co. B1/02/27 5pp. 07837 064.

- 8100090380 Second interim deficiency rept releable tray hanger design previously identified on B01203. Re-evaluation of hanger design continuing in order to identify connections which require mod Next rept to be provided by 810515

  OPREA-0 W Houston Lighting & Power Co. B1/02/27 3ee 07830:2
- B103100610 Final deficiency rept to stud wolds on concrete embedments initially reported 800731 No safety hazard could exist if condition is left uncorrected OPREA,0 W. Houston Liebting & Power Co. 81/03/05 Sno. 07863-03
- 810320069) Second interim deficiency rept re average ultimate tensils loads of 1-inch kwit-bolt concrete espansion anchors. Design change notice revised reducing load capacity & confirmation program being conducted Next rept to be submitted by 810716.

  OPREA.C.W Houston Lighting & Power Co. 81/03/13. 3pp. 07969-26
- 8103300339 Interim deficiency rept re breakdown in quality program for procurement cycle of purchased matta & equipment, initially reported on 800613 Revised program description & associated revised implementation schedules entliker rept by 810924.

  DREA: 0 W Houston Lighting & Power Co 81/03/23 15pp.
- 8103310468 Final deficiency rept re linear indications in previously accepted welds initially reported on 800625 Helds have been repaired or replaced. Remetamination & repair program for ASME welding is underway OPREALO W Houston Lighting & Power Co 81/03/26 Spc 08078 33
- T. Hearing transcripts on non-antitrust matters
- 8103240281 Transcript of 810317 DL hearing in Austin.TX Pp 348-549

  # Atomic Safety and Licensing Board Panel 81/03/17, 206pp.
- 810324025: Transcript of 810318 meeting in Austin.TX Pp 550-760 • Atomic Safety and Licensing Board Penel 81/03/18. 215pp 07980:001
- U Congressional/Executive Correspondence
- BIO027011D Responds to request for rept on possible add1 improvements to NRC licensing process. Legislation allowing interim operations in advance of hearing completion would reduce delay in ficensing process.
  HENDRIE, J M Commissioners B1/03/12 Spp
- --Bi03270947 Bubmits recommendations re-scheduling.personnel resource hearing right for OL proceedings. Panel must obtain exerption from hiring freeze for two recently appointed chairmen COTTER. B. P. Atomic Safety and Licensing Board Panel. Bi/02/25 33pp
- V Operator Examinations
- 8103160246 Advises of review of "Interim Criteria for Shift Staffing" NUREO-0737. Util will provide shift staffing description & site technical advisor requirements on schedule consistent whreview of facility Ol. GOLDBERG, J. H. Houston Lighting & Power Co. 81/03/12 2pp. 079181177
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

  A Application/construction stage documents & correspondence
- 0103041035 Requests authorization for limited restert of complex safety-related concrete & safety-related AMS & ABME welding on B01006. Corrective actions for previously identified moncompilances are essentially completed OPREA-0 W Houston Lighting & Power Co 80/10/02. 9pp. 07813-34
- 8103090004 Updates 801002 request re remeranization, repair & restart a safety-related ABME usiding activities. Util requests authorization to commence limited usiding on 801124. Description of program & schedule encl. OPREA+0 W Houston Lighting & Power Co. 80/11/19. 1ipp. 07827:017
- 8103041023 Modifies Attachment I. Line 18 of util 801119 ltr recomponent cooling water sys in Unit 1 mechanical electrical auxiliary blog DPREA+0 W. Houston Lighting & Power Co. 80/12/02. 4pp. 07813:34

- 8103190702 Litrs to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in NuREO-0612 Forwards NRC position re interim actions & request for addl info. EISECHNUT. O @ Division of Licensing 80/12/22 30cc
- 8103031067 "Environ Statements Project." monthly progress rept for Dec 1980 21TTEL.H E. Oak Ridge National Laboratory "FIN 8-0760-( 8103031067. 80/12/21 App
- 8103190387 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs reprogram for environ qualification of safety-related electrical equipment liters addressed involve cold shutdown.replacement parts & NUREO-0737.
  E19ENHUT.D O. Division of Licensing 81/31/19 &pp
- 8103120014 Ltr to all licensees of operating plants, CP holders & O., applicants, except indian Point 2 & 3.2ion 1 & 2 & Thi-1, forwarding inadvertently omitted pages from NRC 801222 request for addlinfore control of heavy loads EISECHIUT. D. O. Division of Licensing 81/02/03 600
- 8103090885 Forwards revised ARC Region 4 organization chart.effective 810227. SEYFRIT.K V Region 4. Daltas, Office of the Director 81/02/18 2pp 07831 358.
- 8103130714 Authorizes substitution of ASME safety-related welding SEYFRIT.K V. Region 4, Dallas, Office of the Director 61/02/19 10 07912:085
- 8103250024 Ltr to all power reactor licensees & license applicants re PAREG-0619 crateria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D.O. Division of Licensing. 81/02/20 Bpp.
- 8103230030 Ltr to all licensess of operating nuclear power plants & applicants for OLs (escept St Lucie. Units 1 & 2) Requests util review to determine capability to mitigate station blactbout event & promptly implement emergency procedures. EISENHYJT.D.O. Division of Licensing 81/02/25 5pp
- 8103230813 Generic Ltr 81-06 to all CP holders & QL applicants re IOCFR50, 71(e), "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status format & content encl EIBENHUT, D. Q. Division of Licensing, 81/02/26, 102p
- 8103050658 Forwards add1 info re application of cladding & swelling & rupture models for LOCA analysis per NRC 801019 request. Evaluation of potential impact of NUREO-0620 using fuel rod models encl.

  OLDBERG, J. H. Houston Lighting & Power Co. 81/02/27. 6pp. 07832-018
- Bio3090558 Forwards evaluation of cladding swelling & rupture models for LOCA analysis.per NUREO-0630.in response to NRC 801014 ltr. FSRR will be amended by 810501 to reflect ten grid fuel design GOLDSERO, J.H. Houston Lighting & Power Co. 81/02/27. App. 07850, 198.
- 8103200079 Informs that staff functions of Region 4 reassigned, effective 810227. QL Madsen. Chief of Reactor Projects Branch, designated as principal contect & recipient of correspondence re-reactor const & operation activities SSYFRIT. K. V. Region 4. Dellas. Office of the Director 81/03/09 ip. 07971:339
- Bio33i0804 Ltr to all licenses of operating plants, applicants for OLs tholders of CPs forwarding BECY-8i-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  EIBENHUT.D.G. Division of Licensing. 81/03/10 App.
- 8103200735 Presents info verifying adequacy of corrective actions committed to in response to NRC order to show cause. ASME safety-related welding will be resumed on regular basis on 810316.

  OPREA, G. W. Houston Lighting & Power Co. 81/03/13. 3pp. 07967:061.
- B100200270 Forwards Ahend 15 to FSAR Amend consists of changes to Chapter 13 & various technical & editorial changes to other chapters of FSAR.Chapter 13 reflects current util organization re-facility.

  GOLDBERG, J. H. Houston Lighting & Power Co. B1/03/18. 4pp.

- --BIO3200304 Amens to U. application revising Chapter 13 to FBAR recurrent util organization relating to facility COLOBERG. J H. Houston Lighting & Power Co. 81/03/14 2pc 07971 078
- 8103270659 Submits corrections to NRC 819306 trip rept re B10217-19 meeting Organizational structure & operations DA program will be complete by end of 1981 Staffing for operations DA program will not be complete GDLDBERO. J H. Houston Lighting & Power Co. 81/03/24 2pp 08043 162
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- B103180008 Trip repl of B10217-19 visit to util corporate headquarter & project site to gather info for SER imput concerning act capability & organization SELLS.D.E. Literation Branch 2 B1/03/06 7nn 07943 318
- F Security, medical, emergency & fire protection plans
- B103310339 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements M/o encl EISERHUT. D. O. Division of Licensing B1/03/05 6pp
- B103270761 Requests that security guard training & qualification plan be delayed pending receipt of specific guidance re-security plan review schedule.per 800211 ltr
  GDLOBER9.J H Houston Lighting & Power Co. 81/03/25 2pp
  08043 191
- 8103300168 Ack receipt of Generic i.tr B1-01. 'Post-Tiff Requirements of Emergency Operations Facility' & NUREG-0696 "Functional Criteria for Energency Response Facilities" (Response will be submitted on schedule consistent w/NRC CL review GR.08ERO. J H. Housten Lighting & Power Co. 81/03/30 App. 08055-327
- G Adjudicatory correspondence
- Biogo40414 Identification of NRC witnesses it substance of testimony p Bolgo2 order Certificate of Evc encl GUTIERREZ, J. M. Hearing Branch 3 81/03/02 5pp 07820 170
- B103130416 Identification of witnesses & substance of testinory Centificate of Byc encl # Houston Lighting & Power Co. 81/03/02 12pp 0/911-200
- 8103180633 Requests permission to speak at 810318 prehearing conference HAMPHREV-0 D Affiliation Unknown 81703703 1c 07954 184
- 8103180527 Requests to make limited appearance statement at 8(83)U hearing in Austin. TX re-facilities
  PEACHAM Affiliation Unknown 81/03/05 ip
- 8103160533 Requests to make limited appearance statement at ASLD B10317-18 hearing in Austin-18 re facilities DRCWN.0 U. Affiliation Unknown 81703/06 1p 07953.239.
- S103180782 Requests opportunity to express views re facility licerate to ASL8 on B10318 in Austin. TX XELLV.J S. Affiliation Unknown B1/03/07 1p
- 8103190844 Certificate of 810309 Byc for JR Neuman 810309 ltr to ASCE applicants' preliminary answer to Citizens for Equitable Utils. Inc motion for order prohibiting distribution of tape & notice of appearance.

  NEUMAN. J R. Houston Lighting & Power Co NEUMAN. J R Lowenstein. Neuman. Reis. Arelraf & Toll. 81703707. 2pp 07964 003
- 8103190647 Responds to ABLS BIO213 notice of prehearing conference & submits proposed agenda. Includes schedula for hearing filing testimony sequence of presentation of testimony & applicant motion for extension of time.

  MEMMAN. J. R. Lowenstein, Neuman, Reis, Azelrad & Toll 81/03/09. 5pg 07963 058
- --B103190649 Preliminary ensuer to Citizens for Equitable Utils. Incomotion for ASLB order prohibiting distribution of tape. If already received, ASLB should not hear tape until after cral arguments held notice of appearance encil NEUMAN, J.R. Houston Lighting & Power Co. NEUMAN, J.R. 9an Antonio, TX. NEUMAN, J.R. Central Power & Light Co. 81/03/09 4pp. 07763-063

- 9;03200752 Requests that ASLB revise hearing schedule outlined in 80;202 order due to externating circumstances Advises that legal counsel retained by Citizens Concerned About Nuclear Fower. Inc. has withdrawn from proceeding fASTMAN. K.M. Citizens Concerned About Nuclear Power. Inc. 81/03/09 to 07987 060
- BiO3120241 Responds to ASLS BiO213 natice of preheating conference, type:/fyling issues to be considered Scheduling matters should be finalized & aral arguments included on applicant motion & intervenor request

  Auto-1997 J. M. Mearing Branch 3 | Bi/O3/11 | 200
- 8103200588 Submits agenda for prehearing conference in response to 810213 notice of prehearing SIXXIN.L A Citizens Concerned About Ruclear Power. Inc SIX.III.L A Citizens for Equitable Utilities 81/03/11 2pp
- BIO3180625 Requests permission to address ASLB 810318 public nearing Expresses concern re-safety traduaste problems MARATORY D. Affiliation Unknow. B1/03/12 1o
- B:03180383 Requests to make limited appearance statement at 810318 applic hearing capping. A #filiation Unknown BI/03/13 to
- 8103185063 Response apposing Citizens for Equitable Utils 810319 \$ Citizens Conterned About Nuclear Pozer 810312 motions for AS\_B to postpune 810504 evidentiary hearing Intervenors will suffer no irreparable harm Certificate of Svc encl OMITERREIJ M. Hearing Granch 3 81/03/16 Bpp 07942 334
- B103270776 Order directing intervenors Citizens for Equitable Utils.Inc 5 Citizens Concerned About Nuclear Power to respond to interrogatories requesting identity of individuals supplying inforce Contentions 1 & 2 Response due by B10330 BECHDEFER.C Atomic Safety and Licensing Board Panel B1/03/18 bpp CB043 279
- H Jeneral correspondence
- Bigl2BC010 Discusses reactor const QA program deficiencies in response to 800805 & 12 itrs Emphasis is placed on licensee mgt criteria in NGC licensing & insp program Preparation of rule change underway to monitor licensee QA program changes GPQKS.M.J. Office of the Executive Director for Operations. 80/12/08 2pp 94494 302
- 8103300386 Package of 5 ltrs from citizens & local govts supporting issuance of OL for factility APPLICATION OF STATE OF
- K Jiiity Final Befely Analysis Report (FSAR) & amonds
- B103200290 Forwards Amend 15 to FBAR Amend consists of changes to Chapter 13 & various technical & editorial changes to other chapters of FBAR Chapter 13 reflects current util craanization re-facility
  OOLDBEROUN H Houston Lighting & Power Co. 81/03/18 App. 07971:074
- --8103200304 Amend to DL application revising Chapter 13 to FBAR recurrent util organization relating to Facility OCLDBERO.J H. Houston Lighting & Power Co. 81/03/14 2pp
- --BIO3200310 Amend 15 to FBAR
   Houston Lighting & Power Co. 81/03/18 81pp 07971 080
- M Antitrust correspondence
- 8103190627 Supplemental status rept to 810223 settlement between Public Utils Board of City of Brownsville.TX.Central & Southwest Corp.Central Power & Light Co & West TX Utils.
  Characterizes settlement agreement U/Certificate of Svc Spiegel & McDiarnid B1/03/18. 9pp
- 0103260817 Supplemental status rept of Mar 1701. Sattlement completed w/Central & Southwest Corp & subsidiaries Reserves position that no administrative or judicial proceeding will prejudice Erachaville rights in future H/Centificate of Svc SPIEGEL.0. Brownsville.TX. POIRIER.M R Spiegel & McDiarmid B1/03/18 9pp

- Q Inspection reports. If Bulletins & correspondence
- 8103030344 Forwards IE Inst Repts 50-498/80-36 & 50-499/80-36 on BO1117-24 & 1201-04 No noncompliance noted SEIDLE-W C Region 4. Pallas. Reactor Construction & Engineering Support Branch B0/12/31 2pp 07769 161
- --8103030358 IE Insp Repts 50-499/B0-36 & 50-499/B0-36 on B01117-24 & 1201-04 No nonco-pliance noted Major areas inspected const activities including items of nonco-pliance unresolved items & show cause order liens HUBACEX. No . 010ERT. D . CROSSMA\*1, No . Region 4. Dallas. Office of the Director B0/12/30 13nn 07789 163
- BIO3050106 Forwards IE Insp Repts 50-498/80-33 & 50-499/80-33 during Nov-Dec 1980 No noncompliance noted SEIDLE-H C Region 4- Dallas, Reactor Construction & Engineering Support Branch BI/01/14 2pp 07827 289.
- --B103050112 IE insp Repts 50-498/80-33 & 50-499/80-33 during Nov-Dec 1980 No noncompliance noted Major areas inspected storage & maint of corponents & equipments structural steel.safetyrelated welding & followup re show cause compilments PHILLIPS.H 5. CROSEMN. M A Region 4. Dallas. Office of the Director B1/01/14 4pc 07827 270
- 8103120984 Forwards 1E Investigation Repts 50-498/80-31 & 50-499/80-31 on 801015-17, 22-23 & 1113 No noncompliance noted SEYFRIT. K V Region 4. Dallas. Office of the Director 81/01/21 p 07905 243
- --8103120993 IE Investigation Repts 90-498/80-31 & 50-499/80-31 on 801015-17.22-23 & 1113 No noncompliance noted Major areas investigated allegations that individuals were rehired chowere fired as result of NRC investigation CRIBKILL.D D , NERR.R K , DIOALDHA, F L Region 4. Dailas. Office of the Director 81/01/21 10pp 07905 244
- 8103130226 Forwards IE Investigation Repts 50-498/80-34 & 90-499/80-34 on 801027-31 & 1111-12 No noncompliance noted SEIDLE-W C Region 4. Dellass Reactor Cunstruction & Engineering Support Branch 81/01/26 ip 07908 348
- --B103130236 IE Investigation Repts 50-458/80-34 & 50-499/80-34 on B01027-31 & 1111-12 No noncompliance noted Major areas investigated allegations that unqualified personnel working in electrical dept affect record keeping DRISKILL, D.D., JOH/SDN.A.R. Region 4, Dallas, Dffice of the Director SEIDLEN C. Region 4, Dallas, Reactor Construction & Engineering Support Breach B1/01/22 Bap. 07908-349
- 8103130337 Forwards IE Insp. Repts 50-478/01-02 & 50-499/81-02 on 810105-09 No noncompliance noted SEIDLE-K C Region 4. Dallas. Reactor Construction & Engineering Support Branch Bi/01/27 2pp 07912 160
- --Di0313034B IE Insp Repts 50-498/B1-02 & 50-499/B1-02 on Bi0105-09 No noncompliance noted Major areas inspected const activities per resumption of ABME welding & re-exam of repair of existing welds
  TOMLINSOR, b. P. . CROBEMAN, W. A. Region 4. Dallas, Office of the Birector, HALL, R.E. Region 4. Dallas, Reactor Construction & Engineering Support Branch 81/01/27 3pp 07912-142
- DIO3190025 Forwards IE Tusp Repts S0-498/80-38 & 50-499/80-38 on 801215-18 No noncompliance noted SEIDLE: W C Region 4. Dallass. Reactor Construction & Engineering Support Branch Bi/01/30 2pp 07964 152
- --Bi0319003D IE Insp Repts 50-49B/B0-38 & 50-499/B0-38 on B01215-18 No nonco-pliance noted Major areas inspected ARG welding, re-esemination & repair of existing welds & responses to previous insp findings TDMLINBON.D P. TAPIA.U I . CROSSHAN, H. A. Region 4. Dallas. Office of the Director B1/01/29 9p. 07964 154
- B103230122 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcoin Foundry Co.Inc." No Malcoin valve parts in use OPREA.0 W Houston Lighting & Pouer Co. 81/02/10. 4pp. 07976:249
- Bi03261186 Forwards IE insp Repts \$0-498/81-03 & 50-499/81-03 on Bi0119-23 No noncompliance noted. SEIDLE.H.C. Region 4. Dallas. Reactor Construction & Engineering Support Branch Bi/02/11 2pp 08035 281
- --B10326119B IE Insp Repts 50-49B/81-03 & 50-499/B1-03 on B10119-23 No noncompliance noted Major areas inspected followup on items of noncompliance unresolved items & show cause order items TAPIAJ J. GIBERTSL D. CROSSMAY.W A Region 4. Dallas. Office of the Director B1/02/11 11pp 08035-283

- 10320457 Forwards it inspirepts 50-496761-05 & 53-477761-05 31 810202-05 Ng nancompliance noted 8E[DLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 81/02/13 2pp 68040-024
- ~~8103260471 [E Insp Repts 50~498/81~05 & 50~497/81~05 on 810202~05 No noncompliance noted Major areas inspected corrective actions to show cause order & previous insp findings HUBACEK, W. Q. CROSSMAN, H. A. Ragion 4. Dallas. Office of the Director 81/02/13 &pp 08040 026.
- 8103140840 Forwards IE Info Notice 81-04. "Cracking in Main Steam Lines" No response required. SEYFRIT.K V Region 4. Dallas. Office of the Director 81/02/27 In 07917 099
- 8103170019 Forwards IE Circular 81-03. "Inoperable Selsmic Monitoring Instrumentation" No response required SEYFRIT.K V Region 4. Dallas, Office of the Director 81/03/02 ip 07939 147
- B103160B36 Forwards revised IE Bultetin B1-01. Surveillance of Mechanical Snubbers, w/corrected Pages 5 5 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements EEYFRIT.K V Region 4. Dallas. Office of the Director B1/03/04 is. 0.7914 193.
- 8103230181 Forwards IE Info Notice 81-07. "Potential Problem W/Water-Soluble Purge Dam Matls Used During Inert Gas Halding." No response required.
  SEYFRJT.K V Region 4. Dallas. Office of the Director 81/03/16 to. 07977 222
- S Reportable occurrences. LERs & related correspondence
- 8103050829 First interim deficiency rept re environ qualification of slettrical aguipment associated of succession of reedulate pumps. Analysis will determine worst case accident conditions Next rept by 810109 OPREA, 0 N Houston Lighting & Power Co 80/09/24 Spp. 07825 100
- 8103050837 Fourth interim rept re rejectable indications in girth welds in essential cooling water sys pipe initially reported on 800312. Helds are included in limited restart program for ASME pipe 8 pipe support welding Next rept by 810326. OPREA. G. W. Houston Lighting & Power Co 80/12/12 4pp. 07825:124
- BIO3050862 Third interin rept he lineal indications in previously accepted piping welds initially reported on 800625 Linited remeanination & restart program for ASME gize & pipe support welding is in progress. Next rept by 810326 OPREAG. W. Howton Lighting & Power Co. 60/12/12 4pp 07829:339
- Bi03060337 Final deficiency rept re structural backfill math.instially reported on B00321 Four isolated areas in Unit 2 power block found to have densities below specified QC criteria Corrective action not required due to adequacy of backfill.

  OPREA.Q.W. Houston Lighting & Power Co. Bi/02/27 App 07837 064.
- 8103090380 Becond interim deficiency rept re-cable tray hanger design previously identified on 801205. Re-evaluation of hanger design continuing in order to identify connections which require mod Nest rept to be provided by 810515

  DRREA. G. W. Houston Lighting & Power Co 81/02/27 3pp. 07850-215
- 8103100610 Final deficiency rept me stud welds on concrete embedmentsinitially reported 800731.No safety hazard would exist if condition is left uncorrected OPREA.G.W. Houston Lighting & Power Co. 81/03/09. 5pp. 07863:078.
- 8103200691 Second interim deficiency rept re average ultimate tensile loads of 1-inch hwik-bolt concrate expansion anchors Design change notice revised reducing load capacity & confirmation program being conducted. Next rept to be submitted by 810716.

  OPREA.G. N. Houston Lighting & Power Co. 81/03/13 3pp. 07969 267
- 8103300339 Interim deficiency rept to breakdown in quality program for procurement cycle of purchased matls & equipment initially reported on 800613 Revised program description & associated revised implementation schedules encl. Next rept by 810924. OPREALO. H. Houston Lighting & Power Co. 81/03/23 15pp. 08055: 294.
- 8103310468 Final deficiency rept re linear indications in previously accepted welds, initially reported on 800625. Welds have been repaired or replaced Re-examination & repair program for ASME welding is underway OPREA.9. M. Houston Lighting & Power Co 81/03/26 5pp. 08078:334.

#### \_\_\_\_\_

- B100240281 Transtript of R10317 GL hearing in Austin, TY Pp 346-549

   Atomic Safety and Licensing Board Panel B1/03/17 20App
  07984 001
- 8103240291 Transcript of 810318 meeting in Austin.TX Pp 550-769
   Atomic Safet, and Licensing Roard Panel BI/03/18 210pp
  07980 001
- U Congressional/Executive Correspondence
- --Bi03270947 Submits recommendations re scheduling.personnel resc.fc hearing mgt for QL proceedings Panel must obtain exemption from hiring freeze for two recently appointed chairmen COTYER.B P Atomic Safety and Licensing Board Panel. 81/02/25
- V Operator Examinations
- BIO3160246 Advises of review of "Interim Criteria for Shift Staffing ARREO-0737 Util 2011 provide shift staffing description & site technical advisor requirements on schedule consistent w/review of facility OL GOLDSERG. J H. Houston Lighting & Power Co. 81/03/12 2pp 07918 177
- DOCKET 30-500 DAVIS-BESSE NUCLEAR POLER STATION. UNIT 2

A Application/construction stage documents & correspondence

- BiOG190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment licens addressed involve cold shutdown.replacement parts & NUREO-0737 EIEENHUT.D O Division of Licensing 81/01/17 App
- DOCKET 30-301 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

  A Application/construction stage documents & correspondence
- Biodigo397 Ltr to all licensees of operating plunts & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment flows addressed involve cold shutdown.replacement parts & NUREG-0737 EISENHUT.D O Division of Licensing GI/OI/19. App
- DOCKET BIN-50-902 HAVEN NUCLEAR PLANT. UNIT 1

  A Application/construction stage documents & correspondence
- 8103060519 Informs of balance due NRC from CP application review Of-Comptroller will issue invoice MILLER.H.O. License Fee Management Branch. B1/02/24 1c 07836:144.
- 8103090711 Submits listing of expenditures incurred for prof manpoon a contractual support sice from 771216 until CP application withdrawal on 781019 Invoice for balance due util be issued MILLER.H.O. License Fee Management Branch. 81/02/24 16 03844-270
- DBCKET SIN-90-503 HAVEN NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 0103060519 Informs of balance due NRC from CP application review CF Comptroller will issue invoice MILLER.W.O. License Fee Management Branch 81/02/24 19 07836:144
- 8103090711 Submits listing of expenditures incurred for prof marpout contractual support svcs from 771216 until CP application withdrawal on 781019. Invoice for balance due will be issued. MILLER.W.O. License Fee Management Branch. 81/02/24 ip. 07844: 230.

- COCKET BIN-50-908 WPP95 NUCLEAR PROJECT, UNIT 3

  A Application/construction stage documents & correspondence
- 8103190732 Litrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREC-9612 Forwards NRC position re-interim actions & request for addlinfo FISFIRMIT.D O Division of Licensing 80/12/22 30pp
- GiO3190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs to program for environ qualification of safety-related electrical equipment licens addressed involve cold shutdown replacement parts & NUREQ-0737 EISELHUT.D © Division of Licensing 81/01/19 App
- 910312C014 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.2ion 1 & 2 & IMI-1, faruncing inadvertently unitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D 9 Division of Licensing 01/02/03 App
- BIO3160869 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A 1 2 re upgrade of emergency support facilities Requests confirmation within 43 days that implementation dates will be met EISENMUT. D O Division of Licensing 81/02/18. 12pp
- 8103250024 Ltr to all power reactor licensers & license applicants re MAREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller FIREN-MUT.D.Q Division of Licensing 81/02/20 App
- 8103230B13 Generic Ltr 81-06 to all CP holders & CL applicants re 10CFR90 71(e). "Periodic Updating of FBARs." effective B00722. Info re FBAR legal status format & content and E1EERHUT.D D. Division of Licensing 81/02/26 10pp.
- 8103120185 Notifies that IE requested that enc) preservice inspit test requirements for snubbers be included in licensing process. Paquests that requirements to insure snubber operability be implemented. 180650.0 R L. Assistant Director for Licensing. 81/03/05 App.
- 8:03310804 Ltr to ail licensess of operating plants, applicants for OLs & holders of CPs forwarding SECY-01-117 re info necessary to establish environ qualification of safety-related electrical equipment
  EISF:MUIT.D O Division of Licensino 81/03/10 Ann
- $\mathcal F$  Becurity, medical, emergency & fire protection plans
- 930310339 Ltr to all licenses of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Payonse Facilities." Critoria describe acceptable method for meeting NRC requirements W/o encl. EISEMMYT. D. 9. Division of Licensing. 81/03/05. 6pp
- 6103310512 Forwards 801212 itr requesting NRC concurrence u/location of offsite emergency operations facilities Facilities are technically adequate w/o addi backup facilities at greater than 10 miles, despite NUREO-0696 guidance EDUCHEY. O D Washington Public Power Supply Bystem 81/03/20 1p. 08059-197.
- --BIQQ310520 Requests NRC concurrence re-adequacy of location of offsite amergency operation facilities. Util should not be panalized t required to relocate facilities if current NRC guidelines are modified. BDUCHEY: 0 D. Washington Public Power Supply System 80/12/12 3pp 08059:198.
- 9 Inspection reports. IE Bulletins & correspondence
- B1031800B3 Forwards IE Insp Repts 50-508/80-13 & 50-509/80-13 on 803929-1030 & notice of violation.

  SPENCER O. 8 Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch. 80/12/12 2pp. 07942 349.
- --BIGGIBOOB7 Notice of violation from insp on BO0929-1030 SPENCER.O.B Region 5. San Francisco. Reactor Construction & Engineering Support Branch BO/12/12 2pp. 07442:351

- --8103180093 IE insp Repts 50-508/80-13 & 50-509/80-13 on 600929-1030 Noncompliance noted failure to accumplish bolting to properly translate 485igh requirements & to properly maintain equipment.

  BISHOP.T W. Region S. San Francisco. Diffice of the Director. HAYNES.R C. Region S. San Francisco. Reactor Construction & Engineering Support Branch. 80/12/10 17pp 07942-333
- 8103040339 Forwards IE Insp Repts 50-508/80-16 & 50-509/80-16 on 801031-1204. No nonconsitance noted SPENCER.9 S. Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 81/01/13 2pp 07820 134
- --BIO3040346 IE Imap Repts 50-908/80-16 & 90-909/80-16 on 801031-1204 storcompliance noted Major areas inspected constractivities including containment structural steel erection, welding, storage 5 handling.
  BISHOP.T.W. Region 5. San Francisco. Office of the Director DDDDS.R T. Region 5. San Francisco. Reactor Construction \$ Engineering Support Branch. 81/01/12 5pp. 07820-136
- 8103020041 Forwards 1E Circular B1-02, 'Performance of NRC-Licensed Individuals Hile on Duty "No written response required ENGELKEN.R H. Region 3. San Francisco. Office of the Director. B1/02/09 1p 07907-224
- B103170006 Furwards IE Circular 81-03. 'Insperable Seisnic Monitoring Instrumentation," No response required ENGELKEN.R H. Reggin 5. San Francisco, Office of the Director. 81/03/02 ip 07939 104
- 8103260009 Responds to TE Bulletin B0-09. Hydramotor Actuator Deficiencies " Updates 800625 & 0922 responses No Valter Inc supplied actuators found deficient American Marring & Ventilation Co supplied actuators being examined. DOR600r.D.E. Hashington Public Power Supply System 81/03/02 2pp 08042-1064
- Bi03i60830 Forwards revised 1E Bulletin Bi-01. "Burveillance of Mechanical Boubbers." w/corrected Pages 5 & 6. Change in Identification of Pacilities w/CPs to which bulletin is applicable does not affect util requirements. ENOSEKEN R H Region 5. Bon Francisco. Uffice of the Director Bi/03/04 ip 07914 187
- Bio3i20iB6 Notifies that 1E requested that encl preservice insp & test requirements for anobbers be included in licensing process Requests that requirements to insure snobber operability be implemented.

  IEDESCOR L. Assistant Director for Licensing 81/03/06 App. 07903:015.
- B103180820 Forwards IE Mgt Meeting Repts 50-460/81-03, 50-508/81-03 50-513/81-03 on 810225 ENGELKEN.R.H Region 5, San Francisco, Office of the Director. 81/03/04 ip 07933 155
- --BIO3180851 IE Mgt Meeting Repts 50-460/81-03,50-508/81-03,50-509/81-8,50-513/81-03 on 810225 No noncompliance noted Areas discussed actions taken re-concerns expressed by mgt at Oct 1980 systematic appraisal of licensee performance meeting. FAULKENGERRY.B., CREMB, J.L. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 81/03/04, 4pp 07953:156.
- B103200268 Forwards IE Info Notice Bi-06. "Failure of ITE Model K-600 Circuit Breaker." No response required. ENGELKEN.R.H. Region 5. Ban Francisco. Défice of the Director. 81/03/11. 1p. 07969 001
- B103200066 Forwards IE Info Notice B1-05, "Degraded DC Sys at Palitades" No response required. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director. B1/03/13, Ip. 07970-0B1
- B103250019 Ack receipt of 810219 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-509/80-17 & 50-509/80-17 FAULKENBERRY, B. Region 5, San Francisco, Office of the Director. 81/03/18 tp. 07998-034

- ---8103250025 Responds to NRC 810135 for re-violations noted in IE Insp. Repts 50-938/80-17 & 50-939/80-17 Corrective actions welders requalified under correct testing procedures & new guided bend test jig requisitione:
  DOBSON.D E Washington Public Power Suppl, System 81/02/19 4ca 07998 035
- --8103250023 Approves extension until BICC20 for response to GS Spencer 810105.06 & G9 Ites ne 806926.1118-21 & 1208-17 insp ENGELMENTR H Region 3. San Francisco. Office of the Director 81/02/10 1p 07998 024
- --RIGG250032 Requests extension until B10220 to respond to G8 Spencer BIO105.06 t 09 ltrs to 15 to 504 BIO105.06 t 09 ltrs to 504 BIO105.06 t 07998 040
- --BL03250039 Forwards IE Irap Repts 50-508/80-17 & 50-509/80-17 on ingabuly horwards it Insp Hepts 50-508/80-17 & 50-509/80-17 or 801208-19 & hotice of violation SPENDER 9 S. Region S. San Francisco. Reactor Construction & Engineering Support Branca 81/01/09 2pp 07998 041
- --8103250042 Notice of violation from insp on 801208-19 BPENCER, 0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 81/01/09 1p 07978-043
- --BL03250047 IE lnsa Repts 50-508/80-17 & \$0-509/80-17 on B01208-19 Noncompliance roted failure to properly perform welder Qualification tests
  BIBHOP.T W Region 3. San Francisco, Office of the Director
  DODDB.R T Region 5. San francisco, Reactor Construction & Engineering Support Branch 81/01/08 7pp 07978 044
- DOCKET BIN-50-909 MPPSS NUCLEAR PROJECT. UMET 5
- A Application/engateuction state documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for Dis & holders of CPs re-control of heav, loads Requests review per guidelines in N.REG-0612 Forwards MRC position re-interim actions & request for add info EISENHUT, D. G. Division of Licensing 80/12/22 30pp
- B1031903B7 Ltr to all licensees of operating plants & applicants for NOTIONAL TO All Intenses or operating planes wapping OLs & holders of CPs repropram for environ qualification of safety-related electrical equipment, items addressed involve cold shutsown, replacement parts & hu9ED-0737 EISENHUT.D O Division of litensing 81/01/19 App
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Ital III A I 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates uill be met EISENHUT.D. Q. Division of Licensing 81/02/18 12pp
- B103290024 Ltr to all power reactor licensees 5 license applicants re NUREO-0519 criteria. Footnote 2 in Table 2 contains error due to leelage testing deletions Licensee may submit analysis to justify use of existing low flow controller EIBENHUT, D.O. Division of Licensing 81/02/20 Bpp
- B103230B13 Generic Ltr B1-06 to all CP holders & DL applicants re IOCFR30 71(e), "Periodic Ugdating of FSARs." effective B00722 Info re FBAR legal status format & content enci EISENWIT.D 9 Division of Licensing. B1/02/26
- BiO3i20185 Notifies that IE requested that encl preservice insp & test requirements for snubbers be included in licensing process. Requests that requirements to insure snubber operability be TEDESCO.R L Assistant Director for Licensing 81/03/06 600
- Bi03310804 Ltr to all licensees of operating plants applicants for OLs & holders of CPs forwarding SECY-BI-119 to info necessary to establish environ qualification of safety-related electrical equipment EISENHUT, D. O. Division of Licensing B1/03/10 App.
- F Security, medical, emergency & Pire protection plans

ı

8103310338 Ltr to all licensess of operating plants & holders of CPs forwarding NURGO-0696. Functional Criteria for Emergency Response Facilities. 'Criteria describe acceptable method for meeting NC requirements W/o encl
EIBENHUT: D 0 Division of Licensing 81/03/05. 6pp.

- 9103310512 Forwards 801212 ltr requesting NAC conc offgite emergency operations facilities Facilities offsite emergency operations facilities facilities technically adequate w/o add1 tackup facilities than 10 miles despite NUREG-0696 guidance BCUCHEY, Q. D. Washington Public Power Supply Sys
- --- 9103310520 Requests NRC concurrence re adequacy emergency operation facilities Util should not & required to relocate facilities if current N tellthom era BOUCHEY, G D. Washington Public Power Supply S 300
- P Operating license stage documents & corresponde
- 8103120014 Ltr to all licensees of operating plant applicants except Indian Point 2 & 3.2ion & & 2 forwarding inadvertently omitted pages from NRC request for addlinfo re control of heavy loads EIBEN-UT, D. Q. Division of Licensing 81/02/03
- O Inspection reports. IE Bulletins à corresponden
- B103180083 Forwards IE Insp Repts 90-908/80-13 % 9 830929-1030 % notice of violation SPENCER. 9. S Region 5. San Francisco. Reactor C Engineering Support Branch 80/12/12 2pp 07
- -- 8103180087 Notice of violation from 10sp on 8309 SPENCER.9 S Region 3. San Francisco, Reactor Engineering Support Branch 80/12/12 2cp
- --B103180093 1E Insp Repts 50-508/80-13 & 50-509/8 Noncompliance noted failure to accomplish bolt Noncompliance noted failure to accomplish bolt properly translate design requirements by to primaintain equipment BISHQP.T.W. Region 5. San Francisco. Uffice of MAYNES, R.C. Region 5. San Francisco. Reactor Engineering Support Branch 80/12/10 17pp
- 8103040339 Forwards IE losp Repts 50-908/80-16 & S
- 801031-1204 No noncompliance noted BPERGER 9 5 Region 5. Ban Francisco. Reactor C Engineering Support Oranch 81/01/13 2pp 07 --B103040346 IE Insp Repts 50-508/80-16 & 50-509/8
  - noncompliance note in a province the steel erection findluding containment structural steel erection storage & handling BIBHOP. T. W. Region S. San Francisco. Ufflice of DDDBS.R. T. Region S. San Francisco. Reactor C Engineering Support Branch 81/01/12 Spp
- 8)03020041 Forwards IE Circular 81-02, "Performanc Individuals While on Duty " No written response ENGELKEN.R H Region 5, San Francisco, Office o 81/02/09. 1p 07787 204
- BIO3170006 Forwards IE Circular 81-03, "Inoperable Instrumentation" No response required ENGELAEN.R H Region 5, Sen Francisco, Office of BI/03/02 Ip 07937 104
- 8103269009 Responds to IE Bulletin 80-09, "Hydramo Daficiencies" Updates 800625 & 0922 responses & supplied actuators found deficient American Harn Ventilation Co supplied actuators being examined DOBSGN.D. E. Washington Public Power Supply Syst CB042 106
- 8103260037 Responds to IE Bulletin 80-23. "Failure Mfg by Valcor Engineering Corp." All contractors subcontractors requested to identify Valcor valvalves found will be replaced DOBSON.D.E. Washington Public Power Supply Syst 08042-120 08042: 120-
- B103160B30 Forwards revised IE Bulletin 81-01. "Gi Mechanical Gnubbers." w/corrected Pages 5 % 6.Ch identification of facilities w/CPs to which bull applicable does not affect util requirements. ENGELKEN,R If Region 5. San Francisco, Office of 81/03/04 1p 07914.187
- 8103120186 Natifies that IE requested that encl pr requirements for shubbers be included in licensi Requests that requirements to insure soubber ope implemented.
  TEDESCO.R.L. Assistant Director for Licensing

- 9:03180828 Forwards IE Mgt Meeting Repts 50-460/81-03. 50-508/81-03. :Usiaudau romaerds it Mgs Neeting Repts 50-460/81-03.50-508/81-0 50-509/81-03 & 50-513/81-03 on 810225 ENGELAEN,R H. Region 5. San Francisco. (Vilice of the Director 81/03/06 ip 07953 155
- --8103183851 IE Mjt Meeting Repts 50-450/81-03.50-508/81-03.50-509/81-03 t 50-513/81-03 on 810225 No noncompliance noted Areas discussed actions taken re-concerns expressed by mgt at Dct
- CISCUSSED ACTIONS OF THE CONTROL OF Construction & Engineering Support Branch 81/03/04 07757: 156
- BIO3230288 Forwards IE Info Notice Bi-06. 'Failure of ITE Model K-600 Circuit Breaker ' No response requires ENDELMEN.R H Region 3. San Francisco. Office of the Director BI/03/11 1p 07969 001
- 8:03200066 Forwards IC Info Notice 81-05. Degraded DC Sys at OSZONOSA FORMATOR IN THE NUCLEE 81-05. Degraded DC Sys at Palisades. "No response required FASELMEN.R II Region 5. San Francisco. Défice of the Director 01/03/13 1p 07970 GBI
- 9103290019 Ack receipt of 810219 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-508/80-17 & 50-508/80-17 FAULKENBERRY, R Region 5. 81/03/18 1p 07978 034 Region 5. San Francisco. Office of the Director.
- --8)00250025 Responds to NRC 810109 ltr re-violations noted in 1E Insp. Repts 50-500/80-17 5 30-509/80-17 Corrective actions welders requalified under correct testing procedures & new guided
  - . \*Committee one connect testing procedures & new guided band test jig requisitioned COMBON. D.E. Mashington Public Power Supply Bystem 81/02/19 4pp 07790 035
- --8103250020 Approves extension until 810220 for response to 05 Spencer 810105.06 & 07 ltrs re 803726.1118-21 & 1208-19 insp ENGELKEN.R II Region 5. San Francisco. Office of the Director 81702/10 | jp 07778 037
- --BIO3250032 Requests extension until BIO220 to respond to GS Spencer BIO105. On & 09 live ce IE imaps D3BBON.D.E. Washington Public Power Supply System BI/01/29. Ip 07998 040
- --8103280039 Forwards IE Insp Regts 30-508/80-17 & 50-509/80-17 on 801208-19 & notice of violation SPERCER, O.S. Region 9. Sen Francisco. Reactor Construction & Engineering Support Dranch 81/01/09 2pp 07978 041
- --B103250347 IE Insp Repts 50~508/80-17 \$ 59-509/80-17 on 801208-19 Nancompliance noted failure to properly perform welder qualification tests BIBHOP, T. W. Region 5. San Francisco. Office of the Director DODDS, R. T. Region 5. San Francisco. Heactor Construction &

Engineering Support Branch 01/01/00 7pp 07990 044

- DOCKET SO-510 BLUE HILLS STATION, UNIT I
- U Contrassional/Executive Correspondence

MENDRIE. J. M. Compissioners 81/03/12 5pp

- 3103270110 Responds to request for rept on possible addl improvements to NRC licensing pricess togislation allowing interim operations in advance of hearing completion would reduce delay in licensing process
- --BI03270947 Submits recommendations re scheduling personnel resources & hearing mgt for OL proceedings. Panel must obtain exemption from hir ing freeze for two recently appointed chairmen COTTER: B P Atomic Safety and Licensing Board Panel. 81/02/25
- COCKET 50-511 BLUE HILLS STATION, UNIT 2 U Congressional/Executive Correspondence

3Эрр.

8103270110 Responds to request for rept on possible addl improvements to NRC licensing process Legislation allowing interim operations in advance of hearing completion would reduce delay in licensing process B1/03/12 5pp

- --- 8100270947 Submits recommendations re-scheduling.personnel resources ( Position of the commendations of scalabiling personnel resourced in the proceedings from the proceedings from the firm of the cele for two recently appointed chairmen COTTER-B P. Atomic Safety and Licensing Board Panel. 81/02/25 33100
- DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4 A Application/construction stage documents & correspondence
- B103190732 Litrs to all licensees of operating plants applicants for DLs 5 holders of CPs re control of heavy loads Hequests review per guidelines in AUREG-0612 Forwards NRC position reinterim actions & request for addl tofo EISENHUT, D.O. Division of Licensing 80/12/22 3000
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification
- of safety-related olectrical equipment Items addressed involve cold shutdown.replacement parts 5 NLRE9-0737 EBERNALD 0 Division of Licensing 81/01/19 app
- B10312C014 Litr to all licenses of operating plants CP holders & OL applicants, ercept bidsan Point 2 & 3.2 ton 1 & 2 & THI-1, forwarding inadvertently omitted pages from 18C B01222 request for addi info re control of heavy loads EISENHUT. D. C. Division of Licensing 81/02/03 App
- BiO3160667 Ltr to ail operating plants & CP holders forwarding clarification of TMI Action Plan Item III A I 2 re upgrade of energency support facilities Requests confirmation within 45 days that implementation dates will be not
- EISENHUT, D. 9 Division of Licensing 81/02/18 12pp 8103290024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing fou flow controller EISEN-UT. D. 9 Division of Licensing 81/02/20 8pp
- B103230B13 Generic Ltr B1-06 to all CP holders & OL applicants re 10CFR30. 71(e). "Periodic Updating of FSARs." effective 800722 Info re FSAR legal status/format & content encl
- EIBENHUT, D O Division of Licensing 81/02/26 10pp B103120186 Notifies that IE requested that enci preservice insp & test requirements for snubbers be included in licensing process. Requests that requirements to insure snubber operability be
- BiO3310834 Ltr to all licenses of operating plants applicants for OLs & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ qualification of safety-related electrical

TEDESCO, R L. Assistant Director for Licensing 81/03/06 App.

F Becurity, medical, emergency & fire protection plans

FIRSTHULL, D. G. Davising of Licensing, 81/03/10 600

implemented

- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements I/To encl.
  EISENHUT, D. Q. Division of Licensing. 81/03/05 66p.
- B103310512 Forwards 801212 ltr requesting hRC concurrence u/location of offsite emergency operations facilities. Facilities are technically adequate u/o additionally facilities at greater than 10 miles. despite NREG-0496 guidance.
  BDUCKEY. @ D. Washington Public Power Supply System 81/03/20. 1p
- --8103310520 Requests PRC concurrence re adequacy of location of offsite tousinger requests rac concurrence re agricaty or location be emergency operation facilities. Util should not be penalized & required to relocate facilities if current NRC guidelines are modified BOUCHEY, G.D. Washington Public Power Supply System. 80/12/12. 300
- G Inspection reports. IE Sulletine & correspondence
- B103190006 Forwards IE Insp Repts 50-460/81-01 & 50-513/81-01 on BiOli3-16 No noncompliance noted.
  SPENCER, G. S. Region 5. San Francisco. Reactor Construction &
  Engineering Support Branch 81/01/26 2pp 07962-340.

- --8103190011 IE Insp. Repts 90-460/81-01 & 90-513/81-01 on 810113-16 No noncompliance noted Major areas inspected constructivities including licensee action on previous insp findings.

  10CFR90 95e Items IE buildting & potential 10CFR91 defects KIRSCH.D.F. WARNER, H.J. Region 3. San Francisco. Office of the Director. DUDDS, R. T. Region 3. San Francisco. Reactor Construction & Engineering Support Branch 81/01/23 8pp 07962-342.
- 6103020136 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Specified valve parts were not used by vendors Response from 85% outstanding Results will be sent by 810522 MAZUR. D. W. Mashington Public Power Supply System 81/02/03 29: 07387.094
- 8103020072 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty" No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 81/02/09 p. 07787:302.
- 8103040313 Ack receipt of 810127 ltr informing N9C of steps taken to correct violations noted in JE Insp Repts 50-460/80-11 & 30-513/80-11 \$PENCER.9.8 Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 81/02/09 1p 07820-086
- --8103040325 Responds to KRC B01007 & 810105 ltrs re violations noted in FE Insp Repts 50-460/80-11 & 50-513/80-11 Corrective actions initiated B10114 field change notice for technical direction re removal of support 1058 from pipe spool MAZUR.D U Washington Public Power Supply System 81/01/27 3pp 07820 087
- --Bi03040332 Ack receipt of Bi1106 Itr informing NRC of steps taken to correct violations noted in IE Ins; Repts 50-460/80-11 & 50-713/80-11 Add1 info required re undersized pips spool lugs & nondestructive exam SPENCER, 9 Region 5. Ben Francisco, Reactor Construction & Engineering Support Branch Bi/01/03 2pp 070820090
- --B103040341 Responds to NRC 801007 ltr re violations noted in IE Insp. Repts 50-460780-11 & 30-513780-11. Corrective actions GA surveillance performed on random sample of spools & drawings identifying pipe spools w/shop-welded lugs MAZUR:D W. Washington Public Power Supply System. 80/11/06 3pp. 07820 092.
- --8103040350 Forwards IE Insp Repts 50-460/80-11 & 50-513/80-11 on 800828-29 & 0909-12 & notice of violation SPENCER.0.8 Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/10/07. 2pp. 07820-095
- --8103040374 IE Insp Repts 50-460/80-11 % 50-513/80-11 on B00826-29 & 0909-12 Noncompliance noted: undersized shop welds on gipe to pipe attachment fillet welds & unauthorized removal of arc strikes from stainless steel pipe epool KIRBCH.D.F. TOTH.A.D. HERNANDEZ.O. Region 3, 8an Francisco, Office of the Director. 80/10/03 16pp. 07820.099
- 8103170005 Forwards IE Circular 81-03, "Inogerable Seismic Monitoring Instrumentation." No response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 81703702. ip. 07939.102.
- B103140081 Forwards revised IE Bulletin B1-01. "Burveillance of Mechanical Bnubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. ENGELKEN.R.H. Region 5, San Francisco. Office of the Director. B1/03/04. Ip 07914:350.
- 8100120186 Notifies that IF requested that encl preservice insp & test requirements for snubbers be included in licensing process Requests that requirements to insure snubber operability be implemented. TEDEBGO.R.L. Assistant Director for Licensing. 81/03/06 opp.
- 8103180828 Forwards IE Mgt Meeting Repts 50-460/81-03, 50-508/81-03 & 50-513/81-03 on 810225. ENOELKEN.R H Region 5, San Francisco. Office of the Director. 81/03/06. ip.
- --BIO3180851 IE Ngt Meeting Repts 50-460/81-03.50-508/81-03.50-509/81-03 & 50-513/81-03 on BIO228. No noncompliance noted Areas discussed: actions taken re-concerns expressed by mgt at Oct 1980 systematic appraisal of licensee performance meeting FAULKENBERRY, B. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. BI/03/04. 4pp.

- B103200233 Forwards IE Info Notice 81-06. 'Failure of ITE Mad Circuit Breater' No response required EMBELERIAR H. Region 5. San Francisco. Office of the Direc 81/03/11 Ip 07968 325
- BIOS200064 Forwards IE Info Nutice 81-05. "Degraded DC Sis at Palisaces." No response required ENGELKEN.R H Region 5. San Francisco, Office of the Direc 81/03/13 ip 07968 264
- S Reportable occurrences. LERs & related correspondence
- 810302050B Interim deficiency rept for diesel generator combutantate design, originally reported 80120B Design revisions ensuring actuation of generator under tornado conditions currently being evaluated Final rept to be issued 810601 MAZUR, D. M. Washington Public Power Supply Bystem 8170170 07785 061
- 8103020605 Interim deficiency test to Bostrom Bergen Hetal Propelled assemblies. Initially reported on 801208 Hold has been established on assemblies prior to embedment to allow GA review of all records Final rept will be sent by 810501. TAXUN.D W. Washington Public Power Supply Gystem. 81/01/0
- 8103120423 Interim deficiency rept re inadequacy of load rest for spent fuel cash handling crame in General Svcs Bldg. Initially reported on 810107 Following selection of corrective action final rept will be forwarded MAZURID W Washington Public Power Supply System 81/02/0 07901:220
- DOCKET 90-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- BIO3190387 Ltr to all licensees of operating plants & applica
  DLs & holders of CPs re program for environ qualification
  of safety-related electrical equipment Items addressed
  involve toild stutdown-replacement parts & NUREO-0737
  EIGENHUT.D.O Division of Licensing GI/01/19 &pp
- 8103290024 Ltr to all power reactor licensees & license applie MUREO-0619 criteria Footnote 2 in Table 2 contains error duto leakage testing deletions Licensee may subnit analysis trustify use of existing low flow controller EISENHUI.D.G Division of Licensing 81/02/20 Bop

## Q. Adjudicatory correspondence

- B103030773 Response to NRC & applicant findings of fact & confidence environ & site suitability Intervenor agrees w///R Findings 07-45 & 9. npposes NRC Findings 37-45 & applicant Findings 21-27, 118 & 121-125 W/Certificate of Svc MARBETLE M. Forelaws on Board 81/02/13. 6pp 07791 300
- B103030724 Clarifies intent of B10122 motion for suspension of hearings & findings of fact & conclusions of law Forelaws of Board enticipates reviewing & supplementing proposed findings & conclusions filed B10213.

  MARBET-L K. Forelaws on Board 81/02/27. 2pp 07585 001
- 8103060370 Response opposing intervenors' motion for suspensifurther limited hearings & issuance of partial initial decision ASLB proceedings can continue pending state & local developments. Certificate of Svc encl.
  BORDENICK, 8 M Hearing Branch 4. 81/03/04. 7pp. 07037:1
- 8103130420 Order denying intervenor Big123 motion to suspend hearings & proposed findings of fact & conclusions of law Util may engage in administrative proceedings before ABLD w/state & local developments pending. BOWERS.E.B. Atomic Safety and Licensing Board Panel. 81/6 3pp. 07911:220
- B103270652 Advises of stipulation re Intervenor proposed cont NRC elternative site analysis & discovery & hearing schedule Btipulation should be forwarded within next severa wis BORDENICK, B. M. Hearing Branch 4 81/03/26

- CCCRET 50-915 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8103190387 Ltr to all licensees of operating plants & applicants for OLS & holders of CPS to program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown replacement parts & NUREG-0737 ELBERSHIT D. 0. Nurstion of Licenseep B. 1001/19 App.
- 8103189037 Unofficial transcript of Commission 810212 meeting in Washington. DC re SECY-81-20 policy on proceeding U/pending CP % mfg license applications Pp 1-115.

   Convissioners 81/02/12 117pp
- --810303C450 Recommends Commission approve encl draft final rule IOCFR50 re licensing requirements for pending CPs & mfg license applications x proposed statement of requirement re degraded core rulemaking
  DIRCKS.W J Office of the Executive Director for Operations.
  BECY-81-020A 81/02/11 12pp
- A103290024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing defetions Licensee may submit analysis to justify use of existing low flow controller E1SENHUT.D 0 Division of Licensing 81/02/20 8pp

### O Adjudicatory correspondence

- B103030773 Response to NRC & applicant findings of fact & conclusions of law re environ & site suitability Intervenor agrees w/NRC findings D-3:6 & 9.0pposes NRC Findings 37\*45 & applicant Findings 21-27.118 & 121-125 N/Centificate of Svc. MAREET, LK Foreless on Board & B/O2/13 & 6pp 07791 330
- 0103050724 Clarifies intent of 010122 notion for suspension of further hearings & findings of fact & conclusions of law Forelaws on Board anticipates reviewing supplementing proposed findings & conclusions filed 010213

  MARBETIL K Forelaws on Board 01/02/27 2pp 07505 001
- 8103060370 Response opposing intervenors' motion for suspension of further limited hearings & issuance of partial initial recision ABLB proceedings can continue pending state & local developments Certificate of Svc encl BORDENICK. B M. Hearing Branch 4. 81703704 7pp 07837 114.
- 9103130420 Order denying intervenor 010123 motion to suspend further hearings by proposed findings of fact b conclusions of law Util has engage in administrative proceedings before ABLB U/state b local developments pending EDMERBLE B. Abonic Safety and Licensing Board Panel B1/03/10. 3pp. 07911-220.
- 8100270692 Advises of stipulation re intervenor proposed contentions on MRC alternative site analysis & discovery & hearing schedule Btipulation should be forwarded within next several Lis.

  ECROBATION B M Hearing Branch 4 81/03/26. 10. 08043 256.
- DOCHET BIN-90-916 JAMESPORT NUCLEAR STATION, UNIT 1 E. ARC Safety Evaluation Report (SER), supple & correspondence
- B103230960 Discusses OL hearing scheduling process. EER technical input schedule for CVB1 & CVB2 encl DENTON.H R DPfice of Nuclear Reactor Regulation, Director. 81/03/13. Spp. 07977-099.
- O Inspection reports. IE Bulletins & correspondence
- Bi03200140 Forwards IE Circular 81-03, "Inoperable Beismic Monitoring Instrumentation." No written response required CRIER.B.H. Region 1. Philadelphia. Diffice of the Director. 81/03/02. p. 07971.347.
- 8103230224 Forwards revised IE Bulletin 81-01. "Gurveillance of Mechanical Snubbers." w/corrected Pages 5 & 6. Change in identification of facilities w/CPe to which bulletin is applicable does not affect util requirements. (RIER. B.H. Region 1. Philadelphia, Office of the Director. BI/03/04. p. 07977:258.
- 810320016; Forwards IE Info Notice 81-06. "Failure of LTE Model K-600 Circuit Breaker" No response required.
  ORIER-8.H Region 1. Philadelphia, Office of the Director.
  81/03/11. 1p. 07968 298

- S Reportable occurrences. LERs & related correspondence
- B103120406 Interim deficiency rept.originally reported B10117.re potential defects so seam weld decay heat removal exchanger tubing. Generic implications under investigation Eddy current testing program will be used to supply visual data MAZUR. D. H. Nashington Public Power Supply System 81/01/30 3p.07904 360
- DOCKET BIN-50-517 JAMESPORT NUCLEAR BIATION, UNIT 2

  E NRC Safety Evaluation Report (SER), supple & correspondence
- 8103230860 Discusses OL hearing scheduling process BER technical in schedule for CYB1 & CYB2 encl DENTON-N R. Office of Nuclear Reactor Regulation. Director B1/03/13 5pp 07977 099
- G Inspection reports. IE Bulletins & correspondence
- 8103200140 Forwards IE Circular 81-03, "Inoperable Beismic Monitori Instrumentation " No written response required GRIER D. H. Region 1, Philadelphia, Office of the Director 61/03/02 ip 07971-347
- BiO3230224 Forwards revised IE Bulletin 81-01, "Burveillance of Mechanical Bnubbers," w/corrected Pages 5 & Change in identification of facilities w/CPs to which builetin is applicable does not affect util requirements GRIER.B. Region 1. Philadelphia. Office of the Director Bi/03/04. p 07977 258
- 8103200161 Forwards IE Info Notice Bi-06, "Failure of ITE Model K-6 Circuit Breaker," No response required. GRIER.B.H Region 1, Philadelphia, Office of the Director BI/03/11 p. 0796B 29B
- DOCKET SYN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensess of operating plants applicants for CLs & holders of CPu re control of heavy loads. Requests review per guidelines in NUREO-0612 Forwards NRC position re interim actions & request for addl
- 01031903B7 Ltr to all licements of operating plants & applicants for CX.s & holders of GPs re program for environ qualification of safety-related electrical equipment. Items addressed involva cold shutdown-replacement parts & NUREO-0737. ETBENHUT.D.O. Division of Licensing. 81/01/19. App.
- BIO3140669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A.1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met EISENHUT. D. O. Division of Licensing. Bi/O2/18. 12pp.
- 8103250024 Ltr to all power reactor licenses & license applicants : NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licenses may submit analysis to justify use of existing low flow controller. EISELHHUT, D.O. Division of Licensing 81/02/20. Bpp
- 8103170225 Ltr to all BHR licenses (except Humboldt Bay & LeCrosse requesting review of ASME Code Class 1 & 2 pressure boundary piping, fafe ands & fitting matiper guidelines of anci Revision 1 to NUREG-0313. Hodel Tech B
- --BiD3170266 Hodel Tech Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 & 3/4 4 surveillance requirements for ABME Code Class 1,2 & 3 components & ACB operational leakage limiting conditions for operation & surveillance requirements.

  e General Electric Go. Bi/02/26. 4pp.
- 8103170655 Ltr to holders of CPs & applicants for DLs (BHRs) reques review of ASME Class 1.2 & 3 pressure boundary piging, safe ends & fitting mat1 per guidelines of encl Revision 1 to NUREQ-0313 Model Tech Epecs only encl.

  EISENHUT.D. G. Division of Licensing. 81/02/26 3pp.
- 8103230813 Generic Ltr 81-06 to all CP holders & DL applicants ru 10CFR50, 71(e), "Periodic Updating of FSARs." effective B00722 Info ru FSAR legal status format & content enci. EISEMHUT. D. O. Division of Licensing. 81/02/26 10pp.

- 8103310804 Ltr to all litensees of operating plants.applicants for OLs 5 holders of CPs forwarding SECY-Bi-119 rs info necessary to establish environ qualification of safet,-related electrical equipment. EISENHUT.D O Division of Licensing. 81/03/10 63p
- 8103200577 Forwards plan for implementing mussel monitoring program requirements in CP Excavation for discharge diffuser tentatively scheduled for Oct 1981 Prediffuser const monitoring will be initiated in near future.

  HILLS.L.M. Tennessee Valley Authority. 81/03/13 7pp 07968 089
- F. Security, medical, emergency & fire protection plans
- B103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREQ-0056. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NPC requirements W/o encl FISFN-HULD & Division of Licensina B1/03/05 Ann
- Q. Inspection reports: 1E Bulletins & correspondence
- 0102280484 Forwards IE Info Notice 81-01. "Possible Failures of GE Type HFA Relays " No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/01/16 ip.
- 8:03020277 Forwards IE Circular 8:-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/02/0
- B103Q40753 Provides add1 response to 1E Bulletin B0-20 re Westinghouse Type H-2 suitches Info from GE re STRIDE portion of facilities has not been received Info anticipated by B10615 HILLE-L M Tennessee Valley Authority 81/02/10 1p. 07810 t23
- B103190180 Forwards 1E Insp. Repts 50-519/81-01, 50-519/81-01, 50-520/81-01 & 50-521/81-01 on 810106-09. No noncompliance noted MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch, 81/02/10. 2pp. 07965-023
- --8103190194 IE Insp Repts 50-518/81-01.50-519/81-01.50-520/81-01 & 30-521/81-01 on 810106-09 No noncompliance noted Major areas inspected previous insp findings, safety-related gipe & structural steel welding.

  CROMLEY, 8 R. Region 2. Atlanta, Office of the Director HERDT, A. R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/02/09 Bp. 07905-026
- 8103240152 Forwards IE Insp Rapts 90-518/81-02, 50-519/81-02, 50-520/81-02 & 50-521/81-02 on 810105-30 No noncompliance noted. MRPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 81/02/12. 2pp. 07980 230.
- --B103240162 IE insp Repts 50-518/81-02.50-519/81-02.50-520/81-02 & 50-521/81-02 on 810108-30 No moncompliance noted Major areas inspected open items.A-1 drywell penetration frames & A-1 weir wall SMAN.W B. Region 2. Atlanta. Office of the Director CANTRELL,F S. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/11. Spp. 07980 232
- 8103130230 Forwards Suppl 5 to IE Sulletin 80-17. "Failure of Control Rods to Insert During Screm at SWR ' No written response required COSTILL I.S. Beaten 2. Atlanta District of the Parents of the Par
- required O'REILLY, J.P. Region 2. Atlanta: Office of the Director. 81/02/17. Ip. 07908:357.
- B103160516 Forwards IE Circular B1-03. "Inoperable Seismic Monitoring Instrumentation." No response required. KEPPLER, J. 9 Region 3. Chicago, Office of the Director. B1/03/02 lg.
- 8103170011 Forwards revised IE Bulletin 81-01. "Burveillence of Mechanical Bnubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 81/03/04 to
- B103160193 Ack receipt of 810206 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 30-380/80-24 & 30-320/80-24 Final response to be submitted by 810031 LEWIS-R. C. Region 2. Atlanta: Reactor Operations Nuclear Support Branch. 81/03/06 1p. 07921:230.

- --BIO3160205 Responds to NRC BIO114 ltr re violations noted in Repts 50-518/80-24 & 50-520/80-24 Corrective actions: all currently open notification of change repts will be review for inclusion of cause & action to prevent recurrence MILLS.L M. Temessee Valley Authority BI/02/06 Tpp 67991 211
- --5103160215 Forwards 1E Insp Repts 50-518/80-24 & 50-520/80-2/ 201112-13 & notice of violation. App A PURPHY.C E Region 2. Atlanta. Reactor Construction & Eng: Eugoport Branch 81/01/14 2pp 07921 234
- --Bi03160225 Notice of violation from insp on 801112-13
   Region 2. Atlanta. Office of the Director B1/01/14
  07921 236
- --Bi03i60235 IE Insp Repts 30-5i8/80-24 & 50-520/80-24 on B0]1 Noncompliance noted failure to document cause & take corrective action on Notification of Change Rept HNPA-114. HARRIS-J.R. Region 2. Atlanta. Office of the Director. CONLON-T.E. Region 2. Atlanta. Reactor Construction & Eng Support Branch B1/01/13 3pp 07921 237.
- 8103200197 Forwards IE Info Notice 81-06. "Failure of ITE Mode Circuit Breaker' No response required G'REILLY.J P Region 2. Atlanta. Office of the Director 8 ip
- 8103200003 Forwer's IE Info Notice 81-05. "Degraded DC Sys at Palisades ' No response required. C'REILLY.J.P Region 2. Atlanta, Office of the Director fl
- 8 Reportable accurrences. LERs & related correspondence
- 8)03100281 Part 21 rept re reactor protection sys panel design deficiencies initially reported on 800807. Util is auaiting info from GE re final corrective actions.

  MELB.L M Tennessee Valley Authority 81/02/12 2pp 07
- B103040559 First interim deficiency rept.originally reported of 8 0203, re-deficient drawing & document control Bixteen drawings not motilated when new revisions received & drawings not wedsted Will submit final rept by 810316 MILLBL M Tennessee Valley Authority 81/02/26 3pp 091
- 8103130009 Part 21 rept re standby gas treatment sys charcoal initially reported 800508 Final rept will be submitted by 810922 MILLS.L M Tennessee Valley Authority 81/03/02 2pp 02:
- 8103170389 Interim Deficiency Rept 1 re unacceptable wolds document acceptable, initially reported 810206 Approx 60 of 920 total welds identified as deficient, although passed by stringsectors Add1 info will be provided by 810505 MILLS.L.M. Tennessee Valley Authority 81/03/10. Ip 0793
- 8103240430 Final Deficiency Rept 2 re failure to provide recip w/up-to-date revisions of 12 CF Braun specs & associated engineering change notices, initially reported on 810127 & 0203 Superseded documents replaced w/current revisions MILLB, L. H. Tennessee Valley Authority 91/03/16. 4pp 02
- 8103300333 Supplemental Interim Deficiency Rept 2 re-potential excessive pressure drop in essential svc water sys raw water piping, initially reported on 801210 Study being conducted to resolve deficiencies noted in Divs 1 & 2 MILLS-L.M Tennessee Valley Authority. 81703/20. 2pp 08:
- DOCKET 8TN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants applicant DLs & holders of CPs re-control of heavy loads Requests review per guidellines in NUREO-0612 Forwards NRC position reinterim actions & request for add info. EISENHUT. 0. 0. Division of Licensing. 80/12/22 30pp
- B103190387 Ltr to all licensees of operating plants & applican OLs & holders of CPs re program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown, replacement parts & NUREO-0737 EISENHUT, D. O. Division of Licensing. 81/01/19. App.

- G103120014 Ltr to all licensees of operating clames.CP holders & CL applicants.ercept Indian Point 2 & 3. Zion 1 & 2 % TMI-1, farwarding inadvertently oritted pages from NRC 801222 request for audi info re-central of heavy loads EISENHUI.D G Division of Licensing 81/02/03 App
- 8103166269 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Pien Item III A i 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be not EISERWUT. D.G. Division of Licensing 81/02/18 12pp
- 8103250024 Ltr to all power reactor licensees & license applicants re MREG-Obi9 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENNUT. D 9 Division of Licensing 61/02/20 8pp
- 6103170225 Ltr to all HWR incensees (except Humbolst Bay & LaCrosse) requesting review of ASME Code Class I & 2 pressure boundary paping-safe ends & fitting math per guidelines of encl Revision I to NUREO-0313 Model Tech Specs anny oncl EISERMUT. D. O. Division of Licensing 81/02/26 30p
- --8103170266 Model loth Specs Pages 3/4 0-2,3/4 0-3,3/4 4-7 % 3/4 4-8 me surveillance requirements for ASMS Code Class 1.2 % 3 components & RCS operational leakage limiting conditions for operation & surveillance requirements 
   General Electric Co. 81/08/26 4pp.
- 8103170655 Litr to holders of CPs & applicants for CLs (BHRs) requesting review of ASME Class 1.2 % 3 pressure boundary piping, safe ends & fitting rail per guidalines of anci Revision I to AMREG-0313 Model Tech Specs only encl EISERHUT. D.O. Division of Licensing 81/02/26 3no
- 9103230913 Generic Ltr 81-06 to all CP holders & C. applicants re IGCR\$0 78(a). 'Periodic Updating of FBARs.' effective F30722 Info re FSAR legal status.format & content encl FICENHUT.D 0 Division of Licensing 81/02/26 10pp
- 8:033:0804 Ltr to all licensums of operating plants applicants for CLs & holders of CPs forwarding SECY-91-119 re info necessary to establish environ qualification of safety-related electrical equipment.

  FISEPHANT, D. 2. Division of Licensing B1/03/10 Ann
- 8103209577 Forwards plan for implementing mussel monitoring program requirements in CP Excavation for discharge diffuser tentatively scheduled for Oct 1981 Prediffuser constitutioning will be initiated in near future MILLS.L.M. Tennossee Valley Authority 81/03/13 7pp 07968-089.
- F. Becurity, medical, emergency & fire protection plans
- 9)033)033B Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. 'Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements N/o encl EISENHUT. D.O. Division of Licensing 01/09/05 App
- G. Inspection reports. IE Bulletins & correspondence
- 0109280404 Forwards IE info Notice 81-01. "Possible Failures of GE Type IFA Relays " No response required O'RELLEY.J P Region 2. Atlanta. Office of the Director Bi/01/16
- 8103020277 Forwards IE Circular 81-02, "Performance of NRC-Licensed Troividuals While on Duty." No written response required D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 91/02/09
- 8103340752 Provides add1 response to IE Bulletin 80-20 re Westinghouse Type M-2 switches Info from 0E re BIRIDE portion of facilities has not been received info anticipated by 810619. MtLB.t. M Tenessas Valley Authority. 81/02/10 Ip. 07810:123
- 8103190180 Forwards IE Insp Repts 30-518/81-01,50-519/81-01, 50-520/81-01 & 50-521/81-01 on 810106-09 No noncompliance noted MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/02/10 2pp 07965 023

- ---B103193194 IE insp Repts SC-518/81-01.50-519/81-01.50-520/81-01 & 50-521/81-01 on 810105-09 No noncompliance noted Major areas inspected previous insp findings safety-related pipe & structural steel welding CRCMLEY.8 R Region 2. Atlanta. Office of the Director. FERDILAR Regior 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/09 Bpp 07965 025
- B103240152 Forwards 16 Insp Repts 50-518/81-02.50-519/81-02. 50-520/81-92 & 50-921/81-02 on 810105-30. No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 81/02/12 2pp 07980 230
- --8103240162 TE Insp Repts 90-518,81-02.50-519/81-02.50-520/81-02 & 50-521/81-02 on 810105-30 No noncompliance noted Major areas inspected open items.A-I drywell penetration frames & A-I weir wall SMAXLW B Region 2. Atlanta. Office of the Director CANIRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/11 Spg 07980.232
- B103130230 Forwards Suppl 5 to 16 Bulletin B0-17. "Failure of Control Rods to Insert During Scram at BWR." No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B1/02/17 ip 07908 357
- B103160316 Forwards IE Circular B1-03. "Inoperable Seismic Monitoring Instrumentation " No response required KEPPLER. J. G. Region 3. Chicago. Office of the Director. B1/03/02 to
- BiO3170011 Forwards revised 1E Bulletin 81-01. "Surveillance of Mochanical Snubbers." w/corrected Pages 5 & & Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. O'REILLY. J.P. Region 2. Atlanta, Office of the Director 81/03/04 in
- B103200197 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/11 is.
- B103200003 Forwards 1E Info Notice B1-05. "Degraded DC Sys at Palisades." No response requires. O'REILLY-J P. Region 2. Atlanta. Office of the Director. B1/03/13 in
- S Reportable occurrences. LERs & related correspondence
- 0:103:100281 Part 2: rept re reactor protection sys panel design deficiencies initially reported on 800807 Util is awaiting info from OE re final corrective actions MTLLS.L M Tennessee Valley Authority 81/02/12 2pp. 07865 234
- 8103040397 First interim deficiency rept.originally reported on 810127 \$ 0203; re-deficient drawing 8 document control Sixteen drawings not mutilated when new revisions received 8 drawings not updated Will submit final rept by 810316 MICLS, LM Tennessee Valley Authority 81/02/26. 3pp 07809: 116
- Bio3240430 Final Deficiency Rept 2 re failure to provide recipients u/up-to-date revisions of 12 CF Braun specs & associated engineering change notices, initially reported on Bio127 & 0203. Superseded documents replaced u/current revisions MILLS, L. ff. Tennessee Valley Authority 81/03/16. 4pp. 07984-306.
- 8103300333 Supplemental Interim Deficiency Rept 2 re patential excessive pressure drop in essential evoluter sys raw weter piping. Initially reported on 803210 Study being conducted to resolve deficiencies noted in Bivs 1 & 2.

  MICLES, L. M. Tennessee Valley Authority 81/03/20. 2pp. 08055:292.
- DUCKET 81N-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- 8103190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re-interim actions & request for addi
- B1031903B7 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related slectrical equipment. Items addressed involve cold shutdown-replacement parts & NUREG-0737.
  EIBELBUT,D 9 Division of Licensing 81/01/19 App.

- BiO3120014 Ltr to all licensess of operating plants.CP holders & CL applicants, except indian Point 2 & 3.2icn 1 & 2 & TMI-1, forwarding inadvertently omitted pages from RRC BOI222 request for addl info re control of heav, loads EISENHUT,D & Division of Licensino 81/02/03 6cp
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of THI Action Plan Item III A I 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation deter will be met EISECHNUT. D O Division of Licensing 81/02/18 1200.
- BIO3250024 Ltr to all power reactor licensees & license applicants re NAREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee may submit analysis to justify use of existing low Flow Controller EIBENHUT.D 9 Division of Licensing. 81/02/20. Bpp
- 8103170225 Ltr to all BWR licensess (except Humboldt Bay & LaCrosse) requesting review of ABME Code Class 1 & 2 pressure boundary piping, safe ends & fitting mat! per guidelines of encl Revision I to NUREG-0313 Model Tech Specs only encl EIBENHUT-D Q Division of Licensing 81/02/26 3pp.
- --BIO3170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 & 3/4 4-8 re surveillance requirements for ABHE Code Class 1.2 & 3 components & RCS operational leakage liniting conditions for operation & surveillance requirements. • General Electric Co. BI/02/26 4pp
- 8103170655 Ltr to holders of CPs & epplicants for GLs (BMRs) requesting review of ABME Class 1.2 & 3 presents boundary piping, safe ands & fitting mat) per guidelines of encl Revision 1 to NUREO-0313 Model Tech Specs only encl E1861HU1.D Q Division of Licensina 81/02/26 3pp
- 8103230813 Oeneric Ltr 81-06 to all CP holders & OL applicants re 10CFRSO 71(e), "Pariodic Updating of FBARs," effective 8CO722 Info re FBAR legal status, fornat & content encl. EISEMHUT, D. 0. Division of Licensing. 81/02/26. 10pp.
- 8103310804 Ltr to all licensess of operating plants, applicants for OLs b holders of CPs forwarding 9ECY-81-119 re info necessary to satabilish environ qualification of safety-related electrical squipment.
  E1SENHUT.D.O Division of Licensing. 81/03/10 App.
- B103200577 Forwards plan for implementing dussel nonitoring program requirements in CP. Excavation for discharge diffuser tentatively scheduled for Oct 1981. Prediffuser const monitoring will be initiated in mean future MILLBL. M. Tennessee Valley Authority. B1/03/13. 7pp. 07968.085
- F. Becurity, redical, emergency & fire protection plans
- B10331033B Ltr to all licenses of operating plants & holders of CPs forwarding NUREG-0696. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements N/o encl. EISENHUTD.9. Division of Licensing. B1/03/05. 6pp.
- Q. Inspection reports: If Bulletins & correspondence
- B1022B04B4 Forwards 1E Info Notice 81-01. "Possible Failures of GE Type HFA Relays." No response required.
  DTREILLY.J.P. Region 2. Atlanta, Office of the Director. 81/01/16. to.
- 8103020277 Forwards IE Circular 81-02, "Performance of NRC-Licensed Individuals While on Duty " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/02/09. 1p.
- 8103040753 Provides add1 response to IE Bulletin 80-20 re Westinghouse Tupe W-2 switches. Info from GE re BIRIDE portion of facilities has not been received. Info anticipated by 810415. MILLB.L.H. Tennessee Valley Authority. 81/02/10. ip. 07810: 123
- 8103190180 Forwards IE Insp Repts 50-318/81-01, 50-519/81-01, 50-520/81-01 & 50-521/81-01 on BIO104-09. No noncompliance noted. MKRPHY.C. Engine 2, Atlenta, Reactor Construction & Engineering Support Branch. 81/02/10 2pp. 07945.023.

- --8103190194 IE Insp Repts 50-518/81-01.50-519/81-01.50-520/81-01 on 810106-09 No noncompliante noted Major areas inspected previous insp findings safety-related pipe & structural steel welding CROMLEY. B R Region 2. Atlanta. Office of the Director HERDI. A Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 81/02/09 Upp 07965 025
- 8103240192 Forwards IE Inep Repts 50-518/81-02.50-519/81-02. 50-520/81-02 & 50-921/81-02 on 810109-30 No noncompliance nated tWRPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/12 2pp 07980 239
- --8103240162 IE Insp Repts 30-518/81-02.50-519/81-02.50-520/81-02 on 810103-30 No nuncompliance noted Major areas inspected open Items.A-1 drywoll penetration frames & A-1 were well
  SMAN.W B Region 2. Atlanta. Office of the Director.
  CANTRELLE F B Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/11 Sap 07980:232.
- 8103130230 Forwards Suppl 5 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Schan at BMR" No written response regulared of REILEY. J. P. Region 2. Atlanta. Office of the Director 81703717 pp. 07908-357
- B103160516 Forwards IE Circular B1-03. "Inoperable Selamic Monitoring Instrumentation " No response required KEPPLER, J.O. Region 3. Chicago, Office of the Director (11/01/02) to
- BiO3170011 Forwards revised IE Bulletin 81-01, "Surveillance of Muchanical Shubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 121/C1/04
- 8103160193 Ack receipt of 810206 ltr informing ERC of steps taken to correct violations noted in IE Imap Repts 30-518/80-24 5 50-520/80-24 Final response to be submitted by 810331 LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 81/03/06. 1p 07921 230
- --BIO3160205 Responds to NRC BIO114 ltr re violations noted in 11 fines Repts 50-518/80-24 & 50-920/80-24 Corrective actions: all currently open natification of change repts will be reviewed for inclusion of cause & action to prevent recurrence MELIS-L M Tennessee Valley Authority B1/02/06 3pp 03921-231
- ---BIO3160215 Forwards IE Insp Repts 90-518/B0-24 & 50-520/b0-24 on BO1112-13 & notice of violation.App A MURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Brench B1/01/14 2pp. 07921, 234
- --BIO3160225 Notice of violation from insp on BO1112-13 Region 2, Atlanta, Office of the Director. Bi/O1/14 ip 07921:236.
- --8103160235 IE Insp Repts 50-518/80-24 & 90-520/80-24 on 801112-13 Noncompliance noted feilure to document cause & take corrective action on Notification of Change Rept HNPA-114. HARRIS, J. R. Region 2. Atlanta, Office of the Director. CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineeric Support Branch. 81/01/13 3pp 07921 237.
- 8103200197 Forwards IE Info Notice 81-04. "Failure of ITE Model & 603 Circuit Breater." No response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/03/11 ip.
- 8103200003 Forwards 1E Info Notice 81-05, "Degraded DC Sys at Palisades." No response required G/REILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/83 1p.
- S. Reportable occurrences. LERs & related correspondence
- 8103100281 Part 21 rept re reactor protection sys panel design deficiencies initially reported on 800807. Util is awaiting info from OE re final corrective actions. MILLGLL M. Tennessee Valley Authority. 81/02/12 2pg 07865-234
- 8103040559 First interim deficiency rept.originally reported on 01C12.

- BiC3240430 Final Deficiency Rept 2 re failure to provide recipients w/up-to-date revisions of 12 CF Braun specs & associated engineering change notices initially reported on BiO127 & C203 Superseded documents replaced w/current revisions MCLCS-L M Fennessee Valley Authority 61/03/16 4pp 07984 306
- B:03300333 Supplemental Interim Deficiency Rept 2 re-potential escessive pressure drop in essential svc water sys raw water piping, initially reported on B01210 Study being conducted to resolve deficiencies noted in Dive 1 & 2 MILLS.L M. Tennessee Valley Authority 61/03/20 2pp 08055 292
- DOCKET STN-50-52) HARTSVILLE NUCLEAR PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- 8103190732 Ltts to all licensees of operating plants applicants for U.S. & holders of CPs re control of heavy loads Requests review per guidelines in NuRFO-0612 Forwards NRC position re interim actions & request for addl info EIBECHUIT. D.O. Division of Licensing 80/12/22 30ap
- 8103190387 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re program for environ qualification of safety-related electrical equipment items addressed irvolve cold shutdown.replacement parts & NoREO-0737 EISENMUT.D Q Division of Licensing 81/01/19 App
- 8103120014 Ltr to all licensees of operating plants.CP holders & G., applicants, eccept Indian Point 2 % 3.7ion i & 2 % FMI-1, forwarding inadvertently omitted pages from NRC 801222 sequest for add info re control of heavy loads.

  EISENHUT.D G Division of Licensing 81/02/03 6pp
- 8:03160069 Ltr to all operating plants 5 CP holders forwarding clarification of TML Action Plan Item III. A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be met ELECENMUT O 0. Division of Licensing 81/02/18 12pp
- BJ0325024 Ltr to all power reactor licensees & license applicants re thyge0-0619 criteria Footnote 2 in Table 2 contains error due to leekage testing delotions Licensee may submit analysis to justify use of existing low flow controller EISEN-MUT. D. Q. Division of Licensing B1/02/20 Upp
- E193170225 Ltr to all BWR licenses (except Humboldt Bay & LoCrosse) requesting review of ASME Code Class 1 & 2 pressure boundary piping, safe ends & fitting metl per guidelines of encl Revision & to NUREG-0313 Model Tech Specs only encl EISE/BHJT, D. Q Bivision of Licensing B1/02/26 3pp
- --8193170266 Model Tech Specs Pages 3/4 0-2.3/4 0-3.3/4 4-7 % 3/4 4-8 resurveillance requirements for A9ME Code Class 1.2 % 3 corponents & RCS operational lesiage limiting conditions for operation & surveillance requirements.

   General Electric Co B1/02/26. 4pp
- 8303170655 Ltr to holders of CPs & applicants for DLs (BWRs) requesting review of ASME Class 1,2 & 3 pressure boundary piping, safe and & fitting matt per guidelines of encl Revision 1 to MAREO-0313. Model Tech Epecs only encl EISERMUT. D. O Division of Licensing 81/02/26 3pp
- B103230B13 Generic Ltr B1-06 to all CP holders & UL applicants re ICCPR30 71(a), 'Periodic Updeting of FBARs,' effective BC0722\_lnfo re FBAR legal status, format & content encl FISERHUT, D. 0 Bivision of Licensing, B1/02/26 10pp
- 8103316804 Ltr to all licensees of operating plants applicants for OLs belders of CPs forwarding SECY-Bi-119 ra info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT. D. O Division of Licensing. 81/03/10 App.
- 8:03200577 Forwards plan for implementing mussel constoring program requirements in CP Excavation for discharge diffusur tentatively scheduled for Oct 1981 Frediffuser constantively scheduled for Oct 1981 Frediffuser constantively scheduled for Oct 1981 Frediffuser constanting will be initiated in near future MILLS/L IS Tennessee Valley Authority. 81/03/13 7pp
- F Security, medical, emergency & fire protection plans
- 8103310339 Ltr to all licenses of operating plants & holders of CPs forwarding AUREO-0676. "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for neeting NRC requirements W/o encl EIEENHUT. D. Q Division of Licensing 81/03/05 6pp.

- G. Inspection reports, IE Bulletins & correspondence
- B102280484 Forwards IE Info Notice 81-01. "Possible Failures of OE TW HFA Relays 'No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 81/01/16
- 8103020277 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty." No written response required O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 81/02/09 to
- 8103040753 Provides add1 response to 1E Bulletin 80-20 re Westinghous Tupe W-2 suitches Info from 0E re 6TRIDE portion of facilities has not been received, [nfo anticipated by 810615. MILLS-L M Tennesse Valley Authority 81/02/10 1p
- 8103190180 Forwards IE Insp Repts 50-518/81-01,50-519/81-01, 50-520/81-01 & 50-521/81-01 on 810106-09 No noncompliance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/10 2pp
- --8103170194 IE Insp Repts 90-518/81-01.50-519/81-01.50-520/81-01 & 50-521/81-01 on 810106-09 No noncompliance noted Major areas inspected previous insp findings, safety-related pipe & structural steel welding CROM.EV. 8. R Region 2. Atlanta. Office of the Director 81/02/0.800.
- B103240152 Forwards IE insp Repts 50-518/81-02.50-519/81-02. 50-520/81-02 & 50-521/81-02 on 810108-30 No noncompliance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch B1/02/12 2pp
- --8103240162 tE insp Repts 90-518/81-02.50-519/81-02.50-520/81-02 & 50-521/81-02 on B10105-30 No noncompliance noted Hajor areas inspected open stems, A-1 drywell penetration frames & A-1 weir wall SWAN, W B. Region 2. Atlanta. Office of the Director 81/02/11 5pp
- Bi03130230 Forwards Suppl 5 to 16 Bulletin 80-17, "Failure of Control Rods to Insert During Scram at SWR" No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director B1/02/17, In
- G103160516 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation" No response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 81/03/02.
- BiO317001: Forwards revised IE Bulletin Bi-Oi. "Surveillance of Mechanical Soubbers." W/corrected Pages 5 & 6 Changa in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY, J. P. Region 2. Atlanta, Défice of the Director Bi/O3/04.

  Ip
- 8103200197 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breater." No response required. O'REILLY, J. P. Region 2- Atlanta, Office of the Director. 81/03/11.
- 8103200003 Forwards 1E info Notice 81-05, 'Degraded DC Sys at Palisades." No response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 81/03/13.
- 8 Reportable occurrences, LERs & related correspondence
- 8103100281 Part 21 rept re reactor protection sys panel design deficiencies initially reported on 600807 Util is awaiting info from QE re final corrective actions MiLLS-L H Tennessee Valley Authority 81/02/12. 2pp.
- Bio3240430 Final Deficiency Rept 2 re failure to provide recipients w/up-to-date revisions of 12 CF Braun specs & associated engineering change notices initially reported on Bio127 & 0203 Superseded documents replaced w/current revisions.

  MILLBL M Tennassee Valley Authority. Bi/03/16. 4pp
- 8103300333 Supplemental Interim Deficiency Rept 2 re-potential excessive pressure drop in essential svc water sys raw water piping instially reported on 801210 Study being conducted to resolve deficiencies noted in Divs 1 %2 MILLS.L.M Tennessee Valley Authority 81/03/20. 2pp

- DOCKET STN-90-522 SXAGIT NUCLEAR POWER PROJECT. UNIT 1

  A Application/construction stage documents & correspondence
- BIOQ1903B7 Ltr to all licensess of operating plants & applicants for OLs & holders of CPs reprogram for environ qualification of safety-related electrical equipment liens addressed involve cold shutdown.replacement parts & NUREC-0737 EISENHUT.D Q. Division of Licensing BIO/1/19 &pp
- B103180039 Unofficial transcript of Commission B10212 meeting in Washington-DC re SECY-B1-20 policy on proceeding w/pending CP i mfg license applications. Pp 1-115

  Commissioners 81/02/12 117pp
- --Bi00030450 Recomends Commission approve encl draft final rule LOCFR30 re licensing requirements for pending CPs & orgalicense applications & proposed statement of requirement re degraded core ruleraking
  DIRCKS.H.J. Office of the Esecutive Director for Operations.
  SECY-081-020A B1/02/11 12pp
- BiO3250024 Ltr to all power reactor licensees & license applicants re NUREQ-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee ray submit analysis to justify use of existing low flow controller EIREPHUT.O Q. Division of Licensing. 81/02/20. Opp
- DOCKET STN-90-523 SKA017 NUCLEAR POWER PROJECT. UNIT 2

  A Application/construction stage documents & correspondence
- B103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re-program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement parts & NUREG-0737 EISENRUT.D 0 Division of Licensing. B1/01/19 6pp
- BIO3180039 Unofficial transcript of Commission BIO212 mapting in Washington.DC re SECY-BI-20 policy on proceeding w/pending CP & mfg license applications Pp 1-115

  \* Cormissioners BI/O2/12 117pp
- --Bi03030450 Recommends Commission approve encl draft final rule 10CFR50 re licensing requirements for panding CPs & mfg license applications & proposed statement of requirement re degraded core rulerating.

  DIRCKB.M.J. Diffice of the Executive Director for Operations BECY-BI-020A 31/02/11 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

  EISENHUT.D 9 Division of Licensing 81/02/20 App
- DOCKET 8TN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- B103190732 Lins to all licensees of operating plants, applicants for OLs & holders of CPs re control of heavy loads. Requests review per guidelines in NUREO-O612 Forwards NRC position re interim actions & request for addl
- B103190387 Ltr to all licensees of operating plants & applicants for DLs & Adidors of CPs re-program for environ qualification of safety-related electrical equipment. Liters addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT.B.O. Division of Licensing. B1/05/19. App.
- 8103120014 Ltr to all licensees of operating plants, CP holders & DL applicants, except indian Point 2 & 3. Zion ( & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENHUT.D. Q. Division of Licensing 81/02/03. App

1

BIO3250024 Ltr to all power reactor licensees & license applicants re NUREO-O&19 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller.

EIBENHUT.D.O Division of Licensing. B1/02/20. Spp.

- d103230030 Ltr to all licensees of operating nuclear applicants for GLs (except St Lucie Units 1 & 2) R util review to determine capability to nitigate st blackout event & promptly implement emergency proc
- 8103230813 Generic Ltr Bi-Oó to all CP holders & C\_ 10CFRSO, 71fe). "Periodic Updating of FSARs." effec 800722 Info re ISAR legal status format & content EISENHUT.D O Division of Licensing 81/02/26
- 8103120763 Notification of 810305 meeting w/util & C to discuss agendas & schedules for independent dea board meetings KERRIGAN, J.D. Licensing Branch 3 ORIMES, C. 1 S Special Projects Branch B1/03/02 3pp 07905 3
- 8103(00460 Forwards coming Taps for ref to Question 810303 ltr Certificate of Svc encl M/o encl coming VAN BRUNT.E E. Aricona Public Service Co. 81/03/ 07867 226
- B103120165 Urges util to supply App I info as soom a support request to transfer 5 7% ownership interesplant SALTZMAN, J Utility Finance Stanch (formerly Anti-B1/03/04 1p 0790) 357
- 8103170507 Forwards Bechtel Power Corp & util final items no auxiliary feeduator sys review for facili Reponses were reviewed by Auxiliary Feedwater Sys Board & found to sufficiently address outstanding VAN BRUNT.E E Arisona Public Service Co 81/03/07930 058
- B103170604 Requests reg guide Implementation schedul stage Possibility exists during review that util a requested to upgrade plant to reg guide or revisia different than that listed in FSAR Dection 1 8 VAN BRUNT. E. E. Argiona Public Service Co. 81/03/07229 348.
- 8103170642 Forwards supplemental info to 810303 resprequest re-mitigation measures to preserve riparia in Salt & Dila Rivers
  VAN BRUNT, E. E. Aritona Public Service Co. 81/03/07925 155
- 8103261208 Forwards final schedule for independent d ceetings for facilities Wo encl. EISENMUT.D 9 Division of Licensing 81/03/09
- B103310804 Ltr to all licensees of operating plants. & holders of CPs forwarding SECY-B1-119 re info neestablish environ qualification of safety-related equipment. EISENHUT.D C Division of Licensing 81/03/10
- B103170459 Requests that instrumentation & control in raview be rescheduled at first available opportuni will have significant impact on BAR.FSAR & CE89AR-I SCHERER.A. E. C-E Power Systems 81/03/11 ip 4
- 8103190115 Forwards final response to NRC 810213 req tonsequences of Jelay of power Delay will result i lead times, decreased sign reliability & additionable incorporated into environ review VAN BRUNT.E E. Arijone Public Service Co. 81/03/07960:243.
- B103260069 Recommends Caseload Forecast Panel visit scheduled for early Apr 1981 as requested by util cable pull rate has been high since 801028 visit U disagrees w/NRC projected fuel load date KERRIQAN, U. Licensing Branch 3 B1/03/17 ip
- 8103310438 Forwards final schedule for Independent d meetings.per 810122 meeting TEDESCO.R L. Assistant Director for Licensing & 08059-292
- C. Utility Environmental Report (ER), amends & correct
- 8103060302 Forwards responses to NRC 810213 request a rept for facilities. Items addressed include sys der

#### OCKELED HEIVIS

07782:136

07974 353

02028 024

- F Security, reducal, emergency & fire protection plane
- 6:03100471 Requests guidance re acceptability of emergency operations facility design Facility located close to site w/ ratitability requirements upgraded to requirements for test shipping cash Backup facility question raised VAN ERUNT. E E Arizona Public Bervice Co B B1703703 07833 070
- 8103310338 Ltr to all licensees of operating plants & holders of CPs Acquarding NJREG-0698. "Functional Criteria for Emergency Response Facilities" Criteria describe acceptable method for eacting NRC requirements W/o encl
- EISEAHUT.D Q Division of Licensing B1/03/05 6pp B:03180002 Surmary of 810225 meeting o/Rechtel & util in Phoenia.
- Afte initial design review of fire protection sys KERRIGAN J Licensing Branch 3 81/03/06 3pp 07943 300
- 8103330309 Requests NRC quidance re acceptability of emergency contactions facility design Facility will be basement level of administration anner tidy Jeneral Design Criterion 19 uill not be exceeded during accident
  valuarum. E.E. Arizona Public Service Co. 81/03/19 2pp
- 8103310661 Confirms implementation dates for Ols re upgraded emergency facilities in response to NRC ltr to all Ol licensees & CP holders dtd 810218 VAN BRUNTLE E Artiona Public Service Co. 81/03/25 ip 08075 200
- G Adjudicatory correspondence
- 8:03269539 Requests that ASLB proceed in absence of intervenor Hourshan response to disputed contentions
  BISCHOFF, C.A. Smell & Wilmer 81793711 3pp 08041-031
- 3103240039 Discusses joint applicants' itr ve proceeding progress Agrees that intervenor has not filed & does not intend to file response to position statements ASLB should issue order tentifying intervenors contentions to be litigated. P(9998EN H J Hearing Branch 1 B1/03/20 2cg 07990 323
- ⊢ Gen∌ral correspondence
- 0103160340 Provides FERK w/info re participation of El Paso Electric Co ir Palo Verde Project. in response to G10129 request W/u joint application for OL participation agreement & FES esterst DENTON JUR Office of Nuclear Reactor Regulation, Director. 81/03/02 4pg
- --8193160269 Request submitted by FERN. for info re El Paso Electric Co participation in Palo Verde project U/related info JONES. 8 Affiliation Unknown 81/01/29 4nn
- 3103170478 Informs that M Walker has replaced GL Doline as Assistant Director of Energy Programs VAN BRUNT, E. E. Arizona Public Service Co. 81/03/09 2pm 17925 [9]
- 9 Inspection reports. IE Bulletins & correspondence
- 9103040322 Forwards 1E Insp Repts 50-520/80-20.50-529/80-20 & 50-530/80-20 on 801202-05 No noncompliance noted SFEMICR.9 S Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 81/01/15 2pp. 07820.115
- --810304033) IE Insp Repts 50-528/80-20.50-529/80-20 & 50-530/80-20 on 801202-05 he noncompliance noted. Major areas inspected. const activities re licensee action on previous insp findings & concrete placements ECKHAROT, J. H. HERNANDEZ.G. Region S. San Francisco. Office of the Director DODDS.R T. Region S. San Francisco. Reactor Construction & Engineering Support Branch. B1/01/19. 4pp
- B103100395 Forwards IE Insp Repts 50-528/80-21, 50-529/80-21 & 50-530/80-21 on 801208-10 No noncompliance noted 300%-H E Region 5: San Francisco, Fuel Facility & Materials Bafety 3ranch. 81/01/19 2pp 07854-163

- B103050369 Forwards IE Insc Repts 50-528/80-19, 50-529/80-19 & 50-530/80-19 on B01103-21 No noncompliance nated SPENCER. G 5 Region 5. San Francisco, Reactor Construction & Engineering Support Branch 81/01/23 20p 07824:245
- --BI03050379 IE insp Repts 50-528/80-19,50-529/80-19 & 50-530/80-19 BOILO3-21 No monecompliance moted noted Major areas RCPB installation VORDERRANGEGOEN Region 5. San Francisco. Office of the Director CODDER T T Region 5. San Francisco. Reactor Construction & Engineering Support Dranch 81/01/22 App 07824.247
- 8103020599 Supple B01230 response to IE Builetin 80-21. "Valve Yoke Supplied by Malcolm Foundry Co. Int." Vendors have confirmed that no valves have teen identified as using potentially faul tu cat I VAN BRUNT. E E Artiona Public Service Co. 81/02/04 to
- G103020056 Forwards (E Circular Bi-02, "Performance of NRC-Licensed Individuals Unite on Duty 'No written response required ENDELAGNAR H Region 9. San Francisco. Office of the Director 81/02/09 1p 07707 262
- 8103230870 Responds to IE Bulletin 80-16. 'Potential Misapplication Rosemont Inc Models 1131 & 1132 Pressure Franchitters W/ Either A or D Output Codes "Transhitters supplied by Atomics Intl. Anchor/Darling & Cooper VAN BRUNT, E. E. Arizona Public Service Co. 81/02/09 200
- 610319068) Responds to IE Bulletin 80-23, "Failure of Solenoid Valve Mfg by Valcor Engineering Corp " No such valves used in safety-related sys. VAN DRUNT, E.E. Artiona Public Service Co. 81/02/11 15. 07964 057 8103090750 Ack receipt of 901217 ltr informing NRC of steps taken to
- toposity of the receipt of Gold// It informing Net of steps tak correct violation notes in IE hap Repts 53-523/80-17. 50-529/83-17 t 90-530/60-17 SPENCER O B Region 5: San Francisco. Reactor Construction & Engineering Support Branch 81/02/13 ip 07828 073 --Bi03050759 Responds to MRC B01121 ltr re violation noted in IE Ins Rept 50-528/60-17 Corrective actions cleaned & covered Unit I motor operators of ivolation valves in rain steam &
- n-8103050766 Forwards 1E Insp Repts 59-528/80-17.50-529/80-17 & 90-533/80-17 on 800908-30 & notice of violetion GPENCER, 9 & Region D. San Francisco. Reactor Construction & Engineering Support Oranch 80/11/23 2pp 07828 078

feedwater sys Component incorporated into maint program
VAN BRUNT.E C Actions Public Service Co 80/12/17

- --Bi03050772 Nutice of violation from insp on 800908-30.

  \* Region 5. San Francisco. Office of the Director BO/11/21.
  07828 080
- --Bi030507Bt IE Insu Repts 50-526/80-17,50-529/80-17 & 50-530/80-17 800908-30 Noncompliance noted failure to make periodic insps
- BUOVER-30 Noncompliante noted rations to raise periodic inspit

  \*\*maint prescribed by manufacturer for noted operators of
  isolation valves in main steam & feedwater sys

  VDRDERBRUEGSEN Region 5. San Francisco. Office of the Director.

  HAYIES.R.C. Region 5. San Francisco. Reactor Construction &

  Engineering Support Branch 80/11/21 6pp. 07828:081
- B103;10B:4 Ack receipt of B10204 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-328/80-16. 50-529/80-16 & 50-520/80-16. FAULKENBERRY, B Region 3, Ban Francisco, Reactor Construction & Engineering Support Branch. 81/02/27 lp. 07877 249
- --8103110823 Responds to NRC 801224 ltr re-violations noted in IE In Repts 50-528/80-16.50-529/80-16 & 50-530/80-16 Corrective actions: concrete placements repaired per Spec 13-CM-365 by VAN BRUNT, E E Arizona Public Barvice Co Bi/02/04 3pp 07877.250
- --BIO3110931 Forwards IE Insp Repts 50-528/80-16.50-529/80-16 & 50-530/80-16 on BO1007-10 t notice of violation SPENCER, 9 B Region 5, San Francisco. Reactor Construction & Engineering Support Brench. 80/12/24 2pp 07877 253
- --8103110837 Notice of violation from insp on 801007-10. SPENCER, Q. 8 Region 3. San Francisco, Reactor Construction & Engineering Support Branch 80/12/23 2pp 07877:295
- --8103100403 IE Insp Repts 50-528/80-21,50-529/80-21 & 50-530/80-21 on B01208-10 No noncompliance noted Major areas inspected inclementation of environ protection GP requirements & audit of environ program LIEUGI AUGUL C A

- --8103110847 IE Insp Repts 50-528/80-16.50-529/80-16.50-530/80-16 on B01007-10 Noncompliance noted debris found entrapped in concrete placements 30.033.30.033.3003.3004.8 3.404.4 8 34.19, resulting in three pociets of unbonded concrete ECXHANDT.U H. HERNANDEZ.G. Region 5. San Francisco. Office of the Darector DDDDS.R T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/12/23 5pp 07877.257
- BIOGI70029 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation " No response required. ENGELKEN R H Region B. San Francisco. Office of the Director. 81/03/02. 1p. 07939 155
- BiOSi60848 Forwards revised IE Julietin 81-01. "Burvesilance of Mechanical Snubbers." u/corrected Pages 5 & 6 Change in identification of facilities u/CPs to which bulletin is applicable does not affect util requirements ENGELKEN.R H Region 9. San Francisco. Office of the Director. 81/03/04. 1p 07914 207
- 8103200299 Forwards IE Info Notice 81-06. "Failure of ITE Model K-600 Circuit Breaker" No response required ENGELMEN.R H Region 5. San Francisco. Office of the Director 81/03/11. Ip 07968 352
- 8103200042 Forwards IE Info Notice 81-05, "Degraded DC Sys at Palisades." No response required.
  ENGELKEN.R H Region 5. San Francisco. Office of the Director 81/03/13 ip 07970-015
- R Periodic operating reports & related correspondence
- 8103090519 Forwards magnetic tape of hourly meteorological data for 730813-780813.

  VAN BRUNTLE E Artiona Public Service Co 81/03/09 3pp. 67844-131
- --9103090521 Magnetic tape of hourly reteorological data for 730813-780813 4 NVS Corp. 81/03/09. 1p. 07846:133
- 8 Reportable occurrences, LERs & related correspondence
- BIO3110737 Ack receipt of B00915 itr forwarding final deficiency rept re operability failure of vertical fire dampers. ENGELKER R H. Region 5. San Francisco. Office of the Director. 80/10/02 ip. 07885 013
- 8103090049 Ack receipt of 800924 Interim deficiency rept re loose bushings on Corner & Lada sway strute, Sizes 1,2 & 3. EMGELKEN R. H. Region 9, San Francisco, Office of the Director. 80/10/06 tp 0/832.177
- 8103120469 Final deficiency rept reliack of addl rebar reinforcement in containment placement, making wall susceptible to overstressing under selsents conditions. Caused by oversight. Rebar added VAN BRUNT-E.E. Arizona Public Bervice Co. 81/02/04 4pp. 07901:274.
- 8103040566 Becond interim deficiency rept re loose bushings on IYT Orinnell sway struts-initially reported 801120 Visual inspublic be performed by Bechtel Inspublic be completed by B10615. Final rept scheduled for 810715 submittal VAN BRUNT. E.E. Arizone Public Service Co. 81/02/26 4pp. 07818: 132
- 8103100591 Final deficiency rept relicose bushings on Corner & Lada sway struts initially reported 800828 Bechtel has verified that Corner & Lada insured stabling of rigid sway strut paddle ends.elininating possibility of disengagement VAN BRUNT, E.E. Arizona Public Bervice Co. 81/03/02 4pp 07863:097.
- BIOG170554 Interim deficiency rept re weld deficiencies on main control panels, initially reported 800916 Final rept references to 8107151 due to delays in receiving input data & performing analysis No new info available VAN BRUNT, E.E. Arizona Public Service Co. 81/03/10 2pp 07925:178
- 8103240364 Final deficiency rept re cable tray supports not meeting drawing requirement. Caused by drawing misinterpretation. Btructural notes & instructions re cable tray installation revised for clarity.

  VAN BRUNT, E. E. Arizona Public Service Co. B1/03/16 4pp. 07990:265.

- T Hearing transcripts on non-antitrust matters
- BiO3130283 Forwards transcript 'Independent Design Revie, of Paic V Nuclear Generating Station Fire Protection Gys Before Fire Protection Gys Board." Vol 1 of 2 Transcript available in Central Files only VAN ERUNT, E.E. Arizona Public Service Co. 81/03/04 2pp
- DUCKET STN-90-929 PALO VERDE NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- B103390732 Ltrs to all licensees of operating plants, applicants for DLs & holders of CPs re-control of heavy loads. Requests review per guidelines in NUREW-0612 Forwards NRC position re-interim actions & request for addl info EISENHUT.D 0 Division of Licensing 80/12/22 30pp
- Bio3190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs to program for environ qualification of safety-related electrical equipment Items addressed involve cold shuddown-replacement parts & NAREG-0737 EISENHUT.D 0 Division of Licensing BI/O1/19 App
- 8103120014 Ltr to all licensees of operating plants CP holders & Operating plants except Indian Point 2 & 3.7ion 1 & 2 % TMI-1. forwarding inadvertently onitted pages from MRC 801222 request for add1 info re control of heavy loads EIBEMHUT. B O Division of Licensing 81/02/03 6pp
- 8103250024 Ltr to all power reactor licensees & license applicants MMRCO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subcit analysis to justify use of existing low flow controller EISE/NHOT.D @ Division of Licenseing 01/02/20 800
- B103230030 Ltr to all licensees of operating nuclear power plants & applicants for DLs (ercept St Lucie Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT. D O Division of Licensing B1/02/29 5pp
- B103230B13 Generic Ltr B1-06 to all CP holders & OL applicants re 1CCFR50 71(e). "Periodic Updating of FSARs." effective B03722 Info re FSAR legal status.fornat & content encl EISENHULD 9 Division of Licensing B1/02/26 10pp
- B103120763 Notification of 810305 meeting u/util & C-E in Bethesde. to discuss agendas & schedules for Independent design review board meetings.

  KERRIGANUU D. Licensing Branch 3 ORIMES C. I. Standardization Special Projects Branch 81/03/02 3pp 07705 303
- Bi03100460 Forwards joining maps for ref to Question 310 4 roted in Bi0303 ltr Certificate of Bvc encl W/o wncl joining maps. VAN SRUNT, E.E. Arijona Public Service Co. 81/03/03. App. 07867, 226.
- 8103120165 Urges util to supply App 1 info as soon as possible to support request to transfer 5 7% ownership interest in plant.

  SALTZMAN.J. Utility Finance Branch (formerly Antitrust & Index
  - SALTZMAN.J. Utility Finance Branch (formerly Antitrust & Indexnl 01/03/04 lp 07701.357.
- 8103170507 Forwards Becktel Power Corp & util final responses to up items re auxiliary feedwater sys review for facility Responses were reviewe by Auxiliary Feedwater Sys Review Board & found to sufficiently address outstanding concerns VAN BRUNT-E. Arisona Public Service Co. 81/03/06 33pp 07930-059
- B103170604 Requests reg guide implementation schedule for plants in stage Possibility exists during review that util will be requested to upgrade plant to reg guide or revision different than that listed in FBAR Section 1 B VAN BRUNT. E.E. Arizona Public Service Co. B1/03/09 1p
- 8103170642 Forwards supplemental info to 810303 response to NRC B10 request re mitigation measures to preserve riparian habitats in 8alt & Gila Rivers.

  VAN BRUNTLE E Arizona Public Bervice Co. 81/03/09 2pp 07925:159.
- 8:03251208 Forwards final schedule for independent design review meetings for facilities. W/o entl.
  EISENHUT. D. G. Division of Licensing 81/03/09. 1p 08040 245

- b holders of CPs forwarding SECY-81-119 re info necessary to establish environ qualification of safety-related electrical equipment of safety-related electrical equipment. O Division of Licensing 81/03/10 Ann
- BiO317045B Requests that instrumentation & control independent design rayles be rescheduled at first available apportunity Delays will have significant impact on BAR.FSAR & CESEAR-F review SCHERER.A F. C-E Power Systems 81703711 ip 07928 245
- Big3190115 Forwards final response to NRC Big213 request for info re consequences of Jelay of power Delay unil result in longer lead times decreased sys reliability & addl costs info ull be incorporated into environ review VAN BRUNT.E E Ariiona Public Service Co Bi/03/15 B2pp 07960 243
- BIO3260069 Recommends Caseload Forecast Panel visit to facilities be scheduled for early Apr 1981 as requested by util Average catle pull rate has been high since BOI028 visit Util disagrees w/HRC projected fuel load date KERRIGAN.U Licensing Branch 3 81/03/17 1p 08040 118
- 8103310438 Forwards final schedule for independent design review settings per B10122 meeting TEDESCOR L. Assistant Director for Licensing 81/03/23 4pp 98099 292
- C Utility Environmental Report (ER). amends & correspondence
- 8:03Cb0302 Forwards responses to NRC 010213 request for info to environ rept for facilities [tems addressed include sys demand & reliability.need for power, consequences of delay & geography & demagraphy VAN BRONT, E.E. Artiona Public Gervice Co. GI/03/03. 130pp. 07840-220
- E N92 Bafety Evaluation Report (SER), supple & correspondence
- E103120629 Notifies that reasonable date for receipt of ac power sys SER input is 810331 IDR transcript & initial & final responses to open items previously submitted by util to support SER MIRAOLIA-F J Operating Reactors Branch 3 #11/03/06 1p. 07506:127
- F Security, medical, emergency & fire protection plans
- 8103100471 Requests guidance re acceptability of emergency operations facility Jessign Facility located cluse to site u/salitability requirements upgraded to requirements for test stipping cask. Backup facility question raised wall BRUNT. E.E. Artiona Public Bervice Co. 81/03/03 lp. 07653:070
- E103310338 ttr to all licensees of operating plants & holders of CPe forwarding NUREO-0596. 'Functional Criteria für Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements 11/0 encl E19EriMUT.D O Division of Licensing 81/03/05 App
- 8103160502 Burmery of 810225 resting w/Bechtel & util in Phoeniz-AZ re initial design review of fire protection sys REARIGAN J Licensing Branch 3 81/03/06. 3pp 07943 309
- 8:03309399 Requests NRC quidance is acceptability of emergency operations facility design. Facility util be basement level of administration anner bldg Onneral Design Criterion 19 util not be exceeded during accident.

  VAN BRUNT-E E Aritona Public Bervice Co 81/03/19. 2pp 08059 361
- 8103340661 Confirms implementation dates for DLs ro upgraded energency facilities in response to NRC litr to all DL licensees & EP holders did 810218.

  VAN BRUNT, E. E. Artiona Public Service Co. 81/03/25. ip 68075 200
- 9. Adjudicatory correspondence
- B103260509 Requests that ABLB proceed in absence of intervenor Hourihan response to disputed contentions.
  B18CHCFF, C. A. Bnell & Wilmer. B1/03/11 3pp 08041-031

## 14 General correspondence

MCCLIBREN H

B103160240 Provides FERN w/info re participation of El Paso Electri in Palo Verde Project.in response to B10129 request W/o joint application for CL. participation agreement & FEB excerpt DENTON.H R Office of Nuclear Reactor Regulation, Director

Hearing Branch | 81/03/20 200

ักรออก รวร

Agrees that intervends has not filed & foes not intend to file response to position statements ASLD should issue order identified intervenous contentions to be litinated

- --Bi03160260 Request submitted by FERN, for info re El Paso Electric participation in Palo Verde project W/related info UNES.3 Affiliation Unknown B1/01/29 4pp
- 8103170478 Informs that M Walker has replaced SL Dolins as Assistant Director of Energy Programs VAN BRUNT.E E Arizona Public Bervice Co 81/03/09 2pp 07935 191
- O inspection reports. IE Bulletins  $\boldsymbol{b}$  correspondence
- 8103040322 Forwards TE linsp Repts 50-528/80-20.50-529/80-20 & 50-530/80-20 on 801202-09 No noncompliance noted SPENCER.O. S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch 81/01/15 2pp 07820 [15
- --BIO3040331 IE Insp Repts 50-528/80-20.50-529/80-20.50-530/80-20
  BO1202-05. No noncompliance noted Major areas inspected canet activities re licensee action on previous insp findings & concrete placements
  ECKMARGI.J H. MERNANDEZ.O Region 5. San Francisco. Depice of Director DODDS.R T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 81/01/15. 4pp. 07820-117.
- B103100395 Forwards IE Insp Repts 50-528/80-21.50-529/80-21 & 50-530/80-21 on B01208-10 No noncompliance noted (IDDR, H E Region 5. San Francisco, Evel Facility & Materials Bard Branch B1/01/19 2pp 07064 163.
- --BIO3100403 1E lnsp Repts 90-528/80-21,50-529/80-21 & 50-530/80-21 BO1200-10 No noncompliance noted Major areas inspected implementation of environ protection CF requirements & audit of environ program NORTH-H B , GARCIA.E M MENSLAWSKI.F A Region 3, San Francisc Office of the Director GI/O1/1a. Bpp 07864-165.
- B103050359 Forwards IE Insp Repts 50-528/80-19.50-529/80-19 & 90-530/80-19 on 801103-21 No noncompliance noted. SPENCER.O G Region 9. San Francisco. Reactor Construction & Engineering Support Branch. B1/01/23 2pp 07824 245.
- --BI03050379 IE Insp Repts 50-528/80-19,50-529/80-19 & 50-530/80-19
  B01103-21 No noncompliance noted noted Major areas
  inspected protection of installed reactor vessel internals &
  RCPB installation
  VORDERBRUEGOEN Region 5. San Francisco. Office of the Director.
  D0D05.R. T. Region 5. San Francisco. Reactor Construction &
  Engineering Support Dranch. B1/01/22 App. 07824:247
- 8103020699 Supple 801230 response to LE Bulletin 80-21, "Valve Yake Supplied by Malcoln Foundry Co. Inc." Vendors have confirmed that no valves have been identified as using potentially faulty met!

  VAN BRUNT, E.E. Artiona Public Service Co. 81/02/04 1p. 07782-136.
- 8103020056 Forwards 1E Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. ENGELKEN.R. H. Region 5. Sen Francisco, Office of the Director. 81702709 1p 07787 262
- 8103230B70 Responds to 1E Bulletin BO-16. "Potential Misapplication Rosemont Inc Models 1191 & 1192 Pressure Transmitters W/ Either A or D Gutput Codes." Transmitters supplied by Atomics Intl. Anchor/Darling & Cooper.

  VAN DRUNK.E E Arizona Public Service Co B1/02/09. 2pp 079731:353.
- BiO31906B1 Responds to IE Bulletin BO-23. "Failure of Salenoid Valve Mfg by Valcor Engineering Corp." No such valves used in safety-related sys VAN BRUNT, E.E. Arizona Public Service Co. 81/02/11. 1p. 07964:057.

- S0-929/80-17 % 50-930/80-17 SPENCER.O S Region 5. Sah Francisco. Reactor Construction % Engineering Support Branch. 81/02/13 1p. 07828-073
- ...-8103050766 Forwards 1E 1nsa Repts 50-928/80-17.50-529/80-17.5 50-530/80-17 on 800908-30 t notice of /tolation SPENCER.0.8 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/11/20 2pp 07628 078
- "-8103050781 IE Insp Repts 90-528/80-17.50-529/80-17 & 50-530/89-17 on 800708-30 Noncompliance noted failure to make periodic insps & maint prescribed by manufacturer for motor operators of isolation valves in main steam & feedwater sys VCRDERBRUEGGEN Region 5. Sar Francisco, Office of the Director MAYNES, RC Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/11/21 Apr 07828 081
- B103110B14 Ack receipt of B10204 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-520/80-16. 50-520/80-16 & 50-530/80-16. FAULKE/BERRY, B. Region S. Ban Francisco. Reactor Construction & Engineering Support Branch B1/02/27 Ip 07677-249
- --8103110923 Responds to ARC 801224 ltr re violations noted in IE Insp Repts 90-928/80-16-90-527/80-16-6-50-530/80-16-Corrective actions concrete placements repaired per Stat 13-CH-365 by 801117. VAN BRUNI.E E. Arizone Public Service Co. 81/02/04 3pp
- --BID3110B31 Forwards IE Insp Repts 50-528/80-16.50-529/80-16 to 50-539/80-16 on 801007-10 t notice of violation SPENCER, 0 S Region 5. San Francisco, Reactor Construction to Engineering Support Branch 80/12/24 2pp 07877
- --Bl03110B37 Notice of violation from imag on 801007-10 SPENCER-9.5 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/12/23 2pp 07877 255
- --Bi03110847 IE Insp Repts 90-928/80-16.50-529/80-16.6 50-930/80-16 on B01007-10 Noncompliance noted: Gebris found entrapped in concrete placements 3A035, 3A036, 3A038, 3A044 & 3A119. resulting in three pockets of unbonded concrete. ECKHARDT, J. H. HERNANDEZ-O. Region 5. San Francisco. Office of the Director D0093.8 T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 80/12/23 Spp. 3327.287
- 8103170029 Forwards IE Circular 81-03, "Inoperatle Saismic Monitoring Instrumentation" No response required.
  ENGELKEN,R H. Region 5. Ban Francisco, Office of the Director 81/03/02 p. 07939 155
- 810316084B Forwards revised IE Bulletin 81-0; "Burvesilance of Mechanical Shubbers;" w/corrected Pages 5 & 6 Change in identification of facilities w/cPs to which tulletin is applicable does not affect util requirements ENGELKEN.R. H. Region 5. San Francisco. Office of the Director. 81/03/04 1p 07914 207
- 8103200259 Forwards IE Info Notice B1-06. "Failure of ITE Model K-600 Circuit Breaker" No response required ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 81/03/11. 1p. 07968-352.
- 8103200042 Forwards 1E Info Notice 81-05. "Degraded DC Sys at Palisades." No response required ENSELKEN.R H. Region 5. Gan Francisco. Office of the Director. B1/03/13 ip 07970-015.
- R Periodic operating reports & related correspondence
- 8103090519 Forwards magnetic tape of hourly reteorological data for 730813-780813 VAN BRUNTLE E Arizona Public Service Co 81/03/09 3pp 07844 131.
- --Bi03090521 Magnetic tape of hourly meteorological data for 730813-760813.
  4 NUS Corp. 81/03/09. ip 07846 133.
- 8 Reportable occurrences. LERS & related correspondence
- B103110737 Ack receipt of 800915 ltr forwarding final deficiency rept re operability failure of vertical fine dampers ENGELKEN,R.H. Region 5. Ban Francisco. Diffice of the Director 80/10/02 Ip. 07885 013.

B103120469 Final deficiency rept to lack of add1 rebar reinforcement in containment placement making wall susceptible to overstressing under servent conditions Causes by oversight

VAN BRUNT, E. E. Arizona Public Service Co. 81/02/04 4re

San Francisco. Office of the Cirorici

ENCETARN R R

Pabba Tadas

07901 274

07015 136

D 44 1 01.

80/10/06 Ip 07852 177

- BIO3040990 Interim deficiency rept he indications revealed in eite radiographs of previously accepted piping spuols initially reported Bi0127 Bechtel will perform insp Corrective action completion scheduled for Bi0415 VAN BROWNE E Arizona Public Service Co. Bi/02/24 inc.
- 8103040566 Second interim deficiency rept re loose bushings on 1°T Grinnell sway struts, initially reported 801170 Visual inspection by Becktel Inspection to complete the BIC615-Final rept scheduled for 810715 submittel LAY DRUMILE E. Artiona Public Service Co. 81/02/26. App. Orans. 122
- B103100591 Final deficiency rept re loose bushings on Correr & tala sway struts, initially reported B00828 Sechtel has verified that Corner & Lada insured staking or rigid suay strut gaddle ends, eliminating possibility of disengagement VAN BRUNT. E. E. Artiona Public Service Co. B1/03/02 4pc 07863 097
- 8103170954 Interin deficiency rept re weld deficiencies on main con panels, initially reported 800916 final rept reforecast to 810715 due to delays in receiving input data & performing analysts No new info available

  VAN BRUNT, E.E. Arizona Public Bervice Co. 81/03/10 22p 07925 172
- 8103240354 Final deficiency cept re-cable tray supports not reeting frauting requirement Caused by drawing misinterpretation. Structural notes & instructions re-cable tray installation revised for clarity. VAN BRUNT, E.E. Arizona Public Service Co. 81/03/16 422 07790 265
- I Hearing transcripts on non-antitrust matters
- 8103130283 Forwards transcript 'Independent Design Revie. of Palu V Nuclear Generating Station Fire Protection Sys Before Fire Protection Sys Board.' Vol 1 of 2 Transcript available in Central Files only VAN GRUNT.E E Arizona Public Service Co 81/03/06 2pp 07914-073
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATICN, UNIT 3

  A Application/construction stage documents & correspondence
- BiO3190732 Ltrs to all licensees of operating plants, applicants for OLs & holders of CPs re-control of heavy loads Requests review per guidelines in NUREG-Obi2 Forwards NRC position re-interim actions & request for add1 info
  EISENHUT.D O Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs to program for environ qualification of safety-related electrical equipment Items addressed involve cold shutdown-replacement parts & NUREG-0737 EISENMUT.D O. Division of Licensing 81/01/19 & pp
- B103120014 Ltr to all licensees of operating clants.CP holders & [Lapplicants.except Indian Point 2 & 3, Zion 1 & 2 % TMI-1. forwarding inadvertently omitted pages from tRC B01222 request for addition for control of heavy loads EISENBUT.D.O Division of Licensing B1/02/03 &pp
- 8103290024 Ltr to all power reactor licensees & license applicants AUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analyses to justify use of existing low flow controller EISENHUT.D © Division of Licensing. 81/02/20 8pp
- 8103230030 Ltr to all licenses of operating nuclear power plants & applicants for Ols (except Bt Lucie, Units 1 & 2) Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISENHUT.D O Division of Licensing 81/02/25 Spp

- B103230813 Deneric Ltr B1-05 to all CP holders & UL applicants re 100FR30 71(e). Periodic Updating of FEARs, effective g00722 Info re FBAR legal status.format & content encl ETSC-UT.D C Division of Circusing B1/02/26 10pp
- 9133120783 Notification of BiClUS meeting L/Util % C-E in Bothosda. MD to discuss egendes 5 schodules for independent design review board rectifys wasacast. J D. Licensina Branch 3 81/03/02 3p;
- BIO3100460 Forwards soning maps for ref to Question 310 4 noted in util BIO303 ltr Certificate of Svc encl Wa enc! soning maps VAN BRUNTLE E Anisona Public Service Co 81/03/03 2sp
- 9103120165 Urges util to supply App 1 info as soon as possible to support request to transfer 5.7% ownership interest in plant EALTZMAN, J. Utility Finance Granch (formerly Antitrust & Indennity) 81703704 | Ip 07901 337

A7847 324

- 8:(3170507 Forwards Nechtel Power Corp & util final responses to open items to availiary feedwater sys review for facility Responses were reviewed by Auxiliary Feedwater Bys Review Board & found to sufficiently address outstanding concerns ANY BRUNILE & Articena Public Service Cn 81/03/06 33pp 07930 058
- 8103170604 Requests rog guide implementation schedule for plants in Oustage Possibility erists during relieve that util will be requested to ingrade plant to reg guide or revision 13fferent than that listed in FSAR Section 1 8 VAN 3RUNI, E.E. Arriona Public Service Co. 81/03/09 1p 07929-348
- 8103170642 Forwards supplemental info to 810303 response to NGC 810213 requestive intigation reasones to preserve rigarian habitate in Salt & Gille Rivers VAN BRUNT. E. E. Arsiana Public Service Co. 81/03/09 2pp c7925 155
- 8103261208 Forwards final schedule for Independent design reviewerships for facilities W/o entl EISENUIT.D O Division of Licensing 81/03/09 1p. 68040-245.
- 8103310804 Ltr to all licensees of operating plants applicants for CLs & holders of CPs forcarding BECY-RI-119 re info nocessary to establish environ qualification of safety-related electrical equipment.

  FISS::-UT.D.O. Division of Licensing 81/03/10 dep
- 8103170458 Requests that instrumentation & control independent design review be rescreduled at first available opportunity Delays will have significant impact on BAR-FRAR & CEBBAR-F review SCHERR, A.E. CF-Poctor Bystems 81/03/11 1p
- 8103193115 Forwards final response to NPC BiO213 request for info re causequences of delay of accer Delay will result in longer lead times, decreased sys reliability t addl costs Info will be incorporated into environ review VAN ERCHILE E Arizona Public Bervice Co 81/03/15 82pp 07940 2/3
- B:03200067 Recommends Caseload Forecast Panel visit to facilities be scheduled for early Apr 1981; as requested by util Average cable pull rate has been high since 801058 visit Util clasprees u/KRC projected fuel load date RERRIGAM, J Licensing Branch 3 81/03/17 1p 08040:118
- \$103310438 Forwards final schedule for independent design reviewmentings.ppr 810122 meeting tecesors for Licensing 81/03/23 4pp 06699 292
- C Utility Environmental Report (ER), amends & correspondence
- \$105060502 Forwards responses to NRC 8107:13 request for info re environ rept for facilities liters addressed include sys demand \$ reliability, need for power consequences of delay & geography \$ demography. VAT 88.WALE E Artiona Public Service Co 81/03/03 130pp 07848:220

- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8103120620 Notifies that reasonable date for receipt of ac power system is 810331 SDR transcript & initial & final responses to open items previously submitted by util to support SER MERAGLIA.F U. Operating Reactors Branch 3. 81/03/06. Ip 07906-127
- F. Security, metical, emergency & fire protection plans
- B103100475 Requests guidance re acceptability of emergency operation facility design Facility located close to site u/ habitability requirements upgraded to requirements for test shipping cast Backup facility question raised VAN BRUNTLE E Arizona Public Service Co 81/03/03 ip 02855 020
- 8103310338 Ltr to #11 licensees of operating plants & holders of CPs forwarding MuREG-06%. "Functional Criteria for Emergency Response Facilities "Criteria describe acceptable method for meeting NRC requirements W/o encl EISELYNUT, D.G. Disvision of Licensing 81/03/05 App
- B103180002 Summary of 810725 meeting a/Sechtel & util in Phoenic. At relimitial design review of fire protection sys KERRIDAN, J. Licensing Branch 3. 81793706. 3pp. 07943-399
- 8103300369 Requests NRC quidance re acceptabilit, of energency aperations facility design Facility will be basement level of administration anner lifty Peneral Design Criterion IP will not be enceeded during accident VAN URBUNT, E.E. Artiona Public Service Co. 61/03/19 2pp 200.653 311
- 6103310661 Confirms implementation dates for CLs re upgraded emerger facilities in response to NMC ltm to all fig. licensees & CP holions Jule 810210 VAN BRUNIT.E. E. Antiona Public Service Co. 81/03/25 | Jp. 08075-200
- O Adjudicatory correspondence
- 8100260309 Requests that ABLB proceed in absence of intervenor Hoursesponse to dispeted contentions alsolder, C.A. Snell & Wilmer 81/03/il 3pp 08041 031
- @10324C039 Discusses joint applicants' ltr reproceeding progress Agrees that intervenor has not filed & does not intend to file response to position statements ASLB should issue order identifying intervenors contentions to be litigated MCOURREN.H J. Hearing Branch 1 81/03/20 2pp 07990 323
- it General currespondence
- 8103160240 Provides FERN winfo reparticipation of El Paso Electric in Palo Verde Froject. In response to 810129 request Myo joint application for O., participation agreement & FES excerpt DENTOLIN R. Office of Nuclear Reactor Regulation, Director 81/03/02 400
- --8103160260 Request submitted by FERN. for info re El Paso Electric participation in Palu Verde project H/related info JONES. 8 Affiliation Uninoum 81/01/29 App
- B10317047B Informs that M Walker has replaced SL Dolins as Assistant Director of Energy Programs UAN BRUNT.S E. Artiona Public Service Co. 81/03/09 289 07929 191
- G. Inspection reports, 16 Bullatins & correspondence
- 8103040322 Forwards IE Insp Repts 50-528/60-20,50-529/80-20 & 50-530/80-20 on B01202-05 No noncorpliante noted BPENCER.9 B Region 5. San Francisco. Reactor Construction & Engineering Support Branch BI/01/19 2pp 07820.115
- -8103040331 IE Insp Repts 50-528/80-20.50-529/80-20 & 50-530/80-20 801202-05 No noncompliance noted Major areas inspected const activities re licensee action on previous insp findings & concrete placements ECKHARDT.J H. HERNANDEZ.O Region 5. San Francisco. Diffice of Director CODDS.R T. Region 9. San Francisco, Reactor Construction & Engineering Support Branch 81/01/15 App. 07829 117

- G103100395 Forwards IE Insp Repts 90-528/60-21.59-529/60-21 & 50-633/80-21 on G01208-10 No moncompliance noted BOOK.H E. Region 5. San Francisco, Fuel Facilit, & Materials Safety Branch. 81/01/19 2pp 07864 163
- --Bio3i00403 if into Repts 50-528/80-21.50-529/80-21 & 50-530/80-21 on B01208-10 No noncompliants noted Major areas inspected implementation of environ protection CP requirements blaudit of environ program MORTH.H S. CARCIA.E N. MEMBLAWSAI.F A. Region S. San Francisco. Office of the Director B1/01/16 Bpp 07864 165
- 8103050367 Forcards 1E linsp Repts 50-528/80-19.50-529/80-19 & 50-530/80-19 on 801103-21 No noncompliance indeed SPENCER.9.5 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 81/01/23 2pp 07824 249
- --B103050379 IE Insp Repts 50-528/80-19, 50-529/80-19 & 50-530/80-19 on B01103-21 No noncompliance noted noted Major areas inspected protection of installed reactor vessel internals & RCPB installation VORDERRRUEOUEN Region 5. San Francisco. Diffice of the Director DDDBS.R.T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 81/01/22 622 07824 247
- B102020699 Supple 801230 response to IE Bulletin 80-21, "Valve Yakes Supplied by Malcoln Foundry Co. Inc." Vendors have confirmed that no velves have been identified as using potentially faulty nati

  VAN BRUNT.E. E. Arizone Public Service Co. B1/02/04 ip 07/282 136
- 8103020056 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required. ENGELKEN.R. H. Region 5. San Francisco. Office of the Director B1/02/09. jp 07787:262
- B103230870 Responds to IE Sulletin 80-16, "Potential Misapplication of Rosemont Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Gubput Codes." Transmitters supplied by Atomics Intl. Anchor/Darling & Cooper VAN BRUNT, E. E. Artiona Public Service Co B1/02/09 2pp 07974, 353
- B103190681 Responds to IE Sulletin B0-23. "Failure of Solenoid Valves Mfg by Valcor Engineering Corp." No such valves used in sefety-related sys VAN BRUNT, E.E. Arizona Public Service Co. 81/02/11 19. 07964-037.
- 8103090790 Ack receipt of 801217 ltr informing NRC of eteps taken to correct violation noted in IE Insp Repts 50-528/80-17, 50-530/80-17, 50-5
- --8103050766 Forwards IE Insp Repts 50-528/80-17.50-529/80-17 & 50-530/80-17 on 800908-30 & notice of violation. SPENCER.0.S. Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 80/11/23 2pp. 07828-078.
- --Bi03050781 iE Insp Repts 50-528/80-17.50-529/80-17 & 50-530/80-17 on B00908-30. Noncompliance noted failure to make periodic insps & maint prescribed by manufacturer for motor operators of isolation valves in main steam & feeduater sys VORDERSRUEGGEN Region 5. San Francisco. Office of the Director. HAYNES, R. C. Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/11/21. App 07828.031
- B103110B14 Ack receipt of B10204 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/80-16, 50-529/80-16 & 50-530/80-16. FAULKENBERRY, B. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. B1/02/27 19 07877.249.
- --Bi03110823 Responds to NRC 801224 ltr re violations noted in IE Insp. Repts 50-528/80-16.50-529/80-16.50-529/80-16.Carrective actions: concrete placements repaired per Spec 13-CM-365 by 801117.

  VAN BRUNT, E.E. Arizone Public Service Cq. 81/02/04. 3pp. 07877.250.
- --G103110B31 Forwards 1E Insp Repts 50-528/80-16.50-529/80-16 t 50-530/80-16 on 801007-10 t notice of vialation. SPENCER.0.B Region 5. Ban Francisco, Reactor Construction t Engineering Support Branch. 80/12/24. 2pp. 07877:253.
- ---9103110837 Notice of violetian from insp on 801007-10.

  BPENCER, 0 B. Region 5: San Francisco: Reactor Construction & Engineering Support Brench. 80/12/23. 2pp. 07877.255.

- --BIO311CB47 IE Insp Repts 50-528/80-16.50-529/80-16 & 50-530/80-16 on BO1007-10 Noncompliance noted cebris found entrapped in concrete placements 3A035.3A038.3A038.3A04 & 3A119. resulting in three packets of unbonded concrete ECKHARDT.J H., HERNANDEZ.G. Region 5. San Francisco. Office of the Director CODES.R I Region 5. San Francisco. Reactor Construction & Engineering Support Branch B0/12/23 Spp 07877-287
- 8103170029 Forwards IE Circular B1-03. 'Inoperable Seismic Monitoring Instrumentation " No response required ENGELKEN.R H Repino 3. San Francisco, Office of the Director 81/03/02 1p 07939 155
- 8103160848 Forwards revised IE Bulletin 81-01. 'Surveillance of Mechanical Shubbers.' W/corrected Pages 5 & 6 Change in identification of Facilities U/CPs to which bulletin is applicable does not affect util requirements ENSELMEN.R H. Region 5. San Francisco. Office of the Director 81/03/04 ip 0.7914 207
- 8103200259 Forwards IE Info Notice 81-06. "Failure of ITC model k-cod Circuit Broader' No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 81/03/11 1p 07950 352
- B103200042 Forwards IE Info Notice 81-05. "Degraded DC Sys at Palisades" No response required ENSELMEN R H Region 3, San Francisco. Office of the Director 81/03/13 1p 07970-015
- A Periodic operating reports & related correspondence
- B103090519 Forwards magnetic tape of hourly meteorological data for 730813-780813

  VAN BRUNTLE E. Arizona Public Service Co. B1/03/09 3pp 07846::31
- S. Reportable occurrences. LERs & related correspondence
- B103110737 Ack receipt of 800715 ltr forwarding final deficiency rapt re operability failure of vertical fire dampers ENOBLKEN.R.H Region 5. San Francisco. Office of the Director 80710702. ip 07889-013
- B103120469 Final deficiency rept relack of add1 rebar reinforcement in containment placement making wall susceptible to overstressing under sejsmic conditions Caused by oversight Rebar added VAN BRUNT, E.E. Artiona Public Service Co. B1/02/04, 4pp. 07901:274
- 6103040550 Interim deficiency rept re indications revealed in site radiographs of previously accepted piping speals initially reported BIOI27, Bechtel will perform insp Corrective action completion scheduled for BIO415 VAN BRUNT, E.E. Arizona Public Service Co. 81/02/26 3pp 07815-136
- BiOG100991 Final deficiency rept re loose bushings on Corner & Leda sway struts. Initially reported BCO028 Bechtel has verified that Corner & Lada insured staking of rigid sway strut paddle ends. eliminating possibility of disengagement VAN BRUNT. E. E. Arisona Public Bervice Co. BI/03/02 4pp 07863-097
- B103170554 Interim deficiency rept re-weld deficiencies on main control panels.initially reported B00916 Final rept reforecast to B10715.dus to delays in receiving input data & performing analysis. No new Info available
  VAN BRUNT.E E. Ariiona Public Service Co. B1/03/10 2pp 07925:178
- 9100240364 Finel deficiency rept re-cable tray supports not meeting drawing requirement. Caused by drawing misinterpretation. Structural notes & instructions re-cable tray installation revised for clarity.

  VAN BRUNT, E. E. Aritona Public Service Cq. 81/03/16 4pp 07990:265

## T. Hearing transcripts on non-antitrust matters

8103130283 Forwards transcript 'Independent Design Review of Paig Verde Nuclear Generating Station Fire Protection Sys Search.' Vol 1 of 2 Transcript available in Central Files only ya's BRUNT.E E Artiona Public Service Cu 81/03/06 2pp 07914-003

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

- 8:03190387 Litr to all licensees of operating plants & applicants for DLs & holders of CPs to program for environ qualification of the safety-related electrical equipment items addressed involve cold shutdown replacement parts & NUREO-0737 EISENHUT, D O Division of Licensing 81/01/19. Sep
- 8103250024 Ltr to all power reactor licensees & license applicants re NAREO-0019 (riteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subnit analysis to justify use of existing low flow controller EISENHUT. D Q Division of Licensing 81/02/20 8pp
- 8103020529 Forwards "Clinch River Breeder Reactor Project Circulation Verification Program Pretest Predictions for FFTF Natural Circulation Tests Initiated at 100% & 75% Pawer/Flow Constitutes "COPELAND.R L Energy.Dept of

DOCKET SO-938 MEMPHIS STATE UNIV RESEARCH REACTOR

G Inspection reports: IE Bulletins & correspondence

- 8103020151 Forwards 1E Circular 81-02. "Performance of NRC-Licensed Individuals thile on Duty." No written response required O'REILLY.J P. Region 2. Atlanta, Office of the Director. 81/02/09 ip. 07788 044
- 8103020695 Forwards IE Insp Rept 50-538/H1-01 on B10121-23 No rencompliance noted RENNALW B. Region 2. Atlanta. Safeguards Branch 81/02/11 2pp 07782-043
- --Bi03020704 IE Insp Rept 50-53f/Bi-Oi on Bi012i-23 No noncompliance noted Major areas inspected licensee security plan, protection of SMM-security organization & access control alarm sys Details withheld (ref 10CFR2 790).

  IOWELL. J C . MCGUIRE D R Region 2. Atlanta. Diffice of the Director Bi02/II is 07782 045
- P. Periodic operating reports & related correspondence
- 8103310224 Forwards "Ctr for Nuclear Studies Memphis State Univ, 1980 Annual Rept. Nuclear Reactor Operations " UC:58.0 W Memphis State Univ 81/03/27 ip 08061:128
- --BIG3310230 "Ctr for Nuclear Studies, Memphis State Univ, 1980 Annual Rept. Nuclear Reactor Operations " DIETJ.R. L. JUNES.D W. Memphis State Univ B1/03/31 33pp. 08041-124

CCMET BIN-90-946 MARBLE HILL NUCLEAR BIATION, UNIT 1

A Application/construction stage documents & correspondence

- 6103190732 Ltrs to all licensees of operating plants applicants for DLs & holders of CPs re control of heavy loads Requests review per guidelines in NUREO-0612 Forwards NRC position re Interim actions & request for add1 Infb. E18E(NPI). D 0 Division of Licensing B0/12/22. 30pp.
- 8103:90387 Ltr to all licenses of operating plants & applicants for OLs & helders of CPs re-program for environ qualification of safety-related electrical equipment items addressed involve cold shutdown.replacement parts & NUREO-0737 EISENHUT.D 0 Division of Licensing 81/01/19. Spp.
- 8103120014 Ltr to all licensees of operating plants.CP holders & CL applicants, except Indian Point 2 & 3, Zion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addition of control of heavy loads EISENHUT, D. O. Division of Licensing 81/02/03. 6pp.

- Bi03090208 forwards organizational charts depicting ARC Region 3 reorganization.effective Bi0216.
  KEPPLER J G Region 3. Chicago, Office of the Director 81/02/20
  206 07850 341
- 8103250024 Ltr to all power reactor licenses & license applicants of MUREG-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D O Division of Licensing 81/02/20 Bpp
- Bio3230030 Ltr to all licensees of operating nuclear power plants & applicants for CLs (except St Lucie.Units 1 & 2). Requests util review to determine capability to mitigate station blackout event & promptly implement emergency procedures EISECHUT.D O Division of Licensing 81/02/25 5pp
- BIO3230813 Generic Ltr 81-06 to all CP holders & GL applicants re 10CFR90 71(e): "Periodic Updating of FSARs." effective BOO722 Info re FSAR legal status, format & content end EISENHUT, D O Division of Licensing 81/02/26
- 8103050509 Forwards supplemental description of revisions to facility organization per Bio213 ltr Project nanual revisions will be completed during while \$10301 SHIELDS.B W. Public Bervice Co. of Indiana. Inc. 81/02/27.
- 8103310804 Ltr to all licensees of operating plants.applicants for DL 5 holders of CPs forwarding SECY-B1-119 re info necessary to establish environ qualification of safety-related electrical equipment ETSENHUT.D 0 Division of Licensing 81/03/10 6pp.
- 8103300491 Responds to 800926 to 810304 ltrs expressing concerns to evaluation of util rept. "Evaluation of In-Place Concrete Harble Hill Nuclear Generating Station-Units is 2." Revised rept reliable Basis for conclusion encl. MEPPLER, J. 0. Region 3, Chicago, Office of the Director 81/03/20. 9na. 08057-176.
- F Security medical, emergency & fire protection plans
- 8103310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements live enci
- Q Adjudicatory correspondence
- B10324059B Discusses NRC actions under 100FR2 206 taten in response to Bave the Valley B00507 & 14 comments & supporting affidavits. Ltr concludes NRC consideration of filings.
  BTELLO.V. Director's Office. Office of Inspection and Enforcement. B1/03/18 5pp
- H General correspondence
- 8103050681 Forwards revisions to Nuclear Div organization, initially submitted 810213 Appropriate project menual revisions should be completed by 810301.
  BHISLDS 8 W Public Service Co. of Indiana, Inc. 81/02/27. 17pp. 07832
- I. Financial information
- Bi03:B0710 Forwards Annual Financial Rept 1980 for util & Wabesh Vall Power Association. Inc. SHIELDS.B.W. Public Service Co. of Indiana, Inc. 81/03/13. ip. 07944:336
- --BiO3180716 Annual Financial Rept 1980. Supporting documentation encl 4 Public Service Co of Indiana, Inc. 81/01/30. 57pp. 0794/357.
- Q Inspection reports. IE Bulletins & correspondence
- B103020228 Forwards IE Mgt Meeting Repts 50-546/80-45 & 50-547/80-45 801209.

  KEPPLER.J Q Region 3. Chicago. Office of the Director B1/01/15. 2pp. 07794:280
- --8103020240 IE Mgt Meeting Repts 50-546/80-45 & 50-547/80-45 on 8012 Areas discussed, regulatory performance as concluded in systematic assessment of licensee performance program. FIGRELLI.O Region 3. Chicago, Reactor Construction & Engineerin Support Branch. 81/01/07 Bpp. 07784 282.

- 8103030440 Forwards IE Insp Rests 50-946/60-46 t 90-947/80-46 on B01201-30 No nencompliance noted FIQRELLI. G Region 3. Chicago. Reactor Construction & Engineering Support Branch B1/01/16 2pp 07795 017
- --BIOJOJO497 IE Insp. Repts 50-546/80-46 % 50-547/80-46 on BO1201-30 No homographience noted Major areas inspected activities at site to verify activities complied u/confiring step work order & within scope of graduated rescission of order HARRISCH.U J., WILLIAMS.C C. Region 3. Chicago. Office of the Director BI/O1/0B 4pp. 07795-019
- 8103050868 Responds to [E Bulletin 80-23, "Failures of Solenoid Valves Mg by Valcor Engineering Corp " Specified valves are not planned for use in safety-related areas SHELDS:8 W Public Service Co. of Indiana, Inc. 81/02/02 1p. 07809 188
- B103020062 Forwards IE Circular B1-02. 'Performance of NRC-Licensed Individual's While on Duty." No written response required MEPPLER, J. G. Region 3. Chicago, Office of the Director 81/02/09 2pp 07787:279
- B103261140 Forwards IE Insp Rapts 50-546/81-01 & 50-547/81-01 on 810191-31 No noncompliance noted FIORELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch 81/02/12. 2pp 08035-256
- --Bi03261144 IE insp Repts 50-546/Bi-O1 & 50-547/Bi-O1 on Bi0101-31 No noncompliance noted. Major areas inspected storage & maint activities for safety-related items & util receiving insp & const activities

  HARRISO'S, J., WILLIAKS, C. Region 3. Chicago, Office of the Birector Bi/02/10 4pp 08033:258
- 8103160265 Forwards IE Info Notice 81-04, "Cracking in Main Steam Lines." No response required KEPPLER.J O Region 3, Chicago, Office of the Director 81/02/27 2pp 07914 270.
- B103160524 Forwards 1E Circular 81-03, "Inoperatle Seismic Monitoring Instrumentation." No response required MEPPLER. J G Region 3. Chicego, Office of the Director 81/03/02 2pp 07916 32).
- 8103:60876 Forwards revised IE Bulletin 81-0; "Surveillance of Mechanical Shubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements

  KEPPLER. J G Region 3, Chicago, Office of the Director 81/03/04

  1a 07914:341
- 8103200375 Forwards IE Info Notice 81-06. 'Failure of ITE Model K-600 Circuit Breaker " No response required KEPPLER, J G Region 3, Chicago, Office of the Director. 81/03/11 2pp 07972-125
- B10319020B Ack receipt of 810220 itr informing NRC of additions to correct violations noted in IE Insp Repts 50-546/79-02. 50-547/79-02. 50-547/79-25. 50-547/79-25. 50-546/80-03 & 50-547/80-03 REJISHYAN, R.F. Region 3, Chicago, Office of the Director 81/03/12. Ip 07955 067.
- --8103190211 Supple 800718 response to NRC line re IE Insp. Repts 50-546/79-02, 50-547/79-02, 50-546/79-25, 50-547/79-25, 50-546/80-03 & 50-547/80-03 Corrective actions: in-depth study of hat1 handling activities performed 6HIELDS 8 M. Public Service Co. of Indiana. Inc. 81/02/20 2pp 07965.068
- 8103200688 Forwards IE Info Notice 81-05, "Degraded DC 84s at Palisades." No action required.

  KEPPLER.J. 0 Region 3, Chicago, Office of the Director 81/03/13

  2pp. 07964:123
- Bi03200343 Forwards IE Info Notice 81-07, "Potential Problem M/Mater-Boluble Purge Dam Matly Used During Inert Qas Welding." No response required. KEPPLER.J. G. Region 3, Chicago, Office of the Director. 81/03/16 2pp. 07966:300
- B. Reportable occurrences, LERs & related correspondence

1

8103040147 PNO-III-80-213: on 801112. ASME survey team completed implementation survey intends to recommend N-Stamp be issued to util.

HILLIAMS.C.C. Region 3. Chicago. Diffice of the Director FIORELLIO. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 80/11/12. 1p. 07820.032.

- B103030445 PND-III-BC-224 on 801205.1EE authorized r limited electrical L mechanical/piping work for subcontractors.Cherne Contracting Corp & Commonwea J. V. based on favorable insp findings F108ELLI.0. SCHWE10INZ.E., WILLIAMS.C. Region 3. the Director 80/12/05 1p 07799 023
- 8103040725 Final deficiency rept re containment post trumplates initially reported 790416 Subsequent extesting of cores in area of concrete overheating referease in corpressive strength Procedure for rep. SHIELDS. 8 M Public Service Co. of Indiana. Inc. 27810.012
- 8103060352 Final rept re wold deficiencies identifie storage conditions on cable tray hangers initially on 800925. Deficient welds re-evaluate Condition not reportable under ICCER to 55e SHIELDS. SW Public Service to of Indiana. Inc 07897 080
- U Congressional/Executive Correspondence
- 8103230595 Requests that no decision be rade re resulur until IRRC responds to repts by M Cassarp restesting of Flawes concrete
  FORD. H. Senate 81/03/06 ip 07977 280
- B103270110 Responds to request for rept on possible to NRC licensing process Legislation allowing inte operations in advance of hearing completion would delay in licensing process HENDRIE. J. M. Commissioners 81/03/12 Spp
- --8103270947 Eubmits recommendations re scheduling, p hearing mgt for CL proceedings Pahel must obtain from hiring freeze for two recently appointed ch COTTER.B P. Atomic Bafety and Licensing Board P 3300
- DOCKET STN-90-547 MARBLE HILL LUCLEAR STATION. UNIT

  A Application/construction stage documents & corres.
- D103199732 Ltrs to all licensees of operating plants CLs & holders of CPs re control of heavy loads Req review per guidelines in NUREG-0612 Forwards MRC p interin actions & request for addl info EISENAUT.D O Division of Licensing 80/12/22
- B103190397 Ltr to all licensees of operating plants of the bolders of CPs reprogram for environ qualified by afety-related electrical equipment litems addressivative cold shutdown.replacement perts & NUREC-07: EISENHUT.D O Division of Licensing 81/01/19
- 8103120014 Ltr to all licensees of operating plants. applicants, except Indian Point 2 & 3, Zion 1 & 2 & forwarding inadvertently omitted pages from NMC 80 request for add1 info re control of heavy loads EISEKHUT. D Q. Division of Licensing 81/02/03
- 810309020B Forwards organizational charts depicting reorganization.effective 810216 KEPPLER, J. O. Region 3. Chicago, Office of the Dir 2pp. 07890 341
- 8103230024 Ltr to all power reactor licensees & lice AVREO-0619 criteria Footnate 2 in Table 2 contains to leakage testing deletions Licensee may submit a justify use of existing low flow controller EISENHUT. D.C. Division of Licensing 81/02/20.
- Bio3230030 Lir to all licensees of operating nuclear applicants for OLs (except St Lucie, Units 1 & 2) R util review to determine capability to mitigate st blackout event & promptly implement emergency proc EISENHUT, D 0 Division of Licensing, 81/02/25
- 8103230813 Generic Ltr B1-06 to all CP holders & OL of 10CFR30 71(a). "Periodic Updating of FBARs." effect 800722 info he FBAR legal status format & content of EISENHUT, D O. Division of Licensing 81/02/26.
- 8103050897 Forwards supplemental description of reviorganization per 810213 ltr Project manual revision completed during wk of 810301 BHIELDS-S-W Public Service Co. of Indiana, Inc 07826. 256

9103310B04 Ltr to all licensees of operating plants.applicants for Ols & bolders of OPs forwarding SECY-81-119 re Info necessary to establish anvison qualification of safety-related electrical equipment EISEMHJE, D.O. Division of Licensing 81/03/10 Acn

- 6103503491 Responds to 860996 t 819304 line expressing concerns & 103303491 Responds to MOVY/A & B19303 lits expressing concerns & evaluation of util tept. "Evaluation of In-Place Concrete - Marble Hill Nuclear Generating Station. Units 1 % 2 "Revised rept reliable Basis for conclusion encl MEPPLER J G Region 3. Chicago Diffice of the Director B1/03/20 9pp 08057 176
- F. Security, modical, emergency & fire protection plans
- RIO3310338 Lir to all licensees of operating plants & holders of CPs forwarding NURRO-O696 Functional Criteria for Emergenry Response Facilities "Criteria Jescribe acceptable method for meeting NRC requirements life and EISEMAJI.D 3 Division of Licensing 81/03/05 App
- a Adjudicatory correspondence
- 9103240590 Discusses NRC actions wider IOCFR2 206 taken in response to Save the Valley 800507 % 14 comments & supporting affidavits Ltr concludes NRC consideration of filings STELLO.Y Director's Office. Office of Inspection and Enforcement
- H General correspondence
- 9103950481 Forwards revisions to Nuclear Div organization, initially submitted B10213 Appropriate project manual revisions should be completed by B10301 SHELDS 8 N Public Service Co of Indiana, Inc. 01/02/27 1700 07032 001
- 1 Financial information
- 6:03180710 Forwards Annual Financial Rept 1980 for util & Wabash Valley Power Association, Inc. SHIELDS, S. W. Public Bervice Co. of Indiana, Inc. BI/03/13 To 17744 356
- -- 4103180716 Annual Financial Hact 1980 Supporting documentation encl Public Bervice Co. of Indiana, Inc. 81/01/30 57pp 07744: 357
- 1 1-spection reports, IC Bullatins & correspondence
- 0103029228 Forwards 1F Mgt Meeting Repts 50-946/80-45 & 50-947/80-45 on 901207 VEBSTAGE Region 3. Chicago, Office of the Director 81/01/15 202 07784 260
- --8103020240 IE Mgt Mosting Repts 30-546/80-45 & 50-547/80-45 on 801209 Areas discussed regulatory performance as concluded in Areas discussed regulatory performance as concluded in systematic assessment of licensee performance program FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Eupport Branch (81/01/07) Opp 07784 282
- 6103333440 Forwards IF Insp Repts 90-545/80-46 & 50-547/80-46 on 801201-30. No nontonpliance noted FIGRELLI.G Region 3. Chicago. Reactor Cunstruction & Engineering Support Branch, 81/01/16 2pp 07799 017
- --0103030457 IE 1msp Repts 50-546/00-46 & 50-547/80-46 on 801201-30 No noncompliance noted Major areas inspected activities at site to verify activities complied w/confirming stop work order & within scope of graduated rescission of order HARRISON, J.J., MILLIAMS. C.C. Region 3. Chicago. Office of the Director 81/01/08 4pp 07795-019
- 81/33952968 Responds to IE Bulletin 80-23. "Failures of Bolenoid Valves
  Hig by Valvor Engineering Corp ' Specified valves are not
  clained for use in safety-related areas
  SHIELDB, B. W. Public Service Co. of Indiana, Inc. 81/02/02 lp. 07029.345.
- BIOJ261140 Forwards 1E Insp Repts 50-546/81-01 & 50-547/81-01 on 010101-31 No noncompliance notes. FIORELLIG. Region 3. Chicago, Reactor Construction & Engineering Support Branch 81/02/12 2pp 08005 256

- --9103261844 IE loss Regts 50-546/81-01 & 50-547/81-01 so BLOUGH-31 No moncompliance noted Major areas inspected storage & maint activities for safety-related stens & util receiving insp & coost activities HARRISCH. J. WILLIAMS.C.C. Region ( Director 81/02/10 4cm OB035 258 Region 3, Chicago, Office of the
- 8103160665 Forwards IE Info Natice 81-04. Cracking in Main Steam Lines " No response required

  \*EPPLER.J. G. Reason 3. Chicago, Office of the Director 81/02/27 2pp 07914 270
- B103160524 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation." No response required MEPPLER. J. O. Region 3. Chicago. Office of the Director 81/03/02 2pp 0.7916-321
- B103160876 Forwards revised IE Bulletin B1-01. "Surveillance of Fechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is Applicable does not affect util requirements.

  KEPPLER, J. G. Region 3. Chicago, Office of the Director - 81/03/04 10 97914 341
- B103200375 Forcerds IE linfo Notice Bi-Ob. "Failure of ITE Model K-600 Circuit Breaker" No response required KEPPLER, J. Q. Region 3. Chicago. Office of the Director B1/03/11 2pp 07972 125
- B103190208 Ack receipt of B10220 ltr informing NRC of addl steps taken to correct violations noted in IE Insp Repts 50-546/79-02. HEISHHAN, RF Region 3. Chicago. Office of the Director 81/03/12 12 0795.067 50-547/60-03
- --810319021f Supply 800718 response to NRC litrs re IE Insp Repts 50-346/79-02.50-347/79-02.50-347/79-25. 50-546/80-03 & 50-547/80-03 Corrective actions in-depth study of mati handling activities performed SHIELDS, S. W. Public Service Co. of Indiana. Inc. 81/02/20 2pp 07969 068.
- 8103200688 Forwards IE Info Natice 81-05, "Degraded DC Sys at Palisades. " No action required AEPPLER, J O. Region 3, Chicago, Office of the Director. 81/03/13 2pp 07966 123
- 8103200343 Forwards IE Info Notice Al-O7. "Potential Problem M/Water-Eclubic Purge Dam Matls Used During Inert Gas Helding." No response required Region 3. Chicago, Office of the Director BI/03/16 KEPPLER J G. Re
- 8 Reportable occurrences, LERs & related correspondence
- 8103040147 PND-111-80-213 on 801112. ASME survey team completed implementation survey Intends to recommend N-Stamp be issued to util WILLIAMS.C C. Region 3. Chicago. Office of the Director FIGRELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch BO/Ii/12 Ip 07820 032
- 8103030445 PNO-111-80-224 on 801203. I&E authorized resumption of limited electrical & mechanical/piping work for subcontractors. Charme Contracting Corp & Commonwealth Lord JV. Josed on favorable (nep findings FIGRELLIA , SchwEIBINZE , MILLIAMS.C Region 3, Chicago. Office of the Director. 80/12/05 1p 07795 023
- B103040729 Final deficiency rept to containment post-tensioning trumplates initially reported 790416. Subsequent exam & testing of cores in area of concrete overheating revealed decrease in compressive strength Procedure for repair encl. SHIELDS.B W Public Service Co. of Indiana. Inc. 81/02/27 07810 017
- B103060352 Final rept re weld deficiencies identified during maint of students of the rest of the control of the control of the conditions on cable tray harpers, initially reported on B00925 Deficient welds re-examined & re-evaluated. Condition not reportable under 1005R 50 59s. SHIELDS.5 W. Public Bervice Co. of Indiana. Inc. 81/03/02. 2pp. 07837:080
- U Congressional/Executive Correspondence
- B102230595 Requests that no decision be made re resumption of critical work until NRC responds to repts by M Cassero re sound testing of flawed concrete FORD.\*N Senate B1/03/06 1p. 07977 200

- B103270110 Responds to request for rept on possible add1 improvements to INCC literains process Legislation allowing interim operations in advance of hearing completion would reduce delay in literaing process.

  HENDRIEL JH Commissioners 81/03/12 Spr
- --BI03270947 Submits recommendations re scheduling personnel resources to hearing mpt for OL proceedings Panel must obtain exerytion from hiring freeze for two recently appointed chairmen COTICR, B.P. Atomic Safety and Licensing Board Panel 81/02/25
- DOCKET 8TN-50-553 PHIPP8 BEND NUCLEAR STATICH UNIT &
- 8103190732 Ltrs to all licensees of operating plants applicants for OLS & holders of CPS to control of heavy loads Requests review per guidelines in NVREO-Obil2. Forwards NRC position reinterim actions & request for addl info ETBENNUT.D 9. Division of Licensins 80/12/22 30ap
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for envison qualification of safety-related electrical equipment Items addressed involve cold shutdown.replacement perts & NUREG-0737 EIBENMUT.D.O Division of Licensing 81/01/19 App.
- 8103120014 Ltr to all licensess of operating plants.CP holders & DL applicants.except Indian Point 2 & 3.7ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from ARC 801222 request for addl info ne control of heavy loads EISENHUT, D. O Division of Licensing. 81/02/03 App
- 8103160669 Ltr to all operating plants & CP holders forwarding clarification of TME Action Plan Item IEE A 1 2 re upgrade of smergency support facilities Requests confirmation within 45 days that implementation dates will be met EISENHUT.D 9 Division of Licensing 81/02/18 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re NAREO-0619 criteria Footnote 2 in Table 2 contains error due to lealage testing deletions. Licensee may submit analysis to justify use of existing low flow controller EISENHUT. D 0 Division of Licensing. 81/02/20. 8pp
- 8103020533 Forwards info re Faults 26 & 27 in Foundation Piers 34 & 19 of Unit 1 Cooling Tower-initially reported on 810113 & 22.

  Neither fault is capable within meaning of App A to 10CFR100.
- MILLB.L.M Tennessee Valley Authority 81/02/24. 6pp. 07782:101.
- B103230813 Generic Ltr 81-06 to all CP holders & DL applicants re 10CFR50 71(e). "Periodic Updating of FSARs." effective 900722 Info re FSAR legal status.fornat & content encl. EISENHUT.D. Q. Division of Licensing 81/02/26 10pp
- Bio3120197 Responds to Bio114 & 25 repts to discovery of faults during excavation for const of cooling towers. Faults believed formed during tectonic event. Appelachian Drogeny. 250 million yrs ago. Rept not necessary for similar faults uncovered. TEDEBCO.R.L. Assistant Director for Licensing. G1/G3/O2. 2pp 07906.195.
- BioggioBo4 Lit to all licensess of operating plants applicants for OLs k holders of CPs forwarding SECY-Bi-Li9 re info necessary to establish environ qualification of safety-related electrical equipment.

  EISENHUT-D.9. Division of Licensing. 81/03/10 App.
- F. Becurity, medical, emergency & fire protection plans
- BJ0391033B Lit to all licensees of operating glents & holders of CPs forwarding NUREO-0696. "Functional Criteria for Emergency Response Factilities." Criteria describe acceptable method for meeting NRC requirements. W/o encl EISENHUT. D. Q. Division of Licensing. 81/03/05. 6pp.
- G. Inspection reports, IE Bulletins & correspondence
- 9103030172 Forwards IE Insp Rept 50-953/80-17 on 801117-20 No nancompliance noted.

  MRRHY,C.E. Region 2. Atlants, Reactor Construction & Engineering Support Branch. 81/01/02. 2pp. 07790:280.

- --Bi03030185 IE Insp Rept 50-553/80-17 on 801117-20 No noncompliance noted Major areas inspected review of containment radiographs welding procedures & review of nondestructive erap performance in areas of liquid penetrant COLEY. J. L. Region 2. Atlanta. Office of the Director --- ERDT. A Region 2. Atlanta. Peactor Construction & Engineering Support Reach Bi0102 900 07790 282
- B102280484 Forwards IE Info Notice 81-01. "Possible Failures of GE "yea IFA Relays " No response required O'REILLY. J P Region 2. Atlanta. Office of the Director E1/0://b
- B103020277 Forwards IE Circular B1-02. "Performance of NRC-Liceraed Individuals Hhile on Duty 'No written response required O'REILLY.J.P Region 2. Atlanta. Office of the Directur (11/02/07)
- 8103040753 Provides add1 response to IE Bulletin 80-20 re Westinghouse Type M-2 switches Info from GE re STRIDE partian of facilities has not been received Info anticipated by BIC615 MILLS.L.M Tennessee Valley Authority BI/02/10 ip
- 8)03190333 Forwards IE Insp Repts 50-553/81-01 % 90-554/81-01 or 810120-23 No noncompilance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/11 2pp 07954 323
- --310319033B IE insp Repts 50-553/Bi-O1 & 50-554/Bi-O1 on 81012C-23 ho noncompliance noted Major areas inspected steel structures & supports, previous insp findings & licensee identified iOCR30 55e items
  CRDMLEY. B. Region 2. Atlanta, Office of the Director HERDT, A. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch Bi/O2/11 Bpp. 07954, 325
- BIO3130230 Forwards Suppl 5 to IE Bulletin BO-17. "Failure of Control Rods to Insert During Scram at BMR " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 81/02/17 to
- 8103160516 Forwards IE Circular 81-03. "Inoperable Beismic Monitoring Instrumentation" No response required REPPER. J. O. Region 3. Chicago. Office of the Director 81/03/02 to
- 8103170011 Forwards revised IE Bulletin 81-01. "Burveillance of Mechanical Bnubbers." w/corrected Pages 3, & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements.

  D'REILLY, J. P. Region 2. Atlanta- Office of the Director B1/03/04
- B103200197 Forwards IE Info Notice B1-06. "Failure of ITE Model M-602 Circuit Breaker." No response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. U1/03/11
- B103200003 Forwards IE Info Notice 81-05, "Degraded DC Bys at Palisades." No response required.
  O'REILLY-J.P Region 2. Atlanta. Office of the Director U1/03/13
- B. Reportable accurrences. LERs & related correspondence
- BiO31002B1 Part 21 rept re reactor protection sys panel design deficiencies initially reported on BO0807.Util is awaiting info from GE re final corrective actions MILLS-L.M Tennesse Valley Authority. Bi/02/12 2pp
- B103090351 Suppl to final deficiency rept re embedded plates w/o heat traceability-originally reported 801014 Nature of deficiency prevents determination of cause Personnel reinstructed in need for accurate documentation in logs.

  MILLS-L M. Tennessee Valley Authority 81/03/02. 2pp 07850.164
- 8103300333 Supplemental Interim Deficiency Rept 2 re-potential excessive pressure drop in essential svc water sys raw water pipting initially reported on 801210.88404 being conducted to resolve deficiencies noted in Divs 1 & 2 MILLS-L.M. Tennessee Valley Authority. 81/03/20. 29p

- BIO3190722 Ltrs to all licensees of operating plants applicants for CLs & holders of CPS re tontrol of heavy loads Requests review per guidelines in NAREG-0612 Forwards AIRC position re Interim actions & request for addl info respectively. D o Division of Licensing 80/12/22 30pp
- BiO3190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs to program for environ qualification of safety-related olectrical equipment Items addressed involve cold shutdown.replacement parts & NUREG-0737 EISENHUT, D G Division of Licensing HI/01/19 App
- 8)03;200;4 Ltr to all licensees of operating plants.CP holders & OL applicants, except Indian Point 2 & 3.2ion 1 & 2 & TMI-1, forwarding inadvertently omitted pages from NRC 801222 request for addl info re control of heavy loads EISENNUT.D.O Division of Licensing 81/02/03 6pp
- Bi03160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III A. 1 2 re upgrade of energency support facilities Requests confirmation within 45 days that implementation dates will be not EISENHUT.D Q Division of Licensing Bi/02/18 12pp
- 8103250924 Ltr to all power reactor licensees & license applicants re NAREG-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may subnit analysis to justify use of existing low flow controller EISENRUI. D. O. Division of Licensing. 81/02/20 8pp
- 8103020633 Forwards info re Faults 26 & 27 in Foundation Piers 34 & 19 of Unit 1 Cooling Tower.initially reported on 81013 & 22 Neither fault is capable within meaning of App A to 100FR100 MILIS.L.M. Tennessee Valley Authority 81/02/24. 600 07782-101
- 8(03230813 Generic Ltr Bi-O6 to all CP holders & GL applicants re 1CCFR5D.71(a). "Periodic Updating of FSARs." effective BC0722 Info re FSAR legal status format & content encl EISEINHUT.D O Division of Licensing. B1/02/26.
- 9100120197 Responds to 810114 & 20 repts re discovery of Paults during scavetion for const of cooling towers Faults believed fermed during tectonic event. Appalachian Orogeny, 290 million yes ago Rept not necessary for similar faults uncovered TEDESCO.R.L. Assistant Director for Licensing 81/03/02 2pp 07906-195.
- 8103310804 Ltr to all licensees of operating plants applicants for DLs tholders of CPs forwarding BECY-BI-119 rs info necessary to establish environ qualification of safety-related electrical equipment.
  FISSPHUT. D. O. Division of Licensing 81/03/10 dec.
- F Security, medical, emergency & fire protection plane
- Bi03310338 Ltr to all licensees of operating plants & holders of CPs forwarding NUREG-0696, "Functional Criteria for Emergency Response Facilities." Criteria describe acceptable method for meeting NRC requirements. H/o encl EIBENHUT, D. O. Division of Licensing. 81/03/05. 6pp.
- O Inspection reports: IE Sulletins & correspondence
- 8102280494 Forwards IE Info Notice 81-01, "Possible Failures of QE Type HFA Relays." No response required.

  D'REILLY, J.P. Region 2: Atlanta. Office of the Director 81/01/16 is.
- 8103020277 Forwards IE Circular Bi-02, "Performance of NRC-Litensed Individuals While on Duty," No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. Bi/02/09. is
- 8103040753 Provides add1 response to 1E Bulletin 80-20 re Westinghouse Type M-2 switches Info from GE re STRIDE portion of facilities has not been received info anticipated by 810615. MILLER.L.M. Tennesse Valley Authority. 81/02/10. ip.
- 9103190333 Forwards IE Insp Repts 50-553/81-01 & 50-554/81-01 on 810120-23. No noncompliance noted HuRPHY,C E. Region 2. Atlanta, Reactor Construction & Engineering Eupport Branch. 81/02/11. 2pp. 07954: 323.

- MERDY A Region 2. Atlanta. Reactor Construction & Engineerin Support Branch 81/02/11 8pp 07934-325
- 8103130230 Forwards Suppl 9 to 1E Bulletin BO-17. "Failure of Contro Rods to Insert During Scram at BWR." No written response required 0."REILLY.J.P. Region 2. Atlanta, Office of the Director. 81/02/1
- B103160516 Forwards IE Circular B1-03, "Inoperable Baismic Monitorin Instrumentation " No response required KEPPLER. J. 9 Region 3. Chicago, Office of the Director B1/03/02

10

10.

MILL B. L. M

- 8103179011 Forwards revised IE Bulletin 81-01. "Surveillance of Mechanical Snubbers." w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements. O'REILLY, J.P. Region 2. Atjanta, Diffice of the Director 81/03/0
- 8103200197 Forwards IE Info Notice 81-06. "Failure of ITE Model K-60 Circuit Breater" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 81/03/1
- B103200003 Forwards IE Info Notice Bi-05. "Degraded DC Sys at Palisades." No response required O'REILLY, J. P. Region 2. Atlanta. Office of the Director B1/03/1
- S. Reportable occurrences, LERs & related correspondence
- Bi03i0028: Part 21 rept re reactor protection sys panel design deficiencies initially reported on 800807 Util is awaiting info from OE re final corrective actions HILLS.L.M. Tennessee Valley Authority 81/02/12 2pp.
- Bio3090951 Supplito final deficiency reptire embedded plates w/o heatraceability.originally reported S01014 Nature of deficiency prevents determination of cause. Personnel reinstructed in need for accurate documentation in loss

Tennessee Valley Authority 81/03/02 200 07850 16

- BIO330033D Supplemental Interim Deficiency Rept 2 re-potential excessive pressure drop in essential set water sys-rew water piping, initially reported on BO1210 Study being conducted to resolve deficiencies noted in Divs 1 & 2 MILLS.L. M. Tennessee Valley Authority 81/03/20 2pp
- DOCKET STN-90-956 BLACK FOX STATION. UNIT 1
- A. Application/construction stage documents & correspondence
- 8103190397 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown-replacement parts & NUREG-0737. ETBENHUT. D.O. Division of Licensing. 81/01/19. App.
- BiO3180039 Unofficial transcript of Commission BiO212 meeting in Washington.0C re BECY-Bi-20 policy on proceeding w/pending CP & refg license applications.Pp I-ii3.

   Condissioners. Bi/O2/12 ii7pp.
- --Bi03030450 Recommends Commission approve entl draft final rule 100 relitensing requirements for pending CPs & mfg license applications & proposed statement of requirement re degraded core rulemaking.

  DIRCKS.W J. Office of the Executive Director for Operations.

  SECY-81-020A Bi/02/11. 12pp.
- BIO3250024 Ltr to all power reactor licensees & license applicants r MUREO-0619 criteria. Footnote 2 in Table 2 contains error due to leakage testing deletions. Licensee ray subnit analysis to justify use of existing low flow controller ETBENHUT. D.O. Division of Licensing. 81/02/20. 8pp.
- Q. Adjudicatory correspondence
- BiO3240807 Notice of appearance in proceeding Certificate of Svc ent. DAMBLY.D.C Operations & Administrative Division. Bi/03/23. 3pp 07984:332.

- ODCKET STR-50-957 BLACK FOX STATION UNIT 2

  A Application/construction stage documents 5 correspondence
- B103190387 Ltr to all licensers of operating plants & applicants for Ous & rolders of CPs re-program for environ qualification of safety-related electrical equipment litems addressed involve cold shutdown.replacement parts & MUREG-0737 EISENMUT.D 0 Division of ticensing B1/201/19 6pp
- 8103180037 Unofficial transcript of Commission 810212 meeting in Washington, BC re 8ECY-81-20 polity on proceeding w/pending CP & rig license applications Pp 1-115 commissioners 81/02/12 117pp
- --BIO3030450 Recomments Commission approve encl draft final rule 10CFR50 re licensing requirements for pending CPs & mfg license applications & proposed statement of requirement re degraded core rule-raking
  DIRCKB.W.J. Office of the Executive Director for Operations
  SFCY-RI--320A BI/02/11 1200
- B103250024 Ltr to all power reactor licenses & license applicants re MUREQ-0619 criteria Footnots 2 in Table 2 contains error due to leakage testing deletions Licensee may submit amalysis to justify use of existing low flow controller EISENHUT, D Q Division of Licensing B1/02/20 Bpp
- O Adjudicatory correspondence
- 8103240507 Notice of appearance in proceeding Certificate of Svc enct. DAMBLY,D.C. Operations & Administrative Division 81/03/23 3pp 07994 333
- 8103240312 Notice of appearance in proceeding Certificate of Svc encl BAGING M Defice of the Executive Legal Director 81/03/23. 3pp 07994-375
- BOCKET 90-964 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

  A Application/construction stage focuments & correspondence
- Bi03310697 Confirms withdrawal of 760128 license application. Requests that all proprietary info be returned or destroyed ROBINSON, R. K. Ezzon Nuclear Co., Inc. (subs. of Exxon Corp.) 80712718 1p. 08059 162.
- DOCKET BIN-90-966 YELLOW CREEK NUCLEAR PLANT, UNIT 1. TENNESSEE VALLEY
  A. Application/construction stage documents & correspondence
- Bi03190732 Ltrs to all licensees of operating plants applicants for OLs & holders of CPs re control of heavy loads Requests review per guidelines in hUREO-0612 Forwards NRC position re interim actions & request for add1 info EIBENHUT.D.O Division of Licensing. 80/12/22 30pp
- B1031903B7 Ltr to all licensees of operating plants & applicants for DLs & holders of CPs re-program for environ qualification of safety-related electrical equipment. Items addressed involve cold shutdown.replacement parts & NUREO-0737 EIBENHUT.D.O Division of Licensing. 81/01/19 App.
- B103120014 Ltr to all licensees of operating plants CP holders & DL applicants except Indian Point 2 & 3.2ion & & 2 & TMI-1, forwarding inadvertently omitted pages from ARC B01222 request for addl info re control of heavy loads.

  EISENHUT.D.Q Division of Licensing. 81/02/03 6pp
- BIO3160669 Ltr to all operating plants & CP holders forwarding clarification of TMI Action Plan Item III.A. 1.2 re upgrade of emergency support facilities. Requests confirmation within 45 days that implementation dates will be met EISENMUT.D.9. Division of Licensing 81/02/18. 12pp.
- 8103250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller. EISENHUT-D.O. Division of Licensing. 81/02/20. 8pp.

- 8103230813 Generic Ltr 81-06 to all CP holders & OL applicants re 10CFR90 71(e). "Periodic Updating of FSARs." effective 899722 Info re FSAR legal status.format & content enci. FISEINUIL D. G. Biystion of Literating 81/02/26 10ap
- 8103310834 Ltr to all licensees of operating plants applicants for OLs 1. holders of CPs forwarding SECY-BI-LIP re info necessary to establish environ qualification of safety-related electrical equipment FISEINHILD O Division of Licensing 81/03/10 6pp
- F Security, medical, evergency & fire protection plans
- B10331033B Lit to all licensees of operating plants & Folde's of CPs forwarding NUREO-0596. Functional Criteria for Knergercy Response Facilities "Criteria describe acceptable method for neeting NRC requirements U/o encl ELSEMBULT B C Division of Licensing EL/03/05 Opp
- O Inspection reports, IE Bulletins & currespondence
- B1022B0484 Forwards 1E Info Notice B1-01. Possible Fastures of G: \*ype HFA Relays ' No response required DTREILLY, J.P. Region 2. Atlanta, Office of the Director B1/01/16
- B103020277 Forwards IE Circular 81-02. 'Performance of NHC-Licensed Individuals While on Duty 'No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director HIVOZYOZ te
- B103260444 Forwards IE Insp Repts 90-566/81-01 & 90-967/81-01 c · 810112-16 No noncompliance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engliseering Support Branch B1/02/20 2pp 08039 327
- --BIO3260496 IE Insp Repts 50-566/81-01 % 50-567/B1-01 on BiOt12-in 45 noncompliance noted Major areas inspected steel structures & supports, containment rediographic film.containment. Pabrication shops & matl receiving yard COLEY. J. L. Region 2. Atlanta. Diffice of the Director HIPDI. A H. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 81/02/19 8pp 08039 329
- 8103160516 Forwards IE Circular 81-03. 'Imagerable Seismic McCitoring Instrumentation' No response required KEPPLER, J. G. Region 3. Chicago, Office of the Director. 81/61/(2) 10.
- B103170D11 Forwards revised 1E Bulletin B1-01, "Surveillants of Hechanical Snubbers," w/corrected Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  O'REILLY.J.P. Region P. Atlanta. Office of the Director (01/03/04)
- 8103260019 Forwards update to 800805 response to IE Bulletin 79:03A "Longitudinal Weld Defetts in ABME BA-312, Type 304 Stainless Steel Piping." SA-312 Type 300 series fusion welded pipe not used at facilities Addl info will be sent by 810630 MILLS.L.M. Tennessee Valley Authority 81/03/04 2pp.
- 8503200197 Forwards IE Info Notice 81-06, "Failure of TIE Hodel K-600 Circuit Breaker" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 81/03/11 to.
- Bi03200003 Farwards IE Info Notice Bi=05. "Degraded DC 9ys at Palisades." No response required D'REILLY, J.P. Region 2. Atlanta, Défice of the Director - 01/03/13 in
- 8 Reportable accurrences, LERs & related correspondence
- B103110584 First interim deficiency rept re lamination of soil in EACM spray pond, initially reported B10204 Laminations possibly caused by overcompaction of liner 2/or excessive speed of heuling equipment Block samples util be evaluated MILLS.L.M Tennessee Valley Authority 81/03/05 2pp. 07873 335

#### COKELED HEMS

- 8:03:89702 First interim deficiency rept.originally reported 8:02:2 ro inversified letismic analysis of final design for essential row cooling later pumping station. Hatch access platform ho waste mgt bldg Verification incomplete Next rept by 8:07272 HILLS.L.M. Tennesser Valley Authority, 8:17/03/13 2ps 07949 049
- 8103270712 Final coficiency rest willing. It reported on 810220.co bent, shifting & dislocated rebar/anthor boilts Caused by drawing interpretation errors & ingroper handling & rigging practices Rebars straightened & new boilts grouted in MILLS.L M. Tennessee Valley Authority 81/03/20 3pp 08043 310
- B103270B23 Third interim deficiency rept.originally reported on 803923.ne 0A Aujit MB0-7 Deficiencies 2.3.5 & 14 Review of deficiencies 5 proposed corrective action continuing Neit rapt will be submitted by 810922 MH.S.L.M. Tennessey Valley Authority 81703/20 ip 88047-210
- OCCRET 61N-90-967 VELLOW CREEK NUCLEAR PLANT. UNIT 2. TENNESGEE VALLEY

  A Application/construction stage documents & correspondence
- BIO3190732 Lins to all licensees of operating plants, applicants for O.s. & holders of CPs recontrol of heavy loads Requests review per guidelines in NUREG-Obl2 Faruards NRC position reinterin actions & request for addline;

  FIRSTN-NLT, D.O. Division of Licensing 80/12/22 30pp
- 8103190387 Ltr to all licensees of operating plants & applicants for OLs & holders of CPs re prograf for environ qualification of sefety-relates electrical equipment Items addressed involve cold shutdown replacement parts & hURED-0737 SISSIMITED 0 Division of Licenston 81201/19 Acc
- BiO3120014 Lite to all licensees of operating plants, CP holders & Owapplicants, except Indian Point 2 & 3, Zion 1 & 2 & FMI-1, forwarding inadvertently onitted pages from NRC 801222 request for addl info re control of heavy loads EIBERNUT.D Q Division of Licensing 81/02/03 App
- 8103169669 Ltr to all operating plants & CP holders forwarding charification of TMI Action Plan Item 111 A 1 2 re upgrade of emergency support facilities Requests confirmation within 45 days that implementation dates will be not.
  EISENMULD O Division of Licensing 81/02/18 12pp
- E100250024 Ltr to all power reactor licensees & license applicants re NUREO-0619 criteria Footnote 2 in Table 2 contains error due to leakage testing deletions Licensee may submit analysis to justify use of existing low flow controller EISCH-MUT.D 9. Physion of Licenseing 81/02/20 Upp
- 8103050306 Forwards revised description of onsite neteorological eastweeth program Revision will be included to DL application HLLB, L M. Tennessee Valley Authority 81/02/26 14pp 07827 128
- 8]03230813 Generic Ltr 81-06 to all CP holders & D\_ applicants re (CCFR\$0 71(e), "Periodic Updating of FSARs," effective B00722 Info re FBAR legal status.format & content encl EISER-MUT. 0.0 0 Division of Licensking 81/02/26 10pp
- 8103310804 Ltr to all licenses of operating plants, applicants for ULs & holders of CPs forwarding SECY-Bi-119 re info necessary to establish environ quelification of safety-related electrical equipment EISEINUT.D.O Division of Licensing 81/03/10 6pp
- F Becurity, medical, emergency & fire protectson plans
- 8103310338 Lin to all licensees of operating plants & holders of CPs forwarding NUREG-Q494. "Functional Criteria for Emergency Response Facilities " Criteria describe acceptable method for meeting NRC requirements N/o and EISENHUT. D. O Division of Licensing 81/03/05 App.
- O Inspection reports. IE Bulletins & correspondence
- 8102283484 Forwards IE Info Notice 81-01. "Possible Failures of GE Type HFA Relays." No response required Office of the Director. 81/01/16. 1:
- 8103020277 Forwards IE Circular 81-02. "Performance of NRC-Licensed Individuals While on Duty " No written response required O'REJLLY, J.P. Region 2: Atlanta, Office of the Director 81/02/09 is:

- Bi03269444 Forwards IE Insp Repts 99-556/81-01 & 50-567/81-01 on Bi0112-16 No noncompliance noted MARPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch Bi/02/20 200 08039 327
- --8103260456 IE insp Repts 50-566/81-01 % 50-567/81-01 on Bi0112-16 No noncompliance noted Major areas inspected steel structures % supports, containment radiographic film, containment, fabrication shops & matl receiving yard CQLEY, J. Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 81/02/19. Bpp 08039 329
- BiOJi60516 Forwards IE Circular 81-03. "Inoperable Seismic Monitoring Instrumentation" No response required KEPPLER. J.O. Region 3. Chicago. Office of the Director 81/03/02.
- 8103170011 Forwards revised IE Bulletin 81-01, "Surveillance of Mechanical Boubbers," Joseph Pages 5 & 6 Change in identification of facilities w/CPs to which bulletin is applicable does not affect util requirements
  D'REILLY, J. P. Region 2, Atlanta, Office of the Director 81/03/04 in.
- 8103260019 Forwards update to B00805 response to IE Bulletin 79-03A "Longitudinal Keld Defects in ASME SA-312. Type 304 Stainless Steel Piping " SA-312. Type 300 series fusion welded type not used at facilities Addl info will be sent by 810430. MILLBILM Tennessee Valley Authority. 81/03/04 2pp.
- 8103200197 Forwards IE Info Notice Bi-O6. 'Failure of ITE Model K-600 Circuit Breater. No response required O'RETLEY.J P. Region 2. Atlanta. Office of the Director | 81/03/11
- 8)03200003 Forwards IE Info Notice 81-05. "Degraded DC Bys at Palisades." No response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 81/03/13
- 5 Reportable accurrences. LERs & related correspondence
- B1031B0702 First interim deficiency rept.originally reported 810212 re unverified seismic analysis of final design for essential raw cooling water pumping station, batch access platform & wasteingt bidg Varification incomplete Next rept by 810729 MILLS.L.M. Tennessee Valley Authority 81/03/13 2pp 07945.049.
- B103276823 Third interim deficiency rept, originally reported on B00723 re GA Audit M80-7 Deficiencies 2.3.5 & 14 Review of deficiencies 5 proposed corrective action continuing Next rept will be submitted by B10722 MILLS.L.M Tennessee Valley Authority. B1703720. 1p 08047.210
- DOCKET 30-578 SANTILLAN NUCLEAR POWER STATICN. ELECTRA DE VIESOO A Application/construction stage documents & correspondence
- 8103120014 Ltr to all licensees of operating plants.CP holders & OL applicants.except Indian Point 2 & 3. Zion 1 & 2 & TMf-1. forwarding inadvertently unitted pages from NRC B01222 request for add1 info re control of heavy loads EIBENHUT.D O Division of Licensing B1/02/03 App.
- DOCKET 50-579 TRIOA MARK [] POLL-TYPE REACTOR

  A Application/construction stage documents & correspondence
- B103040837 License for QA Co to export instrumentation sys & components, reactor mechanical components.RCS components, syc & replacement equipment, fuel handling equipment & various items for temporary use to Malaysia DEVINC.J.B. Assistant Director for Export/Import & International Bafeguards. B1/02/20. 2pp. 07991.162
- DOCKET 50-503 BUNDEBERT, UNIT 2
- A. Application/construction stage documents & correspondence
- B103100550 Responds to B01125 request re list of possible threatened 8 endangered species in vicinity of plant BAUNDERS.T Interior.Dept of Fish & Wildlife Bervice. 60/12/15. 2pp. 07853:151

- DOCKET STN-50-592 PALO VERDE NUCLEAR STATION. UNIT 4

  A Application/construction stage documents & correspondence
- 810317045B Requests that instrumentation & control independent design review be rescheduled at first available apportunity. Deleys will have significant inject on SAR.FSAR & CESSAR-F review SCHERER: A E C-E Power Systems. 81/03/11 1p.

## F Security, medical, emergency & fire protection plans

- 8103300309 Requests NRC quidence re acceptability of energency operations facility design facility uit) be besement level of administration anner bldg General Design Criterion 19 will not be exceeded during accident.

  VAN BRUNT, & E. Artions Public Service Co. 81/03/19 2pp
- 8103310661 Confirms implementation dates for CLs re upgraded emergency facilities in response to NRC ltr to all GL licensees & CP holders dtd 810218.

  VAN BRUNT. & E Arizona Public Service Co. 81/03/25 1p

## DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

- A Application/construction stage documents & correspondence
- B10317045B Requests that instrumentation & control independent design review be reacheduled at first available opportunity Delays will have eignificant impact on SAR.FSAR & CEBSAR-F review. BCHERRNA & C.-E Power Systems. 81/03/11. 1p.

## F Security, medical, emergancy & fire protection plans

- B103300309 Requests NRC quidance re acceptability of emergency operations facility design. Facility util be basement level of administration annes bldg General Design Criterion 19 util not be exceeded during accident VAN RRINILE F Arizona Public Service Cn 81/03/19 200
- B103310661 Confirms implementation dates for CLs re upgraded emergency facilities in response to NRC life to all CL licensess & CP holders did 810218 VAN BRUNT, 6.6. Arizone Public Service Co 81/03/25 lp.
- DOCKET 50-596 NEW HAVEN, UNIT 1. NEW YORK STATE ELECTRIC & GAB CORP.

  A. Application/construction stage documents & corpsspondence
- 8103090040 Advises of balance due for CP application review. Application was withdrawn 801016.
  MILLERIN. O. License Fee Hanagement Branch. 81/02/27. 1p. 07852-181.

# DOCKET 50-597 NEW HAVEN. UNIT 2. NEW YORK STATE ELECTRIC & GAS CORP.

- A. Application/construction stage documents & correspondence
- 8103090040 Advises of balance due for CP application review.Application was withdrawn 801016.
  MILLER, W U. License Fee Management Branch. 81/02/27. ip. 07852:181.

### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

## DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

- B103200B87 Forwards order re mod of Licenses BNM-7 & 34-06854-05, requiring preparation & submission of radiological contingency plan.
  CUNNINGMAM.R. E. Division of Fuel Cycle & Material Bafety. 81/02/11.
  1p. 07967: 235.
- --BID3200891 Order requiring mod of Licenses SNM-7 & 34-06884-05. Licensee must develop & submit rediclogical contingency plan & application for license amends to incorporate plan as condition of license within 180 days.

  CUNNINGHAN.R E. Division of Fuel Cycle & Haterial Bafety.

  BI702/11. App. 07967:236.
- 8103060510 Forwards organizational charts depicting NRC Region 3 reorganization, effective 810216. MEPPLER.J. Q. Region 3. Chicago, Office of the Director. 81/02/20. 2pp. 07836:087.

- 8103270839 Advises of change in policy re tamper-safing of low enriched U Bingle individual may perform witnessing & certification of tamper-safing program for U enriched to less than 6% PARTCOW J 0 Material Control Licensing Branch. 81/03/19. 1p
- DOCKET 70-0029 ROCKWELL INTERNATIONAL CORP
- BIO3270769 Informs that O Smith of NRC physical security licensing staff will make 801030-31 visit to Canago Part facility to discuss major aspects of physical security plan. MCCORMLE, O W Physical Becurity Licensing Branch 80/10/23 1p.
- B103090266 Forwards order re-mod of License SNM-21, requiring preparation & submission of radiological contingency plan. CUMNINDHAM.R E Division of Fuel Cycle & Material Safety. 81/02/11 pp. 07846-334.
- --8100090274 Order requiring mod of License ShM-21 Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days CUNNINGHAM.R.E. Division of Fuel Cycle & Material BaPety 81/02/11. 6pp 07846:335.
- B103200419 Forwards IE Insp Rept 70-0029/81-01 on B10217-20 & 0333 Nonaccompliance noted Enci withheld (ref 100FR2 790).

  NOROBERHAUG.L. Region 3. San Francisco. Safeguards Branch 01/93/13
  2pp 07966.337
- 8103250115 Informs that case will be assigned to D Huff, effective B10316. Huff will arrange visit to facility. PARTLON. J. D. Matorial Control Licensing Branch 81/03/16 tp 07997-300.

## DOCKET 70-0027 BABCOCK & WILCOX CO.

- 9103260988 Withdraws 800605 request for license amend to provide for questerly sampling of airborne radioactive effluents released from laundry operations. CORDANI,R. A. Babcock & Wilcox Co. r Navel Nuclear Fuel Div. 80/10/28 | 1p. 08040-225
- 8103130635 Forwards IE Insp Rept 70-0027/80-19 on B01111.No noncomplience noted. BTOHR.J P. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. B1/02/05. 1p. 07913:216
- --8103130644 IE Insp Rept 70-0027/80-19 on 801111. No noncomptiance not Major areas inspected:ground water monitoring. WODDRUFF.R.L., HILLBAP.W.J. Region 2. Atlanta, Office of the Director. 01880N.A.F. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 81/02/05. 3pp. 07913 217
- 8103160928 Forwards IE Insp Rept 70-0027/81-02 on 810121-23. No honcompliance noted. KENNA. M. B. Region 2. Atlanta. Bafeguards Stanch. 81/02/10. Ip 07915: 095.
- --8103160933 IE Insp Rept 70-0027/81-02 on 810121-23. No noncompliance noted Major areas inspected operations, facility change to mods.10CFR21 implementation, maint & sefety committee. CONYELL. 0.P. Region 2. Atlanta, Office of the Director. KAHLE. J. B. Region 2. Atlanta, Safeguards Branch. 81/02/10 4pp 07915:096.
- B103090218 Forwards order re-mod of License BNM-42, requiring preparation & submission of radiological contingency plans CURNINGHAM, R. E. Division of Fuel Cycle & Material Bafety. B8/02/31 pp. 07849:016.
- --Bi03090227 Order requiring mod of License SNM-42. Licensee must devei & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days. CUNIND/HAM, R.E. Division of Fuel Cycle & Material Befety. Bi/02/11. 6pp. 07849:017.
- 8103240309 Forwards IE Bafeguards Insp Rept 70-0027/81-01 on 010154-1: No noncompliance noted. KENNA-W.B. Region 2: Atlanta: Bafeguards Branch. 81/02/12 2pp 07981:334.
- --8103240313 IE Bafeguards Insp Rept 70-0027/81-01 on 810114-15 ho noncompliance noted Details withheld (ref 10CFR2.790) BATEB J. M. Region 2, Atlanta, Office of the Director. MCALPINE, E. J. Region 2, Atlanta, Safeguards Branch. 81/02/12 18. 07986:336.

- B103099242 Forwards (E Insp Rept 70-0927/81-03 on 810122-23 No monconpliance noted MEWA.U 8 Region 2. Atlanta. Bafeguards Branch 81/02/13 ip 07848 285
- --Bi03090249 IE insp Rept 70-0027/Bi-03 on Bi0122-23 No noncompliance noted Major areas inspected safeguards upgrade plan Details withheld (ref 10CFR2, 790) t081N.W J. Region 2, Atlanta, Office of the Director MCQUIRE.D R. Region 2, Atlanta, Bafeguards Branch Bi/02/13 ip
- BiO305054 Safety evaluation supporting amend to License SNM-42, authorising const of additions to north end of Bays is & 2a. not of existing process in Bay 3a & utilization of SNM in expanded facility

  METILACH.N. CRCM.N.T. Uranium Fuel Licensing Branch. 81/02/18
  335 07840 237
- O103070277 Amend I3 to License SNM-42 authorizing described operations for modified fuel process excluding punch loading pressing & helium load testing PAOF.R Q Uranum Fuel Licensine Branch 81/02/18 1P 07832-062
- 8103040444 Forwards "Effluent Monitoring Rept from Fuel Cycle Facility.

  Jul-Dec 1980 "

  CORDANI.R.A. Babcock & Wilcox Co., Naval Nuclear Fuel Div.
  81/02/25 10 07810 084
- --Bi03340449 "Effluent Monitoring Rept from Fuel Cycle Facility, Jul-Dec 1980." • Babcock & Wilcos Co., Naval Nuclear Fuel Div 81/02/25 ip.
- B102250147 Forwards IE Insp Rept 70-0027/81-04 on 810210-13 No handempliance noted LEMIS.R C. Region 2. Atlanta. Office of the Director 81/03/17. 2pp 07996:016
- --9103250153 IE Insp Rept 70-0027/81-04 on 810210-13 No noncompliance noted Major areas inspected measurement of statistical controls & internal control. Details withheld (ref 10CRF2 790).

  JGNES-D. W. 7000.9 A. HCALPINE.E.J. Region 2. Atlanta. Office of the Director 81/03/16. 1p 07996.018
- DOCKET 70-0000 TEXAS INSTRUMENTS: INC.
- 8103090097 Forwards order to mod of License BNM-23, requiring preparation & submission of radiological contingency plan. CV-MINGHAM, R. E. Division of Fuel Cycle & Material Bafety. 81/02/11. 19 07849:113
- --8103090103 Order requiring mod of License SNM-23. Licensee must develop be submit redialogical contingency plan & application for licensee amend to incorporate plan as condition of license uithin 180 days CUNINGHAM, R.E. Division of Fuel Cycle & Material Safety 81/02/11 6pp. 07849:114
- DECKET 70-0036 COMBUSTION ENGINEERING. INC.
- 8:103090109 Forwards orders re mod of Licenses BNM-33 & BNM-1067, requiring preparation & submission of redicinglical contingency plans.

  CUNNINGHAM.R E Division of Fuel Cycle & Material Bafety. 81/02/11. 1p. 07849.167
- --8103090118 Order requiring mod of License SNM-03 Licensee must develop a submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days.

  CUMNINGHAM.R.E. Division of Fuel Cycle & Material Safety.
  81/02/11. 6pp. 07849:168.
- --BI03090128 Order requiring mod of License BNM-1067.Licenses must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days.

  CURNINOHAM.R.E. Division of Fuel Cycle & Material Bafety.

  BI/02/11. 6pp. 07849-174.
- 8103090172 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216. MEPPLER.J. O. Region 3. Chicago: Office of the Director. 81/02/20. 2pp. 07852:100.

- B103180257 Forwards revised pages to C-E Hematite fundamental nucleomati control plan EBKR100E-H.E. C-E Power Systems. B1/02/23 9pp. 07944-051.
- DOCKET 70-0053 YALE UNIV
- 8103300345 Discusses [E finsp Repts 70-0053/81-01.30-00582/81-01 & 30-04888/81-01 on 810205-04. No noncompliance noted Major areas inspected high concentrations of radioactive meti in incinerator ash.per licenses 800306 ltr KINNEMAN, U.D. Region I. Philadelphia. Fuel facility & Materials Bafety Branch 81/02/26 2pp. 08037-335

### DOCKET 70-0124 TELEDYNE ISOTOPES

- 8103090206 Forwards orders to mod of Licenses 29-00055-14 & ENM-107, requiring preparation & submission of radiological contingency plans.

  CUININGHAM, R.E. Division of Fuel Cycle & Material Bafety. B1/02/1p 07849:001.
- --8103090213 Order requiring mod of License 29-00055-14. Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 120 days.

  CURNINGHAM. R E Division of Fuel Cycle & Meterial Bafety Bi/02/11 opp 07849:002
- --Bi03090219 Under requiring mod of License BNM-107. Licensee must de & submit radiological contingency plan & application for licensee amend to incorporate plan as condition of license within 240 days. CURNINGHAM. R E Division of Fuel Cycle & Meterial Gafety. Bi702/11. 6pp. 07849-008.

### DOCKET 70-0135 BABCOCK & WILCOX CO.

- 8103270751 Forwards proposed page revisions to Section II of License SNH-145, "Apollo Site Health & Bafety Menuel." "Emergency Procedures," & "Health & Safety Evaluations Manuel." AUSTIN.H A. Bebcock & Wilcox Co., Nuclear Material Div 80/10/30 3pp. 08044:320
- --B103270756 Proposed revised pages to Section II of License SNM-145 \* Batcock & Wilcox Co., Nuclear Material Div. B0/10/15 16pp. 08044-323.
- ---B103270759 "Apollo Bite Health & Bafety Manual." page revisions. AUBTIN.M.A., CORRIDONI.R.D., BAUHAN.T.A Babcock & Milcor Co., Nuclear Material Div. B0/08/25, 23pp. 08044:337.
- --B103270763 "Emergency Procedures." revised pages.
  CORRIDONI.R.D., CARLBON.R.V., AUBTIN.M.A. Babcock & Hilcox Co.,
  Nuclear Material Div. 80/09/12. 12pp. 08044:360.
- --9103270766 Revised "Health & Bafety Evaluations Manual." CORRIDORI.R.D., BAUMAN.T.A., JOHNSON.D F. Babcock & Wilcox Co., Nuclear Haterial Div. 80/10/30. 66pp. 08049:010.
- B103270270 Forwards response to 800822 comments on 8EW 800318 revisit to low enriched U fundamental nuclear mat1 control plan. Enc1 withheld (ref 10CFR2, 790).
  AUSTIN.M.A. Babcock & Wilcox Co., Nuclear Material Div. B0/11/28 ip. 08044:190.
- 8103090648 Forwards IE Insp Rept 70-0135/80-32 on 801216-19 No noncompliance noted MARTIN.N.Q. Region 1. Philadelphia, Bafeguards Branch. 81/01/13. 2pp. 07845:360.
- --8103090658 IE Insp Rept 70-0135/80-32 on 801216-19. No noncompliant noted Major areas inspected: residual holdup in high enriched U facility. Details withheld (ref 10CFR2.790).

  BIBBETT.P., BUMMERS.R. Region 1, Philadelphia, Office of the Director. JOYNER, J. H. Region 1, Philadelphia, Sefeguards Branc 81/01/09. 1p. 07845:362.
- 8103090139 Forwards orders re mod of Licenses BNH-145 & SNH-414, requiring preparation & submission of radiological contingency plans.

  CUNNINGHAMAR E Division of Fuel Cycle & Material Safety. 61/02/1p. 07848:304.

- ~-8103090163 Order requiring nod of License SNM-414 Licenses must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days
  CUNNINGHAM.R E Division of Fuel Cycle & Material Safety
  B1/02/11 & 6pp 07848 305.
- ~-8103090178 Order requiring mod of License 5WH-145 Licensee must develop a submit readiological contingency plan a application for license emend to incorporate plan as condition of license within 180 days

  CURNINGHAM, R.E. Division of Fuel Cycle & Material Safety.

  81702/11 6pp 07848 311
- B103030786 Responds to B01104 request to reduce mat1 control baccounting requirements for highly enriched U.Results of enhanced du measurements is description of program to remove be neasure embedded U should be submitted PARTLOH-J 0 Material Control Licensing Branch. B1/02/12 Ip. 07808 253.
- B100270839 Advises of change in policy re tamper-safing of low enriched U Single individue) may perform withnessing & certification of tamper-safing program for U enriched to less than 6% PARTICOW.J. Q. Material Control Licensing Branch. B1/03/19 (p.

### DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.

- 8103260089 Discusses 800827-28 & 0914-15 radiation surveys of Clinchfield Railroad property north of & adjacent to site to determine compliance w/License Amend S criteria. Concurs w/release of 50-ft strip for unrestricted use.

  STDHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 20709/19, 3pp. 08040:035.
- BiO3270693 Submits rept to escapeive releases of U-234 from scrubber stack of Bidg 233 on 800923-1006. Corrective actions:plant shutdown Sampling date re U-234 stack releases & perimeter & offsite dose concentration date enci.
  MAMBER.H C Nuclear Fuel Services, Inc. (subs of Cetty Dil Co ) 80/10/30 4PP 08046 294
- 8103270835 Forwards response to NRC request for info re App 1 to Revision O of physical safaguards plan Encl withhold. MICHEL.C.J Nuclear Fuel Bervices. Inc. (subs. of Oetty Dil Co.) 80/11/41 | 1p. 08045-117
- 8103300181 Forwards application to revise Amend MPP-1, Section 2 9 to License BNR-124 Application withheld (ref 10CFR2, 790). Amend fee end HERSLEY, B Nuclear Fuel Services, Inc. (subs of Oetty Oil Co.1. 80/11/20 2pp 08053
- 8103300021 Forwards Revision 1 to Chapters 18.19 & 21 of physical safeguards plan. App I info & four drawings Encis withheld (ref 10CFR2 790).
  MICHELOGY Nuclear Fuel Services. Inc. (subs. of Oetty Oil Co.).
  80/12/03. 2pp. 08093.138
- 8103300033 Forwards Revision 20 of nuclear meth control plan. Section 3.0 Revision withheld (ref 10CFR2 790) HENBLEY.K D Nuclear Fuel Bervices. Inc. (subs. of Ostty Oil Co.). 80/12/05 4pp.
- 8103300183 Forwards description of attestation which licenses will provide to revise fundamental nuclear math control plan. Bection 7.0.Revision 8.Description withheld (ref. 10CFR2 790)
  HENBLEY.K.D. Nuclear Fuel Bervices, Inc. (subs. of Oetty Dil Co.).
  80/12/05 2pp 08053:161
- 8103310910 Advises that upgrade rule plan requires mod prior to approvel. Revised plan should be submitted no later than B10201 Enci listing of mods required withheld (ref 10CFR2.790).
  MCCORKLE.O.W. Physical Security Licensing Branch. 81/01/07. ip
- B103130648 Forwards IE Insp Rept 70-0143/80-42 on 801027-1216. No noncompliance noted. KENNA-M.B. Region 2. Atlanta. Befeguards Branch. 81/02/05. 2pp 07913:220.
- --Bi03i30662 IE Insp Rept 70-0143/80-42 on G01027-1216 No noncompliance noted Hajor areas inspected: criticality sefety, radiation protection, stack effluents access controls & physical inventory. Encl 2 withhald (ref 10CFR2, 790).

  LEG.T.D.: JONES, D.M.: TODD-0.A. Region 2. Atlanta, Office of the Director. B1/02/05. 4pp. 07913:222.

- 8103090184 Forwards order to mod of License SNM-124, requipreparation & submission of radiological contingency pi CUMNINGHAM.R E Division of Fuel Cycle & Material Safa 1p 07848-326
- --8103090194 Crder requiring nod of License SNM-124 Licen develop & submit radiological contingency plan & aprifor license arend to incorporate plan as condition of license within 120 days

  CUMMINGHAM R. E Division of Fuel Cycle & Material Sa B1/02/11 6pp 07848-327
- B103040145 Requests meeting to discuss control to account highly enriched U operations Lists topics to be address meeting. PATICHLU 9. Material Control Licensing Branch 81/02 operation
- 8103260891 Submits rept re-results of add1 action re-print redundant sampler comparison.per NRC 801124 ltr.Four-us evaluation of data collected revealed comparability of samplers is acceptable Table summarizing sample data en MANSER.M. C. Nuclear Fuel Services. Inc. (subs. of Gott 81/02/18 2pp. 08040 213
- --8103260899 Forwards IE Insp Rept 70-0143/80-36 on 80116 noncompliance noted STOHR. J P Region 2. Atlanta. Fuel Facility & Materi Branch 81/01/29 lp 08040:215
- --8103260910 IE Insp Rept 70-0143/80-36 on 801103-04 No moted Major areas inspected effluent control & measur MILL88R.W J. Region 2. Atlanta. Office of the Direct Q1850N.A F. Region 2. Atlanta. Fuel Facility & Mater Brenth. 81/01/28 4pp 98040-216.
- 8103060366 Advises that 810203 revision to fundamental nu control plan Section 7 0 is acceptable License Condition of Amend MPP-1 is revised accordingly effective immedia Revision deemed proprietary. PARTLON-J 9 Material Control Licensing Oranch 81/08 02836-295
- Bio3i00391 Deletes Conditions 7 1.7.3 & 7.5 of Amend MPP-License BNM-124 PARTLON.J.O. Material Control Licensing Branch B1/03 07865-205
- B103130721 Ack receipt of supplemental B1021B ltr informations taken to correct violations noted in IE Insp. Rept. 70-0143780-24
  LEWIS.R.C. Region 2: Atlanta: Reactor Operations Nucle. Branch. B1/03706 1p. 07912-069.
- --BIO3130726 Bupplemental response to NRC BI0204 itr rein IE Insp Rept 70-0143/80-24 Corrective ections:cond dises provided around previously undixed storage tank fire suppression sys inspected weekly. MANSER, M.C. Nuclear Fuel Bervices. Inc. (subs. of Os B1/02/18 2pp 07912:070
- 8103240280 Ack receipt of 810220 ltr informing NRC of ste correct violations noted in IE lnsp Rept 70-0143/80-33 LEWIS.R C. Region 2. Atlanta. Office of the Director. 1p 07983 159.
- --810324028B Responds to NRC 810130 ltr re violations not Rept 70-0143/80-33 Corrective actions: initiated daily of sampling trains & weetly insp of sampler probes No proprietary info MANSER.V C Nuclear Fuel Bervices, inc. (subs. of Ge 81/02/20. 3pp 07983:160
- --8103240294 Forwards IE Insp Rept 70-0143/80-33 on 80100 violation. SIGNR.J.P. Region 2. Atlants, Fuel Facility & Materi Branch 81/01/30. ip. 07983:163
- --8103240276 Notice of violation from insp on 801006-10 # Region 2. Atlanta, Office of the Director. 81/01, 07987-164
- --8103240301 IE Insp Rept 70-0143/81-33 on 801006-10 None failure to representatively sample process ventilation to failow health & safety procedures HILLBAP.M.J. Region 2. Atlanta. Office of the Direct GIBEDN.A F. Region 2. Atlanta. Fuel Facility & Mates Brench 81/01/28 Spp. 07983:166.

- 8103260292 Ack receipt of 810303 ltr informing NAC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-39 Region 2. Atlanta, Office of the Director Bl/03/11 5TDHR.JP. Re ip. 38042 340
- --8103260306 Responds to NRC 810212 Itr re violations noted in IE Inap Rept 70-0143/80-39 Corrective actions drill will be renducted before 810731 & emergency plan will be revised to
- --8103260314 Forwards IE Insp Rept 70-0143/80-39 on 801208-11 & notices of violation & deviation STCHR, J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 81/02/12 200 08042:044
- --8103280323 Notice of violation from inse on 801208-11 Region 2, Atlanta, Office of the Director 81/02/12 to 00042 044
- --8103260329 Notice of deviation from insp on 801208-11 \* Region 2, Atlanta, Office of the Director 81/02/10. ip 48342 047
- --8103280341 IE Insp Rept 70~0143/80~39 on 801208-11 Noncompliance noted Hadiore to audit energency plan within specified time period b to conduct drills w/off site agencies. Bite meterological
- JIBON.G T Region 2. Atlanta, Office of the Director JEKKING G R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 81/02/10 4pp 08042:049 8103240116 Responds to 801125 ltr re cumulative inventory differences
- at NFB-fruin facility. Agrees on need to consider for inventory gife, at NFB-fruin facility. Agrees on need to consider from the facility of t
- --B103240123 Discusses cumulative inventory differences 5 implications. Requests that NRC be required to stop reporting values out of context. Press statement explaining analysis of recent differences at NFG-Erwin should be issued COCHRAM, T. D. Natural Resources Defense Council 80/11/25 700
- 8100230167 Forwards IE Insp Rept 70-0143/81-01 on 810127-29 No noncompliance noted.
  LEWIB. R.C. Replon 2. Atlanta, Office of the Director 81/03/17 LEWIS R C Reg 201 07996:037
- --8103250173 IE |nep Rept 70-0143/81-01 on 810127-29 No noncompliance roted Major areas inspected cumulative inventory difference & associated limit of error Details withheld (ref 100FH2 790) JONES, D. W., MCALPINE, E. J. Region 2. Atlanta, Office of the Director B1/03/16 Ip. 07976 039.
- BiO3270B39 Advises of change in policy re tamper-maring of low enriched 103270839 Advises of change in pulsey re-tamper mering of the U-Bingle Individual may perform witnessing & certification of tamper-safing program for U-snriched to less than 6%.
  PARTLOUGH J. G. Material Control Licensing Branch 81/03/19 [p.
- DOCKET 70-0152 PURDUE UNIV.

tower not recalibr

07989-276

Director

- 8103090480 Forwards IE Insp Repts 50-182/81-01 & 70-0192/81-01 on 010112-14 No noncompliance nuted. FIGHER.W. Region 3. Chicago. Fuel Facility & Materials Bafety Brench. B1/02/05 2pp. 07847:340
- --8103090465 IE Imag Repts 50-182/81-01 & 70-0192/81-01 on 810112-14 No noncompliance noted Major areas inspected organization eafety committees, criticality safety, radiation protection & radwaste rgt PECK-C C. Region J. Chicago. Office of the Director. FIBHER, W.L. Region J. Chicago. Fuel Facility & Materiale Bafety Branch. B1/02/05 7pp
- 8103040253 Forwards organizational Charts depicting NRC Region 3 reorganization, effective BiO216.
  KEPPLER, J. G. Region 3, Chicago, Dffice of the Director 81/02/20. 200. 07817:285

- DOCKET 70-0197 TEXAS, UNIV OF
- 8103040558 Forwards License SNM-180 & safety review issued in support sub : license Uranium Fuel Licensing Branch 81/02/18 to 07814 325
- --B103040662 License SNM-180 for Univ of TX authorizing use of 470 g U-235 contained in Ventiched to 20% & 128 pp.
  PAGE.R O Uranium Fuel Licensing Branch 81/02/18 20p.
  07816.326
- --8103040665 Reviews revised & consolidated 810130 application for renewal of License SNM-180 Renewal for five yr tern STEVENSON, R.L., CROW, W. T. Uranium Fuel Licensing Branch Bi/02/18 7pp 07816-328 be beermonded.
- DOCKET 70-0142 LUCIUS PITKIN, INC
- 8103100177 Notifies of termination of License SNM-137 Docket may be removed from active files

  SDONG, A L Uranium Fuel Licensing Branch 81/02/13 in 97865.336.
- ~~8101140395 Forwards Lucius Pittin. Inc folder, per apresent between NRC & New York. KINNEMAN.J.D. Region 1. Philadelphia, Fuel Facility & Haterials Safety Brench 80/12/19 ip 03878 338
- --8103100187 Advises that License BNM-137 is subj to NY State jurisdiction.tag recently amended license, reducing authorized quantity of BNN to less than 350 g U-235.Region 1 will arrange for transfer of files LUBENAU, J. O. Assistant Director for State Agreements Programs. BO/11/10. 1p 07865:338
- DECKET 70-00AD OU ANOMA STATE UNIVERSITY
- 8103240462 IE Insp Findings & Licensee Act dtd 810120 of Licenses 35-0027-03 & 8NN-241 Insp Findings: no noncompliance noted. Region 4. Dallas. Office of the Director 81/01/20 Ip. 07084 328
- DOCKET 70-0067 NUCLEAR BOLENCE & TECHNOLOGY FACTLITY AT RUNY
- B103261132 Forwards draft revised BNM accountability manual for nuclear indepilize reviews drawt reviews but accountability mars science & technology facility incorporating changes & including reviews internal accounting forms
  HENRY, L.G. New York State Univ. of Buffalo. 80/08/ B0/08/14 10 08034 328
- --8103261139 Accountability manual for nuclear science & technology racinity ORLOSKY.P M., PIERRO.M.A., New York, State Univ. of, Buffalo. BO/OB/14 31pp. 08036:329
- DOCKET 70-0303 CARNEGIE MELLON UNIV.
- B103090777 Discusses IE Insp Repts 30-14472/81-01.70-0303/81-01 & 70-0479/81-01 conducted on 810116. No noncompliance noted. No noncompliance noted. Hayer areas inspected radiation select & compliance w/ Commission rules & regulations & conditions of licenses. KINNEMAN, J. D. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. Bi/02/11 1p. 07847-224
- DOCKET 70-309 WESTERN MICHIGAN UNIV.
- 8103100394 Forwards rept of personnel whole body exposures for 1980. HOLT.I.V. Western Michigan Univ. 81/03/04 1p. 07865:318
- --Bi03100399 Rept of personnel whole body exposures for 1980. HDLT, 1. V Hestern Michigan Univ. 81/03/04 10pp. 07865.319.
- DDCKET 70-0315 NAVY, DEPT. OF
- 8103300045 Discusses IE Insp Repts 30-00605/81-01 & 70-0315/81-01 on BiO203 No noncompliance noted Major areas inspected. corrective actions on noncompliance noted in 760728 itr KINNEMAN, J D. Region i. Philadelphia, Fuel Facility & Materials

- DOCKET 70-0364 PARKS TOWNSHIP SITE, BASCOCK & WILCOX CO
- 8103270541 Submits interim organizational revision to all math control & accountability plans covered by License Condition 2 1 When div approves recent proposed organizational changes new organizational chart will be sent.

  AUSTIN.M A. Babcock & Milcor Co., Nuclear Material Div 80/10/14, 10. 09034:014
- 8103310842 Forwards IE Insp. Rept 70-364/80-24 on 801028-31. No noncompliance noted BMITH.O H. Region 1, Philadelphia: Fuel Facility & Materials Bafety Branch. 80/12/31. 2pp. 08061:094.
- --BIO3310B45 IE Insp Rept 70-0364/80-24 on 801028-31. No noncompliance noted Hajor areas inspected organization, mode & changes to facility & sys, internal review & audit & safety committee training.

  ROTH, J. Region 1, Philadelphia, Office of the Director CROCMER, H W. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. B0/12/30. 16pp. 08061:096
- B103310674 Requests correction to NRC 801216 ltr approving Amend 10 to License BNM-414. Revised page numbers were incorrectly cited AUSTIN. H.A. Babcock & Hilcor Co., Nuclear Haterial Div. B1/01/05 1s. 08038:175
- 8103090106 Forwards proposed radiological survey plan for 84H burial area Mort scheduled to commence within month.Wo encl ROUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch 91/02/06. 1p. 07852.122.
- B103090159 Forwards orders re god of Licenses BNM-145 & BNM-414, requiring preparation & submission of rediological contingency plans.
  CUMNINGHAM, R. E. Division of Fuel Cycle & Material Safety. B1/02/11
  1p 07848:304.
- --8103090165 Order requiring mod of License SNM-414. Licensee must develop & submit radiological contingency plan & application for license amend to Incorporate plan as condition of litense within 180 days

  CUNNINGHAN.R E. Division of Fuel Cycle & Material Safety
  81702711. Spp. 07848-305.
- B103030986 Responds to B01104 request to reduce meth control & accounting requirements for highly enriched U Results of embedded U measurements & description of program to remove & measure embedded U should be submitted.

  PARTLOH, J. 0. Naterial Control Licensing Branch. B1/02/12. ip. 07808:253
- BiO3110661 Amend 12 to License SNM-414, revising sample frequency for determining Pu siphs & U siphs contamination & License Condition 36 for air sampling frequency in Pu facility. RDUBE-L.C. Advanced Fuel & Spent Fuel Licensing Branch. B1/02/25. 11pp. 07877:262.

# DOCKET 70-0371 UNITED NUCLEAR CORP.

ı

ţ

- 810327050 Forwards revised pages to Chapters 3 & 4 of fundamental nuclear mati control plan. Pages withheld (ref 100FRZ 790). KIRK.M. F. United Nuclear Corp. 80/11/19, 2pp. 08046: 288
- 8100090058 Forwards order mod for License BNM-368, requiring preparation & submission of radiological contingency plan. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 81/02/11. ip. 07849:132.
- ---8103070064 Order requiring mod of License BNM-368. Licenses must develop & subsit rediological contingency plan & application for license asend to incorporate glan as condition of license within ISO days.

  CUNNINGHAM.R. E. Division of Fuel Cycle & Haterial Safety.
  81702/11. opp. 07849:133.
- 8100040678 Forwards application for amend to License 8NM-358/changing name & organizational structure. Requests review. W/o encl. 8TEVENBOR. R.L. Urenius Fuel Licensing Branch. 81/02/13, ip. 07840-383.
- 8103100333 Forwards "Effluent Monitoring Rept, Jul-Dec 1980." KERK-N.F. United Nuclear Corp., Nevel Products Div. 81/02/16. 1p. 07865:305.
- ---B103100358 "Effluent Honitoring Rept-Jul-Dec 1980." • United Nuclear Corp., Navel Products Div. 81/02/16. 1p. 07885:306.

B103200569 PN8-I-B1-006 on B10315, telcon w/unide of bomb threat. Bearch made of internal & exter Plant declared safe & normal plant operations MADDEN.W. JOYNER.J. CROCKER.H Region 1. Ph the Director B1/03/16 2pp 07972 081

#### DOCKET 70-0394 NORTHEASTERN UNIV.

- 8103050719 Ack receipt of 810108 ltr informing N correct violations noted in 1E Insp Repts 70-0 40-5293/80-01 & 30-13307/80-01. KINNEMAN.J. D. Region 1. Philadelphia. Fuel Fa Safety Branch. 91/01/28. ip. 07821 347
- ---8103090726 Responds to NRC B01211 ltr re viola Repts 70-0394/80-01:40-9393/80-01 & 30-1330 Corrective actions will conduct surveys of c &/or general rediction at end of each experi LATORRE.P. Northeastern Univ. 81/01/08
- --8103050734 Discusses IE Insp Repts 70-0394/80-30-13307/80-01 on 801113 8 forwards notice of KINNEMAN, J. D. Region I. Philadelphis, Fuel Bafety Branch 80/12/11. 2pp. 07821.350

# DOCKET 70-0398 COMMERCE, DEPT. DF

- B103310925 Forwards additinfo re Pu handling in license amend request PEVEY.L E. Commerce.Dept.of. National Bureau B0/12/19. 7pp. 08038-130.
- 8103090280 Forwards order re mod of License SNMpreparation & submission of radiological conti CUNNINOMAM.R.E. Division of Fuel Cycle & Matu ip. 07846:344.
- --Bi03070287 Order requiring mod of License BNM-& submit radiological contingency plan & app license amend to incorporate plan as conditwithin 120 days. CUNNINOHAM.R.E. Division of Fuel Cycle & he Bi/02/11. 6pp 0/846:345.
- B103040646 Requests amend to Licenses 08-00566-callow regular lab waste disposal of solid wastess than one percent of 10CFR20 App C quanticoncentration lass than 10CFR20 App B. Table 2: PEVEY.L E. Commerce.Pept.of, National Bureau B1/02/26. 1p. 07810:056
- 8103050408 Requests waiver to Bi0211 order to m development of radiological contingency plant employee exposure or offsite radiation does Correspondence should be directed to LE Pavey. PEVEY.L E. Commerce.Dept.of, National Bureau B1/03/02. 3pp. 07832:107.
- B103270839 Advises of change in policy re tamper U Bingle individual may perform witnessing & of tamper-safing program for U enriched to les PARTLOH.J. O. Material Control Licensing Brani

#### DOCKET 70-0475 CARNEGIE MELLON UNIV.

- B103090777 Discusses IE limp Repts 30-14472/B1-70-0479/B1-01 conducted on B10116 No noncompl Major areas inspected: rediation sefety & comp Commission rules & regulations & conditions of KINNEMAN. J. D. Region i. Philadelphia. Fuel F. Bafety Branch. B1/02/11. 1p. 07949:224
- DUCKET 70-0687 UNION CARBIDE CORP.
- 8103270164 Requests approval of bypess route to heavily populated grees.

  HART.H.C. Union Carbide Corp. 80/10/22. 1p
- 8103270186 Requests further change of route in HART-H C. Union Carbide Corp. 80/10/23. ip
- --8103270193 Informs that spent reactor fuel wi NY to Bevenneh River-BC on 801104,10 & 17. HART.H.C. Union Carbide Corp. 80/10/23.

- Big3031103 Trip rept of 801210 site visit to Tuzedo.NY to review fuel handling operations related to license renewal KETZLACH.N Uransum Fuel Licensing Granch 80/12/15 2pp
- 8:03310720 Request for renewal of License SNH-637 for period of 10 yrs.
  Supporting documentation encl
  GEORGE NO Union Carbide Corp 80/12/23 7op 08059 113
- Bio309060; Forwards order mod for License SNM-639, requiring preparation & submission of radiological contingency plan CURNIFORMAR E Division of Fuel Cycle & Material Bafety 81/02/11. 1p. 07849 129.
- --BI03090002 Order requiring mod of License SNM-639 Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 120 days.

  CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety 81/02/11 6pp 07849 126
- 8103120664 Notifies that fee for 810209 amend request refunded due to NRC personnel error FISS. B. License Fee Management Branch 81703706 in 07906 126
- DOCHET 70-0698 WALTZ MILL BITE, WESTINGHOUSE ELECTRIC CORP
- 8103310653 Application for revision to License BNM-770 re me: amount of matl authorized for possession. Requests that Page 103 be replaced owlengly revised page.
  SABD.A T. Westinghouse Electric Corp. 81/01/12 2pp. 08058:177
- BIO3C90303 Forwards orders re mod of Licenses BYM-770 & BYM-1107, requiring preparation & submission of radiological contingency plans CMANRGHAM. RE Division of Fuel Cycle & Material Bafety Bi/02/11 (p. 07846-353.
- -- e103090308 Order requiring mod of License BNM-770 Licensee must develop & submit radiological contingency plan & application for license within 180 days

  CUNNINGHAM.R.E Division of Fuel Cycle & Material Bafety.

  B1702/11 App 07846-354
- --6103090321 Order requiring mod of License BNM-1107 Licensee must develop & submit rediclogical contingency plan & application for license arend to incorporate plan as condition of license within 180 days CUXMINAHAMAR.E. Division of Fuel Cycle & Material Safety 81/02/11. 6pp 07846 360
- 8103170220 Forwards request for info resulting from review of B00401 renewal application for License 8NM-770. Info needed recrganization of safety-related responsibilities & radiation esposures.

  KETYLAGH-N. Urenjum Fuel Licensing Branch 81/03/12. 10pp 07934-305

#### DCCKET 70-0734 GENERAL ATCMIC CO

- 6103090721 Requests add1 info re NRC 801210 Invoice 211-81 requiring payment of special projects fee Requests justification of application of IOCFRI70 & accounting of NRC profitime cited in IRC 801208 ltr NB2AN-JP General Atomic Co. (subs. of Oulf Cil Co.). 81/02/05. 3ps 07846;229.
- 8103050766 Forwards order mod for License BNM-696, requiring preparation & submission of radiological contingency plan CUNNINGHAL, R.E. Division of fuel Cycle & Material Safety. 81/02/11. 15. 07837:252.
- --8103040771 Order requiring mod of License SNM-696 Licenses must develop & suchit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days. CUNINGHAM.R.E. Division of Fuel Cycle & Material Bafety 81/02/i1. App. 07837:253.

- B103020278 Forwards 1E. Insp. Rept. 70-0734/B1-02 on B10202-06 No noncampliance noted. Insp. rept. withheld free 10CFR2 790) NORDERHAUG.L. R. Region 5. San Francisco. Safeguards Branch B1/02/20. 2pp. 07784-270
- 8103040714 Forwards "Bemiannual Effluent Rept. Jul-Dec 1980" MORRY: W.R. General Atomic Co. (subs. of Gulf Oil Corp.). 81/02/2 2pp. 07810,034
- --B103040719 "Semiannual Effluent Rept. Jul-Dec 1980 "

  a General Atomic Co (subs of Gulf Gil Corp.). 81/02/27. Spp
  07810 036
- B103120491 Forwards "Semiannual Effluent Rept. Jul-Dec 1980."

  MORRY, W.R. General Atomic Co (subs of Gulf Oil Co.) B1/02/27

  2an 0.7906-058
- --Bi03120457 "Bemiannual Efficient Rept. Jul-Dec 1980." Tables 1-3 lis radiological gaseous & particulate efficient. Liquid efficient & nonradiological efficient data. » General Atoric Co (subs of Gulf Oil Co ). Bi/02/27 Spp. 07906 060
- G103120636 Discusses QA Co B00916 physical security plan & gayment of fee No more fees will be collected until review & approvals are completed.
  D1905-R M. License Fee Management Branch. B1/03/06 ip 07906-128.
- 8103270018 Notifies that GA Co case assigned to D Huff, effective 810316 PARTLOH. J. G. Material Control Licensing Branch. 81/03/16. 1p 08047:100.
- 8103200634 PNO-V-81-012 on 810317 region 5 was notified that license burial permit cancelled for one shipment of radwaste in nonconciliance w/regulations Licensee making radiation survey of shipment THOMAS.R.D. Region 5. San Francisco, Office of the Director. 01/02/17. 1p 07972 104
- 8103270839 Advises of change in policy re-tamper-safing of low enric U. Bingle individual way perform witnessing & certification of tamper-safing program for U enriched to less than 63 PARTLON J. 0 Material Control Licensing Branch 81/03/19 1p.
- COCHET 70-0754 VALLECTIOS NUCLEAR CENTER. GENERAL ELECTRIC CO
- 8103310728 Forwards revised request for route approval for shipment irradiated reactor fuel, originally submitted 801211 Each withheld (red amended Abonic Energy Act of 1934 & Energy Reorganization Act).
  KIRKLAND.M.M. General Electric Co. 80/12/19. 1p. 08058:128
- 8103090329 Forwards order re mod of License SNM-960, requiring preparation & submission of radiological contingency plan. CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety. 81/02/1p. 07847: 227.
- --Bi03090039 Order requiring mod of License BNM-960.Licenses must de & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within IBO days CUNNINGHAM.R E Division of Fuel Cycle & Material Befety Bi/02/11. 6pp 07847:228.
- BIO3181137 Forwards "Effluent Monitoring & Environ Surveillance Programs. Annual Summary, 1980. 'No differentiation can be made between liquid & gaseous effluents generated under License BNM-960 & CA byproduct license. CEST. R. E. - CUNNINGHAM. O. E. General Electric Co. 81/02/20. 1p
- --B1031B1142 "Effluent Monitoring & Environ Surveillance Programs, Am Surmary, 1980 " BROZ, R.E., MOHR, H.C., GEST, R.E. General Electric Co. 81/01/31, 7700.
- B103120786 Advises that NRC does not object to resumption of activit in Cell 3 that are in accordance w/License SNM-960.

  RDUBE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 81/02/26
  3pp. 07901:336.
- G103100269 Discusses procedure for fee determination. Upon completion of review of B10218 request for route approval, NRC will notify licensee refee due.

  WEIBB.D. License Fee Management Branch. B1/03/02. 1p. 07865:23

8103270839	Advises of change in policy re tamper-safing of low	enriched
	individual may perform witnessing & certification reading program for U enriched to less than 6%	
	J G. Material Control Licensing Branch - 81/03/19.	lρ

DOCKET 70-0820 UNITED NUCLEAR CORP.

13pp. 08062:129

- 8103270827 Forwards application for administrative amend to License SAM-777 re P Dessaules appointment as operations canager & mod for Waste packaging & nhipment procedures Fee encl SCHULTZ.D M United Nuclear Corp., UNC Recovery Systems Div 80/10/20. 2pp. 08045:112.
- --Bi03270B29 Application for administrative arend to License ShM-777 re
  P Desseules appointment as operations manager & mod for
  waste packaging & shipment procedures

  > United Nuclear Corp., UNC Recovery Bystems Div B0/10/20 3pp
  00045 114
- BiO3260099 Summarizes S0102B meeting w/State of RI,UNC & Zoino & Associates re groundwater contamination at site.

  Recommendation for Seep well near lagoons does not contain all necessary specs. State of RI S00923 itr encl.
- Recommendation for deep well near lappons does not contain all necessary specs State of RI 800923 ltr encl. HARNER: D.C. Don L. Harner: 80/10/31 &pp 08040 060
- 8103300026 Forwards partial revisions to Chapters 3 % 6 of fundamental nuclear mat1 control program for decormissioning Revisions withheld from public disclosure. L'HEUREUK, J. H. United Nuclear Corp., UNC Recovery Systems Div. 80/12/03 2pp. 08053:140
- 8103310BB2 Forwards GA Program GAP-004 for preparation & shipping of low specific activity radioactive matls for approval Review comments have been incorporated.

  L'HEUREUX. J. H. United Nuclear Corp., UNC Recovery Bystems Div. 80/12/12 p 00062 128.
- --Bi03310886 GA program for preparation & shipping of low specific activity radioactive matis.

   United Nuclear Corp.: UNC Recovery Systems Div 80/12/12.
- --Bi03310891 Returns theck which accompanied 801212 ltr for amend to License SNH-777. Ltr is add1 info to 801020 request for which fee has been gaid
  - fee has been paid. MEISB.D. License Fee Management Branch. 81/01/06 4pp 08062.142
- --8103310896 Quality procedure GP-5.411 re insp of radwaste packaging & shipping.

   United Nuclear Corp., UNC Recovery Systems Biv 80/10/31. 3pp 08062:146
- --B103310899 Btd operating procedure for packaging of decontamination waste.

  HAKEFIELD, J. United Nuclear Corp., UNG Recovery Systems Div BD/11/07. Spp. 08062:149.
- --8103310903 6td operating procedure for reinsp, rework & preparation of lagoon waste containers.

  OREGO.R. United Nuclear Corp., UNC Recovery Systems Div.
  BD/11/07. 7pp. 08062:194.
- --8103310909 Std operating procedure for preparation of radioactive matl burfal shipments.

  DERBAULES, P. United Nuclear Corp., UNC Recovery Systems Div 80/10/15. 3pp. 08062:161.
- B100040514 Forwards IE Insp Rept 70-0820/80-14 on B00818-19 & notice of violation.
  ORIER.B.H. Region 1. Philadelphia, Office of the Director.
  B1/01/14. 2pp 07810:300.
- --8103040524 Notice of violation from inap on 800818-19.

   Region 1, Philadelphia, Office of the Director. 81/01/23. 1p 07810:302.
- --8103040534 IE Insp Rept 70-0820/80-14 on 800818-17. Noncompliance noted: failure to discontinue receipt & processing of slightly irradiated U scrap after 760716. Exhibits concerning slight irradiation of U scrap encl.
- irradiation of U scrap and). KINNEY.H. H. Region I. Philadelphia. Office of the Director. CROCKER.H. M. Region I. Philadelphia. Bafeguards Branch. 80/12/23. 14pp. 07810.303.

- --Bi03040540 Requests info re whether identified scrap mati crossess to United Nuclear Corp Recovery Bys after 1976 was irradiated to wat period of time irradiation occurred GRIER, B.H. Region 1, Philadelphia, Office of the Director, B0/09/04 2pp 07810 317
- --Bi03040545 Requests info requested in entl B00904 ltr to 3M Erickson is forwarded to NRC as soon as possible re KAPL scrap sent to United Nuclear Corp Recovery Sys for processing after Jul 1976 CRIER, B. H. Region 1, Philadelphia, Office of the Director. B0/10/03 3pp 07810-319
- --Bi03040551 Furnishes info requested in 801003 & 0904 itrs re-sispably irradiated scrap fuel math shipped to United Nuclear Plant for recovery

  NARTAR J. Roprou. Dect. of 80/11/13 6pp 07810 322
- --BIO3040555 Forwards info re five Argonaut reactor fuel plates shapped to United Nuclear Corp in 1977

  DAAVEITILA D. A. Michigan Technological Univ. 80/12/16 13pg.
- 8103090011 Forwards list of 88 drums found acceptable during fil0115-16 insp for shipment to & buriel at Barnwell, 80. GRIER.B H. Region i, Philadelphia, Office of the Director. 81/01/16. 3pp 07892 192.
- 8103300285 Draft "Boil Decontamination Criteria for Decormissioning of United Nuclear Corp Resources Co Facility "
   NRC ~ No Detailed Affiliation Given 81/01/31 41pp
- 8103060517 Responds to B01229 comments on NRC draft "Proposed Goff Decontentination Criteria" for decommissioning facility. Proposed soil limit for open land cleanup at site represents target criteria consistent w/EPA stds
  BRUN-E. Y. Uranium Fuel Licensing Branch. 81/02/17 App 07839-359.
- 8103170020 FOIA request for repts re-possible radioactive pollution of cater or land surrounding United Nuclear Corp facility CASSIERE, J. Affiliation Unknown. 61/02/18 Ip
- Telsases for 800701-810101. HELOEEON, K. A. United Nuclear Corp. 81/02/24 tp. 07784 t01.

810302044B Forwards semiannual rept of liquid & airborne effluent

- --8103020455 Bemiannual rept of liquid & airborne effluent releases for 800701-810101. • United Nuclear Corp. 81/02/24 2pp. 97784 102
- 8103040316 Forwards liquid & airborne effluent releases for 800701-B10101 HELQESON.K.A. United Nuclear Corp., UNC Recovery Systems Div B1702/24 ip. 07809 318
- --810304032) Liquid & airborne effluent releases for 800701-810103 

   United Nuclear Corp., UNC Recovery Systems Div 81/02/24 

  29 07809 319
- 07809 319
  B103100524 Approves licensee 810203 request to submit single composite
- BiOGiO0524 Approves licensee BiO203 request to submit single composite sample to establish enrichment of SNM measured during i-month period in conjunction w/decommissioning program PARILOW.J. O. Material Control Licensing Branch. Bi/02/27 tp.
- PARTLOW.J. 0. Material Control Licensing Branch. Bi/02/27 lp. 07865.070.

  B103160220 Notifies that administrative emend fee is required or B1013

withdrawal of emergency plan. WISSS.D. License Fee Management Branch. 81/03/04. ip 07916 343

- 8103170014 Responds to FOIA request for repts re-possible radioactive polition of water or land surrounding United Nuclear Corp facility-Forwards documents listed in app FELTON.J.H. Division of Rules and Records. 81/03/09. 2pp
- --Bi03i70025 Expresses concern re-ongoing developments affecting operations & decomissioning of United Nuclear Corp U reprocessing facility Questions concerning (saue & NRC responses encl. 9ARRAHY.J. J. Rhode Island, State of. 80/06/23 8pp

07930.230.

--8103170034 Submits conclusions from review of info concerning effect of United Nuclear Corp U recovery plant on groundwater in plant vicinity includes RI Water Resources Board recommendations. Criteria for soil decontemination enci. WARNER, D. L. Affiliation Unknown. 77/11/29. App.

- --810317003B Notifies of issuance Amend 10 to License SAM-777.to include decommissioning plan 5 financial commitment PAGE.R 0 Uranium Fuel Licensing Branch 80/02/28 ip
- --8103170060 Explanation of visupraphs presented at B00709 meetings to United Nuclear Corp facility Cover page of rept entitled "Geohydrologic Data for Lower Wood River Groundwater Reservoir-Ri." encl
   N940 No Detailed Affiliation Given. 80/07/08 9no
- 8103270023 Notifies that License SNM-777 amended to delete Condition 12, re emergency plan per 105F870. FAGE.R.O. Urentum Fuel Licensing Brench 81/03/16. 10
- --Bi03270027 Revieus 810126 amend application to delete emergency plan.
  Recommends deletion of emergency preparedness requirements
  of Condition 12 of License SMM-777 Arrangements for handling
  possible fires or contaminated wounds to be maintained
  SIEVENSON R L . CROW. W T. Uranium Fuel Licensing Branch
  BI/02/16 2pm

# DOCKET 70-0824 BABCOCK & WILCOX CO.

- 8103270449 Advises that no add1 renewel fee required for rehewal of License SMM-778. Oft of Controller notified to refund partion of fee due to change in byproduct matl fee category. MILLER W. O License Fee Management Branch 80/10/29 1p 68034 139
- 8103090145 Forwards order re-mod of Licensa BNM-778, requiring preparation & submission of rediological contingency plan.
  CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 81/02/11 ip 0248 297.
- --B103090152 Order requiring mod of License BNM-778. Licensea must develop a submit redialogical contingency plan & application for license amend to incorporate plan as condition of license within 180 days CUNBINOMAM.R.E. Division of Fuel Cycle & Haterial Safety. B1/02/11. 6pp. 07848-278
- 8103270839 Advises of change in policy re temper-safing of low enriched U Single individual may perform witnessing & certification of temper-safing program for U enriched to less than 6%. PARTLOW. J. 9 Material Control Licensing Branch 81703/19 lp

#### DOCKET 70-0854 18010PIC ANALYSIS, INC.

- 8103090255 Forwards order re mod of License BNM-791, requiring preparation & submission of radiological contingency plan.
  CURNING(IAM.R.E. Division of Fuel Cycle & Material Bafety B1/02/11 8p. 07849.062.
- --Bi03090261 Order requiring mod of License BNM-791. Licenses must develop a submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 240 days.

  CUMPINGHAM.R.E Division of Fuel Cycle & Material Bafety BI/02/FI. App. 07849:063

#### DOCKET 70-0925 CIMARRON FACILITY

- 810331091B Responds to NRC telcon inquiry re expert fire safety review of coal liquification project Consultant evaluation of fire protection provisions & recommendations is complete Recommendations & vendor responses encl SHELLEYIN J Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp.). 80/12/23 3pp. 08038:138
- G103050224 Forwards IE Insp Repts 70-1193/G1-01 & 70-0925/G1-01 on B10126-29 & notice of violation.
  HIND, J A Region 3, Chicago, Bafequards Branch. 81/02/20. 2pp. 07825, 222
- --8103050229 Notice of violation from insp on B10126-29 HING. J. A. Region 3, Chicago, Safeguerds Branch. 81/02/19. 2pp. 07825-224.
- --8103050242 IE Insp Repts 70-0925/81-01 & 70-1193/81-01 on 810126-29. Moncompliance noted unauthorized possession of U w/ entithment greater than 3% \$ failure to use acceptable tapper safe seals Details withheld (ref 10CFR2.790). FINLEY. A.O. PATTERBON. J.P. Region 3. Chicago, Office of the Director. MIND. J.A. Region 3. Chicago, Bafeguards Branch. 81/02/19. 2pp. 07825:226.

- 8103090247 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216
  KEPPLER.J. O. Region 3. Chicago. Office of the Director 81/02/20
  20p 07882-059
- DOCKET 70-0971 DREGON STATE UNIV
- 8103230500 Forwards "Rept of Personnel Whole Body Exposures for CY80 MA'40.C.H Oregon State Univ 81/03/13 1p. 07975 287
- --8103230507 "Rept of Personnel Whole Body Exposures for CYBO "

  \* Oregon State Univ B1/03/13 1p 07975 289
- DOCKET 70-0984 PACIFIC NORTHHEBI LAB
- 8103180955 Forwards IE Insp Rept 70-0984/80-02 on 801218 No noncompliance noted.

  BODK.H. E. Region 5. San Francisco. Fuel Facility & Materials Safet Branch. 81/02/02 2pp. 07953-149
- --B1031B0773 IE Insp Rept 70-0984/80-02 on B3121B No noncompliance no Major areas inspected;organization, facility changes & mods, internal audit & review-raduasts mpt & inventory COULEY.N.J. Region 5, San Francisco. Office of the Director. THOMAS.R.D. BOUN.H E Region 5, Ban Francisco. Foel Facility & Materials Safety Branch. 81/02/02 4pp 07933 151
- G103020717 Forwards order re and of License SNM-942.requiring preparation & submission of radiological contingency plan CURNINGHAM.R E Division of Fuel Cycle & Material Safety. B1/02/1: ip. 07782-025.
- --Bi03020719 Order requiring mod of License BNM-942 Licenses must deve & submit radiglogical contingency plan & application for license amend to incorporate plan as condition of license within 180 days CUNNIN9HAM.R E. Division of Fuel Cycle & Material Bafaty 81/02/11. App. 07782:026

#### DOCKET 70-0992 DAVID WITHEREPOON, INC.

- 8103100357 Ack receipt of 810109 ltr informing NRC of steps taken to correct violations noted in 1E insp Rept 70-0992/80-01 Evaluation of response to Item 9 continuing. 91860N.A F Region 2. Atlanta. Office of the Director 81/02/25 pp. 07865 034
- --8103100363 Responds to NRC 810910 ltr re-violations noted in 18 [nsp. Rept 70--0992/80--01. Corrective actions notices posted caution sign posted on gate & gate repaired
  MITHERSPOND David Mitherspoon, Inc. 81/01/09. 1p 07865-035.
- --BIO3190367 Biscusses IE Insp Rept 70-0992/80-01 on 800523 & 0806 & forwards natice of violation.
  BTO:MR.J.P. Region 2, Atlants, Fuel Facility & Materials Safety Branch. B0/09/10 2pp. 07865:036.
- --BiO3100373 Notice of violation from insp on B00523 & 0806 Noncomplia noted:licensed 8MM held at unauthorized location & certificate specifying max quantity U-235 received in two shipments not available. • Region 2. Atjanta, Office of the Director. 80/09/10 2pp. 07865:038.

#### DOCKET 70-1100 COMBUSTION ENGINEERING, INC.

- B103310690 Application for amend to License SNM-1067 to reflect recent organization changes Proposed revisions to license pages encl
  PIANNIF. J. C-E Power Systems 80/11/14, 1800, 08038-186
- B103300017 Describes plans for item control of fuel rods during Dec 1980 physical inventory. Every rod in randomly selected trays will be identified & cross-checked against appropriate tray listing. PIANKI.F. J. C-E Power Systems. 80/11/21. 2pp. 08053:136
- B103310684 Application for amend to License SNM-1067 to authorize possession.use, storage & transfer of fission chambers designed to detect thermal neutrons.

  LICHTENBERGER C-E Power Bystems. B0/12/29. Ip 08058-174.

- 8103200377 Forwards IE Insp Rept 70-1100/80-10 on 801216-19 & 29-31 No noncompliance noted MARTIN.H 0 Region 1. Philadelphia. Safaguards Branch 81/01/30 2pp. 07766 334
- --Bi03200389 IE Insp Rept 70-1100/80-10 on B01216-19 \$ 29-31 No noncompliance nated Major areas inspected measurement controls.internal controls & physical inventory Rept withheld (ref 10CFR2 790) CDHEN.I DELLARATTA.A IBULBAY.H Region I. Philadelphia. Office of the Director B1/01/23 ip 07966-336.
- 8103090109 Forwards orders to mad of Licenses SNH-33 & SNM-1067, requiring preparation & submission of radiological contingency plans
  CURNINGHAN.R E. Division of Fuel Cycle & Material Safety. 81/02/11.
  1p. 07849 167
- --9103090128 Order requiring mod of License SNM-1067 Licensee must develop & submit radiological contingency plan & application for license mand to incorporate plan as condition of license within 180 days

  CURRINOMAN R E Division of Fuel Equie & Material Safety
  B1/02/11. App. 07849-174
- 8103060155 Requests fee payment for B10202 request for amend to safeguards Amend MPP-4 of License BNM-1067. MRISS.D License Fee Menagement Branch. 81/02/18 ip 07639.031.
- 8103120774 Trip rept of 810207-12 visit to C-E Windson,CT facility to review licensed activities & perticipate in IE insp. KETZLACH.N. Urenium Fuel Licensing Branch 81/02/26 3pp. 07901-345
- 8103110039 Trip rept re 910217-19 site visit re renewal of License BNH-770. Comments scheduled for submittal by 810309. Facility response expected by 810410. KETZLACH. N. SODNO, A L. Urenium Fuel Licensing Branch. B1/03/04 ip. 07889.004
- B103170464 Provides rept of personnel whole body exposures for CY80 LICHTENBERGER C-E Power Bystems. 81/03/12 19 07934: 343

#### DOCKET 70-1113 GENERAL ELECTRIC CO

- 9103050235 Ack receipt of IE Insp Rept 70-1113/80-20 on 801117. No proprietary info. KAPLAN. A L. General Electric Co., Nuclear Energy Products Div 81/02/10 ip. 07825-229
- --Bi03050244 Forwards IE Insp Regt 70-1113/80-20 on 801117.No noncompliance noted. STOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 81/02/05 2pp 0/825: 230.
- --8103050255 IE Insp Rept 70-1113/80-20 on 801117 No noncompliance noted. Major areas inspected ground.ater environ monitoring WODDRUFF.R. L., QIBSDN.A.F. Region 2. Atlanta, Office of the Director. 81/02/05 3pp 07828 232.
- B103090199 Forwards order re mod of License SNN-1097 requiring preparation & submission of radiological contingency plan. CUMNINOHAM.R.E. Division of Fuel Cycle & Material Safety 81/02/11. 1p. 07848:345
- B1030902B3 Amend 17 to License SNM-1097, replacing Section 4 4 of Page A-19 of App A w/revised description of activities of Hilampton Tachnological Sefety Council.

  PA9E.R. 9. Uranium Fuel Licensing Branch. B1/02/18. IP. 07852-063.
- B103100254 Forwards "Bemiannual Effluent Rept, Jul-Dec 1980." KAPLAN.A L. General Electric Co., Nuclear Energy Products Biv. B1/02/19. 1p. 07865:231.

- 8103240714 Forwards IE Insp Rept 70-1113/81-02 on 810224-27 No noncompliance noted LEWIS.R C. Region 2. Atlanta. Office of the Director 81/03/11 2pc. 07983 255
- --8103240724 IE Insp Rept 70-1113/B1-02 on B10224-27 No noncompliance noted Major areas inspected organization operations nuclear criticality safety & facility changes & mode CDYELL Q.P., KELLOGO.P. Region Q. Atlanta, Office of the Director 81/03/11. App. 07983-257
- 8103300050 Ack receipt of IE Insp Rept 70-1113/01~02 on 010224-27 ho proprietary info KAPLAN: A L. General Electric Co.: Nuclear Energy Products Div 81/03/17. 1p. 08093-045
- B103270839 Advises of change in policy re tamper-safing of low enriche U Single individual may perform witnessing & certification of tamper-safing program for U enriched to less than 6% PARTLOW-U. 0. Material Control Licensing Branch B1/03/19 ip

#### DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP.

- Bio3310761 Requests authorization to deviate for current inventory from two calender month requirement Delay requested due to annual two-uk plant shutdown Authorization uill not affect SNM safeguards
  DIP1AZZA-R P. Hestinghouse Electric Corp. 80/12/08. 1p
  08062-278
- 81030900B1 Forwards order re-mod of License SNM-1120, requiring preparation & submission of radiological contingency plan CUNNINOHAM, R.E. Division of Fuel Cycle & Material Bafety 81/02/51 ip. 07849:146.
- ---B103090086 Order requiring mod of License BNM-1120 Licenses rost develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days.

  CUNNINGHAM.R.E Division of Fuel Cycle & Material Bafety B1/02/11. Ann 07849 147.

#### DOCKET 70-1144 DHMART CORP.

- 8103100672 Discusses IE insp of Licenses 34-00639-01.34-00639-039 t SNM-1091 on Bi0121-22 & forwards notice of violation FISHER-W.L. Repion 3. Chicago. Fuel Facility & Materials Safety Branch. B1/02/22 2pp 07862.39
- --8103100676 Notice of violation from insp on B10121-22.Noncompliance noted no records of checks or celibr available for Victoreen Model 440 survey neter.
  FIBHER.W. L. Region 3. Chicago. Fuel Facility & Materials Rafety Branch. 81/02/22 ip 07862:139

# DOCKET 70-1151 WEBTINGHOUSE ELECTRIC CORP

- 8603090303 Forwards orders re mod of Licenses SNN-770 & SNN-1107, requiring preparation & submission of radiological contingency plans
  CUNNINGHAM, R. E. Division of Fuel Cycle & Material Bafety. 01/02/1
  1p. 07894:333
- --Bi03090323 Order requiring mod of License BMM-1107. Licenses must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days.

  CUNNINGHAM. R. Division of Fuel Cycle & Material Safety B1/02/11 App. 07846:360.
- 8103040495 Forwards IE Insp Rept 70-1131/81-01 on B10112-13 Na noncompliance noted. KENNA-W.B. Region 2: Atlanta: Bafeguards Branch. B1/02/12 1p 07813: 355.
- --8103040502 IE Insp Rept 70-1151/81-01 on 810112-13 No noncompliance noted. Major areas inspected: #undamental nuclear mati control plan. Details withheld (ref 100FR2.790).
  TODD-9.4. JONES, D. H. Region 2. Atlanta, Office of the Director.

- --8103060262 Forwards IE Insp Rept 70-1151/80-29 on 801114 No noncompliance noted STGHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 81/02/06 ip 07839:318
- --Bi03060270 IE insp Rept 70-1151/80-29 on B01114 No noncompliance noted Major areas inspected groundwater environ monitoring. MODDRUFF, L., HILLBAP, W.J. Region 2, Atlanta, Office of the Director. 01850N.A.F. Region 2, Atlanta, Fuel Facility & Naturials Bafety Branch. B1/02/06 3pp 07039 319.
- 8103180670 Forwards Amend MPP-1 to License 8NM-1107, incorporating new consolidated plan for nuclear met1 control & accounting & requested 100FR70 exemptions Attachments to util 800501, 1001, 31 & 810128 ltrs to be withhald (ref 100FR2 790). BURNETT, R F Division of Bafeguards 81/03/09 lp. 07949:262
- --BIO3189675 Amend MPP-1 to License SNM-1107 incorporating new consolidated plan for nuclear mail control & accounting & requested IOCFR70 exemptions

   Division of Safeguards. BI/03/09. 4pp 07949:263
- 8103240118 Safety evaluation supporting amend to License BNM-1107 authorizing installation of new dry conversion line to replace existing dry conversion fluidized bed Proposed action would have insignificant environ impact SHUHLE Y Uranium Recovery Licensing Branch. 81/03/09. 4pp 07989 262
- GLCC270B39 Advises of change in policy re tamper-safing of low enriched U Bingle individual way perform witnessing & certification of tarper-safing program for U enriched to less than 6% PARILOW. J 0 Material Control Licensing Branch B1/03/19 ip.
- BiO3270173 Requests amend to License BNM-1107, modifying License Condition 3 4(c) by changing phrase "at his plant lab" to "or his designated agent."
  DIPIAZZA,R. Westinghouse Electric Corp. 81/03/26. ip. 08044.242
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.
- g103090234 Forwards orders re-mod of Licenses SUB-1010 & GNM-1174, requiring preparation & submission of radiological contingency plans. CUNNINDHAM.R.E. Division of Fuel Cycle & Haterial Bafaty. 81/02/11. 1p. 07847-043.
- --8103090251 Order requiring mod of License 6NM-1174 Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days.

  CLNNSNOHAM R E Division of Fuel Cycle & Material Befety.

  BL/02/11. 6pp. 07849-056.
- 8103050224 Forwards IE Insp Repts 70-1193/81-01 & 70-0925/81-01 on 810126-29 & notice of violation. HIND.J.A. Region 3, Chicago, Bafeguards Branch. 81/02/20. 2pp. 07825:222
- --9193050229 Notice of violation from insp on 810126-29. HIND J.A. Region 3, Chicago, Bafeguards Branch. B1/02/19. 2pp. 07825-224.
- --8103050242 16 Insp Repts 70-0925/81-01 & 70-1193/81-01 on 810126-29. Noncompliance noted unauthorized possession of U w/ sprichment greater than 3% & fatture to use acceptable tapper safe seals Details withheld (ref 10CFR2.790). FINLEY.A.9., PATTERBON.J.P. Region 3, Chicago, Office of the Director. HIND.J.A. Region 3, Chicago, Befeguards Branch. 81/02/19. 2pp. 07825:226.
- 8103090247 Foruards organizational charts depicting NRC Region 3 reorganization effective 810216. KEPPLER.J. G. Region 3. Chicago, Office of the Director. 81/02/20. 2pp 07852:050.
- DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO.
- Bi03090069 Forwards order to mod of License BNM-1168, requiring preparation 6 submission of radiological contingency plan. CUNNINIGHAM, R. E. Division of Fuel Cycle & Material Bafety. Bi/02/Li. 15. 07849:199.

- CONNINGHAM.R E Division of Foul Cycle & Material Bafety. BJ/02/11 6pp. 07849; 140.
- B103260464 Forwards IE Insp Rept 70-1201/80-12 on B01112 No noncompliance nated BTOHR J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. B1/02/20 1p 08040 351.
- --Bi03260473 IE Insp Rept 70-1201/80-12 on 801112 No noncomplience no Major areas inspected groundwater environ monitoring WDDDRUFF, R.L., MILLSAP, W.J. Region 2, Atlanta, Diffice of the Director GISSDN.A.F. Region 2, Atlanta, Fuel Facility & Materials Befety Branch, G1/02/19 Jpp 08040:352
- 8103170122 Application for renewal of License SNM-1168 authorizing us of low enriched U crids low enriched U depleted or natural U daide byproduct rati & Pu & Cf as sealed sources.

   Babcock & Milcox Co 81/02/27. 600pp. 07924 088.
- 8103100189 Confirms add1 fees required for 810227 requests for amend renewal of License SN1-1168
  WEISB.D License Fee Management Branch 81/03/02 ip 07853:191
- 6103270839 Advises of change in policy re tamper-safing of low enrich U Single individual may perform witnessing & certification of tamper-safing program for U enriched to less then 6% PARTLO-LJ. 9 Material Control Licensing Branch 81/03/19. Ip

# DOCKET 70-1207 NAVY, BEPT. OF

- 8103270623 Forwards revised application for renewel of License BNH-1147 VOOT. J.F. Navy, Dept of. 79/10/30 1p. 08044:039.
- --BI03270633 Forwards revised application for renewal of License BNN-1147 BTARR.R.L. Navy.Dept of 79/05/23 ip 08044:040.
- --8103270644 Revised application for renewal of License BNM-1147.

   Navy Dept of. 79705/23. 46pp. 08044-041
- --8193270647 Addendum 1 to radiological safety manual. • Navy-Dept. of: 79/05/23 34pp. 08044:082.
- DOCKET 70-1220 GENERAL ELECTRIC CO.
- B103090142 Forwards organizational charts depicting NAC Region 3 reorganization, effective 810216. KEPPLER. J. G. Region 3. Chicago: Office of the Director. 81/02/20 200 07850.087.
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO. . INC.
- 8103230199 Forwards 1E losp Rept 70-1257/80-11 on 801219-17.No noncompliance noted. 800K.H E. Region 5. Ban Francisco. Fuel Facility & Materials Safet Branch. B1/01/21. 2pp. 07977:192.
- --B10323016B IE Insp Rept 70-1257/80-11 on 801215-17. No noncompliance noted Major areas inspected organisation facility changes & mode, internal review & audit, safety committee activities, ogrations review & criticality safety.

  COOLEY, M. J. Region 5, San Francisco. Office of the Director. THOMAS, R. D., BOOK, H. E. Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch. B1/01/20 App. 07977: 194
- Bi03030393 Discusses IE Insp Rept 70-1257/80-01 conducted on Bi0112-1 No noncompliance noted. Major eress inspected: activities reprogram for control & accounting of SNM Insp rept withheld (ref 10CFR2, 790). NORDERHAUGLE Region 5, Sen Francisco, Safeguards Stanch. 81/01/28 2pp. 07808:228.
- 8103090220 Submits rept of radioactive meth releases Jul-Dec 1980. Supporting info ench HANSEN.L.E. Exten Nuclear Co., Inc. (subs. of Exten Corp.), 81/02/04. Spp. 07850:347

- --8103090094 Order requiring nod of License SNH-1227 Licensee must develop & submit radiological contingency plan & application for license amend to incorporate plan as condition of license within 180 days

  CUNNINGHAM.R.E Division of Fuel Cycle & Haterial Safety
  B1/62/11 & bo 07849 154.
- 8103060194 Notifies of refund of overpayment refee for Amend 2 to License BNM-1227. MILLER.W D. License Fee Management Branch 81/02/19 15 02839-114
- 8103181094 Responds to 801103.810106 & D206 ltrs re laundry for contaminated clothing Proposed procedures are in accordance w/good industrial practice & may be implemented immediately Encis to licenses itra will be withheld (ref. 10CFR2 7901 PARTLON-J & Material Control Licensing Branch. 81/03/10 Lp 07994-136
- Bi03270839 Advises of change in policy re tamper-safing of low enriched U Single Individual may perform witnessing & certification of tamper-safing program for U enriched to less than 6% PARTLOH-J. 9. Material Control Licensing Branch. 81/03/19 ip.

#### DOCKET 70-1271 BANDWICH COMMUNITY UNIT BCHOOLS

- B103050870 Forwards Bandwich High Bichool application for renewal of Licente 8NH-1223 MEIBB.D License Fee Management Branch. 80/12/19 19 07825 164
- --Bi03050875 Application for ranewal of License BMM-1223, authorizing possession of Pu-beryllium source under supervision of ULISTRIP, until buyer is found for matl 11712NO.C., DUNLOP.T. Benduich (L. 80/11/22, 2pp. 07825:165
- DOCKET 70-1277 AGRICULTURE, DEPT. OF, AGRIC RESEARCH SERVICE
- B103060006 Act receipt of 810109 ltr re corrective & preventive attions taken in response to IE Inep Rept 70-1277/80-02 on 801021-22 KINNEMAN.J.D. Region 1- Philadelphia. Fuel Facility & Materials Safety Branch 81/01/29
- ~~8103060011 Responds to NRC 801216 ltm re violation noted in IE Insp. Rept 70-1277/80-02 on 801021-22 Corrective action: requested OL mod permitting use of sources at all licensee facilities & authorized rivers BERTRAND, A. R. Agriculture, Dept. of. 81/01/09, ip. 07837; D44
- --8103060017 Forwards notice of violation identified in IE Insp Rept 70-1277/80-02 on B01021-22 Noncompliance noted licensed matl stored in Durant, DK Site is not authorized for use. KINNEMAN.J.D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/12/05 2pp. 07837.045
- --B103060021 Notice of violation from ineg on 801021-22 Noncompliance noted: ifcensed metl stored in Durant, DK. Bite is not authorized for use.

  \* Region 1. Philadelphia. Office of the Director. 80/12/05. ig 07837:047.

#### DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

- B103270771 Requests confirmation of licenses intention to pursue application for renswal of License BNM-1265 if renswing application. requests identification of sections of CSAR that satisfy requirements of new regulation. W/svc list. ROUSE-L. C. Advanced fuel & Bpent Fuel Licensing Branch. 80/11/12. 3pp. 08034:049.
- B103250178 Notification of B01120 meeting u/vendor in Silver Spring.MD to discuss 10CFR72 requirements & affects on GE application for renewal of license for Morris operation.

  CLARK.A.T. Advanced Fuel & Spent Fuel Licensing Brench. 80/11/13. 1p. 07976:043

- Bi03090142 Forwards organizational charts depicting NRC Region 3 reorganization.effective Bi0216. KEPPLER, J. G. Region 3. Chicago, Office of the Director Bi/02/20 209 07830 087
- 8103050596 Request for leave for addl discovery per ASLB 801208 orter Discovery should be allowed on issues raised by modified ar addl contentions & on original contentions in light of ICCFR72 Certificate of Syc enc! VAN VRANKEN.J Illinois. State of. 81/02/25 4pp 07829 100
- 8103050604 Add1 contentions submitted per ASLO 801209 order addressing issues re-financial errangements for decontamination & decontassioning & identification & evaluation of external non-induced events affecting design M/Certificate of 6vc VAN VRANKEN.J Illinois. State of 81/02/25 5pp 07827 [13]
- B)03130574 Confirms B10224 telcon request for add) 4 days.until D10302 to file add contentions Svc list encl ROREM.B L Affiliation Unknown. 81/02/25. 3pp 07913 035
- 8103110107 Advises of Amend B to License BNM-1269, adopting NEDD-21026C as ref SAR.per 800123 request Item (b). Incorporating provisions for facility changes, tests & experiments, withdrawn on B01114 ROUBELLC. Advanced Fuel & Spent Fuel Licensing Branch D1/02/2/2pp 07884, 317
- B103130981 Add1 contentions A.B.C & D re environ impact of spent fuel transportation.decontamination & decommissioning procedures & effect of man-induced events. Bvc list encl.

  ROREM.B L Affiliation Unknown. 81/03/01. 4pp. 07913 i&i
- 8103110316 Position re add1 State of IL contentions Contention 4 should be admitted & Contentions 1.2.3 & 5 denied. Contention 4 reets legal requirements for admittance Certificate of svc enci.

  ROTHECHILD. H. U. Apprations & Administrative Division 81/03/07 12pp 07862 169
- 8103120305 Confirms 810309 telcon re 810313 extension granted for MRC to respond to additionations of intervenor Rorem, at al MRC will attempt to file responses prior to 810313 ROTHSCHILD.H U. Operations & Administrative Division. 81/03/10 pp. 07901: 262.
- 8103190409 Response in apposition to intervenor Rorem proposed aedi & previously filed contentions Proposed contentions fail to meet 1005FR2 714(48). Previously filed contentions should be stricken per 1005FR2 H/Certificate of Svc.
  RODNEY.M.A. General Electric Co. RODNEY.M.A. Mayer, Brown & Platt 81/03/10. 7pp. 07965: 194.
- 8103200015 Response to State of IL add1 proposed & originally admitted contentions. Proposed Contentions 1-5 should be stricten for lack of specificity & failure to set forth adequate basis Certificate of Svc enci.

  RDDNEY.M.A. General Electric Co. ROONEY.M.A. Mayer, Brown 4 Plett 81/03/10. 7pp 07969:076
- 8103200020 Response opposing State of IL 810225 motion for addl discovery. Motion is moot Any blanket request for addl discovery should be denied, Proposed addl contentions of IL have no basis in fact or law. Certificate of Svc encl ROUNEY.M A. General Electric Co. ROONEY.M. A. Mayer, Brown & Plats 81/03/10. 3pp. 07969:087.
- B103200025 Renewed request for order dismissing intervenors Rorem et al from proceeding due to feilure to comply W/ASLB order compalling discovery Certificate of Bvc enci RODARY.M.A. General Electric Co., RODARY.M.A. Hayer, Brown & Plett 81/03/10. 2pp. 07972:298.
- 8103200037 Renewed request for order imposing sanctions against State of IL for continuing failure to comply w/ASLB order compelling further discovery.

  RODNEY.M.A. General Electric Co. RODNEY.M.A Mayer, Brown & Platt 81/03/10. 2pp. 07949:107.
- Bio3i203i7 Statement of position opposing admission of intervenor Pored add1 contentions. Contentions do not mast legal requirements, are vegus, lect adequate basis & fail to elect parties to issues to be litigated. Certificate of Bur encl.

  ROTHECHILD.N. U. Operations & Administrative Division. 81/03/11
  11pp. 07901:265.

8103190623 Order admitting State of IL addl Contentions 1.3,4 & 5
Rejects State of IL Contention 2 & all intervenor Rosem
addl contentions
ORDERFORM A Contention Section Report Page 1 - 81/03/1

GOOCHOPE, A. C. Atomic Safety and Licensing Board Panel. BI/03/16 200 07959:233

- 9103180644 Forwards ASLB 810219 order ruling on motion to emend, per request R/d encl.
  ROTHECHILD.M U. Operations & Administrative Division 81/03/17
  La 07947 280
- Bio3230090 Interrogatories & request for production of documents irected to intervenor Rosen.et al. Interrogatories discuss Contentions A-O re witnesses.proposed testimony & publications to be relief upon. ROTHSCHLD, H. U. Operations & Administrative Division. 81/03/19 4pp 07980-310
- --Bi03230095 Interragatories & request for production of documents directed to intervenor State of IL Interrogatories discuss Contentions 1-5 re witnesses to be celled proposed testimony & publications to be relied upon.

  ROTHSCHILD, M U Operations & Administrative Division 81/03/19
  4pp. 07980-314
- --BI03230079 Renews & reasserts B00B14 motion that intervenur Rorem.st all to ordered to respond fully & accurately to NRC interrogatorias & request for production of documents Rorem.st all has filed no answers in response to ASLB B00909 order. RGTHSCHILD, M. U. Derations & Administrative Division. B1/03/19 2pp 97980:318
- --8103230119 Renews & asserts 800819 motion that State of IL be ordered to respond fully & accurately to NRC interrogatories & request for production of documents. IL has filed no ensuers in response to ASLB 800909 order 90THSCHILD.H.U. Operations & Administrative Division 81/03/19 339 07983:329
- B103300240 Informs that NRC will not respond further to applicant 810310 rotions for sanctions against State of IL & Rorem et al ROTHSCHILD.M U. Operations & Administrative Division. B1/03/27, 1p 08057 142.
- 8103180634 Answer to intervenor State of IL 810225 motion for leave for add1 discovery. Request for leave to file add1 discovery on previously admitted contentions & add1 time to file should be denied No objection to schedule. W/Certificate of Svc. ROTHSCHILD, RU Operations & Administrative Division. 81/03/17. 7pp 07953:163
- DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 8103090142 Forwards organizational charts depicting NRC Region 3 rangemization, effective 810216. KEPPLER.J G. Region 3, Chicago, Office of the Director. 81/02/20. 292 07850.087.
- DOCKET 70-1374 IDAHO BYATE UNIV.
- Bi03160436 Forwards request for add1 info re renewal of License 8M4-1373 BTEVENSON.R.L. Uranium Fuel Licensing Branch. 61/03/03 2pp. 07916:198.
- EGGRET 70-1388 MT. CARMEL MERCY HOSP. & MEDICAL CTR. DETROIT.MI
- 8103300366 IE Insp Findings & Licensee Ack dtd 810312 of Licenses 21-00998-01 & 8NM-1374. Insp findings: failure to maintain records of disposal. 6UR0IN.R.E. Region 3. Chicago, Office of the Director. 81/03/12. 19. 08038:014.
- SOCKET 70-1402 ABINGTON MEMORIAL HOSP. ABINGTON, PA
- 8100050716 Ack receipt of B10113 itr informing NRC of steps taken to correct violations noted in tE insp Repts 70-1402/80-01. 30-00453/80-01. Region 1. 30-00453/80-01. Final Facility & Materials Safety Brench. 81/01/29. 1p. 07828:049.

- --BIO3050728 Responds to NRC 801218 ltr re-violations noted in IE Insp. Repts 70-1402/80-01.30-00453/80-01 & 30-02948/80-01 Carrective actions.visual sign installed inside Co-60 room & corner room selected for Cs-137 source therapy BRECHBIEL.R. C. Abington Memorial Hosp Abington.PA 81/01/13 4pp 07828-0390.
- --8103059737 Discusses IE Insp Repts 70~1402/80-01.30-00453/80-01 & 30-02948/80-01 on 801010 & forwards notice of violation KINNEMAN, J D Region 1. Philadelphia, Fuel Facility & Materials 8afety Branch 80/12/18 2pp. 07828 034
- --Bi03050747 Notice of violation from insp on 801010. Noncompliance note failure to take survey of rediation herards in rooms adjacent to room of patient w/radiosctive implant • Region 1. Philadelphia. Office of the Director 80/12/18 2pp. 07828 096
- DOCKET 70-1407 BT LUKE'S HOSP DAVENPORT, TA
- B10302021B IE losp Findings & Licensee Ack dtd B10204 of License SNM-1445 Insp findings no nancompliance noted. BIAITERLY, L. W. Region J. Chicago, Office of the Director. B1/02/04. ip 07785.311
- DOCKET 70-1416 INCARNATE HORD HOSP. BT LOUIS HO
- B103170686 IE insp Findings & Licenses Act 6td 810223 of License SNM-1428 Insp findings no noncompliance noted BURGERR E Region 3. Chicago, Office of the Director. 81/02/23. ip 07939-015
- DOCKET 70-1426 TRANSNUCLEAR, INC.
- 8103270610 Forwards Revision 11 to security plan for chipments of SNM. Encl withheld.

  ANAQUAL J Transnuclear Inc. 80/10/15 2pp. 08044:037.
- DOCKET 70-1441 EASTON HOSP EASTON, PA
- B103100224 Discusses IE insp of Licenses 37-0993B-01 & SNM-1400 on B10112 No noncompliance noted. Major areas inspected. radiation safety.compliance utregulations & Hoense conditions & corrective action to 770522 honcompliance. KINNEMAN. J. D. Region I. Philadelphia, Fuel Facility & Materials Safety Branch B1/02/09. 2pp. 07667:123
- DOCKET 70-1300 WASHINGTON HOSP CENTER WASH DC
- B103190508 Rept of parsonnel whole body exposures for 1980 HILLIAMS.K.D. Washington Hosp. Center Washington.DC. 81/03/18 1p. 07956-070
- DOCKET 70-1421 CONOVER & ASSOCIATES, INC.
- 810316076B Forwards Endorsements 5 to NELIA Binder EB-58 & MAELU Binder X8-58. BARNETT, J.E. Comover & Associates, Inc. Insurance. 81/03/11. 3pp. 07918.306.
- DCICKET 70-1703 EASTMAN KODAK CO.
- 8103310680 Requests license reinstatement for 6-month period effective 810116 Revised application will be submitted within 1 month. HARTER, E. B. Gestman Kodek Co. 81/01/16. 1p. 08058:175.
- BIO3I3D026 Ack receipt of BIO122 ltr informing NRC of steps taken to correct violations noted in IE Imag Rept 70-1703/BI-01.
  GRIER.B.H. Region I. Philadelphia. Office of the Director.
  BI/02/02 1p. 07914:007.
- --BIO3130034 Responds to NRC BIO120 ltr re-violations noted in IE Insp Rept 70-1703/BI-01. Corrective actions: application submitted to NRC for siz-month temporary SNM license to cover lapsed License BNM-1513. Application enci. VANAS.D.W. Eastman Kodak Co. 81/01/22. 2pp. 07914:008.

- --BIO3130115 Subm to notice of violation from insp of License SNM-1513 on BIO116 Noncompliance noted possession of SNM w/o valid. specific license GRIER.B. H. Region I. Philadelphia. Office of the Director B1/01/20. 2pp 07914 O11

  BIO3160306 Requests remittence of fee. H/o encl NRC 801229 ltr requesting payment & company purchase order HEISS.D. License Fee Management Branch 81/03/11 lp. 07917 196

  BOCKET 70-1739 TRI-BTATE MOTOR TRANSIT CO
- B103170670 Responds to B01212 request for data in support of manhours expended in review of B00530 request for amend to transportation security plan Invoice will be revised, charging only 4 manhours to amend review MILLER.W.O. License Fee Management Branch. Bi/03/04 ip 07930:147.
- DECKET 70-1997 ARMY, DEPT. DE
- 8103100705 IE Insp Findings & Licensee Act dtd 801201 of License BNM-1584 Insp findings no noncompliance noted BROWN, R A Region 2. Atlanta. Office of the Director 80/12/01 to 07892-193
- DOCKET 70-2240 ST. FRANCIS HOSP. BLUE ISLAND. IL
- 8103130293 IE Insp Findings & Licensee Ack dtd 810224 of Licenses 12-10094-01 & BNH-1627 Insp findings:no noncompliance noted. • Region 3. Chicago. Office of the Director. 81/02/24 ip
- DOCKET 70-2313 NUCLEAR FUEL SERVICES
- 8103110460 Monthly rept for Feb 1981 re mat1 discards & inventory discrepancy under License SAM-1648 BURN-P. Nuclear Fuel Services. Inc (subs of Oebty Dil Co.) 81703709. 1p. 07882.159,
- DOCKET 70-2317 TELEDYNE CAST PRODUCTS
- 8103120048 Forwards monitoring survey rept conducted at Teledyne Cast Producte per IS Nov 1975 guidelines for decontamination. EON Corp Portable Burvey Meter PSM-700 used: No readings above background found. BOSBING, E. N. Teledyne Cast Products. 81/02/24, 2pp. 07900: 172.
- B1031B0333 Forwards IE Close-out Befety Insp Rept 70-2317/80-01 on 801216. No noncompliante noted BODK. H. E. Region 5. San Francisco. Office of the Director. B1/03/10. 1p. 07944.255.
- --B1031B0345 JE Close-out Safety Inep Rept 70-2317/80-01 on B01216 No Rancarpliance nated Major ereas inspected physical radiation survey & contamination checks made in storage, handling & melting pot areas
  THOMAS.R.D., B00K.H E. Region 5. Ban Francisco, Office of the Director. B1/03/09. 3pp. 07944:256.
- DOCKET 70-2623 MCGUIRE SPENT FUEL PODL, DUKE POHER CO.
- 8103020595 Order setting 810422 oral argument on appeals of util & NRC from ASLB 801031 initial decision. Each side allowed 90 minutes. Parties to notify ASLB secretary by 810413 which person will present argument.
  818H0Pr.C.J. Atomic Befety and Licensing Board Panel. 81/02/25.
  20p. 07782:096
- BIO3040396 Forwards BIO225 notice of finality of Commission action w/regard to generic FES on handling & storage of spent light water power reactor fuel (NUREG-0575).

  BOHINKI.S.M. Hearing Branch 3. 81/03/02. lp. 07820.160.
- 8103200537 Informs that ER Weiss will represent NROC in 810422 argument. Certificate of Svc encl. MEISS. E.R. Harmon & Weiss. 81/03/10. 3pp. 07971.312.
- 8103270640 Requests current DOE position re util application for permission to store spent fuel from Oconee in McGuire spent fuel pool. Transcript pages from Bateman 790913 testimony encl for review.W/o encl. CHRISTENBURY.E. Hearings Division. 81/03/26, 2pp. 08043:246.

- DOCKET 70-2707 INSHAM MEDICAL CENTER LANSING. HI
- B103270617 Discusses IE insp of Licenses GNM-177 & : B10224 & forwards notice of violation GRENIAURGI, D. J. Region 3, Chicago, Fuel Facility Branch. B1/03/16 1p 65165 216
- --Bi03270629 Notice of violation from insp on Bi022 Cs-137 calibr source not leak tested since 7611; Ilnewrity calibr test not performed since B0080; BRENIANBKI.D J. Region J. Chicago, Fuel Facili Safety Branch. B1/03/16
- DOCKET 70-2749 GENERAL ELECTRIC CO.
- 8103020366 Submits application to amend export lice intermediate consignee Fabbricazoni Nucleari BPA: description of natl & deleting one g U-235 as detinstrucents. WILBON.B D General Electric Co. 81/02/06 ip
- DUCKET 70-2838 CINCINNATI OAS & ELECTRIC CO.
- 8103030101 Forwards IE Insp Rept 70~2838/81-01 on 8 noncompliance noted HIND, J A Region 3. Chicago, Bafeguards Branch 07791:047.
- --Bi0303011B IE Insp Rept 70-283B/81-01 on 810122-23 noted Major areas inspected security plans securiorganization.physical barriers & access control withheld (ref 100FR2 790) MADEDA.T J. PITILE.O.L., BRAUND, C. Region 3, (the Director. B1/02/04. 1p. 07791:069
- DOCKET 70-2082 SOUTHERN CALIFORNIA EDISON CD
- 8103270227 Forwards Amend 2 to 780725 license applio DIETCH:R Bouthern California Edison Co. 80/10/2
- --8109270298 Amend 2 to 780725 license application, storage conditions for new fuel.
  DIETCH.R. Bouthern California Edison Co. COTTC 948 & Electric Co. 80/10/27 25pp. 08044:211.
- DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP. POWER BYS
- Bio3310934 Forwards operations safety evaluation re line systregulatory compliance manual. ALARA manual decommissioning plan in support of license applica DIPIAZZA.R P. Hestinghouse Electric Corp. 80/12. 08038-190
- --8103310937 "Demonstration D-II-2, Bafety Analysis# Westinghouse Electric Corp. 80/12/22 64pp.
- --B103310941 Site decommissioning plan for Nuclear f Fuel Fabrication Plant. • Westinghouse Electric Corp., Nuclear Energy ( 42pp. 08058:254.
- --Bi03310945 "Bits ALARA Manual for Nuclear Fuel Div Fabrication Plant."

Westinghouse Electric Corp., Nuclear Energy 8

--Bi03310948 "Bite Regulatory Compliance Manual for AL Nuclear Fuel Fabrication Plant." # Westinghouse Electric Corp., Nuclear Energy 9 175pp. 00038:299.

17pp. 08058:283

- 175pp. 06058:299.

  Bi03020549 Answer objecting to Safe Energy Alliance Contentions 1, 4, 5a, 8b, 9, 12, 14, 17-22, 29, 27-29, 34, 35 t 45-48. Contentions address matters not within sciapplication or are vague. Certificate of Svc encl. COMAN. B. Z., KERRICK, J. R., MARCUCCI, D. R. Westinghous 17/02/13. 28pp. 07783:001.
- 8103100766 Forwards latest draft stipulation Btipulation that Contention B(a) should be include Attachment A as stipulated contention. W/o ancl. TURK.8. © Office of the Executive Lagai Director. 07862:241.

- 8103030642 Request for adequate time to file responses to Bafe Energy Alliance of Central AL contentions Alliance should have Filed contentions shortly after ABLB 810202 order Responses cannot be filed by 810220 M/ Certificate of 8vc. GODHIN.A V Alabama. State of 81/02/20. 4pp 07793 133
- 8103180578 Requests notification of availability of draft EIS.per ICCFR51.54 List of interested groups submitted DOMELENC. Affiliation Unknown 81/02/22 ip 07944 269
- 8103020584 Order granting 810220 joint motion for extension of time. NRC. applicant & petitioner have until 810225 to file stipulations t responses to petitioner contentions & until 810316 for stipulations & responses to Donelson contentions WD\_F.J.F. Atomic Bafety and Licensing Board Panel 81/02/25 Ip. 07702.004
- 8(03050692 Herarandum in support of unstipulated contentions in Attachment 8 to 810229 stipulation Contentions address waste safety.accidents.HEPA filters.need for plant radiation dose models & alternative sites Certificate of 8vc encl. MCPHILLIPS.J.L. Safe Energy Alliance 81/02/25. 13pp. 07829-280
- B103050687 Request to demy proposed Safe Energy Alliance of Central AL.
  Inc. stipulated Contention 1.7. Proposed contention is autside
  ASLB jurisdiction since contention concerns state
  responsibilities. Centificate of Bvc
  ONDMIN. 4 V. Alabama. Bate of But/02/27 6pp 07829:274.
- 8:03:20642 Conditional application for leave to intervene. If atty for safe Energy Alliance of Central AL agrees to modify contentions as listed-request for intervention ull1 be withdrawn HILL FAMS. L Q Safe Energy Alliance 8:703/04 App.
- 5103110302 Discusses 810225 telcan re possibility of filing petition to interveny Refers to 810127 ltr for procedures to follow in filing petition.
  TURKAS E. Office of the Executive Legal Director. 81/03/09. 1p 07282.161
- Bi03i10309 Response to DL Allred Bi02i9 request to withdraw petition to intervene NRC does not oppose request.Certificate of Bvc encl TURN-S E Office of the Executive Legal Director 91/03/09. 7pp 07882.162
- BiO3170018 Response to AL BiO227 motion to deny Bafe Energy Alliance of Central AL. Inc Contention 17 NRC does not oppose motion NRC opposes admission of Contention 17 for reasons set forth in 810225 response to contentions. Certificate of Svc encl TVAN. SE Office of the Executive Legal Director. Bi/03/13 4pp.
- 6103230708 Motion for extension until 810515 to file stipulation &/or responses to Petitioner C Donelson contentions. Confirms 610310 Oral motion to ASLB during telephone conference. NRC & C Donelson do not object. Certificate of Svc encl. COMAN. 8. Z., KENRICK. J. R., MARCUCCI. D. R. Westinghouse Electric Corp 81/03/13 5pp 07974-001.
- B103270472 Memorandum & order directing that DL Allred patition to intervene & request for hearing be dismissed w/prejudice.
  HOLFE.J.F. Atomic Befety and Licensing Board Panel. B1/03/17. 2pp. 08034:150.
- 8103270775 Advises that Mestinghouse has not filed nor asked for exemption to filing installation info per 10CFR70.21 (g) for proposed nuclear fuel fabrication fecility. Info will be submitted 9 months before receiving nuclear matl. BHERR.T.8 Material Control & Accountability Development Branch. BI/03/20. p. 08043:255.
- 8103270464 Discusses 810304 correspondence re status of application by Westinghouse for SNM license for plant. Response deferred panding filing of actual petition for leave to intervene. TURA: B E. Hearing Branch 1. 81/03/25. 2pp. 08034:144.

# DDC4ET 70-2919 PRINCETON QAMMA-TECH

8103200256 Discusses IE Insp Repts 30-05422/80-01.30-10673/80-01. 30-14745/80-01 & 70-2915/80-01 on 810108 & forwards notice of violation. KINNEMAN J. D. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 81/01/29. 2pp. 07966: 223.

- --8103200275 Notice of violation from insp on 810108 Noncompliance not on 800905. Licensee delivered 55-gallon drum containing 8 %Ci CF-252 source to carrier for transport that did not incorporate required seal \*\* Region 1. Philadelphia. Office of the Director 81/01/29.
- DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY
- B103160269 Forwards License SNM-1873 authorizing possession of U-239 contained in 193 fuel assemblies & 100 loose fuel rods Bafety evaluation & Amend 1 to Indomnity Agreement B-BB encl.
  PAGE.R O. Urensum Fuel Licensing Branch 81/02/17. 2pp. 07917.183
- --8103160283 License SNN-1873 for TVA.authorizing use of 2,600 kg U-23 in 193 fuel assemblies & 100 loose fuel rods.
  PAGE.R. O. Uranium Fuel Licensing Branch B1/02/17 ip 07917:185
- --Bi03160294 Sefety evaluation resutif 800513 & 23 applications for license to use 2.600 kg Ul-235 in fuel assemblies & fuel rods Proposed activities can be performed u/o undue risk to public safety Amend I to Indemnity Agreement B-88 encl. BTEVERSON.R L . CROM.W T Uranium Fuel Licensing Brench. B1/02/17 3pp. 07917 186
- DOCKET 70-2930 FIVE FOUR THREE CO . INC.
- BIO3310660 Advises that plan re-safeguerds for SNM of low strategic significance is approved Plan will be implemented within 30 days of ltr receipt Encl to 800313 transmittal ltr will be withheld (ref 10CFR2.790).

  MCCORMIE, Q. M. Physical Security Licensing Branch 80/12/15 ip
  - Troubleton in Tayana barotty areasing plants borigity ty

# DOCKET 70-2936 HISSISSIPPI POWER & LIGHT CO

- 8103310706 Forwards Amend 1 to SNM license application re-storage of unirradiated reactor fuel 6 associated radioactive matl DALE/L.F. Mississippi Power & Light Co. 81/01/12 1p. 08039.120.
- --Bi03310714 Amend 1 to SNM license application re storage of unirradiated reactor fuel & associated radioactive matt.
   Mississipp; Power & Light Co. Bi/0/09 41pp. 08039:121.
- DOCKET 70-2937 PENNSYLVANIA POWER & LIGHT CO.
- 8103310930 Informs that physical security plan for protection of SNM of low strategic significance is approved Plan shall be implemented prior to receipt of BNM MCCORKLE.O.W Physical Security Licensing Brench. 81/01/07. Ip
- 8103120460 Forwards amend to util 801223 application for SNM fuel storage & receipt license.

  CURTIS:N W Pennsylvania Power & Light Co. 81/02/27. 1pp. 07906:065.
- --8103120463 Amend to util 801223 application for BNM fuel storage & receipt license.

  # Pennsylvania Power & Light Co. 80/12/23 14pp. 07906:066.
- DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY
- 8103060671 Forwards TVA 810123 application for license to receive & store unitradiated Puel W/o entl. STEVENBON.R.L. Uranium Fuel Licensing Branch. 81/02/17. ip. 07840:346
- PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS OF TRANSPORTATION CONDITIONS OF TRANSPORTATIO
- DOCKET 71-0002 CHEM-NUCLEAR BYSTEMB, INC.
- 8103020254 Forwards QA Program approval for radioactive mat1 packagu-Ravision 0. MACDDNALD-C.E. Transportation Branch. 91/02/12. lp. 07785:326.
- ~-8103020264 OA program approval for radioactive mail package.0002. Revision 0. MACDONALD.C.E. Transportation Branch. 81/02/12. ip. 07785:327.

DOCKET 71-0003 IND TEST LAS BERVICES CORP

8103030880 Requests registration as user of Models 6717 8/100A.C-8 & 500-80 HANDRAHAM.E Industrial Testing Laboratory Services Corp. 81/02/04 to. 07808 252

#### DOCKET 71-0138 BATTELLE COLUMBUS LABORATORIES

B103020238 Forwards QA program approval for radioactive mat1 package. Revision 0 MACODNALD.C.E. Transportation Branch 81/02/12 1p 07785:314

--8103020247 GA program approval for radioactive math package 0138. Revision 0. MACDONALD.C.E. Transportation Branch 81/02/12 ip 07785 315.

8103030015 Forwards QA program approval for radioactive nat1 package.

Revision 1

MACDONALD.C.E. Transportation Branch. 81/02/18. ig 07791 210

--Bi03030022 0A program approval for radioactive rat1 package 0138, Revision I.
MACDONALD.C.E. Transportation Branch 81/02/18 1p. 07791:211

# DOCKET 71-0164 MAGBACHUSETTS INSTITUTE OF TECHNOLOGY

8103120142 Responds to NRC 801031 request for add1 info re QA program for radidactive matt shipping packages. Forwards revised Chapter 11 to HIT Research Reactor BAR. "QA."
CLARK-L. Massachusetts Institute of Technology 81/02/26 2pp. 07900:189

--Bi03120147 Revised Chapter 11 to MIT Research Restor BAR. "QA "

e Hassachusetts Institute of Technology B1/02/10. 7pp.
07900.191.

B103200780 Forwards QA program approval for Radioactive Matl Package Oldá, Revision O MACDDNALD.C.E. Transportation Branch B1/03/14. lp. 07966 [B3

--Bi03200783 GA Program approval for Radioactive Matl Package 0164, Revision 0. MACDONALD.C E. Transportation Branch, 81/03/16. ip 07966-184.

# DOCKET 71-0179 NUCLEAR CONTAINERS. INC

8103100643 Forwards QA program approval for radioactive met1 package. MACDDNALD.C.E. Transportation Branch 81/02/26 1p. 07862.353.

--Bi03100645 GA program approval for radioactive mat1 package:0179. Revision O. MACDONALD.C.E. Transportation Branch. 81/02/26. ip. 07862-354.

# DOCKET 71-0219 TEREX DIV. /OM CORP.

8103240697 Notifies that div will be sold to IBH Holding AO of Hainz. Hest Germany as of 810101 Requests termination of GA program approval on 801231.

BAKER.R. M. General Motors Corp., Teres Div 80/12/19. ip. 07989: 205.

8103230161 Forwards QA program for transportation packages. HEINTZELMAN.K. General Motors Corp., Teres Div. 81/03/16. 1p. 07980:276.

--8103230164 OA program for transportation packages.

# General Motors Corp., Terex Div. 81/03/16. App. 07980:277.

#### DOCKET 71-0271 RIDIHALOH. EGGERS & ASSOCIATES

B103030005 Forwards QA program approval for radioactive mat1 package, Revision 0. MACDONALD.C.E. Transportation Branch. B1/02/17. 1p. 07791:206.

--Bi03030010 0A program approval for radioactive meth package: 0271, Revision 0. MACDONALD: C.E. Transportation Branch. 81/02/17. ip. 07771: 207. ECCKET 71-0318 MARATHON DIL CO

BIO3130305 Forwards UBS SIERRA (AD-18) GA program for packing be shipment of radiographic sources. XINOSIEV.S.S. Navu. Dect of 81/02/25 Scc. 65111 159

--8103130318 OA program for packing & shipment of radiographic acc

# DOCKET 71-0345 CAROLINA POWER & LIGHT CO

B103020071 Responds to 801110 ltr requesting amend to GA program (
transportation activities All applicable criteria of 10CFR50
App B GA program should be applied to transportation.
Commitment to this effect should be submitted.
MACDONALD.C E Transportation Branch. 81702712 [p 07785]

# DECKET 71-0403 SCHLUMBERGER WELL SERVICES

BIO3|6O3|1 Forwards QA program for Tupe B radioactive mail sealed source transport packages.

RACSTER.C.E Schlumberger Hell Bervices BI/02/23. 10 0/91/

--BIO3160318 OA program for Type 8 radioactive mat1 sealed source transport packages BHOVRD, R. Bichlumberger Well Bervices 81/02/20 18ap. 07914-013

8103240664 Forwards organizational chart & statement of training. inadvantently omitted from GA program RACBIER.C & Schlumberger Hell Services 81/03/10. 3pp. 07909-909

8103200775 Forwards GA program approval for Radioactive Matl Package 9403.Revision 0. MACDONALD.C E. Transportation Branch. 81/03/16 pp. 97968.01

--8103200778 9A Program approval for Radioactive Matl Pettage 040: Revision 0 MACDONALD-C E Transportation Branch 81/03/16 ip 07/88

#### DOCKET 71-0405 ENERGY

8103120150 Forwards QA program approval for Radioactive Matl Packa 0405 Revision 0. MACDDNALD.C.E Transportation Branch. 81/03/04 | jp | 07900 20

--BiO3i20158 GA program approval for Radioactive Matl Package 040: Revision O MACGONALD.C.E. Transportation Branch. 81/03/04. 1p 07903

# DOCKET 71-0406 J 0 SYLVESTER & ASSOCIATES, INC.

8103120242 Forwards "Shipping Container GA Requirements," in respo to 801126 request. YEATON.D.C. J.O. Bylvestar Associates, Inc. B0/12/19 App 07900:293

8103300356 Forwards request for add1 info re B01219 application for approval of GA program Questions address organization thant & statements on GA records insp status & audits.

MACDONALD.C.E. Transportation Branch. 81703719. 2pp 08058 C

#### DOCKET 71-0407 REFINERY PRODUCTS CORP.

8103030950 Forwards GA program for shipping packages. LOOSLE, J. N. Thiokol Corp. 81/01/27. 1p

--BI03030759 GA program for shipping packages. JOROENBON-L. R. LOOBLE, J. W. Thiokel Corp. Bi/01/27. 3pp. 07794:324.

8103030965 Forwards GA program for shipping packages. LDOSLE-J. H. Thiokol Corp. 81/01/27. 1p.

#### DOCKET 71-0408 MISSOUR! STEEL CASTINGS CO

- 9103130302 Forwards OA program in compliance w/regulations for shipping radioisotopes designed for use w/license. GUTHRIE.B. Missouri Steel Castings Co. 81/01/05 ip. 07912:177
- --9103130310 GA program for Missouri Steel Castings Co - Missouri Steel Castings Co 81/01/05 3pg. 07912 178
- 9103170702 Forwards QA program approval for Radioactive Math Pactage 010B. Revision O MACCOVALD. C. E. Transportation Branch 81/03/06 1p 07937 018
- --8/03/20765 OA program approval for Radioactive Matl Package 0409.

  Ravision 0

  MACDONALD.C E Transportation Branch. 81/03/06 to 07939.019
- DOCKET 71-0409 ERISTOL STEEL & IRON WORKS, INC. BRISTOL DIV
- 8103020222 Forwards GA program approval for radioactive matl package, Revision O MATCHARLD, C.E. Transcortation Branch, 81/02/12 is 07785-312
- --Bi03020231 0A program approval for radioactive mat1 package 0409.
  Revision 0
  MACDDMALD.C E Transportation Branch 81/02/12 10 07785:313
- DOCKET 71-0412 AIR PRODUCTE & CHEMICALS
- 9103230837 Forwards QA program approval for Radioactive Hetl Pattage 0412. Revision 0 ACCQC/ALD. C E Transportation Branch 81/03/11. Ip. 07974 055
- --810323084: 04 Program approval for Radioactive Matl Package 0412, Revision 0 NACDONALD,C E Transportation Branch, 81/03/11 1p. 07974,056
- SCCHET 71-0413 CONSTRUCTION ENGINEERING CONSULTANTS. INC.
- 8103040866 Forwards QA program for shipping package.
  MARTIN.O W. Construction Engineering Consultants, Inc. 81/01/28
  1p. 07820-064
- --BI03040871 QA program for shipping package. PARTIN.O W Construction Engineering Consultants. Inc. 01/01/28 top 07820 08
- 8103250359 Forwards QA program approval for Radioactive Hatl Package 0413.Revision 0. MACQCVALD.C.E. Transportation Branch 81/03/11 ip. 07998 051
- --BI03230363 QA program approval for Radioactive Mat1 Package 0413. Revision 0. MACDONALD.C.E. Transportation Branch 81/03/11. 1p. 07998.052.
- DOCKET 71-0414 CLARK EQUIPMENT CO.
- 8103030995 Forwards GA program for transportation of radiographic source mattrin response to NRC 810105 request.

  OUISBERT.D.A. Clark Equipment Co. 81701726. 1p
- --8103031003 QA program for transportation of radiographic source math.

   Clark Equipment Co. 81/01/26. 7pp.
- 8103250347 Forwards QA program approval for Radioactive Hatl Package C414.Revision 0. MACDONALD.C.E. Transportation Branch. 81/03/13. 1p. 07995.345.
- --BI03250353 QA program approval for Radioactive Matl Package 0414. Ravision O MACDONALD.C.E. Transportation Branch. B1/03/13. 1p. 07996:346.
- DOCKET 71-0415 DUQUEBNE LIGHT CO.
- BLO3040943 Forwards QA program for shipping packages. WASHASAUGH, R. J. Duquesne Light Co. B1/01/12. 1p.

- --Bi03040951 GA program for shipping packages
  WASHABAUCH, R.J. Duquesna Light Co. 81/01/12 4pp.
- B103250373 Forwards QA program approval for Radioactive Metl Package 0415. Revision 0. MACOGNALD, C E. Transportation Branch 81/03/11, 1o. 07996:
- --Bi03280378 QA program approval for Radioactive Matl Pactage O41
  Revision O
  MACDIMALD. C. E. Transportation Branch Bi/03/11 is. 07996
- DOCKET 71-0416 THIDAOL CORP
- B103030950 Forwards QA program for shipping packages L008LE-J H Thiokol Corp 81/01/27. 1p. 07794 323
- B103030965 Forwards GA program for shipping packages
  LOOBLE-J W Thickel Corp B1/01/27. ip 07794.330
- --8103030971 0A program for shipping packages
  URRENBONL R. LOOBLE J. W. Thickel Corp. 81/01/27. 3pp
- 8103090717 Requests that GA program for Licenses 43-03227-01.02 & EUB-1311 be administered under same GA approval number GA programs for licenses are identical.

  URGGENENIL R Thiotol Corp B1/02/16 1p. 07844-224
- 8103160021 Forwards organizational chart in response to 810217 reforming on the companies of the companies o
- --BIO3160026 Organizational chart showing radiographic operations radiation eafety organization.

   Thiofol Corp. 81/02/18. 1p. 07918:100
- B103:20427 Forwards QA progrem approval for Radioactive Mat1 Pack 0416.Revision 0 MACDONALD.C E Transportation Branch 81/03/04. ip. 07905:i
- --BIO3120433 GA program approval for Radioactive Matl Package 041 Revision O. MADDONALD.C E. Transportation Branch. 81/03/04 is. 07905
- DOCKET 71-0417 CARIBE SHELL & TUBE. INC
- Bj03110197 Requests registration as user of Model 650. OSGR10.J.M. Caribe Bhell & Tube. Inc. 81/01/21. ip.
- --BIO3110203 GA program for shipping packages.

   Caribe Shell & Tube, Inc. 81/01/23 3pp.
- B103170692 Forwards QA program approval for Radioactive Mat1 Package O417.Revision 0 GACDONALD.C.E Transportation Branch. 81/03/06. ip. 07939:0
- --BiO3170697 GA program approve) for Radioactive Matl Package 041 Revision O MACDONALD, C.E. Transportation Branch. 81/03/06. 1p. 07939
- DOCKET 71-0418 ALLOY CRAFTS CO.
- B103140012 Forwards revised radiological sefety manual. MHITAKER.C.E. Alloy Crafts Co. 81/02/05. 2pp.
- --8103160015 Notifies that company must have approved QA program register w/ARC prior to first shipment under certificate of compliance.H/o code excerpt & sample QA plan. MACDONALD.C.E. Transportation Branch. 80/11/26. Ip.
- --8103160018 Revised radiological sefety menual.
  \* Alloy Grafts Co 81/01/29. 45pp.
- DOCKET 71-0419 NORTHWEBTERN RESEARCH & TESTING, INC.
- B103030932 Forwards GA program for thipping packages Guestions re program should be directed to N Goodenough. UDHNSDN.J.A. Northeastern Research & Testing, Inc. B1/02/05, 07794.319.

- ~-Bi03030939 OA program for shipping packages • Northeastern Research & Testing. Inc. 81/02/06 3pp
- 8103300347 Forwards request for add1 info re 810206 application requesting approval of QA program MACDONAD.C E Transportation Byanch 81/03/19 2pp 08057 337
- EOCKET 71-0420 RADIATION TECHNOLOGY. INC.
- 8103090087 Forwards GA program for radioactive matl shipment. BUCKLEY, R Radiation Technology. 81/02/05. 1p. 07852:135
- DOCKET 71-0421 NAVY, DEPT OF FORCES AFLOAT
- 8103060099 Endorses encl radioactive natl packaging GA program for License 31-17677-01. BMITH.R H Navy.Dept of Forces Afloat. 81/02/06 1p. 07839 006
- --B103D&0107 Forwards QA program for packaging radioactive matl for License 31-17677-01 LOEMENTHAL, R.D. Navy, Dept. of, Forces Afloat. 81/01/07. 3pp. 07839-007.
- --Bi03060115 QA program for packaging radioactive matl for transport & transportation of radioactive matl under certain conditions under License 31-17677-01.

  \* Navy Dept of, Forces Afloat. Bi/01/07 21pp 07839 010.
- DOCKET 71-0422 OKLAHOMA BIEEL CASTINGS CO
- BiO3110215 Resubmits GA program for source receipt & transportation. Previous submittal received no reply from NRC. HAMILTON.J.F. Dishooms Steel Castings Co. Bi/02/13. is.
- --B103110220 QA program for source receipt & transportation \* Otlahoma Bitel Castings Co. 81/02/13. 15pp.
- --B103110226 Requests vendor registration w/NRC of certificate number for each package design & QA program Registration should occur prior to first shipment. MACDONALD.G.E. Transportation Branch. B0/11/26. 1p.
- DOCKET 71-0423 H & H X-RAY SERVICES. INC
- B103090597 Forwards QA program.per 10CFR71 HEAD.K.Y. H&H X-Ray Bervices.Inc. B1/02/17. ip.
- --8103090602 0A program for 10CFR71 requirements.
  # H&H X-Ray Bervices Inc. 81/02/17. 3pp.
- DOCKET 71-0425 QUAD CITY TESTING LABORATORY
- 8103250469 Forwards GA program for industrial radiography BLACK: 8.P. Guad City Testing Laboratory. 81/03/09. ip.
- --8103250473 0A program for industrial radiography.
  BLACK-B. P. Guad City Testing Laboratory. 80/11/30. 19pp.
- DOCKET 71-4940 MODEL: LLD-1, ENERGY, DEPT. DF
- 8103110029 Submits list of active cases where add1 info has been requested, but not received. Requests schedule for info submitted & confinention if cases are to remain open.

  MACDUNALD. C.E. Transportation Branch. B1/02/24. 1p. 07883:006.
- DOCKET 71-4986 MODEL: RA-1, RA-2, RA-3, RA-J, GENERAL ELECTRIC CO.
- 8103120313 Forwards Application Amend T-15,NRC Certificate of Compliance USA/4986/8 F.for transmittal to registered users of RA-series package.
  KAPLAN.A.L. Uranium Recovery Licensing Branch. 80/12/30. 1p. 07904:345.

- COCKET 71-5026 MODEL CN8 14-190, CHEM-NUCLEAR S
  - BI03090228 Requests registration as user of Modi CLAYTON F L Alabama Power Co. B1/01/20 4
  - 8103050844 Advises that PY Baynard is only indinatters re raduaste casks listed in encl RAYNARD.P Y Florida Power Corp. 81/01/30
  - B)02180347 Requests registration as user of Modicasts should be forwarded to CF Deltete at ut MOVEY. Q M. Metropolitan Edison Co. B1/02/04
  - 8103060242 Notifies of registration as user of CMS 8-120, 9080, CMS-1600, CMS 14-2951, CMS 21-30 CARRIER, A1-33-90, CM 6-80A, HM200, HM100 Series Series I MCCDUMALD, C E Transportation Branch, 81/02
  - DOCKET 71-5450 MDDEL. RCC-1. -2. -3. -4. WESTING
  - BIQG060242 Notifies of registration as user of CNB 8-120, 9080. CNB-1600. CNB 14-299H. CNB 21-30 CARRIER. A1-33-90, CN 6-80A, HN200. HN100 Series Series 1 MACDUMALD. C E Transportation Branch 81/02
  - DOCKET 71-5552 MODEL GAS CYLINDER FIRE IMPACT
  - 8103110029 Bubmits list of active cases where a requested but not received. Requests schedule submittal & confirmation if cases are to rema MACDONALD.C E. Transportation Branch 81/02
  - DDCKET 71-5960 MODEL VCD, UNION CARBIDE CORP
  - Bi03190804 Informs that packaging w/Certificate no longer in use.NRC BARP evaluation may be w ROSS.D M Energy, Dept. of. 81/02/20. 1p.
  - DOCKET 71-9595 MODEL. L&M GRNL URANIUM SHIELDED
  - Bi03:10029 Bubmits list of active cases where a requested but not received. Requests schedule submittal & confirmation if cases are to rema MACDENALD. C. E. Transportation Branch. 81/02
  - DOCKET 71-9641 MODEL UNC-2500, UNITED NUCLEAR
  - 8103120121 Forwards Revision 1 to Certificate o Model UNC-2500.
    MACDUNALD, C. E. Transportation Branch. B1/03
  - --B103120139 Certificate of Compliance 5641, Rev UNC-2500. MACDONALD, C. E. Trensportation Branch. 817
  - DOCKET 71-5645 MODEL: AL-L B. ENERGY, DEPT. DF
  - Biodii0029 Bubmits list of active cases where a requested, but not received Requests schedule submittal & confirmation if cases are to rene MACDDINALD.C.E. Transportation Branch. Bi/02
  - DOCKET 71-5740 MODEL: GRNL TRU OF SHIPPING CONT
  - 810G160556 Ack receipt of 800717 ltr providing Compliance 3740 No supplemental request for N safety analysis rept received NRC closing out MACDONALD.C.E. Transportation Branch. 81/02

- DOCKET 31-8753 MODEL DONE LODG TRANSPORT CASK, ENERGY DEPT OF 8103110029 Submits list of active cases where addl info has been requested but not received Requests schedule for info Transportation Branch MACDOMALD, C. E. B1/02/24 DECKET 71-5768 MODEL 88-250-2, COMBUSTION ENGINEERING CO. INC. 8103160208 Advises that add1 fee is required for 800926 renewal -equest. Add1 info submitted on 810128 changes renewal application to rinor amend to certificate of compliance E199.D License Fee Management Branch 81/03/11 in 07919:330 COCKET 71-5805 MODEL VANDENBURGH, CHEM-NUCLEAR SYSTEM, INC. 8103050844 Advises that PY Baumard is only individual authorized for eathers re raduaste casks listed in encl BAYNARD, P Y Florida Power Corp 81/01/30. Zop. DOCKET 71-5889 MODEL AL-L 11. ENERGY, DEPT. OF BIO3110929 Submits list of active cases where addl info has been recuested, but not received Requests schedule for info mittal & confirmation if cases are to remain open MACDONALD, C.E. Transportation Branch. 81/02/24 COCKET 21-5904 MODEL CE-100, GENERAL ELECTRIC CO \$103050107 Requests registration as user of GE Model GE-100 radioactive matis shipping cask
  UTLEY-E E Carolina Power & Light Co. 80/12/24 1p 07827 294. B103240847 Requests registration as user of Model OE-100. MAPLAN, A t. Deneral Electric Co., Nuclear Energy Products Div 81/03/05. If 07989 206 DCCKET 21-5939 HDDEL GE-1500, GENERAL ELECTRIC CD BIOSCOPCOR Forwards GA program for radioactive natl shipment.

  BUCKLEY.R Radiation Technology. B1/02/05. 1p. 07852 105. --8103070091 OA program for radioactive matl shipment
  - Radiation Technology 81/02/05 Spp 07852 136 8103040461 Requests extension of Certificate of Compliance 5939 from 810430 to 820430 Licensee is preparing new evaluations for shallded shipping containers CUININGHAM. O E General Electric Co 81/02/11 1p. 07811: 359 DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO. 8103180270 Requests registration as user of OE Model 700 radioactive ratis shipping cask 50ME-8. Hittman Nuclear & Development Corp. (subs. Hittman Corp.). 81/02/27. | 1p. 07943-361 DOCKET 71-6078 MODEL 927A1 % 927C1, COMBUSTION ENGINEERING CO B1031200B1 Registers facility as user of Model 927A1.Package
  USA/607B/AF shipping container.
  URRIG.R.E. Florida Power & Light Co. 81/02/24. 1p 07900:18B. SCCKET 71-6104 MODEL: ANL-390-SPM, ENERGY, DEPT. OF, CHICAGO 810311C029 Submits list of active cases where addl info has been requested, but not received Requests schedule for info submitted & confirmation if cases are to remain open MACDDMALD, C.E. Transportation Branch. B1/02/24. Ip
- B103050844 Advises that PY Baynerd is only individual authorized matters re reduceste casks listed in encl
  BAYNA9D.P Y. Florida Power Corp. 81/01/30 2pp
- B103060242 Notifies of registration as user of Models 14-190, B-2, CNS 8-120-9080. CNS-1600, CNS 14-293H. CNS 21-300. RAD-WABTE CARRIER, A1-33-90, CN 6-80A. HN200, HN100 Beries 2 & HN100 Series 1 MACDONALD, C. E. Transportation Branch. 81/02/19. 200.
- DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR BYSTEMS, INC.
- B103090215 Requests registration as user of Model 6244 CLAYTON-F. L. Alabama Power Co. B1/01/20 4pp 07846 235.
  - BIO3050844 Advises that PY Baynard is only individual authorized in matters we radwaste casks listed in encl BAYNARD, P. V. Florida Power Corp. 81/01/30 200
  - B10304043B Notification of registration as user of Models CN8 21-0 CN6-B0A.HM-200.90B0.HM-100 Series 1.6244.HM-100 Series 2. CN8-1600 & HM-100s.in response to request HM-100.HM-100s.in response to Tequest HM-100.HM-100.
  - B103060242 Notifies of registration as user of Models 14-190, B-2, & CNS B-120, 9080, CNS-1600, CNS 14-295H, CNS 21-300, RAD-WASTE CARRIER. A1 -33-90. CN 6-80A. HN200. HN100 Beries 2 & HN100 Series 1 MACDONALD, C E Transportation Branch 81/02/19. 2pp.
- DOCKET 71-6275 MODEL, LL-28-4, CHEM-NUCLEAR BYSTEMS, INC.
- 8103050844 Advisos that PY Daynard is only individual authorized finatters to raduaste casks listed in encl BAYNARD P Y. Florida Power Corp. 81/01/30 2pp. 07825-133
- DOCKET 71-6346 MODEL, FBV-1, GENERAL ATOMIC CO.
- 810228030B Responds to 801114 request for re-examination of major fee determination re 801009 amend request for certificate of compliance NAC maintains original position. HILLER.M.O. License Fee Management Branch 81/02/13 2pp. 07765.351.
- DOCKET 71-6347 HODEL FBV-3, GENERAL ATOMIC CO
- 8103240669 Requests registration as user of Model FBV-3. WAREMBDURG, D. Public Bervice Co. of Colorado. 81/03/06 1p 07986:311
- DOCKET 71-6375 HODEL: CNB 4-49, CHEM-NUCLEAR BYSTEMS, INC.
- B103050844 Advises that PY Baynard is only individual authorized fratters re-raduaste casks listed in encl. BAYNARD, P. V. Florida Power Corp.
- 8103250073 Informs that partial refund will be made for application for smend to Certificate of Compliance 6379. MILLER.W. O. License Fee Management Branch. 81/03/17 1p. 07997:322

B1701/30.

- DUCKET 71-6400 MODEL 6400, WEST INGHOUSE ELECTRIC CORP.
- B103050il8 Requests mod to Condition 3 of NRC B01203 itr authorizi Westinghouse to transport large equipment waste in Super Tiger shipping package. DIPIAZZA, R.P. Westinghouse Electric Corp. 80/12/15. 2pp. 07827:301.
- 8102190862 Application for mod to Condition 3 of Certificate of Compilance 6400 authorizing transport of large contaminated equipment waste in two addl Super Tiger shipping packages. Two oversize drawing and Lagerture cards in PDR. BABO.A T. Westinghouse Electric Corp. 81/01/20. 1p. 07708:04
- --9102190871 "Description of US Ecology Super Tiger (Model Number # Westinghouse Electric Corp. 81/01/22. 3pp. 07708:043.

8103090212 Requests registration as user of Model R-2

DOCKET 71-6144 MODEL 8-2, U 8. ECOLOGY

- 8103060230 Forwards check for which payment was stopped Ack receipt of fee payment in lieu of check. KE198-D. Litemse Fee Management Branch 81/02/23 1p 07839 315
- B103240653 Requests approval of encl SAR & revised certificate of compliance re use of storage compartment for shipment of unirradiated U-233 fuel rods in Model Buper Tiger W/o safety analysis & revised certificate.

  ENNEL.W F Energy, Oept. of. 81/03/09 2pp 07989:207
- DOCKET 71-6421 MODEL: CBE-14. ENERGY. DEPT. CF
- 8103110029 Submits list of active cases where additinfo has been requested, but not received. Requests schedule for info submittal & confirmation if cases are to remain open.
  MACQUONALD.C E Transportation Branch 81/02/24 1p
- DOCKET 71-6458 MODEL: 80-5, GENERAL ELECTRIC CO
- B103050569 Application for rensual of Certificate of Compliance 5458. Fee sec! HICHEL.C.J. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). B1/02/11 1p. 07835 ICB.
- Bi03230126 Application Amend T-19 for renewal of Certificate of Corpliance 6438 for BU-5 shipping package.

  KAPLAHA-L. General Electric Co., Nuclear Energy Products Div. Bi/03/04 p. 07997 287
- DOCKET 71-6574 MODEL. HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- B103090177 Requests registration as user of Model HN200 CLAYTON,F L. Alabara Power Co. 81/01/20 4pg. 07846-267
- 8103040438 Notification of registration as user of Models CNS 21-300, CNS-80A.HN-200.9080,HN-100 Series 1.6244,HN-100 Beries 2. CNS-1600 & HN-100s.in response to request MCCONALD.C E. Transportation Branch B1/02/19. 1p.
- 8103050214 Notification of registration as user of Hodels UN-100 Geries
  1 & 2.HN-100s.HN-200 & 9080 in response to request
  HACDONALD.C.E. Transportation Branch. 81/02/19. 1p 07832.208
- B103040242 Notifies of registration as user of Models 14-190.8-2.6244.

  CMS 8-120.9080.CMS-1600.CMS 14-299H, CMS 21-300. FAD-WASTE

  CARRIER.AI-33-90.CM 6-80A.HM200.HM100 Beriss 2 & HM100

  Beriss 1.

  MCD0MALD.C.E. Transportation Stanch. B1/02/19. 2pp.
- DOCKET 71-6591 MODEL: 51032-1 & 1A. EXXON NUCLEAR CO..INC
- 8103041003 Application for amend of Certificate of Compliance 6581 to permit transport of excess unirradiated fuel from customer for recovery of U.Fee encl HANSEN-L.E. Erson Nuclear Co., Inc. (subs. of Exxon Corp.). B1/01/02. jp. 07819:245
- --8103041011 Sefety evaluation re 810102 application for amend of Certificate of Compliance 6581 to permit transport of excess unirradiated fuel from customer for recovery of U. e. Exxon Nuclear Co., Inc. (sube. of Exxon Corp.). 81/01/02. 5pp. 07819-246.
- B103040922 Forwards replacement Table 12-XIV for inclusion in XN-52, Revision I.
  HANBEN-L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).
  B1/01/15. 300. 07810:339.
- DOCKET 71-6601 MODEL: CN8 8-120, CHEM-NUCLEAR BYSTEMS, INC.
- 8103090221 Requests registration as user of Model CNS 8-120. CLAYTON.F. L. Alebama Power Co. 81/01/20. 4pp. 07846:231.
- 8103080844 Advises that PY Baynard is only individual authorited for matters re redwaste casks listed in encl.
  8AYNARD.P.Y. Florida Pawer Corp. 81/01/30. 2pp.
- B103040824 Notification of registration as user of Hodel CNS 8-120 in response to request.

  MACDONALD.G.E. Transportation Branch. 81/02/19, 1p. 07812:293.

- DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC
- 8103170209 Confirms 810217 telcon no cavity measurements of Model NAC-1C on 810219 NRC representative is welcome JOHNSDN-C.R Nuclear Assurance Corp. 81/02/17 1p 07/94 064
- 8103110807 Confirms 810223 telcon me protective paint applied to D for shipment being partially stripped during shipment locident of minor significance due to small quantity of paint particles & low level of releasable contemination JGHNSON-C.R. Nuclear Assurance Corp. 81/02/24 2pp. UFNEL 332
- 8103230121 Requests authorization to ship empty Cast NAC-NI In view specified procedures & to minimize generation of radwastes, requests partial waiver of Condition 13 requirements Fee encl
  OHNBON.C R Nuclear Assurance Coro 81/03/04 2nm OFFRE 274
- 8103250637 Informs that partial fee refund will be made for Newjetor 12 & 13 to Certificate of Compliance 6698 MILLER.W O License Fee Management Branch 81/03/19 tp 02998 740
- DOCKET 71-4717 MODEL 6717-B. GAMMA INDUSTRIES, INC
- 8103030880 Requests registration as user of Models 6717 0.100A.C.0.6 500-80. HANDRAHAN, E. Industrial Testing Laboratory Services Curp. -0.170.27  $1_{\rm P}=0.7808.252$
- 8803093098 Notification of registration as user of Models 521 (3), 6717-8-100 & C-8 in response to request MACOUNALD.C.E. Transportation Branch 81/02/19 tp 0/854 12.3
- B1031B0530 Requests registration as user of Oamma Industries Model 4717-B overpack shipping container.

  CDREY, D. A. Navy, Dept. of, 81/02/19 ip 07944 006
- 8103120039 Bubmits list of Type B packages & requests to be register at users
  ALMRD J. J. Tech/Ops (Technical Operations, Inc.) HI/(U/J) Sep.
  07900.174
- DOCKET 71-9001 MODEL: IF-300, GENERAL ELECTRIC CO
- --8102260067 Revision 2C, Vol 1 of "Consolidated BAR for IF HOO Ghaga Cask." # General Electric Co NEDD-10084 V1 R2C. 80/12//H -2-23p 07745-011.
- DOCKET 71-9006 MODEL: 500-80. AUTOMATION INDUSTRIES. INC
- 8103030880 Requests registration as user of Models 6717 8-169A-C o t BOO-BU. HANDRAHAN-S. Industrial Testing Laboratory Services Corp. U1:02, Ip.
- 8103040819 Notification of registration as user of Hodels 500 GU & 520 in response to request MACDONALD.C E. Trensportation Branch. 81/02/19. Ip 07812 254
- 8103090098 Notification of registration as user of Hodels 860 GJ. 6717-8-100 & C-8 in response to request. MACDUNALD.C.E. Transportation Branch. 81/02/19 ip 07452 123
- BiO3120059 Submits list of Type B packages & requests to be resist, as users.

  MNRO J.J. Tech/Ops (Technical Operations: Inc.). Bi/02/25

- 8103C4CB19 Notification of registration as user of Models 500-SU & 520 in response to request MACCC4ALD, C.E. Transcortation Brench 81/02/19 to 07812 254
- 8100120059 Bubmits list of Type 8 packages & requests to be registered as users
  MARO. J. J. Tech/Ops (Technical Operations, Inc.) 81/02/25 2pp
  0.7900-174
- DOCKET 71-9010 MODEL N. 1-1/2. NUCLEAR ASSURANCE CORP
- 8103110552 Application for Revision 7 to Certificate of Compliance 9010 to permit shipment of spent nuclear fuel in forms other than intact fuel estembles
  CARLSON R. W. Nuclear Assurance Corp. 81/02/16 1400 07876 328
- 81030603B9 Requests registration as user of Model NLI-1/2 BRACKEN, N. W. Energy, Dept. of B1/02/18, 1p. 07835-359
- COCKET 71-9013 MODEL 521, ISOMEDIX, INC.
- 8102170607 Application to renew Certificate of Compliance 9013 for Model 520 or 521 Requests exemption from 10CFR71 re 90 criteria for febrication of irradiator. Fourteen oversize Crasings incl Aperture cards in PDR JARRETTR D Agriculture.Dept of 81/02/05 2pp 07693.019.
- --8102170624 Farwards Revision 0 to Certificate of Compliance 9013 for Hotel 521 HACDDNALD.C E Trensportation Branch. 77/06/03 1p. 07693:021
- --8102170630 Certificate of Compliance 9013 Revision 0 for Model 521 MACDDNALD, C.E. Transportation Branch. 77706/03 2pp. 07673.022
- --8102170636 Requests review of proposed Model 321 specs & revised 10CFR71 analysis. Also requests authorization to deliver loaded irradiator to motor carrier for shipment within US DIETZ.2 Isonadis. Inc. (subs. of Massfield Enterprises, Inc.) 74/01/14 4pp 07693-024
- DOCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.
- 8103261000 Requests registration as user of Tech Ops Model 660. MOBERO, A J. Newport News Bhipbuilding & Dry Dock Co. (subs. of TENNECO Corp.). 81/03/09 1p.
- DOCKET 71-9034 MODEL TRIDA-1, GENERAL ATOMIC CO
- 810303CB59 Requests registration as user of Model TRIOA-1. FELTZ-D E Teras A & M Univ. 81/02/05 ip. 07808.251,
- 6103040828 Notification of registration as user of Model TRIOA-1 in response to request.

  MACBONALD.C E Transportation Branch 81/02/19. ip. 07812:252
- DOCKET 71-9035 MODEL: 680 & 680E, TECHNICAL OPERATIONS, INC.
- 8103230139 Requests registration as user of Models 680 & 680E SKORO-400-P. Briggs Engineering & Testing 81/03/09 ip
- --8103230147 Certificate of Compliance 9035, Revision 2 for Models 680 & 6805 MACDUNALD.C E Transportation Branch. 77/04/13. 2pp.
- DECRET 71-9036 MODEL: C-1. SOURCE PRODUCTION EQUIPMENT CO
- 8103120059 Submits list of Type B packages & requests to be registered as users MURD, J. J. Tech/Ops (Technical Operations, Inc.). 81/02/25. 2pp. 07900-174.

- 8103050844 Advises that PY Baynard is only individual authorized for matters re raduasto casks listed in encl
  8404888.P.Y. Florida Power Corp. 81/01/30 200
- 8103040845 Notification of registration as user of Hodel GE-1630 in response to request.

  MACDONALD.C.E. Transportation Brench. 81/02/20 in 07812.249
- B103040834 Notification of amend to Certificate of Compilarte 9044 to permit waste ratio shipment in accordance w/B10220 ltr Mat1 will be included as add1 contents in Model GE-1600 package Authorization expires B10701 MACDONALD.C.E. Transportation Branch. B1/02/23 ip. 07810 125.
- DOCKET 71-9056 HODEL. EPEC 2-T. BOURCE PRODUCTION EQUIPMENT CO
- Bi03120059 Submits list of Type B packages & requests to be registered as users.
  MUNROLJ.J. Tech/Ops (Technical Operations, Inc.). 81/02/25 20p
- DOCKET 71-9070 MODEL: N-55, ENERGY, DEPT OF
- B103050B44 Advises that PY Baynard is only individual authorized for matters re-raduaste casks listed in encl.
  BAYNARD,P Y Florida Power Corp. 81/01/30 2pp 0/825 133
- B103120397 Requests registration as user of Model N-55 shipping container.

  CUNNINGHAM. 0 E General Electric Co., Nuclear Energy Products Div. B1/02/20 in 07906:191
- B103120135 Requests to be registered as user of Model N-55,Package USAA/907078
  AUSTIN.M. A. Babcock & Hilcox Co., Nuclear Material Div. B1/02/25.
  1p. 07900 187
- DOCKET 71-9079 PODEL. HN-100 BERTES 2. HITTHAN NUCLEAR & DEVELOPMENT
- BIO2280312 Requeste registration as user of Models HN1000s.

  BYLVIA, D. R. Virginia Electric & Power Co. 81/02/05. 1p.
- B10304043B Notification of registration as user of Models CNS 21-300. CN6-BOA. HN-200. 9080. HN-100 Berias 1.6244. HN-100 Berias 2. CNB-1600 & HN-100s. in response to request. MACDMALD, C. E. Transportation Branch 81/02/19.
- 8103050214 Notification of registration as user of Models UN-100 Saria | 1, 2, NN-100s, HN-200 & 9080 in response to request, | MACDONALD. C E | Transportation Branch | B1/02/19. | Ip
- 8103060242 Notifies of registration as user of Models 14-190, B-2,6244, CNS 8-120, 9080, CNS-1600, CNS 14-295H, CNS 21-300, RAD-HABTE CARRIER, A1-33-90, CN 6-80A, HN200, HN100 Beries 2 & HN100 Beries 1 MACDINALD, C. E. Transportation Branch 81/02/19 200
- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8103090185 Requests registration as user of Model 9080 (HN600). CLAYTON, F. L. Alabama Power Co. 81/01/20. 4pp. 07846: 259.
- BIO3050844 Advises that PY Baynard is only individual authorized for matters re raduaste casts listed in encl.
  BAYNARD:P. Y. Florida Power Corp. 81/01/30. 2pp.
- G103040438 Natification of registration as user of Models CNS 21-300, CNS-80A. HN-200, 9080. HN-100 Series 1,6244.HN-100 Series 2, CNS-1600 & HN-100s, in response to request. MACDUNALD, C.E. Transportation Branch. B1/02/19 1p.
- 8103090214 Notification of registration as user of Models UN-100 Beris i & 2.HN-100s.HN-200 & 9080 in response to request.

  MACDDNALD. C. E. Transportation Branch. BI/02/19. ip. 07832:208.
- B103060242 Notifies of registration as user of Models 14-190, 8-2,6244, CNS B-120, 7080, CNS-1600, CNS 14-275H, CNS 21-300, RAD-HASTE CARRIER, A1-33-90, CN 6-804, HN200, HN100 Series 2 & HN100 Series 1. HN100 Series 2. RN100 Series 2. RN1

- DOCKET 71-9081 MODEL CN8-1600, CHEH-NUCLEAR BYSTEMS, INC.
- Bi030901B1 Requests registration as user of Model CN9-1600. CLAYTON.F.L. Alabana Power Cp. Bi/01/20 4pp. 07846: 263
- 8103030844 Advises that PY Baynard is only individual authorized for catters re raduate casks listed in enc!
  BAYNARD, P.Y. Florida Power Core. 81/01/30 230
- BiQ3040438 Notification of registration as user of Hodels CNS 21-300, CN6-BOA. HN-200, 9080, HN-100 Series 1.6244, HN-100 Series 2. CNS-1600 & HN-100s, in response to request HACDONALD. C.E. Trensportation Branch BI/O2/19. 1p.
- 8103060242 Notifies of registration as user of Models 14-190.8-2.6244, CNB 8-120.7080, CNS-1600, CNS 14-275H, CNB 21-300. RAD-WASTE CARRIER. A1-33-90. CN 6-80A. HN200. HN100 Series 2 & HN100 Series 1 HN100 Series 2 & HN100 Series 1 HN100 Series 2 & HN100 SERIES 1 HN100 SERIES
- DOCKET 71-9086 MODEL HN-100 SERIES I. HITTHAN NUCLEAR & DEVELOPMENT
- 8103090167 Requests registration as user of Model HN100-Beries 1 CLAYTON F L. Alabama Power Co. 81/01/20 4pp 07846:275
- B103040439 Notification of registration as user of Models CNS 21-300-CNS-B0A-HN-200,9080-HN-100 Beries 1.6244.HN-100 Series 2. CNS-1600 & HN-100s. in response to reguest MACDONALD.C.E Transportation Branch B1/02/19 ip
- B103050214 Natification of registration as user of Hodels UN-100 Series 1 % 2-HN-100s, HN-200 % 7080 in response to request MACDONALD, C. E. Transportation Branch 81/02/19. ip. 07832:208
- B103060242 Notifies of registration as user of Models 14-190, B-2, 6244, CNS B-120, 9080, CNS-1600, CNS 14-295H, CNS 21-300, RAD-HABTE CARRIER, A1-33-90, CN 6-80A, HN200, HN100 Series 2 & HN100 Series 1.

  MACDDNALD, C. E. Transportation Branch. 81/02/19 2pp.
- DOCKET 71-9089 MODEL. HN-1008, HITTMAN NUCLEAR & DEVELOP. CORP.
- B103090190 Requests registration as user of Model HN100-Series 5 CLAYTON F. L. Alabama Power Co. 81/01/20 4pg. 07845:295
- 8103040438 Notification of registration as user of Models CNS 21-300. CNS-80A.HN-200.9080.HN-100 Beries 1.6244.HN-100 Beries 2. CNS-1600 & HN-100s. in response to request. PACOUNALD. C E Transportation Branch 81/02/19 ip.
- BiO3050214 Notification of registration as user of Models UN-100 Series 1 & 2. HN-100s. HN-200 & 9080 in response to request MACDONALD.C.E. Transportation Branch. BI/02/19. ip.
- B103060242 Notifies of registration as user of Models 14-190,8-2,6244, CNB B-120,9080,CNB-1600.CNS 14-299H,CNB 21-300,RAD-HASTE CARRIER,A1-33-90,CN 6-80A,HN200,HN100 Series 2 & HN100 Series 1 MACDDNALD.C.E. Transportation Branch 81/02/19 2pp
- DDCKET 71-9094 MODEL: CN8 14-195-H. CHEM-NUCLEAR SYSTEMS: INC.
- B103090209 Requests registration as user of Model CN9 14-195H CLAYTON, F. L. Alabama Power Co. 81/01/20 4pg. 07846; 243.
- 8103030844 Advises that PY Baynard is only individual authorized for matters re reducate casts listed in encl BAYNARD-P.Y. Florida Power Corp. 81/01/30. 2pp.
- 8103060242 Notifies of registration as user of Models 14-190.B-2.6244, CNS 8-120.9080.CNS-1600.CNS 14-299H.CNS 21-300.RAD-HABTE CARRIER.A1-33-90.CN 6-804.HN200.HN100 Series 2 & HN100 Series 1. MACDONALD.C.E. Transportation Branch. 81/02/19. 2gp. 07839.309
- DOCKET 71-9094 MODEL: CN8 21-300, CHEM-NUCLEAR BYSTEMS, INC.

1

B103090195 Requests registration as user of Model CNS 21-300. CLAYTON, F. L. Alabama Power Co 81/01/20. 4pp 07846:251

- B103050B44 Advises that PY Beynard is only individual tests re reduces to casks listed in encl.

  BAYNARD, P. Y. Floride Power Corp. B1/01/30. 2;
- B10304043B Notification of registration as user or CN6-80A.HV-200.9080.HN-100 Series 1.6244.HN-100 CN5-1600 % HN-100.in response to request HACDDNALD.C E Transportation Branch B1/02/15
- BI03060171 Requests registration as user of Model MERLING.J A Duquasne Light Co 81/02/19 in.
- 8103060242 Notifies of registration as user of Mor CNS 8-120-9080, CNS-1600, CNS 14-299M, CNS 21-300, CARRIER, A1-33-90, CN 6-80A, HN200, HN100 Series 2 & Series 1. ACCDMALD, C.E. Transportation Branch 81/02/15
- B100250396 Requests registration as user of Model MURRAY.T.D. Toledo Edison Co. 81/02/23. 1p.
- DOCKET 71-9105 MODEL: RAD-WASTE CR. 1. CHEM-NUCLEAR
- B103090200 Requests registration as user of Model CLAYTON-F. L. Alabama Power Co 81/01/20 4pp
- 8103050844 Advises that PY Baynard is only individed the retters re raduaste casks listed in encl.

  BAYHARD P Y Florida Power Corp. 81/01/30 26
- 8103060242 Notifies of registration as user of Moc CN6 8-120, 9080, CN6-1600, CNS 14-295H, CNS 21-300, F CARRIER, A1-33-90, CN 6-80A, HN200, HN100 Series 2, 8 Series 1. MACDONALD, C. E. Transportation Branch 81/02/19
- DOCKET 71-9107 MODEL 771. TECHNICAL OPERATIONS. 1
- B103030973 Requests registration as user of Model KOVACS, F. B. Foster Wheeler Corp. 81/01/28, 19
- Biggo40834 Natification of registration as user of response to request MACDGNALD.C E. Transportation Branch. 81/32/19
- DOCKET 71-9108 MODEL AL-33-90. CHEM-NUCLEAR SYSTE
- 8103090226 Requests registration as user of Model CLAYTON F. L. Alabama Power Co. 81/01/20. 4pp.
- 8103050844 Advises that PY Baynard is only individed matters re radwaste casks listed in encl.
  BAYNARD.P. Y Florida Power Corp. 81/01/30 2p
- 8103060242 Notifies of registration as user of Mod CNS 8-120, 9080, CNS-1600, CNS 14-295H, CNS 21-300, R CARRIER, A1-33-90, CN 6-80A, HN200, HN100 Series 2 8 Series 1. MACCONALD, C. E. Transportation Branch. 81/02/19
- DOCKET 71-9111 MODEL: CNA-80A. CHEM-NUCLEAR SYSTEM
- 8103070173 Requests registration as user of Model CLAYTON, F. L. Alabama Power Co 81/01/20. 4pp.
- 8103050844 Advises that PY Baynard is only individed matters re radwaste casks listed in ancl.
  BAYNARD, P. Y. Florida Power Corp. 81/01/30 2p
- 8103040993 Forwards Revision D to Drawing BC-20-20 A516 matl will be used on all casks fabricated a HANSEN.L.J. Nuclear Packaging. Inc. 81/02/12
- 810304043B Notification of registration as user of CN6-80A: HN-200, 9080. HN-100 Series 1.6244, HN-100 CN8-1600 & HN-100s, in response to request. MACDONALD.C.E. Transportation Branch. 81/02/15

- 81030&0242 Notifies of registration as user of Models 14-190, B-2, 6244. CNS 8-120, 9080. CNS-1600. CNS 14-295H. CNS 21-300, RAD-HASTE CARRIER, A1-33-90. CN 6-80A, HN200. HN100 Series 2 & HN100 Series 1
- MACCONALD, C.E. Transportation Branch. B1/02/19 2pp
- B103120461 Forwards Revision 4 to Certificate of Compliance 9111 for Hodel CH6-BOA.
  ACCODINALD, C. E. Transportation Branch. B1/03/04 3pp 07905 14B.
- --8103120465 Certificate of Compliance 9111. Revision 4. for Model CN6-80A MACDONALD, C. E. Transportation Branch 81/03/04. 3oa 07905 151
- DOCKET 71-9113 HODEL. 7-100, CHEM-NUCLEAR BYSTEMS, INC
- 8103040838 Notification of registration as user of Model 9080 in response to request
  HACKDONALD, C.E. Transportation Branch. 81/02/19. 1p 07812 250.
- DOCKET 71-9127 MODEL: 100-100A-200-200A- GAMMA INDUSTRIES
- 8103030880 Requests registration as user of Models 6717 B.100A,C-8 & 500-5U
  HAMDRAHAN, C. Industrial Testing Laboratory Services Corp. 81/02/04
  16 07808-252
- 8103070078 Notification of registration as user of Models 500-60. 6717-8.100 & C-B in response to request MACDUNALD.C E Transportation Brench. 81/02/19 1p. 07852.123.
- 6103120071 Bubmits list of Type B packages & requests to be registered as user MPRO J J. Tech/Ops (Technical Operations, Inc.) 81/02/25 2pp. 07900-176.
- DOCKET 71-9128 MODEL: C-8, QAMMA INDUSTRIES
- 8163030880 Requests registration as user of Models 5717 B.100A.C-8 & 900-BU MATERAHAN.E Industrial Testing Laboratory Services Corp. 81/02/04 to
- 8103090098 Notification of registration as user of Models 500-80. 6717-8.100 & C-B in response to request. MGCQDMALD.C.E. Transportation Branch. 81/02/19. 1p.
- B103120074 Submits list of Type B packages & requests to be registered as user MURBOUU J Tech/Ops (Technical Operations, Inc.). 81/02/25. 2pp 07900 178
- DOCKET 71-9132 MODEL: T-3, NUCLEAR PACKAGING: INC.
- 810317002: Porwards Revision 5 amends to SAR for Model T-3 shipping cast application.

  HAMBEN.L J. Nuclear Packaging, Inc. 81/02/19. 1p 07928:001
- --BI03170032 Revision 5 amends to BAR for Model T-3 shipping cask.Fifteen oversite drawings encl. Aparture cards will be in PDR.
  4 Nuclear Packaging, Inc. B1/02/18. 13pp. 07928:002.

- DOCKET 71-9139 HODEL 589, GENERAL ELECTRIC CO.
- 8103060129 Requests registration as user of Model GE-589 MILLEL M. Tennessee Valley Authority, 81702/10, 1p. 07839:041
- DOCKET 71-9143 MODEL 920, TECHNICAL GPERATIONS, INC.
- 8103120111 Forwards Revision O to Certificate of Compliance 9143 for Model 920.
  MACDINALD.C E Transportation Branch 81/02/26 ip 07900:263
- --Bi0312011B Certificate of Compliance 9143.Revision O.for Madel 920.
  MACDDNALD.C E Transportation Branch. 81702/26 3pp 07900:264.
- B10325012B Requests registration as user of Model 920.
  MCCDRMACK, J. B. Chicago Bridge & Iron Co. 81/03/13. ip 07997:286.
- DOCKET 71-9145 MODEL NUPAC 50-1.5L, 2.8L, 3 OL & 4.0L, NUC PKG. . INC.
- 8103050431 Forwards Drawing X-20-201D Revision 8.8heets 1 & 2. HANSEN.L J. Nuclear Packaging, Inc. 81/01/23 1b. 07826:097
- B103120796 Forwards Revision 1 to Certificate of Compliance 9145 for Model NUPAC-50 MACCONALD, C.E. Transportation Branch. B1/03/04. 1c. 07905:323.
- --Bigg120801 Certificate of Compliance 9145, Revision 1 for Model NUPAC-50. MACDEMALD, C.E. Transportation Branch 81/03/04, 200. 07905,324
- DOCKET 71-9147 MODEL: 850, TECHNICAL OPERATIONS, INC.
- B103260969 Forwards Revision O to Certificate of Compliance 9147 for Model 830.

  MACDDNALD, C.E. Transportation Brench. 81/03/19. 1o. 08035:168.
- --Bi03260975 Certificate of Compliance 9147.Revision 0, for Model 850. HACDONALD, C.E. Transportation Branch 81/03/19. 5pp. 08035:169.
- DOCKET 71-9891 MODEL: LITHIUN HYDROXIDE FIRE/IMPACT SHIELD.
- 8103110027 Submits list of active cases where add1 info has been requested, but not received. Requests schedule for info submittal & confirmation if cases are to remain open. MACDOMALD, C. E. Transportation Branch. 81/02/24, ip.
- DOCKET 71-9852 MODEL: DT-14. ENERGY, DEPT. OF
- 8103110029 Submits list of active cases where add1 info has been requested, but not retailed. Requests schedule for info submittel & confirmation if cases are to remain open. MACDDNALD.C.E. Transportation Branch. 81/02/24. 1p.



#### COMMISSION MEETING RECORDS BOCER

- 8101290577 Unofficial transcript of Commission 810107 affirmation/ discussion session in Mashington DC re BECY-A-80-180A, SECY-B0-533. SECY-B0-530 & BECY-A-80-179F Pp 1-21 \* Cormissioners 81/01/07 23pp. 07733 359
- --A102230060 SECY-80-530 nearpsets Commission approval of amends to 10CFR70 & 73 re transient shipments of strategic SNM Carriers will be responsible for protection against theft & radiological .ahotana DIRCKS, H.J. Office of the Executive Director for Operations 80/12/04. 37pp 07734 021
- --0102230094 SECV-00-973 Requests Commission accraval of FR publication of effective to IOCFR70 isquing general license to carriers of irradiated reactor fuel Action would grant NRC direct insp # enforcement authority over carriers. Supportive matl gncl DIRCKS.H.J. Office of the Executive Director for Operations 80/12/08. 19pp 07734:088
- 0103023042 Transcript of Commission 810202 meeting in Bethesda. MD to discuss policy planning & program guidance for FY83-87 • Commissioners, 81/02/02, 27cc 07785 028
- 8103090611 Transcript of 810121 meeting w/AIF in Washington CC refuture of nuclear power plants Pp 1-82.
  • Commissioners, 81/01/21 84pp. 07845 115
- --8103090631 Transcript of FM Staszesky introductory statement during 810121 meeting w/Commission re long-term autlook for addl huclear power plants.
  STASSESKY.F.M Atomic Industrial Forum 81/01/21. 3pp. 07045 202
- --B103090637 Submits agenda for 010121 meeting o/Commission. WALEKE, C. Atomic Industrial Forum. 01/01/13 2pp. 07845-205
- --BI03090643 Requests late Nov or early Dac meeting w/Cormission to discuss NRC & industry conflicting views re-future of nuclear power. Atomic Industrial Forum. 80/11/03. 2pp. 07845:204
- 8103160201 Staff requirements memo re B10305 Affirmation Bession 81-9. Directs FR publication of rulemakings re therapeutic treatment of cardiac dysfunction by I-131 & environ radiation protection stds.
  CHILKS J. Office of the Becnetary of the Commission M810303D.
  81/03/06 3pp. 07918:321.
- 8103160310 Transcript of 810303 public meeting w/representatives of ruclear insurance pools in Washington, DC. Pp. 1-35 . Commissioners, 81/03/03. 37pp. 07921:345.
- --Bi03160316 Requests that Commission not publish preference for change in endorsements eliminating licensee waiver of liability claims w/o discussion w/insurance pools.

  BARDES, C. R. American Nuclear Insurers. 81/01/29. 2pp. 07922: 022
- --Bi03160325 Responds to Bi0129 request for delay in publication of notice of preferred Commission alternative re endorsement. Notice published on Bi0218 Meeting w/insurance pouls scheduled for Bi0303 in Washington.OC. CENTON: M. R. Office of Nuclear Reactor Regulation, Director 81/02/25 ip. 07922:024.

- 8103160497 Commission determination releasing transcript of 800718 closed neeting in Washington DC re FYBD budget review Ofc of Executive Director for Operations/Division of Contracts overvier. CHILK. B J Office of the Secretary of the Cormission 81/03/02 55ap. 07915 311
- 8103160574 Transcript of 810227 Affirmation/Discussion Session 81-8 in Washington, DC Pp 1-5

  # Commissioners 81/02/27 Sno 07917 004
- 103040155 SECY-B1-043
  Seets Commission approval of proposed amends to 100FR: & 2
  to implement delegation of DL antitrust determination to
  Directors of Dfc of Nuclear Reactor Regulation & NRSS Draft
  FR notice & text comparison encl.
  DIRCKS.M.J. Office of the Executive Director for Operations
  81/01/19. 30pp. 63074 027.
- --8103040162 SECY-79-353 Beets Conmission approvel of delegation of authority for determination of significant changes at OL antitrust review stage 5 informs of revised OL antitrust review procedures stage of inverse to revised of activities review procedures
  Procedures & draff memo encl
  DENTON, H. R. Office of Nuclear Reactor Regulation, Director
  DIRCKB, W. J. Office of Nuclear Material Bafety &
  Safeguards, Director 79/03/24, 13pp. 65074-034
- --Bi03040170 Delegates authority to make significant change determination for OL antitrust review Review procedures & draft itr to Congress encl. . Commissioners, 79/09/12 Bon 65074-066.
- --8103050865 SECY-81-077 103050865 SECY-01-077
  Requests Commission approvel of notice of final rulemaking to dispose of wester containing tracer levels of H-3 & C-14 w/o regard to radioactivity & to raise limit for disposal in sewerage sys Draft final rule encl. DIRCKS,W.J. Office of the Executive Director for Operations 01/01/28. 71pp 65082 001
- --9103160395 SECV-91-0778 Forwards Ofc of Policy Evaluation 810219 name re preparation of negative declaration & EIS in support of proposed final rule to amend 10CFR20 re radwaste disposal Radiological impact analysis was misinterpreted Action is unwarranted DIRCKS.W.J. Office of the Executive Director for Operations BI/02/24 2pp. 07917.016
- --BIO3160404 Recommends preparation of negative declaration & EIS in support of proposed final rule to amend 10CFR20 re raduaste disposal Environ impacts of proposed rule are long-lasting & HANRAMAN, E.J. Office of Policy Evaluations. 81/02/19 2pp 07917: 018.
- Discusses proposed final rule to amend toCFR20 re disposal Discusses proposed rinar rule to amend (OCRR20 re disposal of tritium & C-14. Even if assessment of secur release amend was in error by couple of orders of magnitude collective doses & health effects are still negligible.

  DIRCKS-H.J. Office of the Executive Director for Operations B1/02/20. 3pp 07917.020.
- -- 8103160446 Informs that proposed final rule to amend IOCFR20 may be subj to legal challenge Inadequacies exist in analysis supporting conclusion that environ effects of rule would be insignificant Attachment 2 of value/impact statement encl. MALSCH, M Q Office of the General Counsel 81/02/09. 13pp 07917 023
- --8102260120 SECY-81-100 Requests Commission approval of enci draft FR hotice announcing withdrawal of proposed rulemaking on burden of proof in anforcement proceedings
  DIRCKS.W.J. Gffice of the Erecutive Director for Operations
  BICKS.D.Y. 2pp 65028:193.

- --8007070498 SECY-80-212 Recommends that Commission approve publication of final rule arending 10CFR2 732 re burden of proof Proponent of order in enforcement action has burden of croof Notice of proposed rule & FR notice encl. BHAPAT-H K Office of the Executive Legel Director 80/04/25 15pp. 02883-300
- --Bi02260130 Advises that Commission has disapproved recommendation in SECY-80-212 re burden of proof in enforcement processings. Draft FR notice of withdrawal of proposed rulemaking encl CHILM. B J Office of the Becretary of the Commission 80/06/20 4pp 6502B 196
- 8103170013 Unofficial transcript of 810218 meeting in Washington DC re SECY-81-20/20A policy on proceeding u/pending CP & mfg license applications Pp 1-91 Viewgraphs & add) TMI-related requirements enci = Gommissioners 81/02/18 99pg 07933 098
- 8103170309 Transcript of 810305 meeting in Washington, DC re discussion of revised licensing procedures Afternoon session Pp 1-71
  • Cormissioners, B1/03/05 74pp, 07923 219
- -- B103170314 Forwards revised draft proposed statement of policy re possible improvements in licensing proceedings
  COTIER B.P. Atomic Safety and Licensing Board Panel. 81/03/05. 11pp 07923-293
- B103170321 Transcript of B10304 meeting in Hashington.DC re discussion of policy.planning & program guidance for FY83-87.Pp 1-27.

  \* Commissioners. 81/03/04. 30pp. 07923 320.
- --8103170326 Forwards marked up "Policy Planning & Program Guidance (PPPO) Comparison of FYB2-96 PPPO H/Draft FYB3-87 PPPO " HANRAHAN, E. J. Office of Policy Evaluations. 81/02/27 47pp.
- A103170668 Transcript of 810305 Affirmation Session 81-9 in Washington, DC. Pp 1-2
  - Commissioners 81/03/09 500 07930:270
- --8102280183 SECV-81-094 Requests Commission approval of publication of draft FR notice for public comment re NRC intention to retain therapeutic treatment of cardiac dysfunction w/1-131. Retention does not violety FDA rules DIRCKS.W J. Office of the Executive Director for Operations 81/02/05. 7pg 45042:169
- --B10228018A SECY-29-542 Recommends Commission approval of encl draft FR notice for public comment re NRC intention to retain therapeutic public corment re NAC intention to retain therepeutic treatment of cardiac dysfaunction w/I-IDI. Related info & draft FR notice re SECY-81-094 encl. MINDOUS R. B. Diffice of Standards Development: Director. 79/09/20. 24pp. 65042.175.
- --8101190671 SECY-80-545 Recommends Commission approval of final amends to 10CFR20 to implement EPA environ radiation protection stds for nuclear power operations. Draft FR notice & Congressional ltr encl. DIRCKB.W.J. Defice of the Executive Director for Operations 80/12/19 | Topp. 03891:101
- 8103170679 Unofficial transcript of Commission 810218 meeting in Washington. CC to discuss & vote on SECY-81-13, systematic safety evaluation of all currently operating nuclear gower reactors Pp 1-70.
  • Commissioners 81/02/18 72pp. 07929:256.
- --BiO31706B2 Recommends deferral of Commission decision re adoption of rule governing systematic safety evaluation of all currently operating nuclear power reactors, until 810227 subcommittee hearing. UDALL M K. House of Rep. 81/02/18. 1p. 07929.329.
- --8103170688 Submits revised plans to implement requirements per Section 110 of NRC 1980 Authorization Act Coordination of operating plant reviews discussed minimizing fluctuations in NRC review requirements & optimizing resources. H/encl DIACKS.W.J. Office of the Executive Director for Operations. 81/02/17. 4pp. 07929:330.
- --8103120093 Recommends development of changes to proposed plan & final rule to clarify systematic evaluation of all currently operating reactors.
  DIRCKS.W.J. Office of the Executive Director for Operations. B1/02/04. 2pp. 65107:235.

- 8103170484 Staff requirements memo on 810218 discussion of GECV-R1-20/20A re colicu on proceeding w/pending CP & mfg becomes adviced reposity on proceeding wypending the emegations of the sepanded ref to NUREG-0718.

  CHILKS J Office of the Becretary of the Commission M810218A 81/02/20 3pp. 07930-227
- 8103170690 Staff requirements memo re 810218 Affirmation Session 81-6 Directs FR publication of notice suspending NRC procedural assistance program & encl draft notice re NRC.

  CHILK.B J. Office of the Becretary of the Commission H810218C CHILK. B J. Office of the E 81/02/20 3pp. 07930:140.
- BIO3170715 Transcript of BiO309 meeting in Washington, DC re discussion of policy planning & program guidance for FVB3-B7. Pp 1-27 \* Commissioners. B1/03/09. 28pp. 07927:011
- 8103170720 Transcript of 810305 meeting in Washington, DC re continued discussion of revised licensing procedures Morning session. Pp 1-24
- Complesioners, 81/03/05, 27pp. 07927.041.
- B103170730 Transcript of B10227 briefing on hearing schedules in Washington, DC. Pp I-28
  + Commissioners 81/02/27 31ss. 07927 073
- Bi03170734 Unofficial transcript of Bi0218 public Affirmation/ Discussion Bession Bi-6 in Washington.DC.Pp 1-4. \* Commissioners BI/02/18 7pp. 07927-104
- 8103170735 Unofficial transcript of 810227 discussion of application of hearing process to pending proceedings in Washington, DC. Pp 1-58
  • Combissioners 81/02/27, 61pp, 07927:111.
- 8103170742 Lists options to accelerate licensing process including 1031/0742 Lists options to accelerate licensing process includ MRC review process options, hearing process options & other options. Category of plants which would benefit include plants due to be completed in 1983 & bayond HANRAHAN.E J. Office of Policy Evaluations. BI/03/03. 11pp. 07927-175
- 8103170749 Transcript of 810226 meeting in Hashington.DC re briefing on Ofc of Nyclear Reactor Regulation licensing schedules. Pp 1-108.
  - Commissioners. 81/02/26 109pp. 07927:188.
- 8103180048 Transcript of 810204 public meeting in Washington, DC re discussion of preliminary policy considerations in development of safety goal Pp 1-47. • Commissioners. 81/02/04 48pp. 07942:080.
- --BI01200449 SECY-B0-551 Recommends approvel of encl draft FR notice of preliminary palicy considerations involved in developing safety goal. HANRAHAN.E J. Office of Policy Evaluations. B0/12/29. 28pp. 03902 154
- --B101200623 BECY-B0-551A
  Forwards draft NUREO, "Toward Bafety Qual:Discussion of Preliminary Policy Considerations." & recommends Commission approval.
  HANRAHAN.E J. Office of Policy Evaluations. 80/12/30 82pp. 03901:211
- 8103180060 Transcript of 810309 meeting in Hashington. BC re-briefing on programmatic EIS for TMI. Pp 1-68.

   Commissioners. 81/03/09. 66pp. 07942:213.
- --B103180071 SECY-81-133 Provides Commission w/programmatic El8, "Decontamination & Disposal of Radwastes Resulting From Mar 28,1979 Accident at TMI-2," & proposed statement of policy by Commission on 813 DIRCKS.W.J. Office of the Executive Director for Operations. 81/02/27. 5pp.
- B103180108 Transcript of B10211 meeting in Hashington, DC for briefing on LOFT Review Group.Pp 1-70.

  \* Commissioners. B1/02/11. 55pp. 07943:052.
- --8102020497 Recommends continuation of LOFT facility test program beyond FY83 w/emphasis placed on development of reactor safety analysis tests for operational extreme condition limits. Cost effectiveness of program results should be assessed. FINLAYBON, F. C. Aerospace Corp. 81/01/29. App. 07597: 276.

- --Bi01230369 Bolicits comments re continued operation of LDFT facility Efforts include addressing specific regulatory needs thow results of LDFT propriem are expected to satisfy needs Comments due Bi0101 Charter & review group membership encl RDBB.D.F Division of Systems Integration. B0/12/08. 2pp. 03905-145.
- --Bi01230371 Comments on NRC FYB2 budget Funding levele considered are those allocated by Ofc of Ejecutive Director in B00702 preliminary markup & requested by Ofc of Nuclear Regulatory Research B00709 PLEBBET, M. S. . ACRS - Advisory Committee on Reactor Safeguards. 80/07/17, 10pg, 03906:147
- --8103180146 "Presentation to Commissions of NRC:LOFT Test Program " MINDOUF P Office of Standards Development, Director. 81/02/11. 1200. 07943-151
- 8103180178 Unofficial transcript of 810212 meeting in Washington, DC re ATWS police Po 1-84. Commissioners. 81/02/12 86pp. 07945.078
- --8103180188 Forwards draft EIA for proposed rule amending 10CFR30, "Domestic Licensing of Production & Utilization Facilities," re ATHS events, EIS not required.
  DIRCKS, W.J. Diffice of the Executive Director for Operations, 81/02/03. 1p. 07945:166.
- --BIO3180176 Draft EIA for proposed rule to amend 10CFR50 re ATMS events. tosionito une transcriptori EIS not required.

  \* NRC - No Detailed Affiliation Given. 81/02/03. 18pp.
- --8103180207 Forwards revised FR notice on SECY-80-409 re 10CFR30 amend. "Domestic Licensing of Production & Utilization Facilities, per 801207 memo about ATMS events Changes in discussion section included. DIRCHS.W.J. Office of the Executive Director for Operations. 81/01/29. 41pp. 07945:185.
- --8103180224 Comments on NRC evaluation of proposed ATM8 rule per 801219 memo. Proposed rule should be published recognizing limited interia rule option to deal w/potential for ATM8 occurrence in BMRs w/Mark I & II containments.
  MINDQUE.R.B. Office of Nuclear Regulatory Research, Director. 81/01/28. 2pp. 07949:226.
- --Bi03180236 Presents summary of findings re ATMS calculations per B01110 request. Detailed presentation of Bys & Reliability Research Div review of ATMS calculations encl. MIMOOUE,R.B. Office of Nuclear Regulatory Research, Director. 80/12/19. 2pp. 07945:228.
- --B103180248 Submits detailed summary of review & comment re ATWS calculations per B01110 request Viewgraphs enci. ROMSOME, F. H. Office of Nuclear Regulatory Research, Director. B0712/15. dep. 07945:230.
- BIO3190075 Unofficial transcript of BIO311 meeting in Washington DC re-discussion & possible vote on full power license for Farley.Pp 1-36. Commissioners. BI/O3/11. 37pp.
- 8103190086 Ack receipt of 810102 patition requesting NRC to order licenses to show cause why OLs S/or CPs should not be revoked pending demonstrated financial ability. Patition being treated under 10CFR2, 206, FR notice encl DENTON.H.R. Office of Nuclear Reactor Regulation, Director. B1/03/12. 1p. 07965; 116.
- --B103190097 Notice of receipt of petition re financial qualifications of nuclear power plant licensess, request for action under 10CFR2. 206.
  DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 61/03/12. ip. 07965:117.
- 8:00:190255 Unofficial transcript of 8:0305 meeting in Washington, DC re 8ECY-B1-20/20A policy on proteeding w/pending CP & mfg applications. Pp 1-23. Commissioners, 81/03/05, 24pp. 07954:235.
- 8103190260 Unofficial transcript of 810311 meeting in Washington DC re ravised licensing procedures. e Commissioners. 81/03/11. 84pp. 07955:271.
- 8103200834 Unofficial transcript of 810310 meeting in Washington.DC re-revision of licensing procedures.Pp 1-57. e Cummissioners. 81/03/10. 59pp. 07967:091.

- --Bi03200840 Forwards suggested changes to T Cotter draft proposed statement of policy sent to Commission on 810305
  SHAPAR.H R Office of the Executive Legal Director 81/03/09 19pp. 07967: 151.
- --Bi03200845 Forwards several charts to be used in discussion on licensing procedures
  BICKWIT, L. Office of the General Counsel 81/03/10. 7pp 07967 170
- 8103200883 Unofficial transcript of 810312 Affirmation/Discussion Session 81-10 in Washington DC Pp 1-12.

   Commissioners 81/03/12. 15pp 07967: 207.
- 8103230049 Unofficial transcript of 810312 meeting in Washington-DC r SECY-81-20/20/204/208 policy on proceeding u/pending CP & mfg license applications Pp 1-44. Commissioners. 81/03/12. 47pp. 07978:041
- --Bl03230072 SECY-B1-0200 Responds to requests from B10305 meeting re changes to Emcl 1 to BECY-B1-208.explanation of required studies. ent. 1 to DELY-BI-WUD-explanation of required studies, comparison of requirements for pending CPs.mgf licenses & current OL applications & preparation for further questions DIRCHS.H.J. Office of the Executive Director for Operations 81/03/11 6pp. 07978 088
- --B103230078 SECY-81-020C ADD 103x3v3/0 BELY-81-0x04 ADO Addenda adding Paragraphs 3 c & d to SECY-81-20C. • Office of the Executive Director for Operations. 81/03/11 1 07978:094
- 8103231037 Commission determination releasing transcript of 810205 closed meeting in Washington DC re response to congressional correspondence Pp 1-7.

   Commissioners, CHill. B. J. Diffice of the Betretary of the Commission 81/03/16 10pp 07973.026.
- 8103231041 Unofficial transcript of 810317 meeting in Washington DC r revised licensing procedures. Pp. 1-40.

  • Commissioners. 81/03/17. 62pp. 07973.036
- 8103240122 Blaff requirements memo re Commission 810309 discussion of 1032401#2 Starf requirements memo re Commission 810309 discussion proposed policy, planning & program guidance for FY83-87. Commission reviewed document through Section II.C 7.3. CHILK-8-J Office of the Secretary of the Commission M810309A 81/03/10 1p. 07989-342.
- 8103250089 Staff requirements memo re 810305 meeting in Washington.00 to discuss policy on proceeding w/pending CP & mfg licence applications. Language in rube endorsing NVREQ-0718 should be similar to revised statement of policy.

  CHILK-S.J. Office of the Secretary of the Commission. MS10303A

  81/03/10 fp. 07997-323.
- B103250095 Staff requirements memo re B10304 discussion of policy, planning & program guidance for FY83-87.
  CHILK: B. J. Office of the Secretary of the Commission. M810304 B1/03/09. 1p. 07997-320
- 8103310943 Unofficial transcript of 810325 meeting in Washington, DC t policy planning & program guidance for FY63-87.
  • Commissioners 81/03/25. 34pp. 08062:225.
- --B103310947 Forwards revised version of Bections I & II of policy, planning & program guidance document based on Commission last two neetings on subj.
  HANRAHANKE J. Office of Policy Evaluations. B1/03/20. 12pp. 08062:260
- ADVISORY COMMITTEE ON REACTOR SAFEQUARDS ACRR
- B103110332 Transcript of ACRS Subcommittee on Reactor Operations 810 meeting in Washington, DC re NUREQ-1580. Pp 1-77 Supporting measing an Americageon Do the NURGE-1380. Pp 1-77 Supporting documents & viewpraphs encl. ACRS - Advisory Committee on Reactor Sefeguards. B1/03/09 105pp 07882:039.
- meeting in Washington.DC. Morning session.Pp 1-184. ACRB Advisory Committee on Reactor Bafeguards. Bi/03/10. 186pp. 07901:005. 8103120345 Transcript of ACRS Subcommittee on Radioactive Matle 8103
- 8103120412 Transcript of ACRS Subcommittee on Reactor Operations 810310 meeting in Washington, DC. Pp. 78-393. Slide presentation encl. \*\* ACRB - Advisory Committee on Reactor Bafeguards Bi/03/10 277pp. 07902:001.

- 8103130497 Transcript of ACRB Bubcommittee un Redinactive Matte BIB III meeting in Washington DC Afternoon session Pp 189-269
  Vieugraphs enct
  w ACRS Advisory Committee on Reactor Bafeguards 8170,1710
  1910a
- U103160370 Transcript of ACRB 010312 291et general meeting in Maskington, DC re-Biate of Technology Rept of Fission Product Indine Pp 1-334

  \* ACRB Advisory Committee on Reactor Safeguards Bizolziz 335pp 07723 008
- B103180428 Transcript of 810313 ACRS 251st general meeting in Washington.BC Pp 335-563 Visupraphs ent1 4 ACRS - Advisory Committee on Reactor Bafeguards B1/03/13 254pp 07937-901
- U103180467 Transcript of ACRB Subcommittee on Reactor Radiological Effects B10311 meeting in Washington DC Pp 297-415

   ACRB Advisory Committee on Reactor Dafeguards Di/03/11 121on 0.7037 202
- 8103180481 Transcript of ACRS Subcommittee on Generic Items (1071) meeting in Washington, UC Pp 1-121 # ACRS - Advisory Committee on Reactor Bafeguards (1170,171) 150pp 07941 071
- 8103100647 Transcript of ACRS Subcommittee on Reactor Radiniughial Effects (10310 meeting in Washington DC Afternoon session Pp. 143-296 Violographs enct # ACRS Advisory Committee on Reactor (Lafeguards (11701/10 2600) 077441 116
- BIOD20027 Oubcits comments on Ofc of Bids Development (NOI2) response to ACRS BOILIO comments & recommendations re Reg Guide 1 97. Revision 2 Implementation schedule for Reg Guide 1 97. Revision 2. inadequate NARL J C. ACRE - Advisory Committee un Reactor Mefeguarde BI/OD/18 2p 07979 348
- --8102180822 Responds to ACRB comments on Modified Draft 3 of Heg Orisia 1 97.Revision 2, "Instrumentation for Light Hater Cooled Buclear Power Plants to Assess Plant & Environs Conditions During & Following Accident" ARLOTTO: O A Bivision of Engineering Standards 811/01/21 .hpp 039AA-001
- 8103230326 Recommends further NRC consideration of development of amergency plans & operability of equipment needed to deal w/ nuclear emergencies which result from natural disturbances HARK.J.C. ACRB Advisory Connectes on Reactor Dafaguards 03/03/16 sp. 07974-228
- UIO3230402 Discusses draft NUREQ-0772, "Technical Bases for Estimating Fission Product Behavior During LMR Accidents," Issuance of Mar ISOS draft NUREG-0771, "Regulatory Impact of Nuclear Reactor Accident Bource Term Assumptions," may be delayed MARI, J C. ACRB Advisory Committee on Reactor Bafeguards 01/03/17, 3pp. 07976-390
- BIO3230472 Bubmits summary of BIO312-14 ACRU meeting to discuse dreft NUREO-0666. "Probabilistic Bafety Analysis of DC Power Uupply Requirements at Nuclear Power Plants." NUREO is acceptable Reliability goals for dc sys should be developed MARK-J C ACRS Advisory Committee on Reactor Defigurade BI/03/17 | jp 07975-330
- O103230524 Submits info re status of generic items concerning tills ACRS will no longer meintain separate list of generic items from list in regis on applications for CPs or DLs MARK.J.C. ACRS Advisory Cormittee on Reactor Safeguards 01/03/17. 2pp 07977-274
- 0103270476 Transcript of ACRS Bubcommittee on Electrical Power Dye 010325 meeting in Hashington, DC. Pp. 1-223 a ACRS Advisory Committee on Reactor Safeguards 01/03/28 227pp 08031-216

COMMISSION BYC CONCLUSIONAL

- HIGHOZOOAO Lorwanda quanterly rept to compress to combine of field to permanent employees fitted to promotest for old dept two tournacy of minorities to window rised disting form fit to also end.

  Also end.

  Also end.

  Incompress tournaments to the compress of the compr
- HIO HUDGERO Entwords governerly rept to torgress includes in fully parenties to personal feeting on the fully governer to the property of a torgress to be seen that the following first the following for the following following for the following f
- BEAUTONIAN Exemperate quarterly rept to include the includes of the full permanent amplitudes hereal t promotes for the full lineway of winnighted to winner have a new first 12 to 40 and 14 a
- HIGHMAND DE Locumentarium of the state of th
- HID IDDOMES Income and a quantum in the confidence of the properties of the confidence of the properties of the confidence of the confiden
- HID NO PROPERTY AND A SECURITION OF STATE OF THE PERSON OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PERSON OF THE PER
- HID RIAO 197 Responds for errol to the life to the engages of rector espapes to the state of taking the state to the state of the state
- HICHTHIND Heapungs to Blow I request for easts etch of order requiby BINDP orders to Bell transfer or error specific eye Lousted grade specifics and of the country of operation at adequate codety mergi-DIKCHUMS I STEEL OF the Kinnights Innaches for sygnations HICHTHING SPECIFICS IN
- HIDIOTOTE I Magneste mesteration of near registers by orders to all licenses to seron distroge bys BRADIORD P.A. Trendssintors. Bird of 19 stock 495
- 0101050518 Buppl 1 to defety evelones on the Buff even descharge by a Commissioner BS-05-33 pp office and
- GIO 10 DOMI I Maspands to Mitch's life by injust of detend Assans draps of JRC France will impact upon ability for a point hage princetty programs is to most industry court 6 appearing assays as appearing an Amaders to apprecia quantum and out of the Amaders to apprecia quantum and out of the Amaders to apprecia quantum and out of the Amaders to appear in the Amaders and Amaders to appear in the Amaders and Amaders and and out of the Amaders and Amaders and and appear in the Amaders and Amader
- GLOTOROUTH Requisite the second of the second between the second of the leaders of the second of the
- USO 10 70 70 Maps by sinfo read flow was preary all addition of the free literary distants on the Distants of the USO 2024 and the USO 2024 an

- 8103100122 Requests partial exemption from hiring freeze Constitutional 5 statutory groscriptions may limit MRC ability to implement DMB Bulletin 81-6 in all areas Retroactive freeze may significantly impair NRC
- AMEARNE, J.F. Commissioners 81/02/11. 4pp 07853.180
- DSQ3100640 Forwards NUREO-0090.Vol 3. Number 3. "Rept to Congress on AOs. Jul-Bept 1980" One AO at licensed nuclear power plant involving failure of saltwater cooling sys Three AOs reported by Agrasment States.

  AMEARNE.J F Commissioners. B1/02/20 1p 07865 308.
- --8103100655 Forwards NUREO-0090. Vol 3. Number 3. "Rept to Congress on ADs. Jul-Sept 1980" One AD at licensed nuclear power plant involving failure of salt water cooling sys Three ADS reported by Agresment States
  AHEARNE. J F Commissioners. 81/02/20. 1p 07865 309
- 8103100u93 Heekly info rept for wk ending 810227 REHM,T A Office of the Elecutive Director for Operations 81/03/04. 38pp. 07862.151
- BIO31100B5 Identifies remaining actions needed for timely amend to U mill Agreement State program Requests timetable outlining actions to resolve all issues as soon as possible Amend application should be submitted by BIO801 Criteria encl AHEARNE. J F. Commissioners 81/02/20 14pp 078B4 330
- 8103110091 Responds to 810105 ltr re NRC first monthly status rept on efforts to carry out licensing & regulatory duties Forwards answers to specific questions raised re emergency planning & safety issues.

  AHEARNE J F. Commissioners. 81/02/23 13pp 07885:261
- --2103110109 Forwards questions re NRC first monthly status rept on efforts to carry out licensing & regulatory duties. Requests response by 810131 to assist in review of NRC FY82 budget request UDALL-M K House of Rep , Interior & Insular Affairs. 81/01/05 350 07885-274
- 8100110119 Forwards NRC B10109 order for mod of license re BWR scram discharge sys & suppl to B10109 discharge sys safety evaluation. Buppl provides evaluation of continued operation while order mods are being implemented AHEARNE, J.F. Commissioners. 81/02/20 1p 07885-277.
- --8103110137 Forwards suppl to BWR scram discharge sys safety evaluation providing basis for continued operation of affected BWRs while mods are baing made CHECK.P. B Assistant Director for Plant Systems. 81/01/12 2pp 07887-380
- 8103120827 Responds to FDIA request for final repts re investigations of causes & sources of radiation exposures suffered by licensed users of radioactive devices in DK during past yr Forwards documents listed in app. FELTON.J.M. Division of Rules and Records. 81/03/05 2pp 07901:341.
- --8103120839 Weekly info rept for wk anding 810206 REHMITA. Office of the Executive Director for Operations. 81/02/11. 2pp
- B103160570 Forwards rept on administration of FOIA by NRC for CYBO.per Public Law 93-502 AHEARNE, J. F. Commissioners. B1/02/26. 1p. 65119: 284
- ~~81031à0à19 Forwards rept on administration of FDIA by NRC for CY80, per Public Law 93~502 AHEARNE, J. F. Commissioners. 81/02/24. 1p. 65119-285.
- --8103160627 Forwards rept on administration of FOIA by NRC for CY80. per Public Law 93-502. AHEANE, J. F. Commissioners. 81/02/26. Ip. 65119:286.
- ---8103160633 Forwards rept on administration of FOIA by NRC for CY80, per Public Law 93-502.
  AHEARNE, J. F. Commissioners. 81/02/26. 1p 69119:287.
- --BIO3160643 Forwards rept on administration of FOIA by NRC for CY80, per Public Law 93-502.

  AHEARNE, J. F. Commissioners. 81/02/26 1p. 65119.288
- --8103160648 Forward: rept on administration of FDIA by NRC for CY80, per Public Law 93-502.

- 8103170016 Weekly info rept for ut ending 810305 REHM.T.A. Office of the Executive Director for Operations 81/03/11 35pp 07939-112
- BIO3170306 Requests that IE travel be exempt from reduction outly DMD Bulletin B1-7 Proposed reduction would directly restrict frequency 8 scope of activities performed by IE personnel AHEARNE, J. F. Commissioners 81/02/26 2pp. 07934 332
- 8103170713 Corrects answer given at 810219 subcommittee meeting a private corps worked for during past 10 yrs Commissioner Hendrie has worked for nonprofit corp. Associated Univs. Inc. for part of last 10 yrs MENDRIE. J M. Commissioners. 81/02/24 10. 07930, 148.
- B103180600 Advises that NRC will participate in President's Executive Exchange Program through placement of exchange executive from private sector in Commission of Court host position description encl.

  AHEARNELUE Commissioners. B1/02/26 3pp 07993.343
- --BIO3180601 Requests NRC participation in President's Ejecutive Exchange Program for 1981-82 CASSIDY, L. M. President of US & Executive Offices B1/01/15 07953 346.
- --BIOJIBO602 Requests that Executive Exchange Program be publicity within NRC Nominations are due on BIOJO2 White House memo encl CABSIDY.L M President of US & Executive Offices. BO/10/29 0793-348
- B103200061 Responds to 810209 ltr re neetings w/citizens groups to broaden outreach & discuss perspectives on future of nuclear regulation Agrees to meeting to discuss similar catters w/scientific groups.
  HENDRIE.J M. Commissioners. B1/03/06 1p 07972 175
- --810320006B Requests public mesting between NRC & scientific groundiscuss future of nuclear regulation SELTZ:F Scientists & Engineers for Secure Energy 81/02/09 4pp. 07972:176
- 8103240009 Transmits draft bill to amend Atomic Energy Act of 1950 clarify that Commission may issue license amend which involves no significant hazarda consideration w/o holding
- prior hearing.
  #ENDRIE.J.M Commissioners. 81/03/11 2pg. 07990 298
  --8103240013 Transmits draft bill to amend Atomic Energy Act of 19
- clarify that Commission may issue license amend which involves no significant hazards consideration w/o halding prior hearing. HENDRIE J. M. Commissioners. 81/03/11. 2pp 07990 300.
- --BI03240018 Transmits draft bill to amend Atomic Energy Act of 19 clarify that Commission may issue license arend chich involves no significant hazards consideration w/o holding prior hearing.

  HENDRIE, J. M. Commissioners. Bi/03/11 2pp. 07990 302
- ---Bi03240022 Transmits draft bill to amend Atomic Energy Act of 1starify that Commission may issue licanse arend which involves no significant hazards consideration w/o holding prior hearing.
  HENDRIE, J. M. Commissioners. 81/03/11 2pp 07990:304
- --BIO3240028 Transmits draft bill to amend Atomic Energy Act of 19 clarify that Commission may issue license amend which involves no significant hazards consideration w/o holding prior hearing.

  HENDRIE, J. M. Commissioners. 81/03/11, 9pp 07990:306.
- 8103240124 Responds to 810129 ltr expressing concern re-slippage of issuance date for facility SER Commission will neet w/ staff to discuss hearing process on 810225 & licensing schedules on 810226.

  AHEARNELJ F. Commissioners. 81/03/03. 2pp
- 8103240129 Ack receipt of draft. "Learning Function in Nuclear Rec Operation & Implication for Siting Policy." HENDRIE.J.M. Commissioners. 81/03/09. ip 07989:260.
- ---8103240134 Forwards draft 'Learning Function in Nuclear Reactor Operation & Implications for Siting Policy, " W/o encl. WEINBERG.A.M. Cas Ridge Univs. 81/03/02. 1p 07989.261.

- 8103240135 Requests 1-ws extension to submit rept identifying steps which Commission could take to especite literating process. discussed in 810217 its 810217 meeting KAMMERER.C. Office of Congressional Affairs 81/03/02.
- 8102200170 Forwards for recommended implementation in research reactor reviews. 'Environ Considerations re Ranewal of Licenses for Research Reactors." based on 740128 memo per 801124 request VOLLMER.R H Assistant Director for Environmental Technology 80/12/31 4pp 07734.174
- BiO3240139 Declines BiO213 invitation to meet & discuss UB nuclear licensing scene, due to heavy workload.
- --B103240143 Requests B10331 meeting to discuss US nuclear licensing scene
  ROSER.T. Germany, Federal Republic of B1/02/13 1p 07989-253
- B103240246 Forwards NUREO-0755, "Rept to Congress on Status of Emergency Response Planning for Nuclear Power Plants." Bacisfies Section 109, Public Law 96-295 FENDRIE. J M. Commissioners 81/03/10 ip 07980-254
- --B103240214 Forwards NJREQ-0755. "Rept to Congress on Status of Emergency Response Planning for Nuclear Power Plants." Satisfies Section 109-Public Lew 96-295 HENDRIEL JM Commissioners 81/03/10. lp. 07980-295
- --B103240260 Forwards NUREG-0755, "Rept to Congress on Status of Emergency Response Planning for Nuclear Power Plants " Satisfies Section 109, Public Law 76-295. HEIDRIE, J. M. Commissioners 81/03/10 ip. 07980:296
- --BI03240267 Forwards NUREG-0795, "Rept to Congress on Status of Emergency Response Planning for Nuclear Power Plants." Satisfies Section 109. Public Law 96-295.
  HEXDRIE.J M. Commissioners. 81/03/10 1p. 07980.237
- --8103240269 Forwards NUREG-0755, "Rept to Congress on Status of Emergency Response Planning for Nuclear Pawer Plants." Satisfies Section 109-Public Law 96-295 HENDRIE, J.M. Commissioners 81/03/10. 1p. 07980.258.
- ---BiD3240272 Forwards NUREO-0755, "Rept to Congress on Btatus of Emergency Response Planning for Nuclear Power Plants." Batisfies Section 109 Public Lew 96-295 HENDRIE, J M. Commissioners. Bi/03/10. ip 07980.299
- -8103240278 NUREQ-0755
  REPORT TO CONGRESS ON STATUS OF EMERGENCY RESPONSE
  PLANNING FOR NUCLEAR POWER PLANTS

  Division of Emergency Preparedness. 81/03/31. 107pp.
  07985:016
- --Bi03240284 Draft "Analysis of Evacuation Time Estamates Around 32 Nuclear Power Plant Sites: "Vol 1. URBANIK.T. Texas A 8 M Univ. 80/10/31. 149pp 07985.105.
- --8103240289 Draft "Analysis of Evacuation Time Estimates Around 52 Nuclear Power Plant Sites." Vol 2 URBANIA. 7. Texas A & M Univ. CUMMINGS.P.L., DEBROBIERS.A.E. Battelle Memorial Institute, Pacific Northwest Laboratory 80/12/31. 109pp. 07985.255.
- Bi03240659 Responds to B0i202 ltr citing concerns expressed in M Levenson & F Rahn paper re consequences of nuclear accidents. NRC status rept re state of technology of iodine release will be completed in Mar.

  AMEARNE, J. F. Commissioners. Bi/02/10. 2pp 07982:286
- --B10303000B Requests comments on "Realistic Estimates of Consequences of Nuclear Accidents," by M Levenson & F Rahn Rept has patential of being most important study to follow accident at TMI.

  LEWIS.F. W. Middle South Utilities. Inc. 80/12/02. 3pp.
- B103260042 Withdraws from Mar 1981 meeting at Univ of Technology of Aachen. HENDRIG-J.M. Commissioners. B1/03/09. 1p. 08040:066
- B103260386 Forwards draft bill to amend 1954 Atomic Energy Act allowing Commission to issue interim OL authorizing fuel loading & low power operation & testing in advance of completion of recorded evidentiary hearing re

- B103260419 Responds to B00727 Itr re-potessium iodide use to protect thursid from radioactive iodine & improved reactor containment design Potassium iodide use remains under study Controlled venting of containment is being studied. >>ENDRIE.J M Commissioners B1/03/12 2pp. 08040.333.
- --B103260429 Discusses potassium iodide use to protect thyroid from radioactive iodine & improved reactor containment design.NRC uill not take action, even after yrs of study.

  VON HIPPELF Princeton Univ. B0/07/27 3pp. 08040 335.
- 8103260576 Forwards summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC HENDRIE: J M Commissioners. 81/03/17 ip 08037 268.
- --BIOJ2605B1 Forwards summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC. HENDRIE. J. M. Commissioners. B1/03/17. Ip 08037.269.
- --BI032605B3 Forwards summery of actions taken by NRC in response to recommendations in Comptroller General 1980 repts ra NRC HENDRIE.J.M. Commissioners 81/03/17. 1p. 08037:270.
- --8103260586 Forwards summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC. RENDRIE, J. H. Commissioners 81/03/17, ip 08037:271.
- --Bi03260591 Forwards surmary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC. HENDRIE-J M. Commissioners. 81/03/17, ip 08037.272
- --8103260594 Forwards summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC HENORIE, J. H. Commissioners 81/03/17, 1p. 08037:273.
- --B103260396 Forwards summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts to NRC HENDRIE, J.M. Commissioners. 81/03/17. Ip. 08037: 274.
- --Bi03260599 Forcerds summary of actions taken by NRC in response to recommendations in Comptroller General 1980 repts re NRC. HENDRIE, J. N. Commissioners. Bi/03/17. 33pp. 08037: 278.
- 8103260985 Heekly info rept for wk ending 810313. REHM.T.A Office of the Executive Director for Operations. 81703718. 47pp. 08035:175.
- 8103261149 Notifies that to continue U mills & mill tailings regulati after Nov 1980, agreement states must enter into amended agreement w/NRC Requests that State of CA submit application for amend by B10701. Hodel amend enci. HENDRIE.J. M. Commissioners. 81/03/17. 24pp.
- 8100254152 Notifies that to continue U mills & mill tailings regulati after Nov 1980 agreement states must enter into amended agreement w/NRC. Requests that State of OR submit application for amend by 81070; Model amend enci. HENDRIE.J M. Commissioners. 81703/13. 41pp.
- 8103261157 Ack efforts of State of NV Dept of Human Resources in processing State of NV amended agreement w/NRC. Identifies remaining actions to be accomplished for amended agreement. Requests formal amend application by 810701. #ENDRIE.U.M. Commissioners. 81/03/16. 24pp. 08037:138.
- --8103261164 Discusses consequences of ACRS recommended phase-out of at end of FYB1.LOFT answers current & potential reactor safety questions & must continue testing until resolution reached

  WILLIAMS, C.E. Energy, Dept. of. 81/01/19. 5pp. 08037:162.
- 8103261190 Responds to 810205 request for delay of issuance of 10CFR6 re licensing procedures for radwasts disposal until policy changes made by current administration. Delay in issuing rule could slow nati waste program development.

  HENDRIE, J. M. Commissioners. 81/03/13. 2pp. 08040: 237.
- --Bi03261199 Responds to Bi0205 request for delay of issuence of 10CF re licensing procedures for radwaste disposal until policy changes made by current administration, Delay in issuing rule could slow nat! waste program development.

  HENDRIE: J. M. Commissioners. 81/03/13 2pp. 08040:239.
- --8103261204 Urgas NRC to postpone final action on proposed rule re radwaste disposal until administration fully appraises NRC

```
obligations for each program ofc.
HENDRIE, J. M. Commissioners. 81/03/16. 10. 08037-044
--BIO3261209 Forwards NRC rept on PYBO contract activity per Public Law 95-901 Rept identifies status of commercial contracts DOE task orders & interagency agreements & corresponding obligations for each program of HENDRIE, J. M. Commissioners 81/03/16, 92pp. 08037-045.
BIO3270007 Ack receipt of BIO202 memo re legislative coordination & clearance per DMS Circular A-19. Nonbudgetary proposals do not require DMS approval Forwards relevant agency response, dtd June 1980 re dMS clearance process.

HENDRIE-J. M. Commissioners 81/03/17 1p.
--8103270010 Discusses executive order regovt regulation process.

DA Stockman memo re legislative coordination & clearance
         CARTER, J. President of US & Executive Offices 78/03/23 App.
8103270927 Responds to 810210 & 13 requests for info re improvements
 11032/074/ Responde to B10210 & 13 requests for info re improve in licensing review process. Recommendations include restoration of immediate effectiveness rule, firm policy on expediting cases & amends to discovery rules DIRCKS.N.J. Office of the Executive Director for Operations B1/02/23 9pp. 08043-335.
--8103160485 SECY-81-111
       inusious sect-81-111
Forwards draft rule raising threshold for admissibility of contentions in NRC hearings. Rule should be approved as subj for further Ofc of General Course! (OOC) study OOC should rept conclusions & recommendations.
BICKHIT.L. Dffice of the General Course! 81/02/17 4pp. 48144-923
```

B103261205 Forwards NRC rept on FY80 contract activity per Public Law

103261203 rorwards NNC rept on Frau contract activity per P 95-901.Rept identifies status of commercial contracts.DDE task orders & interagency adresments & corresponding

# CONTRACT NRC CONTRACTS AND MODIFICATIONS

B102260479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NM.AZ.CO & HY.
Forwards Documents 1-17 listed in app. Document 1B may be obtained from NTIS. FELTON, J. M. Division of Rules and Records. 81/02/05 2pp.

--Bi02260692 Forwards request for procurement DBD-78-014 to execute mod to contract NRC-01-78-014. "Apparent Cancer Incidence in Mesa County, CD, 1970-75." MINDOUE, R. B. Defice of Standards Development, Director. 78/08/18.

--B103020746 Request for procurement OBD-78-014 to execute mod to contract NRC-01-78-014, "Excess Center Incidence in Hesa County." Contractor: CD Dapt of Health. MINGOUSE.R.B. Office of Standards Development, Director. FIN B-10728. NRC-01-78-014. 78/08/18. 4pp.

--8102260703 Requests mod to NRC-01-78-014 to reflect changes in Mesa County cancer research study design. Includes revised scope of work No change required in contract budget. FERGUSON:8. Colorado: State of. 78/08/01. 7pp.

---7911050328 Forwards request for procurement action. Recommends that NRC cover overrun.
MINDOUE, R. B. Defice of Standards Development, Director. 79/09/25. ip. 00887:350.

--7911050330 Request for procurement DBD-78-014 to execute mod to contract NRC-01-78-014, "Excess Cencer Incidence in Mese County." Contractor: CD Dept of Health. MINDOUELR. B. Office of Biandards Development, Director. FIN B-10728. NRC-01-78-014, 79/09/25, 4pp. 00887:351. 8102270565 Notification of contract execution, Mod 2 to "Environ Monitoring Program W/Commonweelth of PA." Contractor: Commonweelth of PA.

Summunevation of PA. BAISDEN.L. Research Contracts Branch. FIN B-5111. NRC-05-80-272. 81/01/07. Ip. BIO3030163 Notification of contract execution.Mod 2 to "Microfiche Sycs:Oak Ridge.TM." Contractor:Microtech Industries.Inc. HAGAN.T.F. Administrative Contracts Branch. NRC-10-79-658. BIO2283. 19. 07790:279.

Bi030302049 Notification of contract execution Mod 7 to "Transport/ Pised Bite Vulnerability Analysis." Contractor: US Army,

109040282 Hod 7. extending period of performance to Bil231.scope of upri-estimating cost to obligating funds to 'Transport/Fixed Bits Vulnerability Analysis''

MARECEK. 9 Army, Dept of, MATTIA, M. J. Administrative Contracts
Branch. FIN-8-1536-1 NRC-02-76-0311 BI/02/01. 2pp 8103030319 Notification of contract execution. Mod I to "Technical Assistance for EIS on 100FRA1." Contractor Dames & Hoore HAIRSTON.C., SHITH.P.A. Technical Assistance Contracts Branch 8-7312. NRC-02-81-049. 01/01/16 1p 07790 232.

--B103030282 Mod 7. extending period of performance to B11231. scope of

--Bi03000331 Mod 1, increasing monetary limitation definitizing unprice order into priced contract & adding terms & conditions to "Technical Assistance for EIS on 10CFR61."
CLINE.J.C. Bases & Moore. MATTIA.H.J. Administrative Contracts Branch. FIN 8-7318-1 NRC-02-81-049 81/01/16 33pp. 07790 233. B103040563 Notification of contract execution.Mod 1 to "Presentation of QE BMR/6 Design & Operation Courses." Contractor: QE BAIBDEN, L Administrative Contracts Branch. Fin B-1224 NRC-05-80-282 81/02/20. 1p. 07810 350. --8103040572 Mod 1.changing course dates & 1981 funding for Article II to "Presentation of QE BUR/6 Design & Operation Courses."

• General Electric Co. MORTON.K.V. Research Contracts Branch FIN 8-1224 NRC-05-80-282 81/02/20. 1p. 07810 351.

B103040724 Responds to FDIA request for winning proposal under RFP-NRR 80-101. Forwards requested info.including proposal. H Dhillon 800804 itt to NRC, representations & certifications, proposal summary & data wheet & contract pricing proposal FELTON.J.M. Division of Rules and Records 81/02/10 ip 07370 079 07820 079 --Bi03040735 Forwards proposal in response to RFP-NRR-80-101. "PWR Severe-Accident Delineation & Assessment." Proposal summary & data sheet & representations & certifications encl DHILLOW.H California. Univ of. Los Angeles 80/08/04 14pp.

--B103040744 Response to RFP RS-NRR-B0-101, "PWR Bevere-Accident

(03040744 Response to RFP RS-NRR-BO-101). "PMR Bevere-Accident Delineation & Assessment " Proposes to perform analyses & assessments of specific water reactor safety-related issues. Includes technical approach & prof & related experience. KASTENBERO-W.E., WEBTHAN,R.A., DHILLON,H. California, Univ. of, Los Angeles RS-NRR-80-101 80/07/31. 97pp.

8103040727 FOIA request for winning proposal submitted under RFP-NRR-MACFARLANE, D.R. ETA Engineering, Inc. 81/01/12 1p. 07820:080. 8103040729 Notification of contract execution: "Environ Assessment of Raffinate Study Disposal at Kerr-McOes Bequoyab Facility. Gore.DK." auarded to Science Applications.inc. HAIRSTON.C.A. EDDEMORTH.P.J. Technical Assistance Contracts Branch FIN 8-7316. NRC-02-81-045. 91/02/20. ip. --Bi03040740 Contract: "Environ Assessment of Raffinate Biudy Disposal at Kerr-McGee Sequoyah Facility, Opre. DK" awarded to Science

Applications, Inc. FINDLEY, D.E. Brience Applications, Inc. MATTIA, M.J. Administrative Contracts Branch. FIN 8-7316 NRC-02-01-045 BiO3040749 Notification of contract execution Mod 3 to "Energetic Thermal Interactions Recriticality & Coolant Flow Phenomena Associated M/Advanced Nuclear Reactor Concepts." Contractor: Associates Arabaneous Rottes Reaction Contracts Contracts Branch Harreron, C.A., EDGEHORTH.P.J. Technical Assistance Contracts Branch FIN 8-6836. NRC-03-80-102. 81/02/24. ip. 07812:157.

--Bi03040764 Mod 3.adding funds obligated to contract under Article IV to "Energetic Thermal Interactions.Recriticality & Coolant Flow Phenocena Associated W/Advanced Nuclear Reactor e Purdue Research Foundation. MATTIA:M J. Administrative Contracts Branch. FIN 8-6836. NRC-03-80-102 81/02/24.

8103040831 Notification of contract execution.Mod 1 to "Consultant to LOFT Egecial Review Group." Contractor:H Isbin. LITTLE.M. Administrative Contracts Branch, FIN 8-7490. NRC-04-81-196. 81/02/19. 1p. 07812:178. --8103040860 Mod 1.changing amount of obligations, to "Consultant to Li Special Review Group. "
1883N.H. 8. Isbin.H. PERLMAN.J. Administrative Contracts Brench
FIN 8-7490. NRC-04-81-196. 81/02/19. 1p. 07812:179.

- BIO3040B92 Notification of contract especition. Mod 3 to "Evaluation of Entrainment Effects Using Power Plant Condenser Tube Simulator "Contractor NY State Energy RBD Authority JACOBS. A Research Contracts Branch FIN 8-6298 NRC-04-78-211 81/01/23 [g 07812-001
- --BIO3040890 Mod 3.extending period of performance from 801231 to 860130.to "Evaluation of Entrainment Effects Using Power Plant Condenser Tube Simulator."
  PRIME.H J. New York, State of KORTCILK V. Research Contracts Brench FIN 8-6298 NRC-04-78-211 BI/01/P3 ip 07812 002
- 8103040911 Notification of contract elecution Mod I to "Steam Generator Modeling During Reflood Stage of LGCA." Contractor MIT B9048ERO. B Research Contracts Brench FIN 8-7229 N9C-04-80-219 81702712 1p 07812 009
- --8103040919 Mod 1.ertending period of performance from 800930 to 810930 & increasing angunt of consideration to "Steam Generator Modeling During Reflood Stage of LUCA"

  DUNNER, G. H. Massachusetts institute of Technology MCRTCN. K. V. Research Contracts Branch Fin 8-7229 NRC-04-80-219 81/02/12 Sco. 07812 010
- BiO3050111 Notification of contract esecution "Bafety Design Criteria for Large (1,000 MH) LMFBR," awarded to P Zaleski FLECNOR.C M Administrative Contracts Branch FIN 8-1557 NRC-11-01-427 Bi/O2/23 1p 07827 295
- --BIO3050131 Contract "Bafety Design Criteria for Large (1,000 MW) LMFSR." avaided to P Zalesti ZALEEKI.P California. Univ of Los Angeles. PERLHAN.J Administrative Contracts Branch. FIN 8-1957 NRC-11-81-427. 81/02/23 5
- BIOCOSO144 Notification of contract execution.Mod 5 to "Technical Assistance Program for Thermal Hydraulic Blability Analyses re LWRs " Contractor Remsseleer Polytechnic Inst JACOBS. A Research Contracts Branch FIN 8-7230 NRC-03-78-128 BI/02/05 Ip 07827-347
- --BI03050157 Mod S, increasing allotted funds available for payrent, to "Technical Assistance Program for Thermal Hydraulic Stability Analyses re LWRs "
  LOGIUDICE. J M. Rensselser Polytechnic Inst. M9470N.K V Research Contracts Dranch FIN 8-7230 NAC-03-78-128 81/02/05. 1p
- 8103050166 Notification of contract execution. "Geotechnical Engineering Reviews of Operator Reactor Plants." a\_arded to US Army Corps of Engineers. GLAGOLA-A F. Technical Assistance Contracts Branch FIN 8-6882. NRC-03-81-121 81/02/12 1;
- --8103050178 Contract "Geotechnical Engineering Reviews of Operator Reactor Plants," awarded to US Army Corps of Engineers FRIEDEN-ALD.R Army. Dept of. Corps of Engineers MATTIA.M J Administrative Contracts Branch FIN 8-6882 NRC-03-81-121 81/02/12 7pp
- 8103350175 Notification of contract esecution Mod 1 to "Microfiche Produce " Contractor Computer Microfilm Intl Corp. HAGAN T F Administrative Contracts Branch. NRC-10-77-124 81/02/12 1p 07825-183.
- --BIO3030182 Mod 1, deabligating funds to "Mitrofithe Produce."
  REED, C Computer Microfilm International Corp. LEBO. C D
  Administrative Contracts Branch. NRC-10-77-124 81/02/12 lp.
  0785-184
- 8103050190 Notification of contract execution: "Evaluation of NRC Bilateral Regulatory Info Exchange Arrangements," aparded to Labouit: & Labouit: Lattie: M. Administrative Contracts Brench. FIN B-1657. NRC-08-81-326. 81/02/26. 1p. 07825.190
- --9103030199 Contract. "Evaluation of NRC Bilateral Regulatory Info Exchange Arrangements" awarded to Lebowitz & Lebowitz LABDHITZA M Lebowitz & Lebowitz. PERLYMAN J Administrative Contracts Brench FIN B-1657. NRC-08-81-336 BI/02/26. 1p. 07825.191.
- --BIO3050202 Forwards contract per 810205 telcon Amends to Articles I-x encl. LABOMITZ, A.M. Labowitz & Labowitz. NRC-08-B1-336. B1/02/12. 6pp 07825 192

- 8102050196 Notification of contract elecution mod it of Children in Characterization of Seismic Motion for Nuclear Power Plant Design Cantractor Moodward-Clyde Consultants JACOBS-A Research Contracts Branch FIN 8-6680 NRC-04-80-192 B1/02/05 1p 07825 198
- --Bi03050203 Mod 1, changing title for contract work & increasing funds currently available for payment to "Engineering Characterization of Seismic Motion for Nuclear Power Plant Design" | IORISS I M. Woodward-Clyde Consultants, Inc. MORION, K. V. Research Contracts Branch FIN B-6680 NRC-04-80-192 81/02/05 to 07825 159
- 8103050327 Notification of contract execution. Mod 3 to "Fire Protection Research Progrem" Contractor Underwriters Labs. Inc WOLLETT.S. Research Contracts Branch FIN B-6197 NRC-04-77-122. 81702702 19 07826 GB7
- --BI03050332 Mud 3, extending contract until Dec 1981 at no add1 cost, to "Fire Protection Research Program" BARTON. R D Underputkers Laboratory, MORTON. K V Research Contracts Brench FIN 8-6197 NRC-04-77-122 B1/02/02 Ip
- B103050630 Mod 2. septiligating funds & closing out contract, to "Microfiche Svcs. Dak Ridge, TN"
  RUDCCHID. J P Microtech Industries, Inc LEBO. C. D Administrative Contracts Branch NRC-10-79-658 B1/02/06 Ip 07029 169.
- 8103050B14 Notification of contract execution.Mod 1 to "Examine Facts in Employee Orievance:Hold Hearing:Including Taking of Testimony & Acceptance of Evidentiary Met1 " Contractor ED Ooldberg.
  FLEENOR.C M Administrative Contracts Branch NRC-10-00-390 81/02/09. 10 07828 197.
- --BI03050827 Had 1, modifying statement of work & revising period of performence, to "Examine Facts in Employee Orlevance; Blod Hearing: Including Tasing of Testimony & Acceptance of Evidentiary Hati"
  GDLDBEHO, B. Oblder Associates. LEBO.C.D. Administrative Contracts Branch. NRC-10-81-390 81/02/09. 3pp 0/028 198
- B10306001B Notification of contract election. Hod 5 to "Investigation of Use of Cyclic. Torsional Screw Plate Test to Determine in Situ LiquePaction Potential of Cohesionless Boil." Contractor Univ of FL JACOBS. A Research Contracts Branch FIN 8-6254. NRC-04-77-171. B1/02/10 1p 07837-233.
- ~-BIO3060179 Mod S.extending period of performance from 801001 to BIO107.to "Investigation of Use of Cyclic. Torsional Screw Plate Test to Determine In Situ Liquefaction Potential of Cohesionless Boil"

  RANDAZZO.A.F. Florida, Univ. of, Osinesville. MORTON, K. V. Research Contracts Branch. FIN 8-6254 NRC-04-77-171. BI/02/10. Spp. 07839: 234.
- B103060182 B0]ic;tation.offer & award of contract. "Bubscription to Energy Daily." awarded to Energy Daily.Inc.
  LAUIMAN.P. Energy Daily.Inc. LEBD.C.D. Administrative Contracts
  Branch NRC=10-B1-392. B1/02/03 36pp. 07839:060.
- B103090114 Notification of contract execution.Mod 1 to "Licensing Assistance/Socioeconomic Impacts Evaluations." Contractor: Social Research & Applications.
  MAIRBTON.C., FIELDB.J.A. Technical Assistance Contracts Brench.
- --8103090120 Mod 1. extending period of performance, to "Licensing Assistance/Bocioeconomic Impacts Evaluations."

  BTERLING.A H. Social Research Applications Corp. MATTIA, M. J. Administrative Contracts Branch. NRC-02-80-032-02. 81/02/25. 1p. 07848-288.
- 8103090130 Notification of contract execution. Mod 1 to "Licensing Assistance/Bocioeconomic Impacts Evaluations." Contractor: Resource Communities Inc.
  HAIRSTON, C., FIELDS, J. A. Technical Assistance Contracts Branch.
  NRC-02-80-032-04. 81/02/25 1p. 07848: 289.
- --B103090136 Mod 1.extending period of performance, to "Licensing Assistance/Sociaeconomic Impacts Evaluations."

  REA.R.H. Resource Communities: Inc. MATTIA.M.J. Administrative Contracts Branch NRC-02-80-032-04. B1/02/25 1p. 07848.290.
- B103090164 Notification of contract execution.Mod 15 to "Btenographic Reporting Evcs." Contractor:Ace Federal Reporters.Inc. LIG01N8.E Administrative Contracts Branch. NRC-17-77-117. B1/02/15. 1p 07848-324.

```
--BI03090171 Mad 15. deobligating belance & decreasing total amount of
contract to "Stenographic Reporting Svcs" " MATSKO.R J ACE Federal Reporters. Inc LEBO.C D Administrative
Contracts Branch NRC-17-77-117 BI/02/13 1p 07848 329
8103090186 Notification of contract execution.Mod t to "Siting
Criteria-History." awarded to Scandpower Corp
LITTLE:M. Administrative Contracts Branch. FIN 8-6512-8
MRC-03-78-169 81/02/11 ip 07848-333
 --Bi03090192 Mod 1, decreasing total amount for close out to 'Siting
                           O304072 NBG 1.0ECTESTING COLOR SHOOM TO COLOR STATE OF COLOR OF CO
8103090187 Notification of contract execution.Mod 9 to "PDR Micrographic Storage & Retrieval Bys " Contractor Access
           WIGGINS.F Administrative Contracts Branch FIN-8-6357
NRC-17-79-449 81/02/18 1p 07848 335
```

- --Bi03090196 Mod 9.adding translator program to NRC document control sys conversion software to "PDR Micrographic Storage & Retrieval Bys FRIEL.K P. Access Corp LEBO.C D. Administrative Contracts Branch FIN-8-6357 NRC-17-79-449 81/02/18 3pp 07848 336
- 8103090269 Natification of contract execution Mps 1 to "Subscription to 1980 Edition of ASME Boiler & Pressure Vessel Code. Including Automatic Addonda Svc." Contractor ABME. COLEMAN.R Administrative Contracts Branch NRC-10-80-696 B1/02/18 p 07846 341
- --BI03090276 Mod 1 revising contract schedule & increasing total amount of contract, to "Bubscription to 1980 Edition of ASME Boller & Pressure Vessel Code. Including Automatic Addende Svc "AOUILERA. W F. American Society of Mechanical Engineers LEBG. C D Administrative Contracts Branch NRC-10-80-696 81/02/18 2pp 0784A 745 8103090281 Natification of contract execution "Subscription to Inside
- NSC. Inside DDE. Nuclear Fuel, Inside FERC, Nucleonics Uk. '
  awarded to McGraw-Hill Inc.
  FLYNN.M J Administrative Contracts Branch NRC-10-BI-364
  BI/02/02 ip
- --8103090292 Contract "Bubscription to Inside NRC.Inside DDE.Nuclear Fuel:Inside FERC.Nucleonics Wk." awarded to McGraw-Hill-Inc COLLINS.P McGraw-Hill Publications Co. LEBO.C D Administrative Contracts Branch NRC-10-81-364
- B103090496 Notification of contract execution.Mod 3 to "Review of Nonradiological Environ Operating Data " Contractor Environ Belence & Engineering. Inc CLAODLA-A F. Technical Assistance Contracts Branch FIN 8-6854 NRC-03-80-106 81/02/26 1p 07847-287
- --8103090462 Mod 3.increasing funds currently available for payment to "Review of Nonradiological Environ Operating Data" 
  # Environmental Science & Engineering, Inc. MATTIA.H J. Administrative Contracts Branch FIN 8-6894 NRC-03-80-106 81/02/26. 1p 07847 288 8103090768 Notification of contract elecution. Mod 1 to "Support in Geotechnical Engineering for Nohreactor Facilities."
- Contractor: UB Dept of Army OLAGOLA, A.F. Technical Ass QLAGDLA, A. F. Technical Assistance Contracts Branch FIN 8-6846 NRC-03-80-125 B1/02/19. Ip. 07849:212 --8103090772 Mod 1.changing project officer.estimated cost of contract & reporting requirements to "Bupport in Geotechnical Engineering for Nonreactor Facilities." FRIEDENWALD,R. Army, Dept. of, Corps of Engineers MATTIA,M. J. Administrative Contracts Branch. FIN B-6846 NRC-03-80-125 81/02/19. 2pp. 07849.213
- 9103100234 Notification of contract ejecution, Mod 7 to "Utilization of BWR & PWR Simulator Facilities" Contractor TVA BAIBDEN.L. Research Contracts Branch. NRC-05-76-357. 81/02/27. lp 07868:125
- --8103100243 Mod 7, increasing amount of funds obligated for FY81.to "Utilization of BUR & PUR Bimulator Facilities." MORTON.K.V. Research Contracts Branch. NRC-05-76-367. 81/02/27. 1p. 07868: 126.

MIRAC, Inc

- --Bi03160257 Mod 2. authorizing use of FH Tingey as consultant, to "Development of Advanced Matl Accounting Sys Simulation Model "
  LUMG.R.F. NUSAC. File MATTEA.H J. Administrative Contracts
  Branch NRC-02-80-024 BI/03/02. Ip 07868 128
- 8103100275 Notification of contract execution, Mod I to 'Licensing Assistance/Socioeconomic (mpacts Evaluation " Contractor Denver Research [mst Denver research inst MAIRBTONIC , FIELDS J A. Technical Assistance Contracts Branch NRC-02-80-032-03 81/03/02 ip 07864:218
- --8103100282 Mod 1.extending period of performance to 820601.to "Licensing Assistance/Spcioeconomic Impacts Evaluation."

  DAVIS-P L. Denver-Univ of MATTIA.M J. Administrative Contr. Branch 1880-02-80-032-03 81/03/02. is 07864:219 8103100294 Notification of contract electrion/fod 1 to "Licensing Assistance/Geotechnical & Hydrological Evaluations"
- Contractor Barr Engineering Co HAIRSTON.C. FIELDS.J.A. Technical Assistance Contracts Branch IRC-02-80-033-03 81/03/02 ip 07864 220. --Bl03100002 Mod 1. extending period of performance to B20213. to "Licensing Assistance/Oeotechnical & Hydrological Evaluations"
  HANSON W. W. Barr Engineering Co. MATTIA.M. J. Administrative Contracts Brench. NRC-02-80-033-03. 81/03/02 16 07864 221
- 8103:00359 Notification of contract elecution. Mod ( to "Licensing Assistance/Opotechnical & Hydrological Evaluations "Contractor Geotechnical Engineers, Inc.
  HAIRBIGN.C., FIECDB.J A Technical Assistance Contracts Branch
  NRC-02-80-033-01 81/03/02 Ip. 07865 040
- --8193109364 Mod | extending period of performance to 820213 to "Licensing Assistance/Geotechnical & Hydrological Evaluations."
  - CASTRO. 9 Geotechnical Engineers, Inc. MATTIA. B. J. Administra Contracts Branch NRC-02-80-033-01 81/03/02 1p. 07865 041
- BIO310055B Notification of contract elecution. Mod 7 to "Bubble Behavior LMFIR Core Disruptive Accidents." Contractor: Univ of VA JACOBS. A Research Contracts Branch FIN 8-3516 NRC-04-75-316 BIO3702 Ip 07862 358.
- --8103100661 Mad 7, extending period of performance to 810930 & incre arount of consideration, to "Bubble Behavior in LMPBR Core Disruptive Accidents"

  MuNOER'P L. Virginia Univ. of MORTON-KV Research Co Dranch FIN 8-5616. NRC-04-75-016 81/03/02 5pp 07862 35
- Bi03100667 Notification of contract elecution.Mod 7 to "FLECHT Separ Effects & Sus Effects Test Programs (FLECHT-SEASET Program) ' Contractor: Westinghouse & EPRI MOULETTIB Research Contracts Branch NRC-04-77-127. 01/03/02
- 92862 130 --BI03100670 Mod 7.supplemental agreement changing total estimated of obligating funds & limitations to "FLECHT Separate Effects & Sys Effects Test Programs (FLECHT-SEASET Program) "
  BARBER ON Electric Power Research Institute MORTON X V.
  Research Contracts Branch TAYLOR J Hestinghouse Electric Corp NRC-04-77-127. B1/03/02 2pp. 07862:131
- B103100758 Notification of contract elecution.Mod ! to "Gonsultant-Special Research Review Group." Contractor Energy Engineering Group.

  LITTLE-M Administrative Contracts Brench FIN 8-6310

  NRC-04-78-225. 81/02/26 ip 07862-239.
- --8103100762 Mod 1.deobligating funds & closing "Consultant-Special Research Review Oroup" HOCEVAR.C.J. Energy Engineering Oroup. PERLHAN.J. Administrat Contracts Dranch FIN 8-6310. NRC-04-78-225 81/02/26. 1p
- 07862.240 810311079D Notification of contract electrion. Mod 2 to "Fuel Cycle Project Review " Contractor Science Applications. Inc. MOLLETT'S Research Contracts Branch FIN 8-6694 NRC-04-00-17E 81/02/20 1p. 07875.358.
- --8103110794 Mod 2.correcting contract to reflect obligation of fund "Fuel Cycle Project Review"
  MARKL.R.L. Science Applications, Inc. MCRTON.K.V. Research
  Contracts Branch. FIN 8-6694. NRC-04-80-178 81/02/20 1p.

07075.359

8103100251 Notification of contract precution Mod 2 to "Development of Advanced Matl Accounting Bys Bimulation Model" Contractor:

- 9103120240 Notification of contract execution.Mod 1 to "Multidimensional Effects in LWR Thermal Hydraulics" Contractor Resselaer Polytechnic Inst.
  JACOBS.A Research Contracts Branch FIN 8-7272 NRC-04-80-236-81/02/11. 1p 07893 360.
- --B10312024B Mod 1.edding funds for FYB1.to "Multidimensional Effects in EMR Thermal Hydraulics" SCAMMELL, R Rensselaer Polytechnic Inst. MORTON.K.V. Research Contracts Branch FIN 8-7272. NRC-04-B0-236 81/02/11. 1p 0783-361
- B103120455 Notification of contract execution Hod 4 to "Durability of Crystalline Nuclear Maste Forms & Natural Analogs at Geologic Storage Conditions 'Contractor Univ of Toledo.
  HADGY-H Research Contracts Brench. FIN 8-6624 NRC-04-78-267 81/02/05 ip 07905 145
- --B103120459 Mod 4, providing no cost extension, to "Durability of Crystalline Nuclear Haste Forms & Natural Analogs et Qeologic Storage Conditions " FREE. H N Toledo. Un(v of. HORTON.K V Research Contracts Brench. FIN 8-6624 NRC-04-78-267 81/02/05 lp. 07905.146
- BiO3:20844 Notification of contract execution. Mod 1 to "Technical Assistance to Bupport NRC IE Personnel in Investigation of Incidents Contractor Parameter. Inc. BAIBDENL Research Contracts Branch FIN 8-1013 NRC-05-80-251. 81/03/02 pp. 07906-019
- --B103120859 Hod 1.adding work under Task Order 2.changing project officer & providing add1 funding to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents." LGFY.R A. Parameter. Inc. MORTON.K V. Research Contracts Branch FIN 8-1013 NRC-05-80-251 81/03/02 2pp 07906 020
- B103:30006 Notification of contract execution Hod 13 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"
  OLAGOLA-A F. Technical Assistance Contracts Branch NRC-03-79-118
  B1/01/28 ip. 07913
- --B103130013 Hod 13, allowing payment for overtime & incidental expenses to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions."

  ABHTON.A H Franklin Institute/Franklin Research Center.

  MATTIA.M J. Administrative Contracts Brench. NRC-03-79-118

  81/01/28 ip. 07913:025.
- 103:30094 Notification of contract execution, Hod 5 to "Electrostatic Copying Svc." awarded to Automation Industries.inc COLEMAN.R Administrative Contracts Branch. NRC-10-76-391 B17/03/04 19 07907 274.
- --8103130105 Hod 5.deobligating funds to "Electrostatic Copying Svc." GORMLEY.R C. Autoration Industries: Inc LEBO.C.D Administrative Contracts Branch. NRC-10-76-391. 81/03/04. 1p. 07907 275
- 0103130264 Notification of contract execution Mod 2 to "Processing of NRC Photographic Requirements." Contractor: Hashington Color Photo MIOOINSIE Administrative Contracts Branch, NRC-10-75-284 81/02/10 1p. 07912-191.
- --8103130273 Mod 2.deobligating balance of contract to "Processing of NRC Photographic Requirements"
  HILSON.L E. MD Color Photo. LEBO.C D. Administrative Contracts
  Branch. NRC-10-76-284. 81/02/10 1p. 07912-192.
- B103130322 Notification of contract execution, Mod 2 to "Nuclear Mat]s Engineering Consultant." Contractor: JL Mershon. LITTLE: M. Administrative Contracts Branch. FIN 8-6487-8 NRC-03-78-136. B1/02/26. 1p. 07912:168.
- --B103130328 Mod 2.deobligating remaining funds & closing out contract, to "Nuclear Matis Engineering Consultant."

  MERSHON, J. L. Mershon, J. L. PERMAN, J. Administrative Contracts
  Branch. FIN 8-6487-8 NRC-03-78-136. B1/02/26. ip. 07912:169.
- B103130651 Notification of contract execution: "Geotechnical Engineering Review of BEP Plants." awarded to Corps of Engineers. CLA00LA:A F. Technical Assistance Contracts Branch. FIN 8-6883 ARC-03-81-122. 81/02/12 1p
- --B103130655 Contract. "Geotechnical Engineering Review of SEP Plants."
  awarded to Corps of Engineers.
  Army. Dept. of. Corps of Engineers. MATTIA.H. J. Administrative
  Contracts Branch. FIN 8-6883. NRC-03-81-122. 81/02/12.

- B103130683 Notification of contract execution. Task Order 2. "Fuel Cycl Project Review." awarded to Science Applications. Inc. WOLLETT. B. Research Contracts Brench. FIN B-6694 NRC-04-80-178. B1/02/20 1p 07913-285
- ---B103130686 Contract 'Fuel Cycle Project Review," (Task Order 2) awa to Science Applications, Inc. MARKL:R Brience Applications: Inc. MORTON, K. V. Research Contracts Branch FIN 8-6694 NRC-04-80-178 B1/02/20. 10pp
- B103160023 Notification of contract elecution Mod 4 to "Development of Strainrange Partitioning for Creap-Fatigue Assessment in Nuclear Components Operating at Elevated Temps." Contractor: Case Mestern Reserve Univ. JACOBS.A. Research Contracts Brench. FIN 8-6252. NRC-04-77-132-81/03/06. 1p. 07921-162.
- ~-8103160028 Mod 4, reessigning original contract number, to "Developme of Strainrange Partitioning for Creep-Fatigue Assessment in Nuclear Components Operating at Elevated Temps."

  MODREA C. Case Mestern MORTON.K V. Research Contracts Branch FIN B-6252. NRC-04-77-132. 81/03/06. 2pp. 07921 163
- 8103160194 Notification of contract execution Mod 16 to "Stenographic Reporting Svcs." WIGGINSE: Administrative Contracts Branch NRC-17-77-117. 81/03/05. 1p. 07921 240.
- --B103160200 Mod 16.deobligating balance remaining under contract to "Btenographic Reporting Bycs."

   ACE Federal Reporters, Inc. LEBG.C.D Administrative Contrac Branch. NRC-17-77-117 B1/03/05. 1p. 07921.241.
- BIO3160213 Notification of contract execution, Mod I to "Training Cour Entitled Bafety Aspects of Industrial Radiography for Btate Regulatory Personnel." Contractor: Gamma Industries Div of NSI. FLYNN, N. J. Administrative Contracts Branch. FIN 8-1618. NRC-06-80-304 81/03/04. 2pp. 07921: 242.
- --Bi03160224 Mod Liestending period of performance.until Bi0327 for f yr & Bi0930 for second yr to "Training Course Entitled. Bafety Aspects of Industrial Radiography for State Regulatory Personnel." RICHARDBON.H D. Nuclear Systems, Gamma Industrias Div. LEBO, C. D Administrative Contracts Brench. FIN B-1618. NRC-06-80-304. Bi/03/04. 2pp. 07921-244.
- 8103160544 Notification of contract execution.Mod 11 to "Ultrasonic Nondestructive Testing of Pressure Vessels," awarded to Univ of MI.

  JACOBS, A Research Contracts Branch. FIN A-4047, NRC-04-75-182.
  BI/02/16 ip. 07916.330.
- --BIO3160550 Mod 11.extending period of performance to B11231 & increasing funding to "Ultrasonic Nondestructive Testing of Pressure Vessels."

  BRINKER(OFF.J. Hichigan, Univ. of MORTON, K. V. Reswerch Contracts Branch. FIN A-4047, NRC-04-75-182. BI/02/16. 7pp. 07916:331.
- B103160559 Notification of contract execution.Mod 2 to "Technical Assistance to Support NRC 1E Personnel in Investigation of Incidents." Contractor: Parameter, Inc. BAISBEN.L. Research Contracts Branch. FIN 8-1013, NRC-05-80-251. B1/03/06. 10. 07916:338.
- --Bi03160571 Mod 2, increasing funding for FYB1, to "Technical Assisten to Support NRC IE Personnel in Investigation of Incidents." \* Perameter, Inc. MORTON, K.V. Research Contracts Brench. FIN B-1013. NRC-05-80-251. B1/09/06. 1p. 07916: 339.
- 8103180994 Natification of contract execution.Mod 1 to "Fission Produ Transport Consultant." Contractor: Science Applications/Inc. LITILE.M. Administrative Contracts Branch. FIN 8-6297. NRC-03-78-210. B1/03/11. ip. 07983:228.
- --B103181001 Mod 1.decreasing amount of contract & officially closing "Fission Product Transport Consultant," FELDMAN, B.A. Science Applications, Inc. PERLMAN, J. K. Administrative Contracts Branch, FIN 8-6297, NRC-04-78-210. 81/03/11, ip. 07953:229.
- B103190024 Notification of contract execution, Mod 2 to "Presentation General & Refresher Courses in Welding Technology & Codes." Contractor: OH Btate Univ.
  BAISDEN.L. Research Contracts Brench, NRC-05-79-264, B1/02/20, 1p. 07960: 355.

- --8103190028 Mod 2.adding courses & FY81 funding to "Presentation of General & Refresher Courses in Helding Technology & Codes " REDMOND, R F Ohio Univ MORTON, K V. Research Contracts Branch. NRC-05-79-264. 01/02/20 1p. 07960.336.
- 8103190053 Notification of contract asscution Hod 1 to "Dept of State Translation Svcs " Contractor Language Bvc Div Dept of State PERLMAN, J. Administrative Contracts Branch. FIN 8-6406-8. NRC-02-78-057. 81/03/03. 1p. 07960.357.
- --8103190072 Mod i.deobligating balance & closing out contract.to
  "Dept of Btate Translation Svcs."

  LEJINS.N M. State.Dept.of. PERLMAN.J. Administrative Contracts
  Branch FIN 8-6406-9. NRC-02-78-037 B1/03/03. 1p. 07960:358
- BiO31900B1 Notification of contract execution.Mod 1 to "Licensing Assistance/Socioeconomic Impacts Evaluations " Contractor. Mountain West Research.Inc. Hountain West Research.Inc. HAIRETON.C., FIELDB.J.A. Technical Assistance Contracts Branch NRC-02-80-032-01 81/03/04. ip. 07960-322.
- --8103190094 Mod 1.extending period of performence to 820213, to
  "Licensing Assistence/Bocloeconomic Impacts Evaluations "
  CHALMERS.P.M Hountain West Research. Inc MATTIA.M J.
  Administrative Contracts Branch. NRC-02-80-032-01. 81/03/04 ip.
- 8103190146 Notification of contract execution. Mod 1 to "Response Burface Methodology Consulting Svcs." Contractor OE Box LITTLE.M Administrative Contracts Brench FIN 8-6285 NRC-04-78-196. 81/03/11 ip 07965.019.
- --8103190196 Mod 1 decreasing amount of contract & officially closing out. "Response Surface Methodology Consulting Bvcs."

   Box. 0 E.P. PERLMAN.J K. Administrative Contracts Branch FIN B-6285. NRC-04-78-196. B1/03/11 1p. 07965:020.
- 8103190164 Notification of contract execution, Mod 2 to "Consultant to LOFT Basecial Review Group," Contractor: H Isbin.
  LITTLE: M Administrative Contracts Branch. FIN 8-7489
  NRC-04-81-196. 81703/10 ip 07965.021.
- --B103190167 Mod 2.correcting FIN B-7490 on original contract & on Mod 1 to read B-7489, to "Consultant to LOFT Special Review Group."

   Isbin-H. PERLMAN.J K. Administrative Contracts Branch. FIN B-7489. NRC-04-81-196.
- BiO3190264 Notification of contract execution: "NUREO/CR-XXXXX, 'Tachnical Basis for Reg Ouide 1.148 Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants', "awarded to NUB Corp. MCNULTY, A. Administrative Contracts Branch. FIN 8-7116. NRC-01-81-009. Bi/03/05. ip. 07965:177.
- --BIO3190279 Contract: "Preparation of Nurse/CR-XXXXX. 'Technical Basis for Reg Ouide 1,145 Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants', "awarded to NUS Corp. EDMONSON.L.R. NUB Corp. PERLMAN.J.K. Administrative Contracts Branch. FIN B-7116 NRC-01-81-009. 81/03/05. 5pp. 07945:178.
- BiQ3190395 Natification of contract execution: "Understanding of Ragulatory Process." awarded to Graduate School, USDA. COLEMAN.R. Administrative Contracts Branch. NRC-10-81-388. 81/03/10. 1p. 07954:337.
- --8103190360 Contract: "Understanding of Regulatory Process," awarded to Graduate School.UBDA.

  Agriculture, Dept. of. LERO, C.D. Administrative Contracts
  Branch, NRC-10-81-388. 81/03/10. 10pp. 07954:338.
- BIO3190677 Notification of contract execution: "Photographic Reproduction Byc." awarded to Bara Photographic.inc. COLEMAN.R. Administrative Contracts Branch. NRC-10-BI-3B7, BI/03/10. 1p.
- --B1031906B2 Bolicitation.offer & award of "Photographic Reproduction Byc" to Bara Photographics. Inc.
  MATSON:H. Affiliation Unknown. LEBG. C. D. Administrative
  Contracts Branch. NRC-10-B1-287 81/03/10. 3ipp.
- 8103190685 Notification of contract esecution.Mod 1 to "Esecutive Development Program." Contractor:Oraduate School,USDA. HIGGINS.E. Administrative Contracts Branch. NRC-10-80-399. 81/03/12. 1p. 07963:218.

- --8103190694 Mod 1. deleting part of Page 1 (objectives) & part of P (scope of work) & adding Task V[I to provide for design development & conduct of addl priority seminars, to "Executive Development Program" VARNER.L 8. Agriculture.Dept of LEBD.C.D. Administrative Contracts Branch NRC-10-80-399 81/03/12 3pp 07963 219.
- B103190883 Notification of contract execution. Mod 3 to "Evaluation of NRC Regulations Governing Conduct of NRC Employees, 10CFRO." Contractor St. Lindenbaum.
  PERLMAN.J. Administrative Contracts Branch FIN 8-1862
  NRC-18-78-472. 81702/17 1p. 07965.294
- --8103190891 Mod 3. deobligating balance & closing contract, to "Evaluate NRC Regulations Governing Conduct of NRC Employees. 100FRO."
  LINDENBAUM. 5. Gol Lindenbaum PERLMAN. J. Administrative Contracts Branch. FIN 8-1962 NRC-18-78-472 81/02/17 1p 07965 295
- 8103200174 Notification of contract execution Mod 2 to "Revpunch & Verification Svcs." Contractor Small Business
  Administration
- MIGOINS.E Administrative Contracts Branch NRC-10-80-695 81/02/11. [g 07972-016.
- --B103200189 Mod 2.providing for verification axes under Item 3.to
  "Keypunch & Verification Bycs "
  TUNBTALL.J.E Smell Bustness Administration. LEBD.C D.
  Administrative Contracts Branch. NRC-10-80-695 B1/02/11 Ip.
- BIO3200484 Notification of grant execution "Development of Method & Bystematic Probabilistic Risk Assessments of Nuclear Power Plants." awarded to IEEE THOMESON.R.D. Office of Administration. FIN 0-1007 NRC-0-04-81-005 BI/03/11. 1p 07967:006.
- --BI03200491 Orant: "Development of Method for Bystematic Probabilis Risk Assessments of Nuclear Power Plants," awarded to IEEE HERR.E. Institute of Electrical & Electronic Engineers THOMPSON.R D. Office of Administration. FIN 9-1007. NRC-G-04-81-005. BI/03/11 17pp. 07947:007.
- 8103200789 Notification of contract execution.Mod 2 to "Health Effec of Low Level Ionizing Radiation." Contractor George Hashington Univ BROMBERG.B. Research Contracts Bhanch. FIN 8-10848. NRC-01-78-0 81/03/12 Ip. 07966:185.
- --9103200794 Mod 2 deobligating erress funds prior to closeout to "H Effect of Low Level lonizing Radiation" OREENE M.P. George Mashington Univ. MORTON, K.V. Research Contracts Brench. FIN B-10848. ARC-01-78-017 81/03/12, ip. 07966-186.
- 8103230014 Notification of contract execution Hod 3 to "Numerical Simulation of Effects of Cooling Tower Complexes on Clouds & Bevere Storms " Contractor 8D School of Mines & Technology.

  HAGEY, H. Research Contracts Branch. FIN 8-5764 NRC-04-76-350. 80/11/13 ip. 07980:305.
- --8103230019 Mod 3. deobligating funds for closeout.to "Numerical Simulation of Effects of Cooling Tower Complexes on Clouds & Bevere Storms."

  FISHER.R.L. South Dakota School of Mines & Technology MORTON.K. V. Research Contracts Branch. FIN B-5764.

  NRC-04-76-350. 80/11/13. 2pp. 07980:306
- 8103230026 Notification of contract esecution: "Development of Comprehensive Human Factors Plan for Nuclear Reactor Regulation:" awarded to Human Factors Bociety Inc. MORTON K.V. Research Contracts Branch. FIN 8-7239. NRC-04-81-18:81702713.
- --8103230083 Contract: "Development of Comprehensive Human Factors P for Nuclear Reactor Regulation," awarded to Human Factors Gociety, Inc. BAYDER,H. L. Human Factors Society, Inc. MORTON,K. V. Research Contracts Brench, FIN 8-7239, NRC-04-81-186, 81/02/13 13pp.
- 8103230066 Notification of contract execution: "Seismic Investigation of Epicentral Region About 800727 Sharpsburg.KY Earthquake." awarded to Univ of KY.
  HAQEV.H. Research Contracts Branch. FIN 8-7477. NRC-04-81-188 81/03/13. 1p. 07978:260.
- --Bi03230071 Contract: "Beismic Investigation of Epicentral Region Al B00727 Sharpsburg.KY Earthquaks." awarded to Univ of KY. MEBLER.F. B. Kentucky, Univ of. MORTON.K V Research Contract Branch. FIN B-7477 NRC-04-81-188.

- 8103230933 Notification of contract execution Rod 1 to "Environ Assessments of Surface & Groundwater Impacts from U Recovery Operations." Contractor Ott Water Engineers HAIRSTON.C & SMITH.P. A. Technical Assistance Contracts Branch NRC-02-80-028-01. 81/03/11. 1p. 07974-024
- --Bi03230939 Mod 1, adding Articles 12-20 to basic ordering agreement to "Environ Assessments of Surface & Groundwater Impacts from U Recovery Operations."

  KUMPAMEY. J H. Ott Mater Engineers. Inc. MATTIA.M J. Administrative Contracts Branch. NRC-02-80-028-01 B1/03/11 1500. 07774-025
- 8103330746 Notification of contract elecution Mod I to "Consultant Bpecial Research Review Group " Contractor MHB Technical Associates FLEENDR.C M. Administrative Contracts Branch FIN 8-6309 IdC-04-78-266 81/03/13 1p 07974 057
- --8103231059 Mod 1, decreasing total amount of contract for closeout to "Consultant Special Research Review Group"

  BRIDENIAUGH D MMB Technical Associates PERLMAN, J Administrative Contracts Branch. FIN 8-6390 MRC-04-78-266.
  81703/13 12 07974 058
- B103240B2B Notification of contract execution.Mod 6 to "Approx Treatments of Third Dimension in Numerical Transport Calculations." Contractor Northwestern Univ HAGEY.H Research Contracts Branch FTN A-4079 N9C-04-74-19B B1
- --B103240836 Ack receipt of B01223 itr granting permission to carry forward unerpected funds Advises of final payment arount appearing on balance sheet to be deobligated SEIBERT, C.H. Northwestern Univ. FIN A-4079 NRC-04-74-198 B1/02/02 ip 07984: 228
- --8103240841 Grants approved to Northwestern Univ to carry over unexpended funds from period of Oct 1978-8ept 1979 HORTON,K V Research Contracts Bratich. FIN A-4079 HRC-04-74-198 B0/12/23 2pp 07984 229
- B103250492 Notification of contract execution "Mailing Svcs." awarded to DC Association for Retarded Citizens.
  COLEMAN.R. Administrative Contracts Branch NRC-35-81-681
  B1/03/16 ip 07996 221
- -8103250498 Contract. "Mailing Svcs." awarded to DC Association for Retarded Citizens. • DC Association for Retarded Citizens LEBO.C.D Administrative Contracts Branch NRC-35-81-681. 81/03/16 11pp. 07996:222
- J103250564 Notification of contract execution. "Attend ACRS Subcornittre Meeting on Reactor Radiological Effects & ACRS 25jet Full Committee Meeting." awarded to MJ Kabat FLEENOR.C M Administrative Contracts Branch. FIN 8-1597 NRC-11-81-431 81/03/16 1p. 07996 238
- --Bi03250573 Contract "Attend ACRS Subcommittee on Reactor Radiological Effects & ACRS 201st Full Committee Meeting," awarded to MJ Kabat. KABAT. M Xabat. M J FERLMAN. J Administrative Contracts Branch FIN B-1557 N9C-11-81-431 81/03/16 3pp 07976.238
- 8103260540 Notification of contract execution. Mod 4 to "Regional Interstate Nuclear Facility Biting Procedures Demonstration Project "Contractor Bouthern Interstate Nuclear Board GUSTAVE. R P. Research Contracts Branch FIN 8-50209. NRC-01-72-324. B1/03/04 ip 08035-306
- --Bi03260856 Mod 4.extending period of performance to Bi033i.to
  'Regional Interstate Nuclear Facility Biting Procedures
  Demonstration Project "
  NEMETH.K.J. Southern Interstate Nuclear Board MCRTON.K V
  Research Contracts Branch. FIN 8-50209. NRC-01-76-324 B1/03/04
  1p. 08035-307.
- BiO3261053 Notification of contract execution.Mod 6 to "Bys Maint Programming." Contractor SBA Subcontractor.Rehab Group.Inc. HAGAN-T.F. Administrative Contracts Branch. NRC-10-79-375 BIO2719. 1p 08035:160.
- --B103261062 Mud & increasing funds to cover svc required through B11014 to "Bys Maint Programming."

  # Rehab Oroup, Inc. MAOAN. T.F. Administrative Contracts Branch NRC-10-79-375. 81/02/19 2pp. 08035:162

- 8103261055 Notification of contract execution Mod 8 to "Coordinatio of Federal/State Radiation Control Activities & Assistance in Solving Radiation Control Problems "Contractor Food & Drug Administration. US Public Health Svc FL(MN, M. Administrative Contracts Branch FIN 8-1620 NRC-06-76-247 81/03/02 Ig 08035 231
- --BI03261069 Mod B. increasing funds & extending period of performan through BI1231 to "Coordination of Federal/State Radiation Control Activities & Assistance in Bolving Radiation Control Problem; = HHS. Dept of. US Public Health Service LEBD.C D Admistrative Contracts Branch. Fill 8-1620 NRC+06-76-247 BI/03/02 Ip 08035-232
- BIO3261060 Responds to FQIA request for Contract NRC-04-77-0A% & subsequent mode or arends forwards documents. Info will be placed in PDR FELTON.J M Division of Rules and Records 81/03/23 2pp
- --8103261072 Contract "Conduct Bludy to Developed Integrated Dafey Info Bys (1818)." awarded to Boeing Computer Svc. Inc. ORANT.B.M Boeing Computer Services. Inc. (subs. of Boeing Co. HALMAN.E. Division of Contracts FIN 8-5714 NRC-04-77-061
- --8103261095 Mod ), adding document control sys & export-import lick data sys in intl programs to "Conduct Study to Developed Integrated Safeguards Info Sys (ISIS)"

  Bosing Corputer Services, Inc. (subs of Bosing Co.)
  MORTON.R V Division of Contracts FIN 8-5714 NRC-04-7/-065
  77/10/12. 2pp
- --8103261102 Mod 2. increasing funds, to "Conduct Study to Develop Integrated Safeguards Info Sys (1819)." GRANT.B M Bosing Computer Services, Inc. (subs. of Bosing Co-MCRTON.K V. Division of Contracts. FIN B-5714 NRC-04-77-06.5 777/11/01 200
- --BIO3261109 Mod 3 revising pariods of performance & increasing fun 'Conduct Study to Develop Integrated Safeguards Info Sys (1981) "
  GRANT-8-M Booing Computer Services, Inc. (subs. of Booing CompRON.K V Division of Contracts, FIN B-9714, NRC-04-77-(M-977-12/14, 2pp.
- --BIO3261115 Mod 4. adding tasks to Btatement of Hork Phase 1. Task 1 "Develop Safeguards Info Requirements," to "Conduct Bludy to Develop Integrated Safeguards Info Bys (ISIS)" Boeing Computer Services, Inc. (subs. of Boeing Co.). MORTON.K.V. Division of Contracts FIN 8-5714 NRC-04-77-065 78/04/04 2p.
- --BIOSE61120 Mod 5. increasing funds, to "Conduct Study to Developed integrated Safeguards info Sys (ISIS)." GRANT, B. If Boeing Computer Services, Inc. (subs. of Boeing Co-HORTON.K V Division of Contracts. FIN B-5714 NRC-04-77-065 78/04/28 2pp
- --Bi03261123 Mod 6.adding tasks to Statement of Hork to "Conduct Bt Develop integrated Bafeguards Info Sys (IBIS)" \* Boeing Computer Services, Inc. (subs. of Boeing Co ). #URTON K V. Division of Contracts. FIN B-3714 NRC-04-77-063 78/03/12 Jpp
- --Bj03261128 Mod 7. increasing funds to "Conduct Study to Develop Integrated Safeguards Info Bys (IBIB)." FUGITT.H.D. Boeing Computer Services: Inc. (subs. of Boeing Co MORTON, K.V. Division of Contracts. FIN 8-3714 NRC-04-77-065 78/06/12. 2pp
- --8103261134 Mod 8, extending period of performence until 781030, to "Conduct Bludy to Developed Integrated Bafeguards Info Sys (1818) "
  FUGITY.H.D. Boeing Computer Services, Inc. (subs. of Boeing Co. MORTON.K.V. Division of Contracts FIN B-3714. NRC-04-77-053 78/08/16 [p.
- B103261069 FBIA request for Contract NRC-04-77-065 & subsequent mod angles. RUTHERFORD, J. F. BDM Corp. BDM/W-JFR-1282-. B1/03/09. Ip.
- B103261073 Notification of contract execution.Mod 4 to "Lease of C1 III and IV Sedans for NRC Motor Pool." Contractor.M Albert Leasing. Inc.
  MARTIN.L. C. Technical Assistance Contracts Branch. NRC-10-78-41

- --8103261082 Mod 4.correcting error on Mod 3 & decreasing total amount of contract for closeout to "Lease of Class III and IV Bedans for NRC Motor Pool"
  HILLER.D N. Mite Albert Leasing, Inc. LEBO.C D. Administrative Contracts Branch NRC-10-78-416 81/03/17. Ip 08039 165
- BIO3261079 Notification of contract execution. Mod 4 to "Core Melt Metis Interactions Evaluations." Contractor Applied Science Associates.inc.
  HAIRBTON.C. EDOEMORTH.P. J. Technical Assistance Contracts Branch FIN 8-6823 NRC-03-80-104 81/03/18 ip. 08035 233
- --B103261086 Mod 4.obligating addl funds to "Core Helt Matis Interactions Evaluations"
- Evaluations "
  Applied Science Associates. Inc MATTIA.M J. Administrative
  Contracts Branch FIN B-6823 NRC-03-80-104 81/03/18 ip
  08035-234
- BIO3241094 Notification of contract execution Mod B to "On-Call Maint for MRC Computer Peripheral Equipment." Contractor Computer Bys Support Corp MARTIN.L. C Technical Assistance Contracts Branch NRC-10-79-395-81/03/16.
- --Bi0326i103 Mod B, increasing ceiling amount of contract, to "On-Cail Maint for NRC Computer Peripheral Equipment"
  RODT.L.E. Computer Systems Support Corp. LEBO.C.D.
  Administrative Contracts Branch. NRC-10-79-395 81/03/16 1p.
  OROS5 167
- B103261111 Notification of contract execution.Mod 1 to "Lease of 10 Class 111 Sedans " Contractor We Try Harder Inc. MARTIN.L. C Technical Assistance Contracts Branch NRC-10-80-371. 81/03/18 1p 08035-246
- --Bi03261116 Mod | increasing total contract exercising option to extend period of performance & adding add1 funding to "Lease of 10 Class | II | Bedans "

   We Try Harder, Inc. LEBO.C. D. Administrative Contracts Branch NRC-10-80-371 81/03/18. 2pp 08035 247
- B103261125 Notification of contract execution.Mod 2 to "Training Courses Entitled. 'Safety Aspects of Industrial Radiography for State Regulatory Personnel'." Contractor.Gamma industries Div of NBI.
  FLYNN.M.J. Administrative Contracts Branch. FIN 8-1618.
  NRC-06-80-304. 81/03718. 1p 08035-254.
- --8103261133 Mod 2.correcting error in Block 10 on Mod 1 to "Training Courses Entitled, 'Safety Aspects of Industrial Radiography for State Regulatory Personnel?."

   Garma Corp. LEBO.C.D. Administrative Contracts Branch #IN B-1618. NRC-06-80-304. B1/03/18. 1p. 08035:255.
- B103270031 Notification of contract execution. Mod 2 to "Disease Incidence Rates From Occupational Exposure to Hexardous Bubstances." Contractor Battelle Columbus Labs OUBTAVE.R.P. Research Contracts Branch ROECKLEIN.A Occupational Health Standards Branch. FIN 8-10660. NRC-01-80-016 81/03/13 to. 65165-197.
- --Bi03270040 Mod 2.obligating addl FVB1 funding to "Disease Incidence Rates From Occupational Exposure to Hazardous Substances " LUKZ.F.J Battelle Kemorial Institute. Columbus Laboratories. MORTON.K.V Research Contracts Branch. FIN B-10660. NRC-01-80-016 81/03/13, 1p. 65165:198.
- 8103270048 Notification of contract execution: "Licensing Assistance/ Qeotechnical & Hydrological Evaluations," awarded to Converse-Hard-Devise-Dison.Inc. HAIRBTON.C., FIELDS.J.A. Technical Assistance Contracts Branch NRC-02-80-033-07. 81/03/18. p.
- --8103270060 Contract. "Licensing Assistance/Geotechnical & Hydrological Evaluations" awarded to Converse-Hard-Davis-Dizon, Inc. LEBKYB, A. O. Converse, Davis & Associates. MATTIA-M. J. Administrative Contracts Branch. NRC-02-B0-0333-07 81/03/IB.
- --Bi03270069 Advises of contract award for "Licensing Assistance/ Geotechnical & Hydrological Evaluations " Requests signature. MATTIA:H.J. Administrative Contracts Branch. NRC-02-B0-033-0. B1/02/24. 12pp.
- 8103270050 Notification of contract execution, Mod 13 to "Consulting Svcs (A-E) re Evaluation of Facility Concepts.Cost Estimates & Bichedules for Experimental Facilities " Contractor: Burns & Rose Inc.
  BROMBERO, B Research Contracts Branch. FIN 8-6220 NRC-04-77-097 81/03/12. 1p. 08045:167.

- --8103270063 Med 13.extending period of performance to 810430.to "Consulting Sycs (A-E) re Evaluation of Facility Concepts. Cost Estimates & Schedules for Experimental Facilities "WEILP H. Burns & Ree Co. MORTON.X V Research Contracts (FIN 8-6220, NRC-04-77-097 81/03/12 ip 08045 168
- 8103270184 Notification of contract elecution Mod I to "Environ Assessment of Oroundwater Contamination in Hood River,RI." Contractor D. Warner. Inc LITTLE.M Administrative Contracts Branch FIN 8-6993 NRC-02-80-076, 81/03/17 Ip 08045-321
- --BiO3270192 Mod I. extending period of performance from BO0917 to "Environ Assessment of Graundwater Contemination in Wood River.RI."

  WARNER.D.C. Con L. Warner PERLMAN. J. Administrative Contr.

  Branch FIN 8-6993. NRC-02-80-076 81/03/17 ip 08045 3
- 8103270349 Forwards revised notification of contract esecution fo "Holding Public Meetings Amid Conflict." DORSEY.M. Administrative Contracts Branch. NRC-10-81-389 B1/03/20 ip 08045-323
- --8103270358 Revised notification of contract execution. Mod 1 to Public Meetings Anid Conflict "Contractor Graduate Bohool. USDA. COLEMAN. R Administrative Contracts Branch NRC-10-81-369 81/03/19 1p 08045 324.
- 8103270423 Notification of contract execution. "Furnish Review Rep Assistance on Draft Critical Elements & Draft Performance Stds for NRC Jobs at 00-15 & Below, "awarded to Lunsford-McKee & Associates. Inc HA9AN.T F Administrative Contracts Branch. NRC-10-81-379 81/03/13 lp. 08045:325
- --8103R70442 Contract "Furnish Review Repts & Assistance on Draft Critical Elements & Draft Performance Stds for hRC Jobs at 09-15 & Below." awarded to Lunsford-McKee & Associates. Inc. LUNSFORD. R C. Lunsford-McKee & Associates. Inc. LEBD.C.D Administrative Contracts Branch. NRC-10-81-379. 81/03/13.
- B103270565 Notification of contract execution-Mod 1 to "Licensing Assistance/Geotechnical & Hydrological Evaluations "Contractor Leeds, Hill & Jouett Inc HARRSTON-C A. FIELDS, J. A. Technical Assistance Contracts Brani
- --BIO327057B Mod | .e:tending period of performance one add1 yr.to
  "Licensing Assistance/Geotechnical & Hydrological
  Evaluations."
  HUNGETI-R. Leeds. Hill & Jewett, Inc. MATTIA.M J. Administr
  Contracts Branch. NRC-02-80-033-02. 81/03/IB 1p. 08034.02
- 8103270594 Notification of contract execution.Mod 1 to "Review Training Acceptance Criteria" Contractor @ Rhodes MCLEAREN.T. Division of Contracts FIN 8-6910 NRC-03-78-157. 81/03/19 1p 08034 059.
- --8103270604 Mod 1. deobligating ercess funds prior to closing out.
  "Review Freining Acceptance Critoria."
  RHODES-0. Rhodes. 0. THOMPSON.R.D. Contract Policy Branch.
  B-6510. NRC-03-78-157 B1/03/19. 1p. 08034-060
- RHODES-0. Rhodes-0. HIDMPSDN.R.D. Contract Policy Branch.
  B-6510. NRC-03-76-157 B1/03/19. 1p. 08034-060

  B103270654 Notification of contract electron-Mod 4 to "Lease of (
  IV Bedans-" Contractor: M Albert Leasing, Inc.
  MARTIN.L C Technical Assistance Contracts Branch NRC-10-78-1
  B1/03/17. 1p. 08043-257.
- --8103270671 Mod 4.decreasing total enount of contract for closeon "Lease of Class IV Bedans." MILLER.D N Mise Albert Leasing, Inc. LEBD.C D. Administral Contracts Brench. NRC-10-78-588 81/03/17. Ip 08043 258.
- B103300439 Notification of contract execution.Mod 2 to "Response Burface Methodology Consulting Bucs." Contractor.GEP Box. LITTLE.M Administrative Contracts Brench FIR 8-6285. NRC-04-78-196 B1/03/19 ip. 08057.170.
- --8103300444 Mod 2.correcting administrative error in amount for closeout to "Response Burface Methodology Consulting Svcs " \* Bor. G.E.P. PERLMAN. J. Administrative Contracts Branch. B-6285: NRC-04-78-196 B1/03/19. ip. 08097:171.
- 8103310B32 Notification of contract elecution.Mod 2 to "Review of Research Plans." Contractor: Intermountain Technologies. HDYLE.A. Administrative Contracts Branch. FIN 8-6303. NRC-04-78-222 81/02/23 1p 08061: 089.

- --B103310838 Mod 2. deobligating belance for closeout, to "Review of NRC Research Plans"

  BROEKITT. 0 Internauntain Technologies. Inc. PERLMAN, J. Administrative Contracts Branch FIN 8-6303. NRC-04-78-222

  B1/02/23 to 08061.090
- B103310893 Notification of contract elecution.Mod 1 to "Buckling Behavior of Steel Containment Shells "Contractor Lockheed Missiles & Space Co MATRETON C. MILES, E.B. Technical Assistance Contracts Branch IRC-03-80-103 B1/03/13 1b 08062 302
- --8103310851 Mod 1. revising dates in contract.to 'Buckling Behavior of Steel Containment Shells " BNEAD.H H Lockheed Hissiles & Bpace Co. (subs. Lockheed Aircraft Corp.). HATTIA.H J Administrative Contracts Branch IARC-03-80-103 81/03/13 2pp 08062.303
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8012110179 PND-I-80-167A investigation into source & sitent of radioactive contamination near Route 17 in Rochelle Perk.NJ. continues Haupood Chemical & Stepan Chemical Cos may be source-but hes not been definitely established. CDSTELLO.F Region I. Philadelphia, Dffice of the Director 80/12/01 1p 07223-102
- 8102260479 Partial response to FDIA request for #11 documents re five categories of info concerning U mills in UT.NM.A2.CO & MY Forwards Documents 1-17 listed in app Document 18 may be obtained from UTIS FELTON.J K Division of Rules and Records 81/02/05 2pp.
- --Bi02260526 Discusses need for stabilitation of tailings pile at Tuba City U mill due to termination of License 6UA-666 Requests that plan for stabiliting pile against wind erosion & schedule for completing work be provided by 6B0331 GILBERT.H.C. Aritone. State of 67/11/29 2pp
- --8102260548 Position paper on "Radon in Structures."

  \* Environmental Protection Agency 80/09/15 96pp
- --B102260556 Provides preliminary analysis of 1969-78 incidence data for lung bone treast liver & thyroid cancers leutemia & mutliple myeloma in Durango.CD. Gamea radiation levels & radon contentrations were found to be elevated FERQUSON.S Colorado. State of 79/12/27 5cp.
- -9102260561 Discusses CO Health Dept proposal to study incidence of acute leuberia & lung cencer in Hose County.CO.Part-time epidemiologist has been retained to work on study due to intense public interest PARBONI.H Sit & Environ. Stds. Br. (Formerly Environ: Prot. Stds. Br.) 787/03/31 p
- --B102260562 Discusses preliminary findings of research proposal. "Study of Apparent Excess Cancer Incidence in Mesa County, CO 1970-75" Study will add to info re effects of low level radiation on women & children.

  ARCHER.V E. HHS, Dept of UB Public Health Bervice. 78/04/03. 3pp
- --8102260566 Forwards request for proposal re Hanford occupational mortality experience & unsolicited proposal re incidence of acute leukewis & lung cancer in Mesa County.CO. Requests review & comments. W/o encl GDLLER.R.R. Division of Siting, Health & Bafeguards Standards. 78/04/14 | jp
- --B102260472 Forwards unsolicited research proposel from CO Health Dept re study of apparent excess cancer incidence in Mesa County, CO between 1970-75 Requests review & comments. PARSONT-M Sit, & Environ Stds Br. (formerly Environ, Prot. 8tds Br.), 78/09/03 16pp.
- --B102260677 Comments on research proposal submitted by CO Health Dept re study of apparent ercess cancer incidence in Mesa County, CG between 1970-75 Proposal lacks evidence of competence of investigators. Recommends support for proposal. COHEN, B. L. Pittsburgh, Univ. of. 78/05/08. 1p.
- --B1022606B3 Notification of 780822 seminar. "Health Effects of Energy Development in CO." in Denver.CO. Agenda & Progress Rept 2 restudy of cancer incidence in Hesa & Weld Counties.CO encl. CUNNINGHAM.M.C. Colorado. State of. 78/08/09. 4pp.

- --B102260692 Forwards request for procurement OBD-78-014 to exto contract NRC-D1-78-014. "Apparent Cancer incidence in Hesa County, CO, 1970-73."
  MINGOUS, R. B. Office of Standards Development. Director ip.
- --8103020746 Request for procurement OSD-78-014 to execute mod contract NRC-01-78-014. "Excess Cancer Incidence in Mesa County " Contractor: CD Dept of Health. MINOQUE.R B Office of Standards Development. Director. I B-10728 NRC-01-78-014 78/08/18 App
- --B102260703 Requests mod to NRC-01-78-014 to reflect changes County cancer research study design Includes revised scope of work No change required in contract budget FEROUSDN.S. Colorado. State of. 78/08/01. 7pp
- --Bi02260711 Forwards proposed FR notice re availability of NUI OdD-Rept contains info re epidemiological investigation or possible relationship between excess cancer incidence in Mesa County. CO & radiation exposure from mill tailings. WHITFIELD-B.C. Radiological Health Standards Branch. 7970 19.
- --7910090482 Forwards NUREG/CR-0635, "Ercess Cancer Incidence: County." Results indicated two-fold increase in leukamia incidence for all ages in Mesa County.

  HINDGUE.R.B. Office of Standards Development, Director. 200. 95031:087
- --7911050328 Forwards request for procurement action. Recommends cover overruh MINOQUE, R. B. Effice of Standards Development. Director. 7 1p. 00887-350.
- --7911050330 Request for procurement DBD-78-014 to execute mod contract N9C-01-78-014, "Excess Cancer Incidence in Mesa County " Contractor CO Dept of Health, HINOQUE, R.B. Office of Standards Development, Director F B-10728 NRC-01-78-014, 79/09/25, 4pp. 00887,351.
- --B102260743 Requests NUREO/CR-0635. "Excess Cancer Incidence to County.CO." for engineering library Univ of HN request encionate. Princeton Univ. 79/10/04. 2pp
- --8102260747 Requests NUREO/CR-0695. "Excess Cancer Incidence : County.CO." HAUZ.M. General Electric Co. 79/09/24. Ip.
- --8102260753 Requests NUREQ/GR-0635, "Excess Cancer Incidents of County, CD." LEWIS. I. Affiliation Unknown. 79/09/24 lp.
- --8102260756 Requests NUREO/CR-0635, "Excess Cancer Incidence : County, CO "
  MATHEMS D.M. Arkenses, Univ. of. 79/09/17 ip.
- --8102260764 Forwards response to 770518 request for explanation statement that NRC lacks clear literaing Authority over storage & disposal of U mill tailings after license expiration.
  ROWDEN.M.A. Commissioners. 77/06/30. 7pp.
- --BI02260770 Discusses AEC authority to require U mill license environ protection measures w/respect to mine tailings as condition to license termination. AEC has authority to require environ protection measures.

  MALSCH.M.D. Atomic Energy Commission. 73/03/22. 3pp.
- --BI02260775 Discusses AEC authority to regulate radium contain accumulated U mill tailings piles. AEC has no regulatory jurisdiction over radium in U mill tailings piles.
  HENNESBEY.J.F. Atomic Energy Commission. 66/06/07. App.
- --8102260782 Discusses AEC regulatory authority over U mill tenhas no regulatory jurisdiction over redium in U mill tallings piles.

  BMAPAR.H.K. Atomic Energy Commission. 69/09/22. 2pp.
- --8102260787 Discusses CO Public Health 1tr re AEC jurisdiction wasts mast produced by U mill AEC has no regulatory jurisdiction over radium in U mill teilings piles.
  Jurisdiction lies w/local authorities.
  OLSON.L.K. Atomic Energy Commission. 60/04/15. 3pp.
- 8102260804 FOIA request for all documents re five categories of

07820 090

- BIO3020033 Responds to FDIA request for SECY-76-249. "Foreign Dunership of Production & Utilization Facilities." Forwards document FELTON.J.M. Division of Rules and Records BI/02/09. 1p 07783-036
- --BI03020045 BECY-7a-245
  Informs Commission of problems in defining foreign ownership control or domination w/respect to facility licenses & NRC monitoring of foreign participation Recommends approval of encl draft ltr.
  CHAPMAN.R R Office of Nuclear Material Bafety & Bafeguards.Director. 76/04/30. 40pp.
- Bi03020036 FOIA request for SECY-76-245, "Foreign Ownership of Production & Utilization Facilities," DOYLE.B H. Affiliation Unknown. Bi/01/19, 1p. 07783-037
- B10302004B Responds to FOIA request for documents relicenses issued for all spent fuel piles to be cleaned up under U Mill Tailings Act of 1978 NRC has no documents subj to request FELTON.J. M. Division of Rules and Records B1/02/23 1p. 07793.03B
- 8103020053 FOIA request submitted on behalf of Pittsburgh Press for documents re licenees issued for all spent fuel piles to be cleaned up under U Mill Teilings Act of 1978.
  HARBRECHT, D. Affiliation Uningum. B1/01/15 ip 07783:039
- --8103020057 Forwards D Harbrecht FDIA request for licenses issued for spent fuel piles to be cleaned up under U Mill Tailings Act of 1978 Requests response FREDLUND.R.R. Energy. Dept. of. 81/01/30 p. 07783:040
- 8103020079 Add1 response to FDIA request for IS categories of documents re Memorandum & Order CLI-80-21 & IE Bulletin 79-018. Forwards documents listed in App A App B documents are withheld advice & recommendations (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 81/02/23 3pp 07787: DAA
- --B103020087 Discusses NRC interpretation of Commission B00527 order reenviron qualification & fire protection (CLI-B0-21). Commission should express dissatisfaction to staff & correct interpretation BRADFORD-P.A. Commissioners COMPB-80-25, 80/07/25, ip
- --B0121B0303 Forwards responses to industry questions & comments be Commission 800323 order & memo per 800804 request. DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 80/09/22 17pp 03788.082
- 8103030037 Responds to FDIA request for summery meeting minutes of ACRB Subcommittee on Extreme External Phenomena as identified in BIO115 FR notice Minutes are not yet available. Lists documents of interest which may be purchased from PDR. FELTON.J.M. Division of Rules and Records. 81/02/17 ip 07791:159.
- B103030044 FD1A request for summary meeting minutes of ACRS Subcommittee on Extreme External Phenomena as identified in B10115 FR notice. BANNER, A.P. Affiliation Unknown. B1/01/22. ip 07791.160
- Bi03030052 Responds to FDIA request that BECY-80-243 be placed in PDR. Forwards document which will be placed in PDR. FELTON, J. M. Division of Rules and Records. 81/02/09. ip. 07791:161.
- --8103030066 BECY-80-243
  Responds to JF Ahearne 800402 info request re summary of experience, duties & number of shift technical advisors required onsite Duties include diagnosis of off-normal events & advising shift supervisor on corrections.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/05/13 2pp.
- --BI030300B3 Forwards "Nuclear Power Plant Shift Technical Advisor: Recommendations for Position Description, Qualifications, Education & Training." THDMAS.E.L. Institute of Nuclear Power Operations. B0/04/22. ip.
- --Bi03030089 "Nuclear Power Plant Shift Technical Advisor:Recommendations for Position Description, Qualifications, Education & Training."
  \* Institute of Nuclear Power Operations. 80/04/18. 23pp.

- 8103040230 Responds to FDIA request for H Denton 771010 memo be supporting documents Forwards documents listed in App A.Rept entitled "Humboldt Bay Power Plant Bite Geology Investigation" is available in PDR FELTONIJ M. Division of Rules and Records B1/02/24 2pp
- Bj03040242 FDIA request for H Denton 771010 meno & supporting documents ARMBTRONS, R. E. Armstrong, Byrd & Associates, Inc. 81/01/29. 1p
- 8103040704 Add1 response to FDIA request for documents written by Royche Forwards BC Rusche 750626 ltm to JM Hendrie Document will be placed in PDR FELTON, J M. Division of Rules and Records. 81/02/14 lp. D7819 252
- --8103040716 Expresses appreciation for excellent work rendered to completing initial publication phase of BRP Div of Personnel has been requested to terminate consulting contract as of 790612

  RUSCHE, N. C. Office of Nuclear Reactor Regulation, Director. 79706726
- B103040724 Responds to FOIA request for winning proposal under RFP-B0-101 Forwards requested info including proposal. H Dhillon 800804 Lt to NRC representations & certifications proposal surmary & data sheet & contract pricing proposal FELTON.J H Division of Rules and Records. 81/02/10 1p 07820 079
- --8103040735 Forwards proposal in response to RFP-NAR-B0-101. "PWA Bevere-Accident Delineation & Assessment." Proposal surmary & data sheet & representations & certifications encl DHILLOM.H California, Univ of. Los Angeles. 80/08/04 14p
- --Bi03040744 Response to RFP RS-NRR-20-101, "PUR Severe-Accident Delineation & Assessment "Proposes to perform analyses & assessments of specific mater reactor safety-related issues includes technical approach & prof & related experience KASTENDERG, W.E., LESTMAN, R.A., DHILLEN, H. California, Univ. D. Los Angeles RS-NRR-80-101 80/07/31 97pp
- 8103040727 FOIA request for winning proposal submitted under RFP-Ni 80-101 MACFARLANE.D.R ETA Engineering inc. 81/01/12 ip. 07020 080
- 8103040771 Add1 response to FDIA request for info re incidents reunaccounted for 5 other types of safeguards violations Forwards NUREQ-0430, Vol 1 Number 4. NUREQ-0390, Vol 1. Number 1 is available at NTIS W/o NUREQ-0430. FELTON. J M Division of Rules and Records 81/02/11 1p. 07819. 294.
- 8103040779 Responds to FOIA request for repts 3 documents re 'Proj Cowboy" conducted by AEC from 1960-1965. Lists repts evailable at NTIS Other repts are available at DEE Forwards UCRL-3578. "Proceedings of Second Ploushare Symposium" FELTON. J. M. Division of Rules and Records 81/02/05. Ip 07019-205
- --Bi03040791 UCRL-5678
  Plowshare Series Rept 2. "Proceedings of Becond Plowshare Symposium 590913-15.8am Francisco.CA "
   Lawrence Livermore Laboratory 59/09/15. 104pp
- BiO3040792 Responds to FDIA request far \$1: categories of info re radioactive mails found in Maywood & Rochelle Park.NJ Forwards documents listed in App A & NRC BiO122 press release. W/o press release FELTON.J M Division of Rules and Records 81/02/13 2pp. 07816: 321.
- --Bi03040792 Chapter 5 of "Thorium: Industrial Hygiene Aspects "
  ALBERT, R.E. New York Univ. Medical Center New York:NY 66/12
  Boo.
- --B103040796 ANL-7291 R1
  Revision 1 of "Radiation Befaty Technician Training Course "
  MOE.H J. LABUK, B R, SCHUMACHER, M C. Argonne National Labora 72/03/31 16pp.
- BIO3040785 FOIA request for repts & documents re "Project Cowboy" conjucted by AEC from 1960-1965, MCLEAI8H.J. Affiliation Unknown. 81/01/08 3pp. 07819 257
- 9103040787 FOIA request for six categories of info re radioactive
- 8103030057 FOIA request that SECY-80-243 be placed in PDR

- 8103040799 Responds to FOIA request for documents to Bay Area Law Enforcement & Security Liaison Group: Including correspondence w/RRC Forwards documents listed in App A FELTON J.M. Division of Rules and Records BI/02/06 2pp 07819-260
- --BIO3040B11 Requests info to update next association directory info will enable more accurate listing of members & organizations SENSENDERFER.W Eight Bail Association 80/09/05 Ip
- --8103040816 Requests info to update next association directory Info will enable more accurate listing of members & organizations. HAWKINS, J. Eiglt Ball Association 79/10/16 1p
- --Bi03040B44 Requests info to update neit association directory Info will enable more accorate listing of cambers & organizations MARNIB. J & Eight Ball Association 78/10/02 ip
- --Bi03040890 Requests info to update next association directory info will enable more accurate listing of members & organizations MCQUEEN. A Eight Ball Association 77/09/01 lp.
- --BIO3040855 Requests info to update next association directory info will enable more accurate listing of members & organizations MCOUGEN.A Eight Ball Association 76/09/10 1p.
- --8103040861 "8-8atl Association Membership Registry, 1980 "
  \* Eight Ball Association 80/12/31 52pp.
- B103040B04 Add1 response to FDIA request for memorandum of understanding between ARC & other named agencies he nuclear threats Forwards memorandum of understanding between ERDA & ASC FELTON J.H. Division of Rules and Records B1/02/13 1p 07820 062
- --Bi03040Bi0 Remorandum of understanding between NRC & ERDA re guidelines for cooperation re special info concerning nuclear technology or activities • Energy, Rept of • Commissioners. 77/03/10 2pp
- B103040805 F01A request for documents he Bay Area Law Enforcement & Security Liaison Group.including correspondence w/NRC ANDRES M Center for National Security Studies. 81/01/13 2pp 07819 262
- R103040998 Responds to FOIA request for current list of Agreement States & addresses Forwards list. FELTON J M Division of Rules and Records 81/02/23 1p 37813 340
  - d103041009 List of Agreement States & addresses & Commissioners 80/10/01 3pp
- B103041001 FOld request for current list of Agreement Btates & addresses MILLINS.R E Proctor & Gamble Co 81/01/23 ip 07813:341
- 8103350343 Responds to FOIA request for all proposels submitted in response to RFP RG-80-188 Forwards nanproprietary versions of proposels
  FELTGM. J M Division of Rules and Records. 81/02/19 2pp 07897-032
- --8103050059 Repreprietary version of revised response to PPP RS-RES-80-188. "Foreign Research & Licensing Practice Coordinator for Operal Reactor Safety Research "Includes responses to specific NRC questions re proposal w URS corp John A Blume & Associates. Engineers (subs URS Corp ). RS-RES-80-188 80/10/31 Aipp
- --8(03050069 Nonpraprietary version of response to RFP R8-RES-80-188. "Foreign Research & Licensing Practice Coordinator for Ceneral Reactor Sefety Research." Vol 2. Describes technical issues & scope of work. 4 URS Corp. • John A. Blume & Associates, Engineers (subs. URS Corp.). R8-RES-80-188 80/06/30 19pp

- --BI03050102 Nonproprietary version of response to RFP RB-RES-80-188, Foreign Research & Licensing Practice Coordinator for Qeneral Reactor Safety Research 'Includes scope of work & recommendation of foreign countries & schedule Nuclear Services Corp. RS-RES-80-188 80/05/30 26pp
- --8103650110 Nonproprietary version of response to RFP RG-REB-80-188,
  "Foreign Research & Licensing Practice Coordinator for
  General Reactor Eafety Research." Part 1 Includes technical
  approach-potential problems & related experience

  International Energy Associates. Ltd RB-REB-80-188 80/06/05
- --Bi03050119 Nonproprietary version of response to RFP RB-RES-80-18B.
  "Foreign Research & Licensing Practice Coordinator for Owneral Reactor Bafety Research." Vol 1. Includes technical approach statement of work & mgt plan
   Brience Applications, Inc. RS-RES-80-18B. 80/06/03 41pp.
- --8103050127 Nonproprietary version of response to RFP R8-RE8-80-188, Foreign Research & Licensing Practice Coordinator for Oeseral Reactor Sefety Research." Vol 1. Includes introduction & summary & detailed scope of work # D'Appolonia Consulting Engineers. Inc R8-RE8-80-188 80/08/30 34pp
- --Bi03G50132 Nonproprietary version of response to RFP R8-REB-80-188.
  "Foreign Research & Licensing Practice Coordinator for Oeneral Reactor Safety Research." Vol 1 Includes technical approach & conceptual framework.

  E Envirosohere Co R8-RES-80-188 B0/06/30 41pp
- --B103050137 Nonproprietary version of response to RFP RB-RES-80-188.
  "Foreign Research & Licensing Practice Coordinator for
  General Reactor Safety Research." Vol I includes technical
  approach.corporate qualifications.project team & mgt
   Boor Allen & Hamilton. Inc. RB-RES-80-189. B0/06/05. 54pp
- --Bi03050149 Nonproprietary version of response to RFP RB-RE6-80-18B. "Foreign Research & Licensing Practice Coordinator for General Reactor Bafety Research." Part 3 Includes scope of work.project approach.organization & personnel e Burns & Ros Co. R8-RE5-80-18B 80/06/04. 20pp
- --8103050155 Nonproprietary version of response to RFP RG-REG-GO-188.
  "Foreign Research & Licensing Practice Coordinator for General Reactor Bafety Research" Includes scope of work, technical support & tasts.nilestones & products Colder Associates RB-REG-80-188 80/06/30 16pp.
- --8103050163 Nongroprietary version of response to RFP R8-R68-80-188.
  "Foreign Research & Licensing Practice Coordinator for General Reactor Bafety Research." Part 1 includes background & methodologies for conducting activities a 0.0pnnell & Associates. Inc. R8-R68-80-188. 80/06/30. 62pp.
- --8103050171 Nonproprietary version of Addendum 1 to response to RFP RB-RE8-80-168. "Foreign Research & Licensing Practice Coordinator for General Reactor Eafety Research." Part 1 Constitutes best & final offer O'Donnell & Associates, Inc. R8-RE8-80-188. 80/10/31 31pp.
- 8103050049 FDIA request for all proposals submitted in response to RFP RB-80-188 MEIERAN.H 8 O'Donnell & Associates, Inc. 81/01/23 1p. 07827 034
- 8103090471 Responds to FQIA request for eight documents reradionuclides in food chain. Forwards documents. FELTON.J.M. Division of Rules and Records. 81/02/20. 1p 07826.101
- --8103050484 Forwards K Rothman & 8 Blum review comments on paper entitled "Environ Influence on Impature Infant Burvival UI 1943-75 " PARSONT.M A Radiological Health Standards Branch. 80/09/10 Ip.
- ~-8103090492 Corments on paper entitled "Environ Influence on Immature Infant Burvivel WI 1963-79." Evidence presented does not warrant conclusion that nuclear plant emissions caused high infant mortality rates. R Dertell review encl. BLUM.8. Mt Binai Medical Center New York-NY 80/09/03. Spp
- --8103050800 "Radionuclide Levels in Milk & Pregnancy Outcomes in WI. 1963-75." BERTELL, R. DIXON, O. JACOBSON, N. Affiliation Unknown 75/12/31.

```
8103050479 FOIA request for eight documents re radionuctides in food
    chain
Rabultu.
                         Center for Farm & Food Research, Inc. 81/01/27 10
    07826 102
8303050867 Responds to FOIA request for winning technical proposal submitted under RFP RS-NMS-81-032. "Technical Support for Confidence Rulenaling Proceeding." NRC has suspended effort to award contract FOIA request has been withdrawn.
    FELTON, J. H. Division of Rules and Records 81/02/24 in
    07839 343
8103050878 FOIA request for winning technical proposal submitted under RPP RB-NNB-81-052. "Technical Support for Confidence Rulemaking Proceeding" RUTHERFORD. J. F. BBM Corp. BDM/W-JFR-B738- B0/12/12 ip
    07829 344
BIOGO60027 Responds to FOIA request for 16 categories of documents
Forwards documents W/o encis
FELTON.J.M. Division of Rules and Records B1/02/25 Ip
    07838.348.
8103060034 FOTA request for 16 categories of documents JONES:L Black Hills Alliance B1/01/15 2cm 07838 349
8103060054 Responds to FOIA request for 15 specific decuments Forwards 14 documents Document 11 was not reproduced due to poor
    legibility W/o encl
    FELTON, J. M. Division of Rules and Records 81/02/25 1p.
    07838:351
8103060058 FOIA request for 15 specific documents
JONES L. Black Hills Altiance 81/01/23, 2pg. 07838 382
8103060066 Responds to FDIA request for info re types or classes of persons making FDIA requests to NRC Forwards listing of FDIA requests received for 1978-1980.
    FELTON, J. M. Division of Rules and Records 81/02/26, ip
    0783B 354
--8103060073 Listing of FDIA requests received for 1978-80
* Division of Rules and Retords 81/02/26 ip.
8103060071 FOIA request for info re types or classes of persons making
   FOIA requests to NRC.
CASSIERE, J. N. Affiliation Unknown 81/02/18. ip 07838 355
8103120201 Responds to FOIA request for documents re Union Carbide Corp
   Chord Project in Edgemont 8B. Forwards Documents 1-3 listed on app. Documents 4 & 5 are being referred to Dept of Agriculture for disclosure determination & direct response. FELTON.U.M. Division of Rules and Records. 81/03/04. 2pp.
   07901-319
--8103120218 Informs NRC that environ rept & license application for SD heap leach U operation will not be completed until late in first quarter of 1979. Lists reasons for schedule change. HILLER.R.L. Union Carbide Corp., Metals Div. 11677. 78/01/04.
```

- MILLER.R.L. Union Carbide Corp., Metals Div 11677. 78/01/04.

  1p.

  --B103120227 Confirms 77:122 telcon re Union Carbide Corp U mining/
  milling project in 80 Forest supervisor will not approve
  mining plan that will authorize mining activities beyond
  exploratory stage before environ impacts are evaluated
  BCARAND.R.A. Fuel Process. & Fab. Branch (Pre 790727) 77/11/23

  1p.

  --B103120236 Summary of 78:215 meeting w/Union Carbide Corp & D'Appolonia
  Consulting Engineers in Bilver Spring.MO to discuss proposed
  commercial scale heap leach Chord.80 project.Lists meeting
  attendees & major points of discussion.
  RUTHMCETSCM.J. Fuel Process. & Fab. Branch (Pre 790727)
  78/12/11. 3pp.

  B103120210 F0IA request for documents re Union Carbide Corp Chord
  Project in Edgemont-BD.
  01800480.P.R. 8 Slack Hills Allience. B1/01/30. 4pp. 07901:321.
- 8103120246 Supplemental response to FDIA request for documents republic opinion on nuclear energy & issues concerning use of nuclear power as means of energy production. Forwards documents listed in App A.W/o enci NURED-0701.
  FELTON, J. H. Division of Rules and Records. 81/03/02. 2pp. 07900.341.

```
B103120Bi4 Responds to FDIA request for names, duty stations & ott identifying info re NRC employees in MD-VA & Washington-DC FRC telephone directory can be purchased from GPD FELTON, J. M. Division of fiules and Records B1/02/27 ip 07901 339
```

- BiO3120819 FOIA request for names duty stations & other identify info re NRC employees in MD.VA & Hashington.DC TURNER, C.H. Federal Employee Denticare Program. 81/02/03 1; 07901:340

  BiO3120827 Responds to FOIA request for final repts re investigations.
- BID312082/ Responds to Folk request for final rapes re investigation of causes & sources of radiation exposures suffered by licensed users of radioactive devices in DA during past unforwards documents listed in app. FELTON. J. M. Division of Rules and Records 81/03/05 2pp. 07901 341
- --8103120839 Westly info rept for whending 810206 REHM.T A Uffice of the Elecutive Director for Operations 81/02/11 2pp
- --8502120122 Forwards IE investigation rept of License 35-17170-0 791219 & notice of violation BROWN.O D. Region 4. Dailas. Fuel Facility & Materials Rafet Branch. 80/01/14 2pp. 02381:071
- --8002120126 Notice of violation from insp on 791219
   Region 4. Dallas, Office of the Director 60/01/14 ip
  02381 073
- --8002120133 IE investigation rept of License 35-17178-01 on 7912 Noncompliance noted individual overexposed to radiation & unauthorized street address BROWN O. D. Region 4, Dallas. Fuel Facility & Materials Safet Branch CAIN.C. Region 4. Dallas. Office of the Director 80/01/14 4pp 02381 074
- 8103120830 FOIA request for final repts re investigations of caus sources of radiation deposures suffered by licensed users of radioactive devices in CK during past yr.

  MCCARTHY.T. Gliahoma Publishing Co. Daily Oklahomian-Oklahoma
  Times 81/01/29 2pp. 07901 343
- 6006270164 Forwards proposed amend to IOCFR50. "Staffing & Maj Ho Hours at Nuclear Power Plants " Comments requested by 806530. HORRISON.W.M. Assistant Director for General Engineering Stand
- MORRISON W.M. Assistant Director for General Engineering Stand BO/05/09 15pp 02797 006
- B103160B1D Responds to FDIA request for listings of tempanies lic to build Pacifities for radiation sterilization & companies performing radiation sterilization in Puerto Rico NRC has no documents subj to request. FELTON-J H. Division of Rules and Records 81/03/09 ip 07915.259
- B103160815 FDIA request for listings of companies licensed to but facilities for radiation sterilliation 5 companies performing radiation sterilliation in Puerto Rico FOI Bycs. Inc B10219 ltr to HEW encl # FOI Services 12778 B1/01/13 2pp 07915 260
- B10316CB23 Add1 response to FOIA request for 57 documents referent Tokar memo to ACRS re-pellet-cladding interaction. Forwards documents listed in app.
  FELTON.J H. Division of Rules and Records B1/03/09 2pp.
  07915-223
- "-8103160847 NEDG-24223
  "Assessment of BWR/3 Mittigation of ATMS (Alternate 3)."
  SMERHODDO 0 . BRANDON.R J General Electric Co SONEDO20
  81/02/28. 167pp.
- --Bi03160B90 NEDD-24222 VI
  "Assessment of BHR Mitigation of ATHS.Vol I. (NUREG-0460 Alternate 3)"
  SHERWOOD.0 0., DITMORE.D C General Electric Co BONEDO21 B1/02/28 225pp
- --8103160855 NE0D-24222 V2
  "Assessment of BWR Mittigation of ATWS.Vol 2. INUREO-0460
  Alternate 3)
  BHERHOOD.0 0 , MATHER.S.L. Oeneral Electric Co 81/02/28
- 8103160864 Add1 response to FOIA request for all documents re Nuc Matis & Equipment Corp & NRC investigation into Executive Director for Operations previously withheld remarks Forwards

- --8103160859 Rept of overview study of existing safequards regulations Transcript excerpt encl
  CONRAM.J H NRC - No Detailed Affiliation Given 76/04/29 59pp
- --8103160873 Submits review of Jd Conran 770413 meeting w/Task Force Lists issues & key points Transcript except entl SNYDER.B J Office of Policy Evaluations 77/04/18 6pp
- 8103166879 Partial response to FOIA request for all documents re Kase, Scholer, Fierman, Hays & Handler Forwards ARC 810217 1tr u/38 page app. W/o enct.
  FELTON: J M Division of Rules and Records 81/02/25 07915: 244
- 8103170175 "Decennial Census of US Climate Summary of Hourly Observations: 1951-60 " Magnetic tape w/documentation encl Commerce.Dept. of 60/12/31 21pp
- Biodi70202 Responds to request for views on scope of AEC legal authority to require licenses formerly engaged in U milling operations to stabilize mill tailings includes facts & law discussion MAPES, J.R. Atomic Energy Commission 73/12/19 600.
- --8103170212 Discusses AEC regulatory authority over U mill tailings AEC has jurisdiction over all source matls U & thorium in tailings do not constitute hazard to health & safety. PRICE-H L Atomic Energy Commission 65/09/22 2pp.
- --BI03170219 Responds to request for views on whether AEC regulatory authority & requirements may be applied to mill tailings containing certain quantities of radium AEC jurisdiction over transfer of waste tailings not supported

  Atomic Energy Commission 60/12/07. 5pp
- --8007240919 Discusses NRC authority to order cleanup of offsits tailings contamination Office of the Executive Legal Director. 80/03/31 7pp 03023 234
- B103170193 F0IA request for all written legal opinions & documents re ARC role in control of offsite tailings locations & whether NRC has authority to order cleanup of locations REID.A B Affiliation Unknown B1/01/28. Ip 07939 097
- 8103170291 Addl response to FDIA request for documents re investigation, audit of regulatory proceeding involving Enserch Corp & subsidiaries or affiliates & correspondence within past 10 yes Forwards App C documents. FELTON.J S Division of Rules and Records B1/02/27 3pp 07934: 325
- --8103170R97 Recommends that ARC provide clarification of IOCFR21 regulation to sub-tier vendors or revise rule to exclude sub-tier vendors from IOCFR21 requirements. O'DONNELL, E.P. Ebasco Services, Inc. (subs. of Enserch Corp.) 78/03/03 200
- --BI03170299 Forwards Ebasto, Inc 780503 request for comments re 10CFR21 reporting requirements Requests response W/a encl. SHIELDS. 8 Defice of the General Countel. 78/09/11.
- --8103170262 Forwards Ebasco, Inc 780803 request for comments re 10CFR21 reporting requirements Requests response W/o entl SHIELDS. W M Defice of the General Counsel 78/05/30
- --BiO3170270 Responds to 780903 request for comments re 10CFR21 reporting requirements Reporting requirements of 10CFR21 are applicable to safety-related equipement & evic delivered after 770810 Rulemaking action is underual to amend 10CFR20. MALSCH.M.G. Office of the General Counsel 78/07/25. Ip.
- --8103170275 Discusses Ebasco.Inc alleged coverup of evidence re seismic & volcanic risks at Philippine plant site.Alleged charges would not constitute violation of US fraud statutes Hatter will be referred to BOJ CUMMINOS.J.J. Office of Inspector & Auditor. 79/12/28 2pp.
- --8103170280 Forwards DOJ response to 791231 referral re alleged coverup of Philippine gover plant solsmic & volcanic risks There is no prosecutable offense against UB laus. M/o encl.

  CUMMIN98.J.J. Defice of Inspector & Auditor. 80/01/21. 1p
- --8103170285 Forwards 8J Chill 791015 memo & JJ Cummings 791228 & 3L

- 8103180595 Resconds to FOIA request for documents re burial of response to the court request for accuments to dutiled of radioactive thorium on property of Haywood Chemical Forwards documents listed in App A Info partially withheld names & addresses (ref FOIA Exemption 6). W/o encis. FELTON. J. H. Division of Rules and Records 81/03/03 1100 A7053 504
- 9103180595 FOIA request for documents re buriel of radioactive thou on property of Maywood Chemical.

  KUM: FG.E. Affiliation Unknown. 81/01/29. 10 07952.216
- B103180397 Addit response to FOIA request for documents re five categories of Info on U mills in UT.NM.AZ.CO & MY. M/o encis. FELTON, J. M. Division of Rules and Records. B1/03/12. Spp. 07953.333
- 8103180598 Responds to FOIA request for documents prepared by MD Trifunac re meetings w/ACRB Documents are available in FELTON, J.M. Division of Rules and Records 81/03/12. 10 07993 340
- B1031B0599 FOIA request for documents prepared by MD Trifunac remeetings w/ACRS

  JORDAN, W S Sheldon, Harmon & Weiss, 81/02/26 2pg. 07993.341
- B103190682 Bolicitation.offer & award of "Photographic Reproduction Svc" to Bara Photographics, Inc. MATBON. W Affiliation Unknown LEBO. C D Administrative Contra MATBON.W Affiliation Unknown LEBO.C ( Branch NRC-10-81-387 81/03/10 31pp
- 8103230681 Responds to FOIA request for 10CFR50. Forwards info. W/o s FELTON.J.M. Division of Rules and Records 81/03/18 ip. 07978 359.
- 8103230688 FDIA request for 10CFR50 & supporting documentation EBERLEIN.F. Control Data Corp. 81/03/09. 1p 07978 360
- R103230494 Responds to FOIA request for names, eddresses & phone num of NRC employees involved in furniture cleaning or upholstery shampooling in past 2 yrs Request is Inappropriate for FOIA No NRC employees have been involved in such work FELTON. JM. Olivision of Rules and Records. 81/03/17. 1p. 07978: 361
- B103230702 FDIA request for names, addresses & phone numbers of NRC employees involved in furniture clasming or upholstery shampooing in pest 2 yrs STOVALL-T L Affiliation Uninown. B1/02/27. ip 07978:362
- 8103230709 Responds to FDIA request for comments & NRC responses to comments on proposed rules 10CFR30,32,70 & 150 FEB containing MRC responses will be provided when available.
  Other comments are available in PDR H/o snc1 locrey.
  FELTON.J H. Division of Rules and Records. 45FR70874 B1/03/17 1p 07980 290
- B103230714 FOIA request for comments & NRC responses to comments or proposed rules 10CFR30,32,70 & 150.
  HDN1CKER,J. Affiliation Unknown. 80/11/11. 3pp. 07980:291
- 8103230719 Add1 response to FOIA request for memorandum of understanding between NRC & other named agencies re nuclear threats Forwards memorandum of understanding between NRC & Defense Intelligence Agency.
  FELTON, J. M. Division of Rules and Records. P=200. B1/03/17. I
- --Bi00230722 Membrendum of understanding between NRC & Defense Intelligence Agency re use of intelligence info. Working relationship statement encl.

  Defense Dept of. Defense Intelligence Agency. AMEARNE, J. F. Commissioners. 80/11/24. 11pp. 07978: 349.
- 8103260048 Add) response to FOIA request for six categories of info radioactive matts found in Maywood & Rochelle Park, NJ. Forwards documents listed in App A Documents 1.2 & 6 partially withheld:home addresses (ref FOIA Examption 6). FELTON-J.H. Division of Rules and Records, 81/03/03, 11pp.
- --8005010214 Matl/Byproduct License 29-13725-02 for Stephan Chemica JONES, J. A. Licensing Management Branch. 80/04/08. 1p.
- --B103260059 Handwritten notes re radioactive matts found in Maywoo

- --Bi03260067 Draft chronology of Maywood Chemical Horks/Stepen Chemical Co. Handwritten notes re environ sampling encl. Info partially withheld home addresses & phone numbers (ref FOIA Exemption 6)

  Stepen Chemical Co. Bi/02/10. 33ap.
- --5103260076 Submits facsimils request.List of attendees at meeting at Stepan Chemical & results of land survey enci. SNYDER.O. L. Region 1, Philadelphia, Office of the Director 81/02/10 3pp
- --8103260081 Forwards info re radiation hatards & thorium in response to request during 801217 public meeting in Rochelle Park,NJ H/G encls.
  SMITH.O. H. Region I. Philadelphia. Fuel Facility & Haterials Bafety Branch. 81/01/30. ip.
- --81032600B7 Forwards enalysis rapt for Stapan Chamical Co.from Samples 37(12:59613:59614 & 59615 BREZENGKI.F T. Environmental Protection Agency 81/01/27 8pp
- --8103260092 Requests site survey to determine suitability for unrestricted use.

  KCNIERNEY, E. J. Managod, NJ. 81/01/23 in
- --B10326011D "Proposed Industrial Bite Rochelle Park NJ. Bubsurface Exploration "
  - Johnson Boile Engineering Co. 67/09/31. 25ap.
- --Bi03260142 Discusses whole body thorium count for residents in vicinity of Stepan Chemical Co. Region i is investigating extent of affaite contamination. Recommends that NRC set up whole body counter in area during First Quarter 1981.

  ORIER. B. H. Region i, Philadelphia, Office of the Director.

  81/01/16 ip.
- --Bi03260148 Recommends that encl meno be sent to V Stello requesting that whole body counting be made available to residents in vicinity of Stepen Chemical RA Fiors Bi0105 ltr to Congress & handwritten notes encl. H/o encl memo KINNEMAN, U.D. Region 1. Philadelphia. Office of the Director. BI/O1/16 72pp.
- --B103260176 Analysis of soil samples collected on B01125. \* Stepan Chemical Co. 80/11/25 34pp
- ---Bi03260183 Requests that Stepan Chamical Co site be given high priority for aerial radiological survey due to discovery of excessive thorium contamination Previous surveys & info reunrestricted areas encl. KINNEMAN.J.D. Region i. Philadelphia. Office of the Director. B0/11/25. 33pp.
- --Bi03260273 Requests termination of Mat1/Byproduct License 29-13725-02. Tritium disposed of by Radiac Research Corp. Receipt encl. BMANBON.E.A. Stepan Chemical Co. 03004 B0/02/21. 2pp
- ~-Bi03260293 Ack receipt of 770411 itr informing NRC of steps taken to correct & prevent violations noted in IE insp of License 29-13725-02.
  NELSON,P.R. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch. 77/04/28. 1p.
- --Bi03260304 Discusses renewel of License 29-13725-02 to store byproduct matls (tritiated proteins). W/o ltr to NRC requesting license renewel.

  BMAMSON, E. A. Stepan Chemical Co. 77/04/11. ip.
- --Bi03260311 Ack receipt of 770128 ltr informing NRC of steps taken to correct & prevent violations noted in IE insp of License 29-13725-02.
  NELBON.P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Brench. 77/04/06. Rpp.
- --BIO3260330 Forwards source matl license application form & license fee schedule, in response to request MY oncl.
  MEISS.D. License Fee Management Branch. 77/02/22. ip.
- --Bi03260338 Ack receipt of NRC 770119 itr re noncompliance of activities. Further resolution is necessary before commitment for corrective action is confirmed.

  BMANSON, E. A. Stepan Chemical Co. 77/01/28. 1p.
- --8103260346 IE insp rept on 761229.Noncompliance noted:thorium possessed at two underground storage locations w/o valid license. GLENN.J. Office of Inspection & Enforcement, Office of the Director. 76/12/29. Spp.

- --BIOJ260354 Advises that Stepan Chamical Co must renew License BTCto authorize storage of thorium
- --8103260362 Requests add1 info specified in Items 8-15 of application for amend of License 29-13725-02

  8ASSIN:N Licensing Management Branch 58921 75/10/30. 1p.
- --8103260369 Met1/Bygroduct License 27-13725-02 for Stepen Checical authorizing possession.use & storage of 331 rCt H-3 88861N.N Division of Fuel Cycle & Material Safety. 79/10/30.
- --8103260374 Application for mati/byproduct license to authorize possession.use & storage of 331 mCi H-3 8HANBON, E A Stepan Chemical Co. 58521, 75/09/19, 2pp.
- --B1032603B2 Discusses expiration of Matl/Byproduct License 29-13725 as of 750731 Requests that vender submit application for new license or discontinue all actions under expired license except storage. Agriel photograph encl.
  BINGER.B. Division of Fuel Cycle & Material Safety. MF M. 34 75/09703 3pp
- --8103260389 Ack receipt of 720829 & 0911 itrs informing AEC of step taten to correct violations noted in insp of licensed program
  O'REILLY, J.P. Atomic Energy Commission, 72/09/21, ip.
- --B103260397 Responds to AEC 720630 ltm re-noncompliance w/AEC requirements. Corrective actions storage area for redinative math has been labeled. Record is kept of all radioactive math used-retained & disposed.
  RED.R.R. Stepan Chemical Co. 72/09/11. 2pp
- --Bi03250403 Confirms telcon re rectification of violations cited by Forwards RE Brintman 720726 itr amending License 29-13725-01 to include 387 mCi tritiated matl RIBD-R.R Stepan Chemical Co. 72/08/29 ip
- --B103260410 Mati/Byproduct License 29-13725-01 for Btepan Chemical of amended in its entirety per 720707 application Amend 1 increases radioactive matl to 387 mCi.
  BRINKMAN-R E Atomic Energy Commission 72/07/26. Ic
- --Bi03260417 Bubmits application for amend to License 29-13725-01-to store 3B7 mCi tritium in form of tagged polypeptides & acylated polypeptides of specified activity RIBO-R.R. Stegan Chemical Co. 72/07/07. 2pp
- --Bi03240425 Discusses IE insp of License 29-13725-01 on 720616 Noncompliances noted:storeroom & refrigerator did not have radiation caution label. Storeroom & refrigerator were not locked.

  D'REILLY, J. P. Atomic Energy Commission. 72/06/30. 2pp
- --Bi03260435 Discusses IE insp of License 29-13725-01 on 720616 Insp revealed four items of noncompliance not affecting public health or safety. Biteps have been taken to correct noncompliances. Outstanding items & insp field notes encl gPSTEIN.E. Atomic Energy Commission. 72/06/30 4ipp
- --9103260513 Mat1/Byproduct License 29-13725-01 for Stepan Chemical authorizing possession & use of 100 mC( H-3 BRINKMAN,RE Atomic Energy Commission. 70/07/01. Ip.
- --Bi03260319 Submits application for arend to License 29-13728-01 to reduce amount of tritium to 100 mCi & to omit requirement for tritiated water.
  RIBO-R R. Stepan Chemical Co. 70/06/30. 1p.
- --8103260526 Application for matl/byproduct license authorizing RR R to use &/or supervise use of 1,000 mCi tritium in form of tritiated water & tritiated polypeptides.
  R180.R R. Stepan Chemical Co. 16637. 70/06/24. 2pp.
- ---81032606B8 Submits info in response to AEC 640106 ltr re violation facility. All drums of thorium-containing products have been removed from bldgs. Roadway areas have been cleaned of radiation-containing debris. Safety instructions encl. FRANCIS. D.H. Stepen Chemical Co. 64/01/23. 3pp.
- --8103260716 Forwards memo re discussion w/Public Health Svc concern Maywood Chemical Works, Requests that licensee be inspected in near future to determine status of compliance w/AEC requaltions & license conditions.

  NUSSBAUMER.D.A. Atomic Energy Commission. 63/07/26, 1p.

- --BLD99A077A Forwards compliance into rept of License R-103 on 570524 Recommends that licensee make survey of facility KIRKMAN R W Aronic Energy Commission 57/06/07 Lc
- --81032A0781 Campliance into rest of License R-103 on 570524 Noncompliance noted large quantities of thorium are stored number and the property of the state of the ENGELKEN.R H. KIRKSON.R W. Atomic Energy Cornission 57/06/06
- --8103250784 Grants Mat1/Biproduct License R-103, authorizing receipt. possession & title of raw source mattern any quantity for processing & resale

  JCHUSON-L. Atomic Energy Commission 56/11/19 2pp
- --BIOJ260790 Approves issuance of meth/byproduct licenses to kerr-McGee OII Industries. Ind. Maywood Chemical Works & Vitro U Co MANN. M. M. Atomic Energy Commission 56/11/13 ip
- --Bi03260793 Forwards excerpt from application for renawal of License R-103 to process & expert source mati VAN ZANOT. D. R. Stepan Chemical Co. 56/11/09 4pp
- -- BID3260798 Requests to be advised if Source Mat1 License R-103 should not be recewed
  JDIM-SSM.L Atomic Energy Commission 36/11/06 lp.
- --8103260803 Forwards application forms for renewal of Source Mati-License R-103 W/o encl JOHNSON L Atomic Energy Commission 56/11/06 1p
- --810326696 Monthly rest for May 1956 re processing of thorium source NICHOLS, E.H. Stepan Chemical Co. 56/10/15 2pp
- --8103260811 Oranta Source Matl License R-103.authorizing receipt, gossession, transfer & delivery of rau source matl in any quantity for processing & resale
  JUP-SON.L Atomic Energy Commission 54/04/01 ip
- --8:03260816 Forwards application for renewal of Source Matl License VAN ZANDT, D.R. Stepan Chemical Co. 54/03/09 1p.
- ---BL03260823 Application for renewal of Source Matl License R-103. authorizing transfer delivery & receipt of thorium source MAN ZAMOT, D. R. Stenan Chemical Co. 54/03/09 4nd
- --8103260826 Radiological survey of Warehouse 5 for Stepan Chemical Co M Roosena 810116 ltr encl. Nuclear Safety Associates 80/12/00 14pp
- 8103250843 Responds to FOIA request for documents transmitted between Off of State Programs & WA State Dept of Bocial & Health Svcs re 1981 annual compatability review No documents are available subj to request. FELTON, J. M. Division of Rules and Records 81/03/23 tp.

08040 199

- 8103260850 FOIA request for doucnents transmitted between Ofc of State Programs & NA State Dept of Social & Health Sycs re 1981 annual compatability review HINGARD. G Affiliation Unknown 81/02/11 Ip. 08040 200
- --8102260856 Declines invitation to participate in NRC 1981 annual compatability review for State of MA Lists reasons for WINGARD Q Affiliation Unknown, 81/02/11 2pp. 08040.201
- --8100260863 Requests that NRC investigate State of WA.Dept of Social Health Svcs. Radiation Control Section Investigation should involve current radiation monitoring program & obligation to inform public of Contamination. Related info encl WINGARD. 3 Publ Public Interest Research Group, Washington 80/10/05.
- 8103260998 Responds to FOIA request for cost-benefit analysis in support of new policy & procedures for enforcement actions No cost-benefit analysis was performed FELTGN.J.M. Division of Rules and Records 81/03/20 ip 08036: 319

on proposed rule 10CFR2 re general statement of policy & on proposes the inforcement actions
multille J Affiliation Unknown. 45FR66784 157 B1/03/01 68036 320

WILL G ALL J4 FULA TROUPS

77/11/01 200

- 0:002610:2 Responds to FOIA request for four specific document by accession number Documents are available in PDR & will be reproduced by Literature Research Co FELTON J M Division of Rules and Records 81/03/24 in 09036 323
- 8103261044 FOIA request for four specific documents listed by accession number CRAUFORD.C. Affiliation Unknown 81/03/16 in. 08036.32
- 8103261060 Responds to FOIA request for Contract NRC-04-77-06: subsequent mods or amends Forwards documents Info will be olaced in POR FELTON, J.M. Division of Rules and Records 81/03/23 2pp
- --Bi03241072 Contract "Conduct Bipdy to Developed Integrated Info Sys (1916)." awarded to Baeing Computer Svc. Inc ARANT.B M. Boeing Computer Services. Inc. (aubs. of Boein HALMAN.E I... Division of Contracts. FIN B-5714 NRC-04-1 77703/15 85pp
- -- 8103241095 Mod I, adding document control sys & export-import 103261095 Mod I.adding document control sys & export-import data sys in intl programs to "Conduct Bludy to Developed Integrated Safeguards Info Bys (1918) "

  Boeing Computer Bervices. Inc (subs of Boeing Co.) MORTON.A V Division of Contracts FIN 8-5714 NRC-04-77/10/12. 2pp.
- --BIO3261102 Mod 2 increasing funds to "Conduct Study to Deve Integrated Safeguards Info Bys (ISIB) " GRANT M Bosing Computer Services, Inc. (subs. of Boels MORTON K V Division of Contracts FIN 8-5714 NRC-04-1
- --B103261109 Mod 3, revising periods of performance & increasing "Conduct Study to Develop Integrated Bafeguards Info Sys GRANT B M Boeing Computer Services, Inc. (subs. of Boein MORTON N V Division of Contracts FIN 8-5714, NRC-04-77/12/14. 2pp
- --G103261115 Mod 4, adding tasks to Btatement of Work-Phase 1, "Develop Gafaguards Info Requirements," to "Conduct Study Develop Integrated Bafaguards Info Sys (ISIS)."

  # Boeing Computer Services, Inc. (subs. of Boeing Co.), MORTON-K V. Division of Contracts. FIN B-5714, NRC-04-78/04/06. 2pp
- --8103261120 Mod 5 intreasing funds to "Conduct Study to Develontegrated Safeguards Info Sys (ISIS)."

  ORANT 8 M Bosing Computer Sarvices, Inc. (subs. of Doei: MORTQN-K V. Division of Contracts. FIN 8-5714 NRG-04-78/04/28 2pp.
- --8193261123 Mod 6.adding tasks to Statement of Work.to "Cond Davelop Integrated Bafeguards Info Sys (ISIB)." Boeing Computer Services, Inc. (subs. of Boeing Co.) MORTON, K. V. Division of Contracts. FIN 8-5714 NRC-04-1
- ---B103261128 Mod 7. increasing funds, to "Conduct Study to Deve Integrated Bafeguards Info Bys (ISIS)." FUGITIM B Bosing Corputer Services, inc. (subs. of Bus MORTON, K. V. Division of Contracts. FIN B-5714. NRC-04-78/06/12 2pp
- --8103261134 Mod 8, extending period of performance until 7810: "Conduct Study to Developed Integrated Safeguards Info Sy CIBIS) -FVOITT, H.D. Boeing Computer Bervices, Inc. (subs. of Boe MORTON, K.V. Division of Contracts: FIN B-5714, NRC-04-178/08/16, 1p
- 8103261065 FOIA request for Contract NRC-04-77-065 & subseque RUTHERFORD, J. F. BDM Corp. BDM/N-JFR-1282- 81/03/09. 1p.
- 8:0327009: Responds to FOIA request for documents re possible of review penels, task forces & committees to study issues raised by Stratton Forwards Documents &-18 listed in app. Documents i=5 are available in PDR. FELTON, J. H. Division of Rules and Records 81/02/11. 2pp. 0B045:119

- MATTEGN. R. J. Division of Sustems Safetu
- --Bi03270103 Summary of B01204 planning meeting to discuss state of to the choice with a control of the 00045 141
- --8103270112 Corments on processed Ofc of Nuclear Regulatory Research program. 'State of Technology Rept on Release of Fiseion Product Indias "Program endorsed sub to referenced ARLOTTO. O A NRC - No Detailed Affiliation Given 80/12/22 2pp 00018 110
- ---8103270119 Submits schedule & designated individuals to work on rept re impact of fission-product iodine & fission-product agreeols on past licensing practice.present regulations & Puture on past literating placetto, present regulations a votors literating application KREDER. W.E. Assistant Director for Radiation Protection 81/01/06 1p. 08049 151
- --8103270128 Summary of 810107 meeting of ad hoc group for development of rept on impact of fission product source terms on licensing Preliminary putline of rept & schedule enci PASEDAG, W.F. Accident Evaluation Branch 81/01/09 Jpp 08035 192
- ---B103270134 Designates R Kasper as Nuclear Bafety Oversight Committee ייטיביי עייטיביי עייטיביים האופיר as nyclear Harety Oversight Commonstact person re iodine issues. EBBIN'S Nuclear Safety Oversight Committee 81/01/02 1p. 08045:157
- --B103270142 Espresses appreciation re nomination of R Kasper to participate as observer w/Research Review Group for peer review of "State of Technology Rept on Iodine " Suitable review mat] uill be provided when available KELBER, C W Assistant Director for Advanced Reactor Safety Research B1/01/07 ip 08045 198
- --RI03270147 Ack receist of 801125 ltr nominating RC Vogel to serve on 1032/0147 Ack receipt or dorling let momentumy he voge. to ser. Research Review Ordup re iddine-ceetum question MINDQUE,R O Défice of Nuclear Regulatory Research. Director 81/01/07 1p. 08045 159
- --Bi03270157 Comments on Nuclear Bafety Oversight Committee Dec 1780 meeting re research program, aerosol release & risk of steam meeting to research program, aerosol release & risk of steam explosion being less than postulated in WASH-1400 MINDOUG, R O Diffice of Nuclear Regulatory Research, Director, 81/01/19 2pp 08045 160
- --BI03270165 Ack receipt of BI0106 ltr re need to investigate state of technological understanding of radioactive fedine release & behavior during potential accidents. Technical rept is being drafted focusing on todine & other available math MINDQUE, R B. Office of Nuclear Regulatory Research, Director 81/01/26. 1p 08049 162
- --B103270170 Requests review & comments re NRC efforts concerning indine release issues b potential regulatory impacts Preliminary lists of refs end AHEARNE, J. Commissioners 81/01/14 3pp 08045:163
- --8103270178 Summarizes schedule for preparation of state of technology rept on fission product iodine in response to NRC 801217 request. Rept objective is to provide Commission w/technical basis for judgments concerning engineered tafety features.
  MINOGUE, R. B. Office of Nuclear Regulatory Research, Director
  80/12/22, 1p. 08045 166

# GEN TEC 18 GENERIC TECHNICAL ISSUES

- B102060467 Requests NRC presence at Mar 1981 meeting of util, GE & Mark II owners group in San Jose, CA to discuss chugging load definition CHAU, H. Mars II Owners Group MK II-077-LIC 81/02/02. 1p.
- Bio3030360 Responds to Bio202 request for NRC attendance at meeting iumududou responds to BIOMUZ request for NRC attendence at mu/Mark II owners group in Ban Jose.CA re Unresolved Safety Issue A-B. Mesting should be held in Dethesda,MD, due to travel budget restrictions.
  DENTON.H.R. Office of Nuclear Reactor Regulation, Director 81/02/11. 1p. 07771:201
- B103110B25 Forwards draft statement of work re cost estimating for proposed safety requirements task description & supporting BAER, R. L. Bafety Program Evaluation Branch 81/02/19 6pp.

8103120199 Notifies of endorsement of proposed research on Environmentally Assisted Cracking in LWR Piping Sus. proposed by BO1218 memo Requests meetings be held to discuss encl comments

DENTION. H. R. Office of Nuclear Reactor Regulation, Director

BIOLOGO 2pp 07403:335

70708711 2ac

- --010120204 Discusses concerns & comments on research program.
  'Environmentally Assisted Cracking in LMR Piping Sys.' per request Recommends work in subj area be initiated & Corrosion Research Review Panel provide review & guidance BENARDYA, V. B1/01/ Chemical Engineering Branch FIN A-2212 2pp 03966 001
- BIO3160727 Notifies that due to time limitations no effort will be diverted to respond to NRC 801027 questions on MCAP-9628 \$ MCAP-9748 re asymmetric LDCA loads Buggests response be re-evaluated re fracture mechanics review ANDERSON. I M Westinghouse Electric Corp 2pp 07918 304 NG-TMA-2089 817027
- 8103180984 Forwards nonproprietary NEDJ-24288. 'Generic Condensati Dicillation Load Definition Rept " Qeneral Electric Co PFN+036-BL 81/03/06 1p BUCHHOLZ.R H 07953.271
- --8103180588 NEDO-24288 103180588 ABDU-24288
  Nonproprietary version of "Generic Condensation Oscillation
  Load Definition Rept "
  WADE O E , IANNI R W . IO-NEEND H E General Electric Co
  BONED299 81/02/28 52pp 07953 272.
- 8103200221 Forwards proprietary version of errata to NEDE-25100-P. "Caorso Bafety Relief Valve Discharge Tests.Phase 1 Test Rept." subnitted on behalf of Mark II owners group Encl 07970.344
- 8103200315 Forwards Errata & Addenda Sheet 1 to NEDD-25109. "Caors Bafety Relief Valve Discharge Tests, Phase I Test Rept. for Mark II containment program. BUCHICLZ.R H General Electric Co MPN-021-81 81/02/18. 1p. 07968.030
- 8103260780 Discusses purpose of AIF Committee on Power Plant Desig Const & Operation.established on Bi0128 & assigned task re-fracture toughness requirements of nuclear component supports per NUREQ-0977. HDMELL.8 H Atomic Industrial Forum 81/03/20. ip 08036 090
- 8103270808 Forwards Suppl 2 to NUREO-0487 & FR notice re Mark II 1 plant pool dynamic LOCA loads evaluation.4/o encls DENTON.H R Office of Nuclear Reactor Regulation, director B1/03/16 ip 08045 107.
- 8103270813 Forwards Suppl 2 to NUREO-0487 & FR notice re Mark II l plant pool dynamic LOCA loads evaluation. W/o encls DENION.H R Office of Nuclear Reactor Regulation, Director 81/03/16 2pp 08045 108
- BIOG270B17 Forwards Buppl 2 to NUREQ-0487 & FR notice re Mark II i plant pool dynamic LDCA loads evaluation.Wo encls DENTON.H.R. Office of Nuclear Reactor Regulation, Director BI/03/16 ip 08045.110
- 8103270819 Forwards Suppl 2 to NUREO-0487 & FR notice re Mark II 1 plant pool dynamic LOCA loads evaluation. W/o encls DENION.H.R. Office of Nuclear Reactor Regulation, Director 81/03/16. 1p 08045 [1].

# INSPECTION AND ENFORCEMENT

- BOOB220271 IE Circular Bi-03. "Insperable Seismic Monitoring Enstrumentation. Director's Office, Office of Inspection and Enforcement. 81/03/02 3pp. 65153.249
- 8008220080 IE Circular 81-01. "Design Problems Involving Indicating Push Button Buttches Mfg by Honeywell, Inc".

   Director's Office, Office of Inspection and Enforcement. 81/01/23. 4pp. 07893:026

- 8008220207 IE Info Notice 81-02. "Transportation of Radiography Devices."

   Director's Diffice, Office of Inspection and Enforcement. 81/01/23 5pp &5025 235
- 8011040265 IE Info Notice Bi-O4. "Cracking in Main Steam Lines "

   Director's Office of Inspection and Enforcement
  Bi/02/27. 2pp. 65153 244
- 8011040269 IE Info Notice 81-06, "Failure of ITE Model K-600 Circuit Breaker" • Director's Office, Office of Inspection and Enforcement 81/03/11 ip 65153 287
- 8011040271 IE Info Notice 81-05. "Degraded DC Sys at Palisades "
   Director's Office. Office of Inspection and Enforcement 81/03/13 2pp. 65153 259
- B011040276 IE Bulletin B1-01. Revision 1. "Burveillance of Mechanical Southers" \* Director's Office. Office of Inspection and Enforcement 81/01/27 6ps
- 8012110179 PNO-1-80-167A investigation into source & extent of radioactive contamination near Route 17 in Rochelle Park.NJ. continues. Maywood Chemical & Stepan Chemical Cos may be source, but has not been definitely established COSTELLO.F. Region 1. Philadelphia. Office of the Director 80/12/01 1p 07223-105
- B1021B0345 PND-III-80-196 IL EPA notified Eileen IL officials that gross alpha activity in public wells erceeds EPA limit Coused by naturally occurring Ra-226 decaying to alpha-smitting daughters PAPERIELLD.C J Region 3. Chicago. Office of the Director 80/10/21 2pp 07704 346
- Bi02270702 PhQ-v-8i-009: on Bi0223, wipe test performed on shipping cask received from DC Cook facility indicated excessive contamination levels Biste of NV has banned util use of burial site, effective Bi0223 Disposition undetermined. THOMAS.R.D. Region 3, San Francisco. Office of the Director Bi/02/24 ip
- BIOJO20131 PNA 80-027A updates & closes out PNA 80-027. State of TX notified Off of State Programs that reported IB3-rom exposure to lab worker found Processor maintains accuracy of initial reading LUBENAU. J D. BCLLINGL A Diffice of State Programs. Director 81/01/30 1p 07/84:347.
- Bi03020152 PNA 80-0218 updates & closes out PNA 80-021 Ofc of State Programs was informed that chromosoms analyses performed by ORNL showed no evidence of significant exposure to pregnant woman. Ten noncompliances identified by state LUBENAULJ D. BOLLINGL A. Office of State Programs, Director. 81/01/30 1p 07784.344.
- 8103020431 PNO-TV-81-004 on 810223.hot reheat temp scram occurredreleasing sinute amount of redioactivity into reactor bidg. Caused by frequency swings on grid sys Btate of CO was notified. MESTERMAN, Y.F. Region 4, Dallas, Office of the Director. 81/02/24.
- B103020496 PNO-III-B1-021 on B10223 received notification that QAD will begin conducting comprehensive amalysis of comparative costs re-upgrading safety at utils to reduce danger to nearby population ctrs. Study will be completed in FYB1.

  MENCZER.W 8 Region 3. Chicago. Office of the Director B1/02/24.

  Zap.
- B10302050) EN-B1-007: on B10303 hotice of proposed imposition of civil penalties to be issued to Ft Hamilton Hughes Memorial Hosp Ctr for alleged failure to rept teletherapy unit malfunction & technician exposure upon entering high radiation area MET/GER-J. R. Enforcement Branch. THOMPSON. D. Director's Office. 81/02/27. 1p. 07785:099.
- B103020591 PNO-III-81-020: on B10224, following lows of air supply, reactor tripped from 98% power. Caused by shutdown of one operating air compressors & stuck open check valve. Air compressors were restored to svc.
  BROWN.C. H. Region 3. Chicago, Office of the Director. B1/02/24
  200.

- 8103020597 PNS-III-81-004 on 810224, two equipment operators were arrested & charged u/possession &/or use of controlled substances Individuals were suspended & access authorization to site was revoked Shift monitoring in progress MORELIUS, C. E. Region 3. Chicago, Office of the Director 81/02/24. In.
- B10303041B PN3-111-80-234 on 801219, unit shut down for schaduled cutage. Tech Bpecs violated when primary containment personnel doors stayed open & when reactor pressure was 90 psip more w/HPC1 & isolation condenser sys but of svc. TONOUE. T Region 3. Chicago. Office of the Director. B0/12/22
- Bi03030445 PNO-III-80-224 on B01205, ill authorized resumption of limited electrical & mechanical/piping work for subcontractors. Cherne Contracting Corp & Commonwealth Lord J.V. based on favorable insp findings. FIDRELLI.0 Region 3, Chicago, Office of the Director. B0/12/05
- 81/03030803 PNS-1-81-005:on 810225.Con Ed customer ave representative received borb threat by telephone. Corporate oft & facilities notified Bomb searches initiated w/nsgative results. No further action anticipated MCKEONN.L. Region 1. Philadelphia, Office of the Director. 81/02/26. 1p
- B103030B42 PNO-[-B1-005 on B10225; customer svc representative received bomb threat by telephone Util corporate ofc notified & bomb search initiated Results negative. MCKEONN.L. M Region I. Philadelphia. Office of the Director B1/02/26 2pp
- 8103030854 PND-II-81-018 on 810224 notification received be indefinite const delay on facilities. Work on Unit 1 will be reduced & const on Unit 2 will be stopped. Caused by financial problems
  PEEBLES, T. Region 2. Atlanta. Office of the Director. 81/02/25.
- SIO3030911 PNO-1-81-028 on SiO225 physical location of ATMS alternate rod insertion splendids in stram discharge air header found to allow insertion of control rods µ/o stram discharge volvent & drain valves closing LOCA may result. JOHNSON J. Region 1. Philadelphia, Office of the Director. SI/O2/22. 200.
- B103030942 PND-III-B0-229 on B01211, unit manually tripped following hi-hi alarm from scram discharge vol continuous monitoring sys. Caused by water leaking into BDV during maint on control rod drive hydraulic control unit IB-ii Drawing encl.
  REIMANN.F Region 3. Chicago, Office of the Director. B0/12/11.
- B103030987 PNO-111-80-238: on B01229; gaseous release of 0.1 Ci occurred when makeup tank vented through instrument line. Venting occurred during improperly authorized maint work. Bldg ventilation secured & bldg evacuated.

  CREDER. L. R. Region 3. Chicago, Office of the Director. B0/12/30.
- 8103030997 PNG-ltt-80-235: on B01227, unit shutdown initiated resulting in outage of greater than two days Caused by maint on main condensar tube leaks. Repairs to be completed & unit returned to avo by 801231.

  REIMANN.F. W. Region 3. Chicago. Office of the Director. B0/12/29.
- Bio3031009 PNG-III-80-231: on 801207.3 Ci technetium generator reported missing Generator properly pactaged & labeled. As of 801215, generator would contain 240 mCi activity, No heared exists unless generator diseasembled.

  OBERG.C.T., SCHULTZ.W.H., DAVIB.A.B. Region 3, Chicago, Office of the Director. 80/12/16. 2pp. 07791:208.
- 8103031014 PNO-III-80-208: on 801106; main generator output breakers tripped: resulting in plant shutdown over two days. Cause not determined. Unit will be maintained in hot standby until 801110, pending determination of cause. KOHLER. J. HEISHMAN. R. F. Region J. Chirago. Office of the Director. 80/II/07. 1p.
- 8103031073 PNO-111-80-208A on 801107. Unit 2 commenced cooldown to cold shutdown resulting in plant shutdown over two days. Caused by maint on pressurizer spray lines due to 801106 trip. Outage to last at least three days.

  KOHLER. J. HEISHMAN.R. F. Region 3. Chicago, Office of the Director. 80/11/07. 1p.

- 8103040015 PNO-III-81-011 water found in 12 containment electrical penetrations in east penetration room Source of water undetermined HEISHMAN.R.F Region 3. Chicago, Office of the Director. 81/01/20
- 8103040029 PNO-III-81-010. on 810116. stop work order re installation of core support assembly vent valves issued to B&H after discrepancies noted included failure to maintain adequate inventory control & to identify valve parts.

  KNOP.R. Region 3. Chicago. Office of the Director. 81/01/19. 2pp.
- 8103040042 PNO-11I-81-009. on 910117, several gaseous releases occurred. Caused by slight pressurization during periodic latidum while manually activated degasifier pumps not operating. HUETER. L. Region 3. Chicago. Office of the Director, 81/01/19 2nn
- BIO3040054 PND-III-80-187: on BOI011, reactor scrammed. Caused by control valve fluctuations resulting in greater than 100 lb differential pressure between main steam lines. Bafety injection initiated.
  BHANBON, E. Region 3. Chicago, Office of the Director BO/10/14 200.
- B103040066 PND-III-80-181: on 801004, unit tripped from 85% power. Caused by high water level trip due to 18 main feedwater pump malfunction Bus 18 would not switch over to offsite power supply automatically. Reactor restarted.

  FORNEY, H. L. Region 3, Chicago, Office of the Director 80/10/06.
- 0103040128 PNU-III-80-210, on 801110, leaking relief valve was cycled in attempt to reseat & resultant blowdown caused reactor scram. During recovery, discovered that A MSIVe did not close, Caused by improperly connected wire in circuit.

  SMITH-J. Region 3. Chicago, Office of the Director. 80/11/12 lp.
- 8103040147 PND-III-80-213: on 801112 ABME survey team completed implementation survey. Intends to recommend N-Btamp be issued to util.
  HILLIANS.C.C. Region 3. Chicago. Office of the Director. 80/11/12.
- B103040445 PNO-III-B0-237: on B01225 unplenned gaseous release occurred during transfer of waste gas to holdup tank. Caused by leaking valve. Investigation continuing. LOVENDALE.P. Region 3. Chicago. Office of the Director. B0/12/29. 1p.
- 8103040474 PND-III-80-180: on 801005, small oil fires occurred. Caused by maint on MBIVs. Valves operated w/throttle valve protective caps removed, allowing oil to leak past packing & spray onto hot steam line. Fires extinguished. Maint completed. CHR ISBOTIMOS. N. HE ISHMAN.R. F. Region 3, Chicago, Office of the Director. 80/10/06. 2pp.
- BiO3040691 PNO-TMI-Bi-006: on BiO227, contaminated rodent feces found in control to see bldg. Affected areas roped bff. Exterminator contacted to capture pests. Contaminated rodents do not pose radialogical risk to public or environ.

  BHANBAKY, M. TMI Program Office. 81/02/27. 2pp.
- 8100050624 PNO-I-81-029: on 810227; security guards went on strike, because of inability to negotiate acceptable contract w/ employer. Licensee has implemented strike contingency plans. State of ME has been notified.

  LADUN,R.H. Region 1. Philadelphia, Office of the Director. 81/02/27. 2pp.
- BiC3050669 PNO-1-Bi-026:on BiO219, 2-inch RCS valve inside containment found leaking, Cause not stated, Plant was shut down to repair leak; Valve isolated & packing leakage reduced. Repair will be attempted after partial cooldown.

  BECKHAND. Region 1, Philadelphia, Office of the Director.

  81/02/20. 2pp.
- B103100385 PNS-IV-81-003: on 810302-03, security guard for 84H received telephonic bomb threats from male callers. Area roped off & searched No bomb found. Local investigation continues.

  MELLY, J. A. Region 4. Dalles, Office of the Director. 81/03/03.
  28s.
- 8103100408 PNO-II-81-20: on 810304, during surveillance functional testing of accessible hydraulic snubbers failure rate of 20% occurred. Functional testing of 107 snubbers revealed 20 which failed to meet criteria.

  JULIAN.C. Region 2, Atlanta. Office of the Director. 81/03/05. Ip.

- BiO3100509 PNO-I-Bi-030 on BiO301 unit tripped from 100% power Coby steam generator low level after feed pump 11 trip because of low suction pressure due to heater drain pump vibration Shutdown extended for repairs & test per IE Bulletin Bi-OI NORRHOLMIL Region 1. Philadelphia. Office of the Director IEB-Bi-Ol Bi/O3/O3 2pp.
- 8103120382 EN-81-005A: on 810306. IE issued order to rescind licens suspension, terminate show cause proceeding & temporarily modify license w/order requiring util to implement specific procedures & submit license amend application. Refs EN-81-05. METCOSR. J. THOMPSON. D. Office of International Programs. Dire 81/03/04 1p. 07904-359
- B103120419 EN-B1-00B notice of violation & notice of proposed imposition of civit penalties will be issued to licensees. Action based on alleged noncompliance re transportation of radioactive matls & radiation protection program TETZOBR, J. THOMPSOND Director's Office. Office of Inspectio Enforcement. 81/03/09. 1p. 07901 219.
- 8103120623 EN-80-053A. on 810309, order to modify license issued to incorporate as requirements, licenses 810127 statements & to terminate 801208 show cause order Hearing may be requested within 23 days of order date.

  BROCKETT, T, THOMPSON.D. Director's Office, Office of Inspectiven of Enforcement. 81/03/09. Ip.
- 8103120630 PNO-II-81-022 on Bi0307, fire occurred in nonsefety-rel digital computer sys in communications room of control bidg Cause not stated. Fire extinguished & investigation is in progress.

  MILLER, M. H. Region 2. Atlanta. Office of the Director. 81/03/110
- 8103130415 PNO-I-81-033 on 810305, clothing worn by two Consolidat X-rey Sycs employees found to be conteninated w/Co-60 from contact w/Dec 1980 leakags of Co-60 source at Garma Industries of Baton Rouge, LA Clothing confiscated, KINNEMAN. J. KISTER: Il Region 1. Philadelphia. Office of the Director 81/03/06. 2pp 07907.054
- 8103170373 PNO-IV-81-007 on 810310, three contract maint workers for working in high radiation area w/o health physics technician supervision or knowledge of eristing radiation hazards. Caused by lar administrative controls for area door keys HUNNICUTT, D.M. BAIRD, J.B. Region 4, Dallas, Office of the Direction of the Direction
- 8103190503 PNG-III-81-029: on B10309 & 10 reactor scrammed First comby loss of voltage on distribution train B due to misaligned electrical distribution breakers. Becond caused when operator failed to correct increasing water level.
  FORNEY.W. Region 3. Chicago. Office of the Director. 81/03/10.
- 8103230650 PNO-IV-81-008 on 810317 radiographic camera containing C1 Ir-192 fell into Gulf of Mexico 14 miles offshore from State of LA Divers searching DODAR. BROWN G.D. Region 4. Dallas. Office of the Director. 81/03/18.
- B103240376 PND-I-B1-036 on B10317.prior to start of day shift.nem of security organization called in sick. Cause of "sick out" unknown but licensee understands work force displeased w/ change to rotating shift assignments.

  DEVLIN.J.W. ALLAN.J.M. Region 1. Philadelphia. Office of the Director. B1/03/17. 2pp.
- 8103300296 EN-81-01A: on 810326, licensee was issued order imposing civil penalties. Action based on alleged violations including failures to calibr radiation survey instruments & to barricade & gost work sites.
  METZOTER, J. R., THOMPSON, D. Director's Office, Office of Inspecand Enforcement. 81/03/26. 1p. 08095:120.
- 8103300352 PNS-III-81-05:on 810323. Midland County Sheriff Dept rate is imported to bomb threat from male caller. Bomb threat procedure & search of facility initiated. No fuel on site Licensee made press release. State of MI will be notified. CREED, J. R. Region 3. Chicago. Office of the Director. 81/03/2
- 8103300393 PNA-81-003: on 810322, newspaper rept published re radius contamination at Aircraft Instrument & Development in Michitar KB. Caused by paint stripping on surplus military aircraft instruments. Mhole body counts in progress.

  MUSSBAUMER, D. A. Assistant Director for Material Bafety & Licen LUBENAU. J. D. Diffice of State Programs. Director. 81/03/25. 1.08085.309.

- 81033197CB PNO-1-81-037 on B10321.69-yr-old woman received 8 mCi I+131 therapy when mistaken for another patient. Caused by distaken identity. Attenting physician notified Madia interest not expected COSTECLO.F., KINNEMAN.J., JOYNER.J. Region 1, Philadelphia, Office of the Director 81/03/25 ip 08075 099
- B103310717 PND-11[-B1-034, on B10321.recirculation loop discharge valve B failed to close Valve inoperability from LOCA loop selection logic circuisty to be tested during outage Contactor at breaker manually closed-closing valve CHRISTIANEGU.F. FIGRELLI.O. Region 3. Chicago, Office of the Director. B1/03/23 lp

#### MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- B103040394 Notifies that NRC may be contacted by preservational organizations participating in annual review of natilandmarks.

  HARTHIG.P. 8 [Interior. Dept of 81/02/27 1p 07820 041
- 8103050541 Requests clarification re-ranufacturer QA program requirements
  SULHAM.B. Jos Queen & Sans. Inc. 81702723 2na 07825 205
- B103050647 Requests clarification of ASME Code requirements re OA program upgrading stock matts. MAZZARELLA.A. BULLYAN.B. Joe Dyson & Sons.inc 81/02/19 27; 07825 061
- 8103060078 Describes methods used in program re systematic assessment of licensee performance Rating assigned will represent collective judgment of four NRC line managers. Program charter and 5 STELLO, V Office of International Programs. Director 81/02/09 dop 0/9318 356
- B103060657 Forwards results of five high-burnup fission gas release calculations based on Riso Natl Lab data GAPCON-2 continues to arbitit intrinsic thermal conservations

  VOCLEMEDE. J C Core Performance Branch 81/02/20 20pp
- 8103090657 Informs of stan re impact of delaying application requiring documentation of deviations from revised 820(01-040) SRP List of plants w/SER issuance in 1982 encl
  TEDESCO.R L. Assistant Director for Licensing 81/01/16 Jpp
- 9103100130 Responds to 810123 ltr requesting info on progress & conclusions of NRC investigation of proposed 8HS Plaza site in Rochelle Park,NJ Contaminated soil will need to be removed before site development.

  KINYEMAN. J D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 81702709 1p. 07866.001
- -8103100135 Requests info on progress & conclusions of NRC investigation of proposed SMS Plaza sites in Rochelle Park.NJ MURNJ 0 Bergen County.NJ. BI/01/23 Ip 07866 002.
- 8103100515 Forwards memo distributed at Pools meeting w/Cormission on NRC noise re-approval of NELIA galicies. Inclusion of full test of polities in NRC regulations would help ensure state approval in format satisfactory to Commission.

  MARRONE, J. American Nuclear Insurers. 81/03/04. 5pp. 07867-208.
- B103100754 Responds to Rochelle Park.NJ 801222 request re restriction necessary for Blocks ID. 19 & 20 due to thorium contemination Further sampling is necessary to ascertain extent of contemination BHITM.0 H Region I. Philadelphia. Office of the Director 81/02/09 ip. 07865 314.
- --B103100761 Requests info re restrictions or regulations applicable to Blocks 18.19 & 20 of Rockelle Park NJ. DAHL INDER: F B Affiliation Unknown 80/12/22. pp. 07865-315.
- B10315005B IE Change Notice B1-04 revising Menual Chapter 2512/07.

   Director's Office. Dffice of Inspection and Enforcement B1/02/25. 100ps 07917-201.
- B103160233 Ack receipt of B10206 ltr expressing concern for safety of nuclear power. Forwards "Reactor Licensing Process " W/o ancl BERKOW.H N Management Analysis Brench. 81/03/06 1p 07921.245.
- --8103160239 Expresses concert for safety of nuclear power plants MAGIE-L Affiliation Uninoun. 81/02/06. 1p. 07921:246

- 8103166272 Pesponis to 810207 request for info re nuclear safety NR policy includes maint of radiation levels as low as reasonably achievable under normal conditions 25CH-0.0 Technical Support Brench 81/03/04 3ep 07917-190
- --B103160276 Requests info re nuclear safety S1RGUD.8 Affiliation Unknown 81/02/07 ip 07595-001
- 8007240519 Discusses NRC authority to order cleanup of offsite tail contamination SHAPAR.H K Office of the Executive Legal Director B0/03/31 03023 234
- 8103170431 Requests support for stronger regulations re radweste shipment Notification should include specific times & routes all low level wastes & should not restrict governor from freely disseminating transportation info.

  RIMER.A Affiliation Unknown 81/02/24. Ip 07923.206
- 8103170489 Forwards summons & complaint filed by J & O Specchio aga Atlantic Richfield Co.et al.in NJ Buperion Court If liability exceeds insurance coverage.Price-Anderson Act provisions applicable ULLEON.JF Atlantic-Richfield Co L-27340-80 81/03/12 2pp 02933 201
- --Bi0317049: Responds to 701102 request re-applicability of Price-Anderson Act to Ilability resulting from Olesson suit exceeding insurance coverage Eccess liability would be covered by Price-Anderson Indemnity provisions.

  SCHUR. 8 H Atomic Energy Commission L-42307-67 70/11/25 07933 203
- --Bi03170499 Complaint requesting compensatory & punitive damages be upon 63010B exposure allegedly due to negligence of AEC.
  Nuclear Matis & Equipment Corp. Nuclear Decontamination Corp.
  Atlantic Richfield Co. et al.
  HORDWITZ-A A Affiliation Unknown. HORDWITZ-A A Affiliation
  Uninoun L-42307-67 63/01/08. 32pp 07933-204
- --8103170503 Corplaint requesting componentory & puntive damages ba on 630108 exposure.allegedly due to negligence of Nuclear Matls & Equipment Corp. Nuclear Decontamination Corp. Atlantic Richfield Co., et al SPECCHIO. J. SPECCHIO. O Affiliation Unknown JOEL.K E Josl. N. E L-27340-80 81/01/15. 12pp. 07903 236.
- B103180703 Agrees w/util "take action" itr & Vol 2 Energy Update article. Jan 1981. Concludes R Nader harm outweighs good. DURANT/E W Affiliation Unknown. 81/02/02: 1p. 07954-100.
- ai03230029 Notification of B10317 meeting w/Muenow & Associates.Inc Bethesda:MD to discuss methods for nondestructive testing of concrete in investigation of quality of workmanship; including pulse scho technique & acoustic emission. B103/12 Dpv 07978 023
- 8103250130 Notification of 810402 meeting w/Util Oroup for Regulato Application in Bethesde. MD to discuss generic review of licensing topical rept. "RETRAN." generic reactor systransient analysis.

  BEROGREN. J B Standardization & Special Projects Branch 81/03/2pp 07997-325.
- B103250233 Supports nuclear power. HENRY, J W. Affiliation Unknown B1/02/17, ip. 07997:276.
- 8103250466 Responds to 810219 \$ 23 ltrs re-metl acceptability for large fasteners per ASME code & substitution of 10CFR30, App B & ANRI N49.2 for NCA-3800 for nuclear applications Code questions should be addressed to ASME. HAA85-W P Quelity Assurance Branch. 81/03/19. 2pp. 07997-359
- B103260351 Bubnits Progress Rept 37.Feb 1981. PLATO.P Mithigen, Univ. of. NRC-01-77-180 B1/03/06 App. 08040:141.
- 8103260601 Comments that drastic positive changes will be needed in to push for strong nuclear program FIRM. D. O. Affiliation Unknown. 81/02/18. Lp.
- 8103310571 Annual rept 1980, MODFTER R. D. Community Public Service Co. 81/03/27. 26pp

# Office of Inspection & Enforcement, Office of the Director 80/09/30 10pp 07170:017

Bi02260479 Partial response to FOIA request for all documents re five categories of info concerning U mills in UT.NN.A2.CO & MY Forwards Documents 1-17 listed in app Document 18 may be obtained from NTIS FELTON.J M. Division of Rules and Records. Bi/02/09 2op

- --8102260711 Forwards proposed FR notice to availability of NuREO/CR-06:35 Rept contains info to epidemiological investigation of possible relationship between access cancer incidence in Mesa County, CO & radiation exposure from mill tailings WHITFIELD.S.C. Radiological Health Standards Branch 79/08/10
- --7910090482 Forwards NUREO/CR-0635. "Excess Cancer Incidence in Mesa County " Results indicated two-fold increase in leukemia incidence for all ages in Mesa County MINDOUG.R.D. Office of Standards Development, Director. 79/08/27 2pp 99031 087
- --BI02260743 Requests NUREO/CR-0635, "Excess Cancer Incidence in Mesa County, CO," for engineering library Univ of HN request encl FRAZERJ Princeton Univ. 79/10/04 2go
- --Bi02260747 Requests NUREO/CR-0635, "Excess Cancer Incidence in Mesa County, CD." HAUZ, M. Oeneral Electric Co. 79/09/24 lp
- --Bij2260793 Requests NUREQ/CR-0639. "Ercess Camter Incidence in Mesa County, CD " LENISM I Affiliation Uninown. 79/09/24 10
- --Bi02260756 Requests NUREO/CR-0635, "Excess Cancer Incidence in Mesa County.CD " HATHENS.D.M. Arkenses, Univ. of 79/09/17 Ip
- B103020624 NUREO/CR-1546 VOI
  MANAGEMENT OF RADIOACTIVE WASTE GASES FROM THE NUCLEAR FUEL
  CYCLE: COMPARISON OF ALTERNATIVES.
  EVANS.A G . PROUT, W E . BUCKNER, J T E I. du Pont de Nemours & Co .
  Inc. FIN 8-4127. DPST-NUREO-80-5 81/02/28. 90pp. Available at
  NTIS 0.7781 089
- 8103020674 NUREO/CR-1781
  ASSESSMENT OF METHODS FOR EVALUATING ADEQUACY OF PHYSICAL
  PROTECTION SYSTEMS
  CHAPMAN-L.D. Sandia Laboratories. FIN A-1060
  81/02/28. 19pp Available at NYIS. 07781-235.
- 8103020700 NUREQ-0040 V04 N04
  "LICENBEE CONTRACTOR & VENDOR INSPECTION STATUS REPORT."
  QUARTERLY REPORT VOLUME 4. NUMBER 4.

   Director's Defice. Office of Inspection and Enforcement.
  80/12/31. 93pp. 07779:103
- 8103020707 NUREG/CR-0781 901
  THE BAYBHINE-11 PROCEDURE CALCULATION OF THE EFFECTS OF
  STRUCTURE DESIGN ON NEUTRON. PRIMARY GAMMA-RAY AND SECONDARY
  OAMMA-RAY DOSE RATES IN AIR.
  LAMPLEY.C.M. Radiation Research Associates. FIN 8-1197. RRA-18008
  81/01/31. 85pp. Available at NTIS. 64.00. 07780:191.
- 8103020723 NUREO/CR-1896
  REVIEW OF SYSTEMS INTERACTION METHODOLOGIES.
  CYBULBKIS.P., DENNINO,R.S., GALLUCCI.R. Battelle Memorial Institute.
  Calumbus Laborator(es. FIN 8-2335. BM1-2073. Bi/Ol/31 175pp.
  Available at NIT8 85.90. 07780: 276.
- D103020775 NUREO/CR-1670
  WRAITH-A COMPUTER CODE FOR CALCULATING INTERNAL & EXTERNAL DOSES RESULTING FROM AN ATMOSPHERIC RELEASE OF RADIOACTIVE MATERIAL.
  SCHERPELZ, R. I., BORBT, F. J., HOENES, O. R. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2268. PNL-3382. 80/12/31. 142pp. Available at NIIS 65.50. 07780:048
- 8103020782 NUREC/CR-1380 V02
  ASSESSMENT OF CURRENT ONBITE INSPECTION TECHNIQUES FOR
  LIGHT-MATER REACTOR FUEL SYSTEMS Discussion Of Inspection
  Techniques.
  BAILEY,N J., MORIS,C.J., REICH,F.R. Bettelle Menorial Institute,
  Pacific Northwest Laboratory, FIN 8-2181, PNL-3325 B1/01/31.
  222pp. Available at NTIB. \$6.00. 07779-190.

(FIS \$2 25 07791 2

- B10303030B NUREC/CR-1482
  ELECTRICAL INSULATORS IN A REACTOR ACCIDENT ENVIRONMENT
  BTUETZER: O M Sandia Laboratories. FIN A-1051-0. SAND80-19
  B1/01/31 70pp Available at NTIB. 07791:001
- 8103030336 NUREO/CR-1872
  REACTOR CALCULATION "BENCHMARK" PCA BLIND TEST RESULTS
  STALLMAN.F W., KAN.F.B., EASTHAM, J.F., Oak Ridge National Lab
  FIR B-0415 ORM./NUREG/TM-4 81/01/31 95pp. Available a
  07/87-330
- 8103030353 NUREC/CR-1345 VO2 NUCLEAR POLER PLANT DEBION CONCEPTS FOR BABDIAGE CONTROL ERICSON-D.M. VARNACO.0 D. Sandia Laboratories. FIN A-1210 SAND80-047772. 81/01/31. 575pp. Available at NTIS. 07804 (
- 8103030820 NUREO-0540 VO2 NII
  TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE November
  1-30.1980.

   Division of Technical Information & Document Control 81/0
  410pp. Available at NIIS 97585.001
- 8103030530 NUREO/CR-1868 EXPERIMENT DATA REPORT FOR LOFT NUCLEAR SMALL BREAK EXPERIMENT L3-6 AND SEVERE CORE TRANSIENT EXPERIMENT L8-1 DAYLESS.P D. CARPENTER.J H. EQ&O Idaho, Inc. FIN A-6048 E0G-2075 BI/01/31 259pp. Available at NTIS. 07801.027
- 8103030580 NUREO-0790 VI2 NO3 INDEXES TO HUCLEAR REGULATORY COMMISSION ISSUANCES. July-September 1980 • Congressioners 80/09/30 33no Available at NTIS 0758
- 8103030593 NUREG-0330 VO4 NO2 STATUS SUMMARY REPORT. ADVANCED REACTOR SAFETY RESEARCH Data As Of March 31.1980. (Buff book) • Division of Reactor Safety Research 80/05/06 74pp.
- 8103030599 NUREQ/CP-0016
  PROCEEDINGS OF THE U.S. NUCLEAR REQULATORY COMMISSION
  MEETING DN REACTOR VESSEL LIQUID LEVEL MEASUREMENT
  KONDIC.N N. Division of Reactor Safety Research. 81/01/31.
  Available at NTIS #5 50 07803-268.
- 8103030610 NUREG/CR-1780

  SOIL-STRUCTURE INTERACTION THE STATUS OF CURRENT ANALYSIS
  METHODS AND RESEARCH.

  JUNSON, J. Lawrence Livermore Laboratory FIN A-0130

  UCRL-53011 81/01/31. 750pp. Available at NTIS \$13.00

  02804.002
- 8103030664 NUREO/CR-1701
  BPECIFICATIONS OF COMPUTATIONAL APPROACH
  COLLINGLUD. HUBBONULH, CHROSTOHEMILU Lawrence Livermore
  Laboretory Fin A-0126 UCRL-13986. Bi/01/31 165pp. Avai
  at NTIB. \$7.75. 07796: 228.
- 8103030821 NUREG/CR-1240 VO2
  LMR PREGBURE VESSEL IRRADIATION SURVEILLANCE DOSIMETRY.
  GUATACTI PROGRAMS APPOPT. APT11-June 1979.
  CUTHRIE-0 L MCELROY, M. N. Hanford Engineering Development
  Laboratory. FIN 8-9988-7. HEDL-TME 80-1. 81/01/31 9App.
  Available at NTIS. \$4.00. 07789:204.
- B103040100 NUREO/CR-1610 V01N02 INSPECTION METHODS FOR PHYSICAL PROTECTION PROJECT. Quarterly Report June-August 1980. B0WDEN.D, D. + BRADLEY.R.T. + MIMICHING.C. Lawrence Livermore Laboratory. FIN A-0143 UCID-18123-80-2 B1/02/28. 16pp Available at NTIS. #1.75. 07819:303.
- 8103040491 NUREO/CR-1837

  QUARTERLY PROGRESS REFORT ON BLOWDOWN HEAT TRANSFER
  SEPERATE-EFFECTS PROGRAM FOR JULY-SEPTEMBER 1990.

  WHITE.J.D., CRADDICK.W.O., FELDE.D.K. Dak Ridge National Labor FIN 8-0125. GRNL/NURE9/TM-4 81/02/28 13pp. Available at 07615 090.
- 8103040511 NURE9/CR-1782
  LOAD COMBINATION PROFRAM, PROJECT II LOAD COMBINATION METHODOLOGY DEVELOPMENT. Interim Report II.
  SCHUARTZ.M. U. RAVINDRA.M. N. COLLINB, J. D. Lawrence Livermor Laboratory. FIN A-0632. UCRL-53009. 81/01/31. 116pp. Ava at NIB 450. 07810:183

8103049538 NUREO/CR-1078
AN INTEGRATED GEOPHYSICAL AND GEDLOGICAL STUDY OF THE
TECTORIC FRAMEWORK OF THE 38TH PARALLEL LINEAMENT IN THE
VICINITY OF ITS INTERSECTION WITH THE EXTENSION OF THE NEW
MARRID FAULT ZONE
SMAILELL H Battelle Manorial Institute. Columbus Leboratories.
HENZE-W J. SEXTON-J L PURGUE UNIV FIN 8-3971 81/01/31 (46pp
Available at NTIS. 34 73 07811 015

B103040548 NUREO/CR-1702 SPECIFICIATION OF COMPUTATIONAL APPROACH. UALL.I B., KAUL.H.K.. POST.R.I Laurence Livermore Laboratory FIN A-0126 UCRL-13985 81/01/31 166pp Available at NTIB \$5 50

8103040579 NUREO/CR-1800 MAIER REACTOR SAFETY RESEARCH DIVISION. Guarterly Progress Report July 1-8ptember 30.1980. RDMAND.A J Brookhaven National Laboratory FIN A-3045 RNL-NuReO-51298 80/11/30 66pp.

BIO3040999 NUREC-0757
RADON RELEASES FROM UNANTUM MINING AND MILLING AND THEIR
CALCULATED HEALTH EFFECTS

Division of Fuel Cycle & Material Befety 81/02/28 109pp
Available at NTIS 94, 25 07819, 327

B103040607 NUREG/CR-1798
ACCEPTANCE AND VERIFICATION FOR EARLY MARNING FIRE
DETECTION SYSTEMS.
BIOCCIO, J. L., ASP. I. HALL.R. E. Brookheven National Leboratory. FIR
A-3335. BNL-NUREG-51296. B1/03/31. 107pp. Available at NTIS.
07018-2029.

B103040623 NUREQ/CR-1930
INDEX OF RISK EXPOSURE AND RISK ACCEPTANCE CRITERIA
MILLER, B., MALL,R.E. Brootheven National Leboratory
BNL-NUREO-51939 01/02/28 103pp. Available at NTIB 64.25
07819, 139

8103040978 NUREO-0758

REPORT OF THE LOFT SPECIAL REVIEW GROUP.
ROSS.D F LOFT Special Review Group.
81/02/28 100pp Available
at NTIS 44 50 07812:038

8103030901 Forwards "Mestinghouse Prediction for LOFT Nuclear Experiment U3-5." per NUREO-0707. Constitutes evaluation model prediction w/MFLASH computer program using supplied set of initial & boundary assumptions JUROENGEN.R W. Hestinghouse Operating Plants Dunere Group 00-49. 81/03/03 pp. 07826-108

103050571 NUREO-0485 VO3 NO2 5Y8TEMATIC EVALUATION PROGRAM STATUS BUMMARY REPORT, \* Office of Management and Program Analysis. Bi/Q2/28. 35pp. Available at NTIB. 43, 75. 07828: 247

8103060758 NUREQ-0566 VOI NOI STANDARDS DEVELOPMENT STATUS SUMMARY REPORT Status as of January 31.1981. (Green Book)
• Internal Information Systems Stanch 81/02/28. 300pp Available at NTES 07838-048

BIO3090584 NUREQ-0090 VO3 NO3 REPORT TO COMPRESS ON ABNORMAL OCCURRENCES July-Beptember 1980 • Office of Management and Program Analysis B1/02/28. 34pp. Available at NTIS. 07847.175.

B103090807 NUREO/CR-1916 A RISK COMPARISON. COPPOLA.A., HALL.R.E Brookhaven National Laboratory. FIN A-3222. BNL-NUREO-51338 81/02/28 91pp. Available at NTIS. 44.00 07851:048.

8103090810 NUREO/CR-1928
DEVELOPMENT OF LICENSEE EVENT REPORT SEQUENCE CODING AND
SEARCH PROCEDURE.
OALLAHER.R.B Dak Ridge National Laboratory. FIN 8-1583.
ORNL/NUREO/KBIC. 81/02/28. 53pp. Available at NTIS. \$3.75.
07831

8103090812 NURED/CR-1936 THE MEASUREMENT OF THO-DIMENSIONAL PHASE SEPARATION PHENOMENA BARASHIM , LAMEY, R T Rensseleer Polytechnic Inst. FIN 8-3873. 81/02/248 265pp Available at NTIS, 86.30. 07851:139. 8103100006 NUREQ-0020 VO9 NO1
DEFRATING UNITS BIATUS REPORT, LICENSED OPERATING REACTORB
Status Report, Data As 0P December 31.1980 (Grey Book)

Licenses Operators Evaluation Branch 81/02/28. 85pp. Available
at NITB

8103100060 NUREG/CR-1400 VO4
QUARTERLY TECHNICAL PRODREGS REPORT ON WATER REACTOR SAFETY
PROGRAMS SPONSORED BY THE NUCLEAR REGULATORY COMMISSION'S
DIVISION OF REACTOR SAFETY RESEARCH October-December 1980.
DEARIEN J A E080 Idaho. Inc FIN A-6038. E00-2079. 81/02/28
37pp Aveilable at NTIS 07864 118.

BIO3100072 NUREO/CR-1720 BUMMARY REPORT OF PREBSURE SENSOR FOR THE LOSS-OF-FLUID-TEST & (LOFT) REACTOR BILLETER: T R Hanfard Engineering Development Laboratory. FIN D-6228. HEDL-THE 80-53 BI/02/28 67pp Available at NTIS 53 75 07863-236.

8103100076 NUREO/CR-1751
ARMA MODELB FOR EARTHQUAKE GROUND HOTIONS.
CHANG/H K , KHIATKOPSKI.J , NAU.R F Laurence Livermore Laboratory.
FIN A-0139. UCRL-15084. 81/02/28 99pp. Available at NTIB.
44 00. 07864.021.

B1031000B7 NUREO/CR-1913 HDR REBPONSE-EXPERIMENTAL AND ANALYFICAL. FINICLE D P. QUENZLER.R.C. RAHL.R O. E080 Idaho, Inc. FIN A-6306. E00-EA-5261 B1/02/28. 143pp. Available at NTIB 65 00 02058-2286

8103100116 NUREO/CR-1816
DETERMINATION OF TORNADO HIND BREEDS FROM TORNADIC SOUNDS.
ARNOLD.R T., 8888.H E Mississippi Univ. of. FIN 8-6278 UN
0220384028. 81/02/28 44pp. Available at NTIS. \$3.25. 07863:341

B103100125 NUREO/CR-1754
TECHNOLOOY, BAFETY AND COSTS OF DECCHNISSIONING REFERENCE
NON-FUEL-CYCLE NUCLEAR FACILITIES
HURPHY-E.B. Battsile Henorial Institute, Pacific Northwest
Laboratory, FIN B-2026, 81/02/28 415pp. Available at NTIB.
95 50. 07855-194

B103100136 NUREO/CR-1134 VO2NO1
BHR BLGMDGHN/EMERGENCY CORE COOLING SEVENTEENTH QUARTERLY
PROGRESS REPORT, January 1-March 31, 1980.
LEE.L. B. General Electric Co. NRC-04-76-215. GEAP-21304-17.
B1/02/28. 39pp. Available at NTIS 62.50.

8103100179 NUREO/CR-1949 V01
NUCLEAR POWER PLANT DESIGN CONCEPTS FOR BABDTAGE PROTECTION.
ERICBON.D. M., VARNADD.G.B. Sandia Laboratorias. FIN A-1210.
SANDBO-047771. 81/02/28 169pp. Available at NTIB. 07866:328.

8103100410 NURE9-0696
FUNCTIONAL CRITERIA FOR EMERGENCY RESPONSE FACILITIES.

\* Division of Emergency Preparadness. 81/02/28. 38pp. Available at NTIS. 08158-270.

B103100640 Forwards NUREO-0090, Vol 3, Number 3. "Rept to Congress on ADs. Jul-Bept 1980." One AO at licensed nuclear power plant involving failure of saltwater cooling sys. Three AOs reported by Agreement States.

AHEARNE, J. F. Commissioners 81/02/20. 1p. 07865; 308.

--Bi03100455 Forwards NUREO-0090, Vol 3 Number 3, "Rept to Congress on ADs. Jul-Bept 1980." One AD at licensed nuclear power plant involving failure of salt water cooling eye. Three AOS reported by Agreement States.

AHEARNE, J. F. Commissioners. 81/02/20. 1p. 07865:309.

8103110332 Transcript of ACRB Subcommittee on Reactor Operations 810309 meeting in Machington: DC re NUREQ-1580. Pp 1-77. Supporting documents & viewgraphs encl. # ACRB - Advisory Committee on Reactor Sefeguerds. 81/03/09. 103pp. 07882:039.

8103110697 Forwards proposed frecture mechanics procedures for primary component support toughness evaluations Procedure modified per NRC comments & recommended for inclusion in NURE9-0577. Bubmits drawings for clarification of applicable geometries. BCHERER: A E. C-E Power Systems. LD-01-013. 81/03/06. 1p. 07885:060.

--Bio3i10705 "Fracture Mechanics Procedures for Primary Component Support Toughness Evaluations:Recommendations for Inclusion in NUREG-0577." \* C-E Power Systems. 81/02/27. 34pp. 07885:061. 0103110919 NUREO/CR-1799 103110819 NUREO/CR-1/99
ADVANCED REACTOR BAFETY RESEARCH DIVISION Quarterly Progress
Report July 1-September 30, 1980.
RAMANO.A J. Brookhaven National Laboratory. FIN A-3015 BNL-NUREO-51297 81/02/28 144pp. Available at NTIS 07878.001.

8103160252 Forwards WCAP-9804. "Probabilistic Amalysis & Operational Data in Response to Item II K 3.2 for Westinghouse NSSS Plants

DURGENSEN, R. H. Hestinghouse Operating Plants Duners Group. DG-52 81/03/13 in 07918 089

"Probabilistic Analysis & Operational Data in Response to NUREO-0737 Item II K. 3 2 for Westinghouse Plants." ANDERBON.T. M. . WOOD. D. C. . 90TTBHALL.C.L. Westinghouse Electric Corp. 81/02/28. 86pp 07918:090.

B103160426 Comments on NUREO-0586. "Draft GEIS on Decommissioning of Nuclear Facilities." Nonpower research & test reactors should be mentioned in DEB MILLER, J.R. Standardization & Special Projects Branch 81/02/11

B103160514 "Environ Behavior of Transuranic Nuclides Leaked From Hater Cooled Nuclear Power Plants," final rept Aug 1977-Dec 1978 BOHEN, V.T. Hoods Hole Oceanographic Instituts. FIN 8-6153 B1/03/31. 63pp 07918:234.

8103180060 Transcript of B10309 meeting in Hashington.DC re briefing on programmatic ETB for TMI.Pp 1-65.

# Commissioners: B1/03/09. 66pp 07942-213.

\_\_BIAGISAA71 SECV\_BI\_133

(Milebouri active):-133 Provides Commission W/programmetic EIB, "Decontemination & Disposal of Radwastes Resulting From Mar 2B,1979 Accident at TMI-2." & proposed statement of policy by Commission on FIR DIRCKS.W J Office of the Executive Director for Operations. B1/02/27. 5pp

8103180962 NUREQ/CR-1877

STRUCTURAL FRAMEWORK OF THE MISSISSIPPI EMBAYMENT OF BOUTHERN ILLINGIS
KOLATA, D.R., TREWORDY, J. D., MABTERS, J. M. Illingis
Survey. FIN 8-6251. 81/03/31. 79pp. 08024: 153. Illingis State Qeological

8103190075 Unofficial transcript of 810311 meeting in Washington. DC re discussion & possible vote on full power license for Farley.Pp 1-36. # Commissioners. 81/03/11. 37pp.

B103190564 NURFO-0748 VOL NOL OPERATING REACTORS LICENBING ACTIONS SUMMARY Date as of Jenuary 31,1781 (Grangs Boot) = Internal Information Bystems Brench. 81/02/28. 147pp. Available at NTIS. 85.50. 07963:070.

9103190737 NUREO-0493 VO3 NO3 SYSTEMATIC EVALUATION PROGRAM STATUS BUMMARY REPORT. Data as of Fabruary 1, 1981. (Buff Book)

or regreaty 1.1741, SUFF BOOK!

— Office of Management and Program Analysis. \* Office of Nuclear Reactor Regulation, Director. 81/02/28. 58pp. Available at NTIS. \$3.75. 08024:345.

8103190763 NUREQ/CR-1783 BENIO763 NORG/CR-1/93
STRUCTURAL INTEGRITY OF WATER REACTOR PRESSURE BOUNDARY
COMPONENTS Quarterly Progress Report April-June 1980.
LOSS,F.J. Navy, Dept. of. Naval Research Laboratory. FIN 8-5528.
81/02/28. 70pp. Available at NTIS. 07964:175.

B103200357 NUREQ/CR-1610 V01N03 INSPECTION METHODS FOR PHYBICAL PROTECTION PROJECT. Guarterly Report Beptember-November 1980. BOMDEN.D.D., MINICHING.C., OLBON.A.W. Lawrence Livermore Laboratory. FIN A-0143 81/02/28. 23pp. Available at NRC 41.75. 08024:267.

POST OF THE PROPERTY OF THE PR 8103230106 NUREO/CR-1767

8103230239 NUREO-CR-1872 ERR: OSSESSES NUMBER-CR-18/2 ERN:
REACTOR CALCULATION "BENCHMARK" PCA BLIND TEST RESULTS.
W, HUFFMAN.J.M. Dat Ridge National Laboratory. FIN 8-0415.
ORNL/NUREO/TH-4. 81/02/13. 3pp. Available at NTIS. 07978:001 9103330343 NUREAZOR-0849 VOSNOS BAFFOUARDS MATERIAL CONTROL AND ACCOUNTING PROGRAM Quarterly Report. April-June 1980 PO0010.A J., DUNN.D R. Lawrence Livermore Laboratory. FIN A-OL UCRL-52715-BO-3. 81/02/28 35op. Available at NTIB 92 25. 00034 330

8)03230432 Discusses draft NUREO-0772, "Technical Bases for Estima Fission Product Behavior During LWR Accidents " Issuence of Mar 1981 draft NUREQ-0771, "Repulatory Impact of Nuclear Reactor Accident Source Term Assumptions, "may be delayed, MARK.) C. ACRS - Advisory Committee on Reactor Safeguards. 81/03/17. 3pg. 07976.358

B103230472 Bubmits summary of B10312-14 ACRS meeting to discuss dr. NUREQ-0666. "Probablistic Safety Analysis of DC Power Bupply Requirements at Nuclear Power Plants." NUREQ is acceptable Reliability goals for dc sys should be developed. MARK.J C. ACRS - Advisory Committee on Reactor Bafeguarde B1/03/17. 1p. 07975-350

8t03230592 Forwards NUREQ-0751. "Review & Evaluation of NRC Safetu Research Program for FV82 "
MARK.J.C. ACRB - Advisory Committee on Reactor Bafeguards.
81/02/12 | ip. 08025 095.

--B103230599 NUREG-0751 103420379 NOREG-0731
REVIEW AND EVALUATION OF THE NUCLEAR REQULATORY COMMISSION
EAFETY RESEARCH PROGRAM FOR FISCAL YEAR 1982
\*\* ACRS - Advisory Cormittee on Reactor Bareguards. 81/02/28
61fp. Available at NII8 08023:076.

8103230991 NUREO-0723 [D323099] NUREO-0723 ENVIRONMENTAL ABSESSMENT RELATED TO THE OPERATION OF BAN MIOUEL URANIUM MILL PROJECT. HM-20 (Pioneer Uravan. Inc.) • Office of Nuclear Material Bafety & Bafeguards. Director B1/01/31. 116pp. Available at NTIB \$4.24. 08026:282.

B103230999 NUREO-0566 VOI NOZ BTANDARDS DEVELOPMENT STATUS SUMMARY REPORT, Data as of February 28,1981. (Green Book)

\* Internal Information Bystems Branch 81/03/31. 191pp. Avail

at NTIS 08025 151 B103240237 NUREQ/CR-1745 ANALYBIS OF TECHNIQUES FOR ESTIMATING EVACUATION TIMES FOR

ANALYBIS OF TECHNIQUES FOR ESTIMATING EVACUATION TIMES FOR EMERGENCY PLANTING ZONES URBANIK, T. LINDELL, M. K. SCHULLER, C. R. Battelle Memorial Instit Pacific Northwest Laboratory. FIN 8-2311. BHARC-401/80-01 80/11/30. 38pp Available at NT18 08026; 217.

8103240246 Forwards NUREC-0755, "Rept to Congress on Status of Emergency Response Planking for Nuclear Power Plants" Satisfies Section 107. Public Law 94-295. MENDRIE, J. H. Commissioners. 81/03/10 1p. 07980; 254.

--8103240254 Forwards NUREG-0755. "Rept to Congress on Status of HENDRIE, J.M. Commissioners. 81/03/10. 1p. 07980; 255.

--8103240260 Forwards NUREO-0755, "Rept to Compress on Status of HENORIE, J. M. Commissioners. 81/03/10. 1p. 07980; 256

--8103240267 Forwards NUREQ-0759, "Rept to Compress on Status of Satisfies Baction 107-Public Law 96-275.

HeNDRIE, J.H. Commissioners B1-103/10 1p. 07980:297.

--8103240269 Forwards NUREG-0759, "Rept to Congress on Status of Satisfies Section 109-Public Lew 96-295.
HEIDRIE, J. M. Commissioners. 81/03/10. 1p 07980: 28 1p 07980: 258.

--8103240272 Forwards NUREG-0755, "Rept to Congress on Status of Emergency Response Planning for Nuclear Power Plants."

Batisfies Bection 109.Public Lew 96-293

HeNDRIE-J.M. Commissioners. 81/03/10. ip. 07980:239.

--8103240278 NUREO-0755
REPORT TO CONORESS ON STATUS OF EMERGENCY RESPONSE PLANNING FOR NUCLEAR POWER PLANTS. \* Division of Emergency Preparedness. 81/03/31. 107pp. 07985: 016

A DENEMALIZED AGE-DAMENDENT LOTS COULD WITH AMMICTATIONS ID

RADIATION STANDARDS
CRAMFORD D J Oak Ridge National Laboratory. FIN 8-0410

ORM, JNUREG/TM-4 81/03/31 89pp Available at NTIS

- 8103250134 Forwards NUREO/CR-1533, "Analysis of FLECHT SEASET Unblocked Bundle Stean Cooling & Boiloff Feets" "ASSIE.H W Westinghouse Electric Corp. NRC-04-77-127, FSS-81-351 81/02/18 1p. 08024-016
- ~-8103250141 NUREO/CR-1533
  AVALYB18 OF THE FLECHT SEASET UNBLGCKED BUNGLE STEAM COOLING
  AND BOILOFF TESTS
  W0:0,5 , H3CHRETTER.L E Heatinghouse Electric Corp , Nuclear
  Energy Systems NRC-04-77-127. EPRI IP-1460. 81/03/31. [35pp
- B103250255 NUREC/CR-1761
  PRESENCE OF PATHOGENIC ANCEBAE IN PCHER PLANT CCCLING
  WATERS Final Report for the Period October 13.1977 to
  September 30.1979
  TYNOAL:R L . SIEVENS.A R . HILLAERT.E Day Ridge National
  Leboratory FII: B-041B DRNL/NUREC/TM-4 81/03/31 35pp
  Available at NTIB 07993 29B
- 8103250261 NUREG/CR-1453
  AQUATIC FODDUEB RADIDAUCLIDE MIGRATION MODEL
  MARIETTAM 0 . MAYLAND. J R Sandia Laboratories JACKSON. D N
  Southwest Research Institute FIN A-1200. BAND80-1047 B1/03/31
  68pp Available at MISS 07973 351
- 8103250273 NLREG/CR-1587
  NCLEAR PIN SIMULATION ANALYSIS OF THIF TEST 105
  HAGAR.R C Dat Ridge National Laboratory FIN 8-0123
  ORNL/NURFO/TH-4 81/03/31 2000p Available at NII8
- B103250432 Forwards tackground info re owners group procedures evaluation & development program to achieve compliance u/ NURCO-0797. Item 1 C 1 activities NRC acknowledgement of program acceptability enci.

  URCEMBER R W Westinghouse Operating Plants Owners Oroup UG-54 B1/03/18 65pp 07996:124
- --Bi02270391 Requests basis document for emergency procedure guidelines, per B01112 neeting Preliminery review of NCAP-9691 to determine conformance w/NUREC-0737, Item I C. I requirements will be completed by and of Feb 1981 HANAUCR. S. H. Division of Human Factors Sefety 8D/12/17 1p. 65030 247
- --Bl03250435 Delineates numers group proposed plans to comply w/ NUREO-0737. Item 1 C. I. requirements re-procedures evaluation & development Group will meet w/ARC in Jan 1981 to discuss risk evaluation retroduif necessary JUROENSEN.R U Westinghouse Operating Plants Owners Group 00-47. B0/12/15 app. 07946 189.
- GIO3250458 NUREO/CR-1769

  ANALYSIS OF FLASHINS TRANSIENT EFFECTS DURING REFILL
  CRO.LEVY.C J. LEI.S. ROTHE.P.H. Crears, Inc. FIN A-4070 IN-321
  B1/03/31 182pp Available at NTIS \$50.50 08027:035.
- 8103250628 Package of 12 comments apposing NUREO-0318 re proposed rulemaking exemption from licensing requirements for smelted alloys containing residual TC-99 & low enriched U.

   Affiliation Unknown. 45FR70877. 80/12/03 74pp 07586:001
- G103250629 NUREO/CR-1909
  TRANSTENT TESTING OF AN IN-CORE IMPEDANCE FLOW SENSOR IN A
  9-RDD MEATED BUNDLE.
  HARDY, J. E. LEAVELL, M. H. LIEBERT, H. Gal Ridge National Laboratory.
  FIN 8-0413 GRNL/NUREO/TM-3 81/03/31 71pp. 07998 053.
- B10325063B MUREO/CR-1951 H080UNDB.A PROGRAM FOR GAP CONDUCTANCE BGUNDB OF FABI REACTOR FUEL PIND KALIMULLAH Argonne National Laboratory. FIN A-2015. ANL-81-2 B1/03/31. 48pp 07998-287.
- B103250646 NUREO/CR-1962 VO1
  INTERNAL DOSIMETRY DATA & METHODS OF ICRP-PART 2.VOL 1:
  COMMITTED DOSE EQUIVALENT AND SECONDARY LIMITS
  ECKERMAN, X F., FORD. M.R., WATSON, B. B. Oak Ridge National Laboratory
  FIN 8-0213 ORML/NUREO/TM-4 B1/03/31. 141pp. 07998:118
- 8t0325064B Requests availability of NUREO/CR-1014. "Integral Geophysical & Geological Study of Tectonic Framework of Thirty-Eighth Parallel Tineament in Vicinity of Intersection w/Estension of New Madrid Fault Zone." for 810323-0421 sale. BROMBERO, B Research Contracts Branch. 81/03/18 1g. 07999.361.

notice including Cormission statement & discussion rept should be revised Marked-up math encl CHILM. B J Office of the Secretary of the Commission S80-551 81/03/18 31pp 08000 294

- B103260022 NUREO/CR-1943
  THE INCOMPLETE LOWER-UPPER CONJUDATE GRADIENT (ILUCO) METHOD FOR SOLVINO LARGE, SPARSE LINEAR BYBTEMS.
  NEIL-C H Los Alaros Scientific Laboratory FIN'A-7016
  LA-B705-MB 81/03/31 18pp. 08041:131
- B10326030 NUREO/CR-1902
  HIGH-TEMPERATURE GAS-CODLED REACTOR SAMETY STUDIES FOR THE
  DIVISION OF REACTOR SAMETY RESEARCH Guarterly progress
  Report July 1-September 30, 1980
  BALL.S. J. CLEVELAND. C. J. COMMLIN. J. C. Dak Ridge National
  Latoratory FIN B-0122 ORNA, MUREO/TM-4 B1/03/31, 22pp
  Available at NTIS 08041 148.
- 8103260039 NUREC/CR-1814
  SIMULATION OF A STEADY-STATE AND TRANSIENT SODIUM BOILLING
  EXPERIMENTS IN A SEVEN-PIN BUNDLE UNDER FLOW RUNDOWN
  COMBITIONS BY USING SODYFIT-IFE CODE
  CHEN.B.C. SHA.W.T. Argoine National Laboratory. FIN A-2045
  ANL-CT-GI-9 81/03/31. 44pp Available at NTIS 08041.167
- B103260301 Forwards "Mestinghouse Prediction for LOFT Nuclear Experiment L3-6 Using NOTRUMP 'Better Estimate' Code." in response to NUREG-0737 requirements Rept available in Central Files only. UNGCNSEIN R W Bestinghouse Operating Plants Owners Group. 09-30 81/03/25 1p 08022-045
- 8103260780 Discusses purpose of AIF Cormittee on Power Plant Design.
  Const & Operation, established on 810128 & assigned task refracture toughness requirements of nuclear component
  supports per NUREO-0977.
  HOWELL, B it Atomic Industrial Forum 81/03/20 ip 08036 090
- 8103270055 Contents on draft NUREC-0518. "DEB to Proposed Rulemaking Exemption From Licensing Requirements for Smalled Alloys Containing Ic-97 & Low Enriched U "Environ & economic analyses do not support broad applicability of rule. HEDEMAN, W N Environmental Protection Agency. 45FR70877 026 81/01/26. 7pp 08044 129
- B103270085 Comments on draft EIS re-proposed rulemaking elemption from licensing requirements for smalted alloys containing Tr-99 & low enrighed U Proposed controls provide adequate assurance that individual & population dosed meet requirements VILLFORTH. J. C. Health & Human Bervices, Dapt. of.. 45FR70877-021-80/12/24 2pp 08044:127
- B100270094 Comments on draft E1S re proposed exemption of licensing requirements for shelted alloys containing Tc-99 & low enriched U Opposes NUREC GRAVES.Z R Affiliation Unknown. 45FR70B77 019 B0/12/24 Ip. DRN44 1254
- BiO3270108 forwards comments on draft EI8 re proposed exemption from licensing requirements for smelted alloys containing Tc-99 & low enriched U Opposes NUREC.

  DREY- K Affiliation Unknown 45fR70877 014. BO/12/19. 3pp. 08044 120
- 8103270116 Corments on draft EIS is proposed aremption from licensing requirements for smalled alloys containing Tc-99 & low enrighed U Draft does not adequately describe range of contamination levels of scrap input or smalled metal. THOMPSON, G.R. Union of Concerned Scientists. 49FR70877 015 00/12/22. 2pp 08044:118
- 8103270253 Comments by OH Citizens for Responsible Energy on NUREO-0586, "Draft Generic EIS on Decommissioning of Nuclear Facilities." Rept contains contradictions re entombment viability & required times.

  ALEXANDER, J. Affiliation Unknown. 46FR11666. 81/03/14 Ip
- 8103270317 NUREG-0748 VOI NO2
  DPERATING REACTORS LICENSING ACTIONS SUMMARY Data as of
  February 28.1981. (Grange Book)
  # Internal Information Bystems Branch. 81/03/31. 123pp.
  08034:152
- 8103270808 Forwards Suppl 2 to NUREO-0487 & FR notice re Mark II lead plant pool dynamic LGCA loads evaluation W/o encls. DENIGN.H R Office of Nuclear Reactor Regulation, Director. 81/33/16. 1p. 08045 to7.

- B103270B16 Comments on draft EIS no proposed exemption from licensing requirements for smelted alloys containing Tc-99 & low-enriched U Opposes NUREO CHARLES B Affiliation Unknown 49FR70B77 012 B1/02/20 2pp
- 8103270817 Forwards Buppi 2 to MUREO-0487 & FR notice re Mark II lead plant pool dynamic LCCA loads evaluation. M/o encis DENTON.H R Office of Nuclear Reactor Regulation, Director 81/03/16 1p 08045 110
- 8103276819 Forwards Suppl 2 to NUREG-0487 & FR notice re Mark II lead plant pool dynamic LOCA loads evaluation Wo enels DENTON-IR R. Office of Nuclear Reactor Regulation, Director 81/03/16 | Ip | C8045 111
- B103310574 Submits comments on "Review & Evaluation of Sys Interactions Methods." "Review of Sys Interaction Methodologies." & "Sys Interaction State-of-Art Review & Methods Evaluation " WAONER, D P. JOF Associates DPM-133-81 81/03/24 3pp 08063.004
- B103310924 NUREO/CR-1845
  FRAPCON-2 A COMPUTER CODE FOR THE CALCULATION OF STEADY
  STATE THERMAL-HECHANICAL BEHAVIOR OF DXIDE FUEL RODS.
  BERNAL O A . BOHN. M P EQ&O Idaho. Inc RAUSCH. W N Battelle
  Menortal Institute, Pacific Northwest Laboratory. FIN A-6050.
  B1/01/31 296pp Available at NTIS \$7 00. 08061 159

## ORG CORRESPONDENCE WITH OTHER DROANIZATIONS

- 791231021B Forwards two std orders for DDE work re fire protection re-evaluation, Requests DDE acceptance EISEN-UT. D. G. Division of Operating Reactors. Fin A-3338 79/12/11 1p 01657-289.
- 8103030415 Notification of B10224 meeting w/Inst of Nuclear Power Operations in Bethesda.MD to discuss integrated operational superience reporting sys MEDBON.F J Director's Office 81/01/30 1p 07795-014
- 8103060688 Submits quarterly rept of svcs performed for Oct-Dec 1980 Computer printouts enci MILLIANSON.M M Energy Dept of Ideho Operations Office 81/01/30 9pp 07840.354
- B103090611 Transcript of B10121 meeting w/AIF in Washington, DC refuture of nuclear power plants Pp 1-82

   Commissioners 81/01/21 84pp. 07845.115.
- --BIGGOPO63: Transcript of FM Stassesky introductory statement during BIG12: meeting u/Commission re long-term outlook for addi nuclear power plants. BTABZESKY.F.M Atomic Industrial Forum. 81/01/21. 3pp. 07843-202.
- --8103090637 Submits agenda for 810121 meeting w/Commission WALGKE.C. Atomic Industrial Forum. 81/01/13 2pp. 07845.209
- --8103090643 Requests late Nov or early Dec meeting u/Commission to discuss NRC & industry conflicting views re-future of nuclear power.

  WALSKE, C. Atomic Industrial Forum 80/11/03 2pp 07845.206
- B103:20192 Discusses need to reiterate NRC policy re ANL contacts w/other agencies Recommends that its clarifying responsibilities during preparation of FEB be forwarded to appropriate mgt level at ANL.
  TEDESCORL Assistant Director for Licensing. 81/02/06 1p.07903-334
- BiO3160357 "Upgrading Emergency Prepardness at Nuclear Power Facilities." presented at American Nuclear Soc Intl Conference in Weshington DC on BO1118 GRIMES, B.K. Director's Office. BO/11/18 4pp. 07916: 153.
- 8103190897 Notification of FV81 midgr review of NBIC program on 810326 in 811ver Bring, MD to discuss accomplishments & Puture plans.
  DIBALVO, R Division of Reactor Bafety Research. 81/03/12 2pp 07944:096

8103260780 Discusses purpose of AIF Connittee on Power Plant Des Const & Operation, established on 810120 & assigned task re fracture toughness requirements of nuclear component supports par NUREO-0577 HOWELL, S. H. Atomic Industrial Forum, 81/03/20 Ip 08036 0

B103261141 Notification of B10317 meeting w/Inst of Nuclear Powe Operations in Bethesda, MD to discuss technical exchange on humans factors programs Agenda and IRELAND.R Division of Human Factors Safety 01/03/16. 3pp 08035:262

#### PR PROPOSED RULE

- 8102020293 Discuses Zion Units i & 2 siting & problems w/evacuat emergency planning due to population density Potential for catastrophe is unlimited Facility site is unreasonable Certificate of Svc encl.

  OUIGO. C. Pollution & Environmental Problems. Inc. 80/12/24
  07598 265
- 8102170111 Revision 1 to preliminary draft. Analysis of Comments Received on MRC Advance Notice of Rulenaking Revision of Reactor Siting Criteria. (45FR50350-800729) " # Oak Ridge National Laboratory 45FR50350 81/01/31 233pg 07692 059
- 8)02270554 Responds to 810126 lit espressing concern re-proposed changes in radwaste disposal regulations at medical facilities Lit will be sent to NRC in Kashington.UC for late comment consideration W/o new announcement BTRASMA.J Region 3. Chicago. Office of the Director 81/01/2
- --D102270558 Protests proposed changes in raduaste dispusal regul at madical facilities Mods will cause cancer & genetic
- defects
  RDIH.L.X Genen's International League for Peace & Freedom
  B1/01/26 1p
- 0103020298 Package of 646 comments opposing proposed tules 100FRC 70 & 150 re-passession, use & transfer of low enriched U as contaminant in metals # Affiliation Unknown 45FR70874 80/12/03 598pp
- 8103020305 Package of 20 comments opposing proposed rules 10CFR30 70 8 150 re exempting use of Tc-99 or low spriched U as contaminant in smelted alloys for consumer products.

  \* Affiliation Unknown. 45FR70874. 80/12/18 15pp.
- 8103030182 Comments on proposed rule 10CFR2 re proposed general statement of policy & procedure for enforcement actions Pattern of severities should be made more uniform CLARKE, E.T. Technical Operatums, Inc. 45FR66794 195. 81/02/09200 07808 154
- B103030194 Forwards comments on behelf of PA Electric-Met Ed & of proposed general statement of policy & procedure for enforcement actions. Policy is unfair.
  TIPTON.T.E. Ogneral Public Utilities GPU Service Corp. 49Fs 154 B1/01/26 12pp.
- 8103030208 Comments on proposed rule 10CFR2 re-proposed general statement of policy & procedure for enforcement actions Policy found unfair & inequitable MARENSDURG, D. M. Public Service Co. of Colorado. 45FR66794 15: B0/12/23. App. 07808:359.
- 8103030218 Comments on proposed rule 10CFR2 re-proposed general statement of policy & procedure for enforcement actions. Rule will mandate penalities inappropriate to severity of violation or infraction BCHERER.A E C-E Power Bystems. 45FR66754 152 81/01/28 2(07805: 357
- 8103030227 Forwards comments on proposed rule 10CFR2 re-proposed general statement of policy 8 procedure for enforcement actions. Rule found too rigid.

  EMELLEY.M J Kerr-McGee Corp. 43FR66754 131 81/01/27 Spp. 07805, 392

- 8103030234 Comments on proposed rule 10CFR2 re-proposed general statement of policy & procedure for enforcement actions Opposes rule ZILLER.E Affiliation Unknown 45FR66794 150. B1/01/23 3pp 07805-349
- 8103030319 Notification of contract elecution.Mod 1 to "Technical Assistance for EIS on 100FR61." Contractor Dames & Moore HAIRSTON.C . SMITH.P. A Technical Assistance Contracts Branch. FIN 8-7312 NRC-02-B1-049 81/01/16 1p. 07790 232
- --BJ03030331 Mod 1. increasing munetary limitation definitizing unpriced order into priced contract & adding terms & conditions to "Technical Assistance For EIS on 100FR61."

  CLINE.J C Dames & Moore. MATTIA, HJ Administrative Contracts Branch FIN B-7318-1 N9C-02-81-049 BI/01/16 33pp.
  02790 233
- 8103040194 Comments on proposed rules 10CFR30.40.50.70 & 72 re-residual radioactivits, Lowering residual levels from 50 mrem/yr to 5 mrem/yr would have small impact on decommissioning cost SMIFR.R I Battelle Memorial Institute. Pacific Northwest Laboratory 45FR10370 BI/02/06 4pp 07809-314
- 8103040884 Comments on proposed rule 10CFR50 re Tech Specs for nuclear polar reactors New Category of requirements based on concept of immediate importance to safety should be included MDFFMAN, D P. Consumers Power Co. 43FR45916-034 81/02/11 1p. 07812-237
- B103041031 Comments on proposed rules 10CFR30.40.70.190 & 170 re request for stay of effective date of radiation protection stds for U mills Effective date of 40CFR190 should be stayed. GVERTGY, J. A. American Mining Congress. 44FR50012. 80/11/04. 2pp.
- 8103050007 Corrents on proposed rules 10CFR30.32.70 & 190 re use of fc-99 & low enriched U as conteminant in metals Also commants on proposed rule 10CFR20 re disposel of radweste in sever sys & samitary landfills. Opposes rules LUFTMAN, M APPLICATION Unknown 43FR67018 334 80/12/20 1p.
- B103050012 Comments on proposed rules 10CFR30.32.70 & 150 re use of Tc-99 & low enriched V as contaminant in metals. Also comments on proposed rule 10CFR20 re disposal of radweste in sewer sys & sanitary landfills. Opposes rules KRAFTIR. Affiliation Unknown 45PRA7018.332. 81/01/27 lp
- 103090024 Forwards E. Nemethy 810112 comments on proposed rule 100FR20 re disposel of low level redwasts. Also comments on proposed rules 100FR30. 32, 70 & 130 re recycling metals containing TC-99 & low enriched U for consumer products. Opposes rules. SPECTER, A. Senate. 45FR70874. 81/01/20. 3pp.
- 8103050029 Comments on proposed rules 10CFR30, 32,70 & 150 re use of Tc-99 & low enriched U as contaminant in metals. Also comments on proposed rule 10CFR20 re disposel of radwaste in sewer sys & sanitary landfills. Opposes rules. TEELINA.M O Homen's International League for Peace & Freedom, 45FR67018 333 B1/01/26. ip.
- 8103050042 Comments on proposed rule 10CFR35 re reporting requirements for medical misedministration of radioactive matis Rule is useless expensive 5 of no value to anyone.

  METZELLR A Milliam Beaumont Hosp, Royal Oak-MI. 45FR31701 005.

  81/01/23 1p. 07585:001
- 8103050051 Comments on proposed rule 10CFR20 re disposed of medical & research radueste into sever sys & sanitary landfills Also comments on proposed rules 10CFR30.32.70 & 150 re recycling radioactive metals for consumer products Opposes rules KRAFT, R Affiliation Unknown 45FR70B74 81/01/27. 1p
- 8103050056 Forwards CE Smith 801230 comments on proposed rule 10CFR35 re reporting requirements for medical misedministration of radioactive matis. Rule represents misephropriation of regulatory power. Medical practices not improved by rule CRAIO.L E. House of Rep. 45FR31701 006 B1/01/30. 2pp. 07827:014
- 8103050077 Responds to 810112 request re proposed rule 10CFR35 on reporting for medical misadministrations of radioactive matis. Rulemaking will not be reopened unless pertinent info was not available when final rule was approved.

  DIRCKB-W J. Office of the Executive Director for Operations.
  45FR31701 CO7. 81/02/05 12pp.
- --BIOJOSOOS4 Forwards CE Smith BO1230 comments on proposed rule iOCFR35 re reporting requirements for medical misedministrations of radioactive mati-for NRC consideration.

  HANBEN.G. House of Rep. 45FR31701 004 BI/01/12

- 8103050099 Comments on proposed rule 10CFR35 re reporting requirements for medical misadministration of radioactive matic Rule is no gain in improvement to public health METZEL.R A William Beaumont Hosp Royal Cak.MI. 45FR31701 003 80/12/10 2pp 07827.012.
- 8103050205 Forwards comments on proposed rule 10CFR61 re disposed of iou level radwaste & low activity bulk solid waste EASON.C F Affiliation Unknown 45FR:3104 004 BI/0I/30 6pp 07832-098
- BIO3050651 Comments on Working Group rept on storage & disposal of nuclear waste Haste can be stored & disposed of safely. No review of supplemental info nocessary NRC should confine review to technical issues Certificate of Svc encl. WHITE.E B American Nuclear Society WHITE.E.B. Pacific Legal Foundation BI/O3/04 12pp 07829-189.
- 8103050802 Comments on proposed rules 10CFR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Diposes rules
  NRKADEOMMA\_J\_Affiliation\_Unknown\_ 45FR70874\_1816\_8D/12/09\_ 1p
- 8103050808 Comments on proposed rules 10CFR30.32.70 & 190 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules.

  STABLEFORD.D.H. Affiliation Unitroum. 49FR70874 1894. 80/12/09 tp.
- 8103050815 Comments on proposed rules 10CFR30.32.70 & 150 repossession-use & transfer of low enriched U as contaminent in metals. Opposes rules. PEDRAYES.H. J. Affiliation Unknown 45FR70874 1702. 80/12/09. 19
- 8103050823 Comments on proposed rules 100FR30-32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules.
  HOLLIS,K Affiliation Unknown 45FR70874 1787. 80/12/09. 1p
- BiO3050DAA Comments on proposed rules 10CFR90 & 91 re draft suppl to EIB for Virgil C Summer Nuclear Station (NUREO-0534). Buppl does not describe potential impacts of serious accidents on human health & environ in menner which is clear to public. NNIOHI.C.F. President of US & Executive Offices. 45FR40101 027. B1/02/04 4pp. 07831-334.
- 8103050910 Comments on proposed rules 10CFR30.32.70 & 150 repassession.use & transfer of low enriched U as contaminant in metals. Opposes rules.
  8TROTERIDGE.8 Affiliation Unknown 45FR70874 1788. 80/12/09 i
- Bi03050916 Comments on proposed rules 10CFR30, 32,70 & 150 re possession, use & transfer of low enriched U as conteminant in metals, Opposes rules, PALAZZO, L. Affiliation Unknown, 45FR70874 1669, B0/12/09, 1p.
- 8103050923 Comments on proposed rules 10CFR30,32,70 & 150 repossession, use & transfer of low enriched U as contaminant in metals. Opposes rules.

  CHIARELLA.E. Affiliation Unknown. 45FR70874 1672. 80/12/09. Ip.
- Bi03050929 Comments on proposed rules 10CFR30, 32,70 % 150 re possession use & trensfer of low enriched U as contaminant in metals. Opposes rules. MICHEL. M. Affiliation Unknown 45FR70874 1674 80/12/09. Ip.
- 8103050932 Corments on proposed rules 10CFR30.32.70 & 150 reposession.use & transfer of low enriched U as contaminant in metals. Opposes rules.

  MACOMBER.1. Affiliation Unknown. 45FR70874 1800. 80/12/09. 1p.
- 8103090938 Comments on proposed rules 100FR30,32.70 & 150 repossession.use & tFansfer of low enriched U es contaminant in metals. Opposes rules. FIBK.P.N. Affiliation Unknown. 45FR70874 1714. 80/12/09.
- B103050945 Comments on proposed rules 10CFR30.32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rules. PIPPENS.D. Affiliation Unknown. 45FR70874 1731. B0/12/09.
- 8103050949 Comments on proposed rules 10CFR30, 32,70 & 150 repossession, use & transfer of low enriched U as contaminant in metals. Opposes rules.

  MULLEN-M Affiliation Unknown. 45FR70874 1728, 80/12/09. 1p.
- Bi03050958 Comments on proposed rules 10CFR30.32,70 & 150 repossession, use & transfer of low enriched U as contaminant in metals Opposes rules.

  SHERIDAN.A. Affiliation Unknown. 45FR70874 1727. 80/12/09. 1p.

- 8103050966 Comments on proposed rules 10CFR30, 32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals Opposes rules HORLEBEIN.K. Affiliation Unknown. 49FR70874 1726 80/12/09 1a
- Bi03050973 Comments on proposed rules IOCFR30.32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules.
  BUTTACAVOLE.A Affiliation Unknown 45FR70874 1724 B0/12/09 1o
- B103050977 Comments on proposed rules 10CFR30, 32, 70 & 150 ra possession.use & transfer of low enriched U as contaminant in metals. Opposes rules RANN-L. Affiliation Unknown. 49FR70B74 2515 B0/12/09 to
- 8103050983 Comments on proposed rules 10CFR30, 32, 70 % 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules
  PRYPUTNIENTICZ Affiliation Unknown. 45FR70874 1915 80/12/09 2nd
- 8103050988 Comments on proposed rules 100FR30,32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rules CRUMLEY.J. J. Affiliation Unknown. 45FR70874 1926 80/12/09 2ap
- 8103050996 Comments on proposed rules 10CFR30, 32, 70 & 150 re possession.use & transfer of low enriched U as contaminant in metals Opposes rules HINDKUR-9 Affiliation Unknown. 45FR70874 2514 R0/12/09 In
- 8103051000 Comments on proposed rules 10CFR30,32.70 & 150 re possession.use & transfer of low enriched U as contaminant in metals. Opposes rules. KRUQMAN.A Affiliation Unknown. 45FR70874 2568 80/12/09 10
- Bi03051005 Comments on proposed rules 100FR30, 32.70 & 150 re possession.use & transfer of low enriched U as contaminent in metals. Opposes rules. LOME.S. Affiliation Unknown. 48FR70874 2503 80/12/09 ip
- B10305100B Comments on proposed rules 10CFR30, 32.70 & 150 re possession.use & transfer of low enriched U as contaminant in metals. Opposes rules.

  MARD.W.L. Affiliation Unknown 45FR70B74 2457. 80/12/09 ip
- 8103060005 Advises recipients of comments on proposed rule 100FR20-that Comment 5 was miscoded. Comment 5 will not be used again.

   Docteting & Services Branch. 45FR26072 81/02/02. ip. 07837:048.
- 8103060361 Comments on ACRS 801210 ltr to Commission, Agrees that institutional issues not resolved & date of waste repository evailability indeterminable. Disagrees w/ACRS conclusion that safe disposal technology exists. W/Certifliate of Svc ABRAMS.R., BIALIK, E. New York, State of, 81/03/02. Spp 07837:088.
- 8103060369 Comments on working group identification of issues Group failed to recognize confidence must be based on existing facts rather than hope. Commission must decide whether waste will be disposed of safely. Certificate of Svc encl.
  ABRAMS.R. BIALIK, E. I. New York, State of. 81/03/02. 18pp 07837:096.
- 8103060483 Forwards notice of petition for rulemaking 30-57 re amend of exemption for ionizing radiation measuring instruments. Proposed rule 10CFR30 results from petition for rulemaking 30-57.
  SHITH:R. 0. Office of Standards Development, Director. 81/02/23 3pp. 07836:056.
- ~-Bi030604B9 Notice of proposed rule 10CFR30 re amend of exemption for ionizing radiation messuring instruments. DIRCKB.M.J. Office of the Executive Director for Operations Bi/02/17. 9pp. 07836:060.
- 8103060683 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CP Appropriate approach is Alternative 1.Alternatives 2.3 & 4 are imprectical restrictive & burdensome.

  ANDERSON.T.N. Westinghouse Electric Corp. 45FR81602 021. 81/02/10 5pp. 07835:343.
- B103060689 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CF. Opposes rule. BTDME.M.S. Boston Edison Co. 45FRB1602 020. 81/02/09. 7pp. 07839:349.

- BIO3060691 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CP Supports. Alternative 1 Other alternatives, if implemented would require many other changes Status que should be maintained COUNSIL-R 0 Northeast Utilities. 45FR81602-019 81/02/04 3; 07638-329
- BIO3060698 Co-ments on proposed rule 10CFR\$0 re design changes in nuclear power plant facilities after issuance of CP NRC should develop one-stop licensing alternative for plants applying for future CPs Alternatives I & 2 most practical DAIL.t. C. Pute Power Co. 45FR81602 018 B1/02/06 2pp 07835 331
- 8103040705 Corments on behalf of Houston Light & Power & Puget Bown Power & Light on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CP.NRC should ceese rulemaking efforts.
  PONELL.D 0 towerstein.Neuman.Reis.Asselrad & Toll 45FR81402 OI 81/02/09 18pp 0/2835.313
- BiO3060708 Forwards comments on proposed rule 10CFR50 re design chain nuclear power plants after issuance of CP Alternative 4 should be modified so details of safety significance can be made conditions of CP & not changed w/o NRC approval VAN BRONT. E. E. Antiona Public Service Co. 45FR81602 016 81/02/5pp. 07835-303
- 8103060715 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CP Supports objective to provide guidance to CP helders. Combination of Alternatives 3 % 9 is not best approach TAYLOR. J. H. Babcock & Milcox Co. 45FR81602 002 81/01/27. 2pp 07835-306
- 8103060726 Comments on proposed rule 10CFR30 re design changes in nuclear power plant facilities after issuance of CP Alternatives 4.5 would penalize plants w/new or different designs Amends disproportionate to benefits to be Jersved FISHER.C R Deneral Atomic Co (subs. of Quif Oil Co.) 45FRB160 004 81/01/27 2pp 07832 360.
- 8103060731 Comments on proposed rule 10CFR50 re design changes in nuclear jower plant facilities after issuance of CP implementation of Alternatives 1 & 5 would maximize resources & would not require development of new procedures URADBURY. R B Stone & Hester Engineering Carp 45FR81602 005 81/01/27 4pp 07035 224
- Bio306073B Comments on proposed rule 10CFR50 re design changes in nuclear power plant factilities after issuance of EP Only Alternatives 1 % 5 should be utilized Mods initiated from discoveries of improvements must not be eliminated 8CHERERIA E. C-E Power Systems. 45FRB1602 CO3 81/01/29. 2pp. 07835 341
- Bio3060744 Comments on proposed rule 10CFR30 re design changes in nuclear power plant facilities after issuance of CP ARC should maintain status quo General criteria for ctanges requiring CP amend should be established. FRYLIN9.R. Public Bervice Electric & Gas Co. of New Jersey. 45FRB1602 006 81/01/30 3pp 07835.336
- Bio3060751 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities after issuance of CP Alternative I should be retained. Principles of Alternative 5 should be developed as option to Alternative I CAHN.A.L. Section 10.4 Principles of Bio101/30 3pp 07832
- B103060792 Forwards solicitation for comments on State Clearinghouse Project 81-12-466.notice of intent to prepare EIS for siting of nuclear power plants. Comment should be sent to NRC & info copy to State Clearinghouse MCCONNAUGHIAY Maryland. State of 49FR50350-B0/12/19 lp. 07632:356
- Bi03060754 Comments on proposed rule 10CFR50 re design changes in nuclear power plant facilities efter issuance of CP.Approach using Alternatives i & 5 would be most beneficial to enhancement of safety & efficient use of resources.

  OIBBS.D C. Atomic Industrial Forum 45FRB1602 007 01/02/02 07932 352.
- B103060760 Comments on proposed rule 10CFR50 re design changes in nuclear power plant factilities after issuance of CP.Current regulations are adequate NRC has not supplied justification for change of regulations.

  LEBGEUF.R. J. LAMB.H.R. / LEIBY.A.C LeBoeuf, Lamb, Leiby & MacRad 45FR81602 010. B1/02/02. 6pp 07832-346

- 9103060773 Comments on proposed rule 100FRSO we design changes in nuclear power plant facilities after issuance of CP implementation would add yet to licensing process & decrease applicant confidence in getting facility constructed MNUTH D.F. Kehr-McGee Chemical Corp. (Subs. of Merr-McGee Corp.) 45FR81602-009 81/02/03 7pp. 07802-339
- B103060782 Comments on proposed rule 100FR50 re design changes in nuclear power plant facilities after issuance of CP Cpposes adoption of procedures that would inhibit licensees from installing improved environ or safety sys in plants 190ERMN.48 M. Environmental Protection Agency 45FR81602-015-81/02/09 108 27802-398.
- 8103060791 Comments on proposed trule 100FP50 he licensing requirements for pending CP 5 mfg license applications No standardized plant should be required to make charges that are not required of all plonts of same design SCHERERA A E CHE Pouch Systems 45FR65247 015 80/11/14 3pp 07622 339
- 8103060779 Comments on proposed rule ICCFR50. Detestic Licensing of Production 5 Utilization Facilities of Melted Cores in Safety Regulation HEISING-OROMAN Massachusetts Institute of Technology 45FR65474 0484 60/12/08 5p 07832 330
- B105040B20 Comments on proposed rule 100FR50 he interim requirements re-nydrogen control 5 certain degraded core considerations 5 considerations of degraded or relited cores in safety regulation Changes should focus on prevention PRESBESMY. A J. Energy. Dept. of. 45PR65466-03B B1/02/03 114pp 03/03-212
- 810309035B Comments on proposed rule 100FR50 re-design changes in nuclear power plant facilities after issuance of CP Status que should be majortained Alternatives 2 & 3 should be postponed until CL tacking dintribles to manageable level. 2000(RCV: 6 Washington Public Power Supply System 45FR81602-022-81702709 3pp 07846-217
- 8103090368 Forwards comments on proposed rule 10CFR50 te consideration of degraced or melted cores in safety regulation Core nelt can be reduced by 4001ptoof monitoring of reactor water level & provision of civerse & redundant reactor feed sys DFRARRELLY.C. Affiliation Unknown 45FR55474 047 81/01/19 20pp 07R45 188
- 8103090373 Comments on projosed rule 100FR90 re development of integrated operational experience reporting sys intended to improve LER 1 NPR95 reporting programs Provision of timely distribution of info to menufacturer should be included CALDER-W Follow Corp. 46FR3341 001 81/02/03 1p 07846 189
- BIOSC90392 Comments on proposed rule 10CFR93 re development of integrated operational experience reporting sys to improve LFR & NPRDS reporting programs Repts should include model number type & other pertinent nameplate data of component VERRA B J Affiliation Unknown 45FR3341 CO2 81/02/05 2pp. 07846 186
- 8103090387 Comments on proposed rule IOCFR30 App 0 & H re reactor vessel mati surveyllance program requirements If "efter completion of testing" means "after completion of analysis of all data" then 90 days is workable submittal period WRGENSEN R H. American Electric Power Co., inc. 45FR75936 008, 81701715 pp. 07946 184
- E103090393 Forwards comments on proposed rule 10CFRSO ne fracture toughness requirements for nuclear power reactors. W/o encl PRATT.C M Power Authority of the State of New York 45FR79536 009 81/01/13 tp 07846 163
- 8103090431 Comments on proposed rule 100FR50 me fracture toughness requirements for nuclear power reactors App H Bection III A requirement that director be notified 30 days in advance of capsule removal should be deleted HOFFMAN. D.P. Consumers Power Co. 45FR79536-011 BI/02/02 ip. 07946-136
- B)03090459 Comments on proposed rule 10CFR50 App G re temp in region of reactor vessel flange & norries. Review of radiographic test NDT & 150 F requirement for vessel flange matt should be made HDFFMAN. D P Consumers Power Co. 45FR75536-012. 81/02/02 2pp. 07844-347
- 8103090469 Corments on proposed rule 100FR73 re searches of individuals at power reactor facilities Opposes rule UHR10.R E Atomic Industrial Forum 45FR79492 016 81/01/23 Epp 0/946 134

- 8103090522 Corments on notice of Intent to prepare EIB for revision of regulations governing plant siting Permission to use federal land in Jestein US should be granted by Secreatry of Interior HITE: I Interior Dept of Dureau of Land Management. 45FR79820 035 81/01/29 2pp 07844 181
- B103090526 Cornents on notice of intent to prepare EIS for revision of regulations governing plant siting EIS should evaluate cost vs benefit of various approaches to site selection CRALFORD. W Energy. Dept of 45FR79820 038 81/02/05 12pp 07384 169
- B103090528 Corrents on behalf of Ofc for Planning & Programming renotice of intent to prepare E18 for revision of regulations governing plant siting No comment necessary
  MALLACE: A T loua, State of 45FR79820 037 81/01/26 Ip
- 8103070532 Comments on notice of intent to prepare EIS for revision of regulations governing plant sitting Recommends incorporating specific population density 2 distribution limits that are dependent on average regional population VILLFORTH. J C . HEX. Dept of. Food & Drug Administration. 49FR79B20 034 81/01/28 3pp 07844 165
- 8103090534 Comments on notice of intent to prepare £15 for revision of regulations governing plant siting Proposed revision is not timely tAC rulemaking procedures are illogical BRADBURY.R B Stone & Nebster Engineering Corp 49FR79820 030 BI/01/16 4pp 07844 161
- B103090536 Comments on notice of intent to prepare E18 for revision of regulations governing plant siting Comments would be pre-nature & would be core appropriate for proposed rulemaking
  ANDERSON, T. M. Westinghouse Electric Corp. 45FR79820 031 81/01/23 4pp. 07846 119
- 8103090537 Connents on nutice of intent to prepare EIS for revision of regulations governing plant siting Supports notice Section 5 of EIS should discuss compatability of siting goals w/NRC safety policy HEDEMAN, W N Environmental Protection Agency 45FR79820 032. 81/01/20 2pp 07846 114
- B103090571 Comments on notice of intent to prepare E1S for revision of regulations governing plant siting E1S should be based on quantitative risk assessments considering plant design-population & emergency planning EDKARDB. 0 K Yankee Atomic Electric Co 45FR79320 033 81/01/27 3pp. 07846.110
- B100090577 Corments on behalf of Dft of Executive Mgt re-notice of intent to prepare EIS for revision of regulations governing plant siting No comments at present time RICHARDSON J.R. South Datota. Blate of 45FR79820-025
- 8103090583 Comments on behalf of Ofc of Mgt. Budget & Planning re notice of intent to prepare EIS for revision of regulations governing plant siting No negative comments to affer at present time INVGC-D 5 Delaware. State of 43FR79820-029 81/01/21 ig 07844-156
- B103090590 Comments on behalf of Federal Aid Coordinator Oft re-notice of intent to prepare EIS for revision of regulations governing plant siting No comments received from state & regional agencies
  BANMS-B A North Dakuta, State of 45FR79820 028. B1/01/13. 1p. 07844 159
- B103090751 Comments on notice of intent to propare EIS for revision of regulations governing plant siting Demographic criteria approaches should not include regionalization as framework for specifying desired degree of remotences. URIO.R E. Florida Power & Light Co. 45FR79020 036 81/01/30 ip 07844 157
- B103100307 Comments by Univ of Banta Clara on proposed rule 10CFR50 Policy language is hostile & will discourage some researchers from using radio;40tobes Action should be delayed until feedback is received HAYN-C H Affiliation Unknown 45FR67077 001. B0/12/15 1p. 07863 196.
- 8103100347 Comments on 810109 working group rept Util adopts comments of Util Nuclear Waste Mgt Group-Edison Electric Inst. Legal std for decisionnaising should not be open to question. Certificate of Svc encl GALLO.J. WILLIAMS.F.C. Consumers Power Co. GALLO.J. Teham. Lincoln & Beale 81/03/05 18pp 07864 33;

- 8107100352 Comments on 810109 working group rept Corrission should not rely on working group surmary of record Summary did not include forum position on some tapics & did not consider correct confidence finding sid Certificate of Svc encl HURIN.W A . PRICE.A S . Atomic Industrial Forum . HDRIN.W A . Debevoies & Liberman 81/03/05. 25pp 0.7865 009
- B103110488 Forwards CA Dept of Conservation review of working grouprept re-proposed waste confidence rulemaking GRBSICA.M. California, State of B1/03/03 ip 07872 148
- --Biogijo493 CA Dept of Conservation comments on Biot29 working group rept re-proposed waste confidence ruleraking Rept has included & represented adequately all issues participant considers significant Certificate of Svc encl GERSICK.M California, State of Bi/OJ/OJ 47pp 07872 149
- BiO3110301 Comments on working group rept on storage & disposal of nuclear waste Commission should find no confidence that radwaste util be disposed of safely or that disposal will be available. Centificate of Svc enci
  Q.SDN.J.F. BENECHAL.M.E. Minnesota. State of 81/03/05 25pp.
  07872 202
- B103110505 Comments on progosed rules 10CPR50 & 51 re mgt & dispusal of nuclear waste Working group rept ample to demenstrate that record supports Commission finding of confidence Question of confidence ripe for decision M/Certificate of Svc SA/GER. H S . WALLACE.L E . BURGER.J F Tennessee Valley Authority B1/03/05 9pp 07871 350
- B103110949 Forwards New England Coalition on Nuclear Pollution concents on NRC working group rept Comments cannot be docketed until all participants are served IV/o enc! STEPHENS.C R Docketing & Services Branch 81/03/06 1p 07879 326
- B103110964 Requests extension until 810316 to file comments on working group 810119 rept re waste confidence ruleraking Personnel changes necessitate extension 81NDERBRAND.C. Wisconsin. State of 81/03/09 ip 07882.340
- B103110365 Forwards NROC comments on IRC working group rapt Comments cannot be docketed until all participants are served M/o encl
  BTEPHENS.C R Docketing & Services Branch B1/03/06 1p
  07882 341
- B10311056B Comments on B10129 working group rept re waste confidence ARC should close proceeding w/positive finding on confidence in safe disposal of nuclear waste & establish w/EPA specific requirements Certificate of Bvc encl BUCKHAM-J A American Institute of Chemical Engineers 81/02/27 7pp 07802 342
- Bio3iio571 Comments of utils on Bio129 working group rept re waste confidence Rept unnecessarily concerned w/details Commission should take no further action until new chairman appointed Certificate of Bvc enct.
  V010T.H H Niagera Mohawk Power Corp V010T.H H Omaha Public Power District V010T.H H Power Authority of the State of New York B1/03/05. 7pp 07882 349.
- 8103110577 Comments on ACRB 801210 ltr & working group 810129 rept rewaste confidence Agrees w/ACRB statement & technical conclusions Rept raises basic questions relevant to Commission determination Certificate of Svc encl BAUSER.M A Edison Electric Institute SAUBER.H A Lowenstein.Neuman.Reis.Azelrad & Toll 81/03/05 21pp. 07877 212
- D103110696 Notice that official svc list for waste confidence rulewaking should be changed to read M Gersic? in place of PC Green for CA Dept of Conservation.

  GERBICK.M California, State of B1/03/03. 1p 07875 349
- Bi03:20603 Comments on proposed rules 10CFR30.32.70 & 150 re possession.use & transfer of low enriched U as conteminant in metals. Opposes rules GRANDBERG, J. Affiliation Unknown. 45FR70874 1914 80/12/09 2pp
- 8103120609 Comments on proposed rules 10CFR30, 32,70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FLINT, S C. Affiliation Unknown 45FR70874 2585 80/12/09 2pp
- 8103120614 Comments on proposed rules 10CFR30.32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals. Opposes rules RICHAROS.P. Affiliation Unknown 45FR70874 2762 80/12/09 4p

- 9(03)20618 Consents on proposed rules LCCFR20, 32,70 % 150 re possession.use & transfer of low enriched U as contaminant in metals Copiese Fules Double E Actualistics Hokening 45FR70874 2351 80/12/09
- B103120645 Comments on proposed rules 10/FR30.32.70 & 150 me possession.use 5 transfer of 16w entriched U as contaminant in metals Uppesses rules BERNETEIN S Affiliation Unknown 45/R70874 2552, B0/12/09
- B103120653 Comments an proposed rules 100FR30-32.70 & 150 ne passession, use & transfer of low enriched U as contaminant in metals Opposes rules Proc.534Cv. A. Affiliation Uninous 45FR70874-2353 80/12/09
- B103120660 Comments on proposed rules 100FR30, 32,70 & 150 re cassession, use & transfer of low entitched U as contaminant in metals Opposed rules MGDRRDPAILB AFFILIATION Uninown 45FR70874 2354 80/12/69
- BIG3120065 Cornents on proposed rules 100FR33,32,70 & 150 re passession,use & transfer of low enriched U as contaminant in netals Opposes rules 
  VRECAND.C Affiliation Unknown 45FR70874 2349. HO/12/09
- 8103120672 Corments on proposed rules 100F830, 32, 70 % 150 repossassion use & transfer of low enriched U as contaminant in metals Diposes rules ENICKSON.6 Affiliation Unknown 45F870874 2350 BO/12/09 1p
- B103120673 Responds to B10116 request for concurrence in instituting Task RM-905-1 Mangauer not available to support task muRLEY. T. E. Division of Safety Technology B1/01/30 Ip
- 8103120579 Comments on proposed rules 100FR30, 32, 70 & 190 re possession, use & transfer of low enriched U as contaminant in retals Opposes rules CALLAMAN D. Affiliation Unknown 45FR70874 2341 BOV12709 lp
- 8103120687 Cotherits on proposed rules 1005830-32-70 & 150 re possession.use & transfer of low enriched U as contaminant in metals Opposes rules FFRETILI M. A. Affiliation Unimown. 405870874 2340 80/12/07
- 8103120667 Corrents on proposed rules 10CFR30.32.70 & 150 re possession.use & transfer of low enriched U as contaminant in metals Opposes rules FERRETTIAN & Affiliation Unknown 45FR70874 2338 83/12/09
- 8103120691 Comments on proposed rules 10CFR30.32.70 & 190 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules
- in metals Opposes rules FERRETTI.M Affiliation Uninoum 45FR70874 2339 60/12/09
- BiO3120697 Comments on proposed rules 100FR30-32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Diposes rules LEVENBAUM.N Affiliation Unknown 45FR70874 2319 B3/12/09

1 p

1 p

- 8103120699 Comments on proposed rules 100FR30, 32, 70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules UCRD.W A Affiliation Unknown 45FR70874 2316. 80/12/09
- SIGNIZOTO2 Comments on proposed rules 100FR30, 32,70 & 150 re possession.use & transfer of law enriched U as contaminant in metals Opposes rules LERNER, J. Affiliation Unknown 45FR70874 2317. 80/12/09
- 8103120706 Comments on proposed rules 100FR30, 32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules SEAN.K.A. Affiliation Unknown 45FR70874 2386 80/12/09
- B103120714 Comments on proposed rules 10CFR30-32.70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules
  DAVIS.O W Affiliation Unknown 49FR70874 2388 80/12/09
- 8103120718 Comments on proposed rules 10CFR30,32,70 & 150 repossession.use & transfer of low enriched U as contaminant in metals Opposes rules DUNCAN.T. Affiliation Unknown. 45FR79874 2421. 80/12/09 ip

```
8103120723 Contents on proposed rules 100FR30,32,70 & 150 re
  possession, use & transfer of low enriched U as contaminant
  possession.use 5 transfer of low enricined U as contaminant
in metals Opposes rules
COBERLY.S J. Affiliation Uninown. 45FR70874 2379 80/12/09 Ip
8103120725 Comments on proposed rules 10CFR30.32.70 & 150 re
   n metals Opposes rules
MCCLOSKEY, P. Affiliation Unknown 45F870874 23R0 80/12/09 in
8103120728 Comments on proposed rules 10CFR30.32.70 & 190 re
possession.use & transfer of low enriched U as contaminant
in metals Opposes rules
GCRDON-P B Affiliation Uninown 45FR7C874 2392 BO/12/09 1p
 8103120732 Corrents on proposed rules 100FR30.32.70 & 150 re
   possession, use & transfer of low enriched U as contaminant
   B100120705 Comments on proposed rules 100FR30-32.70 % 150 re
   possession, use & transfer of low enriched U as contaminant
   in metals Opposes rules

• Affiliation Uningwo. 45FR70874 2391 60/12/09
 8103120737 Comments on proposed rules LCCFR30-32-70 & 150 re
   possession, use & transfer of low enriched U as contaminant
    in metals Opposes rules
                  Affiliation Uninown 45FR70874 2368 80/12/09 1s
    DURTNETT, J
 8103120739 Comments on proposed rules (CCFR30, 32, 70 & 150 re possession, use & transfer of low enriched U as contaminant
    in metals Opposes rules
    TARNE, P.C. Affiliation Unknown 45FR70874 2372 80/12/09 16
 8103120742 Corments on progosed rules 10CFR30-32-70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Deposes rules.
    MCHENNA, D.L. Affiliation Unknown 45FR70874 2377. B0/12/09 1p
 8103120745 Corrents on proposed rules 10CFR30.32.70 & 150 re
    possession.use & transfer of low entithed U as contaminant
    in metals apposes rules
MONAK-CAGNON C Affiliation Unknown 45FR70874 2375 80/12/09
 8103120747 Comments on proposed rules 10CF830-32-70 & 150 re
    possession.use & transfer of low enriched U as contaminant
    in metals Opposes rules
ADLER.S Affiliation Unknown, 45FR70874 2374, 80/12/09 to
 8103120748 Corments on proposed rules (OCFR30-32.70 & 150 re
    cossession, use & cransfer of low enriched V as contaminant
     in metals Opposes rules
DNGACRE S Affiliation Unknown 43FR70874 2396 80/12/09 1p
    LONGACRE S
 8103120751 Comments on proposed rules 100FR30-32,70 & 190 re-
possession.usp & transfer of low enriched V as contaminant
    in metals Opposes rules.
                    Affiliation Unknown. 45FR70874 2395 80/12/09 1p
 3103120755 Comments on proposed rules 10CFR30.32.70 & 150 re
possession.use & transfer of tow enriched V as contaminant
in metals Daposes rules
    GOLDMAN.L A Affiliation Unknown, 45FR70874 2394 80/12/09 1p
 8103120759 Comments on proposed rules 100FR30-32-70 & 180 re
possession.use & transfer of low enriched U as contaminant
   in metals. Opposes rules

- Affiliation Unknown 45FR70874 2393 80/12/09. ip
8103/20764 Comments on proposed rules 100FR30.32.70 & 190 re
possession, use 4 transfer of low enriched U as contaminant
    in metals Opposes rules
   MCCARTHY. X. Affiliation Unknown 45FR70874 2392. 80/12/09. 1p.
```

8103120767 Comments on proposed rules 100FR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant

8103120771 Comments on proposed rules 100FR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in retals.Doposes rules. • Affiliation Unknown 49F870874 2416. 80/12/09. ip.

Affiliation Unknown 45FR70874 2415. 80/12/09. 1p.

metals Opposes rules

REROQUIST M.

- 8:03120773 Comments on proposed rules 10CFR30.32.70 & 150 r ovusieurs comments on proposed rules IOCFR30.32.70 & 150 r possession.use & transfer of low enriched U as contaminan in metals Opposes rules BCMSER. J B Affiliation Unknown. 45FR70974 2420 B0/12 8103120778 Cornents or proposed rules 10CFR30, 32, 70 & 150 r possession.use & transfer of low enriched U as contaminan in metals Opposes rules
  FACIN, M. Affiliation Unknown 45FR70874 2419 80/12/09 B103120781 Comments on proposed rules 100FR30.32.70 & 150 r possession, use & transfer of low enriched U as contaminan in metals Opposes rules.

  AVILA, II Affiliation Uninown 49FR70874 2425. 80/12/09 810312078B Comments on proposed rules IOCFR30.32.70 & 150 r possession use & transfer of low enriched U as contaminan en metals Opposes rules STARREY-E Affiliation Unknown. 45FR70B74 2424 80/12/ B103120795 Comments on proposed rules 10CFR30,32,70 & 190 r possession.use & transfer of low enriched U as contaminan in metals Opposes rules BARGES, B Affiliation Unknown 45FR70874 2423 80/12/0 8103120800 Comments on proposed rules 100FR30.32.70 & 150 r possession, use & transfer of low enriched U as contaminan in metals. Opposes rules BCGEN, M. Affiliation Unknown. 48FR70874 2359. BO/12/09 8103120804 Comments on proposed rules 10CFR30.32,70 & 150 r possession, use & transfer of low enriched U as contaminan in metals Opposes rules. FOX.M W Affiliation Unknown. 45FR70874 2360 80/12/09 B103120005 Corments on proposed rules 10CFR30, 32, 70 & 150 r possession, use & transfer of low enriched U as contaminan in natals Opposes rules GUINNELL, M.L. Affiliation Unknown 45FR70874 2361. 80/
  - 8103120809 Comments on proposed tules 10CFR30.32,70 & 150 r possession.use & transfer of low enriched U as contaminan in metals Opposes rules
    REISINGER. D. C. Affiliation Unknown 45FR70874 2362 80 8103120813 Corrents on proposed rules 10CFR30.32,70 & 150 r possession.use & transfer of low enriched U as contaminan in metals. Opposes rules # Affiliation Unknown 45FR70B74 2363 B0/12/09 ip
  - 8103120818 Comments on proposed rules 100FR30.32.70 & 150 r possession.use & transfer of low enricked U as contaminan in metals. Opposes rules Affiliation Unknown. 45FR70874 2364. 80/1 WILKINSON, K
  - 8103160201 Staff requirements memo re 810305 Affirmation Be Directs FR publication of relemekings re therapeutic treatment of cardiac dysfunction by I-131 & environ radiation protection stds CHILK.S J Office of the Secretary of the Commission. M BI/O3/O6 3pp 07918 321
  - 8103160349 Comments on proposed policy statement re criteri evaluation of Agreement States radiation control program. YOUNG R E Affiliation Unknown. 45FR68726 014. 80/12/1 07585, 001
  - 8103160356 Comments on proposed rule 10CFR71 requiring lice shipping nuclear wastes to provide advance notification t governors Bupports rule CARTER, J. M. , BERKLEY, D. A. Affiliation Unknown. 45FR8105 B1/01/26 1p. 07921:133.
  - 8103160372 Comments on proposed rules 10CFR71 & 73 re advan notification of radwaste shipments Notification should include specific times & routes for spent fuels & low lev TEAGLE, F H Affiliation Unknown. 45FRB1058 004. 81/01/ 07921: 132.
  - 8103160426 Comments on NUREG-0586, "Draft GEIS on Decommiss Nuclear Facilities," Nonpower research & test reactors should be mentioned in DES.
    MILLER, J. R. Standardizatio Standardization & Special Projects Branch. 2pp 07916:194

- 8103160496 Comments by MS X-Rey Svt on proposed Full 10CFR7) reladvance notification of radwaste shipments Regulations should be controlled by individual states. RUSBELL-M. Affiliation Unknown. 45FRB1058-006 B1/01/26 Ic 07921-121
- B103160309 Comments on proposed rule 10CFR71 re advance natification to states of transportation of nuclear waste Rule should be rewritten to exclude radiographic sources except when being transported in Type B packages CLARK-E T Tech/Ops (Technical Operations, Inc.) 49FRB1050 008 B1/02/09. 1p. 07921 119
- BiO3160520 Comments on proposed rule 10CFR73 re shipments of raduaste Notifications should include specific times & routes for spent fuel & low level waste Regulations should not restrict Governor from notifying local authorities.

  TARANDHSKI, D.O. Affiliation Unbingum. 49FR81060-006 B1/02/02 ip
- B103160532 Comments on proposed rule 10CFR73 re shipments of raduaste across state. Notification should include specific time & routes for spent fuel 8 low lovel waste Regulations should not restrict Oovernor from notifying local authorities LEBEAU. O Affiliation Unknown. 45FRB1060 008 B1/02/06 1p 95224 047
- B103160545 Comments on proposed rule 10CFR73 re shipments of spent nuclear fuel or radwaste Governor should be notified in advance when shipments of spent fuel or radwaste will be transported through state.

  WILKEN,E 8 , WILKEN,8 E Affiliation Unknown 45FRB1060 C09 B1/02/05 1p 95224 046
- B103160974 Transcript of B10227 Affirmation/Discussion Session BI-B in Washington. DC Pp 1-3
   Commissioners B1/02/27 Bpp
- --BiO3160395 BECY-Bi-0778

  Forwards Ofc of Palicy Evaluation BiO219 meno re preparation of negative declaration & ETS in support of proposed final rule to amend iOCFR2O re radwaste disposal Radiological impact analysis was misinterpreted Action is uncarranted DIRCRS W J Diffice of the Executive Director for Operations Bi/02/24. 2pp 07917.016.
- --B103160440 BECY-B1-077A

  Discusses proposed finel rule to amend IOCFR20 re disposal of tritium & C-14 Even if assessment of sewer release amend was in error by couple of orders of magnitude collective doses & health effects are still negligible DIRCKS.W J. Office of the Executive Director for Operations B1/02/20. 3pp. 07917 020
- B10318017B Unofficial transcript of B10212 meeting in Washington DC re ATMB policy Pp 1-84. - Contestoners B1/02/12 86pp 07945.07B.
- --810318018B Forwards draft EIA for proposed rule amending 10CFR90. "Domestic Licensing of Production & Utilization Facilities." re ATMS events. EIB not required DIRCKS.W.J. Defice of the Executive Director for Operations 81/02/03. 1p. 07945-166.
- --B103180196 Draft E1A for proposed rule to amend IOCFR50 re ATMS events E18 not required • NRC - No Detailed Affiliation Given. 81/02/03. 18pp 07945-167.
- --Bi03180209 Parwards revised FR notice on BECY-B0-409 re 10CFR90 emend.
  "Domestic Licensing of Production & Utilization Facilities,
  per B01209 memo about ATWB events Changes in discussion
  section included.
  DIRCKS.W.J. Diffice of the Executive Director for Operations
  B1/01/29. 41pp. 07945:185.
- 8103181082 Responds to 801210 ltr re NRC proposal to exempt Tc-99 & low enriched U from licensing & regulatory requirements as residual contamination in any smelted alloy Forwards proposed exemption & relevant info.W/o encl.

  JONES.R.J. Transportation & Product Standards Branch. 45FR70874
  81/03/13. 2pp.
- 8103190851 Orders to modify licenses to incorporate new or upgraded radiological contingency plans per 10CFR30.40 % 70 Plans will assure adequate onsite protection against & response to respond to nuclear accidents
  CUININGHAM.R. Division of Fuel Cycle & Material Bafety 81/02/11
  499p. 07964:316.

- 8:(3190326 Responds to 810120 comments on proposed rule ICCFR23 redisposal of liquid scintifiation media 3 animal carcasses lit will be forwarded to AMSS ABRAHAMIK Region 1. Philadelphia, Office of the Director 45FR67018 81/01/23 1p 07958 005
- --8103190375 Comments on proposed rule LOCFR20 re disposal of liquidintiliation media & animal carcasses Proposal is irresponsible & damperous Opposes rule.
  ZIMMER/AN.8 B Affiliation Unknown 49FR47018 340 81/01/2016 07955
- B103190385 Responds to B10121 comments on proposed rule 100FR20 redisposal of liquid scintillation media & animal cercasses. Ltr will be forwarded to MMSS ABRAHAM.k. Region I. Philadelphia. Office of the Director 45FR67018
- --8103190392 Comments on proposed rule IOCFR20 re disposal of liquing scintiliation media & animal carrasses Opposes rule
  PORTER.A.V Affiliation Unknown 45FR67018 337. 81/01/21
- B103190405 Responds to litr opposing use of radioactive strap metal consumer products NRC proposes to amend licensing requirements that have effect of inhibiting trade in metal scrap contaminated Granull amounts of two reducative matls MALGUIST-E J Energy, Dept. of. 45FR70874 81/01/12. 15
- 8103190420 Responds to 810120 comments on proposed rule 100FR20 re disposal of liquid scintillation media & animal carcasses Ltr will be forwarded to NMBS ABRAHAH.K Region 1. Philadelphia, Office of the Director 45FR67018
- --8103190428 Comments on proposed rule tOCFR20 re disposal of liquistinitilation modia & animal carcasses Opposes rule 808/868, 8 8 Aprillation Unknown 49F867018 337 81/01/20
- 8103190443 Responds to B10120 comments on proposed rule 100FR20 re disposal of liquid scintifiation media & animal carcasses Ltr will be forwarded to NMSS ABRAHAH.K. Region 1. Philadelphia. Office of the Director 45FR67018 336 B1/01/27 ip
- --8103190452 Comments on proposed rule 10CFR20 re disposal of liqu scintillation media & animal carcasses DOCKHORN.M Affiliation Unknown 45FR67018 336 81/01/20
- 8103230709 Responds to FOIA request for coments & NRC responses to comments on proposed rules 10CFR30: 32,70 & 150. FEB containing NRC responses will be provided them available. Other comments are evaluable in PDR. W/o enc. 1 10CFR7. FELTON. J M Division of Rules and Records. 49FR70974 81/03/1 lp.
- 8103230714 FOIA request for comments & NRC responses to comments or groposed rules 10CFR30.32.70 & 190 MDNICKER, J. Affiliation Unknown 002016 80/11/11. 3pp.
- 8103240005 Responds to 810120 comments on proposed rule 100FR20 re disposal of liquid stifit!lletion media & animal carcasses Ltr will be forwarded to NMSB. GRIER, BH Region 1. Philadelphia, Office of the Director 45FR67018 81/01/26 1p 07989:340
- --Bi03240012 Comments on proposed rule 10CFR20 re disposal of liqu scintillation media & animal carcasses Opposes rule VOLPE/L Affiliation Unknown 45FR67018 342. 81/01/20 ip 07989 341.
- B103240492 Comments on proposed rule 10CFR20 re radwaste disposal sever sys & proposed rules 10CFR30.32-70 & 150 re use of contaminated metals in consumer products Requests public hearings
  CLBZANSKI, M United Steelworkers of America 45FR70874 334B.
  B1/02/12 1p.
- 8103240564 Package of three comments on proposed rule 10CFR20 redisposal of liquid scintillation media & enimal carcasses into senitary water sys. Opposes rule. • Affiliation Unknown. 43FR67018. BI/02/19. 3pp. 07385-001
- 8103240566 Package of 38 comments on proposed rules tOCFR30, 32, 70 re exempting from licensing requirements low enriched U as contaminants in metals for consumer products Upposes rules. \* Affiliation Unknown. 45FR70874. 81/03/06. 32pp.

- B103240651 Sunmary of Degraded Cooling Steering Orace 810303 meeting restrategy to assure proper coordination of ARC efforts related to degraded cooling & associated rulenakings MEDEIROS. N. S. Office of Standards Development, Director 81/03/11 3pp 07482 250
- BIO3259013 Connents on proposed rule 10CFR73 reladvance notification to governors of shipments of irradiated reactor fuel 2 proposed rule 10CFR71 religious forces to states of transportation of certain nuclear vastes No comments on rules VAN CLEVE.R G. [Interior.Dept of 45FRB1038-026 BI/03/09 50pp 07997-327
- 8103250017 Comments on proposed rule 100FR73 reladvance notification to governors of shipments of irradiated reactor fuel & proposed rule 100FR71 religiosation to states of transportation of certain nuclear wastes 200BY. J.J. Pennsylvania. State of 45FR81058-013-81/02/13 lp 07796-255
- B103250025 Comments on proposed rule 100FR73 re edvance nutification to governois of shipments of irradiated reactor fuel 5 proposed rule 100FR71 re prenotification to states of transportation of certain nuclear dastes Supports rules PRELESNIK-W L Affiliation Unknown 43FR81058-003 81/01/07 Ip 07996-254
- B103250034 Corrents on proposed rule 100FR73 re advance notification to governors of shipments of irradiated reactor fuel & proposed rule 100FR71 re prerotification to states of transportation of certain nuclear wastes Supports rules CALSOVLA C Affiliation Unknown 45FRB103B 012 81/02/24 12 07985 001
- 8103250035 Comments on proposed mule 100FR73 me advance notification to covernors of shipments of irradiated reactor fuel 5 proposed rule 100FR71 me prenotification to states of transportation of centain nuclear wastes Opposes rule PARFNICO Affiliation to hincom 455PR1058 011 81/02/27 3cm
- B103250041 Contents on proposed rule 100FR73 re advance notification to governors of shipments of irradiated reactor fuel 5 proposed rule 100FR71 re prenotification to states of transportation of certain nuclear vastes
  MILLS:L M Tennesses Valley Authority 45FRB1058 023 B1/03/04.
  2pp 07976 252.
- BIO3250044 Corrents on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel 5 proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules SCRRADER D Affiliation Unknown 45FRB103B 039 BI/03/11 Lp 07585 031
- 8103250050 Comments by Rising Sun Coalition on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel by proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes RUSSECL. G. MCAUS.-470. P. SPRING. A. Affiliation Uninown 45FRB1058 014 81/02/10 2pp 07796-250
- 8103250383 Cornents on proposed rule 10CFR73 re advance notification to governors of shiprents of irradiated teactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules.

  DALIGN.J N. Virginia, State of 45FR81098-038-81/02/23 1p. 07996-248
- Bi03230037 Corrents by City of Salina, KB on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel 8 proposed rule 10CFR71 re-prenotification to states of transportation of certain nuclear wastes CEIB.D B Affiliation Unknown. 45FRB1038-016 B1/02/03. Ip 07996-247
- 8103250063 Comments on proposed rule [OCFR73 re advance notification to governors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules.

  LAMIGR D Colorado. State of 45FR81058 037. 81/02/18 1p 07996 256
- 8103250064 Comments on proposed rule tOCFR73 re advance notification to governors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules.

  HHITE.F Ariansas. State of. 45FR81058 015. 81702712 1p 07996-245.

- 0103250073 Comments on proposed rule 100FR73 re advance notification to governors of shipments of irradiated reactor fuel & proposed rule 100FR71 re prenotification to states of transportation of certain nuclear wastes Supports rules

  KINO, 3 D. New Mosico, State of, 45FR81098-036 81/02/13 1p
- Bio3236079 Comments on proposed rule 10CFR73 re advance notification of povernors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules IECR8CH.ER.E Hypminj. State of 45FR01098 035 B1/02/03 1p 07/97 324
- BiO3250084 Comments on proposed rule 100FR73 re advance notification is governors of shipments of irradiated reactor fuel & proposed rule 100FR71 re grenotification to states of transportation of certain nuclear wastes Supports rules JAMES.F. Alatama. State of 49FR8105B 034 81/02/13. 1p
- 8103290094 Comments on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rules
  HEDEMANN N Environmental Protection Agency 45FR81058 028
  BI/02/27 2pp 07997 321
- 8103250426 Comments on proposed rule 10CFR73 reladvance notification to governors of stipments of irradiated heactor fuel Opposes rule Substantial technical problems harper compliance & enforcement of rule FLOWERS FD General Electric Co. 49FR81060-030-81/03/03-2pp. 07992-258
- B103290457 Corments on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel Endorses tule GUISTE.F.C. Affiliation Unknown 45FR81040 OII GI/02/21 1p 07994-341
- 8103250460 Co-ments on proposed rule 10CFR73 re advance notification t governors of shipments of irradiated reactor fuel Endorses rule MAYB.E. Affiliation Unknown. 45FRB1060 010 B1/02/10 1p 07996-360
- 8103250464 Co-ments on proposed rule 10CFR73 re advance notification t governors of thipments of irradiated reactor fuel Endorses rule. ELLER.C S Affiliation Unknown. 45FRB1060 004 81/01/08 1p 07994 399.
- 8103250470 Comments by Nuclear Assurance Corp on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel Opposes rule Prenotification has little value for governors' of & could jeopardize security JCH/SGNA-C. R Affiliation Unknown. 45FR81060-022 81/03/05. 2pp 07996-397
- BiO325047B Comments on proposed rule 10CFR73 re advance notification t governors of shipments of irradiated reactor fuel Notification should include specific times & routes for spent fuel & lou level radwaste shipments. PENNOCK.S. Affiliation Unknown. 45FRBIO60 012 81/02/08. 1p.
- 8103250483 Forwards comments on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated reactor fuel.

  KASEEL.R.L. Ioue, State of. 45FR81060 019 B1/03/09. 1p 08022-155.
- --Bi03250490 Corments on behalf of Interagency Coordinating Council on Radiation Safety on proposed rule 100FR73 re advance notification to governors of shipments of irradiated reactor fuel Bupports rule. EVRE. J. A. CRANE.L.E. KABSEL.R L. Iowa, State of 45FR81060 Bi/02/26. 5pp. 08022 156.
- 8103230493 Comments on behalf of IL Dept of Nuclear Bafety on proposed rule 10CFR73 re advance hotification to governors of shipments of irradiated reactor fuel. Supports rule QUETAFSDN. P.F. Illinois. Btate of 45FRB1060 021. 81/03/04 ip 08000 360
- BIO3250501 Comments on proposed rule 10CFR73 re advance notification t governors of shipments of irradiated reactor fuel Supports rule. ARIYOBHI. Q R Hawaii, State of. 45FRBIO60 032, 81/02/18, 1p. 08000:359

- 8103250509 Comments on behalf of Disaster Svcs Agency on proposed rule 10CFR73 re advance notification to governors of shipments of irradiated fuel Endurses notification of Type 8 packages 8 spent fuel shipments Notification time should be changed GRIFFITH.C Ohio, State of 45FR81060 001 80/12/19 Gp; 68022 147
- 8103230518 Comments on proposed rule 10CFR71 re-prenotification to states of transportation of certain nuclear wastes Opposes rule Notifications are unnecessary & fail to accomplish intended objectives FLGMERB.F D General Electric Co. 45FRR1058 033 81/03/03 3pp 08022-144
- B103230529 Communits on proposed rule 10CFR73 re-edvance notification to governors of shipments of irrasilated reactor fuel Covernors should be empowered to refuse shipment of spent fuel rods if weather jeopardites safe passage of cargo BIDED THAM. D.P. New England Coalition on Nuclear Pollution 45FRB1060 040 B1/03/09 3pp 08002 141
- 8103250535 Comments on proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Supports rule Rule should require licensees to provide listing of routes to be used CPSTEIN.1. R Affiliation Unknown 45FR81058 002 81/01/07 1p 08001 341
- B103299941 Forwards motion for partial stay pending judicial review of final rule on fire protection Requests action on motion by B10217

  WATKINS.M. Debevoise & Liberran 45FR76602 B1/01/16 Ip 08001 311
- --8103250550 Motion for partial stay of 10CFR30. App R III G.E.& 0 pending judicial review Promulgation of fire protection rules involves serious legal questions & contains several fundamental flaws Affidavits & Certificate of Byc encl WATKINS.M Arkanses Power & Light Co WATKINS.M Boston Edison Co WATKINS.M Floride Power & Light Co B1/01/16 44pp
- 8103290542 Comments on proposed rule 10CFR71 re prenotification to status of transportation of cortain nuclear wastes Upposes rule NRC should inform Congress that shipments are not hazardous SCHENDEL.M R Myoming Mineral Corp. 45FRB1058 031 61/02/24 Jpp 08001 302
- 8103230558 Cumments on proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes Opposes rule. Rule will impose unreasonable & unbeneficial burden on industry & state govt staffs KOVACB-B Foster Wheeler Corp 45FR81050 010 81/02/ID ip 08001-360
- Bi03250567 Comments on proposed rule 10CFR71 re-prenotification to states of transportation of certain nuclear wastes Rule should specify that low specific matls are not included in definition of nuclear waste BRABBI W.A. Affiliation Unknown. 45FR8105B 018 81/02/27 2pp 08001-198
- Bi03290575 Comments on proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes. Specific clarifications should be made excluding nonirradiated low enriched U

  KAPLAN.A.L. General Electric Co., Nuclear Energy Products Div 45FRB1058 009 B1/02/17. 2pp 08001 356
- B103230581 Comments on proposed rule 10CFR71 re-prenotification to states of transportation of certain nuclear wastes. Supports ruls. ADAMBON.E Affiliation Unknown. 45FR81058-020 B1/03/05 1p-07586:001
- B103250584 Comments on proposed rule 10CFR50 releades & etds for nuclear plants Regulation should be divided into two sections one for plants under design & const & second for plants which have OL.

  DAILLE C. Dute Power Co. 49FR86500 001 81/02/06. 2pp
  07998 356
- B103280588 Comments on behalf of Dept of Nuclear Safety on proposed rule 100FR71 re-prenotification to states of transportation of certain nuclear westes. Supports rule.

  OWSTAFBON. P. F. Illinois. State of 45FR81058-021 81/03/05. lp. 07998: 355

- B:03250595 Cornents on proposed rule 100FR50 re development of integrated operational experience reporting sys Rationale is striplistic 5 overlooks idea of unique character of deficiency (EBROSKI,EL, RUBIG, Clectric Power Research Institute 46F006 B1/03/02 Opp
- 8103250596 Contents on proposed rule 1CCFR71 re-prenotification to states of transportation of contain nuclear wastes Opposes rule Local city 8 town govts should be notified re-nuclear shipments
  OET2.C. Affiliation Unknown 45FR81058-022 81/03/05 1p
  07998-354
- B103250605 Comments on proposed rule 100FR50 re codes & stds for nuclear power plants No acceptance criteria sublished in article against which to compare inspiresults Nu criteria for exempting any support from exemination established UTLEY.E.E. Carolina Power & Light Co. 45FR85500 002. 81/02/17 to. 07978 353.
- 8103250607 Comments on proposed rule 10CFR71 to prenotification to states of transportation of certain nuclear wastes Opposed rule Rule violates civil liberties ALLEN U Affiliation Unknown 45FR81058 029, 81/03/04 to 07586
- B103250612 Comments on proposed rule 100FR71 no prenotification to states of transportation of certain nuclear wastes Opposes rule Notifications must include specific details of travel PRICE.E. Affiliation Uninown. 45FR81058-032-81/03/03-12-07998-352
- B10029G620 Comments on proposed rule 10CFR71 re-prenotification to states of transportation of certain nuclear wastes. Rule should require state to ensure that achedule info is protected from unauthorized disclosure GCL03ERO. J. H. Houston Lighting & Power Cn. 45FRB1059-030 B1/03/04 2pp. 07998-34B
- 8103250644 Comments on proposed rules 10CFR2.50.70 & 73 re protects of unclassified safeguards suffo Agronmendo re-evaluation of rules Requirements can be accomplished by 10CFR2 & 7 Category 3 should be eliminated from proposed rule SORENSON R & Battelle Menorial Institute. Pacific Northwest Laboratory 45FR85457 015 81/03/05 25pp 08000 290.
- B103250691 Corments on proposed rules 10CFR2.50.70 & 73 co protects of unclassified safeguards info Extensive revision should be nade to apply only portions or name to info associated w/use of lower risk quantities & types of SNM ERLICHER General Electric Co. 45FR85459 009 B1/03/04. 3pp CB000 287
- 8103250665 Corments on proposed rules ICCFR2.30, 70 & 73 re protects of unclassified safeguards info Exclusion of guard training & qualification represents significant peakness in rule that could be exploited to detriment of plant security HITTLER L. Public Service Electric & Gas Co. of New Jersey 45FR85499 008 81/03/04 2pp. 08000 285
- 8103230672 Comments on proposed rules 10CFR2.50.70 & 73 re protecti of unclassified safeguerds info Rule should be revised to specifically exclude BNM of low strategic significance NARDI.A J Westinghouse Electric Corp 45FR85459 011 81/03/05 2pp 0799 340
- B103250687 Comments on proposed rules 10CFR2.50.70 & 73 re protecti of unclassified safeguards info Only actual limits of error associated withventory differences value for any given inventory period will be of interest KAPLAN.A.L. Owneral Electric Co. Nuclear Energy Products Div 45FRB5459 012 B1/03/05 9pp 07999 352
- B103250672 Comments on proposed rules 10CFR2.50, 70 & 73 re protecti of unclassified safeguards info.Rule should be revised to specifically exclude SMM of low strategic significance NARDI.A J. Westinghouse Electric Corp. 45FR85497 011. 81/03/05 2pp. 07998 350
- 8103290687 Comments on proposed rules 10CFN2.50,70 % 73 re protects of unclassified safeguerds info Only actual limits of error associated withventory differences value for any given inventory period will be of interest KAPLAN.A L. General Electric Co., Muclear Energy Products Div 45FR85459 012 Bi/03/05 9pp 07999-352
- 8103290672 Comments on proposed rules 10CFR2-50, 70 & 73 re protecti of unclassified safeguards info. Rule should be revised to specifically exclude BMM of low strategic significance. NARDLA J. Westinghouse Electric Corp. 45FRS5459 011 81/03/05 2pp. 07998 360.

- 8103230697 Comments on proposed rules 10CFR2-50-70 & 73 re-protection of unclassified safeguards info. Only actual limits of error associated winventory differences value for any given inventory period will be of interest.

  KAPLANA L. General Electric Co. Nuclear Energy Products Div 45FRB3459 012 81/03/05 9pp 07999 352
- B103290672 Comments on proposed rules 100FR2.50.70 & 73 re protection of unclassifies safeguards info Rule should be revised to specifically exclude SMF of low strategic significance MARDLA J Westinghouse Electric Corp LA-81-25 81/03/05 2pp
- B103250687 Corments on proposed rules 10CFR2.50.70 & 73 re protection of unclassified safeguards info Only actual limits of error associated winventory differences value for any given inventory period will be of interest KAPLAN,A.1. Qeneral Electric Co. Nuclear Energy Products Div 45FR65459 012 Bi/03/05 9pp
- 8103250691 Comments on proposed rules 10CFR2.50.70 & 73 re-protection of unclassified safequard info Plant specific safequards analysis covers too broad range af data Requests clarification of composits listing requiring safequards BRADBURY.R D Stone & Hebster Engineering Corp 45FR85459 017 81703709 3p 07586 001
- 8103230894 Comments on proposed rules 10CFR2, So. 70 % 73 he protection of unclassified safeguards info Policy should be reworded to maintain consistency
  DUFF.R T Energy. Dept of 45FR85459 002 81/02/RO. 2pp
  07998 358
- 8103250698 Comments on behalf of Ofc of Atty General on proposed rules 10CFR2,50,70 & 73 re-prototion of unclassified safeguards info. Rule could create impractical sys which compromises both safeguards & safety concerns.

  MUCHNICKI, E. D. Ohio, State of, 45FRB5459 007 81/03/03 App.
- 103250709 Comments on proposed rules 10CFR2-50.70 & 73 re-protection of unclassified safeguards info. Some info restrictions fail outside scope of authorizing statute & are in violation of statutory limitations on NRC power.
  ELLIOTY-C W Thomas & Hair 45FR95459 005 81/03/03 9pp. 08922: 111
- 8103280709 Comments on proposed rules 10CFH2,50,70 & 73 re-protection of unclassified safeguards info Opposes rules Majority of info requiring protection is already covered by normal industry practices governing proprietary commercial info ZEFF.D.H. Babcock & Wilcox Co. 45FR85459 013 81/03/06, 7pp CB000 352
- B103250711 Comments on graposed rules 10CFR2,50,70 & 73 re protection of unclassified safeguards info Rule requires clarification if objectives are to be obtained.

  UTLEY, E. E. Carolina Power & Light Co. 45FRB5459 006. B1/03/03. 3pp. 08000.349.
- B103250713 Comments on proposed rules 10CFR2.50.70 & 73 re-protection of unclassified safeguards info Opposes rule Rule will place significant burden on licensees possessing mat1 of low strategic significance MILBON.R. Excon Nuclear Co. Inc. (subs. of Excon Corp.). 45FR85459-014 81/03/06 3pp. 08000-346.
- 8100250720 Cornents by Nuclear Assurance Corp on proposed rule 10CFR2, 50, 70 & 73 re protection of unclassified safeguards info Requests withholding from disclosure of route info under 10CFR2, 790(d) until shipments using route are completed JOHNBON, C. R. Affiliation Unknown 45FR85459 004. 81/03/03. 2pp 08000:342
- BI03250726 Comments on proposed rules 10CFR2, 50.70 % 73 re-grotection of unclassified safeguards info Rule should be less inclusive & burdensome Scope is far broader than necessary. CLEMENTS, B. R. Texas Utilities Generating Co. 45FR85499 003. BI/03/03 IIpp. 08000:331
- 8103230732 Comments on proposed rules 10CFR2, 50, 70 & 73 re-protection of unclassified safeguards info. Rules provide insufficient protection against disclosures in licensing while establishing overly restrictive handling of info by utils KNUTH. D. F. Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp.) 45FR85459 016 81/03/06 8pp. 08000:323

- BIO3250726 Comments on proposed rules 10CFR71 re notification to sta of waste shippents 10CFR/3 re advance notification to governor re irradiated reactor fuel shipments & 10CFR2-50-70 & 73 re unclassified safeguards info protection RILEY.R & Gouth Carolina. State of 45FR81060-027 B1/03/06. 2pp. 08300-321
- B103250755 Comments on proposed rule 10CFR73 re advance notification governors of shipments of irradiated reactor fuel t proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes.

  BADCER.C.H. Georgia. State of 45FRB1058-024 B1/03/02 ip ORDOO 317
- B103250796 Cornents on proposed rules 10CFR2, 50.70 & 70 re protectio of unclassified safeguards info. Opposes rules. Prohibiting other than licensees to heve access to info will inhibit constructive comments from public UABBERRACH. A E Affiliation Unknown 45FRB5459 001 B1/02/18 08000 316
- B103250759 Comments on proposed rule 10CFR73 re advance notification governors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes

  WERS.S. Energy, Dept. of 45FR81058 040 81/03/06 8pp
- 8103240033 Comments on proposed rule 10CFR73 re advance notification governors of shipments of irradiated reactor fuel & proposed rule 10CFR71 re prenotification to states of transportation of certain nuclear wastes
  BDUCHEY, 0 D Washington Public Power Supply System 45FRB1058 02
  81/03/04 3pc
- 8103260189 Comments on proposed rule 100FR61 re low level waste disposal site Requests NRC waste classification study Low level waste should be Sefined in terms of vol & Ci.
  LEWIG.M I Affiliation Unknown. 45FR13104 003.
- 8103260199 Forwards comments on proposed rule 10CFR2 re-policy & procedure for enforcement actions Policy is unfair & inequitable.
  MCGAUGHY.J P. Mississippi Power & Light Co. 45FR66754-147.
  B1/01/09 18pp. 08040-087
- B103260210 Forwards comments on proposed rule 10CFR2 re-policy & procedure for enforcement actions Policy is needlessly punitive particularly as applied to milling segment of U fuel cycle
  B3096.L A American Mining Congress. 45FR66794-136. B1/02/12. 12ap. 08040-075
- 8103260222 Comments on proposed rule 100FR2 re-policy & procedure fo enforcement actions Requests, under FOIA, cost-benefit analysis supporting policy & procedure, Civil penalties will force univs to shut down reactors. MUNNOLF, J. Affiliation Unknown. 45FR66754 157 81/02/29. 3pp. 08040.161.
- 8103260233 Comments on proposed rule 10CFR2 re-policy & procedure for enforcement action Proposed fine for research reactor violations should be deleted from policy.

  RECKLEY.W American Nuclear Boriety 43FR66784-138. 81/02/24.

  Zpp. 08040-159
- B103260245 Comments on proposed rule 10CFR50 re degraded or melted cores in safety requiation Probabilistic analysis should be promptly implemented for all future safety considerations, including degraded 5 meltad cores.

  HDFFMAN.D.P. Consumers Power Co. 45FR65474 049 B1/02/09. 2pp. 08040:157.
- B103260256 Comments on proposed rule 10CFR50 rs degraded coreconsiderations, Imposition of single failure criterion on vents is both unwarranted & unnecessarily conservative. HOFFMAN, D.P. Consumers Power Co. 45FR65466
- 8103260271 Comments on proposed rule 10CFR30 re development of integrated operational experience reporting sys Rule will require significant increase in license management for negligible improvement to reporting sys effectiveness. DALTROFF, B L. Philadelphia Electric Co. 46FR3541 007. 81/03/02.3pp. 08040:152
- B303260283 Comments on proposed rule 10CFR50 re development of integrated operational experience reporting sys. Industry should be involved in entire developmental process Bys value will be optimized by considering reporting requirements. PARKER.M. 0 Duke Power Ca. 46FR3541 00B. 81/03/02. 2pp. 08040:150.

- Bi03260295 Comments on proposed rule 10CFR50 re development of integrated operational experience reporting sys.NRC findings are inaccurate & misleading. Variation of scope does not render statistical data base useless Opposes rule HAUETER.R L American Nuclear Society 46FR3941 010 Bi/03/05 3pp 08040 147
- 8103260315 Comments on proposed rule 10CFR73 re advance notification to governors re shipments of irradiated reactor fuel Deregulation of low-level raduaste & transportation of waste impinges on civil rights.

  JOSEPH.L.J. Affiliation Uninown. 45FR81060 029 81/03/06 1p 08040 146
- B109260326 Comments on proposed rule 10CFR73 re advance notification to governors re shipments of irradiated reactor fuel. Rule is unnecessary & will interfere w/safe & expeditious movement of spent fuel.

  GDLDBER0.J H Houston Lighting & Power Co. 8T-HL-AE-630. B1/03/04 Ip 08040-145.
- B103260618 Forwards USGS comments on working group rept & ACRB statement re proposed relemaking on storage & disposel of nuclear waste FREDERICK.D O Interior.Dept.of, Geological Survey. 81/03/07 lp 08035-317
- --Bi03260629 Comments on working group rept & ACR8 statement re rulemaking on storage & disposal of nuclear wasts Rept is accurate summary of record & delineates technical issues Commission must address e Interior Dept of Geological Survey. 81/03/04 7pp 08033 318
- B103260812 Notice of P Heish withdrawal of appearance in proceeding & substitution of CA Binderbrand for State of HI. BINDERBRAND.C. Wisconsin, State of B1/03/17, 1p. 08036-207
- --8103260820 Comments on working group rept & ACRB 801210 itr re waste confidence rulemaking Categorization of issues is adequate but phraseology has serious deficiencies. H/Certificate of 8vc.
  81M0ERBRAND.C., LA FOLLETIE.8. Hisconsin, State of. 81/03/17.
  15pp. 08036-208.
- 8103260859 Forwards NRDC comments on working group rept re waste confidence rulemaking. Requests secretary serve copies on all other full perticipants
  WEISS.E R. Harmon & Weiss. 81/03/03 1p. 08036.236
- --B103260867 Response to working group rept on waste confidence rulemating. Appropriate emphasis not given to need for Commission resolution of whether one theoretical route to geological disposal is possible. M/Certificate of 8vc. WEISS.E.R. COCHRAN.T., YUAN.O. Natural Resources Defense Council. B1/03/03 29pp. 08036:257.
- 8103261004 FOIA request for cost-benefit analysis in support of neupolicy & procedures for enforcement actions. Also comments on proposed rule 100FR2 re-general statement of policy & procedure for enforcement actions. MNNNO.F. J. Affiliation Unknown. 43FR66754 187. 81/03/01 3pp 08036:320.
- B103261190 Responds to B10205 request for delay of issuence of 100FR60 re licensing procedures for radwaste disposal until policy changes made by current administration. Delay in issuing rule could slow nat! waste program development. #ENDRIE: J. M. Commissioners. B1/03/13. 2pp. 08040: 237.
- --8103261199 Responds to 810205 request for delay of issuence of 10CFR60 re licensing procedures for radwests disposal until policy changes made by current administration Delay in issuing rule could slow nat! weste program development.

  HENDRIE: J. M. Commissioners. B1/03/13. 2pp. 08040: 239.
- --8103261204 Urgss NRC to postpone final action on proposed rule re redwatte disposal until administration fully appraises NRC nuclear policy intentions Discusses President Reagen 810129 directive-NRC conformence & financial constraints. 80UQUARD-N.L., LUJAN-M. House of Rep., Brience & Technology. 81702705. 2pp. 08040:241.
- BiO3270126 Comments on proposed rules 100FR30.32.70 & 150 repossession use & transfer of low enriched U as contaminent in metals. Deposes rule.
  BEODERMAN. A. Affiliation Unknown. 45FR70874 3359. 81/02/03. ip.
- 8103270139 Forwards comments by constituents on proposed rules 10CFR30. 32.70 % 150 re-passession, use % transfer of low enriched U as contaminant in metals. BPECTERIA. Benate. 45FR70874-3358. 81/02/27. 4pp.

- 8103270156 Comments on proposed rules 100FR30,32,70 & 150 re possession.use & transfer of low enriched U as contaminant in metals Opposes rule INSLEE,N W Affiliation Unknown 45FR70874 3354 81/02/08
  - 8103270167 Comments on proposed rules 10CFR30.32.70 & 150 repossession.use & transfer of low enriched V as contaminant in metals Opposes rule
    TEELINO.M O Komen's International League for Peace & Freedom
    45FR70874 3352 B1/01/26 Ip
  - 8103270180 Comments on proposed rules 100FR30, 32,70 & 190 representation use & transfer of low enriched U as contaminant in metals. Opposes rule.

    THOMASID. United Steelworkers of America 45FR70874 3387.
    81/02/13. is
  - 8103270196 Ack receipt of enci comments on proposed rules 100FR30,: & 190 re-possession.use & transfer of low enriched U as contaminant in metals. Comment will be forwarded to NRC in Washington W/o enci FR notice STRASMALU Region 3. Chicago, Office of the Director. 49FR70R743360 81702/20 1p.
  - --8103270203 Comments on proposed rules 100FR30.32.70 & 153 re possession.use & transfer of low enriched U es contaminant in metals Opposes rule. BEEDERMAN.C. Affillation Unknown 45FR70874 3360 81/02/11
- B103270244 Corrents by Citizens of Bonoma County.CA.on proposed rul 10CfR30.32.70 & 150 re possession.use & transfer of low enriched U as conteninant in metals Opposes rule BERNEL.V K Affiliation Unknown 45FR70874 80/12/20. ip
- 9103270293 Comments by CH Cititiens for Responsible Energy on NREG-0596. "Draft Generic ElS on Decemissioning of Nuclear Facilities." Rept contains contradictions re-entombrant viability & required times
  ALEXANDER, J. Affiliation Uninoum 46FR11666—81703/16. 10
- B103270240 Cumments on proposed rules 100FR30,32,70 & 190 repossession.use & transfer of low enriched U as contaminant in metals Supports rule
- 8103300001 Cornents on proposed rule 10CFR30 re integrated operation experience reporting sys Rule is neither destrable nor

FREMLING. A C. Energy, Dept of 49FR70874 3346 81/02/13 39p

- stportone reporting sys hose is neither destrable nor justifiable MAREMBOURG, D. Public Service Co. of Colorado 46FR3941 004 81/02/25. 2pp 08057-121
- 810330002 Corments, on behalf of Salina, KB VWCA, on proposed rule 10CFR71 he advance state notification of certain nuclear waste trenportation & 10CFR73 he advance notification to governors he shipments of Irradiated reactor fuel STANL-M Affiliation Unknown. 45FR81039 017 81/02/10, ip 08035:361
- B10330005 Comments on proposed rule 10CFRSD re-integrated operation experience reporting sys Opposed to rule due to high initial & long-term expenses & potential for uncontrolled growth of sys w/minimal benefits to industry.

  BOUCHEY. 0 D. Washington Public Power Supply System. 4AFR3541 OD 81/03/10 2pp. 08059:359
- 9103300007 Comments on proposed rule 10CFR71 re advance notification states of transportation of certain types of nuclear waste Commission should reword proposed definition of raduaste to apply only to matis being transported after fuel cycle MCMUNN-J 8. Homesteke Mining Co. 45FR91058 001 81/01/08 1p. 08055 357
- 8103300009 Comments on proposed rule 10EFR30 re integrated operation experience reporting sys. Rule should provide for involvement of Inst of Nuclear Power Operations. Nuclear Bafety Analysis Ctr or englusti organization.

  MCDONALD.R.P. Alabama Power Co. 46FR3541 00B. 81/03/05. 1p. 08035, 358
- 8103300014 Commants on proposed rules 10CFR2,19,20,21,30,40,50,51,670 re disposal of high level radwaste in geologic repositories.

  80U0UARO.M.L. LUJAN.M. House of Rep., Science & Technology, 46FR13971 001. 81/02/05. 2pp 08055:355.
- Bi03300020 Comments on proposed rule 10CFR50 re integrated operation experience reporting sys. Schedule for implementation should be proposed wieech significant step stated. Comprehensive cost/benefit analysis should be included. FAY.C M. Misconsin Electric Power Co. 46FR3541 003. Bi/03/02. 2pp. 08035-354

- G:03303042 Comments on proposed rules ICCFR71 reladvance notification to states of transportation of certain types of nuclear usste & 100FR73 reladvance notification to governors relationshipments of irradiate: reactor fuel REVICEUS.U. American Friends Service Conmittee ASFR81058-019-81/03/03-3-25-08055-351
- Ej03300131 Responds to the expressing concern to proposed changes in radwaste disposal regulations at medical facilities Litr will be sent to 1/20 in Washington. DC for late coment consideration W/o Picl 831038 FR notice SIRASMA. J. Region J. Chicago. Office of the Director B1/02/20 Ip 08/35 349
- B103300145 Co-ments on proposed rule 10CFR50. Apps Q & H Revised definition of Beligine natl is unclear Requirement to use edition of E185 in effect on date of capsole withdrawal requirement of Specific edition to be used should be cited FERGUSDN. J Wingshia Electric & Power Co. 45FR75536 013 B1/02/13 2pp. 08035 301
- B103300152 Forwards comments on behalf of VT Agency of Environ Conservation on proposed rules SOCFR50.51 & 100 re notice of intent to prepare EIS for revision of regulations governing siting of nuclear paper plants
  NEARY.E. Vernant. State of 45FR79820 010 B1/01/12 2pp 08055 035

## PRM PETITION FOR RULEMAKING

- G103050821 Notice of publication for public connent of Sierra Club B01203 petition for rulerating 40-23 re-possession of U Hill tailings at inactive storage sites CH(LK.S.J. Office of the Secretary of the Commission B1/02/19 3pp 07025-072
- --Bi03050926 Petition for repeal of licensing executions re-certain inactive U milling sites & for regulation of bygroduct metls in vicinity
  BEERS.R. DICASCRI.K B Sierre Club. BEERB.R. Beers.R. B0/12/01
  25pp 07925-075
- JiOJO60483 Forwards notice of petition for rulemaking 30-57 re amend of exemption for ionizing radiation measuring instruments. Proposed rule 10CFR30 results from petition for rulemaking 30-57 SHITM: R O Diffice of Standards Development, Director 81/02/23 3pp 07836 056
- --BIO3060489 Notice of proposed rule 10CFR30 re amend of elemption for ionizing radiation measuring instruments. DIRCKS.W J Office of the Elecutive Director for Operations BI/O2/17 9pp 07835 060
- B103100298 Comments on petition for rulemaking 50-29 re ATHS Supports petition NRC should prompligate definitive ATHS regulation. DELOEDROG. L. O. Commonwealth Edison Co. 45FR73080 016. 81/02/02 19 97853.197
- 8103180178 Unofficial transcript of 810212 meeting in Washington, DC re ATK8 policy Pp 1-84 • Commissioners 81/02/12 86pp. 07945 078
- --BIO3180188 Forwards draft EIA for proposed rule amending 10CFR50. "Domestic Licensing of Production & Utilization Facilities." re ATMS events EIS not required DIRCMS.M. J. Office of the Executive Director for Operations 81/02/03 1p 07945 166
- --8103180196 Draft EIA for proposed rule to amend 10CFR50 re ATKS events EIS not required • NRC - No Detailed Affiliation Given. B1/02/03. 18pp
- --Bio3180209 Forwards revised FR notice on SECY-80-409 re 10CFR50 amend.
  "Domestic Licensing of Production & Utilization Facilities, per 801209 meno about ATMS events Changes in discussion section included DIRCKS.H. J. Office of the Elecutive Director for Operations 81/01/29. Alsp. 07943-185

- -- 8103180224 Comments on NRC evaluation of proposed ATMS rule per 601219 reno Proposed cute should be published recogniting limited interim rule aption to deal w/patential for ATMS occurrence in BURS w/Mark I & II containments MILOUGH 8 Office of Nuclear Regulatory Research. Director 81/01/28 2pp 07945 226
- --9100180235 Presents summary of findings re ATMS calculations per 801 request Detailed presentation of Sys & Reliability Research Div review of ATMS calculations encl MINDOUE.R 8 Diffice of Nuclear Regulatory Research. Director 860/12/19 206 07745 228
- --BIO3180248 Submits detailed surrary of review & comment re ATES calculations per 801110 request Viewgraphs encl ROMADME.F H Diffice of Nuclear Regulatory Research. Director 80/12/15 App 07943-230

## PROJ PROJECTS - PREDOCKET LICENSING

- 8103050712 Dept of Mater Resources request for extension until 810311 to file answers to NRC & util joint motion to suspend discovery & notion activity. Neither party objects to extension STRUMMASSER, M. California, State of ISBUANCES A. 81/02/25 2pp.07821-745
- 8103050735 Order granting extension until 810311 for CA Dept of Water Resources 5 other intervenors to file answers to joint motion of util 5 NRC to suspend discovery Good cause ofnen &
- no objection node by parties
  no objection node by parties
  MILLER.M E Atomic Safety and Licensing Sourd Panel (BBUANCES A
  S1/03/03 1p 07828 048
- 8103090836 Forwards AR Boil & Mater Conservation Commission comments of E16-0271. final generic statement on U cilling 180788.9 J. Artansas. State of 16477 B1/01/13. 2pp. 07825 122
- 8103110462 Forwards "Modified Plans for Completing FFIF Natural Circulation Test Program" & "Pretest Predictions for FFIF Reactor Sys Transient Natural Circulation Test from 79% Power : Repts available in Central Files only CARLIBLE.C & Energy, Dapt of 81/03/06 ip 07857:078
- 8103130346 Answer opposing applicant & NRC joint motion to suspend discovery & motion activity Conference should be convened to establish firm dates for conclusion of discovery & commencement of hearings Certificate of Svc encl.

  MCD14RMID.R.C., DAVIDSON.D ! Morthern California Power Agency-California State of. STREBEL.S J Anaheim, CA ISBUANCES A B1/02/11 55pp. 07907 198
- 8103130401 Response in apposition to Northern CA Pawer Agency request for protective order to prevent timely taking of previously noticed & scheduled depositions. Depositions would complete winding-up process Certificate of Svc encl
  FALLIN. J. P. Pecific Ges & Electric Co. ISSUANCES A. B1/03/03
  App. 0791: 194
- BIOGIGO617 Forwards BW Bhackelford affidavit in lieu of deposition FALLIN. Jr. Pacific Gas & Electric Co IBSUANCES A 81/03/02 ip 07913 191
- --8103130621 Affidavit re coordination of Stanislaus plans w/util over resource plan. Requirement for CP would arise in 1989. BHACKELFGRD. B Pacific Gas & Electric Co ISBUANCES A B1/03/02 30p 07913.192.
- --BI03130624 Response to CA Dept of Water Resources Fifth set of interrogetories Response includes info re document storage & production & document numbering sys.Certificate of Bvc encl FALLIN.J F. Pacific Oas & Electric Co. IBSUANCES A. BI/03/02.16pp. 07913:195.
- BIO3190037 Reply to util BIO310 response to Northern CA Power Agency BIO319 motion to compel production of documents withheld by util. Util makes misstatements of fact & has no legitimate basis for withhelding documents. Certificate of Svc encl. ADRAGNA. J M. California, State of. ADRAGNA. J M. Episgel & McDiermid. ISSUANCES A. BI/O3/17. Spp. 07964:165.
- 8103200062 Answer opposing util & NRC joint motion to suspend discover & motion activity No grounds shown for suspension of proceeding. Buspension would obstruct NRC discharge of statutory duties. Portions of transcript encl.
  STRUMWABSER.M. Dept. of Water Resources. California, State of., ISSUANCES A. 81/03/11, 48pp. 07972:279.

- --8103200073 Discusses dacument production requested by intervenors & NRC on 800912 Document production from noncentral aft files of generation planning dept & transmission planning dept to tegin shortly Certificate of Svc encl MEISSR L Pacific Ges & Electric Co ISSUANCES A 80/08/26 12pp 0.7972 356
- 8103200726 Discusses util unilateral termination of processing documents for production Util must immediately resume document production & continue until legal obligation to do so is relieved STRUMHASSER. M. California. State of. IBSUANCES M. 81/03/06 7pp. 07947, 316.
- B103230439 Notice of 810303-06 conference w/counsel for parties in Bethesda-MD re POKE & NRC 810213 juint motion. Northern CA Power Agency 810219 & 19 motions & State of CA Dept of Water Resources 810306 ltr to util MILLER-M E Atomic 8afety and Licensing Board Panel ISBUANCES A 81/03/20 2pp. 07975 361.
- BIO3260872 Response opposing Northern CA Power Agency 910219 motion to compel production of documents withheld by util. Notion is wasteful & designed to cover refusel to proceed w/scheduled depositions

  #E188.R.L. DOYLE, M.M. Pacific Oas & Electric Co DOYLE, M.M. McCutchen. Doule. Brown & Emersen. ISSUANCES A 81/03/10 4pp

  08034-093
- --BI03260877 Requests parties enter into encl stipulation re good faith negotiations u/Northern CA Power Agency If stipulation not signed util will present evidence responding to allegations of unreasonableness of util contuct. W/Certificate of 8vc 00LUS.H.V. Pacific Gas & Electric Co 01/01/14 7pp 08036.297

PT9 10CFR, PART 9 -

- B002120122 Forwards IE investigation rept of License 39-17178-01 on 791219 & notice of violation BROWN, G.D. Region 4. Dallas, Fuel Facility & Materials Safety Branch B0/01/14 2pp 02381:071.
- --B002120126 Notice of violation from insp on 791219.

   Region 4. Dalles. Office of the Director. B0/01/14 ip 02381.073
- --9002120103 IE investigation rept of License 33-17178-01 on 791219
  Noncompliance noted individual overexposed to radiation &
  unauthorized street address
  BROUN.O D. Region 4. Dallas, Fuel Facility & Materials Safety
  Branch. CAIN.C.L. Region 4. Dallas, Office of the Director
  B0/01/14. 4pp. 02381:074
- BiO3310708 PNG-I-Bi-O37 on BiO321,69-yr-old woman received 8 mCi 1-131 therapy when mistaken for another patient Caused by mistaken identity. Attending physician notifical Media interest not exected.

  COSTELLO, F., KINNEMAN, J., JOYNER, J. Region 1, Philadelphia, Office of the Birector. Bi/O3/25. 1p. 08075:097.
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8102250645 Part 21 rept rs failure of electrical cable supplied by Rockbestos Co. initially reported 810126. Cable use in actuators discontinued. Marked-up rept & external ltr encl. COLBY. J. P. Rotork Controls, Inc. 81/01/27, 16pp. 07746: 123.
- B102270563 Part 21 rept re apparent insulation failure of Rockbestos Firewall III control cable, initially reported B10127. Testa Indicate that conductor had exploded through insulation, causing short Mati not dependable after LOCA. BLYTHE.R.T. Rotork Controls, Inc. B1/01/30. 3pp

GA999 GUALITY ASSURANCE INSPECTIONS

- Bi03031139 Ack receipt of B01120 ltr requesting option to rementer nuclear fastener industry at our discretion. POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch. B1/01/21. ip. 07B08:206.
- \*\*-BIO3031144 Responds to NRC 801029 ltr re OA Program Insp Rept 99900719/80-01. Requests option to re-enter nuclear fastner industry at our discretion. LYNCH. J. A. Coast Industrial Bupply Co. 80/11/20 lp. 07808:207.

- --8103031147 Forwards QA Program Insp Rept 99900719780-01 on 800904-07 No moncompliance noted PQTAPDVS. U Region A. Dallas. Vendor Inspection Branch 80/10/29 2pp 07808 208
- --B1G3O3115t GA Program Insp Rept 99900719/B0-01 on B00B04-07 No honcompliance noted Major areas inspected implementation of IOCFR90. App B & applicable codes & atds including QA program review. Procurement document control & program deficiencies KELLEY. W D . WHITESECL. D E Region 4. Dallas. Vendor Inspection Branch 80/09/25 9pp 07808 210
- 8103040136 Ack receipt of 810106 ftr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 97900901/80-01 POTAPQUS.U Region 4. Dallas. Vendor Inspection Branch 81/01/14
- POTAPOVS.V Region 4. Dallas. Vendor Inspection Branch B1/01/14 1p. 07820.051
- --B193040145 Modifies B01209 response to NRC B01105 ltr re deviations noted in GA Program Insp Rept 99900501/B0-01 Deficiencies noted in interface control logs will be corrected by B10331 HAML.H A Bechtel Power Corp (subs of Bechtel Corp.) B1/01/06 [p. 07820.052]
- --8103040153 Act receipt of 801125 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 9790501/80-01 POTAPONS.U Region 4. Dallas. Vendor Inspection Branch 80/12/09 to 07820 056
- --Bi03040160 Responds to NRC 801105 ltr re deviations noted in 0A Progra Insp Rept 99900501/80-01 Corrective actions revised (high rept to reflect numerical clarification of info provided during insp MAHL.H W Bethtel Power Corp (subs of Dechtel Corp.) 60/11/25 200 07820 057.
- 8103040189 A() receipt of 801216 & 810120 itra informing ARC of staps taken to correct deviations 5 violation noted in GA Program Insp Rept 99700302/80-03 POTAPCVS.V Region 4. Dallas. Vendor Inspection Branch 81/01/27 ip 97813 077
- --BIOGO40212 Responds to NRC BIOIOB itr request for addl info re QA Program Insp Rept 99903502/80-03 Corrective actions GA personnel assigned to review manuals for procedures w/non-unique identification & superseded documents RICC.W M Brown & Rost Corp (subs of Helliburton Corp ) BI/01/20 4pp 07813 078
- --BI-03040926 Act receipt of B01216 ltr informing NRC of steps taken to correct deviation noted in GA Program Inep Rept 979000027/B0-03 Add1 info requested re Deviation D POTAPDVS.U. Region 4- Delias. Vendor Inspection Branch 81/01/08 to 07813-082
- --B103040247 Responds to NRC 801120 ltr re deviations & violation nated in OA Program Insp Rept 9990302780-03 Corrective actions revising all South TX 0A procedures including restructuring of OA program numbering sys by 810430 BROOM.K M Brown X Roat Corp. (subs of Halliburton Corp.) B0/12/16. 6pp. 07813-083
- --8103040254 Forwards GA Program Insp Rept 99700302/80-03 on 800929-1003. notice of deviation 5 notice of violation POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 80/11/20 2pp. 07813.098.
- --Bi03040269 Notice of violation from insp on B00929-1003.

  \* Region 4. Dallas. Vendor Inspection Branch. B0/11/21 ip 0/813.091
- --BIO3040277 Notice of deviation from insp on 800929-1003

  \* Region 4. Dellas, Vendor Inspection Branch. 80/11/21 2pp
  07813-092
- --8103040290 GA Program (nsp Rept 99900502/80-03 on 800929-1003 Noncompliance noted superseded GA procedure pages not destroyed, stamped void or superseded by recipients. FOX.D.F., BREAUX.D.G., HALE, C.J. Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/11/21 17pp 0/813.094
- 8103100708 Ack receipt of 810202 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rapt 97900507/80-04.

  SEYPRIT. K V. Region 4 Dallas. Office of the Director. 81/02/25. Ip. 07862 194

- ------IUSIOU/IS Responds to ARC BUISTS ITT TO deviation noted in UA Insp Rept 99900509/80-04 Disagrees w/inspectors finding that unqualified individual was involved w/04 program PASLAM.E.F. Stone & Webster Engineering Corp. 81/02/02 lp W(L1 - / 1 A | F F F 81/02/02 lo
- 8103100718 Ack receipt of 810211 ltr informing NRC of steps taken to rect violation & deviation noted in GA Program Inap Ropt
  - POTAPSVS. U
- --BIO3100722 Responds to NRC BIO122 ltm re violation 5 deviation noted in GA Program Insp Rept 99700399/80-01 Corrective actions required documents posted 5 new operating procedures issued to control use of continuous vulcanisation instrumentation GALKIN.1 S American Insulated Wire Corp B1/02/11. 19pp 07866 204
- --BIO3100727 Forwards QA Program Insp Rept 99900399/80-01 on B01027-30 & notices of violation & Seviation PDFAPQUS,U Region 4. Dallas, Vendor Inspection Branch 81/01/22 2pp. 07866 303
- --BiO3100733 Notice of violation from insp on 801027-30
   Region 4. Dalias. Office of the Director 81/01/19. Ip 07866 305
- --8103100737 Notice of deviation from insp on 801027-30
  \* Region 4, Dallas, Office of the Director. 81/01/19 2pp
- -8103100741 94 Program Insp Rept 99900399/80-01 on 801027-30 Noncompliance noted failure to post required documents & to establish procedures for controlling continuous vulcanizing process & wire measuring instrumentation. FOSTER.N E , BARNES. I. Region 4. Dallas. Vendor Inspection Branch FOSTER, W.E., BARNES, I. Regis 81/01/19 11pp 07866 308
- 8103100747 Forwards GA Program Insp Rept 99900401/80-03 on 801209-11 No noncompliance noted POTAPCVS.V Region 4. Dallas. Vendor Inspection Branch. 81/01/02 200 07862 197
- --8103100751 GA Program Insp Rept 99900401/80-03 on 801209-11. Major areas inspected followup on previous insp findings BRICKLEY.R H., CHAMBERLAIN.D. HALE.C J. Region 4. Dallas, Vendor Inspection Branch 80/12/31 6pp. 07862
  - 03110005 Forwards GA Program Insp Rept 99900266/80-02 on 801208-18 POTAPOVS.U. Region 4: Dallas. Vendor Inspection Branch 81/01/09 2pp. 07885, 227
- --8103110006 Notice of deviation from insp on 801208-11.

  \* Region 4. Dallas. Office of the Director 80/12/29 ip
- --810311000B QA Program Insp Rept 99900266/80-02 on 801208-11 Noncompliance noted two welders welding w/o valid qualifications

  MUNTER V H , WHITESELL D E Region 4, Dallas, Vendor Inspection Branch. 80/12/29 600. 07885; 230.
- 810311001) Forwards GA Program Insp Rept 99900269/80-01 on 801208-12 No noncompliance noted FGFRPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 81/01/20. 2pp 07883 197
- --8103110014 GA Program Imag Rept 99900265/80-01 on 801208-12 Hajor areas inspected action on previous identified insp items. GA program review, review of vendors activities & ANI interface & audits. SUTTON.J. U. GHITESELL.D. E. Region 4. Dallas, Vendor Inspection Branch. Bl/Ol/16 7pp 07885:199.
- B103110055 Ack receipt of B10210 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900509/80-06
- POTAPOVS, U Region 4. Dailas. Vendor Inspection Branch. 81/02/20 07885. 207.
- --8103110067 Responds to NRC 810105 ltm re deviation noted in QA Program Insp Rept 99700309/80-06. Corrective actions: required info entered on Block 23 of nonconformance & disposition rept & other projects reviewed for required info.

  KELLY.R B Stone & Webster Engineering Corp. 81/02/10. 2pp. 07B85: 20B

200 07885 210

t notice of deviation POTAPOVB.U Region 4. Dallas. Vendor Inspection Branch Bi/

- --BIO3110081 Notice of deviation from inep on B01201-05.
   Region 4. Dallas. Office of the Director B0/12/30 ip. 07835 212
- ---BIO3110090 QA Program Insp Rept 9990509/BO-06 on BOI201-09.
  Noncompliance noted failure to enter info on nonconformance Noncompliance noted values to enter into on nonconformance & disposition rept CDSTELLO.JR. HALE.C J. Region 4. Dalles. Vendor Inspection Branch. PERANICH.M V. Region 4. Dallas. Office of the Direc BO/12/30 13pp 07889.213
- B103120388 Forwards QA Program Insp Rept 99900730/80-01 on 801203 to noncompliance noted rid Honoumpilance noted POTAPDVS.U Region 4. Dallas. Vendor Inspection Branch. 81/01 2pp 07905:082
- --8103120373 GA Program Insp Rept 99900730/80-01 on 801203-05 Maj inspected mgt meeting & followup on reported deficiencies in vendor mfg shock doors. BROWN, R. L. WHITESELL, D. E. Region 4. Dallas, Vendor Inspecti Branch 80/12/29 700 07909:084.
- 8103120595 Forwards GA Program Insp Rept 97900316/81-01 on 810106 POTAPDVS.U. Region 4. Dallas. Vendor Inspection Branch 81/01 200. 07905 254
- --B103120601 QA Propram Inap Rept 99900316/81-01 on B10106-08 May inspected, internal audits, design control, mfg process control, equipment caller & product acceptance OLLER, R E . BARNES, J Region 4, Dalles, Vendor Inspection Br B1/01/22 | Hpp. 07903:236.
- 8103120777 Forwards GA Program Insp Rept 99900616/80-01 on 801008 ASKE nuclear certification survey.
  POTAPOUS, U. Region 4, Dallas, Vandor Inspection Branch. BO/II
  1p. 07905-319
- --B103120785 0A Program Insp Rept 99900616/80-01 on 801008-09 Are audited: ABME nuclear survey team performance re program survey QA manual % certification of authorization status ELLERSHAWL.E.. BARKES-I. Region 4. Dallas. Vendor Inspectio Branch. 80/11/04 3pp 07905:320
- B103130092 Forwards GA Program Insp Rept 99900107/80-02 on 800825 notice of deviation.
  PDTAPDV8.U. Region 4, Dailas, Vendor Inspection Branch
  2pp. 07907:283 80/10
- --B103130037 Notice of deviation from insp on 800825-29. \* Region 4. Dallas. Office of the Director. 80/10/09. ip. 07907:235
- --810313006B GA Program Insp Rept 99900107/80-02 on 800825-29.
  Noncompliance noted insp steps approved by persons w/
  responsibilities in activity inspected & rework control
  encet not issued for incomplete insp step.
  BROWN.R. L. WHITESELL.D. E. Region 4, Dallas, Vendor Inspecti
  Branch. 80/10/09. 9pp
- 8103140580 Ack receipt of 810121 ltr informing NRC of steps taken correct deviation noted in OA Program Insp Rept 99900525/80-03 Region 4. Dallas, Vendor Inspection Branch. 81/02 POTAPOVA, U.
- 1.0 07916:345 --8193150590 Responds to NRC 801223 ltr re deviation noted in GA
- Insp Rept 97900525/80-03 Corrective actions interface review will be performed on TMI project piping drawings & audits scheduled for engineering & drafting disciplines.

  BARKER.N.R. Gilbert/Commonwealth Cos. 81/01/21. 4pp. 0791
- --B103160395 Forwards GA Program Insp Rept 99900525/80-03 on 8011 & notice of deviation. POIAPDVS.U. Region 4. Dellas, Vendor Inspection Branch. 80/ 2pp. 07916.330.
- --8103160598 Notice of deviation from insp on 801117-20.
  \* Region 4. Dalles. Office of the Director. 80/12/19. 2pp. 07916:352

- \_\_miggiADADS GA Program Insp Rept 97900529/80-03 pm 801117-20 puncompliance agted requisite list of safetu-related \*\* Tructures, sus & components for TMI-1 Continuing for Project not in place not in place
  FDX.D F. HALE.C J. Region 4. Dallas, Vendor Inspection Branch
  80/12/19 12pp 07916 394
- 8103160608 Ack receipt of 810114 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900519/80-03 Region 4: Dallas: Vendor Inspection Branch 8:/02/03 POTAPOVS, U
- 1p 07917 052
- --B103160610 Responds to NRC 801217 ltr re deviation noted in GA Program Inso Rest 99900519/80-03. Corrective actions, review of past inspirepic vyzoublyzou-UJ. Corrective actions review of past quality action requests to determine possible necessity for egy corrective action rept to be initiated.

  KDNEB-J.H. Bechell Power Corp. (subs. of Bechtel Corp.)

  81701/14 5pp 07917.059.
- --9103160614 Forwards OA Program Insp Rept 99900519/80-03 on 801103-06 & notice of deviation on Frogram insp Hapt 99900519/80-03 on 801103-06 notice of deviation
  POTAPDVS.U Region 4. Dellas, Vendor Inspection Branch 80/12/17
  2pp 07917-058
- --Bi03160617 Notice of deviation from inep on B01103-06.

   Region 4, Dallas, Office of the Director B0/12/15 in
- --8103160624 GA Program Insp Rept 99900519/80-03 on 801103-06.
  Noncompliance nated failure to initiate mpt corrective action rept as required by internal procedures.
  BRICKLEV.R H. ANDERSON.D O. AGEG. J.R. Region 4. Dallas, Vendor Inspection Branch 80/12/15 16pp. 07917.061.
- BIO3190001 Ack receipt of 810130 1tr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 00000701/80-02 POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch. 81/02/19 1p 07960 345.
- --B103190002 Responds to NRC 801223 ltr re deviation noted in GA Program Insp Rept 99900701/80-02 Corrective actions temporary attachment weld assigned number & documented on appropriate attachment were sevised forms. Procedures revised QDDD:H.R. Power Piping Co. (Subs. Harlan Electric Co.) B1/01/30 2pp 07960 346.
- --8103170003 Forwards GA Program Insp Rept 99900701/80-02 on 801028-29 & notice of deviation.

  POIAPDVS.U. Region 4, Dailes, Vendor Inspection Branch. 80/IZ/23
  2pp. 07960.348
- --8103190004 Notice of deviation from Insp on 801028-29 \* Region 4. Dailes, Office of the Director. 80/12/22. 1p 07940 750
- --8103190005 GA Program Insp Rept 99900701/80-02 on 801028-29. Noncompliance noted: temporary attachment weld not documented as required ROBERDS, H. W., BARNES, I. Region 4. Dallas, Vendor Inspection Branch. BO/12/22. 3pp. 07960:351.
- 8103310880 Forwards QA Program Insp Rept 99900720/80-01 on 801023-24 No noncompliance noted.
  POTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch. 81/02/02. 200. 08062:117
- --8103310883 GA Program Insp Rept 99900720/80-01 on 801023-24. No 103:10863 GA Program Insp Rept 99900720780-01 on 801023-24. Md noncompliance noted. Hajor a meas inspected implementation of 100FR50. App B & applicable codes & stds. Also conducted initial mgt meeting & reviewed pertinent documents. KELLEY. M.D., WHITEBELL, D.E. Region 4. Dallas, Vendor Inspection Branch. 61/01/28. 9pp. 08062:119.
- 8103310889 Forwards QA Program Insp Rept 99700030/81-01 on 810112-15. No noncompliance noted. 99 noted Point Inspection Branch. 81/02/04. 2pp. 08062:178.
- --8103310897 GA Program Insp Rept 99900030/81-01 on 810112-15. No NOSION TO A Program insp Rept TYPOOLOGIC INDisense In Biblish in noncompliance noted Hajor areas inspected: implementation of 10CFR3O. App B criteria & applicable codes & stds.

  HUNTER, V. H., WHITEBELL, D. E. Region 4. Dallas, Vendor Inspection Brench. DRISHILL, D. D. Region 4. Delles, Office of the Director. B1/01/27. 6pp. 08062:180.
- 8103310933 Forwards GA Program Insp Rept 99700002/81-01 on 810105-08. No noncompliance noted. POTAPOVB.U. Region 4. Dalles, Vendor Inspection Branch. 81/02/04. 200 08061 118.

noncompliance noted Major areas inspected implementation of 10CFR50, App B. including procurement controls & action on previous findings

--8103310939 GA Program Insp Rept 99900002/81-01 on 810105-08 No

MCNEJILL, W.M., KHITESELL, D.E. Region 4, Dallas, Vendor Enspection Granch 81/01/30 Spp. 08061:120.

#### REC-3D DEAL ATERY CUITEES

- 8102030495 Comments on NRC Task RS 807-5 re second proposed revision Rea Guide I 8. "Personnel Qualification & Training." Contains potential weakness in command & control excessive bias toward crisis operation & too much specific direction JENG. H H Detroit Edison Co. 81/01/29 420 07605.342
- 8103110098 Foruerds comments on second proposed Revision 3 to Reg Quide I 33 "QA Program Requirements (Operation) " MALONEY,O.P. Indiana & Michigan Electric Co. AEP NRC 00508 81/01/30 6pp 07884-322
- B103110106 Comments on proposed Revision 2 to draft Reg Quide 1 8 repersonnel qualification & training Emphasis should be placed on formation of capable may team where exceptions in areas are justified on overall qualifications of team MITTLER L Public Bervice Electric & Gas Co of New Jersey 81/02/03. 322 07884 319
- 8103110115 Forwards comments on second proposed Revision 3 to Reg Guid 1 33, "OA Program Requirements (Operation)." App A should be deleted ABEL. J S Commonwealth Edison Co. 81/01/29 5pg 07884:312
- 8103110131 Forwards comments on second proposed Revision 3 to Reg Guid 1 33, "GA Program Requirements (Operation) " Recommends re-evaluation of sitemsive revision of ANSI NIB, 7/ANS 3 2, re incorporating add guidence resulting from TMI-2 assessment AMARAL.J M. Bechtel Corp 81/01/30 App 07884 305.
- B1031:0170 Forwards comments on Reg Oulde 1 B "Personnel Qualification & Training." Requests that late comments be considered before NRC lesues reg guide DALTROFF, B L Philadelphia Electric Co B1/02/02 4pp 07884 29:
- 8103120845 Comments on Reg Guide 1 8 re personnel qualification Schedule to implement improved technical ed does not provide necessary time for completion of ed program for existing personnel Schedule should be extended if ed is required CROUSE.R P Tolledo Edison Co 683 81/01/30 2pp 07904 034
- 8103:30019 Comments on second proposed Revision 2 to Reg Guide 1 6. "Personnel Qualification & Training " Requiring licensing of all operating instructors is unnecessary Instructors should be licensed or certified according to responsibilities.

  HOFFMAN.D.P. Consumers Power Co. 81/02/04. 3pp. 07911 359
- Bi03;30028 Comments on proposed revision to Reg Guide 1 80 to be issue as Reg Guide 1 68 3 re-preoperational testing of instrument & air control sys After major mode or repairs to sys, only modified or repaired components need testing.

  SMEELDS.8.4. Public Service Co. of Indiana. Inc. 81/02/03 2pp 07912.047
- BiO3:30035 Comments on Reg Ouide 10 8 Ouide is well planned & easy to use. Index would be helpful. JOHNBTON, R.E. Affiliation Unknown 81/02/03 ip 07989-001

- BiO3130091 Forwards comments on second proposed Revision 3 to Reg Quic 1.33. "OA Program Requirements (Operation)." Quide should permit utilization of onsite & offsite reporting. DALTROFF.B.L. Philadelphia Electric Co. 81/02/03. 14pp. 07912: 025.
- 8103160287 Advises of withdraual of Reg Guide 3.24, "Quidance on License Application: Siting, Design & Plant Protection for Independent Spent Fuel Storage Installation" SMITH.R.G. Office of Standards Development, Director. 81/02/18 1p. 07917:194
- 8103180791 Value/impact statement for Reg Quide 5 &2. "Reporting of Physical Security Events. \* Office of Standards Development, Director. 81/02/28 1p. 07972:001.

- Opalification to Training "Requests delay of reg guide publication so that work of first of Nuclear Power Operations can be considered RiveLOJ Long Island Lighting Co. 81/02/23 509 07954.113
- 8:03180729 Comments on proposed Revision 2 to Reg Ouide I B. Personnel Gualification 5 Training "Explementation of educational requirements would be too costly issuance is promature CPANE.P A Pacific Gas & Electric Co. 81/02/19 2pp 07954 111
- B103166944 Comments on proposed Revision 2 to Reg Guide I 8. "Personnel Gualification 5 Training "Opposes revision MCGAUJAY. J P. Mississippi Power & Light Co. AECH-81/79 81/02/23 ip. 07954 178.
- B103180961 Comments on proposed Revision 2 to Reg Guide | B. "Personnal Qualification & Training " Degree requirement is unnecessarily restrictive & will have negative impact on industry MULER.3 E | Illinois Power Co | U-0212 | B1/01/26 | 2pp | 07954.174
- B103180970 Coments on proposed Revision 2 to Reg Ouide I B. "Personnel Oualification & Training " Independent safety engineering group Is unnecessary IRIMBLE.D C Arkansas Power & Light Co GR-0281-02 B1/02/10 2p 07954 147
- 8103180978 Comments on proposed Revision 2 to Reg Guide 1 8. "Personnel Qualification 3 Training." Educational requirements for shift supervisors 3 senior operators contained in ANS 3 1 should be adopted w/o changes in proposed revision BRYANLJ A. Union Electric Co. 81/01/30 2pp. 07954 165
- 8103180986 Coments on proposed Revision 2 to Reg Quide 1 8. 'Personnel Qualification & Training 'Opposes revision
  JUNGENSEILR H. American Electric Power Co., Inc. 81/01/29 | 3pp. 03044 Jun
- 8103181107 Reg Guide | 147. 'Inservice losp of Code Case Acceptability. ASI'E Section XI.Div | " • Diffice of Standards Development. Director 81/02/28 4pp 07546-118
- 8103181151 Corrents on proposed Revision 2 to Reg Ouide I B. 'Personnel Qualification & Training "Changes should include provisions for re-elemination of persons who do not corplete elemination of persons who do not corplete elemination time licit
  MILLS.L.B. Tennessee Valley Authority 81/01/30 4pp 07934-134.
- #1031B1154 Cornents on proposed Revision 2 to Reg Guide 1 B. "Personnel Qualification 5 Training "Post-TMI requirements should be based on sound research & validated by industry experience with Allison. E. Institute of Nuclear Power Operations. 81/01/29 2pp 07-994-118
- B103190229 Contents or proposed Revision 3 to Reg Guide I 33. "OA Program Requirements" Proposed requirement is unnecessarily restrictive & is impractical SUMPTER. J.R. Houston Lighting & Power Co. ST-ML-AE-615. B1/02/03.
- B103200829 Comments on proposed revision to Reg Ouide 1 80 Requirement of gradual loss of air test is unacceptable & unfounded VAY BRUNTLE E Artiona Public Service Co AMPP-17255-JHAV B1/02/09 2pp 07971.300
- 8103200893 Comments on proposed Revision 3 to Reg Guide 1 33. "GA Program Requirements " Requirements are too restrictive ANDOGNIN, C.C. Arizona Public Service Co. 1740. 81/02/18 App. 07971 296
- B103200B99 Comments on proposed Revision 3 to Reg Ouide 1 33, "GA Program Requirements " Quality function for all levels of plant operation, test & audit should be more clearly defined MOSETER, O. L. Mensas Oas & Electric Co. MPLNRC 81-058 B1/02/13 7pp 07971 269
- 8103200903 Surports adoption of ANSI NS38-1979/NBS Handbook 129 es reg guide.Adoption will be beneficial to gauge manufacturers & users & general public COOK.H L Obmart Corp 81/01/23 1p 07971-288
- 8103200909 Comments on proposed Revision 3 to Reg Quide 1 33, 'GA Program Requirements " Proposed revision must be consistent w/other GA program requirements. FERGUSON.J H Virginia Electric & Power Co 066 81/02/06 4pp. 07971 284.

- Program Requirements: Two reg guides specifying QA program requirements are undestrable DOUGLASS.R M Baltimore Gas & Electric Co QAO G-168 81/02/20 24pp 07976 001
- R103230043 Comments on Revision 2 to Reg Guide | 136, "Matte.Const & Testing of Concrete Containments" Scape of reg guide is unclear SILVERNOOD. J B United Engineers & Constructors, Inc. (subs. of Rauthean Co. | 81/02/18 | 30p. 07976 255.
- B103230050 Comments on 801222 revision to draft reg guide re lightning protection for nuclear power plants
  OSSMA\*L.W.R. Claveland Electric Illuminating Co. OSSMAN.W.R. Institute of Electrical & Electronic Engineers. 81/01/28 4pp. 07595-001
- 8103230054 Corments on proposed revision to Reg Guide 1 BG.
  "Preoperational Testing of Instrument & Control Air Sys."
  Reg guide should allow for appropriate testing to be done during other testing phases.u/sufficient documentation
  LODMIB.J S Sergent & Lundy. Inc. 81/02/17 2pp 07976.253.
- 8103230287 Submits comments on Ofc of Stds Development 810123 response to ACRS 801110 comments & recommendations no Reg Ouide 1 97. Revision 2 Implementation schedule for Reg Ouide 1 97. Revision 2 inadequate MARK.J C. ACRS Advisory Committee on Reactor Safeguards 81/03/18 2pp 07979 348
- --BIO21BDB22 Responds to ACRB comments on Modified Draft 3 of Reg Ouide [ 97.Revision 2. "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident " ARLOTTO.0 A Division of Engineering Standards Bi/OI/23 3pp 03966.001
- B103250409 Requests amend to Reg Guide 3 44. "Perimeter Intrusion Alarm Bys " Use of commercially derived brand name "E-Field" to describe electric field fence detector is inappropriate. Amend should delete semblance of product endorsement. WRIGHT, D. D. Technical Socurity Associates, Inc. B1/01/30. 2pp 07097 267
- B103250615 Comments on Reg Quide 3 11 i re operational insp & surveillance of embaniment retention sys for U mill tailings Reg guide not necessary in company situation since ponds erhibit safest design in wastewater impoundment. DURLER.D.L. US Steel Corp. 81/02/02. 2pp. 07998.350
- 8103261214 Comments on behalf of Kraftverkenunion Erlangen, on draft Reg Guide FP 034-4. "Spent Fuel Heat Generation in Independent Spent Fuel Storage Installation "Practical applications are overestimated MANILO., SCHRABER Affiliation Unknown. R 912/HN 81/02/17. 2pp 08040 299
- B103261215 Comments on draft Reg Ouide FP 034-4 re spent fuel heat generation in independent spent fuel storage installation. Usefulness of Figure I would be increased by inclusion of curves in 20-30 GMD/MTU range.

  STEFFEN.R J Westinghouse Electric Corp. WI.RJ8:81-037 81/02/23 ip. 09040-248
- 8103270038 Comments on behalf of Empresa Nacional del Urenio on draft Reg Guide FP 029-4. "Std Format & Content for SAR for Independent Spent Fuel Storage Installation (Dry Storage) " Reg guide should be reworded. CERRAJERD F A Affiliation Uninown 0.6 8 81/02/10 2pp C8044:336
- RES RESEARCH AND TECHNICAL AGSISTANCE REPORTS
- 7909070116 "Heavy-Bection Steel Technology Program," quick-look rept for thermal shock experiment. CHEVERTOULR D. Gak Ridge National Laboratory. FIN 8-0119 79/08/14 30pp. 00926.226
- 8103020680 "Forecasting Electricity Denand by State & by Util Svc Area." progress rept for Oct 1980-Jan 1981. HILLL J Oak Ridge National Laboratory FIN 8-0190-8. 81/02/06. Jpp 07782 131
- 8103030424 "Experimental Criticality Data for Code Validation." informal monthly progress rept for Jan 1981. BIESMAN.S R. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2094. 81/02/02. 3pp. 07790:029.

- 8103030433 "Use of Metin-B for LWR Transient Calculations.Core bys \$
  Code Development." informal rept
  CHENO.H 5 , ARDMSON.A L , HERCZEO, J U Brookhaven National
  Laboratory FIN 8-2094 BNL-NUREG-28785 RO/11/30 57pp
  67790-072
- B103031071 "Technology & Costs of Termination Surveys Associated u/ Decommissioning of Nuclear Facilities." Tonthly progress rast for Dec 1980 MITMERSPOON. J. HOLOWAY. C. F. ROHWER, P. S. Oak Ridge National Laboratory FIN A-9042 ORNL/HASRD-110 81/01/30 App
- B)03031084 "Environ Assessments of Fuel Cycle Facilities." nonthly progress rept for Dec 1980
  ZITTLE.H E. Das Ridge National Laboratory FIN 8-0279
  GRNLFD/E18-145 80/12/31 500. 07794 352

07794 339

- 8103031092 "Dosinetry & Siotransport Models to Icplement ALARA." Quarterly progress rept for Oct-Dec 1980 KDCHER.D C . RYAN.M T . KILLCUOH.G G . Gak Ridge National Laboratory FIN 8-0188 DRNL/HASRD-109 81/01/20 6pp 07794 345
- 8103040671 "Semiscale Mod-2A Test S-UI-1." quick look rept BLAKELY. J. F. HANSON R O. SHIMBON D. J. 60%0 Idaho inc. FIN A-6038 EEG-BEHI-5331 81/31/31, 78pp. 0/816-029
- B103040675 "Blab Core Test Facility Operation & Maint Manual, Single-Beam Density Heasurement Bys" RONRDANZIR R , CURRY I E , THORNYON V B EG&O Idaho, Inc FIN A-6100 EGO-30-5179 81/01/31 150pp 07816 107
- 8103040679 "PMR Training Simulator Evaluation of Thermohydraulic Models for Main Steam Supply Sys." WULFF.M. Brookhaven National Laboratory FIN A-3227 ENL-NUREO-28955, 80/09/30, 83pp 0/816-245
- 0103040695 "Degraded Orid Protection for Class IE Power Bys. Trojan Nuclear Plant," technical evaluation rept CLEVELAND. C.J. E080 Idaho, Inc. FIN A-6429 E00-EA-9310 01/01/31 13nc.
- 8103050023 "Div of Reactor Bafety Research DRNL Programs." monthly highlights rept for Dec 1980 MYNATTIF.R Dak Ridge National Laturatory FIN B-0413 81/01/10 3800. 07914-015
- B103090032 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Dec 1980.

  HOLDMAY.C.F., WITHERSPOUN.J. Oak Ridge National Laboratory FIN A-9085-7 ORN\_-HASRD-108 B0/12/31 9pp 07914 036
- B103090373 "Nuclear Power Plant Design Concepts for Babotage Protection." informal quarterly rept for Oct-Dec 1980 ERICSON.D.M Bandia Laboratories FIN A-1210 91/01/13. 3pp 07914.013
- 8103050385 "Bafeguards for Proliferation Resistant Fuel Cycles."
  Informal monthly progress rept for Dec 1980
  CADMELL 8. Groothaven National Laboratory. FIN A-3221 81/01/27
  Jan 07824 271
  - 8103050832 "Hudson River White Perch." quarterly progress rept Jul-Sept 1980 BARNITHOUSE.L W Clak Ridge National Laboratory FIN 8-0423 80/09/30. 13pp 07823 105
- 8103050835 "GA of Radiation Heasurements for Regulatory Purposes," quarterly rept for 800915-1231 EIBENHONER, E.H. Commerce, Dept of, National Dureau of Standards FIN 0-7239. 81/01/12. 4pp 07825-118.
- 8103050839 "Hudson River Striped Bass." Quarterly progress rept Jul-Sept 1980 BARNTHOUSE,L W., VAN WINKLE,W. (Jak Ridge National Laboratory FIN B-0165, B0/09/30 3pp 07925:120
- 8103050845 "Biocide Byproducts in Aquetic Environs." quarterly rept Jul-Espt 1980. BEAN.R M Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2098. BD/09/30. 10pp. 07825:135.
- 8103090846 "Threadfin Shad Impingement," quarterly progress rept Apr-June 1980. MCLEAN,R.B. Oak Ridge National Laboratory FIN 8-0406 80/06/30 7pp. 07825:145.

CHAPMAN, L.D. Sandia Laboratories (TN A-1060 81/01/31 10pp 0/825 154

"Dhuster's Protection of Muclose har ilities.

CI ATAS/CAO

rect for Oct Dec 1980

- B103050907 "Analysis of Hypothetical Accidents Resulting in Core Meltdown: "monthly progress rept for Jan 1981 DENNING.R S., CYBULBRIS.F., BAYBUTT.F. Battelle Memorial Institut Columbus Latoratories FIN A-4067 NRC-04-76-296, 80/02/17 07629 353
- 8:03050917 'Steam Generator Tube Rugture Transport Mechanism,' mont progress rept for Jah 1981 DENNING.R S Rattelle Memoriai Institute, Chiumbus Caboratories NRC-04-293-12 81/02/17 3pp 07831 314
- BIO3051015 'Program for Standardized Analysis of Fuel Shipping Containers, 'quarterly rept for Oct-Dec 1980 LMITESILES, G.E. Gal Ridge National Laboratory FIN 8-0172 ORN,/CBD/IMF-BI 61/01/26. App 07831-321
- 8103060195 "Nondestructive Examination Evaluation Support," contilly progress rept for Jan 1981 MCCLUNGR K. SMITH-J H. Cas Ridge National Laboratory FIN 9-0 GRILL/MCD/NEES-B. 81/02/06. 4pp 07839 115
- 8103060197 "Bhipping Cask Sabutage Scurre Term Investigation, mont progress nept for Jan 1981 SCHMIDT.E W. Battelle Memorial Institute. Columbus Laboratories FIN 8-6012. B1/02/20 App 07837-019
- Biogo60215 'Decontemination as Precursor to Decommissioning," month progress rept for Jan 1981 PERRIOO.L. D. Battelle Memorial Institute. Pacific Northwest Laboratory FIN 8-2303 81/02/17 5pp 07837-014
- B103060673 Submits status rept for Dec 1980 for core melt programs 3ERMAN.M Sandia Laboratories B1/02/19. App 07840 347
- BIO3060781 Revised pages to "LOCA Series.TC-3.Experiment Operating Spec." Interin rect YACKLE.T R , WATERMAN.M.E. E060 Idaho. Inc. E00-TF8P-5221 81/02/05 10pp 07837 259
- BIOJO90147 "Accident Aerosol Characterization," monthly progress re for Jan 1981 OMZARSKI.P C Vattelle Memorial Institute, Pacific Northwest Laboratory FIN N-2207 BI/02/20 App 07846-279
- B103090469 "Melting Temps of U-Zirconjum-Diggen Compounds (PSCL & P & V Dioxide Bolubility in Zircolog (PSLV)." Interim rept for Jan 1981 HAGRMAN D L. E080 Idaho. Inc. F1N A-6050. EGG-CDF-9303 81/03 32pp 07847 308
- BIO3090475 "LDFT Monthly Progress Rept for Dec 1980 ' LEACH.L P EOSG (Jaho, Inc. FIN A-6048 EOG-LOFT-5336 B1/01/
- 95pp 07848 001
  8103090588 'Natural Circulation Cooldown Calculations for C-E. H&W &
- Biogopues Progress Rept 36 for Jan 1981, re status of site visits t processors, assemblance of radiation sources, time schedule for Test 3 & std decision Pilot study progressing Bite visit program status table enci PLATO, P Michigan. Univ of NRC-01-77-180 81/02/05 9pp 07846 003.
- 8103100007 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypase Lines & Pipes in BMR Piping Bys." Progress Rept 14.810103-30.

  Daedalean Associates. Inc. NRC-04-78-242 81/02/28 7pp 07866 072.
- 8103100144 PR-T-80-052
  "Feasibility Study on Elimination of Advanced Test Reactor Primary Coolant Sys Degassing" nvERs. A L. E080 Idaho. Inc. PR-T-80-052. 80/09/15. 27pp 07067.253.
- 8103100194 PR-T-B0-010 R1
  'Conceptual Design Rept for Advanced Test Reactor Waste Heat
  Recovery'
  BRGHM-R D EG& Idaho Inc. PR-T-80-010 R1 80/05/31. 151pp
  07866 125

- 8103110065 "Div of Reactor Bafety Research DRHL Programs." monthly highlights rept for Jan 1981 MYMATT.F.R. Dak Ridge National Laboratory 81/02/10. 36pp 02877-223
- 8103110764 "Ranona-3B Code Mod & Evaluation " Jah 1981 monthly highlight ltr. DIAMDMD.D J. Brookheven National Laboratory FIN A-3014 81/01/31 4pp 07685:138
- B103110772 'Stress Corrosion Cracking of PWR Steam Generator Tubing.' Jan 1981 monthly highlights VAN ROOYELLO Broothaven National Laboratory FIN A-3208 B1/92/17. 4pp. 07885 142
- 8103110789 "Thermal Hydraulic LMF8R Safety Experiments," Jan 1781 conthly highlights.
  GINSBERG.T Brookhaven National Laboratory FIN A-3024 81/01/31 4pp 07873 341.
- 8103110773 "Thermal Hydraulic LMFBR Bafety Experiments." Dec 1980 monthly highlights. GINSBERG.T Brookhaven National Laboratory FIN A-3024. 80/12/31. 4pp 07872 340
- B103110838 PR-T-79-008
  Feasibility Study for TRA Modular Evaporator Sys \*
  BEATTY,R N . AYERS,A L . PIERCE,R L. EGGO Idaho, Inc. PR-T-79-008,
  79/06/33. 19pp 07882:193
- B103110836 PR-T-78-034
  "Feasibility Study for TRA Heating & Ventileting Sys
  Recirculation Mod "
  BROMM.R.D . SCHELL.M.J. PIERCE.R L. EG&O Idaho. Inc PR-T-78-004
  78/09/29. 37pp 07892-211
- B103120752 "Post-Accident Decontamination Studies," informal monthly progress rept for Feb 1981.
  HALSETH, G. A. Bettelle Memorial Institute, Pacific Northwest Latoratory FIN 8-2387 81/02/26. 3pp 07906-124
- 1103120758 BNL-NUREG-28976
  "Containment Bldg Hydrogen Control Methods Related to
  Dagraded Core Accidents," informal rept.
  BERLAD.A.L. SIBULKIN.M., YANG,C.H. Brookhaven National Laboratory
  BNL-NUREG-28976 B0/11/30, 33pp. 07903:025
- 103120761 "Mubtired Burst Test Program." interim quick-look rept. CHAPHAN.R.H Oak Ridge National Laboratory. FIN B-0120 DRNJ\_HRBT-6 B1/02/20 4pp
- 8103120779 BAL-MUREO-28647

  Radioactive Loading of Ion Exchange Matle; Rediation Related Areas of Concern," informal rept.

  OANGMER. 7. PILLAY, K. K. Broothawen National Laboratory. FIN A-3162

  BNL-MUREO-28647 B0/10/31. 25pp 07903; 118
- B103120784 BNL-NUREC-28910
  "Numerical Behavior of Thor-Like Mass/Energy Equations Upon Flow Reversal:" informal rept. MEYER-J.E Brookhaven National Laboratory. BNL-NUREC-28910. 79/07/31 19pp. 07903 139.
- B103120787 BNL-NUREG-28961
  "Btudy of Fessisility of Microuave Dielectric Heeting for LMFDR Transition Phase Accident Sequence Boiling Studies," informal rept. MAKDNITZ.H & GINBBERG.Y. Brootheven National Laboratory. BNL-NUREG-28961 81/01/31. 120pp. 07903 159
- 8103120847 'NRC Safeguards Mat1 Control & Accounting Project." Oct 1780 monthly itr rept POS010.A. Leavence Livermore Laboratory. FIN A-0115. 81/03/09. 5pp. 07904:221
- B103120B90 "Physical Protection of Nuclear Facilities," Jan 1981 progress rept. CHAPHAM.L. D. Sandia Laboratories. FIN A-1060. B1/03/09. 13pp. 07905-094.
- 8103120851 "Advanced Instrumentation for Reflood Studies Program." foreign trip rept. #ESS.R A. PAYNE, R. ALEXANDER.C.T. Dak Ridge National Laboratory. FIN 8-0413. DRNL/FIR-1025. 81/02/19. 10pp. 07905.067.

- 8:03130005 ORN:/HASRD-111

  Methods in Destmetry for Nuclear Regulation: " quarterly progress rept for Oct-Dec 1980

  ECKERMAN.K F. BERMARD.S R. CRAWFERD.D J Oak Ridge National Laboratory FIN B-0410 URNL/HABRD-111 81/02/09 6pp.
- B103130374 Forwards "Review & Evaluation of Licensing Actions for Eperating Reactors," monthly progress rept for period ending B10228 CARFAYNO. 9 P. Franklin Institute/Franklin Research Center PRC-03-79-118. 81/03/11. ip 07908-122.
- --BIO3130374 B103130374

  \*Review & Evaluation of Licensing Actions for Operating
  Reactors," monthly progress rept for period ending B10228

  # Franklin Institute/Franklin Research Center. NRC-03-79-118
  B1/03/11. 73pp. 07908 123.
- 8103160084 "Bafeguards Analysis for Byproduct Matis & Small Quanti of SNM," monthly progress rept for Jan 1981. CHESIER,R Q , RANDSLPH.M L , ROHWER,P S — Qak Ridge National Laboratory. FIN 0-6108 GRNL/HABRD-112. 81/02/10 — Bpp 07921 135
- BIO3160136 "LCFY Small Experiment Operating Spec.Small Break Test Series L3. Severe Core Transient Test Series L6. Nuclear Tests L3-6 & L6-1." Interim rept Document revision request encl. SEMMEN.R S Energy.Dept. of. Idaho Operations Office LOFT-EQG-B2/12/08 36pp. 07921 187
- 8103160473 "Definition of Parameters for Hajor Accidents at Waste Solidification & Spent Fuel Storage Facilities." informal monthly progress rept for Jan 1981 FREDERICK.E.J. Oas Ridge National Laboratory. FIN B-0425 81702719. App 07916.303.
- 8103160514 "Environ Behavior of Transuranic Nuclides Leaked From W Cooled Nuclear Power Plants: "final rept Aug 1977-Dac 1978. BOHEN.V T. Woods Hole Oceanographic Institute FIN 8-6153. B1/03/31. 63pp 07918-234.
- BIO3160604 "Bafeguards for Proliferation Resistant Fuel Cycles," monthly progress rept for Jan 1981. CADMELL-J Brookhaven Netsonal Laboratory FIN A-3221. 81/02/ 3pp 07917 137.
- 8103170116 "Mater Reactor Research Test Fecilities, 20/3D, Code Development,Code Assessment & Application Divs & Thermal Fuels Behavior Program," monthly repts for Jan 1981. DEARIEN.J A., WILLIAMS.B. E. EG&O Ideho, Inc. EOQ-MRR-5363 81/01/31 2003p. 07937:238.
- 8103170737 "Thermal Fuels Behavior Program PBF-LOCA Test Beries LO quick look rept YACKLEJLR, LEFEBRENT. EGAO Ideho, Inc. FIN A-6041. EGO-TFBP-5329. B1/02/28 63pp. 07930:162.
- BIO3180432 "Technology & Costs of Termination Burveys Associated W Decommissioning of Nuclear Facilities," monthly progress rapt for Jan 1981 MITHERBEROUN.J. HOLDHAY.C.F. Dak Ridge National Laboratory FI A-9042 DRNL/HASRD-113. 81/01/31. 11pp. 07944.075.
- BIO3180816 "Effect of Pressure & Flow on BWR Rod Drop Accident," abstract for ANB conference CHENO, H.B., LU.M. 8., DIAMOND, D. J. Brookhaven National Laborator FIN A-3212. BNL-NUREQ-28999. 81/01/31. 6pp. 07954:001.
- 8103190783 "Short Segmented Cask Code Development, Varification & Application." monthly Aighlights, Dec 1980. GUPPY, J. 9. Brookhaven National Leboratory. FIN A-3015. 81/01/6pp. 07964, 261.
- Bio3190809 "Short Segmented Cask Code Development, Verification & Application," monthly highlights, Jan 1981.

  OUPPY, J. G. Broothaven National Laboratory. FIN A-3015. 81/02/6pp 07964:250
- Bio3190813 "HTOR Befety Program," monthly highlights, Jan 1981. SASTRE, C. Brookheven National Laboratory. FIN A-3016. Bi/02/1 4pp 07964: 246.
- 8103200094 "Program for Standardized Analysis of Fuel Shipping

- 8103230177 "Decontamination as Precursor to Decommissioning," informal monthly progress rept.Feb. 1981.

  PERRIOD. D. Battelle Hemorial Institute. Pacific Northwest Laboratory. FIN 8-2303. 81/03/10. 5pc. 07977.041
- B103240097 "LWR Code Assessment & Application," monthly highlight ltr. Jan 1981 BANA.P Brookhaven National Laboratory FIN A-3215 B1/01/31 8pp. 07989-283
- 8103240144 "Bimulator Improvement Program." monthly highlight ltr. Jan 1981. WULFF.M. Brookhaven National Laboratory FIN A-3014 01/01/31 358. 07989 254
- B1032405B3 "Gourte Term Characteristics Resulting from Explosively-Caused, Secondary Violations of Spent Fuel Shipping Casks," informal monthly grogress rept. Feb 1981 TROTT, B. D. Battelle Memorial Institute, Columbus Laboratories, FIN B-6710, B1/03/13 12pp 07982-316.
- BIO3240683 "LWR In-Plant Measurement Program," monthly progress rept for Jan 1981. MANDLER, J. W. E060 Idaho, Inc. FIN A-6075. 81/02/19 4pp 07982-274
- 8103260669 "Real Time Simulation of Thermal Conduction in Nuclear Fuel Elements," interim rept. MULFF.M Broakhaven National Leboratory BNL-NURE0-28926 81/01/12. Ilpp. 08040:295
- B10331087B "Thermal Hydraulic LMFBR Safety Experiments," Feb monthly highlight ltr. OINSBERG, T., OREENE, O.A. Brookhaven National Laboratory FIN A-3024. 81/02/28 App. 08062:113.
- BiO3310884 "HIOR Safety Program." monthly highlights ltr for Feb 1981 SABIRE.C. Brookhaven National Leberatory FIN A-3016 81/03/11 4pg. 08062:170.
- BIO3310887 "RAMONA-38 Code Mod & Evaluation." Feb monthly highlight Ltr. DIAMOND.D J. Brookhaven National Laboratory FIN A-3014. BI/02/28. 4pp. 08062.174.
- 8103310893 "Bimulator Improvement Program," monthly highlight ltr for Feb 1981. WULFF.M. Brookheven National Laboratory FIN A-3014 81/03/31. 4pp. 08062.186.
- 8103310898 "LWR Code Assessment & Application." Feb monthly highlight ltr. BAMA.P. Brookhaven National Laboratory FIN A-3215. 81/02/28. doi: 08062:190.
- 8103310901 "Stress Corrosion Cracking of PHR Steam Generator Tubing." monthly highlights for Feb 1981. VAN RODYEN.D. Brookhaven National Laboratory. FIN A-3208 81/03/16. 4pp. 08062:195.
- B103310906 "BSC Code Development, Verification & Application," monthly highlights for Feb 1981.

  OUPPY.J. G. Brookhaven National Laboratory. FIN A-3015 B1/03/09 dps. 08062:194

# REVIEW ORP NRC RESEARCH REVIEW ORDUPS

- B101210483 Forwards comments re-future LOFT test plans for special review group. No tests necessary on safety basis. Bubmits table summarfiting tests useful for code assessment LOFT not representative of expected PHR behavior.
  ANDERSON.T.M. Westinghouse Electric Corp. NB-TMA-2369 91/01/16.7pp. 07489:271.
- 8103040851 Notification of contract execution Mod 1 to "Consultant to LOFT Spacial Review Group." Contractor: H Isbin LITTLE.M. Administrative Contracts Branch. FIN 8-7490 NRC-04-81-195. 81702719. 1p. 07812:178.
- --8103040860 Mod 1.changing amount of obligations, to "Consultant to LOFT Bpacial Review Group." IBBIN.H S. Isbin.H. PERLMAN.J. Administrative Contracts Branch FIN 8-7490 NRC-04-81-176. 81/02/19. ip. 07812:179.
- 8103040978 NUREG-0758
  REPORT OF THE LIGHT SPECIAL REVIEW GROUP.
  ROSB-D.F. LOFT Special Review Group. 81/02/28. 100pp. Available
  at NTIS. 94.50. 07812:038

- 8103170695 Forwards schedule for FYB1 midryr revieu ne water rev safety research FEIT.P NRC - No Detailed Affiliation Given 81/03/10 222 07930 143
- 810317070B Forwards schedule for FYB1 mid-yr review re water rea safety research FEIT.R NRC - No Detailed Affiliation Olven. 81/03/10 2pp 07930 149
- 810318D048 Transcript of B10204 public meeting in Washington.DC discussion of preliminary policy considerations in development of safety goal Pp 1-47 
   Commissioners 81/02/04. 48pp
- 8103180108 Transcript of 810211 meeting in Washington, DC for bri on LOFT Review Group Pp 1-70 • Conclusioners 61/02/11 9500 07943 032.
- --Bio2020497 Recommends continuation of LOFT facility test progr. FY80 w/emphasis placed on development of reactor safety analysis tests for operational extreme condition limits. Cost effectiveness of program results should be assessed FINLAYSON.F.C. Aerospace Corp. 81/01/29 4pp 07597-276
- --Biol230369 Bolicits comments to continued operation of LCFT far Efforts include addressing specific regulatory needs & how results of LOFT program are expected to satisfy needs. Comments due Biolol. Charter & review group membership encl ROSB. D.F. Division of Systems Integration BO/12/08. 2pp 03906-145
- --BI01230371 Comments on NRC FYB2 budget Funding levels considered those allocated by Ofc of Executive Director in B00702 preliminary markup & requested by Ofc of Nuclear Regulatory Research B00709
  PLESBET. H B. ACRS Advisory Committee on Reactor Safeguards B0/07/17 10pp 03906-147
- --Bi03180146 "Presentation to Commissions of NRC LOFT Test Progre MINDOUE.R. Office of Standards Development, Director. 81/0 12pp. 07943:151.
- G103180887 Forwards info re Code Assessment Review Group & Advanc Code Review Group B00626-27 joint heating in Silver Bpring. MD FABIC.S Analysis Development Branch. B1/01/21 2pp 07946
- --Bi03180902 Summary of Code Assessment Review Group & Advanced (
  Review Group 800626-27 joint meeting in Silver Spring MD re
  code assessment activities Comments on matl presented at
  meeting & related info encl.
  DDAR, Analusis Development Branch, 80/12/29 2pp 07/94/
- ~-Bi03180928 Invites participation in Code Assessment Review Grow Advanced Code Review Group 800626-27 joint meeting in 1D Falls: ID to code assessment activities. Agenda encl W/o lacture notes on assessment strategy. FABIC.8 Analysis Development Branch. 80/08/19 &pp 079-
- --Bi03180939 Comments on Code Assessment Review Group & Advanced Review Group 800626-27 joint meeting ra code assessment activities. Proposed method for analyzing small broaks end ORIFFITH.P. Massachusetts Institute of Technology 7-044. 80/06/30 6pp. 07946.833
- --BI03180949 Comments on Code Assessment Review Group & Advanced Review Group 800628-27 joint making to code assessment activities Dbjective stds should be developed for code assessment.

  DUKLER:A.E. Houston, Univ. of. B0/07/01 2pp. 07946:139
- --Bi03iB0959 Comments on Code Assessment Review Group & Advanced Review Group B00086-27 joint meeting re-code assessment activities Codes should be qualified by comparing experimental data against code predictions.

  LAMEY, R.T. Rensselder Polytechnic Inst. 80/06/30. 2pp. 07946:141.
- --Bi03180968 Comments on Code Assessment Review Group & Advanced Review Group 800626-27 joint meeting re code acceptance criteria Code predictions should focus on overall analysis of fuel cladding damage re transients.

  SCHROCK-V.E. California Univ. of Berkeley, B0/07/25 2p 07946-143.

ONDOOKE LED HEIMO

- --8103186979 Coments on Code Assessment Review Group & Advanced Code Review Group 806626-27 joint meeting the code acceptance criteria Steedy state capability should be primary focus of code criteria for transient analysis AGEC-L D Electric Power Research Institute 80/07/14 3pp 07946 145
- --BiOJBO9B4 Comments on Code Assessment Review Group & Advanced Code Review Group BCC226-27 joint meeting to code assessment program Scope of program should be limited to focus on licensing regulations involving no fuel damage (SSIM.H S Affiliation Unincom 80/06/29 Spp
- --Bio3181010 Corrents on Code Assessment Review Group & Advanced Code Review Group 800526-27 joint neeting re-code assessment program Code configuration control record should be maintained for inderendent user diversification FEE. 9 C Union Cartifee Corp. 80/07/24 3pp 07946-148
- --8103181017 Comments on steps involved in NRC plan for independent code assessment Summary of assessment steps is provided in encl. Table 1 Draft ltr from SC encl. SHOTAIN.L M. Analysis Development Branch 80/07/08 10pp
- --8103181022 Speech. 'NRC Needs on LIR Safety Codes." presented at Advance3 Code Review Group & Code Assessment Review Group B00626-27 joint -eeting in Silver Spring:HD TD15-L S Aralysis Development Branch 80/06/27 Ip 07946 161
- BIO3250327 Surmary of BIO206 meeting of Probability & Statistics Research Review Group in Betheedal/D re general charter. output-proposal review & KS State computer programs on Sayesian techniques Proposal litrs entl LANCASTER.L E Office of Nuclear Regulatory Research. Director BI/02/11 3pp 07995 313
- --810)250330 Submits proposal re reliability analysis of series-parallel sys Mort related to exponential failure models studied by Proscher & Sethuraman Details funding of project SOBELM California, Univ. of Ganta Darbara 80/11/24 2pp 07995-316
- --8103250336 Forwards concept paper re development of reasure of seriousness of event. Requests review 5 subsequent discussion Cites 801028 meeting w/8 Bernero (NRC) SPANIM J Maximus 81/01/07 1p 07975 318
- 8103250267 Suppl to B10210 staff requirements memb re preliminary policy consideration in safety goal development Proposed FR rotice-including Commission statement & discussion rept should be revised Marked-up matl ancl CHILKS U Office of the Becretary of the Commission. S80~591 81/03/18 31pp 08000 294

#### SECY POSITION PAPERS BEFORE THE COMMISSION

- B101270577 Unofficial transcript of Commission B10107 affirmation/ discussion session in Washington.DC re BECY-A-B0-180A. SECY-80-533.SECY-80-530 & SECY-A-B0-179F Pp 1-21 \* Cornissioners B1/01/07 23pp 07733-359.
- --8102230060 SECY-80-530
  Requests Commission approval of amends to 10CFR70 & 73 retransient shippents of strategic SNN Carriers will be responsible for protection against theft & radiological sabotage
  DIRCKS-W J Office of the Executive Director for Operations.
  80/12/04 37pp 07734 021
- --8102230074 SECY-80-503
  Requests Cormission approval of FR publication of effective aread to 10CFR70 issuing general license to carriers of irradiated reactor fuel Action would grant NRC direct insplenforcement authority over cerriers Supportive matlency DIRCKS-W J Gffice of the Executive Director for Operations 80/12/08 19pp. 07734.058
- 8102180203 GECY-81-061
  Provides Commission Wencl Executive Branch response, correspondence & application for License for Transnuclear, Inc to export high enriched V to Canada DIRCKS. M J Office of the Executive Director for Operations 81/01/25 1p 65023 048

- --BIO2180209 Forwards Transnuclear inc application for license to SNH to Canada Requests recommendation CDSBICK V Office of the Elecutive Director for Operations 78/08/03 ip 65023-052
- ---8102180222 Application by Transnuctear. Inc for license to exporty U-235 contained in 101 kg U to Canada End use statement encl MATSO: V Transnuclear, Inc 78-008/6/01 78/07/28 2pp 65023 053
- --Bi02180228 Forwards application for license to export 94, 24 kg ( tontained in 101 kg U.to Canada MATSCN.V Transnuclear Inc 78/07/28 ip 65023 055
- BiO2260479 Partial response to FOIA request for all documents recategories of info concerning U mills in UT.NM.AZ.CO & WY Forwards Documents 1-17 listed in app Document 18 may be obtained from NTIS FELTON.J M Division of Rules and Records. 81/02/05. 2pp
- 8103020033 Responds to FOIA request for SECY-76-245. "Foreign Ouni of Production & Utilization Facilities." Forwards document FELTON.J M Division of Rules and Records. 81/02/09. 1p. 07/29-036
- --Bi03020045 SECY-76-245
  Informs Cormission of problems in defining foreign ownership control or domination w/respect to facility licenses 8 NRC monitoring of foreign participation Recommends approval of encl draft ltr CHAPMAN.R R Office of Nuclear Material Bafety & Safeguards Director 76/04/30. 40pp.
- Bi03030092 Responds to FDIA request that BECY-80-243 be placed in Forwards document which will be placed in PDR FELTON.J M Division of Rules and Records. B1/02/09 Ip. 07791.161.
- --8103030066 SECY-80-243
  Responds to JF Ahearne 800402 info request re summary of esperience duties is number of shift technical advisors required onsite Duties include diagnosis of off-normal events is advising shift supervisor on corrections DENTON.H R Office of Nuclear Reactor Regulation. Director. 80/09/13 2pp
- ~-BI0303008D Forwards "Nuclear Power Plant Bhift Technical Advisor Recommendations for Position Description, Qualifications, Education & Training." THOMAS.E.L. Institute of Nuclear Power Operations. B0/04/22
- --8103030089 "Nuclear Power Plant Bhift Technical Advisor, Recommendate Position Description, Qualifications, Education & Fraining "
  - \* Institute of Nuclear Power Operations. 80/04/18 23pp
- 8103030921 GECY-B:-106
  Recarmends Commission authorize issuance of license for
  Hestinghouse to export 305,283 kg U.enriched to 3 6% U-235,
  to Korea
  DIRCKS-W J. Office of the Executive Director for Operations
  B1702711 3pp 65068.177
- 8103160312 SECY-81-125
  Requests Commission approval of Transnuclear, inc application for license to export 101 kg U, enriched to 93 3% U-235, to Canada ANL 780821 ltr to DDE re application encl. DIRCKS-W J. Office of the Executive Director for Operations 81702726 17pp 63119:048
- --B103160323 Discusses Transnuclear, inc application for license to 101 kg high enriched U-to Conada Uses cited by AECL are not inimical to compon defense & security of UBA.

  NOSENZO. L. V State. Dept. of, Bureau of Oceans & Internat | Envi. & Scientific Affairs 81/01/30. lp 65119:074.
- 8103160374 Transcript of 810227 Affirmation/Discussion Bassion 81-Hashington, DC. Pp. 1-5 • Cormissioners 81/02/27 8pp. 07917:004.
- \*\*-8103040155 SECY-81-043 Seeks Cormission approval of proposed amends to IOCFRI & 2 to implement delegation of DL entitrust determination to Directors of Ofc of Nuclear Reactor Regulation & NMBB. Draft FR notice & text comparison encl. DIRCKE.M. J. Diffice of the Executive Director for Operations. 81/01/19. 30pp. 65074:027.

- --Biggovile BECY-79-353

  Sects Commission approval of delegation of authority for determination of significant changes at *OL* antitrust review stage & informs of revised *GL* antitrust review procedures Procedures & draft memo enci

  DENTON-H R Office of Nuclear Reactor Regulation. Director DIRCKS-H J Office of Nuclear Material Bafety & Safeguards.Director 79705/24 13pp 55074-054
- --Bi-3040170 Delegates authority to make significant change determination for DL antitrust review Review procedures & draft ltr to Congress encl HENDRIE-J M Commissioners 79/09/12 Bpp 65074 066
- --BI03050865 SECY-81-077
  Requests Commission approval of notice of final rulemaking to dispose of wastes containing tracer levels of H-3 & C-14 w/o regard to radioactivity & to raise limit for disposal in severage sys Draft final rule encl DIRCKS.W. J. Office of the Executive Director for Operations. BI/01/28 71pp 65082 001
- --B103160395 SECY-Bi-0778

  Forwards Ofc of Policy Evaluation 810217 memo ra preparation of negative declaration & EIB in support of proposed final rule to amend IOCFR20 re radwaste disposal Radiological impact analysis was misinterpreted. Action is unwarranted DIRCKS.N J Office of the Elecutive Director for Operations 81/02/24 2pp. 07917-016
- --8103160440 SECY-81-077A

  Discusses propaged final rule to amend 10CFR20 re disposal of tritium & C-14.Even if assessment of sewer release arend was in error by couple of orders of magnitude collective doses & health effects are still negligible DIRCKS-W J. Office of the Executive Director for Operations 81/02/20. 3pp 07917.020.
- --BI02260120 SECY-81-100
  Requests Commission approval of encl draft FR notice
  announcing withdrawal of proposed rulemaking on burden of
  proof in enforcement proceedings
  DIRCKS.W J. Office of the Executive Director for Operations
  B1/02/09. 2pp 65028 193
- --8007070498 SECY-80-212

  Recommends that Commission approve publication of final rule emending IOCFR2.732 re burden of proof Proponent of order in enforcement action has burden of proof Notice of proposed rule & FR notice enci.
  SHAPARI H K Office of the Executive Legal Director 80/04/23 15pp 02883 300
- 8103170668 Transcript of 810305 Affirmation Bession 81-9 in Washington. DC Po 1-2
  - + Commissioners 81/03/05 5pp 07930-270
- --8102280183 BECY-Bi-094
  Requests Commission approval of publication of draft FR notice for public comment re NRC intention to retain therapeutic treatment of cardiac dysfunction w/1-131.
  Retention does not violate FDA rules
  DIRCKB.W.J. Office of the Executive Director for Operations
  81/02/09 7pp. 65042.169.
- --Bi022B01B6 BECY-79-542
  Recommends Commission approval of encl draft FR notice for public comment re NRC intention to retain therapsutic treatment of cardiac disfunction w/I-131 Related info & draft FR notice re BECY-BI-094 encl MINOOUE-R.B. Office of Btandards Development, Director. 79/09/20 26pp 65042-175
- --B101190671 BECY-80-349
  Recommends Commission approval of final amends to 10CFR20 to implement EPA environ radiation protection atds for nuclear power operations. Draft FR notice & Congressional Itr encl. DIRCKB, W.J. Diffice of the Executive Director for Operations. B0/12/19. 10pp. 03891:101
- B10318004B Transcript of B10204 public meeting in Washington.DC rediscussion of preliminary policy considerations in development of safety goal.fp 1-47.

  \*\*Commissioners.\*\* B1/02/04.\*\* 48pp. 07942:080.
- --8101200449 BECY-80-951 Recommends approval of encl draft FR notice of preliminary policy considerations involved in developing safety goal. HANRAHAN-E.J. Office of Policy Evaluations 60/12/29. 28pp. 03902:156.

- --8131206623 SECY-80-551A
  Forwards draft NLREG. 'Toward Gafety Goal Discussion of Preliminary Polic, Considerations." & recommends Commission approval HALRAHAN, C. J. Office of Policy Evaluations. 80/12/30 82pp 2284
- B1031BC060 Transcript of B10309 meeting in Washington DC re brieft on programmatic EIS for TMI Pp 1-69. « Commissioners B1/03/09 66pp. 07942;213
- 8103189091 SECY-77-054
  Informs of task group formed on 741118 to identify principle problem areas re occupational radiation expusures among Commission licensees 8 to develop plan for implementation of IOCFR20 Ltr & task group action plan enci CHAPMA\*\*. R. Dffice of Nuclear Material Safety & Safeguards, Director RUSCHE. B.C. Office of Nuclear Reactor Regulation, Director 77702/04 2pp.
- --8103190827 Urges prompt meeting to develop plan & schedule for immediate coordinated implementation of ALAP goal to worker exposure filan of action for ALAP encl KYUTH.D F Atomic Energy Commission 74/09/25 lopp
- Bi03200883 Unofficial transcript of 810312 Affirmation/Discussion Session 81-10 in Washington. PC Pr 1-12

  Commissioners Bi/03/12 15pp 07967, 207
- 8t03230049 Unofficial transcript of 810312 meeting in Washington. Dr SECY-B1-20/20/20A/203 policy on proceeding w/pending CP & mfg license applications. Pp 1-44 + Commissioners 81/03/12 47pp 07978 041
- --BI03230072 SECY-Bi-020C Responds to requeste from 810305 meeting re changes to Enci i to SECY-Bi-20B. explanation of required studies, comparison of requirements for pending CPs.mgf licenses t
- current OL applications & preparation for further questions
  DIRCKS.W J Diffice of the Executive Director fur Operations
  81/03/11 6pp 07978.088
- Addenda adding Paragraphs 9 c & d to GECY-81-20C

   Office of the Executive Director for Operations | 81/03/11 |
  07978 094
- 8103270091 Responds to FOIA request for documents re-possible form of review panels.task forces & committees to study issues raised by Stratton Forwards Documents 6-18 listed in app Documents 1-9 are available in PDR. FELTON.UM Division of Rules and Records. 81/02/11 2pp 08045.119
- B103160485 SECY-81-111
  Forwards draft rule raising threshold for admissibility of contentions in NRC hearings Rule should be approved as subject further Ofc of General Counsel (BGC) study OOC should rept conclusions & recommendations
  BICKMITL Office of the General Counsel BI/02/17. 4pp 65114-222
- STATE PROD STATE PROGRAMS
- BIO2260479 Partial response to FDIA request for all documents ref categories of info concerning U mills in UT,NM.AZ.CO & MY, Forwards Documents 1-17 listed in app Document 1B may be obtained from NTIS. FECTON.J. H. Division of Rules and Records 81/02/05. 2pp
- --B102260556 Provides preliminary analysis of 1969-78 incidence da for lung.bone.breast.liver & thyroid cancers.leutemia & mutliple myelona in Durango.CO. Gamna radiation levels & radon concentrations were found to be elevated. FERGUSON.B Colorado. Btate of. 79/12/27, 5pp
- BiO2270565 Notification of contract execution Mod 2 to "Environ Monitoring Program M/Commonwealth of PA ' Contractor Commonwealth of PA BAISDEN.L. Research Contracts Branch. FIN 8-5111. NRC-08-80-2 81/01/07 Ip
- 8103020025 Responds to 801211 itr re-comments on NRC review of radiation control program. Statement we personnel required for U mill effort is based on NRC criteria. State action in Kaman case will be addressed in next review. MNSBBAUMER. D. Assistant Director for State Agreements Programs. 81/02/18. 3pp 07782:359

- B103020131 PNA 80-027A updates % closes out PNA 80-027 State of TX notified Ofc of State Programs that reported 183-res. exposure could not be verified No overexposure to lab worker found. Processor maintains accuracy of initial reading. LUBEANAULU O . BOLLING. A Office of State Programs, Director. B1/01/30 1p 07/84 347
- B103020152 PNA B0-0218 updates & closes out PNA R0-021. Ofc of State Programs was informed that chromosome analyses performed by Offic. showed no evidence of significant exposure to pregnant woman Ten noncompliances identified by state LUBENAU. J O. BELLING. L A Office of State Programs. Director B1/01/20 1) 07784 044
- Bio3020162 PNA 80-032A updates PNA 80-32. On Bio107, State of TX informed Ofc of State Programs that Nuclear Diagnostic Labs received postponement of show cause hearing until Bio309 Telephone caller alleged use of unapproved matts.
  LU3ENAU.J D. BOLLING. L A Diffice of Btate Programs. Director Bi/01/30 ip 07/84 343
- 8103030094 Forwards NRC evaluation of State of MA plans for amended agreement to regulate U mills & tailings Addl staffing will be required. FR excerpts encl.
  AHEARNES J F Commissioners. 81/02/10 31pp. 07808 156
- 8103040998 Responds to FQIA request for current list of Agreement States & addresses Forwards list FELTON. In Division of Rules and Records. 81/02/23. ip 07813:340
- --8103041009 List of Agreement States & addresses.
  + Commissioners 80/10/01 3pp.
- B103041601 FDIA request for current list of Agreement States & addresses

  GHLLING.R E Proctor & Gamble Co B1/01/23 in 07813:341.
- B103050535 Requests opportunity to submit comments re CO Dept of Health proposed mod of License BUA-673 & that nod be stayed pending completion of review proceedings Mod is in excess of dept statutory authority Related into encl BEVERLY.R 9 Union Carbide Corp. 18343 80/12/29. 13pp. 02596-001
- --8103050572 Forwards environ mept for U mill Requests review of hydrogeological analysis-viable alternatives to present milling operation 3 adequacy of data. Related info encl H/o environ mept HAZLE-A J Colorado- State of 18343 79/01/17 6pp. 07596.001
- B103050B41 Comments on NRC review of state program for regulation of agreement radioactive moths Univ of RI has been notified of limitations re discharges from research vessel at sea CANNON, J. E. Rhode Island, State of
- 8103050148 Confirms NRC comments made at conclusion of recent radiation control program review NRC believes state program for control of agreement madis is adequate to protect public & is compatible w/NRC program.but addl staffing is required. KERR.O H. Office of State Programs. Director 81/02/19. 2pp 07837.041
- BiO3050156 Confirms NRC comments made at conclusion of recent radiation control program review Based on results of review NRC believes state program for control of agreement matts is adequate to protect public & conjustible w/ARC program KERR-3 W. Office of State Programs, Director 81/02/13 2pp. 07837.039.
- B103040147 Confirms NRC comments made at conclusion of 801215-18 U mill regulatory program review forwards specific comments & recommendations. Response should be submitted by 810302. NUSSBAUMER.D.A. Assistant Director for State Agreements Programs. 81/02/19 4pp. 07837-035.
- 8103060179 Confirms NRC comments made at conclusion of recent radiation control program review. Based on results of review. NRC teliaves state program for control of agreement maths is adequate to protect public & compatible w/NRC program. MERR. O W. Office of State Programs, Director 81/02/13 299. 07837:033
- Biogobol86 Confirms NRC comments made at conclusion of recent radiation control program review. Based on results of review. NRC believes state program for control of agreement matts is adequate to protect public & compatible w/NRC program. NWSSBAUMER. D. A. Assistant Director for State Agreements Programs. 81/02/27 2pp 07837:031

- Bio3060190 Confirms NRC comments made at conclusion of recent radia control program review Based on results of review NRC believes state program for control of agreement matls is adequate & compatible w/NRC program MUSSBAUMER. D. A. Assistant Director for State Agreements Programs. 81/02/13 8pp. 07837-023
- Olicolicos Identifies remaining actions needed for timely amend to mill Agreement State program Requests timetable outlining actions to resolve all issues as soon as possible Amend application should be submitted by 810801 Criteria encl ANEARRE. J F Commissioners 81/02/20 14pp 07884-330.
- 8:03:10093 Requests review of NRC recommendations re Dept of Public Health Agreement State radiation control program Also specific plans to improve agreement natis program. KERR-2 W. Office of State Programs, Director 81/02/25 2pp 07084-328
- 8103110581 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216.

  KEPPLER.J G Region 3. Chicago. Office of the Director 81/02/20
  dop 07875 346
- 8103110593 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216.

  KEPPLERJ G Region 3. Chicago. Office of the Director 81/02/20 6pp 07875-352
- 8103i10586 Forwards organizational charts depicting NRC Region 3 reorganization.effective 810216. KEPPLER.J O Region 3. Chicago. Office of the Director 81/02/26 6pp 07876.310
- 8103(10587 Forwards organisational charts depicting NRC Region 3 reorganization.effective 810216.
  KEPPLER.J G. Region 3, Chicago, Office of the Director. 81/02/266pp. 07876.316
- 8103110590 Forwards organizational charts depicting NRC Region 3 reorganization effective 810216.

  KEPPLER J G. Region 3. Chicago, Office of the Director. 81/02/26 opp. 07876:322
- B103110671 Forwards comments & recommendations on state radiation control program Items addressed Include regulations compatibility.licensing actions.insp procedures & independent measurements.

  NUSBBAUMER.D. A. Assistant Director for State Agreements Programs.
  B1/02/25. 4pp. 07877:308
- B103120284 Ack receipt of B01120 ltr affirming adequacy of health radiation control program to protect public health & safety. Intention of compliance w/technical suggestions made in JO Lubenau B01120 ltr confirmed. FERRER-R A New York State of B0/12/29. [p. 07900:218.
- B103120291 Forwards B Graham comments on 801107 ltr re recent review agreement program FDMINKLE.E H. Tennessee, State of B0/12/19. 2pp. 07900.219.
- BIO3120297 Comments on ltr affirming adequacy of program for regulation of agreement radioactive natis Radiation Control Agency procedures re escalated enforcement action for issuance of emergency orders will be specifically outlined. CANNON.J.E. Rhode Island. Btate of. BI/OI/16. 2pp. 07901:259.
- B103120303 Comments on 800516 ltr re personnel program Recommendation are appropriate to enhancement of program & have been used to improve capabilities COBB. A.B. Mississippi, State of. B1/01/15. 1p. 07901-261.
- 8103130352 Ack receipt of 801209 ltr re CA radiation control program Progress re licensing staff expansion data processing sus updating & expansion & radiation control regulation revisions discussed.

  MYERS. 8. A. California, State of. 81/01/12, [p. 07912:138.
- 8103i60213 Notification of contract execution. Mod I to "Training Cou Entitled. Safety Aspects of Industrial Radiography for State Regulatory Personnel." Contractor: Gamma Industries Div of ISI. FLYNN. H. J. Administrative Contracts Branch. FIN 8-1618. ISC-06-80-304. 81/03/04. 2pp. 07921:242

- yr & 81073D for second yr to "Training Course Entitled.
  Sefety Aspects of Industrial Radiography for State
  Regulatory Personnel "
  RICHARDBON.H D Nuclear Systems Oarma Industries Div LEBD.C D
  Administrative Contracts Brench. FIN 8-1618 NRC-06-80-304
  B1/03/04. 2pp. 07921.244
- 8103160349 Comments on proposed policy statement re-criteria for evaluation of Agreement States radiation control program YDUNG.R E Affiliation Unknown 45FR65726-014. 80/12/12 2pp 07885-001
- 8103170108 Act receipt of response to NRC recommendations re CO radiation control program & CO Bureau of Investigation rept on Cotter U Hill Status of recommendations will be reviewed during nest program evaluation

  KERR.O W Diffice of Statu Programs, Director. 81/03/05 2ep
- MERRING W DIFFICE OF BESTE PROGRAMS PERSECUE. SEPOSTOS ES
- BIO3170743 Forwards comments & recommendations on radiation control program Proteduras should be developed allowing staff to assess time lapsed since applicant or licensee has received deficienty ltr.

  NVSSBAUMER.D A Assistant Director for State Agreements Programs.

  8A/KNS BI/03/04 4pp 07925:117
- BiO3250122 Discusses State of WA radiation control program review Program for regulation of agreement matl is adequate to protect public health & safety & compatible W/NRC program improvements could be made W/o enci its KERR.O.W. Office of State Programs. Director SA/KNS. 81/03/04. 2pp. 07997-283
- B1032&0843 Responds to FOIA request for documents transmitted between Oft of State Programs & MA State Dept of Social & Health Svcs re 1901 annual compatability review. No documents are available subj to request FELTON.J.H. Division of Rules and Records 81/03/23. 1p 08040:199.
- 9:03260850 FOIA request for documents transmitted between Ofc of State Programs & WA State Dept of Bocial & Health Bucs no 1981 ennual competability review.
  WINGARD.G. Affiliation Unknown. B1/02/II. 1p. 08040.200.
- --Bi03260896 Declines invitation to participate in NRC 1981 annual compatability review for State of WA Lists reasons for refusal.

  MINOARD.O. Affiliation Uninown. 81/02/11. 2pp. 08040:201.
- --B103260863 Requests that NRC investigate State of WA, Dept of Social Health Svcs, Registron Control Section. Investigation should invalve current redistion monitoring program & obligation to inform public of contamination. Related info encl. WINGARD. 9. Public Interest Research Group, Washington. 80/10/05 6pp. 08040:203
- 8103261055 Notification of contract execution. Mod 8 to "Coordination of Faderal/State Radiation Control Activities & Assistance in Bolving Radiation Control Problems." Contractor:Food & Drug Administration. US Public Health Svc. FLYNN.M. Administrative Contracts Branch. FIN 8-1620. NRC-06-72-247. 81/03/02. 19. 08035:231.
- --8103261069 Mod 8, increasing funds & extending period of performance through 811231 to "Coordination of Federal/Blate Radiation Control Activities & Assistance in Solving Radiation Control Problems.

  4 HHS, Dept. of, US Public Health Service, LEBO.C.D. Administrative Contracts Brench. FIN 8-1620. NRC-06-76-247. 81/03/02. 1p. 08035:232
- 8109261125 Notification of contract execution Mod 2 to "Training Courses Entitled, '8afety Aspects of Industrial Radiography for State Regulatory Personnel'." Contractor: Gamma Industries Div of NBI.
  FLYNN.M.J. Administrative Contracts Branch. FIN B-1618.
  NRC-06-80-304. 81/09/18 1p. 08035:254.
- 8103261149 Notifies that to continue U mills & mill tailings regulation after Nov 1980, agreement states must enter into amended agreement w/NRC. Requests that State of CA submit application for amend by 810701. Model amend encl.

  HENDRIEJ.M. Commissioners. 81/03/17, 24pp.
- B100251152 Notifies that to continue U mills 5 mill tailings regulation after Nov 1980, agreement states must enter into amended agreement w/NRC. Requests that States of OR submit application for amend by 810701. Model amend ent., HENDRIE: J. M. Commissioners. 81/03/13. 41pp.

remaining actions to be accomplished for amended agreement Requests formal amend application by 810701
HENDRIE, J. M. Cormissioners, B1/03/16, 24pp 08037 138

processing State of NV arended agreement U/ARC Identifies

- --8103261164 Discusses consequences of ACRG recommended phose-ou at end of FMBI LOFT answers current & potential reactor safety questions & must continue testing until resolution reached WILLIAMS.C.E. Energy. Dept. of 81/01/19 500 08037 162
- 8103300393 PNA-Bj-003 on 810322 newspaper rept published re-radic contamination at Aircraft Instrument & Development in Michita, MS Caused by paint stripping on surplus military aircraft instruments Mhole body counts in grogress.

  MUBSBAUMER, D. A. Assistant Director for Material Safety & Lice LUBENAU, J. O. Office of State Programs. Director B1/03/25, 08055-309.

## TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- B102030517 Proposes format for dealing w/licensee questions on NR safety avaluations of responses to IE Bulletin 79-018.
  "Environ Qualification of Class IE Equipment." & SEP submittals
  LAMMEN.D C Componwealth Edison Co IE8-79-018 61/01/23 207005 215
- B102170396 Forwards revised 9A dept organizational chart Revision topical rept will be submitted by B10331 WELLS-JR Duke Power Co. 81/02/09 ip 07684 ii2.
- 8103020482 Forwards Figures [-!]] of App I for Topical Rept UEC-TR-001-9A, "GA Program." revised to reflect current corporate & OA organizations BILVERMODD J. B. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) B1/02/24 Ip 07903.001
- B103030021 Forwards Suppl 3 to XN-NF-75-32 (NP), "Computational Procedure for Evaluating Fuel Rod Bowing " Suppl provides results of addl rod bow measurements of irradiated fuel. OMSLEY.O.F. Exzon Nuclear Co., Inc. 1subs. of Exzon Corp.) GFO 013 81 01/02/24. 1p 07770.173.
- --B103030031 XN-NF-75-32 (NP) S3

  Buppl 3 to "Computational Procedure for Evaluating Fuel Rod

  Bouing."

  KRYSINSKITLL Exton Nuclear Co., Inc. (subs. of Exxon Corp.

  B0/01/19. Bpp. 07790:174.
- 9103030492 Forwards Suppl 3 to XN-NF-75-27 (NP), "Erson Nuclear Neutronics Design Methods for PMRs." UMSLEY.0 F Erson Nuclear Co., Inc. (subs. of Erson Corp.) CFO.014 B1. 81/02/24. 1p. 07803:204.
- --B103030905 XN-MF-75-27 (NP) 63
  Suppl 3 to "Exam Nuclear Neutronice Design Methods for PARE."
  KILLORE.M.R., STOUT.R.B., MORGAN, J.N. Exam Nuclear Co., In (subs. of Exam Corp.). B1/02/09. 45pp. 07803:205.
- Bi03030B37 Forwards Revision 4-Draft 4 to MPPS6-QA-004, operations program. Changes include responses to questions in NRC Bi0114 Itr. Requests review & comments. BUCHEY. 0. D. Weshington Public Power Bupply System GA-81-23 B1/02/27. 1p. 07797: 233.
- --BI03030865 WPPSB-0A-004 R4 DRFT
  Revision 4. Dreft 4 to operational QA program
  FEROUSON.R. L. Washington Public Power Supply System. 81/02/180pp. 07797-234
- 8103041017 Notification of 810303 meeting w/vendor in Bethasda.MI review Erron plan for meeting licensing requirements on Generic 17s17 program Proposed agenda encl.
  8EROGREN.J.S. Standardization & Special Projects Branch. 81703pp. 07812-021.
- B103050301 Forwards "Westinghouse Prediction for LOFT Nuclear Experiment L3-6." per NUREG-0737. Constitutes evaluation model prediction w/WFLASH computer program using supplied set of initial & boundary assumptions JURGENSEN, R. M. Westinghouse Operating Plants Gunera Group B1/03/03. 1p. 07826-108.

ac

--8103050908 8456A:1 "Westinghouse Prediction for LDFT Nuclear Experiment t.3-6" \* Westinghouse Electric Corp. 81703703. 84pp. 07826-109

- 0103050852 Submits 'Source Term Characteritation Resulting from TOJUNGSE SUPTIES "Source Term Character station Resulting rium Explosivel; "Caused, Secondary Violations of Spent Fuel Shipping Casks," monthly progress rept for Jan 1981 TROTT.D D Battelle Memorial Institute, Calumbus Laboratories 137C-04-80-180 81/02/13 2cp 07625 192
- 8103050649 Respons to NAC 010211 request for info re submittal of proprietary version of topical rept me rod too Rept will be TAYLOR, J. H. Dabcock I. Wilcox Co. 81/02/18 ip 07840 345

- BIO3090346 Forwards summary of nuclear low pressure rotor disk replacement shop 5 field procedures presented during 800123 NRC-VEPCD-Westinghouse meeting Marked-up insp status rept & stide encl SCHMERLING. J.M. Wastinghouse Electric Corp. 81/02/27 6pp. 07050 218
- 8103670437 Forwards 'Guidelines & Procedures for Evaluation of Component Supports Basel on Fracture Mechanics ' Rept supersedes 810206 draft Encl available in Central Files MARBTEN.T.U Electric Power Research Institute Mil405065-3 81/03/05 ip 07851 001
- 8103090459 Forwards progretary 8 hopproprietral responses to ARC 810212 request for add1 info to WCAP-9401 Proprietary responses withheld (ref 100FR2 770) Application for Fithholding & afficavit encl. Westinghouse Electric Corp. NS-TMA-2400 81/03/02 07845 247 3600
- 8103100340 Forwards proprietary & monproprietary versions of slide presentation entitled "PALADON Review" from 810204 meeting Affidavit 1 application for withholding info (ref 100FR2 799) encl ANDERSON: I M Hostinghouse Electric Corp. PAR Systems Div 183-IMA-2397 B1/02/27 12pp 07865 094
- 810310061) Forwards "Equipment Qualification Data Parkage." Revision 2 (USINUOI) FOR BASES "EQUIPMENT QUALIFICATION DATA MACKAGE." Hevision of "Equipment proprietary & enoproprietary versions of "Equipment Qualification Test Rept W-RID Indicators (Post-Accident Honitoring) " Proprietary version withheld (ref 10CFR2 790) ANDERSON. J H. Westinghouse Electric Corp. NS-THA-2396 81/02/17 07847 **3**08
- -8103103613 Forwards "Equipment Qualification Data Package." Revision 2 S proprietary & nonproprietary versions of "Equipment Outliffication Data Pactage." R S proprietary & nonproprietary versions of "Equipment Outliffication Test Rept W-RID Indicators (Post-Accident Monitoring)." Proprietary version withheld (ref 10CFR2 790) AMPERSUN. T. M. Westinghouse Electric Corp. NR-IMA-2373. R Westinghouse Electric Corp. NS-TMA-2373. 81/01/26 Pan 07867 309
- --- B103100615 Requests that vendor proprietary mati to withheld (ref WIEGEMANN, R A Westinghouse Electric Corp. AM-81-9 81/01/26 Ass. 07847 311
- --8103100617 EQDP-ESE-14 R2 MEQuipment Qualification Data Package, Revision 2 ANDERSC4.T M. Wastinghouse Electric Corp. 81/01/31 | 1806 07867 317.
- 8103110168 Forwards proprietory version of 'Mark II Containment Program Quencher Conjensation Performance "
  BUCHHOLZ.R H. General Electric Co. MFN-038-81 81/03/04 Ip 07885 146
- B1031:0450 Forwards responses to NRC B01204 request for add1 info on BAU-10129 re LYUX1 & BAW-10130 re LYUX2 TAYLOR J H Babcock & Wilcox Co. 81/03/05. 71pp 07881.064
- 8103110514 Notification of 810220 meeting w/Westinghouse owners group in Bethesda. MB to discuss response to Task Action Plan Item 1.C. 1(3), reenalysis of transients & accidents & preparation of amergency procedure guidelines. RECKHAM-D H Procedures & Test Review Branch. 81/02/05 3pp 07872: 145
- 8103120288 Forwards proposed Revision 5 to TVA-TR75-1A, "QA Program Description for Design Const & Operation of TVA Nuclear Power Plants " MILLS. L. M Tennessee Valley Authority 81/03/04. 1p. 07900.114
- --- B103120293 TVA-TR75-1A R5 Proposed Revision 5 to TVA-TR75-1A, "GA Program Description for Design Const & Operation of TVA Nuclear Power Plants." a Tennessee Valley Authority, 81/03/04 55pp. 07900,115.

- 8103150252 Forwards MCAP-9804. "Probabilistic Analysis & Operationa Data in Response to Item 11 K 3 2 for Westinghouse N856
  - AURGENSEN.R W Hestinghouse Operating Plants Owners Group GG-9. 81/03/13 ip 07918 087
- --81031A0257 WCAP-9804 10316027 K.AR-YBUG
  "Protatilistic Analysis & Operational Data in Response to
  NJREO-0737 Item II K 3 2 for Westinghouse Plants "
  ANDERSENT M . WOOD. D C . GOTTBMALL.C L Westinghouse Electric
  Corp. 81/02/28 85pp 07918.090
- B103160727 Natifies that due to time limitations.no affort will be diverted to respond to NRC B01029 questions on WCAP-9628 & WCAP-9748 re asymmetric LOCA loads Suggests response be re-evaluated re fracture mechanics review Westinghouse Electric Corp. NS-TMA-2389. 81/02/1 20: 07918 304
- 8103[50823 Add] response to FOIA request for 57 documents reference M Tokar meno to ACRS re peliet-cladding interaction Forwards documents listed in app FELTON: J M. Division of Rules and Records. 81/03/09 2pp 07915 227
- --B103160847 NEDD-24223
  "Assessment of BMR/3 Mitigation of ATMS (Alternate 3) "
  SHERMODD: 0 0. BRANCON: R J General Electric Co BONED020 81/02/28 16700
- --8103160850 NED3-24222 V1 "Assessment of BWR Mitigation of ATWB, Vol 1, (NUREQ-0460) Alternate 3)."
  SHERWOOD-0 G. DITMORE.D.C. General Electric Co. GONEDO21
  81/02/28 225pp
- --8103160855 NE00-24222 V2 "Assessment of BWR Mitigation of ATWS, Vol 2. (NUREG-0460) SHERWCOD, 0.0, MATHER, 6.L. Coneral Electric Co. 81/02/28. 425
- B103170361 Forwards info re proposed two-tiered sys of criteria for w/rod bank worth measurements utilizing bank exchange Encl word dank worth measurements utilizing dank attnange. Enc.; info will sutsequently be included in pending repts WCAP-9863 & WCAP-9864 Evaluation requested. ANDERSON. T.M. Westinghouse Electric Corp. NS-TMA-2405. 81/03/03 3ap 07939 270
- 8103170676 Advises that Amend & to Revision 9A of WCAP-8370 is acceptable Amend presents position re Reg Guide 1 (46 & Revision 1 of Reg Guide 1 58
- 8103180380 Discusses NRC acceptance of Amend & to GA Co GA topical in QA-A13010A Arend & revisions reflect organizational & editorial Changes & reg guide commitments. Amend acceptable & should be implemented upon amend issuance HAABS.W P Quality Assurance Branch. 81/03/09. 1p. 07953.090
- 8103180584 Forwards nonproprietary NEDO-24288, "Generic Condensation Oscillation Load Definition Rept." BUCHHOLZ, R. H. General Electric Co. MFN-036-81. 81/03/06. 1p. 07953 271
- --B103180588 NEDD-24288 Nonproprietary version of "Generic Condensation Oscillation Load Definition Rept." HADE, G E : IANNI,R W , TOWNSEND.H.E. General Electric Co. GONED299 81/02/28. 52pp 07953-272
- B103190101 Forwards B0-T0P-1.Revision 3A, "GA Program for Nuclear Po Plants."
  AMARAL,J.M. Bechtel Power Corp. (subs. of Bechtel Corp.). B1/03. 1p. 07960:112
- --B103190104 BQ-TOP-1 R3A Revision 3A of "QA Program for Nuclear Power Plants." BECHTEL. B D Bechtel Power Corp (subs. of Bechtel Corp.) 80/10/31. 10Bpp
- Bi03190493 Recommends that NRC conduct 3-day meeting in Washington to earlier than 2 was after last util receives SER. Util representatives & NSSS suppliers should be invited to all 3 days of meeting LAMKEND.C Electric Power Research Institute. 81/03/09. 2pp. 07945: 241

- B103200221 Forwards proprietary version of errata to NEDE-25100-P. "Caorso Bafety Relief Valve Discharge Tests, Phase I Test Rept." submitted on behalf of Mark II owners group Encl available in Central Files only
  BUCHHOLZ.R H General Etectric Co MFN-020-B1 81/02/18 is 07970 344
- 8103200315 Forwards Errata & Addenda Sheet 1 to NEUD-20100. "Caorso Safety Relief Valve Discharge Tests Phase I Tost Rept." for Mark II containment program BUCHHOLZ R H General Electric Co MFN-021-B1 81/02/18 to 07968 030
- --8103200323 NEDD-25100 ERR 1 Errate & Addenda Sheet 1 to 'Caorso Sefety Relief Valve Discharge Tests, Phase 1 Test Rept " General Electric Co. 79NED104 81/02/28 9pp 07968 031
- 8103200429 Forwards Updating Status Memo 13 re GA Manual ETR-1001 No revisions have been made since Memo 12 publication on 80073) TENZER,B.E. Ebasco Services, Inc. (subs. of Enserch Corp.) 81/03/12 2pp 07971.267
- 8103200980 Forwards comments on "Hold Time Considerations Re PCI Fuel Failures" & NUREO/CR-1462, "Mechanistic Considerations Used in Development of Profit PCI Failure Model " Profit model is BUCHHOLZ.R H General Electric Co MFN-043-81 81/03/12 10pp 07968 092
- B103200619 Advises of plans to clarify specific comments re FPL TGAR 1-76A.Revision 3 to util topical GA rept Forthcoming ltr revised rept util include organization changes & response to NRC questions CARTO.R E Florida Power & Light Co. L-81-116 B1/03/13 ip 07968-049.
- 8103240488 Responds to 810205 request re post-test evaluations for LOFT Test L3-1 & Septiscale Test 8-07-100 LOFT L3-1 800228 submittal consisted of pretest & post-test predictions & are fully responsive to request. BASKIN K. P. C-E Operating Plants Owners Group, 81/03/18, 200 07986 143
- 8103290432 Forwards background info re owners group procedures evaluation & development program to achieve compliance w/ NUREG-0737. Item 1.C.1 activities. NRC acknowledgement of program acceptability encl JURGENSEN, R W. Westinghouse Operating Plants Dwners Group QQ-34 81/Q3/18 65pp. 07996-124.
- --Bi02270351 Requests basis document for emergency procedure guidelines. per BO1112 meeting Preliminary review of MCAP-9651 to determine conformance w/NVREO-0727. Item I C.1 requirements will be completed by and of Feb 1981.

  HANAUER, B. H. Division of Human Factors Safety 80/12/17. Ip 45030, 247
- ~~8103250435 Delineates owners group proposed plans to comply w/ NUREQ-0737. Item I.C. 1. requirements re-procedures evaluation 8 development Group will meet w/NRC in Jan 1981 to discuss
  risk evaluation method if necessary.
  JURGENSEN, R. W. westinghouse Operating Plants Owners Group 00-47
  80/12/15. 2pp 07996-189
- 8103250458 NUREQ/CR-1765 CROWLEY-C. J., WEI.B., ROTHELP.H. Creare, Inc. FIN A-4070 TN-321. BI/03/31. 182pp. Available at NTIS. 450 80 08027:035.
- 8103250749 Informs that revised portions of UEC-TR-001 re GA program contain new position titles which do not correspond to organization description in 17.1.1.1 Differences are readily reconciled. Rept does not need revision.
  HAABS.W.P. Guality Assurance Branch. 81/03/19. ip. 08000:318.
- 8103260301 Forwards "Westinghouse Prediction for LDFT Nuclear Experiment L3-6 Using NOTRUMP 'Better Estimate' Code," in response to NUREO-0737 requirements. Rept available in Central Files only. JURGENSEN, R. W. Westinghouse Operating Plants Owners Group. 00-50. 81/03/25. ip. 08022:045.
- B103260630 Forwards nonproprietary & proprietary versions of "Hydraulic Blowdown Loads Analysis of HDR Test V31.1." Proprietary version withheld (ref. 10CFR2.790). Affidavit for withholding encl. SCHERER, A. E. C-E Power Systems. LD-81-015. 81/03/19. 6pp 08035: 299.

- --8103260637 Nonproprietary version of 'Hudraulic Blowdown Loads of HDR Test V31 1." \* C-E Power Sustems 81/03/31 100ep 08035 305
- 8103270714 Forwards "Westinghouse Prediction for Loft Nuclear Esperiment L3-6." Including corrected curves & plot DUROENSEN R.M. Westinghouse Operating Plants Coners Group. Cl 81/03/20. to 08047:122
- --8103270715 8456A:1 Rt Corrected copy of "Westinghouse Prediction for LOFT Experiment L3-6" Westinghouse Electric Corp. 81/03/20 85pp. 08047 123
- MASTE MOT NUCLEAR WASTE MANAGEMENT
- 8102190878 Forwards impoundment capacity rept in response to Item b Includes Wolf Park Mine well completion rept in response to Item 23 of 800918 Ite & as-built drawings (ne oversize drawing enci Drawing available in PDR MCCLUSKE/ J. P. Cotter Corp. 18286 BL/D1/15 44cm 0770B 0
- 0103020029 Forwards comments on DOE UMFRAP asphalt tailings seal development program in response to 801204 request Program development program, in response to Bulada request program should be scoped as tailings seal sys development program w/asphalt emulsion layer in combination w/overburden layer. SCARANO.R A. Uranium Recovery Licensing Branch 81/02/13 9p 02783 031
- 8103040036 Contract C1. 'Excavation & Lining Tailings Disposal Daun Mining Co. 18410 80/10/31. 191pp.
- 8103040185 Submits response to MA Social & Health Evcs request fo addl info re tailings disposal facility expansion > Dawn Mining Co. 18418 80/07/08 29pp 07812 293
- 8103040456 Forwards proposed design for leakage detection sys tell sunthetic liner Bus installation expected between 810223 & 0331.after major earth excavation & before liner emplacement
  THOMPSON.J E. Dawn Hining Co 18448 81702704 Bon 07813
- 9103050003 Ack receipt of 801031 1tr re implementation & certific of proposed cleanup & disposal stds for inactive U processing sites Advocates use of reliable measurements in determining numerical levels rather than two-tier sys.
  ROSENDAUM. D. M. Environmental Protection Agency. 18177. 80/12 2pp 07828 001
- --8103050005 Expresses concern re interpretation of unqualified n values of physical 5 chemical quantities Supports two-tier sys.qualifying stds as goals to be achieved within accuracy of available field 2 lab instrumentation. CLUSEN.R C Energy Dept of. 18177. 80/10/31 1p 0782B
- 8103050435 Forwards ARC rept re evaluation of proposed U mill tai mgt program, radiological assessment & accident analysis Scope of rept is consistent w/licenses request for technical assistance & NRC 791214 & 800522 litrs. No encl. SCARAND-R A. Uranium Recovery Licensing Branch. 81/01/16 ip 07826: 100
- 8103050454 Forwards NRC rept re evaluation of proposed San Higuel mill tailings mgt program. radiological assessment & accident analysis Brope of rept is consistent w/licensee request for technical assistance & NRC 791214 & 800522 ltrs. W/o encl. SCARAND, R. A. Uranium Recovery Licensing Branch. 81/02/19.
- 8:0305049: Forwards application for renewal of Waste Discharge Pe 5230: authorizing discharge of waste effluents to tailings pand for disposal by evaporation & seepage. Environ checklist encl THOMPSON, J.E. Dawn Mining Co. 18419 80/06/30. 42pp
- B103050935 Requests opportunity to submit comments re CO Dept of proposed mod of License BUA-673 & that mod be stayed pending completion of review proceedings. Mod is in excess of dept statutory authority. Related info encl BEVERLYIR G. Union Cerbide Corp. 18343 B0/12/29 15pp 03364 001 07586:001.
- --Bi03090544 Discusses CO Dept of Health pending decision re U mi license renewal Decision should be coordinated w/NRC & Bureau of Land Mgt. Assessment of environ impacts should be completed to comply w/NEPA. Related info enci LUSCHER.C.W. Interior.Dept.of. Bureau of Land Management. i B0/08/18 17pp. 07594:001.

\* Daun Mining Co. 18420. 80/11/30 64pg 07586.001

79/08/23

EB341

- 8103363169 Eum-arties results of soil, vegetation & well water samples. Recommends restrictions on well water use, vegetation consumption & grazing in contaminated areas ECARAND R A. Uranjow Recovery Licensing Branch. B0/12/29 Spp.
- --B103060176 Summarizes CASL site visit to collect water soil & vegetation samples in investigation of environ contamination near U mill in Canon City. CO. List of samples & map of location encl. DREESEN DR Los Alamos Scientific Laboratory, 13423 79/06/26. 3na
- --Bi03060183 Forwards 'Investigation of Environ Contamination, Canon City, rept R Los Alamos Scientific Laboratory H12-79-345 ip CO.' final cest DREESON, D R L
- 8303060430 Responds to 801222 request for review of Homestake 801023 & 1103 memos. Proposed CD. Dept of Health license condition does not comply u/NRC policy to annual one throughput limit. SCARANGER A. Uranium Recovery Licensing Branch. 81/01/16 lp. 07835:362
- B103060663 Forwards plan for Pond 7 Pond will be replaced w/lined fire-water pond Mag & info re Hypolon tear enc! MCCLUSKEY. U. P. Cotter Corp. 18405 B1/01/30 9pp 07836 099
- B103070559 Surmary of B10130 meeting L/Nuclear Assurance Corp re
  DDE conduct of UMTRAP Application of technical criteria of
  new MRC regulations for U milling operations explained.
  BHAFFER.M M Uranium Recovery Licensing Branch. B1/02/25 1p. 07845 322
- 8103100690 Requests input parameters for MILDDS code by 810202 Final draft rept. "Long-Term Stability of Union Carbide Tailings Piles at Uravan CD," encl MAZLE, A. J. Colorado, State of. 18341. 81/0[/21 23pg. 07586:001.
- --- 8103100697 Order, filed in US District Court for District of CO.
- --B103100707 Burnons, filed in US District Court for District of CO. requiring AJ Haile to respond to Bunflower Coalition CANSPEAKER, J. R. U. S. District Court. District of Colorado 18341 81/01/19 1p 07586-001.
- -- 9103100714 Request, filed in US District Court for District of CO. for appointment of DM Peres as special process server
  ENGDAHL.D E Sunflower Coalition. ENGDAHL.D E. Engdahl & Renzo. B1/01/19 2pp 07586:001
- ~-Bi0310073| Request. filed in US District Court for District of CO.to enjoin from issuing any license re U mill tailings. ENODAML, D.E., RENZD, A.F. Sunflower Coalition, ENODAML, D.E. Engdahl & Renzo 18341. 80/01/19 11pp. 07586:001.
- 8103120031 Outlines generic approach in vicinity site designation procedure DOE will prepare final site designation rept. NRC will use rept in selection & performance of remedial action related to sites. SCARAND, R. A. Uranium Recovery Licensing Branch. 81/02/27. ip. 07586-001
- B103120627 Forwards compents on DOE NEPA B01003 draft implementation plan for U mill tailings remedial action program NRC should concur in site package as submitted to DDE-ABEV. SCARAND, R.A. Uranium Recovery Licensing Branch. 81/02/23. 6pp. 07901:239
- B103120684 Notifies of schedule for license renewal assessment per B10128 telcon Evaluation of DEB is targeted for B10601. Further studies are necessary to define groundwater program BCARANDLR A. Uranium Recovery Licensing Branch. B1/02/20. 2pp. 07701:245

- mill tailings sites DOE is responsible for initiating remedial actions.

  DAVIS-J.O Office of Nuclear Material Bafety & Bafeguards. Direct 80/12/18 tp 07908 271
- --8004090779 Summary of 800107 meeting w/DDE re responsibilities wi deat for implementing U Mill Tailings Radiation Control Act. plans for issuing environ documents, current tailing disposal requirements & licensing of tailing sites for reprocessing.

  WU.O Urantum Recovery Licensing Branch. 80/03/07. Spp 02538 040
- --Bi03130072 Requests that NRC initiate action by property owners finitalization of fences at inactive U mill tailings sites.

  CLUSEN.R C Energy Dept of. 80/11/10 2pp. 07908.277
- 8100180144 Summary of 810123 meeting u/Sandia Natl Labe to BDE UMTR NEPA activities SHAFFER.W.H. Uranium Recovery Licensing Branch. 81/02/18. 200.
- 8103160170 Forwards analytical chamistry rept. MCCLUSKEY, J.P. Cotter Corp. 18592. 81/02/23. 99pp
- 8103160247 Forwards "Solid Waste Disposal Rept. Jan 1981."

  JOVES.R. K. Union Carbide Corp Metals Div. 18864. 81/02/18 2
- B103160249 Submits comments re "Environ Cleenup Stas." monthly rept Jan 1981, Proceedings of B10121-22 workshop on radiological surveys in support of Edyemont cleenup action program should be finalized by 810319. EAD16.0 0. Uranium Recovery Licenting Branch. FIN 8-2216 81/03/06. 3pp 07918:359.
- B103160329 Forwards trip rept of B10121-22 technical workshop in Denver.CO re specific protocols being used by NRC & BD for Edgemont Cleanup Action Progrem Protocol encl. SCARANG-R. A. Uranium Recovery Licensing Branch. 81/02/18. 39pp 0701A 079 8103160339 Forwards "Solid Waste Disposel Rept.Dec 1980."

  "JONES R. Union Carbide Corp. Metals Div 18565. 81/02/04. 37p
- B103160453 Forwards NRC comments re 810203 draft outline & annotate outline for UMTRAP environ assessments.
  BCARANG-R.A. Urenium Recovery Licensing Branch. 81/02/26. 3pp.

07916 218

07916: 221.

- 8103160455 Forwards comment ltrs received re NRC chapters of Dawn Mining Co mill tailings expansion project EIS Lining of proposed tailing pond will alleviate problems w/existing disposal nethods. SCROQOB, A.C. Washington, State of. 18537. 80/12/11. 4pp.
- 810317010B Ack receipt of response to NRC recommendations re CO radiation control program & CO Bureau of Investigation rept on Cotter U Hill. Status of recommendations will be reviewed during next program evaluation.

  KERR, 9 %. Diffice of State Programs, Director. 81/03/05. 2pp.
- 8103:80784 Summary of B102:2 meeting w/DDE in Silver Spring,MD to provide informal input on draft remedial action concept paper for U mill tailings site in Canonaburg,PA. Draft ent BHAFFER. W. M. Uranium Recovery Licensing Branch. 81/03/04. 48pp 07934.010
- 8:03:8:147 Advises of results of 8:0220 meeting w/QAD to resolve concerns that 40CFR190 orders mendated implementation of Reg Guides 4.14 & 4.15 Language in orders will be changed Upon revision, meeting will be held to expedite QAO approval EADIE, O. G. Uranium Recovery Licensing Branch. 81/03/06. Spp. 07934:141
- B1031904B3 Submits status rept re DOE remedial action program Lists significant actions taken re DOE conduct of UMTRAP. SCARAND, R. A. Uranium Recovery Licensing Branch. 81/01/30. 2pp.
- --Bi03190684 Advises that DE Martin has been designated as NRC representative to UMTRAP Technology Working Group, in response to 801009 request.
  MILLER.H.J. Uranium Recovery Licensing Branch. 80/10/30. 1p.

- --Bi02200419 Forwards comments re source terms & transport modeling.per BO1103 outline MILLER.H J. Uranium Recovery Licensing Branch BO/11/19 7pp 65017-126
- --B012310217 Concurs w/final draft of annual status rept on U mill tailings remedial action.pending resulution of one minor discrepancy

  BCARAND.R A Uranium Recovery Licensing Branch. B0/12/04 | Ip. 2021.738
- --Bi03190702 Responds to B01110 request that NRC initiate action by property owners re fences at eight inactive U mill tailings sites. DOE should be taking action DAVIB.J O. Office of Nuclear Material Bafety & Bafeguerds. Director B0/12/16. ip
- --8103190706 Responds to 801125 ltr re disposal site selection for U mill tailings at Durange.CD NRC participation in selection process should first be established in more generic sense for all sites designated by DDE.

  SCARAND.R A Uranium Recovery Licensing Branch. 81/01/29 20p.
- 8103230991 NUREG-0723
  ENVIRONMENTAL ASSESSMENT RELATED TO THE OPERATION OF SAN
  MIQUEL URANIUM MILL PROJECT, WM-20. (Pionest Uravan, Inc.)

   Office of Nuclear Material Safety & Safeguards, Director.
  B1/01/31 | 114pp Available at NTIS | \$4.24. 08026:282.
- 8103240482 Confirms completion of earth cover replacement in main & secondary impoundments as of 810130.

  MCCLUSKEY-J.P. Cotter Corp. 18643 81/02/25. 1p. 07981:334.
- 8103240677 Requests concurrence re 810227 radialogical & engineering assessment for Balt Lete County Fire Station 1. Concurrence schedule encl CAMPRELLR H. Engray, Deat. of. 16696. 81/03/05 200. 07989:361
- B103260029 Expresses support for remedial action program. First scoops of tailings should be removed sometime in 1981.

  KRUEGER, J. P. Edgemont, 80 18587. 81/02/20. 1p.
- 8103240364 Forwards estimates of expected transport fatalities if tailings are moved. If hazard reduction is goal of remedial action program covering tailings in place will be more effective than transport HANCHEYL. A. Bandia Laboratories. 18726 81/03/03. 5pp.

08040, 136

- 8103260407 Forwards "Water Gyality Monitoring Rept 12-80" & list of well numbers which will be used in lieu of well names. CAIN.J. Cotter Corp. 18720. 81/03/10. ip. 08040:338.
- 8103260663 Summary of 810130 meeting w/DDE re fencing of UMTRAP sites. DDE should further explore matter internally & w/DDJ. DDE might possibly reconfer w/NRC at later date. BHAFFER.H M. Uranium Recovery Licensing Branch. 81/03/09. 2pp. 08040:306.
- 8103260991 Forwards proposed notice of intent re preparation of DES for UMTRA site at Balt Lake City.UT. Timely processing required so that encl meeting schedules & comment due dates do not become outdated.

  CAMPBELL.R.H. Energy, Dept. of. 18725. 81/03/06. 6pp. 08040:273.
- B103261030 Discusses variance on percent fines contained in drainpipe filter & cover sand protective layers located in tailings facility interior rim & slopes. Requests relaxation of criteria to permit higher percentage of fines.
  THOMPSON. J. E. Dawn Mining Co. 18727. 81/03/09. 1p. 08040:272.
- 8103261143 Advises that tentative DOE/NRC procedure for obtaining NRC concurrence to proceed w/remedial action at UMTRAP vicinity properties is not required NRC role & responsibility remedial actions is not diminished.

  BHAFFER. M. M. Uranium Recovery Licensing Branch. 81/03/13. App. 08037:001.
- 8103270131 Forwards "Bolid Waste Disposal Rept.Feb 1981." JONES.R.K. Union Carbide Corp. 18717. 81/03/11. ip.
- --B103270136 "Solid Weste Disposal Rept.Feb 1981." - Union Carbide Corp. 18717. 81/03/11. 19pp.

- 8103270146 Forwards revisions to seepage detection sys. Driginal design of 10 Lysimeters in five holes has been changed to 19 Lysimeters in 15 holes Network has been moved to concentrate on slopes Lysimeter depth has been changed THOMPSCN. J. E. Dawn Mining Co. 18728 81/03/10 3pp
- B103270619 Forwards "Input Data for Radiological Assessment of Daun Mining Co U Mill " LAPATIPE New England Small Business Investment Corp 18723 B1703713 1p 08043 010
- --B103270628 "Input Date for Radiological Assessment of Dawn Mining Co Mill" LAPAT.P E New England Shall Business Investment Corp 18723. B1/03/31 2opp 08043 011
- 810327074B Confirms & formalizes NRC acceptance of role of "cooperating agency" in accomplishment of UNITHAP NEPA activities, in reasons to 810210 ltr.
  - agency" in accomplishment of UMTRAP MEPA activities in response to 810210 ltr.

    SCARANDER A Uranium Recovery Licensing Branch 81/03/17 to monda 318
- G103310553 Forwards B10130 & 0313 ltrs w/encl4 re hypaton tear repts.

  Summary of liner failure study also encl

  WEAVER.K Colorado, State of 18750 81/03/18 9pp
- B103310935 Forwards conclusions & recommendations to hydrology rept re nonphysical aspects of hydrologic sys in vicinity of mill, per Amend 13 to license conditions MCCLUSKEY. J. P. Cotter Corp. 18752 81/03/16 10pp. 08061

### XPORTLIC EXPORT AND IMPGRT LICENBEB

- 8012270934 Petition for leave to intervene & request for hearing Requests USOS volcanic & seismic assessment & study of global impact Supportive documentation encl. MATTIBON.O.L. Center for Development Policy. 80/12/09 25pp 07335-182
- 8102180203 SECY-81-061
  Provides Commission w/encl Erecutive Branch response, correspondence & application for license for Transnuclear, Inc to export high enriched U to Canada.
  DIRCKB,W.J. Office of the Executive Director for Operations B1/01/26 1p 45023:048
- B1/01/26 ip 65023:048

  --B102180209 Forwards Transnuclear. Inc application for license to expose BNM to Canada Requests recommendation Q0681CK, L. V. Office of the Executive Director for Operations 78/08/03 ip 65023 052
- --Bi02180222 Application by Transnuclear Inc for license to export 94 kg U-235 contained in 101 tg U.to Canada End use statement ent.
- MATSON, V. Transnuclear. Inc. 78-008/8/01. 78/07/28 2pp 65023-053
- --8102180228 Forwards application for license to export 94.24 kg U-23 contained in 101 kg U-to Canada MATEGN, V Transnuclear, Inc. 78/07/28 lp 65023:055
- @iO2280260 Application to emend export application changing supplier name & address. GAIKIT. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co. Ltd.) B1/02/10. ig. 07599-001
- B103020114 Application by Westinghouse for license to export 3 compensated ionization chambers Model MU23944. to France PDCHAL, W.F. Westinghouse Electric Corp. 2E-20398. B1/01/30. ipp 07/98: 019
- BiO3020330 Application by Bio-Rad Labs for license to export 200 g deuterium isotope in form of 1.000 g deuterium oxide to Japan.

  ABLE: 0.F. Bio-Rad Laboratories. 81/02/09 lpp.
- 8103020335 License for Mitsui & Co (USA).Inc to export 101.640 lb Zircaloy-2 tube shells to Japan.
  DEVINE, JB Assistant Director for Export/Import & International Safeguards. 136179. 81/02/13 ipp.
- Bi03020340 Amend 1 to license for Transnuclear-Inc to increase export to 0.31275 kg U-235 contained in 35.852 kg U to France. DEVINE.J B. Assistant Director for Export/Import & International Bareguards. 80-137/01 TNP-3. 81/02/13. ip. 07885:001.

- B103020343 License for Overseas Bechtel.Inc to export 25 micrograms Cf-252 contained in shielding containers to Taiwan DEVINE.J B Assistant Director for Export/(Typort & International Bafoguards 9713-N-108 B1/02/12 2pp
- Biogogog47 Arend 1 to expert incense for Transnoclear.Inc.renoving Conditions 9 t 10

  DEVINE.U 3 Assistant Director for Export/Import 5 International Sifeguards NUA-34: 80-187/ 81/02/12 19
- 8103029352 License for TX Nuclear Corp to export 1 g Pu-238 as oxide mixed w/beryllium & contained in TX Nuclear Neutron Activation Lab Sys to Suriname
  LEVINE.J 8 Assistant Director for Export/Import & International Safeguards 752018 81/02/12 2pp
- 8103029354 Requests especiations action relissuance of 791015 amend for increase in quantity of law enriched U for esport to Spain WILSCYLS D. General Electric Co. 80% 81010 81/02/11 2pp.
- B103C20359 Submits application for license to import ENM from France HILSON 3 D General Electric Co 81009 81/02/06 2pp
- 8103020647 Forwards export license application for JAERI VAMANN.K Japan Atomic Energy Research Inst MACPJ 2645KY-1 80/01/09 10 C7782 046
- --Bi03020659 Application by Nissho-Tuel American Corp for license to export 21 473 by U to Japan for use in Japan mat testing reactor YAMANALK Nissho-Twal American Corp MACPJ 2645 BO/12/30 bp 07782-047.
- B103020675 Forwards export license application MENDRICK W G. Teras Nuclear Div (subs of Ransay Eng. Co.) 80/12/15 1p. 07782-032
- --Bi)30206B1 Forwards application per Bi0(2) telcon Requests add1 29 copies of new NRC Form 7 COCARDFT.M Teras Nuclear Div (subs. of Ramsay Eng. Co.) Bi/Oi/21 ip 07782 033
- -Bin3020688 Escense for TV Nuclear Corp to export PU-238-By not to exceed ( g.to Suriname HEMORICK. W G Assistant Director for Export/Import & International Safeguards 762018 80/12/15 2pp 07782-034.
- 103020708 Application by Reactor Experiments Inc. for license to export 0.51 mg U-235 & 0.2027 mg Np-237. electrodeposited onto nickel discuto Crechoslovakia Eth of assurance encl HEINAY, D. Reactor Experiments. Inc. C2H 10084 81/02/03 2pp 07782 023.
- 8103030616 Forwards application for license to export U.in form of U herafluoride, to France MATSOV.V Transpurieer, inc. 81/02/12 is 07797-045
- ---8103030623 Application by Transnuclear Inc for litense to export 1.534 Kg U in form of U herafluoride to France MATSDM V Transnuclear Inc 81-076/01 81/02/12 1p 07797 046.
- 8103030696 License for Westinghouse to export five compensated ionization chambers Model NL23944. to France
  DEVINE. J. G. Assistant Director for Export/Import & International Safeguards ZE-2039 B1/02/19 ip 07791.277.
- 8103030499 Amend 1 to GE license extending expiration date from 810301 to 840331
  DEVINE J B. Assistant Director for Export/Import & International Bafaguards SDM-81007 81/02/19. 1p
- 8)03030702 License for Sigma Chemical Co to export 5 kg deuterium oxide to Taluan DEVINE.J B Assistant Director for Export/Inport & International Safeguards D-69 81/02/19 2pp
- B103030705 License for Transnuclear.Inc to export 2 005 kg U-235, contained in 4 446 kg U herafluorise to Butterland DEVINE.J B Assistant Director for Export/Import & International Bafeguards NUK-342 61/02/19 2pp

- BIO3030711 Arend 1 to Transnuclear Inc license increasing quantity of export rati from 370 9755 kg U-235 contained in 10.450 kg U hexafluoride. to 372 8295 kg U-235 contained in 10.502 249 kg U hexafluoride. DEVINE. JB Assistant Director for Export/Import & International Safeguards B1/02/19 ip
- B103030718 Amend I to Westinghouse license extending expiration date from 810501 to 820501.

  DEVINELUB Assistant Director for Export/Import & International Safeguerds ZE-10106 81/02/20. Ip
- 8103030910 License for Byron Jeckson Pump to export specially designed parts 3 components including one shaft impeller assembly, humber assembly two parts at the secondary seal cartridge assemblies, two primary 5 two secondary seal assemblies, to Switzerland DEVINE, J B Assistant Director for Export/Import 5 International Safeguards 793-W-5823 B1/02/20 ip
- B103030916 License for Westinghouse to export two incore neutron detectors. ML-23465. to Switzerland OEVINE. J 0 Assistant Director for Export/Import & International Safeguards ZE-10327 B1/02/20 1p.
- 8103030720 Amend 1 to 9E license extending expiration date from 810301 to 810331
  DEVINE J B. Assistant Director for Export/Import & International Safaguards 80H-81007 81702/19. Ip
- B103030921 SECY-B1-106
  Recommends Co-mission authorite issuance of license for Hestinghouse to export 305.283 kg U.enriched to 3 6% U-235. to Korea
  DIRCKS-H J. Office of the Executive Director for Operations 81/02/11. 3pp 65068 177
- 8103030927 Arend 1 to GE license standing expiration date from 810301 to 810331.

  DEVINE J B. Assistant Director for Export/Import & International Safeguerds 804-81007 81/02/19. 1p
- 8103030933 Forwards application for license to export 10.8 kg U-enriched to approx 93 19% U-235, to France Issuance of license prior to Aug. 1981 requested to assure reliable
- license prior to Aug.1981 requested to assure reliable supply of medical products.

  BALALIB.C 9 Union Carbide Corp 81/02/10. 3pp 07795 296
- --8103030941 License for Union Carbide Corp to export 10.8 kg U.enriched to approx 93 15% U-235.to France BALALIS.C O Assistant Director for Export/Import & International Bafeguards 201 81/02/09. 1p 07795 259
- 8103030992 Requests Executive Granch position re GE application for export license amend adding Fabbrication; Nuclears SPA as intermediate consignee M/o encl ltr.
  DEVINELUB. Assistant Director for Export/Import & International Bafguerds 81/02/20. 1p. 07795-241
- BIO3030961 Executive Branch position re TX Nuclear Corp application for license to export up to one g Pu-238 as oxide mixed w/ beryllium, to South America. License should be granted MEUFRICH.Q F State. Dept of. Bureau of Creans & Internati Environ & Scientific Affairs 81/02/18 p 07795.240
- 8)03040116 Forwards application for export litense for minor nuclear export.Ltr of assurance required.W/o encl.
  DEVINE.J.8 Assistant Director for Export/Import & International Bafeguards 8/02/20 1p. 07819 326.
- B103040130 Forwards application for export license for minor nuclear export.ttr of assurance required.W/o enci DEVINE.J.B. Assistant Director for Export/Import & International Bafeguerds. B1/02/19. 1p. 07819.334
- 8103040344 Confirms that Shikoto Electric Power Co is authorized to import 502 kg U-235 contained in 15,408 kg U. MiyasAYASHi.H. Japan Bi/02/07, tp. 07620,071.
- BiOJ040353 Requests Executive Branch position re anci OE license amend request to increase quantity of U authorized for export to Spain. Vendor expressed urgency. W/o enci.
  SHEA. J. R. Assistant Director for Export/Import & International Safeguards 81/02/23 pp. 07820.148.
- B103040472 Informs that Covt of Japan has appointed Tokyo Electric Power Co.inc as authorized person to receive 792 kg U-235, enriched to 3.95% max. Safeguards & guarantees of Agreement for Cooperation uill apply to SNM.
  MIYARAYASHI, M. Japan. B1/02/09. ip 07811.358.

- 8:03040832 License for Sigma Chemical Co to export 10 kg deuterium oxide to Buitzerland
  DEVINE. J B Assistant Director for Export/Import & International Safeguards. D-64 81/02/20 2pp
- 8103040846 License for Westinghouse to export 35 g U-235.contained in 800 g U-to Suttrerland
  DEVINE J B Assistant Director for Export/Import & International Safequards FE-20162. 81/02/19 2cp
- 8103040965 Submits application to amend export license changing total 4-235 to 0 31278 tg
  MAT8DN.V Transnuclear, Inc. 81/02/19 1p 07812 180
- B103040B72 Submits application to amend export licenses, extending expiration dates to 84033!
  WILBON, B.D. General Electric Co. BDW 81007 81/01/30 ip 67812: IBI
- 8103040875 Submits application to amend export license.extending expiration date to 810901 SCHWAUTZ.C E Hestinghouse Electric Corp. 81/02/10. ip 07812 182
- B103040B97 Forwards Export License XMAT-0170.issued w/o customary 15-day waiting period per request.
  MOGRER N Assistant Director for Export/Import & International Bafeguards B1/02/23 ip 07812 003
- --8103040904 License for Bio-Rad Labs to export 1,000 g deuterium oxide to Japan DEVINE, J B Assistant Director for Export/Import & International Safeguards. BI/02/20 2pp 07812 004
- 8103040923 License for QE Technical Svcs Co & QE to export components, sys & parts for two forced circulation, single cycle, light water cooled & moderated BURS to Taiwan DEVINE, J B. Assistant Director for Export/Import & International Safeguards. BDH-80030 81/02/17 2pp. 07585-001
- 8103040930 License for GE Technical Bycs Co & GE to export 11,400 kg U-235, contained in 478,800 kg U-to Taiwan DEVINE, J B. Assistant Director for Export/Import & International Bafaguards BDM-80031 81/02/17, 2pp. 07585
- B103040935 Amend 2 to OA Co license extending expiration date from B10310 to B20901.

  DEVINE J.B. Assistant Director for Export/Import & International Bafeguards | ECL-1081. | B1/02/23 | 1p
- 8103040944 Arend 9 to 0E & 0E Technical Sycs license to export components & associated equipment for one BMR to Switzerland.
  DEVINE.J. B. Assistant Director for Export/Import & International Safeguards BDW-81004. 81/02/23. 1p.
- 8103040767 License for Westinghouse to export 12.480 kg U-235.contained in 312.000 kg U.to Taiwan DEVINE, J.S. Assistant Director for Export/Import & International Bafeguards. ICB-0718. 81/02/17. 2pp. 07985-001
- BIO3040972 License for Westinghouse to export two PWRs.plus components & associated equipment to Talwan.
  DEVING.J.B. Assistant Director for Export/Import & International Bafaguards. BI/02/17. 3pp 07585 001.
- B103040977 License for C-E to export 5.250 kg U-235.contained in 150.000 kg U. to Taiwan.

  DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards 81/02/17. 2pp.
- 8103040981 License for Mitsubishi Intl Corp to export 256 kg U-235, contained in 8,116 kg U-to Japan.
  DEVINE, J. G. Assistant Director for Export/Import & International Bafaguards. HSA-5480-11. 81/02/23. 2pp.
- 8103040986 License for C-E to export 3,532 kg U-235.contained in 146.400 kg U.to Taiwan. DEVINE, J.B. Assistant Director for Export/Import & International Bafeguards. 81/02/17. 2pp.
- 8103041018 Amend 1 to Exxon Nuclear Co.Inc license to import 27.000 kg U.enriched to max 5% from West Germany.
  DEVINE, J.B. Assistant Director for Export/Import & International Bafaguards. 81/02/20. 1p 07812:024.

- 8103041021 Recommends issuance of license No matl changed circumstances since issuance of License XSNM-1686 MDCRE.R N Assistant Director for Export/Import & International Safeguards. 81/01/26 | [c 07812 025]
- --8103041027 License for Transnuclear. Inc. to export 741.714 kg U-239 contained in 20.893 34 kg U % 0 0355 kg U-235. contained in 1 kg U.to Switzerland DEVINE. J 3 Assistant Director for Export/Import & International Safeguards 80-241/01 RBU-3 81/02/19 2pg 07812 026
- 8103041033 Recommends issuance of license No mat) changed circumstances since issuance of License XSKM-1734 MODRER N. Assistant Director for Export/Inport & International Safeguards 61/02/20. ip 07812 035.
- --Bi03041037 License for Mitsuí & Co (USA). Inc to export 792 kg U-23 contained in 28.380 kg U.ta Japan. DEVINE, J B Assistant Director for Export/Import & Internationa Gafeguards MSK-F5-84 Bi/02/25. 2pp 07812 036.
- Bi03050001 Amend 1 to license for Bigna Chenical Co, adding add1 uitimate consignee & another party to export DEVINE.J B. Assistant Director for Export/Import & International Safeguards. D-35 B1/02/24 Ipp
- B10305022B Ltr of assurance authorizing Tokyo Electric Power Co to possess 146 kg U-235.contained in 5.429 kg U MIYABAYABHI.M Japan B1/02/09 1p. 07827 107.
- G103050231 Requests Executive Branch position re Union Carbide Corpapplication for license to export 19 8 kg highly enriched U for fabrication into fuel elements to be returned for use in Sterling Forest reactor, to France M/o encl application DEVINE, J. B. Assistant Director for Export/Import & International Bafoguerds 810/2/28. 1p. 07825-220.
- 8103090340 Protests, on behalf of Radiocherical Centre Ltd. delay in acting on export license requests for trition Requests investigation of company licenses & re-evaluation of conditions placed on issuance HARMOND W Edio
- 8103050391 Recommends issuance of license No mattichanged circumstances since issuance of x8:Mm-1724 MORE,R N Assistant Director for Esport/Import & International Bafeguards 91/02/20 ip 07824 289
- --B103050400 License for Ediow Intl Co to export 270 kg U-235.contain in 8.558 kg U-to Japan DEVINE.J B Assistant Director for Export/Inport & International Bafeguards UES JA 13 81/02/25 2p 07824 285.
- 8103050427 Recommends issuance of license No matl changed circumstances
  MOCRE,R N Assistant Director for Export/Import & International Safeguards 81/02/20 1p 07824 337
- --BI03050434 L(cense for Mitsul & Co to export 146 kg U-235 contained 5,429 kg U.to Japan DEVINE, J B Assistant Director for Export/Import & International Bafeguards, MBK-F5-R4 (A) BI/02/25 2pp. 07824.338
- 8103050451 Application by Sigma Chemical Co for license to export compounds containing equivalent of 5 kg deuterium oxide liquid over 2-yr period to India STERNUP. Signa Chemical Co (subs of Signa-Aldrich Corp.) D-: 81/02/19 ip 07824 357
- 8103050486 Forwards application for export license for minor nuclear export. Ltr of assurance required W/o encl.
  DEVINE.J.S. Assistant Director for Export/Import & International Safeguards. 81/02/25 pp. 07825-033.
- B1030504BB Revised application by Bigma Chemical Co for license to export 5 kg deuterium oxide to Taiwan STERN-H C. Bigma Chemical Co (subs. of Bigma-Aldrich Corp.). D-6
- B103030504 Requests Executive Branch position re C-E application for license to export specially designed equipment for use in primary cooling sys to Spain.

  HOREER.N Assistant Director for Export/Import & International Safeguards. B1/02/24 ip 07825:050
- 8103050314 Application by C-5 for license to export four subcooled margin monitors to Spain DAIOLE.R.P. Combustion Engineering, Inc. 81/02/17. ip. 07825:0

- 8103050526 Elecutive Branch position re Elion Nuclear Collinc application for license to elport 1.670 kg U-235 contained in 49.200 kg U-to West Dermany License should be granted Ltr of assurance encl MOSENZOL V State Dept of Bureau of Oceans & Internat! Environ & Scientific Affairs 81/02/09 3pp 07828 303
- BID3050597 Application by Sandvik Special Metals Corp for license to export 60 pieces Zircaloy-4 canning tubes to Japan. BAIGERTER, D H Sandvik Special Metals Corp D3-6-81 BI/02/18 ipp 07829 104
- 8103053601 Forwards application for license to export radioisotopically-powered thermoelectric generators. containing Pu dioiide to Israel VUGELBERGER.P. Teladine Energy Systems MET-JWM-1645 B1/02/23 ip 07827 105
- --8103050507 Application by Teledyne Energy Gys for license to export radioisotopically-powered thermoelectric generators. containing fu diocice to Israel VOCLBERGER. P. J. Teledyne Energy Systems. 81/02/23 12 02829 104
- BIO3050798 Forwards application for license to esport 26,237 kg enriched U dioxide.containing 689 kg U-235 to Japan SAIKI.T Hissui & Co. (U.S.A.).Inc. (Subs. of Hitsui & Co. Ltd.) 81/02/12 lp. 07828 136
- --BID3050805 Application by Mitsui & Co.Inc for license to export 26,237 by enriched U dipulde-containing 689 kg U-235 to Japan e Mitsui & Co. U.S.A. J. Inc. (Subs. of Mitsui & Co. Ltd.) MBK-F1-R7 81/02/12 tp. 07828 137.
- 8103050887 Ltr of assurance re export of 256 by U-235 enriched 3 15% to Japan Wyushu Electric Power Co is authorized person MiyaBAYASH1.M Japan 81/02/09. Ip 07829 347.
- B103050898 Application for Amend 1 to Licenses XCCM-0008, XCCM-0016, XCCM-0017, XCCM-0019, extending expiration dates until 840331, MILSON.B D General Electric Co BDH 81007, 81/01/30 tp
- B103050918 Submits application by OA Co to arend license.extending expiration date to B30301 MOHRY.W R General Atomic Co (subs of Gulf Dil Co ) IHL-2047. 81702/23 ip 07585:001
- BIDG050930 Executive Branch position re Intl Customs Svc.inc application for amend to license to export addi 602:367 to depleted U in form of retail plates to Switzerland License arend should be granted
  MOSENZOL V State Dept of, Sureau of Oceans & Internati Environ & Scientific Affairs BiO2/09 1p 07828 192
- B103050935 License for Hestinghouse to export two ML 23944 compensated ionization chambers to France.

  DEVINE-J B Assistant Director for Export/Import & International Safeguards 2E-20398-3 81/02/24, tpp. 07828.193.
- 8103050943 License for Westinghouse to export three NL 23944 corpensated ionitation thanbers to Frante. DEVINE.J B Assistant Director for Export/Import & International Safeguards. 2E-20398 81/02/24 1p 07828-194.
- BiOGO51010 Application by OM Corp. Saginaw Steering Gear Div for license to export ball splines used in refueling sys to Canada. SCHAUBLJ S Ceneral Motors Corp 83389, 81/02/11 1p. 07828.246.
- B103060032 Application by GM Corp. Saginar Steering Gear Div For license to export hall bearing screw & spline assemblies made of stainless steel for use in refueling machine to Canada SCHAUB. J B General Motors Corp. 83360. B1/02/12. 1p. 07839:240.
- 8103060218 License for Reactor Experiments.Inc to export 0.475 mg U-225.contained in 0.51 mg U electrodeposited onto nickel disc, to Crechoslovatia.

  DEVING.J B Assistant Director for Export/Import & International Safeguards. CZK 10084 81/02/25. 2pp 07586-001
- 9103090205 License for JT Baker Chemical Co to export 2.59 kg U, contained in 5.45 kg urengl intrate, to Mexico. DEVINEL J B. Assistant Director for Export/Import & International Safeguards 710-201-2336 81/02/18 2p. 07848.334.

- 8)03090210 Confirms issuance of license to export 3.6 kg deuterium gas to Japan.par 810206 application License issued w/o normal 15-day waiting period MDORER N Assistant Director for Export/Import & International Bafaguards 81/02/17 1p 07848 356
- --8103090217 License for Showa Denko America, Inc to export 3 6 kg devierium gas to Japan DEVINE.J B Assistant Director for Export/Import & International Bafeguards 8(303 81/02/17. 2pp 07848 357.
- B1D3090245 License for C-E to esport NSBS to Taiwan.
  DEVINE, J B Assistant Director for Export/Import & International 
  Safeguerds B1/02/17 2pp 07849.014
- 8103090313 Recommends issuance of License X8NH-1762 No mati changed circumstances from those existing at time of issuance of License X8NH-1734 MORE.R N Assistant Director for Export/Import & International Safeguerds 81/02/18 Ip 07847 208
- --BI03090319 License for Mitsubishi Intl Corp to export 502 kg U-235, contained in 15,048 kg U. to Japan
  DEVINE, J B Assistant Director for Export/Import & International Bafeguards. HBM-5480-10 BI/02/19. 2pp 07847 209.
- B103090443 Forwards application for license to export 1 226 kg U. containing 0 011 kg U-235 to France MATBON.V Transpuctear. Inc. B1/02/25 1p 07847-278
- --8103090449 Application by Transnuclear Inc for license to export 1.2 kg U.containing 0 011 kg U-235 to France MATBON.V Transnuclear Inc 81-080/01 TNP-3 81/02/25 ipp 07647 279
- 8103100001 License for Westinghouse to export 9.464 kg U-235.contained in 305.283 kg U digride sintered paillets encapsulated in sealed fuel rods & assemblies to Bouth Korea DEVINE. J. 8. Assistant Director for Esport/Impurt & International Safequences. ICB-0908. 81/02/26. 2pg. 07057:071.
- 8103100002 Executive Branch position re KMB Fusion. Inc application for license to export 10 mCi tritium contained in hollow glass pellets to United Kingdom License should be granted. MGENZGL V. State-Dept of Bureau of Oceans & Internati, Environ. & Scientific Affairs. 81/02/25. 19. 07837:073
- Bi03i00003 Erecutive Branch position to Ediow Intl Co application for license amend-eliminating requirement to obtain prior approval for re-export of certain quantities. License should be amended. NOBENIGH. V. Btats. Dept. of. Bureau of Greans & Internati. Environ. & Scientific Affairs. Bi/02/23. ip. 07837:074.
- Bio3i00005 Executive Branch position is Manubeni America Corp application for license to export 53.75 g Pu.in form of 135 NBB std semples to Japan Ltr of assurance encl. License should be granted.
  NDSENIO-L.V State. Dept. of, Bureau of Docans & Internati. Environ & Scientific Affairs, 81/02/25 2pp. 07862:101.
- 8103100162 License for Aldrich Chemical Co.Inc to export 5 kg deuterium oxide to Australia. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguerds. 1/81, 81/02/26. 2pp. 07586:001.
- 8103100371 Forwards application for license to export 41.59 g U. containing 0.40 g U-235.to Japan SHIMA.8. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HBA-6702-04. 81/02/19. 1p. 07865:050.
- --Bi03100376 Application by Mitsubishi Intl Corp for license to export 41.59 g U.containing 0.40 g U-235 to Japan. End use statement encl.

  SHIMA B. Mitsubishi International Corp. (subs. of Mitsubishi Corp. ). HBA6702-04. 81/02/19. 2pp. 07865:051.
- B1031003B0 License for Isotope Products Labs to export 10 uCi Cf-252.a fission source to Bweden.

  DEVINE J.B. Assistant Director for Export/Import & International Safeguerds. B1/03/04. 2pp. 07864:157.
- Bi03100385 License for Transnuclear Inc to export 0.068 kg U-235, contained in 3.373 kg U.to West Germany. DEVINE.J.B. Assistant Director for Export/Import & International Safeguards 81-077/01.INF-3. 81/03/04. 2pp. 07864:169.

- 8103100388 License for Transmuclear.Int to export 0 015 kg U-235. contained in 1 534 kg U-to France
  DEVINE.J.B. Assistant Director for Export/Import & International Bafaguards 81-076/01 INP-3 81/03/04. 2pp 07864 I61
- 8103100415 License for Sigma Chemical Co to export 5 kg deuterium dride to India DEVINE, J B Assistant Director for Export/Import & International Safeguards D-71. B1/03/05 2pp 07864.212
- ionisation chamber. AL-6377, to Japan
  DEVINE.J B Assistant Director for Export/Import & International
  Safaguards ZE-60205 B1/03/04. 1p 07864-214.

8103100419 License for Westinghouse to export one compensated

- 8103100649 Application by Isotope Products Labs for license to export 10 mCl source Cm-244 to Venezuela. HELM.K 8 Isotope Products Laboratories 81/02/26 ip 07862 355
- 8103100652 Application by Hestinghouse for license to export one startup assembly 23822 & one housing 23691, to Switzerland POCHAL,W F Hestinghouse Electric Corp ZE-10348. 81/02/24 1p. 07862 356.
- B103100654 Application by QE for license to export 5 kg U disside powder in 5 enrichments to Japan.
  WILBON B D. General Electric Co. BDW 81011. 81/02/18 Ip 07862-327
- 8)03100679 Confirms issuance of license to K-C Forest Products Corp to export two range detector assemblies. Westinghouse Model ML-23821, to South Korea, w/o normal 15-day waiting period MOORE,R.N. Assistant Director for Export/Import & International Safeguerds 81/03/04 1p. 07862-136.
- --810310068: License for K-C Forest Products Corp to export two range detector assemblies. Westinghouse Model ML-23821. to South Korea.

  DEVINE. J. B. Assistant Director for Export/Import & International Safeguards. 81/03/04. 2pp. 07862 137.
- 8103100686 Forwards applications for license to export 3.373 kg.U. containing 0.068 kg.U-235 & 1.534 kg.U. containing 0.015 kg.U-235 to Hest Germany H/o one application. HATSON.V. Transnuclear. Inc. 81-076/01.TNP-3 81/02/12 lp.07662.149.
- --8103100691 Application by Transnuclear Inc for license to export 3 373 kg U.containing 0 068 kg U-235 to West Germany.
  MATBON.V. Transnuclear Inc 81-077/01, TNF-3 81/02/12 ip 07862 150.
- BiO3100695 Forwards application for license to export 14,030 kg U.in form of U hazeluoride.to Bueden. MATBON.V. Transhucleer, Inc. Bi/O3/O3 ip. 07862:189
- --8103100701 Application by Transnuclear Inc for license to export 14.030 kg U. in form of U hexafluoride to Bueden End use
  - statement encl. MATSON, V. Transnuclear, Inc. RBU-365-81-0857. 81/03/02 299 07862:191.
- B103110045 Correction to B10219 application for Amend 1 to export license-changing wording to read that form of mat1 will now be U oxide rather than U hexafluoride.

  MATBON.V. Transnuclear, Inc. B1/02/24. 1p. 07885.001.
- --BiO3110054 Application for Amend 1 to license, reflecting that math will be shipped in form of U herafluoride & not U oxide.Ltr of assurance encl.
  MATBON, V. Transnuclear, Inc. 81/02/19. 2pp. 07885-002
- 8103110837 Amend 1 to GA Co license, extending expiration date from 810301 to 830301.
  DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. IEL-988. 81/03/02. ip. 07877:360.
- Bi03120079 Amend 3 to Intl Customs Bvc.Inc license, increasing quantity for export to 907,185 kg U & extending expiration date to Bi1231. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. 81/03/02. 1p.
- 8103120083 Amend 1 to Trensnuclear. Inc license, changing form of matl to U oxide & supplier to United Nuclear Corp. DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards. NUK-328 80-033/. 81/03/02. 1p. 07900:248

- BiO3120089 Amend 2 to Transnuclear, Inc license increasing quantity for export to 0 31278 to U-235 contained in 35 552 kg U
  DEVINE.J B Assistant Director for Export/Import & International Safeguards 80-173/01 TNP-3 81/03/02 ip 07700 249
- 6103120097 Requests Executive Branch position re encl Feledyne Isotopes, Inc application for license to export 27.5 g Pu-239 to Israel M/o encl DEVINE, J. B. Assistant Director for Export/Import & International Bafaguards 81/03/02. 1p 07900 261.
- 8103120103 Forwards application for export license for ninor nuclear export Ltr of assurance required. W/o and! DEVINE.J B Assistant Director for Export/Import & International Bafeguards 81/03/02 ip. 07900 262
- BIO3120143 License for Marubeni America Corp to export 33 79 g.Pu. contained in NBB stds.to Japan DEVINE.J B Assistant Director for Export/Import & International Bafeguards. ZHOI38-OW 81/03/02 2pp. 07900 273
- B103120154 Requests amend to License XR-0133 to include intermediate consignee Korea Heavy Industries & Const Co HERBCH.M M Westinghouse Electric Corp ILE-045 81/02/25 tp. 07900 278
- 8103120144 Requests amend to License XR-0125 to show name & location of consignee. Tun Ismail Atomic Research Ctr HONRY-WR General Atomic Co. (subs of Oulf Dil Co.) IEL-2050 81/03/02 Ip. 07900.276
- 8103120169 Recommends issuance of license XSNN-1774 No meth changed circumstances since issuance of XBNM-1765 MODRE:R.N. Assistant Director for Export/Import & International Safeguards 81/03/06 ip. 07900 277
- --Bi03120174 License for Transnuclear, Inc to export 4, 254 769 ig U-23 contained in 127,008 ig U & 0, 175 ig U-235, contained in 5 kg U to Switzerland DEVINE, U B. Assistant Director for Export/Import & International Safeguerds RBU 359 80-238 81/03/06. 2pg 07900.278.
- 8103120215 Executive Branch position re Nissho-Twai American Corpapplication for license to export 55,598 kg U-235 contained in 456,130 kg U to Japan.Ltr of assurance encl License
- should be granted.

  NGSENZO.L V State.Dept. of. Bureau of Oceans & Internati Environ

  Beientific Affairs. 81/03/04 3pp 07904 337.
- B103120221 Amend 1 to GE license extending expiration date from B10401 to B40331.
  DEVINE, J B Assistant Director for Export/Import & International Safeguards. BDH-B1015. 81/03/06 1p. 07904.340.
- B10312022B Anend I to GE license extending expiration date from B10401 to 840331.

  DEVINE.J.B. Assistant Director for Export/Import & International Safaguards 80H 81015 81/03/06 1p 07904 232.
- 8103120233 Amend 1 to OE license extending expiration date from B10401 to B40331.

  DEVINE, J. B. Assistant Director for Export/Import & International Safeguards BDH B1015 B1/03/06 1p. 07904 341.
- Bi03120606 Application by Belfab Bailey Controls Co for license to export three replacement nechanisms for second generation control bar supply of main metal bellows to France. MARINDER J. H. Bailey Controls Co. (subs. of Babcock & Wilcox Co.). JOB 1234. Bi/02/27. tp.
- B103120613 Executive Branch position re Carpenter Technology Corpapplication for license to export Zircalog tubes. Zircalog unapper foil & halfnium control rod drive tubes to Argentine Ltrs of assurance encl. License should be granted. NOSENZO.L.V. State. Dept. of. Bureau of Oceans & Internatl. Environ. Brientific Affairs. B1/03/02. 3pp. 07904:256
- 8103120624 Advises that all cases listed in encl to NQC 810218 ltm mabs processed for final licensing action by NRC w/o further referral to Executive Branch.
  NDSENZO,L.V. State.Dept.of. Bureau of Oceans & Internatl Environ.
  Brientific Affairs. 81/03/03. ip. 07904.263.
- B103120634 Executive Branch position re Transnuclear. Int application for license to export 4.254 767 kg U-235, contained in 127,008 kg U & 0,175 kg U-235, in 5 kg U-ks Sutterland Ltrs of assurance entil License should be granted NOSENZOLL V. State Dept. of Bureau of Dreams & Internetl Environ Scientific Affairs. B1/03/04. 4pp. 07904-268

- B103120705 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl DEVINE.U 3 Assistant Director for Export/Amport & International Safeguards B1/03/05 1p 07905 267
- B103120729 Requests Erecutive Branch position relence Isotope Products
  Labs application for license to export SNM to Grazi! for
  research & Instrument callor H/o enc!
  DEVINE. J.3 Assistant Director for Esport/Import & International
  Safequards B1/03/06 1p 07905 268
- BIO312073B Requesta Executive Branch position relench Mitsubishi Intl Corp application for license to export Sid to Japan for use in A&D of ultra-centrifuge for U enrichment W/o enci. DEVINE. J.B. Assistant Director for Export/Import & International Safequards BIJ03/06 12 07905 269
- B103120762 Requests Elecutive Branch position relent Hestinghouse application for amend to export license adding intermediate consignee for purpose of fabrication of equipment 1970 enc. DEVINE. J.8 Assistant Director for Export/Import & International Safequeds 81/03/06 ip 0.7705 304
- 8103120808 Forwards GE 1tr requesting amond to License XSMM-1771. Secreasing quantity of matl authorized for esport to 2 635 g. U-M/o enci. DEVINE. J.3 Assistant Director for Esport/Import & International Safeguerds 81/03/06 ip 07705 327
- 8103120810 Application by Westinghouse for license to export one W\_ 23798 incore fission chamber to Australia CONFALEZ-M Hestinghouse Electric Corp. ASO3534 B1/02/26 1p 07905-1298
- B103120815 License for Transnuclear Inc to export 94 kg U-235 contained in 101 kg U-to Canada DEVINE-U S Assistant Director for Export/Inport & International Safegueris 238-78-008/6/01 81/03/10 2pp 07905 329.
- 8103120820 Advises that Tajwan Power Co has revised due date for supply bids to 810331 Unges prompt issuance of Export Licenses XR-0135 & YSM-1662 MILSBIR 3D Compral Electric Co BDW 81005 B1/01/27 Ip
  - 03:30015 Forwards application for export license for minor nuclear export Litr of assurance required. M/o encl DEVINE. J Assistant Director for Export/Import & International Safeguards 81:03/06 1p 07913 023

07905 331

- J103130023 Requests Executive Branch position relence GE Lighting Business Corp application for litense to export 400 kg tharium axide concatned in liquid sluvry mixture to Gratii over 2-ur period W/o encl EVINE, J8 Assistant Director for Export/Import & International Safeguards 81/03/06 ip 07913:015
- 6103130076 Application by lectope Products Labs for license to export I-10 manacuries Am-241 & I-10 manacuries Pu-238 to Brazil HFLM.V & Isotope Products Laboratories. Bi/02/25. 1pp
- BIO31300B0 Forwards amend to 801125 license application authorizing export of 650 g U.containing 25 g U-235 to Japan WILBON B D General Electric Co. BDW 81019 B1/02/25 1p 07907.272
- --B1031300B5 Amend to B01125 application by OE for license to export 650 g U. containing 25 g U-235, to Japen.
  WILSON B D General Electric Co BDM 81019 81/02/26 ip. 02907 223
- B103130123 Requests Executive Branch position released Belfab Bailey Controls Co application for license to export three bellows for use in control rod drive shaft to France DEVINE. J 9 Assistant Director for Export/Import & International Safeguerds B1/03/06 p 07912:206
- BLO3130185 Discusses C-E application for license to export four subcooled margin monitors for use w/primary coolant sys to Spain License issued u/o 15-day weiting period. MORE.R.N. Office of international Programs. Director Bi/02/27 pp. 07908-094
- --B103130192 License for C-E to export four subcooled margin monitors for use w/primary coolent pump to Bpain. BHEA.J R Office of International Programs, Director 81/02/27 tp 07708 075

- 8103130202 Esecutive Branch position re C-E application for license to expert four subcocled margin conitors for use o/primary coolant sys to Spain License should be issued MOSENZOL V State-Dept of Bureau of Oceans & Internati Environ & State-Dept and Dept of De
- 8103130285 Application by K-C Forest Products Corp for license to export range detector assembly.WL-23821 & source & intermediate range housing assembly to South Korea STANTOIL C K-C Forest Products Corp. 81/03/04 ip 07985 001
- 8103130344 License for Transnuclear, Inc. to export 14 030 kg U-235, contained in 15 038 kg U-5 35 288 kg U-235, contained in 50 125 kg U-to Nest Germany EEVINE. J B Assistant Director for Export/Import & International Safeguards 11, M 248 UE5/EU/ 81/03/09 2pp 07912 146
- E10313063t License for KMS Fusion. Inc to export 10 aCt tritium. contained in increashell glass pellets containing mixture of deuterium & tritium gas. to United Kingdom DEVINE. J. 3 Assistant Director for Export/Import & International Bafeguards Ki19F-0480-4L 81/03/09 2pp
- 810313C638 License for CK Treasury & Supply Delegation to export 39 cubic centimeter glass shells u/deuterium tritium & noon militure to United Kingdon PEVINE. J 3 Assistant Director for Export/Import & International Safeguards 01 7474 81/03/09 2pp
- B103130642 Recommends License x5MM-1736 be granted No mati changed circumstances since (squance of License X8MM-1761 MCORE.R N Office of International Programs. Director B1/03/06 pp 07913 236
- --8103130645 License for Nieshamlwai American Corp to export 55 950 kg U-235 containes in 496 139 kg U.to Japan. CEVINE.J 3 Assistant Director for Export/Import & International Safeguards DOE31-74 81/03/09 2pp 07913 237
- 6103160286 Advises of Cormission approval of Transnoclear. Inc application for license to export highly enriched U to Belgium West Germany & the Netherlands CHILMS J Defice of the Secretary of the Commission. 681-103 81/03/10 12 07917-193
- B103160272 Requests amend of application for Litense 18NM-81002 to stipulate 4 0 m/ U-233 wIL50NB D General Electric Co 80H 81012 81/02/20. Ip
- B103160312 SECY-81-125
  Requests Commission approval of Transnuclear, Inc application for License to espart folling U-envicted to 93.3% U-235.to canade AML 780021 for to DDE re application encl. DIRCKS.W J GPice of the Executive Director for Operations B1/02/26 17pp 65119 040
- --8103160323 Discusses Transnuclear. Inc application for license to export 10f kg high enriched U.to Canada Uses cited by AECL are not inimical to common defense & security of USA NOSENZD.L V State. Dept. of. Bureau of Oceans & Internat! Environ. & Scientific Affairs 81/01/30 12. 65119 074
- BIO3160503 Forwards FR notice of applications for licenses to epoch/import nuclear facilities or matls.
  BHEALUR. Office of International Programs, Director 81/02/27.
  1p
- --8103160611 Notice of applications for licenses to export/import nuclea facilities or matls BMEA.J.R DPfice of International Programs, Director 81/02/27. 20s
- 8103160637 Requests extension of expiration date for License 18NM-79004 from 810301 to 840301 Only 6187 kg U.contained in form of U oride-have been imported out of 2700 kg authorized by license.

  MANSEN.L E Exam Nuclear Co / Inc. (subs. of Exxam Corp.)
  81/02/13 [p. 07917 127
- B103170673 Buthits application by Halprin Supply Co for license to export static electricity direction mater.containing 125 mCi tritium to China F16848.-L. Halprin Supply Co 81/03/02 1p. 07585:001
- 8103170779 Ahend 1 to export license changing name & address of ultimate consignee DEVING.J B Assistant Birector for Export/Import & International Bafeguards 81/03/10 ip 07928 025

- 8103180806 Submits application for Amend 1 to license to export, extending license for 1 yr D Vondy is Export Administrator VCNDY.D. Sargent Industries, Sweeney Div 81/03/03 Ip 07953 359
- 8103180894 Requests extension of present license or new license to import natural U herafluoride from Canada JODY. 3 Nuclear Transport & Storage.Inc 81/02/27 1p 07954 009
- 8103180906 Requests cancellation of 791206 request for license to export SNM to Pakistan. Customer has withdrawn order HELM-K Isotope Products Laboratories 81/03/03. Ip 07933 360
- 8103181086 Submits application for license for Cerec. Inc. to export thorium tetrafluoride, contained in 5 kg thorium fluoride, to Italy COLTON.E. Cerec. Inc. 81/03/09 in 07946 122
- 8103181103 Forwards application for license to export nuclear matl & equipment-extending 6/or amending License X84M-1523 to include Pu-242
  HELM.K Isotope Products Laboratories 81/02/20. 1p 07953 126
- --8]0318]106 Application by Isotopes Products Labs for license to export one microgram Pu-236 two micrograms Pu-238 two micrograms Pu-239 & one microgram Pu-242 to West Germany HELM.K. Isotope Products Laboratorips 81/02/20 ip 07933 127
- GIO3190109 Advises that Commissioners have approved Transnuclear.Inc proposed license to export high enriched U to Canada Ofc of intl Programs informed of action on 810309 CHILKS J Office of the Secretary of the Commission SG1-125 81/03/09. Ip 07965:115
- 8103;90347 Forwards application for export license for minor nuclear export.Ltr of essurance required.H/o encl. DEVINE.J B. Assistant Director for Export/Import & International Bafeguards. 81/03/12 jp 07954.333
- 8103190354 License for QM Corp. Saginaw Steering Gear Div. to export ball bearing screw & spline essemblies, used in refueling machine loads & unloads fuel elements into reactor, to Canada DEVINE, JB Assistant Director for Export/Import & International Bafeguerés 83360 81/03/11. 1p 07954 336
- 8103190359 License for Sanvik Special Metals Corp to export 60 Zircaloy-4 canning tubes to Japan DEVINE-J B. Assistant Director for Export/Import & International Safeguards 03-6-81. 01/03/11. ip. 07954:340.
- B103190363 License for QM Corp.Baginau Steering Qear Div.to export ball splines: used in refueling sys that loads & unloads fuel elements into reactor, to Canada.

  DEVINE. J. B. Assistant Director for Export/Import & International Safeguerds. 83389. B1/03/11. 1p. 07954-349.
- 8103190369 Executive Branch position re Edjou Intl application for amend to export license adding intermediate consignee for storage prior to enrichment & increasing amount of matl authorized for export. W/ltr of assurance.
  NDSENFOL V State-Dept of, Gureau of Oceans & Internati Environ. & Scientific Affairs. Si/03/09. 4pp. 07934:330.
- Bi03190665 Forwards application for license to export 3.372 kg Ucontaining 0.038 kg U-235.to France. MATBON.V. Transnuclear: Inc. 81/03/11. ip. 07964:070
- --8103190669 Application by Transnuclean Inc for license to export 3.372 kg U.containing 0.038 kg U-235 to France MATSON, V. Transnuclean, Inc. 81-091/01, TNP 3. 81/03/11. 1p. 07964: 071.
- BiO3190709 Application by Matheson Qas Products for license to export 1,000 liters chemically pure deuterium & one Bize 2 cylinder containing 1,000 liters to Argentina.

  WDDD.L. Matheson Qas Products. CONICET 181/80. 81/03/04 2pp. 07963:222.
- B103190711 Forwards application for license to export replacement parts & components to Romania.

  MDMRV.W.R. General Atomic Co. (subs. of Quif Dil Co.). IEL-2052.

  B1/03/04. jp. 07963: 224.
- --8103190715 Application by GA Co for license to export nuclear reactor warranty replacement parts & components to Romania. HDMRY.M.R. General Atomic Co. (subs. of Gulf Gil Co.). IEL-2052 81/03/04. 1p. 07963:225.

- 8103190798 Application by Reuter-Stokes, Inc. for license to export s cobalt self-powered neutron detectors & 30 vanadium selfpowered neutron detectors to India EECKHOULA A Reuter-Stokes, Inc. 05-8133 81/03/01. ip 07965
- 8103190805 Requests withdrawal of export license application.per en Isotope Products Labs 810303 ltr DEVINE.J B Assistant Director for Export/Import & International Bafeguards 81703/12 lp 07965-305.
- 8103190861 Arend 4 to license for Edlow Intl Co, recoving condition requiring prior US approval for re-export of matl in quantities larger than 1 mg.
  DEVIREJ. B. Assistant Director for Export/Import & International Bafeguerds. 81/03/02 1p. 07965.003
- B10319089 Informs that License XBNN-1789 granted w/o customary 15-d waiting due to urgent requirement of proposed export & small quentity of matl involved DEVINC.J 8 Assistant Director for Export/Import & International Safeguards. 81/02/27 1p 07765 279
- ~-BIO3190876 License for Isotope Products Labs to export 1 microgram of Pu-238.Pu-239.Pu-236 & Pu-242.as Pu nitrate in 2N nitric acid, to West Germany
  DEVINE.J B Assistant Director for Export/Import & International Safeguards BI/02/27 2pp 07945-280
- BI03230805 Requests Executive Branch position re OA Co application filicense to export miscellaneous specially designed nuclear components to Romania
  DEVINELJ B. Assistant Director for Esport/Import & International
  Safeguards. BI/03/IB lp. 07974-046
- 8103230810 Requests Executive Branch position relenced Reuter-Stakes, application for license to export neutron detectors to India W/o enci DEVINE.J B. Assistant Director for Export/Import & International Safeguards. 81/03/18 ip 07974-047.
- 0103230816 License for Transnuclear.Inc to export 0 011 kg U-235, contained in 1 226 kg U. to France
  DEVINE.J B. Assistant Birector for Export/Import & International Safeguerds 01-080.01.7HP 3. 81703718 2pp. 07774 048
- 8103230917 Forwards application by Mitsubish: Intl Corp for License t export 37.655 kg U. enriched to 3.23% to Jepen. SHIMA.8 Mitsubish: International Corp (subs of Mitsubish: Corp HBA-5480-12 81703/09 3pp 07974 011
- --Bigg230949 Application by Mitsubishi Intl Corp for license to export 37.655 kg Uverriched to 3 25% to Japan End use statement encl.

  BHIMA.S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HSA-5480-12 Bigg309. 3pp 07974 014
- 8103230923 Application by Eberline Instrument Corp for license to export Pu-239 elpha calibr source, Hodel DN8-215. electropiated on 25 millimeter metal disc.to United Kingdom JDHNSCN.N R. Eberline Instrument Corp SO 876518. 81703/10 1p.
- 8103230928 Amend 1 to Sargent Industries license, revising list of export recipients, extending expiration date from 810501 to 830501 & adding condition that individual shipments cannot exceed 100 Ci.

  DEVINE.J 8 Assistant Director for Export/Import & International Safeguards. 81/03/13 1p 07974-023
- 8103230960 Forwards application by Marubeni America Corp for license export 3 g U-233, enriched over 99% to Japan. End use statement encl. OKUDA-H Marubeni America Corp. (subs. of Marubeni Corp.) MA1-HO-6307. 81/03/12. 2pp. 07973:023
- --8103230966 Application by Marubeni America Corp for license to expo 3 g U-233 enriched over 99% to Japan KINO.T. Marubeni America Corp. (subs. of Marubeni Corp.). ZHO200-0W 81/03/12. 1g 07973 025
- B103240616 Submits application for license to import 18 kg U-235 as spent nuclear research reactor fuel from Canada JOHNBON.C.R. Nuclear Assurance Corp. CRJ/81/35/ET8 81/03/10. 19pp. 07989: 185
- 8103240895 Ltr of assurance to Transnuclear Inc application for licen to export 0.011 in U-239, contained in 1 226 kg total U. to France.

  MARCHALJ European Communities, Commission of 81/03/10. ip. 07990:020

- Bi03240A98 Notifies that part of matilitensed for conversion in France & subsequent enrichment at DJE is for use in Suitzerland Export of total titensed mati will be w/EURATOM only prior to return to USA HARMON, D.W. Ediow International Co. 81/03/11 1p. 07989 215
- 8103260041 Executive Branch position re Transnuclear, Inc & Edlow Intl applications for licenses to export 79 42 by U-235, contained in 95 by U-to France Licenses should be granted. NOSENZO.L V. State-Dept of. Bureau of Oceans & Internati Environ & Scientific Affairs 81/03/19 3pp 08041 208
- 8103260911 License for Helprin Supply Co to export 125 mCi of tritium, contained in foils of static electricity detection meter Model 1127-E. to China DEVINELU B Assistant Birector for Export/Import & International Safeguards. 81/03/19 2pp
- 8103260918 License for Westinghouse to export two start-up assemblies. Models 23822 & 23691 to Suitzerland

  DEVINE, J. D. Assistant Director for Export/Import & International

  Gafeguards. B1/03/19 Ip
- 8103260937 License for Isotope Products Labs to export 10 mCs of Cm-244 AS Source, to Venesuela
  AS Source, to Venesuela
  DEVINE, J B. Assistant Director for Esport/Import & International
  Safeguards. 81/03/17 2pp
- B103261027 Submits application to amend export license, increasing OBSCION SURMING APPLICATION OF STREET ABA35 320
- 8103261035 Application by General Motors Comp. Saginab Steering Gear Div for license to export refueling machine ball screws to General Motors Core 81/03/09 to
- 8103261039 Requests Executive Branch position re enci Embassy of Israel DEVINE, J B. Assistant Director for Ergort/Import & International Gafegueris 83390. Bi/03/23. 1p 08035 230.
- B103261044 Gubmits application to amend Export License XU-8302 by adding Halaysian Airlines Sys Berhand as ultimate consigner MGRGAN. M. E. Boeing Co. 74-1635-81R-005 81/03/11. 19 08035.159.
- B103261046 Forwards application for export license for dinor nuclear export. Ltr of assurance required. Wo encl.

  DEVINE, J. B. Assistant Director for Export/Import & International Bafeguerds B1/03/23 1p. 08093 174
- B103270041 Application by Embassy of Israel for license to export 1g U oxide isotopic std to Israel. 11.AII.A. Israel. B1/03/02 4pp
- B103270327 Requests increase in weight of U-235 exported from 240 to 245 ag Delegation of Cormission of European Communities 810320 ltr to DDE encl HANSEN.L E. Erron Nuclear Co., Inc. (subs. of Erron Corp.). 81703726 2pp. 07586.001.
- 8103270798 Forwards application for license to export 200 kg thorive per ur to Brazil. XELLY, J.P. General Electric Co. 81/02/27, 1p. 08034.117
- ---8103270800 Application by GE Lighting Business Group for license to (03270800 Application by occupating austrees droup for size export 200 is therium per ur to Brasil KELLY, J.P. General Electric Co. 81/02/16 ip. 08034:118.

- 8103310836 Forwards application by QA Co for license to export 110 Th-232 to West Oernany
  MORPY.W R General Atomic Co (subs of Gulf Oil Corp.) IEL-2
  81/03/16 1p 08061 091
- -- 9103310939 Application by GA Co for license to export 110 to The West Germany returning mail to owner for disposition.

  MONRY. W R General Atomic Co. (subs of Gulf Oil Corp ).

  IEL-2056 B1/03/16 1p 08061-092.
- B103310841 Application by Hestinghouse for license to export one 23744 BF3 detector & one 23691 housing assembly to France PDCHAL.W.F. Hestinghouse Electric Corp. ZE-40071. B1/03/17 08041 093
- 8103310044 License for GE Co to import 1,450 kg V. enriched to 4%,6 France. prance DEVINE.J.B. Assistant Director for Esport/Import & Internationa Bafeguards. B1/03/29 1p.
- 8103310846 Application by Ediow Intl Co for license to export 199 metric tons of depleted UF4 to United Kingdom RITCH J. Ediou Internetional Co 81/03/18 Ip. 08062:298.
- 8103310851 Ack receipt of Union Carbide 810210 application for exp reimport of 10 B kg of U enriched to 93 15% U-235 Recommends telaport or io mag of the second of the seco 10 08062 299
- --Bi033i0B57 License for Union Carbide Corp to import 10.8 kg U containing up to 10 kg U-235 contained in 55 HTR plate-type fuel elements from France
  DEVING.J.B. Assistant Director for Export/Import & Internation Safeguards 81/03/25 2pp. 08062.300
- 8103310063 Amend 1 to license for Exton Nuclear Co. Inc. increasing
- quantity of U-235 authorized for export from 240 kg to 241 tg. to West Oermany DEVINE.J.B. Assistant Director for Export/Import & International Bakeguerds B1/03/25 Ip.
- 8103310868 Amend 1 to license for GE Technical Bycs Co & GE, increa estimated value of goods to be exported to Taiwan
  DEVINE. J B. Assistant Director for Export/Import & International
  Bafeguards BDN90030. 81/03/25. ip
- 8103310974 Application by JT Baker Chemical Co for license to expo 9.11 lbs V.contained in 19.2158 lbs uranyl nitrate to J. T. Baker Chemical Co. (subs. of Richardson-Merrell, 710-201-3450. 81/03/04. ip. 08062:112. ZAPE. J Inc. )
- 8:033:09:2 Requests Executive Branch position re Boeing Co applica for Amend 9 to export license, adding Malaysian Airlines in Malaysia to list of ultimate consigness to receive emergency aircraft counterweights.

  DEVINE-J B Assistant Director for Export/Import & Internations
  Bardeguards Bi/03/25 1p. 08062-205.
- 8103310919 Executive Branch position re Segmodal Transport Corp. application for license to export 40 NBS U stds & 172 NBS Pu stds to Belgium for calibr of scientific equipment. Recommends license be amended. NOSENZO-L.V. State-Dept. of, Sureau of Oceans & Internati Environmentific Affairs, 81/03/23, 2pp. 08062:206.

## PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this indefindicates that the document is an enclosure to anothe document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

								CUD ICA
AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESS(CN	CATEGO
AAMSDT, M. II	8103200739	50-289 Q	AHEARNE, J. F.	8103020084*	COMM18810H	ANDERSON, T M	8103100613+	TOPREP
ABEL. J. B.	8103040481*	50-10 Q	AHEARNE, J F	8103050883	COMMISSION	ANDERSON, T. M.	@103100617#	TOPREP
ABEL, J. B.	8103110115	RECOD	AHEARNE, J. F.	8103100640	COMMISSION	ANDERSON, C R	8103390429#	50-244
ABEL J B	8103240711	50-237 0	AHEARNE, J. F.	8103100655*	COMMISSION	ANDERSON, T. M.	E83040E83	PR
ABEL, J. B.	8103060469*	50-10 G	AHEARNE J. F.	8103110085	NOTESTMEDS	ANDERSON, T H	8103160727	TOPREP
ABEL. J. B.	B103030769	50-10 V	AHEARNE, J. F	6103110119	COMM1881DN	ANDERSON, C. J.	B103090951	50-322
ABEL.J S.	8103050140	50-10 V	AHEARNE, J F	8103240138	50-170 U	ANDERSON, J M	8103100611	TOPREP
ABEL. J B	8103030860	50-237 P	AHEARNE J F.	8103110091	COMMISSION	ANDERSON, P L	8103040619	50-309
ABEL J B	8103040701	50-295 P	AHEARNE, J. F	8103240572	50-322 U	ANDERSON, O C	8103020422	50-409
ABEL. J. B.	8103050583	50-373 F	AHEARNE, J. F.	8103160970	CONMIGSION	ANDERSON, T H	@103100340	TOPREP
ABEL, J. S.	B10309066B	50-237 P	AHEARNE, J F	e103160619*	COMMISSION	ANDERSON, T. M	8103160257#	TOPREP
ABEL. J. S.	8103110367	50-249 P	AHEARNE, J F	8103160627*	COMMISSION	ANDERSON, T. H.	Ø103090498	TOPREP
ABEL.J 8.	8103200574	50-10 V	AHEARNE, J. F.	8103160633*	COMMISSION	ANDERSON, T. M.	8103130486	90-206
ABEL, J. S.	8103240390	50-10 F	AHEARNE, J. F.	8103160643*	NO1821MM02	ANDERSON, T. M	8103170361	TOPREP
ABERCROMBIE. H	8103040314	50-260 B	AHEARNE, J. F.	8103160648*	COMMISSION	ANDERBON, T. M	8103240310	50-206
ABERCROMBIE: H	8103240413	50-259 S	AHEARNE, J. F.	8103170306	CONMISSION	O CHINDCONA	0100200873	REGOD
ABERCROMBIE. H.	8103240435	50-259 8	AHEARNE, J. F	8103180400	COMITTERTON	andres. M	6103040805	FOLA
ABERCROMBIE, H	8103170546	50-259 R	AHEARNE, J. F	8103240124	50-322 U	ANDREWS, D. L.	8103050429*	50-369
ABLE, O. F	B103020330	XPORTLIC	AHUERO, C.	8103260607	50-361 D	ANDREWS D L	@103090795*	50-348
ABRAHAM, K	8103190326	PR	AKER, R. E.	8103310558*	50-295 B	ANDREWS, 1	8103150912	50-369
ABRAHAM, K.	8103170385	PR	AKI,K.	8103051001*	50-206 P	ANESMANBLEY, M	81030506364	50~313
ABRAHAM, K	R103190420	PR	AKIN, R. C.	8103240314+	50-206 P	ANG, W.P.	8103130172*	50-335
ABRAHAM, K.	8103190443	PR	ALBERT, R E.	8103040792*	FOIA	ANBPACH, K O	@103230671	27-39
ABRAMS, M.	8103170150*	50-320 R	ALBERT. A.	8103170248	50-220 G	ANSPACH, K. G.	0103230724	27-39
ABRAMS, R.	8103060341	PR	ALBRECHT, R. O	8103200532	50-275 H	APPEL.R.R	B103060124	40-8781
ABRAMS, R.	8103040369	PR	ALBRIGHT.C.L.	8103190531	50-289 H	APPEL R R	B103190795	40-8781
ABT. S. R.	8103160343	40-9102	ALDEN. W M	8103050218	90-277 R	ARCHER, V. E.	6105240245	FOIA
ABUAF, N	B103040979	NUREO	ALDEN. H. S.	8103200503	50-269 H	ARCHITZEL.R E	B103150991*	50-317
ADAMSON, E.	8103250581	PR	ALDRICH R. L.	B103270465	50-275 H	ARCHITZEL, R. F.	B103300367#	50-317
ADAMS, R. E.	8103230106	NUREQ	ALEXANDER, C. T.	8103120851	REB	ARIYOSHI.O.R	0103250501	PR
ADLER, B.	B103120747	PR	ALEXANDER, J	8103200733	50-440 0	ARLOTTO C. A	8103270112*	FOIA
ADLER R. H.	<b>@103090671</b>	50-289 T	ALEXANDER, J.	8103180629	50-440 G	ARLOTTO O A	8105180855*	ACRE
ADLER R. W.	8103050653	50-289 G	ALEXANDER, J.	8103270293	PR	ARMSTRONO, R. E	8103040242	FOIA
ADLER, R. H.	8103190628	50-289 G	ALLAN, J. M.	B103240374	1&E	ARNOLD, A. J.	8103130483*	50-317
ADLERIR. W	B103200715	50-289 0	ALLBAUQH, C.	8103170394	50-320 H	ARNOLD, R. C.	8103130547#	50-289
ADLER, V. E.	8103200675*	50-289 Y	ALLEN D. J.	81030301B5	40-7869	ARNOLD, R. C.	8103130552* 8103130557*	50~289 50~289
ADRAGNA, J. H.	8103190037	PROJ	ALLEN, D. J.	B103180027	40-8674	ARNOLD, R. C.		50~320
ADRAQNA, J. H	B103190037	PROJ	ALLEN, J.	8103250607	PR 50~289 H	ARNOLD, R. C. ARNOLD, R. C.	8103030737 8103130563*	50-289
AGEE, L. U.	8103180979#	REVIEW GRP	ALLEN, J. Y.	8103190486				
AGEE, J. R.	B103160624#	0A999	ALLEN C. R.	8103180519	50-275 H	ARNOLD, R T	8103100116	NUREG
AQUILERA, W.F.	B103090276*	TOARTHOO	ALLEN D. C.	8103500335	50-275 H	ARNOLD, L. E	8103230344	90-289
AHEARNE, J. F.	8103230722*	FDIA	ALLEN H. B.	8103190576	50-369 A	ARNOLD, L. E.	8103250411	90-289
AHEARNE, J.	8103270170*	FOIA	ALPERT 6.	3103190398*	50-320 P	ARONSON, A. L.	8103030433	REB
AHEARNE, J. F.	8103160093*	50-320 P	ALPINE, E. J.	8103130662*	70-143	ASHTON, A. H.	8103130013*	CONTRAC
AHEARNE, J. F.	8103030094	COMMISSION	ALGUIST, A E.	8103200699	50-275 H	ASKEY, E	8103270180	PR
AHEARNE, J. F.	8103240459	COMMISSION	AMARAL, J M	8103110131	REGOD TOPREP	ABP, I.	8103040607 8103040899*	NUREG
AHEARNE, J. F.	8103040357	COMMISSION	AMARAL, J. M.	@103190101 @103200459	50-289 H	ASPIN.L ASWELL.D.L	8103040849#	50~295 50~382
AHEARNE, J. F.	8103100155	COMMISSION	AMES, A. E.		50-133 H	ASWELL.D.L	8103030833	
AHEARNE, J. F.	B:03050764	50-320 U	AMIMOTO, P. Y.	8103040265*	50-155 R	ASWELL, D. L	8103040707	50~382
AHEARNE, J. F.	B103050775*	50-320 U	AMSTUTZ, S.	B103110474+				50~382
AHEARNE, J. F.	8103020060	COMMIBBION	ANDERSON, J. J.	B103060575* B103060571*	50-361 A 50-361 A	ABWELL, D. L. ASWELL, D. L.	8103130417 8103310870	50-382 50-382
AHEARNE, J. F.	8103020070*	COMMISSION	ANDERBON, J.	B103080571*	0A999	ASWELL, D. L.	8103170619	
AHEARNE, J. F.	8103020075*	COMMISSION	ANDERSON, D. G.	8103180824	BENIEH ORB	ASWELL, D. L.	8103170619	50-382
AHEARNE, J. F.	8103020078#	COMMISSION	ANDERSON, T. M	B103070536	by KEAIEM AUL	ASWELL, D. L ASWELL, D. L	8103240378	50-382
AHEARNE, J. F.	8103020080#	COMMISSION	ANDERSON, T. M	P103040379		mawatti D. L	0103540318	50~382

ACCESSION

BUBUECT CATEGORY

#### PERSONAL AUTHOR INDEX

SUBJECT

ACCESSION

ACCESSION

SUBJECT

AUTPOR	NUMBER	CATEGORY	POHTUA	NUMBER	CATEGORY	AUTHGR	NUMBER	CATEGORY
AUDETTE R F	81022307590	50-315 P	BARILES S	8103120795	PR	BAYNARD, P. Y	8103110699	50-305
AULICK, D	810350333	50-220 G	BARNES. I	8103140005.	OASSS	BAYNARD, P Y	8103170460	50-302
AULICK, D	6103509339	50-220 o	BARNES, I	8103100741*	QA997	Y 9.GRANYAE Y 9.GRANYAE	8103230737 8103230649	50-302 50-302
AULT.F H AULT.F H	8103110751 # 8103110744#	50-361 I 50-361 I	BARNES, 1 Barney, J	8103120601* 8103200433	0A999 50-289 H	BAYNARD, P Y	8103310392	20-305
AUCTIO H	81031107444	20-361	BARNET	8103200433	30-287 H			
AULUCK, R	8103260445	90-454 A	BASHETT, J.E.	8103150768	70-1621	BAYNE, J P	8102260568	50-333
AUSTIN H A	81032707594	70-135	BARATHOUSE, L. W	8103020835	RES	BAYNE, J. P.	8102260570+	50-333
AUSTIN, M. A	B103270763*	70-135	BARNTHOUSE, L II	8103050839	RES	BAYNE, J. P. BAYNE, J. P.	8103020376 8103020383*	50-333 50-333
AUSTIN.M A AUSTIN.M A	8103270541 8103270791	70-364 70-135	BARR.R.A Darrefill H	8103200539 8103360768	50-287 H 50-320 R	BAYNE, J P	8103020491	50-284
AOSITIC II A	81025,0121	70-133	DANKEYNCH	8103380760	50-320 K		4,0000	400
AUSTIN. M A	8103270270	70-135	BARRETT. L H	8103060513	50-320 R	BAYNE, J P	8103030555	50-266
AUSTIN M A	8103310674	70-364	BARRETT.L. H	8103090165	50-320 P	BAYNE, J P BAYNE, J P	8103030560# 8103040525	20-569 20-599
AUSTIN, M A AUTIO, M A	8103120136 8103170559	71~9070 50-29 8	DARRETT,L H BARRETT,L	8103060130 8103040691	50-289 P 50-320 5	BAYNE, J P	8103040560	50-286
AVANT. 0	8/07/300591	50~187 R	GARRETT. L H	8103110143	20-350 6	BAYNE, J. P	8103040641	50-286
				_,		_		
AVILA. II	B103120761	PR	DARRETT L H	8103110070	50-320 R	BAYNE, J. P.	8103030707 8103030712*	50-3 50-3
AXELRAD.M AXELRAD.M	B103200743 B103200743	50-376 0 50-376 G	BARRETT, L. H BARRETT, L. H	9103120921 9103170536	50-320 P 50-320 R	BAYNE, J P BAYNE, J P	8103030896	50-333
AYALA. R S	6103200699	30-275 H	GARRETT.L H	0103250105	50-320 R	DAYNE, J P	B103040697	50-286
AYERS, A L	8103110830	RES	GARRETT. L	8103200541	50-320 5	BAYNE, J P	8103270736*	50-333
						BANKS L. B	8103170381	50-286
AYERS,A L BACHMANN.R O	8103100144 8103120250	RES 50-70 G	BARTH E L BARTH C A	8103190504 8103310309	50-269 н 50-440 Q	DAYNE.J P Bayne,J P	8103170381	50-200
BACHMANN R. G	8103120230	50-70 0	BARTH C A	8103310320+	50-440 Q 50-440 Q	BAYNE. J P	B103130548*	50-333
BACHMANN, R. Q	8103170473*	50-70 G	BARTON, R D	8103330332*	CONTRACT	DAYNE, J P	0103190496	50-333
BACHMANN. R G	8103270695	50-70 O	BASDEKAS D L	8103050025	50-289 0	BAYNE, J P	8103240523	50-266
DACHMANN D A	81032706974	50-70 G	SAGDENAG P. I	01000000170	50-200 0	BAYNE, J P	8103530995	50~333
BACHMANNIR. C BACHMANNIR. C	81032706974	50-70 0	BASKIN K P	8103550501*	50-289 0 50-361 F	BAYNE, J. P.	8103240195	90-286
BACHOFER M	B103190529	50-289 H	BASHIN K P	8103050362*	50-206 F	BAYNE, J. P	8103270669	50-286
DADER. S	B103030783*	50-237 8	BASKIN K P	8103060541	A 16E-08	BAYNE, J. P.	8103270764	30-247
BADGER. C H	8103250755	PR	BASK IN: Y P	8103180593	A 19E-06	BAYNE, J. P	8103310487	50-286
BAFR.R L	8103110625	GEN TEC 15	BASKIN K P.	8103180598	50-361 A	BEACH, A B	8103260535+	50-458
BAER.T S	8103260737	27-39	BASKIN, K.P.	9103060636	20-50P L	BEA4.R H	8103050845	REB
BAER. T S	8103260743	27-39	BASKIN-K P	G103090398	50-206 P	BEAN.K A	8103120706	PR
SAGAGE 10.11	8103030498#	50-275 Q	BABAIN N P.	8103110548	90-361 A	BEARD, M. E.	8103170575	50-269
BAGAGL 10. H	8103180253*	90-279 G	BASKIN, K.P.	8103110550	90-509 b	BEATTY, R N	8103110830	RES
DAHN.R J	8103250247	50-367 R	BASAIN K P.	B103100390	50-361 A	BECHHOEFER C.	8102260292	50-358
DATER C.	8103190581	50-289 H	BASKIN, K P	B103110655	50-206 G	BECHHOEFER.C	8103020422	50-409
DAILEY.R J	8103050478*	50-247 G	9 N.NERZAG	8100100276	50-361 K	BECHHOEFER. C	8103040568	50-327
BAILEY, R. J	8103050271*	50-333 G	BASKIN, K. P	8103110725	50~361 A	BECHHOEFER. C	B103040574	90-38 <i>1</i> 90-329
DVITEA' H 1	8103050185	NUREQ	DASKIN. K P	8103110336	50-206 F	BECHHOEFER.C.	0103100337	30-324
BAILEY, R J	8103230913*	90-219 G	BASKIN. K P	8103110673	50-361 [	BECINGEFER. C	8103190627	50-409
BAILEY. D	8103200456	50-275 U	BABKIN K P.	8103240488	TOPREP	BECHHQEFER, C	8103190632	50-387
DAIN J N	8103110339	90-289 0	BASKIN K P	8103270680	50-206 P	BECHHOEFER C	8103270776	50-458
BAIR.O. D BAIR.G G	B103020365⇔ B103030661⇔	50-344 B 50-344 B	BABKIN K P BASKIN K P	0103240355 0103260545	90+206 F 50-361 K	DECHMOEFER.C.	8103240546 8103300247	50-358 50-496
ominio d	01030200012	30-044 0	ONSATIA IN I	0102500242	50-361 K	premoer and c	0105000647	00 170
BAIR C G	8103160478*	50-344 R	DASKIN K P	8103300335	50-361 D	BECHTEL. B. D	8103190104*	TOPREP
BAIRD, J 3	8103170373	341	BASKIN, K.P.	8103310495	50-206 P	BECK.O P	8103040750	50-151
BAISDEN, L BAISDEN, L	8102270365 8103040563	90-171 P CONTRACT	DASS.H E	61100100110	NUREO	BECK-G P BECKHAM, D. H	8103310465 8103110514	50-151 TOPREP
BAISCEN. L	B103040324	CONTRACT	N MIZZAG M MIZZAG	8103260369* 8103260368*	FDIA FOIA	BECKMAN, D. A	8103050383+	50-334
				070321,0802	, <b>01</b> h			
BAISDEN, L	B103100234	CONTRACT	BA581N-N	B103040537*	40-8610	BECKMAN, D	8103050669	50-334
BAISCEN.L. BAISCEN.L	8103120844 8103160559	CONTRACT	BV281M' V.	8103260281#	40-8610	BGEDERMAN, A	8103270126 8103270203*	PR PR
BAKER, R M.	8103240437	71-219	BATEMAN, W H BATES, A	8103300528* 8103100040*	50-354 0 50-327 0	BEEDERMAN-C. BEERS.R	8103050826*	PRM
BAKER, K R	8103130119+	50-315 Q	BATES. A	B103100046*	90-327 0 50-327 0	BEERS, R	8103050926*	PRM
5 6 1/2 PM 14 5								
BAKER, K. R. Baker, J. H	8103190278* 8103250261	50-255 0 NUREO	DATES, J W	8103240313#	70-27	BEJARANO, J. R. BELANGER, J. L	8103170456 8103130172*	50-275 50-335
BALALIS, C Q	B103030941 +	XPORILIC	BATH.F J BATH.F J	8103200665# 8103200675#	50-289 T 50-289 T	BELINGER, J. L. BELINGER, J. A.	8103130172*	50-335 50-416
BALALIS- C. O	8103030733	XPORTL IC	BATTLE L. C.	B103200875#	50-289 (	BELMORE, C. I	D103240186*	50-217
BALAMOTIS,P T	8103060557*	50-361 A	BAUER, T L	8103020368	50-192 P	BENAROYA, V	H103120204*	GEN TEC
BALCH, S. E.	8103180606	50-74D H	BALCO 1 '	0103010-0-		DENCHIES M	6103300436	50-289
BALDHIN, C A	81030303336	50-348 M NUREO	BAUER, T L BAUM, E A	0103240506 0101220150*	50-192 R 50-338 F	DENEDICT, M BENEDICT, D. E.	8103209625 8103020638	50-289
BALDHIN, W A	R103030654	50-70 G	BAUH E A	8103040385	50~338 F	DENNETT, A B	B103160624*	0A999
BALDAIN, H A	8103030654	50-70 0	BAUMAN, T. A	8103270759*	70-135	BENTLEY, B. Q.	8103170363	50-287
BALL.S J	8103240030	NUREG	BAUMAN, T A	8103270766*	70-135	BENTSEN, L	8103230675	50-466
BALLENTINE, J M	B10305079B	50-327 8	BAUNACK. H	8103230310*	50	BEOLETTO. J A	8103020428	90~361
BALLENTINE, J M	B103203542	50-327 R	BAUNACK, W	B103180868*	50-333 G 50-220 G	BERG.R.E.	B103040635	40-8585
BALLINGER.P L	B103070506*	50-29B R	BAUNACK W H.	B103270798*	50-333 0	DERG. 9	8103170585	50-269
BANDINI.E	8103200747	50-382 K	BAUSER, M A	B103110577	PR	BEROCREN, J. S	8103041017	TOPREP
BANGERTER.D H	8103050597	YPGRTL IC	BAUSER.M A	B103110577	PR	BEROCREN, J. B.	8103250130	WIRC
BANKS, B. A.	8103090590	PR	BAXLEY, 6 X	B103030795*	50-321 8	BEROMAN, B. M	8103190472	50-289
BANNER, A P	8103030044	FOIA	BAXTER, T A	B103130430	50-289 0	BERKE, M	9103200442	50-289
BARASH, M.	8103090812	NUREO	BAXTER, T A	B103130450	50-289 G	BERKLEY, D. A	8103160356	PR
BARDER G. N BARDER G	8103100670*	CONTRACT	BAXTER, T. A	8103190634	50-289 0	BERKOW, H N.	8103240050#	50-327 M160
Opposition (F	8103190524	50-259 Q	BAXTER, T A.	8103190634	90-289 Q	BERKON, H. H.	8103160233	HIGU
BARCLAY, M	8103230711	50-275 11	BAYOUTT, P	B103050907	RES	BERLADIA L.	8103120758	RES
BARDES C.R	8103160316#	LOCFR	DAYLESS, P D	6103030530	HUREO	BERMAN, M	B1032300734	50-369
BARHAM, C.D. DARHAM, C.D	8103100393	50-324 J	BAYNARD, PY	8103050844	71-5026	BERMAN, M	8103060673	REB
BARHAN, C. D.	8103190494 8103230645	50-261 J 50-324 J	DAYNARD, P Y	8103060247	50-302 0	BERMEL, J. K	8103270244 8103310924	PR NUREO
	G.00E30043	30-3E4 U	BAYNARD, P. Y	8103030747	50-302 F	BERNA, G. A	0103310454	HARLEY
BARI.R A	8103130169*	50-369 P	BAYNARD, P. Y	8103040589	50-302 R	BERNARD, 8. R	8103130005	REB
BARKER, N. R	B103160590#	0A999	BAYNARD. PY	8103090293	50-302 P	BERNSTEIN, S.	8103120645	PR
BARLEY, H BARLEY, H	8103030855# 8103090723#	50-320 G	BAYNARD, P Y	B103060903	50-302 P	BERRY, Q. T.	8103030808	50-286 50-286
BARNES, I	B103120785*	50-320 G GA999	BAYNARD.PY BAYNARD.PY	8103060512	50-302 P	BERTELL.R	8103050396 8103050300*	FOIA
	P.00.80.20*		SHITHWON'S I	<b>8103100</b> 0347	50-302 P	מבת ובנבית	9105030300*	1 0 1 17

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSICN NUMBER	SUBJECT CATEORRY	AUTHGR	ACCESSION NUMBER	SUBJE CATEG
BERTRAND, A.R. BESKID, N.J. BETANCOURT, B. BETENHAUSEN, L. BETTENHAUSEN, L.	8103060011* 8103110329 8103260862 8103260365* 8103200582*	70-1277 40-299 50-275 A 50-334 G 50-213 G	BOODEN. O BOODEN. O BOODEN. O BOODEN. O	8103060137 8103090048 8103050489 8103160241 8103230559	40-1162 40-1162 40-1162 40-1162 40-1162	BGUCHEY, G D BGUCHEY, O, D BGUGHEY, O, D BGUGUARD, M, L BGUGUARD, M, L	8103300005 8103300075 8103310912 81032612044 8103300014	PR 50-347 50-397 COM/15 PR
BETTENHAUBEN, L BEVERLY, R. Q BEVILL, T BEYEA, J BEYEA, J.	8103190676* 8103090535 8103120344 8103230628* 8103180630	90-317 G WASTE MGT 50-461 U 50-369 G 50-289 T	BOODEN. O BOODEN. O BOODEN. O BOODEN. O	8103250565 8103250743 8103250006 8103261213 8103270153	40-1162 40-1162 40-1162 40-1162 40-1162	BOWDEN, D. D. BOWDEN, D. D. BOWEN, V. F. BOWERS, E. S. BOWERG, E. S.	8103040100 8103200357 8103140514 8103130405 8103130420	NURED NURED RES 50-275 50-514
BIALIK,E 1 BIALIK,E I BIBA,H E BICKWIT,L BICKWIT,L	8103060361 8103060369 8103240743* 8007010587 8103160485*	PR PR 50~335 0 50~247 P COMMISSION	BOODEN, 0 BOOOS, L. A BOAN, M. P BOAN, R. J BOAN, R. J	8103270123 8103260210 8103310924 8103030685 8103100478	40-1162 PR NUREQ 50-367 R 50-367 R	BOHERS.E.S BOHMAN.C.E DOMSER.J.S BOYD.D.C	8103130453 8103240542 8103240221 8103120773 8103040066	50-142 50-142 50-293 PR 50-409
BICKWIT. L. BICKWIT. L. BICKWIT, L BICKWIT, L BIESMAN, S. R.	8103270931# 8103130441 8103130630 8103200845# 8103030424	50-275 U 50-247 H 50-367 O 10CFR RES	BCHN.R J BOITEL,E.C BOITEL,E.C BOLLING,L.A BCLLING,L.A	8103240391 8103030663 8103030692 8103020131 8103020152	50-367 R 50-30 R 50-185 R 1&E 1&E	BOYD. D. C BOYD. D. C BOYD. D. C BOYD. D. C BOYD. D. C	8103040054 8103030942 8103040038 8103030425* 8103090105*	50-315 50-237 50-155 50-151 50-264
BIGELOW, M M BILLETER, T. R. BILLUPS, C W BINGGELI, B. L. BIRK, A J	8103240434 8103100072 8103230074* 8103100596* 8103200507	50-341 A NUREQ 50-247 Q 50-275 S 50-289 H	BOULINGLE A BONKER, R. A BONNER, E. B BOOK H. E. BOOK, H. E.	8103020162 8103200416 8103190428* 8103030488* 8103030495*	1&F. 90-289 H PR 90-326 Q 90-326 Q	90YD. D C 80YD. D C 90YD. D C 80YD. D C 80YD. D C	8103050403+ 8103120407+ 8103160794+ 8103161123+ 8103240392+	50-155 50-315 50-315 50-2 50-409
DIRKEL, R. A BISCHOFF, C. A BISHOP, T. H. BISHOP, C. J. BISHOP, T. W	8103030974 8103260909 8103180093* 8103120637* 8103250047*	50-369 F 50-528 0 50-508 G 50-275 G 50-508 G	BODALH E BOOKLH E BOOKLH E BOOKLH E BOOKLH E	8103030307* 8103030449 8103100004 8103100010* 8103040246	50-326 Q 50-326 Q 50-133 Q 50-133 Q 50-89 Q	DDYD.D C BDYD.D BGYER.V S. BRADST W.A BRACKEN.X W	8102190511 8103190639 8103190566* 8103250567 8103050389	50-254 50-254 50-352 PR 71-9010
81840P.T U 81840P.C J. 81840P.C.J. 81840P.C.J. 81840P.B.L	#84040246# 8102260162 9760306018 9760306018 1860636019	50-508	BOOK, H. E. BOOK, H. E. BOOK, H. E. BOOK, H. E. BOOK, H. E.	8103040261* 8103100403* 8103100395 8103100454 8103100464*	50-206 50-328 50-328 60-206 60-206	BRADBURY, R. B. BRADBURY, R. B. BRADBURY, R. B. BRADBURY, R. B. BRADBURY, R. D.	6103070334 6103060731 6103110312* 6103110303 8103250691	PR 90-322 50-322 PR
818H02, V 818H02, C. J. 818H02, C. J. 818H02, C. J. 818H02, C. J	8103190515 8103090516 8103110452 8103120483 8103120530	50-289 H 50-443 O 50-338 G 50-466 G 50-466 Q	000k, H E. 800k, H E 800k, H E 800k, H E 805k, H E	6103230168* 8103250144* 8103230159 8103180965 8103180973*	70-1257 30-206	BRADENBURG, B. L BRADEORD, P. A. BRADEORD, P. A. BRADEORD, P. A. BRADEORD, P. A.	8103030733* 8103020087* 8103170753* 8103170746* 8103050513*	50-3 F01A 50-320 50-320 COMMISS
0.904818 818406-C.J 818486-C.J 818486-C.J 818486-C.J	8103180617 8103180638 8103200830 8103250407 8103250436	50-272 0 50-272 0 50-443 0 50-463 0 50-488 0	BOOK, H E BOOK, H E BOOK, H E BOOK, H E BOOK, H E	8103180192* 6910816018 69103180594 81031805991 810328031	50-113 Q 50-113 Q 50-206 Q 50-206 Q 50-361 Q	BRADFCRD.W H BRADFGRD.P A BRADFGRD.P A BRADFGRD.P A	8103250615 8103170731 8103170731 8103170731	50-348 50-287 50-289 50-320 50-320
818HDP.C.J. 8195ETT.P. 8198INGER.R.H 8188INGER.R.H 8188INGER.R.H	8103260805 8103090658* 8103030342 8103020099 8103180792	50-463 0 70-135 40-8064 40-8064 40-8064	800K, H E 800K, H E 800K, H E 800K, H E	8103250027 6103240700 8103240708* 8103250136 8103180348*	50-361 9 50-312 9 50-312 0 50-206 0 70-2317	BRADLEY, D BRADLEY, R T BRADLEY, E J BRADLEY, E, J BRADLEY, E, J	8103110364* 8103040100 8103130242 8103170560 8103170584	50-311 NUREQ 50-277 50-277 50-171
BITEL, J. B BIXEL, D. A BLACK, B. P. BLACK, B. P BLACK, R. L.	8103030792 7905310449 8103250473* 8103250469 8103120298	50-10 R 50-155 P 71-425 71-425 50-466 G	BOOK, H E BOOKS, P A BOOKS, P. A BOOKS, J M BOOYH, J. E.	B103180333 B103130736# B103130732# B103030425# B103170397	70-2317 50-320 H 50-320 H 50-151 G 50-289 H	BRADLEY, E J GRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J	8103190148 8103190524 8103190563 8103190569 8103190650	50-277 50-352 50-352 50-352 50-352
BLACK, R. L BLACK, R. L BLACK, R. L. BLACK, R. L. BLACK, R. L.	8103160168 8103170539 8103170102 8103260104 8103310103	50-466 0 50-466 0 50-466 0 50-466 0 50-466 T	BORDENICK, B H BORDENICK, B H BORES, R. J. BORES, R. J. BORES, R. J.	8103040370 8103270692 8103110542* 8103050382# 8103110546*	50-514 0 50-514 0 50-286 0 50-320 0 50-387 0	GRADLEY, E J. BRADLEY, E J. BRADLEY, E J. BRADSHAW, J. GRADHEITA, I. H	8103260136 8103230652 8103270403 8103200600 8103200463	50-463 50-352 50-277 50-275 90-275
BLAKE, J. BLAKELY, J. E. BLAKE, J. J. BLAKE, E. L. BLAKE, E. L.	8103050082* 8103040671 8103120448* 8103130522 8103200720	50-416 Q RES 50-280 Q 50-287 T 50-287 Q	BORGER, B BORGMANN, E. A BORGMANN, E. A BORGMANN, E. A BORGMANN, E. A	8103200605 8103160984* 8102040395 8103110768* 8103230120*	50-287 H 50-358 Q 50-358 F 50-358 A 50-398 Q	BRAILE.L.W BRANLETT.L S BRANLETT.L S BRANMER.J BRANCH.M.U	8103040538 8103230569* 8103310590* 8103090349 8103240392*	NUREO 50-313 50-329 50-409
BLAND, J. B BLAND, J. S. BLAUFVSB, F. BLECHER, M. A BLEY, D. C.	8103120461* 8103300367* 8103260579 8103190441 8103020220*	50~317 0 50~317 0 50~462 0 50~289 H 50~327 A	BORGMANN E. A BORGMANN E. A. BORGMANN E. A BORGMANN E. A BORGMANN E. A	8103250185 8103100436 8103110456 8103250138 8103200405	50-358 A 50-358 A 50-398 A 50-398 G 50-358 A	DRANDENBERG, B. BRANDEN, R. J BRASHER, J. W DRAVID, C. BRAUN, R. A.	8103040483 8103140847* 8103130529* 8103030118* 8103170548	50-247 FOIA 50-269 70-2838 50-289
BLOSBOM, J. N. BLOUCH, A. R. BLOWERS, L. BLUBAUCH, R. E. BLUBAUCH, R. E.	8103040473 8103180186* 8103200533 8102230689 8103030858	40-8452 50-277 0 50-275 H 40-4492 40-4492	BORGHANN E. A BORGMANN E. A BORGMANN E. A BORGOUIST M BORIS W R	8103310213 8103310274 8103310383 8103120767 8103180558	90-338 F 50-338 A 90-358 H PR 50-289 H	BREAUX.D.G. BRECHBIEL.R.C BRECHENTIDGE.P BREHMER.M.L. BREITHAUPY.G.L	B103040270* B103050728* B103200620 B103270443 B103200835	0A579 70-1402 30-287 50-338 50-287
BLUM, B. BLUM, B. BLUM, B. BLUM, B. BLUM, B.	9103050492+ 8103230622+ 8103230610 8103230610	FOIA 50-367 0 50-369 0 50-369 0	BORST, F.J. BORYSOURIZ, I.A. BOSSENMAIER, W BOSSING, E.N BOSTON, S.	8103020775 8103170352 8103040328 8103120048 8103200635	NUREO 50-267 H 50-312 P 70-2317 50-289 H	BREMER.S. GREWER.H E. GREZENSKI.F T BRICKLEY.R H URICKLEY.R H	8103040549* 8103110775* 8103240087* 8103140424* 8103100751*	50-361 50-361 FDIA GA999 GA999
BLYTHE, R. Y. BOATHRIGHT, D. E BOCCID, J. L. BODE, R. M. BOODEN, O.	8102270563 8103200699 8103040607 8103090059# 8103060119	PT21 50-275 H NURE0 40-1162 40-1162	BDUCHEY, O. D. BDUCHEY, O. D. BGUCHEY, O. D. BGUCHEY, O. D. BOUCHEY, O. D.	8103310520* 8103090358 8103030613 8103030857 8103260033	50-397 F PR 50-397 8 TDPREP PR	Bridenbauch, D Brigob, L. E Bright, O. O Brinman, R. E. Brinman, R. E.	8103231058* 8103190308* 8103190692 8103260513* 8103260410*	CENTRAC 50-219 50-387 FOIA FOIA

## PERSONAL AUTHOR INDEX

					_			
AJTHCR	ACCESSION NUMBER	SUBJECT CATEGERY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GATEODA
BRIAKERHOFF, J	8103160530+	CONTRACT	BRUMER.E J	8103050383#	50-334 0	BUTLER, S. D. BUTTACAVOLE, A. BYRAN, J. K. BYRCN, P. M. CABLE, J. W.	8103240146*	50-327
BRITTIDAM, R L	8103230717	50-170 G	BRUMER.E J	8103230394	50-247 0		8103050973	PR
BRITTIDAM, R L	8103230718+	90-170 G	BRUMER.E J	8103160304	50-245 0		8103180459	50-483
BROADHURST, M E	8103200639	50-289 H	BRUMER.E J	8103190301	50-219 0		8103050412*	50-341
BROCKETT, T	8103120623	1&E	BRUMER.E J	8103200227	50-27 0		8103050623	50-287
BRCEHL D J BRDEHL D J BRDEHL D J BRDEHL D J BRDEKITT O	8102231108 9102050790 8103240514 9103260592 8103310838*	90-344 0 50-344 P 50-344 F 50-344 P CONTRACT	ERUMER.E J BRUMER.E J BRUMER.E J BRUMER E J BRUMER E J	8103050277 8103180656 8103270782 8103180157 8103170662	50-334	CADENABBO.R.J CADWELL.J CADY.O.W CADY.O.W	8103110704* 8103050385 8103160604 8103050780 8103050780	50-341 Reb Reb 50-70 50-70
BROMBERO, B	8103040911	CONTRACT	BRUINER, E J	8103190846	50-271	CADY, 0 H.	8103050662	50-70
BRCMBERO, B	9103200789	CONTRACT	BRUNNER, E J	8103200576		CADY, 0 H.	8103270479	50-70
BRCMBERO, B	8103270980	CONTRACT	BRUNNER, E J	8103230250		CADY, 0 H	8103270548	90-70
BROMBERO, B	8103250448	NUREO	BRUNNER, E J	8103270798*		CAHILL, H. J	8101220618*	50-3
BROMM, R. D	8103110836	RES	BRUNNER, E J	8103300354		CAHN, A. L.	8103060751	PR
BROPILA D BROWS J C BROWS J C BROWS J C	8:03:00:54 8:03060432 8:03060443 8:03:030622 8:03:60683	RE8 50-286 G 50-286 G 50-286 R 50-288 R	BRUMER.E J BRUMER.E J BRUMER.E J BRUMER.E J BRUSVEM.A D	8103200761 8103200524 8103230684 8103240376 8103200215	50-329 0 50-329 0 50-309 8 50-293 9 50-263 I	CAIN.C.L CAIN.J CALDER.W. CALDWELL.R.A CALLAHAN.D.	8103240407 8103240407 8103090373 8103240205* 8103120679	FOIA WABTE MG PR 50-267 PR
BRONS. J C BRODAS, E II BRODAS, E H BRODAS, E H DROCH, K IF	8103250515 8103100053* 8103130217* 8103200038* 8103340247*	50-286 S 50-239 3 50-251 0 50-261 0 9A999	BRYANT, J.C. BRYANT, J.C. BRYAN, J.K. BRYANT, J.C. BRYANT, J.C.	8103040056* 8103050217* 8103180978 8103040087* 8103050877*	50-413	CALLAHAN C J CALLAHAN C J CALLAN L J CALTAOTRONE, T CAMPBELL D. R.	8103120661* 8103200367* 8103231026* 8103170435 8103100346*	50-317 50-317 50-313 50-287 50-315
08099.10	8103180880+	50-320 P	BRYAN, J K	8103050192*	50-483 0	CAMPBELL.R M CAMPBELL.R H CAMPBELL.R H CAMPBELL.R D CANNADAY.F.X.	8103190497	50-287
08095.10	8103180973+	50-320 P	BRYANT, J C	8103090503*	50-413 0		8103240677	WABTE MG
08098.10	8103180864	50-320 P	BRYANT, J C	8103260552*	50-400 0		8103240991	WABTE MG
09098.00	8002120122+	FOIA	BRYAN, J K	8103030889	50-483 M		8103240095	50-295
09098.00	8002120133+	FOIA	BRYAN, J K	8103100128	50-483 8		8103180802	40-8663
BROWN, R. L.	8103130069*	0A999	BRYAN. J. K	B103110797*	50-483 0	CANNER, I.E. CANNER, I.E. CANNON, J.E. CANNON, J.E. CANTER, H.L.	8103270392	50-29
BROWN, C. H.	8103030335	50-263 8	BRYANT. J. C	B103030854	50-491 8		8103270661	50-29
BROWN, R. E.	8103020124*	50-10 H	BRYAN. J. K	B103120175	50-486 8		8103050841	Btate Pr
BROWN, R. A.	8103103700	40-0129	GRYAN. J. K	B103136040	50-483 8		8103120297	State Pr
BROWN, R. A.	8103100705	70-1997	GRYAN. J. K	B103160749	50-483 8		8103050575*	50-312
BROWN R A	8103100711	40-8151	BRYAN, J. K	8103160714	50-483 C	CANTER.H L CANTRELL.F 8 CANTRELL.F.8 CANTRELL.F.9 CANTRELL.F.8	8103030154*	50-312
BROWN E. J	8101150319	50-206 P	BRYANT, J. C	8103240819*	50-321 G		8103240308*	50-438
BROWN R L	8103120393+	0A999	BRYAN, J. K	8103240259	50-483 A		8103050348*	50-438
BROWNING R F.	8103020120+	50-10 H	BRYAN, J. K	8103310217	50-483 A		8103110521*	50-438
BROWN O D	8103170235+	50-498 O	BUCHACLZ, R. H	8103200221	TOPREP		8103250204*	50-438
DROWN, O. D	8103170242*	50-458 G	BUCHHOLZ, R H	8103200315	TOPREP	CANTRELL, F. 8. CANTRELL, F. 8. CANTRELL, F. 8. CAPHTON, D. L. CAPHTON, D. L.	8103240162*	50-518
ROWN, O. R	8103170226	50-458 G	BUCHHOLZ, R H	8103110168	TOPREP		8103240716*	50-438
ROWN, C. R	8103010349*	50-263 G	BUCHHOLZ, R H	8103180584	TOPREP		8103270104*	50-259
ROWN, C. N	8103130303*	50-263 G	BUCHHOLZ, R H	8103200580	TOPREP		8103030365*	50-334
ROWN, EE, V. L	8103090400*	50-263 G	BUCK, P	8103110538	50-338 P		9103200582*	50-213
ROWN C H	8103020591	50-263 B	BUCKALEW, W H	8103060587*	50-413 A	CAPHTON. D. L	8103190676*	50-317
ROWN H H	8103020400	50-275 G	BUCKHAM, J A	8103110568	PR	CAPONE, D.	8103050557*	50-482
BRGWN R E	0103050570	50-309 O	BUCKLEY, R	8103090087	71-420	CAPPUCT, A. J	8103110281	50-329
BROWN R E	8103050579+	50-307 G	BUCKLEY, R	8103230112	50-275 E	CARBAUGH, E. H	8103120408*	50-331
BROWN F	8103170494	50-289 H	BUCKNER, J T	8103020624	NUREO	CARDINAL, E. V.	8103180583	50-498
BROWN F	6103170508	50-275 H	BUDTIK, D.K	#103240449	50-329 A	CARDONE, A. T.	8103040301*	50-133
BROWN G O.	6103250425	50-459 G	BUDTIK, D.K	#103240454*	50-329 A	CARE, H. J.	8103200565	50-289
BROWN D W.	6103180533	50-490 G	BURDDIN, J.F	#103250004*	50-397 G	CAREY, J. J.	8103050702	50-334
BROWN H H.	6103260788	50-275 G	BURDESS, B.L	#103070799*	50-282 G	CAREY, J. J.	8103050705*	50-334
BROWN H H.	6103260788	50-275 G	BURDESS, B.L	#103176058*	50-282 G	CAREY, J. J.	8103050708*	50-334
BRCWN, Q. D. BROWN, Q. D. BROWN, H. H. BROWN, H. H.	8103230650 8103240193 8103260223 8103260807 8103260807	1&E 50-267 G 50-458 G 90-275 G 50-275 G	BURGER, R E BURGER, J F BURGER, J F BURGIN, R. E BURXE, D J	8103170686 8103110509 8103260121 8103300366 8103240342*	70-1416 PR 50-257 0 70-1398 50-280 G	CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J.	8103050710* 8103050713* 8103050717* 8103050722* 8103050730*	50-334 50-334 50-334 50-334 50-334
BROWNE M BROWNE M BROZIRIE BRUGGERIR M BRUGNERIE J	8103240512 8103260764 8103181142* 8103180552 8103050350*	50-355 Q 50-329 G 70-754 50-186 S 50-334 Q	BURKE, D. J. BURKE, J. 9 BURN, P. BURNETT, J. T. BURNETT, P. T.	8103190328* 8103030900 8103110460 8103160479 8103130172*	50-283 G 50-335 H 50-201 R 40-8084 50-335 G	CAREY, J. J. CAREY, M. H. CAREY, W. M. CARFAYND, B. P. CARLISLE, C. S.	8103050736* 8103130389 8103310471 8103130374 8103110462	50-334 50-271 50-271 RE8 PROJ
BRUMMER, E U	8103180640*	50-220 G	SURNETT, P T	8103240733*	90-338 Q	CARLSON, R. V.	8103270763*	70-135
BRUMMER, E U	810320058!*	50-213 G	SURNETT, R F	8103180670	70-1151 "	CARLSON, R. T.	8103200071*	50-352
BRUMMER, E U	8103200577*	50-213 G	BURNS, 8 O.	8103060271	50-409 P	CARLSON, R. T.	8103300011*	50-410
BRUMMER, E U	8103190666*	50-213 G	BURNS, R, O	8103180692	90-289 H	CARLSON, R. T	8103040345	50-271
BRUMMER, E U	81032302754	50-333 G	BURSTEIN, S	8103290166*	50-266 F	CARLSON, R. T.	8103050803	50-387
BRUNNER, E. J	9103050784	50-220 G	OURBTEIN, S	8103100190	50-266 F	CARLEGIN, R. T.	8103270366*	50-220
BRUNNER, E. J	9103050792	50-333 G	BURSTEIN, S	8103260657	50-266 F	CARLEGIN, R. T.	8103060304	50-322
BRUNNER, E. J	9103060500	50-307 G	BURSTEIN, B	8103260667*	50-266 F	CARLEGIN, R. T.	8103180204	50-289
BRUNNER, E. J	9103180172*	50-277 G	BURSTEIN, B	8103270430	50-266 F	CARLEGIN, R. T.	8103180674	50-354
BRUNNER, E. J	9103190863*	50-271 G	BURSTEIN, S	8103300177	50-301 P	CARLEGIN, R. T.	8103160156*	50-423
BRUNNER, E J	8103050241	50-213 0	BURBTEIN, 8	8103310218	90-266 F	CARLEON, R. T.	8103160145	50-423
BRUNNER, E J	8103120640	50-317 0	BURTNETT, J	8103120737	PR	CARLEON, R. T.	8103190288	50-289
BRUNNER, E J	8103300361*	50-317 0	BURWELL, 8 B	8103050720	90-424 A	CARLEON, R. T.	8103100158	50-423
BRUNNER, E J	8103050294	50-27 0	BURWELL, 8, B	0103050442	90-445 A	CARLEON, J. D.	8103180913*	50-344
GRUNNER, E J	8103180684	50-284 0	BURWELL, 8 B	8103090100	50-445 A	CARLEON, R. T.	8103180092	50-271
BRUNNER, E J	8103180173	50-322 0	BURWELL. 8	8103190145	50-275 A	CARLEON, R. T.	8103100145	50-354
BRUNNER, E J.	8103190042	50-29 0	BUSHEM!, J	8103130480	50-367 Q		8103100165	50-352
BRUNNER, E J.	8103190085	50-272 0	BUSTICN. D R	8103260121	50-259 Q		8103100181	50-387
BRUNNER, E J	8103190473	50-317 0	BUTLER. S. D	8103040593*	50-327 Q		8103200056	50-352
BRUNNER, E J	8103050337	50-334 0	BUTLER. S. O	8103100121*	50-327 Q		8103060315	50-412

CARLSON R T CARLBON R T CARLBON R T CARLBON R T CARLBON R T	8103170892 8103100272 8103100278 8103100265 8103100288	50-272 0 50-423 8 50-387 8 50-352 8 50-387 8	CAGEY, S B CAGEY, S B CAGEY, S B CAGEY, S B CAGEY, S B	8103130396 8103130448 8103200722 8103200722 8103200722	50-361 0 50-361 6 50-361 0 50-361 0	CHILK B J CHILK B J CHILK B J CHILK B J CHILK B J	8103120633 8103170694 8103170690 8103030389 8103030377*	50-273 10CFR 10CFR 50-413 50-272
CARLBON, R. T. CARLEON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	8103300193* 8103060234 8103160222 8103160243 8103190704	50-352 0 50-443 B 50-354 S 50-355 S 50-352 B	CABBIDY, L. M CABBIDY, L. M CABBIERE, J. N CABBIERE, J CABTRO, Q.	8103180602 8103180601 8103060071 8103170020 81031700364	COMMISSION FOIA 70-820	CHICA, 8 J CHILA, 8, J CHILA, 8, J CHILA, 8, J CHILA, 8 J	8103140497 8103190290 8103110500 8103140201 9103190109	100FR 50-320 50-155 LOCFR XPDRTL
CARLSON, R T CARLSON, R T CARLSON, R W CARLSON, R T CARLSON, R T	8103200001 8103200497 8103110652 8103270351 8103270397	50-412 8 50-355 8 71-9010 50-220 Q 50-443 Q	CATCHPOLE, Q J CATCHPOLE, Q J. CATE, C. L. CATTON, I. CAVANAUGH, H.	B103130457 B103310404 B103020220* B103040326 B103100456	40-8693 40-8693 50-329 A 50-142 F 50-313 V	CHILKIS J CHILKIS J CHILKIS J CHILKIS J.	8103250095 8103160286 8103240122 8103250089 8103250102	10CFR YPORTL1 10CFR 10CFR 50-320
CARLSON, J D CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8103250015* 8103270331 8103300003 8103300050 8103250443*	50-344 Q 50-387 B 50-410 Q 50-387 B 50-450 Q	CAVANAUOH, H. CERBONE, R. J. CERMAX, J. CERRAJERO, F. A CHACKES, K. M	8103090435 8103040579 8103050557 8103270058 8103130589	50-368 P Nureo 50-482 A Regod 50-483 O	CHICK: B J CHICK: B J CHICK: B J CHICK: B J CHICK: B J	8103180612 8103190589 8103231037 8103260468 8103250267	50-364 50-471 100FR 50-320 REVIEW
CARLBON, R. T CARPENTER, J M CARRICK, J CARROLL, J T CARTER, J	8103300520 8103030530 8103260829 8103280182 8103270010#	90-354 Q NUREQ 90-294 F 90-219 P COMMISSION	CHACKEB, K. M.	8103130589 8103120386 8103120386 8103120386	50-463 0 50-463 0 50-463 0 50-463 0 50-483 0	CHILK.B. J CHILK.B J CHILSON,V T CHILSON,V T	8103230547 8103250437 8103250437 8103130394* 8103020414	50-295 50-269 50-443 50-250 50-443
CARTER, L. R. CARTER, L. R. CARTER, J. M. CARTER, R. B. CARTER, R. B.	8103230375* 8103230386* 8103160356 8103240225 8103240233*	50-269 P 50-269 P PR 50-184 R 50-184 R	CHAFFEE, A CHAILLE, C. E. CHALMERS, P. M CHAMBERLAIN, D CHANDRABEKARAN	810325C040* 8103240419* 8103190094* 8103100731* 8103040316*	90-205 0 90-312 F CONTRACT 0A9P9 90-280 R	CHINERY,M A. CHINNERY,M CHOU,C M CHOULES,N C CHRISTIE,H F	8103170330* 8103230533 8103040511 8103050394* 8103110698*	50-443 50-443 NUREO 50-294 50-361
CARTURIONT, H R	8103030801* 8103020518 8103020522* 8103100627 8103100632*	50-338 R 50-339 B 50-339 B 50-339 B 50-339 B	CHANDLER.L J. CHANDLER.L J. CHANDLER.L J. CHANDLER.L J. CHANDLER.L J. CHANDLER.L J.	8103150240* 8103150260 8103150264 8103150263	50-361 E 50-361 0 50-361 0 50-361 0 50-361 0	CHRISTOPHER R. CHRISSOTINGS. N CHRISTIANSON. W CHRISTIANSON. W CHRISTIE. M. F	81031905614 8103040474 8103020695 8103040128 8103110713*	50-265 50-231 50-331 50-34
CARTHRIGHT H R	8103110461 8103110468* 8103170439 8103170444* 8103170570	50-339 8 50-339 8 50-338 8 50-338 8 50-339 8	CHANDLER, L. J. CHANG, M. K. CHAPLIN, B. D. CHAPLIN, B. D. CHAPLIN, B. D.	8103110328 8103100076 8103030667* 8103100556* 8103120639*	90-361 0 NUREQ 90-320 B 50-320 B 50-320 S	CHRISTIANSCN, W. CHRISSOTINGS, N. CHRISSOTINGS, N. CHRISSOTINOS, N.	8103050402* 8103050272* 8103150124* 8103160544* 8103120361	50-331 50-254 50-331 50-254 50-402
CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, W R CARTHRIGHT, N R	8103170574* 8103170434 8103170437* 8103240489 8103240495*	50-339 B 50-339 B 60-339 B 50-338 B 50-338 B	CHAPLIN, 8. D. CHAPLIN, 8. D. CHAPMAN, R. R. CHAPMAN, K. R. CHAPMAN, L. D.	8103170565* 8103170565* 8103020045* 8103180091 8103050869	30-320 8 30-320 8 FOIA BECY RES	CHRISSOTINOS, N CHRISTENBURY, E CHRISSOTINOS, N CHRISSOTINOS, N CHRISTIANSON, F	8103170369 8103050674 8103190511 8103190639 8103310717	50-254 50-275 50-254 50-254 50-331
CARTURIONT, W. R.	8103240524 8103240529# 8103240558 8103240561# 8103250481	50-336 8 50-338 8 50-338 8 50-338 8 50-339 8	CHAPMAN, R. H. CHAPMAN, L. D. CHAPMAN, L. D. CHARLEB, B. CHARLEB, E. K	8103120761 8103020674 8103120860 8103270816 8103250236	RES NUREG RES NUREO 50-287 O	CHRIBTENBURY, 6 CHROSTOHSKI, J. CHUNG, J CHUNG, J H. CHUNG, J H	8103270640 8103030664 8103230310• 8103180689• 8103270788•	70-2623 NUREG 50-333 50-286 50-272
CARTHRIGHT H R	8103250489* 8103240755 8103240760* 8103240832 8103240835*	50-339 8 50-339 8 50-339 8 50-339 8 50-339 8	CHARNOFF, Q. CHARNOFF, Q. CHABE, J. W. CHABE, J. W. CHABE, J. W.	8103030866 8103030566 8103120770* 8103240691* 8103270104*	50-220 0 50-220 0 50-257 0 50-259 0 50-259 0	CHWASTYK. J CILLIS.M. CILLIS.M CILLIS.M CIPPOLA.A J	8103190590 8103030507+ 8103190464* 8103240708+ 8103120513	50-289 50-326 90-206 90-312 40-3392
CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R.	B103260842 B103260852* B103310540 B103310570 B103310573*	50-338 B 50-338 B 50-339 B 50-339 8 50-339 B	CHABNOFF, B. A CHAU, H. CHAVEY, E. M. CHEATUM, E. L. CHECK, P. S.	8103200714 8102060467 8103200414 8103110512 8103110133*	27-39 GEN TEC 18 50-289 0 50-466 0 COMMISBION	CLARDY.L. B CLARDY.L. B CLARM.A. T CLARME.E. T CLARM.E. T	8103050402* 8103190122* 8103250178 8103030182 8103160509	50-331 50-331 70-1308 PR PR
CARTURIONT, N. R. CARTURIONT, N. R. CARTURIONT, M. R. CARTURIONT, N. R. CARTURIONT, N. R.	8103310574 8103310578* 8103310579* 8103310430 8103310433*	50-339 8 50-339 8 50-339 8 50-339 8 50-339 8	CHEN, B. C. CHENG, H. B. CHENG, H. B. CHERRY, M. M. CHESTER, R. D	8103260039 8103030433 8103180816 8103030689 8103160084	NUREG REB REB BO-454 G REB	GLARK, R. A. Clark, R. A. Glark, R. A. Clark, R. A. Clark, R. A.	8103030091 8103020728 8103020732+ 8103020739+ 8103030871	50-335 50-318 50-318 50-316 50-285
CARTHRIGHT N R. CARTHRIGHT N.R. CARUBO R. CARUBO R. CASE E. Q.	8103310552 8103310557* 8103100197 8103100776 8103120860*	50-338 8 50-338 8 50-29 P 50-213 P 50-206 H	CHEBTNUT, B. CHEVERTON, R. D. CHIANGI, N. J. CHIANGI, N. J. CHIANGI, N. J. CHIANGI, N. J.	B103200666* 7909070116 B103110600 B103110716 B103230745	90-289 T RES 90-400 B 90-400 S 90-400 S	CLARX. R. A CLARX. R. A CLARX. R. A CLARK. R. A. GLARK. R. A.	8103030878* 8103030885* 8103050715 8103070135 8103020061	50~285 50~285 50~285 50~266 50~266
CABE, E. Q. CABE, E. Q. CABE, E. Q. CABE, E. Q. CABE, E. Q.	8103110854* 8103020201* 8103040929* 8103040950* 8103050257*	50-333 F 50-286 F 50-317 F 50-263 F 50-282 F	CHIARELLA, E. CHILDB, W. V.	8103050923 8103110597* 8103160729* 8103160742* 8103160744*	PR 50-333 6 50-333 6 50-333 6 50-333 6	CLARK, R. A CLARK, R. A CLARK, R. A. CLARK, R. A. CLARK, R. A.	8103050201 8103050539 8103050547* 8103100077 8103070052	50-344 50-317 50-317 50-285 50-266
CABELE.O. CABELE.O. CABELE.O. CABELE.O. CABELE.O.	8103050309* 8103060415* 8103120774* 8103200364* 8103200387*	50-29 F 50-220 F 50-250 F 50-409 F 50-204 F	CHILDS, W. V. CHILDS, W. V. CHILDS, W. V. CHILDS, W. V. CHILES, L.	8103170451* 8103240447* 8103240603* 8103310649* 8103180649	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	B103100021 B103120724 B103050519 B103050527* B103050532*	50-335 50-344 50-282 50-282 50-282
CASE, E. Q. CASEY, B. B. CASEY, B. B. CASEY, B. B. CASEY, B. B.	8103240702* 8103130376 8103130448 8103130376 8103130448	50-266 F 50-361 0 50-361 0 50-361 0 50-361 0	CHILK: B. J. CHILK: B. J. CHILK: B. J. CHILK: B. J. CHILK: B. J.	8102260130* 8103180743* 8103110674 8103110371 8103030821	10CFR 50-237 0 50-275 0 90-275 0 PRM	CLARK-R.A CLARK.R.A. CLARK-L CLARK-L CLARK-H.K	8103120648 B103120652* B103120663* B103120142 B103040469	50-335 50-335 50-335 50-20 50-463

FOH TUA	ACCERSION R38PUSE	SUBJECT CATEGORY	AJHTR	ACCESSION NUMBER	SUBJECT CATEODRY	NOHT UA	ACCEBBICN NUMBER	SUBJECT CATEOCRY
CLARY.R A CLARY.R A CLARY.R A CLARY.R A CLARY.R A	6103120092 81031201054 81031201094 8103120151 8103110214	50-309 P 50-309 P 50-309 P 50-337 P 50-339 P	CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	BI 03170607 BI 03170653 BI 03250072 BI 03250429 BI 03240483	50-348 6 50-364 R 50-364 R 50-364 R 50-348 F 50-348 P	CONLON.T E CONLON.T E CONLON.T E CONLON.T E CONLON.T E	8103050472* 8103040118* 8103040770* 8103160235* 8103050078*	50-390 G 50-413 G 50-302 G 50-518 G 50-348 G
CLARM.D G CLARM.R A CLARM.R A CLARM.R A CLARM.R A	8103100566+ 8103130140 8103130146+ 8103130150+ 8103120173	50-254 S 50-262 P 50-262 P 50-262 P 50-317 P	CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8103270498 8103310434 8103310288 8103270401 8103270411*	50-364 P 90-348 R 50-348 P 50-348 K 50-348 K	CONLON. T E	8103050288* 8103040814* 8103090789* 8103240686* 8103180455*	50-491 0 50-280 0 50-321 0 50-424 0 50-327 0
CLASKIR A CLARKIR A CLARKIR A CLARKIR A CLASKIR A	8103120180 6103120472 8103120474* 8103120477* 8103160808	50-317 H 50-368 P 50-368 P 50-368 P 50-266 P	CLAYION, F. L. CLAYION, F. L. CLEETON, A. R. CLEETON, H. R. CLEETON, H. R.	8103270417# 8103310482 8103350635 8103350637# 8103260160	50-348 K 50-348 R 50-471 0 50-471 0 50-471 0	CONLON, T E	8103040120* 8103090430* 8103180424* 8103180492* 8103190045*	50-302 0 50-400 0 50-327 0 50-349 0 50-389 0
CLARA.R A CLARA.R A CLARA.R A CLARA.R A CLARA.R A	8103200452 8103200455# 8103200476# 8103180246 8103180285	50-368 P 50-368 P 50-368 P 50-313 P 50-309 P	CLEMENTS W L CLEMENTS B R CLEVELAND R S CLEVELAND R S CLEVELAND R S	8103170739* 8103250726 8103260715* 8103260713* 8103260577*	50-320 U PR 40-1947 40-1947 40-1947	CONLON, T.E. CONLON, T.E. CONNAUGHTON, K. CONNER, T.B. CONNER, E.L.	8103130741+ 8103240786+ 8103130119+ 8103030385 8103110509	50-259 Q 50-348 Q 50-315 Q 27-39 50-317 P
CLARP.R A CLARA.R A CLARA.R A GLARA.R A GLARA.R A	8103180294+ 8103180309+ 8103200557 8103160878 8103160563	50-309 P 50-309 P 50-344 P 50-335 G 50-335 F	CLEVELAND. C J CLEVELAND. C J CLEVELAND. C J CLINE. J C CLUSEN. R C	8103040667 B103040685 B103260030 B1030303314 B103050006*	50-269 P 50-344 P NUREO CONTRACT WASTE MOT	CONNER. I B COMMELL. C COMMELL. I J COMMELL. I J. COMMER. I B	8103050849 8103160687* 8103100411 8103130426 8103200707	27-39 50-286 R 50-245 J 50-213 J 27-39
CLARA, R. A. CLARA, R. A. CLARA, R. A. CLARA, R. A. CLARA, R. A.	8103170716 8103160837 8103160853* 8103160868* 8103200032	50-285 F 50-313 P 50-313 P 50-313 P 50-285 P	CLUSEN.R C COBB.A B COBERLY S J COCHRAN, T B COCHRAN, T	B103130072* B103120303 B103120723 B103240123* B103260869*	WASTE MOT State Prog PR 70-143 PR	CONVERTE B CONVERTE B CONVERTE B CONVORTE CONVORTE	8103200707 8103270599 8103270599 8103030097 8103200627	27-39 27-39 27-39 FOIA 50-289 H
CLARA, R. A. CLARA, R. A. CLARA, R. A. CLARA, R. A. CLARA, R. A.	8103250328 8103250334* 8103250349* 8103230043 8103250302	50-335 P 50-335 P 50-335 P 50-339 P 50-309 P	COCKROFT.N CCCKGELL.R G CODELL.R B CODELL.R B COFFEY.M D	8103020681* 8103170622 8103240519* 8103310115* 8103240594	XPORTUIC 50-111 H 50-250 G 50-466 T 50-440 G	CONSTABLE, O L CONSTABLE, O L CONSTABLE, O L CONSTABLE, O L CONTE, R	8103160869* 8103030598* 8103050636* 8103230187* 8103030855*	FDIA 50-362 G 50-313 G 50-382 G 50-320 G
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8103240470 8103240568 8103250352 8103260025 8103330549	50-317 P 50-309 P 50-338 P 50-338 P	COGGIN. C L COGGIN. C L COGGIN. C L COGGIN. C L COGGIN. C L	B103020345* B103020382* B103020375* B103030765* B103030877*	50-321 8 50-366 8 50-365 8 50-366 8 50-321 8	CONTE, R. CONTE, R CONTE, R CONJAY, H. F. CONJAY, H. F.	8103090723* 8103200541 8103250423 8103190855* 8103230861	50-320 0 50-320 8 50-320 8 50-271 9 50-271 0
CLARK, R A CLARA, R A CLARA, R A CLARA, R A CLARA, R A	8103300554# 8103300560* 8103260119 8103261188 8103300505	50-338 P 50-338 P 50-336 P 50-309 P 50-338 P	COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C L	8103130469* 8103230716* 8103230721* 8103230751* 8103230820*	50-366 6 50-366 5 50-366 6 50-366 6	COOK. R J COOK. J W COOK. J W COOK. J. W	8103040159* 8103090482 8103200903 8103020210 8103040649	50-329 0 50-330 0 REPOD 50-329 A 50-329 6
CLARA.R A CLARA.R A CLARA.R A CLARK.R A GLARK.R A	810330509+ 810330514+ 8103310377 8103310616 8103300546	50-338 P 50-338 P 50-368 2 50-282 P 50-338 P	COHEN, B. L. COHEN, B. L. COHEN, R. L. COHN, D. B. COHIX, W. E.	8102260677* 8103206385* 8103261031 8103050611 8103170654	F01A 70-1100 50-320 H 50-369 G 50-289 H	CODK, J. W. CODK, J. W. CODK, J. W CODK, J. W	B103040692 B103130440 B103060479 B103040655 B103040645	50-329 A 50-329 A 50-329 R 50-329 0 50-329 B
CLARA, R. A. GLARA, R. A. GLARA, R. A. CLAUGH, R. H. GLAYTON, F. L.	8103300552* 8103310407 8103300559* 8103200493 81033090167	50-338 P 50-309 P 50-338 P 50-275 H 71-9086	COKINOS D. CCLDY, J. P COLEMAN R. COLEMAN R. COLEMAN R.	8103120769 8102250645 8103090268 8103040581 8103130094	50-254 A PT21 CGNTRACT 50-289 G CONTRACT	COOK, J. W COOK, J. W. COOK, J. W. COOK, J. W.	8103040677 8103100391* 8103100555 8103170398 8103170611	50-327 9 50-275 R 50-327 A 50-329 G 50-329 S
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8103090173 8103090177 8103090181 8103090185 8103090190	71-9111 71-6574 71-9081 71-9080 71-9089	COLEMAN, R COLEMAN, R COLEMAN, R. COLEMAN, R COLEMAN, J. L.	8103190355 8103190677 8103250492 8103270358* 8103030184*	TDARINDO TDARINDO TDARINDO TDARINDO D CEC-OC	COOK, J. W. COOK, J. W. COOK, J. W.	8103200639 8103200644* 8103240476 8103260180 8103260718	50-327 A 50-329 A 50-329 A 50-329 A
CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8103090195 8103090200 8103090212 8103090213	71-9096 71-9105 71-9094 71-6144 71-6244	COLEY, J. L. COLEY, J. L. COLLINS, S. J. COLLINS, J. J. COLLIER, R. P.	8103180508* 8103260456* 8103190879* 8103100651* 8103030001	50-416 0 50-566 0 50-271 0 40-8610 NUREO	COOKEY, M J COOLEY, W J COOLEY, W, J COOKEY, M J	8103260700 8103230168≠ 8103180973≠ 8103200498 8103060452	50-329 A 70-1257 70-984 50-275 H 50-277 0
CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8103090221 8103090226 8103090228 8103240565 8103240773	71-6601 71-9108 71-5026 50-348 @ 50-349 @	COLLING, J D COLLING, J, D COLLING, P. COLLING, P. F. COLOMBO, R. W	8103030664 8103040511 8103090292* 8103160259 8103030740*	NUREQ CUREO CONTRACT 50-250 'V 50-312 6	COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	8103040651 8103110654 8103110658* 8103100623 8103100626*	50-277 B 50-278 S 50-278 B 50-277 B 50-277 S
CLAYION, F. L. CLAYION, F. L. CLAYION, F. L. CLAYION, F. L. CLAYION, F. L.	8103230251 8103050652 8103020451 8103020504 8103020388	50-348	COLOMBO, R. W.	8103030766* 8103030820* 8103130899* 8103130608* 8103170649*	50-312 8 50-312 8 50-312 8 50-312 8 50-312 R	COONEY M J. COONEY M J. COONEY M J. COONEY M J. COONEY M J.	8103100621 8103100624 8103100630 8103110559 8103110495	50-278 B 50-277 B 50-277 B 50-277 B 50-278 B
CLAYTON, F. L.	8103020578 8103030404 8103030877 8103040703 8103100530	50-348 B 50-364 P 50-348 G 50-364 P 50-364 P	COLOMBO, R. W COLOMBO, R. W COLOMBO, R. W. COLOMBO, R. W COLOMBO, R. W	8103170667* 8103170661* 8103230732* 8103240463* 8103240457*	50-312 8 50-312 8 50-312 8 50-312 8	COONEY, M. J. COONEY, M. J. COONEY, M. J. COPELAND, J. G.	8103110727 8103300308 8103310642 8103300342 8103360535	50-278 8 50-278 9 50-277 8 50-277 8 50-466 0
CLAYTON, F. L.	8103060518 8103100184 8103100381 8103100498 8103130399	90-348 R 90-348 F 90-348 F 90-348 P 50-364 P	COLOMBO, R. M COLTON, E. COLTON, E CONDON, T. E. CONKLIM, J. C	8103310547* 8103180020* 8103181086 8103120630 8103260030	50-312 8 40-8040 XPORTLIC 50-390 8 NUREQ	COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, R. L. COPELAND, J. Q.	8103060335 8103050664 8103050664 8103020529 8103190611	50-466 0 50-466 0 50-466 0 50-537 A 50-466 0

AUTHCR	ACCEB910N NUMBER	SUBJECT CATEGORY	AUTHUR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJE
COPELAND, J O COPPOCA, A CORBIN, L C CORDANI, R, A CORDANI, R, A	8103170611 8103090807 8103050620 8103260958 8103040444	50-466	CRAIG.L E CRANE.P A CRANE.P.A CRANE.P.A CRANE.P.A	8103090056 8103020514 8103020579 8103050818 8103180929	90-275 8 90-275 V 90-275 A REQQD	CROSS.J L CRCSSMAN.N A CROUSE.R P CROUSE.R P CRGUSE.R P	8103090198 8103240433 8103120845 8103170127 8103200029	50-327 50-392 REOOD 50-345 50-346
CORDRAY, D. A COREY, D. A CORNELL, C. A CORREA, C. CORREA, M. A	8103200514 8103180530 8103040511 8102030266 8103062362	50-275 H 71-6717 NUREO 50-89 J 50-272 J	CRANE, P. A CRANE, P. A CRANE, P. A CRANE, L. E CRANE, P. A	8103020516 8103030888* 8103050842 8103250490* 8103060279	50-133 J 50-275 0 50-275 0 PR 50-275 A	CROUBE.R.P CROUSE.R.P CROUSE.R.P CROUSE.R.P CROUSE.R.P	8103170796+ 8103020507 8103030738 8103100559 8103160152	50-346 50-346 50-346 50-346 50-346
CORREA, M A CORREA, M A CORREA, M A CORREA, C. CORREA, M A	8103060511 8103060515 8103070607 8103130410 8103110372	50-89 J 50-272 J 50-272 J 50-346 J 50-346 J	CRANE,P A CRANE,P A CRANE,P A CRANE,P A CRANE,P A	8103130484 8103050273 8103050226 8103180489 8103120456	50-275 0 50-275 A 50-133 R 50-275 8 50-275 A	CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P	8103190327 8103180500 8103200526 8103240501 8103270707	50-346 50-346 50-346 50-346 50-346
CORREALM A CORRIDONIAR D CORRIDONIAR D CORRIDONIAR D CORRY A F.	8103110712 8103270759* 8103270763* 8103270766* 8103170528	50-272 J 70-135 70-135 70-135 50-293 P	CRANE,P A CRANE,P A CRANE,P A CRANE,P A CRANE,P A	8103160130 8103170463 8103170542 8103300087 8103170403	50-275 F 50-275 F 50-275 A 50-275 A 50-275 A	CROUSE.R P CROUSE.R P CROW.W T CROW.W T CROW.W T	8103300226 8103310655 8103160294* 8103040665* 8103060964	50-346 50-346 70-2928 70-157 70-27
CORYELL. O P CORYELL. O P COSTELLO.F. COSTELLO.F COSTELLO.J. R	8103160953# 8103240724# 8012110179 8103260174# 8103119090#	70-27 70-1113 1&E 40-8610 0A999	CRANE.P A CRANE.P A CRANE.P A CRANE.P A CRANE.P A	B1 031 70533 B1 031 70615 B1 031 70665 B1 03260626 B1 03200529	50-275 F 50-275 A 50-275 A 50-275 G 90-275 A	CROW, W. T. CROW, W. T. CROWLEY, B. R CROWLEY, B. R CROWLEY, B. R	8103130047* 8103270027* 8103050304* 8103290154* 8103050410*	40-8027 70-820 50-375 50-321 50-348
CDSTELLO, J COSTELLO, F COTTER, B P COTTER, B P COTTER, B P	8103160295 8103310708 8103270947# 8103170314# 8103190637	50-382 0 T&E 50-273 U 10CFR 50-275 Q	CRANE.P A CRANE.P A CRANE.P A CRANE.P A. CRANE.P A	8103230332 8103240386 8103240426 8103240443 8103300311	50-275 A 50-279 A 50-275 F 50-133 P 50-275 A	CROWLEY.B R CROWLEY.B R CROWLEY.B.R. CROWLEY.C J GRUMLEY.J J	8103190194# 8103190333# 8103270158# 8103290458 8103050988	30-518 50-553 50-424 NUREO PR
COTTER, B.P. COTTER, B.P. COTTER, B.P. COTTER, W.T. COTTON, G. D.	8103230635 8103250449 8103270656 8103040593* 8103270238*	50-387 0 50-361 0 50-440 0 50-327 0 70-2882	CRANE, P. A CRAWFORD, J W CRAWFORD, D J CRAWFORD, C CRAWFORD, D J	8103310645 8103070526 8103130005 8103241014 8103240835	50-275 F PR RES FOIA WUREG	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8103040163 8103040178+ 6103040179+ 8103050272 8103050337	50-155 50-155 50-155 50-409 80-237
COTTON O D COTTON O D. COUNSIL, W O COUNSIL, W O COUNSIL, W O	8103120557* 8103170637* 8103200578* 8103100240 8103190664*	50-361 K 50-361 A 50-213 G 50-245 O 50-213 G	CREED, J R CREED, J R CREED, J CREED, J CREED, J R	8103240781* 8103230153* 8103240474* 8103240387 8103300352	50-263 0 50-407 0 50-204 0 50-249 8 50-329 5	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8103090706 8103020178 8103040862 8103050168 8103050173*	50-244 50-409 50-244 50-237 50-237
COUNSIL, W O. COUNSIL, W O. COUNSIL, W O.	8103060691 8103020379 8103100565 8103070438 8103070337	PR 50-336 P 50-213 P 50-245 P 50-245 P	CREGAR, K. O CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L.	8102190480 8103040021# 8103050564# 8103050129# 8103050559#	50-289 H 50-312 G 50-312 G 50-206 G 50-312 G	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D, CRUTCHFIELD, D,	8103050189* 8103060300 8103060289 8103060289 8103100138	50-237 50-213 50-155 50-237 50-219
COUNSIL, H O COUNSIL, H O COUNSIL, H O COUNSIL, H O	8103030884 8103060502 8103070284 8103070414 8103070628	50-213 P 50-213 P 50-213 P 50-213 P 50-213 P	CREWB, J L CREWB, J L CREWB, J L CREWB, J L CREWB, J L.	8103030489 8103050053 8103030130 8103103016 8103180344#	50-275	CRUTCHFIELD.D CRUTCHFIELD.D. CRUTCHFIELD.D. CRUTCHFIELD.D CRUTCHFIELD.D	8103040169 8103040558 8103120022 8103030935 8103030947*	50-245 50-217 50-237 50-155 50-155
COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O.	8103030904 8103060502 8103090211 8103090628 8103100398	50-245 R 50-213 P 50-336 P 50-213 P 50-245 P	CREWS.J.L. CREWS.J.L. CREWS.J.L. CREWS.J.L. CREWS.J.L.	9103180893 8103180515 8103250037 8103040007 8103050124	50-344	CRUICHFIELD. D CRUICHFIELD. D CRUICHFIELD. D CRUICHFIELD. D CRUICHFIELD. D	8103030958* 8103020250 8103040217 8103090033 8103090232	50-155 50-217 50-213 50-245 50-155
COUNSIL, W. O. COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O. COUNSIL, H. O.	8103240557 8103110705 8103240557 8103120335 8103120335	50~213 P 50~245 P 50~213 P 50~213 P 50~213 P	CREWS.J L CREWS.J L CREWS.J L CREWS.J L CREWS.J L	8103290008 8103240737 8103050540 8103240719 8103180317	50-344	GRUTCHFIELD, D. GRUTCHFIELD, D. CRUTCHFIELD, D. GRUTCHFIELD, D. GRUTCHFIELD, D.	8103090236* 8103090243* 8103090257 8103090263* 8103090275*	50-155 50-155 50-255 50-255 50-255
COUNBIL, N.O. COUNBIL, N.O. COUNBIL, N.O. COUNBIL, N.O.	8103130428 8103110625 8103160359 8103160359 8103190603	50-245 P 50-245 P 50-336 P 50-336 P 50-213 P	CREMB. J. L. CREMB. J. L. CREMB. J. L CRLENJAK. R CROCKER. H. W	8103180891* 8103180930 8103240114* 8103240402 8103040534*	50-460 Q 50-312 Q 50-206 Q 50-327 8 70-820	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8103050150 8103050156* 8103050162* 8103040192 8103050318	50-29 50-29 50-29 50-245 50-155
COUNSIL, W O. COUNSIL, W O. COUNSIL, W O. COUNSIL, W O.	8103170603 8103200475 8103250325 8103230665 8103300360	50-213 P 50-336 P 50-245 P 50-336 P 50-213 F	CROCKER, H. W. CROCKER, B. CROCKET, L. CROCKER, H. CRONEBERGER, D.	8103310845* 8103190136* 8103190337 8103200569 8103200504	70-364 50-261 F 50-219 P 70-371 50-289 T	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8103050335 8103120035 8103050326 8103069275 8103020110	50-213 50-155 50-155 50-29 50-244
COUNBIL, W. O. COUNBIL, W. O. COUNBIL, W. O. COUNBIL, W. O. COWAN, B. Z.	8103250391 8103300360 8103270754 8103310362 8103020549	50-213 F 50-213 F 50-245 G 50-245 P 70-2909	CROSBY, P. J. CROSBY, P. J. CROSEMAN, W. A. CROSEMAN, W. A. CROSEMAN, W. A.	8103100450* 8103100465* 8103030358* 8103030096* 8103030112*	50-219 8 50-219 8 50-498 0 50-382 0 50-498 0	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8103090063 8103040221 8103040001 8103040602* 8103040004*	30-213 50-245 30-409 50-409 50-409
COWAN, B. Z. COWAN, L. COWAN, B. Z. COWAN, B. Z. COWQILL, C. J.	8103020549 8103170347 8103230708 8103260768 8103180186*	70-2909 50-287 H 70-2909 70-2909 50-277 G	CROBSMAN, W. A. CROBSMAN, W. A. CROBSMAN, W. A. CROSSMAN, W. A. CROSSMAN, W. A.	8103050361* 8103050285* 8103130348* 8103190012* 8103190030*	50-482 0 50-482 0 50-490 0 50-382 0 50-498 0	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103030983 8103030129 81030301454 8103030170+ 8103060348	50-244 50-206 50-206 50-206 50-213
COMOTILL.C. COMOTILL.C. COX.P. COZENS.G. CRADDICK.H.G.	8103100491 8103170354 8103190447 8103300261 8103040491	50-277 8 50-278 8 50-289 H 50-187 R NUREO	CROSS J L CROSSMAN, W. A. CROSSMAN, W. A. CROSSMAN, H. A. CROSSMAN, H. A.	8103050449* 8103260535* 8103261198* 8103260495* 8103260471*	50-438 0 50-458 0 50-498 0 50-445 0 50-498 0	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103020261 8103041004 8103090739 8103090757* 8103090765*	50-244 50-10 50-255 50-255 50-255

AUTHCR	ACCESSION NUMBER	GUBJECT CATEOCRY	AUTHCR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	EUBJECT CATEOUR
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103040774 8103040778* 8103040790* 8103050249 8103050258*	50-219 P 50-219 P 50-219 P 50-219 P 50-219 P	CRUTCHF (ELD. D CRUTCHF (ELD. D CRUTCHF (ELD. D COLLEY, J H COLVER, H W	8103260571 8103260611 8103310636 81030605574 81032307394	50-244 P 50-244 P 50-244 P 50-361 A 50-302 R	CURTIS.N W CURTIS.N W. CURTIS.N W CURTIS.N W. CURTIS.N.W	8103090408 8103090615 8103100368 8103100523 8103100443	50-367 30-387 50-387 50-387 50-387
CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D.	8103950265+ 8103180854 8103180861+ 8103180871+ 8103930193	50-219 P 50-10 P 50-10 P 50-10 P 50-245 P	Cumminos, J Cumminos, J Cumminos, J Cumminos, P Cumminos, F E	8103170275* 8103170280* 8103230073* 8103240269* 8103200493	FOIA FOIA 50-369 P COMMISSION 50-275 H	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8103110702 8103130421 8103231091 8103200371 8103180594	50-387 50-387 50-387 50-387 50-387
GRUTCHFIELD, D. GRUTCHFIELD, D. GRUTCHFIELD, D. GRUTCHFIELD, D. GRUTCHFIELD, D. GRUTCHFIELD, D.	8:03030205* 8:03030214* 8:103090326 8:1031:10723 8:103090016	50~245 P 50~245 P 50~407 F 50~245 P 50~409 P	CUNNINGHAM, M C CUNNINGHAM, A L CUNNINGHAM, B. E CUNNINGHAM, R E CUNNINGHAM, R E	B1022606B3* B103090767* B103040461 B103020717 B103020719*	FOIA 50-413 G 71-5939 70-984 70-984	CURTIB.N.W CORTIB.N.W CURTIB.N.W CURTIB.N.W CURTIB.N.W	9103180114 9103230429 8103230819 8103240436 8103270711	50-387 50-387 50-387 50-387 50-387
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	B103200018 B103050569 B103110217 B103230840 B103230808	50-409 P 50-155 P 50-255 P 50-29 P 50-225 P	CUNVINGHAM, R. E CUNVINGHAM, R. E CUNVINGHAM, R. E CUNVINGHAM, R. E CUNVINGHAM, R. E	B103060766 B103060771* B103070001 B103070002* B103070058	70-734 70-734 70-687 70-687 70-371	CURTIE, N. W. CURTIE, N. W. CURTIE, N. W. CURTIE, N. W. CURTIE, N. W.	8103300314 8103270341 8103270538 8103270621 8103270657	50-367 50-367 50-367 50-367 50-387
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103230847 8103260989 8103060277* 8103060287* 8103060318*	50-244 P 50-219 F 50-409 P 50-409 P 50-409 P	CUNNINGHAM. R. E CUNNINGHAM. R. E CUNNINGHAM. R. E CUNNINGHAM. R. E CUNNINGHAM. R. E	8103090064* 8103090069 8103090076* 8103090081 8103090086*	70-371 70-1201 70-1201 70-1143 70-1143	CURTIS. N. W. CURTIB. N. W.	8103270669 8103270696 8103270713 8103270731 8103270734	50-387 50-387 50-387 50-387 50-387
CRUTCHFIELD. D. CRUTCHFIELD. D CRUTCHFIELD. D. CRUTCHFIELD. D CRUTCHFIELD. D.	8103130266 8103130275* 8103130280* 8103180405* 8103180413*	50-155 P 50-155 P 50-155 P 50-213 Q 50-213 Q	Cunningham. R. E Cunningham. R. E Cunningham. R. E Cunningham. R. E Cunningham. R. E	8103070087 8103070094* 8103070097 8103070103* 8103070109	70-1257 70-1257 70-33 70-33 70-36	CURT(8, N. W. CURT(8, N. W. CURT(8, N. W. CURT(8, N. W. CURT(8, N. W.	8103270737 8103270742 8103270799 8103310366 8103300382	50-387 50-387 50-387 50-387 50-387
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103240577 8103240582* 8103248609* 8103120073 8103120265	50-213 P 50-213 P 50-213 P 50-213 P 50-255 P	CUNNINGHAM.R.E. CUMMINGHAM.R.E. CUMMINGHAM.R.E. CUMMINGHAM.R.E. CUMMINGHAM.R.E.	8103070118+ 8103070128+ 8103070145 8103070152+ 8103070157	70-36 70-36 70-824 70-824 70-135	CURTIS, N. W CURTIS, N. W CURTIS, N. W CURTIS, N. W CURTIS, N. W.	8103310462 8103310496 8103310501 8103310511 8103310532	90-387 50-387 50-387 50-387 50-387
CRUTCHFIELD, D. CRUTCHFIELD, D. M CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103120249 8103120274 8103120279 8103120306 8103120312	50-29 P 50-255 P 50-244 P 50-244 P 50-29 P	CUNNINGHAM R. E.	8103070165 8103070178 8103070184 8103070194 8103070179	70-135 70-135 70-143 70-143 70-1113	CURTIS, N W. CURTIS, N. W CURTIS, N. W CURTIS, N. W CURTIS, N W	8103310431 8103310437 8103310494 8103310480 8103310628	50-387 50-387 50-387 50-387 50-387
CRUICHFIELD, D CRUICHFIELD, D CRUICHFIELD, D RUICHFIELD, D RUICHFIELD, D	8103180111 9103140212 9103140222 9103140222	50-155 P 50-409 P 50-213 P 50-155 P 50-244 P	CUNNINGHAM, R.E CUNNINGHAM, RE CUNNINGHAM, RE CUNNINGHAM, RE CUNNINGHAM, RE	8103070204 8103390207* 8103090213* 8103090218 8103090219*	70-124 70-1113 70-124 70-27 70-124	CURTNER, A P. CURTNER, A P. CUTCHIN, J. M. CYBULBKIB, P. CYBULBKIB, P.	8103030715 8103030719# 8103200108 8103050707 8103020723	50-124 50-124 50-289 REB NUREG
RUTCHFIELD, D. :RUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	0103180262# 0103180276# 0103230501 0103120280 0103120304	50-244 P 50-244 P 50-206 P 50-255 P 50-206 P	CUNNINGHAM.RE. CUNNINGHAM.RE. CUNNINGHAM.RE. CUNNINGHAM.RE. CUNNINGHAM.RE.	8103070227* 8103070234 8103070237* 8103070251* 8103070255	70-27 40-8027 40-8027 40-8027 70-854	CYBULBKIB, P. CZIKOWBKY, L. D'AMBRUDBO, D. B. D'ANGELD, A. J. DAAVETTILA, D. A.	8103040615 8103170901 8103200554 8103050741= 8103040555	50-287 50-275 50-287 50-397 70-820
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103240058 8103110707 8103180400 8103110454 8103110728	50-409 P 50-155 P 50-213 Q 50-244 P 50-206 P	CUNNINGHAM, R. E.	8103070261* 8103070266 8103070274* 8103070280 8103070287*	70-854 70-25 70-25 70-398 70-398	DAHLINGER, F. B. DAIGLE, R. P. DAIL, L. C. DAIL, L. C. DAIL, L. C.	8103100761* 8103050514 8103050238 8103060678 8103250984	MIBC XPDRTLIC 50-488 PR PR
CRUTCHF FELD, D.	8103110739 8103120300 8103120310 8103180812 8103180821 w	50-155 P 50-213 P 50-409 P 50-213 P 50-213 P	CUNNINGHAILR E. CUNNINGHAM.R E. CUNNINGHAM.R E. CUNNINGHAM.R E. CUNNINGHAM.R E. CUNNINGHAM.R E.	8103090303 8103090308* 8103090321* 8103090339*	70-698 70-698 70-698 70-734 70-734	DAIL.L.C. DAIL.L.C. DALE.L.F. DALE.L.F. DALE.L.F.	8103100567 8103170457 8103310706 8103020351 8103030728	50-491 50-488 70-2936 50-416 50-416
CRUTCHF IELD, D CRUTCHF (ELD, D. CRUTCHF (ELD, D. CRUTCHF (ELD, D. CRUTCHF (ELD, D.	8103180826* 8103130505 8103181145 8103181150* 8103181153*	50-213 P 50-237 P 50-244 P 50-244 P 50-244 P	CUNNINGHAN R CUNNINGHAM R E CUNNINGHAM R E CUNNINGHAM R E CUNNINGHAM O E CUNNINGHAM O E	8103190851* 8103200887 8103200891* 8103181137 8103120397	PR 70-8 70-8 70-754 71-9070	DALE,L.F. DALE,L.F. DALE,L.F. DALE,L.F. DALE,L.F.	8103030742 8103170095 8103100595 8103180228 8103230525	30-416 50-416 50-416 50-416 50-416
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103260218 8103260229* 8103260251* 8103160517 8103260508	90-245 P 50-245 P 50-245 P 50-255 P 60-213 P	CUNNINGHAM, J. D CUNNINGHAM, J. D CUNNINGHAM, G. E. CUNNINGHAM, G. E. CUNNINGHAM, G. E.	8103050700 8103180447 8103170143 8103170638 8103050539	50-289 Q 50-289 Q 50-18 R 50-183 R 50-73 P	DALE, L. F. DALE, L. F. DALTON, J. N. DALTROFF, B. L. DALTROFF, B. L.	8103230541 8103310894 8103250053 8103180164* 8103180223	50-416 50-416 PR 50-277 50-277
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8103200517 8103200719 8103200724 8103200729 8103190514	50-219 P 50-206 P 50-409 P 50-29 P 50-206 P	CURBAM CURREYAM. CURRYAT.E. CURRYAJ. CURTISAN.W.	8103260529 8103260414* 8103040675 8103200119* 8103100192*	30-275 H Wabte M31 Reb 50-289 T 30-387 B	DALTROFF, 8. L.	8103200330 8103110170 8103130051 8103020645 8103260271	50-277 REQOD REQOD 50-277 PR
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D.	8103200528 8103230327 8103230512 8103230519 8103230534	50-206 P 50-27 P 50-255 P 50-206 P 50-217 P	CURTIS. J. R. CURTIS. J. R. CURTIS. N. W CURTIS. N. W CURTIS. N. W	8103040261# 8103180192# 8103230831 8103230842 8103020425#	50-89 Q 50-113 Q 50-387 Q 50-387 Q 50-387 K	DALTROFF, B L. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, B. L.	8103110640 8103130507 8103120367 8103200478 8103200520	50-277 50-277 50-277 50-277 50-277
CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D. CRUTCHFIELD. D.	8103230607 8103230657 8103230666 8103230676 8103270696	50-213 P 50-244 P 50-244 P 50-245 P 50-255 P	CURTIS, N. W CURTIS, N. W. CURTIS, N. W CURTIS, N. W CURTIS, N. W.	8103040273 8103030812 8103020410 8103030768 8103120460	50-387 A 50-387 B 50-387 K 50-387 A 70-2937	DALTROFF, 8. L. DALTROFF, 8. L. DAMBLY, D. C. DANCE, H. C. DANCE, H. C.	8103250285 8103270414* 8103240507 8103040593* 8103050600*	50-277 50-277 50-554 50-327 50-390

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C. DANCE: H. C.	8103120770* 8103100121* 8103130155* 8103130167* 8103130201*	50-327 0 50-327 0 50-327 0 50-327 0 50-327 0	DENTON, H. R DENTON, H. R DENTON, H. R. DENTON, H. R. DENTON, H. R.	8012180503* 8103120199 8102280289 8103030360 8103020194	FOIA OEN TEC 18 50-437 A OEN TEC 18 50-286 F	DEVINE, J B. DEVINE, J B. DEVINE, J B. DEVINE, J B.	8103040116 8103040832 8103040839 8103040704* 8103041018	XPORTLIC XPORTLIC SO-579 XPORTLIC XPORTLIC
DANCE: H. C DANCE: H. C DANCE: H. C DANCE: H. C DANCE: H.	8103160107* 8103240312* 8103240146* 8103240823* 8103040479	50-321 Q 50-321 Q 50-327 Q 50-320 Q 50-280 8	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	B103040917 B103040940 B103050246 B103050299 B103060406	50-317 F 50-263 F 50-262 F 50-29 F 50-220 F	DEVINCENTIB. J DEVINE. J B. DEVINE. J B. DEVINE. J B. DEVINE. J B	8103180510 8103040735 8103040744 8103040781 8103050001	50-443 XPCRTLIC XPORTLIC XPORTLIC XPORTLIC
DANCE, H. C. DANCE, H. C. DANIELSON, D. H. DANIELS, F. T. DANIELSON, D. H.	8103240681* 8103240743* 8103020701* 8103050499* 8103120252*	50-259 0 50-335 0 50-266 0 50-358 0 50-329 0	DENTON, H. R. DENTON, H. R. DENTON, H. R DENTON, H. R DENTON, H. R.	8103120765 8103200359 8103200373 9103240688 8103200781	50-250 F 50-409 F 50-206 F 50-266 F 50-275 P	DEVINE. J B DEVINE. J B DEVINE. J B DEVINE. J B. DEVINE. J B.	8103050935 8103050943 8103041037+ 8103050231 8103050400+	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. DANIELS, A. Q. DANIELS, F. T.	8103200972* 8103170710* 8103180163* 8103230270* 8103190082*	50-295 Q 50-341 Q 50-483 Q 80-320 P 50-358 Q	DENTON, H. R DENTON, H. R DENTON, H. R. DENTON, H. R. DENTON, H. R.	8103200786* 8103200775* 8103090989 8103110854 8103160325*	50-295 P 50-295 P 50-352 H 50-333 F 10CFR	DEVINE, J. 8 DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8.	8103050434* 8103050486 8103060218 8103100001 8103100162	APORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
CANTELSON, D. H DANTELBON, D. H. DARMITZEL, R. W. CARMITZEL, R. W. CARMITZEL, R. W.	8103260051* 8103260084* 8103130446 8103130449# 8103130442	50-237 G 50-373 G 50-70 P 50-70 P 50-70 P	DENTON, H. R.	8103100035 8103160240 8103120404 8103170250 8103170256#	50-327 O 50-528 H 50-352 A 50-10 F 50-10 F	DEVINE, J. B.	8103190849 8103190876+ 8103110897 8103120079 8103120083	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DARMITZEL, R. W. DAVID, E. DAVIDSON, D. I. DAVIDSON, J. DAVIDSON, D. R.	8103160576 8103120618 8103130046 8103170603 8103070683	50-70 P PR PROJ 50-289 H 50-440 8	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8103300499 8103300500* 8103180446 8103181098 8103230486	50-259 P 50-239 P 50-289 H 50-320 H 50-29 F	DEVINE, J B DEVINE, J B DEVINE, J B	8103120089 8103120097 8103120103 8103120143 8103190841	XPORTAIC XPORTAIC XPORTAIC XPORTAIC XPORTAIC
DAVIDBON, D. R. DAVIDBON, D. R. DAVIDBON, D. R. DAVIDBON, D. R. DAVIDBON, D. R.	8103090564 8103090599 8103090538 8103160576 8103230544	50-440 B 50-440 B 50-440 E 50-440 K 50-440 K	DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R.	8103230490* 8103190086 8103190097* 8103200670 8103200674	50-29 F LOCFR LOCFR 50-445 E 50-338 E	DEVINE.J B DEVINE.J B DEVINE.J B DEVINE.J B	8103100390 8103100385 8103100388 8103100419 8103100681*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DAVIES, L. M. DAVIG, D. H DAVIG, A. B. DAVIG, J. Q DAVIG, J. Q.	8103060561* 8103120714 8103031009 8103190702* 8103130060	50-361 A PR I&E WASTE MOT WASTE MOT	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8103200685 8103200687 8103200689 8103230860 8103230866	50-341 E 50-395 E 50-382 E 50-322 E 50-387 E	DEVINE. J. B DEVINE. J. B DEVINE. J. B DEVINE. J. B	8103100415 8103120174* 8103120221 8103120228 8103120233	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DAVIS, A. B. DAVIS, J. S DAVIS, J. S DAVIS, B. DAVIS, P. L.	8103040445 8103060259# 8103180324# 8103170497 8103100282#	50-295 B 40-8702 40-8702 50-289 H CONTRACT	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8103230869 8103230887 8103230891 8103240002 8103230135	50-373 E 50-416 E 50-206 E 50-370 E 50-458 A	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8103120708 8103120729 8103120738 8103120742 8103120808	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DAVIB. B. M. CAVIB. B. M. DAMSON, D. M. DAMSON, D. M. DAMSON, A. Q.	8103260612* 8103260934* 8103310666 8103240058 8103290034	50-317 8 50-317 8 70-1308 71-9001 FR	DENTON, H. R.	8103270808 8103270813 8103270817 8103270819 8103250181	NUREO NUREO NUREO NUREO 50-338 H	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	B103130015 B103130023 B103130123 B103130344 B103130631	XPDRTLIC XPDRTLIC XPDRTLIC XPDRTLIC XPDRTLIC
Dean, B. Dearien, J. A. Dearien, J. A. Decker, R. G. Deeg, R. L.	8103050636* 6103170116 8103100060 9103020422 8103110363	50-313 G RES NUREO 50-409 G 50-367 H	DEREBB. J. D DEROSA. P. P. DEBROBIERS. A. E. DEBBAULES. P DEVINCENTIS. J.	8103180577* 8103240314* 8103240287* 8103310709* 8103270406*	50-454 Q 50-206 P COMMISSION 70-820 50-443 Q	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B	8103130638 8103130649* 8103120819 8103170777 8103170354	XPORTLEC XPORTLEC XPORTLEC XPORTLEC XPORTLEC
DEETER, H. L. DEFARRAR I. G. DELANEY, J. C. DELANEY, J. C. DELANEY, J. C.	8103190481 8103170367 8103260759* 8103040507* 8103260745*	50-289 H 50-289 H 40-1947 40-8610 40-1947	DEVINE.H.F. DEVINE.J.B. DEVINE.J.B. DEVINE.J.B. DEVINE.J.B.	B103040404 B103020343 B103020347 B103020352 B103020335	50-409 J XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8103190359 8103190363 9103190347 8103190805 8103230928	APORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DELANEY, J. C. DELANEY, J. C. DELANEY, J. C. DELANEY, J. C. DELANEY, J. C. DELAND, B. J.	8103260738* 8103040515* 8103040521* 8103260727* 8103190470	40-1947 40-8610 40-8610 40-1947 50-289 H	DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8.	8103020340 8103040923 8103040930 8103040967 8103040972	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVINE, J. B.	8103230805 8103230810 8103230816 8103260911 8103260918	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DELGEDROE, L. O. DELGEDROE, L. O. DELGEDROE, L. O. DELGEDROE, L. O. DELGEDROE, L. O. DELGEDROE, L. O.	8103100298 8103020619 8103250692* 8103110154 8103120562	PRM 50-373 A 50-10 F 50-373 A 50-374 B	DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8.	8103040977 8103040986 8103090217* 8103090245 8103090205	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVINE, J.B. DEVINE, J.B. DEVINE, J.B. DEVINE, J.B. DEVINE, J.B.	8103260937 8103261039 8103261046 8103310844 8103310857*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DELOEDROE: L. O. DELOEDROE: L. O. DELOEDROE: L. O. DELOEDROE: L. O. DELLARAYTA, A.	8103120647 8103170465 8103240371 8103250397 8103200385#	50-373 A 50-373 R 50-373 A 50-373 K 70-1100	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8103030696 8103030699 8103030702 8103030705 8103030711	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVLIN, J. 4. DEVLIN, J. W.	8103310863 8103310868 8103310912 8103050478* 8103050436*	XPDRTLIC XPDRTLIC XPDRTLIC 50-247 50-286
DEMERS. E. A. DEMNING. R. S. DENNING. R. S. DENNIS, N. DENNIS, N. DENNIS, R. S.	8103060615* 8103080907 8103180637* 8103190839* 8103020723	50-361 A REØ 50-289 T 40-3392 NUREG	DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8. DEVINE, J. 8.	8103030920 8103030927 8103040130 8103040846 8103041027#	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVLIN, J. W DEVLIN, J. W DEVLIN, J. W. DEVLIN, J. W. DEVLIN, J. W.	8103050291+ 8103230913+ 8103030803 8103030842 8103050624	50-333 50-219 50-247 50-247 50-309
DENNING, R. 9. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8103050917 8103040250* 8103040162* 8103030066* 8103180932*	RE8 50-133 H 10CFR FOIA 50-237 Q	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8103090319+ 8103030718 8103030910 8103030916 8103030952	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DEVLIN.C.M. DEVLIN.J. DEVLIN.J.W DEWITT.R.B. DEWITT.R.B.	8103190422 8103100412 8103240376 8103090418* 8103100321*	50-289 50-309 50-293 50-185 50-155

#### PERSONAL AUTHOR INDEX 498

AUTHOR

DIGNAN, T. C.

DIGNAN, T G

DIGNAM T Q DIMEGLIO A F. DIPLAZZA R P.

SUB-ECT CATEGORY

ò

50-155 50-329

FOIA

FOLA

RES

ACCESS104

NUMBER

8103130223

B103130223

8103040744\*

B103040735+

B103110764

DONAT. T. J.

8103130143\*

AUTHOR

DEWITT, R 8

DHILLDIA H

DHILLON H

DIAMOND D .I

DHAR, B

DIAMOND, D. J. DIAMOND, D. J. DIAZ, N. J. DICKERSON, M. W. DICKERSON, M. W.	9103180814 8103310887 8103130461 8103031105* 8103183443*	RES RES 50-83 50-267 50-267	s 0 0	DIF1AZZA, R.P. DIP1AZZA, R.P. DIP1AZZA, R. DIRCKS, W.J. DIRCKS, W.J.	8103050118 8103310934 8103270173 81030401624 8103170197*	71-6400 70-2907 70-1151 10CFR 40-1341	DOYLE, M M DOYLE, M M DOYLE, M M DOYLE, M M	B103250267 8103020901* 8103020036 8103260872 B103260872	50-289 50-327 F01A PROJ PROJ
DICKSON, K 8 DICKSON, K B DICKSON, D M DICUS, M J DIECKAMP, H	8103050826* 8103050826* 8103190512 8103190554 8103170387	PRM PRM 50-289 50-289 50-269	Н Н	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8102230060* 8101280310 8102230094* 8101190671* 8103040155*	100FR 50-498 H 100FR 600FR 100FR	DRAPER E L. DRAPER E L DRAPER E L DRAPER E L DREESEN D R	B103230212 B103230223 B103250427* B103180569 B103060176*	50-459 50-459 50-459 50-459 WASTE
DIEHLIC D BLETCH.R. DIETCH.R. DIETCH.R. DIETCH.R.	8103200527 8103270227 8103270238* 8103120553 8103120557*	50-289 70-2882 70-2882 50-361 50-361	н к к	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	B1021B0203 G103020790 B103050B65* B1031B0209* B1031B0188*	SECY 50-327 H 10CFR 10CFR 10CFR	DREESCN.D.R. DREY.K DREY.K DREY.L.A DREY.K	8103060183> 8103120249* 8103270108 8101210350 8103120403*	WASTE 50-483 NUREO 50-320 50-483
DIETCH.R. DIETCH.R. DIETZ.G DIETZ.G R. DIETZ.C R.	8103170635 8103170639* 8102170636* 8103100618 8103030743	50-361 50-361 71-9013 50-325 50-328	A A S S	DIRCHS. W J DIRCHS. W J DIRCHS. W J DIRCHS. W J DIRCHS. W J	8103120053# 8102280183# 8103050077 8103050505 8102260120#	LOCFR LOCFR PR COMMISSION LOCFR	DRIBHILL, D. D URIBHILL, D. D DRIBHILL, D. D DRIBHILL, D. D DROMERICK, A	8103040455# 8103120593* 8103130236# 8103310897* 8103050270	50-445 50-498 50-498 0A999 50-482
DIETZIC R. DIETZIC R DIETZIC R DIETZIC R DIETZIC R DIETZIC R.	8103030887 8103040487 8103249076 8103050177 8103099507	50-324 50-325 50-324 50-324 50-325	P G R S	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	B103030450# B103030921 B103060469# B103170686# B103040889	50-437 A BECY PRM LOCFR 50-295 H	DROMERICK, A W DROMERICK, A W DROMERICK, A W DROMERICK, A W DROMERICK, A W	8103120721 8103130626 8103230271 8103230023 8103230262	50-482 50-482 50-482 50-482
DIETZIC R. DIETZIC R. DIETZIC R DIETZIC R DIETZIC R.	8103250286 8103040644 8103050523 8103050584 8103100605	50-324 50-325 50-324 50-325 50-324	4 8 8 8 8	DIRCHS.W J DIRCHS.W J DIRCHS.W J DIRCHS.W J DIRCHS.W J	8103160440# 8103270927# 8103160395# 8103160839# 8103110225	10CFR COMMIBBION LCCFR 50-3 P 50-341 A	DROMERICK, A W DROMERICK, A W DROMERICK, A. W. DROMERICK, A. W. DVDIEL, R.	8103240031 8103260996 8103270781 8103310696 8103130929*	90~482 50~482 90~482 90~482 50~289
DIETZ/C R DIETZ/C R DIETZ/C R DIETZ/C R DIETZ/C R	8103110679 8103160762 8103110683 8103130510 8103160685	90-324 50-324 50-325 50-324 50-325	5 9 9 8	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8103160312 81031803714 8103160389 8103110383 8103170693*	BECY 50-320 P 50-320 P 50-311 H 50-344 P	DUBDIB, D. L. DUBRY, N. E. DUCKWORTH, J. P. DUCKWORTH, J. P. DUCKWORTH, J. P.	6103050598* 8103120487* 8103270844 8103270849* 8103270853*	50-362 50-315 50-201 50-201 50-201
DIETZ.C R DIETZ.C R DIETZ.C.R DIETZ.C.R DIETZ.C.R	B103170421 B103160771 B103160435 B103170645 B103170446	50-325 50-324 50-324 50-325 50-325	5 5 6 6	DIRCHS.W J DIRCHS.W J DIBALVO,R DISE.D.P DISE.D.P	8103190819 8103230072* 8103190897 8103300008* 8103030686*	50-454 A 10CFR CRG 50-410 G 50-220 P	DUCKWORTH, J P. DUCKWORTH, J P. DUFF, R. T OUKLER, A E DUMMER, O H	8103300004 B103120482 B103250694 B1031B0949* B103040919*	50-201 50-201 PR REVIEW CONTRA
DIETZ-C R DIETZ-C R DIETZ-C R DIETZ-C R DIETZ-C R	8103170481 8103190502 8103230720 8103230689 8103240459	50-325 50-324 50-325 50-324 50-325	8 8 8	D18E.D.P D18E.D.P D18E.D.P D18E.D.P. D18E.D.P	8103040430 8103160575 8103160507 8103240374 8103260799	50-410 A 50-220 P 50-220 P 50-410 A 50-220 P	DUNCAN.T. DUNCAN.E G DUNDAS.H J. DUNHAM.R B DUNLOP.T	8103120718 8103200623 8103160724 8103260808 8103050875*	PR 50-269 50-266 50-275 70-127
DIETZ-C, R DIETZ-C R DIETZ-C, R DIETZ-C, R DIETZ-C, R	8103240579 8103240588 8103270762 8103240467 8103270666	50-325 50-325 50-325 50-324 50-324	8 8 9 6	DISE D P DISE D P DISE D.P. DITMORE, D C DIXON O.	B103270745 B103270710 B10331053B B103166B50# B103050500*	50-220 P 50-220 P 50-220 V FOIA FOIA	DUNN, C. N BUNN, C. N. DUNN, C. N. DUNN, C. N DUNN, C. N	8103190455* 8103050343* 8103090714* 8103090060 8103050282*	50-334 50-334 50-334 50-334 50-334
DIETZ.C R DIETZ.C R DIETZ.C.R DIETZ.C R DIETZ.C R	8103270749 8103300324 8103310544 8103310693 8103310682	50-325 50-324 50-324 50-324 50-324	8 8 8 8	DIXON F J. DIXON F J. DOBSON D. E. DOBSON D. E. DOBSON D. E.	8103200524 8103190424 8103250032* 8103250025* 8103250009	50-289 H 50-287 H 50-308 G 50-508 G 50-508 G	DUNN, C. N.	8103240963 8103170071* 8103100178 8103230228 8103030861	50-334 50-334 50-334 50-334 50-334
DIETZ.R.L. DIGALONA.T.L DIGALOMA.T.L DIGOS.R.M. DIGOS.R.M.	8103310230# 8103040455# 8103120593# 8103060138 8103060486	50-538 50-445 50-498 50-244 50-344	R Q O F P	DOBBON: D.E. DOCKHORN: H DODA: R DODPS: R. T DODDS: R. T.	8103240037 8103190452* 8103230650 8103110847* 8103030521*	50-508	DUNN, D. R. DUNN, C. N. DUNN, B. D. DUNN, G. N. DUNN, C. N.	8103230243 8103100978 8103170338* 8103170147 8103170156	NUREG 50-334 50-280 50-334 50-334
DIGGS.R M BIGGS.R M DIGGS.R M DIGGS.R M DIGGS.R M	8103060524 8103090085 8103170207 8103120636 8103130740	50-237 50-280 50-407 50-89 50-10	P የ የ	DODDS R T.	8103040219* 8103250047* 8103040346* 8103040331* 8103050035*	50-397	DUNN. C. N.	8103170577 8103170589* 8103240408 8103240448 8103240500	50-334 50-334 50-334 50-334 50-334
D1008.R M D1009.R D1009.R D1008.R. D1008.R.	8103120471# 8103120545# 8103120550# 8103160471# 8103240098	50-29 50-317 50-237 50-272 50-269	Р Р Р	DDDDS, R. T. DDDDS, R. T. DDDDS, R. T. DDDDS, R. T. DDDDS, R. T.	B103050379* B103190011* B103100036* B103050741* B103250904*	50-52B Q 50-460 Q 50-397 Q 50-397 Q 50-397 Q	DUNN, C. N DUNN, C. N DUNN, C. N. DUNN, C. N. DUNN, C. N.	8103260365 8103240194 8103260694 8103300286 8103300302	50-334 50-334 50-334 50-334 50-334
DIOGS, R. H DIOGS, R. H DIOGS, R. H DIOGS, R. H DIGNAN, T. G	8103240580 8103240576 8103270755 8103270760 8103040488	50-29 50-219 50-255 50-263 50-471	P P P O	DDERFLEIN.L.T. DDHERTY, J.F. DDHERTY, J.F. DDHERTY, J.F. DDLAN, J.F. DDLAN, J.E	8103270798* 8103040384 8103020419 6103170427 8103040297*	50-333	DUNIA C. N. DUNNA C. N. DUPONTA B. O. DUPONTA B. O. DURONTA E. U.	8103310211 8103310239 8103090272* 8103160944* 8103180703	50-334 50-334 50-254 50-254 MIBC
DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G.	8103040602 8103040602 8103130414 8103130414	50-443 50-443 50-471 50-471	0 0 0	BONALDSON/D BONATAT. J. BONATAT J. BONATAT. J.	81030503824 8103170089# 8103120802# 8103130143#	50-320 q 50-369 q 50-369 q 50-369 q	DURLER, D. L. DURR, J. P. DURR, J. P. DUTTON, D.	8103250615 8103200084* 8103300193* 8103310921	REGOD 50-352 50-352 50-424

ACCESSION

NUMBER

B103190514

8103190537

8103170517 8103170614 8103270667 8103310761

BUBJECT

50-471

50-471 50-471 50-471 50-193

70-1143

CATEGORY

Ģ

ACCESSION

NUMBER

8103180578

8103160467\* 8103270349 8103230038

B103190456

AUTHOR

DONELSON, C.

CONLON, W J.

DOUGLASS, R M

DORGEY. M

DOND' N W

BURJE

CATEG

70-290

50-220

CONTRA

REPOR

50-289

50-352 50-352 50-424

8103310921

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AOHTUA	NO188333A RJEMUN	BUBUECT	POHTrus	ACCESSION NUMBER	SUBJEC CATEGO
EADIE. O Q EADIE. O Q EARLEY. A F EARLEY. A F EARLEY. A F	8103160249 8103181147 8103030870 8103030876+ 6103050706	TOP 322 C	EIBENHUT. D G EIBENHUT. D G EIBENHUT. D. O EISENHUT. D G EISENHUT. D G	8103230030 8103170225 8103170655 8103230813 8103160760	50-3 P 50-10 P 50-322 A 50-3 P 50-387 A	ENGELKEN R H ENGELKEN R H ENGELKEN R H ENGELKEN R H ENGELKEN R H	8103140814 8103140828 8103140830 8103140843 8103140843	50-361 50-312 50-508 50-344 50-323
EARLEY, A F. EARLEY, A F EASON, C F. EASON, C F EASTHAM, J. F.	8103030876* 8103050706 8103260530* 8103250605 8103030336	90-322 0 50-322 0 27-39 PR NUREO	EISENHUT.D 0 EISENHUT.D 0 EISENHUT.D C EISENHUT.D 0 EISENHUT.D 0	8103160763* 8103170191 8103310338 8103130742 8103261208	50-387 A 50-367 A 50-3 F 50-339 P 90-528 A	ENGELKEN.# H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H	8103160648 8103160852 8103160881 8103160882 8103160982	50-528 50-133 50-460 50-206 50-347
EASTMAN. K M EBBIN. B EBERLEIN. F EBNEIER. S. D EBNEIER. S	8103200752 8103270134* 8103230698 8103270390* 8103180216*	50-448 0 FOIA FOIA 50-220 0 50-289 0	EISENHUT, D. O EISENHUT, D. O EISENHUT, D. G EL-AGHRY, M. T EL-ASHRY, M. T	8103310804 8103190132 8103310432* 8103090409 810311048[*	50-3 P 50-352 H 50-248 P 50-327 9 50-327 R	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8103180655 8103180828 8103240653 8103200233 8103200240	50-312 50-460 71-6400 50-460 50-397
EBNETER, S. D ECKERMAN, K. F ECKERMAN, K. F ECKHARDT, J. H ECKHARDT, J. H	8103170277* 8103130005 8103250646 8103110847* 8103030521*	50-287 G REB NUREO 50-528 G 50-361 G	EL-ASHRY.M T EL-ASHRY.M T ELIN.J O ELIN.J U ELLEN.J U ELLERSHAN.L E	8103170520 8103170624 8103030521+ 8103050035+ 8103120785+	90-299 P 90-327 S 90-361 G 90-312 G QA999	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8103200243 8103200249 8103200252 8103200239 0103200262	50-205 50-312 50-133 50-328 50-344
H L.TGRAHADE ECONOMOB. N ECONOMOB. N ECONOMOB. N	8103040331# 8103180412# 8103040801# 8103240783# 8103310789#	50-928 G 50-990 G 50-938 G 50-269 G 50-938 G	ELLERIC 8 ELLIOTTIC W ELLIOTTIA E ELLIGIS J ELLIS J	8103250464 8103250708 8103170203 8103200631 8103200562	PR PR 90-123 V 50-445 G 50-446 O	ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H	8103200269 8103200042 8103200047 8103200052 8103206057	50-508 50-528 50-133 50-344 50-312
EDDINOB. M. EDDLEMAN, W EDGAR, G L EDGAR, G L. EDGAR, G L.	8103200545* 8103170483 8103130427 8103130430* 8103130433	50-327 R 50-289 H 50-70 G 50-70 G 50-70 G	ELLIB, J ELROD, B A ELROD, G A EMERICK, O EMIO,	8103230735 8103050428+ 8103240743+ 8103200612 8103200415	50~445 0 50~335 0 50~335 0 50~289 0 50~289 H	ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELAEN.R H ENGEL.R E	8103200359 8103299054 8103290065 8[03290072 8103230518	50-397 50-440 50-508 50-206 30-265
EDGAR, O.L. EDGAR, O.L. EDGEMORTH, P.J. EDGEMORTH, P.J. EDGEMORTH, P.J.	8103130435* 8103270387 8103030267 8103090223 8103040729	50-70 0 50-70 0 CONTRACT 50-289 0 CONTRACT	ENGDAHL, D E ENGDAHL, D E ENGDAHL, D E ENGDAHL, D E ENGELKEN, R H	8103100731* 8103100731* 8103100714* 8103100714* 8103260781*	UABTE MOT WASTE MOT WASTE MOT FOLA	engle.L B engle.L B engle.L B engle.L.R enginger.S	8103160115 8103120159 8103130416 8103230326 6103183333	50-338 50-338 50-338 50-284
EDGEHORTH, P.J. EDGEHORTH, P.J. EDGEHORTH, P.J. EDGEHORTH, P.J.	8103030057 8103040749 8103230901 8103261079 8103200621	50-259 P CONTRACT 50-443 A CONTRACT 50-289 H	ENGEL.R E ENGELKEN,R.H ENGELKEN,R H ENGEL.R E ENGELKEN.R H	8103243230* 8103110737 8103390045 8103160428* 8103020004	50-321 P 50-528 8 50-528 6 50-298 P 50-394 0	EPPS.R C EPSTEIN.E EPSTEIN.E EPSTEIN.B EPSTEIN.L R	8103110840+ 8103240724+ 8103240439+ 81031490414+ 8103250535	50-309 40-1747 FQTA 50-320 PR
EDLOW, J EDMONGON, L. R EDNETER, 8 D EDWARDG, D. W EDWARDG, D. L	8103139288* 8103170279* 8103040355* 8103070571 8103260675	40-8760 CONYRACT 90-271 G PR 40-3493	ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H	8103020005 8103020007 8103020010 8103020011 8103020012	50-137	ERB.C M ERICKBON.S ERICSON.D M ERICSON.D M ERICSON.D M	8103180163* 8103120672 8103050373 8103030353 8103100179	90-403 PR RES NUREG NUREG
EDWARDS, D. L. EDWARDS, D. L. EECKHOUT, A EHNTHOLT, R. EICH, E.	8103181146 8103260943 8103190798 8103190438 8103230585#	40-3453 40-3453 XPORTL1C 50-289 H 90-247 R	ENGELKEN.R H ENGELKEN.R H ENGELKEN.R H ENGELKEN.R.H ENGELKEN.R H	8103020019 8103020016 8103020021	50-113 0 50-106 0 50-288 0 50-433 0 50-360 0	ERLICH.R. ERWIN.J.H EGWRIDGE.H E EURE.J.A EVANG.B	8103250651 8103030645* 8103180257 8103250490* 8103260496	PR 50-382 70-36 FR 50-289
EIBENHUT, D. O EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O.	7912310218 8103090028 8103020089 8103030970 8103040312	DRO 50-312 P 50-245 F 50-219 F 90-255 F	ENOELKEN.R H ENOELKEN.R H ENOELKEN.R H ENOELKEN.R H	8103020027 8103020028 8103020031 8103020038 8103020041	50-94 Q 50-228 Q 50-70 Q 50-187 Q 50-908 Q	EVANS.A Q EVANS.R EVANS.M II FABIC.S FABIC.S	8103020624 8103190374 8103260547 8103180928* 8103180887	109EG 50-289 50-317 REVIEW C
EIBENHUT.D.Q EISENHUT.D.Q EIBENHUT.D.Q EISENHUT.D.Q EISENHUT.D.Q	8103040326 8103040336 8101220466 8103020040 8101210445	90-27 F 90-10 F 90-3 P 90-289 0 90-3 P	engelken.r.h Engelken.r h Engelken.r.h Engelken.r.h Engelken.r.h	8103020051 8103020056 8103020066 8103020072 8103020081	50-206 Q 50-528 Q 50-312 Q 50-460 Q 50-397 Q	FAGIN.15 FAHNER.T.C. FAHNER.T.C. FAHNER.T.C. FAIRFIELD.R.P	8103120778 8103200714 8103230671 8103230724 8103230667	PR 27-39 27-39 27-39 50-250
EISEMHUT, D. Q. EISEMHUT, D. Q. EISEMHUT, D. Q. EISEMHUT, D. Q EIGEMHUT, D. Q	8103120047* 8103190732 8103040177* 8103040969* 8103120029*	50-320 P 50-3 P 50-245 P 50-217 P 50-237 P	ENGELHEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8103020096 8103020096 8103020102 81030302099	50-344 0 50-133 0 50-89 0 50-508 0 50-206 0	FALCONER, D. P FALM, R. FALLIN, J. F. FALLIN, J. F. FALLIN, J. F.	8103130678* 8103179366 8103130617 8103130624* 8103130491	50-395 50-289 PROJ PROJ PROJ
EISENHOWER, E. H. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8103050835 8101300244* 8101300259* 8101300267* 8103090039*	REB 50-237 P 50-237 P 50-237 P 50-245 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R. H	8103160330 8103160340 8103160636 8103200897 8103200901	50-312	FANELLO.L. FARNELL.A.S. FARNELL.A.S. FARNELL.A.S. FARNELL.A.S.	8103200550 8103230632 8103230632 8103260796 8103260796	50-229 50-329 50-329 50-329
EIBENHUT, D. Q EIGENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q.	8103190387 8103240290 8102260268 8103090696 8103090700#	50-3 P 50-10 P 50-10 P 50-484 A 50-484 A	ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8103100349 8103169652 8103160654 8103160658 8103160661	50-206 P 50-344 Q 90-312 Q 50-206 Q 50-275 Q	FASAND, A FASAND, A FASAND, A FASAND, A	8103030855* 8103090723* 8103040691 8103200541 8103250423	50-320 50-320 50-320 50-320 50-320
EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G. EISENHUT, D. G.	8103120014 8103120056* 8103030417 8103300160 8103160669	50-3 P 50-320 P 50-344 P 50-3 P 50-3 P	engel, J. D engelken, R. H engelken, R. H engelken, R. H engelken, R. H	8103260021* 8103170001 8103170002 8103170004 8103170005	40-659 50-312 0 50-206 0 50-397 0 50-460 0	FABCELL, D. B. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B.	8103180534 8103050135* 8103040027* 8103040033* 8103040041*	50-312 50-312 50-312 50-312
EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O. EIBENHUT, D. O.	8103180264 8103250024 8103070007 8103070102 8103240675	50-3 F 50-3 P 50-489 A 50-312 F 50-344 P	ENGELKEN, R. H. ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELMAN, R	8103170006 8103170023 8103170026 8103170027 8103260983	50-30B	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B	8103050575+ 8103050061+ 8103030154+ 8103180351+ 8103180361+	50-361 50-361 50-362 50-206 50-206

		·						
AUTHOR	ACCESSION NUMBER	BUBJECT CATEOCRY	AU1HOR	ACCEBBOOA RBBMUA	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBUEC'
FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, D FAULKENBERRY, D FAULKENBERRY, D	8103250340+ 9103110814 9103180851+ 9103250019 9103310562	50-206 0 50-528 0 50-460 0 50-508 0 50-188 P	FELTON, J H	8103060378 8103170180 8103060066 8103160620 8103160626	50-443 H 40-1341 F014 50-482 H 50-482 H	FIELDER, J FIELDS, J. A FIELDS, J. A. FIELDS, J. A. FIELDS, J. A.	8103100437 8103100275 8103100294 8103100359 8103190081	50-321 CONTRAC CONTRAC CONTRAC CONTRAC
FAY.C W FAY.C W FAY.C W FAY.C W	8103230309 8103200035 8103110307 8103030814 8103030889	50-265 G 50-266 O 50-266 G 50-266 P 50-265 P	FELTON, J M	8103160864 8103160879 8103120814 8103170251 8103050189	FOIA FOIA FOIA POIA 50-317 F	FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J.	8103110447 8103110491 8103110616 8103110637 8103110651	50~250 50~302 50~259 50~348 50~335
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8103070570 8103070627 8103100331 8103070546 8103300020	50-266 V 50-266 R 50-266 R 50-266 F PR	FELTON, J M	8103120246 8103170244 8103100765 8103180395 8103260048	FOIA 80-220 G 50-271 F FOIA 40-1947	FIELDER, J. FIELDER, J. FIELDS, J.A. FIELDS, J.A. FIELDS, J.A. FINDLEY, D.E.	8103110680 8103170648 8103270048 8103270565 8103040740+	50-327 50-327 CONTRAC CONTRAC CONTRAC
FAY.C W FAY.C W FAY.C W PAY.C W FAY.C N	8103090381 8103100470 8103170324* 8103170320 8103230823	50-266 P 50-266 P 50-266 R 50-266 H 50-266 Q	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8103120201 8103170297 8103110191 8103120827 8103160773	FD1A 50-461 H 50-29 F FD1A 50-352 H	FINDLEY, D. E FINEMAN, C. P. FINER, L FINEROCK, I. R FINEROCK, I. R.	8103050074* 8103050588 8103200471 8103200313 8103040208	50-259 RE8 50-275 50-219 50-219
FAY.C W Fay.C W Fay.C W Fazio.P V. Fee.Q C.	6103200628 8103250393 8103310473 6103200387 8103181010*	50-266 G 50-266 F 50-266 P 50-461 G REVIEW GRP	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	81031A0B10 8103170128 8103110124 81031A0031 81031A0823	FOIA 50-320 R 50-313 F 50-344 F FOIA	FINFROCK.I.R. FINFROCK.I.R FINFROCK.I.R FINFROCK.I.R. FINFROCK.I.R.	8103090273 8103060295 8103170105# 8103100442 8103110703	50-219 50-219 50-219 50-219
FEE.W F FEE.W F FEE.W F FEHRINGER.J H FEHRINGER.J H	8103200578* 8103070337 8103090211 8103100106 8103170136	50-213 0 50-245 P 50-336 P 50-275 P 50-272 P	FELTON, J H FELTON, J H. FELTON, J M FELTON, J M. FELTON, J M	8103170014 8103120405 8103120852 8103170066 8103160049	70-820 90-344 H 90-206 H 90-334 F 90-334 F	FINFROCK.I.R FINFROCK.1.R FINFROCK.I.R. FINFROCK.I.R FINFROCK.I.R	8103110708* 8103100498 8103130564 8103130568* 8103170633	50-219 50-219 50-219 50-219 50-219
FELERAGEND.C D. FELERABEND.C D. PEIL.R A FEIT.R FEIT.P.	8103090797* 8103190058* 8103300016* 8103080984 8103170895	50-282 G 50-282 G 50-410 G 50-413 A REVIEW ORP	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8103170087 8103160181 8103170101 8103180597 8103180598	90-338 F 90-269 F 90-219 F FOIA FOIA	FINEROCK.I.R. FINEROCK.I.R. FINEROCK.I.R. FINEROCK.I.R FINEROCK.I.R	8103160557 8103160561* 8103160776 8103240587 8103250417	50-219 50-219 50-219 50-219 50-219
FEIT, R FELDE, B K FELDMAN, B. A FELTON, J M. FELTON, J M.	8103170708 8103040491 8103181001* 8101080201 8101070330	REVIEW ORP NUREO CONTRACT 50-317 F 50-272 F	FELTON, J M	8103170140 8103250174* 8103170163 8103170123 8103170450	50-195 F 50-344 H 50-324 F 50-261 F 50-334 F	FINFROCK, 1. R. FINFROCK, 1. R FINFROCK, 1. R FINFROCK, 1. R. FINICLE, D. P.	8103240174 8103240362 8103260288 8103310207 8103100087	50-219 50-219 50-219 50-219 NUREO
FELTON, J M "ELTON, J M "ELTON, J M "ELTON, J M "ELTON, J M	8101070332 8101070548 8101080117 8101090097 8101070341	50-3 F 50-282 F 50-327 F 50-361 F 50-72 F	FELTON, J M FELTON, J M. FELTON, J M FELTON, J M FELTON, J M	8103250172 8103200267 8103230696 8103230709 8103230719	50-344 H 50-293 F F01A F01A F01A	FINK.D 0. FINLAYBON.F.C. FINLEY, A. 0. FINLEY, A. 0. FINLEY, A. 0.	8103240401 8102020497* 8103050242* 8103230153* 8103180575	MISC 10CFR 70-925 50-409 50-289
FELTON, J. M	8101070447 8101080051 8101090083 8012040391 8101070148	50-317 F 50-10 F 50-158 F 50-327 F 50-338 F	FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M FELTON, J. M	8103200235 8103230681 8103250685 8103270735 8103260798	50-289 F F01A 50-10 F 50-333 F F01A	FIDRELLI, O. FIDRELLI, O. FIDRELLI, O. FIDRELLI, O. FIDRELLI, O. FIDRELLI, O.	8103040147 8103030445 8103050041 8103070240* 8103020690	50-346 50-346 50-483 50-346 50-266
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8101070462 8101080003 8101080276 8102270852 8102260479	90-331 F 50-10 F 50-282 F 50-320 E 40-229	FELTON, J M FELTON, J M. FELTON, J M FELTON, J M FELTON, J M	8103260843 8103261024 8103261060 8103261012 8103300171	F01A 90-320 H F01A F01A 90-267 F	FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O.	8103040909* 8103030440 8103020384 8103090774* 8103050198	50-329 50-546 50-483 50-454 50-440
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	9103040779 9103040799 8103020033 9103030052 9103040724	FOIA FOIA FOIA FOIA FOIA	FELTZ, D E FELTZ, D E. FERETTI, M M FERGUSON, B FERGUSON, B	8103030859 8103310542 8103120487 8103280703* 8102260556*	71-9034 50-59 P PR FOIA FOIA	FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O.	8103090771 8103180215* 8103120247 8103180132 8103180150	50-454 50-329 50-329 50-456 50-463
FELTON, J. M.	8103040704 8103040771 8103270091 8103040782 8103040804	FOIA FOIA FOIA FOIA FOIA	FERGUSON, J. H. FERGUSON, J. H. FERGUSON, J. H. FERGUSON, J. H. FERGUSON, J. H.	8103200905 6103300145 8103030865* 8103110529 8103160602	REGOD PR TOPREP 50-338 P 50-338 P	FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O.	8103200568* 8103050179 8103050632 8103180371 8103200566	50-275 50-483 50-275 50-461 50-275
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M.	8103030037 8103090301 8103050320 8103050336 8103050220	FD1A 50-282 F 50-250 F 50-272 F 50-155 F	FERGUSON, J H FERNOS, G FERRA, A, A FERRETTI, R. K. FERRETTI, M.	8103240240 8103110506 8103200441 8103120689 8103120691	50-338 P 50-376 Q 50-289 O PR PR	FIDRELLI.Q. FIDRELLI.Q. FIDRELLI.Q. FIDRELLI.Q. FIDRELLI.Q.	8103230125 8103230128* 8103230156 8103230148 8103241017	50-461 50-461 50-456 50-440 50-454
FELTON: J. M.	8103050356 8103090197 8103090202* 8103030106 8103050043	50~206 F 50~344 H 50~344 H 50~329 Q F01A	PERRER, R. A FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J.	8103120284 8103060327 8103060330 8103060339 8103060351	State Prog 50-250 J 50-250 J 90-259 J 50-348 J	FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O.	8103261140 8103260044 8103260072 8103133075 8103250020	50-546 50-237 50-373 50-454 50-373
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8103050471 8103020048 8103020079 8103020113 8103040998	FOIA FOIA FOIA 50-10 H FOIA	FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J. FIELDER, J.	8103060416 8103060424 8103060442 8103060454 8103060345	50-348 J 50-335 J 50-348 J 50-327 J 50-302 J	FIORELLI.O. FIORELLI.O. FIORELLI.O. FIBER.O. FIBH.R.F.	8103020591 8103240409 8103310717 8103170452# 8103250031#	50-263 50-331 14E 50-368 50-361
FELTON, J. M.	8103020044 8103040230 8103050867 8103060027 8103060054	50-247 H 50-133 H F01A F01A F01A	FIELDER, J. FIELDER, J. FIELDS, J.A. FIELDS, J.A. FIELD, M.P.	8103050450 8103050358 8103090114 8103090130 8103200450	50-321 J 50-259 J CONTRACT CONTRACT 50-289 G	Fibher, R. L. Fibher, W. L. Fibher, W. L. Fibher, W. L. Fibher, W. L.	8103230019* 8103040445 8103030987 8103100715* 8103050580	CONTRAC 50-295 50-346 50-409 50-254

AUTHOR	ACCESSION NUMBER	BUBJECT CATEOURY	RCHTUA	ACCESSION NJMBER	SUBJECT CATEODRY	AYTH <b>Ö</b> R	ACCESSION NUMBER	SUBJEC
FISHER.W L FISHER.W L FISHER.W L FISHER.W L	8103040042 8103190837* 8103100704 8103100720* 8103040275	50-255 S 40-3392 50-409 Q 50-409 Q 50-373 Q	FOULSHAM-P. A FOWINKLE, E. W FOX. D F FOX. D F FOX. M W	8103030630 8103120291 8103040290# 8103160605# 8103120804		GARCIA, P. J.	8103060812 8103060813 8103060815 8103060819 8103090566	40-1162 40-1162 40-1162 40-1162 40-3453
FISHER, CR FISHER, WL FISHER, WL FISHER, WL.	8103060726 8103120408# 8103090480 8103090485# 8103120675#	PR 50-331 9 50-182 0 50-182 0 50-461 0	FRANCIB. D H FRANCIB. D H FRANCIB. D H FRANCIB. D H FRANCIB. D H	8103260729* 8103260723* 8103260721* 8103260703* 8103260688*		GARCIA.P J GARCIA.P J GARCIA.P J GARCIA.P J GARCIA.P J	6103120602 8103120716 8103160204 8103160231 8103160443	40-3453 40-1162 40-8452 40-1162 40-3453
F19HER+W L	8103090698	50-263 0	FRANCIB, D H	8103260678*	40-1947	OARCIA.P. J	8103261083	40-8452
F18HER+W L	8103110422	40-2274		8103260683*	40-1947	OARCIA.P. J	8103240373	40-3453
F18HER+W L	8103120668	50-461 0		8103260658*	40-1947	OARCIA.P. J	8103270036	40-1162
F18HER+W L	8103160368	40-659		8103260631*	40-1947	OARDENER.R	8103180386*	50-461
F18HER+W L	8103160358	40-659		8103260638*	40-1947	GARDNER.D. T	8103110710*	50-361
FISHER, W.L.	8103261107*	50-185 G	FRANCIB.D H FRANKLIN.B.K FRAZER.J FREDERICK.D G FREDERICK.E J	8103260590*	40-1947	GARDNER, D. T	8103110718*	50-361
FISHER, W.L.	8103250652	50-367 G		8103170519*	27-39	GARFIELD, P.	8103170395	50-289
FIGHER, W.L.	8103103676*	70-1144		8102260743*	FDIA	GARNER, D. J.	8103030634	50-346
FIGHER, W.L.	8103060495	50-10 G		8103110520	50-367 A	GARRAHY, J. J.	8103170025*	70-820
FIGHER, W.L.	8103261097	50-186 G		8103160473	RES	GARRITY, J. H	8103100217	50-309
F18HER. W L F18HER. W L F18HEL. L F18HEL. L	8103100672 8103130248 8103180015 8103170673 8103181138	70-1144 40-8760 40-8040 xportlic 40-8384	FREDERICH D G FREDRUND R 9 FREDRICHSON P FREE W N FREE DMAN P D	8103260618 8103020057* 8103260186* 8103120459* 8103200449	PR F01A 90-416 0 CONTRACT 50-289 0	GARRITY, J H	8103140388 8103180589 8103310246 8103310194 81033190284	50-307 50-307 50-307 50-309 50-443
F18HER.W L	8103190678	50-409 Q	FREMLING, A O	8103270260	PR	GARY.R J.	8103230190	50-445
F18HER.B P	8103270741	40-6622	FREMSTAD. B A	8103180453*	50-289 H	GARY.R J.	8103230203	50-445
F18HER.J.K	8103260746	50-289 T	FRIEDENWALD, R	8103050178*	CONTRACT	GARY.R J.	8103190293	50-445
F18HER.W L	8103300352	50-329 B	FRIEDENWALD, R	8103090772*	CONTRACT	GARY.R J.	8103110774	50-445
F18K.P N	8103050938	PR	FRIEL, X P	8103090176*	CONTRACT	GARY.R J.	8103170277	50-445
FISSEL R. FISSEL R. FISSEL R FITZGERALD.M J. FITZGERALD.J A	8103200511 8103200510 8103200543 8103170640# 8103230484	50-358 0 50-358 0 50-358 0 50-219 8	FRISCO.D C FROHIE,R. FROST.B R FROST.B R FROST.B R	8103060451 8103260913% 8101220231* 8103020367 8103030788	50-289 H 50-346 S 50-155 F 50-255 P 50-255 S	GARY, R J. GARY, R. J GARY, R J GARY, R J GASKE, M C	8103180666 8103260929 8103240474 8103240474 8103240534	50-445 50-445 50-445 50-445 ACRE
FITZGERALD.M J.	8103240592*	90-219 B	FROST, 8 R. FROST, 8 R FROST, 8 R FROST, 8 R FROST, 8 R	8103030806	50-255 B	GAUSEWITZ.C	8103203922	50-269
FITZPATRICK.B	8103050778*	50-305 0		8103040681	50-255 B	GAY.T E	8103040265*	50-173
FITZPATRICK.B.	8103130021*	50-305 0		8103090371	50-255 P	GEFELL.P. J.	8103170329	50-269
FIX.J.	8103200490	50-289 H		8103230163*	50-255 Q	GEHR.A.C.	8103030888*	50-275
FIX.R.	8103200490	50-289 H		8103310470	50-155 V	GEHR.A.C.	8103056842	50-275
PIX.W.	8103200490	50-209 H	FRYCING.R	8103040744	PR	GEHR.A C	8103130496	50-275
FLANDERS.W.	8103180590*	50-309 R	FUGITT.H D	8103241128*	FOIA	OEHR.A C	8103130590	50-275
FLEENDR.C H	0103050814	CONTRACT	FUGITT.H D	8103241134*	FOIA	GEHR.A C	8103130476	50-275
FLEENDR.C M	8103050111	CONTRACT	FULLER.G M	8103170433	50-446 H	GEHR.A C	8103130500	50-275
FLEENDR.C M	8103230946	CONTRACT	FULLER.G M	8103180522	50-446 H	GEMR.A C	8103200478	50-275
FLEENOR, C. M	8103250364	CONTRACT	FULTON, J F	8103270452*	50-395 A	QEHR.A C	8103200678	50-275
FLE 18CHAKER, D	8103030557	50-275 0	FURBUSH, M H	8103030883	50-275 G	QEHR.A C	8103230715	50-275
FLE 18CHAKER, D.	0103120560	50-275 0	FURBUSH, M H	8103200678	50-275 G	QEHR.A C.	8103230715	50-275
FLE 18CHAKER, D	8103260750	50-275 0	FURBUSH, M H	8103230715	50-275 G	QEIS.D S.	8103230057	PR
FLE 18CHAKER, D	0103260750	50-275 0	FURB, B J.	8103180410	50-324 G	GEORGE, K. D	8103310720	70-687
FLEISCHAKER, D	8103250566	50-275 0	FURR. B J	8103180425*	50-324 Q	GEORGIOU. B S	8103180966	50-275
FLEMING, B T	8103090544*	50-213 B	FURR. B J	8103230297	50-261 Q	GEORGIOU. B S	8103260788	50-275
FLETCHER, J B	8103110753	50-263 P	FURR. B J	8103060233	50-261 Q	GEORGIOU. B S	8103260843	50-275
FLINT, B, C.	8103120609	PR	FURR. B J	8103060240	50-324 Q	GERETY. H F.	8103070576	50-219
FLOWERB, F. D	8103250426	PR	FURR. B J	8103310904	50-324 Q	GERETY. H F	8103160376	50-219
FLOWERS: F D	8103250518	PR	QAGLIARDQ.J E	8103031105*	50-267 0	GERSICK.M	8103110488	PR
FLOWERS: F D	8103250701	PR	Qagliardq.J E	8103050636*	50-313 0	GERSICK.M	8103110493*	PR
FLYNN, M. J	8103090281	CONTRACT	Qamm.J U	8103030677*	50-267 8	GERSICK.M	8103110696	PR
FLYNN, G F	8103030552	50-324 0	Qamm.J U	8103100606*	50-267 R	GERSINER.W.C.	8103190096*	50-461
FLYNN, B F.	8103030561*	50-324 0	Qamm.J U	8103100582*	50-267 8	GERUSKY.F.M	8102270590*	50-171
FLYNN, M	8103261055	CONTRACT	QAHM, J H.	8103310744*	30-267 6	GEST.R.E	8103181142*	70-794
FLYNN, M	8103160213	CONTRACT	QAHM, J W	8103110527*	50-267 8	GEST.R.E	8103181137	70-754
FLYNN, M	8103261125	CONTRACT	QALKIN, 1. S.	8103100722*	GA999	GETZ.L.	8103250596	PR
FOBEB. R	8103240418*	50-255 8	QALLAGHAR, R G	8103100172*	40-7924	GIBBONS, T.D.	8103050078*	50-348
FOEOE, W M	8103180648	50-289 H	QALLAGHER, E J.	8103180215*	50-329 Q	GIBBONS, T.D.	8103180455*	50-327
FOLEY, T F. FOLEY, T FOLEY, T FOLEY, T. F. FONO, M	8103170879* 8103050298* 8103190067* 8103200236* 8103050541	50-271	OALLAHER, R B GALLINA, C. GALLO, J GALLO, R. M GALLO, J	8103090810 8103050362* 8103040736* 8103060505* 8103100347	NUREQ 50-320 Q 50-247 Q 50-387 Q PR	GIBBONS, T. D. GIBBONS, T. D. GIBBON, T. D. GIBSON, T. D. GIBSON, A. F.	8103180426* 6103180492* 8103050754 6103050472* 6103130716*	50-327 50-369 PR 50-390 50-280
FODTE, A.P.	8103170346	50-289 H	OALLO, J. GALLO, R. M. GALLOCCI, R. GAMBLE, D. H GAMMIE, O. B	8103100347	PR	G1860N.A.F.	8103090372+	50-395
FORAN, J.F.	8103200699	50-275 H		8103230684	50-309 8	G1860N.A.F.	8103120848+	50-269
FORD, E.	8103130155#	50-327 G		8103020723	NUREG	G1860N.A.F.	8103240301+	70-143
FORD, E.	8103130167#	50-327 G		8103170285*	FOIA	G1860N.A.F.	8103260910+	70-143
FORD, N	8103230595	50-546 U		8103170417	50-317 J	G1860N.A.F.	8103030255+	70-1113
FORD,M R. FORMEY, W. L. FORMEY, W. L. FORMEY, W. L. FORMEY, W.	8103250646	NUREO	OANGUER. T.	8103120779	REB	OLBSON, A. F.	8103130844*	70-27
	8103040066	50-409 8	OARCIA. E. M.	8103100010*	50-133 0	OLBSON, A. F.	8103040270*	70-1151
	8103240372*	50-409 0	GARCIA. E. M	8103100403*	50-528 0	OLBSON, A. F.	8103160969*	50-369
	8103170503	50-409 8	QARCIA. P. J.	8103031135	40-3453	OLBSON, A. F.	8103160491*	50-369
	8103170724*	50-341 0	GARCIA. P. J.	8103060794	40-1162	OLBSON, O. T.	8103260341*	70-143
FOSTER, W.E. FOSTER, L.E. FOSTER, J.E. FOSTER, H. FOUKE, R. L.	8103100741# 8103180239# 8103170710# 8103060254 8103230647	0A999 50-369	GARCIA: P. J. GARCIA: P. J. GARCIA: P. J. GARCIA: P. J. GARCIA: P. J.	8103060797 8103060800 8103060804 8103060807 8103060810	40-1162 40-1162 40-1162 40-1162 40-1162	01850N. A. F. 01850N. A. F. 01850N. A. F. 01850N. A. F. 01850N. A. F.	8103170057+ 8103240473* 8103100357 8103240141 8103240370*	50-364 70-1201 70-992 27-47 50-348

AUTHER	ACCESSION NUMBER	SUBJECT CATEODRY	FOHT UA	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHUR	ACCESSION NUMBER	SUBJEC CATEOOI
OILBERT. W C GILGERT. D OILBERT. J D OILBERTS. D. E OILBERTS. L D	8102260926+ 8103030336+ 81030200801+ 81030200801	FOIA 50-498 G 50-338 R 50-282 O 50-498 O	GRAESSER, K. L. GRAESSER, K. L. GRAESSER, K. L. GRAESSER, K. L. GRAHAM, H. J.	8103100349 8103100593 8103170521 8103310548 8103170089*	50-295 R 50-295 S 50-295 S 50-295 S 50-369 0	GRIER. B H GRIER. B H GRIER. B H GRIER. B H ORIER. B H	8103090080 8103240005 8103250170 8103050376 8103090708	50-332 PR 50-334 50-334 50-331
OTTBERTS.D E OTTBERT.R S OTTBERTS.D E OTTBERTS.D E OTTBERTS.D E	8103200446+ 8103170392 8103260697 8103190661 8103250131	50-263	GRAHAM H J GRAHAM H J GRANDEERG, J GRANT, B H GRANT, B H.	B103125602* B103130143* B103120603 B103261072* B103261102*	50-369 0 50-369 0 er Foia Foia	ORIES.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8103100636 8103130026 8103100030 8103090074 8103230909	50-272 70-1703 50-293 50-293 50-219
OllDNER, M L OLLINSKY, V OLLEN, D OLLINAND, D L OLNGRICH, R C	6103199278* 8103050789* 8103069924 8103170146* 8103190379	50-255 0 50-350 U 40-8984 50-18 R 50-209 H	GRANT, B. M. GRANT, B. M. GRANT, W. GRANT, W. B. GRAVES: 2 R	8103261109* 8103261120* 8103170532* 8103120408* 8103270074	FOIA FOIA 27-39 50-331 0 Gureo	ORIER. B H GRIER. B H ORIER. B H GRIER. B H GRIER. B H	8103040179 8103040182 8103040183 8103040187 8103040190	50-317 50-244 50-272 50-277 50-220
OINSBERG.T OINSBERG.T OINSBERG.T OINSBERG.T OINSBERG.T	8103110793 8103110789 8103120787 8103310878 8103040825*	RES RES RES SO-375 O	GRAVES R H GRAVES R H GRAVES R H GRAVES R H GRAVES R H	8103030547 8103030822 8103090542 8103170344 8103170600	90-213 R 50-213 R 50-213 8 50-213 R 50-213 S	ORIER. B H GRIER. B H GRIER. B H ORIER. B H ORIER. B H	8103040194 8103040200 8103040202 8103040205 8103040209	50-245 50-219 50-334 50-3 50-213
OIPARD.E H OIRARD.E H OIRARD.E H OIRARD.E H OIRCUARD.P R	8103120425+ 8103120436+ 8103260508+ 8103260211+ 8103120210	50-428	GRAY.JR GRAY.JR GRAY.JR GRAY.JR GREENMAN.E.	8103110347 8103190628 8103200558 8103240578 8103050789*	50-269 0 50-289 0 50-289 T 50-269 Y 50-220 G	ORIER. B H ORIER. B H ORIER. B H ORIER. B H ORIER. B H	8103040214 8103040220 8103040223 8103040228 8103040233	50-293 50-309 50-271 50-333 50-286
OLAGOLA, A F OLAGOLA, A F OLAGOLA, A F GLAGOLA, A F OLAGOLA, A F	8103130006 8103050164 8103130651 8103090768 8103090456	CENTRACT CONTRACT CONTRACT CENTRACT CENTRACT	GREEMMAN.E. GREEM.H J GREEMMAN.E Q GREEM.H J GREEMMAN.E.G	8103090797* 8103240478 8103180689* 8103240461 8103270788*	50-333 0 90-296 8 50-286 0 50-296 8 50-272 0	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8103040236 8103040239 8103040244 8103100097 8103190668	50-29 50-289 50-320 50-387 50-245
GLEASON, J.P. GLEASON, J.P. GLENN, J. GODDARD, R. J. GODDARD, R. J.	8103180508 8103180520 8103260346* 8103040481 8103040506	50-482 0 50-482 0 F01A 50-471 G 50-461 0	OREEMAN.E. Oreen.H J Oreen.H J Oreen.L Oreen.H J	8103050669 8103020524 8103020532 8103110356 8103040639	50-334	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	6103030248 6103030256 6103030263 6103030271 6103030278	90-410 50-322 50-271 50-273 50-333
GDDDARD, R. J. GDDDARD, R. J. GODWIN, A. V. GCLD, P.	8103100335 8103250014 8103030642 8103050687 8103200637*	50-237 G 50-237 T 70-2909 70-2907 50-443 G	CREENE.O A Green.H J Oreenman.E Oreen.H J Oreen.H J	8103310978 8103100490 8103100509 8103100480 8103110477	REB 50-327	ORTER.B H ORTER.B H ORTER.B H ORTER.B H GRIER.B.H	8103030390 8103030379 8103030386 9103030391	50-354 50-219 50-245 50-307 50-277
GCLDBERG.5 GCLDBERG.J H GCLDBERG.J H GOLDBERG.M L GOLDBERG.J H	8103356827* 8103050658 8103090558 8103180572 8103250620	CDNTRACT 50-498 A 50-498 A 50-247 G PR	GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8103110531 8103100441 8103100500 8103100468 8103100508	50-327 5 50-277 9 50-327 5 50-327 6 90-276 6	ORIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. ORIER, B. H.	8103030398 8103030406 8103300186 8103270793 8103200145	50-352 50-220 50-352 50-333 50-3
ODLDBERO, J H GULDBERO, B C ODLDBERO, B C GULDBERO, J H GULDBERO, J R	8103260326 8103090023 8103100026 8103100204 8103120297	PR 50-250 G 50-367 A 50-466 B 50-471 G	OREEN, H J OREEN, H J GREEN, H J GREEN, H J OREEN, H J	8103110609 8103160755 8103170614 8103170530 8103170540	50-259 8 50-259 8 50-327 S 50-327 8 50-260 8	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8103200158 8103200164 8103200166 8103200171 8103200176	50-213 50-277 50-220 50-334 50-309
GELDEERG, J. H OCLIDEERG, J. R GOLDBERG, J. H GOLDBERG, J. R GOLDBERG, J. H	8103160246 8103136042 8103200304+ 8103170043 8103200270	50-498 V 50-471 G 50-498 K 90-471 G 50-498 X	GREEN.H J GREENMAN.E GREEME.M P GREEM.H J GREEM.H J	8103170408 8103170337 8103200794* 8103170590 8103230792	50-327 8 50-272 8 CONTRACT 50-327 8 50-296 B	ORIER, B. H ORIER, B. H ORIER, B. H GRIER, B. H ORIER, B. H	8103200178 8103200181 8103200181 8103200185 8103200186	50-333 50-320 50-245 50-219 50-289
GOLDDERO. B. C GOLDDERO. S. C GOLDDERO. S. C GOLDDERO. J. H GOLDDERO. J. H	0103200737 8103240327 8103240394 8103270659 8103270761	50-395 0 50-395 0 50-250 0 50-498 A 50-498 F	GREEN. H J GREEN. H J GREEN. H J GREEN. H J GREEN, H J	8103240452 8103240548 8103250297 8103250299 8103250497	50-259 S 50-296 S 50-327 S 50-260 B 50-327 S	ORIER. B H	8103200192 8103200193 8103200195 8103200198 8103200199	50-293 50-317 50-271 50-29 50-272
ODLOBERO S C ODLOBERO S C OGLOBERO S C OOLOBERO J H GOLOBERO S C	8103270648 8103310222 8103310237 8103300168 8103310327	50-367 0 50-367 0 50-367 0 90-498 F 30-250 P	GREEN, H J GREEN. H J GREGER, L R GREGER, L R GREGG, R	8103310591 8103310751 8103030587 8103100715* 8103310903*	50-260 8 50-259 8 50-346 8 50-409 0 70-820	GRIER, B H Grier, B H Grier, B H Grier, B H Grier, B H	8103200202 8103200205 8103200207 8103200128 8103200131	50-244 50-286 50-482 50-293 50-213
OCLDMAN, L A COLLER, K R GOLUB, H V CONZALEZ, M GCOO, H R	8103120755 8102260566* 8103260877* 8103120810 8103190002*	PR FOIA PROJ XPORTLIC GA999	ORIDER, H O ORIER, B H ORIER, B H ORIER, B. H ORIER, B H	8103100446 8103040540* 8103040545* 8103110537* 8103120825	50-294 I 70-820 70-820 50-286 Q 50-320 Q	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	8103200135 8103200138 8103200140 8103200143 8103200149	50-309 50-320 50-316 50-322 50-3
GDDDARD R J. GDDDHL[NO: B GCODMAN, L S GCODMAN, L S	8103180379 8103190523 8103170276 8103190648* 81031005014	50-237 0 70-1338 50-269 H 50-409 P 50-409 8	ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8103030849 8103040514 8103090715 8103020127 8103020135	50-320	ORIER B. H ORIER B. H ORIER B. H ORIER B. H ORIER B. H	8103200153 8103200155 8103200159 8103200163 8103200167	50-485 50-244 50-29 50-271 50-334
ODODMAN, L. 9 ODDCHIN, W. L OGODMIN, E. F ODRANSON, R. A ODRDON, P. S	9103110666* 8103060259 8103119312* 9103230777* 8103120728	50-409 8 70-1151 50-322 A 50-263 S PR	ORIER. B H ORIER. B H ORIER. B H ORIER. B H GRIER. B. H	8103020139 8103020146 8103020148 8103020154 8103020158	50-272	ORIER B H Grier B H Orier B H Grier B H Grier B H	8103200173 8103200182 8103200187 8103200190 8103200201	50-412 50-317 50-219 50-363 50-387
GORMLEY, R C GOSSICK. L V GOTCHY, R L. GOTTSHALL-C L GRAESSER. K. L	8103130106* 8102180209* 8103170109* 8103160237* 8103020397	CDITRACT SECY 50-466 O TGPREP 50-299 R	GRIER, B H ORIER, B H ORIER, B H ORIER, B H GRIER, B H	8103040436 8103070011 8103260142* 8103130115* 8103100212	50-443 0 70-820 F01A 70-1703 50-245 0	ORIER, B. H GRIER, B. H GRIER, B. H ORIER, B. H ORIER, B. H.	8103200203 8103200208 8103200210 8103200213 8103200217	50-354 50-272 50-286 50-352 50-277

91 50-70	01 50-70 91 50-70 97 50-70	31* 50~361 57* 50-309 15 71-422	51* TOPREP 54 WASTE : 59* 50~302	05* 50-302 0 50-302 0 50-302	1 50-302 2 50-302 7 50-302	9 50-302 4 50-302	B 50-324 9¢ 50-331 8* 50-237	9+ 50-369 4+ LOCER 6+ 10CER	3 71~6501 8# 50~403 4• PR	0 70-1257 3 71-9111 7 XPORTL1	7 (PCRTLI 1 RES 9 50-482	0+ 50-261 50-261 7 NVRE0	7* 40-1947 2* 40-1947 3* 40-1947	9 XPCRTLI 6+ 50-245 7+ 50-546		44 50-546 5+ 50-389
6103050552 6103270491 6103270492	8103270573 8103270601 8103270491 8103270497 8103270573	8103270501 8103250031* 8103310257* 8103110215 8103200769	8103193696 8102270351* 8103260364 8103040739* 8103040747*	8103940104 9103160705* 8103030040 0103070510 8103070550	8103110551 8103120301 8103160692 8103160697 8103170571	8103170547 8103170482 8103240539 8103240534 8103240534	8103110061 8103249058 8103300569# 810330958# 8101200449#	8101200623+ 8103230379+ 8103160434+ 8103170326+ 8103170742	B103310747* B103641003 B103050048* B103040722	8103090431 8103090220 8103040993 8103160637 8103170021	8103300138 8103270327 8103040671 8103050669 8103100302*	8103020053 8103160800+ 8103180276+ 8103250627 8103040532+		8103240423+ 8103240427# 9103240572+ 9103240553+ 8103240537+	8103260627# 8103260572# 8103260553#	8103260527# 8103260572# 8103260553* 8103260537* 8103250340 8103240698 8103170666* 8103030457*
HALSETH, G.A. HALTERMAN, H. L. HALTERMAN, H. L. HALTERMAN, H. L. HALTERMAN, H. L.	HOLTERMAN, H. L. HALTERMAN, H. L. HALTERMAN, H. L. HALTERMAN, H. L. HALTERMAN, H. L.	PALTERMAN, H. L. HAMADA, O. HAMADI, J. N. HAMILTON, J. F. HAMILTON, L. D.	HAMPEOND, H. K. PANAUER, S. H. HANCHEY, L. A. HANCOCK, J. A. HANCOCK, J. A.	HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A. HANCOCK, J. A.	HANCOCK, J. A.	HANCDER, J. A HANCDER, J. A HANCDER, J. A HANCDER, J. A HANCBAHAN, E	HANNON, J 11 HANYON, J 11 HANYON, J 10 HANYON, J 10 HANRAHAN, E J PANRAHAN, E J	HANRAMAN, E. J. HANRAMAN, E. J. HANRAMAN, E. J. HANRAMAN, E. J. HANRAMAN, E. J.	HANRAHAN, E. J. HANSEN, L. E. HANSEN, H. A. HANSEN, O. HANSEN, C. E.	MANSEN, L. E HANSEN, L. E HANGEN, L. J HANGEN, L. E HANSEN, L. J	HANSELL, D HANSEN, L E HANSON, R O. HANSON, W. D HANSON, W. D	HARBGECHT, D HARDIN, A. K. HARDIN, J. E. HARMON, D. F.		HARMON D F HARMON D F HARMON D F HARMON D F HARMON D F	HARMON, D F HARMON, D F HARMON, D F	HARMON, D F HARMON, D F HARMON, D F HARMON, D W
5 O		ACT A	0	P 0 0 4	н	7 T T	T T	9 9	r G	T	F T	5 A T		Γ	T T Q	T T Q
90-266	27-39 RES RES RES PR	CENTRAC PR CONTRAC 50~458 71-408	NUREC 50-498 50-498 50-498 50-376	50-34 50-358 50-358 50-397 TCPREP	50-415 TCPREP HISC TOPREP 50-220	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	NUREO CONTRACT CONTRACT CONTRACT CONTRACT	90-280 90-266 8660 90-266	CONTRACT	CONTRACT CONTRACT CONTRACT	50-34B CONTRACT CONTRACT CONTRACT CONTRACT				CONFRACT CONTRACT 50-397	CONFRACT CUTTRACT 30-397 50-397 CA999 CA990 CA990 CA990 CA99 CA99
8103250497 8103100699 + 8103240226 + 81032608274	8103020587 8103190783 8103190609 8103310906 8103350493	B103260540 B103250588 B103270531 B1032301424 B103130302	8103030821 8103040416 8103120241 8103180063 8103240389	8102120542 8103050499* 8103195082* 810202330 8103176676	8103120044 8103180380 8103250466 8103250749 8103160467#	8103050175 8103261053 8103261062* 8103030163 8103270423	81 03250293 81 03230014 81 03240828 81 03240828 81 03230346	8103090469 8103100699• 8103240226• 8103261214 8103060312	8103030319 8103030269 9103090223 8103040729 8103050057	8103020606* 8103040749 8103090114 8103090130 8103170656*	8103180507# 8103100251 8103180275 8103100294 8103100359	8103190081 8103170610* 8103230901 8103230933 8103310853		8103261079 8103270048 8103270565 8103050741* 8103250034*	8103270548 8103270565 8103050741*	8103270948 8103270565 8103050741* 8103250034* 8103160624* 8103160625* 8103110090*
GUISTE, F. C. GULDEMOND, W. O. OULDEMOND, W. O. GUMBLE, F. W.	OUNNIND, S H OUPPY, J O OUPPY, J O OUPPY, J O OUPPY, J G	OUSTAVE, R P OUSTAFSON, P F QUSTAVE, R P QUSTE, N J QUITHRIE, D	GUTHRIE, G. L. GUTIERREZ, J. H. GUTIERREZ, J. H. GUTIERREZ, J. H. GUTIERREZ, J. H.	GUTTMANN, J GWYNN, T P GWYNN, T P HAASS, W P HAASS, W P	PAASS.W P HAASS.W P HAASS.W P HAASS.W P HAEHL.J O	HAQAN, T F HAGAN, T F HAQAN, T F HAGAN, T F HAQAN, T F	HAGAR, R C HAGEY, H HAGEY, H HAGEY, H HAGEY, H	HAORMAN, D. L. HAOUE, R. L. HAOUE, R. L. HAPN, G. HATRFIELD, K. J.	HAIRSTON, C HAIRSTON, C HAIRSTON, C HAIRSTON, C A HAIRSTON, C A	HAIRSTON, W. G HAIRSTON, C. A HAIRSTON, C. HAIRSTON, C. HAIRSTON, W. O.	Hairston, U C Hairston, C Hairston, C Hairston, C Hairston, C	HAIRSTON, C HAIRSTON, W G HAIRSTON, C HAIRSTON, C HAIRSTON, C		HAIRSTON, C HAIRSTON, C HAIRSTON, C HAIST, D P HAIST, D P	HAIRSTON, C HAIRSTON, C HAIST, D P	MAIRSTON, C MAIRSTON, C HAIRSTON, C HAIRST, D HAIST, D HALE, C J HALE, C J HALE, C J HALE, C J
50-220 G 50-410 G 50-443 G 50-333 G	50-245 0 50-387 0 50-277 0 50-245 0 50-220 0	50-320 0 50-271 0 50-443 0 50-244 0 50-333 0	50-317 G 50-293 G 50-213 G 50-29 G 50-363 G	50-3 G 50-272 G 50-219 G 50-334 G 50-286 G	50-388 0 50-309 0 50-269 0 50-322 0 50-485 0	50-412 0 50-916 0 50-410 0 50-352 0 50-354 0	50-277	50-334 0 50-410 0 50-320 0 50-363 0 50-286 0	50-272 0 50-485 0 50-516 0 50-220 0 50-387 0	50-352 0 50-245 0 50-443 0 50-3 0 50-317 0	50-29 0 50-271 0 50-333 0 50-309 0 50-289 0	50-219 G 50-293 G 50-412 G REVIEW ORP PR		50-275 G DRO 50-461 A 50-275 G 50-461 A	DRO 50-461 A 50-275 O	DRO 50-461 A 50-275 G 50-461 A 90-470 A 50-219 P 50-289 H 50-309 G
8103500531 8103500558 8103503553	8103200239 8103200023 8103200033 8103200039 8103200045	8103200048 8103200054 8103200058 8103200063 8103200067	8103209074 8103200076 8103200078 8103200082 8103200086	8103200091 8103200099 8103200099 8103200102	8103200105 8103200106 8103230176 8103230176 8103230206	8103230222 8103230224 8103230227 8103230230 8103230237	8103200129 8103200130 8103200133 8103200134 8103200137	8103200141 8103200144 8103200148 8103200150 8103200152	8103200154 8103200157 8103200141 8103200165 8103200170	8103200175 8103200184 9103200188 8103200206 8103200207	8103200277 8103200282 8103200283 8103200287 8103200293	8103200298 8103200302 8103200317 8103180939* 8103250509		8103180040* 8103180357 8103110853 8103030874* 8103120711	8103180040* 8103160357 8103110853 8103030874*	8103180040* 8103160357 8103110853 8103030894* 8103120711 8103120763 8103270095 8103190468 8103160555
QRIER, B H QRIER, B H QRIER, B H QRIER, B H	GRIER, B H GRIER, B H GRIER, B H GRIER, B H ORIER, B H	GRIER. B H GRIER. B H GRIER. B H GRIER. B H GRIER. B H	ORIER.B. H ORIER.B. H ORIER.B. H ORIER.B. H ORIER.B. H	ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	ORIER, B. H. ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	GRIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	GRIER, B H ORIER, B H ORIER, B H GRIER, B H ORIER, B H	ORIER.B H ORIER.B H ORIER.B H ORIER.B H GRIER.B H	QRIER. B H QRIER. B H GRIER. B H. GRIER. B H. GRIER. B H.	ORIER.B H. ORIER.B H. ORIER.B H ORIER.B H ORIER.B H	ORIER, B H. GRIER, B H. ORIER, B H ORIER, B H ORIER, B H	GRIER, B. H GRIER, B. H. GRIER, B. H. GRIFFITH, P GRIFFITH, C	O TEFFE I I I I	ORIMEB, B M. ORIMEB, B M. ORIMEB, C. I. GRIMEB, C. I. GRIMEB, C. I.	ORIMES, B.K. ORIMES, B.K. ORIMES, C. I. ORIMES, B.K.	ORIMES, B. K. ORIMES, B. K. ORIMES, C. I. ORIMEA, F. OROCC, R. M.

.....

MAYNER. I Q

HAVAES, J G

IAVNEC . O

IAYNER. .. G

MYNEG. J 0

MATEL TOUL & B

HAZELTON, W 8

IAYS. J. K

HAZLE, A. J.

HAZLE, A. J

HEARNE, T. J

HEATHERLY. T. L

HEATHER V. T L

HEDEHAN, W N

HEDEMAN, W. N.

HEDEMAN, W. II

HEDEMAN, U. N.

HEENER W O

HEGNER, J. D.

METOER . 1 H

HEIDER, L. H

HETDER L H

HEIDER, L H.

HE INLE IN. D.

HEINS, O L

RETARTOR T. J.

HE INTZELMAN, K

HEISHMAN, R. F.

HEISHMAN, R F

HEISHMAN.R. F

HEISHMAN, R. F.

HEISHMAN, R. F.

HEISHHAN, R. F.

HEISHMAN, R. F.

HEISHHAN, R F

HEISHMAN, R. F.

HE LEHMAN, R F

HEIMBUECHER. J

RETMAN, D

HEAD, K

HEAD, G F

HERDON, F

ACCESSION

8103231107

B103100528

0103240088

8103260078

9103240359

0103040325

01031102704

8103110263+

8103050572+

8103100690

8103070597

8103300323

9103240424

B103050600+

8103240823+

8103030415

8103090537

8103270065

B103060782

8103250094

9103120415

8103100229

8103100341

8103200212

B103230469

8103020708

B103160983\*

B103050557\*

8103170379

8103100449

A103230161

B103040066

B103040474

8103040054

8103020495

0103030335

8103031014

8103031073

8103030942

R103040038

8103030418

8103050383\*

90-204

50-206

50-204

50-206

90-206

90-250

90-338

90-339

50-424

50-4R3

50-390

50-390

NUREO

90-349

50-334

30-271

50-271

50-271

50-320

50-492

50-440

50-255

71-219

50-409

30-315

50-331

IBE

LAE

ILE

50-237

50-155 50-249

XPORTUTO

90-20

DRO

PR

00

WASTE HOT

WASTE MOT

۵

š

Λ

A

8

ñ

o

ត

ā

0

P

Н

8

8

5

8

6

SUBJECT

# PERSONAL AUTHOR INDEX

----

LETSHMAN D F

HETSHMAN, R. F.

HELERMAN, R. F.

HETSHMAN, R. F.

HEISHMAN, R F

HEIEHMAN, R F

HE ( SHMAN, R F

HE I SHMAN, R. F.

HEISHMANLR F

HEISHMAN, R. F.

HE I SHMAN, R. P.

HE I SHMAIL R F

HE I SHMAN, R. F.

HEL FRICH, O. F.

HELBERON, K. A.

HELGESON K A.

HELM. K

HELM, K

HELM, K 9

HELM.K S

HELBON. J D

HELMICK. C.

HENDON, B.

HENDRIE, J. H.

HENDRICK, W O

HENDRICK . W O

HENDRIE, J.K.

HENDRIE, J M

HENDRIE J. M.

HENDRIE J M

HENDRIE, J. M

HENDRIE, J. M.

HENDRIE, J. M.

HENDRIE J. M

HERORIE. J. M.

HENDRIE, J. M.

HENDRIE, J. M

HENDRIE, J. M

HENDRIE, J. M

PENDERBON, J E.

HE I SING-GOODMAN

ACCEBSION

BIOGOAGERA

B103300150

B103120834

B103050407

B103110750

8103160976

8103170362

B103200440

8103180111

8103190208

8103240409

8103250168

8103250197

8103060799

8103030961

8103020440

8103040316

B1031B1103

B1031B1106\*

B103130076

8103100649

8103180906

B103160343

0103050998

8103200515

8103120615

B103020675

8103020688\*

8103120263\*

B103170713

8103190007

8103200061

8103240129

8103240139

B1032A0042

8103240246

8103240254\*

B103240260\*

B103240267\*

8103240269\*

8103240272\*

81030401704

50-315

50-373

50-440

50-341

50-483

50-358

50-346

30-263

50-315

50-546

50-331

50-315

50-259

70-820

70-820

YEAR TITC

\*PORTLIC

XPORTL IC

XPCRTL1C

XPORTI 10

XPORTI 1C

40-8102

50-142 50-289

50-369

XPORTLIC

XPORTL1C

COMM18810N

COMMIRSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

COMMISSION

50-289

LOCER

0

Λ

a

Ω

a

ō

ā

0

U,

BUBUECT

C4.7.C6.DDV

ACCERSION

G 3BMU's

ANTHER

HERDT. A R

HERDT, A R

HERDT, A. R.

HERDT, A.R.

HERDT A R

HERDT, A. R.

HERDT, A R

HERBY, A. R.

HERDT, A. R.

HERDT. A R

HEROT. A R

HERDT. A R

HERDT, A. R

HERDT A R.

HERDT, A.R.

HERDT, A R

HERNANDEZ, Q

HERNANDE Z. Q

HERNANDEZ, Q.

HERNANDEZ, V. A

HERNANDEZ, U.A.

HERNANDEZ, V. A.

HERNANDET, U A

HERNANDEZ, V. A

HERNANDEZ, V. A

HERNANDEZ, V A

HERNANDEZ, V. A

HERNANDEZ, V A

HERR R. K.

HERR. J. C.

HERRERA, T. D.

HERRMANN, H

HERRMANN, H

HERBCH, M. M.

HEWARD, R. W

HEWARD, R.

HEWEY, L. W.

HEWEY, L. W.

HERZ.E.

HEBB. R. A

HERSCHLER, E

HERRMANN, R. B

**SUBJECT** 

50~340

50-369

50-395

50-438

50-276

50~260

50-51B

90-269

50-416

50-553

50-566

50-390

90-33B

90-424 50-280

50-389

50-460

50-528

50-528

50-302

10-302

50-302

50-302

90-302

50-302

50-302

50-302

50-498 50-395

50-206

50-471

XPORTLIC

CONTRACT

PR

REB

50-289

50-289

50-361

105-08

WASTE MO

B103050410\*

8103180239\*

B103040025\*

8103120425

B103120436#

B103120448#

8103190194\*

B103240785#

B103180508\*

B103190338\*

B103260456\*

8103260500\*

B1033107894

8103270158\*

81032700724

B103590511\*

B103040374#

B103110847\*

8103040331\*

8103090513\*

B103090559#

B103160701#

B103160707#

B103170576\*

8103170553

B103170486\*

B103240541#

8103240536+

8103120593\*

8103260414#

8103190042\*

BI03240140

8103590190

B103250079

8103120154

8103120851

8103130538\*

8103130529#

8103060615\*

B103060619\*

8103200471\*

AUTHOR	NUMBER	CATEGOR		AUTHOR	NUMBER	CATEGO	RY	AUTHOR	NOMBER	CATEODR
MARTIN C.	8103270186	70-687		HE I SHMAN, R F	8103050397	50-331	o	HENDRIE, J M	8103240116	70-143
PART.H C	B103270193•	70-687		HEISHMAN, R F	8103050768	50-305	O.	HENDRIE. J M	8103260419	1E81MMQ3
HART, R J	8103040551+	70-820		HEISHMAN, R F	8103130016	50-305	a	HENDRIE, J H	8103270110	30-275
PART. J	8103230642	50-382	F	PEISHMAN R F	8103040015	50-346	8	PENDRIE. J M	8103591135	COMMISSIO
L.TPAN	B103240046	50-382	A	HEIEHMAN, R F	8103050339	50~263	O .	HENDRIE, J M	8103261190	COMMISSIO
HARTER, E. S	8103310680	70-1703		HEISHMAN R F	8103050342*	50~263	Q.	HENDRIE, J M	B103261199*	CQMM18910
HARTMAN, C. J.	B103190153*	50-155	F	HEISHMAN, R F	8103050794	50-409	o	HENDRIE. J M	B103261157	COMMIBBIO
HARTMAN, C. J.	8103110471	50-155	R	⊬EISHMAN₁R F	8103090623	50-373	a	HENDRIE, J M	B103261205	COMM16910
HARTMAN, C	8103230843	50-289	T	HEISHMAN, R F	8103090794	50-282	0	HENDRIE, J. M	B103261209*	COMM18910
HARTWIG. P B	8103040394	HISC		HEISHMAN.R F	8103090264	50-254	()	HENDRIE, J M	8103260576	COMMISSI
HARHODD, F. C	8103200437	50-289	н	HE18HMANLR F	8103100685	50~266	0	HENDRIE, J M	0103260581*	CDMM16910
HASLAM E F.	8:03:00713*	3A9 <b>9</b> 9		HE I SHMAN, R F	8103100689*	50-265	O .	HENDRIE J. M	0103240503#	COMMISSI
HATCH, B. W.	8103040615	50-297	P	HEISHMAN, R F	8103090100	50-264	Q	HENDRIE, J M	8103240586*	COMMISSI
HAUB, A P	8103110598*	50-361	t	HEISHMAN R F	8103130104	50-315	a	HENDRIE. J M	8103260591*	1591 WHD3
HAUETER, R. L.	8103260295	PR		HE ! EHMAN, R. F	8103130112*	50-315	G	HENDRIE, J. M.	B103260594*	COMMISSIO
HAUGHNEY, C. J	8103260497	50-201	Р	HEISHMAN R. F.	8103050398	50-155	Q	HENDRIE. J M	8103260596	COMM16810
HAUGHNEY, C. J	8103260905	50-201	Р	HEISHMAN R F	8103050481	50~39B	Q .	HENDRIE, J M	8103260599*	COMM18810
HAUSIMEY, C. J	8103250183	50-201	Þ	REISHMAN, P. F.	B103050489+	50-358	G	HENDRIE. J M	8103261149	COMM1681
HAUGHNEY, C. J	8103260518	90-201	Р	HEISHMAN R F	0103030367	50-155	G .	HENDRIE, J M	8103270007	COMM1691
HAUGHNEY, C. J.	0103270752	90-201	н	HEISHMAN R F.	8103130274	50-263	G.	PENCRIE, J M	8103270014	50-320
HAUST. D P	#4E0001E01B	50-397	G	HE15HMANLR F	8103130227	90-10	G	HENDRIE J M.	B103270016*	50-320
HAUZ. N	B102250747*	AIDT		HEISHMAN, R. F	8103130233#	50-10	G	HENDRIE, J. M.	B1035903B9	COMMISSIO
HAVERKAMP D R	B103190543*	50-289	r	HE I SHMAN, R. F	8103120480	50-315	G	HENNESSEY, J.F.	B102260775*	FOIA
HAVERHAMP D R	0103190590*	50-289	г	HEISHMAN, R. F.	8103120484#	50~315	G	HENNESSY, N P	B103110315.	50~322
HAHAINS, J E	8103040844*	AIGR		HEIGHMAN, R. F	6103130165*	90-315	G	HENRY, L C.	B103591135	50-57
PAWAINS. J	8103040816#	FOIA		HE LEHMAN, R. F	8103160994*	50-315	0	HENRY, J W	8103250233	HIBC
HAWAINS, F C	81030204034	50-483	Q.	HE ISHMAN, R. F	8103140948	50~346	g .	HENSLEY K. D.	6103300181	70-143
HARKINS, E F	8103260512	27-39		HEISHMAN R. F.	B103160937	50-254	O .	HENSLEY, K D	8103300033	70-143
HAYES, D W	6012170210	50-249	0	HEISHMAIL R. F	8103181111	50-2	Q.	HENSLEY, K. D.	6103300183	70~143
HAYES. D W	8103020403	50~483	ā	HEISHMAN, R. F	8103181113*	50-2	a	HERCZEQ, J N	8103030433	REB
MAYES, D	8103310360	50-494	8	HEISHMAN R. F.	0103190116	50-331	G.	HERDT.A R	8103160537*	90-370
HAYN, C H	8103105309	PR	-	HEISHMAN, R. F	8103170049	90-282	o ·	HERDT, A.R.	8103180412*	50-390
HAYNEB, R. C.	B103040374#	50-460	Q.	HEISHMAN, R. F	8103170071	50~35B	ō	HERDT, A R	8103050082*	50-416
HAYNES R C.	B103030811*	50-397	ō.	HE LEHMAN R F	8103170076*	90-358	ä	HERDT, A. R.	8103030186*	50~553
HAYNES . R C	8103050781	50-528	Ġ	HEISHMAN R. F.	8103240385	50-409	ā	HERDT A R	B103100407#	50-438
HAYNES, R. C.	0103180093*	50-508	a	HE LEHMAN, R F	8103240398+	50-409	Q.	HERDT. A R	8103050384#	50-395
HAYNES, R C	B103100036*	50-397	ā	PEISCHAN, R. F.	8103240214	90-266	Ğ.	HERDT, A R	B103250154*	50-321
HAYNES, J Q	8103100183	50~204	P	REISHMAN, R F	8103050089	50-409	ã	HERDT, A.R.	8103040801*	90-338

AUTHUR	NUMBER	CATEGURY	AUTHOR	NUMBER	CATEGORY	AUTHOR	NUMBER	CATE
MIGHLAND, H.R. HILL, H.M. HILL, L.J. HILL, A.O. HILL, A.	8102230694* 8103190098* 8103020680 8103261137* 8103230638	40-4492 50-272	PORIN, W A HORIN, W A HORLEBEIN, K HORN, C PORGWITZ, A A	8103170565 8103270536 8103050766 8103310638* 8103170495*	50-445 ( 50-445 ( PR 50-269 1	B HUKILL'H D HUKILL'H D	8103140719 8103170549 8103170545 8103180561 8103180561	50-26 50-26 50-26 50-26 50-26
HILLHAN, R E HIND, J A HIND, J A. HIND, J A HIND, J A	8103240186* 8103030118* 8103030101 8103050229* 8103050242*	50-219 R 70-2838 70-2838 70-925 70-925	HOROWITZ, A A HOREY, C M HOSEY, C M HOSEY, C, M HOSEY, C, M	8103170499* 8103110698* 8103120848* 8103120479 8103260370*	50~361 ( 90-269 ( 50~259 8	HURILLIH D. HUMILLIH D.	8103230615 8103240447 8103270691 8103310505 8103310601	50-289 50-289 50-289 50-289 50-289
HIND, J A. HIND, J A HIND, J A HINDERBTEIN, C HINES, E	8103050224 8103020496 8103190089 8103150757 8103120128	70-925 50-295 B 50-461 Q 50-466 Q 50-341 Q	HOSELER. D HOESLER. D E HOSELER. D HOVEY. G K HOVEY. G K	8103190617 8103250238* 8103200547 8103100042 8102180347	50-289 H 50-289 G 50-289 O 50-320 R 71-5026	HULBURT, M A HUMPHREY, M J.	8103310602* 8103180938 8103181051* 8103180633 8103230927*	50~289 40~871 50~271 50~498 CONTRA
Hines, E. Hines, E. Hines, E Hines, E Hintzen, H.	8103090612 8103190364 8103160431 8103160422 8103120414	50-341 B 50-341 0 50-341 B 50-341 B 50-367 H	HOVEY, O K HOVEY, O K HOVEY, O K	8103040485 8103020407 81030204134 8103020525 8103030829	50-320 P 50-320 P 50-320 P 50-320 P	HUNNICUIT, D.M. HUNNICUIT, D.M. HUNNICUIT, D.M.	8103270578* 9103050636* 9103050650* 8103231026* 8103170373	CCNTRA 50-313 50-285 50-313 50-313
H1NZE, W.J. H1RSCHFELDER, D. H1RSCH, D. H1TCHCOCK, M.J. HQAGLAND, K.E.	8103040938 8103040787 8103230670 8103170592 8103190337	NUREO FOIA 50-142 H 50-289 H 50-219 P	HOVEA' O K HONEA' O K HONEA' O K HONEA' O K	8103030652 8103030363 8103040297 8103060478 8103100431	50-320 B 50-320 R 50-320 R 50-320 P	HUNSTAD, A. A. HUNSTAD, A. A. HUNTER, V. H. HUNTER, A. HUNTER, R. G.	8103100361* 8103200736* 8103110008* 8103200617 8103100577*	50-282 30-306 90-799 90-289 30-316
POCEVAR, C. J. HOCHRESTER, L. E. HODOEG, J. W. HOEFLING, R. K. HOENEG, O. R.	8103100762* 8103250141* 8103130662* 8103180077 8103020775	CONTRACT NUREO 70-143 50-361 Q NUREO	HOVEY.O K HOVEY.O K HOVEY.O K HOVEY.O K	8103100549 8103100922 8103120431 8103170558 8103170556	50-320 B 50-320 P 50-320 B 50-320 B 50-320 B	HUNTER, V H HUNTER, D R. HUNTER, R S HUNTER, R. S HUNTER, R. S	8103310897* 8103130172* 8103020626 8103180123* 8103250175#	3A999 50-335 50-315 50-315 50-315
HOFER, O. O HOFER, O. O HOFEMAN, D. P HOFEMAN, D. P HOFEMAN, J.	8103030908 8103240357 8103030374* 8103050256* 8103170485	50-382 A 50-382 A 50-155 Q 50-155 F 50-466 H	HOVEY, O K HOVEY, O K HOVEY, O K	8103170475 8103180466 8103180686 8103180697* 8103170353	50-320 P 50-320 P 50-320 P 50-320 P 50-320 S	HUNTER, R. S. HUNTER, R. S. HURET, J. B. HUGET, J. B. HUGET, A. HUGET, A.	8103170261 8103231076 8103200477 8103090330# 8103310231#	50-315 50-315 50-209 50-29 50-29
HOFFMAN, D. P. HOFFMAN, D. P HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8103070451 8103070459 8103130019 8103260245 8103260256	PR PR RECOD PR PR	HDVEY. O K HOVEY. O K HOVEY. O K HOVEY. O K	8103170518 8103170534 8103170595 8103230694 8103230703	50-320 P 50-320 P 50-320 P 50-320 P	HUSEBY, D. E IANNI, R. W. IDRIBS, I. M IFFLAND, R. R. IGNATONIS, A. J.	8103260612+ 8103180588+ 8103050203+ 8103120431 8103030305+	50-317 TOPREP CONTRAC 50-213 50-250
HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, C. B HOFFMAN, D. P. HOFFMAN, D. P.	8103040884 8103190147= 8103040320 8103040950 8103090392	PR 50-155 F 50-361 D 50-155 B 50-155 P	HOVEY, O K HOVEY, O K HOVEY, O, K HOVEY, O, K HOVEY, O K	8103240243 8103240250* 8103250387 8103300257 8103300272	50-320 P 50-320 P 50-320 P 50-320 R 50-320 P	ionatonis.a J Ilan.a. Inslee.m. n Iosso, c Ippolito. t a	8103190312* 8103270041 8103270196 8103230835 8101300233	50-250 XPORTL: PR 50-359 50-237
HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8103090412 8103100317 8103190111 8103240412 8103260186	50-135 P 50-135 P 50-155 P 50-295 B 50-155 P	HOVEY, O. K HOWARD, J. E HOWE, P. W HOWE, P. W HOWE, P. W	8103300387 8103230458 8103040064 8103090413 8103260521*	50-320 F 50-471 B 30-400 0 50-400 Q	IPPOLITO, T. A IPPOLITO, I. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A	8103030992 8103031006* 8103031024* 8103030086 8103030097*	50-278 50-298 50-278 50-331 50-331
HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOGAN, J. P. HOLLENBACH, D. M.	8103260249 8103260480 8103300476 8103090721 8103190675	50-155 P 50-155 P 50-155 P 70-734 50-287 H	HOWELP W HOWELP W. HOWELL, J C HOWELL, J C HOWELL, J C	8103260501* 8103270506 8103050225* 8103310820* 8103020704*	50-400 0 50-400 0 50-369 0 50-302 0 50-538 0	IPPGLITO.T.A IPPGLITO.T.A IPPOLITO.T.A IPPGLITG.T.A	8103030115* 8103050139 8103180861* 8103040211 8103040224*	50-331 50-278 50-10 50-263 50-263
HOLLIBAN. HOLLINOBAE.F. HOLLINOBAYAC.J. HOLLINGAYAC.J. HOLLINGAYAC.J.	8103050823 8103120330 8103020248 8103041024 8103040457	PR 50-369 H 50-277 P 50-244 P 50-321 P	HOWELL, B. H HOWLETT, Q. H HOYLE, A HOYLE, B HUANG, L T.	8103240780 8103170594* 8103310832 8103181037* 8103190774	DRG 50~336 R CONTRACT 50~271 H 50~361 A	IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A.	8103040225 8103040237* 8103050126 8103090032 8103100646	50-293 50-263 50-263 50-254 50-237
HOLLGHAY, C. J. HOLDHAY, C. F. HOLDHAY, C. F. HOLDHAY, C. F. HOLDHAY, C. F. HOLT, R. R.	8103240042 8103050032 8103031071 8103180432 8103020068	50-327 P REB REB RES 50-247 H	HUBACEK, W. O. HUBACEK, M. O HUBBARD, H. HUBBARD, R. E HUDGON, S.	8103033358* 8103260471* 8103020581 8103260800* 8103180668*	50-498 0 50-498 0 50-70 0 50-237 0 50-220 0	IPPOLITO,T A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A.	8103120080 8103040872 8103050310 8103050314* 8103080322*	50-293 50-333 50-331 50-331
HOLT, I V. HOLT, I. V. HOLZMER, M. M. HONICKER, J. HOOD, D. B.	8103100394 8103100399* 8103130119* 8103230714 8103090079	70-309 70-309 90-315 0 FOIA 50-329 8	HUDBON, J. M HUDBON, J. HUBBNER, L. Q. HUBBNER, L. G. HUBTER, L.	8103030664 8103040511 8103270675* 8103270482* 8103040042	NUREO NUREO 50-263 R 50-262 R 50-255 8	IPPOLITO, T. A.	B103120007 B103120012* B103100409 B103100414* B103100422*	50-293 50-293 50-298 50-298
HODD, D. HODD, D. HODD, D. HODD, D. HODD, D.	8103260043 8103260883 8103190035 8103230307 8103190619	50-458 A 50-329 A 50-329 A 50-329 A 50-329 Q	HUFF.R.J. HUFFMAN.J.M. HUGG.D.B. HUGHEB.J. HUGHEB.J.	8103300392 8103230237 8103090583 8103050204* 8103230151*	50-361 H NUREQ PR 50-440 G 50-440 G	IPPOLITO, T. A.	8103130020 8103130027* 8103110798 8103130193 8103130200*	50-259 50-259 50-271 50-298 50-298
HOOD, D. HOPKINS, J. 8. HOPKINS, J. 8. HORIN, W. A. HORIN, W. A.	8103240079 8103030740* 8103330156* 8103050454 8103050468	50-329 A 50-409 G 50-373 G 50-445 O 90-449 O	HURILL, H. D. HURICL, H. D. HURILL, H. D. HURILL, H. D. HURILL, H. D.	8103100219 8103170111 8103030628 8103040758 8103050520	50-289 0 50-289 1 50-289 R 50-289 P	IPPOLITO, T A. IPPOLITO, T A. IPPOLITO, T A. IPPOLITO, T. A. IPPOLITO, T. A. IPPOLITO, T. A.	8103130205* 8103110818 8103130118* 8103130131*	50-278 50-271 50-259 50-259 50-259
HORIN, W. A HORIN, W. A. HORIN, W. A. HORIN, W. A. HORIN, W. A.	8103050656 8103050668 8103100352 8103100352 8103190565	50-445 G 50-445 G PR PR 90-445 G	HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D.	8103100365 8103200247* 8103060596 8103060628 8103120282	50-289 R 50-289 F 50-289 S 50-269 P 50-269 I	PPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A.	8103110024 8103170079 8103130086 8103130660 8103130666	50-271 50-271 50-293 50-263 50-263

ACCESSION NUMBER

AUTHOR

BUBLECT CATEGORY ACCESSION NUMBER

AUTHOR

BUBUI

ACCEBBION NUMBER

AUTHOR

BUBJECT CATEGORY

ADH TUG	ACCESSION MUMBER	GUBLECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHCR	NOWOEK WCCERRION	SUBJECT CATEOD
IPPCLITO, T. A	8103130675+ 8103169133 8103160003 8103180004+ 8103160006+	50-263 P 50-259 F 50-333 P 50-333 P 50-333 P	JANECEM. R F JANECEM. R F JANECEM. R F JANECEM. R F JANECEM. R F	8103130407 8103120548 8103180745 8103233799 8103200583	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P	JONES, K JONES, J L JONES, N C JONES, B W JONES, J	8103170658 8103110502* 8103180032 8103180032	50-466 50-287 50-285 50-275 50-289
IPPOLITO T. A	8103170206 8103170216+ 8103170247+ 8103126835 8103120840	50-271 P 50-271 P 50-271 P 50-278 P 50-263 0	JANUSKA, A O  JANUSKA, A O	8103240198 8103270484 8103270663 8103360477 8103040278#	50-237 P 50-237 0 50-254 0 50-254 P 50-373 0	J01/E3, W C J01/E5, B W J01/E5, B W J01/E5, R W J01/E5, R A	8103180512 8103120373* 8103120373* 8103120373*	50-285 50-275 50-275 HABTE M 50-445
IPPOLITO T A LPPOLITO T A IPPOLITO T A IPPOLITO T A IPPOLITO T A	6103180137 8103180142* 8103180147* 8103180265 8103181126	50-331 P 50-331 P 50-331 P 50-271 P 50-331 F	Jape.f Jape.f Jape.tir D Jerrins.g r Jenkins.g r	8103240648+ 8103240822+ 8102170507 8103050429+ 8103090755+	50-269 Q 50-261 Q 71-9013 50-369 Q 50-340 Q	JONES, R. J. JONES, B. W. JONES, D. W. JONES, D. W. JONES, B. W.	0103191092 8103190849 8103250153* 8103250173* 8103170052	PR 50-275 70-27 70-143 50-275
IPPOLITO T A	8103183013• 1100816018 1100816018 1100816018	50-293 P 50-220 P 50-324 0 50-220 P 50-220 P	JEMPINS, O.R. JENNING, G.R. JENSEH, C.H. JEDEY, B.	8103090767* 8103260341* 8102030495 8101070349* 8103180894	50-413 G 70-143 REOOD 50-72 F XPORILIC	JONES, B. W. JONES, W. C. JONES, W. C. JONES, B. W. JONES, B. W.	8103200050 8103240505 8103270407* 8103270181 8103270460	50-275 50-285 50-285 50-275 50-275
IPPOLITO T A	8103120749 8103120812 8103120832 8103120832 8103170249	50-271 P 50-293 P 50-298 P 50-298 P 50-259 P	JOEL, K. E. JOHNSON, L. JOHNSON, L. JOHNSON, L. JOHNSON, L.	8103170503* 8103040493* 8103260811* 8103260796* 8103260603*	M16C 40-8610 F01A F01A F01A	JONES, D. W. JONES, W. C. JONES, D. W. JORDAN, M. JORDAN, M.	8103310224 8103310446* 8103310230* 8103120649 8103060965*	50~539 50~285 50~538 PR 50~361
IPPOLITO T A	8103170259* 8103170267* 8103170166 8103170172* 8103170181*	50-259 P 50-259 P 50-271 P 50-271 P 50-271 P	JOHNSON, L JOHNSON, D JOHNSON, D F JOHNSON, 9 H JOHNSON, A H	8103040499* 8103260784* 8103270766* 8103100024* 8103090272*	40-8410 FD1A 70-135 50-344 0 50-338 0	JORDAN, E. L. JORDAN, M. J. JORDAN, M. S. JORDAN, M. B. JORDAN, M. S.	8103260387# 8103130245# 8103180599 8103060349 8103060349	50-244 50-10 FOIA 50-443 50-443
IPPCLITO T A	8103231095 8103260264 8103260278* 8103260278* 8103250673	50-259 P 50-324 P 50-324 P 50-324 P 50-259 P	JOHNSON, A R JOHNSON, M D JOHNSON, M D JOHNSON, J J JOHNSTON, R E	8103130236* 8103231026* 8103180913* 8103030610 8103130035	50-498 0 50-313 0 50-344 0 Nureo Regod	JORDAN, E. O. JORDAN, W. B. JORDAN, W. S. JORGENBON, L. R. JORGENBON, L. R.	8103130388 8103130425 8103130425 8103030959* 8103030971*	50-77 50-443 50-443 71-407 71-416
IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A PPOLITO, T A PPOLITO, T A	8103240559 8103249543 8103310011 8103310015 8103310023	50-298 P 50-331 P 50-333 P 50-333 P 50-333 P	JOHNSON, J A JOHNSON, C R JOHNSON, C R JOHNSON, C R	8103030932 8103240697* 8103170209 8103110807 8103030710	71-419 50-397	JORGENSON, L. R. JORGENSON, L. R. JOSEPH, L. J. JOUXDEF, P. V. JOYNER, J. H.	8103090717 8103160021 B103260315 8103030507# 8103090658#	71-416 71-416 PR 50-326 70-135
PPOLITO: T.A  PPOLITO: T.A  PPOLITO: T.A  PPOLITO: T.A  PPOLITO: T.A	6103310426 6103260413 6103260427* 6103260442* 8103261150	50-29B P 50-220 P 50-220 P 50-220 P 50-254 P	JOHNSON, R. O. JOHNSON, R. O. JOHNSON, R. O. JOHNSON, T. L.	8103030730 8103030736 8103030739 8103240744* 8103130197	90-202 J 50-263 J 50-263 J 50-344 4 40-8584	JOYNER, J. H JOYNER, J. H JOYNER, J. H JOYNER, J. H	8103200395* 8103030803 8103030842 8103200369 8103240376	70-1100 50-247 50-247 70-371 50-273
1PPO_1TO.T.A 1PPO_1TO.T.A 1PPO_1TO.T.A 1PPOL1TO.T.A 1PPOL1TO.T.A	8103241195* 8103241141* 8103240054 8103240042* 8103240070*	50-254 P 50-254 P 50-324 P 50-324 P 50-324 P	JOHNSON, J. E. JOHNSON, J. JOHNSON, J. JOHNSON, G. P. JOHNSON, C. R.	8103060291 8103030570 8103030911 8103110634 8103250720	50-267 R 50-293 8 50-293 8 50-309 P PR	JOYNER, J JULIAN, C. A JULIAN, C. A JULIAN, C. JULIAN, C. A.	8103310708 8103050428* 8103170312* 8103130155* 8103120802*	18E 50-335 50-250 50-327 50-369
IPPOLITO T A IPPOLITO T A IPPOLITO T A IPPCLITO T A IRELAND R IRELAND J H	0103300562 0103300566* 0103310155 0103261141 0103240423	50-331 P 50-331 P 50-220 F 070 50-255 J	JOHNSON, Č. R. JOHNSON, W. P. JOHNSON, W. P. JOHNSON, C. R. JOHNSON, N. R.	8103230121 8103250470 8103130351 6103240516 6103230923	71-6698 PR 50-29 P XPORTLIC XPORTLIC	JULIAN C. A. JULIAN C. A. JULIAN C. JULIAN C. JULIAN C. JULIAN C.	8103130143* 8103160760* 8103240648* 8103270934* 8103100408	50-369 50-348 50-269 50-400 50-324
IRWIN.D.P ISBIN.H 8 ISBIN.H 8 ISBIN.H 8	8103240134 8103240134 8103180984* 8103040840* 8103120709*	90-463 0 90-453 0 REVIEW GRP CONTRACT 90-361 X	JOHNSOM R Q. JOHNSOM R Q JOHNSOM W D JOHNSOM J B JOHNSOM B D	8103170343 8103170350 8103170373 8103300300 8103230636	50-263 J 50-282 J 50-313 B 50-458 V 50-255 F	JULIAN, C JUNGE, M. G JURGENSEN, R. M JURGENSEN, R. M JURGENSEN, R. M.	8103240822* 8103110804 8103250435* 8103070387 8103180786	50-261 40-1162 Toprep Pr Regod
JACKIN. I. N JACKBON. 0 JACKBON. 0 JACKBON. T. J JACKBON. T.	8103190278# 8103260254# 8103260241# 8103110542* 8103110546*	50-255	JOHNSON, B D JONES, C E JONES, C E JONES, E	B103240120 B005010214* B1030907B0* B103040159* B103060034	50-155 F FOIA 50-454 Q 50-329 Q FOIA	JURGENGEN, R. W JURGENBEN, R. W. JURGENBEN, R. W. JURGENBEN, R. W. JURGENBEN, R. W.	8103050501 8103160252 8103250432 8103270714 8103260301	TOPREP TOPREP TOPREP TOPREP TOPREP
JACKSON, K. E. JACKSON, K. E. JACKSON, M. E. JACKSON, D. H. JACOBSON, N.	8103040484 8103200118 8103300281 8103250261 8103050500*	40-8698 40-8693 50-368 A Nureo Fota	JONES, W. C.	8103100100* 8103040058 8103240108 8103160240* 8103100071*	50-285 <b>Q</b> F01A 50-285 <b>F</b> 50-528 H 50-285 <b>Q</b>	KABAT, M KAHLE, J B KALIMULLAH KALIVIANAKIB, N KALIVIANAKIS, N	8103250573* 8103160933* 8103250638 8103020373 8103030592	CONTRAC 70-27 NUREO 50-254 50-265
JACOBS, A JACOBS, A. JACOBS, A. JACOBS, A JACOBS, A	8103040882 8103050144 8103050196 8103060018 8103120240	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	JONES, W. C. JONES, R. JONES, D. H. JONES, C. E. JONES, C. E.	8103180240 8103160339 8103130662* 8103100070* 8103261026*	50-285 G WASTE MOT 70-143 50-285 G 50-494 G	KAL IVIANAKIB, N KAL IVIANAKIB, N KAL IVIANAKIB, N KAL IVIANAKIB, N KAL IVIANAKIB, II	8103100377 8103100499 8103160657 8103170358 8103270618	50-265 50-254 50-254 50-254 50-254
JACOBS.A JACOBS.A JACOBS.A JAFFER.J JAMES.F.	8103140944 8103100658 8103160023 8103030480 8103250084	CONTRACT CONTRACT CONTRACT 50-290 H PR	JONES.D. W. JONES.R. K. JONES.W. C. JONES.R. C. JONES.R. E.	B103040502+ B103140247 B103030622 B103030B44 B103030561+	70-1151 WAGTE MOT 50-285 P 50-285 R 50-324 O	Kalman, O. Kalowski, W. W Kam, F. B. Kaminski, Q. T Kamishlian, J. M.	8103250423 8103100164* 8103030336 8103240230* 8103310453*	50-320 40-792 NUREG 50-321 50-366
JANACEK, R F JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F	8103180531 8103020487 8103160373 8103050158 8103170371	50-237 P 50-237 P 50-237 Q 50-237 P 50-10 Q	JONES W. C JONES W. C JONES W. C. JONES B. JONES D.	8103090540 8103270281 8103230160* 8103200573 8103190474	50-285 P 50-285 P 50-285 0 50-289 H 50-289 H	KAMIBHLIAN, J. M. KAMMERER, C. KAMMERER, C. KAMMERER, C. KAMMERER, C.	8103310464* 8103240091 8103240135 8103230538 8103270702	50-321 50-275 COMMIE 50-322 50-289

KANE.W F KANE.H F KANE.H KANE.H F KANE.W F	8103030648 8103041007 8103160163 8103130340 8103200372	50-393 50-393 50-393 50-395 50-393	E A A A	KELLOGG, P J	8103180296* 8103180831* 8103190328* 8103100408 8103240803*	50-261 50-395 50-260 50-324 50-338	0 5	KEPPLER, J. O KEPPLER, J G KEPPLER, J O KEPPLER, J. O KEPPLER, J O	8103040251 9103040264 8103040272 8103040279 8103040287	50-10 50-30 50-26 50-34
KANHER, A KANNER, A KAPLAN, A. L. KAPLAN, A. L. KAPLAN, A. L.	8103170134 8103160777 8103120313 8103030235 8103250575	50-320 50-352 71-4986 70-1113 PR	R H	KELLOOO, P KELLOOO, P KELLOOO, P. J KELLY, J. A KELLY, J. A	8103240848* 8103240724* 8103300363 8103050017 8103050062	50-321 70-1113 60-366 50-313 50-313		MEPPLER, J O. KEPPLER, J O. KEPPLER, J O. KEPPLER, J O. KEPPLER, J G	8103040272 8103040295 8103040300 8103040306 8103040306	50-33 50-15 50-40 50-31 50-35
KAPLAN, A. L KAPLAN, A. L KAPLAN, A. L KAPLAN, A. L KAPLAN, A. L	8103100294 8103290126 8103240647 8103250687 8103300098	70-1113 71-4450 71-5926 PR 70-1113		MELLY, J A MELLY, J P MELLY, J P. MELLY, J P.	8103050008 8103110067* 8103270800* 8103270776 8103270062*	50-267 GA999 KPORTL1 KPORTL1 50-321		KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8103030244 8103430259 8103030242 8103030270 8103030279	50-446 50-409 50-263 50-331 50-155
KARGEL, R. KARMAN, H. KARMAN, M. KARMAN, M. KARP, U	8103190492 8103050627 8103180613 0103250442 8103260736*	50-344 50-454 50-482 50-450 40-1947	9 0 0	KELLY, P J KELLY, J A KELLY, J S KELLY, J S KELLY, J A F	8103240668* 8103100355 8103100560 8103180782 8103240205*	50-424 50-458 50-285 50-498 50-267	0 5 8 0	KEPPLER, J O KEPPLER, J, O KEPPLER, J, O KEPPLER, J G KEPPLER, J G.	8103030383 8103030289 8103030292 810303030311	50-355 50-341 50-373 50-10 50-367
KABSEL, R. L. KASSEL, R. L. KASTENBERD, W. E. KAUFMAN, R. B KAUL, M. K	8103250490* 8103250483 8103040744* 8103240331 8103040548	PR PR FOIA 40-8726 NUREO		KEMPER, J. 8 KEMPER, J. 8 KEMPER, J. 8 KEMPER, J. 8 KEMPER, J. 8	8103200069* 8103100252 8103270019 8103230503 8103240404	50-352 50-352 50-352 50-352	G G G A A	KEPPLER, J Q.	8103030318 8103051906 8103040253 8103060423 8103060431	50-461 50-461 70-152 50-182 50-155
KAHULOK, P KAY, J A KAY, J A KAY, J A KAY, J A	8103169365 8103110201* 8103030617 9103030800 8103100336	40-8502 50-27 50-27 50-29 50-29	Р Р Р	KEMPER, J. S KEMPER, J. S KENNA, W. B. KENNA, W. B.	8103300309 8103300316 8103050217 8103310807* 8103130648	50-352 50-352 50-369 90-302 70-143	0 8 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8103060437 8103060449 8103060477 8103060482 8103060494	50-2 50-294 50-186 50-150 50-116
KAY, J. A. KAY, J. A. KAY, J. A KAY, J. A	8103070323 8103120443 8103160558 8103180592 8103200176	50-29 50-29 50-29 50-29 50-29	Р Р Р	KENNA, W B KENNA, W B KENNA, W B KENNA, W B.	8103240257* 8103160928 8103020696 8103040495 8103240309	50-250 70-27 50-530 70-1151 70-27	o o	KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8103060498 8103060501 8103060510 8103090107 8103090108	50-123 50-151 70-8 50-409 50-341
KAY, J. A KEATEN, R. W. KEBLUSEK, B. KEBLUSEK, B KEBLUSEK, B	8103310226 8103190641* 8103190019 8103050009 8103050908	50-29 50-287 50-382 50-382 50-382	P O A A	KENNA, W. B. KENNA, W. B KENNA, W. B KENNA, W. B KENNON, E	8103090242 8103250010* 8103241129* 8103050290 8103030439*	70-27 90-335 50-327 90-369 90-382	0 0 1	KEPPLER. J O. KEPPLER. J O. KEPPLER. J O. KEPPLER. J G. KEPPLER. J O.	6103090113 6103090119 6103090123 6103090125 6103090131	50-440 50-264 50-315 50-461 50-329
KEBLUSEK, B KEBLUSEK, B KEBLUSEK, B KEBLUSEK, B	8103030128 8103120470 8103120724 8103120768 8103190318	50-382 50-382 50-382 50-382	A A F V	KENNY, T. KENNY, T. J KENNY, T. J KENRICK, J. R. KENRICK, J. R.	8103230407* 8103250226 8103250229* 8103020549 8103020549	50-247 50-440 50-440 70-2909 70-2909	G G	KEPPLER, J G	8103090137 8103090142 8103090172 8103090176 8103090183	50~305 70~1226 70~36 50~263 50~97
XEBLUSEK, B KEBLUSEK, B KEBLUSEK, B KEBLUSEK, B	8103190310 8103200491 8103290405 8103250401 8103300105	50-382 50-382 50-382 50-382	A A A	KENRICK, J. R KENRICK, J. R KENRICK, J. R KENRICK, J. R KERPLER, J. O	8103230708 8103230708 8103260768 8103260768 8103040900	70-2909 70-2909 70-2909 70-2909 50-329	a	KEPPLER. J. G KEPPLER. J. G KEPPLER. J. G KEPPLER. J. G	8103099208 8103090240 8103090244 8103090247 8103090254	50-546 50-155 50-331 70-925 50-346
KEELEY, O B KEENEN, B. KEIMIG, R. R KEIMIG, R. R. KEIMIG, R. R.	8103040020 8103300389 8103190672# 8103050271# 8103190098#	50-329 50-289 50-213 50-213 50-272	A H O O O	KEPPLER, J. O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8103040142 8103020228 8103130677 8103120395 8103120400*	50-329 50-946 50-263 50-331 50-331	0 0 0 0	KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O.	8103100214 8103100237 8103100524 8103100529 8103130157	50-10 50-265 50-367 50-358 50-315
KEIMIO, R. R KEIMIO, R. R KEIMIO, R. KEIMIO, R. KEIMIO, R.	8103180315# 8103190308# 8103050669 8103030570 8103030911		0 0 9 8 8	KEPPLER, J 0 KEPPLER, J. 0. KEPPLER, J. 0 KEPPLER, J. 0 KEPPLER, J. 0	8103180198 8103180203* 8103170698 8103170704* 8103190824	50-329 50-329 50-341 50-341 40-3392	a a a a	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8103170100 8103110581 8103110583 8103110586 8103110587	50-305 State F State F State F
HEIMIQ.R.R HEIMIQ.R. HEIMIQ.R.R. KEIMIQ.R.R KEIMIQ.R.R	8103050624 8103100509 8103100491 8103170354 8103170337	50-272 50-277 50-278	6 6 6 8	KÉPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	81031708304 8103020046 8103020050 8103020054 8103020058	40-3392 50-294 50-116 50-151 50-440	Q Q Q Q	Meppler, J O. Meppler, J O. Meppler, J O. Meppler, J O. Keppler, J O.	8103110590 8103160628 8103160662 8103160665 8103160668	8tate F 50-305 50-258 50-546 50-346
KEIMIO.R.R. KEIMIO.R.R. KEIMIO.R.R. KEITH.R.B. KEITH.R.B.	8103190553* 8103190543* 8103190590* 8103050628* 8103270694*	50-289 50-316	T T 8	KEPPLER, J O. KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J G	8103020059 8103020062 8103020067 8103020069 8103020073	50-329 50-546 50-263 50-367 50-331	Q Q Q Q Q	KEPPLER, J Q. KEPPLER, J Q. KEPPLER, J Q. KEPPLER, J Q. KEPPLER, J. Q	8103160672 8103160676 8103160695 8103160700 8103160704	50-483 50-266 50-295 50-315 50-329
KELBER, C. N. KELLEY, W. D. KELLEY, D. L. KELLEY, W. D. KELLER, Q. V.	8103270142* 8103031151* 8103050650* 8103310885* 8103090059*	FOIA GA999 50-285 GA999 40-1162	a	KEPPLER, J. O. KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8103020077 8103020094 8103020098 8103020101 8103020104	50-341 50-409 50-305 50-266 50-461	a a a a	KEPPLER. J. G. KEPPLER. J. G KEPPLER. J. G. KEPPLER. J. G. KEPPLER. J. G.	B103160706 B103160475 B103160478 B103160481 B103160486	50-282 50-367 50-331 50-315 50-461
KELLER, Q. R. KELLNER, D. KELLOGO, P. J. KELLOGO, P. J. KELLOGO, P. J.	8103040538 8103230683* 8103120571* 8103041026* 8103050272*	50-338 50-416	H G G	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	8103020107 8103020109 8103020115 8103020125 8103020128	50-346 50-315 50-10 50-155 50-483	a 0 0 0 0	KEPPLER, J. Q. KEPPLER, J. Q KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	8103160487 8103160488 8103160494 8103160504 8103160508	50-440 50-358 50-10 30-329 50-155
KELL090, P. J. KELL090, P. J. KELL090, P. J. KELL090, P. J. KELL090, P. J.	8103160800* 8103240634* 8103310654* 8103120783* 8103240342*	50-416 50-261 50-324	0 0 0 0 0	KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8103020133 8103140988 8103190248# 8103190262 8103040249	50-358 50-315 50-255 50-255 50-373	a e e a o	KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	8103160511 8103160516 8103160521 8103160524 8103160527	50-409 50-259 50-263 50-546 50-346

EPPLER. J. O. 1103200374 50-301 0 NI NEPHANI. J. D. 8103105684 30-8610 NGESTER. 9 L. 1010310794 30-462 EPPLER. J. O. 1103200374 30-462 EPPLER. J. O. 1103200374 30-462 EPPLER. J. O. 1103200375 30-461 0 NI NEPHANI. J. D. 8103100309 40-860 NGH. R. J. 101030031073 30-461 NI NEPHANI. J. D. 8103100309 40-860 NGH. R. J. 101030031073 30-304 NEPPLER. J. O. 1103230395 30-30-46 0 NI NEPHANI. J. D. 8103003114 70-406 NGH. R. J. 10103031073 30-304 NEPPLER. J. O. 1103230395 30-30-46 0 NI NEPHANI. J. D. 8103003114 70-406 NGH. R. J. 10103031073 30-304 NEPPLER. J. O. 1103230395 30-30-46 0 NI NEPHANI. J. D. 8103003114 70-406 NGH. R. J. 10103031073 30-304 NEPPLER. J. O. 1103230395 30-30-46 0 NI NEPHANI. J. D. 810300016 70-407 NGH. R. J. 10103031073 30-304 NEPPLER. J. O. 1103230035 30-305 0 NI NEPPLER.
NEPPLER. J
MEPPLER, J. 0
KEPPLER. J. 0 8103200481 50-315 0 K1PER. K. L 810310349 50-410 A K0TBCH. J. L. 8103160182 40-6659  KEPPLER. J. 0 8103200488 50-546 0 K1PK. M. F 810327060 70-371 K0TBCH. J. L 8103160187 40-259  KEPPLER. J. 0 8103200489 50-546 0 K1PK. M. F 810327060 70-371 K0TBCH. J. L 8103160187 40-259  KEPPLER. J. 0 8103200493 50-263 0 K1PK. M. F 8103100359 70-371 K0TBCH. J. L 8103180187 40-259  KEPPLER. J. 0 8103200495 50-10 0 K1PK. O. B 8103110335 50-327 B K0TBCH. J. L 8103180069 40-259  KEPPLER. J. 0 8103200275 50-305 0 K1PK. O. B 8103110335 50-327 B K0VACS. F. G. 8103260667 40-8084  KEPPLER. J. 0 8103200255 50-346 Q K1PK. O. B 8103170413* 90-327 B K0VACS. F. G. 8103260967 40-8084  KEPPLER. J. 0 8103200260 50-155 Q K1PK. O. B 8103170413* 90-327 B K0VACS. F. G. 8103260358 PR  KEPPLER. J. 0 8103200260 50-155 Q K1PK. O. B 8103170413* 90-327 B K0VACS. B 8103260358 PR  KEPPLER. J. 0 8103200260 50-315 Q K1PK. O. B 8103170413* 90-327 B K0VACS. B 8103260358 PR  KEPPLER. J. 0 8103200260 50-315 Q K1PK. O. B 8103260776* 50-327 B K0VACS. B 8103200369 PR  KEPPLER. J. 0 8103200260 50-315 Q K1PK. O. B 8103260776* F01A KRAFT. R. 8103090012 PR  KEPPLER. J. 0 8103200365 50-358 Q K1PK.AN. R. B 8103260776* F01A KRAFT. R. 8103090012 PR  KEPPLER. J. 0 8103200316 50-358 Q K1PK.AN. R. B 810326078* F01A KREST. R. 8103200306 HUREO KEPPLER. J. 0 8103200316 50-358 Q K1PK.AN. R. B 810326078* F01A KREST. R. B 8103200306 HUREO KEPPLER. J. 0 8103200316 50-367 Q K1PK.AN. R. B 810326078* F01A KREST. R. B 8103200301 FOR KREPPLER. J. 0 8103200328 50-341 Q K1PK.AN. R. B 810326078* F01A KREST. R. B 8103200301 FOR KREPPLER. J. 0 8103200328 50-346 Q K1PK.EN. R. B 8103200301 FOR KREPPLER. J. 0 8103200328 50-346 Q K1PK.EN. R. B 8103200301 FOR KREPPLER. J. 0 8103200328 50-346 Q K1PK.EN. R. B 8103200301 FOR KREPPLER. J. 0 8103200339 50-346 Q K1PK.EN. B 8103200301 FOR KREPPLER. J. 0 8103200339 50-346 Q K1PK.EN. B 8103200301 50-333 Q KRUMANIA. R. 8103200339 50-347 Q K1PK.EN. B 8103200301 50-333 Q KRUMANIA. R. 8103200339 50-346 Q K1PK.EN. B 8103100047 50-320 Q K1PK.EN. J
KEPPLER. J O         8103200291         50-440         0         KIRKMAN.R.H         8103260776*         FOIA         KRAFT.R.         810308091         PR           KEPPLER. J O         9103200277         50-341         0         KIRKMAN.R.H         8103260726*         40-1947         KREGER.H.E         8103270119*         FOIA           KEPPLER. J O         8103200306         50-329         0         KIRKMAN.R.H         8103260606*         40-1947         KREGER.H.E         9103230106*         90-416         MCREGER.H.E         9103190396*         90-320         MCREGER.J.J.         9103190396*         90-320         MCREGER.J.J.         9103190396*         90-320         MCREGER.J.J.         9103190396*         90-320         MCREGER.J.J.         91031903003         90-320         MCREGER.J.J.         91031030003
KEPPLER, J G         8103200345         50-863         0         KISTER, H. 8         8103180190*         50-322         0         KRY818SKI, T. L.         810303031*         TOPREP FOIA           KEPPLER, J G         8103200345         50-346         0         KISTER, H. 8.         8103100412         50-307         0         KUNBITIB, T. J.         810319076*         FOIA           KEPPLER, J G         8103200345         50-305         0         KISTER, H. 8.         8103100412         50-309         9         KUNBITIB, T. J.         8103190179*         50-339           KEPPLER, J G         8103200345         50-266         0         KISTER, H. 8.         8103100412         50-309         9         KUNBITIB, T. J.         8103190179*         50-339           KEPPLER, J G         8103200045         50-255         8         KLEINSTROE, W. P. 8103100407*         50-498         Q         KUSSIE, R. R. 8103200423         50-244           KEPPLER, J G         9103260123         50-10         F         KNAPP, P. J.         8103100407*         50-333         Q         KUYKENDALL, A. 8103000561*         90-361
·

NUCK. A	8103250261	NUREO	LEBO.C D	8103040391	CONTRACT CONTRACT CONTRACT	LEWIS, R. C.	8103120793	50-36
L'HEUREUX. J. H	8103300026	70-820	LEBO.C D	8103261069		LEWIS, R. C.	8103130147	50-32
L'HEUREUX. J. H	8103310882	70-820	LEBO.C D	8103130106		LEWIS, R. C.	8103130159	50-32
LA FOLLETTE. B.	8103260820*	PR	LEBO.C D	8103160224		LEWIS, R. C.	8103130674	50-32
LASOEUF. R. J.	8103270400	50-285 P	LEBO.C D	8103160200		LEWIS, R. C	8103270071#	50-32
LABOWITZ,A M LABOWITZ,A M LACEY,W 8 LACEY,W 8 LACEY,W 8.	8103050202+ 8103050197+ 8103100586+ 8103100587+ 8103170517+	CONTRACT CONTRACT 50-334 B 50-334 B 50-334 S	LEBO.C. D LEBO.C. D LEBO.C. D. LEBO.C D. LEBO.C D	81031903602 8103190682 8103190694 8103270442 8103250498	CONTRACT CONTRACT CONTRACT	LEWIS.R C LEWIS.R C LEWIS.R C. LEWIS.R C. LEWIS.R C.	B103040570 B103130136+ B1031301B9 B103130209 B103160074	50-327 50-349 50-327 50-321
LACEY.W B LACEY.W B LACEY.W B LACEY.W S. LACEY.W B.	8103130604# 8103130611# 8103170609# 8103260686# 8103260691#	50-334 8 50-334 8 50-334 8 50-334 6 50-334 8	LEBO.C D LEBO.C D LEBO.C D LEBO.C D	81032611034 81032610824 81032706714 81032611164 81032611334	CONTRACT CONTRACT CONTRACT	LEWIS.R C LEWIS.R C LEWIS.R LEWIS.R LEWIS.R C	6103240299+ 6103160994 8103160284 8103230263+ 6103090286	50-321 50-346 50-261 30-352 50-324
LACEY, W B LADESICH, J. LADUN, R. LADUN, R. H LAOIEWBKI, J. B.	8103260707* 8103270682 8103050436* 8103050624 8103060545*	50-334 8 50-206 P 50-226 0 50-307 6 50-318 8	LEBCEUF, R. J LEE, E. W. K LEE, L. B LEE, M. V LEE, O. R	8103060760 8103040159* 8103100136 8103190459 8103110792*	NUREQ 50-289 H	LEWIS.R.C LEWIS.R.C LEWIS.R.C LEWIS.R.C LEWIS.R.C	8103180824 8103190313 8103190321 8103200931 8103240695*	50-395 50-395 50-280 50-261 50-269
LADIEWSKI, J. S.	8103110487#	50-317 8	LEE,R.L	8103230162*		LEWIS, R C	8103240140	50-327
LADIEWSKI, J. S.	8103260893#	50-317 8	LEE,T.D	8103130662*		LEWIS, R C	8103260169	50-416
LAHEY, R. T.	8103180959#	REVIEH GRP	LEE,W.B	8103310638*		LEWIS, R C	8103050141	50-261
LAHEY, R. T.	8103090812	NUREO	LEECH,P	8103170383		LEWIS, R C,	8103050770	50-338
LAI, J.	8103120769	50-254 A	LEFEBRE,N.T	8103170737		LEWIS, R C,	8103090563	50-390
Lainas, O. C.	8103060387	50-219 P	LEIBY.A C	8103060760	PR	LEWIS.B H.	8103100772	50-320
Lainas, O. C.	8103090725	50-255 P	LEIBY.A C	8103270400	50-285 P	LEWIS.R C.	8103160782	50-261
Lainas, O. C.	8103060365	50-29 P	LEITHAUSER.J A.	8103250249	50-158 0	LEWIS.R C.	8103170075	50-369
Lainas, O. C.	8103060400	50-244 P	LEJINS.N M.	8103170072#	CONTRACT	LEWIS.R C	8103270516*	50-400
Lainas, O. C.	8103060436	50-237 P	LEMPGES.T E	8103180659#	50-220 0	LEWIS.R C	6103120744	50-259
LAINAB, O.C. LAINAB, O.C. LAINAB, O.C. LAINAB, O.C. LAINAB, O.C.	8103090014 8103090681 8103160465 8103060344 8103060419	50-245 P 50-155 P 50-213 P 50-206 P 50-409 P	LEMPGEB. T.E. LEMPGEB. T.E. LEMPGEB. T.E. LEMPGEB. T.E. LEMPGEB. T.E. LEMPGEB. T.E.	8103270361* 8103060212 8103180463 8103230854 8103030753	50-220	LEWIG, R C LEWIS, R. C LEWIS, R C LEWIS, R. C LEWIS, R. C	8103120828 8103180194 8103180260 8103180368 8103130700	50-269 50-369 50-261 50-390 50-280
Lainas, O. C Lamb, H. R Lamb, P. R. Lamb, H. R Lamken, D. C	8103110820 8103060760 8103170529 8103270400 8102030517	50-307 P PR 90-275 H 50-285 P Toprep	LEMPOEB.T.E. LEMPOEB.T E LEMPOEB.T E LEMPOEB.T E LEMPOEB.T E	8103110668 8103120532 8103120536 8103170628 8103160462	20-550 1 20-550 8 20-550 8 20-550 A	LEWIS.R.C. LEWIS.R.C LEWIS.R.C. LEWIS.R.C. LEWIS.R.C	8103130721 8103130729 8103160193 8103160903 8103190232	70-143 50-364 50-518 50-302 50-250
LAMKEN, D. C. LAMM, R. D LAMPLEY, C. M LANCABTER, L. E LANDSMAN, R	8103190493 8103250063 8103020707 8103250327 8103170532*	TOPREP PR NUREO REVIEW GRP 27-39	LEMPOEB, T. E LENAHAN, J. J. LENAHAN, J. J LENAHAN, J. J LENAHAN, J. J	8103270316 8103040770* 8103040814* 8103090789* 8103240786*	50-220 6 50-302 0 50-280 0 50-321 0 50-348 0	LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8103240264 8103240655 8103240726 8103240811 8103240834	50-438 50-259 50-336 50-261 50-321
LANDSMAN: R. B.	8103180215*	50-329 Q	LENTSCH. J W	8103170440	50~344 P	LEWIB.R C	810327080	50-259
LANE: J. R.	8103030858	40-4492	LEONARD, S M	8103200637*	50~443 0	LEWIS.R C.	8103240241	50-250
LANE: J. R.	8103260956	40-4492	LERNER, J	8103120702	PR	LEWIB.R C.	8103240280	70-143
LANKBBURY: R.	8103050374*	50-254 Q	LESKYS, A. O.	8103270060*	CONTRACT	LEWIB.R C.	8103240611	50-269
LANNING: D. D.	8103310924	NUREO	LESSOR, L. C	8103070504	50~298 R	LEWIB.R C.	8103240714	70-1113
LANPHER, L. C. LANPHER, L. C. LANPHER, L. C. LANPHER, L. C. LANPHER, L. C.	8103020400 8103180566 8103180566 8103260845 8103260845	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	LEBSY:R P. LESSY:R P. LEBBY:R P. LEBBY:R:P. LEBSY:R P.	8103060357 8103120594 8103170097 8103170316 8103190484	50-443 Q 50-463 Q 50-443 F 50-443 Q	LEWIBAR C. Lewisar C. Lewisar C. Lewisar C. Lewisar C	8103240800 8103240286 8103240315 8103240730 8103240775	50-321 50-438 50-280 50-335 50-348
LAPAT, P. E.	8103270619	WASTE MOT	LEVENBAUM, M.	8103120697	PR	LEWIS.R.C.	8103260200	50-389
LAPAT, P. E.	8103270628*	WASTE MOT	LEVENSON, M	8103240601	50-287 T	LEWIS.R.C	8103240291	50-321
LAPHAM, N. W.	8103160622	50-367 A	LEVENSON, M	8103240601	50-287 T	LEWIS.R.C	8103240660	50-424
LARSON, C.	8103200222*	50-263 I	LEVINE, B. H.	8103060609	50-5 8	LEWIS.R.C.	8103270053	50-280
LASSELLE, K.	8103180709	50-289 H	LEVINE, M. M	8103040579	NUREO	LEWIS.R.C.	8103270132	50-424
LABUK, B. R.	8103040796*	FOIA	LEVINE.J M	8103170601*	50-213 B	LENIB.R.C.	8103250002	50-335
LATORRE, P.	8103050726*	40-5293	LEWIS.M I.	8102260753*	FOIA	LENIB.R.C.	8103250147	70-27
LAUCHB, J. R.	8103190475	50-289 H	LEWIS.R C.	8103040565*	50-327 G	LENIB.R.C.	8103250167	70-143
LAUTMAN, P.	8103060182	CONTRACT	LEWIS.R.C.	8103050590*	50-390 G	LENIB.R.C.	8103240704	50-269
LAVERTY, J. H.	8103270467	50-289 G	LEWIS.F.W.	8103030008*	COMMISSION	LENIB.R.C.	8103240747	50-369
LANTHER, J. C.	8103160184	40-8728	LEWIB.R. C.	8103120561+	50-338	Lewis.r C.	8103250179	50-438
LANTON, M. D.	8103260695	40-8084	LEWIB.R. C.	8103030293		Lewis.r C.	8103261117	50-327
LANTON, M. D.	8103250740	40-8084	LEWIB.R. C.	8103050160+		Lewis.r C.	8103250133	50-321
LAYFIELD, R. L.	8103260499*	40-1947	LEWIB.R. C.	8103170084+		Lewis.r.C.	8103260487	50-400
LAYFIELD, R. L.	8103260479*	40-1947	LEWIB.R. C.	8103240620+		Lewis.r.C.	8103270051	50-321
LAYPIELD, R. L.	8103260450*	40-1947	LEWIS.R.C.	8103041022	50-416 0	LEWIS R. C.	0103310625	50-261
LAZNON, J.	8103310257*	50-309 P	LEWIS.R.C.	8103050264	50-338 0	LEWIS R. C.	0103270467	50-259
LEACH, L. P.	8103090475	REG	LEWIS.R.C.	8103160790*	50-261 0	LEWIS R. C.	0103300363	50-366
LEAVELL, H. H.	8103250629	NUREO	LEWIS.R.C.	8103040578*	50-327 0	LEWIS R. C.	0103310798	50-302
LEBEAU, O.	8103160532	PR	LEWIS.R.C.	8103060303*	50-302 0	LEWIS R. C.	0103310828	50-280
LEBO: C. D.	8103090292*	CONTRACT	LEWIS, R. C.	8103100045	50-257 0	LEWON, R.	8103170617	50-275
LEBO: C. D.	8103060182	CONTRACT	LEWIS, M. I.	8103260189	PR	LIBRIZZI, F.P.	8101220627+	50-272
LEBO: C. D.	8103050630	CONTRACT	LEWIS, R. C.	8103050368*	50-321 0	LICHTSTEINER, E.	8103060627+	50-361
LEBO: C. D.	8103050827*	CONTRACT	LEWIS, R. C.	8103050417	50-335 0	LICHTENBERGER	8103310684	70-1100
LEBO: C. D.	8103130273*	CONTRACT	LEWIS, R. C.	8103100111	50-327 0	LICHTENBERGER	8103170464	70-1100
LEBO, C. D.	8103200189*	CONTRACT	LEWIB, R. C.	8103160907*	50-302	LIDIAK, E. G.	8103040536	NUREO
LEBO, C. D.	8103050182*	CONTRACT	LEWIB, R. C.	8103190300*		LIEBERT, H.	8103250629	NUREO
LEBO, C. D.	8103070171*	CONTRACT	LEWIB, R. C.	8103090766*		LINDELL, M. K.	8103240237	NUREO
LEBO, C. D.	8103070176*	CONTRACT	LEWIB, R. C.	8103310635*		LINDER, F.	8103050100+	50-409
LEBO, C. D.	8103070276*	CONTRACT	LEWIS, R. C.	8103120775		LINDER, F.	8103200296	50-409

AU THOR	ACCESSION PACHUM	GUBJECT CATEOCRY	AUTHGR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGGRY
LINGERBAUM S	8103190591*	CONTRACT	LOZIER, G	8103230558*	50-333 0	MACCONALD. C E	8103170692	71-417
LINGER F	8103030830	50-409 P	LU, M S	8103180816	RES		8103170697*	71-417
LINGER F	8103060469	50-409 P	LUGE'AU, J O	8103100187*	70-162		8103170702	71-408
LINGER F	8103100495	50-409 B	LUGE'AU, J O	8103020131	1&E		8103170705*	71-408
LINGER F	9103110660	50-409 S	LUGENAU, J O	8103020152	1&E		8103230837	71-412
LINDER, F	8103090425	50-409 P	LUBENAU. J D	B103020162	1&E	MACDONALD, C E	8103230841*	71-412
LINDER, F	8103120087	50-409 Q	LUBENAU. J O	B103303343	1\$E		8103250359	71-413
LINDER, F	8103130381	50-409 R	LUFTMAY. M	B103050007	PR		8103250363*	71-413
LINDER, F	8103190690±	50-409 Q	LUIGARD. J	B103190546	50-289 H		8103250373	71-415
LINDER, F	8103090274	50-409 F	LUJAN. K	B103261204+	COMM1881CN		8103250378*	71-415
LINDER, F	8103090432	50-409 P	LUJAN.H	B103300014	PR	MACDONALD, C E	8103250347	71-414
LINDER, F	8103310255	50-409 P	LUKEN.T A	B103180529	50-358 U		8103250353*	71-414
LINDER, F	8103130413	50-409 F	LUKZ.F J	B103270040*	CONTRACT		8103200775	71-403
LINDER, F	8103140551	50-409 F	LUMB.R F	B103100257*	CONTRACT		8103200770*	71-403
LINDER, F	8103190645	50-409 P	LUMDVALL.A E	B103180503	50-317 G		8103200780	71-164
LINDER, F LINEMAN, J LINEMAN, J J LINEMAN, J J LINEMAY, J J	8103250182 8103060824 8103031135 8103060375 8103160204	50-407	LUNDVALLIA E LUNDVALLIA E LUNDVALLIA E LUNDVALLIA E LUNDVALLIA E	8103300358* 8103199679 8103030695 8103030764 8103090395	50-317 0 50-317 0 50-317 P 90-317 P 50-317 P	MACDONALD, C E	8103200783* 8103260969 8103260975* 8103300347 8103300356	71-164 71-9147 71-9147 71-419 71-406
LINENBERGER.G	8103110512	50-466 0	LUNDVALLIA E	8103190571	50-317 P	MACFARLANE, D. R.	8103040727	F01A
LINVILLE.J	8102230310*	50-333 0	LUNDVALLIA E	8103100445	90-317 P	MACHON, R. D.	8103020548	50-293
LINVILLE.J C	8103270778*	50-333 0	LUNDVALLIA E	8103130432	50-317 P	MACHON, R. D.	8103090518	50-293
LIPPOLO.W J	8103270706	50-318 P	LUNDVALLIA E	8103200244	90-317 P	MACHON, R. D.	8103230542	50-293
LITTLEFIELD.P	8103310257*	50-309 P	LUNDVALLIA E	8103230505	50-317 H	MACHON, R. D.	8103200700	50-293
LITTLE. L. W	8103200803+	50-275 P	LUNDVALLA E	8103270807	50-317 F	MACHON.R D	8103270513	50-293
LITTLE. W S	8103020695	50-331 S	LUNDVALLA E	8103270596	50-317 F	MACTOLEK-BLAKE	8103240186*	50-219
LITTLE. W S	8103030305	50-263 S	LUNDVALLA E	8103270428	50-317 P	MACKENZTE, J	8103230423	50-361
LITTLE. W S	8103040128	50-331 S	LUNDVALLA E	8103270487	50-317 P	MACOMBER, I	8103050932	PR
LITTLE. B H	8103050412+	50-341 O	LUNDVALLA E	8103270570	50-317 P	MADDEN, W J	8103100412	50-309
LITTLE.WA	8103050349+	90-263 0	LUNSFORD, R. C.	8103270442*	CONTRACT	MADDEN, U. MADDOX, H MADDOX, B G MADDOX, B G MADEDA, T. J	8103200549	70-371
LITTLE.WB	8103050402+	50-231 0	EURITO, R. J.	8103032655*	90-382		8103180587	50-320
LITTLE.WS	8103090799+	50-262 0	EUSCHER, C. G.	8103050544*	Wabte Mot		8103180504*	50-327
LITTLE.WB	8103130303+	50-263 0	EYNCH, J. A.	8103031144*	0a999		8103250304*	50-327
LITTLE.WB	8103190122+	90-331 0	EYNCH, M. D.	8103230322	90-397   A		8103030118*	70-2838
LITTLE. H	8103090186	CONTRACT	LYEN.A E	8103040661	50-334 P	MADEDALT J	8103240474*	50-206
LITTLE. W S	810319038*	50-282 G	LYEN.A E	8103090593	50-295 P	MADISON, A. L	8103050349*	50-263
LITTLE. M	8103340851	CONTRACT	LYENS.M G.	8103110724*	50-361 E	MADISON, A. L	8103130303*	50-263
LITTLE. M	8103050992	50-206 P	LYTLE.P M	8103260746	50-269 F	MADEEN, O. L	8103031105*	50-267
LITTLE. W S	8103020591	50-263 8	MAGARIFUR.T C	8103270832*	50-333 Q	MADSEN, G. L	8103031094	50-267
LITTLE.M	8103050190	CONTRACT	PAGARTHUR, T.C.	8103250624	27-47	MADSEN.O.L.	8103090592	50-362
LITTLE.M	8103100758	COUTRACT	MACARTHUR, T.C.	8103260159	27-47	MADSEN.O.L.	8103050648	50-313
LITTLE.M	8103130322	CONTRACT	MACDONALD, C.E.	8103230147	71-9035	MADSEN.O.L.	8103050648	50-265
LITTLE.M	8103190033	50-206 P	MACDONALD, C.E.	8102170624	71-9013	MADSEN.O.L.	8103180436#	50-267
LITTLE.M	8103190164	CONTRACT	MACDONALD, C.E.	8102170630	71-9013	MADSEN.O.L.	8103230175	50-362
LITTLE, M	8103190994	CONTRACT	MAGDDNALD.C E	8103110226*	71-422	MADSEN.O.L	8103180433	50-247
LITTLE, M	8103190144	CONTRACT	MAGDDNALD.C E	8103150015*	71-418	MADSEN.O.L	8103231014	50-313
LITTLE, M	8103270184	CONTRACT	MAGDDNALD.C E	8103020071	71-345	MADSEN.O.L	8103041027	50-313
LITTLE, M	8103270457	50-320 P	MAGDDNALD.C E	8103020222	71-409	MADSEN.O.L	8103050093	50-265
LITTLE, W 8	8103240409	50-331 B	MAGDDNALD.C E	8103020231*	71-409	MADSEN.O.L	8103020431	50-267
LITTLE.H	B103300439	CONTRACT	MACDONALD.C E	8103020238	71-138	MADSEN.O L.	8103110778	90-298
LITTLE.H	B103310717	50-331 B	MACDONALD.C E	8103020247*	71-138	MADSEN.O L	8103110787	50-267
LIVERMORE.H H	B103040159*	50-329 Q	MACDONALD.C E	8103020254	71-2	MADSEN.O L.	8103230152	50-289
LIVERMORE.H H	B103230141*	50-461 Q	MACDONALD.C E	8103020264*	71-2	MADSEN.O L	8103170373	90-313
LIVINGART.A	B103190380	50-289 H	MACDONALD.C E	8103030005	71-271	MADSEN.O.L	8103200294	90-267
LOBO.W O	8103110553*	50-302 B	MACDONALD.C E	8103030010*	71-271	MAGIELL	8103140239*	H18C
LOCKHOOD.H A	8103170599	50-352 0	MACDONALD.C E	8103030015	71-138	MAGROWLR.	8103170537*	50-249
LODGE.T	8103180626*	50-440 0	MACDONALD.C.E	8103030022*	71-138	MAHANLR R	8103030451	50-395
LODGE.T	8103180626*	50-440 0	MACDONALD.C E	8103040458	71-6244	MAIERLJ E	8103040199	50-244
LOEWENTHAL.R G	8103060107*	71-421	MACDONALD.C E	8103040819	71-9006	MAIERLJ E.	8103030813	50-244
LOFY.R A	6103120859#	CONTRACT	MACDONALD.C E	8103040824	71-6601	MAIER, J E	B103030784	50-244
LOGIUDICE.J M	6103030157#	CONTRACT	MACDONALD.C E	8103040828	71-9034	MAIER, J E	B103090831	50-244
LONG.E M	6103190638	50-287 H	MACDONALD.C E	8103040834	71-9107	MAIER, J E	B103090423	50-244
LONG.R B	6103300300	50-458 U	MACDONALD.C E	8103040838	71-9113	MAIER, J E	B103100375	50-244
LONG.H A	6103190413	50-287 H	MACDONALD.C E	8103050214	71-6574	MAIER, J E	B103100520	50-244
LONGACRE, 8. LCOXINODILL, D LOOMIS, J 8 LOOMIS, J LOOMIS, J	8103120748	PR	MAGDONALD, C.E.	8103040242	71-9026	MAIER, J.E.	8103100580	50-244
	8103170341	50-289 Q	MAGDONALD, C.E.	8103090098	71-6717	MAIER, J.E.	8103100447	50-244
	8103230054	REGOD	MAGDONALD, C.E.	8103040845	71-9044	MAIER, J.E.	8103170418	50-244
	8103090330#	50-29 P	MAGDONALD, C.E.	8103040854	71-9044	MAIER, J.E.	8103170421	50-244
	8103310231#	90-29 P	MAGDONALD, C.E.	8103110029	71-4960	MAIER, J.E.	8103250242	50-244
LODSLE, J H LODSLE, J H LODSLE, J H LODSLE, J H LOSS, F. J	8103030950 8103030959* 8103030965 8103030971* 8103190763	71-416 71-407 71-416 71-416 NUREO	MACDONALD.C.E MACDONALD.C.E MACDONALD.C.E MACDONALD.C.E MACDONALD.C.E	B103160556 B103100643 B103100645* B103120111 B103120118*	71-5740 71-179 71-179 71-179 71-9143 71-9143	MAIER, J. E. MAIER, J. E. MAIER, J. E. MAIER, J. E. MAIER, J. E.	8103200575 8103200584 8103270709 8103200597 8103260617	50244 50244 80244 80244 50244
LOTHROP, J. N	8103050679*	50-289 T	MACDONALD.C.E	8103120121	71-3641	MATER, J	8103300283	50-244
LOUDERBACK, J. E	8103190801	40-9714	MACDONALD.C.E	8103120139*	71-3641	MAKATURA, L.	8103130594*	50-346
LOUDERBACK, T. E	8103060835	40-9714	MACDONALD.C.E	8103120150	71-405	MAKOWITZ, H	8103120787	RE8
LOUDERBACK, T. E	8103180918	40-8714	MACDONALD.C.E	8103120158*	71-405	MALMROB, M. H	8103100024*	50-344
LOUGHRAY, J. J.	8103180550	50-289 H	MACDONALD.C.E	8103120427	71-416	MALMROB, M. H.	8103240744*	50-344
LOUISELLE, B. M	8103030690+	90-382   1	MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE	B103120433*	71-416	MALONEY, Q. P.	8103110098	REGOD
LOVENDALE, P	8103040445	50-295   8		B103120461	71-9111	MALGNEY, Q. P.	8103230354	59-315
LOVENDALE, P C	8103261107+	50-186   0		B103120465*	71-9111	MALSCH, M. O.	8102260770*	FDIA
LOWE, B	8103091005	PR		B103120776	71-9145	MALSCH, M. Q.	8103170270*	FDIA
LOWENSTEIR, R.	8103090533	50-331   J		B103120B01*	71-9145	MALSCH, M. Q.	8103160446*	LOCFR

	ACCERDION	CUD CCT		**********	010 1007		********	01 0 m²
AUTHOR	ACCERSION NUMBER	SUBJECT CATEOGRY	PÜHTUA	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SLDJE CATEG
MANDLER. J W	8103240683	RES	MARTIN. W Q	B103050449	50-247 0	MATTIA, J.	8103250446+	50-450
MANGUSI, J MANN, M M	8103270610 8103260790*	70-1426 FOIA	MARTIN, H J Martin, D E	8103200377 8103031126	70-1100 40-8502	L M.ALTIAN L M.ALTIAN	8103040772* 8103040740*	CONTRA
MANRY, M MANRY, M	8103020539 8103020576	50-321 6 50-366 8	MARTIN. W O MARTIN. D E	8103230913×	50-219 Q 40-8502	MATTIA.H J MATTINGE, J J	8103050074* B103050562	50-259 50-312
MANRY, M MANRY, M	8103020569 8103030750	50-366 B 50-321 B	MARTIN.J D MARTIN.C W	8103120596 8103170597	40-8743 50-269 H	MATTIMBE, J. J. MATTIA, M. J.	0103030739 8103040764#	50-312 CONTRA
MANRY, M MANRY, M	8103030759 8103030869	50-366 B 50-321 B	MARTIN.T. MARTIN.T	8103030570 8103030911	90-293 B 50-293 B	U L.3OHITIAN	810327006 <b>9</b> 0 8103050761	CONTRA 50-312
MANRY, M	8103040193	50-321 R	MARTIN, F J	8103200498	50-275 H	MATTIME, J. J.	8103030815	50-312
HANRY, M	8103070370	50-366 B	MARTIN, 0 8	8103170477	50-289 H	MATTIMEE, J. J.	8103110362	50-312
MANRY, M MANRY, M	8103070505 8103130458	50-321 R 50-366 В	MARTIN, R L MARTIN, J D.	8103130359 <b>+</b> 8103260175+	50-298 R	U L.BOHITTAM U M.AITTAM	8103110580 8103070120*	50-312 CONTRAC
HANRY, M MANRY, M	8103130462 8103130467	50-321 ß 50~366 ₿	MARTIN R E MARTIN L C	B103240594 B103261094	50-440 G CONTRACT	MAITTAM J U U JENITTAM	8103990136* 8103040748	CONTRAC 50-312
MANRY, M	8103160730	50-321 £	MARTIN, L. C	B103261073	CONTRACT	MATTIA.M J	8103090462*	CONTRAC
MANRY, M MANRY, M	8103310447 8103310459	50-366 R 50-321 R	MARTIN. L. C	8103270654 8103261111	CONTRACT	U C SOMITIAN	8103110544 8103180954#	50-312 50-312
MANRY, M	8103160737	50-366 Ø	MARTIN L C MARTGRE, J	8103120467	50-416 A	MATTINGE, J. J.	8103150567	50-312
MANRY, M	8103230707	50-366 B	MARTORE. J A	8103530858	50-416 A	MAITIAM J.	8103100257*	CONTRAC
MANRY, M MANRY, M	8103230712 8103230746	50-346 B 50-366 B	MARIORE, J A MASSIE, H W	B103260999 B103250134	50-416 A NUREQ	MATTIA-H J. MATTIA-M J.	8103100305*	CONTRAC
MANRY, M MANRY, M	8103530859 8103530B15	50-366 B 50-366 B	MASSICOT P MASTERS, J. M	B103230594 B103180762	50-320 F NUREO	L M.AITIAM U U.3OHITTAH	8103100364# 8103130584	CONTRAC 50-312
MANSER.W C	8103270653	70-143	MATHEWS, D II	B102260756*	FOIA	MATTIA, M J	8103190094*	CONTRAC
MANSER W C.	8103130726*	70-143	MATHEWS. E R	8103170201+	50-305 0	MATTIMOE, J. J. MATTIMOE, J. J.	81031E0391 81031E0391	50-312
MANSER, W. C. MANSER, W. C.	8103240891 8103240288+	70-143 70-143	MATPEWS, E. R MATPEWS, E. R	8103090737 8103190197*	50-305 Q 50-305 Q	MATTIMCE J J.	8103110384	50-312 50-312
MANSER,W C MANSPEAKER,J R	8103260306# 8103100697#	70-143 Wabte mgt	MATHEWS, E. R MATHEWS, E. R	8103170191* 8103240556	50-305 0 50-305 0	L L'ECMITTAM L L'ECMITTAM	8103260108 8103170644	50-312 50-312
MANSPEAKER, J R	8103100707*	HASTE HOT	MATHEWS, E. R.	B1030704B4+	50-305 G	MATTIA. M. J	8103230903•	50-443
MAPES, J.R. MARABITO, R	8103170202# 8103020597	FOIA 50-275 B	MATHEWS, E. R. MATHEWS, E. R.	8103190110+ 8103030690	50-305 Q 50-305 P	MATTIMOE, J J	8103170442 8103170657	50-312 50-312
HARACEK, J. J.	B103160053*	90-334 F	MATHENY, D.	@103030B34*	50-346 8	MATTIA.M J	B103230939*	CONTRAC
MARBET.L K	8103030773	50-514 <i>0</i>	MATHEWS, E R	8103030833			81033108614	CONTRAC
MARBET, L K Marchal, J	8103050724 8103240685	50-514 G XPORTLIC	MATHER, B. L. Mathews, E. R.	B103160B55* B103100537	FD1A 50-305 S	MATTIMOE, J. J MATTIMOE, J. J	6103240460 6103240417	50-312 50-312
MARCOUX, L. C. Marcocciid r	8103180506 8103020549	90-309 H 70-2909	MATHEWB. E. R MATHEWB. E. R	B103170354 B103130459	90-305 G 50-305 V	MATTIMOE, J. J MATTIAN J.	8103240453 8103241086*	50-312 CONTRAC
MARCUCCIAD R.	8103230708	70-2909	MATHEWS, E R	B103170525	50-305 P	MATTIA, M J.	B103270060#	CONTRAC
MARCUCCT, D. R	8103260769	70-2909	MATHEWS, E R	8103231064	50-305 0 50-305 F	MATTIA.M J	8103270578* 8103310561	CONTRAC
MARECEK, O. Marietta, M. G.	0103520591 8103030585*	CONTRACT NUREO	MATHEWS, E. R MATHEWS, E. R	B103249370 B103230693	50-305 F	MATTIMOE, J J MATTSON, R J.	B103110832*	50-312 0EN TEC
MARINGER, J. H Mark, J. C.	8103120406 8103230592	XPORTLIC NUREO	MATHENS, E. R MATHENS, E. R	8103260593 8103310652	50-305 F 50-305 P	MAURA.F A MAURIN.L V	8103330155# 8103230201	50-373 50-382
MARK.J.C.	8103230324	ACRS	MATHEWS, E. R.	B103270726	50-305 P	MAURIN, L. V.	B103230221	90-392
MARK, J. C. MARK, J. C.	8103230432 8103230442	ACRS 50-361 0	MATHEWS, E R	8103310437 8103120399	50-395 S 50-397 S	MACRINAL V MACRINAL V.	B103040498 B103170538	50-382 50-382
MARK, J. C.	8103230472	ACRB	MATLOCK, R G	8103030784	50-397 B 50-397 B	MAURIN.L. V MAXWELL, O F	8103260373 8103040089*	50-362 50-400
MARK, J. C.	8103230524	ACRE	MATLOCK, R O	81031C0416				
MARK.J.C. Mark.J.C.	8103230207 8103230308	ACR8 50-395 D	MATLOCK, R. Q MATLOCK, R. Q	B1031704B7 B103170634	50-397 B	MAXWELL, D. C.	8103130358*	50-400 50-10
MARKE, R. L. MARKE, R.	8103110794* 8103130686*	CONTRACT CONTRACT	MATORE, J. A MATOKO, R. J	8103090096 8103090171•	90-416 A CONTRACT	MAXWELL O F. MAYLE L	8103270534* 8103170564*	50-400 50-29
MARKOWITZ, P. W.	8103181025*	50-271 H	MATBON, V	8105180555*	SECY	MAYER, L Ü.	8103170CGB+	50-282
HARRONE, J.	8103100515	M18C	V WCSTAM	8103030414 8103030414	SECY XPORTLIC	MAYER, L. O. MAYER, L. O.	8101220591* 8103050307*	90~262 50-262
HARSH, W. C. HARSH, R. J.	8103030304# 8103120770#	50-250 G 50-259 G	MATSON, V. MATSON, V	B103030953*	XPORTLIC	MAYER, L O.	8103050618	90~263
MARSHALLAN, H	8103190312* 8102270630	50-250 0 50-329 0	MATEON, V. MATEON, V.	8103100686 8103100691*	XPORTLIC XPORTLIC	MAYER.L O Mayer.L O	8103030758 8103020458	50-243 50-243
MARBHALL W. H.	8103120336	50-329 0	MATBON, V.	8103040865	XPCRTL1C	MAYER, L D	8103030549	50-262
MARBOLAIB, L. D MARBTON, T. V.	9103230462 8103090437	50-27! P TOPREP	MATSON, V. MATSON, V.	8103110054* 8103110045	XPGRTLIC XPGRTLIC	MAYER, L O. MAYER, L O	8103030587 8103030828	50-585 50-593
MARTIN, H. G MARTIN, T. T.	9103050463* 8103190879*	50-247 G 50-271 G	MATSON, V. MATSON, V	8103090443 8103090449#	XPORTLIC XPORTLIC	MAYER.L O Mayer.L O	8103070447 8103100204	50-243 50-243
				8103100701+	XPORTLIC	MAYER, L O	0103100354	20-505
HARTIN, W. G. HARTIN, T. J.	B103050421* 8103100151*	50-286 Q 50-354 8	MATSON, V. MATSON, V.	8103100675	XPORTL IC CONTRACT	MAYER, L. O. MAYER, L. O.	6103170158 6103130228	50~282
MARTIN, T. T. MARTIN, W. Q.	8102050278* 8103050284	50-29 G 50-333 G	MATBON, W. MATBON, V.	8103190682* 8103190665	XPORTLIC	MAYER L D MAYER L D	8103170192	50-263 50-263
MARTIN, J. B.	8103120621	40-1341	MATSON, V.	8103190669*	XPORTL IC		8103180525	90-202
MARTIN, R. D. MARTIN, R. D.	#103030304*	50-250 G 50-302 G	MATTIP.K. HATTIBONIG.L.	8103130046 8012290534	PROJ XPGRTLIC	MAYER, L. O. MAYER, L. D.	8103190478 8103200731	50-306 50-263
MARTIN, W. O. MARTIN, R. D.	8103090648 8103030170*	70-135 50-261 G	MATTIA, J. MATTIA, J. C.	8103300016* 8103200084*	30-410 Ø 50-352 Ø	MAYER, L. D. MAYER, L. O	0103240253 0103230766	50-263 50-263
MARTIN-R.D.	8103030170*	50-369 G	MATTIA. J.	8103050812*	50-387 0	MAYER, L. O	8103530903	50-263
MARTIN, T. T.	8103190067#	50-29 G	HATTIA. J	8103060311* 8103030331*	50~322 0 CONTRACT	MAYER, L. O MAYER, L. O	0103240354 0103360149	90-202 90-243
HARTIN, W. O. Hartin, L. E.	8103050251 8103050285#	50-289 G 50-482 G	MATTIA H. J. MATTIMOE, J. J.	8103040016*	50-312 0 50-312 0	MAYER, L. O MAYER, L. O	8103300366 8103310176	50-263
HARTÉN: T. J. Hartén: T. J.	8103190113 8103200505×	50-354 8 50-355 8	MATTIMOE: J. J. MATTIA: J. C.	8103050550* 8103160156*	50-423 Ø	MAYER, L. O	8103310209	50-262 50-282
MARTIN, W. O.	8103090724	50-293 Q	MATTIA, M. J.	8103130013+	CONTRACT	HAYER L. O.	B103319234	50-263
MARTIN, Q. W. MARTIN, Q. W	8103040866 8103040871*	71-413 71-413	MATTIA, M. J. MATTIA, M. J	8103030282*	CONTRACT 50-287 0	MAYSIE. Mazurid. W.	8103250460 8103040341*	PR 50-460
MARTIN, T. T.	8103200236*	50-29 0 50-286 0	MATTIA: M. J. MATTIA: M. J	8103050178# 8103130655#	CONTRACT CONTRACT	MAZUR, D. W. MAZUR, D. W.	8103020508 8103020605	50-460 50-460
MARTINIU Q.	0103050414	JVEGU G						.50

AUTHCR	ACCESSION NJ~3ER	SUBJECT CATEGORY	AUTHOR	ACCESSIGN NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBJEC CATEGO
MAZUR, D H MAZZARELLA, A	8103040325+ 8103120406 8103120423 8103020136 8103050647	50-460 G 50-460 E 50-460 E 50-460 G MISC	MCGRIFF. J H MCGRIFF. J H MCGRIFF. J H MCGRIFF. J H MCGRIFF. J H	8103100496* 8103100486* 8103110486* 8103110535* 8103100504*	50-327 8 50-327 8 50-327 8 50-327 8 90-327 5 50-327 5	MICHEL.C J MICHELSON.C MICHELSON.A MICHEL.C MIDURA.H J	8103040669 8103120285# 8103190489 9103270244 8103170313	71-6458 50-269 50-289 PR 50-272
MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J MCAUSLAND, P	8103240502+ 8103240313+ 8103250153+ 8103250173+ 8103250173	70-1151 70-27 70-27 70-143 PR	MCGRIFF, J M MCGRIFF, J M MCGRIFF, J M MCGRIFF, J M MCGRIFF, J M	B103100477+ B103170534+ B103170413+ B103170595+ B103250306+	50-327 8 50-327 9 50-327 8 50-327 6 50-327 8	MILAVICKAS.L MILES.E B MILEY.O H MILHISER.R.J	8103040750 8103100251 8103310853 8103040750 8103040707	50-151 CONTRAC CONTRAC 50-151 50-362
MCBREARTY,R A	8103050812*	50-387 0	MCGRIFF. J M	8103250507*	50-327 6	MILHISER.R.J	8103130417	50-382
MCBREARTY,R A	8103180678*	50-354 0	MCGUIRE. D R	6103050225*	50-359 0	MILLER.R.L.	8103120218*	F01A
MCBRIDE,M F	8103200538	50-220 0	MCGUIRE. J	8103310620*	50-302 0	MILLER.W.O	8103270449	70-824
MCHRIDE,M	8103200538	50-220 0	MCGUIRE. J	6103040338	40-2051	MILLER.W.J	8103190684*	Wabte M
MCCABE,E C	8103180186*	50-277 0	MCGUIRE. D R	6103240261*	50-250 0	MILLER.H.J	8102200419*	Wabte M
MCCABE, E. C	8103040505+	50-387 0	MCQUIRE, D R	B103020704*	50-539 0	MILLER.L.	8103050135*	50-206
MCCABE, E. C	8103140661+	50-317 0		B103261137*	50-327 0	MILLEN.C.K	8103050013*	50-267
MCCABE, E. C	8103300367+	50-317 0		B103090249*	70-27	MILLER.L	8103180361*	50-206
MCCABE, E. C	8103179354	50-278 8		B103250016*	50-335 0	MILLER.D E	8103120408*	50-331
MCCANN, J.	8103230310+	50-333 0		B103050296*	50-369 0	MILLER.W D	8103020001	50-346
MCCARTHY, K	8103120764	PR	MCGUIRE, D R	8103130733+	50-364 Q	MILLER, W. H	8103040120*	50-302
MCCARTHY, T	8103120830	FOIA	MCGUIRE, D	8103180272+	50-261 Q	MILLER, J. R	8103160426	PR
MCCARTHY, W J	8103110240+	50-341 A	MCGUIRE, D R	8103170263	50-324 &	MILLER, M. I.	8103180573	50-454
MCCARTHY, D	8103200222+	50-263 I	MCGUIRE, D,	8103240204	50-302 8	MILLER, W. O	8102280308	71-6346
MCCAUGHY, J P	810330774	50-416 S	MCGURREN, H J	8103170340	27-39	MILLER, W. O	8103040703	40-3453
MCCLOSKEY, K MCCLOSKEY, P MCCLOSKEY, J P MCCLOSKEY, J P MCCLONO, R. H	9103129453 9103120725 9102190878 9103040463 9103040195	PA PR Waste mot Waste mot Res	MCGURREIN H J MCGURREN, H J MCGURREN, H J MCGURREN, H J MCKENVA, D L	8103170513 8103190527 8103200745 8103240039 8103120742	27-39 50-309	MILLER.W D MILLER, J R. MILLER, J R MILLER, J R MILLER, J R	8103060194 8103050236 8103050241* 8103060009 8103060830	70-1257 50-54 50-54 50-184 50-70
MCCLUSKEY. J P	8103120348	40-8511	MCKEOWID L	6103050436*	50-286 0	MILLER.W O	8103060428	50-313
MCCLUSKEY. A J	8103110802	40-851:	MCKEOWN, L	6103030803	50-247 8	MILLER,W O	8103180390	50-313
MCCLUSKEY. J P	8103140170	Waste Mot	MCKEOWN, L M	8103030842	50-247 6	MILLER.W.O	8103060439	50-272
MCCLUSKEY. J P	8103240482	Waste Mot	MCKIBBEN, J C	6103100418	50-186 P	MILLER.W.O	8103060519	50-502
MCCLUSKEY. J P	8103310935	Waste Mot	MCKIBBEN, J C	8103180552	50-186 8	MILLER.W O	8103090702	50-344
MCCOLL, A. C MCCOLL, A. C. MCCOLLUM, B MCCO:MAUOHHAY MCCORKLE+O W	8103050769 8103050769 8103230849 8103060752 8103270765	50~445 0 50~445 0 50~387 U PR 70~25	MCKIBBEN, J C MCKIBBEN, J C MCKINNEY, R MCLEAN, R B	8103240510 8103240471 8103300297 8103200614 8103050846	90-186 8 50-186 8 50-186 8 50-287 H RES	MILLER.W O MILLER.L MILLER.D S MILLER.W O MILLER.B	8103090711 8103240728* 8103030514 8103090040 8103040623	50-502 50-206 50-309 50-596 Nureo
1CCCRALE, 0 W	8103310440	70-2930	MCLEATEN, J	8103040785	FOIA	MILLER. J F	8103190541	50-289
1CCCRALE, 0 W	8103310910	70-143	MCLEAREN, T	8103270594	CONTRACT	MILLER. W O	8103120023	50-280
1CCCRALE, 0. W	8103310930	70-2937	MCLOED, C.	8102260504	FOIA	MILLER, W H	8103130741*	50-259
1CCCRACK, J B	8103250138	71-9143	MCLCUGHLIN, M. T.	8103020053*	50-293 8	MILLER. M E.	8103050735	PROJ
1CCRACKEN, K H	8103050494*	90-348 P	MCLOUGHLIN, M. T.	8103090523*	50-293 8	MILLEVILLE, D P	8103190479	50-289
HCDIARDID, A C	8103130046	PROJ	MCLQUONLINES T.	8103070624	50-293 8	MILLER, U. D. MILLER, J. R. MILLER, J. R. MILLER, W. H. MILLER, M. E.	8103170470	70-1739
HCDONALD, J A	8103030600*	50-390 0	MCLQUONLINES T.	8103200704+	50-293 8		8103140519	50-184
HCDONALD, J A	8103310694*	50-261 0	MCLQUONLINES T.	8103270626+	50-293 8		8103160526#	50-186
HCDONALD, J A	8103240823*	50-390 0	MCMUNNES S	8103309007	PR		8103120630	50-390
HCDONALD, M.	8103230853*	50-389 U	MCNEES. J. L.	8103060475	50-348 F		8103130402	50-250
MCDONALD, M. MCDONALD, R. P. MCDONALD, R. P. MCDONALD, R. P. MCDOMELL, T. MCDOFFIE, M. A.	8103180453*	50-250 H	MCNEILL, W M	8103310939*	0A999	MILLER, W O	8103170007	50-247
	8103300009	PR	MCNIERNEY, E J	8103260092*	FOIA	HILLER, J R.	8103230125	50-182
	8103180504	50-348 R	MCNULTY, A	8103190264	CONTRACT	MILLER, J R.	8103230129*	50-182
	8103250414*	HABTE MOT	MCOBCAR, J J	8103160136*	50~423 G	MILLER, L K	8103170315*	50-272
	8103310518	50-400 A	MCPHILLIPS, J L	8103050692	70-2909	MILLER, W O.	8103190073	50-271
MCELRBY, N. N.	8103030821	NUREO	MCQUEEN: A	8103040855#	FOIA	MILLER, R. B.	8103190183*	50-327
MCEWEN, J. E.	8103170091+	90-317 F	MCQUEEN: A	8103040850#	FOIA	MILLER, W. O.	8103230336	50-206
MCFARLAND, C. R	8103053219+	50-395 O	MEACHAM: M	8103180527	50-498 0	MILLER, W. O.	8103230342	50-29
MCGARRY, J. M	8103270590	50-369 O	MECREDY: R	8103070429#	50-244 P	MILLER, W. O.	8103230368	50-219
MCGARRY, J. M	8103270590	50-369 O	MEDEIROS: M F.	8103060384	50-443 H	MILLER, J. R.	8103240838	50-267
MCGAUGHY, J.P.	8103030785	50-416 B	MEDEIROS M S.	B103240651	PR	MILLER, J. R.	8103240844	50-267
MCGAUGH, J.L.	8103030480 •	50-326 D	MEIERAN, M.B.	B103050049	FOIA	MILLER, J. R.	8103240852*	50-267
MCGAUGHY, J.P.	8103250197	PR	MEISS R. L	B103200073*	PROJ	MILLER, D. N.	8103241082*	CDNTRAC
MCGAUGHY, J.P.	8103040745	50-416 S	MEISS R. L.	B103260872	PROJ	MILLER, D. N.	8103270671*	CONTRAC
MCGAUPHY, J.P.	8103050056 •	50-416 O	MEKBEL C.	B103090561*	50-346 B	MILLER, W. O.	8103250093	71-6375
MCDAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P.	8103050891	50-416 8	MELLINGER.C W	8103200602	50-269 0	MILLER, J.R.	8103250414	50-267
	8103030687	50-416 0	MENCZER,W.B	8103020496	50-295 8	MILLER, W. O.	8103250637	71-6698
	8103160944	REGOD	MENDENHALLE.	8103270631*	50-254 8	MILLER, M. E.	8103250438	PROJ
	8103130048	50-416 8	MENDL.J.E.	8103040605	50-266 P	MILLS, L. M.	8101220517*	50-327
	8103240021	50-416 8	MERKEL.L S	8103190918	50-289 H	MILLS, L. M.	8101220526*	50-327
MCGAUGHY, J.P.	8103240037	50-416 8	MERRIWEATHER, N. MERRIWEATHER, N. MERRITT, W. J. MERSHON, J. L. MESLER, F. B.	8103180495*	90-327 0	MILLS, L. M	8103050444	50-390
NCGAUGHY, J.P.	8103170422	50-416 9		8103180492*	50-369 0	MILLS, L. M	8103040583*	50-327
MCGAUGHY, J.P.	8103170199	50-416 F		8103090586	90-293 P	MILLS, L. M	8103030793	50-438
MCGAUGHY, J.P	8103170659	50-416 8		8103130328*	CONTRACT	MILLS, L. M	8103180392*	50-390
MCGAUGHY, J.P	8103230726	50-416 9		8103230071*	CONTRACT	MILLS, L. M	8103050587*	50-390
MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P. MCGAUGHY, J.P.	8103250441 8103270701 8103310643 8103310411 8103310400	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	METZGER, J.R. METZGER, J. METZGER, J. METZGTER, J.R MEYER, J.E	B103020901 B103120382 B103120419 B103300294 B103120784	1&E 1&E 1&E 8&B	MILLS, L. M. MILLS, L. M. MILLS, L. M MILLS, L. M MILLS, L. M	8103240593 8103050582* 8103040768 8103040754 8103030809	50-438 50-390 50-438 50-328 50-390
MCGEE, W.E.	8103090552*	50-249 8	MEYERS, D. D	8103170089*	50-369 0	MILLB, L. M.	8103030853	50-328
MCGGVERN, J.J.	8103120459	90-34 P	MEYER, C. R	8103090850	50-388 A	MILLB, L. M	8103240297*	50-438
MCGREGOR, L. O	8103190503	50-409 8	MICHEL, C. J.	8103270835	70-143	MILLB, L. M	8103180385*	50-390
MCGREGOR, L.	8103190517	50-346 F	MICHEL, C. J.	8103300021	70-143	MILLBAP, W. J	8103240301*	70-143
MCGRIFF, J. M.	8103020536*	50-327 B	MICHEL, M.	8103050929	PR	MILLBAP, W. J.	8103240910*	70-143

AUTHCR	ACCEBBION NUMBER	SUBJECT CATEOURY	AUTHCR	ACCESSION NUMBER	SUDJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBU CATE
MILLB-L M. MILLB-L M. MILLB-L. M. MILLBAP, M. J. MILLBA-L M.	8103050573* 8103181151 8103120749* 8103130644* 8103030778	90-390 0 RE <b>00</b> D 50-259 g 70-27 50-328 8	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8103230451 8103249607 8103261211 8103270044 8103190176	50-323 A 50-327 G 50-259 G 50-259 G 50-259 F	MIRAQLIA.F.J. MIRAGLIA.F.J. MIRAGLIA.F.J MITCHELL.D.B. MITCHELL.D. B.	8103300289 8103310384 8103310419 8103170193* 8103040591*	50-47 50-34 50-31 50-32 50-28
MILLS.L. M. MILLSAP.W.J MILLS.L. M. MILLS.L. M. MILLS.L. M. MILLS.L. M.	8103160209# 8103060270# 8103240293* 8103030780 8103040753	50-518 0 70-1151 50-438 0 50-390 6 50-518 0	MILLB.L M MILLB.L M MILLB.L M MILLB.L M MILLS.L M	8103170212 8103240400 8103240466 8103240539 8103261122+	50-327 P 50-518 S 50-327 0 50-327 0 50-327 0	MITCHELLIR. MITCHELLIR MITCHELLID O MITCHELLID & MITCHELLID. O	8103180497 8103180607 8103170573* 8103170552* 8103180565*	50-39; 50-36; 50-28; 50-28;
MILLS.L.M.	8103040789	20-438 8	MILLBIL M	8103230548	50-259 P	MITTL.R.L	8103050344#	50-272
MILLS.L.M.	8103040802	90-239 0	MILLBIL M.	8103240341	50-259 P	MITTL.R.L	8103110106	REGOD
MILLS.L.M	8103060129	71-9139	MILLBIL M	8103240404	50-328 B	MITTL.R.L	8103050698#	50-272
MILLS.L.M	8103100281	50-518 6	MILLBIL M	8103240420	90-328 B	MITTL.R.L	8103050208	50-272
MILLS.L.M	8103050909	50-328 8	MILLBIL M	8103300163	50-439 B	MITTL.R.L	8103060547	50-272
MILLS.L M	8103120544	50-390 A	MILLE, L. M	8103260239	50-259 F	MITTL, A. L.	8103250665	PR
MILLSAP.W J	8103260473*	70-1201	MILLE, I., M	8103261180	50-259 Q	MITTL, R. L.	8103180564	90-272
MILLS.L M	8103030670	50-260 P	MILLE, L. M	8103270505	50-438 8	MITTL, R. L.	8103230539	50-311
MILLS.L M	8103040777	50-438 0	MILLE, L. M	8103270672	50-328 6	MITTL, R. L.	8103230713	50-272
MILLS.L M	8103240274*	50-433 0	MILLE, L. M	8103270724	50-390 8	MIYABAYASHI, M	6103040344	XPERTL
#111.8+1. M #111.8+1. M #111.8+1. M #111.8+1. M	8103020401 8103020475 8103020510 8103030789 8103040700	50-327 A 50-327 P 50-259 P 50-327 P 50-438 6	MICLB-L M MICLB-L M MICLB-L M MICLB-L M. MICLB-L M	8103300158 8103270512 8103270522 8103270712 8103270777	50-39Q 8 50-299 F 90-438 8 90-566 8 50-328 A	MIYABAYASHI,M MIYASAYASHI,M MIYABAYASHI,M MOBERO,A J MOE,H J	8103040472 8103050228 8103050887 8103281000 8103040796*	XPORTL XPORTL XPORTL 71-903: FOIA
MICLB, L. M	8103110809	40-1341	MICLE.C.M.	8103270823	50-566 B	MOFFETT, T	8103050870*	COMMISS
MICLB, L. M	8103020427	50-390 A	MICLE.C.M	8103300333	50-518 B	MOHR, H C	8103181142*	70~754
MICLS, L. M	8103020633	50-553 A	MICLE.C.M	8103270462	50-438 B	MOLHOLT, B	8103928557	50-289
MICLB, L. M	8103030771	50-390 S	MICLE.C.M	8103300173	50-327 P	MONAK-GAGNON, C	8103120745	PR
MICLB, L. M	8103040696	50-390 S	MICLE.C.M.	8103310477	50-327 R	MONDEN, T.	8103310833	xPORTL
MILLE, L. M MILLE, L. M MILLE, L. M MILLE, L. M	8103040717 8103040757 8103040557 8103040775 8103050306	50-259 F 50-328 B 50-518 8 50-328 S 50-566 A	MILLE.L.M MILLE.L.M MILLE.L M MILLE.L M MILLE.L M.	8103310405 8103310488 8103310500 8103310559 8103310559	50-438 S 50-438 S 50-327 P 50-328 B 50-438 S	HENYGOMERY, D. M. HONTI, W. A. HONTI, W. A. HONTOYA, J. B. HODDY, D. E.	8103180491 • 8103110611 8103190343 8103200649 8103090911	50-369 50-247 50-247 50-275 50-29
HILLS.C. H HILLS.C. H HILLS.C. H HILLS.C. H	8103060336 8103080497 8103090604 8103090638 8103090653	50-259 F 50-259 R 50-390 8 50-438 B 50-328 B	MILLS.L M. MILLS.L.M MILLS.L M MILLS.L M MINECK.D L	8103310599 8103310485 8103310551 8103310624 8103040487	50-390 S 50-390 G 50-438 G 50-438 G 50-331 R	MODDY, D. E. MODDY, D. E. MODDY, W. C. MCDDY, D. E. MODDY, W. C.	8103100183 8103130359* 8103240338 8103310631 8103310489	50-29 50-29 50-206 50-29 50-206
MICLE, L. M	8103120182	50-328 8	MINECK. D. C.	8103050967	90-331 8	MCON, C, W	8103120741	50-466
MICLE, L. M	8103130027	50-438 8	MINECK. D. L	8103090924	90-331 R	MOON, C, W.	8103170744	50-466
MICLE, L. M	8103180280	40-1341	MINECK. D. L.	8103170476	90-331 8	MOON, C,	8103260445	50-454
MICLE, L. M	8103090551	50-553 6	MINECK. D. L.	8103170498	90-331 8	MOGNIMMAN, B,	8103120660	PR
MICLE, L. M	8103110522	50-438 8	MINECK. D. C.	8103170966	50-331 6	MOORE, R, N	8103041021	XPCRTL1
MILLB, L, M. MILLB, L, M. MILLB, L, M. MILLB, L, M. MILLB, L, M.	8103110545 8103110614 8103110664 8103130009 8103100453	50-328	Mineck, D. L. Mineck, D. L. Miner, 8 Miner, 9 Miner, 9	8103180495 8103310673 8103031083 8103180909 8103120740	90-331 R 90-331 B 90-315 P 50-315 P	MDORE.D.E MCDAE.D.E MODAE.R.N MODRE.R.N MOORE.D.E	8103050225 8103310820 8103090210 6103090276 8103050276	50-369 50-302 XPDR TL I XPOR TL I 90-369
MILLS.L.M.	8103110414	50-259 P	Minichind, C	8103040100	NUREO	MOORE, R. N.	8103041033	XPORTLI
MILLS.L.H.	8103110659	50-328 8	Minichind, C	8103200357	NUREO	MOORE, R. N.	8103050391	XPORTLI
MILLS.L.K	8103110721	50-327 P	Minnich, J. E	8103270019*	50-320 H	MOORE, R. N.	8103050427	XPORTLI
MILLS.L.M.	8103170085	50-259 Q	Minnich, J. E.	8103250111*	50-320 R	MOORE, R. N.	8103040897	XPORTLI
MILLS.L.M.	8103180886	50-259 Q	Minnich, J. E.	8103250116*	50-320 R	MOORE, R. N.	8103050504	XPORTLI
Mille, L.M.	8103100325	50-259 P	Minnich, M.	8103180683	50-289 0	MOORE, Q W.	8103050599	50-334
Mille, L.M.	8103100601	50-259 P	Minns, J. L.	8103240405+	50-250 0	MOORE, G W	8103050603•	50-334
Mille, L.M.	8103110433	50-328 8	Minoque, R. 8	8102260692+	F01A	MOORE, R N	8103130185	XPDRTLI
Mille, L.M.	8103110627	50-328 8	Minoque, R. 8.	8103020746+	F01A	MOORE, J. E.	8103030573	50-272
Mille, L.M	8103110648	50-327 P	Minoque, R. 8.	7910090482+	F01A	MOORE, J. E	8103040609	50-155
MILLB, L. M.	8103120288	TOPREP	MINDQUE, R. B.	8102280186+	10CFR	MDORE.R N	8103100679	XPORTLI
MILLB, L. M.	8103250041	PR		7711050328+	FOIA	MDORE.D E.	8103130733+	50-364
MILLB, L. M.	8103260019	50-327 G		7711050330+	FOIA	MODRE.A C.	8103169028+	CONTRAC
MILLB, L. M.	8103110584	50-346 B		8103180236+	10CFR	MODRE.R.N.	8103130642	XPORTLI
MILLB, L. M	8103130405	50-328 8		8103270178+	FOIA	MODRE.R.N	8103120169	XPORTLI
MILLB, L. N.	8103160844	50-327 Q	MENOQUE R. O	8103270157*	FOIA	MOORE, J. E	8103160374	50-247
MILLB, L. M.	8103160883	50-259 Q	MENOQUE R. B.	8103270165*	FOIA	MOORE, J. E	8103230065	50-247
MILLB, L. M.	8103130466	50-438 B	MENOQUE R. B.	8103180224*	10CFR	MOORE, R. N	8103310891	xpdq TL 1
MILLB, L. M.	8103250187#	50-438 Q	MENOQUE R.	8103180146*	10CFR	MOORE, J. E	8103270638	50-155
MILLB, L. M.	8103160572	50-328 F	MENOQUE R. B.	8103270147*	FOIA	MORAN, D. M	8103250433	50-289
MILLB, L. M.	8103170194	50-257 F	Miraglia, F. J.	8103110373	50-272 P	MORAN, D. M. MOREADITH: F.L. MOROAN, J. N. MOROAN, H. E. MORIST, A. V	8103250434	50-289
MILLB, L. M.	8103170322	50-390 K	Miraglia, F. J.	8103230409	50-361 D		8103270452*	50-395
MILLB, L. M.	8103170376	50-438 B	Miraglia, F. J.	8103040173	50-361 E		8103030503*	TOPREP
MILLB, L. M.	8103170502	50-390 B	Miraglia, F. J.	8103040180*	50-361 E		8103261044	XPORTL I
MILLB, L. M.	8103260477	50-259 Q	Miraglia, F. J.	8103050420	50-361 O		8103060278	50-293
MILLES L. M	8103160578	50-328 A	Miraglia, F. J.	8103160336	50-413 A	MDRIS, C. J	B103020782	NUREO
MILLES L. M.	8103160593	50-239 P	Miraglia, F. J.	8103180980	50-361 E	MORISI. A. V.	B1031B0622	50-293
MILLES L. M.	8103170141	50-326 A	Miraglia, F. J	8103120849*	50-311 P	MORISI. A. V.	B103060476	50-293
MILLES L. M.	8103170389	50-518 S	Miraglia, F. J.	8103120854*	50-311 P	MORISI. A. V.	B103200070	50-293
MILLES L. M.	8103170583	50-259 P	Miraglia, F. J.	8103120858*	50-311 P	MORISI. A. V.	B103200272*	50-293
MILLS L. M.	B103170489	50-327 P	HIRAGLIA-F. J.	8103090783	50-471 F	HDRIBI.A.V	8103100386	50-293
HILLS L. M.	B103180544	50-390 B	HIRAGLIA-F. J.	8103200008	50-275 E	HDRIBI.A.V.	8103100592	50-293
HILLS L. W.	B103180562	50-328 B	HIRAGLIA-F. J.	8103120620	50-529 E	HDRIBI.A.V.	8103230654	50-293
HILLS L. M.	B103180702	50-566 B	HIRAGLIA-F. J.	8103230898	50-416 A	HDRIBI.A.V.	8103230687	50-293
HILLS L. M.	B103200577	50-518 A	HIRAGLIA-F.	8103231073	50-416 F	MDRIBI.A.V.	8103240213	50-293

POHTUN	ACCESSION NUMBER	TOBLEUB CATEODRY	AUTHCR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHER	ACCESSION NJMBER	SUBJEC CATEGO
MORRISON, W M MCRRIS, A E MORRIS, P A MORROW, D. MORSE, A E	9008270164* 8103180889 8103090192* 8103240642 8103200948	FOIA 90-320 P CONTRACT 40-8463 50-275 H	MURPHY, C E	6103050453# 8103160522# 8103040077# 8103040762# 8103180396#	50-370 Q 50-370 Q 50-413 Q 50-302 Q 50-390 Q	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MUBBONUMER, D MYERS, B A	8103260902 8103310592 8103310617 8103020325 8103130352	50-346 50-346 50-346 State P State P
MORTENSEN, N MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	8103100406 8103261075* 8103251102* 8103261109* 9103261115*	50-205 B FOIA FOIA FOIA FOIA	MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E	8103050067+ 8103240302+ 8103030172 8103100397 8103040752+	50-416 9 50-438 0 50-993 0 50-438 0 90-302 0	MYERS,D O MYERS,S MYNATT,F R MYNATT,F R MYRABO,A L	8103240648+ 8103250759 8103050023 8103110665 8103190485+	50-269 PR RES RES 50-263
MORTON, K. V.	8103251120# 8103251123# 8103251128# 8103251134# 8103230019#	FDIA FDIA FDIA FDIA CDNTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E. MURPHY, C E	8103160215# 8103050068 8103050210 8103050281 8103050300	50-518	NAKADEGAWA, J NAPIN, D. A NAPIN, D. A NAPUDA, G NAPUDA, G.	8103050802 8103230375* 8103230386* 8103050789* 8103050797*	PR 50-269 50-269 50-220 50-333
MORTON, R MORTON, K V	8103120732 8103240841* 8102270590* 8103040890* 8103050332*	PR CUNTRACT 50-171 P CONTRACT CONTRACT	MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E	8103050333 8103040050+ 8103040049 8103040807 8103050390	50-438 Q 50-413 Q 50-413 Q 50-280 Q 50-348 Q	MARDACCI.G A NARDI.A J NARDI.A J MARRUW.L NARROW.L	8103100554* 8103250672 8103240375 8103050812* 8103060311*	50-289 PR 50-87 50-387 50-322
MORTON, K. V.	8103050157+ 8103050203+ 8103120459+ 8103360179+ 8103120248+	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	AURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E	8103180217# 8103180237# 8103250145# 8103040074# 8103040795	50-349 Q 50-349 Q 50-321 Q 50-400 Q 50-338 Q	DARROW, L. NAU, R. F. NAVARRO, J. P. NAVARRO, J. P. NEARY, E.	8103250448+ 8103100076 8103170170 8103310299 8103300152	90-450 NUREQ 50-322 50-322 PR
MORTON K V. MERTON K V. MERTON K V. MORTON K V. MORTON K V.	8103040919+ 8103230326 8103230083+ 8103160550+ 8103040572+	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E	8103040821 6103050553 8103070784 8103110517 8103120421	50-395	NEELY.DR. NEHEMIAB.JV NEIGHBORB.D NEIL.CH NEIGLER.JH	8103230678* 8103240414* 8103031075 8103260922 8103250023*	50-287 50-250 50-261 NUREO 50-373
MORTON, R. V. MORTON, R. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8103110794# 8103130696# 6103190028# 8103100243# 8103100661#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8103120429 8103120441 8103240674# 8103090498* 8103040111*	50-296 G 50-280 G 50-424 G 50-413 G 50-302 G	NEISLER. J NEISLER. J NEIBLER. J NELBON. C. A. NELBON. P. R	8103170358 8103170365 8103310360 8103260772* 8103260311#	90-293 50-298 50-494 40-1947 FOIA
MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, A. V. MORTON, A. V.	8103100670+ 8103120859+ 8103260556+ 8103160028+ 81031600571+	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY C E	8103040743 8103090422* 8103180417 8103250193* 8103180449	50-302 G 50-400 G 50-327 G 90-438 G 50-327 G	NELSON.P R NELSON.C NELSON.J D NELSON.J D. NELSON.J D	8103260293* 8103040258* 8103110315 8103160333 8103160327	FOIA 50-133 40-299 40-299 40-299
PORTON, K. V PORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	8103200794* 8103270063* 8103230071* 8103270040* 8103240425*	CONTRACT CONTRACT CONTRACT CONTRACT 50-369 S	MURPHY, C E	8103180483 8103180501 8103190180 8103240722* 8103190340	50-367	NELBON, J. D. NELBON, R. L. NELBON, R. L. NELBON, B. O. NELBON, P. R.	8103110334 8103050778# 8103130021# 8103300321 8103190572	40-259 50-305 50-305 50-275 50-225
MOSLAK, T MCUNT, R E MCWATT, W E MCWRY, W R MCWRY, W R	8103030855* 8103100015 8103200406 8103050918 8103040714	50-320 G 50-255 G 50-289 G XPORTLIC 70-734	MURPHY. C E MURPHY. C E MURPHY. C E MURPHY. N MURPHY. N	8103190333 8103240152 8103260536• 8103270444 8103050045	50-553 G 50-51B G 50-400 G 50-275 H 50-416 G	NEL 9DN. P NEMETH, K. J. NERSES, V. NERSES, V. NERSES, V.	8103250404 8103260556# 8103069023 8103130338 8103160536	50-264 CONTRAC 50-389 50-389
MOURY, W. R.	8103030818 8103030825 6103120451 8103120164 6103190711	50-87 R 50-163 R 70-734 XPORTLIC XPORTLIC	MURPHY.C E. MURPHY.C E. MURPHY.C E. MURPHY.C E. MURPHY.C E.	8103050460 8103090160 8103240710 8103260444 8103260493	50-438 Q 50-389 Q 50-438 Q 90-546 Q 90-390 Q	NEREES V. NERBES V. NERBES V NEUMANN, M. R NEUMANN, M. R.	B103170777 B103230010 B103240082 B102240105 B103051014	50-389 50-389 50-387 40-8380 40-8380
MORRY, W. R. MORRY, W. R. MORRY, W. R. MROCZKA, E. J. MROCZKA, E. J.	8103190715+ 8103310836 8103310839+ 8103050627 8103040630	XPORTLIC XPORTLIC XPORTLIC 50-245 8 50-245 6	MURPHY. W P MURPHY. W. P MURPHY. C E MURPHY. C E MURPHY. E 9	8103030851 8103030856* 8103310778 8103160457 8103100125	50-271 B 50-271 B 50-338 Q 50-370 Q NUREQ	NEUMANN, IS R NEWACKECK, R L NEWBERRY, B NEWMAN, J R NEWMAN, J R	8103260701 8103300071 8103060786 8103050664 8103050664	40-8380 50-228 50-320 50-466 50-466
MRECZKA, E. J MRECZKA, E. J MRECZKA, E. J MRECZKA, E. J MRECZKA, E. J	6103050612 6103050608 6103100505 6103050673 6103170663	50-336 S 50-336 S 50-336 S 50-245 R 50-245 R	MURPHY, C E MURPHY, U P MURPHY, C E MURPHY, U P MURPHY, U P	8103±00972* 8103090948 8103240733* 8103240530 8103240532*	50-314 8 50-271 0 50-338 0 50-271 8 50-271 8	MEHMAN, J.R. NEWMAN, J.R. NEWMAN, J.R. NEWMAN, J.R. NEWMAN, J.R.	8103170611 8103170611 8103170644 8103170647 8103170647#	50-466 50-466 50-498 50-498 50-498
M9DCZKA, E. J MROCZKA, E. J MUCHNICKI, E. D MUELLER, C. MUIR, P. H	6103170591 6103310476 6103250698 6103170302 6103260522+	50-336 R 50-245 R PR 90-461 H 27-39	MURRAY, B MURRAY, T. D. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D.	8103130172* 8103020509 8103030541 8103050287 8103250396	50-335 G 50-346 S 50-346 S 50-346 R 71-9096	NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R.	8103190649* 8103190649* 8103190649* 8103190644 8103190649*	50-498 50-498 50-498 50-498 50-498
MULKEY J P. HULLEN. M MULLENS, J. A MURGER, P. L. MUNNO, F. J.	8103140940* 8103050949 8103250429 8103100661* 8103240222	50-348 G PR NUREO CONTRACT PR	MURRAY, T. D. MURRAY, H. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D. MURRAY, T. D.	8103030826 9103200548 8103030838 8103130573 8103090557	50-346 8 50-275 H 50-346 B 50-346 5 50-346 S	NEWTON, M NEXON, H H NICHOLE, E, H NICHOLEON, N A NICHOLE, T, C	8103180555 8103310620* 8103260806* 8103070704* 8103030832	50-289 50-10 FOIA 50-263 50-395
MUNNO, F. J MUNGO, J. J. MUNGO, J. J. MUNGO, J. J. MUNGORO, L. T.	8103261004 8103120059 8103120071 8103120074 8102230694+	FOIA 71-6717 71-9127 71-9128 40-4492	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D.	8103090363 8103130393 8103130386 8103160736 8103170612	50-346 B 50-346 R 50-346 B 50-346 B 50-346 B	NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C. NICHOLB, T. C.	8103020362 8103020461 8103030760 8103030698 8103120294	50-395 50-395 50-395 50-395 50-395
MURDOCK.W D. MURLEY.T E MURLEY.T E MURLEY.T E MURLEY.T E	8103190457 8103020044+ 8103120673 8102280404+ 8102280325+	50-269 H 50-289 G PR 50-369 P 50-369 P	MURRAY, M J. MURRAY, T. D MURRAY, M J MURRAY, T D MURRAY, T D.	8103180967# 8103170488 8103260792 8103260426 8103310627	50-237	NICHOLS, T. C. NICHOLS, T. C. NICHOLS, T. C NICHOLS, T. C NICHOLS, T. C	8103110635 8103110653 8103120307 8103100374 8103160872	50-395 50-395 50-395 50-395 50-393

MICHOLB. F C MICHOLB. T C MICHOLB. T C MICHOLB. T C MICHOLB. T C	8103100362 8103100521 8103200622 8103170448 8103170451	50-375 8 50-375 A 50-375 A 50-395 8 50-395 S	NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	8103100009 8103120202 8103120613 8103120624 8103120219	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	O'RETLLY, J P O'RETLLY, J P O'RETLLY, J P O'RETLLY, J P	8102280484 8102280574 8103120841• 81030503358 8103060293	50-259 50-321 50-269 50-321 50-302
NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T C	8103170526 8103170578 8103180778 8103130419 8103170569	50-395 B 50-395 B 50-395 A 50-395 K 50-395 B	NOSENZO, L. V. NOSENZO, L. V. NOSENZO, L. V. NOSENZO, L. V. NOVAK, T. M.	8103120634 8103190369 8103260041 8103310919 8103040984	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC 30-250 P	D'REILLY, J.P. O'REILLY, J.P. D'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8103090752 81032403244 8103020133 8103020145 8103020147	50-250 50-280 50-13 50-124 50-129
NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T C NICHOLS, T. C	8103190643 8103230680 8103250440 8103270747 8103230444	50-375 8 50-375 8 50-375 8 50-375 0 50-375 6	NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVAK, T. M.	B103200324 B103100057 B103110412 B103110193 B103110221	50-34B P 50-317 P 50-271 P 50-261 P 50-272 P	D'REILLY. J P D'REILLY. J P D'REILLY. J P O'REILLY. J P.	8103020149 8103020151 8103020156 8103020189 8103020164	50-160 50-538 50-111 50-406 50-83
MICHOLS, T C MICHOLS, T C MICHOLS, T C MICHOLS, T C MICHOLS, T C	8103230653 8103310705 8103260275 8103270443 8103270540	50-395 A 50-395 Q 50-395 A 50-395 A 50-395 B	M T.AAVDM M T.AAVDM M T.AAVDM M T.AAVDM M T.AAVDM	8103110423 8103110449 8103090090 8103110183 8103110398	50-302 P 50-309 P 50-286 P 50-315 P 50-287 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8103020168 8103020170 8103020177 6103020186 8103020193	50-62 50-437 50-280 50-261 50-302
NICHOLB, T C NICHOLB, T C NICHOLB, T C NICHOLB, T C NICHOLB, T C	8103270559 8103270620 8103270436 8103300070 8103300157	50-395 @ 50-395 8 50-395 A 50-395 8 50-395 A	NÖVAK.T M NÖVAK.T N NÖVAK.T M NÖVAK.T M NÖVAK.T M	8103110436 8103160458 8103180014 8103160227 8103250156	90-368 P 90-277 P 50-339 P 50-338 P 50-325 P	D'REJLLY, J. P O'REJLLY, J P O'REJLLY, J P O'REJLLY, J P	8103020203 8103020242 6103020251 8103020259 8103020263	50-269 50-400 50-250 50-348 50-321
NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C	8103300161 8103310414 8103310461 8103310494 8103310359	50-395 A 50-395 A 50-395 A 50-395 A 50-395 A	NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8103230191 8103240644 8103190646# 8103230232 8103230245	50-368 0 50-368 0 50-289 0 50-331 P 50-313 P	OTREILLY, J.P. OTREILLY, J.P. OTREILLY, J.P. OTREILLY, J.P. OTREILLY, J.P.	8103020269 8103020270 8103020277 8103040126 8103040133	50-416 50-345 50-259 50-348 50-302
NICHOLS, T. C NICHOLS, T. C NICOLOBI, J NIESLER, J. H NIEZNANSKI, J	8103310366 8103310458 8103060259* 8103230162* 8103170643	50-395 A 50-399 к 40-8702 50-456 G 50-269 н	NOVAK.T. H NOVAK.T. H NOVAK.T. H NOVAK.T. H NOVAK.T. H	8103240051 8103240622 8103260083 8103261148 8103260990	50-346 P 50-334 P 50-259 P 50-263 P 50-312 P	0.8E1CTA.7 b 0.8E1CTA.7 b 0.8E1CTA.7 b 0.8E1CTA.7 b 0.8E1CTA.7 b	8103040139 8103040141 8103040144 8103040149 8103040156	50-321 50-414 50-375 50-280 50-259
NILBON,R. NIMITZ,R. L. NIPAR, J. E. NIX,R. T. NIX,R. T.	0103250713 8103050762* 8103100172* 8103160734* 8103160740*	PR 50-333 Q 40-7924 50-321 B 50-366 B	NOVAK, T. H NOVARRO, J. P NOVARRO, J. NOVARRO, J. P. NOVARRO, J. P.	8103260149 8103030756 8103090431 8103160393 8103160539	50-254 P 50-322 A 50-322 A 50-322 F 50-322 E	0.8E1FFA. Y. b 0.8E1FFA. Y. b 0.8E1FFA. Y. b 0.8E1FFA. Y. b	8103040164 8103040167 8103040174 8103050015 8103160723	50-250 50-261 50-261 50-259 50-321
NIX.R T NIXON W A. NOELL.P N. NDELL.P.N. NDONAN.V.B	8103230833* 8103136047* 8103060313* 8103240605* 8103020017	50-366 8 40-8027 50-409 P 50-213 P 50-373 E	NOVARRO, J. P NOVARRO, J. P NOVARRO, J. P. NOVARRO, J. P NOVARRO, J. P	8103160587 8103240235 8103180326 8103180587 8103190521	50-322 A 50-322 G 50-322 E 50-322 A	O'REILLY. J P O'REILLY. J P O'REILLY. J P O'REILLY, J P	8103100735 8103120579 8103130230 8103140482 8103140491	50-324 50-416 50-518 50-239 50-393
NOCHAN, V. B NCOHAN, V. B NOCHAN, V. B. NORDERHAUG, L. R. NORDERHAUG, L. R.	9103050470 9103041030 8103310148* 8103030383 8103020278	50-313 0 50-369 P 50-369 0 70-1257 70-734	NOVARRO, J P NOWICKI, S J NOWICKI, S J NOWICKI, S J NUCENT, E L	8103200442 8103020712 8103120186 8103250180 8103040783	50-322 E 50-206 P 50-206 P 50-206 P 40-2259	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P. O'REILLY, J P.	8103160694 6103160706 8103160709 8103160713 8103160716	50-321 50-261 50-261 50-280 50-348
NCRDERHAUD, L. R. NCRDERHAUD, L. R. NORDERHAUD, L. R. NORDERHAUD, L. R. NORDERHAUD, L.	8103230086 8103230053 8103230179 8103230088 8103200419	50~206 Q 50~326 Q 50~187 Q 50~206 Q 70~25	NUGENT, E. L. NUGENT, E. L. NUGENT, E. L. NUGENT, E. L. NUNN, D. E.	8103261016 8103170467 8103170470* 8103310608 8103180559	40-4492 40-2259 40-2259 40-2259 50-361 8	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8103160718 8103160722 8103160725 8103160960 8103160964	50~250 50~302 50~321 50~269
NORDERHAUD, L. R NORDERHAUD, L. R. NORELIUB, C. E. NORELIUB, C. E. NORELIUB, C. E.	8103230060 8103260486 8103040159+ 8103170710+ 8103020597	50-326 9 50-433 9 50-329 9 50-341 0 50-295 8	NUSSBAUMER.D.A NUSSBAUMER.D.A NUSSBAUMER.D.A NUSSBAUMER.D.A. NUSSBAUMER.D.A.	8103260716+ 8103260692+ 8103260666+ 8103040528+ 8103260646+	FOIA 40-1947 40-1947 40-8610 40-1947	O'REILLY, J.P. O'REILLY, J.P. D'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8103160583 8103160597 8103160600 8103160645 8103160651	90-416 90-395 90-437 90-302 90-269
NORELIUB, C. E. NORELIUB, C. E. NORELIUB, C. E. NORELIUB, C. E. NORELIUB, C. E.	8103090678 8103110763 8103230115 8103230146 8103260461	50-305 G 50-358 A 50-358 G 50-409 G 50-206 G	NUSSBAUMER.D A NUSSBAUMER.D A NUSSBAUMER.D A NUSSBAUMER.D A NUSSBAUMER.D A	8103260652* 8103260642* 8103260600* 8102270094 8103060190	40-1947 40-1947 40-1947 50-139 S State Prog	O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8103160659 8103160663 8103160674 8103160677 8103170062	50-261 50-250 50-348 50-488 50-261
NORELIUS: C. NORRHOLM, L. J. NORRHOLM, L. NORRHOLM, L. NORRIB, K. B.	8103240771 8103190098* 8103100509 8103170337 8103190593	50-263 Q 50-272 Q 50-272 S 50-272 S 50-289 H	NUSSBAUMER, D. A. NUSSBAUMER, D. A. NUSSBAUMER, D. A. NUSSBAUMER, D. A. NUSSBAUMER, D. A.	8103060167 8103110671 8103060186 8103170743 8103300393	State Prog State Prog State Prog State Prog IAE	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J. P.	8103140812 8103140821 8103170011 8103179028 8103170033	50-390 50-395 50-259 50-250 50-466
NORTH: H. B NORTH: H. B NORTH: H. B NORTH: H. NORTON: B.	8103050575* 8103100403* 8103240708* 8103200409 8103030888*	50-312 0 50-528 0 50-312 0 50-312 S 50-275 0	O'BRIEN, J. P. O'BRIEN, J. O'CONNOR, P. W O'CONNOR, P. O'DONNELL, E P	8103050575* 8103030154* 8103100438 8103180398* 8103170257*	50-312 0 50-312 0 50-237 P 50-237 G FOIA	O'REILLY, J. P.	8103170041 8103170052 8103170056 8103170059 8103170063	50-269 50-437 50-348 50-302 50-417
NORTON, B. NORTON, B. NORTON, B. NORTON, B. NORTON, B.	8103050842 8103200678 8103200678 8103230715 8103230715	50-275	D'FARRELLY.C. D'NEILL.B D'NEILL.J. O'NEILL.J. D'NEILL.J.	8103090368 8103030855* 8103110619 8103120374 8103180567	PR 50-320 0 50-155 0 50-155 0 50-155 0	O'REILLY, J P.	8103170067 8103170079 8103170083 8103170098 8103130739	50-280 50-321 50-261 50-416 50-259
NOBENZO, L. V. NOBENZO, L. V. NOBENZO, L. V. NOBENZO, L. V. NOBENZO, L. V.	8103140323* 8103050526 8103050730 8103100002 8103100003	SECY XPORTLIC XPORTLIC XPORTLIC XPORTLIC	O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8103260425* 8103260389* 8103120829 8103130708* 8103120754*	POIA FOIA 50-250 G 50-280 G 50-259 G	O'REILLY, J. P.	8103240789 8103240805 8103200197 8103200238 8103200242	50-338 50-390 50-259 50-348 50-395

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	POHTUA	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJE
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8103200246 8103200258 8103200263 8103200271 8103200278	\$0-437	OPREALG W ORDERS W T ORGERS W T ORLOSKY, P M CSORIO. J M	8103310469 8103050170* 8103249648* 8103261139* 8103110197	50-49B S 50-261 G 50-269 G 50-57 P 71-417	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8103030751 8103040629 8103040699 8103040713 8103030714	50-369 50-369 50-369 50-369 50-369
O'REILLY, , P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8103200281 8103200289 8103203301 8103203314 8103193844	50-269 0 50-458 0 50-261 0 90-280 0 50-340 0	CSBMAN. W R DSSMAN. W.R OSTER. J OSTER. J OSTER. J	8103230350 8103230050 8103076581 8103070618 8103316613	REGOD REGOD 50-10 J 50-254 J 50-10 I	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8103030731 8103090278 8103120804 8103130133 8103050528	50-364 50-264 50-364 90-364 90-364
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P, O'REILLY, J P,	8103190871 8103190380 8103190884 8103190888 8103190895	50-261 0 50-302 0 50-437 0 50-395 0 50-416 0	OSTRANDER.N C OTT.E OUDRE.R P OUBRE.R P GUELLETTE.R N	8103240428 8103190490 8103130961 8103230728 8103100439*	50-142 H 50-287 H 50-312 S 50-312 S 50-369 S	PARKER, H O	8103060460 8103090517 8103100457 8103160187 8103260283	90-287 50-364 90-364 90-264 PR
D'RETLLY, J P O'RETLLY, J P, O'RETLLY, J P, O'RETLLY, J P, O'RETLLY, J P,	8103200003 8103200013 8103200019 8103200024 8103200030	50-259 0 50-269 0 50-250 0 50-468 0 50-280 0	CUELLETTE.R W CUELLETTE.R W OUELLETTE.R W OUELLETTE.R W OUELLETTE.R W	8103040632* 8103040706* B103040720* B103100435* B103100484*	50-369 8 50-369 8 50-369 8 50-369 8 50-369 8	PARKER, W. O.	8103090640 8103100467 8103110321 8103100426 8103100441	50-264 50-364 50-364 50-364
DIRETULY J.P. DIRETULY J.P. DISULLIVAN J.F DISULLIVAN J.F DITOOLE J.D.	8103200336 8103260355 8103260365* 8103260357* 8103260357*	50-321 0 90-348 0 50-155 H 50-155 H 50-247 0	OUGLLETTE, R W OUGLLETTE, R W OUGLLETTE, R W OUGLLETTE, R W OUZTB, J E	B103100494* B103130456* B103130487* B103100449* B103120783*	50-369 8 50-369 8 50-369 8 50-369 5 90-324 0	PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8103110491 6103130481 8103160851 6103160961 8103180478	90-267 50-369 50-269 50-369 50-369
0 100LE. J D.	8103099067 8103240092 8102250439 8103030873 8103030722	90-247	DVERBY, O DVERDEER, E O OVERTON, J A OHGLEY, O F OHGLEY, O F	8103120552 B103190469 B103041031 B103030021 B103030492	50-367 H 50-289 H PR TOPREP TOPREP	PARKER, W. D.	8103240602 8103100428 8103110676 8103130484 8103260492	50-369 50-369 50-369 50-369 50-269
DITOOLE, J.D. DITOOLE, J.D. DITOOLE, J.D. DITOOLE, J.D. DITOOLE, J.D.	8103020393 8103030707 8103030712* 8103100517 8103130391	50-247 P 50-3 P 50-3 P 50-3 R 50-9 P	ONZARSKI.P C PACE.P L PACE.P L PACE.P L PACE.P L	B103090147 B103160735# B103130366# B103130592# B103160758#	RE8 50-250 6 50-335 8 50-335 8 50-335 8	PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8103120438 8103240628* 8103240712* 8103130515 8103130545	50-269 50-269 50-269 50-369 50-369
0 * EGOLE. J D 0 * TOOLE. J D 0 * TOOLE. J D 0 * TOOLE. J D 2 * TOOLE. J D	6103130468+ 8103170472 8103170874 8103170613 8103230578	50-3 P 50-247 P 50-247 P 50-247 G 50-247 R	PAGE.R O. PAGE.R O PAGE.R O PAGE.R O PAGE.R O	B103170038* B103160269 B103160283* B103040658 B103040662*	70-820 70-2928 70-2928 70-157 70-157	PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	B103160746 B103230479 B103240757• B103170484 B103200611	50~410 50~369 50~369 50~269 50~269
1'TOOLE, J D 1'TOOLE, J D 1'TOOLE, J D 1'TOOLE, J D 0'TOOLE, J D	8103240575 8103200589 8103250246 8103260574 8103270764	50-247 8 50-247 P 50-247 P 50-247 S 50-247 P	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAIBLEY, T. C	8103090277 8103090283 8103130031 8103270023 8103190509	70-27 70-1113 40-8027 70-820 50-289 H	PARKER, W O PARKER, W O PARKER, W O. PARKER, W O. PARKER, W O	8103240527 8103310770 8103240396 8103230644 8103240332	50-364 50-364 50-364 50-264 50-244
D'TODLE, J D. D'TODLE, J D. D'TODLE, J D. OBERG, C T ODAR, F	8103300304 8103310341 8103310346 6103031009 8103180902#	50-247 P 50-247 P 50-247 P 1&E REVIEW GRP	PALAZZO, L PALHIOTTO, N PANAGOS, A PAGLINO, R J PAGLINO, R J	8103050916 8103110206* 8103170528* 8103270390* 8103050812*	PR 40-8610 50-295 8 50-220 0 50-387 0	PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	6103240455 6103240393 8103270704 6103310913 6103270664	50~367 50~267 50~267 50~267
DESTMANN, M. J. DESTMANN, M. J. DESTMANN, M. J. CESTMANN, M. J. DESTMANN, M. J.	8103050585+ 8103040278+ 8103090704+ 8103110432+ 8103250658+	90-254 0 90-373 0 50-263 0 40-2274 90-367 0	PAPAY, L. T. PAPERIELLO, C. J.	8103240101 8103020423 8103180331* 8103240106* 8102180345	90-206 Q 90-361 B 50-206 Q 90-206 Q	PARKER, W D PARKER, W O PARKER, W. O. PARKINSON, T F PARKE, C V	8103300318 8103300336 8103300385 8103030719* 8103200094	50-369 50-369 50-369 50-124 REB
COLE.H O ORUDA.H. OLIVER.R H CLIVERA.E OLLER.R E	8103200556 8103230760 8103103076 8103200659* 8103120601*	50-289 H XPORTLIC MUREO 50-443 Q QA999	PAPERIELLO, C. J.	8103170532+ 8103050585+ 8103040298+ 8103090704+ 8103120680+	27-39 50-254	PARRIB.H G. PARRIB.H.G. PARBONT.M. PARBONT.M PARBONT.M.	8103020639 8103230498 8102260561* 8102260672* 8103050484*	50-438 50-390 FOLA FOLA FOLA
OLMSTEAD, W J OLSHAN, L. OLSON, L. M OLSON, L. K CLSON, A. H.	8103200050 8103050723 8103193296 8102260787* 8103040100	50-275 G 50-247 P 50-247 P FOIA NUREO	PAPERIELLO.C. J. PAPERIELLO.C J. PARCZEWSKI-K I. PARENT.C D PARIS.W. C.	8103110432* 8103259658* 8103310148* 8103250035 8103260737	40-2274 50-367 G 50-369 O PR 50-329 G	PARSON, C. H PARTLDW, J. O. PARTLOW, J. Q PARTLOW, J. Q FARTLOW, J. Q	8103200482 8103030986 8103060149 8103060366 8103100524	50-289 70-135 70-143 70-143 70-820
CLSON, A.W. OLSON, R.C. OLSON, R.C. OLSON, J. F. OLSZALSKI, M.	8103200357 8103130476 8103120454 8103110591 8103240492	NUREO 50-317 P 50-317 P PR PR	PARIS, O. H PARKER, W. O. PARKER, W. O PARKER, W. O. PARKER, W. O	8103190632 8103160510* 8103040087* 8103040078* 8103160498*	50-387 0 50-370 G 50-413 0 50-413 Q 50-370 G	PARTLOW, J. G PARTLOW, J. G PARTLOW, J. G PARTLOW, J. G PARTLOW, J. G	8103100391 8103181094 8103230118 8103270018 8103270839	70-143 70-125 70-25 70-734 70-8
ONCAVAGE, M P OPREA, O W CPREA, O W OPREA, G, W GPREA, O, W	8103030892 8103050829 8103041035 8103050004 8103041923	50-250 0 50-478 8 50-478 A 50-478 A 50-478 A	PARKER, W O PARKER, M. E PARKER, W O PARKER, W. O PARKER, W O	8103040057* 8103050403* 8103060770 8103160480* 8103170081*	50-413 0 50-155 0 50-369 8 50-370 0 50-369 0	PAGEDAO, W PAGEDAO, W. F PAGTERNAK, R. J. PAGTERNAK, R. J. PAGTERNAK, R. J.	8103270099* 8103270128* 8103050752* 8103230264* 8103100203	FOIA FOIA 50-333 50-333 50-333
OPREA.O.W OPREA.O.W OPREA.O.W OPREA.O.W. OPREA.O.W.	B103050837 B103050862 B103230122 B103060337 B103070380	50-478 B 50-478 B 50-498 Q 50-498 S 50-498 S	PARKER, H. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	8103030082 8103040044 8103120836* 8103030073 8103050419	50-269 0 50-413 0 50-269 0 50-413 0 50-369 0	PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J.	0103270815# 8103050311 8103110555 8103130383 8103160726	50-333 50-333 50-333 60-333 50-333
OPREA.O W. OPREA.O W. CPREA.O W OPREA.O W OPREA.O W	8103100410 8103200491 8103200799 8103300339 8103300307	50-49B 8 50-498 8 50-498 A 50-498 8 50-466 A	PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	8103180207+ 8103070304 8103070758 8103070474 8103070818	50-369 0 50-369 P 50-413 0 50-413 0	PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J. PASTERNAK, R. J.	8103160737 8103160743 8103170646 8103240441 8103240596	50-333 50-333 50-333 50-333 50-333

## PARTIAL N. J. 80201844   92-20 S   PRINCE D   PRINCE	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOCRY		ACCE8810N NUMBER	6UBU CATE
Pathway	PASTVA, M. J. PASTVA, M. J. PASTVA, M. J. PASTVA, M. J.	8103040693* 8103100620* 8103030748* 8103040647*	90-325 8 50-325 8 50-325 8	PERLMAN, J. PERLMAN, J. PERNY, C. D PERRIGO, L. D	8103270463 8103300444 8103240261 8103060215	* 50-320 * CONTRACT * 50-250 REB	P PIKE-D B PILANT-J, M PILANT-J, M PILANT-J, M PILANT-J, M	8103261051 8103110782+ 8103130132	50-29 50-29 50-29 50-29
## ABBIT N. J. GIOGLOSOPIE DE PETERDICA P. BIOGROSOPIE SO-280 U FILANT. J. BIOGLOSOPIE SO-280	PASTVA, M. J. PASTVA, M. J. PASTVA, M. J.	8103050934* 8103050574* 8103110486*	50-324 S 50-325 S 50-324 S	PERRY, W PERRY, P. A PERSON, R. T.	8103260370 8103160528 8103160703	50-348 50-155 50-267	Q PILANT, J M. I PILANT, J M PILANT, J M	B103050549 B103130375 B103050490	50-298 50-298 50-298
PAGINA, H. J.  102320703-  10-232	PASTVA, H. J.	8103160690+	50-325 8	PETERSEN, H E	8103040508	50-295	J PILANT, J. H	0103240147	50-296
	PASTVA, H. J.	8103170629+	50-325 8	PETERSON, D	8103130371*	50-255 R	R PILANT, J. H.	8103250120	50-298
	PASTVA, M. J.	8103180643+	50-324 8	PETERSON, H. Y.	8103240586*	50-289 T	PILAYT, J. H	8103240770	50-298
PASTALA II 0103700749 59-30 B PETROEC D BIOGROSSIA 0-313 O PLATE I 0103700749 116 FASTALA II 0103700749 59-32 B PETROEC D BIOGROSSIA 0-313 O PLATE II 0103700749 116 FASTALA II 0103700749 59-32 B PETROEC D BIOGROSSIA 0-313 O PLATE II 0103700749 116 FASTALA	PABIVA.H J.	8103230723*	50-325 B	PETRICK, N A	8103030770	50-492 A	PIPERD L	8103270692	50-269
	PABIVA.H J.	8103230705*	50-324 S	PETRICK, N A.	8103050549	50-482 A	PIPPENBD.	8103050945	PR
	PABIVA.H J.	8103240590*	50-325 B	PETRICK, N A	8103050642	50-482 A	PIRTLE, O. L.	8103240781*	50-263
PASTALLA J. 0103010641	PASTVA.H J.	8103270674+	50-324 B	PETTONE C D	8103200582*	50-213 Q	PLATO, P	8103040675	RES
	PASTVA.H J.	8103270757+	50-325 B	PETTENGILL H J	8103120602	40-3453	PLATO, P.	8103260351	11190
	PASTVA.H J.	8103300329+	50-324 B	PETTENGILL H J	8103120776	40-8452	PLATZKE, R. 14	8103040635	40-8581
PATON. 10 D	PASTVA.H J	8103310688#	50-324 S	PETTENOILL, H J	8103160231	40-1162	PLUMLEE, Q. L	8103180443+	90-267
	PATE,R. J	8103050061*	50-361 Q	PETTENOILL, H J	8103160443	40-3453	PLUMMER, A. M	8103020723	Nureo
	PATE,R.	8103180361*	90-206 Q	PETTENOILL, H J	8103190139	40-8584	PDCHAL, W. F	8103020114	Kpartli
PATIEON D. E. 8103200943 30-398 0 PEVEY. L. E. 9103090409 70-396 POINEERIER, T. C. 9103090499 30-297 POINEERIER, T. C. 91031002796, 30-297 POINEERIER, T. S. 9103100291, 30-	PATON W D.	8103270979	50-329 G	PETTENOILL, H J	8103181104	40-299	PODWAL 0 E	8103240545 (	50-289
	PATTERBON J P	8103050242*	70-925	PETTENOILL, H J	8103240373	40-3453	POGGIO A	8103226853 (	RES
	PATTERBON E B	8103130452*	50-289 G	PETTENOILL, H J	8103260953	40-8985	POGGIO A J	8103250243 (	NUREO
PAULEON. II A BIOGGOGOSO 50-153 P PHILLIPS. II P BIOGGOGOST 50-461 O POIL R. A. BIOGGOGOST 50-461 O POIL R. B. BIOGGOGOST 50-461 O POIL R. BIOGGOGOST 50-461 O POIL R. B. BIOGGOGOST 50-461 O POIL R. BIOGGOGOST 50-461 O POIL R. B. BIOGGOGOST 50-461 O	PATTIBON, Q E.	8103200543	50-358 Q	PEVEY-L E	8103030408	70-398	POINDEXTER.T.C	8103060786	50-320
	PAUL, R. A	8103100715#	80-409 Q	PFAFF-B J	8103180695	40-6659	POIRTER.M R	8103170627	50-445
	PAUL, R. A	8103190839#	40-3392	PFEFFERKORN-W	8103260393	50-488 0	POIRTER.M R	8103260817	50-445
PECHA C. C. C. 8103090489 50-182 0 PHILLIPS, J. 8103300689 50-289 H POD.E. D. S. 9103006816 N PEEBARS, T. 8103103905 50-389 H POD.E. D. S. 9103006816 N PEEBARS, T. 8103103905 50-381 S PLANKI, F. J. 8103303069 70-1100 PRITER, A V. 8103103094 50-481 S PLANKI, F. J. 8103303067 70-1100 PRITER, A V. 810320949 50-488 PLANKI, F. J. 8103203067 70-1100 PRITER, A V. 810320949 50-488 PLANKI, F. J. 8103203068 PODE, R. T. 8103200369 50-281 S PODE, R. T. 8103200369 50-281 S PODE, R. T. 8103200369 50-289 PODE, R. T. 810320369 50-289 PODE, R. T. 8103200369 50-289 PODE, R. 810	PAULBON, W. A	8103030550	50-155 P	PHILLIPS.M P.	8103120680*	50-461 0	POK.E.A.	8103200586 5	60-275
	PAULBON, W. A	8103180167	50-155 P	PHILLIPS.J.P.	8103090641	40-8102	POLK.P.J.	81030603134 5	50-409
	PAULBON, W. A	8103261006	50-217 P	PHILLIPS.T J	8103200493	50-275 H	POLK.H.E.	81033101484 5	50-369
PELTIER. I. A 8103110511 50-358 A PIERCE. R. 1010110830 RES POTAPOVS. U. 81031031167- 00499- PELTIER. I. 8103400455 50-358 A PIERWO. J. 8103030399 50-289 H POTAPOVS. U. 810310073- 00499- PELTIER. I. 81031003040 50-358 A PIERWO. J. 81030505040 50-358 A PI	PECKIC C.	8103090485*	50-182 0	PHILLIP8-J.H	8103300389	50-287 Н	POOLE, D. C.	8103060810 5	0-302
	PEDRAYESIH. J	8103050815	PR	PIANKI-F.J.	8103310690	70-1100	PORTER, A. V.	8103190392+ P	R
	PEEBLESIT.	8103030854	50-491 8	PIANKI-F.J.	8103300017	70-1100	PORTER, W. L.	8103200549 5	0-488
PELTOP. PENCE. M. B BIO3260732 MUREO PIGOTT. D. R. BIO3260734 SO-317 B PIGOTT. D. R. BIO3260734 SO-327 B PIGOTT. D. R. BIO3260734 SO-327 B PIGOTT. D. R. BIO3260734 SO-327 B PIGOTT. D. R. BIO3260734 SO-328 B PIGOTT. D. R. BIO33000774 SO-328 B PIGOTT. D. R. BIO3000774 SO-328 B PI	PELTIER, 1 A	8103110511	50-358 A	PIERCE, R. L.	810311083D	RES	POTAPOVA, U.	8103031147* 0	4999
	PELTIER, 1	8103040465	50-358 A	PIERNO, J.	8103300389	50-289 H	POTAPOVA, U.	8103120777 0	4999
	PELTIER, 1. A	8103039640	50-358 A	PIERRO, M. A	8103261139*	50-57 P	POTAPOVA, U.	8103040254+ 0	4999
PENDICK, B. B103290479 PR PLODIT, D. R. B1030903498 50-361 0 POTAPOVS, U. B103110005 8A-99 PEOPLES, D. L. B101203493 50-10 F PIDDIT, D. R. B1030905598 50-361 0 POTAPOVS, U. B1031000134 0A999 PEOPLES, D. L. B103100700 0A999 PIDDIT, D. R. B10305050598 50-361 0 POTAPOVS, U. B103110011 0A999 PERLANA, J. B1031007012 CONTRACT PIDDIT, D. R. B1030505768 50-361 0 POTAPOVS, U. B103110011 0A999 PERLANA, J. B103190893 CONTRACT PIDDIT, D. R. B1030505768 50-361 0 POTAPOVS, U. B1031007279 0A999 PERLANA, J. B1031908918 CONTRACT PIDDIT, D. R. B1030505768 50-361 0 POTAPOVS, U. B1031007279 0A999 PERLANA, J. B1031908918 CONTRACT PIDDIT, D. R. B1030505768 50-361 0 POTAPOVS, U. B1031007279 0A999 PERLANA, J. B103040609 CONTRACT PIDDIT, D. R. B1030505768 50-361 0 POTAPOVS, U. B103100809 0A999 PERLANA, J. B10305050168 50-361 0 POTAPOVS, U. B103100809 0A999 PERLANA, J. B1030505168 50-361 0 POTAPOVS, U. B10310880 0A999 PERLANA, J. B1030505168 50-361 0 POTAPOVS, U. B10310880 0A999 PERLANA, J. B1030505168 50-361 0 POTAPOVS, U. B10310880 0A999 PERLANA, J. B103103880 CONTRACT PIDDIT, D. R. B1030505568 50-361 0 POTAPOVS, U. B10310689 0A999 PERLANA, J. B1031007628 CONTRACT PIDDIT, D. R. B1030505568 50-361 0 POTAPOVS, U. B10310689 0A999 PERLANA, J. B1031007628 CONTRACT PIDDIT, D. R. B1030505718 50-361 0 POTAPOVS, U. B10310930 0A999 PERLANA, J. B1031007628 CONTRACT PIDDIT, D. R. B1030505718 50-361 0 POTAPOVS, U. B103100730 0A999 PERLANA, J. B1031007628 CONTRACT PIDDIT, D. R. B1030505518 50-361 0 POTAPOVS, U. B103100750 0A999 PERLANA, J. B1031900728 CONTRACT PIDDIT, D. R. B103200664 50-361 0 POTAPOVS, U. B103100718 0A999 PERLANA, J. B1031900728 CONTRACT PIDDIT, D. R. B103200664 50-361 0 POTAPOVS, U. B103100718 0A999 PERLANA, J. B1031900728 CONTRACT PIDDIT, D. R. B103200666 50-361 0 POTAPOVS, U. B103100718 0A999 PERLANA, J. B1031900728 CONTRACT PIDDIT, D. R. B103200666 50-361 0 POTAPOVS, U. B103100718 0A999 PERLANA, J. B1031900728 CONTRACT PIDDIT, D. R. B103200666 50-361 0 POTAPOVS, U. B103100788 50-3269 PERLANA, J. B103190168 CONTRACT PIDDIT, D.	PELTO: P.	8103020723	NUREO	PIGOTT, D. R.	8103050560#	50-361 0	POTAPOVS.U	8103160595+ 0:	A999
	PENCE: N. B	8103240934*	50-317 8	PIGOTT, D. R.	8103050565#	50-361 0	POTAPOVS.U	8103190003+ 0:	A999
	PENDERGRAFT: R	8103100513*	50-368 8	PIGOTT, D. R.	8103050571#	50-361 0	POTAPOVS.U	8103100747 0:	A999
PERLMAN, J. B1031908B3 CONTRACT P100TT, D.R. B103050576+ 50-361 Q P0TAPDVS, U. B10310727+ QA999 PERLMAN, J. B103190891+ CONTRACT P100TT, D.R. B10309088+ 50-361 Q P0TAPDVS, U. B10310809 QA999 PERLMAN, J. B103040860+ CONTRACT P100TT, D.R. B10309058+ 50-361 Q P0TAPDVS, U. B10310809 QA999 PERLMAN, J. B10305101+ CONTRACT P100TT, D.R. B10305058+ 50-361 Q P0TAPDVS, U. B10310809 QA999 PERLMAN, J. B103050131+ CONTRACT P100TT, D.R. B10305058+ 50-361 Q P0TAPDVS, U. B10310809 QA999 PERLMAN, J. B10310839+ CONTRACT P100TT, D.R. B10305058+ 50-361 Q P0TAPDVS, U. B10310839 QA999 PERLMAN, J. B103100762+ CONTRACT P100TT, D.R. B10305057+ 50-361 Q P0TAPDVS, U. B103109309 QA999 PERLMAN, J. B103100762+ CONTRACT P100TT, D.R. B10305057+ 50-361 Q P0TAPDVS, U. B103100763+ QA999 PERLMAN, J. B103100762+ CONTRACT P100TT, D.R. B10305057+ 50-361 Q P0TAPDVS, U. B103160380 QA999 PERLMAN, J. B103100762+ CONTRACT P100TT, D.R. B10305057+ 50-361 Q P0TAPDVS, U. B103160380 QA999 PERLMAN, J. B10319008+ CONTRACT P100TT, D.R. B10305057+ 50-361 Q P0TAPDVS, U. B103160380 QA999 PERLMAN, J. B10319008+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TAPDVS, U. B10319007+ QA999 PERLMAN, J. B103190052+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TAPDVS, U. B10319007+ QA999 PERLMAN, J. B103190072+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TAPDVS, U. B10319017+ QA999 PERLMAN, J. B103190072+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TAPDVS, U. B103190072+ QONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TAPDVS, U. B10319039+ 50-329 PERLMAN, J. B103190167+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TTER, J.P. B10327082+ S0-332 PERLMAN, J. B103190168+ CONTRACT P100TT, D.R. B10320064+ 50-361 Q P0TTER, J.P. B10327082+ S0-329 PERLMAN, J. B103190168+ CONTRACT P100TT, D.R. B10320064+ S0-361 Q P0TLM, R. M B10319059+ S0-329 PERLMAN, J. B10321068+ CONTRACT P100TT, D.R. B10320064+ S0-361 Q P0TLM, R. M B103100774+ S0-324 PERLMAN, J. B10323058+ CONTRACT P100TT, D.R. B103240736 S0-361 Q P0TLM, R. M B10324068+ S0-329 P0TLM, R. M B1032200573+ S0-329 P0TLMAN, J. B103220573+ S0-329 P0	PENHOCK, B.	8103250478	PR	PIGOTT, D. R.	B103050548*	50-361 0	POTAPOVS, U	8103110005 0/	4999
	PEOPLES, D. L.	8101230543±	50-10 F	PIGOTT, D. R.	B103050555*	50-361 0	POTAPOVS, U	8103120388 0/	4999
	PEOPLES, D. L	8101220258±	50-10 F	PIGOTT, D. R	B103050560*	50-361 0	POTAPOVS, U	8103040134 0/	4999
PERLHAN, J. B10310838 CONTRACT PLOTT, D.R. B103090565 0 POTAPOVS, U. B10310838 0A999 PERLHAN, J. B103100762* CONTRACT PLOTT, D.R. B103090576* 50-361 0 POTAPOVS, U. B103100380 0A999 PERLHAN, J. B103100328 CONTRACT PLOTT, D.R. B103090576* 50-361 0 POTAPOVS, U. B103100380 0A999 PERLHAN, J. B103100328 CONTRACT PLOTT, D.R. B103200658 50-361 0 POTAPOVS, U. B10310055 0A999 PERLHAN, J. B103190052 CONTRACT PLOTT, D.R. B10320064 50-361 0 POTAPOVS, U. B103100718 0A999 PERLHAN, J. B103190072* CONTRACT PLOTT, D.R. B103200664 50-361 0 POTAPOVS, U. B103100718 0A999 PERLHAN, J. B103190072* CONTRACT PLOTT, D.R. B103200664 50-361 0 POTAPOVS, U. B103100718 0A999 PERLHAN, J. R. B103190072* CONTRACT PLOTT, D.R. B103200664 50-361 0 POTTER, J.P. B10320082* 30-333 PERLHAN, J. K. B103190279* CONTRACT PLOTT, D.R. B103200664 50-361 0 POTTER, J.P. B10320082* 27-47 PERLHAN, J. K. B103190167* CONTRACT PLOTT, D.R. B103200664 50-361 0 POTTER, J.P. B103230629* 50-289 PERLHAN, J. K. B103190156* CONTRACT PLOTT, D.R. B103200696 50-361 0 POTTER, J.P. B103230629* 50-289 PERLHAN, J. K. B103190156* CONTRACT PLOTT, D.R. B103200696 50-361 0 POULK-R. M. B103100774* 50-324 PERLHAN, J. K. B103200689* CONTRACT PLOTT, D.R. B103260736* 50-361 0 POULK-R. M. B103100774* 50-324 PERLHAN, J. B103230689* CONTRACT PLOTT, D.R. B103260736* 50-361 0 POULK-R. M. B103100774* 50-325 PERLHAN, J. B103230589* CONTRACT PLOTT, D.R. B103260764* 50-361 0 POULK-R. M. B103100598* 50-325 PERLHAN, J. B103230589* CONTRACT PLOTT, D.R. B103260764* 50-361 0 POULK-R. M. B103100598* 50-325 PERLHAN, J. B103230573** CONTRACT PLOTT, D.R. B103260764* 50-361 0 POULK-R. M. B103100598* 50-325 PERLHAN, J. B103230573** CONTRACT PLOTT, D.R. B103260754* 50-361 0 POULK-R. M. B1032300573** S0-325 PERLHAN, J. B103230573** CONTRACT PLOTT, D.R. B103260754* S0-325 PERLHAN, J. B103230573** CONTRACT PLOTT, D.R. B10	PERLMAN, J.	8103190893	CONTRACT	PIGOTT, D. R	8103050576*	50-361 0	POTAPOVS, U.	8103100727+ 0/	4999
	PERLMAN, J.	8103190891#	CONTRACT	PIGOTT, D. R.	8103050581*	50-361 0	POTAPOVS, V	8103040189 0/	4999
	PERLMAN, J.	8103040860#	CONTRACT	PIGOTT, D. R	8103059548*	50-361 0	POTAPOVS, U.	8103120599 0/	4999
PERLMAN, J. B103190093 CONTRACT P100TT. D. R. B103200696 50-361 0 P0TER, J P. B103100718 GA999 PERLMAN, J. B1031900729 CONTRACT P100TT. D. R. B103200696 50-361 0 P0TER, J P. B1032708329 50-393 PERLMAN, J. K. B1031901679 CONTRACT P100TT. D. R. B103200696 50-361 0 P0TER, J P. B1032306249 27-47 PERLMAN, J. K. B1031901679 CONTRACT P100TT. D. R. B103200644 50-361 0 P0TTER, J P. B1032306249 50-289 PERLMAN, J. K. B103190189 CONTRACT P100TT. D. R. B103200696 50-361 0 P0TTER, M. B103100389 50-289 PERLMAN, J. K. B103190189 CONTRACT P100TT. D. R. B103200769 50-361 0 P0TTER, M. B1031005774 50-324 PERLMAN, J. B1032310889 CONTRACT P100TT. D. R. B103260756 50-361 0 P0ULK-R. M. B1031057744 50-324 PERLMAN, J. B1032310889 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B1031057744 50-324 PERLMAN, J. B1032305739 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B10310589 50-329 PERLMAN, J. B1032305739 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B103100589 50-329 PERLMAN, J. B1032305739 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B1032404659 50-329 PERLMAN, J. B1032305739 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B1032404659 50-329 PERLMAN, J. B1032305739 CONTRACT P100TT, D. R. B103260756 50-361 0 P0ULK-R. M. B1032404659 50-329	PERLHAN, J.	8103310838*	CONTRACT	PIGOTT, D. R.	8103050545*	50-361 0	POTAPOVS, U.	8103310889 0/	4999
	PERLHAN, J.	8103050199*	CONTRACT	PIGOTT, D. R.	8103050571*	50-361 0	POTAPOVS, U.	8103310933 0/	4999
	PERLHAN, J.	8103100762*	CONTRACT	PIGOTT, D. R	8103050576*	50-361 0	POTAPOVS, U.	8103140580 0/	4 <b>9</b> 99
PERLMAN, J. K. B103190156* CONTRACT PIGOTT, D. R. B103260756 50-361 0 POULK, R. M. B103160774* 50-324  PERLMAN, J. B103231088* CONTRACT PIGOTT, D. R. B103260761* 50-361 0 POULK, R. M. B103170652* 50-325  PERLMAN, J. B103250573* CONTRACT PIGOTT, D. R. B103260761* 50-361 0 POULK, R. M. B103240465* 50-325	PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J. K. PERLMAN, J. K	8103170053 8103170072* 8103170279*	CONTRACT CONTRACT CONTRACT	PIGOTT, D. R. PIGOTT, D. R. PIGOTT, D. R.	8103200696 8103200664 8103200696	50-361 0 50-361 0 50-361 0	POTAPGVS,U. POTTER,J P. POTTER,J P.	9103100718 ga 9103270932* 50 9103250624* 27	1999 3-333 7-47
	PERLMAN, J. K. PERLMAN, J. K. PERLMAN, J. PERLMAN, J. PERLMAN, J.	8103170156* 8103231058* 8103250573*	CONTRACT CONTRACT CONTRACT	PIGOTT, D.R. Pigott, D.R. Pigott, D.R	8103260796 8103260761* 8103260756	50-361 0 50-361 0 50-361 0	POULK: R. M POULK: R. M POULK: R. M	8103160774* 50 8103170652* 50 8103240465* 50	0-324 0-325 0-325

RGHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHER	ACCESSIGN NUMBER	GUBUECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
POWELL, T E POWELL, D C POWERS, T POYSER, R W PRATICO 15	8102033639* 3103060705 6103310573* 8103310650 8103090393	50-382 ( PR 50-346 5 40-2259 PR	REHM. I A REHM. I A REHM. I A REHM. I A REYM I A	8103126839* 8103050776 8103050785 8103150693 8103170016	FOIA COMMISSION COMMISSION COMMISSION COMMISSION	REYES.L REYNOLDS.S D REYNOLDS.A REYNOLDS.J R REYNOLDS.J R	8103190517 8103180098* 8103170598 8103050594 8103050564	50-346 8 50-271 0 50-269 H 50-275 0
PRATTLU T PRATTLO H PRATTLO M PRELESTIKLIL PRESSESKYLA J	8103130177* 8103030733* 8163640483 8163250926 8103066820	50-369 P 50-3 P 50-247 G PR PR	REHM, 1 A REICH, F R REID, A 2 REID, R H REID, R H	9103840745 8103020782 8103170173 8103050151 8103040032	CCMMISBICN NUREO FOIA 50-269 P 50-313 P	REYNOLDS, J R. REYNOLDS, J R. REYNOLDS, S D. REYNOLDS, J R. REYNOLDS, M 6	8103050594 8103050564 8103300528* 8103030557 8103050656	50-275 0 50-275 0 50-354 0 50-275 0 50-445 0
PRICELE R PRICELE R PRICELE R PRICELE R PRICELE R	8103260724+ 8103260722+ 8103260719+ 8103260709+ 8103260698+	4D-1947 40-1947 40-1947 40-1947 40-1947	REID.R W REID.R W REID.R W REID.R W REID.R W	8103050725 8103030393 8103030899* 8103030923* 8103030576	50-289 P 50-269 P 50-269 P 50-269 P 50-30 P	REYNOLDS, N 8 REYNOLDS, N 8 REYNOLDS, N 8 REYNOLDS, N 9 REYNOLDS, U REYNOLDS, J R	8103050648 8103050656 8103050668 8103300042 8103130559	50-445 0 50-445 0 50-445 C PR 50-275 0
PRICE.E R PRICE.H L PRICE.E PRICE.A S PRICEI.N	8103260672+ 8103170212+ 8103250612 8103100352 9103110124+	40-1947 Fola <i>PR</i> PR 50-271 H	REID.R W REID.R W REID.R W REID.R W REID.R W	8103040428 8103100642 8103041015 8103040129 8103050566	50-289 0 50-289 P 50-346 P 50-312 F 50-312 F	REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, N S	B103120560 B103120560 B103120560 B103120574* B103190565	50-275 0 50-275 0 50-275 0 50-275 0 50-445 0
PRIME.W J PRINCE C PRINCLE.W W PRITCHETT.T II PROJEW E	8103040890+ 8103290585 8102190636 8103050197+ 8103020624	CONTRACT 50-275 H 50-369 A 50-317 F MCREO	REID.R W REID.R W REID.R W REID.R W	8103090018 8103060308 8103090699 0103120332 6103110784	50~269 P 50~302 P 50~269 P 50~312 P 50~269 P	REYNOLDS, N S REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R	8103190565 8103269790 8103260720 8103260720 8103260750	90-445 0 50-275 0 50-275 0 50-275 0 50-275 0
PRYPUTNIEU(CI PUCKETT.J K PURCELL.J F PURCHIT.S GUAN.E	8103050793 8103130716* 8103030823 8103260587* 8103110794*	PR 50-280 Q 50-367 R 50-247 E 50-361 I	REID, R W REID, R W REID, R W REID, R W REID, R W	8103120465 8103120468 8103120493* 8103120496* 8103110176	50~287 P 50~302 P 50~302 P 50~302 P 50~302 P	REYNOLDS, J R REYNOLDS, N S REYNOLDS, N, S RHSE, S J RHOADS, O O	8103240544 8103270536 8103270536 8103240450# 8103060505#	50-275 G 50-445 Q 50-445 Q 50-249 8 50-367 Q
GUICK. D GUICK. D GUICK. D GUICK. D GUICK. D R	8103100053+ 6103270094+ 8103130678+ 8103130217+ 8103190317+	50-259 0 50-321 0 50-395 0 50-251 0 50-395 0	RE1D.R W RE1D.R W RE1D.R W RE1D.R W RE1D.R W	8103120862 8103120227 8103120276 8103110781 8103120502	50-269 P 50-269 P 50-269 P 50-302 P 90-321 P	RHDDE. 0 K RHDDE. 0 K RHDDE. 0 K RHDDE. 0 K	8103200647 8103250270 8103270604* 8103300232 8103300273	50-410 8 50-410 8 CONTRACT 50-410 A 50-410 A
901CK-D-R J1CF-D J1GG-C J1GG-C J1L1C1-V	8103200038• 8103240402 8102020293 6103270721 8103200498	50-261 0 50-327 8 PR 50-295 C 50-275 H	REID.R W REID.R W REID.R W REID.R W	8103120505* 8103120508* 8103120789 8103120828 8103160202	50-321 P 50-321 P 50-269 P 50-312 P 50-375 P	RICE.W M RICHARDS.P RICHARDSON.J R RICHARDSON.H D RICHLEY.E A	81030402124 8103120614 8103070577 8103160224+ 8103030663	GA999 PR PR Contract 50-30 R
JINGELLATIL ABYLT M VACSTERLO E RACSTERLO E RACERLA M	B103120805 B103130533 B103160311 B103240664 B103200707	PR 50~184 C 7(-403 7[-403 27~39	REID.R W REID.R W REID.R W REID.R W REID.H W	8103120261 8103129643 8103179390 8103160248 8103120811	50-269 P 50-269 F 50-302 P 50-289 P 50-302 F	RICHLEY.E A RICHTER T T RIDOWAY.K R RIDOWAY.K R RIDOWAY.K R	8103030692 8103190483 8103030425* 8103070105* 8103181123*	50-185 R 50-289 H 50-151 Q 50-264 Q 50-2 Q
RACER.R M RACER.R M RACER.R M RACER.M S RACER.M S	8103270502 8103270597 8103270599 8103053578+ 8103170480*	27-39 27-39 27-39 50-331 8 50-331 8	RETD.R W RETD.R W RETD.R W RETD.R W RETD.R W	8103140581 8103140589 8103160589 8103160581	50-289 P 50-321 P 50-277 P 50-366 P 50-366 P	RIEL O L. RIEBLAND, J. 1 RIGO, W A RILEY.R C RILEY.R W.	8103200646* 8103120439 8103190373 8103190400 8103290736	50-443 ¢ 50-255 8 50-267 H 50-269 H PR
RAGER, M. S. RAGER, M. S. RAHL, R. G. RAMAND, A. J. RANDAZZO, A. F.	8103170504+ 8103310679+ 8103100087 8103110819 8103060179+	50-331 S 50-331 B NUREO NUREO CONTRACT	REID.R W REID.R W REID.R W REID.R W REID.R W	8103170242* 8103200085 8103180138 8103180152* 8103180837	50-366 P 50-111 W 50-313 P 50-313 P 50-313 P	RIMER, A RISCHLING, J L RISCHLING, J RISC, R R. RISC, R R	B103170431 B103100369* B103100966* B103260526* B103260519*	MIBC 50-316 8 90-316 8 FOIA FOIA
RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B	810316044B 8103030639 8103100609 8103200403 8103200120	50-309 P 50-309 P 50-309 F 50-309 P 50-309 F	REID.R W REIFF.D D REILLY.M A REIMAIN.F REIMANN.F W	B103180B53* B103160127* B103050709 B103040474 B103031014	50-313 P 50-339 P 50-289 T 50-265 S 50-304 S	RIBD.R.R RIBO.R R RIBO.R R RITCH.J RIVELLO.J	8103260417* 8103260403* 8103260397* 8103310846 8103180916	FOIA FOIA FOIA XPORTLIC REGOD
RANDAZZA, J. B. RANDAZZA, J. B. RANDOLPH, M. L. RANDOLPH, J. B. RAPATH, A.	8103230763 8103240382 8103160684 8103310200* 8103050631	50-307 V 90-307 P RES 50-307 Q 50-367 O	REIMANN, F REIMANN, F REIMANN, F REIMANN, F REIMANN, F	8103031073 8103030942 8103030418 8103030997 8103040298•	50-304 8 50-237 8 50-249 8 50-304 8 50-373 0	RTZZO, P. O. RTZZO, P. O. RTZZO, P. O. ROBERTS, E. W. ROSERTSUN, F.	0103060545* 8103110487* 8103260893* 8103160124* 8103120751	50-318 8 50-317 8 50-317 8 50-195 P
RAUSCH T J RAUSCH W N RAUSCH T J RAUSCH T J RAUSCH T J	8103260137* 8103310924 8103020668 8103260044 8103260284	50-10 F NUREO 50-454 0 50-237 0 50-237 0	REIMANN, F W REIMANN, F W REIMANN, F W REIMANN, F REIMANN, F	8103139245* 8103300155* 8103170369 8103240387 8103240419*	50-10 0 50-373 0 50-254 B 50-10 B 50-312 F	ROBERDS, H. W. ROBERTS, D. D. ROBINSON, R. K. RODINSON, D. L. ROBLEE, P. D.	8103190005# 8103200534 8103310697 8103300155# 8103180030#	9A999 50-289 H 50-564 A 50-373 3 40-8040
RAUSCH.T J RAVINDRA.M K RAWY.L RAYBURM.C L RAYMUND.W J	8103241511 8103240511 8103050977 8103260645* 8103190879*	50-10 0 NJRE0 PR 50-318 8 50-271 0	REIMER.E T REIMHARD.X REIS.H F. REIS.H F REISINGER.D C	8101220599* 8103190514 8103230701 8103230701 8103120809	50-317 F 50-289 H 50-250 Q 50-250 Q	ROBLEE, P D ROCKHOLD, H C ROCKHOLD, H C RODRIQUEZ, R J RODRIQUEZ, R J	8103180024* 8103100104 8103170136 8103040637 8103170647	40-8040 50-275 P 50-272 P 50-312 B 50-312 R
RAYMOND. W J REA.R H REBELOWSKI.T RECKLEY. W. REDHOND.R F	8103050298+ 8103090136+ 8103230407+ 8103240233 8103199628+	SO-29 G CONTRACT SO-247 G PR CONTRACT	REITER.L. REMICK.F J RENNELS.A E RENZO.A F RENZO.A F	8103170323* 8103200803* 8103250066 8103100731* 8103100731*	50-443 0 50-275 P 40-2061 Waste Mot Waste Mot	RODRIGUEZ,R J. ROECKLEIN,A ROGAN,R E ROGEN,M ROGERS,L H	8103310603 8103270031 8103240545 8103120800 8103260757*	50-312 8 CONTRACT 50-289 0 PR 40-1947
REED.C REED.C REED.J REED.J G REHGGCW,C R	81031300894 8103110390* 8103050182* 8103190613 8103170492	50-454 Q 50-373 Q COMTRACT 50-483 Q 50-275 H	REQUA.O RESETAR.JO RESERR.E.P REYES.L A REYES.L A	8103041013 8103109510* 8103260715* 8103040315 8103170362	50-309 P 50-336 8 40-1947 50-346 B 50-346 8	ROGERS, L. R. ROGERS, L. R ROGERS, W. J ROGERS, R. F ROGERS, R. F.	B103260740* B103260733* B103160953* B103160107* B103240312*	40-1947 40-1947 50-346 0 50-321 0 50-321 0

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHGR	ACCESSION NUMBER	SL BUECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBU. SATE
903ERS.R.C. 903ERS.D.H 903ERS.W.H 803ERS.W.H. 803ERS.U.L.	8103180768 8103200474 8103130460* 8103130464* 8103170586*	50-289 H 50-275 H 50-366 B 50-321 B 50-338 R	ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, M. A	8103110661 8103120786 8103110107 6103230530 8102260764*	70-364 70-754 70-1308 50-201 H FOIA	SCARAND, R. A SCARAND, R. A SCARAND, R. A SCARAND, R. A SCARAND, R. A	8103140453 8103120031 8103170113 8103170120 8103181100	WASTE WASTE 40-87- 40-841 40-341
ROGERS R F.	8103240848*	50-321 0	ROWE.C	8103180324*	40~8702	SCARANO, R A	8103181112	40-299
ROGERS, P	8103170492*	50-368 8	ROWE.B	8103180270	71-5942	SCARANO, R A	8103181118	40-871
ROGUE, F	8103040100	NUREO	ROWBOME.F H	8103180248*	100fr	SCARANO, R A	8103270744	40-856
ROGUE, F	8103200397	NUREO	ROY.Q W	8103260354*	40-1947	SCARANO, R A	8103270748	WASTE
ROHRDANZ, R. R	8103040675	REB	RUBIN.M P	8103170646*	50-289 0	SCHAUB, J B	8103051010	FPORTL
PCHER.P S.	8103031071	RES	RUBID: A RUNKLE: Q E RUCCCHID: J P RUGFF: J: C RUSCAVDER: M E	8103250595	PR	SCHAUS.J 8	6103CA3032	XPORTL
PCHER.P S.	8103140084	RES		8103250261	NUREO	SCHAUFLER.A E	8103240545	50-287
PGMAND.A.J.	8103040579	I.UREO		8103050530	CONTRACT	SCHEIN.C W	6103190410	50-287
PGMAN.T.W	8103240520	50-220 8		8103300179	50-375 G	SCHELL.M J	8103110836	RES
POMAND.F.R	8103250243	50-289 0		8103173398	50-267 H	SCHENSEL.X R	8103120036	40-858
80чеяр. L V	8103160255	90-275 H	RUSCHE, B. C	B103040716#	FDIA	SCHENDEL:K R	810314 <i>02</i> 67	40-850
80эр, н	8103050268	50-361 A	RUSCHE, B. C	B103180091	SECY	SCHENDEL:K R	8103120042*	40-858
80ор, н	8103050644	50-361 A	RUSSELL, K	B103160496	PR	SCHENDEL:K R	8103250542	PR
80эр, н	8103120750	90-361 A	RUSSELL, O	B103290090	PR	SCHERER:A E	8103060791	PR
80ор, н	8103170738	50-361 F	RUSSELL, J. E	B103060083	40-6622	SCHERPER:Z:R [	8103020775	NUREO
H.GOCR	8103170766	90-361 A	RUSSELL.I. B	8103040694	50-317	SCHERER.A E	8103030218	PR
H.GOCR	8103170760	50-361 A	RUSSELL.L B	8103060538		SCHERER.A E	6103260738	PR
H.GOCR	8103310915	50-361 0	RUSSELL.L S	8103116480		SCHERER.A E	8103076621	50-470
A.M.VENGCR	8103190409	70-1309	RUSSELL.L S	8103269603		SCHERER.A E	8103110677	NUREO
A.M.VENGCR	8103200015	70-1308	RUSSELL.L B	8103269882		SCHERER.A E	6103170458	50-470
RCONEY, H. A	8103200020	70-1308	RUSSELL.L B	8103240635	50-318 8	SCHERER, A E	6103269639	1GPREP
PCONEY, H. A	8103200025	70-1308	RUSSELL.L B	8103240924	50-317 8	SCHERER, A E	8103300380	50-470
PCONEY, M. A	8103200037	70-1308	RUTBERO.J	8103240025	50-315 0	SCHLEIGER, T E.	8103060291*	50-267
RCONEY, M. A	8103190409	70-1308	RUTHERFORD.J F	8103050878	FOIA	SCHLIEF, O	8103190407*	50-320
PGCNEY, M. A	8103200015	70-1308	RUTHERFORD.J F	8103261065	FOIA	SCHMERLING, J H	8103690246	1GPREP
RODNEY, M. A RODNEY, M. A RODNEY, M. A RODNEY, V. L. ROOY, L. D	8103200020 8103200025 8103200037 8103310619 8101230527*	70-1308 70-1309 70-1308 50-271 F 50-331 F	RYAN, R RYAN, M T RYAN, R SABO, A T. SABO, A T.	8103160040* 8103031092 8103030894* 8103310653 8103196862	50-275 G RES 50-275 G 70-698 71-6403	SCHMIDT. A D SCHMIDT. E. II SCHMIDT. A. D SCHMIDT. A D SCHMIDT. A D	8103160731 8103060197 8103130361 8103130585 9103160753	50~250 RES 50~335 50~335
ROOT, L. D	8103130041	REGOD	BADWITH.L	8103050479	FOTA	BCHMIDT, H.C. BCHMIDT, A.D. BCHMIDT, A.D. BCHMIDT, A.D. BCMNAUTT, C.E. BCHNEIDER, F. W.	8103090567	50-449
ROOT, L. D	8103030845	50-331 P	BAHA.P.	8103240097	RES		8193160712	50-335
ROOT, L. D.	8103040197	50-331 P	BAHA.P	8103310898	RES		8103130359	50-250
ROOT, L. D	8103270791*	50-331 G	BAIKI.T	8102280260	XPORTLIC		8103040876	(PORTL)
ROOT, L. D	8103050280	50-331 F	GAIKI.T	8103050798	XPORTLIC		8103190903*	50-272
POOTAL D POOTAL E POOTAL D FOREMABLE	8103250124 8103261103* 8103240216 8103310402 8103130574	50-331 0 CONTRACT 50-331 F 30-331 Q 70-1308	SAKAKTIS SAKENABIC A SAKENABIC SALTZMANIJ BI SALTZMANIJ.	8103050469 8103110546* 8103250448* 8103060739 8103120165	50-36! D 50-387 Q 50-450 Q 50-370 J 50-528 A	SCHNEIDER, F. W. SCHNEIDER, F. W. SCHNEIDER, F. W. SCHNEIDER, F. W. SCHNEIDER, F. W.	8103230401 8103060464 8103960471 8102270094 8103240560	50-272 50-272 50-272 50-139 50-272
ROREM B L	8103130591	70-1308	SANCIC.D	8103230558*	50-333	SCHNEIDER, F. W.	8103030009*	50-272
ROSEN R. H	8103050092*	FDIA	BANDERS.W.F	8103180678*		SCHNEIDER, F. W.	8103110379	50-272
ROSENBAUM, D. H	8103090003	Waste Hot	SANDQUIST.O H	8101070345*		SCHNEIDER, F. W.	8103160468	50-272
ROSENBERO, A.	8103230444*	90-352 H	GANGER.H 8	8103110505		SCHNEIDER, F. W.	8103250424	50-272
ROSENTIMAL, A. B.	6103270938*	90-338 U	SANGER.H S	8103260121		SCHNEIDER, F. W.	8103160525*	50-272
ROSENTHAL, A S	8103090514	50-443 0	BARBOUR. B.	8103130397*	50-346 R	SCHNEIDER F U.	8103180537	50-272
ROSENTHAL, A S	8103230477	50-443 0	BASSANI.A	8103190879*	50-271 Q	SCHOR, L	8103090330*	50-29
ROSENTHAL, W P	8103240314*	50-206 P	GASBANI.A D	8103180214*	50-289 O	SCHOR, L	8103310231*	50-29
ROSER, T	8103240143*	COMMISSION	BASSANI.A D	8103190297*	50-289 G	SCHRADER	8103261214	REG30
ROSS, D F	8101230369*	10CFR	BASTRE.C	8103190813	REB	BCHRADER, D.	8103110342	50-367
R058-D H	8103190806	71-5560	BASTRE.C.	8103310884	RE8	SCHRADER: D	8103170550	50-269
R058-D F	8103040978	NUREQ	BAUER.A K.	8103190519	50-289 H	BCHRADER: D	8103250044	PR
R058-D F	8103130160*	50-369 P	BAUNDERS.T	8103100950	50-583 A	SCHROCK: V. E.	8103180768*	REVIEH
R058-D F	8103200114*	50-289 I	BAUNDERS.G.A	8103130457	40-8693	SCHROEDER: M. E	8103170500	50-275
R058-D F	8103200115*	50-289 I	BAUNDERS.G.A.	8103310604	40-8493	BCHROCK: C. A	8103100543#	50-305
ROTELLA, T B. ROTH, J. POTH, L. K ROTHE, P. H ROTHFLEIBCH, J	8103190179# 8103310845# 8102270538# 8103250458 8103120236#	90-339 P 70-364 PR NUREO FOIA	SAVAGE, J. W. SAVAGE, J. W. SAXON, H. J. SCAMMELL, R SCARANO, R. A.	8103040100 8103200357 8103190465 8103120248* 8103120227*	NUREO SO-289 H CONTRACT FOIA	SCHULTZ.D M SCHULLER.C R SCHULTZ.W H SCHULZ.R D SCHULMAN.H J	8103270827 8103240237 8103031007 8103170278* 8103200538	70-820 NUREO 1%E 50-255 50-220
ROTHSCHILD, H U	8103040405	50-445	SCARAND, R. A	8012310217+	HASTE MOT	SCHULTZ, G.A	8103110463	50-387
ROTHSCHILD, H U	8103060391		SCARAND, R. A	8103060169	HASTE MOT	SCHULTZ, G.R	8103260735	50-387
ROTHSCHILD, H U	8103110316		SCARAND, R. A	8103050435	WASTE MOT	SCHU:'ACHER, M.C	8103040796*	FOIA
ROTHSCHILD, M U	8103120305		SCARAND, R. A	8103060410	WASTE MOT	SCHUR, B. H	8103170491*	MISC
ROTHSCHILD, M U	8103120317		SCARAND, R. A.	8103160207	40-6659	SCHUSTER: M	8103100432	50-205
ROTHSCHILD, M U.	8103160384	50-445 0	SCARAND, R. A	8103190706*	HASTE MOT	SCHWARTZAM W	8103040511	HUREO
	8103180072	50-445 0	BCARAND, R. A.	8103190683	HASTE MOT	SCHWARTZAJ.	8103203546	50~269
	8103180614	70-1308	SCARAND, R. A	8103090748	40-8498	SCHWAN.C	8103100406	50~204
	8103180634	70-1308	BCARAND, R. A.	8103060244	40-8722	SCHWAN.C	8103100452	50~206
	8103230090	70-1308	BCARAND, R. A.	8103160412	40-8200	SCHWENNING.L	8103170618*	50~346
ROTHSCHILD, M U	8103230095*	70-1308	BCARAND, R. A	8103020029	WASTE HOT	SCHWECHANN, T	8103030639#	50-382
ROTHSCHILD, M U	8103230099*	70-1308	BCARAND, R. A	8103160329	WASTE HOT	SCHWEIBINZ, E	8103030445	50-546
ROTHSCHILD, M U	8103230119*	70-1308	BCARAND, R. A.	8103050454	WASTE HOT	SCHWENCER, A	8103020037	50-424
ROTHSCHILD, M U	8103270569	50-445	BCARAND, R. A.	8103120644	40-3453	BCHWEIBINZ, E	8103180140#	50-456
ROTHSCHILD, M U	8103300240	70-1308	BCARAND, R. A.	8103120654	WASTE HOT	GCHWENCER, A	8103030698	50-327
ROUSE, L. C.	8102260529*	40-1162	BCARAND, R. A	8103120780	WABTE MOT	BCHMENCER, A	8103050109#	50-327
ROUSE, L. C.	8102260538*	40-3453	BCARAND, R. A.	8103120627	WASTE MOT	BCHMENCER, A	8103050113*	50-327
ROUSE, L. C.	8103060091*	40-6622	BCARAND, R. A.	8103160155	40-6659	BCHMENCER, A	8103030356	50-327
ROUSE, L. C.	8103270771	70-1308	BCARAND, R. A.	8103120682	40-8584	BCHMENCER, A	8103030380*	50-327
ROUSE, L. C.	8103090106	70-364	BCARAND, R. A.	8103160221	40-8698	BCHMENCER, A	8103030395#	50-327

SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8103099687 8103090693* 8103040927 8103110846 8103180104	50-424 A 50-424 A 50-327 E 50-327 P 50-327 P	SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V	8103030150 8103030158 8103030164 8103030169 8103030179	50-274 P 50-72 P 50-252 P 50-131 P 50-262 P	SHAPAR.H K SHAPAR.H K SHAPAR.H K SHAPAR.H K SHAPKER,J.	8102260782* 8007240519* 8007070498* 8103200840* 8103170710*	FOIA 10CFR 10CFR 50-341
SCHWENCER, A SCHWENCER, A SCHWEIBINZ, E SCHWEIBINZ, E SCINIO, J	8103180110* 8103180120* 8103253642 8103310717 8103310122	50-327 P 50-327 P 50-348 € 50-331 6 50-369 0	SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V	8103040956 8103040961 8103110282 8103050108 0103050115	90-278 P 90-267 P 50-289 P 90-498 A 50-482 A	SHARP, J SHARP, D R SHATTERLY, L W SHATTERLY, L W SHAUB, E. T	8103200603 8103190183* 8103020218 8103250341 8103270788*	50-289 50-327 70-1407 40-8700 50-272
U 0.11038 U 0.11038 U 0.11038 U 0.11038	8103020349 8103110694 6103170589 8103090549 8103030779	50-10 R 50-237 S 50-237 S 50-249 S 50-237 S	SEYFRET.K V SEYFRET.K V. GEYFRET.K V GEYFRET.K V. SEYFRET.K V	8103050122 8103050880 8103050885 8103130714 8103100059	50-445 A 50-382 A 50-498 A 50-498 A 50-285 Q	HAWHU BHEA, JR BHEA, JJ BHEA, JJ BHEA, JR	8103250022* 8103040353 8103090201 8103120179 8103130192*	50-237 XPDRTL1 50-245 50-245 XPGRTL1
0.11038 SCOTT.D J SCOTT.D J SCOTT.D J	8103130353 8103170531 8103170543 8103240348 8103380618	50-10 R 50-249 S 50-237 G 50-10 R 50-237 S	SEYFRIT. K V	8103100708 8103160631 8103160634 8103160640 8103160642	0A999 50-445 G 50-382 G 50-498 G 50-267 G	BHEA.J R BHEA.J R BHEA.J F BHEA.J. R BHEA.J. R	8103140403 8103140411 8103140421 8103140421	XPORTL1 XPORTL1 50-155 50-245 XPORTL1
SCDTT, D. J. SCHOGOS, A. C. SEAMS, J. SEGEV, A. SEIBERT, C. H.	8103240444 8103160495 8103050619* 8103030001 8103240836#	50-249 S WASTE MOT 50-361 A NUREO CONTRACT	GEYFRIT.K V EEYFRIT.K V SEYFRIT.K V SEYFRIT.K V GEYFRIT.K V	8103160644 8103160649 8103170009 8103170010 8103170015	50-285 0 50-313 0 50-382 0 50-482 0 50-458 0	BHEA, J J SPEA, J. J SHEOLOSKY, J I SHELDON, K P SHELLEY, W J	8103240890 8103310704 8103189315• 8103056826• 8103310918	50-245 50-245 50-245 PRM 70-925
SEIDLE, W. C SEIDLE, W. C SEIDLE, W. C SEIDLE, W. C SEIDLE, W. C	8103030344 8103050090 8103050106 8103050354 8103050279	50-498 0 50-382 0 50-493 0 50-482 0 50-482 0	SEYFRIT.K V SEYFRIT.K V. SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8103170019 8103170045 8103170048 8103170051 8103170053	50-49B	SHELLEY. W J SHELLEY. W J SHELLEY. W J SHEPLEY. B E	8103030227 8103050896 B103300231 B103250119 B103090627•	PR 40-8027 40-8027 40-2061 50-373
SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C.	8103130236* 8103130226 8103130337 8103190308 8103190325	50-498 Q 50-498 Q 50-498 Q 50-382 Q 50-498 Q	BEYFRIT, K. V. BEYFRIT, K. V. BEYFRIT, K. V. BEYFRIT, K. V.	81 031 70097 81 032 702 86 81 032 702 72 81 032 703 00 81 032 703 08	50-298 Q 50-247 Q 50-285 Q 50-298 Q 50-313 Q	SHERIDAN A SHERMAN M P. SHERR T. B SHERMODD O O SHERMODD O O	8103050958 8103230073* 8103270775 8103160847* 8103169850*	PR 50-369 70-2909 FOIA FOIA
SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C.	8103269916 8103260924* 8103261186 8103260457 8103260483	50-458 Q 50-458 Q 50-498 Q 50-478 Q 50-448 Q	SEYFRIT, K V.	8103160825 8103160832 8103160835 8103160836 8103160837	50-462 Q 50-382 Q 50-445 Q 50-458 Q	BHERNOOD, O O BYERNOOD, O L SHETROM, S SHEWMAKER, R E GHIELDS, B	8103160855* 8103110348 8103250245* 8103110292 8103170259*	F01A 50-275 50-209 50-329 F01A
SEINEN, S. J. BEITZ, F. SELDY, J. D. SELLE, D. SELLE, D.	8103310671 8103200068* 8103060643 9103126411* 8103116851*	90-482 9 COMMISSICN 50-329 A 50-352 A 50-327 P	SEYFRIT, N. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	8103140838 8103140841 8103140842 8103140984 8103200021	50-247 Q 50-285 Q 50-298 Q 50-313 Q 50-267 P	SHIELDS, W. N BHIELDS, B. W BHIELDS, B. W BHIELDS, B. W BHIELDS, B. W	8103170262+ 8103050868 8103130028 8103190211+ 8103040725	FD1A 50-846 REGOD 80-846 50-846
GELLS.D.E GEMKEN.F B GENECHAL M E GEMENDERFER, W GEXTON.J L	8103180008 8103140134 8103110501 8103040811* 8103040538	50~498 E REB PR FOIA NUREO	SEYFRIT, K. V.	81 03200079 81 03200083 81 03200089 81 03200089	50~498 A 50~445 A 50~382 A 50~458 A 50~313 P	SHIELDS, B. W. SHIELDS, S. W. SHIELDS, B. W. SHIMA, S.	8103030389 8103050681 8103060352 8103180710 8103100371	50-546 50-546 50-546 50-546 XPORTLE
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V, SEYFRIT, K V,	8103031105* 8103230031 8103230045 8103090463 8103040437	50-267	GEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V.	8103200096 8103200098 8103200100 8103240093 8103230167	90-285 P 90-482 A 90-298 P 90-313 Q 90-285 Q	BHIMA: 8 BHIMA: 8 BHIMA: 8 BHIMECK: D. J. BHIVELY: C. N.	8103100376* 8103230917 8103230949* 8103040671 8103120626*	XPORTL10 XPORTL10 XPORTL10 RES 50-368
SEYFRIT, K. V.	8103040455* 8103120584 8103120593* 8103200214 8103200219	50-445 Q 50-498 Q 50-498 Q 50-72 Q 50-252 Q	BEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V	B103230170 B103230172 B103230174 B103230178 B103230181	50-298 Q 50-313 Q 50-267 Q 50-458 Q 50-498 Q	BHIVELY, C. N. BHIVELY, C. N. BHIVELY, C. N. BHIVELY, C. N.	8103170455# 8103170452# 8103240437# 8103310656# 8103310577#	50-369 50-369 50-313 50-313 50-368
SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V	8103200224 8103200230 8103200237 8103200292 8103200299	50-131 0 50-189 0 50-112 0 50-59 0 50-192 0	SEYFAIT, X V SEYFRIT, K V SEYFRIT, K. V SHA, W T SHACKELFORD, B	8103230184 8103230184 8103230186 8103240039 8103139621*	50-449 Q 50-302 Q 50-402 Q NUREO PROJ	BHOMAERT, E. SHOPENN, N. M. SHOPENN, N. M. SHORB, E. M. SHOTKIN, L. M.	8103200609 8103260614# 8103260620# 8103090428 8103181017#	50-289 40-1947 40-1947 50-367 REVIEH 6
GEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	0103200331 0103200337 0103200341 0103200340 0103200353	50-298 0 50-274 0 50-313 0 50-267 0 50-285 0	SHAFER.W D. SHAFFNER.J.A SHAFFER.W M SHAFFER.W M SHAFFER.W M	8103130172# 8103170524# 8103160144 8103090559 8103180786	50-335 Q 27-39 Wabte mot Wabte mot Wabte mot	SHOTWELL, J. A SHOTWELL, J. A SHOTWELL, J. A SHOURD, R. R. SHUM, E. Y.	8103200789 8103200632 8103200637* 8103160318* 8103060317	50-471 50-443 50-443 71-403 70-820
SEYFHIT.K V SEYFRIT.K V SEYFRIT.K V GEYFRIT.K V GEYFRIT.K V	0103200852 9103200857 8103200861 9103160305 8103160313	50-148 0 50-284 0 50-262 0 50-298 0 50-285 0	SHAFFER, W M BHAFFER, W M SHALLER, D. V SHALLER, D. V SHALLER, D. V	8103261143 8103261143 8103100342 8103090477 8103050485*	WABTE HOT Wabte Mut 50-315 R 50-315 R 50-315 R	BHUM.E.Y. GIRUMAKER.J.J. SHUMAKER.J. SHYMLOCK.M BIBULKIN.M	8103240118 8103200579 8103250422 8103040479 8103120758	70-1151 50-287 50-287 50-280 REB
SEYFRIT, N V GEYFRIT, N V GEYFRIT, N V SEYFRIT, N, V SEYFRIT, N, V	8103160354 8103160078 8103100728 8103200675 8103030100	50-313 Q 50-267 Q 50-458 Q 50-298 Q 50-188 P	SPALLER. D. V SHALLER. D. V SHALLER. D. V SHALLER. D. V SHALLER, D. V	8103050626 8103030831 8103100360 8103100562 8103160532	50-316 8 50-316 8 50-316 8 50-316 8 50-315 8	BICKLEB, K. M BIDEOGTHAM, D. P BIEBER, J. D. BIEFKEN, D. L BILBERG, J.	8103030746 8103290529 8103230491 8103170524* 8103130385	50-245 PR 50-334 27-39 50-387
SEYFRIT, A V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8103030108 8103030112 8103030119 8103030127 8103030143	30-112 P 30-313 P 50-148 P 50-39 P 50-172 P	SHALLER, D. V SHALLER, B. V SHAMLA, W. A. GIYANJAXY, M SHANBAXY, M	8103230755 8103270689 8103130463 8103090723• 8103040691	50-315 8 . 50-315 8 50-263 8 50-320 0 50-320 8	BILBERO, J. BILBERO, J. BILBERO, J. E. BILBERO, J. E. BILBERO, J. E.	8103130385 8103130385 8103200751 8103200757* 8103200751	50-387 50-387 50-387 50-397 50-397
1								

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	RÜHTUA	ACCESSION NUMBER	BUBLE CATEG
BILBERO, J. E SILLIMAY, M. A SILVERWOOD, J. B SILVERWOOD, J. B. SILVER, H.	8103200757* 8103060299 8103230043 8103020482 8103130343	50-387 O 50-220 R REGOD TOPREP 50-287 P	SNYDER. B J SNYDER. H L SNYDER. H L SNYDER. B J BNYDER. B J	8103180075 9103230339 9103100427 9103260978 9103160979	40-8584 40-8584	SPENCER, O. S SPENCER, O. S SPENCER, O. S SPENCER, O. S SPENCER, O. S	8103100029 9103050729 8103030424 9103040313 8103240697*	50-397 50-397 50-397 50-460 50-397
Birmons, K	8103160720*	50-339 6	SHYDER, B. J.	8103190126	50-320 P	SPENCER. 0. 8	8103050750	50-828
Birpson, C	8103260968	50-369 H	SMYDER, B. J.	8103260973	50-320 P	SPENCER. 0 S	8103240673	50-397
Birderbrand, C	8103110964	PR	SMYDER, B. J.	8103230430	50-321 H	SPENCER. 9 S	810325000!	50-397
Birderbrand, C	8103260812	PR	SMYDER, H. L.	8103240487	40-8504	SPEROFF, R	810311070!*	50-237
Bircerbrand, C	8103260820*	PR	SMYDER, H. L.	8103240490	40-8584	SPEROFF, R	8103!70548*	50-237
8100ER. 8	8103260382*	FOIA	ENYDER.B J	8103250481	50-320 P	SPESSARD, R L	8103040474	50-265
8100ER. 8.	8103260937*	27-39	SOBEL.M	8103250330*	REVIEW ORP	SPESSARD, R L	8103031014	50-304
8100H. K. P	8103300487*	50-254 P	SOHINKI,S M	8103040376	70-2623	SPESSARD, R L	8103031073	50-304
810181. J. M.	8103310493	50-245 J	SOLLENBERGER.D	8103260753	40-8585	SPESSARD, R L	8103090627+	50-373
810181. J. M.	8103310498	50-213 J	SOONO.P Y	8103110540*	50-338 P	SPESSARD, R L	8103090272+	50-254
SINIBI, J. M.	8103310424	50-245 J	SOONO, A. L	8103100177	70-162	SPEBBARD, R. L.	8103130245*	50-10
SINIBI, J. M.	8103310452	50-29 J	SODNO, A. L	8103110037	70-1100	SPEBBARD, R. L.	8103160944*	50-254
SINKIN, C. A.	8103200588	50-498 Q	SORENSON, R. L	8103250644	PR	SPIECEL, Q.	8103190629	50-445
SINKIN, C. A.	8103200588	50-498 Q	SORRENTINO, A. V	8103230558	50-333 G	SPIECEL, Q.	8103260817	50-449
SIROIS, H. J.	8103060629#	50-361 A	SOUCY, A. R	8103070587	50-29 J	SPIECEL, Q.	8103190629	50-445
SKIBBE, W. II	8103180797	90-289 0	SOUDER, J L	8103040110	50-244 F	SPIECEL, O	8103760817	50-445
SKINKER, P. H.	8103120783#	50-324 0	SOUDER, J L	8103110743	50-440 A	SPIELES, P.	8103100628	40-8380
SKIAR, J. B.	8103240367*	50-219 8	SOUDER, J L	8103200681	50-369 A	SPIESS, H. R	8103260732	40-1947
SKOLDS, J. L.	8103180831*	50-399 0	SOUDER, J L	8103100080	50-272 F	SPIESS, H. R	8103260728	40-1947
SKORDHOD, P.	8103230138	71-9039	SOUDER, J L	8103100083	50-272 F	SPITZDERO, D. B	8103170242*	50-458
BLAWINBKI, W. J	8103110082	40-8155	SOUDER, J L	8103100089	50-311 F	SPRING,A. ERENIAWSKI,D.J SRENIAWSKI,D.J ERENIAWSKI,D.J STABLEFORD,D H	B10325050	PR
BLIFER, B. G.	8103310214*	50-271 P	SOUDER, J L	8103100088	50-289 F		B103260018	40-659
BNITH, J.	8103040128	50-231 B	SOUDER, J L	8103100092	50-245 F		B103270617	70-2707
BNITH, T. H	8103190672*	90-213 Q	SOUDER, J L	8103100094	50-213 F		B103270629+	70-2707
BNITH, O. H	8103050755*	50-333 Q	SOUDER, J L	8103100099	50-263 F		B103050808	PR
BALTH, Q. H BALTH, Q. BALTH, R. L BALTH, B. W. SALTH, T. H	8103310842 8103030291* 8103100770* 8103160911* 8103050271*	70-364 50-333	BOUDER, J. L.	8103100101 8103100105 8103100107 8103100113 8103100668	50-261 F 50-302 F 50-244 F 50-313 F 50-259 F	STAFFORD, A H STAHL, M STAHLE, C. STALLMAN, F W STAMIRIS, B	8103030801* 8103300002 8103051007 8103030336 8103200567*	50-33B PR 50-327 NUREO 50-329
BHTTH, O. H Entth, O. H BHTTH, O. H BHTTH, O. H.	8103050372 8103270821# 8103030319 8103050746 8103110526	50-320 0 50-333 0 CONTRACT 50-333 0 50-286 0	SOUDER, J. L. SOUDER, J. L. SOUDER, J. L. SOUDER, J. L. BOUDER, J. L.	8103109674 8103109675 8103109680 8103260972 8103261052	50-29 F 50-315 F 50-267 F 50-250 F 50-282 F	STAMIRIS.B. STAMIRIS.B. STAMPLEY.N.L. STAMPLEY.N.L STAMICN.C	8103200963 8103200570+ 8103240615 8103130400 8103130285	50-329 50-329 50-416 50-416 XPORTL1
841TH, 0 H 841TH, M T 841TH, 0 H 846TH, 8 846TH, 0	8103260081# 8103050879 8103110544 8103200487 8103200487	FOIA 40-8681 50-387 G 50-289 O 50-289 O	BOUDER, J. L.	8103261059 8103261066 8103261076 8103270397 8103300475	50~272 F 50~206 F 50~199 F 50~317 F 50~271 F	STARKEY, R. D. STARKEY, E. STARKEY, R. D. STARKEY, R. D. STARKEY, R. B.	8103060763 8103120788 8103060826 8101300569 8103050154#	50-261 50-261 50-261 50-261
BMITH, R. H	8103040099	71-421	SOUDER, J L	8103260965	50-313 F	Stark.r.m	8103030985	50-397
BMITH, R. 1	8103040154	PR	SOUDER, J L	8103270591	50-484 H	Starkey,r b	8103160786+	50-261
BMITH, J. H	8103060195	REB	SOUDER, J L	8103270605	50-29 F	Stark.r.m	8103030003	50-387
SMITH, G. C.	8103230913#	50-217 G	GOUDER, J L	8103270612	50-290 F	Stark.r m	8103080234	90-387
BMETH, J. D.	8103140953#	50-346 G	SOUDER, J L	8103261165	50-334 F	Stark.r m	8103090671	90-387
BRITH, Q. H.	8103100754	M18C	SOUDER, J. L.	8103261183	50-155 F	STARK, R. M.	8103110439	90-387
BRITH, R. J.	8103160287	REGOD		8103261189	50-334 F	STARK, R. M.	8103130218	90-387
BRITH, O. H.	8103270809	50-333 G		8103261194	50-324 F	STARKEY, R. B	8103050546	90-261
BRITH, D. C.	8103030679#	50-289 T		8103261200	50-334 F	STARKEY, R. B	8103050551	90-261
BRITH, R. O.	8103060483	PRM		8103261210	50-358 F	STARKEY, R. B	8103050556+	90-261
BHITH, B BHITH, R. L. SHITH, C. V. SHITH, I. W.	8103200467 8103030777 8103020569 8103040708 8103110561	50-275 H 50-271 P 50-289 O 50-243 P 50-289 O	BOVDER, J. L. BOVDER, J. L. BOUDER, J. L. BOUDER, J. L. BOUDER, J. L. BOVDER, J. L.	8103261212 8103270009 8103270012 8103300478 8103300472	50-269 F 50-334 F 50-219 F 50-261 F 50-293 F	STARKEY, R. B. STARKEY, R. B STARKEY, R. B STARK, R. M STARKEY, R. B.	8103050562+ 8103040321 8103310629+ 8103100424 8103110479	50-261 50-261 50-261 50-387 50-261
BMITH, R. L.	8103130363	50-271 G	BOUDER, J. L	8103300473	50-289 F	STARK: R. M.	8103170754	50-387
BMITH, R. L.	8103160568	50-271 P	BONDON, T. L	8103240221*	50-293 R	BTARKEY: R. G.	8103170380	50-261
BMITH, R. L.	8103170555	50-271 R	BPAHN, M J	8103250336*	REVIEW GRP	STARK: R. M	8103230009	50-387
BMITH, P. A.	8103230933	CONTRACT	BPECCHIO, J	8103170503*	MISC	STARK: R. M	8103230013	50-387
BMITH, J. W.	8103180605	50-289 O	BPECTER, A	8103050024	PR	STARK: R. M	8103230315	50-387
BMITH, R. L. BMITH, I. W. BMITH, I. W. BMITH, R. L. BMITH, R. L.	8103230661	50-27 P	BPECTOR, 8. M	8103030819+	50-244 B	STARKEY, R. B.	8103190372	50-261
	8103250232	50-289 0	BPECTER, A.	8103270139	PR	STARKEY, R. B.	8103190384+	50-261
	8103250241	50-289 0	BPEED, L. J.	8103310200+	50-309 G	STARK, R. M	8103240625	50-387
	8103300319	50-271 R	BPENCER, O. B	8103040350+	50-460 G	STARK, R. M	8103310863	50-387
	6103310206	50-271 P	BPENCER, Q. B.	8103030799+	50-397 Q	STARR, R. L.	8103270633+	70-1207
Smoker, C. B.	8103100540#	50-305 8	SPENCER, 0 S.	8103050766*	50-528 Q	STASZESKY, F M	8103090631*	100FR
Smoker, C. B.	8103310647#	50-305 8	SPENCER, 0 S.	8103180083	50-508 Q	STEELE, H. J.	6103030775*	50-272
Smalder, R. P.	8103260376	50-244 P	SPENCER, 0 S	8103180087*	50-508 Q	STEELE, H. J.	8103030682*	50-272
Bnead, M. M.	8103310861#	CONTRACT	SPENCER, 0 S	8103110837*	50-528 Q	STEELE, H. J.	8103030767*	50-272
Bnyder, B. J.	8103160873#	FOIA	SPENCER, 0 S.	8103110831*	50-528 Q	STEELE, H. J.	8103090356*	50-272
BNYDER, M. L.	8103240610	40-8584	SPENCER, Q B.	8103040332 •	50-460 0	STEELE, W. J.	8103310632+	50-272
BNYDER, H. L.	8103051012	40-8584	SPENCER, Q B.	8103030512	50-361 Q	STEELE, W. J.	8103310718+	50-272
BNYDER, Q. L.	8103260076*	FOIA	SPENCER, Q B.	8103040207	50-397 0	STEELE, W. J.	8103310730+	50-272
BNYDER, H. L.	8103230083*	CONTRACT	SPENCER, Q B.	8103250039 •	50-508 0	STEFANETTI, M. J.	8103200486	50-275
BNYDER, B. J.	8103090073	50-320 H	SPENCER, Q B.	8103250042 •	50-508 0	STEFFEN, R. J.	8103261215	REGOD
BNYDER.B.J.	8103060692	50-320 H	BPENCER, G. S.	8103040339	50-508 0	STEFFY, A. W.	8103170445	50-289
BNYDER.B.J.	8103130724	50-320 H	BPENCER, G. S.	8103040322	50-528 0	STE INER: Q. R.	8103110476	50-327
BNYDER.B.J.	8103230283	50-320 P	BPENCER, G. S.	8103030026	50-312 0	STELLO: V.	8103060078	MIBC
BNYDER.O.F.	8103190635	50-289 H	SPENCER, G. B.	8103050369	50-528 0	STELLO: V.	8103020664	50-320
BNYDER.B.J.	8103120039	50-320 P	BPENCER, G. S.	8103190006	50-460 0	STELLO: V.	8103020672*	50-320

AUTHER	ACCESSION NUMBER	SUBLECT CATEGERY	FONTUA	ACCEF SION NUMBER	SUBJECT Category	POHTUA	ACCESSION NUMBER	SUBJEC CATEGO
STELLO V STELLO, V STELLO, V STELLO, V STELLO, V	8103040161 8103040181 • 8103060039 8103060049 • 8103120163	50-272 G 50-272 G 50-237 G 50-237 G 50-237 G	STOYER, C H STRASMA, J STRASMA, J STRASMA, J STRAUBE, M	8103090059+ 8102270554 8103270196 8103300131 8103260763	40-1(62 PR PR PR PR 50-269 G	SYLVIA.B R SYLVIA.B R SYLVIA.B.R SYLVIA.B R SYLVIA.B R	8103231098 8103231083 8103170333 8103170581 8103300274	50-260 50-338 50-260 50-338 50-339
STELLO, V STELLO, V STELLO, V STELLO, V	8103066401 8103130012 8103050239 8103350248* 8103110117	50~443 H 50~443 H 40~672 40~672 50~271 H	STREBEL.S J STREBEC.S J. STREETER.J F STREETER.J F STREETER.J F	B103130046 8103130046 81030503944 8103050766* 8103309155*	PROJ PROJ 50-254 0 50-409 0 50-373 0	SYLVIA.B.R SYLVIA.B.R SYLVIA.B.R SYLVIA.B.R SYLVIA.B.R	8103230637 8103230787 8103260379 8103260467 8103270526	50-280 50-338 50-280 50-339 90-338
616. LG. V 616LLO. V 916LLO. V 516CLO. V 616CLO. V	8103110759 6103100753 8103100760* 8103181133 8103181135*	50-271 H 50-247 Q 50-247 Q 50-255 P 50-255 P	STREHLOW, R A STRICHT, R L STROTERIDGE, S STROUG, S STROUGE, R A	8103230084* 8103270658 8103053910 8103160276* 8103180774	90-369 P 50-483 A PR Misc 50-289 H	GYLVIA.B R SYLVIA.B R BYSLO.J TAGART.B W TALNABI,J W	8103310278 8103310565 8103030847* 8103040548 8103260819	50-338 50-280 50-346 NUREO 50-272
STELLO. V STELLO. V STELLO. V STELLO. V STELLO. V	8103181019 8103181032 8103181042 8103181059 8103250164	50-271 H 50-271 H 50-271 H 50-271 H 50-266 F	STRUMWASSER. M STRUMWASSER, M STRUMWASSER, M STUEBNER, V. F STUETZER, O. M	8103050712 8103200726 8103200062 8103200267 8103036308	0397 H 50~289 H 6099 6099	TALNAGI. J W TAM.P B TAMBLING.T N TAPIA. J I TAPIA. J I	8103760651 8103120373* 8103130172* 8103170030* 8103261178*	50-272 50-275 50-335 50-498 50-498
STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	8103240598 8103260349 8103260392 8103261156 8103261166*	50-346 0 50-155 H 50-3 F 50-259 0 50-259 0	SULT, M SULT M SULPAN, B SULPAN, B SULLIVAN, R F	8103130a01 8103313914 8103050a47 8103050641 8103120770*	50-322 A 50-322 A HISC HISC 50-259 Q	TARANG.PS.L.B G TARNE.P C TATTERSALL.A P TATTERSALL.A P TAUBER.H	8103160520 8103120737 8103120571* 8103240803* 8103050483	PR PR 50-338 50-331
STECLO, V STECLO, V STEPHENS, W. F STEPHENS, C. R STEPHENS, C. R	8103300496 6103300498* 8103190386 8103110549 8103110565	50-220 G 50-220 G 50-287 H PR PR	SULL IVAN.R. F SULL IVAN.R. F SUMMERS.R SUMMIER. J.R SUTPHIN.R	8103240281+ 6103270104+ 8103090638+ 6103190229 6103046029	50-259 Q 50-259 Q 70-139 REGOD 50-330 B	TAYLOR. J H TAYLOR. J H TAYLOR. J H TAYLOR. J J TAYLOR. J H	8103060715 8103260495# 8103060649 8103109670# 8103110490	PR 50~445 TOPREP CONTRAC TOPREP
STEPTOE, P. P. STERI (NO.A W STERIUSERG, D IN STERIUSERG, D IM STERIUSERG, D IM	B103050704 B103070120+ B103030498+ B103100024+ B103050488	50-237	SUTPHIN R N SUTTON, J R SVENSSON, B A SVENSSON, B, A SHAN, W, B	8103180215# 8103110014# 8103100346# 8103050495# 8103249162#	50-329 Q QA999 50-315 R 50-315 R 50-518 Q	TAYLOR.J H TEAGLE.F H TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103270673# 8103160372 8103170602# 8102050224 8102050224	50-269 PR 50-352 50-275 MISC
STERNBERG, D M STERNBERG, D M STERN W P STERNBERG, D M STERNBERG, D M	8103180913* 8103180523* 8103050491 8103250015* 8103240744*	50-344 Q 50-275 Q XPORTLIC 50-344 Q 50-344 Q	SUANBY, O.T. SUANBY, G.T. SUANBY, G.J. SUANBERGUU SUANBERGUU SUANSON, E. A	8103110308 8103119343 8103200123 8103240737 8103240562*	40-3453 40-3453 40-3453 50-327 40-1947	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103090259 G103050423 B103120172 B103040023 B103031087	50-361 50-361 CRO 50-462 50-463
STETAALT.F STEVENSON/R L STEVENSON/R L STEVENSON/R L STEVENSON/R L	8103160911* 8103069578 8103060671 8103160294* 8103040565*	50-302	SWANSON, E. A SWANSON, E. A SWANSON, E. A SWANSON, E. A SWANSON, E. A	8103249548* 6103240532* 8103240506* 8103240488* 6103240440*	40-1947 40-1947 40-1947 40-1947 40-1947	TEDESCO, R L.	8103040761 8103060070 8103060104 8103060473 8103110211	50-382 50-445 50-358 50-483 50-341
STEVENBORUR L STEVENSONUR L STEVENSON R STEWARTOR C STEWARTOR C	8103160436 8103270027# 8103250256 8103050076# 8103190012#	70-1374 70-820 NURED 50-382 G 50-362 G	SWANSON, E. A. SWANSON, E. A. SWANSON, E. A. SWANSON, E. A. SWANSON, E. A.	8103240374# 8103240338* 8103240319* 8103240325# 8103240304#	FD1A FD1A 40-8410 40-8610 FD1A	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103060111 8103060375 8103730050 8103050345 8103060507	50-358 50-373 50-369 50-416 50-367
GTEWART, R C STILLUSEL, D U STILWELL, T C STILWELL, T C STICKER, O P	8103240433 8103020320* 8103040313* 8103240605* 8103170935	50-382 S 50-329 A 50-409 P 50-213 P 50-269 H	EHANSON, E. A. SHANSON, E. A. EHANSON, E. A. SHANSON, E. A. BHANSON, E.	B103240263* B103240273* B103240247* B103240205* B103230375*	40-8610 F01A 40-8410 40-8610 50-269 P	TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L. TEDESCO.R.L.	8103040331 8103090718 8103090730 8103130095 8103200342	50-387 50-395 50-302 50-445 50-445
STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P.	8103100367* 8103260089 8103090366 8103260899* 8103050422*	70-992 70-143 50-395 0 70-143 50-369 0	SUANSONLE SWANSONLE SWANSONLE SWANSONLE R SWANSONLD T	8103230386* 8103260198* 8103040094 8103120487* 8103120259	50-269 P 40-8610 50-315 S 50-315 Q 50-289 Q	TEDESCO. R L	8103050259 8103110272 8103060691 8103090049 8103100168	50-361 50-369 50-395 50-369 50-397
STEHRUUP STEHRUUP STEHRUUP STEHRUUP STEHRUUP	8103240274# 8103650747 810365074# 8103650244# 8103130635	70-143 50-348 G 50-413 G 70-1113 70-27	SWANSON. D T SWANSON. D T SWANSON. D T SWANSON. D T SWANSON. D T	8103170471 8103170473* 8103170538 8103230656 8103270172	50-70 0 50-70 0 50-289 7 50-289 0 50-70 0	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R.L TEDESCO.R.L	8103110250 8103160105 8103200356 8103110208 8103130065	90-482 50-362 50-352 50-362 50-362
9 C.8HOT8 9 C.8HOT2 9 C.8HOT2 9 C.8HOT3 9 C.8HOT3	B103060262* B103160965* B103160485* B103150050 B103260314*	70-1151 50-369	SWART, F E SWART, F E SWART, F E SWETLAND, P EWINTH, K L	8103030843 8103060291# 8103060284 8103230684 8103020782	90-267 P 50-267 R 50-267 R 50-309 B NUREG	TEDESCO, R L TEDESCO, R. L	8103110235 8103120093 8103120422 8103130056 8103110239	50-362 50-352 50-445 50-311 50-382
STOOR, J. P STUAR, J. P STOAR, J. P STOLZ, J. F STOLZ, J. F	8103250614 8103260464 8103260272 8103160748* 8103090216*	27-47 70-1201 70-143 50-346 8 50-237 0	SYLVIA. B R SYLVIA. B R SYLVIA. B R SYLVIA. B R SYLVIA. B R	8103290494 8103130705* 8103120554 8103280912 8103050776*	50-260 0 50-280 0 50-338 0 71-9079 90-338 0	TEDESCO, R. L.	8103160447 8103120197 8103160102 8103160191 8103110742	50-382 50-553 50-373 50-397 50-382
STOLT, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8103160499 31031801804 8103240102 (4103300481 8103300489#	50-346 P 50-346 P 50-346 P 50-346 P	SYLVIA, B R SYLVIA, B R SYLVIA, G R SYLVIA, B R SYLVIA, B R	8103030795 8103040266 8103040293 8103040333 8103040356	90-338 R 50-320 Q 50-338 P 90-280 P 50-280 F	TEDESCO, R. L.	8103160245 8103170100 8103180130 8103110382 8103110389	50-358 50-352 50-471 50-397 50-387
STOLZ, J F STOTT M L STOUT M B STOVEL T L STOWERN S	8103300490* 8103190467 8103030905* 8103230702 8133062699	50-346 P 50-289 H TOPREP FOIA PR	SYLVIA, B R. Sylvia, B R Sylvia, B R Sylvia, B R Sylvia, B R	8103040307 8103240322* 8103070327 8103100420 8103170173	50-280 R 50-280 G 50-338 P 50-280 P 50-339 P	TEDESCO, R. L.	8103120207 8103130151 8103160147 8103160216 8103120416	50-364 50-369 50-416 50-416 50-395

		-						
AUTHCR	ACCESSION NUMBER	SUBJECT	AUTHCR	NOTEGET ON	SUBJECT CATEGORY	AUTHOR	VOLESTON	CATEG
TECÉSCO, R L TECESCO, R L TECESCO, R L TECESCO, R L TECESCO, R, L	8103160176 8103170215 8103120186 8103120817 8103160261	50-382 A 50-373 E 50-397 Q 50-275 A 50-445 E	THOMPSON, D. THOMPSON, J E THOMPSON, R D THOMPSON, R D THOMPSON, R	8103120623 8103270146 8103200484 81032004916	I ME HASTE MGT TOARTOOD  CONTRACT CONTRACT 0 OSE-00	TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C.	9103100507 8103120316 8103110629 8103120599 8103120617	50-369 50-313 50-313 50-368 50-369
TEDESCO, R. L.	8103160266 8103160273 8103160290 8103160296 8103160989	50-397 A 50-311 P 50-369 F 50-329 A 50-416 F	THOMPECN. D. THOMPECN. R. D. THOMPEON. D. THOMPEON. D. THOMPEON. D. THOMPEON. D.	B103190524 8103270604 8103250415 8103300276 B1033030B554	50-259 G CONTRACT 50-220 8	TRIMBLE, D. C TRIMBLE, D. C TRIMBLE, D. C TRIMBLE, D. C TRIMBLE, D. C	8103110445 8103160493 8103170453 8103160499 8163170450	50-349 50-313 50-348 50-313 50-38
TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	6103190023 6103160979 6103170772 6103230257 8103230298	50-352 H 50-445 I 90-361 D 50-352 H 90-341 A	THORUS, L THORNTON, V E THORNBURGH, D THRGM, E D TIERGEY, J E	8103090723 • 8103040675 8103270021 • 8102270389 8103050579 •	90-320 Q RES 50-320 H 50-269 P	TRIMBLE, D C	8103:90121 8103230559 8103180513 8103180544 8103240127	50-313 50-313 50-313 50-368 50-368
TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103260923 8103230270 8103230420 8103230155 8103230345	50-275 A 50-382 F 50-482 A 50-358 A 50-482 A	TILLMAN, A TILLMAN, A TILLMAN, A TIPTON, T TOALSTON, A	8103740261+ 8103750016+ 8103170263 8103030194 8103310413	50-250 0	TRIMBLE.D.C TRIMBLE.D.C TRIMBLE.D.C TRIMBLE.D.C TRIMBLE.D.C	81032403a3 8103240427 8103240239 8103240230 6103240415	50-348 50-313 50-313 50-313
TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103230347 8103230356 8103230457 8103231079 8103250171	50-387 A 50-443 A 50-352 H 50-443 F 50-454 A	TOBIAS, M.L. TOBIAS, M.J. U.W.NIEDI J.W.NIEDI J.W.NIEDI V.W.NIEDI	8103230106 8103261137* 81032070249* 8103180272* 8103230638	NUREQ 50-327 Q 70-27 90-261 Q 50-327 8	TRIMBLE, D C	8103270641 8105310549 8105310589 8103310591 8103310575	50-313 50-313 50-313 50-313 50-368
TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8103250379 8103230891 8103250099 8103250103 8103250108	50-397 A 50-458 A 50-438 E 50-482 A 50-483 A	TOBIN; W TODD, O A TODD, Q A TODD, O A. TOM, NEON, D P	8103249304 8103130662* 8103040802* 8103250153* 8103130348*	50-302 B 70-143 70-1151 70-27 50-498 Q	TRIPP.L E TRIPP.L E TRIPP.L E TROKETIA.R TROOP.C L	9103189578+ 8103189098+ 8103300528+ 8103120409 8103140507	50-354 50-271 50-354 50-344 50-269
TECESCO.R.L TECESCO.R.L TECESCO.R.L TECESCO.R.L TECESCO.R.L	8103240570 8103240604 8103240749 8103250684 8103260110	50-389 C 50-272 F 50-389 A 50-397 A 50-450 A	TOME INSONED P TOMP L E. TONGUELT. TONGUELT TONGUELT.	8103170030* 8103181022* 8103030418 8103020377 8103130245*	50-498 O REVIEW GRP 50-249 S 50-249 S 50-10 G	TRUSAGSA1.W TROIT.D B TROIT.D D TROUP.O L TROUP.O L	6:03190676* 8103050852 8103240583 8103160969* 8103190057*	50-317 TGPREP RES 50-369 50-364
TEDESCO. A L TEDESCO. A. L TEDESCO. A. L TEDESCO. R. L TEDESCO. R. L	8103240120 8103240133 8103300480 8103260097 8103261160	50-329 A 50-329 A 50-275 B 50-454 A 50-387 A	TONGUE, T. TOCKER, D. W. TOPOLEKT, E. TORCIVIA, J. A. TGRRICE, R. A.	B103240387 B103170575* B103170327 B103230843 B103200424	50-10 5 50-331 9 50-289 H 50-289 T 50-275 H	TRDY.C.T TRUMILL.L D TRUBSELL.H H TRUST.O. TSCHAECHE.A !!	0103190431 8103110470 8103030352+ 8103190625 8103230639	50~259 50~275 40~8064 50~289 50~70
TEDEECO, R. L. TEDESCO, R. L. TEDESCO, R. L. TEDESCO, R. L. TEDESCO, R. L.	8103310438 8103310147 8103310166 8103310932 8103310372	50-528 A 50-397 A 50-397 A 50-322 A 50-483 A	TOTHLA D TOTHLA D TOTHLA D TOTHLA D TOTHLA D	9503940374% 8103030811% 810304021% 8103100036% 8103240697%	50-460 0 50-397 0 50-397 0 50-397 0 50-397 0	TUBBS, R TUCKER, H. TULEY, C. R TUNSTALL, J. E. TURINSXY, P. J.	8103179374+ 8109200420 8103170183+ 8103200189+ 8103030864	99-254 50-267 50-327 CENTRACT 50-111
TEDESCO, R. L TEELING, M. O TEELING, M. O TEITT, T. R. TENZER, B. E	8103310382 8103050029 8103270167 8103100582 8103200429	50-454 A PR PR 50-289 R TOPREP	TOWNLEY, E. L. TOWNSEND, H. E. TRAMM, T. R. TRAMM, T. R. TRAMM, T. R.	8103050485# 8103180588# 8103050638# 8103030540	50-315 R 10PREP 50-295 P 50-454 A 50-295 P	TURK.S E TURK.S E TURK.S E TURK.S E TURK.S E	8103160766 8103110302 8103110309 8103170318 8103180610	70-2909 70-2909 70-2909 70-2909 50-483
TERRO, D TERRY, O. A TETZLAFF, A L. TMATCHER, R W TMATCHER, R W	8103261009* 8103230973 8103100346* 8103040100 8103200357	50-482 A 50-277 P 50-315 R NUREO NUREO	TRAMMELL, C. H TRAMM, T. R TRAMM, T. R TRAMM, T. R TRAMM, T. R	8103050556° 8103030702 8103110407 8103130241 8103170507	50-317 P 50-454 K 50-454 A 50-295 P 50-295 P	TURK, S.E. TURK, S.E. TURK, S.E. TURKEY, R.E. TURKER, C. H	8103190059 810323008[ 8103270464 8101220624+ 8103120819	50-488 50-403 70-2907 50-72 FOIA
THIES A C THIES A C THOM T THOMAS E L THOMAS S J	8103170103 8103310549 8103170550* 8103030083* 8103050836	50-269	TRAMM, T R	8103160630 8103170496 8103180517 8103230886 8103200351	50-295 0 50-299 P 50-10 P 50-295 P 50-10 P	TURNER. 6.  JUROVLIN. 8  TUILLEY. R C  TYLER. W J  JYNDAL. R. L	8103300487* 8103240526* 8103230355* 8103170490 8103250256	50-254 50-250 50-269 50-275 Nureo
THOMAS, M. THOMAS, R. D. THOMAS, R. D THOMAS, J. A THOMAS, R. D	8103050348* 8103230169* 8103250144* 8103190308* 8103180973*	50-438 G 70-1257 50-206 G 50-219 G 70-984	TRAMM, T R TRAMM, T R TRAUTMAN, D TREAT, E H TRESBITT, M M	8103230793 8103310448 8103310468 8103190630 8103270703	50-295 F 50-454 W 50-346 S 90-289 H 50-289 H	UDALL.M M. GOALL.M M. UDALL.M M. UDERITZ.R.A UDERITZ.R.A	8103110108* 8103050813* 8103170462* 8103240734 8103030004	50-272 100FR 100FR 50-272 50-272
Thomas M Thomas M Thomas D Thomas M Thomas J. L.	8103110521* 8103090503* 8103270180 8103240716* 8103030864	50-438 0 50-413 3 PR 50-438 0 50-111 W	TREBY.S A TREWORGY.J O TRICKOVIC.R.S TRICKGVIC.R S TRIFUNAC.M D	8103110254 8103180962 8103120327 8103170923 8103240227	90-338 O NUREO 50-416 A 50-416 A 50-443 O	UDERITZ.R A UDERITZ.R A UDERITZ.R A UDERITZ.R A UDERITZ.R A UDERITZ.R A	8:03030772 8:03030678 8:03030762 8:03090554 8:03160515	50-272 50-272 50-272 50-272 50-272
THOMAS. R. D. THOMAS. E. S. THOMAS. R. D. THOMAS. R. D. THOMAS. R. D. THOMAS. R. D	8102270702 8103030683 8103180345* 8103200634 8103240298	1&E 50-220 P 70-2317 70-734 70-1257	TRIFUNAC.H B TRIMBLE.D.C. TRIMBLE.D.C TRIMBLE.D.C. TRIMBLE.D.C.	8103240236* 8103100511 8103041034* 8103050630* 8103050079*	50-443	UDERITZ.R.A. UDERITZ.R.A. UDERITZ.R.A. UDERITZ.R.A. UDERITZ.R.A. UDERITZ.R.A.	8103170271 8103319626 8103310711 8103310724 6103310351	50-272 50-272 50-272 50-272 50-272
THOMPSON, J. E. THOMPSON, O. R. THOMPSON, J. E. THOMPSON, D. THOMPSON, D.	8103050491 8103270114 8103040456 8103050731 8103020501	HABTE MGT NURBE WABTE MGT 40-8084 1&E	TRIMBLE, D. C.	8103180970 8103230214 8103030796 8103030790 8103040471	REGGD 50-313 F 50-313 R 50-313 P 50-313 P	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8103030872 8103070530 8103030817 8103070465 8103070168*	50-389 50-389 PR 90-389
THOMPAON, D. THOMPAON, O. THOMPAON, J. E THOMPAON, O. THOMPAON, O.	8103120382 8103130447 8103261030 8103120419 8103120439	1&E 50-361 D Warte HOT 1&E 50-255 B	TRIMBLE, D. C.	8103030824 8103090535 8103090547 8103110138# 8103090379	50-313 P 50-313 P 50-313 P 50-313 F 50-368 P	UHRIGORE UHRIGORE UHRIGORE UHRIGORE UHRIGORE	8103090751 8103050324* 8103230274 8103230054 8103040742	PR 50-250 50-335 50-335 50-250

АОНТОЯ	ACCESSION NUMBER	SUBJECT CATEGORY	PCHTUA	ACCESSION NEMDER	SUBJECT CATEGORY	Y	ROHTUA	ACCESSION NUMBER	BUBJECT CATEODRY
UMRIG.R E UMRIG.R E UMRIG.R E UMRIG.R E UMRIG.R E	8103230409 8103040773 8103040781 8103120081 81031390274#	50-250 0 50-335 0 50-369 0 71-6078 50-250 0	VAN BRUNT, E.E.	B103170642 B103170554 B103170115 B103240364 B103300309	50 - 528 50 - 528 50 - 528 50 - 528 50 - 528	A B A S F	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8103120061 8103120068* 8103120076* 8103160264 8103250307	50-334 P 50-334 P 50-334 P 50-272 F 50-272 P
CHRIG.R E UHRIG.R E CHRIG.R E UHRIG.R E UHRIG.R E	8103060622 8103100334 8103250273 8103100314 8103100599	50-250 P 50-250 P 50-335 R 50-250 P 50-250 P	VAN BRUNT, E E VAN CLEVE, A G VAN RODYEM D. VAN RODYEM D. VAN SCYOC, J. M	8103310661 B103250013 B103110772 B103310901 B103190403	50-528 PR <i>REB</i> REB 50-207	н	VARGA, B. A.	8103250311* 8103250318* 8103160143 8103160569 8103170003	50-272 P 50-272 P 50-261 P 50-348 P 50-261 P
UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8103110711 8103070400 8103240249+ 8103110510 8103110463	50-250 R 50-250 P 50-250 Q 50-250 P 50-250 P	VAN VRANKEN, J VAN VRANKEN, J VAN WINKLE, W VAN ZANOT, Ü. R VAN ZANOT, Ü. R	8103050596 8103050604 8103050839 8103260816# B103260823#	70-1308 70-1308 RE9 <i>FOIA</i> FOIA		VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8103230281 8103230351 8103230361* 8103230372* 8103250626	50-250 P 50-305 P 50-305 P 50-305 F 50-272 P
UHRIGER E UHRIGER E UHRIGER E UHRIGER E UHRIGER E	8103259306# 8103160854 8103130429 8103230417 8103270879	50-335 0 50-369 A 50-389 A 50-250 P 50-250 P	VAN ZAMOT, D. R VAN ZAMOT, B. R VAN ZAMOT, D. R VAN ZAMOT, D. R VAN ZAMOT, D. R	B103260793* B103260762* B103260765* B103260753* B103260751*	FOIA 40-1947 40-1947 40-1947 40-1947		VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8103230169 8103230852 81032360876 8103231077 8103260246	50-241 F 50-295 P 50-334 Q 50-305 P 50-281 P
UHRIO, R. E. UHRIG, R. E. UHRIG, R. E. UHRIG, R. E. UHRIG, R. E.	8103160599 8103240202 8103200619 8103239318 8103240368	50-387 A 50-335 P TDPREP 50-250 P 50-335 P	VAN ZANDT, D R VAN ZANDT, D R VAN ZANDT, D R VAN ZANDT, D R VAN ZANDT, D R	8103260748* 8103260742* 8103260734* 8103260730* B103260731*	40-1947 40-1947 40-1947 40-1947 40-1947		VARQA. 8 A VARQA. 8 A VARNADO, 0. B VARNADO, 0. B. VARNAE, L. B	8103260260* 8103260280* 8103030353 8103100179 8103190694*	50-281 P 50-281 P NUREO NUREO CONTRACT
UHRIG.R E UHRIG.R E UHRIG.R E ULLRICH.H F UPRIGHT.C M	8103760543 8103269602 8103260455 8103050222* 8103260186*	90-250 F 50-335 F 50-389 R 50-277 R 50-416 0	VANAS. D W VANDEL. T E VANDELL. T B VANDELL. T D VANDELL. T D	8103130034* 8103950361* 8103031126 B103050328 B103130367	70-1703 50-482 40-8502 40-8786 50-255	G R	VERNA B J. VERPLANCK D M VICKERS T. VILLFORTH J C VILLFORTH J. C	8103090382 8103310214* 8103040571* 8103270085 8103090532	PR 50-271 P 50-361 A NUREO PR
URBANIM. T URBANIM. T URBANIM. T UTLEY. E E UTLEY. E E	8103240284+ 8103240237 8103240289+ 8103090107 3103250605	COMMISSION 71-5926 PR	VANDELL, T. D. VANDOORN, P. K. VANDOORN, P. K. VANDOORN, P. K. VANDOORN, P. K.	B103240225 B103040056* B103050577* B103090503* B1031B0508*	40-8502 90-413 50-413 50-413 80-416	0 0 0	VINCENT, R. A.	8103040763 8103110617 8103160501 8103270677 8103310406	50-255 R 50-155 P 50-255 P 50-255 B 50-255 P
UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.F E	8103020443 6103190130+ 8103190169+ 8103030752 8103050655	50-261 P 50-261 F 50-324 F 50-261 P 50-261 P	VANSICKEL, U VARGA, G A VARGA, B A VARGA, B A VARGA, B, A	B103180499+ B103110459+ B103020140 B10302075B B103020762+	90-331 50-280 50-272 50-315 50-315	В Р Г Р	VINSON, T J VISSING, O. VISSING, O VOGELBERGER, P VOGELBERGER, P J	8103040548 8010230589 8103090193 8103090601 8103090607*	NUREO 50-269 P 50-269 P XPORTLIC XPORTLIC
UTLEY. € € UTLEY. € € UTLEY. € E UTLEY. € E	3103110592 6103070529 8103070582 8103070633 8103110638	50-324 P 50~324 P 50-261 P 50-324 P 50-261 P	VARGALS A VARGALS A VARGALS A VARGALS A VARGALS A	B103020767* 8103930313 B103030330 B103030452 B103030463*	50-315 50-334 50-250 50-280 50-280	р Р Р Р	VCOEL. W J. VCOLEWEDE, J C VCOT, J. F VCIOT, H H VCIOT, H H	8103190389 8103060657 8103270623 8103040736* 8103110571	50-287 H M16C 70-1207 50-247 O PR
UTLEY. E E UTLEY. E E UTLEY. E E UTLEY. E E UTLEY. E E	B103250711 B103110403 B103110687 B103120669 B103110424	PR 90-261 P 50-325 P 50-324 F 50-324 P	VARCA. S. A VARCA. S. A VARCA. S. A VARCA. S. A VARCA. S. A	8103030476* 8103031113 8103031118* 8103031132* 8103040229	50-280 50-247 50-247 50-247 50-280	<b>Ե</b> Ե Ե	VOIOT. H H VOIOT. H H VOIOT. H H VOLLE. H	8103110571 8103110571 8103110571 8103110571 8103200502	PR PR PR PR 50-275 H
UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E	8103130369 8103130384 8103130512 8103160437 8103240407	50-261 P 50-324 P 50-261 0 50-324 P 50-261 F	VAROA B. A VAROA, B. A VAROA, B. A VAROA, B. A VAROA, B. A	B103040231 B103040243* B103040245* B10304024B* B103040267*	50-314 50-280	թ թ թ թ	VOLLEN, R. J VOLLEN, R. J VOLLEN, R. J. VOLLEN, R. J VOLLEN, R. J.	8103050685 8103050685 8103050707 8103050707 8103179532	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0
UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E	8103160459 8103180846 8103240210 8103230591 8103240491	50-324 P 50-325 P 50-261 P 50-261 P 50-324 V	Varca. 8 a Varca. 8. a Varca 8. a Varca. 8 a Varca. 8. a	B103050138 B103050147* B103050169* B103040252 B103040260*	50-247 50-247 50-334	P P P P	VOLLEN.R.J. VOLLMER.R.H. VOLPE.L VON HIPPEL.F VON HIPPEL.F.	8103190532 8102200170* 8103240012* 8103230628* 8103260429*	50-367 0 COMMISSICY PR 50-369 0 COMMISSICY
UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E UTLEY.E E	8103249345 8103240352 8103270649 8103270669 8103310546	50-324 F 50-261 F 50-324 P 50-324 P 50-261 0	VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A	8103040270* 8103040278 8103040291* 8103040311* 8103040304*	50-334 90-334 90-334	P P P P	VON ZELLEN B. U. VONDY, D VORDERBRUEGGEN VORDERBRUEGGEN VREELAND, C.	8103180628 8103180806 8103050781* 8103050379* 8103120663	50-289 H XPORTLIC 50-528 G 50-528 G PR
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8103050759• 8103020699 8103110823• 8103120469 8103060708	50-528 0 50-528 0 50-528 0 50-528 5 PR	VARGA. 8 A VARGA. 8 A VARGA. 6 A VARGA. 6 A. VARGA. 8 A	B103040280 8103040288* 8103040060 8103040067* 8103040084*	50-316 50-348 50-348	P P P P	WACHOB, H. M WADE, G. E. WAOINBLAST, F. R. WAONER, A. G. WAONER, A. G.	8103190510 8103180588* 6103190612 8103041026* 8103240634*	50-289 N TOPREP 50-289 H 50-416 G 50-416 G
VAN BRUNT.E E VAN DRUNT.E E VAN BRUNT.E E VAN BUSKIRK.M VAN BRUNT.E E	8103200829 8103230870 8103190681 8103050623 8103040550	REOGD 50-528 G 50-528 T 50-289 T 50-529 S	VARGA, S.A. VARGA, S.A. VARGA, S.A. VARGA, S.A. VARGA, S.A.	B103040870 B103040878 B103070140 B103060265 B103060267#	50-305 50-247 50-250	P F O P P	HAGNER, W. J. HAGNER, W. J. HAGNER, W. J. HAGNER, P. C. HAGNER, D. P.	8103170011* 8103050741* 8103250004* 8103170768 8103310574	50-460 0 50-397 0 50-377 0 50-269 0 NUREO
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8103040566 8103100591 8103360302 8103100460 8103100471	50-528 S 50-528 B 50-528 C 50-528 A 50-528 F	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8103040269* 8103090095 8103130090 8103110448 8103110785	50-334 50-250 50-280	P Q P P	WAHL, H W. WAHL, H A. WAKEFIELD, J WALBRIDGE, W. C. WALBRIDGE, M. C.	8103040160* 8103040149* 8103310897* 8103180662* 8103100568	0A999 GA999 70-820 50-312 3 30-312 8
VAN BRUNT.E E	8103130283 8103170507 8103690519 8103170478 6163170404	50-528 T 50-528 A 50-528 R 50-528 H 50-528 A	VARQA.8 A VARQA.5 A VARQA.5 A VARQA.8 A VARQA.8 A	8103130073 8103050495 8103050502* 8103050512* 8103120447	50-280 50-280 50-280	6 6 6	HALBRIDGE, W. C. WALKER, R. D. WALKER, R. F. WALKER, Q. J WALKER, R. S.	8103270919 8103090627* 8103160703* 8103260814 8103190009*	50-312 F 50-373 G 50-267 I 50-275 H 50-289 H

AUTHCR	ACCEBSION NUMBER	BUBJECT CATEGORY	POHTUA	ACCEBB10h RBB*:UA	SUBJECT CATEODRY	AUTHER	ACCESSION RESMON	SUBLEC CATECO
MALMER.R S HALL.T B HALLACE.A T MALLACE.T J. MALLACE.L E.	8103130409 8103040548 8103090528 8103060235 8103110505	50-352 H NUREC PR 50-223 B PR	WEIL-C H WEIL-P H WEILER,R A WEINBERG,A M WEISE-S	8103040159 8103270063 8103260557 8103240134 8103050170	* 50-329 0 * CONTRACT * 50-361 A * CCMMISSION	WHITESELL, D. E. SHITESELL, D. E.	8103110008 8103120393 8103110014 8103051015 8103310897#	0A999 0A999 0A999 REB 0A999
HALLACE.L E HALGUIST.E J. HALSKE.C WALEKE.C WALTERS.J.F	8103260121 8103190405 8103090643* 8103090637* 8103230355*	50-259 0 PR 10CFR 10CFR 50-267 P	WE 185. D WE 185. D WE 185. D WE 186. D	B103240B22 B103260330 B103050B70 B103310891 B103060155	• FOIA 70-1271	WAITESELL, DE WHITESELL, DE WHITESER, HE WHITESELL, DE UHITESER, HE	0103310885* 8103070522 8103270076* 8103310939* 8103130678*	0A999 PR 90-321 97PA 90-395
HALTERS.D K WALTON O A HANO,J S WANG.C.H WANG.C.H	8103040118# 8103060505* 8103120709# 8103040708 8103230500	50-413 Q 50-367 Q 50-361 K 50-243 P 50-106 R	We 188. D We 188. D We 188. D We 188. E R We 188. E R	8103050250 8103100189 8103100259 8103250869 8103130455	71-6400 70-1201 70-754 PR 50-289 G	WHITEHER, H L WHITE, F WHITESIDES, O E WHITE, J D. WHITE, E B.	8103170317* 8103250064 8103260074 810204049[ 8103050651	50-395 PR REB NUREO PR
WARD, H L WARD, K D WARD, K D WARD, E C WARD, E C	8103051008 8103020701* 8103120252* 8103270477 8103270673	PR 90-266 0 90-329 0 90-282 R 50-263 R	WE186.E R WE186.E R WE188.E R WE188.E R WE183.E R	8103260859 81032608694 8103130455 8103060349 8103060349	PR PR 50-289 0 50-443 0 50-443 0	WHITE, E B WHITE, A K WHITFIELD, B C WHITMEY, O O. UMITSELL, B	8103050451 8103190179* 8102260711* 8103230551* 8103130579*	PR 50-339 FOIA 50-293 50-346
MAREMBOURD D W MAREMBOURD D W MAREMBOURD D W MAREMBOURD D MAREMBOURD D	8103030208 8103030744 8103030741 8103300001 81033030671	PR 50-267 P 50-267 P PR 50-267 B	ME 188' E H ME 188' D ME 188' D ME 188' D	8103200111 8103160439 81032333393 8103120464 8103200537	40-299 40-8714 DR0 70-687 70-2623	WICHERS D L	8102270638 8102190832 8102200397 8103240038 8103110304	40-8502 40-8502 40-8502 40-8502 40-8502
HAREMBDURG, D. W. HAREMBDURG, D. W. HAREMBDURG, D. HAREMBDURG, D. W. HAREMBDURG, D.	8103030703 8103040634 8103160492 8103110954 8103100979	90-267 P 50-267 V 90-267 F 90-267 P 90-267 G	ME 168. D ME 188. D ME 188. E R ME 188. E R	8103160208 8103160306 8103180536 8103180604 8103180556	71-5768 70-1703 50-289 0 50-289 0 50-289 0	WICHERS, D. L. WIDNER, W. A. WIDNER, W. A. WIDNER, W. A. WIONER, W. A.	8103160931 8103020709 6103170093 8103250142* 8103020614	40-8502 50-321 50-366 50-321 50-321
MAREMODURO. D MAREMODURO. D MAREMODURO. D MAREMODURO. D MAREMODURO. D	8103310737 8103100481 8103100604 8103110524 8103240669	50-267 8 50-267 R 50-267 R 50-267 R 71-6347	WEISB.E R WEISB.E R WEISB.E R WEISB.E R WEISB.E R	8103180404 8103190416 8103190422* 8103190416 8103190422*	50-289 0 50-275 0 50-275 0 50-275 0 50-275 0	WICHER, W A WIDNER, W A WIDNER, W A WIDNER, W A WIDNER, W A	8103100425 8103100485 8103160862 8103260503 8103130570	50-321 50-321 50-321 50-321
HAREMBOURO, D HAREMBOURO, D HAREMBOURO, D HAREMBOURO, D HAREMBOURO, D	8103160699 8103180785 8103190056 8103240476 8103300067	50-267 1 50-267 F 50-267 F 50-267 P 50-267 F	WELLS, J. R WELLS, D. A WELLS, D. A WENDERLICH, R. L. WENDERLICH, R. L.	8102170396 8103160482 8103160752 8103040657* 8103260645*	TOPREP 50-341 & 50-341 & 50-317 & 50-318 &	WIDNER, W A	8103240295* 8103250139* 8103260100 8103240509 8102261174	50-321 50-321 50-321 50-321
MARNER, D.L. MARNER, D.L. MARNER, J.W. MARNER, D.L. MARNICK, R.W.	8103170034* 8103240099 8103180679 8103270192* 8103030997	70-820 70-820 50-329 H CONTRACT 50-304 S	WENDLAWBRI,F WENDLAWBRI,F WENDLAWBRI,F WENDLAWBRI,F WENDLAWBRI,F A	8103030507* 8103100010* 8103040261* 8103100403* 8103100464*	50-324 Q 50-133 Q 50-89 Q 50-528 Q 50-206 Q	WIDNER, W A WIERIG, R. D WIESEMANN, R A WIESEMANN, R A WIESEMANN, R A WIESEMANN, R A	8103303249 8103020723 8103170893+ 8103100615+ 8103130490+	50-321 NUREQ 50-334 TOPREP 50-206
VARMICK.R F. WARNICK.R F. WARNICK.R F WARNICK.R F WARNICK.R F	8103050778* 8103130021* 8103040015 8103100699* 8103050499*	50-305 G 50-305 G 50-346 B 50-266 G 50-358 G	WENSLAWSKI.F A WENSLAWSKI.F A WENSLAWSKI.F. A WENSLAWSKI.F A WENSLAWSKI.F	8103180192* 8103180591* 8103250031* 8103240708* 8103290409	50-113 Q 50-206 Q 50-361 Q 30-312 Q 50-312 B	WIESS, D. WIGOINS, E WIGOINS, E WIGOINS, E WIGOINS, F.	810316-2220 8103130264 8103200174 8103090164 8103090187	70-820 CONTRACT CONTRACT CONTRACT CONTRACT
Harnick, R. F. Harnick, R. F. Harnick, R. F. Warnick, R. F. Warnick, R. F	8103160953* 810319082* 8103240226* 8103170362 8103190503	50-346 0 50-358 0 50-266 0 50-346 8 50-409 8	Werling, J A Werling, J A Werling, J. A Werling, J. A Werling, J. A	8103060171 8103920385 8103100584 8103100587 8103170508	71-9096 50-334	WICOINS.E. WICOINS.E. WILEDRN,I WILCOX.J D. WILCOX,J D.	8103160194 8103190685 8103170242* 6103240308* 8103250206*	CONTRACT CONTRACT 50-459 50-439 50-439
Harnick, R. F. Harren, B. K. Habhabaugh, R. J. Hashabaugh, R. J. Habberbach, A. E.	8103190517 8103030776 8103040943 8103040951* 8103250756	50-346 B 50-329 0 71-415 71-415 PR	Werling, J A Werling, J A Werling, J A Werling, J. A Werling, J. A	8103120476 8103130599 8103170605 8103260676 8103260697	50-334 8 50-334 8 50-334 8 50-334 5 50-334 8	WILCDX.D P. WILKEN.E S. WILKEY.A M. WILKEY.A M. WILKEY.A M	8103120485# 8103160545 8103020536# 8103100496# 8103100486#	50-201 PR 50-327 50-327 50-327
HATANABE,H.T. HATANABE,H.T. HATERMAN,M.E. HATFORD,M. HATKINS,M.	8103200763* 8103200763* 8103060781 8103170388* 8103250541	50-387 0 50-387 9 RES 50-261 R PR	WERMTEL. J. WERNER. J. WERNER. B. J. WESCOTT, H. M. WESLEY. D. A.	8103200119* 8103170493* 8103310423* 8103180386* 8103260095	50-289 T 50-346 S 50-346 B 50-461 Q 50-295 P	WILKEY, A M. WILKINSON, K. WILKINSON, E. WILKINSON, R. E.	6103100477# 6103170595# 6103120816 6103161154 6103240629	50-327 50-327 PR REGOD 50-294
Wathing, M. Watking, M. Watking, M. Watking, M. Watking, M.	8103250550* 8103250550* 8103250550* 8103250550*	PR PR PR PR PR	WESTERMAN, T. F WESTERMAN, T. F WESTERMAN, T. F WESTERMAN, T. F WESTERMAN, T. F	8103031105* 8103050598* 8103180443* 8103230187* 8103020431	50-267 0 50-382 0 50-267 0 50-382 0 50-267 8	HILLARD, C. L. HILLARD, C. L. HILLARD, F. HILLARD, F. WILLIARD, F. WILLIAMSON, R. WILLIAMSON, P. A	8103200512 8103200539 8103250256 8103100569* 8103110748*	50-287 50-275 NUREO 50-213 50-361
HATEON, B. B. WAV. B. D. L. MAYLAND, J. R. MEABER, G. O. MEAVER, K.	8103250646 8103190473 8103250261 8103190458 8103310553	NUREG 50-289 H NUREG 50-289 H WASTE MGT	WESTERMAN, T. F. WESTMAN, R. A WETTERHAHN, M. J. WETTERHAHN, M. J. WETZEL, R. A.	8103300294 8103040744* 8102040399* 8103050495 8103050099	50-267 S FOIA 50-358 F 50-272 O PR	WILLIAMS, C. C. WILLIAMS, C WILLIAMS, H. P. WILLIAMS, C. C WILLIAMS, C. C.	8103040147 8103030445 8103170443* 8103030457* 8103070780*	50-846 50-846 50-334 50-846 50-454
WEBB.A J. Weber.D A Weber.R. Webster.E. H Webster.E. H	8103200552 8103040482 8103240746 8103120571* 8103240803*	50-275 H 50-247 P 50-289 I 50-338 Q 50-338 Q	HETZEL-R. A WHARTON, R. J. WHARTON, R. J. WHARTON, R. J. WHARTON, R. J.	8103050042 8103130526 8103130526 8103130526 8103230640	PR 50-361 0 50-361 0 90-361 0 50-361 0	WILLIAMS H.A. WILLIAMS C.C. WILLIAMS C.E. WILLIAMS R.E WILLIAMSON M.M	8103130444* 8103050204* 8103261164* 8103041001 8103060688	50-247 50-440 COMMISS FOIA ORO
HEOST, H. HEHMANN, G. HET, S HETCHMAN, M. S. HETDNER, S.	8103060326 8103120408* 8103250458 8103170436 8103170430	50-142 F 50-331 G NUREO 50-483 A 50-289 H	WHARTON, R. J. WHEATLEY, A. O. WHITAKER, C. E. WHITESELL, D. E. WHITESELL, D. E.	8103230640 8103170384 8103160012 8103031151+ 8103130068*	50-361 0 50-275 H 71-418 0A999 0A999	WILLIAMS, B.E. WILLIFORD, R.E. WILLIAMS, C.C. WILLIAMS, C.C. WILLIAMS, C.C.	8103170116 8103310924 8103180140+ 8103230162+ 8103261026+	REB NUREO 50-456 50-454

		gueu£01		ACCESSON	SCBUSC I	ALLTHIBO	ACCESSION NUMBER	BUBUECT
A .THIP  UPUS 1483 - 5 - 5	#10875104 #16984 31030511444 #1030301514	508.551 CATEGERY 50-546 d 50-440 d	AUTHOR UITHADW. G C WITHADW. G C	AU 10:ER B103030761 B103030777	CATEGORY 50-155 R 50-155 B	AUTHOR YOUNG C A YOUNG LOOD, B J	8103170286 8103040161 8103120237	CATEGORY 50-289 H 50-369 0
MILLIAME, C. C. WILLIAME, C. C. WILLIAME, L. G. WILLIAME, F. C.	9:03050003* 9:03150642 9:03150642	50-373 0 70-4909 PR	µ[тынС./ -3 -6 (/11 = RZW. 9 -6 µ[тынСи. 3 -6	8163046669 8163056269 8163190351	50-155 R 50-155 P 50-155 0	YOUNGBLOOD B J	8103270114+ 8103160110	50-466 D 50-369 F
util (AMS.F C WILLIS E WILLIAMS.M D WILLS U	9107140847 8103140866* 8112140568 8107040707 8103130417	PR 50-324 R 70-1590 50-362 S 50-362 S	WITHROW 3 C WITHROW 9 C WITHAN G F WITTICH W WITTICH W	8103231069 8103231081 8103193540 8103230642 8103240046	50-195 0 50-155 0 50-289 H 50-382 F 50-382 A	AUNAGB/000° B 1 AUNAGB/000° B 1 AUNAGB/000° B 1 AUNAGB/000° B 1	8103110240 8103110074 8103110097* 0103190523 8103120642	50-400 A 50-387 A 50-387 A 50-289 H 50-410 A
GTE SCHOOL R MESCHAIR D WILLEGE B MESCHAIR D MESCHAIR D	8102120704* 8102120320 8103040872 8103040898 8103040559	50-351 K PERTLIC PERTLIC PERTLIC PERTLIC	WIZMER, DIR MOUSHOUSKI, A MOUF, UIF MOUF, UIF MOUF, UIF	8163180540* 8163050622* 8163203863* 8163220564 8163220766	50-315	YOUNGBLOOD, B. J. YOUNGBLOOD, B. J. YOUNGBLOOD, B. J. YOUNGBLOOD, B. J.	8103130720 8103230903* 8103230641 8103230648* 8103240573	50-454 A 50-443 A 50-373 E 50-373 E 50-389 A
WILSON 5 D WILSON 6 F WILSON 5 D WILSON 5 D WILSON 6 D	8(07076565 6(07) 20277* 9(07) 0354 8(07) 6072	70-2745 CONTRACT (PCRTL:C *PCRTL:C (PCRTL:C	NO.FF.S J WOLFE, J F WOLFF, C F WOLLETT, S WOLLETT, S	8103110512 8107270472 8107090645 8107950327 8107110790	50-466 0 70-2909 40-8602 CONTRACT CONTRACT	AOPHGBFCOD: 8 1 AOPHGGFCOD: 8 1 AOPHGGFCOD: 8 1 AOPHGGFCOD: 8 1 AOPHGBFCOD: 8 1	8103250476 8103250480* 8103250737 8103250002 8103270105	50-466 D 50-466 D 50-466 D 50-466 D
411 854. 8 0 41 2551 8 0 41 2551 8 5 41 2551 3 5 41 2551 3 5	8103133080 8153130085* 8103080473 8103080593 8103080596*	(PCRTL1C (PORTL1C 50-27 P 50-281 S 50-281 S	NOLLETT S NOLLETT S NOCHO H NOTHER J NORG T	8103130483 8103103667 8103160239* 8103250029 8103310669	CCHTRACT CCNTRACT 50-369 G MISC 40-229	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YUAN, Q YUMAS, G P	8103010138 8103310389 8103310397 8103360869* 8103100010*	90-369 F 50-322 A 50-373 A PR 90-133 G
MILSON J C MILSON J N MILSON F R MILSON J C MILSON J C	A:07050801+ 8103120473 B:03110374 B:03100635 A:03100639+	50-281 6 50-322 A 50-344 J 50-181 8 50-281 6	NONS. 5 NOOD. E C NOOD. E C NOOD. D C	8103250141# 8103160248 8163049612 9163310260# 8163160257#	NUREO 50-309 6 50-309 6 50-309 0 TOPREP	YUMAS, O.P. YUMAS, O.P. YUMDT, C.P. YUMDT, C.P. YUMDT, C.P.	8103100464# 8103160591# 8103020362 8103030646 8103180673	50-206 0 50-206 0 50-344 5 50-344 5 50-344 9
MILEGAL J. L. MILEGAL J. L. MILEGAL J. L. MILEGAL J. L.	9153136470 9163150422+ 9163113475+ 9163133477+ 9163170579	50-280 8 90-281 8 50-281 9 50-280 5 50-280 8	MEODIL WOODHEADIC P WOODRUFFIR L WOODRUFFIR L WOODRUFFIR L	8103190709 8103050509 8103050255* 8103150644* 8103080270*	XPD91LIC 50-142 0 70-1113 70-27 70-1151	YUNDT.C P YUNDT.C P ZAHLER.R.E ZAHLER.R E ZAHLER.R E	8103170474 8103170317 8103020360 8103020439 8103020439	50-344 F 50-344 S 50-289 0 50-289 0 50-289 0
UTLSON U ULSON U .F TLSON U L TLSON U L TLSON V	8107170985* 9103170489 8103190851 8103190854* 8107230973	50-280 B MISC 50-281 S 50-281 6 50-320 P	WOODRUFFIR L WOODS J WOOSTER, R D WOOLEVERIE J WOOLEVERIE J	8103260473* 8103360261 8103310571 8103060331* 8103060420	70-1201 50-187 R M18C 50-412 B 50-412 Q	ZAVLER.R E ZAVLER.R E ZAJAG.L D ZAJAG.L D ZALEGAI.P	8103190628 8103240543 8103160537* B103270072* B103050131*	90-289 0 90-289 0 90-370 0 90-280 0 CONTRACT
MILSON U L MILSON U L MILSON U L MILSON U L	8103251027 8103240516 81032405214 8103209390 8103310535	1PCRTLIC 50-280 6 50-280 9 50-466 D 50-280 9	WOOLEVER.E.J HOOLSEY.R T HOOTCALP D HRAY.J R HRAY.J R	8103240384 8103120747* 8103040615 8163120716* 8103040372*	90-412 B 40-299 50-287 P 50-280 Q 50-395 Q	ZAPF. J ZARBIB. W A ZAVACOSKI. R W ZEBROSKI. C L ZECH. O G.	8103310874 8103160428# 8103130716# 8103250593 8103160372	XPORTLIC 50-298 P 50-280 Q PR MISC
WILSON / L WILT D II WILT D D WILT D D WINDER, W A	8103310582* 8:03160626* 8:03:50626* 6:03:50619 8:03:60461	50-280 8 50-440 0 50-440 0 50-440 0 50-321 P	WRAY. J. R. URIGHT. G. C. WRIGHT. D. D. WRIGHT. D. D. WRIGHT. F. B.	8103120475 8103040038 8103050403* 8103250409 8103250160	50-259 B 50-155 E 50-155 G HEGOD 50-471 G	ZETF, D W ZEIDLER, W F ZELLER, H D ZELLER, H D ZEMPER, R R	B103250709 B103150460 B103050562 B103260659 B103050229*	PR 50-287 H 50-389 A 50-387 A 50-287 0
MINDARD. G MINGARD. G MINDARD. G MINDAUR. S MITHERSPOON. P	8103240863* 8103240650 8103240654* 8103050794 8103120704*	F01A F01A F01A PR 50-361 K	MU. 0 MULFF. H MULFF. H MULFF. H MULFF. M	8004090779* 8103040679 8103260669 8103240144 8103310693	NASTE MOT REG REB REB RES	ZIBULSKY-H ZILLER-E ZIMMERMAN-B B ZIRWAS-K ZIRWAS-K	8103200385* 8103030234 8103190375* 8103170597* 8103180623*	70-1100 PR PR 50-237 9 50-237 8
WITHERSPOOM P WITHERSPOOM J WITHERS SOON D WITHERS SO WITHERS SOON J	8103170709# 8103050037 8103100363# 8103236204 8103331071	50-361 K RES 70-992 50-344 G RES	WULLER, O E HUNDERLICH, J R HURM, J G YACKLE, T R YACKLE, J R	8103180961 8103030398# 8103100135# 8103060781 8103170737	REJOD 50-265 B 1118C RES RES	ZITTEL.H E ZITTLE.H E ZCORY.J J ZUBER.E A ZUFELT.E	B103031067 B103031084 B103250017 B103190495 B103130387*	50-361 A RE8 PR 50-287 H 50-333 R
WITHERSPOSE J WITHERS S D WITHERS S D WITHERS P D WITHERS D D	B103180432 B103050568 B1031400374 B103030841 B103090574	RE9 50-344 P 50-344 F 50-344 R 50-344 P	YAMANA, K YAMANA, K YANG, C. H YEATCN, D. C YIN, I. T	8103020647 8103020659* 8103120758 8103120742 8103200572*	XPORTLIC XPORTLIC REB 71-405 50-295 Q	ZULLA: 8. 8 ZULLA: 8. 8. ZURAKOWSKI.P. R ZWETZIO: 0. 8	B103110534* B103110532* B103110528* B103250144* B103040041*	50-286 0 50-286 0 50-286 0 50-312 0
WITHERS B D	8103170608 8103209248 8103200254* 8103200551 8103200555*	50-344 P 50-344 P 50-344 P 50-344 P 50-344 P	YIR. I T YOUNG. R E YOUNG. T YOUNG. T YOUNGBLOOD. E J	8103260984# 8103160349 8102030498# 8163180523# 8103050352	50-373	ZWETZIC.O B	8103240728*	50~205 0
WITHERS, G D WITHERS, G D WITHERS, G D WITHERS, G D WITHERS, O C	8103240349 8103270435 8103270748 8103270770# 8103020409	50-344 F 50-344 P 50-344 P 50-344 P 50-155 P	AGONGBF 000* 8 1 AGONGBF 000* 8 1 AGONGBF 000* 8 1 AGONGBF 000* 8 1 AGONGBF 000* 8 1	8103050360 8103050366 8103050371 8103050377 8103050381	50-389 D 50-389 D 50-389 D 50-389 D 50-389 D			

## CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this indefindicates that the document is an enclosure to anothe document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION:	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIAT 1014	ACCESSION NUMBER	SUBJEC CATEGO:	
ACF Federal Reporters, Inc	8103090171*	CGNTRAC	т		8103180504	50~348	R
	B103160200+	DARTINGS			8103180507*	SC-34B	R
Abington Memorial Hosp Abington, PA	8103050728*	70-1402			9103190108+	50-364	P
Access Corp.	8103070176*	CCNTRAC	Т		B103230251	50-34B	G
Aersspace Corp	B102020497•	10CFR			8103240493	50-349	h
Aerotest Operations	8103300071	20-558	F		0103240565	50-34B	g
Ayriculture. Dept of	8102170607	71-9013			0103240773 0103250072	50-34B 50-354	GI R
	8103060011° 8103170360°	70-1277 CONTRAC			8103230429	50-348	F
	8103190694*	CONTRAC			B103270401	50-34B	ĸ.
Alabama Power Co	8103020389	50-348	P		8103270401	30-349	ĸ.
	8103020388	50-348	Ρ		0103270411*	50-348	ĸ
	B103020451	90-364	P		8103270411#	50-348	K
	8103020504 8103020598	50-364 50-348	8 b		8103270417# 8103270417#	50~348 50-348	ĸ
	8103020606* 8103030606	50-348 50-364	5 P		8103270698 8103300009	50-364 PR	P
	8103030679	50-348	o o		0103310288	50-346	P
	8103040703	50~364	P		8103310588	50-346	P
	8103050652	50-348	٩		8103310294#	90-048	₽
	8103050654*	50-348	Ρ		Ø103310294#	50-348	P
	8103040518	90-348	Đ.		0103310422	50-348	R
	8103060518	50-348	Ŕ		B103310427#	50-348 50-348	E E
	8103060525* 8103040525*	50-348 50-348	R R		8103310434 8103310439#	50-348	R
	8103090167	71-9084		Alabama. State of	8103030642	70-2909	
	B103090173	71-9111			8103050687	70-2909	1
	8103090177	71-6574			8103060475	30-24B	F
	6103090181	71-9081			81032500B4	PR	_
	8103090185	71-9080		Alleghany Electric Cooperative, Inc.	8103130385	50-307	G
	8103990190	71-9089		Allied Chemical Corp	8103120513	40-3392 71-418	
	8103090195	71-9096 71-9105		Alloy Crafts Co	8103160012 8103160018+	71-41B	
	8103090200 8103090209	71-9094		American Electric Power Co . Inc	81030903B7	PR	
	8103090212	71-6144		Thirt year at a second of the	0103180986	REGGD	
	8103090215	71-6244		American Friends Service Cormittee	8103300042	PR	
4	8103090221	71-6601		American Institute of Chemical Engineers	8103110568	PR .	
	8103090226	71-910B		American Insulated Hire Corp	8103100722*	GAPPP	
	8103090228 8103100184	71-5026 50-348	F	American Mining Congress	8103041031 8103260210	PR PR	
	8103100184	50-348	F	American Nuclear Insurers	8103100515	MISC	
	8103100381	50-349	F		+91E031E01B	100FR	
	8103100381	50-348	f	American Nuclear Society	8103050651	6-6	
	8103100498	50-348	P		B103590533	PR	
	8103100498	50-348	P		0103260295	PR	
	B103100502*	90-34B	P P	American Sociaty of Mechanical Engineers American Sociological Association	0103070276* 0103240540	CONTRAC* 50-289	-
	B103100503*	50-348 50-348	P	American politicogical Association Anaheim, CA	B103110773#	50-264 50-361	ī
	6103100503* 8103100530	50-344	þ	mag. Elm V.	8103133046	PRDJ	•
	B103100531*	50-364	P	Anti-Nuclear Group Representing York	8103030615	50-289	g
	8103130399	50-364	P		8103180430	50-209	ī
	8103170607	50-348	8	Applied Health Physics, Inc	B103100172*	40-7924	. !
	B103170610*	50~34B	e R	Applied Science Associates, Inc. Argonne National Laboratory	8103261086# 8103040796#	CCNTRACT FDIA	ľ
	8103170653	50-364 50-364	R	Wildoutta Massaudt Cannigani &	8103010776	40-297	
	8103170656*	30- <b>3</b> 07	••			-10-677	

AUTHER AFFILIATION	ACCEBBION NUMBER	SUBJEC CATEQDI	Rγ	AUTHOR AFFIL IATION	ACCEBBION NUMBER	SUB- CAT
Arizona Public Service Co.	8103250638 8103260039 8103020699 8103020699 8103020699	NUREO NUREO 30-328 50-528 50-528	a a		8103120599 8103120610+ 8103120617 8103120626+ 8103160493	50-36 50-36 50-36 50-36 50-36
	B103040550 B103040550 B103040566 B103040566 B103050759+	\$0-529 \$0-529 \$0-528 \$0-528 \$0-528	5 5 6 6		8103180499 8103170480 8103170452* 8103170453 8103170455*	50-3 50-3 50-3 50-3 50-3
	8103050302 8103050302 8103050302 8103050708 8103090519	50-528 50-528 50-528 PR 50-528	C C R		8103180513 8103180513 8103180546 8103180549+ 8103180970	50-3: 50-3: 50-3: 50-3: REGOI
	8103090819 8103090519 8103103460 8103100460 8103100460	50-528 50-528 50-528 50-528 50-528	R R A A		0103170121 0103230214 0103230559 0103230569* 0103240127	50-3: 50-3: 50-3: 50-3:
	8103100471 8103100471 8103100471 8103100591 8103110823#	90-528 50-528 50-528 50-528 50-528	F F 8		8103240239 8103240239 8103240360 8103240360 8103240363	50-31 50-31 50-31 50-31
	8103110823+ 8103110823+ 8103120469 6103120469 6103120469	50-528 50-528 50-528 50-528 50-528	0 8 8		8103240415 8103240425* 8103240427 8103240437* 8103250550*	50-38 50-38 50-31 50-31 PR
	8103130283 8103130283 8103130283 8103170478 8103170478	50-528 50-528 50-528 50-528 50-528	T T H H		8103270641 8103300391 8103310589 8103310590* 8103310595	50-31 50-31 50-31 50-31
	B103170478 G103170507 G103170507 G103170507 B103170554	50-528 50-528 50-528 50-528 50-528	H A A B	Arkenses. Btate of	8103310597# 8103310649 8103310656# 8103050836 8103250064	50-38 50-31 30-31 PROJ PR
	8103170604 6103170604 6103170604 6103170642 6103170642	50-528 50-528 50-528 50-528 50-528	A A A	Armstrong:Byrd & Associates:Inc. Army,Dept.of Army,Dept.of, Corps of Engineers	8102260736* 8103040242 8103030282* 8103050178* 8103090772*	FOIA FDIA CONTR CONTR
	8103170442 6103190115 8103190481 8103200829 6103200893	90-528 50-528 50-528 REGOD REGOD	A O	Atlantic Electric of New Jersey Atlantic-Richfield Co. Atlas Minerals	8103130655# 8103170616# 8103170489 8103110308 8103110343	CONTR 50-17 MISC 40-34
Arizone. State of	8103230870 8103240344 8103300309 8103310661 8102260526*	50-520 50-520 50-520 50-528 FOLA	0 8 F F		8103181146 8103200123 8103260675 8103260681* 8103260943	40-34 40-34 40-34 40-34
Arkansas Pouer & Light Co.	8103030790 8103030796 8103030802* 8103030824 8103030824	50-313 50-313 50-313 50-313 50-313	P R R P	Atomic Industrial Forum	8103260948# 8103060754 8103090465 8103090631# 8103090637#	40-34 PR PR 100FR
	8103040471 8103041034* 8103050030* 8103050079* 8103070379	50-313 50-313 50-313 50-313 50-368	P G G P	Austin. TX	8103090643* 8103100352 8103260780 8103190649* 8103130106*	10CFR PR ORO 50-49 CONTR
	9103090435 8103090440+ 9103090535 8103090535 8103090547	50-369 50-368 50-313 50-313	ь ь ь	Bebcock & Wilcox Co.	8103050878 8103241065 8103060649 8103060715 8103110490	FOIA FOIA TOPRE PR TOPRE
	8103100507 8103100511 8103100513+ 8103100519+ 8103100656	50-369 50-369 50-368 50-368 50-313	8 8 8 V		8103170122 #103230355# 8103230375* 8103230386* 8103240419*	70-12 50-24 50-26 50-26 50-31
•	8103110138+ 8103110138+ 8103110148+ 8103110148+ 8103110445	50-313 50-313 50-313 50-313 50-348	F F F P	Babcock & Wiltor Co., Navel Nuclear Fuel Div.	8103250709 8103270693+ 8103040444 81030404449+	PR 50-26 70-27 70-27
	8103110629 8103120316 8103120316	50-313 50-313 50-313	9 R R		81032609 <del>3</del> 8 9103120136	70-27 71-90
	8103150351+ 8103150351+	50-313 50-313	R		8103270270 8103270541	70-13 70-36

## 1	AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEGO	RY	AUTHUR AFFILIATIO:	ACCESSION NJMBER	CATEO	
Baths   Control C (says of Barcel b)		B103270751 B103270756* B103270759* B103270763*	70-135 70-135 70-135 70-135			8103030424 8103040154 8103050845	REB Pr REB	
	Wilcox Co. )	B103120606 B103050664	XPDRTL1	o		8103100125 8103120752 8103230177	NUREG REB REB	
Balifacers Gas & Electric Co.		118091E018	50-466	G.		6103240289* 6103230644	CCHM189	104
Bicologo   Solid   S		8101070449+ 8101080207+	50-317 50-317	F F		8103040478* 8103060751	40-8452 PR	
010300177   00-017   F   0103000177   00-017   F   0103000177   00-017   F   0103000177   00-017   F   0103000177   00-017   0103000177   00-017   F   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   0103000177   00-017   0103000177   00-017   0103000177   0103000177   00-017   0103000177   00-017   0103000177   00-017   0103000177   010		8103030764 8103040654 8103040657*	50-317 50-317 50-317	В В		8103130483* 8103260737 8103040145*	50-317 50-329 Qa999	G G
SIGNOFFDED   20-317   P   SIGNOFFDED   20-		8103050211* 8103050211* 8103060538	50-317 50-317 50-318	F F B		8103100396# 8103120327 8103130479*	50-361 50-416 50-317	A A P
## STATE COUNTY PAY ALL STATE COUNTY AND ALL STATE PAY AND ALL STA		8103090385 8103090385 8103090624 8103100445	50-317 50-317 50-293 50-317	P 8 8	Beers, R	8103190101 8103190104+ 8103240601	TOPREP TOPREP 50-289	7
## BIO2100476 50-317 P Blats to Veater, Boothern Bilance ## BIO3000330 ## POPTAL CALL PROPERTY ## BIO3000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.0000374   \$0.000000374   \$0.00000374   \$0.00000374   \$0.00000374   \$0.000000374   \$0.000000374   \$0.00000037		8103110480 8103110487+ 8103120454 8103130432	50-317 50-317 50-317 50-317	8 8 P	Berger: D. Berks County Chamber of Cormerce	8103160777 8103170134 8103190525	50-352 50-320 50-289	H H H
Biolivery   South   Poly   Biolivery   B		8103130476 8103180603	50~317 50~317	P 0	Black & Veatch, Bouthern Science Applications, Inc., Div.	8103300487#	50-254	P
Biologrospos   Solid   File		8103190479 8103200244	50-317 50-317	ā		810306005B 8103120210	FOIA FOIA	_
Biographic   Society   S		8103230505 8103230505 8103260547	50-317 50-317 50-317	H P	Basing Co. Basing Computer Services: Inc. (subs. of	8103230622* 8103261044 8103261072*	50-369 XPORTLIC FOIA	:
Biologroup   Solid   Folk   Biologroup   Solid   Folk   Biologroup   Folk   Folk   Biologroup   Folk   Folk   Biologroup   Folk   Folk   Biologroup   Folk		8103260633 8103260645# 8103260882	50-318 50-318 50-317	9 9 6		8103261102* 8103261109* 8103261115* 8103261120*	FDIA FDIA FDIA	
Bio3270487   So-177   P   Bio3270487   So-177   P   Bio3270487   So-177   P   Bio3270487   So-177   P   Bio3270570   So-177   P   Bio3270570   So-177   P   Bio3270570   So-177   P   Bio3270570   So-177   P   Bio320060478   So-279   Bio3270570   So-177   P   Bio320060487   P   Bio327056   So-279   Bio32705602*   So-177   P   Bio327056   So-279   Bio3270602*   So-177   P   Bio3270708   So-187   P   Bio3270708   So-287   Bio3270708   So-187   P   Bio3270708   So-287   Bio3270708   So-287   Bio3270708   So-279   Bio3270808		8103240934* 8103270428 8103270428	50-317 50-317 50-317	8 P P	Borg-Warner Corp. Byron Jackson Pump Div	8103261134* 8103030137* 8103060623*	FDIA FDIA 50-361	A
Sindaroscale   Sind		8103270497 8103270497 8103270570	50-317 50-317 50-317	Р Р Р		8103030630 8103060278 8103060476	50-293 50-293 50-293	0.0
Barr Engineering Co. Battelle Memorial Institute, Columbus  Bio300058e Bi03103030e Bi03103030e Bi03103030e Bi03103030e Bi03103058e Bi03103058e Bi03103058e Bi03103058e Bi03103058e Bi03103058e Bi03103058e Bi0310058e Bi0310058 Bi031		8103270602* 8103270602* 8103270706	50-317 50-317 50-318	P P P		8103090523+ 8103090586 8103100386	50-293 50-293 50-293	3 4 4 4 6
BIO3030001 NURE9   BIO3170533   S0-273   BIO3170533   S0-273   BIO3170533   S0-273   BIO3170537   S0-471   BIO3170537   S0-471   BIO3170537   S0-471   BIO3170517   REB   BIO3170517   S0-471   BIO3050917   REB   BIO3200070   S0-273   BIO3200177   REB   BIO3200070   S0-273   BIO3200177   REB   BIO3200280   S0-273   BIO3200170   B	Battelle Memorial Institute, Columbus	8103300358*	50-317 CONTRACT	g		8103180422 8103190051 8103190051	50-293 50-293 50-293	0 0 1
B103240186   S0-219   R   B103200700   S0-293   B103200700   S0-293   B103200700   S0-293   B103200700   S0-293   B103200700   S0-293   B103200700   S0-293   S0-29	Laboratories	8103040538 8103050852 8103050907 8103050917	NUREO TOPREP REB REB			8103190533* 8103190537 8103190614 8103200070	50-293 50-471 50-471 50-293	P 0 0 0 F
#1032700409 CURTANO #1032700409 B103230551 50-293 ####################################	1	8103180637# 8103240178# 8103240186# 8103240379#	50-219 50-219 50-309	Ř R		8103200700 8103200704* 8103230458	50-293 50-293 50-471	F 8 8
								R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	)4 Y	AUTHOR AFFILTATION	ACCEBBION NJHBER	SUBJECT CATEGORY
	810323GA54 810325GA87 810324G213 8103240221* 8103250550*	50-293 50-293 50-293 50-293 PR	F P R		8103110488 8103110493* 8103110696 8103110710* 8103110724*	PR PR PR 50-361   50-361
Bor. O E P Briggs Engineering & Testing	8103270613 8103270626* 8103190156* 8103300444* 8103230138	50-293 50-293 CONTRAC CONTRAC 71-9035	T		8103110730+ 8103110754+ 8103110754+ 8103110760+ 8103110760+	50-361 1 50-361 1 50-361 1 50-361 1
Brootheven National Laboratory	B103030433 B103040579 B103040579 B103040607 S103040623	REB NUREO NUREO NUREO NUREG			8103110762* 8103110762* 8103110766* 8103130352 8103180566	90-261   50-361   90-361   Btate Prog 50-275 0
	8103040679 8103050385 8103090807 8103110764 8103110772	RES RES NUREG RES RES			8103190037 8103200699 8103200726 8103260529 8103260788	PRUJ 50-275 H PROJ 50-275 H 50-275 O
	8103110769 8103110793 8103110819 8103120758 8103120769	RES RES NUREG RES 50-254	A	California, Univ of, Berkaley	8103260807 8103260845 8103120704* 8103120709* 8103180968*	90-275 3 50-275 0 50-361 K 90-361 K REVIEW GRP
	8103120779 8103120784 8103120787 8103130169* 8103130177*	RES RES RES 50-369 50-369	p P	California. Univ of, Irvina California. Univ of, Los Angeles	8103030480# 8103040735# 8103040744# 8103050131# 8103050988	50-326 G F01A F01A CONTRACT 50-142 G
	8103160604 8103186816 8103190783 8103190809 8103190813	REG REG REG RES RES		California, Univ. of, Santa Bartara Carella, Dain, Gilfilan & Rhodes	8103060326 8103240420 8103250203 8103250330* 8103110339	50-142 F 50-142 H 50-433 F REVIEW GRP 50-289 0
	8103203769 8103240097 8103240144 8103260669 8103310878	50-466 RES RES RES RES	G	Caribe Bhell & Tube. Inc Carolina Environmental Study Group	9103110197 91031102034 8103050611 8103230610 8103230622*	71-417 71-417 90-369 0 90-369 0
	8103310884 8103310887 8103310893 8103310898 8103310901	RES RES RES RES RES		Carolina Power & Light Co	8101300569 8103020443 8103030552 8103030551	50-261 6 50-261 P 50-324 0 50-324 0 50-324 0
Brown & Root Corp (subs of Halliturton	8103310906 8103040212*	RES GA999			8103030561*	50-324 0
Corp ) Brownsville.TX	8103040247# 8103190629 8103190629	0A999 50-445 50-445	M M		8103030743 8103030748# 8103030752 8103030752	50-329 B 50-325 B 50-261 P 50-261 P
	6103190629 6103190629 6103260817 8103260817 8103260817	50-445 50-445 50-445 50-445 50-445	м м м м		8103030887 8103030887 8103040064 8103040208 8103040644	50-324 P 50-324 P 20-400 0 50-217 R 50-325 8
Bruce Norton	8103260817 8103030868+ 8103030868+ 6103050842 8103050942	50-445 50-275 50-275 50-275 50-275	M 0 0 0 0		8103040647* 8103040687 8103040693* 8103030107 8103030154*	50-325 8 50-325 6 50-325 9 71-5926 50-261 9
Burns & Rae Co Business, Industrial, & Professional	8103200678 8103230715 8103050149* 8103270063* 8103180453*	50-275 50-275 FDIA CCNTRACT 50-289	0		8103050177 8103050177 8103050191* 8103050523 81030505336*	50-324 R 50-324 R 50-324 R 50-324 S 50-324 B
Association  C-E Operating Plants Owners Group  C-E Power Systems	8103240488 8103030218 8103060738 8103060791	TCPREP PR PR PR			8103050544 8103050551 8103050558* 8103050562* 8103050584	50-261 8 50-261 8 50-261 6 50-261 6 50-325 8
	8103070621 8103110697 8103110706+ 8103170464 8103170464	50-470 NUREQ NUREQ 50-470 70-1100	A		8103050594# 8103050655 8103060233 8103060240 8103060321	50-325 S 50-261 P 50-261 G 50-324 G 50-261 R
	8103260630 8103260637• 8103300017 8103310684	70-36 TOPREP TOPREP 70-1100 70-1100			8103040328* 8103040763 8103040826 8103090413	50-261 R 50-261 8 50-261 8 50-400 0 50-400 0
California. State of	8103310690 8103020400 8103040265* 8103050712	70-1100 50-275 50-133 PROJ	С Н		8103090413 8103090413 8103090507 8103090509*	50-400 0 50-400 0 50-325 9 50-325 8

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR	٧	affiltatien	ACCESSION	TOBUBLE ROOSTAD	4
	8103090529 8103090582 8103090633 8103090633 8103100393	50-324 50-261 50-324 50-324 50-324	- - - - - - - - - - - - -	6 5 6	1103190384+ 8103190494 9103190502 9103190502 9103190502	50-261 50-261 50-324 50-324 50-324	9 1 1 1 1 1
	8103100393 8103100605 8103100605 8103100612*	50-324 50-324 50-324 50-324 50-324	J R R R	6 6	9103190506* 8103230297 9103230591 9103230591 9103230645	50-324 50-261 50-261 50-261 50-324	К С С С С С С С С С С С С С С С С С С С
	8103100518 8103100620* 8103110403 8103110424 8103110424	50-325 50-325 50-261 50-324 50-324	9 P P	5 6	3103230589 3103230705• 3103230720 3103230723• 3103230745	50-324 50-324 50-325 50-325 50-400	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
	6103110479 61031104634 0103110592 6103110595	50-261 50-261 50-324 50-324 50-324	Я Р Р	6	3103240076 3103240076 5103240210 3103240215* 3103240345	50-324 50-324 50-261 50-261 50-324	() () () () ()
	8103110595* 6103110597* (1103110597* 6103110600 6103110600	50-324 50-324 50-324 30-400 50-400	թ թ 5		3103240345 3103240352 3103240407 3103240459 3103240465*	50-324 50-261 50-261 50-325 50-325	F F S S
	B103110600 B103110600 B103110628 B103110679 B1031110683	90-400 90-400 90-261 90-324 90-325	8 6 6		8103240467 8103240472* 8103240491 8103240579 9103240584*	50-324 50-324 50-324 50-325 50-325	5 6 7 8 8
	0103110606# 0103110607 0103110691# 0103110692# 0103110716	50-324 50-325 50-325 50-325 50-400	8 P 8 8		8103240588 8103240590* 8103250286 8103250286 8103250286	50-325 50-325 50-324 50-324 50-324	5 R R R
	B103110716 B103110716 B103110716 B103120669 B103120669	90-400 90-400 50-400 90-324 50-324	8 F F		8103250289* 8103250605 8103250711 8103260501* 8103260521*	50~324 PR PR 50~400 50~400	Q Q
	8103130369 0103130384 0103130384 8103130510 0103130510	50-261 50-324 50-324 50-324 50-324	P P B B		8103240521+ 8103240521+ 8103240521+ 8103270534 8103270609	50-400 50-400 50-400 50-400 50-324	а в в
	8103130512 8103130517* 8103160150* 8103160437 8103160442*	50-261 50-261 50-261 50-324 50-324	д Р Р		B103270609 8103270649 8103270649 B103270666 B103270674*	50-324 50-324 50-324 50-324 50-324	P P S S
	8103160457 8103160459 8103160464* 8103160464*	50-324 50-324 50-324 50-324 50-325	р Р Р		8103270749 8103270757* 8103270762 8103270767* 8103200326	50-325 50-325 50-325 50-325 50-324	S S S S S
	0103160690# 0103160762 0103160765# 0103160771 0103160774#	50-325 50-324 50-324 50-324 50-324	8 8		8103303329* 8103310518 8103310544 8103310546 8103310568*	50-324 50-400 50-324 50-251 50-324	S A G G
	8103160786* 8103170380 8103170388* 8103170446 8103170449*	50-261 50-261 50-261 50-325 50-325			8103310629* 8103310682 8103310688* 8103310693 8103310703*	50-261 50-324 50-324 50-324 50-324	0 8 8 8
	8103170481 8103170484* 8103170621 8103170629* 8103170645	50-325 50-325 50-325 50-325	9 8 6	Caroline County, VA Case Hestern Cetholic Univ	8103310904 8103310904 8101070185* 8103160028* 8103130388	50-324 50-324 50-339 CONTRACT 50-77	P
	8103170652* 8103180410 8103180410 8103180425* 8103180635	50-325 50-324 50-324 50-324 50-324	Q Q Q	Center for Development Policy Center for Farm & Food Research, Inc Center for Law in the Public Interest	8012290534 8103050479 8103030557 8103050554 8103050554	XPORTL 10 FOIA 50-275 50-275 50-275	9
	8103180643# 8103180846 8103180882# 8103170130# 8103170136#		P F		8103050564 8103050564 8103120560 8103120560 8103120574*	\$0-275 \$0-275 \$0-275 \$0-275 \$0-275	00000
	8103190169# 8103190169# 8103190177# 8103190177# 8103190372	80~024 50~024	F F		8103120574* 8103130559 810326056 8103260720 8103260720	50-275 50-275 50-275 50-275 50-275	9090

Center For National Becurity Studies Central Power & Light Co	B103250750 B103260750 B103040805 B103190649#	50-275 50-275 FDIA 50-498	0	Coelition for Nuclear Power Plant Postponement Coelition for the Environment, St Louis	8103180918 8103190801 8103060451 8103120386	40-8714 40-8714 50-289 50-483
Cerac. Inc	9103180030*	40-8040		Region Coast Industrial Supply Co	B103031144#	0A999
	9103180024+ 8103180030+	40-8040 40-8040		Cole & Co.	8103040591*	50-289
Chackes & Hoare	8103181086 8103120386 8103130389 81030302660	XPDRTL IC 50-483 50-483 50-159	G O F	Colorado Bital of Mines Colorado Biete Univ	8103070059* 8103060271* 8103110315 8103110334	40-1162 50-267 40-299 40-299
Charlevote,MI Cherry, M. M. /Cherry, Flynn & Kanter Chicago Bridge & Iron Co	8103030659 8103250128	30-454 71-9143	Ġ		8103160327	40-279
Chickering & Gregory	B103050541 B103050548*	50-361 50-361	Q Q		8103160333 8103160343	40-279 40-8102
	B103050548+	30-361	0	Colorado. Stata of	8102240534*	A103 A103
	B103050555+ B103050555+	50-351 50-361	0		8102240703*	FOIA
	8103050560¢	50-361 50-361	0		8103050572* 8103100690	WABTE HO
	B103050565+	50-361	٥		8103250063 8103310553	PR Wabte Ho
	8103050565* 8103050571*	50-361 50-361	Q G	Combustion Engineering, Inc	8103050514	XPOATL10
	8103050571* 8103050576*	50-361 50-361	0		8103100573* 8103240537	50-317 50-470
	8103050576+	20-351	0		8103270474* 8103300380	50-317 30-470
	8103050581* 8103050581*	50-361 50-361	0 0		810330038[*	50-470
	8103130396 8103130396	50-361 50-361	0	Commerce. Dapt. of	8103170153* 8103170159*	20-350 20-350
	8103130448	50-361	0		8103170163 <b>+</b> 8103170167+	50-320 50-320
	8103130448 8103200664	50-361	0		8103170175*	FOTA
	8103200696 8103200722	50-361 50-361	9	Commerce,Dept.of, National Bureau of Standards	8103040646	40-4348
	8103260756	90-361	0		8103050408 8103050835	70-398 RES
	8103260756 8103260761*	50-361 50-361	G G		8103130533	50-184
Cincinnati Cas & Electric Co.	0103260761* 0102040393	50-361 50-358	0 F		8103240225 8103240233+	50-184 50-184
	8103100436	50-358	A	Commerce-Dept. of. National Marine	8103310925 8103190576	70-378 50-367
	8103110456 8103110768*	50-358 50-358	A A	Fisheries Service Committee to Bridge the Gap	8103230470	50-142
	8103160984* 8103170186*	50-358 50-358	Q F	Commonwealth Edison Co.	8101080014*	50-10
	8103200405 8103230120*	50-358 50-358	A G		8101080014* 8101080019* 8101080019*	50-10 50-10
	B103240419+ B103250138	50-312 50-358	F Q		8101080019#	50-10 50-10
	8103250185	50-358	Ä		8101080019* 8101080019*	50-10 50-10
	8103310213 8103310274	50-350 50-350	F A		8101080019* 8101080019*	50-10 50-10
	8103310383 8103310384•	50-358 50-358	K K		8101080019#	50-10
Citizen Action in the Northeast	8103230464	50-352	Ĥ		8101080019* 8101080019*	50~10 50~10
Citizens Against Nuclear Dangers Citizens Association for Sound Energy	8103260786 8103200562	50-387 50-445	0		8101080019* 8101080019*	50-10 50-10
•••	8103200562 8103200631	50-445 50-445	0		8101080017*	50-10
	8103230738	50-445	ğ		8101080029* 8101080029*	50-10 50-10
Citizens Concerned About Nuclear Power.	8103230735 8103200588	50-445 50-498	9		8101080033* 8101080033*	50-10 50-10
Inc.	8103200752	50-498	o		8101080033*	50-10
Citizens for Equitable Utilities Citizens for Fair Utility Regulation	81 03200588 81 03050769	50-498 50-445	0		8101080039* 8101080039*	50-10 50-10
	0103230647	50-449	o .		#84008006B*	50-10 50-10
Citizens for Total Energy Clark Equipment Co.	8103020581 8103030995	50-70 71-414	G		8101080068#	50-10
Clermont County. OH	8103031003* 8103200510	71-414 50-358	0		#8400801018 #8400801018	50-10 50-10
Clariford Clarker and all and a	8103200543	50-358	0		8101080048* 8101080068*	50-10 50-10
Claveland Electric Itluminating Co	8103090538 8103090564	50-440 50-440	8 6		8101080068*	50-10
	8103090564 8103090599	50-440 50-440	8 9		#8400801018 #8400801018	50-10 50-10
	8103090599 8103160576	80-440 50-440	B K		8101080048* 8101080068*	50-10 50-10
	9103160576 9103160576	50-440 50-440 50-440	K K		#101080008#	50-10
	8103160586*	50-440	Ŕ		8101220258* 8101230543*	50-10 50-10
	8103230050 8103230544	REGGD 30-440	К		8102030517 8103020357	TOPREP 50-454
Cleveland-Cliffs Iron Co.	8103230544 8103060835	50-440 40-8714	Ř		8103020369	80-10 50-10
					8103020369	30-10

*******************	74-6-6-6					
	8103020369 8103020373 8103020374+ 8103020374+ 8103020374+	50-10 50-254 50-10 50-10 50-10	R R R R	8103100349 8103100351* 8103100351* 8103100377 8103100384*	50-295 50-295 50-295 50-265 50-265	R R 8 8
	8103020381 * 8103020397 8103020397 8103020404 * 8103020404 *	50-254 50-295 50-295 50-295 50-295	त च त स स	8103100499 810310050& 8103100593 810310059& 8103110119	50-254 50-254 50-295 90-295 REGOD	8 8 8
	8103020487 8103020489* 8103020419 8103020668 8103030540	50-237 50-237 50-373 50-454 50-295	P P A Q P	8103110154 8103110367 8103110390* 8103110409 8103110494	50-273 50-249 50-373 50-454 50-237	А В
	8103030545 8103030545# 8103030545# 8103030592 8103030598#	50-275 50-275 50-275 50-265 50-265	የ የ 8 8	8103110701* 8103120548 8103120562 8103120647 8103130089*	50-237 50-237 50-374 50-373 50-454	8 8 8 0
	8103030769 8103030769 8103030769 8103030769 8103030769	50-10 50-10 50-10 50-10 50-10	v v v v	8103130241 8103130241 8103130353 8103130353 8103130353	50-295 50-295 50-10 50-10 50-10	P R R R
	8103030769 8103030769 8103030769 8103030769 8103030779	50-10 50-10 50-10 50-10 50-237	V V V B	8103130358# 8103130358# 8103130358# 8103130407 8103160373	50-10 50-10 50-10 50-237 50-237	R R R Q
	8103030783* 8103030792 8103030792 8103030792 8103030792	50-237 50-10 50-10 50-10 50-10	ម ក R R	8103160373 8103160373 8103160373 8103160373 8103160373	50-237 50-237 50-237 50-237 50-237	0 0 0
	8103030792 8103030792 8103030807* 8103030807*	50-10 50-10 50-10 90-10 50-10	ղ ብ ብ ብ	8103160630 8103160630 8103160657 8103160657 8103160666*	50-295 50-295 50-254 50-254 50-254	G G R R
	8103030807* 8103030807* 8103030807* 8103030807*	50-10 50-10 50-10 50-10 50-10	ក ក ក ក	8103140464* 8103170355 8103170355 8103170371 8103170371	50-254 50-254 50-254 50-10 50-10	R R Q
	8103030860 8103030860 8103030860 8103030860	50-237 50-237 50-237 50-237 50-237	P P P P	8103170371 8103170371 8103170371 8103170371 8103170371	50-10 50-10 50-10 50-10 50-10	0 0 0
	8103030860 8103030902 8103040701 8103040701 8103050140	50-237 50-454 50-295 50-295 50-10	р И Р Р	8103170374# 8103170374# 8103170465 8103170465 8103170468#	50-254 50-254 50-373 50-373 50-373	R R R R
	8103050140 8103050140 8103050140 8103050140 8103050140	50-10 50-10 50-10 50-10 80-10	V V V V	8103170468# 8103170496 8103170496 8103170509 8103170509	50-373 50-295 50-295 50-295 50-299	R P P P
	8103050140 8103050140 8103050140 8103050158 8103050158	50-10 50-10 50-10 50-237 50-237	V V V P P	8103170512* 8103170521 8103170528* 8103170531 8103170537*	50-295 50-295 50-295 50-249 50-249	P 6 6 8
	8103050158 8103050158 8103050583 8103050638* 8103060445*	50-237 50-237 50-373 50-295 50-10	6 6 6	9103170543 8103170548* 8103170580 9103170587* 8103180517	50-237 50-237 50-237 50-237 50-10	9888
	8103060481# 8103090549 8103090552# 8103090581 8103090581	50-10 50-249 50-249 50-10 60-10	0 8 1 J	8103180517 8103180517 8103180517 8103180531 8103180542#	50-10 50-10 50-10 50-237 50-237	6 to to
	8103090581 8103090581 8103090581 8103090581 8103090581	50-10 50-10 50-10 50-10 50-10	ป บ บ	8103180542# 8103180551# 8103180551# 8103180563# 8103180563#	50-237 50-237 50-237 50-237 50-237	6 6 6
	8103090618 8103090648 8103090683 8103100298 8103100349	50-254 50-237 50-440 PRM 50-275	J P B	8103180577+ 8103180618 8103180623+ 8103180745 8103200044	50-454 50-237 50-237 50-237 50-237	9 8 8 9

8103200264	80-23	7 G		8103270618	50-254	S
8103200284	90-23			8103270631*	50-254	S
8103200284 8103200351	50-23; 50-10	, 0 P		8103270663 8103300383	50-254 50-237	3
8103200351	50-10	P		0103300477	50-254	P
8103200351	5C-10	Р		8103300477	50-294	F
B103200351	50-10	P		8103300479+	50-254	ρ
8103200351 8103203351	50-10 50-10	P		8103300479* 8103300487*	50-254 50-254	P
8103200351	5C-10	P		0103310449	50-454	P K
8103500321	53-10	Р		8103310467*	50-454	ĸ
8103203351 8103200351	50-10 50-10	e P		8103310540	90-295	8
0103200351	5C-10	P		8103310558* 8103310613	50-295 50-10	8 1
8103200351 8103200351	50-10 50-10	P		8103310613	50-10	i
				6103310613	50-10	1
8103200369 <b>*</b>		P P		8103310613	50-10	1
8103200369*	50-10	p		8103310613 8103310613	90-10 01-06	I I
8103200369* 8103200369*		ъ Б		8103310613	50-10	i
				8103310950*	50-10	1
8103200369*		P		8103310620# 8103310620#	50-10 50-10	ī
8103200369		P		H103310620*	50-10	1
8103200369 <b>*</b>		P P		8103310620* 8103310620*	50-10 50-10	1
8103200369*	50-10	Р				
B103200369#	50-10	P	Community Public Service Co	8103310620* 8103310571	50-10 M18C	1
8103200369* 8103200574	50-10 50-10	P	Computer Microfilm International Corp	8103030185*	CONTRAC	
8103200574	50-10	Ÿ	Computer Systems Support Corp Connecticut Yenkee Atomic Power Co	8103261103* 9103030547	CONTRAC* 50~213	7   Q
B103200574	50-10	v		8103030994#	50-213	a
8103230793 8103230799	50-295 50-237	Fρ		8103000855	30~213	R
8103230799	50-237	P		8103030827# 8103030827#	50-213 50-213	R P
8103230886	50-295	Р		8103040502	50-213	p
8103240198 8103240198	50-237 50-237	P		8103060502	50-213	P
8103240198	50-237	P		8103070284 8103090414	50-213 50-213	Р Р
8103240198 8103240348	50-237 50-10	.p		8103070542	50-213	В
				U103090544*	80-213	8
8103240348 8103240348	50-10 50-10	R		8103040628	50-213	P
#C6C0450353#	50-10	R		8103090628 8103100565	50-213 50-213	P P
8103240353* 8103240353*	50-10 50-10	R		81031E0335	90-213	Р
0103240371	50-373	A		8103170344	50-213	R
B103240371	50-373	Α		8103170349# 8103170600	50-213	Ŕ
8103240390 8103240444	50-10 50-249	F S		8103170601	50-213 50-213	6
8103240450*	50-249	ã		8103170603 8103170604*	50-213 50-213	P G
8103240575	90-247	9				
8103240581 <b>=</b> 8103240711	50-247 50-237	8		8103200578 <b>*</b> 8103260557	50-213 50-213	Q P
B103250397	50-237	ĸ	Conner, Moore & Corber	8103300390	30-213	F
8103250397	50-373	×	Towns a college	8102040399* 8103080695	50-250 50-272	F Q
8103250400+ 8103250592+	50-373 50-10	K F		8103050847	27-39	
B103250692*	50-10	F		8103200707	27-39	
8103250692*	50-10 50-10	F		8103270502 8103270599	27-39 27-39	
B103250A92*			Conover & Associates, Inc. Insurance	8103160768	70-1621	
8103520945*	50-10 50-10	F F	Consolidated Edison Co. of New York	B101070354*	90-3	F
8103250692+	50-10	F		B101220618*	50-3	F
8103250692: 8103250692:	50-10 50-10	F		8102250439 8102250439	50-247 50-247	R R
8103250702+	50-10	F		8103020393	50-247	P
8103250702+	50-10	F		9103030707	50-3	P
8103250702* 8103250702*	50-10 50-10	F		8103030707 8103030707	50-3 50-3	P P
8103250702+	50-10	F		8103030712*	50-3	P P
8103250702#	50-10	F		8103030712*	50-0	-
8103250702 <b>+</b> 8103250702 <b>+</b>	50-10 50-10	F		8103030712* 8103030717*	50-3 50-3	P P
8103250702*	50-10	F		8103030720*	50-3	P
0103240137*	50-10	F		B103030720# B103030722	50-3 50-247	P P
8103261193 8103261193	50-10	Q			90-3	Р
8103261193	50-10 80-10	G G		8103030723# 8103030723#	50-3	P
8103261193 8103261193	50-10	G .		B103030733*	50-3	P P
3	50-10	G		8103030733* 8103030873	50-3 50-247	p

AUTHOR AFFILIATION	ACCESSION NUMBER	CAT	JECT EQCRY	AUTHUR			
	8103040483 8103040483 8103040736 8103050496 8103090067	50-24 50-24 50-24	17 0 17 0	AFFILIATION	#CCESSIC/ NUMBER 8102090418 8103090451 6103090482	CATE 50-15 FR PR 50-33	GORY 5 P
	8103100517 8103100517 8103100518 8103100518 8103100518	50-3	R R R R		8103103317 8103103321 8103100347 8103103469 8103100555 8103103555		5 P 5 P 7 A
	8103110611 8103130391 8103130391 8103130408# 8103130408# 8103130412#	50-24 50-3 50-3 50-3	7 6 P P F		8103100558 8103100558 8103110471 8103110474 8103110617	50-329 50-329	A A R R
	8103130412* 8103130412* 8103170274 8103170472 8103170620*	50-3 50-3 50-24; 50-24;	7 P 7 G		8103130019 8103130223 8103130367 8103130371• 8103130440	RECOD 50-155 50-255 50-255 50-329	R
	8103170323 8103200589 8103230578 8103230585* 0103240092	50-24; 50-24; 50-24; 50-24; 50-24;	, s , b , t		8103130440 8103130491 8103130491 8103160501 8103160528	50-329 50-329 50-329 50-255 50-155	A G P I
	8103240075# B103250246 B103260574 8103260587# B103270764	50-247 50-247 50-247 50-247 50-247	9 9 8		8103160528 8103160528 8103160538• 8103170611 8103170611	50-155 50-155 50-155 50-329 50-329	9 1 1
	8103270764 610330304 8103310341 8103310346* 8103310383*	50-247 50-247 50-247 50-247 50-247	þ		8103190111 8103190111 8103190111 8103190147# 8103190153#	50-155 50-155 50-155 50-155 50-155	Р Р F F
Construction Engineering Consultants, Inc Consumers Power Co.	8103040865 8103040871# 7905310449 8101090087#	71-413 71-413 50-155 50-155	P F		8103190351 8103190358 8103190358 8103200524 8103200524	50-155 50-329 50-329 50-329 50-329	9 0 0
	8101220231* 8103020210 8103020367 8103020367	50-155 50-329 50-329 50-255	F A A P		8103200639 8103200644# 8103200644# 8103200650*	50-329 50-329 50-329 50-329 50-329	A A A A
	01030303744 8103030781 8103030787 8103030788 8103030791*	50-155 50-155 50-155 50-255	9 8 6		8103200761 8103200761 8103230581 8103230581	50-329 50-329 50-329 50-329 50-329	A G Q H H
	8103030797 8103030804+ 8103030805 8103030810+	50-155 50-155 50-255 50-255	8 8 8	6 8 8	3103230632 3103230632 3103230636 3103231069	50-329 50-329 50-259 50-155	0 0 F 0
	8103040020 8103040645 8103040645 8103040649	50-329 50-329 50-329 50-329	8 8	6 8 8	103240120 103240412 103240418 103240423	50-155 50-255 50-255 50-255 50-255	F S S J
	B103040655 B103040667 B103040673* B103040677	50-329 50-155 50-155 50-329	6 R R 8	8 8 8	103240445 103240454* 103240454* 103240496	50-329 50-329 50-329	A A A
	8103040681 8103040686* 8103040692 8103040692	50-255 50-255 50-329 50-329 50-255	S S A A	8 8 8:		50-255 50-155 50-329	G P A A
	8103040769# B1030408B4 8103050256# 8103050269	50-235 PR 50-155 50-155	R F P R	8) 6) 6)	03260480 03260700 03260718	PR 50-155 50-329 50-329	<del>Р</del> Р А
	8103060550 8103060555* 8103060643 8103060643	50-155 50-155 50-155 50-329 50-329	8 8 A A	9) 8) 81	03260737 03260737 03260796	50-329 ( 50-329 ( 50-329 ( 50-329 (	A 0 0 0
	8103090391 8103090392	50-255 50-255 50-155 50-155	р Р	81 81	03270677 03270681# 03300476	50-255	3 5

AUTHOR AFF IL IATION	ACCESSION NUMBER	SJBJECI CATEGORY	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT . CATEODRY
Control Data Corp Converse, Davis & Associates Cotter Corp	8103310470 8103230689 8103270060* 8102190878 8103060663	SO-155 V FOIA CONTRACT WASTE MOT WASTE MOT	Ofctson, K B Doc-Bearch Associates Doherty, J F Don L Warner	8103190364 8103050826* 8103030057 8103040386 8103260099	50-341 Q PRM FOTA 50-466 Q 70-820
	0103110802 0103120348 0103120351> 0103140170 0103240462	40-8511 40-8511 40-8511 HASTE MOT WASTE MOT	Duke Paser Ca	8103270192* 8102170394 8103030073 8103030082 6103030714	CONTRACT TOPREP 50-413 0 50-269 0 50-369 P
Council on Environ-ental Quality Crawded Allience	8103240407 8103240414* 8103310935 8103110621 8103120385	WABTE MOT Wabte Mot Wabte Mot SO-155 Q SO-483 G		8103030714 8103030731 8103030734* 8103030751 8103030751	50-369 P 50-369 P 50-369 P 50-369 P
Creare, Inc. Critical Mass Energy Project D'Appolonia Consulting Engineers, Inc DC Association for Retarded Citizens Daedalwan Associates, Inc	8103250458 8103150391* 8103050127* 8103250498* 8103100007	NUREG 50-320 P FOIA CONTRACT RES		B103040044 B103040057# B103040078# B1030400B7# B103040629	50-413 0 50-413 0 50-413 0 50-413 0 50-369 9
Dairyland Power Cooperative	8103030830 8103030840* 8103050100* 8103060404 8103060469	50-409 P 50-409 P 50-409 Q 50-409 J 50-409 P		8103040632* 8103040699 8103040706* 8103040713 8103040720*	50-369 B 50-369 B 50-369 B 50-369 B
	B103090294 B103090429 B103090432 B103100499 B103100501*	90-409 F 50-409 P 50-409 P 50-409 S 50-409 S		8103090238 8103050417 8103050528 8103050528 8103050533*	50-488 0 50-369 0 50-369 P 50-369 P
	8103110666 8103110666 8103120067 8103130381 8103130382	50-409 8 50-409 8 50-409 0 50-409 R 50-409 R		8103050533* 8103060460 8103060498 8103060770 8103070278	50-369 P 50-287 P PR 50-369 B 50-269 R
	8103130413 8103160551 8103170645 8103170648* 8103170680*	50-409 F 50-409 F 50-409 P 50-409 P 50-409 G		8103090278 8103090285# 8103090304 8103090310# 8103090494	50-269 R 50-269 R 50-369 P 50-369 P 50-413 Q
Dames & Moore	8103200296 8103230182 8103310255 8102230694+ 8103030331+	50-409 G 50-409 F 50-409. P 40-4492 Contract		8103090494 8103090517 8103090517 8103090578 8103090578	50-413 0 50-369 F 50-369 F 50-369 P 50-369 P
Dauphin County, PA  David Witherspoon, Inc  Dawn Mining Co	8103250111+ 8103250116+ 8103270019+ 8103100363+ 8103040036	50-320 R 50-320 R 50-320 H 70-992 Habie Mst		8103090978 8103090978 8103090640 8103090640 8103090640	50-369 P 50-369 P 50-269 P 50-269 P
	8103040185 8103040456 8103050491 8103050753 8103261030	TOM STEAM TOM STEAM TOM STEAM TOM STEAM TOM STEAM		8103070758 8103070818 8103070818 8103100426 8103100428	50-413 9 50-413 9 50-413 9 50-369 9 50-369 8
Debevoise & Liberman	8103270146 8103020567 8103050656 8103050656	WABTE MOT 50-393		8103100435* 8103100439* 8103100441 8103100449* 8103100457	50-369 B 50-369 B 50-369 B 50-369 B
	8103050668 8103100352 8103170565 8103250541 8103250550+	50-445 0 PR 50-445 0 PR PR		8103100467 8103100484# 8103100494# 8103100367 8103110321	50-367 8 50-367 8 50-367 9 50-471 A 50-269 P
Defense, Dept of, Defense Intelligence Agency	8103270536 8103270590 8103230722*	50-445 0 50-369 0 FOIA		8103110321 8103110321 8103110321 8103110491	50-269 P 50-269 P 50-269 P 50-287 6
Defense, Dept. of. Defense Nuclear Agency  Delaware, State of	8103230717 8103230718*	50-170 G 50-170 G PR		8103110502+ B103110676	50-267 B
Delmarva Power & Light Co. Denver:Univ. of Dept. of Hater Resources. California. State of.	8103170526* 8103100282* 8103200062	50-171 I CONTRACT PROJ		8103110676 8103110676 8103120438 8103120438	50-269 0 50-269 0 50-269 P 50-269 P
Detroit Editon Co.	8102030455 8103050483 8103070612 8103110240# 8103120128	RE00D 90-341 A 90-341 B 90-341 A 90-341 0		6103120438 8103120445* 8103120445* 8103120445* 8103120806	50-269 P 50-269 P 50-269 P 50-269 P
	B103140422 B103140431 B1031404B2 B103140752	50-341 8 50-341 8 50-341 8 50-341 8		8103120836* 8103130133 8103130454 8103130456* 8103130481	50-269 G 50-369 G 50-369 B 50-369 B

	Ø103130487* Ø103130515 Ø103130515 Ø103130545	50-369 50-369 50-369 50-369	5 P P		8103050708* 8103050710* 8103050713*	50-334 50-334 50-334
	8103130545	50-369	P		8103050717* 8103050722*	50-334 50-334
	6103160189* B103160189* B103160189* B103160196* B103160196*	50-269 50-269 50-269 50-269	4 4 4 4		8103050730* 8103050736* 8103060171 8103060331* 8103060420	50-334 50-334 71-9096 50-412 50-412
	8103160196# 8103160480# 8103160498# 8103160510# 8103160746	50-269 50-370 50-370 50-370 50-413	F Q Q Q S		8103090060 8103090714* 8103100178 8103100578 8103100581*	50-334 50-334 50-334 50-334 50-334
	8103160851 8103160851 8103160961 8103170081 8103170103	50~269 50~269 50~369 50~369 50~269	0 0 0		B103100584 B103100586* B103100587 B103100589* B103120476	50-334 50-334 50-334 50-334 50-334
	8103170454 8103170457 8103180207+ 8103180478 8103200549	50-269 50-448 50-369 50-369 50-488	P A Q Q O		8103130559 8103130606* 8103130611* 8103160353* 8103160058*	50-334 50-334 50-334 50-334 50-334
	8103200611 8103230479 8103230479 8103230644 8103230644	50-249 50-369 50-359 50-269 50-269	F P P P		8103170071* 8103170078* 8103170147 8103170151* 8103170156	50-334 50-334 50-334 50-334 50-334
	8103230644 8103240332 8103240332 8103240332 8103240373	50-269 50-269 50-269 50-269	ն 6 6 6		8103170142* 8103170508 8103170517* 8103170577 8103170582*	50-334 50-334 50-334 50-334 50-334
	8103240393 8103240393 8103240398 8103240398*	50-269 50-269 50-269 50-269	P B P P		8103170589* 8103170608 8103170609* 8103190455* 8103190463*	50-334 50-334 50-334 50-334 50-334
	8103240398= 8103240455 8108240527 8103240527 8103240602	50-269 50-369 50-369 50-369 50-369	P P F F O		8103230228 8103230491 8103240194 8103240200* 8103240384	50-334 50-334 50-334 50-334 50-412
	8103240628* 8103240628* 8103240628* 8103240712* 8103240712*	50-269 50-269 50-269 50-269	G G G G		8103240408 8103240448 8103240509 8103240563 8103260565	50-334 50-334 50-334 50-334 50-334
	8103240712+ 8103240797+ 8103250584 8103260283 8103260472	50-269 PR 50-269 PR 50-269	0 Q		0103269676 8103260696* 8103260691* 8103260694 8103260697	50-334 50-334 50-334 50-334
	8103260492 8103260492 8103270590 8103270590 8103270684	50-269 50-269 50-369 50-369 50-269	6 0 0 0		8103260707* 8103300284 8103300289* 8103300302 8103310211	50-334 50-334 50-334 50-334 50-334
	8103270704 8103270704 8103270704 8103300318 8103300318	50-267 50-269 50-269 50-369 50-369	9 9 9	E. I du Pont de Nemours & Co . Inc EG&O Ideho. Inc.	8103310239 81033102394 813030500 8103050506 8103040661	50-334 50-334 NUREO NUREO 50-334
	8103300336 8103300355 8103300359* 8103310549 8103310549	50-369 50-369 50-369 50-269 50-269	р Р І		8103040567 8103040671 8103040575 8103040682 8103040685	50-287 RES RES 50-247 50-344
Duquasne Light Co.	8103310549 8103310438# 8103310770 8103310913 8103020385	50-269 50-269 50-369 50-269 50-334	8 0 1 1		8103040781 8103090449 8103090475 8103090588 8103090593	REG REG REG 50-298
	8103030861 8103040943 8103040943 8103040951# 8103050282#	50-334 71-415 71-415 71-415 50-334	P Q		8103100060 8103100087 8103100106 8103100144 8103100134	NUREO NUREO 50-295 REB REB
	8103050343* 8103050559 8103050603* 8103050702 8103050705*	50-334 50-334 50-334 50-334 50-334	ឲ ជ R R		8103110830 8103110836 8103170114 8103170136 8103170737	468 20-515 468 468

Author Appliation	ACCESSION NUMBER	TOSLBUS PRODOTAD	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBUECT CATEGORY
ETA Engineering, Inc Easteen Podes Co.	8103240583 8103310924 9103940727 8103130034* 8103310680	RES NUREG FDTA 70-1703 70-1703	Esson Nyclear Co . Inc (subs of Esson Corp )	8103040641 8103180792 8103180803* 8103030021	40-8102 40-8064 40-8664 TOPREF TOPREF
Easton, PA	8103190456 8103250267	50-289 0 50-289 0		8103030031* 8103030492 8103030503*	TOPREP TOPREP
Edasco Services, Inc. (subs. of Enserch Coep.)	8103030062* 8103170297* 8103200427	FOIA FOPREP		8103040922 8103041003 8103041011*	71-65A) 71-65Bl 71-65Bl
Bberjine Instrument Comp Bilert, Seamans, Cherin & Mellott	8103080316* 8103230923 8103020549 8103230708 8103250768	50-280 ff xp091L10 70-2909 70-2909 70-2909		B103090220 B103990646* B103160637 B103250713 B103270327	70-1257 40-8102 XPORTLIC PR XPDRTLIC
Ecological Analysts, inc Edgement, 83 Edison Electric institute Edio_ (nternational Co.	8103940215+ 8103260029 8103110577 8103050340 8103130255+	50-219 R WABIE MOT PR XPORTLIC 40-8760	FOI Services federal American Partners	8103310697 8103160815 8102230689 8103030858 8103030866#	30-364 A FOIA 40-4492 40-4492 40-4492
Edwards & Angelb Eight Rail Association	8100240698 8103310846 8103060384 8103040811* 8100040816*	XPDRTLIC XPCRTLIC 50-443 H FOIA FOIA	Federal Emergency Management Agently	8103260956 8103030894* 8103180040# 8103200666# 8103200675#	40-4492 55-275 G 50-275 G 50-289 T 50-289 T
Elactric Power Resparch Institute	8103040844* 81030408564 8103040855* 8103040861* 8103070437	FOIA FOIA FOIA TOPREP	Føderal Empløyer Denticare Program Fleischater. D. S Florida Power & Light Co	8103120819 8103030997 8103120560 8103260790 8103030094	FD1A 50-275 0 50-275 0 50-275 0 50-335 0
Energy Daily,Inc	8103100670* 8103180979* 8103190493 8103290595 8103050182	CONTRACT REVIEW ORP TOPREP PR CONTRACT		8103030817 8103030872 8103040742 8103040773 8103040781	50-389 6 50-389 6 50-290 3 50-335 3 50-389 9
Energy Engineering Group Energy Resources Co. Inc Energy, Dept of	8103100762* 8103050092* 8103020057* 8103040551* 8103040310*	CONTRACT FOIA 70-820 FOIA		8103050324* 8103050329* 8103060325 8103060622 8103060622	50-250 F 50-250 F 50-250 S 50-250 P 50-253 P
	8103050306% 8103060389 8103060820 8103090526 8103110462	HABTE MGT 71-9010 PR PR PROJ		8103090168 8103090400 8103090400 8103090530 8103090731	50-389 3 50-280 P 50-250 P 50-339 S PR
	8103130072* 8103190405 8103190806 8103240653 8103240677	HABTE MOT PR 71-5550 71-6400 HASTE MOT		8103100314 8103100314 8103100334 8103100339	50-250 P 50-250 P 50-250 P 50-250 P
	8103250A94 8103250759 8103260862 8103260991 8103261164+	PR PR 50-279 A Waste Mot Commission		91031105199 9103110510 9103110513* 9103110513*	50-250 F 50-250 F 50-250 F 50-250 F 50-250 F
Energy, Dept of, €linch River Breeder Reactor Plant	8103020529	PR 50-537 A		8103110663 8103110663 8103110472*	50-250 F 50-250 P 50-250 P
Energy Dept of Idaho Operations Office Engdahl & Renzo	8103160688 8103160136 8103100714#	ORG REB Waste mot		8103110572+ 8103110711 8103110711	50-250 P 50-250 P 50-250 9
Environmental Protection Agency	8103100731* 8102240548* 8103030717* 8103040338 8103050003			8103110714* 8103110719* 8103110719* 8103120081	50-250 R 50-250 R 50-250 R 71-6078
	8103040468 8103040782 8103090937 6103090942 8103230423	50-261 D PR PR PR 90-389 A 50-361 D		8103130350 8103130350 8103130350 8103130354* 8103130354*	
	8103230573 8103250094 8103260087 8103260659 8103270065	50-320 P PR		8103130394* 8103130361 8103130366* 8103130429 8103130585	50-335 8 50-335 9 50-387 A 50-335 6
Environmental Science & Engineering, In Envirosphere Co. European Communities, Commission of	8103300390	50-466 D CONTRACT		8103130592* 8103160554 8103160599 8103160712 8103160720*	50~389 A 50~389 A 50~335 B
Erron Minerals Co., USA	6103020077 610303030342 6103030352+	40-8054 40-8054		8103160731 9103160735* 8103160758 8103160758#	50-335 5

AUTHOR AFF IL. IAT I ON	ACCESSION NUMBER	SUBJE		AVII+E9	AG128300A	l Gun anns	
	8103180653+ 8103180653+ 8103180653+ 8103180653+ 8103200619	50-250 50-250 50-250 50-250 TGPREP	н н е	AFFILIATION Foster Weeler Corp Foundation for National Progress For Fart & Curningha-	A.1.247E/D	CATEGORY 71-9107 PR FGIA	
	8103230274 8103230318 8103230409 8103230617 8103230617	50-335 50-250 50-250 50-250 50-250	P G	Forboro Corp Franklin Institute/Franklin Research	8103360447 8103360415 810336619 910390373 8103360313	\$0-289 G * \$0-361 A * \$0-361 A PR	
	8103230631* 8103230631* 81032308531*	50-250 50-250 50-250 50-389	6 6 6	Center	8103130013¢	CONTRACT	
	8103240202 8103240249* 8103240249* 8103240368	50-250 50-250	g G	Friends of the Earth	8103130376# 8103240605# 8103030654 8103050662	ЯЕВ 50-213 р 50-70 0 50-70 0	
	8103250006* 8103250273 8103250276* 8103250550*	50-335 50-335 50-335	p G R R	Furgo, Inc	8103050780 8103230640 8103270479 8103270548 8103230903#	\$0-70 0 \$0-361 G \$0-70 G \$0-70 G \$0-443 A	
	8103260455 8103260543 8103260602	PR 50-389 50-250 50-335	R F F	Oarma Corp. General Atomic Co. (subs. of Qulf. □i) Co.)	810339188 8103261133#	CONTRACT 30-89 A	
Florida Power Corp	8103270879 8103270879 9E88075E018 810327883	50-250 50-250 50-250 50-250	թ թ թ		8103030825 8103050918 8103060726 8103090721	50-163 R	
	8103310376 8103310376 8103310380* 9103310380*	50-250 50-250 50-250	P P P		8103120164 8103120451 8103120457# 81031907[1	70-734 XPERTLIC Y0-734 70-734 XPDRTLIC	
	8103030040 8103030047# 8103030747	50-302 50-302 50-302	R R	General Atomic Co (subs of Gulf Oil Corp )	8103190715+ 8103040714	XPDRTL1C 70-734	
	B103040594*	90-305 90-305 90-305 90-305	0 H R G	Oomera) Electric Co	8103040719# 6103310635 6103310839# 81022600\$B	70-704 XPCRTL1C XPCRTL1C 71-9001	
	8103050844 8103060247 8103060503	20-305	<b>գ</b> գ թ		8102260067# 8102260351# 8102260535# 8102260747#	71-9001 50-333 p 50-333 p FOIA	
	8103060512 8103050514# 8103060818 8103070293	50-302 50-302 50-302	ե Ե Ե		8103020354 8103020359 8103020766 8103040461 6103040572*	XPORTLIC XPORTLIC 70-2745 71-5939 CONTRACT	
	8103090513* 5 8103090550 5 8103090551 5 8103100387 5	10-305 t 10-305 t 10-305 t	6 8 6 9		81 <b>0310</b> 0654	XPORTLIC SO-73 P NUREG XPORTLIC	
	8103110553* 5 8103110699 5 8103120301 5 8103120490* 5	0-302 P	• •		8103120820 8103130080 8103130085# 8103130427	TOPREP XPOATLIC XPORTLIC XPORTLIC 50-70 G	
	8103160697 5 8103160701# 9 8103160707+ 9 8103160705+ 5	0-302 s 0-302 s 0-302 s 0-302 s	3		8103130433 8103130435¢ 8103130442 8103130443*	50-70 0 50-70 0 50-70 0 50-70 P 50-70 P	
	8103170482 80 8103170486* 50 8103170947 80 8103170953* 50	0-302 P 0-302 S 0-302 S 0-302 S 0-302 S			8103130449+ 8103130975+ 8103160292 8103160428+	50-70 P 50-70 P 50-219 P (PORTLIC 50-290 P	
	8103170576* 50 8103230649 50 8103230737 50 8103230739* 50	-302 R			B103160B47# F 8103160B50# F B103160B55# F B103170143 5	00-70 P OIA OIA OIA 0-10 R	
pride. State of	8103240936# 50 8103240539 50 8103240541# 50 8103310392 50	-302 S -302 B -302 B -302 P			8103170266* 3 8103170638 5 8103170644* 5 8103180384 TI	0-18 R 0-10 P 0-183 R 0-183 R DPREP	
orida. Univ. of, Qainesville	8103190700 50- 8103060179# CDI 8103130461 50-	-335 H -250 P NTRACT -83 B -514 0		,	8103181137 70 8103181142+ 70 8103190409 70	OPREP 0-754 0-754 0-1308 0-1308	
		-514 g				0-1308 0-1308	

AUTHER AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8103200037 8103200221 8103200315 8103200323# 8103200580	70-1308 TOPREP TOPREP TOPREP TOPREP		8103160862 8103160862 8103170093 8103230707 8103230712	50-321 50-321 50-356 50-366 50-366
	8103200763+ 8103230518 8103230527+ 8103240230+ 8103250426	50-387 G 50-265 P 50-265 P 50-321 P PR		8103230716* 8103230721* 8103230746 8103230751* 8103230812	50-365 E
	8103250518 6103250651 8103260021# 8103261027 8103270587	PR PR 40-659 XP047LIC 50-70 0		8103230820* 8103230826 8103230833* 8103240222 8103240295*	50-366 ( 50-366 ( 50-366 ( 50-32( ( 50-32) (
General Electric Co., Nuclear Energy Products Div.	8103270796 8103270800+ 8103310666 8103310928 8103050235	XPORTLIC XPORTLIC 70-1308 70-754 70-1113		8103240295* 8103240509 8103240509 8103240668* 8103250139*	50-321 3 50-321 6 50-321 6 50-321 6
	8103100254 8103100262+ 8103120377 8103240647 8103250126	70-1113 70-1113 71-9070 71-5926 71-6458		8103250139* 8103250142* 8103260100 8103260100 8103260503	20-351 0 20-351 0 20-351 0 20-351 0
General Motors Corp.	8103250575 8103250687 8103250701 8103300058 8103051010	PR PR PR 70-1113 XPDRTLIC		8103260503 8103261174 8103261174 8103270062• 8103300268	50-321 9 50-321 0 50-321 0 50-321 0 50-321 P
General Motors Corp., Tere: Div	8103060032 8103261035 8103230161 8103230164# 8103240637	XPORTLIC XPORTLIC 71-219 71-219 71-219		8103300325 B103310447 B103310453* B103310459 B103310464*	50-424 A 50-366 R 50-366 R 50-321 R 50-321 R
General Public Utilities - OPU Service	8103030194 8103090594 8103100552 8103160396	PR 50-219 J 50-209 R 50-219 J	Georgia, State of Geotechnical Engineers, Inc Gerrany, Federal Republic of Getty Dil Co., Petrotonice Co. Div	8103310921 8103250755 8103100364* 8103240143* 8103180695	50-424 Q PR CONTRACT COMMIBSION 40-6659
George Hashington Unity Georgia Power Co	8103200794+ 8103020539 8103020545+ 8103020569 8103020575+ 8103020576	CONTRACT  50-321	Oilbert/Cornonwealth Cos.  Oolder Associates	8103160547* 8103160570* 8103270452* 8103050155* 8103050827*	50-395 A GA999 50-395 A FOIA CONTRACT
	B1030205B2* B103020614 B103020614 B103020709 B103030750	50-366 8 50-321 P 90-321 P 50-321 q 90-321 6	Gulf States Utilities Co.  Hall X-Ray Services, Inc	8103180569 8103230212 8103230223 8103250427# 8103090597	50-456 9 50-456 3 50-458 0 50-458 0 71-423
	8103030755+ 8103030755+ 8103030765+ 8103030869 8103030877+	90-321 8 90-366 6 90-366 6 90-321 8	HEW.Dept. of. Food & Drug Administration Mis. Dept. of. US Public Health Service	B103070597 B103070602* B103070602* B103070532 B102260562*	71-423 71-423 71-423 PR FOIA
	8103040193 8103040193 8103040199* 8103040199* 8103090390	50-321 R 50-321 R 50-321 R 50-321 R 50-366 B	Halprin Supply Co. Halterman.H L. Hanford Engineering Development Laboratory	8103180648 8103261069# 8103170673 8103270601 8103030821	50-259 H CONTRACT XPGRTLIC 50-70 Q NUREG
	8103090505 8103090505 8103090508* 8103090508* 8103100425	50-321 R 50-321 R 50-321 R 50-321 R 50-321 P	Hanover County, VA Hermon & Weise	8103100072 8101070210 8103060347 8103180556 8103180604	NUREQ 50-339 F 50-443 Q 50-289 Q 50-289 Q
	8103100425 8103100427* 8103100427* 8103100485 8103130458	50-321 P 50-321 P 50-321 P 50-321 P 50-326 8		8103190616 8103190616 8103190622* 8103190622* 8103200537	50-275 Q 50-275 Q 50-275 Q 50-275 Q 70-2623
	8103130460+ 8103130462 8103130464+ 8103130467 8103130469+	50-366 8 50-321 8 50-321 8 50-366 8 50-366 8	Harris - Toups. Associates Hawaii. State of Hezelton Environmental Sciences Corp.	8103260359 81032608694 8103160547* 8103250501 8103270482*	PR PR 50-322 E PR 50-282 R
	8103160466	50-321 P 50-321 P 50-321 P 50-321 P 50-321 B	Health & Human Services, Dept. of, Herrmann, H. Herrmann, R.E. Hill.Christopher & Phillips	8103270085 8103260160 8103170042* 8103180566 8103260788	NUREO 50-471 G 50-206 P 50-275 G 50-275 G
	8103160737	50-321 S 50-366 S 50-366 S	Hinderstein.C. Hittman Nuclear & Development Corp. (subs. Hittman Corp.)	8103260807 8103260845 8103050757 8103180270	90-275 0 50-275 0 50-466 0 71-5942

Homestate Mining Co House of Res	8103300007 8103020801+ 8103040699+ 8103090056 8103090084+	PR 50-327 50-275 PR PR	H H		8103050631 8103180967* 8103200714 8103230671 8103230724	50-357 50-237 27-39 27-39 27-39
	8103120615 8103130409 8103170276 8103170286 8103170682*	50-349 50-352 50-289 50-289 100F#	V Н Н	‡}}linois, Uni∨ of, Urbana-Champaign	8103250493 8103250586 8103260792 8103040750 8103040755+	PR FR 50-237 50-151 50-151
	8103180529 8103180536 8103190009* 8103200456 8103230849	50-358 50-369 50-289 50-275 50-369	0 О Н О	Indiana & Michigan Electric Co	8103310465 8103020626 8103050477 8103050485*	50-151 50-315 50-315 50-315 50-315
House of Rep. , Appropriations House of Rep. , Government Operations House of Rep. , Interior & Insular Affairs House of Rep. , Science & Technology	0103120344 6103050690* 0103050613* 6103110108* 8103261204*	50-461 COMM1581 50-320 COMM1861 CCMM1881	U ION		8103050485* 8103050624 8103050626* 8103100342 8103100346*	90-319 50-316 50-316 50-315 50-315
Housing & Urban Development-Dept of Houston Lighting & Power Co.	6103300014 8103260607 6103041023 8103041039 8103050004	PR 50-361 30-498 50-498 50-498	D A A		8103100340 8103100369* 8103100362 8103100566* 8103100572*	50-316 50-316 50-316 50-316
	8103050458 8103050658 8103050664 8103050829 8103050837	50-498 50-466 50-466 50-498 50-498	A Q S B		8103100577* 8103110098 8103170261 8103180123* 8103230354	50-315 8600 50-315 50-315 50-319
	8103050837 8103050862 8103050862 8103060337 8103060337	50-448 50-448 50-498 50-448 50-498	ម ម ម ភ		8103230795 8103230760+ 8103231076 8103250175+ 8103270689	50-315 50-315 50-315 50-315 50-315
	8103060535 8103090380 8103090350 8103090558	50-466 50-498 50-490 50-490 50-498	Q 5 8 A A	Indiana & Michigan Power Co	8103270694* 8103030831 8103060297* 8103180532 8103180540*	50-315 1 53-316 5 50-315 1 50-315 1
	8103103204 8103100209+ 8103100610	50-465 50-465 50-490	3 0 8	Indians, State of Industrial Testing Laboratory Services Corp.	8103130480 8103030880	50-367 71-33
	0103130414 0103160246	50-498 50-498	0	institute of Electrical & Electronic Engineers	8103200491#	CONTRACT
	8103190229 8103190411	REGOD 30-466	o	Institute of Nuclear Power Operations	8103030083*	REGOD FOIA
	8103190644 8103190644 8103190649#	50-498 50-498 50-498 50-498	9 9 9	Interior, Dept of	8103030089* 8103181154 8103040394 8103040320 8103250013	FOIA REOGD MISC 30-361 ( PR
	B103200290	50-498 30-498	K K	Interior,Dept of, Bureau of Land	8103090544*	TON STBAW
	8103200304# 8103200310#	50-498 50-498	K K	Management Interior Dept of Fish & Wildlife Bervice		PR 50-583
	8103200691 8103200691	50-498 50-498 50-498	Ж 8 8	Interior Dept of Geological Burvey	8103110320	30-367 50-263
	0103200755 B103200755	50-478 50-498	A A		8103260629 8103260629 8103260629	746-02 98 89
	8103230122 8103250620	50-498 PR	q	intermountain Technologies, inc. Internetional Energy Associates, Ltd.	6103310838* 6103050110*	CONTRACT FOIA
	8103250325 8103270559 8103270761 8103300168	PR 50-498 50-498 50-498	A F	lowe Electric Light & Power Co	8101070472* 8101230527* 8103030845 8103030850*	50~331 ( 50~331 ( 50~331 (
	B103300307 B103300339	50-466 50-498	B		B103040197	30-331 i
Haustan, Univ. of	8103310468 8103180749*	BO-498 REVIEW C	g 995		8103040487 8103040497* 8103050280	50-331 ( 50-331 (
Human Design Group Human Factors Society, Inc.	8103270463* 8103230083*	50-320 CONTRACT 50-322	р Г О		8103050567 8103050578*	90-331 50-331
Hunton & Williams	8103030870 8103030876# 8103030704 8103260136	50-322 50-322 50-463	0		8103090524 8103090525* 8103130041 8103170476	166-06 166-06 166-06 166-06
[chthyological Associates, Inc. ]]][neis Power Co.	8103100554* 8103090565	50-289 50-461 REGOD	8 8		8103170460# 8103170498	50-331 50-331
titimia State Contacts Consum	8103180961 8103190096# 8103240381 8103180962	50-461 50-461 NUREO	<b>Q</b> <b>A</b>		8103170504* 8103170566 8103170575* 8103180495	50-331 50-331 50-331
Illinois State Geological Burvey Bitinois, State of	8103020587 8103050596 8103050604	27-39 70-1308 70-1308			8103180499# 8103240216	50-331 50-331

AUTOCA AFFICIATION	ACCESSION	SUBJEC CATES		AUTHGR AFFILIATION	ACCERSION NUMBER	GUDJECT CATEGORY
		50-331 50-331 50-331 50-331 50-331	3 0 0 5 5	Kerr-McDee Corp	810390531 8103930423 8103930423 8103930553	PR 40-11027 40-13027 40-2061 40-11027
towa State of	8103690928 8103250483 9103250490+ 8103046850+	PR PR PR CENTRAC	:т	Kosh, Lauiselle, Lurito & Associates, inc Labouit: & Labouit:	0103030659* 0103090199*	50-302 1 50-392 1 60NTRACT 60NTRACT
	0103190167*	CGVTRAC	:Τ	Late County. DH	8103240594 8103160m9	50-440 9
teman Lancoln & Beale	8103053704 8103100347 8103180573 8103230632 8103260798	50-237 PR 50-454 50-229 50-329	G G G	Lancaster. PA Lawrence Livernore Laboratory	8103030810 8103030864 8103040100 0103040511	50-320 P NOREG NUREG NUREG NOREG
isonedis, inc. (subs. of Maesfield Enterprises, inc.)	61021705354	71-9013	ı		0103040948 0103040791#	NUREO FOTA
Tabiope Products Laboratories	8103130076 8103130076 8103180905 8103181103	XPGRTLI XPGRTLI XPORTLI XFCRTLI	c c		8103100076 8103110840# 8103120709#	NUREQ 50-007 P 90-051 R REU
Israel J. T. Baher Chemical Co. Lsubs. of Figherdschifterrell. Inc.)	8103181106+ 8103270041 8103316874	1 TROOK 1 JTROOK 1 JTROOK	C		0103120047 0103120033 0103200337 0103200243 0103260095	ACH NUREO NUREO NUREO 50-295 P
J G - Sylvestar Associates, Inc JBF Associates	6103120242 8103310574	71 - 406 NUREG		LeBoeuf, Lamb, Leiby & MacRae	0100000000	50-240 F
Vapan	8103040344 8103040472 8103050228 8103050887	XPCRTLI XPORTLI XPORTLI XPORTLI	C C		8103060740 8103110971 8103200938 8103270400	PR PR 50-220 0 50-215 2
Japan Atomic Energy Research Inst Wersey Central Power & Light Co	8103020547	XPORTL I		League of Women Voters of Greater York, PA		90-209 P
	8103040295 8103040298* 8103090273 8103100442 9103100450*	50-219 50-219 50-219 50-219 50-219	R F S S	Lebanon County,PA Lebanon Valley General Hosp Lebanon,PA Leeds, Hill & Jauett, Inc	0103190473 0103190500 0103190509 0103270570#	50-207 H 50-207 H
	8103100456	50~219	5	Lehigh Univ	0103190337 0103070467*	90-219 P 90-219 F
	8103100465+ 8103110703 8103110705+ 8103130564	50-219 50-219 50-219 50-219	S P P	Lockheed Missiles & Space Co. (evbs Lockheed Aircraft Curp 1 Lockwood, Reid & Rolger	810331081*	TOANTHACT
	8103130568+ 8103160557 8103160561+ 8103160565+ 8103160776	50-219 50-219 50-219 50-219 50-219	P P P P	Lodge, T.J Long Island Lighting Co	0100180626* 8100000754 9100000976* 8100050706 8100090401	50-440 0 50-022 A 50-022 0 50-022 A
	8103170105# 8103170110# 8103170633 8103170640# 8103200313	50-219 50-219 50-219 50-219 50-219	F 6 5		8100160000 8100160907 8100170170 8100100926	20~055 d 20~055 V 20~055 V 20~055 E 20~055 E
	B103240174 B103240362 B103240367* B103240515 B103240518*	50-219 50-219 50-219 50-219 50-219	R R P P		8103100502 0103100716 8103170521 0103200642 0103240235	20~235 V 20~355 € 20~355 V BC000 20~255 E
	8103240587 8103240592* 8103250417 8103250288 8103310207	50-219 50-219 50-219 50-219 50-219	9 6 F F	Los Alamos Scientific Laboratory Louisiana Power & Light Co	B103310299 B103060176+ B103060183+ B103260022 B103030603	50-322 A WARTE HOT NUREO 50-382 1
John A. Blume & Associates, Engineers	8103170503* 8103050059*	HISC FOJA			8103030545* 8103030708	50-382 I 50-382 A
(subs. URB Corp.)  Johnson Boils Engineering Co.  Jos. Dyson & Bons. Inc.	81030500694 8103260118* 8103050641	FDIA FOIA MISC			B103040498 B103040707 B103130417	50-382 A 50-382 6 50-382 8
Jaseph Cat Corp Justics.Dept of K-C Forest Products Corp Katat, M J	8103050647 81033004874 8103120855 8103130285 81032505734	MISC 50-254 50-206 XPORTLIC CONTRACT			0103170511 0103170514* 0103170516* 010317053B 0103170617	50-302 K 50-362 K 50-362 K 50-362 A 50-362 A
Kansas Gas & Electric Co	8103180680 8103180704 8103200640 8103200899 8103240132	50-482 50-482 50-482 REGGD 50-482	8 5 A		0103170623* 0103170627* 0103200747 0103230201 0103230221	50-362 G 50-382 K 50-382 K 50-382 A
Kansas Municipal Energy Agency Kansas Blate Univ Kentucky. Univ of Kent-HCGee Chemical Corp (subs of Kerr-KcGee Corp )	8103050689 8103310562 8103230071# 8103060773	50-402 50-108 CONTRACT PR	H P		8103230642 8103240046 8103240357 8103240378 8103260373	50-382 F 50-382 A 50-382 B 50-382 A
	8103250732	PR		Louisiana, State of	8103310870	50-382 8
	8103310918	70-925		Lowell, Univ. of	8103030639# 8103230142# 8103060235	50-362 1 50-458 A 50-223 6

## CORPORATE SOURCE INDEX

AUTHOR AFFIL [AT ] ON	ACCESSION NUMBER	JUBUR 10 J T A S		PCHTUA HOLTALLITAA	ACCESSION NUMBER	3000ECT
Lowenstein-Newman, Reis, Arelrad & Toll	8103050664 8103060705 8103090533 8103110577 8103190611	50-466 PR 50-331 PR 50-466	0 7 0	Marubens America Corp (subs of Marube	8102310452 8103310493	50-27 30-245 50-213 KPGRTLEC
	8103190544 8103190544	50-490	o	Corp )	e4960520018	
	8103170647 8103170647 8103170647 8103170647	50-498 50-498 50-498	9 9	Maryland. State of Massachusetts Institute of Technology	8103050752 8103230354 81033409194 81033510019 8103050799	
Lunsford-McKer & Associates, inc HD Color Photo HHB Technical Associates	8103230701 8103270442* 8103130273* 8103231058*	50-376 50-250 CGNTRAC CONTRAC	T		8103120142 8103120147* 8103170330* 8103180939*	PR 50-20 50-20 50-443 REVIEW GR
Hadison Gas & Electric Co Maine Yankee Atomic Power Co	8103240800* 8103270728* 8103030839 8103040612 8103040617*	50-237 50-305 50-339 50-309 50-309	9	Massachusetts Voice of Energy Massachusetts Hildlife Federation Massachusetts. State of	8103200625 8103170497 8103260160 8103200632 8103200632	50-269 50-269 50-471 50-449 50-443
	8103100217 8103100223 8103100248 8103100609 8103110634	50-309 50-309 50-309 50-309 50-309	R 8 F P	Matheson 9as Products	8103200637+ 8103200637+ 8103200759 8103260160 8103190709	50-443   50-443   50-471   50-471   XPORILIC
	8103160388 8103160448 8103160454 8103160505 8103160584	50-369 50-369 50-369 50-369 50-369	р Р Р	Mayer, Orawn & Platt	8103250336 •  8103250340 •  8103190409  8103200013  8103200020	REVIEW GRA REVIEW GRA 70-1308 70-1308 70-1308
	8103180589 9103180590# 8103200120 8103200400 8103230863	50-309 50-309 50-309 50-309	R F P V	Maywood, flJ McCotl.A.C McCutchen.Doyle.Brown & Emersen McCutchen.Hill Publications Go.	8103200025 8103200037 8103260072* 8103050769 8103260872	70-1308 70-1308 FDIA 50-445 PROJ
Maine, State of	8103240302 8103310194 8103310260* 8103310246 8103050570	50309 50309 50309 50309	0 0 0	Memphis State Unav  Hershan, J. L.  Metropolitan Edison Co	8103090292+ 8103310224 8103310230+ 8103130328+ 8102180347 8103020407	50~538 R 50~538 R 50~538 R CONTRACT 71~5026 50~320 P
Manufacturers Association of York,PA Mapleton Intervenors Mark II Dwners Oroup	81030505794 0103150635 8102270630 8103120336 0102060467	GEN 160 20-354 20-354 20-364 20-304	61 0 H		8103020413+ 8103020420+ 8103020439	50~320 P 50~320 P 50~284 G
Marsh & Hclennan.Inc . H & M Nuclear Consultants.Inc. Div	6105000569	50-09	J		8103030628 8103030628	50-289 P
	61 03040312 61 03040312 61 03040327 61 03040327	20-520 20-520 30-580 30-580			8103030662 8103030667# 8103030737 8103030829 8103030863	50-320 8 50-320 9 50-320 P 50-320 P
	81 0306 0330 81 0306 0330 81 0306 0339 81 0306 0339 81 0306 0348	50-250 50-250 50-257 50-257	* 1 1 0 1		8103030867* 8103030874* 8103040297 8103040309* 8103040485	50-220 R 50-220 R 50-220 R 50-220 H 50-220 P
	8103060351 8103060351 8103060362 8103060362 8103060368	50-348 50-348 50-272 50-272 50-259			8103040758 8103040767* 8103090520 8103060478 8103060586	50-289 R 50-289 R 50-289 P 50-320 P 50-289 S
	0103060416 8103060416 8103060424 8103060424 8103060442	50-348 50-348 50-335 50-335 50-348	ر ر ر ر		8103060591* 8103060628 8103100042 8103100051* 8103100219	50-289 B 50-289 P 50-320 R 50-320 R 50-289 Q
	8103060442 8103060450 8103060454 8103060511 8103060515	50-348 50-321 50-327 50-89 50-272	7 7 7		8103100365 8103100365 8103100370+ 8103100370+ 8103100431	50-287 R 50-287 R 50-289 R 50-287 R 50-380 P
	8103100437 8103110372 8103110447 8103110451 8103110616	50-321 50-346 50-250 50-302 50-259	רכנננ		8103100522 8103100556* 8103120282 8103120282	50-320 P 50-320 8 50-320 5 50-287 1
	8103110637 8103110651 8103110651 8103110680 6103110712	50-348 50-335 50-335 50-327 50-272	7777		8103120531 8103120539+ 8103130450 8103130452+ 8103130529+	50-320 6 50-320 6 50-287 0 50-287 0 50-287 1
	8103110712 8103130410	50-272 50-346	<b>J</b>		B103130538* B103130547*	50~289 T

ACCEGBION

NUMBER

6103130963\*

6103140719 6103170111 8103170139\* 8103170353 SUBJECT

CATEGORY

6

50-289 50-289 50-289 50-320 50-320

ACCESSION

NUMBER

8103130048

8103130048 8103130400 8103170075 8103170179

AUTHOR AFFILIATION SUBJEC CATEGO

50-416

50-416 50-416 50-416 50-416

POHTUA AFFILIATION

	@103170353	50-320	6		8103170144	30-416
	0103170387	50-289	1		0103170422	50-416
	#103170475 8103170518	50~320 50-320	F		8103170457 8103180228	50-416 50-416
	B103170534	20-350	P		8103180228	90-416
	8103170545	50-289	S		8103180944	RECOD
	8103170552*	50-269	6		8103230525	50-416
	8103170556 8103170558	50-320 50-320	9		8103230526 8103230541	50-416 50-416
	8103170363	50-320	8		0103230541	50-416
	B103170965#	50-320	5		0103230726	50-416
	B10317034B	50-289	8		8103230726	50-416
	8103170573+ 8103180466	50-289 50-320	9		Ø103240021 Ø103240037	50-416 50-416
	8103180475+	50-320	P		B103240615	50-416
	8103180541	50-289	Я		8103250441	50-416
	8103180949#	50-287	R		8103250441	50-416
	8103169686 8103180697*	50-320 50-320	P		8103260199 8103270701	PR 30-416
	B103190595	50-020	P		8103310400	50-416
	8103140958	50-2B9	G		B103310411	50-416
	8103190634	50-289	0		8103310463	50-416
	8103190641* 8103190690	50~289 50-289	F		8103310706 8103310714*	70-2936 70-2936
	8103200247*	50-289	F		8103310894	50-416
	B1032C0253*	50-289	F		8103310894	50-416
	8103200504	50-289	Ţ	Mississippi. Btate of	8103120303	State F
	8103230615 8103230620*	50-269 50-289	P	Mississippi Univ. of. Missouri Steel Castings Co.	8103100116 8103130302	NURES 71~408
	8103230694	50-320	P	·	8103130310*	71-408
	8103230703	50-320	P	Missouri. State of	8103170436	50-493
	0103230843	50-267	Ţ		8103260624	50-493
	8103240243 8103240250*	50-320 50-320	P	Missouri, Univ. of, Columbia	8103100418 8103100423#	50-184 50-186
	0103240256*	50-320	P		8103180552	50-18á
	0103240449	50-289	F		8103240471	50-186
	8103240543	90-289 90-289	0		8103240510	50-186 50-186
	6103240545 6103240501	30-269	T	Missourians for Bafe Energy	8103300297 8103120386	50-483
	8103250387	50-320	P P		8103130587	50-483 XPORTL
	8103270679	20-583		"Mitsubish: International Corp. (subs. of Mitsubish: Corp.)	0103100371	AFURTE
	8103270683+ 8103270691	90-289 90-289	P		#47E001E018	XPORTL:
	B103300257	20-350	Ř		8103230917	XPDRTL
	8103300264+ B103300292	50-320 50-320	Pi R		8103230747*	XPORTL:
				Mitsuf & Co. (U.S.A.), Inc. (Subs. of Mitsuf & Co., Ltd.)	8105580570	
	8103300387 8103310505	50-320 50-269	F		8103050798	XPORTL
	0103310801	50-289	P		8103050805*	XPORTL
Michigan State Univ.	8103310602* 8103100446	50-269 50-294	P	Montana, Univ. of	8103310830 8103170203	XP0ATL 50-123
			-	High veries Office. Dr	8103170203	50-123
Michigan Technological Univ	8103260829 8103040555*	50-294 70-820	F		0103170208*	50-123
Michigan: State of	B103050246#	50-155	F		8103170208#	50-123
Michigan, Univ of	8103240434 8103090495	30-341 Res	A	Mountain West Research, Inc. Mt. Sinel Medical Center New York-NY	8103190094# 8103050492#	CONTRAI FOIA
<del></del>				NUB Carp.	8103040357#	50-351
	8103160550+ 8103260351	CONTRACT MISC	Ī		8103040251*	50-528
Microtech Industries, Inc	8103050430	CONTRACT			8103110540#	9CC-06
Middle South Utilities, Inc. Mike Albert Leasing, Inc.	8103030008+ 8103261082+	COMMISSI			8103110478* 8103190279*	50-361 CONTRA
				NUSAC, Inc.	8103100257*	CONTRA
Hiller & Chevalier	8103270671+ 8103030385	€0NTRA€1 27~39		National Aeronautics & Space Admin.	8103020638	50-30
Minerals Exploration Co. (subs. of Union- Qil Co. of California)	8103240487	40-8584			B103020440*	50-30 30-30
are an ar agreements	8103240490	40-8584			B103020646# B103020651#	50-30
	8103240610	40-8584			8103020654* 8103030663	50 - 30 50 - 30
Minnesota Power & Light Co.	8103030774	50-416	8			
Minnesota, State of Mississippi Power & Light Co.	8103110301 8103020351	PR 50~416	q		8103030666* 8103030692	50-30 50-185
	6103020351	50-416	g		8103030674*	50-195
	8103030687	90-416	G	National Gypsum Co. Natural Resources Defense Council	8103180757 8103240123*	50-269 70-143
	8103030697	50-416	0	MARCON INCOME TAR DELAMES COOKETT		
	8103030725 8103030725	50-416 50-416	9	Navy, Dept. of	8103240869# 8103130305	PR 71-318
	0103030742	50~416	Α	meadingher or	8103130316#	71-310
	8103030785	50-416	8		8103180530 8103270623	71-671 70-120
					MILLIE / DAK	(V-16V

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOOR	t٧	AUTHOR AFFILIATION	ACCESSION	SUBJEC CATEGO	)RY
Navy.Dept of. Forces Afloat  Navy.Dept.of. Naval Research Laboratory  Nebraska Public Power District	8103040099 8103040107* 8103040115* 8103190743 8103030491	71-421 71-421 71-421 NUREO 90-298	R	Nissho-iwai American Corp North Carolina State Univ North Dakota. State of	8103310938 8103020599 8103030864 8103170522 8103090590	30-220 XPORTL1 30-111 30-111 PR	c v
	8103030503* 8103050490	50-298 50-298	R P	Northeast Nuclear Energy Co. (subs. of	8103020399	50-336	P
	8103050493 8103050649 8103090504	50-298 50-298 50-298	P F R	Northeast Utilities)	8103030904 8103030904 8103030909* 8103030909*	50~245 50-245 50~245 50~245	R R R
	8103090506* 8103110782* 8103130132 8103130375 8103130379*	50-298 50-298 50-298 50-298 50-298	R G F R		9103040630 9103040633* 9103050608 8103050610* 9103050612	50-245 50-245 50-336 50-336	8 8 8
	8103160418 8103160423# 8103190559 8103250120 8103260167	50-298 50-298 50-298 50-298 50-298	6 6 6		8103050616* 8103050676* 8103050676* 8103060502	50-336 50-336 50-245 50-245 50-213	9 8 8 8 9
New England Coelition on Nuclear	8103260770 8103260775# 8103261051 8103020414	50-298 60-298 50-298 50-443	R R Q		8103060502 8103090211 8103090337 8103090340*	50-213 50-336 50-245 50-245	ь ь
Pollution	9103060349	50-443	ø		8103090438 8103090628	50-245 50-213	P P
New England Small Business Investment Corp.	8103130425 8103230533 8103250529 8103270619	50-443 50-443 Fr Wabte Mg	r T		8103090628 8103100240 8103100398 8103100305 8103100510+	50-213 50-245 50-245 50-336 50-336	P G P & S
•	8103270628*	MARTE MO	T		8103110525	50-245	9
Naw Meilco, State of Naw York Univ. Naw York Univ. Medical Center Naw York,NY Naw York, State Univ. of, Buffelo	8103250073 8103020068 8103040792# 8103261132 8103261132	PR 50-247 FDIA 50-57 50-57	Н Р Ө		8103110705 8103120335 8103130428 8103160359	50-245 50-213 50-245 50-336	P P P
New York, State of	8103261139* 8103261139* 8103030717* 8103040736* 8103040890*	50-57 50-57 50-3 50-247 CONTRACT	P P D		0103170663 8103170666# 8103200475 8103230665 8103250325	50~245 50~245 50~336 50~336 50~245	R R P P
Newport News Shipbuilding & Dry Dock Co (subs of TENNECO Corp.)	8103060361 8103060369 8103120284 8103261000	PR PR Btate Pr 71-9033	a g		9103250391 8103250391 8103250391 8103260557 8103260557	50-213 50-213 50-213 50-213	F F P
Riegare Mohawk Power Corp.	8103030586*	50-220	P		8103270754 8103300360	50-245 50-213	Q F
	8103030688* 8103030753 8103030757* 8103040430	50-220 50-220 50-220 50-410	р 8 8		8103310395 8103300390 8103300390	50-213 50-213 50-245	F F P
	8103060212 8103060299 8103060309# 8103110571	be 20-550 20-550 20-550	Q R R	Northwest Utilities	8103310476 8103310482* 8103310482* 8103030746 8103090629	50-245 50-245 50-245 50-245 50-245	8 8 8
	8103120532 8103110998	50-550 20-550	8		8103050673 8103060691	50-245 PR	Ŗ
	8103120534* 8103120536 8103120539* 8103160462	50-220 50-220 50-220 50-220	9 9 1		8103130411 8103120431 8103130425	50-245 50-213 50-213	? ? ?
	8103160467# 8103160467# 8103160507 8103160575	50-220 50-220 50-220 50-220	1 P P		8103140359 8103170591 8103170594* 8103190403 8103250350*	50-336 50-336 50-213 FR	P # # P
	8103170628 8103170631+ 8103180463	50-220 50-220	8	Northeastern Research & Testing, Inc. Northeastern Univ.	8103030932 8103030939# 8103050724#	71-419 71-419 40-5293	
	8103180559# 8103200538 8103200547	50-220 50-220 50-410	0 0 B	Northern California Pauer Agency. California Btate of. Northern Indiana Public Bervice Co.	810303046 8103030685	PROJ 50-367	Я
	8103230654 8103230654	20-550	ğ	Monthaus Sucreme Short datates on.	B103030823	50-367	R
	8103240374 8103240520 8103250270 8103260799 8103270316	50-410 50-220 50-410 50-220 50-220	А 8 Р		8103090428 8103100478 8103240391 8103250247	90-367 50-367 90-367 90-367	A R R
	8103270361# 8103270710 8103270748 8103270780#	50-220 50-220 50-220	G P P	Northern States Power Co.	B101070552* B101070552* B101080283* B101080283* B101220571*	50-282 50-282 50-282 50-282	F F F
	8103300008+ 8103300008+	50-410 50-410	ŭ A		8101220591# 8103020083 8103020083	50-282 50-282 50-282	F 0 0

AUHOR AFFILIATION	ACCESSION AUMBER	SUBJECT CATEGOR	!Y	AUTHSR AFFILIATION	ACCEBBION NUMBER	SUA. CATE
	8103020438 8103020444* 8103030565 8103030565 8103030575*	50-263 50-263 50-282 50-282 50-282	R R R R		8103120485* 8103130726* 8103240288* 8103260306* 8103260871	20-20 70-14 70-14 70-14 70-14
	8103030575# 8103030587 81030305594* 8103030710 8103030730	50-282 50-263 50-263 50-263	А П Р Ј		8103270453 8103270835 8103270844 8103270849* 8103270893*	70~14 70~14 80~26 80~26 80~26
	8103030736 8103030739 8103030759 8103030828 8103030828	50~263 50~263 50~263 50~282 50~282	ر و و		8103300004 8103300021 8103300033 8103300181 8103300183	50 - 20 70 - 10 70 - 10 70 - 10 70 - 10
	8103030635* 8103030835* 8103050307* 8103050307* 8103050313*	50-282 50-282 50-282 50-282	ቴ ዩ ዩ	Nuclear Parkaging, Inc  Nuclear Safety Associates	8103040973 8103050431 8103170021 8103170032* 8103260826*	71-9: 71-9: 71-9: 71-9: F01A
	8103050618 8103050522* 8103090447 8103100206 8103100356	50-263 50-263 50-263 50-263	5 7 P P	Nuclear Bafety Oversight Committee Nuclear Servites Corp Nuclear Systems: Oamma Industries Div. Nuclear Transport & Storage: Inc O'Donnell & Associates, Inc.	8103270134* 8103050102* 8103160224* 8103180894 8103050049	F01A F01A C0NTF X60A F01A
	8103105361 * 8103130228 8103130228 8103130234 * 8103130234 *	50-282 50-282 50-282 50-282	8 F F F	Cak Ridge National Laboratory	8103050163* 8103050171* 7909070116 8102170111 8103020680	FOIA FOIA REB PR REB
	8103130463 8103170008* 8103170008* 8103170158 8103170158	50-263 50-282 50-262 50-282 50-282	9 F F P		8103030336 8103031067 8103031071 8103031084 8103031092	NUREC 50-36 RES RES REB
	8103170192 8103170343 8103170350 8103170350 8103180525	50-243 50-263 50-282 50-282 50-282	トソソチ		8103040491 8103050023 8103050032 8103050832 9103050839	NUREO REB RES RES
	8103190478 8103190485* 8103190661 8103200215 8103200215	50-263 50-263 50-263 50-263	R R Q 1		8103030846 8103051015 8103060195 8103090810 8103110465	RES RES NURE: NES
	8103200215 8103200222* 8103200222* 8103200222* 8103200446*	50-263 50-263 50-263 50-263 50-263	1 1 1 0		6103120761 6103120651 6103130005 6103160084 6103160473	REB REB REB REB
	8103200731 8103200736* 8103230766 8103230777* 8103230803	50-304 50-306 50-263 50-263	6 8 8 8 8		8103180432 8103200074 8103230106 8103230237 8103240835	RES RES NURE NURE NURE
	8103240253 8103240354 8103250131 8103250687 8103270477	50-262 50-263 50-263 50-263	P G G R		8103250256 8103250293 8103250629 8103250646 8103260030	NURE( NURE( NURE( NURE(
	8103270673 81032706754 8103300149 810330038 8103310178	50-263 50-263 50-263 50-263	18 19 19 19 19 19	Oak Ridge Univs Ogle Petroleum, Inc Obia Citizens for Responsible Energy Obia Univ	8103240134# 8103130457 8103310604 8103180629 8103190028#	COMM! 40-86 40-86 50-44 CONTE
	8103310178 8103310209 8103310209 8103310234 8103310337*	50-262 50-262 50-262 50-263 50-262	P R P R	Ohio, State of Ohmert Corp. Oblahoma Publishing Co. Daily Oklahomian -Oklahoma City Times	8103250509 8103250698 8103200903 8103120830	PR PR REGOL FD1A
Northrop Research & Technical Center Northwestern Univ Nuclear Assurance Corp.	8103310357* 8103300261 8103240936* 8103110652 8103110807	50-282 50-187 CONTRACT 71-9010 71-6698	R Å	Oklahoma Steel Castings Co.  Omaha Public Power District	8103110220# 8103030622 8103030844 8103030852#	71-43 50-28 50-28 50-28
Nuclear Dynamics Nuclear Energy Bervice, Inc.	8103170209 8103230121 8103240616 8103180802 81030902229*	71-6698 71-6698 XPORTLIC 40-8663 50-289	G		8103040508 8103090540 8103090541* 8103100070* 8103100091*	50-26 50-26 50-26 50-26
Nuclear Fuel Services, Inc. (subs. of Qetty Dil Co.)	8103110538• 810306066 <del>9</del>	50-338 71-6458	P		8103100100* 8103110571	50-20 PR
verty Diff Co. 7	8103110440 8103120482	50-201	R R		8103120350 8103180240 8103180512	50-20 50-20

AUTHOR AFFILLATION	ACCESBION NUMBER	SuBu CA7E	GORY	АЛТИСА			
	81031805164 81032301604 8103240108 8103240505	\$0-28 50-28	5 R 5 G	AFFILIATIO, Parsons. Brinterhoff, Quata & Douglas. Inc.	ACCESSION NUMBER B103240411	CATE	GORY
	8103270281 8103270407* 8103270416* 8103310446*	\$0-58	9 P 9 P 5 P	Pathfinder Mires Corp	8103040783 8103040768 8103050083 8103170467	40-22 40-22 40-65	59 59 22
Orange County, CA Orange County, VA Oregon State Univ.	8103310451* 8103110470 8101070204* 8103940700	50-28: 50-27:	5 Р 5 н 3 г		8103170470 8103261016 9103261022 8103310608 8103310630	40-44	72 72 59
	8103040710* 8103230500 8103230500	90-245 90-108 90-108	P R	Pennfield Corp Pennsylvania Power & Light Co	8103000A20 8103020410 9103020410 8103020425	50-269 50-367 50-367	ж к н
Oit Water Engineers, Inc Pacific Oas & Electric Co	0103230507* 8103230507* 0103230507* 0103230939*	50-106 50-106 50-106 CDNIRA	R R CT		8103020429* 8103030768 8103030768 8103030812 8163040273	50-367 50-387 50-387	A A S
	B103020514 B103020579 B103030883 B103030883	50-275 50-133 50-275 50-275 50-275	0 C C		8103090408 8103090615 8103090615 8103100192•	50-387 50-387 50-387 50-387 50-387	A A A
	810303088# 810303088# 8103030826 8103050233# 8103050273	50-275 50-275 50-133 50-133 50-275	Q R R		8103100368 8103100368 8103100443 8103100443	50-387 50-387 50-387 50-387	A A S S
	0103050018 0103050842 0103050842 0103050842	50-275 50-275 50-275 50-275	A 9 0		8103100523 8103100523 8103110702	50-387 50-387 50-387	A A S
	0103060279 8103120696 8103130401 9103130484	50-275 50-275 PROJ	A A		8103120460 8103120463+ 6103130385 9103130385	70-2937 70-2937 50-387 50-387	o G
	8103130404 8103130496 8103130496 8103130496 8103130500	50-275 50-275 50-275 50-275	0 0		8103130421 8103130421 8103180114 8103180594 8103200571	50-367 50-367 50-367 50-387 50-387	A A A E
	8103130500 8103130617 8103130621*	50-275 50-275 PROJ PAOJ	0		8103200751 8103200751 8103200757+ 8103200757+	50-387 50-387 50-387 50-387	G G G
	0103160130 0103160130 0103170403 0103170403	50-275 50-275 50-275 50-275 50-275	F A A		8103200763+ 8103230429 8103230429 8103230437+ 8103230437+	50-387 50-387 50-387 50-387	o K K
	8103170463 8103170463 8103170533 8103170533 8103170542	50-275 50-275 50-275 50-275 50-275	F F F		8103230819 8103230819 8103230831 8103230831	50-387 50-387 50-387 50-387 50-387	к о о
	8103170342 8103170615 8103170615 8103170665	50-275 50-275 50-275 50-275	A A A	; ;	8103230834 • 8103230834 • 8103230842 8103230842	50-387 50-387 50-387 50-387	9
	8103170669 8103180489 8103180929 8103200073#	50-275 50-275 RE02D PROJ	A 8	! 8	9103231091 9103240436 9103240436 9103270341	50-387 50-387 50-387 50-397	S A A
	8103200527 8103200678 8103230332 8103230332	50-275 50-275 50-275 50-275	A Q A	6 6	1103270341 2103270538 1103270538 1103270621	50-387 50-387 50-387 50-387	A A A
	8103230335* 8103230715 8103230715	50-275 50-275 50-275 50-275	A 0	6 8 8	103270621 103270637 103270637 103270668 103270668	50-387 50-387 50-387	A E E A A
	8103240386 8103240426 8103240443	50-275 30-275 50-133 50-275	A F P G	9 9 8	103270711	50-367 50-367 50-387	A A A
	8103260872 8103260877+ 8103300087	50-275 PROJ PROJ 50-275 50-275	Q A A	В 8 8	103270713 103270731 103270731	50-387 50-387 50-387	0 0 A
atific Legal Foundation atempter, Inc.	6103300311 6103310645 8103050651	90-275 50-275 PR CONTRACT	A F	8 9 8	103270734 103270737 103270737	50-387 50-387 50-387	I I A A

AUTHCR AFF ILLATICU	MUMBER CAT	BUECT TEGGRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR
	8103270797 50-3 8103270799 50-3 8103270802* 50-3 8103270802* 50-3 8103300314 50-3	387 A 387 A 387 A 387 A		91031704064 81031706064 91031706064 91031706064 91031706064	50-171 50-171 50-171
	8103300314 50-3 8103300382 50-3 810330382 50-3 8103310431 50-3	87 A 97 A 87 A		8103170606# 8103170606# 8103180164# 8103180223 8103180223	50-171 50-171 50-277 50-277 50-277
	8103310437 50-3( 8103310437 50-3( 8103310454 50-3( 8103310454 50-3( 8103310462 50-36	97 A 97 A 97 A		8103190168 8103190526 8103190526 8103190530* 8103190530*	50~277 s 50~352 k 50~352 k 50~352 k
	8103310462 50-38 8103310480 50-38 8103310480 50-38 8103310494 50-38 8103310494 50-38	17 A 17 A 17 A		0103190534 6103190534 0103190539 6103190539 0103190542	50-052 K 50-352 K 50-352 K 50-352 K 50-352 K
	8103310501 50-38 8103310501 50-38 8103310511 50-38 8103310511 50-38 8103310532 50-38	7 A 7 F 7 F		8103190542 8103190545 8103190545 8103190547 8103190547	50-352 K 50-352 K 50-352 K
Pernsylvenia State Univ	8103310532 50-38; 8103310545 50-38; 8103310545 50-38; 8103310528 50-38; 9103310628 50-38;	A A A		8103190549 8103190549 8103190552 8103190552 8103190555	90~352 K 80~352 K 50~352 K
Pennsylvania. State of	8103060609 50-5 8102270590 50-17 8103050620 90-289 8103050623 50-289 8103050653 50-289	T T		9103190555 8103190556 8103190556 8103190558 8103190558	50-352 K 50-352 K 50-352 K
	8103050671 50-289 81030506779 50-289 8103050709 50-289 8103190435 50-289 8103190628 50-289	т т н о		8103170360 8103170360 8103170363 8103170363 8103170366#	20-325 V 20-325 V 20-325 P 20-325 P
sople for Energy Progress	B1032004B7 50-289 B103200715 50-289 B103250017 PR B103250021 50-289 B103270021 50-320	о н		8103190369 8103190369 8103190370# 8103190570# 8103190571#	50-352 A 50-352 A 50-352 A 50-352 A
feffertarn & Cooley, P A hiladelphia Electric Co	8102230839 50-70 8103260395 50-488 8103020645 50-277 8103040651 50-277 8103050218 50-277	G G P S R		8103190571# 8103190574# 8103190574# 8103190577	50-352 A 50-352 A 50-352 A
	8103050218 50-277 8103050222* 50-277 8103080222* 50-277 8103080452 50-277 8103100252 50-352	R R G Q		8103190582 8103190582 8103190586 8103190586	80-352 K 80-352 K 80-352 K 80-352 K
	8103100621 50-278 8103100623 50-277 8103100624 50-277 8103100626 50-277 8103100630 50-277	8 8 8		8103190588 0103190891 8103190891 8103190894	90-352 K 90-352 K 90-352 K 90-352 K
	8103110170 RE00D 8103110495 50-278 8103110599 50-277 8103110640 50-277 8103110644 50-278	8 8 P 8		8103190598 5 8103190598 5 8103190602 5 8103190602 5	0-352 K 0-352 K 0-352 K 0-352 K 0-352 K
8103110658* 8103110729 9103120367 8103120367 8103130051	8103110729 50-278 8103120367 50-277 8103120367 50-277 8103130051 REGOD	9 8 V V		8103190405 5 8103190405 5 8103190480 5 8103190480 5	0-352 K 0-352 K 0-352 C 0-352 C
	8103130242 50-277 9103130503 50-352 8103130507 50-277 9103170560 50-277	F F A P J		8103190682# 86 8103190683# 86 8103190686# 86 8103190686# 86	0-352 C 0-352 C 0-352 C
	8103170584 50-171 8103170584 50-171 8103170584 50-171 8103170584 50-171	J 1 1 1		8103190659* 50 8103190659* 50 8103200065* 00 8103200330 50	-352 c -352 c -352 c -277 o -277 a
	B103170584 50-171 B103170584 50-171 B103170584 50-171 B103170584 50-171 B103170606 50-171			8103200478 50 8103200478 50 8103200520 50 8103200520 50	-277 F -277 F -277 P -277 P -352 A

AUTHCR AFFILIATION	ACCESSION NUMBER	SUBJI CATE		AUIHOR			
	8103260136	50-46		AFFILIATION	ACCESSION NUMBER	8v9./E 03143	
	8103260271 8103260604 8103270015	PR 50-35;	? A		8103030729		 Р
	8103270403	50-352 50-27			8103030733. 8103030753. 9103030808	30-3	P
	8103270403 8103270414#	50-27; 50-27;			8103333894	50-285 50-333	5 P
	8103270414+ 8103270424+	30-27	ρ		8103040483 9103040483	50-247 50-247	
	8103270424*	50-277	ρ		8103040525 8103040541	50-286 50-286	p
	8103300305 8103300305 8103300308	50-35 50-35	a		8103340660 8103640697	50-285	
	8103300316 8103300316	50-276 50-352 50-352	5		8103050311	50-286 50-333 53-333	P R R
	8103300342	50-277	-		8103050752. 8103060396	50-233 50-286	g F
Physicians for Social Responsibility	8103310642 0103050850	50-277 50-356			8103050432	50-285	Q.
pictard Lowe & Garrick, Inc. Pickard Lowe & Garrick	0103020220* 0103170130*	30~329 50~329	A		8103050443 8103050393 8103100203	50-284 PA	Q
Pitteburgh, Univ. of Plateau Resources, Ltd	8102260677 <b>•</b> 8103040464	FOIA			8103100755	20-586 20-333	GI R
	8103050186 8103050186	40-869 40-785 40-786	9		8103100527• 8103100534•	20-596 20-586	R
	0103100027	40-867			8103110528• 8103110532•	50-286 50-286	Q Q
and the formula managed all Great have t	8103180027 8103200118	40-867 40-869			8103110534+ 8103110555	20-559	a
Pollution & Environmental Problems. Inc Pollution Environmental Problems Porter County Chapter Intervenors	0102020293 0103270721	PR 30-295	٥		8103110557+ 8103110571	50-333 50-333 PR	s
filter general phoposis transcribing	0103050685	50-367	Q		8103130387 <b>•</b>	50-333 50-333	P A
Portland General Electric Co	8103020552 8103020562	50-367 50-367 50-344	0 8		8103130534	90-333	Þ
	8103020565* 8103030646	50-344 50-344	8		8103130348• 8103130363•	50-333 50-333 50-286	P P
	0103030861#	50-344	8		8103160687.	30-286	R R
	8103030841 8103030848* 0103030568	50-344 50-344	R R		8103160726 8103160729+	50-333 50-333	9 S
	G103050790	50-344 50-344	b b		8103160739 8103160742# 8103160743	50~333 50-333	5 5
	8103090594 8103110376	50-344 50-344	p ال		8103160744+	50-333 50-333	s S
	0103160037# 8103160042#	50-344 50-344	F		8103170381 8103170646	50-285 50-333	P S
	8103160673 B103160678	50-344	R		8103170451 <b>+</b> 8103190494	50-333 50-333	8
	0103170317 0103170440	50-344 50-344 50-344	9 8		8103230264+ 8103230552	50-333 50-333	G G
	0103170474 0103170600	50-344 50-344	F P		8103230558+ 8103240195	50-333 50-286	G F
	8103190492	50-344	н		8103240441	50-333	S
	8103200240 8103200254# 8103200264#	50-344 50-344	P		8103240447# 8103240523 8103240396	50-265	5 P S
	0103200551	50-344 50-344	9		8103240603+ 8103260515	50-333	9 5
	8103200555* 8103200560*	50-344 50-344	P P		8103260527+	50-266	5
	8103230204 8103231108	50-344 50-344	G G		8103270669 B103270736+ B103270738+	\$0-333	Q F F
	B103240349 B103240814	50-344	F		B103270764		P
	0103240592 0103270635	50-344 50-344 50-344	F P P		B103270764 B103270813#	50-333	P Oi
	8103270740 8103270770+	50-344 50-344	ь Б		B103310487 B103310491* B103310664	50-286	P P
Power Authority of the State of New York	B103270773*	50-344	P				s s
TOTAL POST OF THE STATE OF NEW YORK	8102260568 8102260570*	50-333 50-333 50-333	ь Б	Power Piping Co. (Subs. Harian Electric Co. 1	8103190002+	QAP99	_
	B102260372# B102260375#	50-333	þ	President of UB & Executive Offices	B103050864	PR	H
	8103020376 8103020383#	50-333 50-333	P			COMMIBSIO:	
	8103020371# 8103020471	50-333 50-286	P P		B103270010*	COMMISSION FOIA	
	B103020495#	50-266	P P	•	<b>9103530458</b> •	01881MM03	
	8103030565 8103030560# 8103030569#	50-286 50-286	P P			FOIA 30-247 (	۰
	8103030707 8103030707	50-3 50-3	Ъ Ь	Public Interest Research Group. Hashington		FOIA	•
	8103030707	50-3	P	Public Bervice Co. of Colorado		PR 50-267 (	8
	8103030712# 8103030712#	50-3 50-3	P P P			30-267 E	8
	8103030712# 8103030726#	50-3 50-3	ŕ			50-267 F	

AUTHT# AFF1U1AT1GH	ACCESSION NUMBER	SUB-E		AUTHOR AFF IL JATION	ACCEGGION FIGHBER	CATE
	8103330744 8103030843 8103340634 8103350013• 8103350276	50-267 50-267 50-267 50-267	P V		8103170271 8103170271 8103170313 8103170315 8103170378	
	8103050300 8103060284 8103060605 8103100481 8103100483•	50-267 50-267 50-267 50-267	R R R R		0103180537 8103180564 8103180568 8103180113 8103180763	90-39
	8103100579 8103100509 8103100204 8103100626+ 8103110524	50-267 50-257 50-267 50-267 50-267	5 S R R S		H1002009094 B100230401 H100230509 H100230713 B100230713	50~25 50~27 90~11 90~27 90~27
	8103110527 • 8103110554 8103110792 • 8103160492 8103160699	50-267 50-267 50-267 50-267 50-267	1 0 6		0100240960 0100240706 0100240706 0100250424 0100250665	50-273 50-273 50-273 50-273 PR
	8103160703* 8103180785 8103190055 8103240476 8103240480*	50-267 50-267 50-267 50-267 50-267	1 F P P		0100010091 0100010626 0100010602# 0100010711 0100010710#	50-274 50-274 50-274 50-272 50-274
	8103240669 8103300001 8103300067 8103300174* 8103300192*	71-6347 PR 50-267 50-267 50-267	F F	Puerto Rico Water Resources Authority Purdue Res∍erch Foundation Purdue Univ	0109310724 6109310730* 0109300743 8109040764* 0109040990	90~272 90~272 90~076 00*184 NUMEO
Public Service ic of Indians, Inc	6103310737 6103310744* 6103040725 6103040725 8103050589	50-267 50-267 50-546 50-546 50-546	8 8 8 8	Guad City Testing Laboratory Radiation Research Associates Radiation Technology	8103250469 8103250470* 8103020707 8103090007 810309087	71 - 425 71 - 425 NURLO 71 - 420 71 - 420
	8103050589 8103050681 8103050868 8103050858	50-546 50-546 50-546 50-546 50-546	А Н С С В	Randolph Associates. Inc Reactor Experiments. Inc Relat Graup. Inc	6163096991= 0103090091= 0103170319= 0103020708 0103261082=	71-420 71-420 27-39 XPG91L CONTRAC
	8103110571 8103130028 8103180710 8103180716• 8103190211•	PR REQGD 50-546 50-546 50-546	1 1	Rensselær Polytechnic Inst	8100030157# 8100090815 8100120240# 8100180959# 8100190572	CONTHAC NUREG CONTRIAC REVIER 50-225
Public Service Co. of New Hampshire  Public Service Electric & Gas Co. of New Jersey	8103040502 8103180310 8103270405* 8101070333*	50-443 50-443 50-443 50-272	0 8 9 F	Resource Co-munities.Inc Reuter-Stokes, Inc. Rhode Island, Btate of	8103070136# 8103170798 8103050841 8103180297 8103170025#	CONTRAC XPORTLE State P State P 70-920
	8102280182 8103030004 8103030009± 8103030012+ 8103030678	50-219 50-272 50-272 50-272 50-272	P P P P	Rhodes, Q. Rso Algori, Ltd	8103270667 8103270604* 8103160479 8103250740 8103250695	50-193 CONTRAC 40-8084 40-8084 40-8084
	8103030682* 8103030762 8103030767* 8103030772 8103030775*	90-272 50-272	88888	Riverside, CA  Rachester Que & Electric Corp	B103110684× B103110775× B103130046 B1030308784 B103030813	50~351 50~351 PROJ 50~244 50~244
	8103050208 8103050344+ 81030503344+ 8103050331+ 8103050351+	50-272 50-272 50-272	р Г Г Г		8103030816 6103030819• 6103060199 6103090423 61030904294	50-244 50-244 50-244 50-244 50-244
	8103050698+ 8103060464 8103060464 8103060471 8103060471	50-272 50-272 50-272	G G G		6103070931 6103100378 6103100447 6103100520 6103100560	30-244 50-244 50-244 50-244 50-244
	8103060744 8103090554 8103090556*	50-272 PR 50-272	R R & B		8103170418 8103170421 8103200423 8103200978 8103200984	50-244 50-244 50-244 50-244 50-244
	8103100151± 8103110106 8103110379 8103160468				8103200597 8103200598= 8103250242 8103250619 8103270707	50-244 50-244 50-244 50-244 50-244
	B103160515	80-272 F 80-272 F 80-272 F 80-272 F	3	Rockwell International Corp. Rocky Mountain Energy Co	8103300283 8103070347 8102260105 8103051016 8103100628	50-244 50-329 40-8390 40-8390 40-8396

AUTHOR AFF ILLIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY	AUTHOR AFFILIATION	accesbiun Munder	BUHLEC CATEOC	
	8103100628 8103100631* 8103100631* 8103260701 8103260705*	40-8390 40-8380 40-8380 40-8380 40-8380	•		8103110690* 8103110690* 8103110736* 8103110736* 9103110744*	50-361 50-361 50-361 50-261 50-361	] [ ] ] ]
Roges & Gray	8103040488 8103040402 8103130414 8103170937 8103170914	50-471 50-443 50-471 50-471 50-471	G G G		8103110744* 8103110748* 8103110748* 8103110751* 8103110751*	50-351 50-361 50-361 50-361 50-361	1 1 1
Roswell Park Memorial Institute  Rotort Controls. Inc	8103180864 8103180873# 8103180880# 8103230645 8102270563	90-320 90-320 90-320 9721 9721	<b>բ</b>		8103120557* 8103120557* 8103120559* 8103120559* 8103120717*	50-061 50-361 50-361 50-361 50-361	K K K K
STC Systems.Inc Secremento Municipal Utility District	8103110204* 8103030982 8103030735 8103030740* 8103030761	40-8610 80-312 50-312 50-312 50-312	r 6 8		8103120717* 8103130396 8103130396 8103130448 8103130448	50-361 50-361 50-361 50-361	x 0 0 0
	8103030766# 6103030813 8103030820# 6103040016# 8103040320	50-312 50-312 50-312 50-312	9 8 6 0 P		B103170639• B103203664 B103200664 B103200696 B103200696	50-361 50-361 50-361 50-361 50-361	A 60 0 0 0
	8103040A37 8103040748 8103050550# B103100548 8103110362	50-312 50-312 50-312 50-312 50-312	8 0 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Sen Diego.Univ of. Ban Luis Obispo Mothers for Peace	8103200722 8103200722 8103270238+ 8103130526 9103050534	50-361 50-361 70-2682 50-361 50-275	0
	8103110384 0103110580 9103110544 0103120391 9103130561	50-312 50-312 50-312 50-312	P J P 1 8		8103050554 8103050564 8103050564 8103120560 8103260720	50-275 50-275 50-275 53-275 50-275	00000
	8103130584 8103130595* 8103130600 8103130608* 8103170442	50-312 50-312 50-312 50-312	8 3 8 9 u	Sandia laborataries	8103300392 8103020674 8103030308 8103030353 8103040615	50-361 NUREO NUREO NUREO 50-207	H P
	0103170647 8103170649# 8103170657 8103170661# 8103170664	50-312 50-312 50-312 50-312	R R G & B		8103050373 8103050869 8103060587* 8103060589*	RES RES 50-413 50-413 RES	٨
	8103170467# 8103180462# 8103180954# 8103190567 8103190568#	50-312 50-312 50-312 50-312	8 0 0 R		8103100179 8103120850 8103230073# 8103230261 8103260364	NUREO RES SO-369 NUREO WASTE MO	.p.
	B103230728 B103230732# B103240417 B103240453 B103240457#	50-312 50-312 50-312 50-312 50-312	6 8 F 8 6	Sandvik Special Metals Corp Bandwich: IL Sargent & Lundy, Enc. Bargent Industries: Sweeney Div	8103050597 8103050875* 8103230034 8103300281 8103180605	0117809X 1791-07 00098 835-06 117809X	A
	8103240460 01032404634 8103260108 8103270519 0103310561	50-312 50-312 50-312 50-312	3 6 0 F 8	Scandpower Inc. Scenic Shoreline Preservation Conference, Inc. Schieft Hendin & Waite Schieft Hendin & Waite	8103200587 0103160311	CONTRACT 50-275 50-441 71-403	o e
Safe Energy Alliance Belimbury.MA	8103310967* 8103310603 8103030692 8103180642 8103200659*	50-312 50-312 70-2909 70-2909 50-443	g 3	Schott Optical Olass, Inc Beignee Applications, Inc.	8103240564 8103240564 8103100164* 8103040740* 8103050074* 8103050119*	71-403 71-403 40-7924 CONTRACT 50-259 FOCA	
San Antonio: TX San Clemente: CA San Diego Gas & Electric Co.	8103190649# 8103020434# 8101090104# 8101090104# 8103050367#	90-498 50-361 90-361 50-361 50-206	0 F F F	Scientists & Engineers for Secure Energy Senate	8103110794* 8103130686* 8103181001* 8103200068* 8103050024	CONTRACT CONTRACT CONTRACT COPMISSION	
	8103050548* 8103050548* 8103050555* 8103050555* 8103050560*	50-361 50-361 50-361 50-361 50-361	0 0 0 0		8103110364* 8103120330 8103130444* 8103180649 8103180479	30-311 50-369 50-247 50-250 50-329	H H H
	8103050560# 8103050565# 8103050571# 8103050571#	00-361 160-361 160-361 140-96	0 0 0	Sensible Maine Power	8103230595 8103230675 8103270137 8103300300 8103030514	50-546 80-466 PR 50-458 50-309	OH DO
	8103050574# 8103050576* 8103050581# 8103050581# 8103110684#	50-361 50-361 50-361 50-361 50-361	0 0	Shaw. Pittman. Potts & Trowbridge	8103020439 8103020560 8103030566 8103130385	50-289 50-289 50-220 50-387	0

R9HTUA	ACCESSION	CATEGORY		APP (LIAITON			-
AFFILIATIC9	8103130450 8103130450 8103130522 8103190534 8103200538	50-289 50-289 50-289	- G T Q Q	South Datota, State of Southern California Edison Co.	8103090577 8101090104# 8101220201# 8103020423 8103020428	146-06 146-06	f f 8 f
	8103200751 8103200751 8103200757+ 8103200757+	50-387 50-387 50-387 50-387	0 0 0 9		8103020428 8103030362* 8103050367* 8103050543* 8103050548*	50-206 50-206 50-361	\$ F Q Q
Sheldon Herman & Weles Sierra Club	8103130425 8103130455 8103180599 8103050826* 8103050451	•	0		8103050555# 8103050555# 8103050560# 8103050560# 8103050565#	50-361 50-361 50-361 50-361 50-361	90000
Bigma Chemical Co (subs of Sigma-Aldri ch Corp.)  Small Business Administration	8103053488 8103220189* 8103333888*	XEORTGIC CONTRACT	٥		0103050565# 0103050571# 0103050571# 0103050574#	50-361 50-361 50-361 50-361	0 0
Snell & Wilmer	8103030888# 8103050842 8103050842	50-275 50-275 50-275 50-275	9		0103050581# 0103050501#	50-361 50-361 50-361	9
	8103130496 8103130496 8103130500 8103130500 8103200678	50-275 50-275 50-275 50-275	0 0 0		8102060543 8103060636 8103090398 8103100183	50-206 50-206 50-206	A P P
Social Research Applications Corp Sol Lindentaum	8103233715 8103260509 8103090120+ 8103190891+	90-275 90-928 CONTRACT			8103100374 8103100390 8103100402* 8103100528	50-345 50-361 50-361 50-206	a A B
South Carolina Electric & Cas Co	8103020362 8103020461 8103020567 81030205714	50-395 50-395 50-395 50-395 50-395	K G G G		8103110336 8103110336 8103110340 8103110548 8103110550	50-205 50-261 50-361 50-268	F A A B
	8103030651 8103030698 8103030701+ 8103030740 8103030763+	50-395 50-395 50-395 50-395	и Е E		0103110655 6103110673 6103110673 6103110684#	50-361 50-361 50-361	0 1 1
	81031003521 81031003521 8103110635	50-395 50-395 50-395 50-395	9 8 A A		D103110498* B103110713# B103110718* B103110725	50-351 50-351 50-351 50-361 50-361	)   
	8103110653 8103120294 8103120307 8103120320+	50-395 50-395 50-395 50-395	G A A		B103120553 D103120553 D103120557* D103120557*	50-361 50-361 50-361	K K K
	8103130419 8103130473 8103160878 8103170448	50-345 50-345 50-345 50-345	к 0 8		8103120859# 8103120859# 8103120698# 8103120717#	50-361 50-361 50-361	yi H K
	8193170451 8193170526 8193170569 8193170578 8193180778	50-395 50-395 50-395 50-395 50-395	8 8 8 A		8103120717# 8103120722# 8103130276 8103130376	50-361 50-361 50-361 50-361	K K O
	8103190643 8103200622 8103230444 8103230653 8103230680	50-395 50-395 50-395 50-395 50-395	8 A E A		8103130396 8103130448 8103130448 8103170635 8103170635	50-361 50-361 50-361 50-361	0 0 4 4
	8103250440 8103260275 8103270436 8103270443 8103270443	50-395 50-395 50-395 50-395 50-395	6 A A A		9103170639* 8103170639* 8103180268 8103180331* 8103180889	50-361 50-361 50-361 50-361 50-361	A Q G
	8103270559 9103270620 8103270747 8103360070 8103300157	50-395 50-395 50-395 50-395 50-395	0 8 0 8		B1031B0593 B103200664 B103200664 B103200696 B103200696	50~361 50~361 50~361 50~361 50~361	¥ G G G G
	8103300161 8103310359 8103310366 8103310414 8103310458	50-395 50-395 50-395 50-395 50-395	A A A A		8103200722 8103200722 8103231107 8103240101 8103240106*	50-361 50-361 50-206 50-206	9 0
Bouth Caroline Public Bervice Authority	8103310461 8103310494 8103310905 8103020567	50-395 50-395 50-395 50-395	A A G		8103240338 8103240355 8103240357 8103260078 8103260088	50-206 50-206 50-206 50-206 50-206	Р Р О
South Carolina. State of	8103020571+ 8103180497	50-395	н		9103260545 8103260545	50-361 50-361	ĸ
South Daiota School of Mines & Technolo	8103180607 8103250736 9103230019	50-369 PR CONTRA			8103260551* 8103260551* 8103260756	50-361 50-361 50-361	K X Q

	81032607 81032607	50-3		AFF ILIATION	ACCESSIO NUMBER	N BUBJECT CATEGORY
	810325076 810327022 810327022	51* 50-36 27 70-28 27 70-28	51 G 982		8103260376 8103260379 810326403 8103260413	4* FOIA 7* FOIA 3* FOIA
	810327022 810327023 810327023 810327023 810327048	8# 70-28 8# 70-28	892 182 182		8103260440 8103260466 8103260506 8103260519	9* 40-1947 9* 40-1947 9* 40-1947
	810327068 610330033 810330033 610331048 810331049	2 50-36 2 50-36 7 50-30	1 p 1 p 6 p		8103260526 8103260532 8103260548 8103260562 81032605970	* 40-1947 * 40-1947 * 40-1947
Southern California, Univ of	810324022 810324022 810324023 810324023	7 50-440 7 50-440	0 0		81032606331 8103260638 8103260658 8103260678	40-1947 40-1947 40-1947
Southern Interstate Nuclear Board Southwest Research Institute Spiegel & McDiarmid	8103260596 8103250261	CONTRA	O CT		8103240483* 8103240488* 8103240703*	40-1947 FOJA
CP-14991 & INCDIATING	8103190037 8103190629 8103190629 8103190629	PROJ 50-449	м		B103240721* B103240723* B103240728* B103260729*	
	8103190629 8103260817 8103260817 8103260817 8103260817	50-445 50-445 50-445 50-445	M M M		8103260730# B103260731# B103260732# B103260734#	40-1947 40-1947 40-1947 40-1947
Stafto, Inc. Standardized Nuclear Unit Power Plant System	8103170091 8103020686		F 0		8103260742# 8103260748#	40-1947 40-1947
	8103020606 8103020606 8103020694	50-462 50-462 50-462	() () ()		8103260751* 8103260753* 8103260762* 8103260765* 8103260793*	40-1947 40-1947 40-1947 40-1947 FOIA
	8103020694 8103020694 8103030770 8103030549 8103030549	50-482 50-482 50-482 50-482 50-482	0 G A A	Stone & Webster Engineering Corp.	8103240604 B103240814 B103240823 B103040731 B103070534	FOIA FOIA FOIA PR
	8103080549 8103050587# 8103050557# 8103050557# 8103050642	50~482 50~482 50~482 50~482 50~482	A A A		G103100713+ G103110067+ G103110303 G103110312+ G103250691	04999 04999 50-322 A 50-322 A
	8103050642 8103050642 8103260613 8103260613 8103260613	50-402 50-402 50-482 50-482 50-482	A A A A	Stone & Webster, Inc Sunflower Coelition	8103310314 8103170173 8103310306 8103100714 8103100731	50-322 A 50-322 A 50-322 A HASTE MGT
	8103270409 8103270409 8103270409 8103270658 8103310671	50-462 50-462 50-462 50-463 56-462	A A A	Busquehanna Environmantab Advocates Tech/Ops (Technical Operations, Inc.)	B103110463 B103260735 B103120059 B103120071	90-397 G 50-397 G 50-397 G 71-6717 71-9127
ate.Dept.of ate.Dept.of. Byreau of Oceans & Cternati.Environ. & Scientific Affairs	8103190072* 8103030961	CONTRACT XPORTLIC		Technical Operatums, Inc. Technical Security Associates, Inc. Telegrapa Cast Park	8103160509	71-9128 PR PR
	8103050526 8103050930 8103100002	XPORTLIC XPORTLIC XPORTLIC		Teledyne Cast Products Teledyne Energy Systems	8103250409 8103120048	REGGD 70-2317 XPORTLIC
	8103100003 6103100005 8103120215 6103120613 8103120624	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Feledyne Isotopes Tennessee Velley Authority	8101080123+ 8101080123+	XPORTLIC 50-298 R 50-327 F 50-327 F 30-327 F
	8103120634 8103130202 8103140323+ 8103190369 9103260041	XPORTLIC XPORTLIC BECY XPORTLIC XPORTLIC			8101220526# 5 8101220526# 5	00-327 F 00-327 F 00-327 F 00-327 A 00-390 A
pan Chemical Co.	8103310919 8103260059* 8103260067* 8103260178* 8103260198*	XPORTLIC FOIA FOIA FOIA 40-8610			8103020475 56 8103020475 56 8103020510 56	0-370 A 0-327 P 0-327 P 0-239 P 0-296 B
	8103260203# 8103260247# 8103260263# 8103260273#	40-8610 40-8610 40-8610 FOIA FOIA			8103020528+ 50 8103020532 50 9103020536+ 50 8103020633 50	0-276 S 0-327 S 0-327 S 0-337 A
	8103260319# 8103260325#	40-8610 40-8610 *GIA			8103030670 50 8103030674# 50 8103030771 50 8103030771 50	0-240 P 0-240 P 0-390 B 0-390 B

8103030853 8103030853	50-370 50-370		8103110584 8103110609	30-5 30-2
81030+0559	50-518		8103110613*	50-2
8102040583* 8103040637	50-327 50-296	) 5	8103110614 8103110614	€0-3 50-3
B103040643*	50-276	3	8103110627	50-3
8103040696	50-370	3	8103110648	50-3
8103040700	50-438	3	8103110659	50-3
B103040717	50-259	<del>.</del>	8103110664	50~3
8103040717	50-259	•	8103110664	50-3
8103040753 9103040754	50-518 50-328		8103110721 8103110809	50-2 40-1
0.000.40767	50 300		fr. dh. 00. 00	
8103040757 8103040748	50-328 50-438		8103150598 8103150185	50-0 1026
8103040775	\$0-328		8103120293*	TOPR
8103040777	50-438		8103120544	50-3
8103040777	50-438	)	8103120749+	\$0-2
8103040789	50-438	3	8103130009	50-5
8103040802	50-239	)	8103130027	50-4
8103090306 8103050444	50-566 50-390		8103130027	20-4
8103050449*	50-428		8103130405 8103130451	50-3 50-2
8103050497 8103050497	50-259 50-259		8103130451	50-2
8103050497	50-259	7	8103130451 8103130466	50-2 53-4
8103050511*	90-299		8103130466	50-4
0102020211*	90-259	1	8103160205#	50-5
8103050511*	50-259	1	8103160572	50-3
8103050573.	50~390	)	8103140578	50-3
8103080582*	90-390		8103160593	50-2
8103050587+ 8103050909	50-370 50-328	i 3	8103160593	50-2
0100000107	20-350	•	8103160755	30-2
B103060127	71-9139		B103160757*	55-2
8103060314 8103060336	50-260 50-259	3 :	B103160844	50-3
8103080336	50-259	•	8103140883 8103170085	50-2 50-2
B10306079B	90-327	1	8103170005	50-2
8103090148	50-327		D. 004 70000	
B103090203+	50-327	· •	8103170085 8103170085	50-2 50-2
8103390409	50-327	l	8103170141	50-3
B103090409	50-327	}	8103170194	50-2
8103090551	90-593	i	\$10317 <b>01</b> 94	20-5
8103090604	50-390	<b>3</b>	8103170194	50-2
8103090638	90-438		0103170322	50-3
8103090638	50-430		8103170322	50-3
8103090553 8103100281	50-328 50-518	i 3	8103170325* 8103170325*	50-3 50-3
			81031703254	20-3
8103100352	50-259		8103170376	50-4
8103100325	50-259 30-259	! !	Ø1031703B9	\$0-3 \$0-3
8103100453	50-328	<b>1</b>	810317040B 8103170413*	50-3
8103100468	90-327	i	8103170459	50-3
8103100477*	50-327	<b>,</b>	#1.0p.170.460	50-0
8103100480	90-327		Ø103170459 Ø10317050⊋	90-3
8103100486*	90-327		8103170502	50-0
8103100490	50-327		8103170920	5C-2
8103100496*	50-327	i	8103170530	50-3
8103100500	50-327		8103170936*	50-3
8103100504+ B10310050B	50-327 50-296		B103170540	50-2
8103100508	90-296	) 	8103(70546 8103(70546	90-2 50-2
B103100601	50-257		8103170546	50-2
8103100601	50~259			50-2
8103100801	20-524		8103170549* 8103170550*	50-2 50-2
*E031001E01B	50-259		8103170583	50-2
8103100403*	50-259	•	8103170590	50-3
81031036034	50-259		8103170595#	50-3
8103110414	50-259	•	8103170614	50-3
8103110414	50-259		8103170624	50-3
8103110414 8103110433	50-259 50-328		8103170624	50-3 40-1
8103110440#	50-259		8103180280 8103180287*	40-1
8103110440*	50250			
B103110440*	50-259 50-259		8103180287# 8103180385 <b>*</b>	40-1 30-3
8103110475	50-327	!	8103180392*	50-3
8103110476	50-327		8103180544	50-3
8103110477	50-327	1	8103180962	50-3
8103110481*	50-327		B103180702	50-5
8103110481* 8103110486*	50-327		9103180886	80-2
8103110485*	50-327 PR		8103180886	50-2 50-2
8103110522	50-430		8103180884 8103181151	REGG
· <del></del>			2102121111	

.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUSJ	ECT SORY	hus			
	B103190176	50-22		AUTHOR AFFICIATION	ALIFED: N	SUBLE	FCT
	8103190212	20-35	7 P	A-7 ICIATIO4	NUMBER * ****	CATEC	)5 RY
	6103190217*	50-32; 50-32;			61033331 <b>;13</b> 6103313333	50-327 50-327	7 p
	6103190217#	30-32	7 Þ		5:00016417 9:00016483:	:0-327	P .
	8103200542 0103200545∙	50-32	. "		8103310495	50-3 <i>27</i> 50-370	R
	8103200577	90-516	ÀE		6000016465		-
	8103230491 8103230498	50-326 50-390	) A		A1v331C483 A1C3313438	50-438	S
	B103230548		•		B109910453.	50-4 <u>38</u> 50-327	ē
	B10323054a	50-259 50-259			⊕1°391° <u>9</u> 13	50-327	P
	8103230548 8103230792	30-259 90-296			8100010505* 8100010505	50-327 50-438	P
	0103230790*	50-296			9163310551 9163310555	30-436	<b>S</b>
	B103240274+	50-438	0		01033:0559	50-32e 50-43e	5 6
	8103240274± 8103240293±	50-438 50-438			8100016555	43-439	8
	0103240297# 0103240341	50-438 50-259	ā		91393:054: 81033:3594•	50 - 260 50 - 260	9
	0100240341		•		8103310559 8103310435	696-63	S
	(4103540341	50-254 50-259	þ			5J-43B	S
	8103240404 8103240404	90-320 90-328			81033;1624 8113310824	\$0~438 \$0~438	G G
	B103240413	50-259	8	Tennessee, State of	9103310791 8103310757•	50-259 50-259	S
	B103240420	90-228		nearly 25	8312940358.	: 9-327	S F
	B103240430 B103240435	50-259		Terry Corp	6163123241	State Pr	r c q
	8103240452 8103240458*	50-259 50-259	s	Tetor Exploration Orilling Co. Inc Teras A & K Univ	8103350154 8103350154	50-061 40-8781	Ā
				• • • • • • • • • • • • • • • • • • • •	6103333994 8103246284•	71-9034	
	8103240464 8103240466	50-294 50-327			01032402994	CC www ( CB )	
	#10324046## #103240478	50-294 50-294	6	Teras instruments, Inc	8103310942	1221HH331	, b
	6100240484#	50-276	S 6	Texas Nuclear Div (subs of Ramsay Eng Co )	8102270774 <b>•</b> 8103323675	50-247 19081416	P
	0103240333	30-327	0		8153022881*	IPO41L1C	
	8103240548 8103240349+	50~296 50~296	8	Feras Utilities Generating Co	6103050655		
	0100240593 0103240607	50-438 50-327	0		8103050555	90-445 56-445	G
			G		8103050548 8163356548	50-445 50-445	0
	0103250041 0103250187#	PR 50-436	g		8100393567	53-445	Ä
	######################################	50~409 50-327	9 6		0103116774 0103160665	50-445	0
	0100290279	50-260	8		8103180556	50-445 50-445	s
	D100530009*	90-327	S		8103192277 8103190294		0
	8103250315+ 0103250497	50-260 50-327	8		8103190284	50-445	a
	0103250907 0103250019	50-327 50-327	S		8103190273 8103190565	20-449	ē
			-		8103233190 8103233190	50-445	Q
	8103590151 8103590015	50-327 50-259	0				G.
•	8103240151	50-259 50-259	G G		8103236203 61032464 <i>7</i> 4	50-445	0 9
	B103590533	30-599	F		8103240474 8103243474	53-445	S S
	G100260239	50-237	F		8103250320		Ā
	8103260239 8103260477	50-259 50-257	F G		8103250725	PR	
	0100240477 0103240477	50~259 50-259	0		8103260729 8103260729	5C-445 5	6 5
				Teras, Univ of	8103270536 8103020369		0 P
	0103591100 0103591155+	50-327 50-259	G.		B103020372+		p
	8103261180 8103261180	50-259 50-259	9		8103030573	50-192	9
	0103591511	50-259	à		8103030181	50-192 1	9 9
	B103261211	50-259	a		8103030964	50-192 (	В
	8103261211 8103270044	30-259 50-259	g g				6 6
	8103270044 8103270044	50-259 50-259	Q Q		B103030697	60-165 1	B
	8103270462						8 9
I	8103270505	50-430 50-438	8 6			50-192 6	9
	8103270512 8103270512	50-259 50-259	F			50-192 F	R R
•	8103270522	50-438	8	The Nuclear Regulatory Commission	8103240911+	50-192 A	
	8103270672	50-328	8	• •			
•	8103270712 8103270724	50-566 50-390	8 9		8103030950	50-327 ( 71-416	,
	8103270724 8103270777	50-390 50-328	8 A			71-407 71-407	
	8103270823		6			71-407	
ŧ	B100330015B	50-966 50-390	8			71-416	
•	8103300163 8103300168	50-390 50-438	8		8103090717	71-416 71-416	
	B103300173	50-327	Р		8103160021	71-416	

.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		ACHTUA AFF IL 1AT JON	ACCEBBION NUMBER	SUBJEC CATEGO
Thomas & Hair Three Mile Island Public Interest Resource Center	81031600264 8103250708 8103250245+	71-416 PR 50-289	0	US Steel Corp Underwriters Laboratory Union 78 Minerals Exploration Co	8103270599 8103250615 8103350332* 8103230339	27-39 REGOD CCN1RAC 40-8584
Timeple: Inc Taleco Edison Co.	81031C0651* 8103020507	40-8610 50-346	P	Union Carbide Corp.	0103030933	XPCQ7L1
	8103020509 8103030541 8103030546• 8103030738 810303020826	50-346 50-346 50-346 50-346 50-346	8 6 6 9		8103050535 8103120659 8103181010* 8103270131 8103270136*	WABTE M 30-34 REVIEW ( WASTE M WASTE M
	8103030834+ 8103930836 8103030847+ 8103050287	50-346 50-346 80-346 50-346 50-346	S S S R R	Union Carbide Corp .Hetels Div	8103270164 8103270186 8103270193* 8103310720 8103120218*	70-697 70-697 70-697 70-697 FOTA
	8103050293* 8103090557 8103090561* 8103090568*	50-346 50-346 50-346 50-346	5 5 6 9	Union Electric Co	8103160247 8103160339 8103310609 8103030889 81030301924	HASTE HO HASTE HO 40-229 50-483 50-483
	8103120845 8103120845 8103130393 81031303974 8103130573 8103130579+	50-346 REGGD 50-346 50-346 50-346	R R R S		8103100128 8103110787* 8103120175 8103130040 8103160749	50-483 50-486 50-483 50-483
	8103130566 8103130594* 8103160152 8103160159* 8103160736	50-346 50-346 50-346 50-346 50-346	2 2 4 4 2		8103180459 8103180714 8103180978 8103240259 8103310217	50-483 50-483 REGGD 50-483 50-483
	8103140748* 8103170127 8103170488 8103170493* 8103170612	50-346 50-346 50-346 50-346 50-346	5 6 5 8	Union Ainerals Union of Concerned Bigatists	8103051012 8103100427 8103110497* 8103130447 8103130455	40-8504 40-8584 50-338 50-361 50-239
	8103170618* 8103180500 9103180503* 8103190327 8103190756*	50-346 50-346 50-346 50-346 50-346	8 P P G		B103180556 B103180604 B103190616 B103190616 B103190622*	50-289 50-289 50-275 50-275 50-275
	8103200329 8103200626 8103240501 8103250396	50-346 50-346 50-346 71-9096	Q F P	United Engineers & Constructors. Inc. (subs of Raytheon Co.)	8103190422* 8103270116 8103020482 8103230043	50~275 NUMEQ TOPREP RECOD
	B103260426 B103260902 B103260913* B103270707 B103300226 B103310392	50-346 50-346 50-346 50-346 50-346 50-346	8 8 8 8	United Nuclear Corp.  United Nuclear Corp , UNG Recovery Bystems Div.	8103020448 8103020455* 8103190795 8103270660 8103040316	70-820 70-820 40-8761 70-371 70-820
	8103310593* 8103310617 8103310623* 8103310627 8103310655	50-346 50-346 50-346 50-346 50-346	8 8 8 6	,	8103040321* 8103090645 8103090652* 8103270827 8103270829*	70-820 40-8602 40-8602 70-820 70-820
Toledo. Univ of Tracerlab.inc Transnuclear. Inc	8103120459* 8103260736* 8102180222* 8102180238* 8103030616	CONTRACT 40-1947 SECY SECY XPORTLIC			8103300026 8103310882 8103310886* 8103310896* 8103310899*	70-820 70-820 70-820 70-820 70-820
	8103030623* 8103040865 8103090443 8103090449* 8103100586	XPORTUTO XPORTUTO XPORTUTO XPORTUTO XPORTUTO XPORTUTO		United Nuclear Corp Navel Products Div. United Steelworkers of America	8103310903# 8103310909# 8103100353 8103100358# 8103240492	70-820 70-820 70-371 70-371 PR
	8103100691 * 8103100695 8103100701 * 8103110034 *	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Utah, Btate of Utah, Univ. of Vermont Yankes Nuclear Power Corp.	8103050879 8103050879 8101070345* 8101220624* 8103030777	PR 40-8681 50-72 50-72 50-371
U.S District Court, District of Coloredo	8103190665 8103190669* 8103270610 8103100697* 8103100707*	XPORTLIC XPORTLIC 70-1426 WASTE MC	; }T		8103030854 8103030856* 8103090548 8103100229 8103100341	50-271 50-271 50-271 50-271 50-271
URB Corp US Ecology, Inc. (Formerly Nuclear Engineering)	8103050059* 8103050049* 8103200707	FO!A FO!A 27-39			8103100770* 8103100778* 8103130363 8103130389	50-271 50-271 50-271 50-271
	8103260522* 8103260530*	27-39 27-39			8103160548 8103170535	30-271 50-271

Virginia Electric & Power Co

81032405	32* 50-	271 g		81032402 81032403 81032404	55* 20-580 0
81 033003 81 033003		271 R		81032404	89+ 50-338 8
01033105	06 50~	271 A		81032405	16 50-280 S
81033104: 81033001:	71 50-			81032405; 81032405; 81032405;	21# 50-280 8 24 50-338 5
81010702; 81012201				810324055	29+ 50-330 8 58 50-330 8
810228051	2 71-	338 F 9079		810324056	1 * 50-33B B
810302051 810302052	80-3	339 g		810325048 810325048	1 50-339 6
810003079	5 5n-c	_		810325045 810326037	6 50-280 0
910303039 910303039	'5 50-3 'L* 50-3			810326037	
810304026	6 50-3			810326046	7 50-339 p
810304029 810304033				8103260760 8103260760 8103260832	50-339 S
810304033	50-2	80 Р			. 30-334 B
810304036 010304036	6 รถ-จิ			8103260835 8103260842	70 207
8103040366	5 50-2			8103240892	* 50-338 S
8103040366		60 F		8103270526 8103300143	
6103040385 8103040365	3 50-3; 3 50-3;			8103310278	50-338 g
B103050776	9 50-30	3 <b>3</b> 0		8103310535	50-338 0 53-280 g
B10306Q307		90 P		8103310540 8103310552	50-339 g 50-339 g
8103060307 8103060 <b>5</b> 93		30 R		8103310557*	50-338 B
APE040E01B	• 50-20	81 S		8103310565	30-280 p
8103040400 8103040400	* 30-28	11 g		8103310565 8103310565	20-580 b
8103090327				8103310570 8103310573*	50-339 B 50-880 b
B103100420	50-28 50-33	0 P 0 P			50-339 g
B103100420 B103100420	50~26	о г		8103310576 8103310578•	50-339 g
8103100420	50-28(	0 P		B103310579*	50-339 g 50-339 g
6103100824	50-339			B103310930 B103310265*	50-280 g 50-339 g
8103100A32+ 8103100A35	50-28 50-28	9 8	Virginia Tech	8100310693*	50-339 g
8103100639±	90-26 i	i s		8103030719 8103030719#	30-124 R
	50-339	_	Virginia, Blate of	B103170445 B103250053	50-124 R 50-330 S
8103110468# 8103110529	50-339 50-338		Virginia, Univ. of		PR
8103110533# 8103110533#	50~338	, r	VollaniR. J. & Whicher, J. M.,	8103050689 8103050689	CONTRACT 50-367 Q
8103110333#	50-218		Washington Hosp Center Washington, DC	B103050707 B103190532	50-367 0 50-367 0
8103120556 8103130470	50-338 50-280	-	Washington Public Power Supply System	8103170508	70-1500
8103130470 8103130472#	50-280	8	Dopping agetem	8103020136 8103020508	50-460 Q 50-460 B
8103130475	20-581 20-581	6		8103020405	30-460 B
0103130427*	50-200			8103030413 8103030786	50-397 8 50-397 8
8103130705*	50-260	G)		8103030857	TOPREP
8103140404#	50-038 50-338	P		0103030055+	TOPREP
8103170333	50-280	A		6103040325# 6103040341#	50-460 G 50-460 G
0103170338# 0103170338#	50-280	R		8103090358	PR
8103170434	50-280 50-337	ft E		8103100416	50-397 g
8103170437# 8103170439	50-339 50-338	8		B103100537 B103100540#	50-305 B 50-205 B
8103170444#		8		8103100543± 9103120399	50-305 g 50-397 g
B103170570	50-336 50-339	8 8		B103120406	
8103170574+ B103170579	50-280 50-280	8		8103120423	50-460 B 50-460 B
8103170581	50-33B	8 R		8103170487 8103170634	50-397 8
8103170581	50-338	R		B1032800254	50-397 g 50-508 @
8103170585* 8103170586*	30-260 50-338	8		B103250002+	50-508 g
8103170586#	50-336	R R		8103570004	50-508 6
8103190173	80-33 <b>9</b>	Þ		EE0092C01B	PR
8103190179* 8103190451	50-339 50-281	P			50-508 @
B103190694+	50-281	8 9			50-508 g PR
8103200274 8103200905	50-039 REGGD	Р		8103330075	50-397 K
8103230637	50-280		·		50-397 к 50-397 г
8103230437	50-280	₽ P	Washington State Univ	8103310320*	50-397 F
8103230787 8103231083	50-338 50-338	P 0	Weshington, State of	8103060473	50-27 P
8103231098	50-280	8	We Try Herder, Inc. West Chicago, FL	8103261116# (	NASTE HOT CONTRACT
				6103250066	10-2061

A FOLKATION	410E8310* 11.78E#	CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
Mestern Machager	<b>5110161394</b>	70-309	Hillie: Beaumont Hosp Royal (Jak.Mi	610005004
Hestern N. (lear larvous as of Freig Clase Corp	6102100399 e203050459 6123050119	40-1:52	Wilt. D D Wisconsin Electric Power Co	0103050099 0103160619 01031603669 0103030669
	e102069137 9103090049	40-1:52 40-1162		8103030B14 8103090381
	8:03 60241 8 03250559 6 03250565 9:03250743	40-1162 40-1162		8103090546 8103090570 8103090574
mesturghouse Electrum Comp	8:03260005 8:0326:213 8:03270123 9:03270:53 8:01210483	40-1162		8103090574 8103090629 8103090629 8103090636 8103090636
	0102190362 0102190371 0103020114 0103020549 01030402741	71-6460 71-6400 *PORTLIC 76-2709		8103100190 8103100331 8103100333 8103100333
	8103040876 8103050118 81030505084 8103060254 8103060258	*PERTL1C 71-6400		0100100470 0100100470 0100110007 0100100200 0100160724
	8103050593 8103090345 81030904030 8103090458 8103090535	PR TLPPEP 50-205 P TCPFEP PR		81 031 70320 01 031 70320 01 031 70324 # 81 031 70324 # 01 03200035
	8103103559+ 6103100574+ 8103100511 8103100513+ 8103100615+	50-213 P 50-213 P TCPREP TOPREP TOPREP		01 03200620 01 03230309 01 03230823 01 03250184 01 03250184
	8103100617• 8103100552 8103100670• 8103120154 8103120910	TOPREP APERTLIC CONTRACT APDRILIC XPORTLIC		0100250166# 0100250393 0100250393 0100260657 0100260657
	8103130485 8103130490* 8103150257* 8103160364* 8103160727	50-206 P 50-206 P TOPREP 50-336 P TOPREP		8100220567# 8103260567# 8103270430 8103270430 0100000020
	8103170361 8103190183# 8103230708 8103240310 81032403[4#	TCPREP 50-327 P 70-2909 50-206 P 50-205 P		0103300177 0103310210 0103310210 0103310473 0103310473
	8103240375 8103240383+ 8103250134 8103250672 8103260768	50-87 P 50-87 P NUREO PR 70-2909	Wisconsin Power & Light Co Risconsin Public Bervice Corp	8103310475* 8103310479* 8103270726* 8103030690 8103030033
	8103261215 8103270173 8103270715• 8103310653 8103310761	REGGD 70-1151 TOPREP 70-698 70-1143		8103030037* 8103090684* 8103090737 8103130459 8103170356
lestinghouse Electric Corp., Nuclear Energy Systems	8103316841 8103310934 8103310937+ 8103250141+	XPORTL1C 70-2909 70-2909 NUREO		6103170525 6103170110* 6103170191* 8103170197*
	8103310941. 8103310945.	70-2909 70-2909		8103230693
estinghouse Electric Corp., PRR Systems Div	0103310948• 0103100340	70-2909 70-2909 TOPREP		0103231064 0103240370 0103240596
estinghouse Operating Plants Dumers Group	8103170593* 8103050501	30-334 P TOPREP		8103270726 8103270726 8103270728*
	8103160252 8103250432 8103250435• 8103260301	TOPREP TOPREP TOPREP TOPREP	Wisconsin, State of	8103310637 8103310647# 8103310652
eston Geoghysical Corp	8103270714 8103040028* 8103040028* 8103040034*	TOPRÉP 50-329 A 50-329 A	Homen's international League for Peace &	8103040605 8103110564 8103260812 8103260820*
narton & Pegalies	B103040034+	50-329 A 50-329 A 50-361 O	preedom	8102270558*
	8103230640	50-361 0	Hoods Hole Oceanopraphic Institute Hoodward-Clyde Consultants, Inc	8103050029 8103270167 8103160514 8103050203#

Nile canal com:			_		n.ontooded	30-2.7	
·	6103040841*	146-00	A		8103110201*	50-29	F
	8103060565	50-361	A		6103110504	50-29	¢.
	8103060571+	50 - 36 1	A		8103120443	50-29	ρ
	8103040575*	50-34L	A		8103130351	50-27	Р
Wieming Mineral Corp	8102170332	40~8502			0103130351	50-29	P
-1	# PE BOP 15618	40-8502			8103130351	50-29	₽
	8195569341	40-8502			8103130359+	50-29	įp.
•	8102270639	40-8902			8103130359*	50-29	Þ
	C. 400 401 = 0						
	8103040635	40~8585			9103130359*	50-29	P
	8103040638*	40-8595			8163163598	50-29	P
	8103110304	40-8502			B(33170559	20-54	6
	8103120034	40-8589			8103[70564*	50-29	5
	8103120042*	40-8565			8103:80592	5C-27	P
	8103160267	40-0502			8103203196		_
	8103180731	40-8502				50-29	p.
	810324003B	40-8502			8103200204+	50-29	Þ
	8103250542	PR			0103230469	50-29	F
					6103570392	50-29	1
Hyaning. Btate of	8103110894	40-1162			Ø103270661	50-29	t
	8103180938	40-8714			8100270564#	50-27	,
	8103240542	40-8663			8103310214#	50-271	ė
	8103290079	PΩ			8103310226	50-29	é
	8103240483	40-6348			6103310559	50-29	è
Yantes Atomic Electric Co	0103030617	50-29	F		8103310531+	50-29	F
ASULTA MEDILLE CLASSIFIC CO.	0.00000000		•		01033105314	30-21	-
	8103030800	50-29	P		8103310231*	50-29	Р
	8103096383	50-27	P		8103310257*	50-309	P
	6103090323	50-29	þ		1640125018	50-29	R
	8103090330*	90-29	ρ	Zimmer Area Citizers - Zimmer Area	8103203511	50-358	9
	8103090330#	50-29	P	Citizens of KY			•
		50-29	Ų				
	8103090511						
	8103090812*	50-29	R				
	8103090812* 8103090871	50-5è 50-5è	Ð				
	8103090812*	50-29					



### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondockated items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

19037 8 2270 9 9 2270 9 9 3392 9 9 3392 9 9 3392 9 9 3392 9 9 3392 9 9 3992	B1032401784 B103270492+ B1031105784 B103060565+ B1030605714 B1030605714 B103030424 B103030424 B103031072 B103031074	90-349 90-361 90-361 90-361 50-361 868 REB REB 868 868 868 868 868 868 868 86	R R R A I I A I I I I I I I I I I I I I	8103120761 8103120847 8103120847 8103120839 8103120851 0103120855 8103130374 8103160084 0103160136 0103160136 0103160136 0103170116 0103170136 8103170737 8103180816 8103190809 8103190809 8103190809 8103190813 8103200094 6103230177 9103240144 8103240583 8103240583	8103120761 8103120851 8103120851 9103120851 9103130859 9103140084 9103140136 9103140136 9103140473 8103140473 8103170116 8103170136 8103170136 9103190432 910319089 910319089 910319089 910319089 910319089 910319089 910319089 910319089 9103290177 9103240144 8103240893	REB REB REB REB REB REB REB REB REB REB	ORNL/MRBT-&  ORNL/MABRD-\$12  LOFT-EQO-\$293  EQO-WRR-\$363 PEOD-EA-\$265 EQO-TFBP-\$329  DRNL/MABRD-\$13  BNL-NUREO-28999
15037 8 8 2278 8 3392 8 3392 8 3392 8 9 3392 8 9 3392 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	9103270492+ 3103010578+ 31030603754+ 31030603714- 31030603714- 3103030424- 3103030424- 3103031071- 3103031071- 3103031071- 3103031071- 3103031071- 3103040677- 310304067-	90-341 90-361 90	A I N888 4  A N888 2  A N888 2  A ORNNUREO-20703  A ORN./ANARRD-100  ORN./ED/EU-143  ORN./ANARD-109  P EQQ-EA-3330  P EQQ-30-3179  BNL-NUREO-28988  P EQQ-EA-5007  P EQQ-EA-5007  P EQQ-EA-5007  P EQQ-EA-5010	8103120847 8103120819 8103120831 8103120831 8103120831 8103120831 8103120084 81031400134 8103140473 8103140473 8103170134 8103170134 8103190813 8103190813 8103190813 810320094 8103240144 8100240983	8103120837 8103120831 8103120833 8103120833 8103140084 8103140084 8103140073 8103140473 8103140473 8103170737 8103180832 8103170737 8103180832 810319089 810329094	REB REB REB REB REB REB REB REB REB REB	ORNL/FTR-1025  ORNL/MASRD-112 LOFT-E40-9293  E00-WRR-5363 P E00-FA-5265 E00-TFBP-5329 ORNL/MASRD-113  BNL-NUREG-28999
2278 2392 3392 42913-1 8A 42493-1 8A 42493-1 8A 42493-1 8A 43482-1 54496-2 779070114 7790707144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 77907070144 779070707070707070707070707070707070707	103110678+ 1103060561+ 13103060561+ 13103060571+ 13103060571+ 13103020680 10103040680 10103030424 10103030431 10103040671 10103040661 10103040677 10103040677 10103040679 101030406679 101030406681 101030406681 101030406681	90-361 / 90-	I N888 4  A N886 2  A N886 2  A ORNLYBURED-20705  A ORNLYBURED-110  ORNLYBURED-110  ORNLYBURED-109  P EQU-EA-5330  P EQU-EA-5331  EQU-BET1-3331  EQU-BET1-3331  EQU-BET1-3331  P EQU-EA-5307  BNL-NUREQ-28985  P EQU-EA-5310	8103120819 8103120851 8103120851 8103120853 8103120874 8103140084 8103140473 8103140473 8103140604 8103170116 9103170136 9103170136 9103170136 8103190813 8103190813 8103200094 8103200094 8103240144 8100240189	8103120851 8103120851 8103120853 8103130376# 8103160894 8103160136 8103160473 8103160514 8103170116 8103170136 8103170136 8103190816 8103190816 8103190816 8103190816 8103190816 8103190819 8103190819 8103190819 8103190819 8103190819 8103190819 8103190819 8103190819 8103190819 8103190819 8103230177 8103240144	REG REB REB REB REB REB REB SO-272 REB REB REB REB REB REB REB REB REB REB	ORNL/MASSD-112 LOFT-EQO-9293 EQO-MRR-5363 P EQO-EA-3265 EQO-TFBP-5329 DRNL/MASSD-113
3392 3292 32913-1 RA 42482-1 54493-1 RA 84498-2 8154498-2 8103020400 8103030424 8103030433 8103031042 8103031042 8103031042 8103031042 8103031042 8103031042 8103040667 8103040667 8103040667 8103040667 810304067 810305084 810305084	103110678+ 1103060561+ 13103060561+ 13103060571+ 13103060571+ 13103020680 10103040680 10103030424 10103030431 10103040671 10103040661 10103040677 10103040677 10103040679 101030406679 101030406681 101030406681 101030406681	90-361 / 90-	I N888 4  A N886 2  A N886 2  A ORNLYBURED-20705  A ORNLYBURED-110  ORNLYBURED-110  ORNLYBURED-109  P EQU-EA-5330  P EQU-EA-5331  EQU-BET1-3331  EQU-BET1-3331  EQU-BET1-3331  P EQU-EA-5307  BNL-NUREQ-28985  P EQU-EA-5310	8103120851 B103120853 8103120853 8103140084 B103140473 B103160914 B103160914 B103170116 B103170136 B103170137 B103180402 H103160816 B103190813 B103190813 B103190813 B103190814 B103240094 B103240144 B103240184	8103120831 8103130376# 8103140084 8103140134 8103140134 8103140514 8103170116 8103170136 8103170136 8103170136 8103170136 810319083 810319083 810319089 810319089 810319089 810319089 810324099 810324099	REB AES REB REB REB REB REB REB REB REB REB REB	ORNL/MARRO-112 LOFT-EQO-9293 EQO-WRR-5363 P EQO-EA-3265 EQO-TFBP-5329 DRNL/MARRO-113
42913-1 RA 8 42493-1 RA 8 42493-1 RA 8 54496-2 7909070114 7 8163020680 8 8163030434 9 8163031072 8163031072 8163031074 8163030673 9 8163040661 9 8163040679 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 8163040681 9 816305081 9	8103060565* 81030605754* 81030605754* 81030605754* 7797070116* 8103030424* 8103031074* 8103031074* 8103031074* 8103031074* 8103040667* 8103040667* 8103040679* 81030406679* 81030406679* 8103040668	50-361 / 50-361 / 50-361 / 50-361 / 68 REB	A N888 4  A N886 2  A ORN NUREO-20705  A ORN. / MARRO-110  CHNL / MARRO-110  CHNL / MARRO-109  P EQG-EA-3130  P EQG-EA-3131  EQG-30-31-311  EQG-30-31-79  BNL - NUREO-28988  P EQG-EA-3307  P EQG-EA-3310	8103120374 8103130374 8103140018 81031400134 8103140473 81031404604 8103170116 8103170136 8103170136 8103180814 8103190783 8103190813 8103200094 8103290094 8103240144 8100240184	8103120853 8103130376* 8103140084 8103140136 8103140473 8103140514 8103170116 8103170136 8103170737 8103180816 8103170737 8103180819 810319089 810319089 8103190819 810324087 810324087 810324087 810324087	AES REB AES REB SO-272 I REB SO-272 I REB	ORNL/MARRO-112 LOFT-EQO-9293 EQO-WRR-5363 P EQO-EA-3265 EQO-TFBP-5329 DRNL/MARRO-113
43482-1 8 8 54478-1 8 A 8 9 54478-1 8 A 8 9 54478-1 8 A 8 9 54478-2 8 B 7909070114 7 6 103020480 9 9 103020480 9 1030201047 8 1030201047 9 103040641 9 103040675 9 103040675 9 103040676 9 103040678 9	81030609754 81030609714 9790707116 8103030424 8103030423 8103031071 8103031071 8103031071 8103031071 8103031072 8103040677 8103040677 8103040679 81030406679 8103040668	## ## ## ## ## ## ## ## ## ## ## ## ##	A A BNNUREO-20705 A DRNL/ED/EJE-144 ORNL/HASRD-110 DRNL/HASRD-109 P EQO-EA-5330 P EQO-EA-5331 EQG-30-5179 BNL-NUREO-28935 P EQO-EA-5307 P EQO-EA-5307	8103130374 8103160084 0103160136 0103160473 0103160604 0103170116 0103170116 0103170136 0103170737 01031806916 0103190783 0103190818 0103190813 0103190813 010320094 0103240144 0103240144 0103240189	8103130376* 9103140084 91031400473 9103140473 9103140473 9103140804 9103170136 9103170137 9103180816 9103190809 9103140913 9103140913 91031200094	REB REB REB REB REB REB REB REB REB REB	LOFT-EQO-9293  EDO-WRR-5363 P EOO-EA-9265 EOO-TFBP-9329 DRNL/HASRD-113 BNL-NUREG-28999
54473-1 RA  54476-2  97909701146  77909701146  77909701146  71909701146  7100304424  9103031047  9103031047  9103031047  9103040641  9103040647  9103040675  9103040678  9103040678  9103040678  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103040679  9103050899	81030609754 81030609714 9790707116 8103030424 8103030423 8103031071 8103031071 8103031071 8103031071 8103031072 8103040677 8103040677 8103040679 81030406679 8103040668	## ## ## ## ## ## ## ## ## ## ## ## ##	A A BNNUREO-20705 A DRNL/ED/EJE-144 ORNL/HASRD-110 DRNL/HASRD-109 P EQO-EA-5330 P EQO-EA-5331 EQG-30-5179 BNL-NUREO-28935 P EQO-EA-5307 P EQO-EA-5307	B1031400B4 D103140473 B103140914  D103140914  D103140914  D103170116 D103170136 B103170737 B103180814 B103190783 B103190813 B103190813 B10320094  G103230177 G103240144 B1003240983	8103140084 8103140136 8103140473 81031408514 8103170114 8103170136 810317037 8103180432 8103180433 8103190816 810319089 8103190819 8103140813 8103140813 8103140813 8103140813 8103140813 8103140813 8103140813 8103140813	RES RES RES RES RES JO-272 RES RES RES RES RES RES RES RES RES RES	LOFT-EQO-9293  EDO-WRR-5363 P EOO-EA-9265 EOO-TFBP-9329 DRNL/HASRD-113 BNL-NUREG-28999
94498-2 97907070114 97907070114 97907070114 9103020430 9103030433 9103030433 9103031047 9103030404 9103040464 9103040467 910305047 910305047 910305047	1030609714 9790970714 91030304080 0103030424 1103031047 1103031071 1103031071 1103031071 1103040667 1103040667 1103040677 1103040679 1103040667 1103040667 1103040667 1103040667	90-361 / REB	A BNL-NUREO-20705 A ORNL/ED/E18-144 ORNL/HABRD-110 ORNL/HABRD-109 P EQO-EA-5330 P EQO-EA-5330 EQO-30-5179 BNL-NUREO-28988 P EQC-EA-53007 P EQC-EA-53007 P EQC-EA-53007 P EQC-EA-53007 P EQC-EA-53007 P EQC-EA-5300	0103160136 0103160473 0103160914 0103160614 0103170116 0103170137 0103170137 0103170137 0103170137 0103170137 010310016 010319013 0103190013 0103190013 0103290074 0103240144 0103240144 0103240144	8103140136 8103140473 8103140614 8103140614 8103170116 8103170136 8103170136 8103190438 810319089 810319089 810319089 810319089 810319089 8103240144 8103240144 8103240144	REG REB REB REB REB REB REB REB REB REB REB	LOFT-EQO-9293  E00-WRR-5060 P E00-EA-9265 E00-TFBP-9329 DRNL/HASRD-110 BNL-NUREG-28999
79070701146 7 81630206160 81630206160 81630206160 81630206160 8103031062 8103031062 8103031064 8103031092 81030306661 91030306661 91030306661 91030306671 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103030673 8103050393 8103050393 8103050394 8103050840 8103050840 8103050840 8103050840 8103050840 8103050840 8103050847 8103050840 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847 8103050847	7907070116 9103030424 9103030424 9103031067 9103031071 9103031071 9103040667 9103040667 9103040679 9103040679 9103040679 9103040679 9103040679 9103040679 9103040679	REB REB REB SO-334 E SO-207 REB	BNL-NUREQ-20705 A ORNL/ED/EIE-144 ORNL/HARRD-110 ORNL/HARRD-145 ORNL/HARRD-109 P EQQ-EA-5330 P EQQ-EA-5331 EQQ-30-5179 BNL-NUREQ-28955 P EQQ-EA-5307 P EQQ-EA-5307	8103140473 B103140604 B103170116 G103170136 G103170136 G103170737 B103180432 B103180616 G103190763 B103190813 B103200094 G103230177 G103240144 B103240144 B103240144	8103160473 8103160604 8103170116 8103170116 8103170136 810317037 8103180402 8103190809 8103190809 810319081 8103290177 8103240144 8103240144	REG REG REG JO-272 I REG REG REG REG REG REG REG REG REG REG	EQO-WRR-5363 P EQO-EA-3265 EQO-IFBP-5329 DRNL/MASRD-113 BNL-NUREQ-28999
8100020680 8100030424 9100030433 9100030433 9100030433 9100030471 8100030404 910003040661 91003040661 91003040677 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 91003040673 9100305083	81030304080 B103030424 B103030433 B103031067 B103031071 b103031071 b10304064 B1030406671 B103040679 B103040679 B103040679 B103040689 B103040689 B103040689 B103040689	REB REB REB REB REB REB 80-334 1 50-207 1 RES REB REB REB REB REB REB	A ORNL/ED/EJE-144 ORNL/HABRD-110 ORNL/HABRD-109 P EQQ-EA-5330 P EQQ-EA-5345 EQQ-30-5179 BNL-NUREQ-2B985 P EQQ-EA-5307 P EQQ-EA-5310	8103180918 0103180604 9103170116 0103170136 9103170737 8103180818 9103190783 9103190818 9103190813 9103190813 9103290074 9103240144 9103240184	8103140504 8103140504 8103170116 8103170136 8103170137 8103180816 8103140183 8103140183 8103140181 8103240094 8103240044 8103240144 8103240144	REB	P E09-EA-5265 E00-TFBP-5329 DRNL/MASRD-113 BNL-NURE0-28999
### ##################################	0103030424 1103030433 1103031071 11103031071 11103031084 1103031092 110304067 110304067 110304067 110304067 110304067 110304069 110304069 110304069 110304069 110305023 110305023	RES RES 30-7351 / RES RES 50-334 / 850-207 / RES RES RES RES RES RES RES RES RES	A ORNL/ED/EJE-144 ORNL/HABRD-110 ORNL/HABRD-109 P EQQ-EA-5330 P EQQ-EA-5345 EQQ-30-5179 BNL-NUREQ-2B985 P EQQ-EA-5307 P EQQ-EA-5310	0103160604 0103170116 0103170136 0103170136 0103170136 0103180616 0103190783 0103190813 010320094 0103230177 0103240144 0103240144	8103140604 B103170116 B103170137 B103170737 B103180402 B103190818 B103140809 B103140813 B103240813 B103240814 B103240144 B103240144	REG REB 50-272 LES RES RES REB REB REB REB REB REB REB	P E09-EA-5265 E00-TFBP-5329 DRNL/MASRD-113 BNL-NURE0-28999
110000433 110000433 1100001071 1100001071 1100001071 1100001071 1100000071 1100000071 11000000071 1100000000	8103030433 8103031067 8103031071 8103031084 8103031082 8103040667 8103040667 8103040679 8103040679 8103040689 8103040689 8103040689	REB 30-334 REB	A ORNL/ED/EJE-144 ORNL/HABRD-110 ORNL/HABRD-109 P EQQ-EA-5330 P EQQ-EA-5345 EQQ-30-5179 BNL-NUREQ-2B985 P EQQ-EA-5307 P EQQ-EA-5310	8103170116 0103170136 9103170737 8103180402 H103180816 8103190783 8103190813 810320094 6103230177 9103240144 8103240144 8103240183	8103170116 8103170737 8103180832 8103180832 8103190809 8103190809 8103190809 8103290177 8103290177 8103240097 8103240144	RED 50-272   REB REB REB REB REB REB REB REB REB REB	P E09-EA-5265 E00-TFBP-5329 DRNL/MASRD-113 BNL-NURE0-28999
### ### #### #### ####################	B103031067 B103031071 B103031084 B103031092 B103040661 B103040667 B103040679 B103040679 B103040682 B103040682 B103040683 B103040683 B103040683	90-751 / REB REG REB S0-334 1 50-207 1 REB	A ORNL/ED/EJE-144 ORNL/HABRD-110 ORNL/HABRD-109 P EQQ-EA-5330 P EQQ-EA-5345 EQQ-30-5179 BNL-NUREQ-2B985 P EQQ-EA-5307 P EQQ-EA-5310	0103170136 0103170737 0103180402 0103190816 0103190809 0103190809 0103190809 0103200094 0103230177 010324097 0103240144 0103240183	8103170136 8103170737 9103180432 8103180416 8103140809 9103140809 9103240097 8103240144 8103240283	50-272 IRES REB RES	P E09-EA-5265 E00-TFBP-5329 DRNL/MASRD-113 BNL-NURE0-28999
9307031071 9103031094 9103031094 91030306661 9103040667 9103040675 9103040675 9103040675 9103040675 9103040675 9103040675 9103040675 910303032 9103030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 91030373 910307	8103031071 9103031094 9103031092 9103040661 81030406671 9103040679 9103040679 9103040679 9103040679 9103040673 9103040673 9103030303	REB REB 30-334 50-207 RES REB 80-247 50-344 REB REB	ORNL/HARRD-110 ORNL/ED/ELB-145 URNL/HARRD-109 P EQG-EA-5330 P EQG-EA-5331 EEG-BEHI-5331 EQG-30-5179 BNL-NUREG-28935 P EQG-EA-5307 P EQG-EA-5310	8103170737 8103180816 8103190783 8103190809 8103190813 8103200094 6103230177 9103240097 8103240144 8103240183	8103170737 8103180816 8103190783 8103190783 8103190809 810312080094 8103220077 8103240097 8103240144 8103240144	REED REED REED REED REED REED REED REED	P E09-EA-5265 E00-TFBP-5329 DRNL/MASRD-113 BNL-NURE0-28999
8103031094 8103031094 8103031092 81030306641 00 81030306641 0103040671 8103030678 8103040679 9103040679 9103040679 9103040679 9103030678 9103050832 9103050839 9103050839 9103050839 9103050849	8103031084 8103031092 8103040661 8103040671 8103040673 8103040673 9103040673 9103040683 9103040683 9103090023 9103090023	REB 90-334 1 50-287 1 REB REG REG 80-247 6 50-247 6 80-247 6 80-247 6 80-247 6 80-247 6 80-868 8	ORNL/HARRD-109 P EQG-EA-3130 P EQG-EA-3131 EQG-30-5179 BNL-NUREG-28988 P EQG-EA-3107 P EQG-EA-310	8103170737 8103180816 8103190783 8103190809 8103190813 8103200094 6103230177 9103240097 8103240144 8103240183	8103170737 8103180816 8103190783 8103190783 8103190809 810312080094 8103220077 8103240097 8103240144 8103240144	REED REED REED REED REED REED REED REED	EGO-TF8P-5329 DRNL/HABRD-113 BNL-NUREG-28999
8103031094  8103031092  8103030664  9103040667  9103040677  8103040679  9103040682  9103040685  9103040685  9103030835  910308385  910308889	8103031092 0103040661 810304067 8103040673 8103040679 8103040679 8103040682 8103040683 8103090023 8103090032	REB 50-334 I 50-287 I REB REB 90-247 I 50-344 I REB REB	URNL/HASRD-109 P EQQ-EA-5330 P EQQ-EA-5345 EEQ-BEHI-5331 EQQ-30-5179 BNL-NUREQ-28985 P EQQ-EA-5307 P EQQ-EA-5310	8103180432 8103180816 8103190783 8103190813 8103200094 6103230177 8103240097 8103240144 8103240183	8103180432 8103190816 8103190783 8103190809 8103190813 8103290094 8103290177 810324097 8103240144 8103240583	REB REBB REBB REBB REBB REBB REBB REBB	DANL/HÄSRÖ-113 BNL-NUREG-28999
8103040661 9103940677 8103040678 9103040678 9103040688 9103040688 9103040688 9103090022 910309032 910309038 91030908 910308 910308 910308 910308 910308 910308 910308 910308 910308 910308	0103040661 0103040671 0103040671 0103040679 0103040679 0103040602 0103040603 0103050023 0103050023	90-334 ( 50-287 ( RES RES RES 90-247 ( 50-344 ( RES RES	P EQQ-EA-5390 P EQG-EA-5345 EEG-BERT - 5331 EQQ-30-5179 BNL-NUREG-28985 P EQG-EA-5307 P EQG-EA-5310	8103190783 8103190809 8103190813 8103200094 6103230177 910324097 8103240144 8100240983	8103190783 8103190809 8103190813 8103200094 8103230177 8103240197 8103240144 8103240583	RES RES RES RES RES RES	
3103040661 310304067 9103040673 9103040673 9103040673 9103040683 9103040683 9103040683 9103050032 9103050032 9103050032 910305053 910305055 910305055 91030505 910305 9	0103040661 0103040671 0103040671 0103040679 0103040679 0103040602 0103040603 0103050023 0103050023	90-334 ( 50-287 ( RES RES RES 90-247 ( 50-344 ( RES RES	P EQQ-EA-5390 P EQG-EA-5345 EEG-BERT - 5331 EQQ-30-5179 BNL-NUREG-28985 P EQG-EA-5307 P EQG-EA-5310	8103190783 8103190809 8103190813 8103200094 6103230177 910324097 8103240144 8100240983	8103190783 8103190809 8103190813 8103200094 8103230177 8103240197 8103240144 8103240583	RES RES RES RES RES RES	
0103040667 8 0103040671 8 0103040675 8 0103040675 8 0103040675 8 0103040682 8 0103040685 9 0103040685 9 0103050373 9 010305085 9 010305085 9 010305085 9 010305085 9 010305085 9 010305085 9 010305085 9 010305087	8103040667 8103040671 8103040679 8103040679 8103040682 8103040683 8103090023 8103090032	50-207   RES RES BES 50-247   50-344   RES RES	P E00-EA-5345 E60-BEHI-5331 E00-30-5179 BNL-NUREC-28985 P E00-EA-5307 P E00-EA-5310	8103190809 8103190813 8103200094 6103230177 9303240097 8103240144 8103240983	8103190809 8103190813 8103280094 8103280097 8103280097 8103280184 8103280183	RES RES RES RES RES RES	CRNL/CSD/INF-81
0102040A71 8 102040A71 8 102040A77 9 1020503032 9 1020503032 9 1020503032 9 1020503032 9 1020503032 9 1020503040 9 1020505024 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 10205050504 9 1020505050505050505050505050505050505050	B103040671 B103040679 B103040679 B1030406B2 B1030406B5 B103050023 B103050023	REB REB 30-247 ( 30-344 ) REB REB	EEQ-BENI-5331 EQQ-30-5179 BNL-NUREG-28988 P EQG-EA-5307 P EQQ-EA-5310	8103190813 8103200094 6103230177 910324097 8103240144 8103240983	8103140813 8103280094 8103230177 8103240947 8103240144 8103240583	AES RES RES RES RES	ORNL/CSD/INF-81
8103040678  8103040679  9103040682  9103040683  910309023  9103093373  9103093373  9103090385  9103050832  9103050837  9103050846  9103050846  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847  9103050847	0103040679 0103040679 0103040602 0103040605 0103050023 0103050023	REB 80-247 6 50-344 1 REB REB	EQQ-30-5179 BNL-NUREG-28988 P EQQ-EA-5307 P EQQ-EA-5310	8103200094 6103230177 6103240097 8103240144 8103240983	8103200094 8103230177 8103240097 8103240144 8103240583	res res res res	CRNL/CSD/INF-81
8103040679	0103040579 0103040602 0103040605 0103050023 0103050023	REB 50-247 50-344 REB REB	BNL-NUREO-28998 P E00-EA-9907 P E00-EA-9910	6103230177 8103240097 6103240144 8103240383	8103230177 6103240097 8103240144 8103240583	res Res Res	CHMC/CSD/INF-BI
6103049682 8 8103040685 8 8103040685 8 8103040685 8 810305032 8 8 81030503373 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	8103040602 8103040605 8103050023 8103050032	50-247 ( 50-344 ) RES RES	P E00-EA-5307 P E00-EA-5310	8503240097 8103240144 8103240583	8103240097 8103240144 8103240583	reb Res Res	
6103040602 8 8103040603 8 8103040603 8 810303022 8 8103030323 8 8103030835 8 8103030835 8 8103030835 8 8103030845 8 8103030845 8 8103030847 8 810303084 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	8103040685 8103050023 8103050032	50-344   REB REB	P EQQ-EA-5310	8503240097 8103240144 8103240583	8103240097 8103240144 8103240583	reb Res Res	
83/304/0615 8 810309022	0103050023 0103050032	RES RES		8103240144 8103240583	8103240144 8103240583	res res	
8103050023 88 8103050332 88 8103050335 88 8103050835 88 8103050835 88 8103050835 88 8103050837 88 8103050845 8103050845 8103050845 8103050847 88 8103050847 88 8103050847 89 81050847 89 81050847 89 81050847 89 81050847 89 81050847 89 8105087 89 8105087 89 8105087 89 8105087 89 8105087 89 8105087 89 8105087 89	8103030032	RES RES	ORNE-HAGRD-108	B100240983	B103240503	RES	
03000000000000000000000000000000000000		REB	ORNG-HABRD-100				
B1030903B5 B103090B2 B103030B25 B103030B35 B103030B45 B103030B46 B103030B46 B103030B47 B1030B47 B1030B47 B1030B47 B	8100050373					. 4 44 6.3	
B1030903B5 B103090B2 B103030B25 B103030B35 B103030B45 B103030B46 B103030B46 B103030B47 B1030B47 B1030B47 B1030B47 B				0.000.014	0150010115	250	011 -111050 00004
6103050832 8103050835 8103050837 8103050845 8103050846 8103050846 8103050847 810305097 810305097 810305097 8103050175 8103050175 8103050175 8103050177	8103080385			8103590994	8103260669	REO	BNL-NUREQ-28924
8103350835 8 8103350837 8 8103350837 8 8103350845 9 8103350847 9 810355097 8 810355917 8 810355015 8 810355017 9 810355017 9	8103050832	REB		8103310878	8103310878	REB	
81 03050839 8 81 03050845 8 81 03050846 8 81 03050849 8 81 03050907 8 81 03050917 8 81 03051015 8 81 0305195 9 81 03060195 8 81 03060197 8 81 03060197 8	8103030835	RES		8103310884	8103310864	RES	
#1 00050845	8103050839	RES		8103310887 8103310893	8103310887 8103310893	REB RES	
B103050B46 B103050B49 B103050P07 B103050P07 B103050P17 B103050195 B103050195 B103050197 B103050215 B103050215	4114144			8103310013	4107314212	WE S	
#1030508AP	D103050B45	REB		8103310898	8480102018	RES	
B102030407 B1020304017 B102031015 B102030195 B102060195 B102060197 B102060215	0103050046	REG		8103310901	0103310701	REB	
6103050917 8103051015 8103050195 8103050197 8103050216 81	6103090849	RES		B103310906	8103310906	RES	_
@103031015 8 8103050195 9 8103060197 8 8103050218 8	8103050707	REB	NRC-04-76-296	81A0648	8103110538+		P
8103060195 B 8103060197 B 8103060215 B	0103050917	RES		B406A L	61030505064	TOPREP	
8103060195 8103060197 8103060215	6103051015	RED	ORAL/COD/INF-01	8456A-1 R1	B103270718+	TOPREP	
8603060197 8103060218	C9103060195	RES	QRNL/MCD/NEES-0	ANL-7291 R1	8103040796*	FQ(A	
#10305021B 8	0103060197	REB		BCL-585-21 ERR	B103240399*	50-309	P
	8103040219	REB		BNL-MIREG-28647	8103120779	RES	
	6103040473	RES		BMC~MU4E0-58410	8103120784	REO	
	8103060781	REB	E00-1FBP-5221	BNL-MURE0-26951	8103120787	RES	
_	0103090147	RES	Sect of all news	BNL-NURE0-28776	8103120758	RES	
Drogorer	8103070447	REB	E0Q-000-5303	BNL-NURE0-29019	8103120769		A
	B103070437	REB	E00-LOFT-5336	BO-TOP-1 ROA	8103190104	TOPREP	••
	8103070478	RES	EGG-CAAD-5356	CE-1-A R16	8103200369+		P
8103040588	8103040388	ngo	EUG-CHAD-5336	CE-1-4 HIS	41032003011		•
	D. BOOD CARE		P E00-EA-5358	CEN-122(B)14P	8103270494+		P
8100090695	8103090593	REB		COT 1028100	B103120351#	40-8511	
8103100007 B	8103090693	REO		DC-1102 RB	8103060623*		A
8103160106	8103090695 8103100007		P ECO-EA-3117 RJ	E-115-556	8103060951		A N888 16
8103110018	8103090693	REB		EODP-EBE-14 RZ	B103100617#	TOPREP	
D107410744	8103090695 8103100007			JCP9113	8103040215*	50-217	R
	8103090695 8103100007 8103100106 8103110665	<b>REA</b>			B103170648+		P
010041411	8103090695 8103100007 8103100106 8103110465	REO REG				71-9001	18457
0102110.0.	8103090693 8103100007 8103100106 8103110665 8103110764 8103110772	REB		LAC-TR-093	8102240047*		
Of Carlotta	8103090693 8103100007 8103100106 8103110665 B103110764 8103110772 8103110789	REB REB		LAC-TR-093 NEDD-10084 VI R2C	8102260057* 8103130575*	50-219	P 79NED288
B103120752 6	8103090693 8103100007 8103100106 8103110665 8103110764 8103110772	REB		LAC-TR-093	8102260057* 8103130575* 8103160830*		80NED051

NUMBER	NUMBER	CATEGGRY	NUMBER .	NUMBER	NUMBER	CATEGGRY	NUMBER
NEDD-24222 V2 NEDD-24223 NEDD-24243 NEDD-24243 BI NEDD-24259-A	E103160855+ B103160845+ B102260351+ B102260355+ B103230327+		BONECO20 BONECO261 BONECO278	NUREO/CR-1877 NUREO/CR-1878 NUREO/CR-1898 NUREO/CR-1902 NUREO/CR-1909	8103180762 8103040538 8103020723 8103260030 8103250629	NUREG NUREG NUREG NUREG NUREG	BM1-2073 GRNL/NUREQ/TH-4 GRNL/NUREQ/TM-3
NEDD-24289 IMEOG-29100 ERR 1 N9-MF6E-81-054 NUREO CR-1704 NUREO-0011 804	8103180588• 8103200323• 8103390403• 8103260095 8103030836	TOPREP TOPREP 50-206 P 50-295 P 50-327 E	80160299 79NED104 UCRL-15140	NUREO/CR-1913 NUREO/CR-1916 NUREG/CR-1927 NUREO/CR-1928 NUREO/CR-1930	8103100087 8103090007 8103030001 8103040010 8103040623	NUREO NUREO NUREO NUREO NUREO	BUT-NOWEC-21334 BUT-5045 BUT-5045 BUT-5045 BUT-5045 BUT-NOWEC-21334
NUREG-0020 V05 1101 NUREG-0040 V04 N04 NUREG-0040 V03 N03 NUREG-0117 505 NUREG-0117 505 DRFT	8103103006 8103023703 8103070584 8103270079 8103190103*	NUREO NUREO NUREO 50-364 E 50-364 P		Nureg/CR-1936 Nureg/CR-1943 Nureg/CR-1951 Nureg/CR-1955 Nureg/CR-1962 VO1	8103090812 810326022 8103250638 8103240835 8103250646	NUREG NUREG NUREG NUREG	LA-8709-MS ANL-81-2 ORNL/NUREG/TM-4 ORNL/NUREG/TM-4
NUREG-0330 V04 NO2 NUREG-0470 S02 NUREG-0485 V03 NO2 NUREG-0485 V03 NO3 NUREG-0517 E05	8103030393 8103250485* 8103030591 8103190737 8103030571	50-311 E		NUS-1761 ADD 1 ORIL (MARRO-111 PERS 75-113 RI POE-1015-80 PLG-0147	8103110540* 8103130005 8103040615* 8103030846* 8103020220*	50-338 F RES 50-361 A 80-344 F 50-329 A	
NUREG-0919 NUREG-0540 VO2 NT1 NUREG-0566 VO1 1:01 NUREG-0566 VO1 NO2 NUREG-0666 VO3 1:01	8103230659 • 8103030520 8103060758 8103230999 8103180920 •	50-373 E NUREO HUREO NUREO 50-237 O		PR-T-78-004 PR-T-79-008 PR-T-80-010 R1 PR-T-80-052 RERR-91	8103110836 8103110830 8103100154 8103100144 8103060852*	REB REB RES RES 50-272 A	
NUREO-0693 VOZ NUREO-0693 VOZ NUREO-0693 VOZ NUREO-0696 BOZ	8103180664 81032336724 8103180079# 81031800854 8103100410	50-275 E 50-289 0 50-320 P 50-320 P MU9E0		RH-80-6-891 RH-81-1-8F-1 RH-81-2-801 SE-8P-58180) R1 86CY-76-249	8103310486* 8103050511* 8103310490* 8103240314* 8103020045*	50-327 R 50-259 R 50-327 R 50-206 P FOIA	
NUREG-0712 NUREG-0712 SO1 NUREG-0717 NUREG-0723 NUREG-0748 V91 NO1	8103030679 8103160987+ 8103030656 8103230991 8103190564	50-351 E 50-361 E 50-395 E HASTE MOT NUREO		SECY-77-054 SECY-79-353 SECY-79-342 SECY-80-168 SECY-80-212	8103183091 8103040162* 8102280186* 8007010387 8007070498*	BECY 10CFR 10CFR 50-247 P 10CFR	
NUREG-0748 VOI NO2 NUREG-0750 VIZ NO3 NUREG-0751 NUREG-0755 NUREG-0756 ERR	8103270317 8103030380 8103230599+ 8103240278* 8103230291+	NUREO MUREO NUREO COMMISSION 50-250 P		86CY-80-243 55CY-80-325 56CY-80-530 86CY-80-533 56CY-80-545	8103030066* 8103180932* 8102230060* 8102230044* 8101190671*	F01A 50-237 O 10CFR 10CFR	
NUREO-0757 NUREO-0758 NUREO-CR-1872 ERR NUREO/BR-0001 V1 NUREO/CP-0016	8103040599 8103040978 8103230239 8012040152 8103030599	NUREO NUREO NUREO NUREO NUREO	ORML/NUREG/TM-4	SECY-80-551 SECY-80-551A SECY-81-020A SECY-81-020C BECY-81-020C ADD	8101200449# B101200623# B103030450# B103230072# B103230078#	10CFR 10CFR 50-437 A 10CFR 10CFR	
NUREG/CR-0781 801 NUREG/CR-0849 V02N02 NUREG/CR-1134 V02N01 NUREG/CR-1240 V02 NUREG/CR-1349 V01	8103020707 8103230243 8103100134 8103030821 8103100179	NUREO NUREO NUREO NUREO	RRA-T8008 UCRL-3215-80-3 0EAP-21304-17 HEDL-1ME 80-1 SAND80-0477/1	BECY-81-043 BECY-81-061 BECY-81-077 BECY-81-077A BECY-81-0778	8103040195* 8102180203 81030908654 B103160440* 8103160379*	10CFR BECY 10CFR 10CFR 10CFR	
NUREO/CR-1345 V02 NUREO/CR-1380 V02 NUREO/CR-1460 V04 NUREO/CR-1453 HUREO/CR-1533	8103030353 8103020782 8103100060 8103250261 8103250141+	NUREO NUREO NUREO NUREO NUREO	BAND80-0477/2 PNL-3325 EQG-2079 BAY080-1047 EPRI NP-1460	SECY-81-094 SECY-81-100 SECY-81-106 SECY-81-111 SECY-81-119	8103160839# 8103160485# 810360839#	10CFR 10CFR SECY COMMISSION 50-3 P	
NUREO/CR-1546 VOI NUREO/CR-1587 NUREO/CR-1610 VOINOZ NUREO/CR-1610 VOINO3 NUREO/CR-1659 VO2	8103020424 8103250293 8103040100 8103200357 8103040515		DPST-NUREO-80-5 DRNL/NUREO/TM-4 UC1D-18123-80-2 BANDBO-1897	SECY-81-125 SECY-81-133 SHECO-8101 T4-1025 TM-600	8103160312 6103180071+ 6103110312+ 8103060619+ 8103300487+	SECY 50-320 P 50-322 A 50-361 A 50-264 P	QAT J-2443
NUREG/CR-1692 NUREG/CR-1690 NUREG/CR-1701 NUREG/CR-1702 NUREG/CR-1720	8103030308 8103020775 8103030664 8103040548 8103100072	NUREO NUREO NUREO NUREO NUREO	SAND80-1957 PML-3382 UCRL-13986 UCRL-13985 MEDL-TME 80-53	TM-64 R1 TR-75-74 R1 TVA-TR75-14 R3 UCRL-5678 UTEC ME 80-015	8103060429+ 8103060557+ 8103120293+ 8103040791+ 8101070345+	50-361 A 50-361 A 10PREP FOIA 50-72 F	N888 59
NUREO/CR-1745 NUREO/CR-1751 NUREO/CR-1754 NUREO/CR-1761 NUREO/CR-1765	8103240237 8103100076 8103100125 8103250256 8103250458	NUREO NUREO NUREO NUREO NUREO	BMARC-401/80-01 UCRL-13084 ORNL/NUREQ/TM-4 TM-321	WCAP-9804 WPP88-0A-004 R4 DRFT XN-NF-73-27 (NP) 83 XN-NF-75-32 (NP) 83 Y1003J01A13	8103140257* 81030308654 8103030505* 8103030031* 8103240230*	TOPREP TOPREP TOPREP TOPREP 50-321 P	
NUREO/CR-1767 NUREO/CR-1780 NUREO/CR-1781 NUREO/CR-1782 NUREO/CR-1783	8103230106 8103030610 8103020674 8103040511 8103190763	NUREO NUREO NUREO NUREO NUREO	ORNL-ANDREO/TM-4 UCRL-53011 BANDBO-2332 UCRL-53009	Y1003J01A17 YAEC-1138 YAEC-1207 YAEC-1238	8103160428* 8103310257* 8103200204* 8103310214*	50-298 P 50-309 P 50-29 P 50-271 P	
NUREO/CR-1798 NUREO/CR-1799 NUREO/CR-1800 NUREO/CR-1814 NUREO/CR-1816	8103040607 8103110819 8103040379 8103260039 8103100116	NUREO NUREO NUREO NUREO NUREO	BML-MUREO-51296 BML-MUREO-51297 BML-MUREO-51298 AML-CT-81-9 UM 0220384028				
NUREO/CR-1837 Nureo/CR-1835 Nureo/CR-1838 Nureo/CR-1868 Rureo/CR-1872	8103040491 8103310924 8103190337 8103030530 8103030336	HUREO HUREO 50-219 P HUREO HUREO	ORNL/NUREO/TH-4 E90-2075 ORNL/NUREO/TM-4				

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the dock number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Content

ACCESOTO	4 (40/5/8).17		
	PRINCIPAL		
ENCLOSURE	DOCUMENT	DATE	SUBJECT
ENCLUSURE	POCONENT	188060	CATEOCRY
7910090402	0102260479		
771107070702	8102260479	81/02/05	FOIA
	0102260477	01/02/05	FOIA
7911050330		01/02/05	FOTA
8002120122	0103120027	00/01/14	EOTA
8005150156	0193120027	89/01/14	FOLA
0000100100	0.000.000.00	00.00.00	<b></b>
6005150133	0103120627	80/01/14	FOLA
0004070777	0103130060	60/15/16	HASTE HOT
8008010214	8103590018	01/03/03	FOIA
0006270164	8103140773	01/03/05	FOIA
8007070440	8103180974	01/05/53	1-GCFR
(1000)	0100110100	1. 1. 1. N. 1. 1. N. 1.	men.
0007240519	B103170100	01/02/25	FDIA
0011040713	0103170171	81703705	90-367 A
8012040390	0012040371	00/15/03	50-327 F
8015100203	0103020079	H1/02/23	FOIA
0012310217	81001190603	81/01/30	MABIE MOT
0101070105	0101070140	00/12/03	50-338 F
0101070204	8101050190	00/15/03	50-330 F
0101070510	0101070160	00/15/03	50-330 F
0101070220	0101070160	80/15/03	80-339 F
0101070333	8101070000	80/12/01	50-212 F
8101070349	0101070341	00/15/05	50-72 F
8101010354	$a_{101010393}$	$BO \times 15 \times 07$	50~3 F
8101070447	8101070447	80/15/05	50-317 F
8101070467	8101020482	00/15/03	90-331 F
0101070472	8101070462	60/12/03	50-331 F
D101070552	0101070540	80/12/01	50-282 F
B1010B0014	01016800003	130115103	50-10 F
B1010B001A	B10100003	00/12/03	30-10 F
8101000029	01910800000	00/15/03	50-10 F
8101000033	0101000003	80/12/03	30-10 F
8101000033	B101080003	80/12/03	50-10 F
01010000068	0101080051	80/15/05	50-10 F
8101080153	0101000119	00/15/01	50-327 F
8101080207	0101000501	00/11/28	50-317 F
8101080203	6101080276	80/15/03	50-202 F
8101090087	E000001018	80115105	50~135 F
8101090104	8101090097	60/12/01	<b>50</b> ~36! F
8101140090	0100100177	01/02/13	70-182
8101190671	8103170668	61/03/05	LOCER
6101200447	8100100040	81702704	105FR
8101500953	0103100040	01/02/04	1 OCFR
8101220158	8101070160	E012103	80-338 F
8101350501	8101090097	B0\15\01	50-361 F
B101220231	B101090083	00/15/05	30-155 F
8101220258	B1010800003	80/13/03	50-10 F
8101220917	8101080119	80/12/01	30-327 F
8101550354	G012040391	80/15/03	50~327 F
8101220591	B10107054B	80/12/01	50-282 F
8101220399	8101070447	80115105	50-317 F
B101550918	8101070352	60/12/01	90-3 F

ACCERBIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 186UEO	SUBJECT	łγ
8101220624	0101070341	00/15/05		
0101220627	0101070330	80/12/02	50-72	F
8101230369	0103100100	80/12/01	30-272	F
0101230371	8103180108	81/02/11	LCCFR	
8101230527	0101070462	80/12/03	100FR 90-331	F
8101230543				
8101300544	8101000091	80/12/02	50-10	F
8101300259	8101300233 8101300233	81/01/13	50-207	þ
6101300267	8101300233	81/01/13 81/01/13	10-237 50-237	P
8102020497	01031001CB	81/02/11	100FR	P
B102040399	0.000			
0102170524	0102040399 0102170407	81/01/30	30-35B	F
8102170630		01/02/09	71-9013	
0102170635	8102170607	01/02/03	71-7013	
8105160504	8102170607 8102180203	81/02/05	71-9013	
aroe tones,	0105160507	81/01/26	BECA	
8102180222	8102180200	81/01/26	BECY	
8102100228	8105180503	81/01/26	BECY	
8105140855	8103230207,	61/03/18	ACRE	
8102170837	0105120833	81/01/09	40-8502	
8102190871	8102190862	B1/01/20	71-6400	
B102200170	0100240139	81/02/20	(694188)	OΝ
B102200419	8103170683	01/01/30	WASTE MO	
B105530090	8101290577	01/01/07	10CFR	•
8102230094	8101290577	81/01/07	LOCFR	
8102230694	8102230689	81/02/04	40-4192	
8102230759	8100180909	81/03/02	50-315	ρ
0102260067	B102260058	01/02/04	71-9001	•
8102260125	8103160574	81/02/27	ICCFR	
8102240130	0103160574	61/02/27	LOCER	
8105590359	8102260479	81/02/05	FOIA	
8102250529	8102260479	81/02/05	40-1162	
0102260533	9102260479	81/02/05	40-1162	
8102260538	8102260479	81/02/05	40-3453	
8102250548	8102260479	81/02/05	FOIA	
B102260951	8102260368	81/02/20	30-333	P
8102240555	6102250968	81/02/20	50-333	p
8102260356	B102260479	81/02/05	FOIA	•
8102260561	8102260479	81/02/03	FOIA	
8102260362	8102260479	81/02/05	FOIA	
0102260566	8102260479	81/02/05	FOIA	
8102280579	6102240548	B1/02/20	50-333	р
8102260572	8102240568	81/05/50	30~333	P
8102250575	8102260968	81/02/20	30-333	P
8102260672	8102240479	81/02/05	FOIA	•
8102260577	8102260479	81/02/05	FOLA	
8105590683	8102260479	81/02/05	FOLA	
8105590925	8102260479	81/02/05	FOIA	
8102260703	6102260479	81/02/05	FOIA	
0102240711	8102260479	81/02/05	FOIA	
8102260743	8102260479	81/02/05	FOIA	

# ACCESSION NUMBER ACCESSION NUMBER PRINCIPAL DATE SUBJECT PRINCIPAL DATE PR

FA.C. SCUME	PATRITPAL	DATE	SUBJECT			ENCLOSURE	PRINCIPAL	DATE	CATEO	
ENCLOSURE										
8152260747						8103030008 8103030008				
810226075 810226075						8103030009		01/02/17	50-272	
8102269764	0102260479	81/02/0				9103030010	8103030005	81/02/17	71-271	
8102240770	0 8102266479	81/02/0	i FOIA		•	3103030012	8103030004	01/02/17	50-272	P
B16226077						103030055	8103030019	01/02/10	71-130	
8102260782 8102260782						3103030031 3103030047	8103030021 8103030040	81/02/24 81/02/27	TOPREP 50~302	18
8102270351	8103250433	80/12/17				3103030045	8103030054	81/02/11	50-335	ä
8102270558	B102270554	01/01/33	PR (		Ε	3103030066	6103030052	81705704	FOIA	
8102270590				P	8	1103030083	B103030052	01/02/09	FOLA	
81C2270774 8102280183				R		1103030089	8103030052	01/02/09	FOIA	
8102280186						1103030047	8103030084 8103030086	01/05/10	50-331 50-331	b L
8102289325	0103230058	81/02/19	50-369	P		1102020115	8103030086	01/02/10	00-331	P
8102280404		81/02/19	50-369	Р	e	103030118	8103030101	81702705	70-2000	
8103020044 8103020045				0	8	103030145	0103030129	81/05/09	50~206	, p
8103020047			FO1A 50-289	G		103030161	8103030130	01/02/06	50~312	Q P
8103020052	8103020040			Q.		103030170	8103030127	U1/05/09	50~206 50~206	- j.
8103020057	8103020053	81/01/15	FOIA			103030186	0103030172	81/01/02	80 08"	
8103020070 8103020075		81/02/17	C04418910			103030205	8103030173	81/05/12	50-550 50-245	O P
8103020078			11221PM03			103030214	8103030193	81/02/13	30-245	P
8103020080	8103050000		CO3418510			103030306	8103030269	81701712 81701712	00NTRAC 50~250	່ ຜ
8103020084		81/02/17	COMM15810	ON						
8103020087 8103020103	8103020079 8103020099	81/02/23	FOIA	•		103030331	8103030313 8103030319	01/02/07	50-334 CONTRAC	T P
8103020116	8103050110	81/01/23	40-8064 50-244	p		103030352	8103030342	80/12/23	40~8064	
8103020150	8103020113	81/05/53	50-10	н		103030358 103030374	0103030344 0103030367	01/01/29	50~49D 50~155	a a
8:03020124	8103020113	81/02/23	50-10	н						••
8103050550	8103020194 8103020210	81/02/13		F	8	103030380 103030387	0103030356 0103030356	81702713 81702713	50-327 50-327	b h
8103020231	0103020222	81/02/12	50-329 71-409	A	· · · · · · · · · · · · · · · · · · ·	103030395	9103030394	01/02/13	80-327	,
8103020240	8103050558	81/01/15		O.		103030410 103030425	6103030401 6103030401	01\01\05 01\01\05	50-191 50-151	O)
8103020247	8103020238	81/02/12	71-138					01/01/02	20-134	a
8103020264 8103020372	8103020254 8103020368	81/02/12	71-2	_		103030450 103030457	8103180039 8103030440	01/02/12	80-407	۸
B103020374	8103020369	81/02/24 81/02/06		P Pl	9:	E840C0E01	8103030492	01/02/07	50~200 50~346	O).
8103020381	B103020373	81/02/09		R	8:	103030470 103030476	8103030452 8103030452	01/02/09	50~200	P
8103020383	8103020376	81/02/20	50-333	P				81/05/04	20~500	tı
8103020391 8103020403	9103020376 9103020384	81/02/20	50-333	ρ		103030480 103030488	0103030447 6103030447	01/01/14	50~326	a
8103020404	8103020397	81/01/19 81/02/04		Q R	81	03030495	8102020449	81/01/14 81/01/14	50~326 50~326	a a
8103020413	8103020407	81/02/23		P		03030498	8103030489	01/01/13	80-275	Q
8103020420	8103020407	81/02/23	50-320	P			8103030491	81/03/01	20-540	Ħ
8103020425 8103020429	8103020410 8103020410	81/02/27	50-367	К		03030505 03030507	8103030492	01/02/24	TOPREP	
B103020434	8103020428	81/02/27 81/02/23		K F	81	03030921	8103030449 8103030512	01/01/14 81/01/09	50~36 <i>1</i>	O)
B103020444	8103020438	81/02/27		R	18	03030545 03030546	8103030540	01/02/17	80-295	);
B103020453	8103020448	81/02/24	70-820		· .	03030544	8103030541	81/05/19	50-346	0
8103020489 8103020495	8103020487 8103020491	81/02/23	50-237 F		61	03030554 03030560	B103030547	81/02/17	50-213	R
8103020522	8103020318	81\05\52 81\05\50		р 8	91	1960£060	8103030555 8103030552	81/02/20 81/02/27	90~204	P
8103050258	8103020524	81/02/24		g	91	03030569	8103030595	81/02/20	80~324 80~206	P
8103020536	8103020532	81/02/24	50-327 E	B	_	03030575	8103030565	81/02/27	90-505	ĮR.
8103020545 8103020553	81 <i>0</i> 3020539 8103020548	81/02/19	30-321	8		03030577	8103030573	01/02/27	80-272	o
8103020365	8103020562	81/02/18 81/02/23	50-293 g 50-344 g			03030594 03030598	9103030597 9103030592	01/02/13	50-593	R
8103020571	8103020567	81/05/59	\$0-395 Q		811	03030623	B103030616	81/05/15	SO-265 XPORYLIC	£i
8103020575	8103020549	81/02/50	50-366 g	2	81	9E40E0E0	8103030635	81/02/27	50-302	1
8103020582 8103020606	8103020576 8103020598	81/02/19	80-366 8	•		03030645	8103030639	01/02/27	50-382	t
8103020640	8103020638	81/02/23 81/02/23	50-348 8 50-30 p			03030650 03030655	8103030435	B1/02/27	50-382	i
Ø103020646	9103020638	81/02/23	\$0-30 P		810	1 6600000	8103030639 8103030646	01/02/27 81/02/25	50-382 50-344	9
8103020651	8103020438	81/02/23	50-30 p		816	03030666	E990E0E018	81/02/20	50-30	Ř
8103020654 8103020659	8103020638 8103020647	81/02/23	50-30 p		Bio	3030667	8103030462	B1/02/25	50-320	8
8103020672	8103020664	81/02/10	XPORTLIC 50-320 G		810 Ara	03030674 03030677	8103030670	81/02/20	70-260	P
8103050981	B103020675	80/12/15	XPORTLIC	•	810	3030765	8103030671 8103030678	B1/02/26 B1/02/26	50-267	Ø
8103020688	8103020675	90/12/15	MPDRTLIC		810	3030484	9103030483	81\03\05		e P
8103020701 8103020704	8103020496 8103020496	81/01/07	50-266 g	1	910	3030488	6103030463	81/03/02		
8103020719	8103020717	81/02/11	50~538 Q 70-984	•	810	77030944	8103030492	81/02/20		P R
8103020732	8103020728	81/02/10	30-318 p		810	3030712	8103030498 8103030707	81/03/02	50-396	K
B103020735	B103020728	81/02/10	50-318 P		910	3030717	8103030707	81/02/27 81/02/27		P P
8103020739 8103020746	8103020728 8102260479	81/02/10	50-31B P		810	3030719	8103030714			-
8103020762	B10302075B	81/02/05	FQ1A 50-315 p		910	3030720	8103030707	81/02/25 B1/02/27		R Þ
8103020767	8103020758	81/01/30	30-315 P		910	3030723	8103030707 8103030707	81/02/27	80-3	P
							01400			P P
									'	•

			ACCEBION NOTABLE
0011/0101	D. T. T.	a	**********

					PCCE68	ICM MONDER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188080	CATEGOR CATEGOR		ENCLOSURE	PRINCIPAL DCCUMENT	DATE 159UED	5UBJE(	
8103030733 8103030734 8103030740 8103030748 8103030755	8103030707 8103030731 8103030735 8103030743 8103030750	81/02/27 81/02/27 81/02/24 81/02/24 81/02/24	20-351 20-352 20-364 20-364	P 6 6 6 6 6	81033406 810334067 810334007 810334007 810334008	6103040060 8103040064 8103040050 8103040049	81/02/13 81/02/13 81/02/13 81/02/13	30-348 30-400 30-348 50-413 50-348	P G P G P
8103030757 8103030763 8103030765 8103030766 9103030767	8103030753 8103030760 8103030761 8103030761	81/02/20 81/02/25 81/02/24 81/02/25 B1/02/26	50-220 50-395 50-366 50-312 50-272	8 8 8 8 8	810324008 810324005 810324010 810324010 810304011	8103040064 8103040049 8103040049	81/01/28 81/02/10 81/01/28 81/01/28 81/02/13	50-413 50-400 50-413 50-413 50-302	0 0 0
8103030775 8103030783 8103030787 8103030791 8103030799	8193030772 8103030779 8103030781 8103030788 9103030434	81/02/02 81/02/26 81/02/26 81/02/26	50-272 50-237 50-155 50-255 50-397	8 8 8 8 8 9	8103040116 8103040120 8102040143 8103040153 8102040153	8103040104 8103040135 8103040136	81/01/28 81/02/13 81/01/14 81/01/14 81/02/27	50-413 50-302 GA999 GA999 10058	0
8103030801 8103030802 8103030804 8103030807	8103030795 8103030796 8103030797 8103030434 8103030772	81/02/27 81/02/25 81/02/26 81/02/02 81/02/25	50-338 50-313 50-155 50-397 50-10	R R G O H	8193949159 8193949166 8193949176 8193949177 8193949177	8103040136 8103160574 8103160574	81/01/12 81/01/14 81/02/27 81/02/27 91/01/09	50-329 0A999 10CFR 10CFR 50-245	0
8103036810 8103030811 8103030819 8103030820 8103030827	8103030806 8103030434 8103030813 8103030815 8103030822	81/02/26 81/02/02 81/02/25 81/02/25	50-255 50-397 50-244 50-312 50-213	6 6 6 8	810304017 910304018 810334018 810304019 810304019	8103040173 8103040161 8103040163	80/09/16 81/02/06 81/02/18 80/09/16 80/09/16	50-155 50-361 50-272 50-155 50-155	P G P
6103030834 6103030835 6103030837 6103030840 6103030847	8103030828 8103030828 8103030833 8103030830 8103030830	81/02/26 81/02/27 81/02/27 81/02/16 81/02/27	50-346 50-202 50-305 50-409 50-346	8 8 8	8103040199 8103340215 8103340215 8103340225 8103040225	8103040187 8103040208 8103040207	81/02/26 81/01/27 81/02/27 81/01/09 81/02/12	80-321 84999 80-219 50-397 80-263	R Q P
8103030848 8103030850 8103030858 8103030855 6103030856	010303044 0103030304 010303034 010303064 0103030661	01/02/27 01/02/20 01/02/25 00/12/17 01/02/25	50-344 50-331 50-265 50-320 50-271	R P R 0	810304022 810304023 810304023 810304024 810334024 810334024	8103040211 8103040211 8103040229	81/02/10 81/02/12 81/02/12 81/01/27	0A999 50-263 50-263 50-280 50-316	6 6
8103030869 R103030866 B103030867 B103030874 B103030876	8103030837 8103030850 8103030863 8103030863 8103030870	81/02/27 81/02/26 81/02/26 81/02/27	TOPREP 40-4492 50-320 50-320 50-322	ft Ft O	8103040247 810304024 810304025 810304025 810304025	8103040229 8103040230 8103040189	81/01/27 81/02/10 81/02/24 81/01/27 81/02/10	0A999 50-280 50-133 0A999 50-316	Р Н Р
0103039877 0103030078 010303988 0103030808 0103030894	8103030883 8103030871 8103030883 8103030883	01/02/24 81/02/10 81/02/10 01/02/27 81/02/27	50-321 50-205 50-265 50-275 50-275	8 P P 0	&L03040256 B103940266 U103940266 B103040265 B103040265	8103040252 8103040246 8103040230	81/02/24 81/02/11 81/01/16 81/02/24 81/02/10	50-133 50-334 50-89 50-133 50-316	N P O H P
8103030899 8103030709 8103030914 8103030929	8103030435 8103030043 8103030043 8103030343	81/02/10 81/02/10 81/02/10 81/02/10	50-269 50-249 50-269 50-269 71-419	P R P	8103040265 8103040276 8103040273 8103040273 8103040288	8103040252 8103040266 8103040189	81/01/27 61/02/11 81/02/27 81/01/27 81/02/12	0A999 50-324 50-320 0A999 50-3[6	р Q Р
8103030741 8103030747 8103030753 8103030758 8103030758	8103030933 8103030935 8103030935 8103030935	81/02/19 81/01/12 81/01/12 81/01/27	XFORTUIC 50-155 50-155 50-155 71-407	p q q	8103040290 810304029 8103040294 8103040296 8103040301	8103040278 8103040280 8103040275	81/01/27 81/02/11 81/02/12 81/01/22 81/02/24	0A999 50-334 50-316 50-373 50-133	Р 0 Н
8103030971 8103031003 8103031005 8103031018 8103031024	6103030942 6103030942 6103030942 6103030942	81/01/27 81/01/26 81/01/30 81/01/30 81/01/30	71-416 71-414 50-298 50-298 50-298	P P	8103040300 0103940304 0103040301 0103040311 0103040321	6103040280 6103040297 6103040278	91/02/11 81/02/12 81/02/26 81/02/11 81/02/24	50-334 50-316 50-320 50-334 70-820	P የ የ
0103031105 0103031110 0103031122 0103031132 0103031144	8103031094 6103031113 8103031113 8103031113 8103031139	80/12/04 81/02/09 81/02/09 81/02/09 81/01/21	50-267 80-247 50-247 50-247 GA999	р Р	6103040325 9103640331 8103340335 8103340341 8103040342	9103040322 8103040313 8103040313	61/02/09 81/01/15 81/02/09 81/02/09	50-460 50-326 50-460 50-460 50-509	0 0 0 0
8103031147 8103031151 8103040002 8103040003 8103040004	0103031139 8103031139 8103040001 8103040001 8103040001	81/01/21 81/01/21 81/02/04 81/02/04 81/02/04	0/444 0/444 50-404 50-404 50-404	<b>የ</b> የ	8193040396 8103040355 8103040355 8103040374 8103040445	8103040343 8103040313 8103040313	81/02/09 80/12/31 81/02/09 81/02/09 81/02/25	50-469 50-271 50-460 50-460 70-27	G G G
8103040014 8103040021 8103040027 8103040028 8103040033	6103040007 6103040007 6103040007 6103040020 6103040007	B1/02/13 B1/02/13 B1/02/13 B1/02/13	50-312 50-312 50-312 50-312	0 0 0 A 0	B103040455 8103040476 8103040476 8103040497 8103040497	8103040473 8103040480 8103040487	81/01/21 81/02/27 91/01/29 81/02/25 81/01/29	50~445 40~8452 40~8610 50~331 40~8610	ar R
8103040034 8103040041 8103040050 8103040056 8103040057	8103040020 8103040007 8103040044 8103040044 6103040047	81/03/02 81/02/13 81/02/09 81/02/09	50-329 50-312 50-413 50-413 50-413	A Q Q Q	810304050; 810304050; 810334081; 810334052; 810304052;	B103040480 B103040480 B103040480	81/02/12 81/01/29 81/01/29 81/01/29 81/01/14	70-1151 40-8610 40-8610 40-8610 70-920	

ENCLOSURE	PRINCIPAL DOCUMENT	DATE DSUED	GUBJECT CATEGORY	En	ICLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT	
								CATEGORY	· -
8103040528	B (03040480	81/01/29	40-8610			B103041029	B1/02/11	50-313	Q.
8103040532 8103040534	8103040480 8103040514	81/01/29 81/01/14	40-8610 70-820			8103041033 8103050003	81/02/20	WASTE MOT	г
8103040539	8103040480	81/01/29	40-0610	81	03050013	B100000008	81/02/06	50-267	q
8103040540	B103040514	81/01/14	70-620	61	03050030	8103050017	81/01/29	50-313	0
8103040545	8103040514	B1/01/14	70-820	RI	03050035	8103050026	81/01/16	50-312	a
8103040551	8103040514	81/01/14	70-820			8103050041	81/01/07	50-483	ã
8103040555 8103040569	8103040514 8103040558	81/01/14 81/01/09	70-820 50-219 F			B103090049	81/02/18	50-416	а
8103040572	8103040563	81105150	TOARTIED			8103050043 8103050053	81/02/19 B1/01/14	FO1A 50-361	0
									•
8103040578 8103040583	8103040570 8103040570	81/02/06 81/02/04	50-327 ( 50-327 (			8103050045	81/02/18	50-416	G
B103040565	8103040570	81/02/06	50-327	<b></b>		8103050043 8103050045	81/02/19	FOIA 90-416	a
8103040587	8103040570	81/02/06	50-327	មា	03050074	8103050057	81/05/50	50-259	P
8103040591	8103040581	81/02/26	50-289	91	03050078	8103050068	81/01/15	50-348	G.
8103040593	8193040570	81/02/06	50-327	BI	03050079	8103050062	81/01/29	50-313	Q-
8103040594	01030405B9	81/02/27	\$0~302		03050082	8103090045	81/05/18	50-416	G-
8103040619 8103040632	8103040612 8193040629	81/02/24 81/02/26	50-309 50-369		103050084 103050092	8103050077 8103050043	81/05/14	89 A103	
0103040633	8103040630	81/02/23	50-245	. **	103050072	B103050043	81/01/09	50-382	0
8103040636	B 103040635	81/02/26	40-85B5						_
9103040643	B (03040639	81/02/27	30-296		103050100 103050102	B1030500B9 B103050043	81/02/19 81/02/19	90-409 4103	Q
8103040647	8103040644	81/02/27	50-325	B1	03050109	8103050098	81/02/09	50-327	P
8103040657 B103040662	8103040654 8103040658	81/02/18 81/02/18	50-317 70-197	91	03090110	B103050043	81/02/19	FOIA	_
3103040a0x	0103040338	81/02/13	70-137	91	103050112	8103050106	81/01/14	50-498	a
8103040665	8103040459	61/02/18	70-157		103050113	8103050098	81/02/09	50-327	Þ
8103040473 8103040686	8103040669 8103040681	81/02/27 81/02/27			103050119	8103050043	81/02/19	FOIA	_
B103040693	B103040687	81/02/24		,	103050121 103050127	8103050098 8103050043	81/02/09 81/02/19	50-327 FOIA	P
8103040706	8103040699	81/05/56	50-369		03050129	8103050124	81/02/13	50-206	G
B103040710	B103040708	81/02/26	50-243		103050131	0100000111	04 (00 (00	CONTRACT	
B103040716	8103040704	81/05/11	FOIA	91	103050132	8103050111 8103050043	81/02/23 81/02/19	FOIA	
8103040719 8103040720	8103040714 8103040713	81/02/27	70-734	81	103050133	8103050126	81/02/12	50-263	P
8103040725	8103040724	81/02/26	90~369 F0[a		103050135 103050137	8103050124 8103050043	81/02/13	50-206	9
					103030137	0102020043	81/02/19	FBIA	
8103040736 8103040740	8103040483 8103040729	81/02/27 81/02/20	50-247 CONTRACT		103050143	8103050139	81/02/10		P
8103040744	8103040724	81/02/10	FOIA		103050147 103050149	8103050138 8103050043	81/02/10 81/02/19	50-247 FOTA	P
8103040747	B103040743	B1/02/09		9	103050154	8103050141	81/02/19	50-261	Q
8103040752	B133040743	81/02/09	20-305	0	103050155	8103050043	81/02/19	FOIA	
8102040755	B103040750	81/05/58	50-151	۱۹ و	103050156	8103030130	81/01/23	50-29	þ
8103040759 8103040762	8103040743	81/02/09		91	103050157	8103050144	81/02/05	CONTRACT	•
B103040762	8103040743 8103040749	81/02/09 81/02/24	50-302 Contract		103050160	8103090141	81/02/19	10-261	g
8103040766	B103040743	81/02/09			103050161 103050162	8103050138 8103050150	81/02/10	50-247 50-29	ъ Б
8103040767	B103040758	81/02/28	50-289						
8103040769	B103040763	81/02/27		, 4,	103050164	8103050043 8103050141	81/02/19 81/02/19	FDIA 50-201	a
8103040770 8103040778	8103040743 8103340774	81/02/09		9 A1	103050169	8103050138	81/02/10	50-247	ř
8103040784	8103040774	81/02/11			103050170	B103050141	81/02/19	50-261	a
				8.	103050171	8103050043	81/02/19	FOIA	
8103040788 8103040790	8103040783 8103040774	81/02/27 81/02/11	40~2259 50-219		103050173	8103050168	60115130		P
8103040791	8103040779	81/02/05	FOIA	01	103050176 103050178	8103050148 84103050108	80/12/30	50-237 CONTRACT	P
8103040792	B103040782	81/02/13	FOLA		103050182	8103050175	81/02/12	CONTRACT	
8193040796	8103040782	81/05/13	FOIA		103050185	8103050148	B0/15/30		P
8100040801	8103040795	B1/01/30	50-338	9 B:	102030191	8103050177	01/02/26	50-324	R
Ø103040810 Ø103040811	B103040804 B103040799	81/02/13	FOIA FOIA	81	103050192	8103050179	81/02/09	50-483	G
8103040814	8103040807	81/01/26	50-280		103050197 103053199	8103050189 8103050190	81/02/26	50-317 CONTRACT	F
0103040816	8103040799	81/02/06	FOIA		103050202	8103050170	81/05/59	CONTRACT	
Ø103040B25	B103040821	81/01/30	50-395	•					
0103040844	B103040799	81/05/09	FOIA	0,	103050203 103050204	8103050196 8103050198	81/02/05 81/01/26	CONTRACT 50-440	a
8103040850 8103040855	8103040799 8103040799	81/02/05 81/02/05	FOIA FOIA		103050211	8103050178	81/03/02	50-317	F
8103040860	8103040951	81/02/19	CONTRACT		103050219	0103050210	81/01/20	50~395	G
				81	103050222	8103050218	81/02/26	50-277	R
8103040861 8103040871	8103040799 8103040866	81/01/58	FD1A 71-413	ıe	103050225	B103050217	81/01/27	50-369	ø
8103040870	8103040882	81/01/23	CONTRACT	81	103050229	B103050224	81/02/20	70-925	
8103040899	8103040889	81/02/19	50-295	H 81	103050233 103050241	8103050226	81/03/03 81/02/19		R P
8103040904	8103040897	81702723	XPORILIC		103050242	B103050224	81/05/50	70-925	
8103040909	8103040900	81/01/08	50-329	Q gr	103090244	B103050235	81/02/10	70-1113	
8103040919 8103040929	8103040911 8103040917	B1/02/12 B1/02/13	CONTRACT 50-317	_ 61	10305024B	B103030539	81/05/59	70~1113 40-672	
8103040950	B103040917	81/02/13	\$0-263		103050255	8103050235	81/05/10	70~1113	
B103040951	8193040943	81/01/12	71-415	61	103050254 103050257	8103050220 8103050246	81/02/18		۴ ج
8103040994	8103040984	81/02/11	50-250	0					
8103041009	8103040998	81/02/23	FOLA	91	103059258	0103050249	81/02/11		Ę.
6103041011	8103041003	81/01/02	71-6581	A:	103050265 103050266	8103050 <b>8</b> 49 8103050220	81/02/11 81/02/18		P
8103041026 8103041027	8103041022 8103041021	81/01/19 81/01/26	50-416 XPDRTLIC	u 6:	103050271	8103050261	81/01/09	50-213	0
			5	8:	103050272	0103050264	81/01/19	50-338	a

8103050560

#### ACCESSION NUMBER DD167 IDA DATE SUBJECT PRINTER DATE CUR ICCY FROLINGURE DOCUMENT TEGLIER CATEAGON FROI CSHOP COCUMENT ISSUED CATECORY 6103090282 B103050222 81702702 9/1-774 RIAZOSOSAS 8103350551 B1 /00/27 50-261 . D103050295 B102050270 41/01/20 30-493 ũ B103050945 6103080841 81/02/24 50-361 0 B103050281 81701750 B102050288 90-491 ā 8103050566 810303041 B1/02/24 20-315 8103050291 B103050284 81701700 50-333 ă ñ 8103050571 D 103080841 61/02/24 30-341 ă 8103050287 61702/19 Ř 0103050293 90-234 8107790977 8103350535 80712720 MARTE MOT H10305029A 8103050290 017/03/10 51-349 ۵ B103090923 R1030505A3 81 /02 /24 30-390 B10305029B 8103050294 81/01/16 90-20 ă 810335353 8103050565 81 /02/24 30-312 ñ 8103050304 B103350100 81701730 50-395 R103050376 BI /02/24 6103053541 90-244 ž 8103050301 01/02/17 0100053707 9A-202 0103363677 8102050555 81/01/30 90-413 81/02/15 n 0103050309 8103050299 90-20 r 0103053578 BIO2030567 81/02/24 50-331 ā F 6103050313 BIARASARA 01/02/12 50..202 0102050570 8103055570 90-205 a 8103090310 81/02/17 0103050314 90-371 B102050501 6103050641 81/02/24 50-361 0103050315 B103030311 01/02/18 30-333 'n 8103050592 B103050643 81702724 50-390 0103050310 81/02/17 8103050317 50-331 B103050585 B1 / 01 / 14 90-254 ā 8103090322 RIGGORGALO 61702712 50-331 'n 8100034587 6103050563 B1/02/24 50-390 ă 8103050324 8103050370 81702717 50-250 8103050590 8103050563 01/02/24 80-200 n 8103090330 81/02/17 30-250 8103050329 8102050503 8103050563 81/02/24 30-370 ñ 0103030322 01/03/09/03/2 01/02/03 CONTRACT B100050594 9107050504 81/02/27 50-325 8103050342 0100000000 01/01/20 90-243 n B103090392 8107050598 81701712 40-202 ā 6107050343 8107050772 81701722 a 8103350600 8102050353 81/02/24 30-302 ñ 8103050334 01/02/17 0100000044 80-222 REGRASSIANS BLOZOBOSED 01/09/08 90-274 ĸ 0103050333 01/01/20 50-43B 8103050348 ۵ 8102053602 6103050401 81/02/23 VENDTI IC 0103053349 0103050339 B1/01/20 50-243 ñ B103030610 8103053±08 81 4 02/27 50-336 8103050350 B103060333 OLYGIANS 50-234 REGRESSIA B103090413 81/02/24 50-336 B10305033A 81702713 01/03/05/0351 90-272 B103050622 8103030618 H1/02/29 80-263 ě 8103050337 01/01/22 R103050355 50-134 a B103050626 0102050420 81/02/27 â R103050361 8103050354 81701719 90-101 B103050474 50-313 B107053400 01/01/10 ā B10305033A 81705718 50-204 4102050362 B103050A38 8103030435 61/02/09 RI 03090365 0103050332 81/01/22 50-334 a BI 02050420 8103099439 81/02/25 90-471 8103050356 01/02/18 BL03050367 30-206 8103350450 8103050648 81/01/19 50-285 01/02/09/02/69 REGROSOSSA 81701729 50-321 a 0.03050654 BLOZOSOKSO 81/62/19 b 50-349 B103050379 #1030503A9 B1701723 90-920 ō 6103090A7A 8103050673 81/02/27 30-245 0102050302 B163695972 81701709 50-320 B103053A29 8103050671 81/02/23 80-209 0103050383 8103050376 81701720 50-234 ñ BIDDOSOASA 6103050653 BLIODIDA 90-275 ń 81/01/13 0102020303 10-254 0103050394 n 8103050703 0103050702 01/02/29 50-334 ĕ 8103090400 APDATLIC 810000000101 01/02/20 0102050700 8100090702 81702729 90-334 ь 0103050402 Λ R103030397 01701718 90-231 0103050710 8103050702 91/02/25 50-334 8103050403 0100000000 01/01/27 50-153 a 0103050713 8103030702 81/02/25 50-334 0103090410 8103050390 01/01/29 R103350717 8102053702 61/00/29 80-224 8103050407 61703702 50-341 0.00000412 d 0103050722 8103350702 81/02/25 90-334 0100050414 01/01/29 0103050421 50-206 a SUBSBRADE 8107090719 81/01/28 49-9543 8100050422 8103050419 81105110 30-359 ก 810005021A B) 00050728 81/01/29 70-1402 0103050428 01/2050417 01/01/20 50-333 50-334 n 8102030230 6103050702 01/02/25 8103050419 01/02/19 01/02/09/04/29 30-347 ถ 0103050704 8103030719 81/01/28 40-5293 81103050434 810005040 81705750 APCRY 10 8101030736 8103050702 01/02/25 20-234 ø 8103090436 8103050414 BL701729 90-228 n B103030737 8103090716 81/01/29 8103030444 50 320 00/09/17 BL02050453 a B107053741 B103050229 81/01/28 50-397 a B103050449 01/01/29 30-247 0103050456 81/01/28 40-5293 9102050142 8103050219 00/09/17 8103050444 30-390 70-1402 0100050462 H103050747 B103050716 81/01/29 8103050463 B103050449 BL 701729 50-247 a 8193050746 81/01/30 8103080752 90-333 0 B103090460 81702710 90~408 0103050755 01/03/05/04/49 8102050744 81701730 50-333 8103050444 80/09/17 50-390 30-333 0103050472 8103050788 B103050746 81/01/30 0103050470 ELO2040440 B1701709 40-247 n 8103350759 6103050750 81/02/13 50-528 81702720 8103050471 FOLA 81/01/20 0103050484 R107050760 R103050754 50-409 a 0103050489 8103090477 81702727 30-313 R 0103050762 8103050746 81/01/30 50-333 ā 81/02/13 8103090489 8163690481 03 (03 (22 50~359 í١ B163636288 8100050050 50-528 n 81/02/13 50-528 6103090492 B103050421 81702720 FULA 8103353772 8103050750 ò D103050779 50-320 8103090479 0103090401 01/01/27 30-351 8103050764 81702713 0103050500 8103030471 01702720 FUIA B103250776 8103050770 81/02/19 30-038 ā B103050493 01/02/25 30-203 P B102030778 81030507A9 R1/01/E6 10-305 a 0103090502 6103030306 0100050495 81/02/25 90-280 8100050781 B103050790 81/02/13 0102050500 0103050501 81/03/03 TOPREP 8103090764 81/02/13 10-220 ti 8103050188 81/01/DA 50-220 0103050511 B103040497 F11702727 30-259 ρ B103090709 B103050781 a 01/02/29 8103050792 81/01/05 50-200 8103050312 0103050499 8103030797 TENATI IC B103050505 01/02/06 C098165108 D103050805 9103050798 81/02/12 R103030513 B103050B03 BEZ0170A 50-387 40702704 COMMISSION 8103050012 0102050910 \$103050505 81/02/25 90-282 B103050813 8103050764 81/02/13 50-320 8103050519 8103030327 8103050821 8103090919 81/02/25 50-282 B103050B26 BE/02/19 PRH 8103050532 CONTRACT 8103050528 81703702 90-369 8103050827 8103050814 81702709 8103059533 81/02/11 40-8027 0100050523 カレノカフィンス 50-324 ď R103050859 B103050856 0103050936 8103030544 MARTE MOT A103030865 8103160574 81702727 10CFR 8103050539 20/12/22 70-1271 60/12/19 0103050547 8103050537 01/02/20 50-317 р #103050875 8103050870 81/02/17 COMM15810N 0103050883 B103050541 81/02/24 50-361 a 6103030890 8100050548 0103050972 RI/02/20 50-204 9103050540 81/05/59 50-312 8103631030 61000000000 70-1277 8103040011 B103060006 B1/01/29 8103090541 81702724 50~361 G A103090999 8100060017 8103043004 B1/01/29 70~1077 0103050556 81000000000 81/02/20 30-317 81/01/29 70-1227 01/02/27 50-402 B103060021 B103060004 8103030957 8103090947 A 81/02/23 50-237 0 8103050546 81/02/27 50-261 8103060049 B103040039 8103050538 81/02/26 FOIA B1030A00&A 81/02/26 50-312 a A1030A0073 0103050559 8103090540 40-6622 B103363091 8103040083 81/02/12 01/02/24 8103080841 50-361 α

	PRINCIPA								
ENCLOSUR						PRINCIPAL	DATE		
				OORY	ENCL OSUR	DOCUMENT		SUBJEC	
								CATEGO	RY
81030601					81030901				
81030601			06 71-42	1					F
B1030601			29 WASTE		B1030701			70-143	
10905018	<b>79 810</b> 304001	8 81/02/1	O CONTR		B1030401		7 81/02/16		+
81030601	BJ B10306016	9 80/12/2	9 NASTE		810307026	2 810309019	7 81/02/16		
			. MHOIE	HU I	810309020	3 810309019			Н
81030602	59 810306022					- 0.000,017	0 01/02/2	7 50-327	þ
81030602					810309020	7 810200040			
				51	810307021				
B1030602				0 Р					
B1030602			3 50-25	0 P	B10307021				0
81030602	70 B10306029	0 61/02/1	9 70-11		810304051		0 01/02/16	XPORTLIC	
				••	81030303	9 810309020	5 81/02/11		•
810309053	7 810306027	1 8170070	3 50-40					10-124	
910306026	7 810306027	1 81/03/0			810309022	7 8103090218	81/02/11	30.03	
B10306029					810309022	9 810309022			_
B10306029					810309023				Q
810306025					810309023				Р
01000021	7 810306028	9 B1\05\1	9 50-315	5 G	810309023				ρ
810306029					010304023	9 8103090234	81/05/11	40-8027	
			2 50-219	R	#100cmes				
810306030			0 50-302		B10304054			50-155	ρ
B10306030	9 810306029	9 81/02/2			810309024		81/02/13		•
810306031		4 B1/01/0			810307025	1 8103090234	81/02/11	40-8027	
810306031	3 810304027	81/03/0			810309026	B103090255	81/02/11		
		01/03/0	3 50-409	, b	810309026	3 8103090257		70-854	_
810306031	6 810304030	7 04 (05 (6)	<b>.</b>			0.00070237	81/01/55	50- <i>25</i> 5	P
810304031					810309026	7 04000	_		
				P				50-255	p
810306035		81/02/2	7 50-261	R	910309027			50-255	P
EE0306033	1 8103060319	81/02/04	4 30-412		810309027		81/01/21	50-254	œ.
810306035	5 8103060344	81/02/13			810309027	8103090266	81/02/11	70-25	G,
			30-200		810309027	8103090257	81/01/22		_
810306035	B 810305034E	81/02/08	BA	_			001/E&	50-295	P
810304037					8103090278	8103090268	01./00		
810306039			90~29	P	810309028			TONTRACT	
				P	510307028			90~269	R
810306040			50-244	P	810309058		81/02/11	70-398	
810306041	8103060406	81/02/13	30-220		810305053		81/02/02	CONTRACT	
				-	B103090297	8103090286	81/02/11		^
8103060430	9103060419	81/02/17	50-409	ρ			41.027.,	30-324	G
B103060447	B103060436		50-237		B10309030B	6103090303	81.700.411		
9103060465	B103060435			Ρ	8103090310		81/05/11	70-698	
810306048				Q	8103090319		81/05/53		P
BI 030604B9				0			61/02/18	XPORTL.1C	
0103080469	8103060483	81/02/23	PRM		8103090321		81/02/11	70-698	
					8103090330	8103050323	81/03/03		P
8103060505		81/01/07	50~387	a					
8103060508		81/03/03		p	B103070334		81/02/13	50-409	F
B103060514	8103090215	81/03/03			8103090339	B103090329	81/02/11		۲
9103060525	8103060518	81/03/02		P	8103090340	8103090337		70-754	
8103060545				R	8103090370		81/02/26		Р
4.000000	0103090338	10/03/01	50~318	3			80/12/24	90-395	Gr Gr
01030/004					B103090372	8103090366	80/12/24		ā
8103060951		B1/02/13	30-361	Α					_
8103060552		81/03/02	50-272	R	B103090403	8103090398	81/03/03	50-206	P
8103060855		81/03/02	50~155		8103090418	B103090412	81/03/05		
8103060557	8103060541	81/02/13		6	8103070422	8103090413			P
8103060561	8103060941		30-361	Λ	B103090429		81/02/18		G .
***********	0102000341	81/05/13	50-361	A	B103090427	8103090423	81/03/05	50-244 f	P
8103040565	0102010011				0103070430	B103090413	81/02/18	<b>50-400</b> (	o o
8103060571	8103060541	81/02/13	50-361	A	710707444				
	8103060541	91/02/13	50-361	A	8103090440	8103090439	81/03/05	50-368 F	p
8103060572	8103060569	81/02/23	30-155	P	8103090449	8103090443	01/02/25	XPORTL1C	
8103060575	B103060541	81/02/13	50-361		8103090462	8103090456	81/02/26		
B103060587	8103060584	81/02/24	80-412	A	0103090485	8103090480		CONTRACT	
		01104744	50-413	Α	8103090498		81/02/05	50-192 0	3
9103060589	8103060584	04 (00 (04			***************************************	8103090494	B1/02/24	50-413 G	3
8103040391		81/02/24	50-413	Α	B103090503				
8103060596	8103060586	81/03/03	50-289	8		8103090494	81/02/24	50~413 0	1
	8103060593	81/03/02	50-261	š	8103090506	8103090504	81/03/02	50-298 R	
B103060600	8103060593	81/03/02	50-2BI	ĕ	8050505018	B103090505	81/02/28		
8103060602	8103060593	81/03/02	50-281		B10309J509	8103070507	81/05/59	50-321 R	
			20.501	s	8103090512	B103090911	01/02/20	50-325 8	
8103060615	8103060541	81/02/13		_		3.00070311	81/02/27	50-29 R	
B103060619	8103060341	81/02/13	80-361	Ą	B103090513	B103000***	64 465 :		
8103060623		B1/02/13	50-361	A		B103090510	81/02/27	50-302 g	3
8103060629	8103060541	81/05/13	50-361	A	8103090521	8103090519	81/03/09	50-528 R	
	B103060541	81/02/13	80-361	Ä	B103090523	8103090518	81/03/02	50-293 B	
8103060771	8103060766	81/02/11	70-734		B103090925	8103090524	81/02/26	50-331 R	
					8103090541	B103090540	81/02/27	30-285 P	
8103050005	8103090001	81/02/11	70~687				01702727	20-802 P	
8103090037	B103090032	81/02/12		_	B103090344	8103090542	01.400.00		
8103090039	B103090033		50-254	F	8103090552		81/03/02	50-213 S	
8103090059	8103070048	81/01/13	50-245	P		9103090549	81/02/19	50~249 B	
8103090064		81/02/09	40-1162		8103090555	8103090550	81/03/04	90-305 8	
010307004	8103090058	81/02/11	70-371		B103090356	8103090554	81/02/27	50-272 9	
BIANCALA					8103090561	8103090957	81/03/02	50-346 B	
B103090076	8103090069	81/02/11	70-1201				UJ/ UE	20.240 B	
8103090086	8103090081	81/02/11			8103090568	8103090563	01 100 101		
B103090091	8103090087	81/02/05	70-1143		Ø103090574	9102000000	81/03/04	50-346 B	
B103090094	8103090089		71~420		0103090602	8103070570	81/05/59	90-266 V	
8103090103		81/02/11	70-1257			8103090597	81/02/17	71-423	
0102030103	8103090097	81/02/11	70-33		8103090627	B103090623	81/01/20	50-373 Q	
O. 000000					E103090631	8103090611	81/01/21	IOCFR	
8103090105	B103090100	81/01/23	90-264	a			-1.01/61	* UCFR	
8103090118	8103090109	81/02/11		u	9103090636	8103090629	01/02/09		
8103090120	8103090114		70-36		B103090437		01/02/27	50-266 R	
8103090128	8103090109	81/02/25	CONTRACT			8103090611	81/01/21	LOCFR	
8103090136		81/02/11	70-36		B103090643	8103090611	81/01/21	10CFR	
	8103040130	B1/02/25	CONTRACT		8103090646	8103090641	81/02/20	40~8102	
B103080+50					8103090452	8103090645	81/02/26	40-8602	
8103090152	8103090145	81/02/11	70-824						
B103090165	B103090159	81/02/11	70-138		B103090658	B10309064B	81/01/13	70-124	
B103090168	B103090160	81/02/18	<b>30-389</b>		8103090684	B10309067B	81/02/26	70-135	
6103090171	B103090164	81/02/13		0	8103070685	8103090681		50-305 0	
8103090178	B103090159	81/02/11	CONTRACT		8103090693		61/02/13	50-155 P	
		01/02/11	70-135		8103070843	8103090687	81/02/17	50-424 A	
					9103070700	8103090696	81/02/03	30-484 A	

~						er aumzen			
ENGL OSURE	PRINCIPAL BOCUMENT	DATE Qaueel	GUBJECT CATEGOR		ENGLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	6U0JE CATEG	
8103090704 8103090712 8103090714 8103090723 8103090731	8103090898 8103090708 8103090708 8103090715 8103090725	81/02/06 80/12/17 81/01/29 81/01/15 81/02/10	50-263 50-244 50-334 50-320 50-255	0 F 0 P	8103(00494 8103100496 8103100901 9103100902 8103100503	8103100457 8103103450 8103100455 8103103458 8103100458	81/03/02 81/03/03 81/02/25 81/03/04 81/03/04	50-369 50-327 50-409 50-348 50-348	5 6 8
0103090755 0103090757 0103090761 0103090762 0103090765	8103090747 8103090739 8103090758 8103090739 8103090739	81/05/10 81/05/10 81/05/10 81/05/10	50-349 50-255 50-413 50-255 50-255	0 0 0	0103160304 8103160306 8103160313 8103160316 8103160316	8103100500 8103100499 8103100505 8103100511 8103100508	81/03/05 81/03/02 91/02/27 81/03/03 81/03/06	50-327 50-254 50-336 50-368 50-276	9 5 8 8
8103090765 8103090767 8103090772 8103090774 8103090780	8103090752 8103090758 8103090758 8103090771 8103090771	01/01/59 01/01/59 01/05/14 01/05/03	50-250 50-413 CONTRACT 50-454 50-454	() ()	8103102518 8103100519 8103100531 8103100540 8103102543	8103100517 8103100507 8103100530 8103100537 8103100537	81/03/01 81/03/03 81/03/04 81/03/04	50-3 50-368 50-364 50-305 50-305	6 6 6 8 8
8103090789 8103090799 0103100008 8103100010 8103100024	B103090784 B103090794 B103100004 B103100004 B103100016	81/01/30 01/01/20 61/01/15 61/01/15 61/01/19	50-321 50-222 50-133 50-133 50-344	0 0 0 0	8103100547 8103100596 8103100596 8103103598 8103103986	8103100521 8103100552 8103100549 8103100535 8103100562	81/03/04 81/03/05 81/03/03 81/03/05 81/03/03	50-395 50-289 50-320 50-329 50-316	A R B A S
B103100036 B103100040 B103100046 B103100051 B103100053	8103100029 8103100035 8103100035 8103100042 8103100045	81/01/59 81/05/59 81/05/59 81/05/59	50-397 50-327 50-327 50-320 50-259	0 0 0 0	8103100569 6103100572 6103100373 8103100373 6103100377	9103100565 9103100571 9103100565 9103100565	81/03/03 81/03/03 81/03/03 81/02/25	50-213 50-316 50-317 50-213 50-316	<b>1</b> 8 9 9 9
8103100069 8103100070 8103100091 8103100100	8103100057 8103100059 8103100077 8103100059 8103100059	01/02/19 01/02/24 01/02/20 01/02/24 01/02/24	50-265 50-265 50-265 50-265 50-285	9 9 0 0	1800010018 800100180 8000100180 8000100180	8103100578 8103100579 8103100584 8103100587 8103100593	81/03/04 81/03/03 81/03/02 81/03/02 81/03/05	50-334 50-267 50-334 50-334 50-295	R 9 9
0103100121 0103100135 0103100151 0103100159 0103100164	8103100111 0103100130 8103100149 0103100153 0103100197	81/01/29 B1/02/09 B1/02/02 B1/02/06	50-327 MISC 50-354 50-29 40-7924	0 8 R	0103100603 040010018 010010018 010310061 010010010	8103100601 8103100604 8103100605 8103100611 8103100611	81/03/04 81/03/03 81/03/03 81/02/17 81/02/17	50-259 50-267 50-324 TOPREP TOPREP	я Я
8103100172 8103100187 8103100192 8103100209 8103100223	8103100157 8103100177 8103100181 8103100204 8103100217	01/02/06 E1/20/18 E0/20/18 F0/E0/18	40-7924 70-162 50-307 50-466 50-309	8 8 8	8103100617 8103100620 8103103626 8103100627 8103100631	8103103628 8103160753 8103160753 810316071	81/02/17 81/02/19 81/03/02 81/03/02 81/03/02	10PAEP 50-325 50-277 50-286 40-8383	9 B R
0103100243 0103100252 0103100282 0103100202	8103100234 8103100251 8103100254 8103100275 8103100274	81/02/27 81/03/02 81/02/19 81/03/02 81/03/02	CONTRACT CONTRACT 70-1113 CONTRACT CONTRACT		8103109632 8103109534 8103100645 8103100651	0103100629 0103100622 0103100635 0103100643 0103100648	81/03/03 81/03/06 81/03/06 81/03/06	50-339 50-286 50-281 71-179 40-8510	8 R 8
0103100321 0103100335 0103100346 0103100351 0103100350	8103100317 8103100331 8103100349 8103100349 8103100393	81/03/06 81/02/10 81/03/05 81/03/05	50-190 50-266 50-315 50-295 70-371	P R R	@103100699 B103100676 B103100676 B103100681	8103100640 8103100659 8103100657 8103100679	81/02/20 81/03/02 81/03/02 81/02/25	COMMINST CONTRACT CONTRACT 70-1144 XPORTLIC	•
8103100361 8103100363 8103100364 8103100367 8103100364	0103100354 8103100357 8103100357 8103100360	81/03/09 81/02/25 81/03/02 81/03/25 81/03/03	50-262 70-992 CONTRACT 70-992 50-316	8	8103100689 8103100691 8103100697 8103100699 8t03100701	8103100465 8103100484 8103100490 8163100485 8103100495	81/03/03 81/02/12 81/01/22 81/01/22	30-266 KPORTLEC MASTE MO 50-266 XPORTLEC	Τ
8103100370 8103100373 8103100376 8103100384 8103100384	B103100369 B103100397 B103100371 B103100377 B103100390	61703796 61703705 61703705 61703796 61703736	50-207 70-972 xportuic 50-265 50-361	R B A	8103160707 8103100713 8103100714 8103100715 8103100720	8103100590 8103100508 8103100690 8103100704 8103100704	81/01/21 81/02/25 81/01/21 81/01/21 81/01/21	WASTE MO DATTT WASTE MO 50-407 50-407	
8103100399 8103100401 8103100402 8103100403 8103100407	8103100394 8103100397 8103100390 8103100393 8103100397	81/01/02 81/01/19 81/01/02 81/03/04	70-309 50-438 50-361 50-528 50-438	0 A Q 0	#103100722 #103100727 #103100731 #103100733 #103100737	8103100718 8103100718 8103100570 8103100710 8103100718	81/02/27 81/02/27 81/01/21 81/02/27 81/02/27	04979 04999 Warie MQ 04999 04999	ıτ
8103100414 8103100417 8103100422 8103100423 8103100427	8103100409 8103100409 8103100409 8103100418 8103100423	81\03\59 81\03\03 81\03\53 81\03\53	50-298 50-298 50-298 50-186 50-321	P P P P	8103100741 8103100751 8103100760 8103100761 8103100762	8103100718 8103100747 8103100753 8103100754 6103100758	81/02/27 81/01/02 81/03/02 81/02/09 81/02/26	0A999 0A999 50-247 M180 CONTRACT	<b>o</b>
0103100435 8103100437 8103100447 8103100430 8103100464	8103100426 8103100428 8103100441 8103100442 8103100454	81/03/04 81/03/05 81/03/04 81/03/03 81/01/19	50-369 50-369 50-369 50-219 50-206	8 8 8 6 0	8103100770 8103160778 810311000A 8103110009 8103110014	8103100765 8103110005 8103110005 8103110011	81/03/03 81/03/03 81/01/09 81/01/20	50-271 50-271 Qappo Qappo Qappo	F
8103100465 8103100477 8103100483 8103100484 6103100484	8103100456 8103100469 8103100491 8103100467 8103100480	81/03/06 81/03/06 81/03/05 81/03/03 81/03/04	50-219 50-327 50-247 50-349 50-327	8 8 8	9103110029 8103110054 8103110057 9103110075 8103110091	8103110024 8103110045 8103110055 8103110055 8103110085	81/03/02 61/02/24 61/02/20 81/02/20 81/02/20	50-271 XPORTLIC GA999 GA999 GA999	P

ENCLOSURE	PRINCIPAL DJCUNENI	DATE ISSUED	SUBJECT CATEGOR			ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8103110087 8103110070 8103110108 8103110124 8103110133	8103110074 8103110055 8103110091 8103110117 8103110119	81/02/27 81/02/20 81/02/23 81/02/27 81/02/20	50-369 0A999 CCMMISS 50-271 CCMMISS	М		8103110736 8103110744 8103110746 8103110748 8103110751	8103110673 8103110673 8103110673 8103110673 8103110673	81/03/10 81/03/10 81/03/10 81/03/10 81/03/10	1 136-06 1 146-06 286-06 1 136-06	
8103110138 8103110148 8103110189 8103110200 8103110201	8103110126 8103110126 8103110183 8103110193 8103110191	81/03/06 81/03/06 81/02/24 81/02/23 81/03/05	50-313 50-313 50-315 50-261 50-29	4 4 4 4 4		8103110754 8103110757 8103110760 8103110762 8103110766	8103110673 8103110750 8103110673 8103110673 8103110673	81/03/10 81/03/05 81/03/10 81/03/10 81/03/10	50-361 I 50-483 Q 50-361 I 50-361 I	
8103110203 8103110204 8103110209 8103110220 8103110224	8103110197 8103110199 8103110191 8103110215 8103110215	81/01/21 81/01/22 81/03/05 81/02/13 81/02/13	71-417 40-8610 50-29 71-422 71-422	F		8103110768 8103110773 8103110775 8103110782 8103110792	8103110763 8103110673 8103110673 8103110778 8103110787	81/03/05 81/03/10 81/03/10 81/03/03	50-358 A 50-361 I 50-361 I 50-278 0 50-267 0	
8103110229 8103110240 8103110263 8103110270 8103110275	8103110221 8103110225 8103110254 8103110254 8103110272	81/02/23 81/02/25 81/03/09 81/03/09 81/02/24	50-272 50-341 50-338 50-338 50-369	P ^ 0 0 P		8103110794 8103110823 8103110826 8103110831 8103110832	8103110790 8103110814 8103110820 8103110814 8103110825	81/02/20 81/02/27 81/03/02 81/02/27 81/02/19	CONTRACT 50-528 0 50-309 P 50-528 0 GEN TEC 18	
8103110312 8103110364 8103110390 8103110404 8103110416	8103110303 8103110353 8103110375 8103110378 8103110412	81/03/06 81/03/05 81/03/03 81/02/25 81/02/20	50-322 50-311 50-373 50-289 50-271	A H O P		8103110837 8103110840 8103110847 8103110851 8103110856	8103110814 8103110820 8103110814 8103110844 8103110854	81/02/27 81/03/02 81/02/27 81/02/27 81/02/24	50-528 Q 50-309 P 50-528 Q 50-327 P 50-333 F	
8103110429 8103110432 8103110440 8103110443 8103110494	8103110423 8103110422 8103110414 8103110436 8103110449	81/02/23 81/02/06 81/03/03 81/02/25 81/02/23	50-302 40-2274 50-259 50-368 50-309	P P P		8103120012 8103120029 8103120042 8103120047 8103120053	8103120007 8103120022 8103120034 8103120039 8103170479	81/02/19 81/01/09 81/02/27 81/02/18	50-293 P 50-237 P 40-8585 50-320 P 10CFR	
8103110459 8103110457 8103110468 8103110474 8103110481	8103110449 8103110452 8103110461 8103110471 8103110476	81/02/24 81/03/09 81/03/05 81/03/06 81/03/04	50-280 50-338 50-339 50-155 50-327	P 0 8 R R	·	8103120056 8103120068 8103120072 8103120076 8103120105	8103150045 8103150091 8103150091 8103150036	81/02/27 81/03/03 81/03/03 81/03/03 81/02/27	50-320 P 90-334 P 50-334 P 50-309 P	
8103110483 8103110486 8103110487 8103110493 8103110502	8103110479 8103110477 8103110480 8103110488 8103110491	81/03/05 81/03/04 81/03/05 81/03/03 81/03/04	50-261 50-327 50-317 PR 50-287	R 8 8		0103120109 0103120110 0103120139 0103120147 0103120158	8103120150 8103120142 8103120142 8103120142	81/02/27 81/02/26 81/03/02 81/02/26 81/03/04	50-309 P 71-9143 71-5641 50-20 B 71-405	
8103110513 8103110521 8103110527 8103110528 8103110532	8103110510 8103110617 8103110524 8103110526 8103110526	81/03/05 81/02/03 81/03/06 81/01/30 81/01/30	50-250 50-438 50-267 50-286 50-286	ያ 6 0	,	B103120174 B103120204 B103120216 B103120218 B103120227	8103120169 8103120199 8103120207 8103120201 8103120201	81/03/06 81/01/30 81/03/04 81/03/04 81/03/04	XPORTLIC QEN TEC IS 50-364 P FOIA FOIA	
8103110533 8103110534 8103110535 8103110537 8103110538	8103110929 8103110526 8103110931 8103110526 8103110529	81/03/06 81/01/30 81/03/04 81/03/06 81/03/06	50-338 50-285 50-327 50-286 50-338	P 0 0 P		8103120236 8103120245 8103120248 8103120249 8103120252	8103120201 8103120229 8103120240 8103120239 8103120247	81/03/04 81/02/27 81/02/11 81/02/19 81/02/02	FO1A 80-269 P CONTRACT 50-483 H 80-329 0	
8103110537 8103110540 8103110542 8103110546 8103110553	8103110526 8103110529 8103110526 8103110544 8103110551	81/01/30 81/03/06 81/01/30 81/02/04 81/03/06	50-286 50-338 50-286 50-387 50-302	9 0 0		8103120263 8103120270 8103120272 8103120285 8103120293	8103120259 8103120261 8103120259 8103120259 8103120288	81/03/09 81/03/02 81/03/09 81/03/09 81/03/04	50-289 0 50-269 P 50-287 0 50-289 0 TOPREP	
8103110557 8103110595 8103110597 8103110613 8103110658	8103110593 8103110592 8103110592 8103110609 8103110654	81/03/09 81/03/09 81/03/03 81/03/06	50-333 50-324 50-324 50-259 50-278	800		8103120308 9103120320 9103120321 9103120351 8103120373	8103120296 8103120307 8103120316 8103120348 8103120353	81/02/27 81/03/04 81/03/03 81/02/09 81/03/10	50-269 P 50-395 A 50-313 R 40-8511 50-275 Q	
8103110666 8103110672 8103110678 8103110684 8103110686	8103110660 8103110663 8103110673 8103110673 8103110679	81/02/25 81/03/05 81/03/10 81/03/10 81/03/03	50-409 50-250 50-361 50-361 50-324	8 ! ! \$	6 6	8103120490 8103120403 8103120403 8103120408 8103120411	8103120386 8103120395 8103120386 8103120395 8103120404	81/01/09 81/02/02 81/02/02 81/03/05	9A999 50-331 9 50-331 9 50-332 A	
8103110690 8103110691 8103110692 8103110698 8103110701	8103110673 8103110687 8103110683 8103110673 8103110694	81/03/10 81/03/05 81/03/06 81/03/10 81/02/06	50-361 50-325 50-325 50-361 50-237	1 8 1 8	6 8 0	9103120425 3103120433 9103120436 3103120444 3103120445	8103120421 8103120427 8103120429 8103120422 8103120438	81/02/04 81/03/04 81/02/04 81/02/27 81/03/06	50-438 Q 71-416 50-296 Q 50-445 E 50-269 P	
8103110704 8103110706 8103110708 8103110710 8103110713	8103110673 8103110697 8103110703 8103110673 8103110673	81/03/10 81/03/06 81/03/04 81/03/10 81/03/10	50-361 NUREQ 50-219 50-361 50-361	1 P	E 5 5	9103120448 9103120450 9103120457 9103120459 9103120463	8103120441 8103120447 8103120451 8103120455 8103120460	81/02/04 81/03/02 81/02/27 81/02/05 81/02/27	50-280 0 50-334 P 70-734 CONTRACT 70-2937	
8103110714 8103110718 8103110719 6103110724 8103110730	8103110711 8103110673 8103110711 8103110673 8103110673	81/03/10 81/03/10 81/03/10 81/03/10	50-290 50-361 50-250 50-361 50-361	R I R I	9 6 8	B103120465 B103120471 B103120474 B103120477 B103120484	8103120461 8103120443 8103120472 8103120472 8103120480	81/03/04 81/03/05 81/03/03 81/03/03 81/02/04	71-9111 50-29 P 50-368 P 50-368 P 50-315 Q	

			ACCESSION NUMBER
PRINCIPAL	DATE	SUD JECT	***********

	PRINCIPAL	DATE	CHIO IDA	-	**-*				
ENGLOSURE	DOCUMENT	ISSUED	CATEOD		ENGLOSURE	PRINCIPAL GOCUMENT	DATE ESSUED	SUBJEC CATEGO	
0103120485	8103120402	81/02/25	90~201	R	0103130146	0102120110			
6103120467 8103120490	8103120480 8103120488	01/02/04 81/02/25	50-315 50-302	Q P	B(03)301 90	8103130140 8103130140	91\03\05 91\03\05	50-282 50-282	P P
B103120493	8103120488	81/02/25	50-302	p	8103130150 8103120160	8193130147 8193139151	81/02/05 81/03/04	50-327	4
8103120496	8103120489	01/05/52	90-302	f	8103130165	8103133157	81/02/24	50-315 50-315	P
8103120505	8103120502	61/02/27	50-321	þ	8103133167	6103130159			
B103150234 B103150208	8103120502 8103120532	81/02/27 81/03/04	50-321	р 9	8103(30169	8103130151	81/02/05 81/03/04	50-327 50-369	₽ P
0103120539	0103120536	01/03/04	50-220	8	8103130172 6103130177	81931361a3 81831361a3	91/05/23	50-335	G.
@103(20545	8103120454	01/03/04	90-317	Р	8103130192	8193130185	81/ <b>03</b> /04 81/02/27	50-369 XPORTL 1	c P
B103150220	8103120548	91703706	50-237	P	8103130200	8103130193	81/02/25		
#1#3120557 #1#3120559	8103120553 8103120553	01/03/05 01/03/05	50-361	K	8103120201	9103130160	81/02/06	50-298 50-327	P
8103150961	8103150536	81/05/05	50-JJ9	0	8103130 <i>2</i> 05 810313921 <i>7</i>	8103130193 8103130193	81702725	30~548	P
8103150292	Ø193120956	01/02/02	50-330	G	8(93(30233	8103130227	81705703 81705706	30-251 30-10	0
8103120571	8103120396	81/05/05	90-338	ā	8100130204	8103130228	81/03/11	50-282	F
8103120574 8103120576	8103150200 8103150390	81703709 81703709	90-275 50-361	0	9103130234	8103130226	81/01/26	50-49a	ó
01/03/150250	8103120583	81703708	90-361	(2)	0103133245 8103130255	8103130227 8103130248	81705753 81705703	50-10 40-9760	g
8103120593	8103120504	81/01/21	50-490	G	8100130223	8103130264	81/05/10	CONTRACT	1
B103120601	0103120595	81/01/27	QA999	_	8103130275	8103130266	81/05/52	50-155	p
8103150950 8103150910	8103150717	81703704 81703705	90-36B 836-08	9	8103130265	8103130266	81/02/25	30-135	ŕ
8103150937	8103150933	01/02/20	50-275	0	9(03)30310 8(03)30303	8103130294 8103130302	81/01/30 81/01/05	50-263 71-408	ø
B103150935	8103150931	81703705	50-320	8	8100130318	0103130305	01/02/25	71-318	
8103120452	B103120649	01/02/25	50-335	P	8103130328	8103120322	81/02/26	CONTRACT	
0103120657 0103120661	B103120640	81702725	50-335 50-317	a P	8103130346	8103130337	81/01/27	50-498	0
8103120463	8103120648	B1/02/25	90-395	l,	0103130354 £103133358	8103130350 8103130353	81/03/07 81/03/03	50-250 50-10	R R
8103120675	8103150208	B1\05\09	50-461	a	£103130359	B103130351	81/07/09	90-29	P
8103120680	0103120660	01/02/06	50-461	<b>a</b>	0103130366	8103130361	81/02/29	50-335	8
8103120698 8103120794	0103150883 0103(50883	81703705 81703705	50-361 50-361	K	8100130371 8103139376	B163130367	81/03/06	50-255	Ř
0100120709	8103150993	01/03/05	146-06	ĸ	B103130379	8103130374 8103120375	B1/03/11 B1/03/01	868 30-548	R
0103120717	6103150993	01/03/05	30-361	ĸ	8103130382	8103130391	81/02/27	50-409	Ħ
8103120722 8103120731	B103120553	01/03/05	50-361	H	6103130387	0103136383	81/03/06	50-333	A
8103120747	B103120724 B103120744	01/03/04 01/02/24	50-257	ų P	6103130397 8103130409	0103130593 0103120391	01/03/06	30-345	R
8103120794	0103120744	01/03/04	50-259	a	8103133412	1900130391	81/03/11 81/03/11	50-3 50-3	p P
01/03120760	8103120744	U1703704	90-257	0	B103130433	8103130427	81703708	50-7G	0
B103120779 B103120774	0103120744 0103120769	01703704 01702713	50-257	ā	8103130439	8103130433	81/03/05	30-70	0
0103120703	8103120775	811/05/02	50-250 50-324	F Q	fi103130443 fi103130444	8193139442 8103130441	81/03/11	50-70	P
0103120709 0103120777	#103120777 #103120772	00/11/05 01/03/05	0A979 40-299		8(03130446	0103130446	81/03/06 81/02/29	30-247 30-70	H P
_					8103130452	8103130450	81/03/05	50-289	0
8103150803 8103150891	0103120795 0103120795	81703704 81702705	71-7145 90-369	O.	0103130496	8103130494	81/03/05	50-349	8
9103150853	0103120021	H1703705	50~ 320	Б	0103130460 8103130464	8103130456 8103130462	81/03/05 81/03/05	30-366 50-321	5 9
0103120036 0103120036	0103120020 0103120020	81703704 81703705	50-267 FD1A	G	8103130469	B103130467	81/03/05	50-366	S
					8103130472	0103130470	61/03/09	90-201	8
6103120841 6103120843	8103150050 8103150050	01703704 01703704	50-269 50-269	0	8103(30473	0103130419	B1/03/11		K
E103150U48	B103150858	81/03/04	30-269	ō	8100130475 8100130477	8103130470 8103130470	81/03/09 81/03/07		5 8
B103150844	0103150049 0103150049	81702726	30-311 30-311	Ь Ъ	8103130479	8103150476	81/03/03	50-317	P
					8103130483	8103130475	81/03/03	50-317	P
0103120896 0103120898	8103120846 8103120846	81702726 81702726	50-311	b b	8103139487 8103139490	8103136481	81/03/04		8
0103120059	8103120844	01/03/05	CONTRACT		8103139470 8103130517	010313048£ 0103130512	B1/03/94 B1/03/10		Р О
0103130013 8103150860	8103130009 810315088\$	81703710 81701788	CONTRACT	H	8103100529	8103130522	91/03/04	50-269	٢
					H103(3953B	8103130522	81/03/04	50-289	τ
0103130055 0103130051	8103130019	81702724 81702724	50-305 50-259	0 P	8103130547 0103130548	B103130525 B103130536	81703704 81703711		T P
8103130034	9103130059	81/02/02	20-1703		8103130552	8103130522	81/03/04		7
0103132036 0103130047	8103130020 8103130020	01/02/24 01/02/24	50-259 40- <i>00</i> 27	fs.	8103130597 8103130560	8103130522 8103130536	81/03/04		٦ 9
8103130057 8103130068	8103130052 8103130052	80/10/17 80/10/17	9A999 9A999		EACCETE018 8400515018	9103130522 8103130564	81/03/04 81/03/09		Ţ P
8103130072	8103130060	80115118	WABTE NO		0103130575	8103130564	B1103109	50~219	P
8103130078 8103130089	8103130073 8103130080	01/02/24 81/02/25	50~275 XPORTLIC	þ	8103130579 8103130592	0103130573 0103130565	81702727 81702726		<b>S</b>
8103130106	8103130079 8103130074	B1702717 81703704	50-454 CONTRACT	0	9103130594 8103130595	8103130586 8103130594	81/03/04 81/03/04		8
8103130112	0103130104	81/01/23	50~315	Q	40402120404	0103130399	81/03/36	50-334	9
B103130115 B103130115	8103130108 8103130059	01/02/02	70-1703 50-259	Þ	910313060 <i>9</i> 9103130611	8602120960 8602120960	81703705 81703706		8 5
8103130159 8103130119	8103130104 8103130108	81701723 81702727	50-315 50-259	() ()	8103130521 8103130524	8103130617 8103133617	81/03/02	6807 F084	
8103130134	8103130108	81/02/27 81/02/27	50-259 50-369	Р 0	8103130644 8103130645	6103130635 6103130642	81702705 81703704	70-27 XPORTLIC	
8103130138	8103130133 8103130133	01/02/27	30-369	Ö	G1Q3130655	0103130651	81/02/15	CONTRACT	

ACCESSION NUMBER				ACCESS	ION NUMBER			
PRINCI ENCLOSURE DOCUM	ENT ISSUED	SUBJEC CATEGO			PRINCIPAL	DATE 199UED	SUBJ	
8103130668 810313 8103130666 810313 8103130671 810313 8103130678 810313 6103130678 810313	0648 81/02/05 0650 81/03/02 0660 81/03/02	50-263	P P P	810316057 810316058 810316059 810316059 810316059	1 8103160559 6 8103160576 0 8103160580 5 8103160580	81/03/06 81/03/13 81/02/05 81/02/05	CONTR 50-446 GA999 GA999 GA999	 AC T
8103130679 810313 8103130686 810313 8103130705 810313 8103130708 810313 8103130711 810313	0693 81/02/20 0700 81/03/06 0700 81/03/06	50-243 CGN1RAC 50-280 50-280 50-280	T 0 0 0 0 0 0 0 0 0	810316060 810316060 810316061 810316061 810316061	810316080 5 8103160602 6 810316060 6 8103160603	81/02/09 81/03/12 81/02/03 81/02/27 81/02/03	GAP99 SO-JJE GAP99 XPORTU GAP99	
8103130716 810313 8103130726 810313 8103130732 810313 8103130733 810313 8103130736 810313	7721 81/03/06 7724 81/02/25 7729 81/03/06 7724 81/02/25	50-280 70-143 50-320 50-364 50-320	0 H D H	810316061 8103160618 810316062 810316062 810316062	8103160570 8103160608 8103160620	81/02/03 81/02/26 81/02/03 81/02/26 81/02/26	0A999 COMMIS GA999 30-482 COMMIS	н
8103130741 8103130 8103160015 8103160 8103160018 8103160 8103160028 8103160	012 81/02/05 012 81/02/05 021 81/02/18 023 81/03/06	50-259 71-418 71-418 71-416 CONTRACT	<b>0</b>	8103160633 8103160643 8103160648 8103160668 810316066	8103160570 8103160570 8103160657	81/02/26 81/02/26 81/02/26 81/03/02 81/03/02	COMMIS COMMIS COMMIS 50-254 50-344	610N 81CN 810N 8
8103160037 8103160 8103160042 8103160 8103160058 8103160 8103160093 8103160	031 81/03/06 049 81/03/11 049 81/03/11 089 81/03/03	50-344 50-344 50-334 50-334 50-320	F F F P	8103140687 8103140070 8103140707 8103140707 8103140707	8103160685 8103160692 8103160699	81/03/13 81/03/05 81/03/10 81/03/11 81/03/10	50-286 50-325 50-302 50-267 50-302	5
8103160114 8103160 8103160124 8103160 8103160127 8103160 8103160150 8103160	111 91/02/27 114 81/02/27 115 81/02/20 143 91/03/09	50-321 50-195 50-155 50-338 50-261	9 P P	8103160720 8103160729 8103160734 8103160735 8103160740	8103160712 8103160726 8103160730 8103160731 8103160737	81/03/12 81/03/19 81/03/10 81/03/02	50-335 50-333 125-05 50-250 50-366	8 9 8
8103160159 8103160 8103160189 8103160 8103160196 8103160	52 81/03/05 81 81/03/12 81 81/03/12 91 81/03/05	50-423 50-346 50-269 50-269 CONIRACT	9 F F	8103160742 8103160744 8103160748 8103160757 8103160758	8103160739 8103160743 8103160736 8103160755 8103160753	81/03/09 81/03/09 81/03/06 81/03/09 81/03/26	50-333 50-333 50-346 50-259 50-335	8 8 8
B103160205 8103160: B103160215 8103160: B103160225 8103160: B103160235 8103160: B103160235 8103160:	93 81/03/06 13 81/03/04 93 81/03/06 93 81/03/06	50-518 50-518 CONTRACT 50-518 50-518	0 0 0	8103169763 8103160765 8103160770 8103160774 8103140786	B103160760 B103160762 B103160760 B103160771 B103160782	81/02/28 81/03/05 81/02/28 81/03/09 81/03/02	50-387 50-324 50-387 50-324 50-261	A 8 A B
8103160239 81031602 8103160254 81031602 8103160257 81031602 8103160260 81031602 8103160276 81031602	48 81/03/05 52 81/03/13 40 81/03/02 72 81/03/04	TOPREP	н Н	8103160790 8103160792 8103160794 8103160800 6103160839	8103160782 8103160782 8103160782 8103160782 8103310804	B1/03/02 B1/03/02 B1/03/02 B1/03/02 B1/03/10	50-261 50-261 50-261 50-261 50-3	0 0 0
B103160283 B1031602 B103160294 B1031603 B103160316 B1031603 B103160323 B1031603 B103160323 B1031603	59 81/02/17 10 91/03/03 11 81/02/23 12 81/02/26	70-2928 70-2928 10CFR 71-403 8ECY		8103160847 8103160890 8103160859 8103160869 8103160873	8103160823 8103160823 8103160823 8103160864 8103160864	81/03/09 81/03/09 81/03/09 81/02/26 81/02/26	FOIA FOIA FOIA FOIA FOIA	·
8103160325 81031603 8103160364 81031603 8103160369 81031603 8103160404 81031605	99 81/03/06 58 81/02/12 54 81/02/27 54 81/02/27	10CFR 50-336 40-659 10CFR 10CFR	Р	8103160905 8103160907 8103160907 8103160911 8103160933	8103160903 8103160903 8103160903 810316093 8103160938	81/03/09 81/03/09 81/03/09 81/03/09 81/02/10	50-302 50-302 90-302 50-302 70-27	0 0 0 0
8103160423 61031604 8103160440 81031603 8103160440 81031603 8103160440 81031603 8103160440 810316063	8 81/03/05 4 81/02/27 7 81/03/11 4 81/02/27	50-298 F 50-298 F 10CFR 50-324 F 10CFR	•	8103160944 8103160953 8103160960 8103160965 8103160969	8103160948 8103160954 8103160961	81/02/10 81/02/09 81/02/10 81/03/04 81/03/04	50-254 50-346 50-348 50-369 50-369	0 0 0 0
8103160464 B10316046 B103160466 B10316046 B103160467 B10316046 B103160471 B10316046	9 81/03/13 1 81/03/06 2 81/03/12 8 81/03/06	50-309 p 50-324 p 50-321 p 50-220 1 50-272 p	1	8103160983 8103160984 8103160994 8103170008 8103170025	8103160976 8103160988 8101080276	81/03/10 81/03/06 81/02/09 80/12/03 91/03/09	50-320 50-358 50-315 50-262 70-820	H Q Q F
8103160480 810316043 8103160498 810327011 8103160498 810316045 8103160522 810316045 8103160525 810316051	0 91/03/12 (7 81/02/26 (7 91/02/26 (7 91/02/26 (	80-370 Q COMMIBBION 50-370 Q 50-370 Q		8103170032 8103170034 8103170038 8103170060 8103170071	8103170021 6103170014 6103170014 8103170014	81/02/19 81/03/09 81/03/09 81/03/09	71-9132 70-820 70-820 70-820 70-820 50-334	F
8103160326 8103160329 8103160331 8103160331 8103160337 810316043	81/03/05 81/02/26 81/03/09 81/02/26	50-272 P 50-186 P 50-370 G 50-272 P 50-370 G		8103170078 8103170081 8103170084 8103170086 8103170089	8103170066 8103170075 8103170075 8103170075	31/03/10 31/03/04 31/03/04 31/03/04	50-334 50-369 50-369 50-369 50-369	F Q Q Q
8103160538 8103160529 8103160547 810316053 8103160550 810316055 8103160565 810316055	81/03/12 5 81/02/16 C 81/03/13 5	00-155 1 00-322 E ONTRACT 00-219 P		B103170091 B103170109 B103170109 B103170110 B103170139	8101080201 8 8103170101 8 8103170102 8 8103170101 8	0/11/28 0/103/12 01/03/13	90-317 90-219 90-466 90-219 90-320	F F O F P

					#CCE#310	N NUMBER			
ENCLOSURE.	PRINCIPAL BOCUMENT	DATE	CATEGOR		EACLOSURE	PRINCIPAL DOCUMENT	BATE (13U281	SUBJE CATEG	
8103170146 8103170150 8103170151 8103170153 8103170159	8103170143 8103170128 8103170147 8103170128 8103170128	81/02/25 81/03/05 81/03/05 81/03/05	50-18 50-320 50-334 50-320 50-320	# # # #	8103170395 8103170596 8103170587 8103170589 8103170593	8193170579 8193170581 8193170589 8193170577 8193170577	81/03/11 81/03/13 81/03/13 81/03/13	50-280 50-336 50-237 50-334 50-334	9 R B
8103170162 8103170163 8103170167 8103170173 8103170175	8103170156 8103170126 8103170128 8103170128 8103170128	81/03/13 81/03/05 81/03/05 81/03/12 81/03/05	50-334 50-320 50-320 50-322 FOIA	R R A	8103170594 8103170595 8103170596 8103170501 8103170502	9103170371 8103170590 8103170984 8103170600 8103170599	81/03/13 81/03/13 81/03/13 81/03/13	50-336 50-327 50-171 50-213 50-352	A 9 9 0
8103170186 8103170196 8103170197 8103170202 8103170208	8103170087 8103170191 8103170180 8103170180 8103170203	81703711 81703705 81702725 81702725 81703711	50~358 50~367 40~1341 FOIA 50~123	F A V	8103170406 8103170409 8103170410 8103170414 8103170418	8103170584 8103170505 8103170607 8103170584 8103170612	81/03/13 81/03/07 81/03/09 81/03/13 81/03/06	50-171 50-334 50-348 50-171 50-346	! 9 !
8103170212 8103170219 8103170235 8103170242 0103170256	8103170100 8103170180 8103170226 8103170226 8103170250	81702725 81702725 81701715 81701715 81703706	FOIA FOIA 50-458 50-458 50-10	0 0 F	8103170620 8103170623 8103170627 8103170627 8103170629	8103170613 8103170619 8103170584 8103170619 8103170621	81/03/13 81/03/13 81/03/13 81/03/13	50-247 50-381 50-171 50-382 50-325	Q A I A 8
8103170257 8103170259 8103170262 8103170266 8103170270	8103170251 8103170251 8103170251 8103170251 8103170251	81702727 81702727 81702727 81702726 81702727	F01A F01A F01A 50-10 F01A	þ	0103170531 8103170539 8103170539 8103170549 8103170649	8103170628 8103170633 8103170633 8103170638 8103170647	81/03/10 81/03/12 81/03/16 81/03/06	50-220 50-361 50-219 50-183 50-312	8 A 8 9 R
B103170279 B103170280 B103170289 B103170314 B103170315	8103170251 8103170251 8103170251 8103170309 8103170313	81/02/27 81/02/27 81/02/27 81/03/05 81/03/11	FOIA FOIA FOIA LGCFR 50-272	R	6103170651 8103170652 8103170656 8100317066 81003170666	8103170546 8103170645 8103170653 8103170657 8103170653	81/03/11 61/03/10 61/03/11 61/03/11	50-333 50-325 50-364 50-312 50-245	8 8 8 8
8103170323 6103170324 6103170325 6103170326 6103170330	8103170316 8103170320 8103170321 8103170321	01/03/16 81/03/10 90/03/10 90/03/14 81/03/16	30-443 50-266 50-340 100FR 30-443	K G	8103176657 8103170671 8103170678 9103170698 8103170493	9103170664 9103170390 9103170679 9103170679 8103170075	81/03/10 81/03/04 81/02/18 81/03/11	50-312 50-302 Locer Locer 50-354	8 P
8103170338 8103170349 8103170374 8103170388 8103170413	8103170333 8103170344 8103170059 8103170380 8103170408	81/03/10 81/03/10 81/03/15 81/03/13	50-280 50-213 50-254 50-261 50-327	8 8 8 8	B103170697 G103170704 B103170705 B103170710 G103170724	8103170592 8103170698 8103170702 8103170598 8103170598	81/03/05 81/02/05 81/02/05 81/02/05	71-417 50-341 71-408 50-341 50-341	0 0
8103170437 8103170444 8103170449 8103170452 8103170455	8103170434 8103170439 8103170446 8103170490 8103170493	81/03/10 81/03/15 81/03/11 81/03/13	50-339 50-338 50-325 50-360 50-368	ន ន ន ម	8103170739 8103170746 6103170753 8103180304 8103180304	8103170731 8103170731 8103170731 8103180003 8103180003	81/02/24 81/02/24 81/02/24 81/03/02 81/03/02	50-333 50-330 50-320 50-320	0 U U P P
8103170468 0103170470 0103170473 0103170480 0103170484	8103170465 8103170467 8103170471 9103170476 8103170481	01/03/11 01/03/16 01/03/11 01/03/11	50-373 40-2259 50-70 50-331 90-325	R 0 8	910310000 6103160018 6103160018 6103160010	8103180009 8103180031 8103180011 8103180014 8103180015	81/03/04 81/03/05 81/03/05 81/03/03 81/02/27	50-293 50-220 50-220 50-339 40-8040	ዋ የ የ
B103170496 B103170491 B103170493 B103170495 G103170503	8103170482 8103170489 8103170488 8103170487 8103170489	01/03/12 01/03/12 01/03/12 01/03/12	50-302 M180 50-346 M160 M180	8 8	8103180024 8103180043 8103180040 8103180071 8103180075	8103180015 8103180015 8103180060 8103180060	81/02/27 81/02/27 81/03/05 81/03/09 81/03/09	40-8040 40-8040 80-275 50-320 50-320	0 P
8103170504 9103170512 8103170514 9103170516 8103170517	8103170478 8103170507 8103170511 8103170511 8103170500	01/03/05 01/03/09 01/03/09 01/03/01	50-331 50-295 50-302 50-302 50-334	8 P K K	### ##################################	8103180040 8103180083 8103180083 8103180083	91/03/09 91/03/09 91/03/09 91/03/09	50-320 50-320 50-508 50-508 50-271	P 0 0
8103170319 8103170324 8103170528 8103170532 8103170536	8103170513 8103170513 8103170521 8103170513	01/03/16 01/03/16 01/03/16	27-39 27-39 50-295 27-39 50-327	8	8103180110 8103180116 8103180120 8103180140	6103180104 6103180104 6103180104 6103180111 6103180132	B1/03/06 B1/03/06 B1/03/12 B1/03/05	50-327 50-327 50-327 50-315 50-454	6 6 6
0103170937 0103170949 0103170949 0103170950 0103170952	8103170531 8103170543 8103170540 8103170546 8103170545	01/03/09 61/03/10 61/03/10 01/03/13	50-247 50-237 50-260 50-259 50-289	8 8 8 8	8103180142 9103180145 8103180147 8103180152 8103180153	8103180137 8103180168 8103180137 8103180138 8103180150	81/03/03 81/02/11 81/03/03 81/03/09 81/02/05	50-33! 10CFR 50-331 50-313 50-483	P P 0
01 03170583 81 03170561 81 03170563 01 03170564 81 03170565	8103170547 8103170555 8103170554 8103170559 8103170558	01/03/11 90/00/18 1/03/19 1/03/19 01/03/18	50-302 50-271 50-320 60-29 50-320	8 8 8	8103150164 8103180171 8103180172 8103180177 8103180180	8103180157 8103180158 8103180157 8103180157 8103180139	81/02/06 81/03/09 81/02/06 81/02/06 81/03/09	50-277 50-313 50-277 50-277 50-313	о Р О Р
8103170573 8103170574 8103170575 8103170576 8103170582	81031703AB 8103170570 81031705AA 8103170571 8103170577	81/03/13 81/03/11 81/03/11 81/03/12	50-289 50-339 50-331 50-302 50-334	6 8 8 8	8103180184 8103180188 8103180190 8103180192 8103180193	8103160197 8103180178 8103180173 8103180183 8103180178	81/02/04 91/02/12 81/01/21 81/02/05 81/02/12	50-277 100FR 50-322 50-113 100FR	0 0

ACCESSION NUMBER			ACCESSION NUMBER	
PRINCI ENGLOSURE 600UM		SUBJECT CATEGORY	PRINCIPAL DATE Enclosure document issued	CVITIOUSEA CVITIOUSEA
6103180207 810318 8103180207 810318 8103180207 810318 8103180207 810318 8103180207 810318	0198 81/02/02 0194 81/03/05 0198 81/02/02 0178 81/02/12	\$0-329 0 \$0-359 0 \$0-329 0 ICCFR 50-329 0	B103160800 8103180772 81782774 8103160821 8103160012 81703710 810316082 8103160812 61703710 810316081 103180826 81703710 8103180826 8103180826 (11703706)	40-8564 50-213 P 50-213 P 50-856 G
810316-216 810316 0103180217 910318 9103180222 810318 8103180224 810318 8103180736 810318	0194 81/03/06 0194 81/03/06 0178 81/02/12	50-289 G 50-369 G 50-369 G 100FR 100FR	9103180837 81/03/10 8103180859 6103180837 91/03/10 8103180861 81/03180837 91/03/10 8103180868 8103180837 81/03/10 8103180871 81/03180834 91/03/11	50~313 P 50~317 P 50~10 P 50~317 P 50~10 P
8103180239 810318 8103180249 810318 8103160262 810318 8103180269 810318 8103180272 810318	0178 81/02/12 0255 81/03/02 0255 81/03/02	50-369 Q 100FR 50-244 P 50-244 P 50-261 Q	B103160873   B103160844   B07097/05	50 320 P 56-320 P 50-325 P REVIEW ORP 50-344 Q
8103180275 810318 8103180287 810316 81031802874 810318 81031802875 810318 81031803087 810318	0280 81/02/27 0285 81/03/05 0284 81/02/10	50-244 P 40-1341 50-309 P 50-251 Q 50-309 P	B103180920   G103100379   G1703713   G1703713   G1703723   G1703723   G1703723   G1703723   G1703723   G1703180937   G170318093   G1703	50- 237 O REVIEW GRP 50- 237 O REVIEW GRP 50-237 O
8103180315 819318 8103180324 810318 8103180331 810318 6103180344 819318 8103180345 810318	0308 81/01/22 0317 81/03/02	50-245 Q 40-8702 50-206 Q 50-205 Q 70-2317	8103180747 8103180087 01701721 8103180754 019318079 01703773 8103180759 0103180379 01703773 8103180757 8103180379 01703713	REVIEW ORP 50-012 0 50-837 0 REVIEW ORP 50-237 0
8103180351 810318 8103180385 810318 8103180385 810318	0317 81/03/02 0368 81/03/06 0371 81/02/09	50-206 Q 50-206 Q 50-370 Q 50-461 Q 50-370 Q	8103180968 8103180807 81701721 8103180977 8103180965 01702702 8103180978 8103180807 81701721 8103180988 8103180807 81701721 8103180987 8103180900 81702723	REVIEW GRP 70-904 REVIEW GRP REVIEW ORP 50-061 E
8103180395 810318 8103180398 810318 8103180401 810318 8103180405 810318 8103180412 810318	0379 81/03/13 0358 81/03/05 0400 81/03/05	50-370 0 50-237 0 50-390 0 50-213 0 50-390 0	8103181001 81031810994 81703711 8103181017 8103180887 81701721 8103181022 8103180887 81701721 8103181025 8103181019 81703712	CONTRACT REVIEW QUAREVIEW GRAP REVIEW GRAP 50 - 271 H
8103180413 810318 8103180425 810318 8103180426 810318 8103180435 810318 8103180443 810318	0410 81/01/30 0417 81/02/09 0433 81/01/29	50-213 0 50-324 0 50-327 0 50-267 0 50-267 0	8103181037 8103181032 81701712 8103181051 8103181042 81703712 8103181105 8103181103 017072710 8103181113 8103181111 81702710 8103181123 8103181111 81702710	50 -271 H 50 -271 H xequit (c 50 -2 0 50 -2 0
8103180453 810318 6103180455 810318 8103180475 810318 8103180485 810318 8103180491 810318	0449 BI/02/10 Q465 BI/03/11 Q478 BI/03/04	50-269 H 50-327 Q 50-320 P 50-369 Q 50-369 Q	8103181135 8103181130 81703707 8103181142 8103181137 81702720 8103181150 8103181145 81703771 8103181153 8103181145 81703711 8103190002 8103190001 81702777	50-255 P 70-754 50-244 P 50-244 P GA999
8103180492 810318 8103180499 810318 8103180503 810318 8103180507 810318 8103180508 810318	0495 81/03/12 0500 81/03/13 0504 81/03/12 0501 81/02/10	50-369 G 50-331 R 50-346 P 50-348 R 50-416 G	8103190003 8103190001 81702719 8103190004 8103190001 81702719 8103190009 8103190007 81702719 8103190009 8103190007 01702727 8103190011 8103190006 81701726	0A949 0A949 0A949 50-209 II 50-460 Q
8103180516 810318 8103180523 810318 8103180540 810318 8103180549 810318 8103180549 810318	0515 81/02/06 0532 81/03/12 0531 81/03/12 0546 81/03/13	50-265 R 50-275 Q 50-315 S 50-237 P 50-368 R	8103190012 8103190008 01/01/30 8103190028 8103190024 81/02/20 8103190030 0103190029 01/01/30 8103190042 8103190039 01/02/26 8103190045 8103190040 01/02/11	50-992 G C04fBACT 50-499 G 50-206 P 50-389 G
8103180551 810318 8103180563 810318 8103180565 810318 8103180568 810318 8103180577 810318	0531 81/03/12 0561 81/03/13 0564 81/03/13 0573 81/02/13	50-237 P 50-237 P 50-289 R 50-272 P 50-454 Q	8103190057 8103190090 81/02/11 8103190058 8103190049 81/02/12 8103190062 8103190062 81/02/12 8103190072 8103190053 81/03/03 8103190076 8103190071 81/02/13	50-364 0 50-282 0 50-29 0 CUNTRACT 50-350 0
8103180508 810318 8103180590 810318 8103180591 810318 8103180601 810318 8103180602 810318	0000 81/02/26 0000 81/02/26 0000 81/02/26	COMMISSION COMMISSION COMMISSION		50-380 0 CUNTRACT 50-461 Q 10CFR 50-272 Q
8103180623 810318 8103180626 810318 6103180637 810318 8103180643 810318 8103180653 810318	0619 81/03/15 0630 81/03/06 0635 81/03/09 0649 81/03/10	50-237 S 50-440 0 50-289 T 50-324 S 50-250 H	8103190103 8103190075 81703711 8103190104 8103190101 81703712 8103190108 8103190075 81703711 8103190110 8103190100 81702725	50-364 P TOPREP 50-364 P 50-305 0 50-331 0
8103180459 B10318 8103180460 B10318 8103180463 B10318 8103180468 B10318	0656 81/02/04 0655 81/03/05 0656 81/02/04 0656 81/02/04	50-220 Q 50-220 Q 50-220 Q 50-220 Q	8103190130 8103190123 81/03/16 8103190136 8103190123 81/03/16 8103190147 8103190140 81/03/12 8103190153 8103190140 81/03/12	50-261 F 50-261 F 50-159 F 50-159 F CONTRACT
8103180675 810318 8103180678 810318 8103180689 810318 8103180697 810318 810318069716 810318	0674 81/01/21 0684 81/01/20 0686 81/03/11	70-1151 50-394 0 50-286 0 50-320 P 50-546 1	8103190167 8103190164 81/03/10 8103190169 8103190163 61/03/13 8103190172 8103190166 61/03/11 8103190175 6103190166 61/03/11	CONTRACT 50-324 F 50-271 P 50-271 P 50-324 F

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESS1	CN NUMBER			
ENCLOSURE	PRINCIFAL DECUMENT	DATE ISSUED	GUG JEC T CATEGOR			PRINCIPAL BOCKMENT	DATE ISELED	SUBJE CATEG	
0103190179 8103190181 9103190183 8103190191 8103190194	8103190173 8103190166 8103190176 8103190185 8103190180	81/03/10 81/03/14 81/03/14 81/03/10	50-339 50-271 50-327 50-305 50-510	9 9 9 0 0	8103190630 910319083 910319083 9103192035 910319363	8103190824	81/02/12 81/02/13 81/02/14 81/02/13	40-339 40-339 PR 50-271 50-271	2
8103190197 8103190201 8103190211 8103190216 8103190217	8103190183 8103190183 8103190208 8103190206 8103190212	81/03/19 81/03/15 81/03/15 81/03/15	50-305 50-305 50-546 50-271 50-327	() () () ()	609715018 7497215018 7497215018 609715018	8103190846 9103190969 8103170883 6103190892	81/02/12 81/02/27 81/02/12 81/02/17 81/02/04	50-27) XPORTLI 50-27] CONTRAC 50-272	1C 0
8103170231 8103170232 8103170235 8103170242 8103170247	8103140518 8103140518 8103140518 8103140518	81/03/05 81/03/06 81/03/06 81/03/06	50-366 50-271 50-366 50-364 50-271	ն 6 6	810320028 810320038 810320035 9103200055 6103200068	8103200018 8193200031 8103200043 8103200051	61/03/09 61/03/03 91/03/11 61/05/11	50-409 50-261 50-339 50-352 00:4188	9 9 9
8103170259 8103170268 8103170269 8103170278 8103170279	8103170247 8103170262 8103170247 8103170262 8103170264	81/03/06 81/02/11 81/03/06 81/03/05 81/03/05	50-259 50-255 50-257 90-255 Centract	6 6	8:03200971 8:03200073 0:03260073 8:03230684 8:03230114	8103200056 8103200062 8103200056 8103200056 8103200108	81/02/03 11/02/18 11/02/03 11/03/11	80-352 PADJ 50-352 50-352 50-289	0 0 7
8103170294 8103170297 8103170306 8103170308	8103190282 8103190288 8103190282 8103190282 8103190201	81703710 81701728 81703710 81703710 81701729	50-250 50-289 50-250 50-250 50-219	0 0 0	8103200115 8103200119 8103200204 610320222	8103200108 8103200108 8103200174 8103200176 8103200215	81/03/11 81/03/11 81/03/11 81/03/14	50-269 50-289 CONTRAC' 50-29 50-263	1 7 9
8103190312 8103190317 8103190328 8103190338 8103190360	8103190202 8103190313 8103190321 8103190333 8103190338	81/03/10 81/02/11 81/02/11 81/02/11 81/03/04	90~290 50~399 30~200 50~990 CONTRACT	0	B103200236 B103200247 B103200254 B10320254 B10320254	8103200227 8103200235 8103200235 8103200248 8103260248	81/01/29 81/03/18 81/03/16 81/03/16	50-29 50-287 50-287 50-344 50-344	0 F F P
8103190375 6103190364 6103190391 6103190392 8103190396	8103190383 8103190383 8103190383 8103190383	81/03/17 81/03/16 81/03/17 81/03/17	PR 50-241 50-320 PR 50-320	8 P P	8103200272 0103200275 0103200200 0103200304 0103200310	8103260267 8103260256 8103260267 8103260250 6103260250	81/03/17 91/01/29 91/03/19 91/03/18 91/03/18	50-293 70-2915 50-293 50-498 50-498	F K
8103170398 8103170407 8103170414 8103170428 8103170452	8103170383 8103170383 8103170383 8103170420 8103170443	B1703717 B1703717 B1703717 B1701723 B1701727	50-320 50-320 30-320 PR PR	ր 9	CSE00/C018 eccosco10 44/00/C018 e8/00/C018 e8/00/C019	8103203315 8103203324 810320359 810320351 8103260377	81/02/18 81/02/13 81/02/13 81/03/16 81/01/30	TOPREP 50-348 50-469 50-10 70-1100	P F P
8103170455 8103170463 8103170485 8103170506 8103170530	8103190450 8103190450 8103190470 8103140502 8103170526	81703719 81703713 81703711 81703717	90-334 90-334 90-263 90-324 90-392	F B B K	010220397 9103206446 8103200476 4103200470 810320476	8103200440 8103200440 8103200452 8103200452 8103200452	81/02/13 90/80/18 60/80/18 60/80/18	50-206 50-263 50-369 50-369	F Q P P
8103190893 8100190543 8100190590 8103190593 8103190561	0103140238 0103140238 0103140238 0103140238	81.03\18 81.03\18 81.03\18 81.03\18	50-299 50-289 50-289 50-289 50-289	P 7 7 1	8103200491 8103230903 610320343 8103250560	8103203434 8103200497 8403203542 8103200551 8103200551	81/03/11 81/02/13 81/03/12 81/03/16 81/03/16	CDNFRACT 50-355 50-327 50-344 50-344	8 A P
8103190558 8103190560 8103190570 8103190571 8103190574	640916018 6400416018 6400416018 6400416018	81/03/17 81/02/27 81/03/17 81/03/17 81/03/17	50-352 50-352 50-352 50-352 50-352	A A A A	8103200541 8103200547 8103200548 6103200570 8103200572	910320557 9103203563 910320366 6103203565	81/03/05 81/03/11 61/02/09 81/03/11 61/02/09	50-344 50-329 50-295 50-329 50-295	P 0 0 0
8103170641 8103170641 9103170646 8103170649	8103170616 8103170634 8103170634 8103170649 8103170647	81703709 81703717 81703717	50-2/5 50-2/17 50-2/17 50-4/9 50-4/1	0 0 0 P 0	0103200578 8103200579 810320369 8103200582 8103200598	8103203576 8103200576 8103200576 8103200576 8103200597	81/03/19 81/02/12 81/02/13 81/02/13	50-213 50-213 50-213 50-2(3 50-214	0 0 0 F
8103190652 B103190653 8103190654 B103190656 B103190657	8103170650 8103170650 8103170651 8103170650 8103170630	81/03/17 81/03/17 81/03/16 81/03/17 81/03/17	50~352 50~352 50~352 50~352	C B C C	0103200637 0103200644 0103200646 0103200650 0103200652	8103200632 810320639 810320639 810320639	81/03/13 61/03/16 61/03/13 61/03/13	30-443 50-329 50-443 50-329 50-443	0 4 0 4 0
8103190564 8103190566 8103190569 8103190570 8103190672	8103170662 8103170662 8103170662 8103170662 8103170662	81/05/04 81/05/04 81/05/04 81/05/04	XPORTL 10	0 0 0	810320659 810320646 8103200679 8103200704 8103200736	8103230632 8103200658 8103200700 8103200700	81/03/13 81/03/16 81/03/16 81/03/10 81/03/13	50-443 50-269 50-289 50-273 50-305	G T T 8
8103190676 8103190680 9103190682 8103190684 8103190694	6103190673 6103190678 6103190677 6103190663 6103190665	81\03\15 81\01\30 81\03\13 81\03\10 81\01\51	50-317 50-409 CONTRACT WASTE MOT CONTRACT	Q 0	9103200797 8103200763 8103200778 810320783 8103200786	8103200751 8103200751 8103200775 8103200780 8103200781	81/03/09 81/03/09 81/03/16 81/03/16 81/02/18	50-387 50-387 71-403 71-164 50-295	о о Р
8103190702 8103190706 8103190713 8103190756 8103190629	8103190683 8103190683 8103190711 8103190748 8103180071	81/01/30 81/01/30 81/03/04 81/03/04 77/02/04	WASIE MOT TOM STBAM TOMOTIC TOMOTIC TOMOTIC WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WASIE WA WA WA WA WASIE WA WA WA WA WA WA WA WA WA WA WA WA WA		0102200794 81002200799 81002209040 8100220840 8100220843	810J200789 810J200781 810J200781 810J200834 810J200834	81/03/18 81/02/18 81/02/18 81/03/10	CDNTRACT 50-295 50-295 106FR LCCFR	P P

0.0000	***************************************			,	********			
8103230074 8103230078 8103230079 8103230083 8103230084	8103230045 8103230049 8103230056 8103230024 8103230058	81/03/19 81/03/12 81/02/19 81/02/13	50-247 10CFR 50-369 CONTRACT 50-369	0 P P	8103231058 8103240012 8103240013 8103240018 8103240022	8103230946 8103240005 8103240009 8103240009 8103240009	81/03/13 81/03/11 81/03/11 81/03/11	CONTRACT PR COMMISSION COMMISSION COMMISSION
8103230075 8103230079 8103230119 8103230120 8103230126	8103230070 8103230070 8103230070 8103230115 8103230126	81/03/19 81/03/19 81/03/19 81/03/05 81/02/10	70-1308 70-1308 70-1308 50-358 50-461	Q Q	8103240028 8103240050 8103240062 8103240065 8103245095	8103240009 8103240042 8103240051 8103240058 8103240092	81/03/11 81/03/13 81/03/16 81/03/04 81/02/06	CDH41681DN 50-327 P 50-346 P 50-409 P 50-247 0
8103230129 8103230141 8103230142 8103230147 8103230151	8103230125 8103230126 8103230135 8103230138 8103230148	81/03/10 81/02/10 81/03/16 81/03/05 81/02/11	50-182 50-461 50-439 71-9035 50-440	P	8103240106 8103240114 8103240123 8103240134 8103240143	8103240101 8103240101 8103240116 8103240129 8103240139	80/11/13 80/11/13 81/03/12 81/03/09 81/03/09	50-206 0 50-206 0 70-143 COMMISBION COMMISBION
8103230153 8103230160 8103230162 8103230164 8103230168	8103230146 8103230152 6103230154 8103230161 8103230169	81/03/09 81/03/10 81/03/16 81/03/16 81/01/2]	50-409 50-285 50-456 71-219 70-1257	0 0	8103240146 8103240162 8103240178 8103240186 8103240200	8103240140 8103240152 8103240174 8103240174 8103240194	81/03/20 81/03/18 81/03/18 81/03/19	50-327 G 50-518 G 50-219 R 50-219 R 50-334 P
8103230187 8103230263 8103230264 8103230275 8103230284	8103230175 8103230257 8103230250 8103230250 8103230250	81/02/15 81/02/15 81/03/09 81/01/28	50-382 50-352 50-333 50-333 50-333	а н о о	8103240205 8103240215 8103240221 8103240226 8103240230	8103240193 8103240210 8103240213 8103240214 8103240222	81/03/18 81/03/17 81/03/19 81/02/19 81/03/17	50-261 P 50-261 P 50-293 R 50-266 G 50-321 P
8103230290 8103230291 8103230295 8103230310 8103230335	8103230283 8103230281 8103230250 8103230350 8103230332	81/02/25 81/03/09 81/02/12 81/02/12 81/03/19	50-320 50-250 50-333 50-333 50-275	P P Q Q A	8103240233 8103240236 8103240247 8103240249 8103240230	8103240225 8103240227 8103240240 8103240241 E420426018	81/03/20 81/03/20 81/03/16 81/03/11 81/03/18	50-104 R 50-443 Q 50-338 P 50-250 Q 50-320 P
8103230355 8103230361 8103230366 8103230372 8103230375	8010230589 8103230351 8103230351 8103230351	80/09/30 81/03/09 81/03/09 81/03/09	50-269 50-305 50-305 50-305 50-269	P P P P	8103240254 8103240256 8103240257 8103240260 8103240261	8103240246 8103240243 8103240241 8103240246 8103240241	81/03/10 81/03/18 81/03/10 81/03/11	CDMM1681CN 50-320 P 50-290 Q CDM11691ON 50-250 Q
8103230386 8103230407 8103230437 8103230461 8103230464	8010230589 8103230395 8103230429 8103230458 8103230457	81/03/16 81/03/16 81/03/16 81/03/16	50-269 50-247 50-387 50-471 50-352	Р О К 8 Н	8103240267 8103240269 8103240272 8103240274 8103240278	8103240246 8103240246 8103240246 8103240264 8103240246	81/03/10 81/03/10 81/03/10 81/03/10	COMMISSION COMMISSION COMMISSION 50-438 G COMMISSION
6103230490 6103230507 8103230527 6103230551 6103230558	B103230486 B103230500 B103230518 B103230542 B103230552	81/03/11 81/03/13 81/03/09 81/03/18	50-29 50-106 50-265 50-293 90-333	F	8103240284 8103240288 8103240289 8103240293 8103240294	8103240246 8103240280 8103240246 8103240286 8103240280	81/03/11 81/03/10 81/03/10 81/03/10	COMMISSION 70-143 COMMISSION 50-438 0 70-143
8103230569 8103230585 8103230599 8103230620 8103230622	8103230559 8103230578 8103230592 8103230615 8103230610	81/03/11 81/03/13 81/03/13	50-313 50-247 NUREG 50-289 50-369	R R P O	8103240298 8103240296 8103240297 8103240299 8103240301	8103240291 8103240280 8103240286 8103240291 8103240280	81/03/13 21/03/19 1/03/13 1/03/18	50-321 0 70-143 50-438 0 50-321 0 70-143
8103230628 8103230631 8103230648 8103230659 8103230672	B103230610 B103230617 B103230641 B103230641 B103230656	81/03/11 81/03/10 81/03/13 103/20	50-369 50-250 50-373 50-373 50-289	Q P E E E	8103240302 8103240303 8103240304 8103240308 8103240312	8103240286 8103240286 8103240291 8103240286 8103240291	E1/03/12 21/03/18 21/03/18 21/03/18	50-438 Q 50-438 Q 50-321 Q 50-438 Q 50-321 Q
8103230678 8103230683 8103230705 9103230716 8103230718	8103230656 8103230675 8103230689 8103230707 8103230717	81/03/20 81/03/13 81/03/16 81/03/17 81/03/12	50-289 50-466 50-324 50-366 50-170	О Н В Ф	8103240313 8103240314 8103240322 8103240324 8103240334	8103240309 8103240310 8103240315 8103240315 8103240315	81/03/15 81/03/15 81/03/16 81/03/16	70-27 50-206 P 50-280 Q 50-280 Q 50-280 Q
8103230721 8103230722 8103230723 8103230732 8103230739	6103230712 8103230719 8103230720 6103230728 6103230737	81/03/17 81/03/17 81/03/13 81/03/16 81/03/13	50-366 FDIA 50-325 50-312 50-302	ម ទ ទ R	B103240336 B103240342 B103240353 B103240367 B103240380	8103240290 8103240315 8103240348 8103240362 8103240375	81/01/23 11/03/18 11/03/19 11/03/19	50~10 P 50~280 G 50~10 R 50~217 R 50~87 P
8103230751 8103230760 8103230777 8103230798 8103230820	8103230746 8103230755 8103230766 8103230792 8103230812	81/03/17 81/03/13 81/03/18 81/03/17	50-366 50-315 50-263 50-296 50-366	ម ទ ទ ទ	8103240388 8103240392 8103240398 8103240399 8103240405	8103240385 8103240385 8103240393 8103240382 8103240394	81/02/17 81/02/17 81/03/17 81/03/17 81/03/23	50-409 G 50-409 G 50-269 P 50-309 P 50-250 G
6103230833 8103230834 8103230841 8103230853 8103230903	6103230824 6103230819 6103230837 6103230849 6103230901	81/03/17 81/03/20 81/03/11 81/03/06 61/03/10	50-366 50-387 71-412 50-389 50-443	8 Q U A	8103240414 8103240418 8103240419 8103240425 8103240437	8103240394 8103240412 8103240417 8103240415 8103240429	81/03/23 81/03/18 81/03/17 81/03/19 81/03/18	50-250 0 50-255 8 50-312 F 50-368 8 50-313 8

# PRINCIPAL DOCUMENTS

ACCESSION	NUMBER								
	PRINCIPAL	DATE	508JEC1		ACCESS	ON NUMBER			
ENCLOSURE	DOCUMENT	138050	CATEGOR		ENCLOSURE	PRINCIPAL	DATE	£'∵3 ,€	
8103240447 8103240450	8103240441 8103240444	81/03/19 81/03/17	50-333 50-249	5 8	********		182,50	CATES	
B103240454	8103240445	81/03/20	<b>5</b> 0-329	Α	6103240849 8103240852	8103243834	81/63/16	36-331	2
8103240457 8103240458	8103240453 8103240452	81/03/17 81/03/17	50-312 50-259	9 8	81 07250304 81 07250304	8103252001	81/03/16	50-247	þ
•••					81 03527010	HIG32GAAA	81/03/17	\$Q-335	3
8103249463 8103240465	8103240460 8103240459	81/03/16 81/03/18	50-312 50-325	\$ 6	8103250015	-195250002	81/03/17	30-339	3
8100240468	8103240461	81/01/16	50-296	8	8103250018	8103353030	81/02/23		a
8103240472 8103240475	810J240467 810J240470	81/03/19 81/03/13	50-324 50-317	9	810325C022 810325C022	8103250014	81/03/23	\$0-315 \$0-237	3
					8103250025	6103525016	81/02/17 81/03/18	36-373	3
8103240480 8103240484	8103240476 8103240478	81/03/16	50-267 50-296	6 b	8103250028			50-50g	9
8103240495	8103240489	01/03/18	50-338	В	8103250331	8103250019 8103250027	81/03/18	30-55g	þ
8103240508 8103240511	8103240906 8103240506	81703711 81703711	50-192 50-192	R	#103250032 #103250039	8103250019	81/03/18	50-761 50-519	9
0.00740810	8103240519	01/03/19	50-219		B103250049	8103250037 8103250037	11/20/18 81/20/18	50-119 50-114	9
8103240510 8103240519	8103240394	81/03/23	50~214 50~250	P Q	8103253942	0103250317			3
8103240521 8103240526	8103240516 8103240394	81/03/19 81/03/19	50-250 50-250	0	\$103259047 8103250111	810325 <u>0</u> 019	81/03/18 81/03/18	50-56a 50-50a	9
6103240929	8103240524	81/03/18	50-23H	8	8103253116	0103250105 0103250105	81103119	50-325	P
8103240931	B103240374	81/03/23	50-250	o	8103520133	8103250133	81/03/18	50-329 50-321	a J
8103240532	£103240530	01/03/20	50 - 271	8	8103250141	8103250134	81102118		-
8103240536 8103240541	8103240534 8103240539	81/03/19 81/03/19	50~302 50-302	8	8103250142 8103250144	8103250133 8103250133	01/03/19	%0-3\$1 %0+E3	9
8103240549	B103240548	81/03/18	50-298	អ	8103250145	8103250133	81/03/14	50-238 50-321	0
B103240561	8103240558	81/03/18	50-008	ន	B1 032531 49	8103520133	81/03/19	30-321	ò
B103240574	B103240973	81/03/18	50-309	Α	8103250153 8103250154	0103250147	81/03/17	76-27	
8103240581 8103240582	8103240575 8103240577	81/03/16 81/02/26	50-247 50-213	8	8103520191	8103250133 8103250158	81/03/19	50-321	0
8103240584	8103240979	81703718	50-325	ß	8103250163 8103250163	8103250157	81/03/18	\$0-325 50-255	g J
B103240985	8103240577	81/02/26	50-213	P	•	8103253164	81/03/16	20-596	۶
8103240595 8103240590	8103240578 8103240588	81703723 81703718	50-209 50-325	1	8103250173 8103250175	B103250167 B103250169	81/03/17	70-143	
6103240572	8103240507	81/03/16	50-219	8	8103250176	8103253172	81/03/17 81/03/16	30-315 50-344	G H
B103240603	8103240596	81/03/19	20-333	O	8103250177 8103250187	8103250171 8103250179	81/03/16	50-454	٨
8103240605	B103240577	01/05/59	50-213	þ	8103250193			50-438	3
8103240509 8103240620	8103240977 8103240615	81/02/26 81/02/13	50-213 50-416	р 0	B103590148	8103250179 8103250179	81/03/18 81/03/18	50-438 50-438	a
R100240526	8103540912	61/02/13	30-416	Q.	9103250204 8103250206	8103250179	81/03/18	50-438	3
8103240628	0103540911	81/03/11	20-544	a	8103250238	8103250226 81032502 <b>3</b> 2	81/03/16 81/03/16	50-440 50-289	0
0103240634	0103240419	61/05/13	50-416	œ	8103250245	8103250241	81/03/18		
8103240639 8103240640	8103240611 8103240611	81/03/1 <b>1</b> 81/03/11	50-269 50-269	0	B103250276	B103250273	81/02/27	50-289 50-335	Ç R
8103240640 8103240666	8103240611	11/03/11	60-598	q	8103250289 8103250304	8103250286 8103250297	81/02/26		R S
	8193240455	81/03/10	20-538	Q	6103290311	8103250307	81/03/04		ē
8103240 <i>66</i> 8 8103240674	8103240660 8103240660	81/03/13 81/03/13	50-424 50-424	0	8103250315	8103250299	81/03/20	50-260	В
8103249678	8103240660	81/03/13	50-424	g	8103230316 8103250318	8103250307 8103250307	81/03/06 81/03/05	50-272	P
8103240681 8103240686	8103540990 8103540990	01/03/13	50-257 50-424	a	8103250330	8103250327	81/02/11	50-272 REVIEW GR	P
			-		8103250334	B10325032B	91/03/10	50-335	P
8103240697 8103240702	8103240693 8103240688	81/02/13	50-397 50-266	Q F	8103250326	8103250327	81/02/11	REVIEW CR	
8103240700	8103240700	81/02/24	50-312	Q	8103250337 8103250340	8103250328 8103250327	81/03/10	REVIEW OR	P P
8103240712 8103240714	B103240704 B103240710	81/02/18	50-249 50-430	Q Q	8103253349 8103250353	B103250328 B103250347	81/03/10	\$0-335	₽
8103240722	B103240704	01/03/18						71-414	
8103240724	8103240714	81/03/11	50-269 70-1113	0	8103250357 8103250363	8103250352 8103250359	81/03/13 81/03/11	50-338 71-413	P
8103240720 8103240733	8103240719 8103240726	01/02/26 01/03/10	50-206 50-338	G G	B103 <b>290</b> 378	0103250373	81/03/11	71-415	
8103240738	B103240730	81/03/15	50-335	ů	8103250400 8103257427	8103250377 8103250425	81/03/05		K Q
8103240743	8103240730	01/03/12	50~335	œ	8103250435	B103250432	81/03/18	TOPREP	
8103240744	8103240737	81/02/26	50-344	G	B103250433 B103250443	8103253442	81/03/24	50-450	Q
8103240757 8103240776	8103240747 8103240704	81/03/18	50-264 50-564	G	\$10325044B \$103250473	8103250442 8103250469	81/03/24 81/03/09	50-450 71-425	0
8103240781	8103240771	81/03/17	50-263	Ğ	8103250480	8103250476	81/03/19		ð
8103240765	8103240704	81/03/18	50-269	O	8103250485	8103250476	81/03/19	30-466	D
8103240786 6103240793	8103240775	81/03/12	50-346	a	8103250489	B103250481	81/03/18	50-339	8
8103240803	8103240789 8103240789	81/03/10 81/03/10	50~330 50~338	a a	0940826018 8940826018	8103250483 8103250492	81/03/05 81/03/(6	PA CONTRACT	
B103240807	8103240800	01/03/11	50-321	ā	9103250907	8103250497	81/03/20	50-327	8
8103240812	8103240805	81/03/10	50-390	a	8103250530	8103250541	81/01/16	PR	
8103240815 8103240819	8103240811 8103240800	81/03/10 81/03/11	30~261 50~321	a	8103250973 8103250624	8103250944 8103250614	81/02/13	CONTRACT 27-47	
8103240822	8103240811	81/03/10	30-261	0	8103250635	8103290685	81/03/11	50-272	P
8103240823	8103240805	81/03/10	50-390	ø	8103250658	8103250852	81/05/50		Q
8103240836 8103240839	8103240828	81/02/03	CONTRACT		8: 03250692	8103293689	81/03/19 81/03/19		F F
8103240839 8103240841	8103240834 8103240828	81/02/10	CONTRACT	G	8103250702 8103260021	810325068 <b>5</b> 810326001 <b>8</b>	81/03/16	40-659	
9103240844	8103240838	91/03/16	50-267	P	8103260051	8103260044 8103250048	81/02/13 81/03/03	50~237 FQIA	a
8103240847	8103240838	81/03/16	50-267	Р	81 03260059	2107520040	_,,,		

ENCLOSURE	PRINCIPAL COCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1560ED	BUBJECT CATEGORY
6103260062 8103260066 8103260067 8103260070 B103260076	8103260054 8103260054 8103260048 8103260054 8103260048	81/03/20 81/03/20 81/03/03 81/03/20 81/03/03	50-324 P 50-324 P FOIA 50-324 P	8103240471 8103240473 8103260474 8103260479 8103240488	8103260457 8103260464 8103260461 8103260048 8103260048	81/02/13 81/02/20 81/03/16 81/03/03 81/03/03	50-498 0 70-1201 50-206 0 40-1947
8103260081 8103260084 8103260087 8103260092 8103260103	8103260048 8103260072 8103260048 8103260048 8103260048	81/03/03 81/02/13 81/03/03 81/03/03 81/03/03	FOIA 50-373 G FOIA FOIA 40-9610	8103260495 B103260499 B103260591 B103260596 B103260509	8103260493 8103260948 8103260487 8193260948 81932609493	81/03/50 81/03/03 81/03/19 81/03/03	50-445 Q 40-1947 50-400 Q 40-1947 50-390 Q
8103260109 8103260113 8103260118 8103260137 8103260142	8103260097 8103260048 810326048 8103260123 8103260048	81/03/23 91/03/03 91/03/03 91/03/17 91/03/03	50-494 A 40-8610 FOIA 90-10 F	8103260513 8103260519 8103260521 8103260522 8103260524	8103260048 8103260048 8103260487 8103260512 8103260516	81/03/03 81/03/19 81/03/11 81/03/11 81/02/06	FOIA FOIA 50-400 0 27-39 50-455 0
8103260148 8103260159 8103260161 8103260174 8103260179	8103260048 8103260141 8103260048 8103260048 B103260167	81/03/03 81/03/06 81/03/03 81/03/03 81/03/13	FDIA 27-47 40-8610 40-8610 50-298 R	8103260526 8103260527 8103260530 8103260532 8103260533	810326048 8103260515 8103260512 8103260048 8103260516	81/03/03 81/03/11 81/03/11 81/03/03	F014 50-286 5 27-39 40-1947 50-458 0
8103260178 8103260183 8103260186 8103260191 8103260198	8103240648 8103240048 8103240149 8103240048 8103240048	81/03/03 81/03/03 81/03/03 81/03/03	FOIA FOIA 50-416 0 40-8610 40-8610	8103260536 8103260537 8103260539 8103260542 8103260548	8103260487 8103260512 8103260048 8103260487 8103260048	81/03/19 81/03/11 81/03/03 81/03/19 81/03/03	50-400 G 27-39 40-1947 50-400 G 40-1947
8103269205 8103260211 8103260229 8103260238 8103260241	8103260048 8103260203 6103260218 8103260218 8103260048	81/03/03 81/03/12 81/03/11 81/03/11 81/03/03	40-8610 50-387 6 90-245 P 50-249 P 40-8610	8103260551 8103260553 8103260553 8103260556	8103240545 8103240487 8103240048 8103240048 8103240048	81/03/24 81/03/19 81/03/03 81/03/04 81/03/03	50-361 K 50-400 G 40-1947 CCNTRACT 40-1947
8103269247 8103260251 8103260254 8103260260 8103260263	8103260048 8103260218 8103260048 8103260246 8103260048	81/03/03 81/03/11 81/03/03 81/03/16 81/03/03	40-8610 50-245 P 40-8610 50-281 P 40-8610	6103240572 8103240577 8103240589 8103240581 8103240583	8103260048 8103260048 8103260571 8103260576 8103260576	81/03/03 81/03/03 81/03/24 81/03/17 81/03/17	40-1947 40-1947 90-244 P CDM(16910N CDM(15810N
8103260269 8103260273 8103260278 8103260280 8103260281	8103260246 8103260048 8103260264 8103260246 8103260048	81/03/16 81/03/03 81/03/16 81/03/16 81/03/03	50-281 P FOIA 50-324 P 50-281 P 40-8610	8103260586 8103260587 8103260590 8103260591 8103260594	8103260576 8103260574 8103260048 8103260576 8103260576	81/03/17 81/03/20 81/03/03 81/03/17 81/03/17	COM118610N 50-247 B 40-1947 COM11881CM COM115510N
81 03260289 81 03260293 81 03260298 81 03260304 81 03260306	8103260264 8103260048 8103260264 8103260048 8103260292	81/03/16 81/03/03 81/03/16 81/03/11	50-324 P FOIA 50-324 P FOIA 70-143	8103260596 8103260599 8103260606 8103260606	8103260576 8103260576 8103260048 8103260048 8103260603	81/03/17 81/03/17 81/03/03 81/03/03 81/03/13	COMMISSION COMMISSION 40-1947 40-1947 50-317 B
81 03260311 81 03260314 81 03260319 81 03260323 81 03260325	8103260048 8103260292 8103260048 8103260292 8103260048	81/03/03 81/03/11 81/03/03 81/03/11 81/03/03	FDIA 70-143 40-8610 70-143 40-8510	6103240414 6103240420 6103240421 6103240423	8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/24 81/03/03 81/03/03	40-1947 40-1947 50-244 P 40-1947 40-1947
81 03260329 81 03260330 81 03260339 81 03260341 81 03260346	8103260292 8103260048 8103260048 8103260292 8103260048	81/03/11 81/03/03 81/03/03 81/03/11 81/03/03	70-143 FOIA FOIA 70-143 FOIA	8103240431 8103240431 8103240437 8103240438 8103240442	8103260618 8103260048 8103260630 8103260048 8103260048	81/03/09 81/03/03 81/03/19 81/03/03	PR 40-1947 TOPREP 40-1947 40-1947
B1 03260354 B1 03260357 B1 03260360 B1 03260362 B1 03260365	8103260048 8103260349 8103260353 8103260048 8103260349	81/03/03 81/03/20 81/03/13 81/03/03 81/03/20	40-1947 50-155 H 50-348 Q FOIA 50-155 H	8103260646 8103260646 8103260692 8103260658 8103260666	8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/03 81/03/03	50-318 8 40-1947 40-1947 40-1947 40-1947
81 03260369 81 03260370 81 03260374 81 03260382 81 03260387	8103260048 8103260355 0103260048 8103260048 8103260376	81/03/03 81/03/13 81/03/03 81/03/03 81/03/17	FOIA 50-34B G FOIA FOIA 50-244 P	6103240467 6103240478 6103240481 8103240481	8103260657 8103260048 8103260048 8103260675 8103260048	81/03/03 61/03/03 61/03/03 81/03/18	50-266 F 40-1947 40-1947 40-3453 40-1947
81 03260389 81 03260397 81 03260403 81 03260410 81 03260414	8103260048 8103260048 8103260048 8103260048 8103260407	81/03/03 81/03/03 81/03/03 81/03/10	FOIA FOIA FOIA FOIA WASTE HOI	8103240484 8103240491 8103240492 8103240498	B103260676 B103260048 B103260048 B103260048 B103260048	81/03/12 81/03/03 81/03/12 81/03/03 81/03/03	50-334 8 FOIA 50-334 8 40-1947 40-1947
8103260417 6103260425 6103260427 6103260429 8103260434	8103260048 8103260048 8103260413 8103260419 8103260413	81/03/03 81/03/03 81/03/19 81/03/12 81/03/19	FOIA FOIA 50-220 P COMMISSION 50-220 P	8103260703 8103260705 8103260707 8103260709 8103260713	8103260048 B103260701 B103260697 B103260048 B103260048	81/03/03 81/03/12 81/03/12 81/03/03	40-1947 40-8380 50-334 8 40-1947 40-1947
81 03260435 81 03260440 81 03260442 81 03260450 81 03260456	8103260048 8103260048 8103260413 8103260048 8103260444	81/03/03 81/03/03 81/03/19 81/03/03 81/02/20	FOIA 40-1947 50-220 P 40-1947 50-566 G	8103260715 8103260716 8103260719 8103260721 8103260722	8103260048 8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/03 81/03/03 81/03/03	40-1947 FOTA 40-1947 40-1947 40-1947

ACCESSIO	W NUMBER				ACCE8610	:I NJMBER		
ENCLOSURE	JA91 DNI P9 HABMUSCO	DATE 185UED	SUBJECT	Y	ENCLOSURE	PRINCIPAL COSUMENT	PATE (SSUED	SUBJECT CATECCRY
8103260723 8103260724 8103260725 8103260726 8103260727	8103260048 8103260048 81 <i>03260048</i> 8103260048 8103260048	B1/03/03 B1/03/03 B1/03/03	40-1947 40-1947 40-1947 40-1947 40-1947		8103261149 8103261155 8103261161 8103261169 8103261166	6103261140 6103261150 6103261150 6103261157 6103261156	61/03/19 81/03/19 81/03/16 61/03/16	50-544 Q 50-254 P 50-254 P CCMH16810N 50-259 Q
8103260728 8103260729 8103260730 8103260731 8103260732	8103260048 8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/03 81/03/03	40-1947 40-1947 40-1947 40-1947 40-1947		8103261177 8103261196 8103261198 8103261199 8103261204	8103261156 8103261189 8103261186 8103261190 8103261190	81/03/20 81/03/19 81/02/11 81/03/13	50-259 0 50-309 P 50-498 0 COMMISSION COMMISSION
8103260733 8103260734 8103260736 8103260738 8103260740	8103260048 8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/03 81/03/03 81/03/63	40-1947 40-1947 40-1947 40-1947 40-1947		8160261209 6102270010 8103270916 6103270019 6103270021	0103261205 8103270007 8103270014 8103270014 8103270014	81/03/16 81/03/17 81/03/17 81/03/17 81/03/17	02E-06 02E-06 02E-06 02E-06 02E-06
8103260742 8103260745 8103260748 8103260751 8103260753	8103260048 8103260048 8103260048 8103260048 8103260048	81/03/03 81/03/03 81/03/03 81/03/03	40-1947 40-1947 40-1947 40-1947 40-1947		8103270027 8103270040 8103270055 8103270060 8103270062	8103270023 8103270031 8103270053 8103270048 8103270051	81/03/16 81/03/13 81/03/13 81/03/18 81/03/19	70-820 CGNTRACT 50-280 Q CCNTRACT 90-321 Q
8103260757 8103260759 8103260760 8103260761 8103260762	8103260048 8103260048 8103260755 8103260756 8103260048	81/03/03 81/03/18 81/03/16 81/03/03	40-1947 40-1947 50-339 50-361 40-1947	8 0	8103270069 8103270069 8103270071 8103270072 8103270082	8103270050 8103270048 8103270051 8103270053 8103270051	81/03/12 81/03/18 81/03/19 81/03/13 81/03/19	CONTRACT CONTRACT 50-321 Q 50-280 Q 50-321 Q
8103260765 8103260772 8103260775 8103260776 8103260781	8103260048 8103260048 8103260770 8103260048 8103260048	60,00018 60,00018 61,00018 60,00018 60,00018	40-1947 40-1947 50-270 FDIA FDIA	e	8103270089 8103270098 8103270099 8103270103 8103270104	8103270080 8103270091 8103270091 8103270091 8103270080	81/03/10 81/03/19 81/02/11 81/02/11	50~259 Q 50~321 Q FO!A FO!A 50~259 Q
8103260784 8103260790 8103260793 8103260798 8103260800	8103260048 8103260048 8103260048 8103260048 8103260772	81/03/03 81/03/03 81/03/03 81/03/03 81/03/17	FOIA FOIA FOIA FOIA 50-23/	o	8103270112 8103270114 8103270119 8103270126 8103270134	8103270091 8103270109 8103270091 8103270091 8103270091	81/02/11 81/03/19 81/02/11 81/02/11 81/02/11	F01A 50-466 D F01A F01A F01A
8103240820 8103240811 8103240811	8103260048 8103260048 8103260048 8103260048 8103260812	81/03/03 81/03/03 81/03/03 81/03/03 81/03/17	FOIA FOIA FOIA FOIA PR		6100270134 8103270142 8103270145 8103270147 8103270157	8103270131 8103270391 8103270132 8103270391 8103270091	81/02/11 81/02/11 81/02/11 81/02/11	WASTE MOT FOLA 50~424 O FOLA FOLA
8103260823 8103260826 8103260835 8103260852	8103260048 8103260832 8103260842 8103260850	81703703 81703718 81703718 81703718	FOTA FOTA 90-337 50-338 FOTA	8 6	8103270158 8103270165 8103270170 8103270178 6103270178	6103270132 6103270091 6103270091 6103270091 8103270184	81/03/13 81/02/11 81/02/11 81/02/11 81/03/17	50-424 0 FOLA FOLA FOLA CCYLRACT
8103240849 8103240849 8103240877 8103240893 8103240899	8103260850 8103260859 8103260872 8103260882 8103260891	81/02/19 81/03/10 81/03/13 81/03/13	FOTA PR PROJ 50-317 70-143	S	8103270193 8103270203 8103270236 8103270356 8103270361	8103270186 6103270196 6103270227 6103270349 6103270351	80/10/23 81/02/20 80/10/27 81/03/20 81/02/20	70-687 PR 70-2882 CONTRACT 50-220 Q
8103260910 8103260913 8103260934 8103260948 8103260975	8103260891 8103260402 8103260924 8103260943 8103260969	81/02/18 81/03/20 81/03/17 81/03/09 81/03/19	70-143 50-346 50-317 40-3453 71-9147	8	8103270366 8103270390 8103270406 8103270407 8103270411	8103270351 6103270351 6103270397 8103270400 8103270401	81/02/20 81/02/20 81/03/25 81/03/25	50-220 G 50-220 G 50-443 G 50-285 P 50-348 K
8103260978 8103261099 8103261026 8103261026	8103260973 8103260976 8103261016 8103261017 8103261053	81/03/10 81/03/20 81/02/12 81/02/12	50-320 50-482 40-4472 53-454 CCNTRACT	Р А О	8103270414 8103270416 8103270417 8103270424 8103270433	8103270403 8103270403 8103270401 8103270403 8103270428	81/03/24 81/03/25 81/03/25 81/03/24 81/03/23	50-277 P 50-285 P 50-348 K 50-277 P 50-317 P
8103261069 8103261072 8103261082 8103261086 8103261095	8103261055 8103261060 8103261073 8103261079 8103261060	81/03/02 81/03/23 81/03/17 81/03/18 81/03/23	CONTRACT FOLA CONTRACT CONTRACT FOLA		8103270442 8103270452 8103270463 8103270482 8103270494	8103270423 8103270443 8103270457 8103270477 8103270487	81/03/13 81/03/20 81/03/17 81/03/25 81/03/23	CDNTRACT 50-395 A 50-320 P 50-282 R 50-317 P
8103261102 8103261103 8103261107 8103261109 8103261115	8103261060 8103261094 8103261097 8103261060 8103261060	81/03/23 81/03/16 81/03/23 81/03/23	FOTA CONTRACT 50-186 FOTA FOTA	o	8103270507 8103270518 8103270534 8103270576 8103270602	8103270502 8103270506 8103270506 8103270565 8103270570	81/03/13 81/03/12 81/03/18 81/03/23	27-39 50-400 0 50-400 0 CONTRACT 50-317 P
81193261153 61192261153 61032611154 6103261116	8103261111 8103261060 8103261117 8103261060 8103261060	81/03/18 81/03/23 81/03/23 81/03/23	CONTRACT FOIA 50-327 FOIA FOIA	a	8103270604 8103270626 8103270628 8103270629 6103270631	8193270594 8103270613 8103270619 8103270617 8103270618	81/03/19 81/03/19 81/03/13 81/03/66 61/03/09	CCNTRACT 50-293 S WARTE HOT 70-2707 50-254 S
8103261129 8103261133 8103261134 8103261137 8103261139	8103261117 8103261125 8103261060 8103261117 8103261132	81/03/18 81/03/18 81/03/23 81/03/18 80/08/14	50-327 CDNIRACT FOIA 50-327 50-57	a P	8103270633 8103270644 8103270647 8103270664 8103270671	8103270623 8103270623 8103270623 8103270661 8103270654	79/10/30 79/10/30 79/10/30 81/03/24 81/03/17	70-1207 70-1207 70-1207 70-1207 50-29 I CONTRACT

ACCESS 1 Or						14 NU:18ER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	6U8JECT CATEGOR		ENCL DOURE	PR INCIPAL THEMODOR	DATE 165UED	EUBJECT POSETAS	
6103270674	8103270666	81/03/20	50-324	 6 R	8103310023	B103310011 B103310103	81/03/18 81/03/27	50-333	P T
8103270675 8103270681 8103270683	8103270673 8103270677 8103270679	81/03/25 81/03/13 81/03/27	50-263 50-255 50-289	6 P	8103310115 8103310140 8103310209	8103310103 8103310122 8103310194	81/03/27 81/03/25	50-466 50-369 50-309	Ç
8103270693	8103270684	81103153	30-594	þ	B103310214	8103310506	81/03/56	90-271	P
8103270694 8103270697	8103270689 8103270695	B1/03/23 B1/03/25	50-315 50-70	8	8103310231 8103310231	8103310224 8103310226	81/03/27 81/03/20	50-530 50-29	R P
8103270699 8103270708	8103270695 8103270706	81/03/29 81/03/24	50-70 50-318	G P	9103310207 9103310257	8103310235 8103310246	81/03/27 81/03/24	90-334 90-309	Ð
6103270715 6103270726	8103270714 8103270726	B1/03/20 81/03/24	TOPREP 50-305	P	8103310274	8103310288	81/03/24 81/03/27	50-34 <i>0</i> 50-322	P
8103270736 8103270738	8103270735 8103270735	81/03/19 81/03/19	50-333 50-333	F	8103310306 8103310314 8103310320	8103310299 8103310309	81/03/27 81/03/27	50-322 50-440	A Q
8103270750 8103270756	B103270745 B103270751	B1/03/20 B0/10/30	50-220 70-135	P	8103310335 8103310346	8103310329 8103310341	81/03/30 81/03/26	50-250 50-247	ř P
8103270757	8103270749	81/03/20	50-325	8	B103310353	B103310341	81/03/26	50-247	Р
8103270759 8103270763	8103270751 8103270751	80/10/30 80/10/30	70-135 70-135		9103310357 9103310390	8103310209 8103310376	81/03/27 81/03/10	50-250 50-250	₽ P
8103270766 8103270767	8103270751 8103270762	80/10/30 81/03/18	70-135 50-325	8	B103310386 B103310427	8103310383 8103310422	81703727 81703726	50-350 50-340	ĸ
B103270770 B103270773	8103270768 8103270768	B1/03/23 B1/03/23	50-344 50-344	P P	8103310432 8103310437	8103310426 8103310434	B1/03/18 B1/03/23	50-298 50-348	P R
8103270788 8103270791	8103270782 8103270786	81/02/04 81/03/20	90-272 50-331	0	8103310446 810331045	8103310441 8103310441	81/03/30 81/03/30	50-269 50-269	P P
B103270798	8103270793	81/02/20	50-333	G	B103310453	8103310447	81/03/10	50-366	R
8103270800 8103270802	8103270796 8103270799	B1/03/25	XPDRTL10 50-387	A	8103310464 8103310467	8103310459 8103310448	B1/03/10 B1/03/20	50-321 50-454	ĸ
8103270815 8103270821	8103270809 8103270809	B1/02/20	50-333 50-333	0	8103310475 8103310479	8103310473 8103310473	81/03/24 81/03/24	50-266 50-266	P P
8103270826 8103270829	8103270809	80\10\30 B1\05\50	50-333 70-820	0	8103310482	0103310476	81/03/26	50-245	R
8103270832 8103270849	8103270809 8103270844	B1/02/20 B0/10/29	50-333 50-201	Q P	8103310483 8103310486 8103310490	8103310477 B103310477	81/03/24 81/03/24 81/03/24	50-327 50-327	R H
8103270853 8103270883	8103270844 8103270879	B0/10/29 B1/03/10	50-201 50-250	የ የ	8103310491 8103310506	8103310477 8103310487 8103310500	81/03/23 81/03/25	50-327 50-284 50-327	R P P
8103270927	8103270110	81/03/12	COH41881		B103310920	8103310512	81/03/20	50-397	F
8103270931 8103270938	8103270110 8103270110	81/03/12 81/03/12	50-275 50-338	U	B103310557 B103310558	8103310552 8103310548	81/03/27 81/03/20	50-338 50-295	8
8103270947 8103300008	8103270110 8103300003	81/03/12 81/02/23	50-293 50-410	g U	B103310567 B103310568	8103310561 8103310544	81/03/23 81/03/25	90-312 50-324	8
8103300011 8103300013	8103300003 8103300003	81/05/53 81/05/53	50-410 50-410	œ Gr	8103310573	8103310570	B1/03/26	90-339	8
8103300016 8103300078	8103300003 8103300075	81/02/23	50-410 50-397	0 8	810331057B 8103310579 8103310582	8103310540 8103310576 8103310535	81/03/26 81/03/26 81/03/27	50-339 50-339 50-260	5 8 6
B1 03300155	8103300150	81/02/23	50-373	ä	8103310590	8103310589	81/03/25	90-313	B
8103300174 8103300192	B103300171 B103300171	81/03/25 81/03/25	30-267 30-267	F F	8103310593 8103310594	8103310592 8103310591	81/03/24 81/03/25	50~346 50~260	8
8103300193 8103300264	8103300185 8103300257	81\03\50	50-352 50-320	û F	8103310597 8103310602	8103310595 8103310601	81/03/26	50-368 50-289	B
81 03300289 81 03300324	8103300319	B1/03/24 B1/03/23	90-334 50-271	P R	9103310670	8103310613	81/03/27	50-10	
81 03300329 81 03300338	8103300326 8103300354	81/03/53	50-324 50-317	8	8103310623 8103310627	8103310617 8103310625 8103310626	81/03/24 81/03/19	50-346 50-261	0
8103300359 8103300361	8103300355 8103300354	B1/03/27 B1/02/20	50-369 50-317	P	8103310632 6103310633 6103310633	8103310620 8103310625	81/03/20 81/03/24 81/03/19	80-272 80-339 50-241	8 0
8103300362	8103300354	81/02/20	50-317	G	8103310438	8103310549	81/03/24	50-269	1
8103300367 8103300381	0103300354 0103300380	81/02/20	50-317 50-470	9	8103310641 8103310646	8103310625 8103310625	81/03/19 81/03/19	50-261 50-261	Q Q
81 03300 444 81 03300 479	0103300439 0103300477	81/03/19 81/03/26	CONTRACT 50-254	P	8103310647 8103310654	8103310637 8103310625	81/03/26 81/03/19	50-305 50-261	9 0
8103300485 8103300487	8103300481 8103300477	81/03/24 81/03/26	50-346 50-254	p P	8109310656	8103310649 8103310664	81/03/24	50-313	8
81 03300 498 81 03300 490	0103300481 0103300481	81/03/24 81/03/24	50-346 50-346	р Р	8103310669 8103310679 8103310688	0103310673	81/03/27 81/03/25	50-333 50-331 50-324	8 8 6
8103300498	8103300496	81/03/20	80-220	Ġ	8103310703	8103310693 8103310693	81/03/27 81/03/26	50-324	В
8103300500 8103300509	8103300475 8103300505	B1/03/04 B1/03/20	50-259 50-338	P	8103310714 8103310718	8103310706 8103310711	81/01/12 81/03/20	70-2936 \$0-272	8
8103300514 8103300528	8103300505 8103300520	81/03/26 81/03/20	50-339 50-354	Ö	8103310730 8103310744	8103310724 8103310737	81/03/20 81/03/03	50-272 50-267	8
8103300552 8103300554	8103300546 8103300549	81/03/24 81/03/18	50-338 50-338	P	8103310759	8103310751	81/03/25	50-259	5
8103300555 8103300557	8103300546 8103300546	81/03/24 81/03/18	50-338 50-336	P	8103310789 8103310807	8103310778 8103310798	81/02/25 81/03/25	50-33B 50-302	G G
8103300559 8103300560	8103300546 8103300549	81/03/24 81/03/18	50-338 50-338	P	8103310820 8103310839 8103310839	8103310798 8103310832	81/03/25 81/03/25	50-302 CONTRACT	
8103300566	8103300562	81/03/23	80-331	P	8101310839 8101310839	8103310836 8103310842	80/12/31	XPORTL10	•
8103330568 8103300569	8103300562 8103300562	81/03/23 81/03/23	50-331 50-331	P	8103310857 8103310841	8103310851 8103310853	91/03/25 81/03/13	XPORTL 10	
8103310015 8103310020	8103310011 8103310011	81/03/18 81/03/18	50-333 50-333	P	8103310895 9103310896	8103310880 8103310882	81/02/02 80/12/12	9A999 70-820	

ACCESS!	อง เพษ	1BER

PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEBORY
8103310662	80/12/12	70-820
8103310962	80/12/12	70-820
8103310889	81/02/04	<b>G</b> ል499
8103310662	80/12/12	70-820
8193310885	80715715	70-820
	70301082 810301082 810301089 810301089	DDCUMENT 188VED 8103310882 80/12/12 8103310882 80/12/12 8103310882 80/12/12 8103310882 80/12/12

PRINCIPAL DOCUMENT	DATE 1890E0	SUBJECT CATEGORY
8103310934 8103310934 8103310933 8103310934	80115155 80115155 80115155 60115115	70-820 70-2969 04979 70-2909 70-2969
8103316943 8103310934	81/03/25 80/12/22	100fh 70-2909
	B103316934 B103316934 B103316934 B103316934 B103316934	BIGGG16934 B1/03/25 B103316934 B2/12/22 B103316934 B2/12/22 B103316934 B2/12/22 B103316934 B1/12/22

### DEFINITIONS OF DOCKET 50 CATEGORIES

### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses,
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A. C. M. P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

on are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

### O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 5. Correspondence regarding the Final Salety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Ouality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

- . Tenodic environmental monitoring, enfuent testing, of similar reports.
- 3. Periodic personnel exposure reports.
- Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

# S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50,55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1.7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

# U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive of Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

# V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

# W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

## **DEFINITIONS OF NONDOCKETED CATEGORIES**

### - Commission Meeting Records

gory contains documentation pertaining to open and closed Commission meetings. It

ishine Act Federal Register notices.

I, written explanation of closed meetings.

tification of General Counsel on closed meetings.

nmission Determination Statements regarding the public disclosure of transcripts of nmission meetings.

batim unofficial and official transcripts or portions of transcripts of open and closed nmission meetings made publicly available in accordance with provisions of 10CFR Part 9. Sunshine Act, and Commission policies.

flosures to released transcripts, including applicable viewgraphs, staff papers, and staff respondence.

ff requirements memoranda for open meetings; memoranda to record; record of votes of muissioners on items under consideration at meetings.

# Advisory Committee on Reactor Safeguards

gory contains documentation pertaining to the responsibilities of the Advisory Committee or Safeguards. ACRS serves as an independent advisory committee to the Commission in ited areas. The committee provides advice with respect to the hazards of new or existar facilities and the adequacy of related safety standards. The documents in this category

batim transcripts of ACRS subcommittee and full committee meetings relating to facility use applications and safety-related matters.

RS meeting announcements; description of meeting agendas.

RS-generated reports, memoranda and correspondence that are publicly available.

RS consultant reports, comments and related correspondence.

RS and NRC technical correspondence pertaining to safety matters under review by the risory Committee on Reactor Safeguards.

#### SION - NRC Commissioners

gory contains documentation pertaining to the daily conduct of Commission business in e of the Commissioners, including:

oming and outgoing correspondence to and from the Commissioners relating to official C business, including reports and other enclosures.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers, with a SECY series designation prepared for Commission review, see SECY category.

# CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

## DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

## FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

#### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

#### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

C (Millittanton to take numerical action and

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR),
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the TOCFR category,

#### PROJ Projects Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetle characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - Meeting notices, summaties and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - 4. Early site review information.
  - 5 Backup technical documents submitted in support of the application.
  - 6. Faily site visits.
- B. Unlity PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - Amendments and changes to the PSAR.
  - 1. Transmittal letters.
  - Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, buels, orders, et al. pertaining to pre-hearing conferences, if any.
- M Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

- . Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites

ι

# PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### OA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

- guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Ouick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

# REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

- 2. Summary minutes of review group meetings representing views expressed, including dissenting
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakines

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

- a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
- b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

#### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

	•	

ND SUBTILL (Add Volume No. of appropriate)	2 (Leave blank)
itle List of Documents Made Publicly Availab March 1-31, 1981	•
H(S)	5. DATE REPORT COMPLETED
	MONTH April YEAR 1981
RMING ORGANIZATION NAME AND MAILING ADDRESS (Include 2	
sion of Technical Information and Document C Nuclear Regulatory Commission	ontrol MONTH June 1981
ington, D.C. 20555	G (I. cave blank)
	8 (Leave blank)
OHING ORGANIZATION NAME AND MAILING ADDRESS finctude 2	I 10 PDO B C1/T ASK (MODELLING AND
sion of Technical Information and Document Co	ntrol
Nuclear Regulatory Commission ington, D.C. 20555	11 CONTRACT NO
ов неронт	FRIOD COVERED (Inclusive dates)
hly	
EMENTARY NOTES	14 (Leave plank)
AAC1 (200 words to less)	
This document is a monthly publication con information received and generated by the	taining descriptions of

merly issued through the U.S. Department of Energy's Technical Information Center under the title *Power Reactor Docket Information (PRDI)*. This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.